Title List of Documents Made Publicly Available

October 1-31, 1983

Office of Administration U.S. Nuclear Regulatory Commission



Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

October 1-31, 1983

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



	·		
			:

CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	χV
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	6
Domestic Licensing of Special Nuclear Material — Docket 70	379
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	388
Licensing of Independent Spent Fuel Storage — Docket 72	394
Nondocketed Items	395
10 CFR — Commission Meeting Records	395
ACRS — Advisory Committee on Reactor Safeguards	396
ADVCM — NRC Advisory Committees	396
COMMISSION — NRC Commissioners	396
CONTRACT — NRC Contracts and Modifications	398
FOIA — Freedom of Information Act Requests and Releases	407
GEN TECH IS — Generic Technical Issues	442
I&E — Inspection and Enforcement	444
MISC — Public Document Room Miscellaneous	447
NUREG — NUREG Reports and Related Correspondence	448
ORG — Correspondence with Other Organizations	464
PR — Proposed Rule	465
PRM — Petition for Rulemaking	466
PROJ — Projects - Predocket Licensing	466
PT21 — Noncompliance Reports and Related Correspondence	467
QA999 — Quality Assurance Inspections	469
REGGD — Regulatory Guides	474
RES — Research and Technical Assistance Reports	474
REVIEW GROUP — NRC Research Review Groups	474
SECY — Position Papers Before the Commission	474
STATE PROG — State Programs	476
TOPREP — Vendor Reports and Related Correspondence	476
WASH—Regulatory Publications—Pre-NUREG Series	480
WASTE MGT — Nuclear Waste Management	481
XPORTLIC — Export and Import Licenses	482
Personal Author Index	489
Corporate Source Index	523
Report Number Index	553
Cross Reference of Enclosures to Principal Documents	555
Appendix A — Definitions of Docket 50 Categories	
Appendix B — Definitions of Nondocketed Categories	

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence

(3)

8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. (5) Tennessee Valley Authority. (6) 82/03/04. (7) VASSALLO, D.B. Operating Reactors Branch 2. (8) 1p. 1216:254. 24XFiche: 50-259, 82/03/04,

Operating Reactors Branch 2. (8) 1p. 1216:254. 24XFich. 8203090028.

- NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

I&E - Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT — Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

1) NUREG—NUREG Reports and Related Correspondence

8203090207 NUREG/CR-1672 V02

RISK ASSESSMENT METHODOLOGY DEVELOPMENT FOR WASTE ISOLATION
IN GEOLOGIC MEDIA. Technical Review of Documents
NUREG/CR-1262, NUREG/CR-1376, NUREG/CR-1377, NUREG/CR-1397 &
NUREG/CR-1608.

5 - STEVENS, C.A., FULLWOOD, R.A., BASIN, S.L. Science Applications, Inc.

FIN B-6694. SAI-262-81-PA. 82/02/28. Division of Risk Analysis.

123 p. Available at NRC. \$6.00. 12176:217.

- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Ra	dwaste Disposal Sites - Docket 27		40-8452	Bear Creek Uranium Co , Casper, WY	4
27-039	Sheffield, IL, U S Ecology, Inc	1	40-8502	Wyoming Mineral Corp , Lakewood, CO	5
27-048	Richland, WA, U.S. Ecology, Inc.	i	40-8584	Minerals Exploration Co, Los Angeles, CA	5
Domestic Lice	nsing of Source Material — Docket 40		40-8599	Air Force, Dept. of, Brooks AFB, TX	5
40-0017	Dow Chemical Co, Midland, MI	1	40-8674	Plateau Resources, Ltd., Grand Junction, CO	5
40-0086	W R. Grace & Co , Pompton Plains, NJ	1	40-8681	Energy Fuels Nuclear, Inc , Denver, CO	5
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8697	Rocky Mountain Energy Co , Denver, CO	5
40-0462	Dow Chemical Co, Midland, MI	2	40-8698	Plateau Resources, Ltd , Grand Junction, CO	5
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8714	Cleveland-Cliffs Iron Co , Cleveland, OH	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8745	Ogle Petroleum, Inc , Casper, WY	6
40-2061	Kerr-McGee Chemical Corp , Oklahoma City, OK	2	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	6
40-2259	Pathfinder Mines Corp , Riverton, WY	3	40-8781	Teton Exploration Drilling Co., Inc., Casper, WY	6
40-3392	Allied Chemical Corp , Morristown, NJ	3	40-8783	Uranerz USA, Inc., Casper, WY	6
40-3453	Atlas Minerals, Inc., Denver, CO	3	40-8786	Uranium Resources, Inc., Richardson, TX	6
40-4492	Federal-American Partners, Riverton, WY	3	40-8794	Molycorp, Inc., Los Angeles, CA	6
40-4931	Navy, Dept. of, Annapolis, MD	3	40-8801	Radiation Management Corp., Northbrook, IL	6
40-6500	Energy, Dept of, Canonsburg, PA	3	40-8807	Air Force, Dept. of, Tinker AFB, OK	6
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	3	40-8829	Wyoming Fuel Co., Lakewood, CO	6
40-6659	Getty Oil CoPetrotomics Co., Shirley Basin, WY	3	40-8839	Santa Fe Mining, Inc., Albuquerque, NM	6
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	4	Domestic Licer Docket 50	nsing of Production and Utilization Facilities—	
40-7869	Plateau Resources, Ltd , Grand Junction, CO	4		Heir of Michigan Bossarch Bonatas	6
40-8027	Kerr-McGec Nuclear Corp., Oklahoma City, OK	4	50-2 50-3	Univ. of Michigan Research Reactor Indian Point Station, Unit 1	7
40-8035	Cotter Corp., Roswell, NM	4	50-5	Pennsylvania State Univ. Research Reactor	8
40-8064	Exxon Minerals Co., USA, Houston, TX	4	50-10	Dresden Nuclear Power Station, Unit 1	8
40-8084	Rio Algom Corp., Moab, UT	4	50-18	Vallectos Boiling Water Reactor	9
40-8102	Exxon Co., USA, Houston, TX	4	50-20	Massachusetts Institute of Technology	0
40-8348	Minerals Exploration Co., Los Angeles, CA	4	60.07	Research Reactor	9
40-8380	Rocky Mountain Energy Co.,	4	50-27	Washington State Univ. Research Reactor Yankee-Rowe Nuclear Power Station	10
	Broomfield, CO		50-29	rankee-nowe muciear power diation	10

Docket	Name	Page	Docket	Name	Page
50-54	Union Carbide Research Reactor	12	50-220	Nine Mile Point Nuclear Station, Unit 1	29
50-57	State Univ of New York Research Reactor	12	50-223	Univ of Lowell Research Reactor	31
50-59	Texas A&M Univ Research Reactor	12	50-224	Univ of California Research Reactor	31
50-62	Univ of Virginia Research Reactor	12	50-225	RPI Critical Experiment	31
50-70	General Electric Test Reactor	13	50-228	Aerotest Radiography & Research Reactor	32
50-73	General Electric Nuclear Test Reactor	13	50-237	Dresden Nuclear Power Station, Unit 2	32
50-83	Univ of Florida Training Reactor	13	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35
50-87	Westinghouse Critical Experiment	13	50-245	Millstone Nuclear Power Station, Unit 1	37
50-89	General Atomic Co	13	50-247	Indian Point Station, Unit 2	38
50-112	Univ of Oklahoma Research Reactor	13	50-249	Dresden Nuclear Power Station, Unit 3	40
50-116	Iowa State Univ. Research Reactor	13	50-250	Turkey Point Plant, Unit 3	43
50-123	Univ of Missouri Research Reactor	14	50-251	Turkey Point Plant, Unit 4	45
50-124	Virginia Polytechnic Institute	.,	50-254	Quad-Cities Station, Unit 1	47
	Training Reactor	14	50-255	Palisades Nuclear Plant	49
50-128	Texas A&M Univ Research Reactor	14	50-259	Browns Ferry Nuclear Power Station, Unit 1	51
50-133	•	14	50-260	Browns Ferry Nuclear Power Station, Unit 2	55
50-134	Worcester Polytechnic Institute Research Reactor	15	50-261	H B Robinson Plant, Unit 2	57
50-139	Univ. of Washington Research Reactor	15	50-263	Monticello Nuclear Generating Plant	60
50-142	UCLA Training Reactor	15	50-265	Quad-Cities Station, Unit 2	62
50-148	Univ. of Kansas Research Reactor	15	50-266	Point Beach Nuclear Plant, Unit 1	64
50-155	Big Rock Point Nuclear Plant	16	50-267	Fort St Vrain Nuclear Generating Station	67
50-163	General Atomic Co	21	50-269	Oconee Nuclear Station, Unit 1	70
50-166	Univ of Maryland Research Reactor	21	50-270	Oconee Nuclear Station, Unit 2	72
50-170	National Naval Medical Center	22	50-271	Vermont Yankee Nuclear Power Station	75
50-171	Peach Bottom Atomic Power Station, Unit 1	22	50-272	Salem Nuclear Generating Station, Unit 1	76
50-183	Vallecitos Experimental Superheat Reactor	22	50-275	Diablo Canyon Nuclear Power Plant, Unit I	78
50-186	Univ of Missouri Research Reactor	22	50-277	Peach Bottom Atomic Power Station, Unit 2	88
50-188	Kansas State Univ Research Reactor	22	50-278	Peach Bottom Atomic Power Station, Unit 3	91
50-192	Univ. of Texas Research Reactor	22	50-280	Surry Power Station, Unit 1	93
50-193	Rhode Island & Providence Plantations AEC	22	50-281	Surry Power Station, Unit 2	95
50-199	Manhattan College Research Reactor	23	50-282	Prairie Island Nuclear Station, Unit 1	97
50-201	West Valley Reprocessing Plant	23	50-285	Fort Calhoun Station, Unit 1	99
50-206	San Onofre Nuclear Station, Unit I	24	50-286	Indian Point Station, Unit 3	102
50-213	Haddam Neck Plant	26	50-287	Oconee Nuclear Station, Unit 3	103
50-219	Oyster Creek Nuclear Power Plant	28	50-289	Three Mile Island Nuclear Station, Unit 1	106

Docket	Name	Page	Docket	Name	Page
50-293	Pilgrim Nuclear Power Station, Unit I	114	50-344	Trojan Nuclear Plant	213
50-295	Zion Nuclear Power Station, Unit 1	115	50-346	Davis-Besse Nuclear Power Station, Unit 1	215
50-296	Browns Ferry Nuclear Power Station, Unit 3	117	50-348	Joseph M Farley Nuclear Plant, Unit 1	218
50-298	Cooper Nuclear Station	120	50-352	Limerick Generating Station, Unit 1	221
50-301	Point Beach Nuclear Plant, Unit 2	122	50-353	Limerick Generating Station, Unit 2	225
50-302	Crystal River Nuclear Plant, Unit 3	124	50-354	Hope Creek Nuclear Station, Unit 1	229
50-304	Zion Nuclear Power Station, Unit 2	127	50-358	William H Zimmer Nuclear Station, Unit 1	230
50-305	Kewaunee Nuclear Power Plant	129	50-361	San Onofre Nuclear Station, Unit 2	234
50-306	Prairie Island Nuclear Station, Unit 2	131	50-362	San Onofre Nuclear Station, Unit 3	237
50-309	Maine Yankee Atomic Power Plant	133	50-364	Joseph M Farley Nuclear Plant, Unit 2	239
50-311	Salem Nuclear Generating Station, Unit 2	135	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	242
50-312	Rancho Seco Nuclear Generating Station	138	50-367	Bailly Generating Station	245
50-313	Arkansas Nuclear One, Unit 1	141	50-368	Arkansas Nuclear One, Unit 2	245
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	143	50-369	William B McGuire Nuclear Station, Unit 1	247
50-316	Donald C Cook Nuclear Power Plant, Unit 2	146	50-370	William B. McGuire Nuclear Station, Unit 2	250
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	149	50-373	LaSalle County Station, Unit 1	253
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	151	50-374	LaSalle County Station, Unit 2	255
50-320	Three Mile Island Nuclear Station, Unit 2	153	50-382	Waterford Generating Station, Unit 3	258
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	159	50-387	Susquehanna Steam Electric Station, Unit 1	262
50-322	Shoreham Nuclear Power Station	161	50-388	Susquehanna Steam Electric Station, Unit 2	265
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	164	50-389	St. Lucie Plant, Unit 2	267
50-324	Brunswick Steam Electric Plant, Unit 2	171	50-390	Watts Bar Nuclear Plant, Unit 1	269
50-325	Brunswick Steam Electric Plant, Unit 1	175	50-391	Watts Bar Nuclear Plant, Unu 2	273
50-327	Sequoyah Nuclear Plant, Unit 1	179	50-395	Virgii C Summer Nuclear Station, Unit 1	277
50-328	Sequoyah Nuclear Plant, Unit 2	181	50-397	WPPSS Nuclear Project, Unit 2	279
50-329	Midland Plant, Unit 1	184	50-400	Shearon Harris Nuclear Power Plant, Unit 1	282
50-330	Midland Plant, Unit 2	191	50-401	Shearon Harris Nuclear Power Plant, Unit 2	288
50-331	Duane Arnold Energy Center	198	50-406	Tuskegee Institute Research Reactor	293
50-333	James A. Fitzpatrick Nuclear Power Plant	200	50-409	La Crosse Boiling Water Reactor	29,1
50-334	Beaver Valley Power Station, Unit 1	202	50-410	Nine Mile Point Nuclear Station, Unit 2	295
50-335	St. Lucie Plant, Unit 1	204	50-412	Beaver Valley Power Station, Unit 2	296
50-336	Millstone Nuclear Power Station, Unit 2	206	50-413	Catawba Nuclear Station, Unit 1	298
50-338	North Anna Power Station, Unit !	207	50-414	Catawba Nuclear Station, Unit 2	302
50-339	North Anna Power Station, Unit 2	209	50-416	Grand Gulf Nuclear Station, Unit 1	306
50-341	Enrico Fermi Atomic Power Plant, Unit 2	2 11	50-417	Grand Gulf Nuclear Station, Unit 2	311

Docket	Name	Page	Docket	Name	Page
50-423	Millstone Nuclear Power Station, Unit 3	312	STN-50-499	South Texas Project, Unit 2	363
50-424	Alvin W Vogtle Nuclear Plant, Unit I	313	STN-50-508	WPPSS Nuclear Project, Unit 3	365
50-425	Alvin W Vogtle Nuclear Plant, Unit 2	314	50-513	WPPSS Nuclear Project, Unit 4	366
50-433	UC-Santa Barbara Research Reactor	315	50-514	Pebble Springs Nuclear Plant, Unit 1	366
50-434	Surry Power Station, Unit 3	315	50-515	Pebble Springs Nuclear Plant, Unit 2	366
50-438	Bellefonte Nuclear Plant, Unit 1	315	50-522	Skagit Nuclear Power Project, Unit 1	367
50-439	Bellefonte Nuclear Plant, Unit 2	317	50-523	Skagit Nuclear Power Project, Unit 2	367
50-440	Perry Nuclear Power Plant, Unit 1	319	STN-50-528	Palo Verde Nuclear Station, Unit I	368
50-441	Perry Nuclear Power Plant, Unit 2	322	STN-50-529	Palo Verde Nuclear Station, Unit 2	370
50-443	Seabrook Nuclear Station, Unit 1	324	STN-50-530	Palo Verde Nuclear Station, Unit 3	373
50-444	Seabrook Nuclear Station, Unit 2	328	50-537	Chuch River Breeder Reactor	375
50-445	Comanche Peak Steam Electric Station,	332	STN-50-546	Marble Hill Nuclear Station, Unit 1	376
60 146	Unit 1	336	STN-50-547	Marble Hill Nuclear Station, Unit 2	377
50-446	Comanche Peak Steam Electric Station, Unit 2	330	STN-50-553	Phipps Bend Nuclear Station, Unit 1	378
STN-50-447	GESSAR-238	340	STN-50-554	Phipps Bend Nuclear Station, Unit 2	378
STN-50-454	Byron Station, Unit 1	340	STN-50-556	Black Fox Station, Unit 1	378
STN-50-455	Byron Station, Unit 2	344	STN-50-557	Black Fox Station, Unit 2	379
STN-50-456	Braidwood Station, Unit 1	346	Domestic Lice	ensing of Special Nuclear Material - Docket 70	
STN-50-457	Braidwood Statton, Unit 2	348	70-0025	Rockwell International Corp, Canoga Park, CA	379
50-458	River Bend Station, Unit 1	350	70-0027	Babcock & Wilcox Co , Lynchburg, VA	379
50-459	River Bend Station, Unit 2	352	70-0027	Combustion Engineering, Inc., Windsor, CT	380
50-460	WPPSS Nuclear Project, Unit 1	353	70-0035	Babcock & Wilcox Co , Apollo, PA	380
50-461	Clinton Power Station, Unit 1	354	70-0143	Nuclear Fuel Services, Inc., Erwin, TN	380
50-462	Clinton Power Station, Unit 2	355	70-0364	Babcock & Wilcox Co., Apollo, PA	382
STN-50-470	CESSAR System 80	355	70-0371	UNC Naval Products, Inc., Uncasville, CT	382
50-471	Pilgrim Nuclear Power Station, Unit 2	356	70-0474	Upsala College, East Orange, NJ	383
STN-50-482	Wolf Creek Generating Station	356	70-0572	Monsanto Research Corp , Dayton, OH	383
STN-50-483	Callaway Plant, Unit 1	357	70-0698	Westinghouse Electric Corp., Pittsburgh, PA	
STN-50-486	Callaway Plant, Unit 2	359	70-0734	GA Technologies, Inc., San Diego, CA	383
STN-50-491	Cherokee Nuclear Station, Unit 1	360	70-0754	General Electric Co , Pleasanton, CA	383
STN-50-492	Cherokee Nuclear Station, Unit 2	360	70-0734	United Nuclear Corp , Wood River	383
STN-50-493	Cherokee Nuclear Station, Unit 3	360	70-0620	Junction, RI	383
50-496	Montague Nuclear Power Station, Unit 1	360	70-0824	Babcock & Wilcox Co., Lynchburg, VA	383
50-497	Montague Nuclear Power Station, Unit 2	360	70-0984	Battelle Memorial Institute, Richland, WA	384
STN-50-498	South Texas Project, Unit 1	361	70-1100	Combustion Engineering, Inc., Windsor, CT	384

Docket	Name	Page	Docket	Name	Page
70-1113	General Electric Co , Wilmington, NC	384	71-0503	Penn Inspection Co	388
70-1143	Westinghouse Electric Corp , Pittsburgh, PA	385	71-0504	Texas Utility Generating Co	388
70-1144	Ohmart Corp , Cincinnati, OH	385	71-0505	Southwest Research Institute	388
70-1151	Westinghouse Electric Corp , Pittsburgh, PA	385	71-0506	Babcock & Wilcox Co.	388
70-1201	Babcock & Wilcox Co., Lynchburg, VA	386	71-4909	Model, GE-21PF-1, General Electric Co	389
70-1257	Exxon Nuclear Co , Inc , Richland, WA	386	71-5059	Model NFS-Uranyl Nat , Nuclear Fuel	389
70-1308	General Electric Co , San Jose, CA	386	71-5088	Services, Inc Model: D34710-1, D34710-2, Rockwell	209
70-1426	Transnuclear, Inc., Falls Church, VA	386	71-5000	International Corp	389
70-1462	Harper Hospital, Detroit, MI	386	71-5450	Model RCC -1, -2, -3, -4, Westinghouse Electric Corp	389
70-1487	Dow Chemical USA, Midland, MI	386	71-5595	Model: L&M ORNL Uranium Shielded Cask,	547
70-1795	George Washington Univ , Washington, DC	387	11-5555	Energy, Dept. of	389
70-2067	Union Carbide Corp , Marietta, OH	387	71-5797	Model: Inner & Outer HFIR UN, Energy, Dept of	389
70-2319	Our Lady of Lourdes Hospital, Camden, NJ	387	71-5805	Model: CNS 3-55, Chem-Nuclear Systems,	202
70-2430	Mercer Medical Center, Trenton, NJ	387	71-5005	Inc.	389
70-2808	Westmoreland Hospital, Greensburg, PA	387	71-5828	Model: TREAT, Energy, Dept. of	389
70-2941	Tennessee Valley Authority, Chattanooga, TN	387	71-5908	Model DOT-6M Type B, Babcock & Wilcox Co	389
70-2945	Union Electric Co, St. Louis, MO	387	71-5939	Model: GE-1500, General Electric Co.	389
70-2946	Louisiana Power & Light Co., New Orleans, LA	387	71-5957	Model: BMI-1, Battelle Columbus Laboratory	389
70-2949	Arizona Public Service Co., Phoenix, AZ	387	71-5971	Model: GE-200, General Electric Co.	389
70-2950	Washington Public Power Supply System,		71-6003	Model: M-130, Energy, Dept. of	389
	Richland, WA	387	71-6144	Model: B-2, U.S. Ecology, Inc.	389
70-2960	Kansas Gas & Electric Co, Wichita, KS	387	71-6166	Model: 0.5T, Energy, Dept. of	390
70-2968	Cleveland Electric Illuminating Co., Cleveland, OH	387	71-6346	Model: FSV-1, GA Technologies, Inc.	390
70-2973	Commonwealth Edison Co., Chicago, IL	387	71-6400	Model: 6400, Westinghouse Electric Corp.	3 90
70-2977	Detroit Edison Co., Detroit, MI	388	71-6478	Model: 4T, Energy, Dept. of	3 90
70-2983	Pennsylvania Power & Light Co.,		71-6550	Model: 6-GS-1, Energy, Dept. of	390
	Allentown, PA	388	71-6574	HN-200, Hitiman Nuclear &	400
70-2988	Philadelphia Electric Co., Philadelphia, PA	388	-1 4454	Development Corp.	390
	tadioactive Material for Transport and on of Radioactive Material Under Certain - Docket 71		71-6601	Model CNS 8-120, Chem-Nuclear Systems, Inc.	390
71-0037	Navy, Dept of	388	71-6679	Model: 6679, U.S. Ecology, Inc.	390
71-0059	General Electric Co.	388	71-6697	Model: GE-8500, General Electric Co.	390
71-0137	Metals Testing Co, Inc.	388	71-6771	Model: SN-1, Metropolitan Edison Co.	390
71-0148	United Engineers & Constructors, Inc.	388	71-9009	Model: FL 10-1, General Electric Co.	390
71-0466	Minnesota Mining & Manufacturing Co.		71-9010	Model: NLI-1/2, NL Industries, Inc.	390
,. 5100	(3M Co.)	388	71-9016	Model: TN-9, No Users	391

Docket	Name	Page	Docket	Name	Page
71-9027	Model 741 & 741E, Technical Operations, Inc.	391	71-9126	Model. 20, 20A, 50, 50A, Gamma Industries	392
71-9032	Model 650, Technical Operations, Inc	391	71-9127	Model 100, 100A, 200, 200A, Gamma Industries	392
71-9033	Model 660 & 660E, Technical Operations, Inc	391	71-9128	Model: C-8, Gamma Industries	392
71-9039	Model: 715, Technical Operations, Inc	391	71-9132	Model T-3, Energy, Dept of	392
71-9039	Model: GE-1600, General Electric Co	391	71-9143	Model: 920, Technical Operations, Inc	392
71-9070	Model N-55, Energy, Dept. of	391	71-9145	Model: NUPAC 50-1 5L, -2 5L, -3 0L & -4 0L, No Users	393
71-9080	Model: 9080, Hittman Nuclear &	391	71-9147	Model. 850, Technical Operations, Inc	393
71-9086	Development Corp Model HN-100, Series 1, Hittman Nuclear &	391	71-9151	Model, HN-100, Series 3, Hittman Nuclear & Development Corp	393
71-9089	Development Corp Model: HN-100S, Hittman Nuclear & Development Corp.	391	71-9152	Model: CNS 1-13C II, Chem-Nuclear Systems, Inc	393
71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	392	71-9158	Model, CNS 3-70, Ridihalgh, Eggers & Associates	393
71-9093	Model HN-400, Hittman Nuclear &	392	71-9159	Model: NUPAC 14/190L, /190M & /190H, Nuclear Packaging, Inc.	393
	Development Corp.	392	71-9160	Model: 20-VS & 40-VS Gulf Nuclear, Inc.	393
71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc	392	71-9163	Model: GNG-20, Gulf Nuclear, Inc	393
71-9100	Model: KKP-20-4950, Kerr-McGee Nuclear		71-9181	Model: PAS-2, Nuclear Packaging, Inc.	393
71-9105	Corp. Model: Rad-Waste CR.I, Chem-Nuclear	392	71-9182	Model: Husman Irradiator, Agriculture, Dept. of	393
71 3100	Systems, Inc.	392	71-9184	Model: PAS-1, Nuclear Packaging, Inc	393
71-9107	Model. 771, Technical Operations, Inc	392	71-9510	Model GPHS, Energy, Dept of	393
71-9108	Model CNS 6-75, Chem-Nuclear Systems, Inc	392	71-9852	Model DT-14, Energy, Dept. of	393
71-9111	Model: CNS 6-80-2 & CNS 6-80-2A, Chem-		Licensing of	Independent Spent Fuel Storage — Docket 72	
	Nuclear Systems, Inc	392	72-0001	Morris Operations, General Electric Co	394

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27			Ogle Petroleum, Inc , Casper, WY	40-8745	6
Richland, WA, U.S Ecology, Inc	27-048	1	Pathfinder Mines Corp , Riverton, WY	40-2259	3
Sheffield, IL, U S Ecology, Inc	27-039	1	Pathfinder Mines Corp , Shirley Basin, WY	40-6622	3
Domestic Licensing of Source Material — Dock	et 40		Plateau Resources, Ltd.,	40-7869	4
Air Force, Dept of, Brooks AFB, TX	40-8599	5	Grand Junction, CO	10.0001	-
Air Force, Dept of, Tinker AFB, OK	40-8807	6	Plateau Resources, Ltd , Grand Junction, CO	40-8674	.5
Allied Chemical Corp , Morristown, NJ	40-3392	3	Plateau Resources, Ltd ,	40-8698	5
Atlas Minerals, Inc., Denver, CO	40-3453	3	Grand Junction, CO	40 8001	,
Bear Creek Uranium Co., Casper, WY	40-8452	4	Radiation Management Corp , Northbrook, IL	40-8801	6
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	6	Rio Algom Corp , Moab, UT	40-8084	4
Cotter Corp., Roswell, NM	40-8035	4	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Dow Chemical Co, Midland, MI	40-0017	1	Rocky Mountain Energy Co , Denver, CO	40-8697	5
Dow Chemical Co., Midland, MI	40-0462	2	Santa Fe Mining, Inc , Albuquerque, NM	40-8839	6
Energy Fuels Nuclear, Inc , Denver, CO	40-8681	5	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Energy, Dept. of, Canonsburg, PA	40-6500	3	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	Ćs.
Exxon Co., USA, Houston, TX	40-8102	4	Union Carbide Corp , Grand Junction, CO	40-0299	1
Exxon Minerals Co., USA, Houston, TX	40-8064	4	• • • • • • • • • • • • • • • • • • • •	40-8783	
Federal-American Partners, Riverton, WY	40-4492	3	Uranerz USA, Inc., Casper, WY		Ó
Getty Oil CoPetrotomics Co., Shirley Basin, WY	40-6659	3	Uranium Resources, Inc., Richardson, TX W. R. Grace & Co., Pompton Plains, NJ	40-8786 40-0086	1
Kawecki Berylco Industries, Inc.,	40-6940	4	Wyoming Fuel Co , Lakewood, CO	40-8829	6
Boyertown, PA Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Wyoming Mineral Corp , Lakewood, CO	40-8502	,5
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8027	4	Domestic Licensing of Production and Utilizati Docket 50	on Facilities —	
Kerr-McGee Nuclear Corp.,	40-8768	6	Aerotest Radiography & Research Reactor	50-228	32
Oklahoma City, OK	40-0700	v	Alvin W Vogtle Nuclear Plant, Unit 1	50-424	313
Minerals Exploration Co., Los Angeles, CA	40-8348	4	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	314
Minerals Exploration Co., Los Angeles, CA	40-8584	5	Arkansas Nuclear One, Unit 1	50-313	141
Molycorp, Inc., Los Angeles, CA	40-8794	6	Arkansas Nuclear One, Unit 2	50-368	245
Navy, Dept. of, Annapolis, MD	40-4931	3	Bailly Generating Station	50-367	245
Nuclear Metals, Inc., Concord, MA	40-0672	2	Beaver Valley Power Station, Unit 1	50-334	202

Beaver Valley Power Station, Unit 2 50-412 296 Diablo Canyon Nuclear Power Plant, Unit 2 50-323 164 Bellefonte Nuclear Plant, Unit 1 50-438 315 Donald C Cook Nuclear Power Plant, Unit 1 50-315 143 Bellefonte Nuclear Plant, Unit 2 50-439 317 Donald C Cook Nuclear Power Plant, Unit 2 50-316 146 Big Rock Point Nuclear Plant 50-155 16 Dresden Nuclear Power Station, Unit 1 50-10 8 Black Fox Station, Unit 1 STN-50-556 378 Dresden Nuclear Power Station, Unit 2 50-237 32 Braidwood Station, Unit 2 STN-50-557 379 Dresden Nuclear Power Station, Unit 3 50-249 40 Braidwood Station, Unit 1 STN-50-456 346 Duane Arnold Energy Center 50-331 198 Browns Ferry Nuclear Power Station, Unit 1 50-259 51 Edwin I. Hatch Nuclear Plant, Unit 1 50-321 159 Browns Ferry Nuclear Power Station, Unit 2 50-260 55 Enrico Fermi Atomic Power' Plant, Unit 2 50-341 211 Browns Ferry Nuclear Power Station, Unit 3 50-296 117
Bellefonte Nuclear Plant, Unit 2 50-439 317 Donald C Cook Nuclear Power Plant, Unit 2 50-316 146 Big Rock Point Nuclear Plant 50-155 16 Dresden Nuclear Power Station, Unit 1 50-10 8 Black Fox Station, Unit 1 STN-50-556 378 Dresden Nuclear Power Station, Unit 2 50-237 32 Black Fox Station, Unit 2 STN-50-557 379 Dresden Nuclear Power Station, Unit 3 50-249 40 Braidwood Station, Unit 1 STN-50-456 346 Duane Arnold Energy Center 50-331 198 Braidwood Station, Unit 2 STN-50-457 348 Edwin I. Hatch Nuclear Plant, Unit 1 50-321 159 Browns Ferry Nuclear Power Station, Unit 2 50-260 55 Entrico Fermi Atomic Power Plant, Unit 2 50-341 211 Browns Ferry Nuclear Power Station, Unit 3 50-296 117 Fort Calhoun Station, Unit 1 50-285 99 Brunswick Steam Electric Plant, Unit 1 50-325 175 Fort St. Vrain Nuclear Generating Station 50-267 67
Big Rock Point Nuclear Plant 50-155 16 Dresden Nuclear Power Station, Unit 1 50-10 8 Black Fox Station, Unit 1 STN-50-556 378 Dresden Nuclear Power Station, Unit 2 50-237 32 Black Fox Station, Unit 2 STN-50-557 379 Dresden Nuclear Power Station, Unit 3 50-249 40 Braidwood Station, Unit 1 STN-50-456 346 Duane Arnold Energy Center 50-331 198 Braidwood Station, Unit 2 STN-50-457 348 Edwin I. Hatch Nuclear Plant, Unit 1 50-321 159 Browns Ferry Nuclear Power Station, Unit 2 50-366 242 Browns Ferry Nuclear Power Station, Unit 2 50-260 55 Enrico Fermi Atomic Power Plant, Unit 2 50-341 211 Browns Ferry Nuclear Power Station, Unit 3 50-285 99 Brunswick Steam Electric Plant, Unit 1 50-267 67
Black Fox Station, Unit 1 STN-50-556 378 Dresden Nuclear Power Station, Unit 2 STN-50-557 379 Dresden Nuclear Power Station, Unit 3 STN-50-456 346 Duane Arnold Energy Center STN-50-457 348 Braidwood Station, Unit 2 STN-50-457 348 Browns Ferry Nuclear Power Station, Unit 1 STN-50-457 348 Browns Ferry Nuclear Power Station, Unit 1 STN-50-457 348 Browns Ferry Nuclear Power Station, Unit 1 STN-50-457 348 Browns Ferry Nuclear Power Station, Unit 1 STN-50-457 348 Browns Ferry Nuclear Power Station, Unit 1 SO-259 51 Browns Ferry Nuclear Power Station, Unit 2 So-366 242 Browns Ferry Nuclear Power Station, Unit 2 So-260 55 Enrico Fermi Atomic Power Plant, Unit 2 So-341 211 Browns Ferry Nuclear Power Station, Unit 3 So-296 117 Fort Calhoun Station, Unit 1 So-285 99 Brunswick Steam Electric Plant, Unit 1 So-267 67
Black Fox Station, Unit 2 Braidwood Station, Unit 1 STN-50-456 Braidwood Station, Unit 2 Braidwood Station, Unit 2 Browns Ferry Nuclear Power Station, Unit 1 Browns Ferry Nuclear Power Station, Unit 2 Browns Ferry Nuclear Power Station, Unit 3 SO-259 STN-50-457 S48 Edwin I. Hatch Nuclear Plant, Unit 2 SO-366 242 Browns Ferry Nuclear Power Station, Unit 2 SO-260 S5 Enrico Fermi Atomic Power Plant, Unit 2 SO-341 211 Browns Ferry Nuclear Power Station, Unit 3 SO-296 STN-50-457 Fort Calhoun Station, Unit 1 SO-285 99 Brunswick Steam Electric Plant, Unit 1 SO-267 67
Braidwood Station, Unit 1 STN-50-456 Braidwood Station, Unit 2 STN-50-457 Browns Ferry Nuclear Power Station, Unit 1 SO-259 Browns Ferry Nuclear Power Station, Unit 2 Browns Ferry Nuclear Power Station, Unit 3 SO-260 SSTN-50-457 SHOW I. Hatch Nuclear Plant, Unit 2 SO-366 SO-366 SO-366 SO-366 SO-366 SO-366 Brunswick Steam Electric Plant, Unit 1 SO-285 Port St. Vrain Nuclear Generating Station SO-267 SO-267
Braidwood Station, Unit 2 STN-50-457 348 Edwin I. Hatch Nuclear Plant, Unit 1 50-321 159 Browns Ferry Nuclear Power Station, Unit 1 50-259 51 Edwin I. Hatch Nuclear Plant, Unit 2 50-366 242 Browns Ferry Nuclear Power Station, Unit 2 50-260 55 Enrico Fermi Atomic Power Plant, Unit 2 50-341 211 Browns Ferry Nuclear Power Station, Unit 3 50-296 117 Fort Calhoun Station, Unit 1 50-285 99 Brunswick Steam Electric Plant, Unit 1 50-325 175 Fort St. Vrain Nuclear Generating Station 50-267 67
Browns Ferry Nuclear Power Station, Unit 1 50-259 51 Edwin I. Hatch Nuclear Plant, Unit 2 50-366 242 Browns Ferry Nuclear Power Station, Unit 2 50-260 55 Enrico Fermi Atomic Power Plant, Unit 2 50-341 211 Browns Ferry Nuclear Power Station, Unit 3 50-296 117 Fort Calhoun Station, Unit 1 50-285 99 Brunswick Steam Electric Plant, Unit 1 50-325 175 Fort St. Vrain Nuclear Generating Station 50-267 67
Browns Ferry Nuclear Power Station, Unit 2 50-260 55 Enrico Fermi Atomic Power Plant, Unit 2 50-341 211 Browns Ferry Nuclear Power Station, Unit 3 50-296 117 Fort Calhoun Station, Unit 1 50-285 99 Brunswick Steam Electric Plant, Unit 1 50-325 175 Fort St. Vrain Nuclear Generating Station 50-267 67
Browns Ferry Nuclear Power Station, Unit 3 50-296 117 Fort Calhoun Station, Unit 1 50-285 99 Brunswick Steam Electric Plant, Unit 1 50-325 175 Fort St. Vrain Nuclear Generating Station 50-267 67
Brunswick Steam Electric Plant, Unit 1 50-325 175 Fort St. Vrain Nuclear Generating Station 50-267 67
, , , , , , , , , , , , , , , , , , ,
Brunswick Steam Electric Plant, Unit 2 50-324 171 General Atomic Co 50-163 21
Byron Station, Unit 1 STN-50-454 340 General Atomic Co 50-89 13
Byron Station, Unit 2 STN-50-455 344 General Electric Nuclear Test Reactor 50-73 13
Callaway Plant, Unit 1 STN-50-483 357 General Electric Test Reactor 50-70 13
Callaway Plant, Unit 2 STN-50-486 359 GESSAR-238 STN-50-447 340
Calvert Cliffs Nuclear Power Plant, Unit 1 50-317 149 Grand Gulf Nuclear Station, Unit 1 50-416 306
Calvert Cliffs Nuclear Power Plant, Unit 2 50-318 151 Grand Gulf Nuclear Station, Unit 2 50-417 311
Catawba Nuclear Station, Unit I 50-413 298 H B Robinson Plant, Unit 2 50-261 57
Catawba Nuclear Station, Unit 2 50-414 302 Haddam Neck Plant 50-213 26
CESSAR System 80 STN-50-470 355 Hope Creek Nuclear Station, Unit 1 50-354 229
Cherokee Nuclear Station, Unit 1 STN-50-49! 360 Humboldt Bay Power Plant, Unit 3 50-133 14
Cherokee Nuclear Station, Unit 2 STN-50-492 360 Indian Point Station, Unit 1 50-3 7
Cherokee Nuclear Station, Unit 3 STN-50-493 360 Indian Point Station, Unit 2 50-247 38
Clinch River Breeder Reactor 50-537 375 Indian Point Station, Unit 3 50-286 102
Chinton Power Station, Unit 1 50-461 354 Iowa State Univ. Research Reactor 50-116 13
Chinton Power Station, Unit 2 50-462 355 James A. Fitzpatrick Nuclear Power Plant 50-333 200
Comanche Peak Steam Electric Station, 50-445 332 Joseph M. Farley Nuclear Plant, Unit 1 50-348 218 Unit 1
Joseph M. Farley Nuclear Plant, Unit 2 50-364 239 Comanche Peak Steam Electric Station, 50-446 336 Unit 2 Kansas State Univ. Research Reactor 50-188 22
Davis-Besse Nuclear Power Station, Unit I 50-346 215 LaSalle County Station, Unit 1 50-373 253 Diablo Canyon Nuclear Power Plant, Unit ! 50-275 78 LaSalle County Station, Unit 2 50-374 255

Name	Docket	Page	Name	Docket	Page
Limerick Generating Station, Unit 1	50-352	221	Perry Nuclear Power Plant, Unit 2	50-441	322
Limerick Generating Station, Unit 2	50-353	225	Phipps Bend Nuclear Station, Unit 1	STN-50-553	378
Maine Yankee Atomic Power Plant	50-309	133	Phipps Bend Nuclear Station, Unit 2	STN-50-554	378
Manhattan College Research Reactor	50-199	23	Pilgrim Nuclear Power Station, Unit 1	50-293	114
Marble Hill Nuclear Station, Unit 1	STN-50-546	376	Pilgrim Nuclear Power Station, Unit 2	50-471	356
Marble Hill Nuclear Station, Unit 2	STN-50-547	377	Point Beach Nuclear Plant, Unit I	50-266	(r-l
Massachusetts Institute of Technology Research Reactor	50-20	9	Point Beach Nuclear Plant, Unit 2	50-301	122
Midland Plant, Unit 1	50-329	184	Prairie Island Nuclear Station, Unit 1	50-282	97
Midland Plant, Unit 2	50-330	191	Prairie Island Nuclear Station, Unit 2	50-306	131
Milisione Nuclear Power Station, Unit 1	50-245	37	Quad-Cities Station, Unit 1	50-254	47
Millstone Nuclear Power Station, Unit 2	50-336	206	Quad-Cities Station, Unit 2	50-265	62
Millstone Nuclear Power Station, Unit 3	50-423	312	Rancho Seco Nuclear Generating Station	50-312	138
Montague Nuclear Power Station, Unit 1	50-496	360	Rhode Island & Providence Plantations AEC	50-193	22
Montague Nuclear Power Station, Unit 2	50-497	360	River Bend Station, Unit 1	50-458	350
Monticello Nuclear Generating Plant	50-263	60	River Bend Station, Unit 2	50-459	352
National Naval Medical Center	50-170	22	Robert Enimet Ginna Nuclear Plant, Unit 1	50-244	35
Nine Mile Point Nuclear Station, Unit 1	50-220	29	RPI Critical Experiment	50-225	31
Nine Mile Point Nuclear Station, Unit 2	50-410	295	Salem Nuclear Generating Station, Unit 1	50-272	76
North Anna Power Station, Unit 1	50-338	207	Salem Nuclear Generating Station, Unit 2	50-311	135
North Anna Power Station, Unit 2	50-339	209	San Onofre Nuclear Station, Unit 1	50-206	24
Oconce Nuclear Station, Unit 1	50-269	70	San Onofre Nuclear Station, Unit 2	50-361	234
Oconce Nuclear Station, Unit 2	50-270	72	San Onofre Nuclear Station, Unit 3	50-362	237
Oconee Nuclear Station, Unit 3	50-287	103	Seabrook Nuclear Station, Unit 1	50-443	324
Oyster Creek Nuclear Power Plant	50-219	28	Seabrook Nuclear Station, Unit 2	50-444	328
Palisades Nuclear Plant	50-255	49	Sequoyah Nuclear Plant, Unit 1	50-327	179
Palo Verde Nuclear Station, Unit 1	STN-50-528	368	Sequoyah Nuclear Plant, Unit 2	50-328	181
Palo Verde Nuclear Station, Unit 2	STN-50-529	370	Shearon Harris Nuclear Power Plant, Unit 1	50-400	282
Palo Verde Nuclear Station, Unit 3	STN-50-530	373	Shearon Harris Nuclear Power Plant, Unit 2	50-401	288
Peach Bottom Atomic Power Station, Unit 1	50-171	22	Shoreham Nuclear Power Station	50-322	161
Peach Bottom Atomic Power Station, Unit 2	50-277	88	Skugit Nuclear Power Project, Unit 1	50-522	367
Peach Bottom Atomic Power Station, Unit 3	50-278	91	Skagit Nuclear Power Project, Unit 2	50-523	367
Pebble Springs Nuclear Plant, Unit 1	50-514	366	South Texas Project, Unit 1	STN-50-498	361
Pebble Springs Nuclear Plant, Unit 2	50-515	366	South Texas Project, Unit 2	STN-50-499	363
Pennsylvania State Univ. Research Reactor	50-5	8	St Lucie Plant, Unit 1	50-335	204
Perry Nuclear Power Plant, Unit 1	50-440	319	St. Lucie Plant, Unit 2	50-389	267

Name	Docket	Page	Name	Docket	Page
State Univ of New York Research Reactor	50-57	12	Waterford Generating Station, Unit 3	50-382	258
Surry Power Station, Unit 1	50-280	93	Watts Bar Nuclear Plant, Unit 1	50-390	269
Surry Power Station, Unit 2	50-281	95	Watts Bar Nuclear Plant, Unit 2	50-391	273
Surry Power Station, Unit 3	50-434	315	West Valley Reprocessing Plant	50-201	23
Susquehanna Steam Electric Station, Unit 1	50-387	262	Westinghouse Critical Experiment	50-87	13
Susquehanna Steam Electric Station, Unit 2	50-388	265	William B McGuire Nuclear Station, Unit 1	50-369	247
Texas A&M Univ Research Reactor	50-128	14	William B McGuire Nuclear Station, Unit 2	50-370	250
Texas A&M Univ. Research Reactor	50-59	12	William H. Zimmer Nuclear Station, Unit 1	50-358	230
Three Mile Island Nuclear Station, Unit 1	50-289	106	Wolf Creek Generating Station	STN-50-482	356
Three Mile Island Nuclear Station, Unit 2	50-320	153	Worcester Polytechnic Institute Research Reactor	50-134	15
Trojan Nuclear Plant	50-344	213	WPPSS Nuclear Project, Unit 1	50-460	353
Turkey Point Plant, Unit 3	50-250	43	WPPSS Nuclear Project, Unit 2	50-397	279
Turkey Point Plant, Unit 4	50-251	45	WPPSS Nuclear Project, Unit 3	STN-50-508	365
Tuskegee Institute Research Reactor	50-406	293	WPPSS Nuclear Project, Unit 4	50-513	366
UC-Santa Barbara Research Reactor	50-433	315	Yankee-Rowe Nuclear Power Station	50-29	10
UCLA Training Reactor	50-142	15	Zion Nuclear Power Station, Unit 1	50-295	115
Union Carbide Research Reactor	50-54	12	Zion Nuclear Power Station, Unit 2	50-304	127
Univ of California Research Reactor	50-224	31			
Univ of Florida Training Reactor	50-83	13	Domestic Licensing of Special Nuclear Mate	riał – Docket 70	0
Univ of Kansas Research Reactor	50-148	15	Arizona Public Service Co , Phoenix, AZ	70-2949	387
Univ of Lowell Research Reactor	50-223	31	Babcock & Wilcox Co , Apollo, PA	70-0135	380
Univ of Maryland Research Reactor	50-166	21	Babcock & Wtlcox Co , Apollo, PA	70-0364	382
Univ of Michigan Research Reactor	50-2	6	Babcock & Wilcox Co , Lynchburg, VA	70-1201	386
Univ of Missouri Research Reactor	50-186	22	Babcock & Wilcox Co , Lynchburg, VA	70-0824	383
Univ of Missouri Research Reactor	50-123	14	Babcock & Wilcox Co , Lynchburg, VA	70-0027	379
Univ. of Oklahoma Research Reactor	50-112	13	Battelle Memorial Institute, Richland, WA	70-0984	384
Univ of Texas Research Reactor	50-192	22	Cleveland Electric Illuminating Co, Cleveland, OH	70-2968	387
Univ. of Virginia Research Reactor	50-62	12	Combustion Engineering, Inc., Windsor, CT	70-1100	384
Univ of Washington Research Reactor	50-139	15	Combustion Engineering, Inc., Windsor, CT	70-0036	380
Vallecitos Boiling Water Reactor	50-18	9	Commonwealth Edison Co , Chicago, IL	70-2973	387
Vallectos Experimental Superheat Reactor	50-183	22	Detroit Edison Co., Detroit, MI	70-2977	388
Vermont Yankee Nuclear Power Station	50-271	75	Dow Chemical USA, Midland, MI	70-1487	386
Virgil C. Summer Nuclear Station, Unit 1	50-395	277	Exxon Nuclear Co., Inc., Richland, WA	70-1467	386
Virginia Polytechnic Institute Training Reactor	50-124	14	GA Technologies, Inc., San Diego, CA	70-0734	383
Washington State Univ. Research Reactor	50-27	10	General Electric Co , Pleasanton, CA	70-0754	383

Name	Docket	Page	Name	Docket	Page
General Electric Co , San Jose, CA	70-1308	386	Model 0 5T, Energy, Dept of	71-6166	390
General Electric Co , Wilmington, NC	70-1113	384	Model 100, 100A, 200, 200A, Gamma	71-9127	392
George Washington Univ , Washington, DC	70-1795	387	Industries	71-9126	202
Harper Hospital, Detroit, MI	70-1462	386	Model 20, 20A, 50, 50A, Gamma Industries		392
Kansas Gas & Electric Co , Wichita, KS	70-2960	387	Model 20-VS & 40-VS, Gulf Nuclear, Inc	71-9160 71-6478	393
Louisiana Power & Light Co, New Orleans, LA	70-2946	387	Model 4T, Energy, Dept of Model: 6-GS-1, Energy, Dept of	71-6550	390 390
Mercer Medical Center, Trenton, NJ	70-2430	387	Model 6400, Westinghouse Electric Corp	71-6400	39()
Monsanto Research Corp., Dayton, OH	70-0572	383	Model 650, Technical Operations, Inc	71-9032	391
Nuclear Fuel Services, Inc , Erwin, TN	70-0143	380	Model 660 & 660E Technical Operations,	71-9033	391
Ohmart Corp , Cincinnati, OH	70-1144	385	Inc		
Our Lady of Lourdes Hospital, Camden, NJ	70-2319	387	Model: 6679, U.S. Ecology, Inc.	71-6679	390
Pennsylvania Power & Light Co,	70-2983	388	Model 715, Technical Operations, Inc	71-9039	391
Allentown, PA			Model 741 & 741E, Technical Operations, Inc.	71-9027	391
Philadelphia Electric Co., Philadelphia, PA	70-2988	388	Model 771, Technical Operations, Inc.	71-9107	392
Rockwell International Corp , Canoga Park, CA	70-0025	379	Model 850, Technical Operations, Inc	71-9147	393
Tennessee Valley Authority, Chattanooga, TN	70-2941	387	Model: 9080, Hittman Nuclear & Development Corp	71-9080	391
Transnuclear, Inc., Falls Church, VA	70-1426	386	Model: 920, Technical Operations, Inc	71-9143	392
UNC Naval Products, Inc , Uncasville, CT	70-0371	382	Model B-2, U.S. Ecology, Inc	71-9143	389
Union Carbide Corp , Marietta, OH	70-2067	387			
Union Electric Co., St Louis, MO	70-2945	387	Model: BMI-1, Battelle Columbus Laboratory	71-5957	389
United Nuclear Corp , Wood River Junction, RI	70-0820	383	Model C-8, Gamma Industries Model CNS 1-13C II, Chem-Nuclear	71-9128 71-9152	392 393
Upsala College, East Orange, NJ	70-0474	383	Systems, Inc.		
Washington Public Power Supply System,	70-2950	387	Model CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	392
Richland, WA			Model: CNS 3-55, Chem-Nuclear Systems,	71-5805	389
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	385	Inc.		
Westinghouse Electric Corp., Pittsburgh, PA	70-1151	385	Model CNS 3-70, Ridihalgh, Eggers & Associates	71-9158	393
Westinghouse Electric Corp., Pittsburgh, PA	70-0698	383	Model, CNS 6-75, Chem-Nuclear Systems,	71-9108	392
Westmoreland Hospital, Greensburg, PA	70-2808	387	Inc.		
Packaging of Radioactive Material for Transportation of Radioactive Material Under Conditions — Docket 71			Model: CNS 6-80-2 & CNS 6-80-2A, Chem-Nuclear Systems, Inc. Model: CNS 8-120, Chem-Nuclear Systems,	71-9111 71-6601	392 390
Babcock & Wilcox Co.	71-0506	388	Inc.		
General Electric Co	71-0059	388	Model: D34710-1, D34710-2, Rockwell International Corp.	71-5088	389
Metals Testing Co, Inc.	71-0137	388	Model, DOT-6M Type B, Babcock &	71-5908	389
Minnesota Mining & Manufacturing Co. (3M Co.)	71-0466	388	Wilcox Co. Model: DT-14, Energy, Dept. of	71-9852	393

Name	Docket	Page	Name	Docket	Page
Model FL 10-1, General Electric Co	71-9009	390	Model M-130, Energy, Dept of	71-6003	389
Model FSV-1, GA Technologies, Inc.	71-6346	390	Model N-55, Energy, Dept of	71-9070	391
Model GE-1500, General Electric Co	71-5939	389	Model NFS-Uranyl Nit, Nuclear Fuel	71-5059	389
Model GE-1600, General Electric Co	71-9044	391	Services, Inc. Model NLI-1/2, NL Industries, Inc.	71-9010	390
Model: GE-200, General Electric Co.	71-5971	389	·	71-9159	393
Model, GE-21PF-1, General Electric Co.	71-4909	389	Model: NUPAC 14/190L, /190M & /190H, Nuclear Packaging	71-9139	37.7
Model GE-8500, General Electric Co.	71-6697	390	Model: NUPAC 50-1 5L, -2 5L, -3.0L & -4 0L, No Users	71-9145	393
Model: GNG-20, Gulf Nuclear, Inc.	71-9163	393	Model PAS-1, Nuclear Packaging, Inc	71-9184	393
Model GPHS, Energy, Dept. of	71-9510	393	Model PAS-2, Nuclear Packaging, Inc	71-9181	393
Model HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	391	Model Rad-Waste CR.I, Chem-Nuclear Systems, Inc	71-9105	392
Model HN-100, Series 3, Hutman Nuclear & Development Corp.	71-9151	393	Model: RCC, -1, -2, -3, -4, Westinghouse Electric Corp.	71-5450	389
Model: HN-100S, Hittman Nuclear & Development Corp	71-9089	3 91	Model SN-1, Metropolitan Edison Co.	71-6771	390
Model, HN-200, Hittman Nuclear & Development Corp	71-6574	390	Model T-3, Energy, Dept. of	71-9132	392
Model HN-300, Hittman Nuclear &	71-9092	392	Model TN-9, No Users	71-9016	391
Development Corp			Model TREAT, Energy, Dept of	71-5828	389
Model: HN-400, Hittman Nuclear & Development Corp.	71-9093	392	Navy, Dept of	71-0037	388
Model Husman Irradiator, Agriculture,	71-9182	393	Penn Inspection Co	71-0503	388
Dept. of	71 7102	5,5	Southwest Research Institute	71-0505	388
Model, Inner & Outer HFIR UN, Energy, Dept, of	71-5797	389	Texas Utility Generating Co	71-0504	388
Model KKP-20-4950, Kerr-McGee Nuclear Corp.	71-9100	392	United Engineers & Constructors, Inc Licensing of Independent Spent Fuel Storage — Docket 72	71-0148	388
Model: L&M ORNL Uranium Shielded Cask, Energy, Dept of	71-5595	389	Morris Operations, General Electric Co	72-0001	394

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U.S. ECOLOGY, INC.

- 8310120063 Guarterly monitoring data of presometers & wells in vicinity of Trench 18 & Trench 18 sumps for Oct 1982 Jul 1783 W/830915 ltr HTPSMER.W M US Ecology. Inc (formerly Nuclear Engineering) 83/07/31 ESSIG.T H Region 3. Office of Director 4pp 20497 149
- B310060140 Notification of contract execution Mod 9 to "Sheffield Trench Cap Study " Contractor Univ of Illinois DELOATCH, V Technical Assistance Contracts Branch FIN 8-6945-3 B3/09/23 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director SHAFFNER, J NRC No Detailed Affiliation Given 1p 20660 361
- --8310060184 Mod 9.adding funds to Article III for contractor to attend conference in Denver.CD to "Sheffield Trench (ap Study " * Illinois, Univ of, Urbana, IL GUSTAVE,R P Division of Contracts FIN B-6765-3 83/097/23 Ip 80660 362
- 8310040194 Memorandum & order requiring parties to rept jaintly on status of sottlement negotiations by B31031 Issues to be addressed in rept listed COTTER, B P , KLINE, J R , LUEBKE, E A Atomic Bafety and Licensing Board Panel G3/09/30 3pp 20608 247
- 8310170390 Summary of quarterly monitoring data of pietometers & wells in vicinity of Trench 18 & Trench 18 sumps for Jul-Sept 1983 W/830929 ltr ARMBRUST, A J US Ecology, Inc (formerly Nuclear Engineering) 83/09/30 ESSIG, T H Region 2, Office of Director 2pp 20785 033
- 8310050557 Joint motion to continue proceedings through 840229 to permit add1 time for settlement negotiation Certificate of Svc enci EVC enci WETTERHAHN,M J US Ecology, Inc. (formerly Nuclear Engineering) LESSY,R P Hearing Branch 3 93/10/03 Atomic Safety and Licensing Board Panel 4pp 20632 174
- 8310250049 Motion for 15-day extension to rept jointly on status of settlement negotiations w/NRC & licensee, due to change in responsible parties & party location Certificate of Svc encl CHASNOFF, B A Illinois, State of 83/10/19 4pp 20894 170
- 8310250051 Notice of change of address & of addition of DL Etchison to svc list Related correspondence CHASNOFF,B A Illinois, State of 83/10/17 ip 20894 198
- 8310260268 Order granting State of IL 831021 motion for 15-day extension to rept jointly on status of settlement negotiations Rept due by 831115 CUTTER, B P Abomic Safety and Licensing Board Panel 83/10/24 Illinois, State of 1p 20712 021

DOCKET 27-048 RICHLAND, WA, U S ECOLOGY, INC

- 8310280080 Forwards correspondence w/EPA for past 3 yrs,including EPA 830817 response re duality of regulation for nuclear waste sites at Hanford,MA & Beatty,NV EASON,C F UB Ecology, Inc (formerly Nuclear Engineering) 83/09/30 LOHAUS,P Division of Haste Management 7pp 120765 068
- 8310280281 Requests approval for recommended disposal scenario for proposed waste packages to bury flaw low level raduaste HIPSHER, W M US Ecology, Inc. (formerly Nuclear Engineering) 83/10/12 BCMAFFNER, J Low Level Waste Licensing Branch 2pp 20042 314

8310310207 Forwards SNM receipt & burial rept for Sept 1983 & rept of isotopic activity 4/a encl WRIGHT, 9 V VS Ecology, Inc. (formerly Nuclear Engineering) 83/10/14 BROWNING. B Low Level Waste Licensing Branch ip 20965 302

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0017 DOW CHEMICAL CO , MIDLAND, MI

- 8310110065 Further response to FDIA request for records re incineration of radioactive matls by Dow Chemical Co Midland.MI plant Forwards App 8 documents Documents also available in PDR FELTON, JM Division of Rules and Records 83/06/20 GARDE.B P Government Accountability Project 2pp 20704 001
- --B31011010B Forwards Insp Findings & Licensee Ack re activities under Licenses 21-00265-04,8TB-527 & BMB-111 & Div of Compliance Form AEC-992 concerning noncompliance activities under Licenses 21-00265-02 & 21-00265-06 GRIER.B H Atomic Energy Commission 70/06/0B SILVERSTEIN.L Dow Chemical Co. 1p 20704-052
- --8310110115 Insp Findings & Licensee Ack dtd 700519-20 of Licenses 818-527.6MB-111 & 21-000265 04 Insp findings no noncompliance noted Related info encl 6CMLTZ.W H Atomic Energy Commission 70/06/08 16pp 20704 053

DOCKET 40-0086 W R ORACE & CO . POMPTON PLAINS, NJ

- 83101/0143 Responds to 830529 ltr & forwards guidelines for decontamination of facilities KINNEMAN,J D Region 1, Office of Director 83/09/23 TONGUE,T O W R Grace & Co Ip 20786 213
- --B310170151 Requests guidelines for decontamination of facilities & equipment prior to release for unrestricted use or termination of licenses for byproduct source or SNM, per IE Insp Rept 40-0086/74-01
 TONGUE,T O W R Grace & Co B3/05/25 KINNCMAN, J D Region I, Office of Director 1p 20786 214
- --8310170157 "Guidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Bygroduct Bource or SNM" * Atomic Energy Commission, Directorate of Licensing 73/12/31 4pp 20786-215
- --B310170165 "Quidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct. Source or SNM"

 * Division of Fuel Cycle & Material Safety 88/07/31 4pp. 2078A 219
- B310170011 "Radiological Survey of WR Grace Property, Hayne, NJ, Addendum," final rept FRAME, P W., BERGER, J D., COMDRA, R D. Dak Ridge National Laboratory FIN A-9093-0 83/09/30 Division of Safeguards 14pp 20814-052

DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO

B310260416 Forwards plan for testing clay cap & cover math & availability for final reclamation of inactive tailing area re Amend 18 to License BUA-648
LYONB, P. J. L. Union Carbide Corp. 83/06/16 WODLSEY, R. Uranium.
Recovery Field Office. 17pp. 20926 337

- B310040100 Monthly rept of water level elevations for monitor wells around pumpbact well for 830801-0701 M/830909 ltr HORTON 0 Union Carbide Corp 83/09/09 PETTENGILL H Uransum Recovery Field Office 3pp 20634 352
- 83i0200009 Raises objections to initial exploration drilling plans for determining existence of possible confining zones in Upper Wind River Aquifer PETTENGILL, HJ Uransum Recovery Field Office 83/09/14 Union Carbide Corp ip 20844 265
- 8310280165 Forwards Rev 1 to 830328 application for amend to License 8UA-648, increasing capacity of A-9 pit tailings area, in response to NRC 830818 request Approval should be obtained by 831001 to permit const LYONS.P J L Union Carbide Corp 83/09/21 PETTENGILL, H Uranium Recovery Field Office App 20946 267
- ~-8310280167 Rev 1 to 830328 application for amend to License SUA-64B, increasing capacity of A-9 pit tailings area * Union Carbide Corp 83/09/30 53pp 20946 271
- --8310280170 Nev 1 to "Impact of Increased A-9 Pit Tailings Disposal Facility on Subsurface Hydrologic Conditions " DAVIBLE A., MARDMELL R.E. Water, Waste & Land, Inc. 83/09/30 20pp 20945-324
- --83102B0175 Rev i to "Embankment Stability for A-9 Pit Increased Tailings Disposal Capacity Plan " W/one oversize map. Aperture card is available in PDR MARDMELL,R E Water, Waste & Land, Inc 83/09/30 10pp 20746 344
- --8310280177 Rev 1 to "Final Rept on Club Mesa Spray Sys Disposal MARTIN.R K . KYLE.W C Union Carbide Corp 83/09/30 13pp
- --8310280178 "Evaluation of Ground Hater Seepage Collection Sys at A-9 Pit Below Grade Tailings " W/two oversize maps Aperture cards are available in PDR HOMESTILE H. HOFFMAN.G L. Hydro-Engineering 83/09/30 49pp
- B310210146 Submits questions re inactive tailings area horizontal drains Questions must be addressed before issuance of permit to construct
 HERMANSKY.J Wyoming. State of B3/09/23 WARDWELL.R E WatHaste & Land, Inc. 19 20883 355 83/09/23 WARDWELL.R E Water,
- 8310310406 EN-83-070 on 831103.notice of violation & proposed imposition of civil penalty will be issued in amount of \$4,000 Action based on breakdown in mgt oversight & control of radiation safety program FLACK, E. AXELRAD, J. Director's Office. Office of Inspection and Enforcement 83/10/27 ip 20959 183
- DOCKET 40-0462 DOW CHEMICAL CD , MIDLAND, MI
- 3310110065 Further response to FOIA request for records re incineration of radioactive matis by Dou Chemical Co Midland, Hi plant Forwards App B documents Documents also available in PDR FELTON, J.H. Division of Rules and Records 83/06/20 GARDE, B P Government Accountability Project 2pp 20704 001
- --831011010B Forwards Insp Findings & Licensee Ack re activities under Licenses 21-00265-04.878-527 & SMB-111 & Div of Compliance Form AEC-592 concerning noncompliance activities under Licenses 21-00265-02 & 21-00265-06 GRIER, B H Atomic Energy Commission 70/06/08 SILVERSTEIN, L Dow Chemical Co 1p 20704 052
- --B310110115 Insp Findings & Licensee Ack dtd 700519-20 of Licenses ST8-527:SH8-111 & 21-000265-04 Insp findings no noncompliance noted Related info encl SCHULTZIH H Atomic Energy Commission 70/06/08 16pp 20704 053
- ICKET 40-0672 NUCLEAR METALS, INC . CONCORD, HA
- 110050516 Responds to NRC 830701 ltr re violations noted in 1E insprept on 830525-27 & 0608-10 & forwards remittance for civil analty Corrective actions exposures to workers hands sevaluated Health physics staff will meet weetly JMBACO,F J Nuclear Metals, Inc 83/09/30 Director's Office, ffice of Inspection and Enforcement 5pp 20634 121

- 8310270635 Responds to 830727 memo re civil penalties imposed on George Washington Univ Medical Ctr & Nuclear Metals, Inc Ltrs to licensees, notices of violation & insp repts encl DIRCKS W J Diffice of the Executive Director for Operations 83/10/03 GILINSKY,V Commissioners ip 20946-04
- --8310270637 Discusses IE insp on 830601-02 & forwards notice of violation & proposed imposition of civil penalty MURLEY.T E Region i, Office of Director 83/09/01 LLONAI George Washington Univ Medical Center Wash DC 3pp 20946 83/09/01 LLONARD, F DC 3pp 20946 042
- --8310270444 Notice of violation & proposed imposition of civil penalty in amount of \$2,500 Noncompliance noted adequate survey not performed to assure compliance ω/10CFR20 10b(a) re radioactive releases

 MURLEY.TE Region 1, Office of Director 83/09/01 5pp MURLEY, T E 20946 045
- --B310270647 Discusses IE insp on 830525-27 & forwards notice of violation & proposed imposition of civil penalty MURLEY.T E Region 1. Office of Director 83/09/01 TUFFII Nuclear Metals, Inc. 4pp 20946-074 83/09/01 TUFFIN, N B
- ~~8310270452 Notice of violation & proposed imposition of civil penalty in amount of 49,500 Noncompliance noted during Fourth Guarter 1982 & First Guarter 1983,10-15 individuals exposed to high contamination levels
 MURLEY.TE Region 1, Office of Director 83/09/01 4pp 20946 078
- ---B310270456 Requests description of noncompliances identified at George Washington Univ Medical Ctr & Nuclear Metals. Inc which resulted in proposed fines of \$2,500 & \$9,000 respectively GILINSKY. V Commissioners 83/09/2/ AXELRAD, J Director's Dffice, Office of Inspection and Enforcement ip 20946 078
- B310190226 Ack receipt of \$9,600 in full payment of civil penalties proposed on B30901 AXELRAD.J A Enforcement Staff B3/10/13 TUFFIN.W B Nuclear Metals. Inc 2pp 20038 092
- DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, IN
- B310280321 Forwards info showing results of radiological geotechnical and the hydrological investigations per decommissioning design project to assess suitability of Pond 10 as evaporation pond Wome oversize map Aperture card in available in PDR MILLEL M Tennessee Valley Authority 83/09/06 SMITH, R D Uranium Recovery Field Office 24pp 20963 191
- --8310280322 "Design Notes for Special Decommissioning Aspects, Geotechnical Evaluation of Pond IO " * MacLaren Engineers, Inc. * Golder Associates 83/01/31 71pp 20963 217
- 8310240344 Forwards descriptions of two work activities planned to begin 831001 & to be completed before 831101. In support of Edgement U Mill decommissioning project Activities will be conducted within existing license conditions MILLS, L M Tennessee Valley Authority 83/09/21 SMITH, R D Uranium Recovery Field Office Spp 20918 351
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , DKLAHDMA CITY, DK
- 8310170678 Advises that no comments have been received on EIA re state authorization to develop & enforce environ stds Future Federal capital grant requests should be enforced Requests copy of FEG upon completion CURTIS, M Illinois, State of 83/09/02 PAGE, R G Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 2pp 20798 157
- 8310120310 Advises that M Krippel will replace SC Munson as health physicist at West Chicago facility SHELLEY, W J Kerr-McGee Corp 83/09/28 HIND. J Region 3, Office of Director ip 20701 010
- 8310120314 Responds to NRC B30831 ltr re violations noted in IE Insp Rept 40-2061/83-02 Actions to reduce Pb-212 concentrations undertaken Rescission of notice of violation requested DENNY.I L Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 83/09/30 KEPPLER.J 0 Region 3. Office of Director Hpp 83/09/30 20700 308

- 8310180392 Requests NRC written concurrence w/bursal of PCB contaminated soil in EPA approved PCB landfill Thorium-natural soil concentrations.PCB contaminated soil table encl.
 - BHELLEY,W J. Kerr-McGse Chemical Corp. (subs. of Kerr-McGee Corp.) 83/09/30 NIXON,W A. Uranium Fuel Licensing Branch. 3pp 20825-360
- 8310250662 Requests notice of violation contained in 1E Insp Rept 40-2061/83-02 be withdrawn SHELLEY.W J Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 83/09/30 NIXON.W A Uranium Fuel Licensing Branch ip 20908 109
- 8310310356 Ack roceipt of 830930 request that citations contained in notice of violation in IE Insp Rept 40-2061/83-02 be rescinded as inappropriate Pertinent air sampling data currently under review KEPPLER.J G Region 3. Office of Director B3/10/26 RAINEY,J L Kerr-McGee Chemica) Corp (subs of Kerr-McGee Corp) ip 20960 286
- --8310310342 Responds to NRC 830831 ltr re violations noted in IE Insp Rept 40-2041/83-02 on 830804 Citations re radiation surveys contained in notice of violation inappropriate & should be rescinded DENNY.1 L Rerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 83/09/30 KEPPLER.J G Region 3, Office of Director Spp 20740 286
- DOCKET 40-2259 PATHFINDER MINES CORP / RIVERTON, WY
- B310030205 Bubmits personnel overexposure rept for Jan-June 1983, per Amend 16 to Condition 25 of License SUA-672 Two individuals exceeded 15-uGi natural U/liter limit of urine action level * Pathfinder Mines Corp 83/08/30 Uranium Recovery Field Office 2pp 20602 398
- 8310280323 Forwards one oversize general land use map in response to NRC request Aperture card is available in PDR SMITH.P.J. Pathfinder Mines Corp. 83/09/15 WDDLSEY.R.T. Utanzum Recovery Field Office ip. 20944-361
- 8310260003 Forwards annual soil survey data not available when semiannual effluent montoring rept.dtd 830831, submitted for License BUA-672 HARDGROVE, T W Pathfinder Mines Corp 83/09/26 WDDLGEY, R T Uranium Recovery Field Office 1p 20928 048
- --8310260006 Boil samples from 830615, omitted from 830831 semiannual effluent monitoring rept
 * Pathfinder Mines Corp 83/09/26 4pp 20928 049
- DOCKET 40-3392 ALLIED CHEMICAL CURP , MORRIBTOWN, NJ
- 8310170623 Forwards amend to Allied Chemical License SUN-526, adving litense conditions to Jul 1982 renewal application CIPOLLA, A J Allied Chemical Corp 83/09/30 KOSLA, B Uranium Fuel Licensing Branch 2pp 20798-171
- ~~8310170633 Revised application for amend to License SUB~526, adding license conditions section * Allied Chemical Corp 83/09/30 29pp 20798 173
- DOCKET 40-3453 ATLAS MINERALS, INC., DENVER, CO.
- 8310190106 Responds to NRC 830825 ltr re violations noted in 1E insp of License SUA-917 on 830726-28 Corrective actions alpha survey meter properly calibr using correct probe area dimensions 8LUBACON, RE Atlas Minerals 83/09/23 BROWN, G.D. Region 4, Office of Director, 3pp. 20822 107
- 8310190017 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in If insp of License 8UA-917 BRDWN, O D NRC - No Detailed Affiliation Given 83/10/11 BLUBAUGH, R E Atlas Minerals ip 80023 134
- DOCKET 40-4492 FEDERAL AMERICAN PARTNERS, RIVERTON, WY
- 8310140299 Forwards supplementary info "Cleanup of Windblown Tailings Contamination to be Conducted W/Resouting of Willow Springs Draw Near Federal American Partners U Milling Facilities at West Gas Hills: HY "ANDRUB: N J American Nuclear Corp B3/08/22 GILLEN, D Uranium Recovery Field Office. 2pp 20794-084

- ---B310140297 Supplementary info "Cleanup of Windblown Tailings Contamination to be Conducted W/Rerouting of Willow Springs Draw Near Federal American Partners U Milling Facilities at West Gas Wills.WY " Wone oversize map Aperture card in PDR * American Nuclear Corp B3/08/12 Opp 20794 086
- DOCKET 40~4931 NAVY, DEPT OF, ANNAPOLIS, MD
- 8310210300 IE Insp Findings & Licensee Ack dtd 830923 of License SUD-564 Insp findings no noncompliance noted # Region 1, Office of Director 83/09/23 ip 20855 214
- DOCKET 40-6500 ENERGY, DEPT OF, CANONEBURG, PA
- 831007021i Discusses items of interest Meeting held on 830921 w/C-E in Windson.CT re C-E proposed license amend application to modify air sampling sys On 830915,NRC concurred in DOE remedial action plan for Canonsburg,PA site PAGE.R C Uranium Fuel Licensing Branch 83/09/22 DAVIS,J Q Office of Nuclear Material 8afety & Safeguards,Director ip 20679 353
- 8310110441 Summary of 830715 & 21 meetings w/DDE & C-E re remedial action plan & proposed license amend application concerning mod of air sampling sys in Windsor plants respectively PAGE.R G Uranium Fuel Licensing Branch 83709722 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 20714 341
- 8310180403 Summary of data from radon monitoring network in Canonsburg. PA area during 830428-0728 W/830730 ltr RUDY, C R Monsanto Research Corp 83/09/30 CROW.W T Uranium Fuel Licensing Branch 4pp 20825 335
- 8310210099 Summary of 831007 meetings w/DDE in Canonsburg,PA & Silver Spring,MD re remedial actions to be taken to stabilize radioactive matl on Canonsburg site & decontamination of Latty Avenue site & vicinity properties PAOE,R O Uranium Fuel Licensing Branch 83/10/12 DAVIS,J O Office of Nuclear Material Safety & Safeguards,Director ip 20883 315
- DOCKET 40-6622 PATHFINDER MINES CORP . SHIRLEY BASIN. WY
- 8310030224 "Environ Monitoring Data W/Dose Calculations, Second Quarter 1983 " W/830909 ltr 8MITH.J C Pathfinder Mines Corp 83/06/30 Uranium Recovery Field Office 30pp 20604 182
- 8308300607 Forwards "First Quarter 1983 Environ Monitoring Data w/Dose Calculations," per License Condition 37 Ingestion doses calculated for previous two quarters too large by factor of five SMITH.J C Pathfinder Mines Corp 83/07/08 BROWN.G D Region 4. Office of Director 1p 20208 166
- ---B308300610 "First Quarter 1983 Environ Monitoring Data w/Dose Calculations " * Pathfinder Mines Corp 83/07/08 26pp 20208 167
- 8310200456 Recommends License SUA-442 be amended by revising License Condition 36 to change frequency for exchanging & reading TLD chips from monthly to quarterly QARCIA.P J, PETTENGILL.H Uranium Recovery Field Office B3/0B/25 Uranium Recovery Field Office 2pp 20861 137
- B310200471 Advises of issuance of amend to License SUA-442 revising Condition 36 by changing frequency for exchanging & reading TLD chips used for radon monitoring from monthly to quarterly SMITH.R D Uranium Recovery Field Office 83/08/29 RUSSELL.J E Pathfinder Mines Corp 2pp 20844 348
- 8310250169 Requests answers to listed questions re Hinton & Whicker research paper "Field Experiment on Radon Flux From Reclaimed U Mill Tailings"
 BEACH, 0 Wyuming, State of 83/09/08 HINTON, T Pathfinder Mines Corp ip 20908 324
- DOCKET 40-6659 GETTY DIL CO PETROTOMICS CO. . SHIRLEY BASIN. WY
- 8310270545 Forwards rev to environ rept, 6td 810401, updating gamma, dust, radom & exposure data through 1982 & in some cases, through Aug 1983 PFAFF, 8 J Getty/Petrotomics Co 83/09/22 GARCIA, P Uranium Recovery Field Office App 20938 039

- B310030502 Forwards summary of data for leach area & dryer control room verification samples taken on B30517 No response required Variation in U content will be pursued w/technical staff EVERETIR J Region 4, Office of Director B3/09/26 WHITMAN, J H Oetty/Petrotomics Co 2pp 20601 167
- B31026034B Forwards application to amend License SUA-551, reflecting current conditions or practices or to correlate w/monitoring fraquency per Reg Guides B 30 & B 31 PFAFF.B J Cetty/Petrotomics Co B3/09/27 GARCIA.P Uranium Recovery Field Office ip 20928 083
- --83:0260352 Application for amend to License SUA-551, reflecting current conditions or practices or to correlate w/monitoring frequency per Reg Guides 8 20 t 8 31 s Getty/Fetrotomics Co 83/09/22 11pp 20928 084
- DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA
- 8310270576 Summarizes items of interest from DDE 831013 meeting.DQT 831014 meeting.Kerr-McGee 831019 meeting & Applied Health Physics.Inc 831048 meeting PAGE.R 0 Uramium Fuel Licensing Branch 83/10/20 DAVIS,J C Office of Nuclear Material Safety & Bafeguards.Director Ip
- DOCKET 40-7849 PLATEAU RESQUECES, LTD , GRAND JUNCTION, CD
- 8310070402 Application for amend to License SUA-1013 to estend expiration date to 840331 Time will allow completion of decommissioning, submission of final rept & NRC site insp to terminate license

 QERDEHAN.F W Plateau Resources, Ltd. 83/09/02 SHITH.R N NRC No Detailed Affiliation Given ip 20464 272
- 8310200371 Advises of Issuance of Amend 4 to License SUA-1013, revising Condition 4 to extend expiration date to 840630 SHITH.R D Uranium Recovery Field Office 83/09/30 Plateau Resources, Ltd Jp 20874 070
- --8310200373 Safety evaluation supporting Amend 4 to License SUA-1013 HAWKINS.E F. LINEHAN.J Uranium Recovery Field Office 83/09/30 2pp 20874 071
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP . OKLAHDMA CITY, DK
- 8310190038 Forwards State of TX statutes & regulations defining "source matl," "byproduct matl" & "raduaste," NRC regulations defining "byproduct matl" & "source matl" & itr from TX Dept of Health to Kerr-McGee HOFFMAN.8 Kerr-McGee Corp 83/09/20 CUNNINGHAM.8 Division of Fuel Cycle & Material Safety 10pp 20838 074
- 8310070034 Advises of issuence of Amend 23 to License SUB-1010, in response to 830621 request to exempt treated raffinate storage ponds from spare pand requirements PAGE.R 0 Uranium Fuel Licensing Branch 83/09/28 SHELLEY, H J Kerr-HcGee Corp Ip 20671 358
- ---8310070037 Safety evaluation supporting Amend 23 to License SUB-1010.

 per B30621 request for continuation to 840701 of exemption
 from spare ponding requirements

 KOSLA, B.M. CROW, W.T. Uranius Fuel Licensing Branch 83/09/27
 2pp 20671 359
- 310270576 Summarizes items of interest from DOE 831013 meeting. DDT 831014 meeting. Kerr-McGee 831018 meeting & Applied Health Physics. Inc 831018 meeting Physics. Inc 831018 meeting Branch 83/10/20 DAVIS. J 9 Defice of Nuclear Material Safety & Safeguards. Director 19
- ICKET 40-8035 COTTER CORP ROSWELL, NM
- 10210099 Summary of 831007 mertings w/DDE in Canonsburg.PA & Silver Spring.HD re remedial actions to be taken to stabilize radioactive math on Canonsburg site & decontamination of Latty Avenue site & vicinity properties
 PADS.R O Uranium Fuel Licensing Spanch 83/10/12 DAVIS.J © Office of Nuclear Haterial Safety & Safeguards.Director lp 20883 315

- DOCKET 40-8064 EXXON MINERALS CO , USA, HOUSTON, TX
- 8310260357 Forwards estimated reclamation bond approved by WY Dept of Environ Quality for Exxon Highland U operation re Licenses SUA-1139 & SUA-1064 Bond estimate revised annually to reflect current land status & reclamation plans SHANNON, J.B. Exxon Corp. 83/08/31 SMIYH.R.D. Uranium Recovery Field Office. 3pp. 20918 298
- DOCKET 40-8084 RID ALGOM CORP . MDAB, UT
- 8310310375 Forwards IE Insp Rept 40-9084/83-01 on 830523-26 No noncompliance noted BROWN G D Region 4. Office of Director 83/07/19 LAHTON M D Rio Algom, Ltd 2pp 20940 002
- ---8310310380 IE Insp Rept 40-8084/83-01 on 830523-24 No noncompliance noted Major areas inspected U milling operations & radiation safety program including organization mpt & training & internal exposure & contamination control SHOPENN.N M , EVERETT.R J Region 4. Office of Director 83/07/07 7pp 20940 004
- 8310060502 Forwards one oversize revised land use survey map.indicating changes in Township 29 South Range 24 East since 830215
 Aperture card is available in PDR
 PATTISON.R S Rio Algom. Ltd 83/09/12 SNITH,R D NRC ~ Nu
 Detailed Affiliation Given 1p 20644 145
- DOCKET 40-8102 EXXON CO . USA, HOUSTON, TX
- 8310260357 Forwards estimated reclamation bond approved by WY Dept of Environ Quality for Erxon Highland U operation re Licenses SUA-1139 & SUA-1064 Bond estimate revised annually to reflect current land status & reclamation plans SHANNON, J B. Exxon Corp. 83/08/31 SMITH.R D. Uranium Recovery Field Office. 3pp. 20918 298
- 8310200349 Recommends administrative changes to License SUA-1139 re deletion of License Conditions 36 & 37 & rev of License Condition 35, per Low Level Waste Licensing Branch summary of environ monitoring data PANGBURN, 0 C Uranium Recovery Field Office 83/09/20 Uranium Recovery Field Office 2pp 20874 270
- 8310200412 Supports amend to License SUA-1139 deleting reporting requirements under 40CFR190 Changes constitute Amend 5 to license Amend initiated by NRC for benefit of Commission & 1s exempt from fees
 PANGBURN.G C Uranium Recovery Field Office 83/09/28 MILLER, W ()
 License Fee Management Branch 1p 20844 360
- 8310240092 Advises of issuance of amend to License SUA-1139 deleting Conditions 36 & 37 & revising Condition 35 re environ & effluent monitoring procedures SMITH.R D. Uranium Recovery Field Office 83/09/28 Exxon Corp ip 20903 197
- DOCKET 40-8348 MINERALS EXPLORATION CO . LOS ANGELES, CA
- B3101B0125 Advises that licensee intends to continue monitoring A-3 project site Sampling of well's will begin on 830926 VDLK.N & Union Dil Co. of Colifornia B3/09/19 WASTLER.S Uranium Recovery Field Office 1p 20827 095
- DOCKET 40-8380 ROCKY MOUNTAIN CHERGY CO . BROOMFIELD, CO
- 8310040601 Confirms 8309;3 telcon re draft review of licensee groundwater restoration repts for acid lixaviant test patterns at Nine Mile Lake facility Evaluation of potential environ impacts recommended BROWN. M L. Region 4, Office of Director 83/09/15 LINEHAN, J J NRC No Detailed Affiliation Given 1p 20627 349
- DOCKET 40-8452 BEAR CREEK URANIUM CO . CASPER. WY
- B310030199 "Semiannual Environ Monitoring Rept.Jan-June 1983 " W/B30B30 ltr BLDSSGM.J N Bear Creek Uranium Co B3/06/30 Uranium Recovery Fjeld Office 17pp 20603 131

- B310030241 Forwards tailings dam erosion analysis (App K to Nov 1981 tailings mgt plan), per Amend 20 to Condition 39 of License SUA-1310 Reduction of dam slope not necessary to meet goal of long-term erosion protection

 MEDLOCK.R L Bear Creek Vinanium to B3/09/08 SMITH, R D Vianium Recovery Field Office 2pp 20604 151
- --8310030250 "Bear Creek U Co Tailings Dam Erosion Analysis (App K to Nuv 1981 Tailings Mgt Plan) " * Bear Creek Uranium Co 83/09/30 29pp 20604 153
- 8310200419 Advises of issuance of Amend 21 to License SUA-1310 re expansion of present tailings disposal area SMITH,R D. Ulanium Recovery Field Office 83/09/30 Bear Creek Uranium Co. 4pp. 20844 396
- 8310240094 Advises of issuance of amend to License SUA-1310.revising Condition 51 by deleting previous language barring const of expanded disposal area until NRC authorization given & adding Subparagraphs e-i to license PANOBURN, 6 C. PETTENSILL, H.J. Uranium Recovery Field Office 83/09/30 Uranium Recovery Field Office 7pp 20903 190
- DUCKET 40 8502 WYOMING MINERAL CORP , LAKEWOOD, CO
- 8310040605 Requests current form for application for permit to mine an amend to permit to mine Form needed to incorporate 800718 application for in situ R&D license w/820201 rev to application to mine,per 630802 request RUTLEDGE, C. Wyoming Mineral Corp. 83/09/08 CHANCELLOR, R. A. Wyoming, State of 1p. 20627 350
- 6310210102 Forwards application for renewal of Source Matl License SUA-1341 RUTLEDGE.C Wyoming Mineral Corp 83/09/28 Division of Fuel Cycle & Material Bafety 2pp 20883 273
- --8310210107 Application for renewal of Source Matllicense SUA-1341 RUTLEDGE,C Wyoming Mineral Corp 83/09/26 40pp 20883 275
- DOCKET 40-8584 MINERALS EXPLORATION CO . LOB ANGELES, CA
- 8310030221 Forwards summary of environ monitoring & meteorological conditions.per Section 5 & Conditions 34.43 & 48 of License SUA-1350 Environ monitoring will be modified by Amend 12 to reflect suspension of milling operations KLEIN-T J Union 76 Minerals Exploration Co 83/08/31 9NITH,R D Uranium Recovery Field Office 78pp 20604 0/3
- 8310030203 Forwards "Rept of Engineering Assessment Present Pond Liner Bys Tailings Impoundment, Sweetwater U Project Near Rawlins, WY for Minerals Exploration Co" & "Tailings Impoundment Leak Analysis" KLEIN.T J Union 76 Minerals Exploration Co 83/09/07 SHITH, R D Uranium Recovery Field Office 2pp 20603 078
- --8310030210 "Rept of Engineering Assessment, Present Pond Liner Sys Tailings Impoundment, Sweetwater U Project Near Rawlins, WY for Minerals Exploration Co " BDDDY, J R Union 76 Minerals Exploration Co 83/07/29 19pp 20603 080
- --8310030215 "Failings Impoundment Leak Analysis " * Water, Waste & Land, Inc 83/09/30 32pp 20603 099
- 8310200446 Discusses Amend 12 to Source Matl License SUA-1350 to reduce or suspend certain environ & in-plant monitoring requirements during period of shutdown & reduction in monitoring programs GARCIA, P. J., PETTENGILL, H. J. Uranium Recovery Field Office 83/09/22 Uranium Recovery Field Office 5pp 20859 334
- 8310200438 Advises of amend to License SUA-1350 adding Condition 53 re reducing or suspending air particulate sample requirements during period of suspended operations at Sweetwater M111 SMITH:R D. Uranium Recovery Field Office 83/09/23 HILL.C 7 Minerals Exploration Co (subs of Union Oil Co of Ca)ifornia) 2pp 20859 332
- 8310240045 Submits const analysis of single vs double liner leak detection sys at U Mill Tailings Pond TFR 1 5/294,pet 830510 meeting w/NRC & Minerals Exploration Co LIDSTOR; C Wyoming State of 83/09/23 BEACH.© Wyoming, State of 4pp 20903 230

- DOCKET 40-8599 AIR FORCE, DEPT OF, BROOKS AFB, TX
- 8310270417 Responds to NRC 830913 ltr re special safety insp of license SMB-1314 Maint work scheduled to prevent further leakage into process sewer sys at Weldon Spring Chemical Plant REGISTER, B F Army, Dept of 83/10/18 Region 3, Office of Director 3pp 20923 082
- DOCKET 40-8674 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 8310180133 Effluent manitoring rept for Jan-June 1983 H/830826 1tr QERDEMAN.F W Plateau Resources, Ltd 83/06/30 Region 4, Office of Director 10pp 20827 067
- 8310200452 Recommends changes to License Conditions 10 & 19 to License SUA-1326 re organizational changes for Ore Buying Station JOHNSON T L , LINEHAN, J J Uranium Recovery Field Office 83/08/25 Uranium Recovery Field Office 3pp 20861 134
- B310200470 Advises of issuance of amend to License SUA-1026, revising Conditions 10 & 19 re occupational radiation safety program & ALARA program: respectively SMITHARD Uranium Recovery Field Office B3/0B/25 Plateau Resources, Ltd 2pp 20844 350
- DOCKET 40-8681 ENERGY FUELS NUCLEAR. INC., DENVER, CO
- 8310240090 Advises of issuance of amend to License 8UA-135B adding Condition 27 to establish revised tailings reclamation plan & setting requirements for rev to reclamation configuration as tailings disposal increases SMITH.R D Uranium Recovery Field Office 83/09/12 Energy Fuels Nuclear, Inc. 2pp. 20903 178
- --8310240095 Discusses vender 830521 request for Amend 22 to License SUA-1358 amending requirements re tailings reclamation cover License Condition 27 should be revised GILLEN,D M. LINEHAN, J. Uranium Recovery Field Office 83/09/12 Uranium Recovery Field Office 3pp 20903 200
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO , DENVER, CO
- 8310200342 Application for extension of License SUA-1338 to authorize final site-closure activities
 NEUMANN,M R Rocky Mountain Energy Co 83/08/30 LINEHAN, J
 Uranium Recovery Field Office 1p 20874 069
- DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 8310180104 Effluent monitoring rept for Jan-June 1983 W/830826 ltr GERDEMAN,F W Plateau Resources, Ltd 83/06/30 Region 4, Office of Director 52pp 2083 306
- 8310180384 Submits review of licensee environ monitoring repts for 1982 Licensee has met all license requirements for interim period prior to plant operation but failed to provide chemical parameter data for groundwater samples JOHNSON, T.L. Uranium Recovery Field Office 89/07/25 Uranium Recovery Field Office 9pp 20827 001
- B310180127 Addendum to effluent monitoring rept for 1982 W/B30902 1tr GERDEMAN,F W Plateau Resources, Ltd 83/08/30 BMITH,R D Uranium Recovery Field Office 15pp 20827 080
- 8310270519 Advises that License SUA-1371 amended by modifying Conditions 38 & 39, approving revised reclamation plan & deleting requirement for submittat of revised surety instrument SMITH, R D Uranium Recovery Field Office 93/09/27 Plateau Resources, Ltd 3pp 20937 206
- --B310270524 Discusses vendor B30412 & 0620 requests for Amend 8 to License SUA-1371, requesting changes to axisting reclamation plan & decreasing amount of surety Rev to License Conditions 38 & 39 recommended JOHNSON, J L. LINEHAN, J J Uranium Recovery Field Office 83/09/27 Uranium Recovery Field Office 5pp 20937 209

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO . CLEVELAND. OH

8310240052 Submits info to document use of best practicable technology to restore groundwater quality at Collins Draw Project LOUDERBACK, T.E. Cleveland-Cliffs Iron Co. 83/09/23 SHAFFER, R. Wyoming, State of 15pp 20903 216

DOCKET 40-8745 OGLE PETROLEUM, INC., CASFER, MY

8310180172 "Fourth Semiannual Rept.830219-0826" W/830916 ltr CATCHPOLE.G J Ogie Petroleum, Inc. 83/08/26 SMITH, D Recovery Field Office 152pp 20824 t30 Urabium

DOCKET 40-8769 KERR-MOGEE NUCLEAR CORP , DKLAHOMA CITY, DK

831018013B Recommends that R&D license for "D" Sand Project not be issued Results of second pump test, baseline water quality & admitor well water quality cost be received before license can be issued OGLE: X M En

OGLE: X M Energy, Dept of 83/09/16 20827 059 Energy, Dept of Spp

83102±0377 Forwards responses to MY Dept of Environ Quality 830526 corports & questions re Q-Sand ISL project.per D Gillen

request
FREEMAN, H.D. Kerr-McGee Nuclear Corp. 83/10/03
Uranium Recovery Field Office 26pp. 20921 194 83/10/03 LINEHAN. J J

8310260411 Application for amend to License SUA-ISB7 increasing total dissolved solids & sulfate levels for monitor uell GMH-1 Table confirming increased levels due to natural groundwater quality fluctuations & license amend fee encl FREEMAN.M Kerr-McGee Nuclear Corp 83/10/05 LINEHAN.J.J Uranium Recovery Field Office 10pp 20918-335

DOCKET 40-8781 TETOM EXPLORATION DRILLING CO., INC., CASPER, WY

9310270141 Forwards Source Matl License 5UA-1403 SMITH.R D. Uranius Recovery Field Office 83/09/30 APPEL,R Teton Exploration Drilling Co., Inc. 1pp. 20939 108

-8310270157 Source Matl License SUA-1403 for UNC Teton Exploration Drilling, Inc authorizing U recovery & processing & const of evaporation pond areas • Uranium Retovery Field Office 83/07/30 lipp 20939 109

DOCKET 40-8783 URANERZ USA INC . CASPER. HY

8310260414 Forwards application for amend to License SUA-1401 proposing reduced well number for stabilisation monitoring period Approval requested prior to start of restoration phase of Ruth ISL R&D project SCHERVILLE, & G. Uraneri USA. Inc. 83/09/29 LINEHAN, J.J. Uranium Recovery Field Office. 1p. 20928-073

-83102±0*18 Application for amend to License 5UA-1401.proposing reduced well number for stabilization monitoring period
* Uraner: USA, Inc. 83/09/29 8pp. 20928-074

DOCKET 40-8/86 URANIUM RESOURCES, INC., RICHARDSON, TX

B310030559 Comments on MS Pelizza B30B0B ltr re addit decommissioning plans for License | JORD Sand & sludge removal from evaporation ponds recommended RANCEN.L D. SMITH.M A Myoming. State of 83/09/12 LINEMAN.J. Uranium Recovery Field Office | Ip 20607 361 U. U. NAHANIJ S1160/EB

33(0210123 Forwards gamma survey for North Platte well field & documents commitment to maintain at least 6 inches of water in two solar evaporation ponds or removal of all sand & sludge within pond PELIZZA, M.S. Uranium Resources, Inc. 63/09/22 JDHNSON, T. NRC - No. Detailed Affiliation Given 2pp. 20883-329

DOCKET 40-8794 MOLYCORP, INC . LOS ANGELES. CA

B3100700B7 Forwards amend fee in response to B30726 approval of B30706 proposal to discontinue personal desimetry badga program DOUGLASS.S J. Molycorp. Inc. B3/0B/02 WEISS.D. License Fee Management Branch 1p 20681 024

--B310070090 Requests payment of fee for review of 820706 request for amend to License SNB-1408 WEISS, D. License Fee Management Branch 83/07/26 DOUGLASING J. Malycarp, Inc. 1p. 20481 (425

--8310070092 Application for amend to License SNB-1400, deleting dosims program Dosimetry badge results & radiation monitoling repts Program bostnery dauge resisted a journality montenancy for 1983 ent1
DOUGLASS, S. J. Molycorp, Inc. 83/07/06 SDDNG, A.L. NRC Nu
Detailed Affiliation Given 17pp 20681 026

8310050177 Issues Amend 3 to License SMR-1408 authorizing discontinuation of personnel dosimater monitoring program at York facility Safety evaluation encl PAGE.R G Uranium Fuel Litensing Branch 83/09/21 WARNID, W M Malycorp, Inc. 1p. 20639-359

--8310050181 Safety evaluation supporting Amend 3 to License (MNR-1400) S00NG.A L - Uranium Fuel Licensing Branch - 83/09/20 - 2pp

DOCKET 40-8801 RADIATION MANAGEMENT CORP , NORTHBROOK, II

8310170308 Summarizes 830830 visit to West Lake Landfill Site in St Louis,MO Second visit expected on 830921 to obtain info on landfill from MO Dept of Natural Resources & City of Bridgeton Files O'CONNOR J T , BANER JI, S K Missours, Univ of, Columbia, MD B3/09/19 WYNGARDEN, S NRC - No Detailed Affiliation Given BERGER, J Oak Ridge Associated Univ 4pp 20796-129

B310200409 Requests permission to perform radioactivity measurements soil surface & water in West Lake landfill area to confirm Radiation Mgt Corp study BANERJI.S K. D'CONNOR.J T. Missouri. Univ. of. Columbia, Mg. B3/09/29 WYNGARDEN.S. NRC - No Detailed Affiliation Given. 1p. 20859 218

DOCKET 40-8807 AIR FORCE, DEPT OF, TINKER AFB. OK

8310030400 IE Insp Findings & Licensee Ack dtd 830824 of License STB-1407 Insp findings no violations observed HOCKER.C A Region 4. Office of Director 83/08/24 ip

DOCKET 40-8829 WYDMING FUEL CO . LAKEWOOD, CO

8310260373 Forwards State of NE Game & Parks Commission & NL State Historical Society re impact of Crowe Butte project on cultural resources & endangered species, per J Linchan 630/06 STOUT D.M. Myoming Fuel Co. 83/10/06 WASTLER, S. Utanium Rectives Field Office. 3pp. 20918-356

DOCKET 40-8839 SANTA FE MINING, INC , ALBUQUERQUE, NM

8310180136 Advises that as result of 830914 meeting & addl review of Neuman-Hitherspoon theory, adjustment of proposed pump test made MOFFMAN, G. L. Hydro-Engineering 83/09/21 LINEHAN, J. NR(- No Detailed Affiliation Given WILLIAMS, R. R. C. Williams & Assoriation Inc. BOXICH, J. Santa Fe Engineers, Inc. 3pp. 20827-064

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR F Security, medical, emergency & fire protection plans

8310210124 Forwards Amend 28 to License R-79 re updates to physical security plan Changes meet requirements of 100FR/3 6/
THOMAS, C D Standardization & Special Projects Branch 82/10/1/
KERR, W F Michigan, Univ of, Ann Arbor, MI 3pp 20883 316 ;
Fiche 50-002,83/10/17,8310210124

--B310210132 Amend 28 to License R-79, incorporating latest requirements for updated physical security plan
THOMAS,C O Standardization & Special Projects Branch 83/10/17
Rpp 20883 319 24% Fiche 50-002,83/10/17.8310210124

- P Operating license stage documents & coirespondence
- 8310210124 Forwards Amend 28 to License R-79 re updates to physical security plan Changes meet requirements of 10GFR73 67 THOMAS, C O Standardization & Special Projects Branch 83/10/17 KERR, W F Michigan, Univ of Ann Arber, MI 3pp 20883 316 24 Fiche 50-002, 83/10/17,8310210126
- --8310210132 Amend 28 to License R-79, incorporating latest requirements for updated physical security plan
 THOMAS, C O Standardization & Special Projects Branch 83/10/17
 2pp 20883 319 24% Fiche 30-002,03/10/17,8310210124
- DOCKET 50-3 INDIAN POINT STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310050548 Forwards post-exercise/post-drill assessments.per JS Bragg 830608 commitment Previously noted deficiencies corrected MCLDUGHLIN.D Federal Emergency Management Agency 83/09/29 DIRCKS WJ Office of the Executive Director for Operations 2pp 20629 267 24% Fiche 50-003,83/09/29.8310050548
- --8310050552 Post-exercise assessment of 830824-25 exercise.Rockland County.for Indian Point Nuclear Power Station * Faderal Emergancy Management Agency 83/09/26 56pp 20629 269 24X Fithe 50-003,83/09/29,B310050348
- --8310050554 Post-drill assessment of 830823 drill of Westchester County bus evacuation procedures for Indian Point Nuclear Power Station
 * Federal Emergency Management Agency 83/07/15 7pp 20629 328 24X Fiche 50-003.83/07/27.831005054B
- 8310130111 Forwards application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/07/29 VARGA, S A Operating Reactors Branch 1 2pp 20726 274 24X Fiche 50-003,83/09/29,8310130111
- --8310130115 Application for amend to Licenses DPR-5 & DPR-24 incorporating changes to facility organization structure reposition of fire protection & safety administrator O'TODE.J D Consolidated Edison Co of New York, Inc. 83/09/29 2pp 20726 296 24X Fiche 50-003,83/09/29,8310130111
- --8310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator * Consolidated Edison Co. of New York, Inc. 83/09/29 10pp 20726 298 24X Firhe 50-003.83/09/29.8310130111
- 8310240304 Forwards mods to physical security plan.per 821109 request Mods withheld (ref 10CFR2 790 & 10CFR73 21) O'TDOLE.J D Consolidated Edison Co of New York, Inc. 83/10/14 VAROA.S A Operating Reactors Branch 1 2pp 20910 324 24X Fiche 50-003.83/10/14.8310240304
- VARGA: S A Operating Reactors Branch 1 2pp 20710 324 24X Fiche 50-003,83/10/14,8310260304
- B310280253 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records B3/10/25 Document Management Branch 1p 20962 318 24X Fiche 50-003,83/10/25. B310280253
- --8310280261 Forwards public version of revised emergency plan implementing procedures.including Procedures IP-1002 re emergency notification & communication & IP-1023 re operational support ctr
 0'TOULE, J D , GAUNY, R D Consolidated Edison Co of New York, Inc 83/05/04 ALLAN, J M Region 1, Office of Director 3pp 20962 319 24X Fiche 50-003,83/10/25.8310280253
- --8310280267 Public version of revised emergency plan implementing procedures, including Procedures IP-1002 re emergency notification & communication & IP-1003 re operational support ctr

 * Consolidated Edison Co of New York, Inc 83/05/02 56pp 20962 322 24X Fiche 50-003,83/10/25,8310280253
- P Operating license stage documents & correspondence
- B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L. Affiliation Unknown B3/05/02 NRC No Detailed Affiliation Given. 1p 21004 270 24X Fiche 50-000, B3/05/02, B31031017

- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON.J M Division of Rules and Records 83/07/06 CONNER.L Affiliation Unknown Ip 21004 271 24% Fichs 50-000,83/07/06,8310310031
- 8310130111 Forwards application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator O'TODLELJ D Consolidated Edison Co of New York, Inc 63/09/29 VARGA, S.A. Operating Reactors Branch I 2pp 20724 294 24X Fiche 50-003,63/09/29,6310130111
- ~-8310130115 Application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator O'TOOLE-J D Consolidated Edison Co of New York, Inc 89/09/29 2pp 20726 294 .24X Fiche 50~003,83/09/29,8310130111
- ~~8310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator * Consolidated Edison Co. of New York, Inc. 83/09/29 10pp 20726 298 24x Fiche 50-003,83/09/29,8310130111
- G Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wolder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fache 50-000 03/09/26,0308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Int 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342
- 8308300345 lE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 20777 350 24% Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29.8308300349
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Properadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 800103) 83/10/07 Consolidated Edison Co of New York: Inc 79pp 20882 026 24% Ficho 50-000, 83/10/07. 8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 837/10/11 Congalidated Edison Co of New York Inc. 117pp 21043-075 24X Fiche 50-000.83/10/11,8308300759
- 8308300761 1E Info Notice 83-68, "Respirator User Warning, Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enci JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fichs 50-000,83/10/11,8308300761.
- T Hearing transcripts on non-antitrust matters
- 8310120027 Transcript of B31003 open session in Washington.DC re emergency planning Pp 1-28 Supporting documentation encl * Commissioners 83/10/03 111pp 20750 07A 24X Fiche 50-003.83/10/03.8310120027

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

- O Inspection reports. IE Bulletins & correspondence
- B3101803B2 Forwards IE Mgt Heeting Rept 50-005/B3-58 on 830B12 STAROSTECKI.R Region 1. Office of Director B3/10/03 LEVINE, S Pennsylvania State Univ. University Park. PA 2pp 20803 203 P4) Fithe 50-005.83/10/03.83101803B2
- --8310180384 IE Mgt Meeting Rept 50-005/83-58 on 830812 Major areas discussed inpact of decentralization of operator lizensing FERLIC.K , KELLER.R Region I. Office of Director 83/09/26 2pp 20803 205 24X Fiche 50-005.83/10/03,8310180382
- DOCKET 50-10 DRESDEN MUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8310040121 Releases public version of revised emergency plan implementing procedure PELTON.J H Division of Rules and Records 83/09/22 Document Management Branch 1p 20634 341 24X Fiche 50-010.83/09/22.8310040121
- --8310040136 Public version of Rev O to Emergency Plan Implementing Procedure EPIP 300-16. "Radiation Surveys Under Accident Conditions" W/830913 ltr.receipt form.procedure history & safety evaluation
 SCOTT.D J Commonwealth Edison Co 83/09/09 10pp 20634 342 24% Fiche 50-010.63/09/22.8310040121
- 8310270009 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20940 167 24X Fichs 50-010,83/10/21, 8310270009
- --8310270017 Public version of Rev 5 to Emergency Plan Implementing Procedure EP1P 300-1. "Initial Notifications & Generating Station Emergency Plan Responses (Primary Responsibility Station Director) " #/833014 ltr SCOTT.D J Commonwealth Edison Co 83/10/03 DENION, H R Office of Nuclear Reactor Regulation, Director 20pp 20940 168 24X Fiche 50-010,83/10/21.8310270009
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON.JM Division of Rules and Records 83/10/21 Document Management Dranch ip 20937 216 24X Fiche 50-000.83/10/21.
 - 33i0270837 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6, "Administration & Englistics Manager" H/83i017 ltr & receipt form NELL19.C A , HESSNER.R , MODRE.R D Commonwealth Edison Co 83/02/18 DENTON H R NRC No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000.83/10/21.83i0270526
 - 10280307 Releases public version of revised generating stations emergency plan telephone directory FELTON. J M Division of Rules and Records 83/10/25 Document Hanagement Branch 1p 20763 126 24% Fiche 50-000.63/10/25.
- --8310280314 Public version of revised generating stations emergency plan telephone directory GALLE, D.P. MODRER D. Commonwealth Edison Co. 83/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 64pp 20963
- 8310280191 Releases public version of revised emergency plan implementing procedura FELTON J M Division of Rules and Records 83/10/26 Document Hanagement Branch 1p 20962 266 24X Fiche 50-600.83/10/26. 8310280191
- ~~8310280209 Public version of Rev I to Emergency Plan Implementing Procedure EGF-15, "Emergency Operations Facility Activation" HODRE, R.D. Commonwealth Edison Co. 83/08/02 50pp. 20962 267 24X Fiche 50-000, 83/10/26, 8310280191

G Adjudicatory correspondence

- 8310070156 Forwards Director's Dacision 83-14 denying 830909 10cl82 P06 petition re transport of spent nuclear fuel from West Valley DAVIS.J 6 Office of Nuclear Material Bafety & Safeguards Director 83/09/30 CELEBREZZE.A J Ohio, State of 2pp 20680 308 24X Fiche 50-000,83/09/30,8310070156
- --8310070161 Forwards Director's Decision 83-14.denying 830824 1001R2 \$101 petition re transport of sprnt nuclear fuel from Wast Valley DAVIS.J G Office of Nuclear Material Safety & Safeguards.Director 83/09/30 RESNIKOFFIM Sierra Club Ip 20680 309 24X Fiche 50-006.83/09/30.6310070156
- --0310070167 Notice of issuance of Director's Decision 83-14 denying State of OH & Sierra Club 830709 & 0824, respectively, iOCFR2 206 petitions re-transport of spent nuclear fuel from West Valley DAVIS.J G Office of Nuclear Material Safety & Safeguards. Director 83/07/30 2pp 20680 310 24X Fiche 50-000.83/07/30,8310070156
- --8310070171 Director's Decision 83-14, denying State of OH & Sierra Club B30909 & 0824, respectively, IOCFR2 204 petitions re transport of spent nuclear fuel from West Valley Request for hearing & for preparation of E13 denies of DAVIS, J 9 Office of Nuclear Material Safety & Safeguards, Director 83/09/30 18pp 20480 312 24X Fiche 50-000. B3/09/30, B310070154
- B310270297 Order extending time until B31128 for Commission to art to review Director's Decision DD-83-14. denying Sterra Club & State of OH requests
 CHILK: S. J. Office of the Secretary of the Commission B3/10/25 Commissioners ip 20923 195 24X Fiche 50-000, B3/10/25, B310270297

J Insurance & indemnity information

- 8310240071 Forwards Endorsements 149 & 150 to NELIA Policy NF-43 & Endorsements 126 & 127 to MAELU Policy MF-22
 OSTER.J Commonwealth Edison Co 83/10/13 SALTZMAN.J Assistment Director for State & Licensee Relations 5pp 20881 335 24X
 Fiche 50-010-83/10/13.8310240071
- P Operating license stage documents & correspondence
- 8310070020 Ack receipt of 830824 itr requesting Commission publish notice of pending license amend in FR re New York State Energy R&D Authority license for utils w/irradiated fuel storage facilities
 DAVIS.J G Office of Nuclear Material Safety & Safeguards, Dilictor, 83/09/22 RESNIKOFF.M Sieria Club ip 20671 361 24%
 Fiche 50-000.83/09/22.8310070020
- --B310070025 Notice of issuance of Sierra Club request that Commission take action to amend New York State Energy R&D Authority license for utils w/irradiated fuel storage facilities DAVIS.J G Office of Nuclear Material Safety & Safeguards. Director 83/09/22 ip 20671 362 24X Fiche 50-000.83/09/22.8310070020
- 8310260301 Forwards add1 info requested in NRC 830316 ltr re util response to SEP Topic III-4 A. "Tornado Missiles " Cooling water to HXs is supplied from svc water sys which is independent from condensate storage tank RYBAK. 8 Commonwealth Edison Co 83/10/18 OILBERT.R Operating Reactors Branch 5 18pp 20912 206 24X Fiche 50-010,83/10/18, 831092000
- 8310280147 Forwards 830930 Director's Decision 83-14 denying State of OH & Sierra Club 10CFR2 206 petitions re transportation of spent fuel from West Valley facility, per 830930 request CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 83/10/10 MILLER.F Environmental Policy Institute 2pp 20961 329 24X Fiche 50-000, 83/10/18.8310280147
- G Inspection reports, IE Bulletins & correspondence
- B30B300340 IE info Notice B3-6i, "Alleged Use of Stand-Ins for Wolder Gualification Tests " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000, B3/09/26, B30B300340

- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 114pp 20777 210 24X Fiche 50-000 83/09/26 8308300342
- 8308300345 lE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20777 350 24X Fiche 50-000,83/09/26,8308300345
- B30B300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83209/29 Consolidated Edison Co of New York, Inc. 118pp 20716 324 24X Fiche 50-000.83709/29,8308300349
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18,50-237/83-27,50-249/83-25,50-284/83-27,50-265/83-26,50-295/83-19,50-304/83-20,50-373/83-38,50-345/83-38,50-454/83-44,50-455/83-33,50-486/83-14 & 50-457/83-13
 NORELIUS, C E Division of Project & Resident Programs 83/10/04
 REED, C Commonwealth Edison Co 2pp 20834 098 24X
 Fiche 50-000,83/10/04.8310200124
- --831020014B IE Mgt Meeting Repts 50-020/B3-1B, 50-237/B3-27, 50-249/B3-25, 50-254/B3-27, 50-245/B3-26, 50-295/B3-1B, 50-304/B3-20, 50-373/B3-38, 50-374/B3-38, 50-454/B3-44, 50-455/B3-33, 50-456/B3-14 & 50-457/B3-13

 NORCLIUS, C E Division of Project & Resident Programs DAVIS, A B Region 3, Office of Director B3/10/03 App 20B34 100 24X Fiche 50-000, 83/10/04, 8310200124
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JURDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 830B300752 IE Info Notice 83-46, "Fatality at Argentine Critical Facility " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000, B3/10/07, B30B300752
- 8310210053 Forwards IE Insp Repts 50-010/83-17.50-237/83-26 & 50-249/83-24 on 830829-31.0901.02 & 08 & notice of violation PAPERIELLO,C J Region 3. Office of Director 83/10/07 REED,C Commonwealth Edison Co 2pp 20855 286 24% Fiche 50-010.83/10/07.8310210083
- --8310210061 Notice of violation from insp on 830827-31,0901,02 & 08 PAPERIELLO,C J Region 3. Office of Director 83/10/07 2pp 20855 288 24X Fiche 50-010,83/10/07.8310210053
- --8310210074 IE Insp Repts 50-010/83-17,50-237/83-26 & 50-249/83-24 on 830829-31,0701,02 & 08 Noncompliance noted inadequate calibr of D-1 & D-2/3 chimney monitors & failure to follow procedures re radiation protection PAUL, R A, HUETER, L J, GREGER, L R Region 3, Office of Director 83/10/07 8pp 20855 290 24X Fiche 50-010,83/10/07,8310210053
- 8308300757 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Pases "Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68; "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" 8vc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 127 24X Fiche 50-000.83/10/11.8308300761
- 8310140036 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-09, 50-237/83-14 & 50-249/83-13

 NORELIUS, C Division of Project & Resident Programs 83/10/11

 REED. C Commonwealth Edison Co ip 20767 341 24X

 Fiche 50-010,83/10/11,8310140036
- ---B310140047 Responds to NRC B30823 Itr re violations noted in IE Insp Repts 50-010/B3-09.50-237/B3-14 & 50-249/B3-13 Corrective actions operations personnel closed & latched ell bettery charger cabinets FARRAR.D L. Commonwealth Edison Co B3/09/22 KEPPLER, J 9 Region 3. Office of Director 5pp 20767 342 24X Fichs 50-010.B3/10/ii.B310140036

- 8310140099 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-12, 30-237/83-20 & 50-249/83-18

 NORELIUS, C E Division of Project & Resident Programs 83/10/11

 REED. C Commonwealth Edison Co 1p 20766 099 24X

 Fiche 50-010,83/10/11,8310140099
- --B310140104 Responds to NRC 830721 ltr re violations noted in IE Insp Repts 50-010/83-12.50-237/83-20 & 50-249/83-18 Corrective actions scope & general method of training program completely detailed in training procedures FARRAR, D. Commonwealth Edison Co 83/09/16 KEPPLER, J O. Region 3, Office of Director 8pp 20766 100 24X Fiche 50-010,83/10/11.8310140099
- 8310180268 Clarifies NRC position reprocedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months AXELSDN.W L Region 3. Office of Director 83/10/14 REED.C Commonwealth Edison Co 7pp 20802 302 24X Fiche 30-010.83/10/14, 8310180268
- S Reportable occurrences, LERs & related correspondence
- 831026000B Add1 response to F01A request for 17 categories of records Forwards documents listed in Apps B.C & D Info re fraudulent practices of Ray Miller, Inc available in PDR FELTON, J M Division of Rules and Records 83/06/23 CLEWEYT, J, Public Citizen Litigation Group 15pp 20270 001 24X Fiche 50-000, 83/06/23, 8310260008
- --B310260096 Describes facility B21203 flood & corrective actions taken Chronology of events encl.including notification of event & procedure for briefing commissioner PERKING.X E. NRC No Detailed Affiliation Qiven B3/06/OB DEYGUNG.R C Director's Office. Diffice of Inspection and Enforcement lipp 20921 136 24X Fiche 50-010, 83/06/23, 8310260008
- 8310060428 PND-III-83-089 on 830929, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govts alleged inadequate preparation by local agencies STRASHM.J., HBNCZER.W. Region 3. Office of Director 83/09/302pp 20641 221 24X Fiche 50-000,83/09/30.8310060428
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-Eil6M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified

 BERBERIAN, M. J. Foxboro Corp. 63/09/30 Director's Office, Office of Inspection and Enforcement 11pp. 20651 064 24X

 Fiche 50-000,83/09/30,8310070301

DOCKET 50-18 VALLECITOS SOILING WATER REACTOR

- @ Inspection reports: IE Bulletins & correspondence
- 8310040391 Forwards IE Insp Repts 50-018/83-01 & 50-183/83-01 on 830907 No noncompliance noted WENSLANBKI,F Region 5, Office of Director, 83/09/15, DARMITZEL,R W General Electric Co 2pp 20620-124 24X Fiche 50-018,83/09/15
- --8310040399 IE Insp Repts 30-018/83-01 & 50-183/83-01 on 830907. No noncompliance noted Major areas inspected organization, procedures, surveys, posting & annual repts SHERMAN.C.I. WENBLAWRIF A Region 5, Office of Director 83/09/10 3pp 20620 126 24% Fiche 50-018,83/09/15,8310040391.
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

 F Security, medical, emergency & fire protection plans
- 8310130216 Requests extension until 840120 for implementation of emergency plan.per 830624 ltr Add1 time will allow for exchange of ideas during reactor menagers mesting & intl symposium on uses of low & medium flux research reactors CLARK.L Massachusetts Institute of Technology, Cambridge, MA 83/10/05 THOMAS.C 0 Standardization & Bescial Projects Branch. ip 20725 049 24X Fichs 50-080.83/10/05,83/0130214.

- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- 8310030143 Requests extension of 831019 submittal date for changes to 801220 security plan to 831115.per 830919 ltr HILSON.W E Hoshington State Univ. Pullman. WA 83/09/27 TROMAS.C O Standardication & Special Projects Branch | 19 20570 038 | 24X Fiche 50-027.83/09/27.8310030143
- ---B310030151 Advises of Region V assumption of responsibility for review of changes to licenses security plans, safeguards contingency plans & guard transing & qualification plans, per 100FR80 34(p) SCHUSTER.M D Region 5, Office of Director 83/09/21 HILSON.H E Mashington State Univ , Pullman, WA 1p 20570 039 24X Fiche 50-027, B3/09/27, B310030143
- 8310210088 Responds to 830927 request to extend submittal of security plan changes until 831115 Changes requested do not fall within scope of 1005850 54(p) Extension denied THOMAS. O Standardization & Special Projects Branch 83/10/17 WILSON.W E Washington State Univ , Pullman, WA ip 20983 338 24% Fichs 50-027,83/10/17,8310210088
- O Inspection reports: IE Bulletins & correspondence
- 8310310237 Forwards IE Insp Rept 50-027/83-01 on 830919-21 & notice of violation W/o notice of violation SCARANG-R A Division of Radiological Safety & Safeguards Program 93/10/14 WILSON-W E Washington State Univ Pullman, WA 2pp 20947 195 24X Fiche 50-027,83/10/14-8310310239
- --B310310241 IE Insp Rept 50-027/83-01 on B30919-21 Noncompliance noted failure to calibr continuous air monitor sys as required by Tech Spec 4 3 3 SKERMAN,C I , MENSLAHSKI,F A Region 5, Office of Director B3/10/14 App 20947 197 24X Fiche 50-027,B3/10/14,B310310239
- DOCKET 50-29 YANKEE-ROHE NUCLEAR POHER STATION F Security, medical, emergency & fire protection plans
- 8310120137 Forwards IE Safeguards Insp Rept 50-029/83-10 on 830725-29 & notice of violation
 MARTIN.T T Division of Engineering & Technical Programs 83/09/10
 HEIDERL H Yenkee Atomic Electric Co 2pp 20695 281 24X
 Fiche 50-029,83/09/10,8310120137
- --8310120139 Notice of violation from insp on 830725-29 * Region I. Office of Director 83/09/10 1p 20695 283 24% Fiche. 50-029,83/09/10. 8310120137
- --0310120143 IE Safaguards Insp Rept 50-029/83-10 on 830725-29 Noncompliance noted failure to record required training
- 8310270184 Forwards IE Insp Rept 50-029/83-12 on 830823-25 No nencompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/10/07 HEIDERLH Yankee Atomic Electric Co 2pp 20924 176 24X Fiche 50-029,83/10/07.8310270184
- --8310270194 IE Insp Rept 50-029/83-12 on 830823-25 No noncompliance noted Major areas inspected Phase II of annual emergency exercise performed on 830824 SMIYH.R H. Region i. Office of Director CROCKER.H W. Division of Engineering & Technical Programs 83/09/28 6pp 20924 178 24K Fiche 50-029.83/10/07.8310270184 Division
- B310270532 Releases public version of changed page to emergency plan FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20938 029 24% Fiche 50-029,83/10/21.
- --8310270534 Public version of Change 2 to Page 7 9 of emergency plan W/820722 it's breceipt form MARKT.D E Yankee Atomic Electric Co 82/07/22 3pp 20938 031 24X Fiche 50-029.63/10/21.8310270532

- J Insurance & indemnity information
- 8310240026 Forwards Endorsements 1.2 & 3 to NELIA & MAELU Certificate N-4 & M-4, respectively
 SINISI, J M Marsh & McLennan, Inc. 83/10/14 SALTZMAN, J D
 Assistant Director for State & Licensee Relations 25pp 20882 00
 24% Fiche 50-029, 83/10/14, 8310240026
- B310240148 Forwards Endorsement 106 to NELIA Policy NF-76 & Endorsement 88 to MAELU Policy MF-26 SINIBI, J M Marsh & McLennan. Inc. B3/10/14 BALTZMAN, J D Aşbistant Director for State & Licensec Relations. 3pp. 20881 173
- P Operating license stage documents & correspondence
- 8310310017 FDIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER, L Affiliation Unknown 83/05/02 NRC No Detailed Affiliation Given 1p 21004 270 24X Fiche 50-000,83/05/02.
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable repts are unavailable
 FELTON, J.M. Division of Rules and Records 83/07/06 CONNER, L.
 Affiliation Unknown ip 21004 271 24% Fiche 50-000,83/07/06,
 8310310031
- 8310030054 Informs that steam generator level transmitters classifie as qualification not yet established (Category II A) Final resolution of category items will be included in NRC overall review of equipment qualification program GRUTCHFIELD. D. Operating Reactors Branch 5 83/09/27 KAY. J A Yankse Abmic Electric Co 4pp 20450 i5i 24X Fiche 50-029,83/09/27.8310050054
- 8310040108 Provides add1 info re inadequate core cooling instrumentation implementation schedule & equipment qualification.por 830927 & 29 requests concerning 830728 proposed mods All mods will be complete by 1985 refueling KAY, J A Yankee Atomic Electric Co 83/09/29 CRUTCHFIELD.D Operating Reactors Branch 5 ip 20508 003 24% Fiche 50-029,83/09/29.8310040108
- 8310040330 Forwards "Yankee Nuclear Power Station Process Control Program," for solid waste, per Tech Spec Section 3/4 il 3 Review & approval requested KAY.J A Yankee Atomic Electric Co 83/09/30 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 20617 094 24X Fiche 50-029, 83/09/30, 8310040330
- --8310040333 "Yankee Nuclear Power Station Process Control Program," solid waste * Yankee Atomic Electric Co 83/09/30 22pp 20617 096 24x Fiche 50-029,83/09/30,8310040330
- 8310050166 Submits desired wording re core-wide transient analysis methods ref in 830921 telcon & described in "Methods for Analysis of BKRS Sys Transient Analysis Model (RETRAN) "
 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/09/30 NO Detailed Affiliation Given 1p 20828 288 24%
 Fiche 50-029,83/09/30.8310050166 NR
- B310060003 Summary of B30916 meeting w/utils.Natl Weather Svc & FERC Bethesda,MD re Natl Weather Svc draft rept establishing 22-inch PMP level at facility Attendance list encl DUDLEY.R F Operating Reactors Branch 5 B3/10/03 Operating Reactors Branch 5 B3/10/03, B310060003
- 8310120369 Forwards "PMP for Upper Deerfield River Basin MA/VT Including Orographic Mod," final rept Rept completes studies under NRC-03-83-102,dtd 830309 Project & financial status MILLER, J.F. Commerce, Dept of, Natl Oceanographic & Atmospheric Administration FIN B-8640 83/10/03 STALEY, 0 Division of Engineering ip 20699 203 24X Fiche 50-027,83/10/03,8310120369
- --8310120374 "PMP for Upper Deerfield River Basin MA/VT Including 310120374 "PMP for Upper Deerfield River Basin MA/VT Including Drographic Mod"
 MILLER, J.F., HANSEN, E.M., FENN, D.D. Commerce, Dept. of, Natl
 Oceanographic & Atmospheric Administration FIN 8-8840 83/09/3,
 NRC - No Detailed Affiliation Given 43pp 20699 204 24X
 Fiche 50-029, 83/10/03, 8310120369
- 8310110161 Forwards SER supporting startup program for Cycle XVI, based on June 1983 add1 info CRUTCHFIELD. D. Operating Reactors Branch 5 83/10/05 KAY, J A Yankee Atomic Electric Co 2pp 20666 275 24X Fiche 50-029,83/10/05

- --8310110166 SER supporting low power physics tests for Cycle XVI * Office of Nuclear Reactor Regulation, Director 93/10/05 2pp 20666 277 24X Fiche 50-029.83/10/05,8310110161
- 8310120329 Responds to 821201 request for exemption from requirements of 10CFR90 44(c)(3)(ii) re hydrogen recombiner capability Review revealed util misinterpreted recombiner capability requirement Informal opinion encl
 EISENHUT.D G Division of Licensing B3/10/05 KAY, J A Yankee Atomic Electric Co 5pp 20699 282 24% Fiche 50-029.83/10/05, 82010308
- ---82071500B1 Responds to B20216 & 0303 requests for interpretation of 10CFR50 44 requiring util to provide purging sys Under interim requirements, util must sither install internal recombiner or provide capacity for external recombiner or provide capacity for external recombiner OLMSTEAD, W J Regulations Division 82/05/13 DIGNAN, T @ Ropes & Gray DIGNAN, T @ Vermont Yankee Nuclear Power Corp 7pp 20697 287 24X Fiche 50-029,83/10/05,8310120329
- --8310120333 Marked-up memo forwarding W Olmstead ltr to Dignan re hydrogen recombiner capability Change to cover ltr provided W/o ent! SCINTO, J NRC - No Detailed Affiliation Given 83/09/01 CRUTCHFIELD. D NRC - No Detailed Affiliation Given 1p 20699 294 24X Fiche 50-029.83/10/05.8310120329
- 8310120354 Requests completion schedules presented in integrated plant safety assessment rept be updated within 30 days of ltr receipt Immediate milestones should be established for evaluation methods & acceptance criteria review CRUTCHFIELD.D Operating Reactors Branch 5 83/10/06 KAY, J A Yankee Atomic Electric Co 2pp 20699 193 24X Fiche 50-029,83/10/06,8310120354
- 8310120203 Informs that future FR monthly publications will be submitted w/o transmittal ltr CRUTCHFIELD, D Operating Reactors Branch 5 83/10/07 KAY, J A Yankee Atomic Electric Co 2pp 20696 104 24X Fiche 50-029,83/10/07,8310120203
- B310190097 Forwards Rev 14 to operational QA program Rev addresses organizational & programmatic changes to QA program SHEPARD, A M Yankee Atomic Electric Co B3/10/12 MURLEY, T F Region 1, Office of Director 1p 20822 117 24X Fiche 50-000, 83/10/12, 8310190097
- --8310170105 Rev 14 to operational GA program
 PETERSON, W K , SHEPARD. A M , MURPHY, W P Yankee Atomic Electric
 Co YOGAP-1-A R14 83/10/12 134pp 20822 118 24X
 Fiche 30-000,83/10/12,8310170097
- 83i0170360 Provides status of Harriman Dam stability analysis currently under review by FERC Results of PMP study performed by Natl Heather 8yc & seismic input recommendations to be used in analysis provided to FERC CRUTCHFIELD.D Operating Reactors Branch 5 83/10/14 KAY, J A Yankee Atomic Electric Co 3pp 20786 171 24% Fiche 50-029,83/10/14.8310170360
- 8310250463 Informs that facility will be in compliance w/NUREG-0737, Item II F 2 re inadequate core cooling instrumentation.per 830728 Itr.in response to 830627 safety evaluation.pending completion of upgraded procedures CRUTCHFIELD, D. Operating Reactors Granch 5 83/10/24 KAY.J A Yankee Atomic Electric Co. Spp. 2089/ 149 24X Fiche 50-029,83/10/24.8310250463
- 8310270238 Advises that util Bill24 response to Generic Ltr 81-21 provides reasonable assurance that steam formation at upper head of reactor vessel during natural circulation cooldown will not occur, per TMI Action Plan Item I C 1 CRUTCHFIELD. D Operating Reactors Branch 5 83/10/25 KAY, J A Yankee Atomic Electric C 4pp 20924 051 24X Fiche 50-029,83/10/25.8310270238
- 83103102B3 Requests description of mechanical tube plugging program, to complete review instigated by findings of IE Insp Rept 50-027/82-12 Documents referenced in Mestinghouse 821122 ltr should be included Response due in 60 days CRUTCHFIELD.D Operating Reactors Branch 5 83/10/27 KAY, J A Yankee Atomic Electric Co 2pp. 20961 284 24x Fiche 50-029.63/10/27,8310310283
- 8310310360 Informs that request for extension to submit response to Generic Ltr 83-28 re Salem ATMS events denied Info should be submitted by 831105 CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/27 KAY, J. A Yanker Atomic Electric Co. 3pp. 20961 122 24X Fiche 50-029,83/10/27,8310310360

- @ Inspection reports, IE Bulletins & correspondence
- 83i0120137 Forwards IE Safeguards Insp Rept 50-029/83-10 on 830725-29 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 83/09/10 HEIDER, L H Yankee Atomic Electric Co 2pp 20495 281 24X Fiche 50-029,83/09/10,8310120137
- --B310120139 Notice of violation from insp on 830725-29
 * Region 1, Office of Director 83/09/10 ip 20695 283 R4X
 Fiche 50-029,83/09/10,8310120137
- --8310120143 IE Bafeguards Insp Rept 50-029/83-10 on 830725-29
 Noncompliance noted failure to record required training
 data
 DUNLOP,J M , MARTIN.W G . GODY,A T Region 1. Diffice of Director
 83/09/09 3pp 20695 284 24X Fiche 50-029.83/09/10.8310120137
- 830B300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Helder Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,830B30Q340
- B30B300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/09/26 Consolidated Edison Co of New
 York, Inc. 116pp 20777 210 24X Fiche 50-000, B3/09/26, B30B300343;
- 830B300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 11Bpp 2077B 001 24X Fiche 50-000,83/09/26,830B300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Sys W/o 100FR50 59 Evaluation " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Byo list encl JORDAN E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 2J3 24X Fiche 50-000,83/10/07,83083003/8.
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000.83/10/07.8308300782
- #310270184 Forwards IE Insp Rept 50-029/83-12 on 830823-25 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/10/07. HEIDERI, H Yankee Atomic Electric Co 2pp 20924 176 24X Fiche 50-029.83/10/07.8310270184
- --8310270194 IE Insp Rept 50-029/83-12 on 830823-25 No noncompliance noted Major areas inspected Phase II of annual emergency exercise performed on 830824
 BMITH, R H Region 1, Office of Director CROCKER, H H Division of Engineering & Technical Programs 83/09/28 6pp 20924-17H 24X Fichs 50-029,83/10/07.8310270184
- B30B300759 IE Info Notice B3-67. "Emergency Use Respirator Matl Defect Causes Production of Notious Cases " Byo list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24% Fiche 50-000, B3/10/11. B30B300757.
- 830B300761 IE Info Notice 83-68, "Respirator User Marning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,830B300761.
- 8310270013 Notification of Significant Licensee Meeting 83-91 on 831114 in Rowe, MA to discuss SALP COLLINS, 8 T Region 1, Office of Director 83/10/20 Region 1, Office of Director 20p 20940 188 24X Fiche 50-029, 83/10/20, 8310270013

- 8310310283 Requests description of mechanical tube plugging program, to complete review instigated by findings of IE Insp. Rept. 50-027/82-12 Documents referenced in Westinghouse 821122 ltr should be included Response due in 60 days. CRUTCHFIELD.D. Operating Reactors Branch 5 83/10/27 KAY. J. A Yankee Atomic Electric Co. 2pp. 20941 284 24X Fishe 50-029,83/10/27,8310310283
- R Periodic operating reports & related correspondence
- B310190012 Monthly operating rept for Aug 1983 W/B30909 ltr BATTERBON.S , HEIDER.L H Yankee Atomic Electric Co B3/09/09 Division of Data Automation & Management Information 6pp 20822 095 24X Fiche S0-029.83/09/09.B310190012
- S. Reportable occurrences, LERs & related correspondence
- 8310270340 FDIA request for placement of listed LERs in PDR ORABER, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 058 24% Fiche 50-000,83/09/08,8310270340
- 8310250523 LER 93-027/01T-0 on 830831, while performing Procedure OP-2100 "Plant Startup From Cold Shutdown." LPSI & HPSI pump breaker i found inoperable.contrary to Tech Specs Caused by procedural error Procedure revised W/830914 ltr MAY.E L . ST LAURENT.N N Yanter Atomic Electric Co 83/09/14 MURLEY.T E Region i. Office of Director 3pp 20901 296 24) Fiche 50-029,63/09/14-8310250523
- 8310270347 Responds to FOIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received FELTON, J M Division of Rules and Records 83/09/29 GRABER, L D NUS Corp 1p 20938 040 24% Fiche 50-000.83/09/29.83102/0347
- 8310250232 LER 83-028/03L-0 on 830901. during heatup in Mode 3, leak discovered in albow in high pressure steam drain line upstream of TV-406 Caused by steam erosion on piping elbow Elbow & piping replaced W/830930 ltr FRENCH.L D , SI LAURENT.N N Yankes Atomic Electric Co 83/09/3 MURLEY.T E Region I. Office of Director 2pp 20899 IPI 24X Fiche 50-029,83/09/30.8310250232
- 8310250418 LER B3-029/03L-0 on 830902, during recovery from 1 wk maint outage main coplant sys subcooking margin monitor failed Caused by loss of one in-core thermocouple input g-10 Input replaced by refueling channel thermocouple A-5 W/830930 itr ELLIS, D.W., BT LAURENT, N.N. Yankee Atomic Electric Co. 83/09/30 MWRLEY, T.E. Region 1. 0ffice of Director 2pp 20897 197 24X Fiche 50-029,83/09/30,8310250418
- |310250421 LER 83-030/03L-0 on 830902, while in Mode 2, leak discovered on body to bonnet flange on trap bypass valve AS-V-641 Caused by failed body bonnet flange gasket Casket replaced Valve reassembled W/830930 ltr RICE.D A . ST LAURENT.N N Yanker Atomic Electric Co 83/09/30 MURLEY.T E Region I. Office of Director 2pp 20897 004 24X Fiche 50-029,83/09/30.8310250421
- 3310140082 PND-I-83-105 on B31007.seismic event occurred in northwestern US w/magnitude of 5 2 on Richter scale in NY & 4 0 in NN No damage to equipment identified GALLO.R M. GREENMAN.E G Region 1. Office of Director B3/10/07 1p 20766 116 24X Fiche 50-000.83/10/07.8310140092
- 8310250327 LER 83-031/03L-0 on 830913, primary meteorological systemoved for mod to data signal transmission sys Secondary sys continued in svc No corrective action necessary W/831013 ltr RICELD A . ST LAURENT, N N Yankee Atomic Electric Co 83/10/13 MURLEY, T E Region I. Office of Director 2pp 20897 338 24X Fiche 50-029,83/10/13.8310250327
- 310250277 LER 83-032/03L-0 on 830915, while in Mode 1, main contant sys subcooling margin monitor failed Caused by loss of one of eight in-core thermocouple F-7 inputs Thermocouple F-7 input replaced by thermocouple H-7 H/B31014 ltr ELLIS.D W . ST LAURENT, N N Yankee Atomic Electric Co 83/10/14 MURLEY, Y E Region 1. Office of Director 2pp 20899 185 24X Fische 50-029,83/10/14,8310250277
- 310280018 LER 83-033/03L-0 on 830918, during Mode 1 operation, primary vent stack noble gas monitor channel failed Caused by improper reinstallation of drainage bottle Detector dried out W/831018 ltr
 FRENCH, L D , ST LAURENT, N Yankee Atomic Electric Co 83/10/18
 MURLEY, T E Region 1, Office of Director 2pp 20934 173 24X
 Fiche 50-029,83/10/18,8310280018

- B310280015 LER 83-034/99T-0 on 830919, underground file main sertion for yard hydrants 14 & 15 isolated Caused by deliberate removal of section from svc for waste compacting const Sys will be modified W/831019 ltr
 MAY.E L , ST LAURENTIN N Yankee Atomic Electric Co 83/10/19
 MURLEY.T F Region 1, Office of Director 3pp 20934 1/5 /4X
 Fichs 50-029,83/10/19.8310280015
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR
- U Congressional/Executive Correspondence
- 8310110617 Responds to 830701 questions re proposed retransfer of License R-81 Transfer precluded under law since transferpe, Cintichem. Inc., is US curp whose parent corp. F Hoffman LaRoche & Co. Ltd. is Shuitzerland corp. PALLADINO. N. J. Commissioners 83/09/22 SIMPSON, A. K. Senate, Environment & Public Works 13pp 20/01 338 24X Fiche 50-054,83/09/22,8310110617
- --8310110620 Poses questions on NRC position that proposed transfer C License R-BI from Union Carbide Subsidiary 8 to Cintichem, Inc is prohibited SIMPSUN.A X Senate, Environment & Public Works B3/09/01 PALLADINO.N J Commissioners 2pp 20701 351 24X Fiche 50-054, B3/09/22, B310110617
- DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR
 P Operating license stage documents & correspondence
- 8310270232 Forwards Amend 19 to License H-77 Amend makes editorial changes to Table 3 1.corrects related editorial errors on Fage 21 & allows change in testing interval of dry chamber door interlock
 THOMAS.C D Standardization & Special Projects Branch 83/10/13 HENRY.L Q New York, State Univ of Buffalo, NY 3pp 20943 OS 24X Fiche 50-057.83/10/13.8310270232
- --8310270243 Amend 19 to License R-77, making editorial changes to 1 at 3 1, correcting related editorial errors on Page 21 & allowing changes in testing interval of dry chamber door interlock THOMAS. C 0 Standardization & Special Projects Branch 83/10/15pp 20943 060 24% Fiche 50-057.83/10/13.8310270232
- R Periodic operating reports & related correspondence
- B310140222 Rept of changes tests & experiments conducted w/o prior Commission approval during Jul 1982 June 1983 ORLOSKY.F M New York. State Univ of Buffalo, NY 83/10/03 Region 1, Office of Director 1p 20/61 181 24X Fiche 50-057.83/10/03.8310140222
- DOCKET 50-59 TEXAS A&M UNIV REGEARCH REACTOR

 F. Security, medical, emergency & fire protection plans
- B310250673 Releases public version of licenses 831013 ltr advising on emergency plan implementation within 1/0-day requirement FELTON, J M Division of Rules and Records B3/10/21 Document Hanagement Branch ip 20908 356 24% Fiche 50-059,83/10/21, 8310250673
- --8310230683 Submits public version of indication that emergency plan implemented within 120-day requirement ERDMAN.C A Texas A&M Univ . College Station, TX 83/10/13 THOMAS.C D Standardization & Special Projects Branch 1p 20908 357 24X Fiche 50-059.83/10/21.8310250673
- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

 S Reportable occurrences, LLRs & related correspondence
- 8310060092 EN-83-062 on 831006, notices of violation & proposed imposition of \$1,000 civil penalty to be issued Action based on violation of Tech Specs re alterations made to corp configuration
 CRAIG.J. AXELRAD.J Director's Office. Office of Inspection and Enforcement 83/10/03 ip 20647-17/ 24X Fiche 50-062,83/10/03-8310060092

DOCKET 50-70 GENERAL ELECTRIC TEST REACTUR

G Adjudicatory correspondence

8310120372 Memprandum & order granting J Turk B30915 request for 60-day extension of deadline for filing amends to contentions & petition FRYE. J II Atomic Safety and Licensing Board Panel B3/10/07 TURK. J Turk. J Ip 20699 253 24X Fiche 50-070.83/10/07, 8310120372

DOCKET 50-7J GENERAL ELECTRIC NUCLEAR TEST REACTOR

1 Inspection reports, IE Bulletins & correspondence

8310310233 Forwards IE Insp Rept 50-073/8%-02 on 830813-15 No moncompliance noted WENSLAWSKI,F A Hegiph 5, Uffice of Director 83/10/17 DARMITZELIR W General Electric Co 2pp 20947 115 24X Fiche 50-073,83/10/17,8310310233

---B310310249 IE Insp Rept 50-073/BJ-02 on 830813-15 No noncompliance nated Major areas inspected radiation protection/environ protection, transportation activities & Tech Spec requirements

OARCIA,E M : WENSLAWSKI.F A Region 5, Office of Director B3/10/17 5pp 20947 117 24X Fiche 50-073, B3/10/17, B310310293

DOCKET 50 83 UNIV OF FLORIDA TRAINING REACTOR

F Security, medical. emergency & fire protection plans

8310050028 Grants extension until 831015 for receipt of amended emergency plan, in reponse to 830915 request THOMAS, C B Standardization & Special Projects Branch 83/09/26 DIAZ, N J Florida, Univ of, Gainesville, FL 2pp 20650 2/9 243 Fiche 50-083,83/09/26.8310050028

8310110362 Releases public version of licensee request for extension to submit amends to emergency plan
FELTON, J Division of Rules and Records 83/10/05 Document Management Branch 1p 20713 220 24X Fiche 50-083,83/10/05,8310110362

--8310110366 forwards public version of licensee request for add) 30-day extension until 831015 to submit amends to emergency plan DIAZ,N J florida. Univ of, Gainesville, FL 83/09/15 THOMAS,C Standardization & Special Projects Branch ip 20713 321 34X Fiche 50-083,83/10/05,83/0110362

8310210162 Responds to 830331 Rev 6 to physical security plan re request for clarification of ambiguous terminology Change acceptable THOMAS, C II Standardization & Special Projects Branch 83/10/17 DIAZ,N J Florida, Univ of, Gainesville, FL 2pp 20884 081 24X Fiche 50-083,83/10/17,8310210162

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

Q Inspection reports, IE Bulletins & correspondence

B310050559 Forwards IE Insp Rept 50-087/B3-03 on 830908 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director B3/09/21 SCHOLAND,G W Westinghouse Electric Corp 2pp 20633 177 P4X Fiche 50-087, 83/09/21,8310050559

--8310050564 IE Insp Rept 50-087/83-03 on 830908 No noncompliance noted Major areas inspected radiation protection & radwaste mgt programs, qualifications, audits, training, radiation protection procedures, instruments & equipment GRANT.W B , GREGER L R Region 3, Office of Director 03/09/19 4pp 20633 179 24X Fichs 00-087,83/09/21,8310050559

S Reportable occurrences, LERs & related correspondence

8310310275 PNO-II)-83-106 on 831025 two men in pickup truck parked outside (icility delivered bomb threat Training reactor shut down & bidd searched No bomb discovered KERS.D A. CRELD.J R. Region 3, Office of Directoi 03/10/24 lp 20747 114 24X Fith: 50-087,83/10/26.8310310275 DOCKET SO 89 GENERAL ATOMIC CO

P Operating license stage documents & correspondence

8310180319 Comments on amends to Licenses R-38 & R-47 to reflect name change to GA Technologies Co Amends unnecessary since facilities operational through 1983 HDGAN.JF GA Technologies, Inc./General Atomic Co 83/10/13 THO

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

E NRC Safety Evaluation Report (StR), suppls & correspondence

8310180071 SAFETY EVALUATION REPORT RELATED TO THE BENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF DELAHOMA RESEARCH REACTOR Docket No. 50-112 * Division of Licensing NUREC-0996 83/09/30 57pp 20826 174 24% Fiche 50-112.83/09/30,8310180071

DOCKET 50-116 JOWA STATE UNIV RESEARCH REACTOR

E NRC Safety Evaluation Report (STR), supply & correspondence

8310180169 SAFETY EVALUATION REPORT RELAYED TO THE RENEWAL OF TIME OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE IQUA STATE UNIVERSITY Docket No. 50-116

* Division of Licensing NUREO-1016 83/09/30 83pp Available at NRC \$4 75 20825 089 24% Fiche 50-116,83/09/30,8310180169

F Security, medical, emergency & fire protection plans

8310030123 Forwards responses to NRC 830815 questions Portable health physics instruments & fire protection sys described HENDRICKSDM,R Inum State Univ . Ames. IA 82/09/28 THOMAS.C () Standard: 1ation & Special Projects Branch 9pp 20590 042 PAX Fiche 50~116.03/09/28.8310030123

P Operating license stage documents & correspondence

8310030093 Forwards rev to Tech Specs for UTR-10 reactor Rev details operating & special repts distribution HENDRICKSON.R lowa State Univ. Ames. IA 83/09/28 CHU. A Standardization & Special Projects Branch 1p 20590 064 24x Fiche 50-116.83/09/28.8310030093

--8310030100 Rev to lech Specs detailing operating & special repts distribution * Iowa State Univ , Ames, IA 83/09/28 4pp 20590 065 24X Fiche 80-116.83/09/28.8310030093

8310170731 Advises that AT Chu assigned as project manager for facility THOMAS, C. D. Standardization & Special Projects Branch 83/10/03 HENDRICKEON, R. I Dua State Univ. Amer. IA 2pp 20797 333 24X Fiche 30-116.83/10/05.83101707JI

Q Inspection reports: IE Bulletins & correspondence

83i0120202 Forwards IE Insp Rept 50-i14/83-02 on 830913-14 No nancompliance mated PAPERIELLO,C J. Region 3, Office of Director 83/09/23 8PINROD, N I Jawa State Univ. Ames. 1A 2pp 20696 108 24X Fiche 50-i16.83/09/23.83j0120202

--8310120204 IE Insp Rept 50-114/83-02 on 830913-14 No noncompliance noted Major areas inspected radiation protection & raduatte mpt programs, including qualifications, audits, training, radiation protection procedures & instruments & equipment GRANT, W B. GREGER, L. R. Region 3, Office of Director 83/09/83 5pp 20476 110 24X Fiche 50-116.63/09/23,8310120202

8310030123 Forwards responses to NRC 830815 questions Portable health physics instruments & fire protection sys described HENDRICKSON.R Iowa State Univ . Ames. IA 83/09/28 THOMAS.C O Standardization & Special Projects Branch 9pp 20590 042 24K Fichs 50-114.83/09/28.8310030123 DOCKET 50-123 UNIV DF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8310200242 Forwards IE Insp Rept 50-123/83-02 on 830913-16 & notices of violation & deviation
NORELIUS.C E Division of Project & Resident Programs 83/10/07
WARNER.D L Missouri. Univ of. Rolla 2pp 20830 103 24X
Fichs 50-123

P Operating license stage documents & correspondence

8310170734 Forwards preliminary questions & comments associated w/ application for renewal of OL Responses should be available by 831114 for site visit by LASL & NRC THOMAS.C O Standardization & Special Projects Branch 83/10/06 BOLONIA E Missouri, Univ of, Rolla 10pp 20797 342 24X Fiche 50-123,83/10/06,8310170734

Q Inspection reports. IE Bulletins & correspondence

8310200242 Forwards IE Insp Rept 50-123/83-02 on 830913-16 & notices of violation & deviation
NORELIUS, C E Division of Project & Resident Programs 83/10/07
MARNER, D L Missouri, Univ of Rella 2pp 20830 103 24X
Ficha 50-123.83/10/07.8310200242

--8310200250 Notice of violation from insp on B30913-16 NORELIUS,C E Division of Project & Resident Programs 83/10/07 ip 20830-105 24X Fiche 50-123.83/10/07.8310200242

--8310200255 Notice of deviation from insp on 830913-16 * Region 3, Office of Director 83/10/07 ip 20830 106 24X Fiche 50-123,83/10/07,8310200242

--8310200268 IE Insp Rept 50-123/83-02 on 830913-16 Noncompliance noted feiture to provide analysis of possible hazards associated w/esperiments performed on 830223 & 0913 Deviation noted fasiture to feiture stopping stopping for several fillowards procedures RIOGHAY, R R DEFAVETTE, R . TAMBLING, T N Region 3, Office of Director 83/10/05 11pp. 20830 107 24X Fiche 50-123,83/10/07,8310200242

R Periodic operating reports & related correspondence

8310110097 Forwards Rev 1 to operator requalification program & "Progress Rept 1982-1983,Univ of Kissouri - Rolla Nuclear Reator Facility " Staff now consists of three senjor reactor operators & two reactor operators BOLON,A E Missouri, Univ of, Rolla 83/10/05 THOMAS,C U Standardization & Special Projects Branch | Ip 20658 280 24X Fiche 50-123,83/10/05.8310110099

8310110113 "Progress Rept 1982-1983, Univ of Missour; - Rolla Nuclear Reactor Facility " BCLON.A E Missouri, Univ of, Rolla 83/03/31 135pp 20668 301 24X Fiche 80-123.83/10/05.8310110099

Operator Examinations

310110099 Forwards Rev I to operator requalification program & "Progress Rept 1982-1983. Univ of Hissouri - Rolla Nuclear Reactor Facility " Staff now consists of three senior reactor operators & two reactor operators
BDCONIA E Missouri. Univ of Rolla 93/10/05 THOMAS. C O Standardization & Special Projects Branch 1p 20668 280 24X Fiche 50-123.83/10/05.8310110099

-8310110110 Rev 1 to operator requalification program for Univ of Hissouri - Rolla nuclear reactor facility * Missouri Univ of. Rolla 81/03/31 20pp 20668 281 24X Fichs 50-123,83/10/05,8310110099

--8310110113 "Progress Rept 1982-1983, Univ of Missouri - Rolla Nuclear Reactor Facility " BOLONA E Missouri, Univ of Rolla 83/03/31 135pp 20668 301 24X Fiche 50-123,83/10/05,8310110099

BOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTUR

F Security, medical, emergency & fire protection plans

8310210299 Forwards Revs 1 & 2 to physical security plan Revs withheld * Virginia Polytechnic Institute & State Univ , Dlacksburg, VA 83/09/27 CARLSON, D Division of Safeguards ip 20858 215 24X Fiche 50-124,83/09/27,8310210299 DOCKET 50-128 TEXAS ASM UNIV RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8310200268 IE Insp Rept 50-123/83-02 on 830913-16 Numcompliance noted failure to provide analysis of possible hazards associated w/experiments performed on 830223 & 091% Deviation noted failure to follow std procedures RIDOMAY, K. R., BEFAYETTE, R., TAMBLING, T. N. Region 3, Liffice of Director 83/10/05 11pp 20830 10/ 24X Fiche 50-123/83/10/0/48310200242

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

B310210159 Responds to util B30H08 ltm re change to Rev 2 to security plan Changes consistent w/provisions of 10CFR50 34(p), do not decrease effectiveness of plan & are acceptable CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/1/ SCHUYLER, J.O. Pacific Gas & Flectric Co. 2pp. 20884 079 2/4X Fiche 50~133,83/10/17,8310210159

P Operating license stage documents & correspondence

8310250113 Forwards topical outline for submitting info for decommissioning facility for placement in PDR under docket PEARSON.W R Chemical Engineering Branch 83/10/24 Division 9 Technical Information & Document Control 10pp 20896 258 24X Fiche 50-133.83/10/24.8310250113

@ Inspection reports, IE Bulletins & contespondence

8308300340 IE Info Natice 83-61. "Alleged Use of Stand-Ins for Welder gualification Tests " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754-022 24X Fiche 50-000,83/09/26.8300

8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Sve list enel JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of N York, Inc. 114pp 20777 210 24X Fiche 50-000,83/09/26.8308 (COC)

8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouser-Type 5A-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of No York, Inc. 118pp 20778 001 24X Fiche 50-000,03/09/26,8300300074

B30B300349 lE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list enc!

JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/29 Consolidated Edison (p. n.f. Ne York, Inc. 115pp 20716 324 24X Fiche 50-000, B3/09/29, B30B100344

8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Hyparb Loops Used in Westinghouse Plants" Syc list encl JORDAN, E. D. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consultdated Edison Co. of Ne-York, Inc. 76pp. 20827 213 24X Fiche 50-000,83/10/07,83083003376

B308300752 IE Info Notice B3-66. "Fatality at Argentine Critica)
Facility " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post B30103) 83/10/07 Consolidated Edison Co. of New
York, Inc. 77pp 20882 026 24X Fichc 50-000.83/10/07,8308300752

8308300759 1E Info Notice 83-67. "Emergency Use Respirator Mot) Defect Causes Production of Novious Gases " Svt list and I JORDAN, Et Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Int 117pp 21043 075 24X Fiche 50-000,83/10/11,8300300/55

830830076: IE Info Notice 83-68, "Respirator User Warning Defrictive Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,830DJ007&1

- R Periodic operating reports & related correspondence
- 8310190260 Monthly operating rept for Aug 1983 W/830908 ltr DERKS.P 5. WELKS.E D Pacific Gas & Electric Co 83/09 Division of Data Automation & Management Information 5p 20818 064 24X Fiche 50-133 83/09/08 8310190260 83709708
- DOCKET 50-134 WORCESTER POLYTECH INST. RESEARCH REACTOR F Security, medical, emergency & fire protection plans
- 8310270291 Forwards IE Insp Rept 50-134/8J-02 on 830818-19 No noncompliance unted STAROSTECKI.R Division of Project & Resident Programs 83/10/11 WILBUK.L C Worcester Polytechnic Inst 2°pp 20923 12° 24X Fiche 50-134,84/16/11.8310270291
- --8310270275 IE insp Rept 50-134/83-02 on 830818-19 No noncompliance noted Major areas inspected effect of Washburn Lab renovation on reactor facility, radiation control, emergency plan & environ monitoring KINNEY, W W , ELSASSER, T C Region 1. Office of Director 83/10/07 /pp 20923 224 247 Fiche 40-134,83/10/11,83/10270291
- @ Inspection reports: IE Bulletins & correspondence
- 8310270291 Forwards IE Insp Rept 50-134/83-02 on 830818 19 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 83/10/11 WILBUR,L C Morce-tor Polytechnic Inst 2pp 20923 22P 24X Fichs 30-134,83/10/11,8310270291
- --8310270295 IE Insp Rept 50-134/83-02 on 830818-19 No noncompliance noted Major aleas inspected effect of Washburn Lab tensyation on reactor facility, radiation control, emergency plan & environ monitoring MINNEY, W. W., 6L5ASSER, T. G., Region I. Office of Director 83/10/07 7pp 20923 224 24X Fishe 50-134,83/10/11.8310270291
- DOCKET 50~139 UNIV OF WASHINGTON REBEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8310310352 Forwards IE Insp Rept 50-139/83-01 on 830921-23 & notice of violation W/o notice of violation SCARAND,R A Division of Radiological Safety & Safeguards Program 83/10/13 BOWLN-J R Washington, Univ of, Seattle, WA Upp 20960 294 24X Fiche 50-139/83/10/13/8310310392
- --8310310387 IF Insp Rept 50-i37/83-01 on 83092i-23 Noncompliance noted failure to calibi flow measuring devices installed in Tech Spec required effluent monitors SHERMAN, C I., WENSLAWSKI, F. A. Region 5, Office of Director 83/10/13 7pp 20960 296 24X Fiche 50-139,83/10/13,8310310352

DOCKET 50-142 UCLA TRAINING REACTOR

- 9 Adjudicatory correspondence
- 8310030374 Response to Committee to Bridge the Gap 830830 comments on IE inspired an SNM possession Gap alleged discrepancies based on conjecture & misinterpretation of reported info Certificate of Byc encl CORMIER.W [I California, Univ of, Los Angeles, CA 83/09/07 Upp 20593 047 24% Fiche 50-142.83/09/07,8310030374
- 8310040172 Memorandum & order ruling on UCLA & NRC scope objections to Committee to Bridge the Gap prefiled direct testimony Objections overruled w/exception of Panel 1.Pargraphs 4-6 Panel III.Pargraphs 15 to Jectulis Averture westprovided in the Atlanta Safety and Licensing BRIGHT, 0 D. LUEDKE, F. A., FRYE, J. H. Atlanta Safety and Licensing Board Panel 83/09/30 California, Univ. of. Los Angeles, (A. 10pp. 20608 093 24X Fiche 50-142,83/09/30.8310040192
- 8310[10054 Memorandum & order memorializing 831003 tolcon re rebuttal testimony, technical issues, expert interrogatories, photographs & official notice, FRYE. H Atomic 8afety and licensing Board Panel 83/10/04 3pp 2068 241 24X Fiche 50-142,83/10/04.8310110054
- 8310260263 Hamorandum & Order LNP-83-67, quanting NRC petition for reconsideration of LBP-83-25A, Section B & denying NRC petition for reconsideration of LBP-83-25A, Section L & Committee to Bridge the Gap objections to SNM inventory LUEBKE, E A, BRIGHT, O O, FRYE, JH Atomic Safety and Licensing Board Panel B3/10/24 Office of the Executive Local Director 13pp 20712 OOB 24X Fiche 50-142,83/10/24,83/0260263

- 8310310240 Notice of resumption of evidentiary hearing he proposed renewal of OL Hearing will commence on 031129 in Los Angeles. CA & will continue through 831102 FRYE. JH Atomic Safety and Licensing Board Panel 83/10/27 to 20947 122 247 Fiths 50-142.83/10/27.8310310240
- H General correspondence
- B3[0]80]35 Opposes relicensing of potentially dangerous reactor Reactin should be shut down until all safety questions resolved JOACHIN.M Affiliation Unknown B3/10/07 FRYE, J H Atomic Garety and Licensing Board Panel 1p 20809 185 24X Fiche 50-142, 83/10/07, 83[0]80]135
- 8310260302 Opposes relicensing of nuclear reactor at UCLA LEVV.D Affiliation Unknown 83/10/25 FRVE.J H Atomic Safety and Licensing Board Panel 1p 20911 034 24X Fiche 50-142.83/10/25.8310260302
- T Hearing transcripts on non-antitrust matters
- 8310190121 Transcript of 831011 hearing in Los Angeles, CA re proposed renewal of facility license Pp 2,507-2,630 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/10/11 144pp 20817 100 24X Fiche 50-142,83/10/11,8310190121
- 8310170123 Transcript of 831012 hearing in Los Angeles.CA re proposed renewal of facility license Pp 2.631-2.82/ Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/10/12 24/pp 20821 130 24X fiche 50~147.83/10/12.0310190123
- 8310200i16 Transcript of 831019 hearing in tos Angeles.(A re proposed renewal of UL Pp 2:828-3.030 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/10/13 309pp 20837 125 24% Fiche 50-142:83/10/13.0310200116
- 8310200112 Transcript of 831014 hearing in Los Angeles.(A re proposed renewal of OL Py 3.031-3.192 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/10/14 215pp 20836 067 24X Fiche 30-142.83/10/14.8310200112
- B310280016 forwards missing pages from BJ0802 & 1014 hearing transcripts re proposed renewal of DL Corrected pages to B31014 hearing transcript also encl EYSTER.R E Taylor Associates B3/10/21 FRYE.J H , LUEDKE.! A , BRIGHT.G D Atomic Safety and Licensing Board Panel ip 20932 279 247 Fiche 50-142.83/10/21.8310280016
- --8310280020 Pagps from 83080? & 1014 hearing transcripts re Ut. renewal inadvertently omitted from original & corrected pages to 831014 transcript * Atomic Safety and Licensing Board Panel #3/10/21 16pp 20932 280 24X Fiche 50-142,83/10/21,8310280016
- DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8310170735 Releases public version of revised emergency preparedness plan FELTON,JM Division of Rules and Records 83/10/06 Docum Management Branch 1p 2079/ 303 24% Fiche 50-148,83/10/06, 8310170735 Dor ument
- --8310170738 Public version of revised emergency preparedness plan * Kansas, Univ of, Lawrence, KB 83/08/31 37pp 20797 304 24X Ficha 50-148,83/10/06,8310170735
- 8310210237 Forwards addendum to Section 4, "Site Surroundings." to hazards summary rept
 MEGLER.R B Kansas, Univ of, Lawrence, KS 83/10/11 MERNARD, H
 Division of Licensing ip 20852 036 24% Fiche 50-148, 83/10/11,
 831021023/
- --8310210239 Addendum to Section 4. "51t: & Surroundings," to hazards summary rept * Kansas, Univ of, Lawrence, KS 83/10/11 2pp 2085; 03/ 24X Fiche 50-148,83/10/11,831021023/
- p Operating license stage documents & coirespondence
- 8310170728 Advises that AT Chu assigned as project manager for facility THOMAS.C O Standardization & Special Projects Branch 83. MESSLER, Rausas, Univ of Laurence KS 3pp 20747-356 83710705 MESLER, R Kansas, Univ of, Lawr Fiche 50-148, 03/10/05, 8310170728

- DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANI

 F Securaty, medical, energency & Fire protection plans
- 8310110019 Releases public version of revised emergency plan implementing procedure FELTON, J.M. Division of Roles and Recurds 83/10/05 Document Management Branch 1p 2068/ 357 24X Fiche 50-000.83/10/05. 8310110019
- --8310110024 Public version of Nev & to Emergency Plan Implementing Procedure E01-7. "Offsite Duse Worksheet (Protective Actions) " W/930922 ith & receipt form BRADLEY, J. Consumers Power Co. 83707/19 Document Management Branch 2pp 20687 358 24x Fithe 50-000.83/10/05.8310110017
- 8310110255 Releases public version of revised emergency plan FELTON, J. M. Division of Rules and Records 83/10/05 Uncumpu Management Branch 1p 2060; 359 24X Fiche 50-155, 83/10/05.
- --8310110259 Public version of Rev 70 to emergency plan W/830926 ltr & receipt form + Consumers Power Co 83/09/23 App 20682 260 24X Fiche 50-155.83/10/05,8310110259
- B310180614 Advises that B30B17 proposed changes to physical security plan. Rev 9, atceptable per 10CFR30 54(p) Requested 45% Variance does not meet 10CFR33 55(g)(4) Encls to itrustheld (ref 10CFR321) CRUTCHFIFED, D Operating Reactors Bravia 5 B3/10/11 VANDEDHALLE, D J Consumers Power Co Jpp 20817 339 249 Fiche 50-155, 8J/10/11, 8J10180614
- 8310180335 Forwards, for info, listed documents which will not be introduced into evidence Oversite map end! Aperture cast available in PDR GALLO.J Isham, Lincoln & Beale GALLO.J Consumers Power Co 83/10/14 BLOCH, PB : PARIS.O H : SHON.F J Atomic Safety and Licensing Doard Panel 733pp 20809 2/9 24X Fiche 50-15%, 83/10/14,8310180335
- 8310200410 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/30/17 Document Management Branch lp 20859 217 24% Fiche 50-155.83/10/17, B310200410
 - 9310200417 Forwards public version of Sev 34 to Emergency Flan
 Implementing Procedure EFIF 4A, "Plant Superintendent" &
 Rev 35 to Procedure EFIF 6B. 'Personnel Monitoring
 Evacuation & Reassembly "Receipt for a enc!

 Consumers Power Co. 03/09/27 NRC No Detailed Affiliation
 Given 2pp 20059 220 24X Fiche 50-155.83/10/17.8310200410
 - 3310200473 Public version of Nev 34 to Emergency Plan Implementing Procedure EPIP 4A. "Plant Superintendent" 1 Nev J5 to Procedure EPIP 6B. "Personnel Monitoring Evaluation 2 Neassembly "

 * Consumers Power Co. 83/09/26 11pp 20859 272 447 Fiche 50-155.83/10/17.8310300410
- B310250522 Forwards SALP Rept 50-155/83-15 for Jul 1782 Junt 1783 Util has improved rating in five functional areas including satisfactory resolution of previously identified concerns KEPPLER, J G Region 3, Office of Director 83/10/20 DENJT(, K & Consumers Power Co. 2pp. 20700-316 -4X Fiche 50-155.83/10/20.
- -8310250535 SALP Rept 50-155/63-15 for Jul 1982 June 1983 Elicensee should develop & implement program to identify applicable regulatory requirements & licensee commitments to ensure compliance w/GA activities All other areas acceptable a Region 3. Office of Director 8J/10/20 24pp 20900 318 24x Fiche 50-155.83/10/20,8310250527
- 331026011B Forwards exemption requests from certain requirements of 10CFR50. App R. Section III 9 3 re fire detection & fixed first suppression requirements VANDEWALLE, D. Consumers Power Co. B3/10/20 CRVFCH IELD. D. Operating Reactors Granch 5 7pp. 26915-236 24X Fiche 50-155,83/10/20. B310260118
- 8310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures FELTON.J M. Division of Rules and Records 83/10/21 Documen Management Branch ip 20928-337 24X Fiche 50-000,89/10/21, 8010270491

- --B310270510 Forwards public version of Nev 2 to controlled copuloide.

 List of general ofc ctr/cmergoncy operations facility
 emergency implementing procidures & list depicting location
 of proprietary info in procedures
 CMRLEY.A Consumers Pour Co B3709715 Office of Nuclear
 Reactor Regulation, Director 7pp 20928 33H 24X
 Fiche 50-000,83/10/21.83102/0491
- 8310270590 Releases public version of revised general ofc control ctr/
 emergency operations facility emergency implementing
 procedules
 FELTON, J.M. Division of Rule: and Records 83/10/25 Document
 Management Branch 1p 20944 322 24% Fiche 50-000, 83/10/25.
 B310270590
- --B310270593 Forwards public version of revised general ofc control of emergency operations facility emergency implementing procedures including Procedure GEN-2 re emergency telephone numbers Receipt form encl
 CARLEY, A Consumers Power (a 83/10/13 Document Maungement Branch App 20944 323 24X Fishe 50-000.83/10/25.8310270570
- --831027059/ Public version of revised general ofc control cti/emirger operations facility emergency implementing procedures, including freedoure GEN-2 is emergency telephone numbers * Consumers Power Co 80/10/11 4/2pp 20944 % 7 4/4Y Fiche 50-000, 83/10/25, 83102/0590

G Adjudicatory correspondence

- B309130169 Submits preliminary list of witnesses & testimony on Contention II-D is air crash & small civilian aircraft sighted over plant Extension for testimony filling data to B30930 requested Related correspondence O'NEILL. J O'Neill. J B3/09/07 BLOCH, P B , PARIS. O H , S'RN, f Atomac Safety and Licensing Board Panel ip 20056 PBL 2/49 Fiche 50-195, 03/09/07.8309130367
- 8310040184 Memorandum % Order LBP-83-62 denying Christa Natia 830824 motion to reopen record on criticality Alleged grounds for reopening moot BLOCH, P. B., PARIS, O. H., SHON, F. J. Atomic Safety and Licensing Brown Panel 03/07/30 Christa Maria Spp. 20608 247 24X Fiche 50-155,83/07/30,8310040184
- 8310040267 Order extending time until 83100/ for Commission to art treview ALAB-725 CHILK, S.J. Office of the Secretary of the Commission 83/09/ Kt Commissioners 1p 20612 342 24X Fiche 50-155,83/07/30, B310040267
- 8310050483 Motion for leave to file util testimony nut of time on Contention 9(8) Delay due to irreconcilable difference between witnesses, necessitating reappriarisal of util case Certificate of Syc encl QALLO, J Consumers Power Co QALLO, J Isham, Lincoln & Deale 83/10/02 Atomic Safety and Licensing Board Panel 5pp 20633 236 24X Fiche 50-155,83/10/02,0310050483
- --8310050486 Forwards RW Sinderman, RD Klimm, E Muma, F We)ch & GI I osuft testimony on emergency planning Contention 9(8) GALLO, J Isham, Lincoln & Meale GALLO, J Consumers Power to B3/10/02 BLOCH, P.B., PARIS, O.H., 1940N, F.J. Atomic Safety and Licensing Bound Panel Jpp. 20633-241 24K Fiche 50-155, 83/10/02 B310050483
- --8310050489 Testimony of RW Sinderman re Christa-Maria Contention 9(4) on summer & winter emergency plans Evacuation time retimates take into account seasonal factors Plan adequately addresses summer & winter conditions SINDERMAN.R W Consumers Power Co 03/10/02 34pp 20633 244 24X Piche 50 155,8310/028,3310050483
- ~~8310090491 Testimony of RD Klimm re Chiista-Maria Contention 7(8) on summer & winter emergency plans Evacuation time estimate studies address summer & winter conditions KLIMM R D Consumers Power Co KLIMM, R D HMM Associates, Inc 83/10/02 (7pp 20633 278 24X Fiche 50~155, 83/10/07, 831005,0483
- --8310050494 festimony of E Muma re Christa-Maria Contention 9(8) on summer & winter emergency plans County emergency plan flexible enough to accommodate influx of seasonal pupulation during summer & adverse winter weather MUMA, E. Consumers Power Co. MUMA, E. Charlevoix, NJ. 83/10/02/7pp. 20633 295 24% Fiche 50-155/83/10/02/8310050483
- --8310050501 Testimony of QT Labater ie Christa-Maria Contention 7(8) usummer & winter emergency plans Summer/winter conditions will not have effects significant enough to require separate planning LABATER, Q T Consumers Power Co LAGATER, Q T (hailevoix, MI 83/10/02 7pp 20633 302 24X Fiche 50-155, 83/10/02, 8310050483

- --8310050507 Festimony of F Welch re Christa-Maria Contention 9(0) on summer & winter emergency plans Emergency plan will accommodate difficulties pased by winter weather WELCH: F Consumers Power Cn WFLCH: Charlevoix, MI 83/10/02 10pp 20633 309 24X Fiche 50-155,83/10/02.8310050483
- 8310110207 Forwards list of witnesses & documents for 851024-1106 hearing re spont fuel pool med lestimony of AJ Behwart; will be forwarded if requested Kelated corcespondence D'NEILL, J O'Neill, J 8910/03 ILUCH, P B , PARIS, O H , 840N, F J Atomic Safety and Licensing Board Panil 11pp 20265 031 247 Fiche 50-155, 83/10/03, 8310110,07
- B310110063 Motion for extension of time for filing testimony of GP Betourne & RM Marusich from 830930 to 831008 Wilness has not received all documentation needed Centificate of Svience Co. (AMIC). Consumis Forest Co. (AMIC). Lesant Lucal & Hool
 - enci GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Boald B3/10/04 Atomic Safety and Licensing Board Panel. Spp 20667-307 24X Fiche 50-155:83/10/04.8310110063
- - COPELAND, V.O. Consumers Power Co. COPLLAND, V.O. Isliam. Lincoln 8 Beale. 83/10/04. Atomic Bofety and Licensing Board Ponel. 14pp 20679-303. 24X Fiche 50-155, 83/10/04. 8310120365
- #310140039 Advises of inability to testify at #31024-1106 hearing due to teaching & counseling dutits

 SCHWARTZ.A J. Michigan. Univ. of, Ann Arbor, M1 #83/10/04

 BLOCH.P B , SHIN.F J , PARIS.D H Atomic Safety and Licensing Roard

 Panel 1p 20748 084 24X Fiche 50-155,83/10/04.8310140019
- #310130051 Informs that parties agreed to listed order of prejentation of issues at #31025-1104 evidentiary hearings & P Yamov testifying out of order during first wk of hearings GODDARD, R J Hearing Branch 3 #3/10/11 BLOCK, P B , SHON, F J , PARIS, O H Atomic Safety and Licensing Roard Panel 2pp 20725 063 #24X Ficho 50-155,83/10/11.8310130051
- B310130194 Notice expressing ASIB concern over licensee limited interpretation of aircraft crash issue in spent fuel pool expansion proceeding BLOCK-R Admic Safety and Licensing Board Panel 03/10/12 lp 20719 147 24X Fich
- B310170420 Motion for order & subposes calling J Homigan as ASIB witness Hennigan believes testifying would be improper or constitute conflict of interest w/duties as state employee Braft testimony & Certificate of Svc encl GALLO. J Consumers Power Co GALLO. J Islam, Lincoln & Bealt 83/10/12 Atomic Sofety and Licensing Board Pantl Lapp 20784 021 24X Fiche 50-135.B3/10/12.G310170420
- B310140247 Advises that time for Commission to review ALAB-72% expired Commission declined review Becision became final agency action on B31007 Commissioner G11insky separate views encl CHILK.S J Office of the Secretary of the Commission B3/10/13 O'NEILL.J O'Neill, J 2pp 20761 237 24% Fiche 50-155,83/10/13,8310140247
- B310180230 Response opposing Christa-Maria B31007 motion for early recess on Halloween & for sito visit Normal 5 PM recess provides ample time for Halloween festivities Bito visit walcomed Cartificate of Svc encl.
 GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Deale B3/10/13 Atomic Bafety and Licensing Board Papel. 4pp. 20808 181 24X fiche 50-155.63/10/13.8310180230
- B31018034B Forwards prof qualifications of HJ Eckert & MK Prahhakara, inadvertently omitted from 830430 testimony GALLO, J Isham, Lincoln & Boale OALLO, J Consumers Power Co 83/10/13 BLOCH, P B Atomic Bafety and Licensing Board Panel PARIS, D H , BHON, F J Atomic Bafety and Licensing Appeal Panel 3pp 20803 008 24% Fiche 50-155, 83/10/13, 8310180348
- #310180335 Forwards, for info.listed documents which will not be introduced into evidence Oversize map encl Aperture card available in PDR GALLO, I sham. Lincoln & Beale GALLO, J Consumers Power Cp 83/10/14 BLOCK, P B . PARIS.O H . SHON, F J Atomic Safety and Licensing Board Panel 733pp 20809 P/9 24X Fiche 50-15%.

- 8310180222 Forwards VB Hallman affidavit & photo of UB Air Force B-52 bomber flying over containment bldg CALLO, J Consumers Power Co B3710/15 BLOCH P B PARIS, O H . SHON, F J Atomic Safety and Licensing Board Panel 2pp 2080B 185 24X Fiche 50-155,83/10/15,83101802/2
- --8310180224 Affidavit of VB Hallman attesting that UB Air Force B-52 bomber flew directly over facility in June 1966 Photograph encl HALLMAN, V II Cunsumers Power Co 83/09/20 2pp 20808 18/ 24/ Fiche 50-155,83/10/15,8310180222
- 8310240128 Advises that L Reiton 820917 deposition or d'Neill Contention III on development of site-specific spectrum & wark performed by TERA Corp & LLL may be used as cross-standarion tool &/or offered into evidence GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/19 BLOCH, P.B. PARIS, O.H., SHON, F.J Atomic Safety and Licensing Board Panel 2pp 20881 154 24X Fiche 90-155,83/10/19,8310240128
- --8310240132 Motion to strike MP Phillips testimony re Christa-Maria Contention 9, Subparts 1,6,0 & 9 Testimony beyond scope of contention & Irrelevant Certificate of Svc enci GALLO, J. THORNFON P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale 83/10/19 Atomic Safety and Licensing Board Panel 8pp 20881 156 24X Fiche 50-155,83/10/19,8310240128
- B310250140 Informs that TM Cheng will replace D Persinko as co-sponsor for NRC testimony on O'Neill Contention IJ C re seismic crane issue Prof qualifications oncl
 BACHMANN,R O Hearing Branch I 83/10/19 BLDCH,P B . SHON,F J ,
 PARIS,O H Atomic Safety and Licensing Roard Panel 3pp
 20896 290 24X Fiche 50-155,83/10/19,8310250160
- 8310250307 Advises that ASLD June 1982 hearing in Boyne Falls, MI re proposed expansion of spent fuel storage capacity at facility will reconvene on 831025 in Petoskey, MI Response to written limited appearance statement encl CRUTCHFILLD. D. Operating Reactors Brench 5 83/10/21 WILL, C W Affiliation Unknown 67pp 20876 005 24X Fiche 50-155,83/10/21.
- 8310310206 Hotion to quash hearing subpossa directed to RJ Rajewski Licensee not served w/copy of subpossa application.clearly violating lOCFR2 701(b) & 10CFR2 712(b) Testimony would be irrelevant Certificate of Svc encl GALLO.J. COPELAND.V © Consumers Power Co QALLO.J. Isham. Lincoln & Beale 63/10/24 Atomic Safety and Licensing Board Panel 5pp 20958 324 24% Fiche 50-195.83/10/24,8310310206
- 8310310139 Mation to strike P Chen testimeny re Christa Maria Contention 8 & U'Neill Contention IIIE-2 genuine issue of fact Trestimony beyond scope of genuine issue Certificate of Byc encl 9ALLO, J, THORYTON, P Consumers Power Co. GALLO, J. Isham, Lincoln & Beale B3/10/25 Atomic Safety and Licensing Board Panel Spp 20759 060 24% Fiche 50~155,83/10/25,8310310139
- B310310145 Notice of Appearance in proceeding Certificate of Svc enc) FITZOIBBONG, R Consumers Power Co FITZOIBBONS, R Isham, Lincoln & Beale B3/10/25 3pp 20939 011 24X Fiche 50-155.02/10/25, B3103101445
- 8310310391 Motion to quask J Mol 831025 subpoems to appear at 831026 hearing re Christa-Maria Contention 9(8) & O'Neill Contention 11D Subpoema not relevant to contention issue Certificate of 8vc enc! GALLO, J FITZ018B0NS.R Consumers Power Co GALLO, J Isham. Lincoln & Beale 83/10/26 Atomic Safety and Licensing Board Panel 7pp 20959 275 24X Fiche 50-135,83/10/26,8310310391
- P Operating license stage documents & correspondence
- B310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/07/01 PEDRO.J NUI Carp 2pp 20704 137 24% Fiche 50-000.B3/07/01.B310110004
- 8310050005 Summary of B30915 meeting w/util & Structural Mechanics Assoc in Bethesda, MD re seismic capability of semigantry crane EMCH.R L. Deelating Reactors Branch 5 83/09/26 Operating Reactors Branch 5 8pp 20650 247 P4X Fiche 50-155, 83/09/26, 83100500005

- 8310040264 Forwards Rev i to "Confirmatory Analysis, Support Wall Stress. Analysis," in response to NRC 930813 ltr Analysis conservatively demonstrates & quantifies that adequate safety margins inherent in walls Commitment closed BURDINE.T C Consumers Power Co 83/09/28 CRUTCHFIELD.U Operating Reactors Branch 5 lp 20613 136 24x Fiche 50-155.03/09/28.8310040264
- --8310040266 Rev 1 to "Confirmatory Analysis, Support Wall Stress Analysis " • Consumers Power Co 83/09/28 57pp 20613 137 24X Fichs 50-155,83/09/28,8310040264
- 8310030492 Forwards supplied 810515 SER re application for design changes in spent fuel pool makeup line & thermal & structural analyses of pool at 150 F Design acceptable CRUTCHFIELD.D Operating Reactors Branch 5 83/09/30 VANDEWALLE.D J Consumers Power Co 3pp 20401 087 24X Fiche 50-155,83/09/30.8310030492
- --83(0030497 Supplemental safety evaluation accepting mod to spent fuol storage pool makeup line & 150 F operation temp * Office of Nuclear Reactor Regulation. Director 83/09/30 21pp 20401 990 24x Fiche 50-155.83/09/30.8310030492
- 8310060024 Forwards "Environ Equipment Qualification Results of Failure Modes & Effects Analysis (FM&EA) " Results show safety functions of equipment performed after event will not affect functions or mislead operator TONER. K A Consumers Power Co 83/07/30 CRUTCH-[ELD.D Operating Reactors Branch 5 2pp 20647 107 24X Fiche 50-155.83/09/30.
- --8310060030 "Environ Equipment Qualification Results of Failure Modes & Effects Analysis (FM&EA) " * Consumers Power Co 83/09/30 19pp 20647 109 24X Fichs 50-155,83/09/30,8310060024
- 9310060080 Requests exemption from requirements of 10CFR50 54(m)(2) & (3).licensed operator staffing Second shift supervisor not necessary due to plant size & simplicity lech Specs correcting current staffing differences submitted 821220 VANDEHALLED J Consumers Power Co 83/10/03 CRUICHFIELD D Operating Reactors Branch 5 2pp 20648 333 24% Fiche 50-155.83/10/03.8310060080
- B310180452 Forwards notice of consideration of issuance of amend to ticense DPR-6 to incorporate MAPLHOR limits for fuel assemblies G13 & G14 into Tech Specs, per util B30707 application CRUTCHFIELD.D Operating Reactors Branch 5 B3/10/04 VANDEMALLE, D J Consumers Power Co 3pp 20802 112 24x Fiche 50-135,83/10/04.8310180452
- ~-8310180457 Notice of consideration of issuance of amend to License DPR-6 to incorporate MAPLHGR limits for fuel assemblies GI3 & GI4 into Tech Specs, per util B30907 application CRUTCHFIELD.D Operating Reactors Branch 5 B3/10/04 6pp 20802 115 24X Fishe 50-155,83/10/04.8310180452
- 8310120274 Advises that FR.containing Commission monthly notices which afford public opportunities for hearing on requests for action will be transmitted w/o forwarding ltm in future CRUICHFIELD. D. Operating Reactors Branch 5 83/E0/07 VANDEWALLE.D.J. Consumers Power Co. 3pp. 20691 047 24% Fiche 50-000.83/10/07.8310120274
- 8310130296 Forwards formal responses to NRC 830817 & 0915 requests for addlineo re seismic capability of semigantry crane Responses transmitted informally on 830825 & 0923 BDRDINE.T C Consumers Power Ca 83/10/07 CRUTCHFIELD.D Operating Reactors Branch 5 1p 20719 275 24X Fiche 50-155.83/10/07.8310130496
- --8310130297 "CPC Responses," discussing semigantry crane * Whiting Corp 83/08/25 10pp 20719 276 24X Fiche 50-155,83/10/07,8310130296
- --8310130298 "Seismic Rish Contribution of Reactor Bldg Crone to Big Rock Point Spent Fuel Pool " * Structural Mechanics Associates 83/08/25 18pp 20719 286 24X Fichs 50-155.83/10/07.8310130296
- --83i0i30299 "CPC Responses." comparing SRP Section 3 7 2 W/bldg & crane analyses + D'Appolonia Consulting Engineers, Inc 83/09/23 20pp 20719 304 24X Fiche 50-155,83/10/07.8310130296
- --8310130301 "Analysis Methodology, Crane Seismic Rept 75/5/ Ton Gantry, Crane 8577 " • Whiting Corp 83/09/23 app 20719 324 24X Fiche 50-155.83/10/07.8310130296

- --8310130302 "Uncertainty in Variables Affecting Crane Responses" * Structural Mechanics Associates 83/09/23 Hpp 20717 32/ 247 Fiche 50-155,83/10/07,8:10130296
- 8310270219 Application for amend to License DPR-6, changing Tech Spec reactor vessel pressure/temp limits VANDEWALLE, D. J. Consumers Power Co. B3/10/24 CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 20924-077 24X Fiche 50-159,83/10/24,8310270219
- --8310270221 Proposed Foch Spec Table 4-1 changing hydrostatic tert pressure/temp limits, heatup pressure/temp limits & cooldnum pressure/temp limits to 18 EffY * Consumers Power Co 83/10/24 16pp 20924 080 24X Fiche 50-155.83/10/24.83102/0219
- 8310310376 Forwards supplemental application for amend to License DART-6, revising lech Specs to expand spent fuel pool storage capacity, per 770626 application VANDEHALIE, D. J. Consumers Power Co. B3/10/25 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp. 20959 242 24X Fiche 50-155,83/10/25,8310310376
- --8310310379 Supplemental application for amend to License DPR-6.10v1st Tech Specs to expand spent fuel pool sturage capacity.per 790626 application DEMITT.R B Consumers Power Co 83/10/25 3pp 20959 244 24K Fiche 50-155.83/10/25.8310310376
- --8310310383 Proposed Tech Specs re spent fuel pool storage capacity expansion * Consumers Power Co 83/10/25 5mp 20959 247 24X Fiche 50-155,83/10/25,8310310376
- 9 Inspection reports. IE Bulletins & correspondence
- 8310060360 Forwards IE insp Rept 50-155/8J-14 on 830723-0909 & notice of violation SHAFER.W D Region 3, Office of Director 83/09/21 DEWITT.R B Consumers Power Co. 2pp. 20646 110 24X Fiche 50-155,83/09/21, 8310060360
- --8310060372 Notice of Viplation from insp on 830723-0909 SHAFER: W D Region 3, Office of Director 83/09/21 ! 20446 112 24% Fiche 50-155,83/09/21,8310060360
- --8310060374 IE Insp Rept 50-155/83-14 on 830723-0909 Noncompliance nated failure to implement control of tools WRIGHT OC. BOYO. D. C. Region 3. Office of Director 83/09/20 7pp 20446 113 24x Fiche 50-155,83/09/21,8310040360
- B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3709/26 Consolidated Edison Co of New
 York, Inc 117pp 20754 022 24X Fiche 50-000,83709/26,83000000240
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Oas Detectors Positioned at Control Room Ventilation Air Intales " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26.83080000342
- 8308300345 IE Info Notice 85-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fest 830103) 83709726 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83709726,8308300345
- 9308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50~000,83/09/29,8300300349
- 8310120326 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 90-155/83-12
 NDRELIUS, C E Division of Project & Resident Programs 83/10/05
 DEWITT R B Consumers Power Co ip 20700 267 24X
 Fiche 50-155,83/10/05,8310130326
- --B310120327 Responds to NRC 830822 ltr re violations noted in IE Insp Rept 50-155/83-12 Corrective actions roution signs on breaker cabinets modified & administrative procedures & training will be revised by 831215 VANDEWALLE, D. J. Consumers Power Co. B3/09/21 KEPPLER, J.G. Region 3, Office of Director. 3pp. 20700 268—24X Fiche 50-155, 83/10/05, 8310120326

- B308300378 IE Info Notice B3-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, I. Division of Emergency Properedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000.B3/10/07,8308300378
- B308300752 IE Info Notice B3-64. "Fatality at Argentine Critical Facility " Svc list encl JORDAN, F L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Ldison to of New York, Inc. 79pp 20882 026 24% Fiche 50-000, B3/10/07, B308300792
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Notices Gases " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,83083000757
- #308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post #30103) #83/10/11 Consolidated Edison Cn. of New York, Inc. 120pp 20827 129 24X Fichs 50-000,83/10/11.8308000761
- 8310180262 Clarifius NRC position re procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in sucl Update will be provided every 6 months
 AXELSON.W L. Region 3, Office of Director 63/10/14 DEWITT,R B Consumers Power Co. 7pp. 20802 282 24X Fiche 50-155,83/10/14, 8310180262
- 8310180551 Notification of 831021 meeting w/BWR licenses in Bethesda.
 MD to discuss future insps for intergranular stress
 corresion cracking
 MIRAGLIA:F J Assistant Director for Safety Assessment BJ/10/14
 EISENHUT.D G Division of Licensing 5pp 20823 35B 24Y
 Fiche 50 000.03/10/14.8310180551
- 8310250191 Forwards final SALP Rept 50-255/83-21 for Jul 1982 June 1983 Licensee improvement since earlier assessments noted KEPPLER, J G Region 3, Office of Director 83/10/20 DEWITT, R D Consumers Power Ca 2pp 20894 001 24% Fiche 50-000,83/10/20,8310250191
- --8310250203 Informs that licensee will meet all commitments in plant regulatory performance improvement program, in response to NRC 830909 ltr transmitting SALP for Jul 1982 June 1983 VANDEWALLE, D. J. Consumers Power Co. 83/09/26 KEPPLER, J. Q. Region G. 08ftc of Directo 1 p. 20894 036 24X Fiche 50-000,83/10/20,8310250191
- 8310250522 Forwards BALP Rept 50-155/83-15 for Jul 1982 June 1983 Util has improved rating in five functional areas including satisfactory resolution of previously identified concerns KEPPLERIJ 9 Region 3. Office of Director 83/10/20 DEWITT,R B Consumers Power Co 2pp 20900 316 24X Fiche 50-155.83/10/20. 8310250555
- --8310250535 SALP Rupt 50-155/83-15 for Jul 1982 June 1783 Licensee should develop & implement program to identify applicable regulatory requirements & licensee commitments to onsure compliance w/GA activities All other areas acceptable * Region 3, Office of Director 83/10/20 24pp 20700 318 24x Fiche 50-155,63/10/20,8310250522
- --8310250548 Discusses proposed 830916 mouting to discuss SALP for Jul 1982 June 1983 SALP rept documenting analyses conclusions & recommendations provided for review prior to meeting Comments on rept to be discussed at meeting HIND. J A Division of Radiological & Materials Bafety Programs 83/09/09 DEMITT.R B Consumers Power Cs 3pp 20900 342 24X Fiche 50-155,83/10/20,8310250522
- S Reportable occurrences, LERs & related correspondence
- 8310120110 LER 83-011/03L-O on B30828, packing leak occurred on inlot valve M07062 in loop 1 of emergency condenser Caused by inlet valve opening time being slower than outlet valve time Packing replaced W/830928 ltr
 BORDINE: 1 C Consumers Power Co 83/09/28 KEPPLCR. J Q Region 3. Office of Director 2pp 20694 171 24X Fiche 50-155.83/09/28, 8310120110
- B310170465 Updated LER B2-023/03X-1 on B20801.backup core spray valve M0-7071 opening stroke found approx 1/2 normal full stroke Caused by marginal clotch New model operator installed W/B31006 ltr B0RDINE.T C Consumers Power Co B3/10/06 KEPPLER.J G Region 3, Office of Director 2pp 20/83 250 24X Fiche 50-155.83/10/06, B310170465

- 83i0170484 Updated LER 82-021/03X-1 on 820707.during quarterly test of backup core spray valve M0-70/1.both open & closed position indication lights remained on w/valve returned to normal closed position Caused by worn clutch W/831004 ltr BORDINE.1 C Consumers Power Co 83/10/06 KEPPLER.J 9 Region 1.0ffice of Director 2pp 20/83 340 24X Fiche 30-155.83/10/06.8310170486
- 8310170552 Updated LER 82-017/03X-1 on 820503 backup core sprny sysatutomatic valve MO-7071 made inoperable in closed position for repair & troubleshooting Limit switch in closing control circuit adjusted W/831000 ltr
 BORDINE-T C Consumers Power Co 83/10/06 KEPPLER-J G Region J. Office of Director 1p 20780 349 24X Fiche 50-155,83/10/06,8310170552
- 8310270245 LER 83-013/03L-0 on 830921, following lightning strike, blown fuse observed on static inverter equipment for one of two containment vacuum relief loops Telephone & security equipment & domestic water controls affected W/831020 ltr BORDINE, T C Consumers Power Co 83/10/20 KEPPLER, J 9 Region 3, Office of Director 2pp 20924 047 24X Fiche 50-155.83/10/20, 83102/0245
- T Hearing transcripts on non-antitrust matters
- 8310040620 Testimony of Christa-Maria, Bier & Mills on Christa-Malia Contention 8 & D'Neill Contention III-2 re makeup water line CHRISTA-MARIA Christa-Maria 83/09/25 12pp 20626 062 PAX Fiche 50-155.83/09/25.8310040620
- --83100406P1 Testimony of Christa-Maria, Bier & Mills on Christa-Maria Contention 2 & O'Meill Contention IIA re south wall workers CHRISTA-MARIA Christa-Maria 83/09/28 5pp 20626 074 P4X Fiche 50-155,63/09/29,8310040620
- --8310040624 Testimony of Christa-Maria. Dier & Mills on O'Neill Contention II E 4 re adequate containment shielding Certificate of Svc encl CRRISTA-MARIA Christa-Maria 83/09/JO 3pp 20626 079 24X Fiche 50-155.83/09/25.8310040620
- 8310040553 Forwards testimony of RM Sinderman re Christa-Maria emergency planning Contention 9 Testimony concludes that no justification exists for enlarging size of present emergency planning zones OALLO.J Isham, Lincoln & Beale GALLO.J Consumers Power Co 83/09/29 BLOCK, P B . SHON.F J . PARIS.D H Atomic Safety and Licensing Board Panel 2pp 20623 217 24X Fiche 50-195.D3/09/49, 8310040583
- --8310040557 Tostimony of RW Sinderman on Christa-Maria Contention 9 19 size of emergency planning zones SINDERMAN, RW Consumers Power Co 83/09/29 35pp 20623 214 24X Fiche 80-155,83/09/29,8310040557
- G310040345 Forwards CE Axtell.RM Sinderman & EF Beni testimony re Christa-Maria Contention 2 & O'Neill Contention IIA CALLO.J Isham, Lincoln & Beale OALLO.J Consumers Power Co B3/09/30 BLOCH.P B , PARIS.O H , SHON.F J Atomic Safety and Licensing Board Panel 2pp 20621 017 24X Fiche 50-155.83/09/30. B310040365
- --8310040367 Yestimony of RW Sinderman re Christa-Maria Contention D & O'Neill Contention 11A on use of appropriate coefficients & ALARA program Util has implemented comprehensive radiation safety program SINDERMAN, R W Consumers Power Co 83/09/30 10pp 20601 017 24X Fiche 50-155.83/09/30,8310040365
- ~~8310040369 Testimony of EF Benz re Christa-Maria Contention 2 & O'Neill Contention IIA on radiation dose rate measurement outside south wall from spent fuel stored in spent fuel pool BENZ:EF Consumers Power Co 83/09/30 14pp 20621 029 24) Fiche 50-155,63/09/30,8310040365
- --8310040373 Testimony of CE Axtell re Christa-Maria Contention 2 & G'Neill Contention IIA on dimensions of south wall of spent fuel pool Discrepancy has no effect on radiation dose calculations provided by util AXTELL.C E Consumers Power Co 83/09/30 186pp 20621:043, 24X Fiche 50-155,83/09/30,8310040365
- 8310040376 Forwards HJ Eckert & MK Prabhakara bestimony re Contentions 8 & IIIE-2 on structural integrity of spent fuel pool concrete GALLO.J Isham Lincoln & Beale GALLO.J Consumers Power Co G3/09/30 BLOCH.P D . PARIS.O H . SHON.F J Atomic Bafety and Licensing Board Panel 2pp 20618 001 24X Fiche 50-155.83/09/30. B310040376

- --B310040381 Yestimony of HJ Eckert & MK Prabhakara re Christa-Maria Contention 8 & D'Neill Contention IIIE-2 on structural integrity of concrete spent fuel pool if pool coolant temprises to 150 F for extended period of time ECKERT. H J. PRABHAKARA. H K Consumers Power Co. ECKERT. H J. NUS Corp. B37097/30 378pp. 20618 003 24x Fiche 50-155.83/097/30.83100.463374
- 8310040505 Forwards JV Lyczkowski & W Hickey joint testimony re U'Nc;11 Contention IA re Ohio Natl Quard flights in plant vicinity Related correspondence OALLO.J Isham. Lincoln & Beale QALLO.J Consumers Power Co 83/09/30 BLOCH.P B , PARIS.D H , SHON.F J Atomic Safety and Licensing Board Panel 1p 20625 245 24X Fiche 50-155.83/09/30.8310040505
- --8310040517 Testimony of JV Lyczkowski & NP Rickey is O'Neill Contention IID on Dhio Natl Quard firights in plant vicinity Chance of accident at plant is less than one in one hundred million LYCZKOWSKI, J V . HICKEY, W P Consumers Power Co LYCZKOWSKI, J V Ohio, State of 83/09/30 21pp 20625 246 24% Fiche 50-155,83/09/30.8310040505
- 8310040545 Testimony of Christa-Maria on emergency planning & risk of aircraft contentions CHRISTA-MARIA Christa-Maria 83/09/30 62pp 20623 147 P4X Fiche 50-155,83/09/30.8310040545
- B31004054B Forwards testimony of RW Sinderman re O'Neill Contention IIE-4 Testimony justifies adequacy of containment shell GALLO.J Isham, Lincoln & Beale GALLO.J Consumers Power Co B3/09/30 BLOCH.P B . PARIS.Q H . SHON.F J Atomic Bafety and Licenting Board Panel 2pp 20622 121 24X Fiche 50-199.83/09/30. B310040548
- -831004056B Testimony of RW Sinderman re O'Neill Contention IIE-4 withesking adequacy of steel containment shell SINDERMAN R W Consumers Power Co. 83/09/30 /pp 20682 123 24% Fiche 80-185, 83/09/30, 8310040848
- 831004085# Forwards CE Artell & RM Marusith testimony re Christa Maria emergency planning Contention 9(6)
 OALLO, J. Isham. Lincoin & Beate GALLO, J. Consumers Power of 83/09/30 BLOCH, P.B., PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Board Panel ip 20422 130 24% Fiche 50-155,83/09/30,831004055#
- --8310040560 Testimony of RM Marusich re Christa-Maria Contention 9(6) on emergency planning - radiation monitoring Util has capability to assess degree of core damage promotly following accident MARUSICH R M Consumers Power Co 83/09/30 16pp 20622 131 24% Fiche 50-155,83/09/30,8310040351
 - Di0040564 Testimony of CE Artel) re Christa-Maria Contention 7(6) on swargency planning radiation monitoring Use of noble gas effluent monitors, implant indine instruments & containment high-range radiation monitors discussed AXTELL. C E Consumers Power Co 83/09/30 13pp 20622 147 24X Fiche 50-155,83/09/30,83/09040551
 - 0040594 Forwards AE Tome testimony on D'Neili Contention 11-D relisk of accident from crashes of certain aircraft
 ALLO, J. Isham, Lincoln & Beate GALLO, J. Consumers Power Co.
 3/09/30 BLOCH, P. B. PARIS, D. H. SHON, F. J. Atomic Bafety and icensing Board Panel. 2pp. 20626-169 24X Fiche 50-155,83/09/30,310040594
 - 310040611 Testimony of AE Tome on O'Neill Contention II-D re risks from unscheduled general aviation flights
 TOME.AE Consumers Power Co. TOME.AE Wood-Leaver & Associates, Inc. 83/09/30 449p 20626 191 24X
 Fiche 50-155,83/09/30,8310040594
- 310050461 Testimony of KM Campe on O'Neill Contention II D re nircraft hazards at plant Risk of aircraft crash & impact on plant sufficiently low so aircraft impacts need not be design basis for plant CAMPE.K M Site Analysis Branch 83/09/30 88pp 20629 041 24X Fiche 50-155,83/09/30,8310000461
- --8310050478 Testimony of 8 Djock re Christa-Harta Contention 2 & O'No.11 Contention II A Util calculations of dose rate at south boundary of spent fuel pool acceptable BLOCK.8 Division of Systems Integration (post 811005) 83/07/30 9pp 20629:132 24X Fiche:50-155.83/09/30.8310050464

- --83100504B1 Testimony of Mi. Wohl to U'NCOLL Contention II E. 4 Adequat shielding of containment blig exists to protect public from potential radioactivity releases from expanded spent fuel pool WOHL, M. L. Accident Evaluation Branch 83/09/30 7pp 20/07/34/24X Fiche 90-195 83/09/30-8310050461
- --B3:0050485 Testimony of MP Phillips re Christa-Maria Contention 9, Subparts 1,6.8 % 9 Discusses how possibility of feel pool accident considered in determining planning basis for size of emergency planning rone PHILLIPS M P Division of Radiological & Materials Safety Programs 83/09/30 54pp 20629 148 24X Fiche 50-155,87/09/3 8310050441
- --B310030495 Testimony of D Persinko re Christa-Maria (ontent) on 0 b O'Noill Contention III C-2.Genuino Issue of Fact 5 Spent fuel structure adequate to withstand increased load from pool expansion for water temp up to 350 f PERSINKO, D Systematic Evaluation Program Branch B3/09/30 7p 20629 204 24% Fiche 50-155.83/09/30.8310050461
- --8310050500 Testimony of P Chan re Christa-Maria Contention (1 & (*Ne Contention (1) E-2, Genuine Issue of Lart 1 Spent fuel pos) makeup line adequately designed for seismic loads CHEN.P Systematic Evaluation Program Branch 83/09/30 10pp 20629 211 24X Fiche 50-155, 03/09/30, 0310050461
- --8310030504 Testimony of MA Caluso be Christa-Maria Contention of & G'Naill Contention II E 2.Genuine Issue of Fact 5 Temp gradients acceptable for input into structural analysis CARUSOL M A Operating Reactors Assessment Branch 83/09/30 7, 20629 221 24X Fiche 50-155.83/09/30.8310050461
- --83i00505i4 Testimuny of F Clemenson & RL Emch re Christa-Molia Contention B & D'Neill Contention II E-2. Genuine Issue of Fact I Remotrly activated makeup water sys is reliable Certificate of Gyc encl CLEMENSON, F Auxiliary Systems Branch EMCH.R I Division of Licensing 83/09/30 33pp 20629 228 24x Fiche 50-155, B3/09/30.8310050461
- 8310050483 Motion for leave to file util testimony out of time on Contention 9(8) Delay due to preconcilable differences between uitnesses, necessitating reapphaisal of util case Certificate of Syr enc!

 GALLO, J. Consumers Power Co. GALLO, J. Isham, Lincoln & Neals 83/10/02 Atomic Safety and Licensing Board Panel Spp. 20633 236 24% Fiche 50-155,83/10/02.8310050483
- ~-8310050486 Forwards RW Sinderman, RD Klimm, E Muma, F We)th & GT lasa testimony on emergency planning Contention 9(8)
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/02 BLOCH, F B. PARIB, O H., SHON, F J Atomic Safety and Litersing Board Panel 3pp 20633 241 24X Fiche 50-155, B3/10/02,8310030483
- -8310060487 Testimony of RW Sinderman re Christa-Maita Contention 9 on summer & winter emergency plans Evacuation time estimates take into account seasonal factors Plan adequately addresses summer & winter conditions
 SINDERNAN, RW Consumers Power Co 83/10/02 34pp 20633 244
 24X Fiche 50-155,83/10/02.8310050483
- ~-8310090491 Testimony of RD Kljmm re Christa-Maria Contention 9:8) summer & winter emergency plans Evacuation time estimate studies address summer & winter conditions KLIMM.R D Consumers Power Co KLIMM.R D HMM Associates, Inc. 83/10/02 17pp 20633 278 24X Fiche 50-155.83/10/02.8310050
- ~~8310050494 Testimony of E Muma re Christa-Maria Contention 9(8) of summer & winter emergency plans County emergency plan flexible enough to accommodate influx of seasonal population during summer & adverse winter weather MUMA, E. Consumers Power Co. NUMA, E. Charlevoix, NI. 83/10/0, 7pp. 20633 295 24X Fiche 50~155,83/10/02,8310050483
- ~~8310050501 Testimony of GT Lasater re (hrista-Maria Contention V()
 summer & winter emergency plans Summer/winter conditions
 will not have effects significant enough to require separate
 planning
 LABATER, G T Consumers Power Co LABATER, G T Charlevois, M1
 83/10/02 7pp 20633 302 24% Fiche 50~155.83/10/02,83100504
- ~-8310050507 Testimony of F Welch re Christa-Maria Contention 9(8) summer & winter emergency plans Emergency plan will accommodate difficulties posed by winter weather WELCH.F. Consumers Power to WELCH.F. Consumers Power to WELCH.F. Charlevoix, MI 83/10 10pp 20603 307 24% Fiche 50-155.83/10/02.8310050483

- 10110045 Forwards R Marwsich testimony on G'Neill Contention 11 D 3ALLO, J Isham, Lincoln & Beule GALLO, J Consumers Power Co 33/10/04 BLOCH, P.B., PARIS, O.H., SHON, F.J., Atomic Safety and Licensing Board Panel 2pp 20465 278 24% Fiche 50-155,83/10/04,8310110045
- 8310110293 Testimony of RN Majusich re U'Neill Contention II-D on risks from unscheduled general aviation flights Probability of crash within SRP criterion MARUSICH, R M Consumers Power Co 83/10/04 7pp 20645 280 24X Fiche 50-155,83/10/04,8310110045
- iol30001 Testimony of NC Chokshi % B Persinko re O'Neill Contention II C.as restated in ASLB 820217 order le spent fuel pool mod Prof qualifications encl CHOKSHi N C Structural & Geotechnical Engineering Branch PERSINKO, D Systematic Evaluation Program Branch 83/10/0/ 18pp 20725 236 24x Fiche 50-155.83/10/07.8310130001
- B3i0130002 Testimony of L. Reiter te site specific spectra (earthquake ground motion) Prof qualifications & Certificate of Svc oncl
 REITCR.L. Geosciences Branch B3/10/07 23pp 20725 254 24X
 Fiche 50-105,83/10/07,8310130001
- iiO120211 Forwards CR Norman,YF Chan,SB Beachum,RB Jenkins,Pl Yanev, AJ Eggenberger & DJ VandeWalle testimony on D'Neill Contention IIC re seismic stability of overhead containment
- Contention IIC reseismic stability of everhead containment crame
 crame
 GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co
 83/10/08 BLOCH, P.B., PARIS, O.H., SHON, F.J. Atomic Safety and
 Licensing Board Panel 2pp 20688 045 24X Fiche 50-155, 83/10/08,
 8310120211
- -8310120215 Testimony of CR Norman re O'Neill Contention 11C on seismic stability of overhead crane Crane will not deform permanently, become unstable or tip over due to postulated seismic loading NORMAN. CR Consumers Power Co NORMAN. CR Whiting Corp 83/10/08 140pp 20688 067 24X Fiche 50~195,83/10/08,8310120211
- -8310120218 Testimony of YF Chan re O'Ncill Contention IIC on seismic stability of overhead crane Crane supports & crane staps structurally sound & able to withstand leadings associated w/pestulated seismic event, w/mod to connection as noted CHAN, Y F Consumers Power to 83/10/00 38pp 20488 230 24X Fishe 50-155.83/10/09 8301019021
- -8310120221 Testimony of SB Beachum & RB Jenkins re O'Neill Contention IIC on seismic stability of overhead crane Mode to trane provide added safety re earthquake loading No anchorage component found deficient BEACHUM.S B., JENKING.R B. Consumers Power Co. 83/10/08 18pp 20688 268 24x Fiche 50-155,83/10/08,8310120211
- -8310120225 Testimony of AJ Eggenbreger to D'Neill Contention IIC on seismic stability of containment crane Summarizes results of methodology used in analyses performed by Whiting Crane Corp & Structural Mechanics Assoc. Inc EOGENBERGER, A D'Appolonia Contuiting Engineers, Inc 83/10/09 373pp 20688 286 24X Fiche 50-155,83/10/08,8310120211
- -8310120227 Testimony of DJ VandeWalle ie O'Neill Contention IIC on seismic stability of containment crane Explains applicable seismic design criteria & genesis & licensing status of earthquake peak ground acceleration VANDEWALLE, DJ Consumers Power Co 83/10/08 9pp 20489 279 24X Fiche 50-155,83/10/08,8310120211
- -8310120233 Testimony of PI Yanev re D'Neill Contention IIC on seismic stability of containment crane Crane. w/mods. will safely perform function during & after earthquake associated w/ postulated ground acceleration of 12g YANEV, PI Consumers Fower Co YANEV, PI EQE, Inc 83/10/08 125pp 20489 308 24% Fiche 50-155,83/10/08,8310120211
- 3310130214 Forwards QP Betourne testimony on Contention 11D re risk of accident from crash of B-52 bomber GALLO, J [Sansumers Power Co Gallo, J [Sansumers Power
- --8310130218 Testimony of QP Retourne on O'Neill Contention IID re risk of B-52 bomber crash Strategic Air Command prohibited use of plant as navigational offset BETURNE. OF Consumers Power Co 83/10/08 20pp 20725 028 24X Fiche 50-155,83/10/08.8310130214

- 8310140074 Forwards J Hess testimony & E Muma revised testimony re Christa-Maria Contention 9(8) on summer & winter emergency plans GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co 83/10/10 BLOCH.P B . PARIS.D H . SHON,F J Atomic Safety and Licensing Board Panel 2pp 20768 023 24X Fiche 50~155,83/10/10, 8310140074
- --8310140076 Testimony of JF Hess re Christa-Maria Contention 9(B) on summer & winter emergency plans Charlevoix emergency plan adequately considers effects of heavy tourism in summer & adverse winter weather conditions
 HESS, J F Consumers Power Co HESS, J F Charlevoix, MI B3/10/13 4pp 2076B 025 24X Fiche 50-155, 83/10/10, 8310140074
- --8310140078 Revised testimony of E Muma re Christa-Maria Contention 9(B) on summer & winter emergency plans Charlevoix emergency plan allows different seasonal conditions to be considered MUMA.E Consumers Power Co MUMA.E Charlevoix MI 83/10/13 6pp 20768 029 24X Fiche 50-155.83/10/10.8310140074
- 8310130174 Forwards DJ VandeWalle new testimony on D'Neill Contention IIC re-seismic stability of containment crane Final revs inadvertently unitted GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co B3/10/11 BLOCH, P B . PARIS, D H . SHON, F J Atomic Bafety and Licensing Board Panel 1p 20724 305 24X Fiche 50-155.83/10/11.8310130174
- --8310:30179 Testimony of DJ VandeWalle re O'Neill Contention IIC on seismic stability of containment crane Explains applicable seismic design criteria & genesis & licensing status of earthquake peak ground acceleration VANDEWALLE.D J Consumers Power Co 83/10/11 9pp 20724 306 24X Fiche 30-155.83/10/11.8310130174
- 8310310350 Transcript of 831025 hearing in Petoskey,MI Pp 2,720-2,976 Supporting documentation encl * Atomic Bafety and Licensing Board Panel 83/10/25 359pp 20956 075 24X Fiche 30-155,83/10/25,831031035
- V Operator Examinations
- 8310250522 Forwards SALP Rept 50-155/83-15 for Jul 1782 June 1783 Util has improved rating in five functional areas including satisfactory resolution of previously identified concerns KEPPLERIJ 0 Region 3. Office of Director B3/10/20 DEWITT.R B Consumers Power Co 2pp 20700 316 24X Fiche 50-135:83/10/20, 8310250522
- --8310250535 BALP Rept 30-135/83-15 for Jul 1982 June 1983 Licensee should develop & implement program to identify applicable regulatory requirements & licensee commitments to ensure compliance w/GA activities All other areas acceptable * Region 3, Office of Director 83/10/20 24pp 20900 318 24X Fiche 50-155,83/10/20,8310250522
- DOCKET BO-160 GENERAL ATOMIC CO
- P Operating license stage documents & correspondence
- 8310180319 Comments on amends to Licenses R-38 & R-67 to reflect name change to OA Technologies Co Amends unnecessary since facilities operational through 1983 HOOAN, J.P. GA Technologies. Inc. /General Atomic Co. 83/10/13 THOMAS.C.O. Standardization & Special Projects Branch. 2pp 20806 231 R4X Fiche 50-089,83/10/13,8310180319
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

 F Security, medical, emergency & fire protection plans
- 8310040239 Requests extension until 831031 to submit emergency plan.
 Hritten agreement w/Montgomery County Fire Dept & Univ of
 Maryland College Park Campus Police Dept awaited
 TOLL.J & Maryland, Univ of, College Park, MD 83/09/29
 THOMAS,C Standardization & Special Projects Brench ip
 20617 274 24X Fiche 50-166,83/09/29,8310040258
- 8310240147 Responds to 830929 request for extension in responding to emergency plan questions Final extension until 83103; granted THOMAS.C O Standardization & Special Projects Branch 83/10/17 TOLL.J S Maryland, Univ of, College Park, MD 1p 20884.341 24X Fiche 50-146,83/10/17,8310240147

V Operator Examinations

- 8310140118 Rev 3 to "Reactor Operator Requalification Program for Maryland Univ Training Reactor " M/830930 ltr TOLL J S Faryland: Univ of, Collage Park MD 83/06/01 THOMAS, C Standardization & Special Projects Branch 18pp 20763 058 24X Fithe 50-166.83/06/01.8310140118
- 8310210138 Requests technical assistance in reviewing & providing evaluation rept to Rev 3 to reactor operator requalification program Rept should identify criteria used to establish bases for program acceptability THOMAS, C 0 Standardization & Special Projects Branch 83/10/17 800HER H R Licensee Gualifications Branch 1p 20883 358 243 Fiche 50~166,83/10/17.8310210138

DOCKET 50-170 NATIONAL NAVAL HEBICAL CENTER

- F Hecurity, medical, emergency & fire protection plans
- 8310210412 Releases public version of licensee notification of emergency plan implementation FELTON J M Division of Rules and Records 83/10/17 Document Management Branch ip 20882 340 24% Fiche 50-170,83/10/17, 8310210412
- -8310210413 Submits public version of notification that Oct 1989 emergency plan implemented & placed into effect on 831007 ADCOCK.B R Defense. Dept of Defense Nuclear Agency 83/10/11 THOMAS.C O Standardization & Special Projects Branch | Ip 20882 341 24% Fiche 50-170.83/10/17.8310210412
- DOCKET 50-17) PEACH BOTTOM ATOMIC FOWER STATION, UNIT 1
 P Operating license stage documents & correspondence
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be place in PDR & list of facilities for which repts are unavailable FELTON. J H Division of Rules and Records 83/07/06 CONNER.L. Affiliation Unknown 1p 21004 271 24X Fiche 30-000.83/07/06.

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERMEAT REACTOR G Inspection reports. IE Bulletins & correspondence

- 8310040391 Forwards IE Insp Repts 50~018/83-01 & 30~183/83-01 on 830907 No noncompliance noted WENSLANGKI,F Region 5. Office of Director 83/09/15 DARMITZEL,R W General Electric Co 2pp 20620 124 24x Fiche 50~018,83/09/15
- --8310040399 lE Insp Repts 50-018/03-01 k 50-183/83-01 on 830907 No noncompliance noted Major areas inspected organization, procedures, surveys, posting & annual repts SHERMAN, C 1 . HENSLAHERI, F A Region 5, Office of Director 83/09/15 3pp 20620 126 24X Fiche 50-018, 83/09/15 8310040391

DOCKET 50-184 UNIV OF MISSOURI RESEARCH REACTOR

- F Security, medical, emergency & fire protection plans
- 83io170347 Forwards request for route approval for shipment from Columbia.MO to Idaho Falls.ID per 10CFR73 37 Same route as approved in 1982 Info re planned shipping dates will be forwarded MEYER.W A Missouri. Univ of. Columbia. MD 83/07/16 HELLMAN.C Division of Safeguards App 20843 173 24X Fishe 50~166.83/07/16.8310170347
- 8310210158 Advises that proposed route to be used for transport of spent reactor fuelper 820916 threacceptable Approval does not provide relief from assuring highway safety nor local or state legislation Spent suchear fuel route survey encl SHERR. T St. Material Transfer Safeguards Licensing Branch 83/10/07 MEYER: H A Missouri. Univ of, Columbia, MO 2pp 20884 062 24X Fiche 50-186,83/10/07.8310210158
- --8310210163 "Spent Nuclear Fuel Route Survey Columbia, MO to Idaho Falls, ID "
 * NRC No Detailed Affiliation Given 83/10/3] 15pp
 50-186,83/10/07,8310210158

- DDCRET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

 R Periodic operating reports & telated correspondence
- 8310130090 Annual operating rept for Oct 1982 Sept 1983 FAMIRE Kanses State Univ 83/10/07 MILLERIJR Standardization & Special Projects Branch & App 20724 059 24X Fiche 50-188.83/10/07.8310130090
- DOCKET 50-192 UNIV OF TEXAS RESFARCH REACTOR

 F Security, medical, emergency & fire protection plans
- 8310110380 Releases public version of revised emergency plan & emergency procedures
 FELTON. M Division of Rules and Records 83/10/05 Document Management Branch 1p 20713 231 24% Fithe 50-172.83/10/05.
- --83;0110386 Forwards public version of revised emergency plans a smergency procedures including Procedures 2 O re emergency classification procedures, 31 re emergency call list k S2 re emergency equipment 9AUER.T.L. Texas. Univ. of, Austin. TX 83/07/21 THOMAS.(O Standardization k Special Projects Branch ip 20713 23.) EAK Fiche 30-192.83/10/05,8310110380
- ---8310110390 Public version of revised emergency plan * Texas, Univ of, Austin, TX 83/07/31 39pp 20713 233 241 Fiche 50-192.83/10/05.8310110380
- --8310110392 Public version of revised emergency plan implementing procedures, including Procedures 2 0 re emergency classification procedures. SI re emergency call list & 52 re emergency equipment * Texas. Univ of Austin, TX 83/07/31 9pp 20713 2/2 24x Fiche 50-192,83/10/05,8310110380
- 8310110424 Releases public version of licensee ltr transmitting ltra of agreement to be included w/revised emergency plan FELTON.J M Division of Rules and Records 83/10/05 Document Management Branch lp 20706 321 24X Fiche 50-192,83/10/05,831010424
- --8310110429 Public version of ltrs of agreement to be included w/revisemergency plan dtd 830721 One add1 ltr of agreement w/local
 hosp not yet received W/830902 ltr
 BAUER, T.L. Texas. Univ of, Austin, TX 83/09/02 THOMAG, C.O.
 Standardization & Special Projects Branch 4pp 20706 322 24x
 Fiche 50-192.83/10/05,8310110424
- DUCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC F Security, medical, emergency & fire protection plans
- B310250997 Forwards IE Bafeguards Insp Rept 50-193/83-02 on B30824-25 No noncompliance noted MARTIN:T T Division of Engineering & Technical Programs B3/10/04 51NEGLTO:A F Rhode Island, State of 2pp 20900 272 P4X Fichs 50-193:B3/10/04:B310250597
- --8310280603 IE Bafeguards Insp Rept 50-193/83-02 on 830824-25 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate strategic significance
 BUNLAP, J M , ODDY A T Region 1, Office of Director 83/09/30 28p 20900 274 24% Fiche 50-193,83/10/04,8310250597
- G Inspection reports, IE Bullotins & correspondence
- 8310250597 Forwards IE Safeguards Insp Rept 50-193/83-02 on 830024-25 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/10/00 DIMEOLIO.A F Rhode Island, State of 2pp 20900 272 24X Fiche 50-193.83/10/04.8310250597
- --B310250403 IE Bafeguards Insp Rept 50-193/83-02 on B30824-25 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate strategic significance DUNLAP.J M., GDDY.A T. Region 1, Office of Director B3/07/30 2pp 20900.274 24X Fiche 50-193,83/10/04,8310250597

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

- P Operating license stage documents & correspondence
- 8310050044 Forwards FR notice of consideration of 830826 application for renowal of License R-94
 THOMAS.C O Standardization & Special Projects Branch 83/09/23
 KANE.R S Manhattan College, Riverdale, NY 2pp 20650 281 24)
 Fiche 50-199,83/09/23.8310050044
- --B310050047 Notice of consideration of Manhattan College 830826 application for renewal of License R-94
 THOMAS.C O Standardisation & Special Projects Branch 83/09/23
 Spp 20450 283 24X Fiche 50-199.83/09/23.8310050044
- **Q** Inspection reports, IE θυλλοτίπε & correspondence
- 8310180377 Ack receipt of 830805 & 17 ltrs informing NRC of steps taken to correct violations noted in IC Insp Rept 50-199/83-01 STAROSTECKI.R Division of Project & Resident Programs 83/10/07 KANE.R Hanhattan College, Riverdale, NY 2pp 20803 192 24X Fiche 50-199,83/10/07.8310180377
- --8310180380 Responds to NRC 830711 ltr re violations noted in IC Insp Rept 50-199/83-01 Requests 3-wk extension to provide complete reply due to changes in personnel Extension will enable implementation of operator requalification program KANE, R S Manhattan College, Riverdale, NY 83/08/05 STAROSTECKI, R Division of Project & Resident Programs 2pp 20803 194 24x Fiche 50-199,83/10/07,8310180377
- ---8310180363 Responds to NRC 830711 Itr re violations noted in IE Insp Rept 50-199/83-01 Corrective actions requalification program will be conducted continuously over 2-yr cycles & revised as needed to account for changes in equipment KANE,R S Manhattan College, Riverdale, NY B3/08/17 STAR0STECKI,R Division of Project & Resident Programs 5pp 20803 196 24X Fiche 50-199.83/10/07.8310180377

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- G Adjudicatory correspondence
- 8310070156 Forwards Director's Decision 83-14, denying 830909 10CFR2 206 petition re transport of spent nuclear fuel from Most Valley DAVIS.J & Office of Nuclear Material Safety & Safeguards, Director 83/09/30 CELEBREZZE, AJ Ohio, State of 2pp 20680 308 24X Fiche 50-000, 83/09/30, 8310070156
- --8310070161 Forwards Director's Decision 83-14, denying 830824 10CFR2 206 petition re transport of spent nuclear fuel from West Valley DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/30 RESNIKOFF, M Sierra Club ip 20680 309 24X Fiche 50-000,03/09/30,8310070156
- --8310070167 Notice of issuance of Director's Decision 83-14, denying State of OH & Sierra Club 830909 & 0824; respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/30 2pp 20680 310 24X Fiche 50-000.83/09/30,8310070156
- --B310070171 Director's Decision B3-14, denying State of OH & Sierra Club B30909 & OB24, respectively, IOCFR2, 206 prtitions retransport of spent nuclear fuel from West Valley Request for hearing & for preparation of EIS denied DAVIS, J C Office of Nuclear Material Safety & Safeguards, Director B3/09/30 18pp 20680 312 24X Fiche 50-000, B3/09/30, B310070156
- 8310270297 Order extending time until 831128 for Commission to act to review Director's Decision DD-83-14, denying Sierra Club & State of OH requests
 CHILK: 8 J Office of the Secretary of the Commission 83/10/25
 Commissioners ip 20923 195 24X Fiche 50-000, 83/10/25, 8310270297
- I Financial information
- B310120005 FDIA request for documents to costs & const of & improvements to Mostern New York Nuclear Svc Ctr, West Valley, NY ARNOLD, Ø A Show, Pittman, Potts & Trowbridge 83/06/27 Office of Administration 2pp 20751 069 24X Fiche 50-201, 83/06/27, B310120005

- 8310120006 Responds to FOIA request for documents re costs & const of & improvements to Western New York Nuclear Svc Ctr. West Valley, NY Forwards documents listed in App A Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/14 ARNOLD. Q A Shaw. Pittman. Potts & Troubridge 3pp 20751 071 24X Fichs 50-201.83/0//14.8310120006
- ~~831012000B Forwards schedule showing source & application of funds for Mar-June 1984 to demonstrate that wendor has necessary funds to continue const of facility, per 660322 ltr RUNION.T C Nuclear Fuel Services, Inc (subs of Getty Dal Co) 66/03/2B HCDRIDE.J A Atomic Energy Commission 2pp 20751 074 24X Fiche 50-201,83/07/14,8310120006
- ~-B310120009 Forwards schedule showing vendor consulidated balance sheet as of 660228 & consulidated balance sheet projected for 66031 Addl line of credit of \$1,000,000 received from MFg & Traders Trust Co Ltr entl RUNION,T C Nuclear Fuel Bervices, Inc (subs of Getty Oil Co) 66/03/22 NORRIDE: JA Atomic Energy Commission 5pp 20751 076 24X Fiche 50-201.83/07/14,8310120006
- --8310120011 Forwards "Info Subsequent to CP Submission 5," from vendor, requesting extension of const completion date to 660630 Request includes financial data to cover period through 660630 BECHMORER.B G Scharfeld, Bechhoefer & Baron 66/02/25 MCBRIDE.J A Atomic Energy Commission 1p 20751 081 24X Fiche 50-201.83/07/14.8310120006
- --8310120012 Application to amend License CSF-1, extending comst completion date to 660630 Certificate of Svc & consolidated balance sheet encl RUNION.T C Nuclear Fuel Services, Inc (subs of Getty O₁1 Co) 66/02/24 9pp 20751 0B2 24X Fiche 50-201,83/07/14.8310120006
- ~-8310i20013 Forwards "Info Subsequent to CP Submission 3," containing suppl info requested by NRC Info in Part 1 covers statement of general financial responsibility Info contained in second part should be withheld (ref 10CFR2 790)
 RUNION,T C Nuclear Fuel Services. Inc (subs of Getty Gil Co) 65/08/25 MCRIPE. JA Atomic Energy Commission 1p 20751 071 24X Fiche 50-201.83/07/14,8310120006
- --8310120014 Application to amend License CBF-1 supplementing or replacing & superseding Paragraph 7 re applicant financial responsibility RUNION.T C Nuclear Fuel Services. Inc (suba of Getty Dil Co) 65/08/25 4pp 20751 092 24X Fiche 50-201.82/07/14.8310120006
- --8310120015 Forwards "Info Subsequent to CP. Submission 2." dtd 650719, Certificate of Svc & marked-up "Info Subsequent to CP Bubmission 1" BECHHDEFER, B G Scharfeld, Beckhoefer & Baron 65/07/19 HCBRIDE, J A Atomic Energy Commission 1p 20751 076 24X Fiche 50-201.83/07/14.8310120006
- --8310120020 Discusses current appraisal of NFB reprocessing project Summary of most current cost review encl Addl data will be included in semiannual rept to be filed in Oct 1964, in connection w/licensing procedure.
 RNNION, T C Noclear Fuel Services. Inc (subs of Getty Oil Co).
 64/08/17 SCABORO, O T Atomic Energy Commission Spp 20751 137 24X Fiche 50-201.83/07/14, B310120006
- --B310}20023 Notifies that on 640402, substantially all fixed assets & portion of quick assets of fuel fabrication facility at Port Hope were sold & transferred by NFB to Canadian Hestinghouse Co.Ltd BECHHOEFER B Q Scharfeld, Bechhoefer & Baron 64/05/15 JOHNSON, L E Atomic Energy Commission ip 2075} 140, 24X fiche 50-201.B3/07/14.8310120006
- --8310120026 Order amending provisional CP CPCSF-2 to require NfS to file rept covering 6-month period ending Mar 31 & Sept 30 of each yr w/Director of Div of Licensing RIGOS.E. | MOLMAN.A. | CALLIHAN.D. | Atomic Safety and Licensing Board Panel 63/11/29 | Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.) | App. 20751 141 | 24% Fiche 50-201.83/07/14.8310120006
- --B31012002B Response to applicant motion for amend to provisional CP CPCSF-2 Info provided by applicant in proposed "NFS Exhibit E" & in statement of Commission 630316 memorandum & order "CONNER, T B Nuclear Fuel Bervices, Inc (subs of Getty Oil Co.) CONNER, T B New York, State of CONNER, T B Atomic Energy Commission 63/11/14 7pp 20751 145 24X Fiche 50-201, B3/07/14,8310120006

- --8310120030 Statement in support of NFS 631023 motion requesting Commission take actions on loan arrangements & submittal of financial repts Draft NFS motion. Certificate of byc & term loan agreement encl RUEBKAUSEN.O M New York, State of * Affiliation Unknown 63/10/29 23pp 2075) 152 24% Fiche 50-201.83/07/14.8310120006
- --8310120032 Memorandum & order amending CPCSF-2 by incorporating condition to require applicants to furnish evidence of financial qualifications adequate to constitute proper basis for required finding MCCUDL.W G Acomac Energy Commission 83/09/13 Nuclear Fuel Services, Inc. (subs. of Gatty Dil Co.). 4pp. 20751-175 24X Fichs 50-201.83/07/14.8310120006
- --8310120034 Forwards Amend 1 to NFS 630130 CP application submitted by NY State Atomic & Space Development Authority Certificate of Bvc encl
 RUEBHAUSEN.O M Debevoise & Plimpton 63/04/09 MCCCCL.W B Atomic Energy Commission Ip 20751 1/9 24X
 Fiche 50-201.83/07/14.8310120006
- ~-8310120036 Nemorandum of Agreement between NY State Oft of Atomic Development & NY State Atomic R&O Authority to coordinate respective responsibilities for development of Atomic energy Certificate of Svc encl
 AKELRAD, M Atomic Energy Commission TOUNSEND, D . FEROUSON, W
 New York, State of 63/03/21 13pp 20751 184 24X
 Fiche 50-201.83/07/14.8310120006
- --8310120037 Responds to 630213 ltr re NFS application for licenses
 Memorandum of Agreement between NY State Ofc of Atomic
 Bevelopment & NY State Atomic R&D Authority from Governor of
 State of NY encl
 TOHNSEND, O New York, State of 63/04/08 LOHENSYEIN, R Atomic
 Energy Commission 2pp 20751 197 24X Fiche 50-201.83/07/14,
 8310120006
- --8310120042 Forwards Amend 4 to Part A of NFS CP application re financial qualifications & related info STUMBLER.A Scharfeld. Beckhoefer & Baron 63/03/29 CONNER.T B Atomic Energy Commission | p 2075| 197 24X Fiche 50-201.63/07/14.8310120006
- --8310120044 Amend 4 to CP application to construct spent fuel reprocessing plant Amend responds to Commission 630314 lt;, requesting add1 financial data re pending application Add1 financial info encl RUNION.T C Nuclear Fuel Services. Inc (subs of Getty Oil Co) 63/03/29 20pp 20751 200 P4X Fiche 50-201, 63/03/14.8310120006
- --B310120047 Forwards Amend 1 to Part A of NFB application for Jicense to construct & operate spent fuel processing plant BECHHOEFER, B G Schanfeld, Bechhoefer & Baron 63/02/13 Atomic Energy Commission 1p 20751 220 24X fiche 50~201,83/07/14.8310120006
- ~-8310120049 Amend 1 to Part A of application for license to construct & operate spent fuel processing plant Certificate of Svc & financial info enci RUNION T C Nuclear Fuel Services. Inc (subs of Getty Oil Co) 63/02/12 32pp 20751 221 24% Fiche 50-201.83/07/14.8310120006
 - 83[0120207 Application to amend License CSF-1, revising Paragraph 5 of original application re applicant financial qualifications RUNION.T C Nuclear Fuel Services, Inc. (subs. of Qebty Oil Co.) a Scharfeld. Bechboefer & Baron. 65/07/15 26pp 20751 097 24X Fishe 50-201.83/07/14.83[0120005

Operating license stage documents & correspondence

- 9310070020 Ack receipt of B30B24 ltr requesting Commission publish notice of pending license amend in FR re New York State Energy R&D Authority license for utils w/irradiated fuci storage facilities
 DAVIS.J 0 Office of Nuclear Material Safety & Safeguards.Director B3/09/22 RESNINGEF.M Sierra Club ip 20671 361 24X Fiche 50-000.83/09/22.8310070020
 - 10280147 Forwards 830930 Director's Decision 83-14, denying State of 3H & Sierra Club 10CFR2 206 potitions re transportation of spent fuel from West Valley facility, per 830930 request 2UNNINGHAM.R E Division of Fuel Cycle & Material Safety 80/10/18 NILLER.F Environmental Policy Institute 2pp 20961 329 24X iche 50-000,83/10/18.8310280147

- DOCKET 50-206 SAN DRIDFRE MUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310030110 Forwards revs to physical security plan Revs withheld (ref 100FR73 21)
 MEDFORD, M D Southern California Edison Co 83/09/29 Division of Liconsing 2pp 20590 051 24X Fiche 50-206.83/09/.19, 8310030110
- 8310130012 Forwards two errata pages to Rev 11 to Mar 1981 physical security plan Safeguards contingency plan submitted on 830923 will replace Chapter 8 of physical security plan by 831215 Pages withheld (ref 10CFR/J 21) MEDFORD M O Southern California Edison Co 83/10/0/ Bivisson of Licensing 1p 20725 208 24% Fiche 50-204,83/10/07,8310130012
- --8310130131 "SEP Topic 111-5 A High Energy Line Break Analysis Instite Containment." For San Onofre Nuclear Generating Station. Unit 1
 4 Bechtel Corp 63/08/05 23pp 20720 003 24X Fiche 50-206.83/10/11.8310130127
- B310130424 Requests fee due per B30211 revised physical security plan be remitted within 15 days of receipt of lti MILLER, W O License Fee Hanagement Branch B3/10/11 DIETCH, R Southern California Edison Co 2pp 20769 242 24X Fiche 50-206,83/10/11,8310130424

H General correspondence

- 8310050071 Responds to 830822 ltr rs seismic upgrading requirements Encl orders relate to seismic upgrading & post-TMI-related issues Util intends to submit plan for early restait for NR(revious & approval CRUTCHFIELD.D. Operating Reactors Branch 5 83/09/27 MERTENS, J Affiliation Unknown 2pp 20639 277 247 Fiche 50-206.83/09/27, 9310050091
- 8310190008 Informs of organizational & personnel changes resulting from Jan 1980 centralization of nuclear engineering & operations dept News to Tech Specs being prepared for future submittal FOGARTY, D J Southern California Edison Ca 83/10/17 DENTON, R R Office of Nuclear Reactor Regulation, Director 2pp 20823 304 24X Fiche 50-206, 83/10/17, 8310190008

P Operating license stage documents & correspondence

- B310310017 FOIA request for documents reintegrated leak rate tests for listed facilities to be placed in PDR CONNER, L. Affiliation Unknown B3/05/02 NRC No Detailed Affiliation Given Ip 21004 2/0 24% Fiche 50-000,83/05/02, B310310017
- 8305240501 Provides status of actions requested in 83040) clarification of 821120 SER on environ qualification of safety-related electrical equipment "Equipment Environ Qualification," technical evaluation rept no longer considered proprietary BASKIN, K.P. Southern California Edison Co. 83/05/20 CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 20932-296-248 Fiche 50-206,63/05/20,6305240501
- --B104070444 "Equipment Environ Qualification, San Opofre Unit 1," proprietary technical evaluation rept released for PDR, pei licensee 330520 jtr CRANE, C.J. Franklin Institute/Franklin Research Center NRC-03-79-118 IER-C5257-179 81/04/03 LOMBARDO, J. NRC No Detailed Affiliation Given 2/0pp 20932 307 24X Fiche 50-206,83/05/20,8305240501
- 8310310031 Responds to FOIA request for documents re integrated load rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON.J M Division of Rules and Records 83/07/06 CONNER.L Affiliation Unknown Ip 21004 271 24X Fishe 50-000,83/07/06,83/07/06
- 8310070283 Forwards multiple response spectra verification for MilOE computer code per SEF Topic 1JI-6, in response to 830802 ltr KRIEGER.R W Southern Callifornia Edison Co 83/09/28 CRUTCHFIELD.D Operating Reactors Branch 5 421pp 20655 288 247 Fiche 50-206.83/09/28.8310070283

- 8310120278 Forwards response to J Mertens 830805 request for addl info re open items involving damaged snubbers & water hammer Assessment of areas complete RAY.H B Southern California Edison Co 83/09/29 MARTIN, J B Region 5, Office of Director Topp 20693 078 24X Fiche 50-206,83/09/29,8310190270
- B31014022J Advises that in initial evaluation of SEP Topic VI-4.
 "Containment Inolation Sys ({lectrical;" penetrations erroneously evaluated against CDC 35 instead of CDC 57 Addl mode to plant configuration unnecessary KRICQER,R W Southern California Edison Co 83/09/30 CRUTCHIELD,D Operating Reactors Branch 5 2pp 20761 1/9 24X Fiche 30-206.03/09/30.8310140223
- 8310060195 Forwards Final evaluation of StP Topic XV-7, "Reactor Coolant Pump Rotor Servers & Reactor Coolant Pump Rotor Servers & Reactor Coolant Pump Shaft Broak " lacility design meets current criteria Evaluation uill be basic input to integrated safety assessment PAULSON.W A Operating Reactors Branch 5 83/10/05 DIETCH, R Southern California Edison Co. "Opp. 20647 137 24X Fiche 50-206, 83/10/05, 8310060195
- B310120170 Forwards comments on draft SER of SEP Topics II-3 A, II-3 B, II-3 B i & II-3 C re hydrology requirements capability & safety-related water supply, respectively Aerial survey date drawlings enci KRIEGER.R W Southern California Edison Co B3/10/05 CRUTCHFILLD.D Operating Reactors Branch 5 7pp 20693 119 24X Fiche 50 %06.81/10/05.8310120170
- 8Ji012039J Informs that transmittal ltr will no longer accompany monthly FR notices Recipients should carefully peruse publication for applicable hearing apportunity notices CRUTCHFICID.D. Operating Reactors Branch 5 83/10/07 DIFICH, R Southern California Edison Co. Pap. P0499-105 P4X Fiche 50-206,80/10/07,8310120893
- 8310130127 Forwards Aug 1983 "SEP Topic 111-5 A High Energy Line Break Analysis Inside Containment " Evaluation will be conducted per implementation of mods required by 10CER90, App R KRIEGER,R W Southern California Edison Co B3/10/11 CRUTCHFIFLD.D Operating Reactors Branch 5 2pp 20720 001 24X Fiche 50-206.83/10/11.8310130127
- --8310130131 "SFP Topic III-5 A High Energy Line Break Analysis Inside Containment," for San Onofre Nuclear Generating Station.Unit 1 * Necktel Corp 83/08/05 23pp 20720 003 24X Fiche 50-206/83/10/11.8310130177
- 6310130316 forwards Addendum 1 to supplemental study rept on SEP lopic 111-5 B. "Effects of Pipe Break Outside Containment" KRIEGER,R W Southern California Edison Co 83/10/11 CRUTCHFIIID,D Operating Reactors Branch 5 ip 20717 101 24X Ficho 50 806-84/10/11.8310130314
- --8310130325 Addondum 1 to "Supplemental Study Rept on Effects of Piping Sys Break Gutside Containment" * Bechtel Corp. 83/08/19 53pp 20717 102 24X Fiche 50-206/03/10/11/8310130316
- 8310200284 Addresses SEP Topic V-A. "Reactor Vessel Integrity," documented in NURFG-0569. "Evaluation of Integrity of SEP Reactor Vessels" SEP Topic V-6 resolved as result of evaluation performed per pressurized thermal shock issue KRIEGER, R W. Southern California Edison Co. 83/10/13 CRUTCHFILD. Operating Reactors Branch 5 2pp. 20829 3PO 24X Fiche 50-206.8J/10/13.83102002844
- 8310250124 Forwards Rev 1 to Calculation BFK-CC-01 1, "Reevaluation of Spent Fuel Storage Racks," in response to NRC 830724 request Racks in fully loaded condition fail to meet seismic criteria MEDFORD, M O Southern California Edison Co 83/10/17 CRUTCHFILLD, D Operating Reactors Branch 5 2pp 20898 189 24X Fiche 50-206,83/10/17,8310250124
- --B31025012B Rev I to "Reevaluation of Spent Fuel Storage Racks " W/four oversize drawlings Aperture cards are available in PDR KUNDALKAR, R., DAY, R. S. Becktel Corp. SRR-CC-01 I R01 83/08/30 34pp 20098 187 24x Fiche 50-206.83/10/17.8310250124
- 8310250196 Piscuss BEP Fopic III-10 A. "Thermal Overload Protection for Motors of Motor Operated Valves." per 810724 safety evaluation Mod of valve motors to bypars thermal overload devices winecestary KRIEGER, R W. Bouthern California Edison Co. 83/10/17 CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 20892 359—24X Fichs 50-206-83/10/17-8310250194

- B310250254 Summary of B31005 meeting w/util % Westinghouse remethodology being used to prioritize backfit projects Viewgraphs encl PAULSDN.W A Uperating Reactors Branch 5 B3/10/20 Deerating Reactors Branch 5 7pp 20898 221 24% Fiche 50-206.83/10/20.
- 8310250630 Forwards proprietary viewgraphs provided at B31005 meeting w/util & Westinghouse Viewgraphs withheld per NRC Manual Chapter 9 5(4) since matl intended for general info will not be used as basis for NRC actions CRUTCHFIELD.D Operating Reactors Branch 5 83/10/24 HIESEMANN, R A Westinghouse Electric Carp 3pp 20899 316 24X Fiche 50-206,83/10/24,8310250630
- 8310270101 Revised Proposed Change 120 to Tech Specs, clarifying 830720 & 0907 submittals re boron dilution reactor criticality & primary plant makeup pump NRC analysis of proposed change should be limited to refueling made analysis & results MEDFORD. N O Southern California Edison Co 83/10/25 DENTON. H R Office of Nuclear Reactor Regulation. Director 3pp 20925 028 24X Fiche 50-206.83/10/25.8310270101
- 8310280141 Advises that commitments in util 830930 ltr re SEP Topic VI-4. "Containment Isolation Sys (Electrical)." NUREG-0578 & NUREG-0737, Item II E 4 2 acceptable No mods to steam generator sample & blowdown lines required PAULSON.W Operating Reactors Branch 5 83/10/27 DIETCH.R Southern California Edison Co. 4pp. 20929 042 PAX Fiche 50-206.83/10/27.8310280141
- G Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 8 20103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000-83/09/26.8308300340
- 830B300342 IC info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Byr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Int 116pp 20777 210 24X Fiche 50-000,83/09/26.8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, C L Divinion of Emergency Preparedness & Engineering Response (Post B30103) 87/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24% Fiche 50-000, 87/09/26, 8308300345
- B31012029B Submits comments on B30826 SALP analyses Decrator errors primarily result of inadequate procedures or training Actions taken to improve training & operating experience feedback in maint program FOGARTY.D J Southern California Edison Co B3/09/28 MARTIN.J B Region 5. Office of Director 2pp 20693 170 24X Fiche 50~206,83/09/28,8310120298
- 8308300349 lE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consulidated Edison Co of New York, Inc. 115pp 20716 324 24% Fiche 50-000,83/09/29,8308300349
- 8310120258 Responds to 830830 confirmatory action ltr re potential cracks in Transamerica Delaval diesel crankshaft No cracks identified in crankshafts Cracked connecting rod bolt washer discovered on rod cap nut 5 of generator 2 RAY, H 8 Southern California Edison Co 83/07/27 MARTIN, J B Region 5. Office of Director 2pp 20691 328 24X Fiche 50~206,83/09/29.8310120258
- #310200208 Forwards 1E Insp Repts 50-206/#3-17.50-361/#3-27 & 50-362/#3-27 on #30804-0716 No noncompliance noted #15H0P.T W Division of Resident Reactor Project & Engineering Programs #3210/04 MCCARTHY.C # Southern California Edison Co 2pp 20834 128 24% Fiche 50-206/#3210704/#3310200208
- --8310200214 IE Insp Repts 50-206/83-19.50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted Major areas inspected operational safety verification witnessing precriticality, initial criticality & low power physics testing CHAFFE.A E. D'ANGELO.A. SIEWART.J P. Region 5. Office of Director 83/09/30 i8pp 20834 i30 24% Fiche 50-206.83/10/04.8310200208

- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Bvc list encl JORDAN.E L Divition of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8306300752 IE Info Notice 83~66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp. 20882 026 24X Fiche 50~000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Nozious Gases " Svc list encl JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York. Inc 17pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Cn of New York, Inc 120pp 20827 127 24% Fiche 50-000,83/10/11,8308360761
- 8310200220 Forwards IE Mot Meeting Repts 50-206/B3-22.50-361/B3-34 & 50-362/B3-34 on B30708 re SALP rept for Jul 1982 May 1983 MARTIN.J B Region 5. Office of Director B3/10/14 MCCARTHY.C B Southern California Edison Co. 2pp 20829 327 24X Fiche 50-206.83/10/14.8310200220
- --8310200224 JE Mgt Meeting Repts 50-204/83-22,50-341/83-36 & 50-362/83-34 on 830708 Major areas discussed SALP rept for Jul 1989 May 1983 KIRSCH,D F Region 5, Office of Director 83/10/13 2pp 20829 329 24X Fiche 50-206.83/10/14.8310200220
- --8310200228 SALP rept for Jul 1982 May 1983 * Region 5. Office of Director 93/07/15 42pp 20829 331 24x Fich* 50-204.83/10/14.8310200220
- --B310200232 Summarizes major investigative activities involving facilities for SALP board review covering Jul 1982 May 1983
 SMACKLETON, B C Office of Investigation 83/06/06 BISHOP, T W Region 5. Office of Director 2pp 20830 011 24% Fiche 50-206,83/10/14,8310200220
- --B30A230142 Evaluates plant LERs for Jul 1982 May 1983 to assist in SALP review Areas re personnel error & saltwater cooling require further evaluation
 SEYFRIT.K V Reactor Operations Analysis Branch B3/06/15
 SIERNBERG.D Division of Resident Reactor Project & Engineering Programs 2pp 20830 013 24% Fiche 50-206.83/10/14.8310200220
- ~-8306170106 Forwards observations from evaluation of LERs for 820701-830530, to assist in SALP review Licensee submittals above average in terms of reporting completeness & factual accuracy
 SEYFRIT.X V Reactor Operations Analysis Branch 82/06/10
 STERNBERGOD Division of Resident. Reactor Project & Engineering Programs 6pp 20830 015 24X Fiche 50-206,83/10/14,8310200220
- -8306170442 Forwards evaluation of LERs for period 820701 to 830530 in support of ongoing SALP review SEYFRIT.K V Director's Office 83/06/10 SIERNBERG, D Division of Resident Reactor Project & Engineering Programs App 20830 021 24X Fichs 50-206.83/10/14.8310200220
- l Periodic operating reports & related correspondence
- 3310190010 Monthly operating rept for Aug 1983 W/830919 ltr SPEER:M J . RAY.H B Southern California Edison Co 83/09/15 Office of Resource Management. Director App 20823 998 24X Fiche 50~206.83/09/15.8310190010
- S Reportable occurrences, LERs & related correspondence
- B310120184 RD 83-004 on 830927, leakage path for introduction of unfiltered outside air into CAEATS created as result of work performed on air conditioning sys during Apr 1981 Ventilation duct capped on 830921 RAY.H B Southern Callfornia Edison Co 83/09/28 MARTIN, J B Region 5. Office of Director 2pp 20695 296 2AX Fiche 50-206.83/09/28,8310120184
- 8310040396 PNO-V-83-041 on 830929.appsor 60 items discovered in unrestricted storage areas Surveys continuing Press release expected MENSLAMSKI,F, KIRSCH,D Region 5. Office of Director B3/09/29 1p 20619 168 24% Fiche 50-206.62/09/29,8310040396

- 9310070301 Potential Part 21 rept re underrange characteristic of Model N-LiiGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified

 BERBERIAN.M J Foxboro Corp 83/09/30 Director's Office, Office, of Inspection and Enforcement 11pp 20651 064 24X

 Fishe 50-000,83/09/30,8310070301
- 8310250455 LER 83-004/01T-0 on 830927.evaluation confirmed operator observation that path for outside air to enter control room existed from Apr 1981 to 830921.bypassing control room emergency air treatment sys filters W/831012 ltr HAYNES.J 0 Southern California Edison Co 83/10/12 MARTIN.J B Region 5. Office of Director 4pp 20897 109 24X Fiche 50-206,83/10/12.8310290455
- 8310250355 PNO-V-83-049 on 831018.const traft person injured working to 12 kV circuit breaker Norkman accidently contacted hot const power supply circuit Smoke observed coming from manhole Plant unaffected MDRRILLEP Region 5, Office of Director 83/10/19 ip 20898 122 24X Fiche 50-205.83/10/19.8310250355
- 8310310284 PNS-V-83-011 on 831024. San Frencisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be unlive or exaggerated SCHAEFER, D. W. NORDERHAUGIL R. Region 5, Deflice of Director 83/10/24 lp 20941 282 24x Fiche 50-206, 83/10/24, 8310310984

V Operator Examinations

8310030109 Requests by 831028 schedule for requalification training & elams for 1984 Schedule needed for periodic audits of licensed operator requalification programs 81SHOP.T W Division of Resident Reactor Project & Engineering Programs 83/09/26 FOGARTY.D J Southern California Edison Co 2pp 20590 053 24X Fiche 50-206.83/09/26.8310030109

DOCKET 50-213 HADDAM NECK PLANT

- F. Socurity, medical, emergency & fire protection plans
- 8310180437 Forwards 1C Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted STAROSTECK1, R Division of Project & Resident Programs 83/09/28 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 20802 143 24% Fiche 50-213, 83/09/28, 8310180439
- --8310180447 lE Insp Rept 50-213/83-16 on 830523-0424 No noncompliance noted Major areas inspected review of period repts.shift logs & operating records, physical security, atmospheric checks of cleaning facility & plant trips REBELOHSKI, T A Region I, Uffice of Director ELGASSER, T C Division of Project & Resident Programs 83/09/27 lipp 20802 150 24% Fiche 50-213,83/09/28,8310180437
- 8310060236 Releases public version of revised emergency plan implementing procedure FELTON J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20660 233 24% Fiche 50-213,83/09/30, 8310060236
- --8310060262 Public version of fev 15 to Emergency Plan Implementing Procedure CPIP 1 5-2, "Notification & Communitation "COUNSIL.N G Connecticut Yankee Atomic Power Co 83/06/09 EISENHUT.D G Division of Licensing 41pp 20660 235 24X Fiche 50-213.83/09/30.8310060256
- 8310110193 Notification of 831013 meeting w/util in Bethesda.MB to discuss control room fire protection & alternative safe shutdown capability
 CRUICHFIELD.D Operating Reactors Branch 5 83/10/05 ERICKEDN, P. Operating Reactors Branch 5 3pp 20665 008 24X
 Fiche 50-213,83/10/05.8310110193
- 8310270003 Notification of 831k15 meeting w/util/WESTEC.States of Cl | MA & FEMA in West Springfield.MA to discuss results of consequences of Quabbin Dam floading & emergency procedures for floading events

 BROWN S W Systematic Evaluation Program Branch 83/10/19

 GRIMES.C I Systematic Evaluation Program Branch 2pp 20939 Ipj
 24X Fishs 50-213.83/10/19.8310270003
- 031027001B Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/21 Document, Management Branch Lp 20940-190 24X Fiche 80-213,83/10/21.

- --8310270021 Public version of Nov O to Emergency Plan Implementing Procedure EP)? 1 5-43, "Personnel Radiation Exposure Control During Nuclear Emergencies" W/831011 ltm FERGESON, J.H., COUNSIL, W.G. Connecticut Yankee Atomic Power Co. 83/10/01 CJSENHUT, D.G. Division of Licensing Bpp 20940 191 24X Fiche 50-213,83/10/21.8J10270018
- 8310280311 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963-083 24X Fiche 50-213.83/10/25. 8310280311
- --8310280313 Public version of Rev 16 to Emergency Plan Implementing Procedure EPIP 1 5-2, "Notification & Communication " H/ 830811 lt: COUNSIL.W G Connecticut Yaukee Atomic Power Co 83/08/01 EISENHULD G Division of Licensing 42pp 20763 084 24X Fiche 50-213,83/10/25,8310280311
- P Operating license stage documents & coirespondence
- 8310310017 :OIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER, L Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given 1p 21004 2/0 24X Fiche 50-000,83/05/02, 8310310017
- 8310310031 Responds to FDIA request for documents re integrated leak rate toots for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable
 FELTON.J M Division of Rules and Records 83/07/06 CONNER.L Affiliation Unknown 1p 21004 271 24X Fiche 50-000.83/07/06, 8310310031
- B310030140 Comments on potential for flooding of plant site resulting from failure of Goodnough Dike W/or Windsor Dam at Guabhin Research Ctr analysis, flooding protection measures provide plotection against dam failure CRUTCHFIELD D Operating Reactors Branch 5 83/09/26 CDUNGIL,W G Connecticut Yankee Atomic Power Co 4pp 20591 071 24X Fiche 50-213,83/09/26.8310030140
- --8308300317 "Quabbin Dam Failure Flooding Consequences at Hoddam Neck Plant," technical evaluation rept SCHERRER, J S Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05504-412 83/08/25 CHERY, D NRC - No Detailed Affiliation Given 280pp 50591 075 24X Fiche 50-213,83/09/26,8310030140
- 83i0120375 Responds to 830726 request to review training program & confirm that stated items addressed in Generic Ltr 81-21.
 "Natural Circulation Cooldown "Training given to all licensed operators in 1981 addressed listed items CQUNSIL.W 9 Connecticut Yankee Atomic Power Co 83/09/27 CRUTCHIFIELD.D Operating Reactors Branch 5 2pp 20699 201 24X Fiche 50-213.83/09/27.83i0120375
- 8310060213 Responds to 830914 proposal to develop integrated review for pending licensing actions Meeting to discuss proposed review requested EISEMUT.D G Division of Licensing 83/10/05 COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20647 131 24X Fiche 50-000.83/10/05,8310060213
- 8310120308 Requests update of completion schedules presented in integrated plant safety assessment rept within 30 days CRUTCHFIELD, D. Operating Reartors Branch 5 83/10/06 COUNSIL.W Q Connecticut Yankee Atomic Power Co (COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20701 004 24% Fiche 50-000,83/10/06,8310120308
- 8310120411 Notifies that util will no longer roceive portions of FR containing Commission monthly notices w/transmittal ltr Util should carefully peruse publication for hearing opportunity notices CRUTCHFIELD. D Operating Reactors Branch 5 83/10/07 COUNSIL.W G Connecticut Yankee Atomic Power Co 2pp 20699 041 24X Fiche 50-000.83/10/07.8310120411
- 8310180344 Revises schedule for submittal of svc water sys analysis identified in Integrated Plant Safety Assessment.NUREG-0826 & associated SEP Topic IX-3 Delays due to upgrades per NUREG-0737.Item III D 3 4 Analysis expected by 831230 GOUNSIL:N G Connecticut Yankee Atomic Power Co 83/10/07 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 20802 358 24X Fiche 50-213.83/10/07.8310180344

- 8310180409 Forwards listed revs to "Corporate Drganization for Nuclear Incidents (CONI) Procedure Manual," per Section V of App E to 10CFR50 W/o encl COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/10/12 EISENHUT, D G DIVISION of Licensing 1p 20803 173 24X Fiche 50-000, 83/10/12, 8310180409
- 8310280112 Denies 830906 request for 120-day extension to respond to Generic Ltr 83-28 re generic implications of Salem ATMS events NRC review schedule door not permit extension Response due by 831105 CRUTCHFIELD.D Operating Reactors Branch 5 B3/10/26 COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20929 261 24X Fiche 50-000.B3/10/26.8310280112
- Q Inspection reports, 1E Bulletins & correspondence
- B30B300340 IE Info Notice B3-61. "Alleged Use of Stand-Ins for Helder Qualification Tests " Svc list encl JDRDAN,C L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,830B300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- B30B300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B330103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 2077B 001 24X Ficho 50-000,83/09/26,830B300345
- 8310180204 Forwards IE Insp Rept 50-213/83-17 on 830627-0731 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 83/09/27 COUNSIL.W 0 Connecticut Yankee Atomic Power Co 2pp 20808 226 24X Fiche 50-213,83/09/27.8310180204
- --8310180209 IE Insp Rept 50-213/83-17 on 830627-0731 No noncompliance noted Major areas inspected licensee action on previous insp findings.plant operations.shift logs & operation records & review of periodic repts
 REDECOMSKI,7 A Region i. Office of Director ELSASSER,T C Division of Project & Resident Programs 83/09/21 6pp 20808 228 24X Fiche 50-214,83/09/27,8310180204
- 83i0180437 Forwards IE Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted STAROSICCKI,R Division of Project & Resident Programs 83/09/28 COUNSIL.W G Connecticut Yankee Atomic Power Co 2pp 20802 148 24X Fiche 50-213,83/09/28,8310180439
- --B310180447 IE Insp Rept 50-213/83-16 on 830523-0626 No noncompliance noted Major areas inspected review of period repts, shift logs & operating records, physical security, atmospheric checks of cleaning facility & plant trips REDELOWSKI, T A Region I, Defice of Director ELSASBER, T C Division of Project & Resident Programs 83/09/27 lipp 20802 150 24X Fiche 50-213,63/09/28,8310180439
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enc! JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/27 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/27,8308300349
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Nutice 83-66, "Fatality at Argentine Critical Facility " Syc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noticus Cases " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 89/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000.89/10/11,8308300759

- 8308300761 IE Info Notice 83-69. "Respirator User Harning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list
 - enc1 JORDAN-R L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co York, Inc. 120pp. 20827-129 24X Fichs 50-200 ost 8301031 83/10/11 Consolidated Edison Co of New 120pp 20827 127 24X Fiche 50-000.8J/10/11.8308300/41
- R Periodic operating reports & related correspondence
- 8310190007 Monthly operating rept for Aug 1983 H/830914 ltr ELMS.A. ORAVES.R H Connecticut Yankee Atomic Power Co 6: Office of Resource Management, Director 10pp 20823 117 Fiche 50-213,83/08/31,8310190007 03/05/31
- S Reportable occurrences, LERs & related correspondence
- 8310250315 LER 83-016/03L-0 on 830401.during normal operation charging pump 8 declared inoperable after pump outboard motor revealed high temp alarm Caused by broken tharmocouple uires Wires repaired W/830926 lt; CLOSIU5.c J. GRAVES.R H. Connecticut Yankee Atomic Power (o. 83/09/26 MURLEY.T E. Region 1. Office of Director 2pp 20898 017 24X Fiche 50-213.83/09/26.8310230315
- B31025032: LER B3-015/03L-0 on B3083. during surveillance testing on Channel I of pressure level instrumentation trip relay failure discovered Caused by stuck relay Relay manually cycled & lubricated M/830926 litr CLOSIUS. 6 J. GRAVES. R H Connecticut Yankee Atomic Power Co B3/09/26 MURLEY, T E Region I. Office of Director 2pp 20898 001 24% Fiche 50-213.03/09/26.8310830321
- B3(0070301 Potential Part 21 rept re underrange characteristic of Hodel N-E110M transmitter Underrange iero offset may occur unen transmitter initially pressurized from atmospheric to suppressed zero input End users notified SERBERIAN, M J Forboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement | Ilpp 20651 064 24X Fiche 50-000,83/09/30.8310070301
- DOCKET 50-219 DYSTER CREEK NUCLEAR POWER PLANT

- Security, medical, emergency & fire protection plans
- HODIOSS Releases public version of revised emergency plan implementing procedures FELTON.) M Bivision of Rulos and Records 83/09/30 Docum Management Branch 1p 20715 228 24X Fiche 30-219.83/09/30. Document
- --B310110399 Public version of revised Emergency Plan Implementing Procedures EPIP-1 re classification of emergency conditions, EPIP-4 re site emergency & IPIP-5 re general emergency FIEDLER.P B Jersey Central Power & Light Co B3/05/20 54pp 20715 229 24X Fiche 50-219,83/09/30,8310110385
- B310270155 Ack receipt of 830930 ltr informing NAC of steps taken to correct violations noted in IF Insp Rept 50-219/83-20
 STAROSTECKI,R Division of Project & Resident Programs B1/10/2i
 FIEDLER.P B Congrel Public Utilities GPU Service Corp 2pp
 20925 015 24X Fiche 50-219,83/10/21,8310270155
- ~8310270158 Responds to NRC 630902 ltr re violations noted in IE lnsp Rept 50-219763-20 Corrective actions individual appropriately disciplined Details withheld (ref [OCFR73 2]) FIEDLER,F D General Public Utilities QPU Service Corp 83/09/30 STAROBIECKL R Bivision of Project & Resident Programs 3pp 20925 017 24X Fiche 50-219,03/10/21,0310270155

VC list onel LAKE.E L ICK, J H / RDE, C N 32 351 PAX

- 8310070020 Ack receipt of 830824 ltr requesting Commission publish notice of pending license amend in FR in New York State Energy R&D Authority license for utils w/irradiated fuel storage facilities

 DAVIS, J G Diffice of Nuclear Material Safety & Safequards, Director
 83/09/22 RESNIBUFF M Sierra Club ip 206/1 361 24x
 Fiche 50-000, BJ/09/22, 8310070020
- 8310030263 Forwards Amend 68 to License DPR-16 & safety evaluation 330030263 Forwards Amend 68 to Literia 194-16 & safety e Anend authorizes changes to administrative organization allocating personnel between maint div & matl dept CRUTCHFIELD. D. Operating Reactors Branch 5 83/09/28 General Public Utilities - OPU Service Corp. 3pp. 20 Fiche 50-219,83/09/28,8310030263 6 1601 (III. P. 18 94 041 | 243 ₹0591 041
- --8310030268 Amend 6B to License DPR-16, authorizing changes to administrative organization by allocating personnel between maint 8 const div & newly established plant matl dept CRUTCHFIELD N Operating Reactors Insuch 5 83/09/28 10pp 20591 044 Fixes 50-219,03/09/28,8310030263
- --8310030272 Sefety evaluation supporting Amend 68 to License DPR-16 * Office of Nuclear Reactor Regulation, Director 83/09/28 2, 20991 054 24X Fiche 50-219,83/09/28,0310030263
- 8310030443 Informs that Section 4 31 of integrated plant safety assessment rept (NUREG-0822) did Jan 1903 complete.except for implementation of mods to diesel generator trips by end of Cycle 13 outage & IE post-implementation review CRUTCHFIELD.D. Operating Reactors Branch 5 83/09/29 FIEDER.P & General Public Utilities GPU Service Corp 2pp 20602 06.1 241 Fiche 50-219.83/09/29,8310030443
- 8310110217 Forwards status of NURLG-0822 issues requiring refined engineering analysis or continuation of ongoing evaluation, per 830810 request Addl submittal date inadvertently omitted by NRC, indicated by actorisks
 FIEDLER, P. B. General Public Utilities GPU Service Corp. B'87. 83710701 CRUTCHFIELD, D Corrating Reactors Branch 5 4pp 20665 056 Fiche 50-219, 83/10/04, 8310110/17
- 8310120334 Advises that future Commission Fk monthly notices will be forwarded w/o transmittal ltr Perusal of each publication for hearing opportunity nutices recommended CRUTCHFIELD.D Operating Reactors Branch 5 83/10/07 FIEDLER.P General Public Utilities GPU Service Corp 2pp 20697 275 Priche 50-219,83/10/07,8310120334 FIEDLER, P B
- 8310170335 Application to amend tirense DPR-16 consisting of Rev I to Tech Sper Change Request 104 reflecting visual insplot attractes to the core spray spargers, repair assemblies & core spray piping internal to reactor vessel FIEDLER.P B Genoral Public Utilities GPU Service Corp BU/10/11 NRC No Detailed Affiliation Given 3pp 20786 152 24X 89/10/11 Fiche 50-219, 83/10/11, 8310170335
- 8310200211 Forwards (NPO evaluations on util mgt Svc list entl BLAME,E L Shaw, Pittman, Potts & Trowbridge BLAME,E L Metropolitan Edison Co B3/10/18 EDLES,6 J , BUCK,J H , KUIN ,C N Atomic Safety and Licensing Appeal Panel 47pp 20832 351 24% Fiche 50-000,83/10/18,8310200211
- 9310210249 Forwards corrected pages to INPO rept provided on 0010[0] BLAKE,E L. Shaw, Pittman, Potts & Trowbridge BLAKE,E L. Metropolistan Edison Co. 93/10/19 EDIES,C J., BUCK,J H., KUHL,C N. Atomic Safety and Licensing Appeal Panel. App. 20851 049 14X Fiche 50-000,83/10/19.8310210249
- B310210209 Notification of B31027 meeting w/util in Bethesda, MD to discuss proposed expanded safety sys facility LDMBARDO, J. Operating Reactors Branch 5 B3/10/20 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 20855 110 Fiche 50-219,83/10/20,8310210207 20895 110 24x
- 8310270180 Discusses B31007 mgt meeting held in Region I ofc to inform region of results of INPO recent assessment of facility List of attendees encl
 MURLEY. T C Region 1, Office of Director 83/10/20 DIECHAMP.**
 General Public Utilities GPU Service Corp 2pp 20924 358 ***
 Fiche 50-219.83/10/20.8310270180
- 8310240124 Notification of 831108 meeting w/util in Parsippany.NJ to discuss SEP integrated plant safety assessment rept supply full-term OL conversion process & status of Cycle 10 refueling/maint outage
 LOMBARDD, J. J. Operating Reactors Branch 5 B3/10/21
 CRUICHFIELD. D. Operating Reactors Branch 5 3pp 2
 Fische 30-219, 83/10/21, 8310240124 208Bi 150 S4T

- 8310270331 Ack receipt of 830906 request for extension to submit 120-day response to Generic Ltr 80-28 te Salem ATMS events
 Request denied Info re schedules for final implementation
 should be provided by 831105
 CRUTCHFIELD D Operating Reactors Branch 5 83/10/26 FIEDLEM.P 8
 General Public Utilities GPU bervice Corp 3pp 20923 140 24X
 Fiche 50-219,83/10/26.83102/0331
- Q Inspection reports: IE Bulletine & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Wilder Qualification (ests " S/C list entl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison (o of New York Int 117pp 20754 022 24X Fiche 50-000,83/09/26,8308
- 8308300342 IC Info Notice 83-62, "Failure of Redundant losic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list enri JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,83083003042
- B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays," Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 (Onsolidated Edison Co. of New York, Inc. 118pp 2078 001 24% Fishe 50-000, 83/09/26, 83008300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Gurveillance of Flow in RTI) Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/0/ Consolidated Edison Co of Nevork, Inc 76pp 20827 213 24X Fich. 50-000.83/10/07,83(8300378
- 8308300752 IE Info Notice 83~66, "latality at Argentine Critical Facility " Svc lint encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/0/ Consolidated Edison Co of Net York, Inc 79pp 20882 0P6 24X Fiche 50-000,83/10/07,8308200752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causet Production of Norlous Gases" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Can
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310170335 Application to amend License DPR-16 consisting of Nev I to Tech Spec Change Request 104 reflecting visual insp of all accessible core spray spargers repeir assemblies & core spray piping internal to reactor vessel FIEDLER.P B General Public Utilities QPU Service Corp NRC No Detailed Affiliation Given 3pp 20784 152 24X Fiche 50-219.83/10/11.8310170335
- 83i0180551 Notification of 83i021 meeting w/BWR licensers in Bethesda.

 MD to dircuss future insps for intergranular stress corrosion cracking

 MIRAGLIA,I V Assistant Director for Safety Assessment BB/10/14

 EISENHUT, D G Division of Licensing bpp 20823 35H 24X

 Fiche 50-000,83/10/14,8310180551
- 8310270155 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/83-20 STAROSIECKI, R Division of Project & Resident Programs 83/10/21 FIEDLER, P B General Public Utilities GPU Service Corp 2pp 20925 015 R4X Fiche 50-217,83/10/21.8310270135
- --8310270188 Responds to NRC 830902 ltr re violations noted in If Insp Rept 50 &19783-20 Corrective actions individual appropriately disciplined Details withheld (ref 10CF673 21) FIEDLIK:P B Grneral Public Utilities - GPU Service Corp 83709730 STARDSTEL41:R Division of Praject & Resident Programs 3pp 20925 017 24X Fiche 50-219.83/10/21.8310270155

- R Periodic operating reports & related correspondence
- B310190031 Monthly operating rept for Aug 1983 W/B30916 ltr
 MOLNAR, J. R., FIEDLER, P. B., BARAN, R. Openbral Public Utilities GPU
 Bervice Corp. B3/09/06 Division of Data Automation & Management
 Information Bpp 20823 241 24X Fiche 50-219,83/09/06,B310190031
- S Reportable occurrences, LLRs % related correspondence
- 9310270527 FOIA request for three categories of documents re 830606 gos leak at facility ARGYROS.D Chamlin, Schottland, Rosen, Cavanagh & Uliano 93/06/22 NRC - No Detailed Affiliation Given 1p 2093/224 24X Fiche 50-219,83/06/22,8310270527
- 8310270341 Responds to FOIA request for three categories of documents re 830606 gas leak at facility Forwards App A documents FELTON.J M Division of Rules and Records 83/07/22 ARGYROS.D L Chamilin. Schottland. Rosen. Cavanagh & Uliano 2pp 20937 225 24) Fiche 50-000.03/07/22.8310270541
- --83102/0547 Submits morning rept for Region 1, listing B30606 & 07 events ALLAN.J M. Region 1, Office of Director B3/06/07 BLAMA, J Program Support Dranch 1p 20937 228 24X Fiche 50-000, B3/07/22,B310270541
- 8310200161 LER 83-017/01T-0 on 830826, arming relay for diesel generator protective relay set at value possibly causing breaker to open during fast start Caused by design deficiency Betting changed M/830717 ltr
 DICKINSON.A C , FIEDLER, P U General Public Utilities GPV Service Corp 83/09/17 NURLEY.T E Region i, Uffice of Director App 20834 08/ 24% Fiche 50-217,83/09/17,8310200161
- DOCKET 50 320 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310060149 Forwards emergency preparedness exercise objectives for exercise planned for 830928, per 811026 ltm Meeting tentatively scheduled for 830/18 at facility Droft scenario for initial review will be provided MANGAN,C V Niagara Mohawk Power Corp 83/07/08 MURLEY,T C Region 1, Office of Urrector App 2048 344 24% Fiche 50-220,83/07/08,8310060149
- 8310060361 Forwards Rev O to "Niagara Mohauk Power Corp Nine Mile Point Unit i Emergency Preparedness Exercise Scenario 3A." per NRC 811026 request Exercise scheduled for 830728 LEMPGES.T E Niagara Mohauk Power Corp 83/08/03 MURLEY.T F Region I. Office of Director 214pp 20642 121 24X Fiche 50-220.83/08/03.8310060361
- B310120070 Forwards IE Insp Hept 50-220/03-20 on B30721 & 25-0826 No noncompliance noted STANDSTICKI,R Division of Project & Resident Programs B3/09/20 RHODE,G K Niagara Mohauk Power Corp 2pp 20697 128 24X Fiche 50-220
- --8310120096 IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance noted Major areas inspected licensee action on previous insp findings.operational safety verification. physical security surveillance testing & safety sys HUDSON.S D. MCBREARTY.R A Region 1. Office of Director LAZARUS.W J Division of Project & Resident Programs B.1/09/16 12pp 20697 ISO 24X Fiche 50-220.83/09/20.8310120090
- J Insurance & indemnity information
- 8310140043 Forwards Endorsement 69 to MAELU Policy MF-46 RUSHMOREJJ W Niagara Mohawk Power Curp 83/10/03 SALTZMAN, J Assistant Director for Btate & Licensee Relations 2pp 2076B 278 24X Fichs 80-220,03/10/03,0310140043
- 8310140154 Forwards Endorsement 83 to NELIA Policy NF-161 RUSHMORE,J W. Niagara Hohawk Power Corp. 83/10/03 SALTZMAN,J Assistant Director for State & Licensee Relacions .2pp. 20762-360 24X Fichs 50-220,83/10/03,8310140154
- P Operating license stage documents & correspondence
- 8310060581 Requests util analyze potential for fluoding of safety-related structures. sys & components caused by location of security fence for Unit 2 for rainfall events up to PMP Response due in 43 days
 VASSALLO.D B Operating Reactors Branch 2 83/09/19 RHDDE.O K Niggara Mohawk Power Corp Spp 20661 207 24X
 Fiche 50-220,01/09/19.8310060581

- 8310060574 Forwards safety evaluation of util 791217 & 820129 responses re operability of containment vent & purge valves Addl info requested within 15 days VASSALLO,D B Operating Reactors Branch 2 83/09/21 RHODE.G K Niagara Mohawk Power Corp Opp 20651 229 24x Fiche 50-220,83/09/21,83100605/4
- --83;0060378 Safety evaluation re demonstration of containment purge & vent valve operability (8-24) Util info failed to demonstrate operability of 20-inch & 24-inch valves to close against buildup of containment pressure in event of COCA + NRC No Detailed Affiliation Given 83/09/21 Spp 20661 232 24% Fiche 50-220,63/09/21,8310060374
- 8310120406 Forwards application to amend License BPR-63, consisting of proposed change to Tech Specs re reporting requirements for reactor vessel matl surveillance specimen MANGAN.C V Niagara Mohawk Power Corp 83/09/26 DENTON,H 9 Office of Nuclear Reactor Regulation. Director Ip 20699 025 24X Fiche 50-220.83/09/26.8310120406
- --8310120416 Application to amend License DPR-63, revising Tech Specs to incorporate current reporting requirements for reactor vessel matl surveillance specimen, per recent rev to 10CFR50.

 App H Supporting info encl
 MANOAN, C V Miagara Hohawk Power Corp 83/10/06 7pp
 20699 026 24x Fiche 50-220.83/09/26.8310120406
- 8310040597 Forwards response to draft technical evaluation rept assessing conformance w/general load handling guidriines of NUREG-OGI2. "Control of Heavy Loads at Nuclear Fower Plants." Addi response unil be provided by 831115 LEMPOES,T E Niagara Mohawk Power Corp 83/09/30 EISENHUT, D Q Division of Litensing 9pp 20625 327 24X Fiche 50-220.83/09/30, 8310040597
- 310040431 Forwards sys component evaluation wortsheets resolving outstanding environ qualification items for electrical equipment, per Schedule 1 of App C to util 830520 & 0709 ltrs No equipment yet determined unacceptable MANGAN.C V Niagara Hohawk Power Corp 83/09/30 VASSALLO, U B Operating Reactors Branch 2 55pp 20425 352 24X Fishe 30-220.83/09/30.831004063:
- 831018009B Forwards "Summary Rept & Program Plan for Control Room Design Review." per 830707 ltr re NURF9-0737.ltem I D 1 activities MAN9AN.C V Niegara Mohawk Power Corp 83/09/30 VASSALLN.D B Operating Reactors Branch 2 lp 2080/184 24X Fiche \$0-220.83/09/30.831018009&
- ~-8310180102 *8udmary Rept & Program Plan for Control Room Design Review * • Niagara Mohawk Power Corp 83/09/30 23pp 20807 185 24X Fiche 50-220,83/09/30.8310180098
- 10120097 Forwards response to 630908 request for add1 info recriticality analysis, supporting application for spent fuel storage capacity expansion
 HANGAN, C V Niagara Hohawk Power Corp 83/10/05 VASSALLO, D B
 Operating Reactors Branch 2 8pp 20497 120 24X
 Fiche 30-220,83/10/05.8310120097
- 310120209 Forwards revised Tech Spec Table 3 & 4a re safety-related hydraulic mechanical snubbors info supercedes 800418 & 810320 submittals HANGAN.C V. Niagara Hohauk Power Corp. 83/10/05 VASGALLO, D.B. Operating Reactors Branch 2 Ip. 20A76 115 24X Fisher 50-220,83/10/05.8310120203
- ~8310120208 Revised Tech Specs Table 3 & 4a & 5 re safety~related hydraulic snobbers • Niagara Mehauk Power Corp 83/10/05 7pp 20696 11& 24x Fiche 50-220,83/10/05,8310120205
- 3310120373 Requests 2-yr extension to implementation date in amended rule 10CFR50 44(m) requiring min number of licensed operators & senior operators on shift at all times TMI Item I A I 3 implemented using shift technical advisor HANGAN.C V Niagara Mohauk Power Carp 83/10/06 DENTON,H R Office of Nuclear Results of Cart Regulation, Director 1p 20699 19/ 24X Fiche 50-220,83/10/06,8310120373
- 310170586 Responds to NRC 830921 ltr requesting assessment of operability of containment vent & purgr isolation valves & closure of valves until adequate info provided Final evaluation will be submitted by B31114 HANOAN.C V Niagara Mohaw Power Corp B3/10/11 VASSALLO,D 1 Operating Reactors Branch 2 Jpp 20780 220 24X Fiche 50-220.83/t0/11.8310170586

- 83(014022] Responds to 83082] request for position to NURCG-0/3/. Item 11 E A 2(7). "Containment Isolation on High Radiation" " Completion of evaluation anticipated by 83(20) MANGAN, C V Niagara Mohawk Power Corp 83/10/12 VASSALLO, D B Operating Reactors Branch 2 1p 20/61 187 249 Fiche 50-220, 03/10/12, 83(014022)
- 8310210171 Outlines proposed program for integration of engineering evaluations & plant improvements resulting from current & anticipated regulatory requirements & reliability improvement needs.

 MANDAN, C.V. Niagara Mohauk Power Corp. 831/10/19 VASSALLO, D.B. Operating Reactors Branch 2 13pp. 20055-126 24X
 Fiche 50-220, 83/10/19, 83102101/1
- O [nspection reports: IE Bulletin: & correspondence
- 8310070114 Forwards safety evaluation of licensee 800502 & 820730 requests for sellof from inservice lasp requirements of Section XI of ASME Boiler & Pressure Vissel Code Relief from impractical requirements granted VASSALLO, D 8 Operating Reactors Branch 2 83/09/17 RHODE, G R Ningara Nohauk Power Corp 3ps 20600 085 24X Fiche 50-220, 83/09/19, 8310070114
- --B310070119 Safety evaluation of licensec 800502 \$ 820730 requests for relief from inservice inspirequirements of Section XI of ASME Noiter & Prissure Vessel Code Relief from impractical requirements granted # Office of Nuclear Reactor Regulation, Director B3/09/19 9pp 20480 088 24X Fiche 50-220,63/09/19,8310070114
- --820920034 "Nine Mile Point Unit | Inservice Insp Program," technical evaluation ript * Strence Applications, Inc. NRC-03-82-096 SAI-186-028-11 82/09/17 NRC - No Detailed Affiliation Given 30pp 20680 097 24% Fiche 50-220,83/09/19,8310070114
- --83100/01/3 Notice of grant of relief from impractical ASME Boiler & Pressure Vessel Code inspirequirements VASSALLO.D D Operating Reactors Branch 2 83/09/15 29p 2000 127 24X Fiche 50-220,83/09/19,8310070114
- --B310120096 IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance noted Major areas inspected licensee action on previous insp findings, operational affety verification, physical security surveillance testing & safety mys HUDSDM, S D. INCREARTY, R A. Region 1, Office of Director LAZARUS, W J. Division of Project & Resident Pragrams 83/09/16 12pp 20697 130 24x Fiche 50-220.83/09/20.8310120090
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Wolder Qualification Tests " Svc list entl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3709/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Fast 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fithe 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential failures of Hestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 (onsolidated Edison Co of New York, Inc. 1189p 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 9308300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 57 Evaluation " Syc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/27 Consolidated Edison Co. of New York, Inc. 115pp. 20716-324 24X Fiche 50-000,83/07/29,8308,800347
- 8310060005 EN-83-06) on 831006, notice of violation & proposed imposition of \$40,000 civil penalty will be issued based on util failure to place main steam line high radiation trip sys in tripped condition when both channels inoperable MCINGLER, 0, AXELHAD, J Director's Office, Office of Inspection and Enforcement 83/10/03 ip 20649 294 24X Fiche 50-220,83/10/03,8310060005

- g310270581 Discusses IE insps on 830607-24,0805,12-15 & 18-22 & forwards notice of violation & proposed imposition of civil penalty MURLEY.T C Region 1, Office of Director 83/10/06 RHODE,8 K Niagara Mohauk Power Corp 4pp 20943 355 24X Fiche 50-220,83/10/06,8310270581
- --83102/0585 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted inadequate review of shift checks, inadequate monitoring of plant parameters & inadequate understanding of Tech Specs MURLEY. TE Region i, Office of Director 83/10/06 4pp 20943 359 24% Fiche 50-220.83/10/06 8310270581
- 8308300978 IE info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Sv. list end I JORDAN.E L Division of Emergency Preparedness & Englineering Response (Past 830103) B3/10/0/ Censolidated Edison Co of New York, Inc. 74pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300792 IE Info Notice 83-66, "fatality at Argentine Critical Facility " Svc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp. 20882 026 24X Fiche 50-000,83/10/07,8308300752
- B30B300759 IE Info Notice B3-67, "Fmergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JCRDAN. C L Division of Emergency Preparadness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000.B3/10/11.B300300759
- #308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Byt list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Editon Co. of New York, Inc. 120pp. 20827 129. 24X Ficha 50-000.83/10/11.8308300761
- 8310160951 Natification of 831021 meeting w/BWR licensers in Bethesda. MD to discuss future insps for intergranular stress corrosion chacking MTRACLIA.F J Assistant Director for Sofety Assessment 83/10/14 EISENNUT.D & Division of Licensing 5pp 20823-358 24X Fiche 50~000.83/10/14/8310180551
- 8310270207 Ack receipt of 830901 & 07 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/83-14 Violation reduced to Level V to ack 1781 verification & Jul 1983 reverification of design adequacy MARTIN [T Division of Engineering & Technical Programs 83/10/18 RHODE, G K , 8510ERT, C R Nisagara Mohawk Power Corp 2pp 20724 10t 24% Fiche 50-220.83/10/18.8310270207
- --8310270212 Responds to 830906 telcon request for add1 info to 830901 responds to violation Item B noted in IF Insp Rept 50-220/83-16 Engineering Procedure LP 090, "Control of Design & Design Verification" forms forwarded W/o enri LEMPGES.T E Niagara Mohawk Power Corp 83/09/0/ BRIGGS, L Region 1, Office of Director 2pp 20924 103 24X Fiche 50-220.83/10/18.83102/0207
- --8310270217 Responds to NRC 830803 ltr re violations noted in IL Insp Rept 50-220/8J-16 Corrective actions valve operators on listed valves removed, closed & modified & seismir calculations performed on cooling lines LEMPGES, TE Niagara Mohauk Power Corp 83/09/01 MARTIN. 1 T Division of Engineering & Technical Programs 3pp 20924 105 24X Filhe 50-220,83/10/18,83102/0207
- R Periodic operating reports & related correspondence
- 8310140iii Monthly operating rept for Sept 1983 W/831007 ltr ROMAN.T W. LEMPGES.T E. Niagara Mohawk Power Corp. 83/10/05 Director's Office. Office of Inspection and Enforcement 5pp 20766 ll1 24X Fiche 50-220.83/10/05.831014011
- B Reportable occurrences. Likks & related correspondence
- 8310170169 Updated RD 83-23 on 850809, circuit breaker for core spiny pump suction valve 81-21 taken out of svc for preventive maint while leaving valve in open position Event did not violate Tech Spec 3 3 4 b as previously reported LEMPGES. I E Niagara Mohauk Power Corp. 83/09/26 MURLEY, T F. Region 1. Office of Director 1p. 200/1 089 24X Fiche 50-220, 83/09/26 8310190169

- 8310310359 LER B3-024/03L-0 on 830826, onc of two inadequate core cooling reactor core level indicators failed surveillance test Caused by high register value due to bad contacts Systeminitialized & register zeroed W/830726 ltr
 KESEL D T . LEMPGES T E Niagara Mohawk Power Corp B3/09/26
 MURLEY T E Region to Defice of Director 2pp 20761 125 PAX Fiche 50-220,83/09/26.8310310359
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N FilgM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified DERBERIAN,M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Firhe 50-000,83/09/30.8310070301

DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

- F Security, medical, emergency & fire protection plans
- 9310120153 Forwards IE Insp Rept 50-223/83-01 on 830822-23 No noncompliance noted MARTIN.T 1 Division of Engineering & Technical Programs 83/09/21 BEGHIAN.L E. Lowell. Univ of 2pp 20698-085 24\(\lambda\) Fiche 50-223,81/09/21,310120153
- --8310120156 IE Insp Rept 50-223/83-01 on 830822-23 No noncompliance noted Major areas inspected physical protection measures for SNM of moderate strategic significance DUNLAP, J M., GCDY, A T. Region 1. Office of Director 83/09/20 2pp 20498 087 247 Fichs 50-223,83/09/21,8310120153
- G Inspection reports, IE Bulletins & correspondence
- 9310120153 Forwards IE Insp Rept 50-223/83-01 on 930822-23 No noncompliance noted MARTIN, T 1 Division of Engineering & Technical Programs 83/09/21 BEGHIAN, L C. Lowell. Univ of 2pp 20698 085 24% Fiche 50-223,83/09/21,8310120153
- ---B310120156 IE Insp Rept 50-223/83-01 on B30822-23 No noncompliance noted Major areas inspected physical protection measures for SNM of moderate strategic significance DUNLAP.J M. GDDY.A T. Region 1. Office of Director B3/09/20 2pp 20698 087 24X Fiche 50-223.93/09/21.8310120153
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

 5 Reportable occurrences, LLRs & related correspondence
- 8310200176 PNO-V-83-047 on 831011, licensee received notification from Radiation Detection Co of one film badge indicating potential whole body exposure of IB rem film badge not representative of exposure

 8HERMAN.C. MENSLAWSKI, F. Region 5, Office of Director B9/10/12

 1p 20835 315 24X Fiche 50 224,83/10/12,6310200174

DOCKET 50-225 RPI CRITICAL EXPERIMENT

- P Operating license stage documents & correspondence
- 8310110121 Application to amend License CX-22 changing Tech Specs as part of license renewal process WICKS.F Rensselaer Polytechnic Inst., Yroy, NY 83/10/05 THOMAS,C Q Standardization & Special Projects Branch 1p 20665 308 24X Fiche 50-225.83/10/05.8310110121
- --8310110122 Amended Tech Specs re License CX-22 renewal * Rensselaer Polytechnic Inst , Tray, NY 83/10/05 3lp; 20466 309 24X Fiche 50-225,83/10/05,8310110121
- B310200051 Forwards ltr dtd B31012 to replace B31005 ltr re Tech Specs Original ltr missing signatures HARRIS, D.R. Rensselaer Polytechnic Inst , Troy, NY 83/10/13 THOMAS, C. D. Standardization & Special Projects Branch 1p 20837 008 24Y Fiche 50-225, 83/10/13,8310200051
- --B310200055 Forwards amended lech Specs W/o encls
 HARRIS,D R , WICKS:F Rensselarr Polytechnic Inst , Troy, NY
 B3/10/12 THOMAS.C D Standardization & Special Projects Branch
 1p 20837 009 24X Fiche 50-225.83/10/13.8310200051

- G Inspection reports, IE Bulletins & correspondence
- 8310240110 Forwards 1E Insp Rept 50-225/83-03 on 830810-12 No noncompliance noted STAROSICCKI, R. Division of Project & Resident Programs B1/10/04 LAMEY, R. T. Remsselaer Polytechnic Inst., Troy, NY Ppp 20881 08/ 24X Fiche 50-225 83/10/04,8310240110
- ~-B310240))5 IE Insp Rept 50-225/83-03 on B30810-12 No noncompliance noted Major areas inspected licensee action on previous insp findings, facility operations, radiation controls & environ monitoring KINNEY, W W. ELSASSER, T C. Region I. Office of Dailetto B3/10/03 App. 2088 089 24X Fache S0-225, B3/10/04, B3/0240110

DOCKET 50-228 AEROTEST RADIOGRAPHY & REAFARCH RFACTOR

Q Inspection reports. IE Bulletins & correspondence

- 8310210254 Forwards IE Insp Rept 50-228/83-02 on 830920-39 No noncompliance noted WENSLAMSKI,F A Region 5, Office of Director 83/10/07 NEWACHECK,R Aerotest Operations, Inc. 2pp. 20801-252 24X Fiche 50-228,83/10/07.8310210794
- --8310210256 IE Insp Rept 50-228/83-02 on 8.0928-29 No noncompliance noted Major areas inspected radiation protection program, organization, posting & labeling, instrument calibr.personnel monitoring, effluent releases & surveys CILLIS, H., KENSLAWSKI, F. Region S. Office of Director 83/10/07 opp 20851 254 24X Fiche 50-228,83/10/07,8310210254

DOCKET 50-237 DRESDEN NUCLEAR POWER DTATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8310040121 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Mecords 83/09/22 Document Management Branch 1p 20634 341 24% Fiche 50 010.83/09/22.
- --B310040196 Public version of Rev O to Emergency Plan Implementing Procedure EPIP 300-16. "Radiation Surveys Under Accident Conditions" W/B30913 ltr.receipt form.procedure history & safety evaluation SCOTT.D J. Commonwealth Edison Co. 83/09/09 10pp 20/34 242 24X Fiche 50-010.83/09/22.8310040121
- 8310140262 Forwards IE Insp Repts 50-237/83-28 & 50-249/63 26 un 830913-16 No noticompliance noted PAPERIELLO, C J Region 3. Office of Director 83/09/30 REED, C Commonwealth Ldison Co 2pp 20761 275 24X Fiche 50-237.83/09/30. 8310140262
- --8310140267 IE Insp Repts 50-037/83-28 & 50-249/83-26 on 830913-16 No noncompliance noted Major areas inspected emergeticy preparedness exercise PLOSRIT, f. GLOGRESH, W. SMLLL, M. Region 3. Office of Director 82/09/30 10pp 20761 297 24X Fiche 50-237, 83/09/30, 8310140262
- 8310270009 Releases public version of revised emergency plan implementing procedure FELTON.J M Bivision of Rules and Records 83/10/21 Decument Hanagement Branch 1p 20940 147 24X Ficho 50-010.83/10/21.8310270009
- --8310270017 Public version of Nev 5 to Emergency Plan Implementing Procedure EPIP 300-1. "Initial Notifications & Generating Station Emergency Plan Responses (Primary Responsibility Station Director) "W/831014 lt. SCOTT.D J. Commonwealth Edison Co. B3/10/03 DENIGN, H.R. Diffice of Nuclear Reactor Regulation, Director 20pp 20940 168 24X Ficht 50-010.83/10/21.83107/0009
- B310270526 Releases public version of revised emergency plan implementing procedure FELTON, J N. Division of Rules and Records B3/10/21 Document Management Branch ip 2093/216 24X Fiche 50-000, B3/10/21, 8310270574
- ~-831027053/ Public version of Nev 2 to imargency Plan Implementing Procedure EGF-6, "Administration & Logistics Manager" W/83101/ Itr & receipt form NELLIS CA , HESSNER, R. M. MORRE, R. D. Gommonwealth [dison to 83/02/18 DENTON, H. R. NR. No Detailed Affiliation Given /pp 20937 217 24% Fiche 50-000, 83/10/2(, 8310270224

- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J.N. Division of Roles and Records. 83/10/25. Document Management Branch. Ip. 20943-1/4. 24X Fiche 50-000-53/10/25, 8310280307.
- --8310280.314 Public version of revised questating stations emitging plan telephone directory GALLE, D. F., MUDRE, R. D. Commonwealth Edison Co. 1/3/08/11 PERTON IR Diffice of Nuclear Reactin Regulation, Director App. 20963-127 24X Fiche 50-000-83/10/25.8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON.JM Dyvision of Ruler and Records 83/10/26 December Management Branch 1p 20962 266 24% Fiche 50 000 BJ/10/26. 8310280191
- --8310280209 Public version of Nev 1 to Emergency Plan Implementant Procedure ECL-15, "Emergency Operations Lacility Activation" MORE.R D (ommonwealth Educor Co G3/08/02 Sopp 20/66/c/c/ 24% Fiche 50 C00, 83/10/25, 8,110,80(9)
- d Adjudicatory coirespundence
- 8310070156 Enrwards Director's Decision 8J-14, denying 670909 10(18.) Impatition re transport of spent muclear fort from West Valley DAVIS, J G Office of Nuclear Material Bafety & Safaquards birector 83/09/30 CCLLBREZZL/A J Ohio State of 2pp 20080 304 , 4% Fiche 50 000.03/09/30.8310070156
- -8310070161 Forwards Director's Decision Ed 14, denying throbes included presention retransport of spirit nuclear fuel from West Valley DAVIS.J G. Office of Nuclear Nuterial Safety & Safequards Director 83/09/30 RESNIKUEEN Silia (1nh. 1). 20680-309 24X fishe 50-000.83/09/30 88310070156
- --B310070167 Notice of issuance of Director's Decision 194-14 denying State of ON & Sierra Club 830709 & 98/4 respectively.
 10CFR2 706 petitions re transport of spent nuclear fuel fina West Valley
 DAVIS-J G Office of Nuclear Material Safety & Safequards Director 83/09/30 2pp 20080 310 24X
 Ficho 50-000,63/09/30,83100/0156
- ~-8310070171 Pirector's Decision B3-14, dinying State of CH & Sign a Cta-830909 & 0824, respectively, 10CH & 206 petitions 7 e transport of spent nucleur fuel from Work Valley Requort for hearing 5 for preparation of E15 denind DAVIS.J O Defice of Nuclear Material Eafety & Safeguards Director 83/09/30 18pp 20680 312 24X Fiche 50-000, 63/09/30, 83100/01%
- 8310270297 Order extending time until 831129 for Commission to but to review Director's Decision DD 83-14 denging Sierra (lub 's State of GH requests CHILLS J Office of the Secretary of the Commission Bi/10/P's Commissioners in 20923-195 24X Fiche 50-000-83710/P's GB10270297
- P Operating income stage documents & correspondence
- 8310040471 Submits addl info to allow iscuance of full-torm () for 40 yrs from original provisional OL issued 691272 Request consistent w/Atomic Energy Act & NRC regulations RYBAK. B. Commonwealth Edison Co. 83/09/27 DENTUNIER DIFFER C. Nuclear Reactor Regulation. Director app. 20621.271 1/93 Fiche 50-237,03/09/27.8310040474
- 8310040320 Commits to formal submittal of proposed radiological (1% amend by 840106 RYBAK, B Commonwealth Edison Co 83/09/28 DENTUN, If R 411fice of Nuclear Reactor Regulation, Director 1p 20620 (111 1/1) Ficha 50-737,0%/09/28,8310040800
- 8310070264 Forwards proprietory "Diesden R/3 Nuclear Generating Plants Suppression Pool Temp Response." "EI Hatch Nuclear Frants Station Units 1 to 2 Suppression Pool Temp Response" & Max & I 830825 meeting viewfraphs Repts withheld (rof 1011R) 7/0) PFEFFERLEN.H C. General Electric Co. 83/09/30 VA55ALLU.D & Operating Reactors Branch P. Alpp. 20811 292 2/47 Fiche 50 000.07/09/30.83100/02/44
- 8310050524 Forwards SER results response to NUREG-0737. Item 11 H 1. "RCS Vents" Item complete CRUTCHFIELD.D. Operating Reactors Branch 5 83/10/03 FARRAY. It 4 Commonwealth Edison Co. App. 70632 3Jb 24X Fiche 50-237. 81/10/0-8310050524

- 8310050534 'Selected Operating Reactor Issues Program II MCb Vents (NOREG 0717. Item II B 1), 'final technical evaluation rept for Dierden Units 7 t 3 HELD.J | Lawrence Livermore Laboratory FIN A-02',0 TF-38070823A 83704705 ALBERTHALLO NRC - No Detailed Affiliation Given 4pp 2063, 341 248 Fiche 50 237,83713703, 8310050524
- 8310120189 forwards response to NRC 830316 questions & request for add: info re SEP Topic III-5 A concerning pipe breaks inside containment REBAK. B. Commonwealth Edison Co. 83/10/03 GILDERT, R. Operating Reactors Branch 5 5pp. 20695-349 24X Fiche 50-237,83710/03,8310120189
- 8310110168 Corrects Paragraph 3 M 5 of Amend 75 to License DPR-19 re 821221 request for Cycle 9 optration w/reload feel supplied by Exxon Nuclear (o CRUTCHTILLD.D Operating Reactors Branch 5 83/10/05 FARRAN.D (Commonwealth Edison Co 3pp 20666 23ts 24X Fiche 50-237.83/10/05,8310110184
- 8310200273 forwards schedules for equipment qualification test programs for facilities per 810528 ltr Dates given for current qualification activities should be viewed as "target dates' tool as firm dates.

 BARNES, P. L. Communumealth Edison Co. 83/10/05 KFP/LER, J. G. Region 3, Office of Director. 10pp. 20830-034, 24% Ficbe 50-000, 83/10/05, 83005002/4.
- 8310120424 Requests formal update of completion schedules from integrated plant safety assessment repts to facilitate overall SIF resolution Response requested within JU days CRUTCHFIELD D Operating Reactors Brouch 5 83/10/06 FARRAS, D L Commonwealth Edison Co. 2pp. 20698 7HO 24X Fiche 50-237,83/10/06,8310120474
- 8310120303 Notifies that monthly publication of FR notices will be provided w/o transmittal life provided w/o transmittal life (RUICKFILLIO, D. Operating Keartons Branch 5 83/10/07 FARRAY, D. I. Commonwealth Edison Co. 2pp. 70690 336 24X Fiche 50-237, B3/10/07, B31012-0.037
- 8310260001 Forwards add1 info requested in NRC 830316 ltm re util response to 517 Topic 111-4 A. "Formado Nissiles" (noting water to HXs is supplied from svc water sys which is independent from condensate storage tank RYBAK.B Commonwealth Edison to 03/10/18 OllBLR1.R Operating Reactors Branch 5 18pp 20712 206 247 Fiche 50-010.83/10/10.8310260001
- 831028014/ Forwards 830930 Director's Detision 83-14 doining State of OH & Bierra Club 10CFR2 206 prtitions re transportation of spent fuel from West Valley facility, pt. 830930 request CUNNINGHAM, R. 1 Division of Fuel Cycle & Material Safety 83/10/10 MILLFR/ Environmental Policy Institute 2pp 20961 3/9 24% Fiche 50 000.83/10/19.831028014/
- 8310250188 Forwards Amends 76 % 67 to Licences DPR-19 % DPR-25, respectively & safety evoluation Amend changes Tech Specs re operability requirements for ECLS ring header snubbers CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/21 FARRAR, D. L. Commonwealth Edison Co. 2pp. 20873 344 24% Fiche 50-237,83/10/21,8310250188
- --8310250195 Amends 76 & 67 to licenses IPR-19 & DPR 25 respectively, changing tech Specs re operability requirements for ECCS ring header snubbers, per BUCALS application CRUTCHIFICED, D. Operating Reactors Winarch 5 83/10/21 JApp 20893 346 24X Fiche 50-237.83/10/21,8310250188
- ~-B310250200 Bafety evaluation supporting Amends 76 % 67 to Licenser DPR-19 % DPR-25, respectively * Office of Nuclear Reactor Repulation, Director 63/10/21 2μμ 2099 360 24X Fiche 50-227.63/10/21.6310250168
- 8310310052 Denies 830702 request for extension to submit formal response to Generic Ltr 83-28 to Salem ATMS event Info must be submitted by 83105 Participation in owners group for issues requiring long-range planning acceptable CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/26 FARRAR, D. Commandwalth Edison Co. 3pp. 20751-046 24X Fiche 20-237,83/10/26,8310310052
- G Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Noti.# 85 51, "Alleged Use of Stand Ins for Welder Qualification Testr" Sec list encl JORDAN,E L Division of Emergency Preparadness & Enganeering Response (Past B30103) 83709/26 Consolidated Edison Co. of New York, Inc. 117pp 20794 022 24% Fiche 50-000.83709/26.8.003J00.440

- 8308300.442 IE Info Notice 83-62, "Failure of Redundant losic Cas Detector: Positioned at Control Room Ventilation Am Intakes " Svc list encl JORDAN L Division of Emergeticy Preparedness & Engineering Response (Post 830103) 87/09/26 Convolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26,8308300042
- 8308200345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 5A i Differential Relows" Svt list ench JORDAN, I Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Cn of New York Inc 114yy 20778 001 24X Fichs 90-000,83/09/26,8308/00345
- GJ08300J49 IE Info Notice 83 64, "Lead Shielding Attached to Safety-Related bys W/o 10ClMS0 59 Evalvation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 87/09/29 Consolidated Edison Cn of New York, Int. 115pp 20716 324 24X Fithe 50-000, 8J/09/29, 8J00J00347
- 8310140262 Forwards IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 83/09/30 MEED,C Commonwealth Edison Co 2pp 20761 495 24% Fiche 50-237.83/09/30.8310140262
- --8310140267 IE Insp Repts 50-237/83-28 & 50-249/83-26 on 630913-16 No noncompliance noted Major aleas Inspected emergency preparedness exercise PLOSKI, T. GLOCERSEN, W., SNELL, W. Region 3, Office of Director. 63/09/30 | 10pp | 20761 | 297 | 248 | Fiche 50-237, D3/09/30, B310140762
- 8310200124 Forwards IE Mgt Merting Repts 50-010/83-18, 50-237/83-P7, 50-249/83-25, 50-259/83-27, 90-45/83-26, 50-295/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38 50-454/83-44, 50-455/83-33, 50-455/83-14 & 50-457/83-13 NORELIUS, C E Division of Project & Resident Programs 8710/04 REED. C Commonwealth Edison (0 2pg 20834-098 P4) Fiche 50 000.03/10/04,8310200124
- --B310200148 IE Mqt Merting Repts 50-020/B3-18.50-23//B3-27.50-249/B3-25, 50-254/B3-27.50-265/B3-26.50-255/B3 19.50-304/B3-20, 50-372/B3-38.50-372/B3-50-454/B3-44.50-455/B3 33.50-454/B3-44.50-455/B3 33.NGRECIUS.C I Division of Project Resident Programs DAVIS.A B Region 3, Office of Directon B3/10/03 4pp 20534 100 24X Fiche 50-000, G3/10/04.8310700124
- 8310110140 Discusses concerns re licensee actions following failure of certain ECCB/containment isolation valves.per review of infairn LER 83-006/011 0 & 1E Insp Repts 50-737/83-07 & 50-249/83-06 License amend application requested CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/05 FARRAR, D. I. Commonwealth Edison Co. 5pp. 20666 RYS 24X Ficht 50-237,83/10/05,8310110140
- 8310170337 Submits status of as-built reviews of safe shutdown piging supports for It Bulletin 79-14 As result of review of Guad Cities, two piping sys found to have addl discrepancies Seven new hangers added RYBAK.B Commonwealth Edison Co 83/10/06 KEPPLER, J G Renion 3, Office of Director 2pp 20/85 155 24X Fithe 50-000.83/10/06, 83101/033/
- 830B300378 IE Info Notice B3-65, "Burveillance of Flow in KTD Bycass Loops Used in Wostinghouse Plants " Svt list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3710707 Consolidated Edison Co. of New York, Inc. 76pp. 20827 213 24X Fiche 50-000,83/10/07.830B300978
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E t Division of Emergency Prenaredness & Engineering Response (Pust 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000.83/10/07.8308300752
- 8310210053 Forwards IE Insp Repts 50-010/E3-17.50-23//85-24 & 50-249/83-24 on 830829-31.0901.02 & 08 & notice of violation PAPERIELLO, C. J. Regian 3. Office of Director 83/10/07 RLED, C. Commonwealth Edison Co. 2pp. 20855-286 24X Fiche 50-010.83/10/07.8310210003
- --8310210061 Notice of violation from insp on 830829-31,0901,02 & 08 PAPERIELLO,C J Region 3. Office of Director 83/10/07 2 pp 20855 288 PAX Fiche 50-010,03/10/07.8310210053
- --8310210074 IE Insp Repts 50-010/83-17.50-237/83-26 & 50-249/83-24 un 830829-31.0901.02 & 08 Noncompliance noted inadequate calibr of D-1 & D-2/3 chimney monitors & failure to follow procedures re vadiation protection PAUL.R A , HUFTLK.L J . OREGUER.L R Region 3, Office of Director 83/10/07 8pp 20855 290 24X Fiche 50-010.83/10/07.8310810053

- 8308300759 IE info Notice 83-67, "Emergency Use Respirator Hatl Diffict Causes Production of Nortons (aces ' Size list ently JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Pust 830)(3) 837(0/11 (or b)) dated Editon Co. of New York, Inc. 117pp P1043 075 24X Fiche 50-000.83/10/11, 8308309/57
- 8308300761 IE Info Notice 83-68, 'Respirator User Warning Delective Self-Contained Breathing Apparatus Air Cylinders' Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering
 - encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 63/10/11 (ansalidated Editor Co. of New
 York, Inc. 190pp. 20827-129 24% Fiche 50-000, 83/10/11, 8308300/61
- 8310140036 Ack receipt of 830922 ltr informing NRC of stips taken to correct violations noted in If Insp Repts 50-010/03 09. 50-237/03-14 % 50-249/03-13 NDRELIUS.C Division of Project & Resident Programs 83/10/)1 REED.C Commonwealth Edison Co ip 20767 341 24X Fiche 50 010.83/10/11.8310140034
- --B310140049 Responds to NRC 830823 itr re violations noted in il lose Repts 50-010/83-09,50-237/83-14 & 50-2497/83-13 Corrective actions operations personnel closed & latched all battery charger cabinets FARRAR, D L Commonwealth Edison Co B3/09/22 KEPPLER, J & Region 3, Office of Director Spp E0767 342 247 Fiche 50-010,83/10/11,83J0140036
- 8310140099 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-010787 LP. 50-237/83-20 & 50-249/83-18 NDRELIUS.C E Division of Project & Resident Programs BJ/10/11 REED.C Commonwealth Edison Co 1p £0766 099 EAX Fiche 50-010.83/10/11.8310140099
- --BB10140104 Responds to NRC 930/21 ltr re violations noted in il lissp Repts 50-010/83-12.50-237/83-20 t NO-249/83-18 Corrective actions scope & general method of training program completely detailed in training procedures FARRAR.D L Commonwealth Edison Co BB/09/16 KLPFLER.J Q Region 3, Office of Directon Epp 20/66 100 24% Fiche 50-010.83/10/11.63f0140099
 - 13018026B Clarifies NRC position re-procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months AXELSON. W.L. Region 3, Office of Director 83/10/14 REED. C Commonwealth Edison Co. 7pp. 20802 302 24X Fiche 50-010.83/10/14, 8310180268
- 8310180551 Notification of 831021 meeting w/BWR licensers in Bothesda. MD to discuss future insps for intergranular stress corresion cracking MIRAGLIA.F J. Assistant Director for bafety Assessment B17/10/14 EISENKOT, D. G. Division of Licensing 5pp 20823 358 24X Fiche 50-000.83/10/14.8310180591

Periodic operating reports & related correspondence

10120273 Monthly operating repts for bept 1983 W/8,31003 ltr 3CMR0E0EM, B.A., SCOTT. D.J. Commonwealth Edison Co. 87/10/03 Sirector's Office, Office of inspection and Enforcement 16pp 20493 081 24% Fiche 50-237, 83/10/03, 8310120273

Reportable occurrences, LERs & related correspondence

- iiOi10425 FDIA request for info re PND-111-83-027 concerning faulty valve radiographs.PND-111-83-026 concerning use of lubricant on valve seats & info on DGE/NRC 8304(7-20 meetings concerning geologic repository in salt program HA477.5 t. Ohio Citizens for Meaponsible Energy 83/05/k0 FELION.J H Division of Rules and Records 1p 20/06/001 24% Fiche 50-000, 83/05/10.8310110425
- 3310110430 Responds to FGIA request for four different categories of documents described in 830510 ltr Forwards matilisted in App Airesponsive to Items 1.2 & 4 DDF should be contacted for matirequested in Item 3 of itr FELION. J M Division of Rules and Records 83/06/14 HIATI, 5 in Ohio Citizens for Responsible Energy 3pp 20706 007 24% Fiche 50-000, 83/06/14, 8310110430
- ~-8310110461 Excerpt from notification of events at two different facilities re deficiency contenting control complex chilled water sys & info received that grease incorrectly used on MSIVs.respectively Related info encl # Region 3, Office of Director 83/04/08 11pp 20/06 044 24) Fiche 50-000.83/06/14.8310110430

- --B3(01)046/ Daily rept relevents at three different ficilitic; [A(1)44/) experienced arram due to lam water level PNO-111-B) 076 updates use of lubricants on valve sents.

 * Region 3. Office of Director B3/04/13 lp 70/06 062 74% Fichs 50-000 B3/06/14-B3(01)04/06
- --BilolioA/B Responds to BilolioA its requesting info ie use of fullight matts on valve seating surfaces Lubircants & cleaning solvents used on valve component surfaces, per vendo; recommendations & maint practices.

 FARRAR-D L Commanueaith Ldison Co Bilol/22 KFPPLFR, J (Region 3, Office of Directo; App. 20/06/063 24v Fiche 40-000.83/06/14-83101104/0
- 8310260008 Add1 response to FOIA request for 1/ categories of Includes Forwards documents listed in Apps B.C & D Info Te Fraudulent practices of Roy Hiller. Inc available in PDR FELTON. J N Division of Rules and Hecords 83/06/23 (LFWIII, I Public Citizen Litigation Group 15pp 20928 001 (AX Fiche 50-000.03/06/23.8310260008
- --B310260076 Describes facility B21203 flood 2 corrective action, tasks Chronology of events encl.including notification of event 2 procedure for briefing commissioner PERKINS, K. NKC No Detailed Affiliation Given U3/06/(9) DEYQUNG, R.C. Director's Office Office of Inspection and Enforcement 11pp 20721 136 24X Licke 50-010.83/06/3 1, B310260008
- B310070301 Potential Part 21 rept to underrange characteristic of Model N-EliOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notific BERBERIAN M J Foxboro Colp B3709740 Director's Uffice, NFF1 of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000.03709/30.8310070301
- B3100603/3 LER B3-064/03L-0 on B30905, control rod drive scram disclassivol continuous ultrasonic test indication displayed estats info Cauted by heating steam line leak above monitor cabinet Leak repaired Hodule replaced W/83(003 16) (NOTE). REELS, SCOTI, D.J. Commonwealth Edison Co. 83/10/03 KFTP1(R., F. Region 3, Office of Director 3pp (0646 069 10X). Fiche 50-237, 03/10/03, 8310060373
- B310110140 Discusses concern's relicensee actions following failure a certain ECCS/containment isolation valves,per review of information that B3-006/017-0 & IE Insp. Repts 50-237/83-07 & 50-247/83-08 License amend application requested CRUTCHFIELD. D. Operating Reactors Branch 5 B3/10/05 PARMAR, License amend application requested CRUTCHFIELD. D. Operating Reactors Branch 5 B3/10/05 PARMAR, License amend application 5 B3/10/05 PARMAR, License 3010110140
- 8310170553 Responds to item of concern in NRC 83090/ itr ie URD/19 % OB11 events involving discovery of holes in expansion bellows on torus to drywell vacuum breaker lines Corrective actions roumerated RYBAK, B. Commonwealth Edition (a. 83/10/0/ BENIUN.II R. Office Nuclear feattor Regulation, Director 4pp. 20/80-207 PAX Fiche 50-237,83/10/07.8310170053
- 9310210127 LER 83-068/017-0 on 831002, during HPCI surveillante pitte 2300-8, motor operated valve 2301-35 failed to open on receiving open signal Caused by Limitorque valve operator terminal 5 broken lug connector lug replaced W/831012 lt; ANANOAPPA, A . SCOTT.D J Commonwealth Edison Co 83/10/12 KEPPLER.J G Region 3. Office of Director 4pp 20000 21/ . A Fiche 50-237,83/10/12.8310210127
- 8310210313 LER 83-046/03L-0 on 830718 MSIV 20 2 5 s clorure time exceeded Tech Spec requirement of 3 to 5 r Coused by timing mechanism out of adjustment Mechanism adjusted W/831012 lt; MAXMELLID. SCOTI.D J. Commonwealth Edison Co. 83/10/12 KEPPLER.J O. Region 3, Office of Director. 3pp. 20810 217 2-4 Fiche 50-237 83/10/12 8310210.113

- DOCKET 50- 244 ROBLER EMMET GINEA NUCLEAR PLANT, UNIT J
- B310120344 Notification of B310/7 musting w/util in Bethesda,MD to discuss mods to fire protection safe shutdown plan DICK.0 7 Operating Reactors Branch 5 B3/10/07 (RUTCHIJEID,)) Operating Reactors Branch 5 Jpp 20/00 25/ 24/ Fiche 50 244, 03/10/07.8310120344
- 8310270076 Releases public version of revised emergency plan implementing procedures
 FELTON.J M. Division of Rules and Records 83/10/20 Document Management Branch to 20942 098 24X Fiche 50-244,83/10/20.8310270076
- --8310270085 Forwards public version of revised emergency plan implementing procedures including Procedures SC-607 restation call list SC-606 respecialized notification list & SC-233 research & rescue operation MAICR, J E. Rochester Gas & Llectric Corp. 83/10/07 MURITY, T. Region 1. Uffice of Director ip 20942 059 24X Fiche 30-244,83/10/20.83102/00/4
- --B3102/0094 Public version of revised emergency plan implementing procedures including Procedures SC-60/ re station call list. SC-606 re specialized notification list & SC-233 re search & rescue operation BDDINE-J C . SPECTER, S M Nuchester Gas & Electric Corp B3/10/05 SJpp 20942 05/ P4X Fiche SO-244,83/10/20,8310270076
- P Operating license stage documents & correspondence
- 8310310017 FDIA request for documents reintegrated leak rate tests for listed facilities to be placed in PDR CONNER. L. Affiliation Unknown 83/09/02 NRC - No Detailed Affiliation Given ip 21004 270 24X Fiche 50-000.63/09/02. 8310310017
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavoilable FELTON, J M. Division of Rulet and Records 83/07/04 CONNER.t. Affiliation Unknown ip 21004 271 24X Fiche 50~000,83/07/04,8310310031
- --B310310073 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," including analysis & interpretation of Type A test results & summary analysis of Type B & C tests performed since last Type A test in Oct 1972 WHITE, L D Rockester Gar & Llectric Corp 76/05/19 PURPLE, R A Office of Nuclear Reactor Regulation, Director 1p 21007 075 24X Fiche 50 000, B3/07/06, B310310031
- --B310310076 "Reactor Containment Bldg Integrated Leak Rate Tost "
 * Rochester Cas & Electric Corp 76/02/28 120pp 2100/ 076
 24% Fiche 50-000, 83/07/06, 8310310031
- 8310070020 Ack receipt of 830824 ltr requesting Commission publish notice of pending license amond in FR to New York State Energy R&D Authority license for utils w/irradiated fool storage faculties

 DAVIS.J G Office of Nuclear Material Safety & Safequards, Director 83/09/22 RESNIKOFF, M Sierra Club ip 20671 361 24X Fiche 50-000.03/09/22, 8310070020
- B310040491 Forwards safety evaluation supporting Westinghouse licensee responses to NVREG-0737. Items II K 3 1. "Automatic PDRV Isolation" & 1I K 3 2. "Ropt on PURVs" & Franklin Research Ctr "Operating Reactor PURV Repts (F-37). TMI Action "CRUTCHFIELD.D Operating Reactors Branch 5 83/09/27 MAJER.J E Rochester Gas & Flectric Corp 17pp 20624 106 24X Fiche 50-244.83/09/27.8310040401
- B310030080 Forwards safety evaluation accepting snow sampling & vent procedures subj to described and to Item 6 35 of Procedure 9C-452 License Conditions 2 C(7)1 through 20 (ref NUREG-0714) satisfied CRUTCHFIELD, D Operating Reactors Branch 5 83/07/29 MAJER, J F Rochester Gas & Liectric Corp 2pp 20570 069 24X Fiche 50-244.83/09/29.8310030080
- ~~8310030082 Safety evaluation supporting snow sampling & vent procedures subj to mod to Piotedure SC 45?

 * Office of Nuclear Reactor Regulation, Director 83/09/29 4pp 20570 071 24X Fiche 30-244,83/09/29,8310030080

- 8310070365 Forwards Amend 57 to License DPR-18 & safety evaluation Amend changes Tech Specs to keep releases of radioactive matl to unrestricted areas during normal operations ALARA CRUTCHFIELD.D Operating Reactors Branch 5 83/09/29 MAIER, J E Rochester Oas & Electric Corp. App. 20664 147 24X Fiche 50-244.83/09/29.8310070J65
- --B31007036B Amend 57 to License DPR-18.changing Tech Specs to keep releases of radioactive matl to unrestricted areas during normal operations ALARA CRUTCHTIELD.D Operating Reactors Branch 5 83/09/29 81pp 20664 153 24X Fiche 50-244.8J/09/29.8310070365
- --8310070372 Safety evaluation supporting Amend 57 to License DPR-18 * Office of Nuclear Reactor Regulation, Director B3/09/28 Bp; 20644 234 24x Fiche 50-244.83/09/29.8310070365
- --8301210240 "Radiological Effluent Tech Spec Implementation (A-2),"
 technical evaluation rept
 CHEN, S Franklin Institute/Franklin Research Center
 NRC-03-81-130 TER-C5506-93 83/01/19 CONGEL,F NRC No
 Detailed Affiliation Given 30pp 20664 242 24X
 Fiche 50-244.83/09/39,83100/0365
- B30B300771 Board Notification B3-128A forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid valves
 EISENHUT.D G Division of Licensing B3/10/04 PALLADING,N J .
 QILINSKY,V , ROBERTS.T M Commissioners Sipp 20818-001 24X
 Fiche 50-000,83/10/04.B30B300771
- --B310050206 Comments on Franklin Research Ctr qualification methodology research test of ASCO solenoid values Issuance of notification to licensees & applicants requiring response re values failing test recommended VOLLMER, R H Division of Engineering B3/09/28 EISENHUT, D G Division of Licensing 5pp 20818 CG2 24X Fiche 50-000, B3/10/O6,8308300771
- 8310120328 Advises that monthly publication of portions of FR notice will be forwarded w/o transmittal ltr Addressess listed on svc list should puruse monthly publication for pertinent hearing opportunity notices
 CRUTCHFIELD.D Operating Reactors Branch 5 83/10/07 MAJER, J E Rochester Gas & Electric Corp 2pp 20700 271 24X
 Fiche 50-244,83/10/07.8310120328
- B310180192 Responds to request for add1 info re 821208 proposed Tech Spec for plant heatup & cooldown curves based on results of capsule T Info supplied by Hestinghouse Chart summary of neutron flux munitor encl MAIER.J E Rochester Gas & Electric Corp 83/10/10 CRUTCHFIELD.D Operating Reactors Branch 5 App 20808 343 24X Fiche 50-244,83/10/10.8310180192
- 8310180193 Forwards response to requests for add1 info re special lifting devices used for control of heavy loads (ref NURTG-0612) MAIER, J E Pacific Gas & Electric Co 83/10/12 CRUTCHFIELD, D Operating Reactors Branch 5 22pp 20009 061 24X Fiche 50-244, 83/10/12, 8310180193
- 8310250681 Forwards SER (NUREG-0944) & FR notice re full-term OL application Provisional OL/full-term OL conversion issue will be resolved by ASLB W/o SER CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/14 MAJER. J E Rochester Gas & Electric Corp. 2pp. 20908 351 24X Fiche 50-244.83/10/14.8310250681
- --8310250682 Notice of availability of SER for full-term OL (NUREO-0744) CRUTCHFIELD.D Operating Reactors Branch 5 83/10/14 Ip 20908 353 24X Fiche 50-244.83/10/14.8310250681
- 8310260353 Forwards SER (NUREG-0821) "Integrated Plant SAR" for full committee review on util full term GL application W/o encl MIRAGLIA.F J Division of Licensing 83/10/14 RAY.J J ACRB Advisory Committee on Reactor Safeguards to 20918 332 24X Fiche 50-244,83/10/14.8310260353
- Q Inspection reports. JE Bulletins & correspondence
- 8310060017 Forwards 1E Insp Rept 50-244/83-20 on 830816-19 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/09/22 MAIER, J E Rochester Gas & Electric Corp 2pp 20649 253 24X Fiche 30-244,83/09/22,8310060017

- --8310060019 IE Insp Rept 50-244/83-20 on 830816-19 No noncompliance noted Major areas inspected radiation protection program including GA & GC in radioactive matls shipping & receipt & preparation & shipment of radioactive matls COLLINS.D J. BHANBAKY.N N Region I. Office of Director 83/09/16 7pp 20649 255 24X Fiche 50-244.83/09/22.8310060017
- 8310060044 Forwards IE Insp Rept 50-244/83-18 on 830802-05 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/09/27 MAIEM.J E Rochester Gas & Llectric Corp 2pp 20647 0/4 24X Fiche 50-244,83/09/22,8310060044
- --8310060048 IE Insp Rept 50-244/83-18 on 830802-05 No noncompliance noted Major areas inspected licensee actions in response to IE Bulletins 79-02,79-14 & 80-11 VARELA,A A. DURR.J P. Reçion I. Office of Director 83/07/16 Bpp 20647 076 24X Fiche 50-244,83/09/22,8310060044
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list anci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Totic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN.E L Djvision of Emergency Preparedness & Engineering Response (Post 830103) 83709/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83709/26,8308300342
- 8308300345 IE Info Notice 83-69. "Patential Failures of Westinghouse Type SA-1 Differential Relays" Eye list enel JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24% Fiche 50-000,83/09/26,8308'00345
 - 108300349 IE Info Notice 83-64. "Lead Shielding Attached to Tafety-Related Sys W/o 10CFR50 59 Evaluation " Svc list ncl ORDAN.E L Division of Emergency Preparedness & Engineering #sponse (Post 830103) 83/09/29 Consolidated Edison Co of New ork. Inc 115pp 20716-324 24% Fiche 50-000.83/09/29.8308300349
 - D210214 Forwards IE Insp Rept 50-244/8J-19 on B30808-0911 & notice f violation
 TAROSTECKI.R Division of Project & Resident Programs 83/10/05
 #AJER, J E Rochester Gas & Electric Corp 2pp 20852 089 P4X
 Fiche 50-244,83/10/05
 - 8310210217 Notice of violation from insp on 830808-0911 * Region 1, Office of Director 83/10/05 ip 20852 091 24X Fiche 50-244.83/10/05.8310210214
 - 8310210220 IE Insp Rept 50-244/83-17 on 830808-0911 Noncompliance noted Parlure to take prompt corrective action on Audit Finding 80-36 re status of Quality Group B & C sys leakage erams
 - erams
 ZIMMERMAN, R P , LAZARUS, W J Region 1, Office of Director
 B3/10/05 10pp 20852 092 24X Fiche 50-244,83/10/05.8310210214
 -)8300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Bypass.cops Used in Mestinghouse Plants " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering tesponse (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
 -)8300752 IE Info Notice 83-66. "Fatality at Argentine Critical Tacility " Syc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering tesponse (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
 - 18300757 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect auses Production of Noxious Gases " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison to of New York, Inc 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 3308300761 IE Info Notice 83-68, "Respirator User Walning Defective 8elf-Contained Breathing Apparatus Air Cylinders" Bvc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 127 24X fiche 50-000,83/10/11,8308300761

- 8310270143 Forwards SER re restart following steam generator tube rupture event on 820125.per NURLR-0916 Generator tube Fiber optic insplaceoptable.based on 10fo in 0til 821122 ltr CRUTCHFIELD.D Operating Reactors Branch 5 83/10/25 MALLY.JE Rochester Gas & Liectric Corp. 2pp. 200424 138 24X Fiche 50-244,83/10/25.8310270143
- --8310270149 Safety evaluation supporting steam generator tube fiber
 - optic insp # Office of Nuclear Reacton Regulation, Directon #83/10/25 20924 140 24% Fiche 50-244,83/10/25.8310270143
- R Periodic operating reports & related correspondence
- B310190032 Monthly operating rept for Aug 1983 W/B30906 ltr MCNAMARA.A E., SNOW.B A. Rochester Gas & Electric Corp. 03/09/06 NRC - No Detailed Affiliation Olven - 6pp. 20823 230 - 24y Fiche 50-244, 83/09/06. 8310190032
- S Reportable occurrences. LERs & related correspondence
- 8310250305 LER 83-026/017-0 on 830915, boild acid stolage tank solution concentration less than Tech Uped requirements Caused by leakage of reactor makeup water through valve FCV-110A & check valve 355 Sampling increased W/830929 ltr FILKINS, D. L. NAIER, J. E. Rochester Gas & Electric Corp. 85/09/29 MRRLEY, T. E. Region 1. Office of Director. App. 20899 004 24X Fiche 30-244, 83/09/29, 8310250305
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-E119M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.M J Forboro Corp 83/09/30 Director's Office Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30,8310070301
- 8310]10204 Forwards safety evaluation re thermal-hydraulic analysis of 820125 steam generator tube rupture incident ltem / resolved Reviews of Items 1.3,4,5 & 17 complete Remaining items still under review CRUTCHFIELD,D Operating Reactors Branch 5 83/10/05 MAJER.J F Rochester Gas & Clectric Corp 2pp 20665 308 24X Fiche 50-244,83/10/05,8310110204
- --8310110206 Safety evaluation supporting licenses evaluation of 6/10175 steam generator tube rupture incident.per NUREG-0716 POFfice of Nuclear Reactor Regulation, Director 69/10/05 6pp 20665 310 24% Fiche 50-244.83/10/05.8310110204
- 8310250217 LER BD-027/03L-0 on 830716, while reducing power, trip occurred from 1// power resulting in violations of Tech Specs 3 1 1 1a & c Caused by low-low stram generator level in loop B Operator counseled W/031006 ltr
 BEATTY, E J. MATER, J E Rochester Gas & Electric Corp B3/10/06 MURLEY, T E Region 1, Office of Director 3pp 20073 30/ AX Fiche 50-244, 83/10/06,831025021/
- B3101400B2 PND-I-B3-105 on B31007, seasmic event occurred in northeastern UB w/magnitude of 5 2 on Richter scale in NY & 4 0 in NH No damage to equipment identified GALLO,R M Region 1. Office of Director 83/10/07 ip 20766 116 24X Fiche 50-000,83/10/07,83101400B2
- 8310170373 Forwards SER re reactor coolant pump trip & restart criteria after \$20125 tube failure incident Adequate steps taken addressing items.based on info provided in 821122 ltr & B30422 response to Generic Lti B3-10d ltems B & 9 resolved CRUTCHTIELD.D Operating Reactors Branch 5 B3/10/14 MAILR.J F Rochester Das & Liectric Corp 2pp 20785 005 .44X Fiche 50-244.83/10/14,83101703/3
- --8310170378 SER supporting resolution of SER Items 8 % 9 re reactor coolant pump trip % restart criteria after 820125 tube failure incident

 * Office of Nuclear Reactor Regulation, Director 03/10/14 5pp 20785 007 24K Fichs 50-244,83/10/14.8310170373
- 8310190029 Summary of 831005 meeting w/util, INPO & ANL re INPU simulation of steam generator tube rupture event Summary & agenda enct DICK.0 F Operating Reactors Branch 5 83/10/14 Operating Reactors Branch 5 83/10/14 Operating Reactors Branch 5 14pp 20823 141 24X Fiche 50-244,83/10/14.83/10/140.83/140.83/10/140.83/10/140.83/10/140.83/140.83/10/140.83/10/140.83/14
- 8310270143 Forwards SER re restart following steam generator tube rupture event on 820125,per NUREG-0916 Generator tube fiber optic insplaceptable.based on info in util 821122 ltr CRUTCHFIELD.D Operating Reactors Branch 5 83/10/25 MAJLR.J E Rochester Gas & Electric Corp 2pp 20924 138 24% Fiche 50-244.83/10/25.8310270143

- --8310270149 Safety evaluation supporting steam generator tube fiber
 - optic insp * Office of Nuclear Reactor Regulation, Director 83/10/25 2pp 20924 140 24X Fiche 50-244.83/10/25,83102/014;
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8310060035 Forwards matl for 831005 emergency response exercise Infoneeded for obtaining security & Ladiation protection clearances for NRC personnel requested by 830914 Exercise objectives for licensee entl W/O enrl COUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W G Northeast Utilities 83/08/08 MWRLEY.T E Region 1. Defice of Director 5pp 20647 245 24X Fiche 50-245,83/08/08.8310060035
- 8310060205 Forwards draft exercise controller manual for upcoming 831005 full-scale emergency preparedness exercise Info re NRC personnel participation & roles requested to allow inclusion in final manual W/o enc! COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B3/08/22 MURLCY.T C Region 1. Office of Director 2pp 20647 035 24X Fiche 50-245,83/08/22,8310060705
- 8310120259 Forwards "Re-Entry & Recovery Scenario" section of emergency preparedness exercise controllers manual Limited distribution requested until completion of 831005 exercise COUNSILW & Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/09/27 MURLEY, T. F. Region 1, Office of Director 25pp 20693 145 24X Fiche 50-245,83/09/27,8310120259

J Insurance & indemnity information

- B316270461 Forwards Endorsements BY & BO to NELIA Policy NF-173 & MAELU Policy MF-52, respectively, Endorsement 4 to NELIA Certificates NF-15 & NF-16 & MAELU Certificates MF-15 & nr-10 SINISI, J M. Marsh & McLennan, Inc. 83/10/21 SALTZMAN, J D Assistant Director for State & Licenser Relations /pp. 20923 126 24X Fiche 50-245,83/10/21,8310270461
- Operating license stage documents & correspondency
- 8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L Affiliation Unknown 83/05/02 NRC No Detailed Affiliation Olven 1p 21004 270 24X Fichs 50-000,03/05/02,
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON, J M Division of Rules and Records 83/07/06 CONNER.L Affiliation Unknown ip 21004 271 24X Fiche 50-000,83/07/06,831020021
- ---B3:03:0072 "Resutor Containment Bldg Integrated Lesk Rate Test "
- 8310030428 Requests that proposed Tech Spec change per 001015 ltr be reviewed considering schedule for integrated primary containment leak rate test to be conducted during upcoming refueling outage
 CDUNSIL, H Q, BEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) SEARS, C F Northeast Utilities 83/09/22
 CRUTCHFIELD, D Operating Reactors Branch 5 tp 20593 1// 24) Fiche 50-245,03/09/22,8310030420
- B310170656 Requests rev to confirmatory order contained in B30314 ltm for NUREG-0737 ltems II F J 1 & 11 F i 2 to specify new B40101 completion date Replacement of Geiger-Mueller in detectors will be completed by B40101 COUNBIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Uclinties) COUNBIL.W 0 Northeast Utilities B3/09/27 MILLER.J Q, Operating Reactors Branch 3 2pp 20782 070 24X Fiche 50-245,83/09/27,8310170656
- 0310170504 Application to amend Licenses DPR-21 & DPR-65, revising Tech Spec Section 6 re administrative controls to comply w/final rule on licensed operator staffing at nuclear power units per 44FR31611 per 44R31611
 COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W O Northeast Utilities 83/10/04
 MILLER.J R Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 20784 137 24X Fiche 50-245,83/10/04
 8310170504

- 8310040213 Responds to 830914 proposal to develop integrated review for pending licensing actions Meeting to discuss proposed review requested
 - requested
 EISENHUT, D © Division of Licensing 83/10/05 COUNSIL, W ©
 Connecticut Yankee Atomic Power Co COUNSIL, W © Northeast Nuclear
 Energy Co (subs of Northeast Utilities) 5pp 20647 131 24X
 Fiche 30-000.83/10/05.8310060213
- B31012030B Requests update of completion schedules presented in integrated plant safety assessment rept within 30 days CRUTCHFIELD. D Operating Reactors Branch 5 82/10/06 CDUNSIL.W Q Connecticut Yankee Atomic Power Co CDUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 20701 004 24X Fiche 50-000.83/10/06.831012030B NSIL, W.O. Northeast Nuclear Spp 20701 004 24X
- 8310120411 Notifies that util will no longer receive portions of FR containing Commission monthly notices w/transmittal ltr Util should carefully peruse publication for hearing opportunity notices
 CRUTCHFIELD.D Operating Reactors Branch 5 83/10/07 COUNBIL, W Q
 Connecticut Yankee Atomic Power Co 2pp 20699 041 24X
 Fiche 50-000,83/10/07,8310120411
- 8310180469 Submits addl info re NRC request to expand results of B21203 analysis of stack failure consequences to include failure of stack at foundation since SEP Topic III-2 had determined limiting foundation capacities COUNSIL, M. G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, M. G. Northeast Utilities 83/10/07 CRUTCHFIELD. D. Operating Reactors Branch 5. 2pp. 20802-051 24X Fiche 50-245.83/10/07.8310180469
- 8310180409 Forwards listed revs to "Corporate Organization for Nuclear Incidents (CONI) Procedure Manual," per Section V of App E to 10CFR50 W/o encl COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G COUNSIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W O
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 COUNSIL.W O Northeast Utilities BJ/10/12 EISENNUT.D O
 Division of Licensing ip 20803 179 24% Fiche 50-000,83/10/12,8310180409
- B310280112 Denies 830906 request for 120-day extension to respond to Generic Ltr 83-28 re generic implications of Balem ATMS events NRC review schedule does not permit extension Response due by 831105
 GRUTCHFIELD.D Operating Reactors Branch 5 83/10/26 COUNBIL.H G Connecticut Yankse Atomic Powrn Go COUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20929 261 24X Fiche 50-000.83/10/26.8310280112

@ Inspection reports. IE Bulletins & correspondence

- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list entl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000.83/09/26.8308300942
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFRS0 57 Evaluation " Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/29 Consolidated Edison Co of New
 York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Nes York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.83083000378

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 (onsolidated Edison Co of New York, Inc 79pp 20862 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300789 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Noticus Gases." Syc list end. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21042-075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830107) 83/10/11 Cansolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308000761
- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda. MD to discuss future insps for intergranular stress corrosion cracking MIRAOLIA.F J Assistant Director for Safety Assessment 83/10/14 EISENHUT, D G Division of Licensing 5pp 20823 358 24X Fiche 50-000,83/10/14.8310180551
- 8310270193 Summary of 831021 meeting w/util re future insps for intergranular stress corrosion cracking Visugraphs encl SMEALJ J Operating Reactors Branch 5 83/10/24 Operating Reactors Branch 5 18pp 20924 338 24X Fiche 50-245.83/10/24.8310270193
- R Periodic operating reports & related correspondence
- 8310190015 Honthly operating rept for Aug 1983 H/830914 lt.
 HARRAN, O . MROCZKA, E J Northeast Nutlear Energy Co (subs of
 Northeast Utilities) HROCZKA, E J Northeast Utilities 83/09/06
 Division of Data Automation & Hanagement Information & 6pp
 20823 [28 24% Fiche 50-245, 83/09/06, 83]0190015
- Glozoo129 Monthly operating rept for Sept 1983 4/831014 ltr HARRAN.G . MRGCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/10/02 Office of Resource Management. Director 7pp 20834 343 24X Fiche 50-245,83/10/02.8310200129
- Reportable occurrences, LERs & related correspondence
- 8310180336 Updated LER 82-029/03X-1 on B21207. levels of five water storage tanks A & 8 found below Tech Spec limits Caused by stripped gear in make-up valve operator A & sticking brake & binding valve in motor operator B H/830631 ltr
 THULL.T B . NRDCZKA.E J Northeast Utilities MRDCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities)
 83/08/31 MURLEY.T E Region 1. Office of Director 4pp.
 20802 394 R4X Fishe S0-245.83/08/31.8310180336.
- NOO70163 Part 21 rept re potential defects in molded case of 100amp frame.multi-pole & & HE series circuit breakers Initially reported on 839902 ERHARDT.J V. Gould. Inc 83/09/26 MURLEY.T E Region 1. Office of Director 10pp. 20659 095 24X Fiche 50-000.83/09/26, 8310070163
- 310250263 LER 83-027/03L-0 on 830829 & 0926.time delay relay 595-117A tripped at 16 & 15 3 strespectively Caused by instrument drift Relay reset. #/830928 ltr
 THULL Y S , MROCZKA, E J Northeast Utilities MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/09/28 MURLEY, T E Region 1, Office of Director Jpp 20898 232 24% Fiche 30-245,83/09/28,8310250263
- 310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN. N J Fusboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement Jipp 20651 064 24X Fishe 50-000,83/09/30.8310070301
- BOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 310040228 forwards Suppl 1 to "Evaluation of Indian Point 2 fire Protection Program." per 830110 commitment, in response to 820810 ltr Addl exemptions requested from requirements of LOCFR50 48 & App R 9-TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/07/13 "ISENHUT, D. 9. Division of Licensing 2pp 20612 175 24X "Iche 50-247,83/07/13,8310040228

- -- 8310040235 Suppl 1 to 'Evaluation of Indian Paint & fire Protectic, Program " # TERA Curp 83/06/30 50pp 20612 177 24X Fiche 50-247,83/07/13,8310040228
- 8310050548 Forwards post-exercise/post-drill assessment.per US Brail 830608 commitment Previously noted deficiencies corrected MCLQUOHLIN, D. Federal Emergency Management Agency 63/09//s DIRCKG, H. J. Office of the Executive Director for Operations App 20629 267 24X Fiche 50-003.83/09/27.8J10050548
- ~~8310050552 Post-exercise assessment of 830824-25 exercise, Rockland County, for Indian Point Nuclea: Power Station
 * Federal Emergency Management Agency 83/09/24 56pp 20429 269 24% Fishe 50-003.83/09/29,8310050548
- --B310050554 Post-drill assessment of 830823 drill of Westchester Co. bus evacuation procedures for Indian Point Nuclear Power Station * Federal Emergency Management Agency 83/09/15 Yep 20629 328 24% Fiche 50-003.83/09/29.8310050348
- 8310130111 Forwards application for amond to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/09/29 VARGA, S A Operating Reactors Branch 1 2pp 20/46 294 24% Fichs 50-003,83/09/29,8310130111
- --8310130115 Application for amond to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator OfTOGLE.JD Consolidated Edison Co of New York, Inc. 84/07/27 2pp 20726 296 24x Fishe 50-003,83/09/29,8310130111
- --9310130119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator

 * Consolidated Edison Co of New York, Inc. 83/09/29 10pp 20726 298 24X Fiche 50-003,83/09/29,8310130111
- B310130305 Forwards FEMA 830929 itr transmitting FEMA Region II post-exercise Assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County MASSELL, D.F. Hearing Branch 1 83/10/04 GLEASON, G.P., PARRIS, O.H., SHON, F.J. Atomic Safety and Licensing Board Fanel 1, 20717 204 24% Fiche 50-247.83/10/04.8310130305
- 8310170321 Staff requirements mimb re Commission 831003 briefind by FEMA on recent emergency planning exercises in vicinity of facilities Commission noted sucressful completion of exercise Enforcement action unnecessary CHILK, S. J. Office of the Secretary of the Commission 83/10/11 Office of the Secretary of the Commission 1p 20795 277 24X Fiche 50-247, 83/10/11, 83/10/70321
- B310260304 Forwards mode to physical security plan, per 821109 request Mode withheld (ref 10CFR2 790 & 10CFR73 21) O TOOLE, J D Consolidated Edison Co of New York, Inc B3/10/14 VARCA, 5 A Operating Reactors Branch 1 2pp 20910 024 24X Fiche 50-003.83/10/14,8310260304
- 8310280253 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20962 318 24X Fiche 50-003,83/10/25, 8310280253
- --8310280261 Forwards public version of revised emergency plan implementing procedures including Procedures IP-1002 reemergency notification & communication & IP-1023 reoperational support ctr
 0/100LE-J D , OAVNY, R D Consolidated Edison Co of New York Im 83/05/06 ALLAN, J M Region I, Office of Director 3pp 20962 317 24X Fichs 50-003.83/10/25,8310280253
- --8310280267 Public version of revised emergency plan implementing procedures, including Procedures IP-1002 re emergency notification & communication & IP-1023 re operational support ctr Consolidated Edison Co of New York, Inc. 83/05/02 96pp 20962 322 244 Fiche 50-003.83/10/25,8310280253

G Adjudicatory correspondence

- 8310130305 Forwards FEMA 830929 1th transmitting FEMA Region 11 past-exercise assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County MASSCLLIDF Hearing Branch 1 83/10/04 (BEASON 0 P., PARRIS, 0 H.; SION,F. J. Atomic Safety and Licensing Board Panel 1p 20719 204 24X Fiche 50-247,83/10/04.8310130305
- 8310180145 Advises that SM Schinki & JF Neyer employed as legal & technical assistants, respectively Schinki & Meyer under recusal re Indian Point special proceeding due to previous employment contact
 BERNITAL-F Commissioners 83/10/17 Atomic Sufety and Licensing Board Panel ip 20809 167 24X Fiche 50-247, 83/10/17, 8310180145
- 8310190085 Order advising that ASLB expects to issue recommendations to Commission by 831024 GLEASON.J.P. Atomic Safety and Licensing Board Panel 83/10/17 bp 20822 267 24X Fiche 50-247.83/10/17.8310190085
- 8310240187 Forwards RH Bogardus 830920 ltr re adequacy of radiological amergency response plan
 HERBEK, R F New York, State of 83/10/17 NRC No Detailed
 Affiliation Given 3pp 208/8 089 74X Fiche 50-247,83/10/17,
 8310240187
- 83i 0260224 Opinion & recommendations to Commission on societal significance of risk estimates ASLB recommended safety improvements necessary to snaure plant will be operated w/reasonable assurance that public safety will be protected SHON.F J. PARIS, O H. GLEMBON.J.P. Atomic Safety and Licensing Board Panel 83/10/24 504pp 20913 033 24X Fiche 50-247,83/10/24,8310260724
- B310270307 Errata correcting Pages 3 & 435 of ASLB 831024 recommendations to Commission CLEASUN.J P Atomic Bafety and Licensing Board Panel 83/10/25 ip 20923 192 24X Fichs 50-247,83/10/25,8310270,d07
- P Operating license stage documents & correspondence
- 8310120242 Forwards identification & listing of electrical equipment important to safety, per 10CFR50 49 & schedule for either qualification or replacement of unqualified equipment Response to 830502 request for clarification also entl 0'TODLE-J D Consolidated Edison Co of New York, Inc 83/05/20 VARGA, S A Operating Reactors Branch 1 2pp 20692 124 24X Fiche 50-247, 83/05/20, 8310120142
- --8310120243 "Identification & Listing of Electrical Equipment Important to Safety,Per 100FR50 49 " * Consolidated Edison Co. of New York, Inc. 83/05/20 35pp 20492 124 24X Fiche 50-247,83/05/20,8310120242
- 8310120277 Forwards addl justifications for continued operation for specific items of unqualified equipment in response to 830502 request for clarification of environ qualification 0 TOOLE, J D Consolidated Edison Co of New York, Inc 83/06/07 VARGA, S A Operating Reactors Branch 1 7pp 20642 115 24% Fiche 50-247,83/06/09,8310120297
- 831005014B Forwards safety evaluation to NUREG-0737, Item II K 3 2 & Westinghouse Owners Group Rept WCAP-9804 based on results encl in Franklin Research Ctr technical evaluation rept Automatic PORV isolation sys not required VARGA. S A Operating Reactors Branch I 83/09/13 0'TDOLE, J D Consolidated Edison Co of New York, Inc 14pp 20639 100 24X Fiche 50-247.83/09/13.8310050148
- EGIO110460 Forwards safety evaluation re util responses to NUREG 0737. Item II (1 4, "Containment Pressure Monitor," Item II (1 4, "Containment Water Level Monitor" & Item II F 1 4, "Containment Hydrogen Monitor" Items resolved VARGA, S A Operating Reactors Branch I 83/09/21 D'TOOLE, J B Consolidated Edison Co of New York, Inc 10pp 20707 353 24% Fiche 50-247,83/09/21,8310110440
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon I & 2.Fermi 2 & Callaway EISENNUT, D 0 Division of Litensing 83/09/29 PALLADIND, N J , GILINSKY, V , ROBERTS, T Commissioners 3pp 20632 001 24X Fiche 50 000,83/09/29,8308300357
- ~-8310050558 "Interaction Between Piping & Pipe Clamps " Distribution lists encl TERAC.D Division of Engineering 83/08/31 Edpp 20632 004 24X Fiche 50-247,83/09/29,8308300357

- 8310130111 Forwards application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator G*TOOLE, J D Consulidated Edison Co of New York, Inc. 83/09/29 VARGAS A Operating Reactors Branch I 2pp 20/26/294 24X Fishe 50-003,83/09/29.83(013011)
- --8310130115 Application for amend to Licenses DPR-5 & DPR-26 incorporating changes to facility organization structure reposition of fire protection & safety administrator O'TOOLC, J D Consolidated Edison to of New York, Inc. 83/09/29 2pp 20726 296 24X Fiche 50-003,83/09/29,8310130111
- --8310330119 Proposed Tech Spec incorporating changes to facility organization structure re fire protection & safety administrator * Consolidated Edison Co. of New York, Inc. 83/09/29 10pp 20726 298 24X Fiche 50-00 & 83/09/29 8310130111
- 8310180579 Forwards safety evaluation supporting completion of generic issues re containment venting & purging (Multi-plant Action B-24) & NUREG-0737, Item II E 4 P VARGA:8 A Operating Reactors Branch I 83/09/29 O'TOGLL.J B Consolidated Edison Co. of New York, Inc. 14pp 20824 301 P4X Fiche 50-247, 83/09/29, 83/0180579
- 9310120194 Forwards add1 into on NUREG-0737. Item II K 3 17. "Rept on Outages of ECCS", per 830897 telton & NRC 830819 itr Add1 data factored into probabilistic safety study submitted on 820305 O'TOOLE J D Consolidated Edison Co of New York, Inc 82/09/30 VARGA 8 A Operating Reactors Branch I 5pp 20696 098 24X Fiche 50-247.83/09/30.8310120194
- 8308300763 Board Notification B3-151 provides info re desirability of current ECCS actuation togic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station
 EISENHUT, D 9 Division of Licensing B3/10/04 PALLADINO, N J .
 G3LINSRY, V . ROBERTS, T Commissioners 2pp 20698 033 24X
 Fiche 50-000,83/10/04.8308300743
- --83101105/4 Requests board notification he issued be rev to ECCB actuation logic of pre-TMI accident configuration in Borssele Nuclear Power Plant Westinghouse Owners Group will be requested to evaluate benefits of rev W/o encl MATTBON.R J Division of Systems Integration (post 011005) 83/07/26 CISENHUT.D G Division of Licensing 17pp 67005 170 24X Fiche 50-000.83/10/04.8308300763
- 83:0120366 Requests 6-month extension to 840506 for submittal of summary technical rept re math surveillance programs por lOCFR50. App H Reactor vessel surveillance capsule withdrawn on 821106 O'TOOLE. J D Consolidated Edison Co of New York, Inc. 83/10/04 VARGA: 8 A Operating Reactors Branch 1 ip 20697.102 PAX Fiche 50-247, 83/10/04, 8310120366
- 8308300771 Doard Notification 83-128A forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid valves
 EISENHUT, D.G. Division of Licensing 83/10/06 PALLADING, N.J. Commissioners 31pp 20818 001 24X Fiche 80-000,83/10/06,8308300771
- 8310270602 Informs that requirements of NUREG-0737. Item II N 3 17. "Rept on Outages of ECCS," mot Review of item complete VAROAS A Operating Reactors Branch 1 83710/19 0'TOOLE, J Consolidated Edison Co of New York, Inc. 2pp 20946-259 24X Fiche 50-247.83/10/19.8310270602
- G Inspection reports. IE Bulletins & correspondence
- B31003015B Notifies that GA program description review insp resched for B31003, per B30823 & 26 telcon requests
 MARTIN.T T Division of Engineering & Technical Programs 03/09 07000E, J D Consolidated Edison Co of New York, Inc ip 20590 089 24X Fiche 50-247,83/09/12,8310030158
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand Ins for Held Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineer Response (Post 830103) 83/07/26 Consolidated Edison York, Inc 117pp 20754 022 24X Fiche 50-000,03/09/26,
- 8308300342 IE Info Natice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JURDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of Naj York, Inc. 116pp 20777 210 24X Picke 50-000.83/09/26,830000034)

- B30B300345 IE Info Notice B3-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Energency Preparedness & Engineering Response (Post B30103) B3709726 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000.83709726.8308300345
- 030B300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl URBOAN E L. Davision of Empression Preparedness & Engineering
- enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,83080000349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Nestinghouse Plants" Svi list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 03/10/07 Consolidated Edison Co of Nei York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Natice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 024 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Notions Oases" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8J/40/11 Consolidated Edison Co of New York, Int. 117pp 21043-075 24X fichs 50-000.8J/10/11.8308300759
- 8308300763 1E Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svt list enc!

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fiche 30-000.83/10/11, 8308300761
- S Reportable occurrences, LERs & related correspondence
- B310190163 LER 83-033/03L-0 on B3082B, while in hot shutdown, M5IV for loop RI failed to completely close during isolation of secondary plant for maint Caused by insufficient lubrication of valve stem packing Stem packing lubricated W/B30927 ltr D:TOOLE, J D Consolidated Edison Co of New York, Inc B3/09/27 MYRLEY, T E Region 1. 0ffice of Director 2pp 20821 056 24X Fiche 50-247,83/09/27,8310190163
 - 710070301 Potential Part 21 rept re underrange characteristic of Yodel N-EilGM transmitter Underrange zero offset may occur then transmitter initially pressurized from atmospheric to oppressed zero input End users notified EMBERIAN.N.J. Forboro Corp. 83/09/30 Director's Office, Office f Inspection and Enforcement lipp. 20651-064 24% (che 50-000,83/09/30.83100/030)
 - 0120124 PNO-I-63-103 on 831004, licenses commenced á-day outage to epair moisture separator reheater tube leaks Leats, ndicated in four of six reheaters Unit will be maintained in hot shutdown Cooling fan motors reptaced (ENNY, T., KISTER, H. Region i, Diffice of Director 83/10/05 ip 20676 154 24X Fiche 50-247,83/10/05,8310120124
 - HO280074 RD on 831004.138-kV station availary power supply lost when pilot wire receiver relay tripped Cause under investigation Supply reestablished to all 5 9-kV buses Also reported per Part 21 JACKSON.C W Consolidated Edison Co of New York, Inc 83/10/05 MURLEY, I E Region 1. Office of Director 1p 20935 065 24X Fiche 50-247.83/10/05.8310280074
 - 10140082 PNG-I~83-103 on B31007, seismic event occurred in northeastern US w/magnitude of 5 2 on Richter scale in NV & 4 0 in NH No damage to equipment identified GALLG.R M Region t, Office of Director 83/10/07 ip 20766 116 24% Fiche 50-000.83/10/07.8310140092
- 310170310 PNO-I-83-103A on 831004. Licensee began unscheduled outage to repair maisture separator reheater tube leaks NHC notified on 831011 of reactor coolant leak on steam generator 2P hot leg manway Plant will be in cold shutdown for repairs FOLEY.T. JACOBS.R. NORRHOLM.L. Region 1. Office of Director 83/10/12 1p 20786 151 24X Fiche 50-247.83/10/12.8310170310
- 310200165 Part 21 rept re static temp calibr check on transmitters Initially reported on 831013 Caused by irregular setpoint for pressurizer pressure safety injection function New 1,824 parig setpoint recommended RAME, EP Westinghouse Electric Corp 83/10/13 DEYBUNG, R C Director's Diffice, Office of Inspection and Enforcement 2pp 83/10/13,8310200165

- T Hearing transcripts on non-antitrust matters
- 8310120029 Transcript of 831003 open session in Washington b(re emergency planning Pp 1-28 Supporting documentation encl * Commissioners 83/10/03 [lipp 20750 076 24X Fiche 50-003, 83/10/03, 8310120029
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 8310040121 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/09/22 December Management Branch 1p 20434 341 24X Fiche 50-010.03/09/22 8310040121
- --B310040436 Public version of Rev C to Emergency Plan Implementing Procedure EPIP 300-16. "Radiation Surveys Under Accident Conditions " M/B30913 ltr.receipt form.procedure history & safety evaluation
 BCOTT.D J Commonwealth Edison Co B3/09/09 10pp 200/14 342 24X Fiche 50-010, 03/09/22. E310040121
- 9310140242 Forwards IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16 No moncompliance noted PAPERIELLG, C J Region 3, Office of Director 83/09/30 NEED, C Commonwealth Edison Co 2pp 20741 295 24X Fishe 50-237, \$\text{R}\gamma\text{R}\g
- B310270009 Releases public version of revised emergency plan implementing procedure FELTON J M Division of Rules and Records B3/10/21 Document Management Branch ip 20940 167 24X Fiche 50-010,83/10/21, B310270009
- ~-B310270017 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 300-1. "Initial Notifications & Generating Station Emergency Plan Responses (Primary Responsibility Station Director) "W/831014 ltr SCOTT,D J Commonwealth Edison Co 83/10/03 DENTON,H R 0011 of Nuclear Reactor Regulation, Director 20pp 20940 Idil 20 Fiche 50-010,83/10/21,8310270009
- 8310270826 Releases public version of revised emergency planimplementing procedure FELTON.J M. Division of Rules and Records 83/10/21 Decument Management Branch ip 2093/216 24X Fache 50-000.83/10/21, 8310270526
- --8310270537 Public version of Rev 2 to Emergency Plan Implemential Procedure EDF-6, "Administration & Logistics Manager" W/831017 ltr & receipt form NELLIS, C A , HESSNER.R , MODRE,R D Commonwealth Edison (o 83/02/18 DENTON, H R NRC No Detailed Affiliation Given //) 20937 217 24X Fighe 50~000, 83/10/21, 8310270926
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000,03/10/25, 8310280307
- --8310280314 Public version of revised generating stations emergent plan telephone directory GALLE,DP, MODRE,RD Commonwealth Edison Co. 83/09/11 DENTON,HR. Office of Nuclear Reactor Regulation, Director Apr 20963 127 24% Fiche 50-000,83/10/25,8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000.83/10/26 8310280191
- ~~8310280209 Public version of Rev i to Emergency Plan Implementally Procedure EOF-15, "Emergency Operations Facility Activation" MODRE, R D Commonwealth Edison Co 83/08/02 50pp 20767 [b] 24X Fiche 50-000, 83/10/26, 8310280191

G Adjudicatory correspondence

- 83:0070154 Forwards Director's Decision 83-14 denying 830909 10CFR2 206 petition re transport of spent nuclear fuel from West Valley DAVIS.J C Office of Nuclear Material Safety & Safeguards Director 83:09/30 CELEBREZZE.A J Ohio. State of 2pp 20680 308 24X Fiche 50-000.83/09/30.8310070154
- --8310070161 Forwards Director's Decision 83-14, denying 830824 10CFR2 206 petition re transport of spent nuclear fuel from West Valley DAVIS.J G Office of Nuclear Material Safety & Safeguards.Director 83/09/30 REBNIKOFF, M Sierra Club 1p 20680 309 24x Fiche 50-000.83/09/30,8310070156
- --8310070167 Notice of issuance of Director's Decision 83-14, denying State of OH & Sierra Club 830909 & 6824; respectively, 10CFR2 206 petitions re transport of spent nuclear fuel from West Valley DAVIS.J 0 Office of Nuclear Material Safety & Safeguards. Director 83/09/30 2pp 20680 310 24X Fiche 50-000,83/09/30,8310070136
- --8310070171 Director's Decision 83-14, denying State of DH & Bierra Club 830909 & 0824, respectively, 100FRZ 206 petitions re transport of spent nuclear fuel from West Valley Request for hearing & for preparation of LIS denied DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director 83/09/30 18pp 20480 312 24X Fiche 50-000,83/09/30,8310070156
- 8310270297 Order extending time until 831128 for Commission to act to review Director's Decision DD-83-14, denying Sierra Club & State of OH requests CHILK.5 J Office of the Secretary of the Commission 83/10/25 Commissioners ip 20923 195 24X Fichs 50-000.83/10/25, 8310270297
- P Operating license stage documents & correspondence
- 8310040320 Commits to formal submittal of proposed radiological ETS amend by 840106

 RYBAK, D Commonwelth Edison Co 83/09/28 DENTON, H R Diffice of Nuclear Reactor Regulation, Director Ip 20620 218 24X Fiche 50-237,83/09/28,83100403P0
- 8310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant Suppression Pool Temp Response." "El Hatch Nuclear Power Station Units 1 & 2 Suppression Pool Temp Response" & Mark I B30825 meeting viewgraphs Repts withheld (ref locrit2 790) PFEFFERLEN.H C General Electric Co B3/09/30. VASSALLO,D B Operating Restors Brench 2 Sipp 20811 272 24X Fiche 50-000,83/09/30.83100702/44
- 8310050524 Forwards SER re util response to NUREQ-0737, Item [I B],
 "RCS Vents" Item complete
 CRUTCHFIELD,D Operating Reactors Branch 5 83/10/03 FARRAR,D L
 Commonwealth Edison Co App 20632 335 24X Fiche 50-237,83/10/03.
 8310050524
- --8310050534 "Selected Operating Reactor Issues Program II.RCS Vents (NUREG-0737: Item II B 1)," Final technical evaluation rept for Dresden Units 2 & 3 HELD, J T Lawrence Livermore Laboratory FIN A-0250 TF-380/0823A 83/04/06 ALBERTHAL, 0 NRC No Detailed Affiliation Oiven 4pp 20632 341 24X Fiche 50-237,83/10/03,8310050524
- 8310200273 Forwards schedules for equipment qualification test programs for Facilities.per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates BARNES, P. L. Commonwealth Edison Co. 83/10/05 XEPPLER, J. G. Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000,83/10/05,83/10/2002/3
- 8310120303 Notifies that monthly publication of FR notices will be provided w/o transmittal ltr CRUTCH# [ELD.D Operating Reactors Branch 5 83/10/07 FARRAR,D.L Commonwealth Edison Co 2pp 20690 336 24X Fiche 50-237,83/10/07,8310120303
- 8310260001 Forwards add1 info requested in NRC 830316 ltr re util response to SEP Topic III-4 A, "Tornado Missiles " Cooling water to HXs is supplied from svc water sys which is independent from condensate storage tank RYBAK.B Commonwealth Edison Co 83/10/18 QILBERT, R Operating Reactors Branch 5 18pp 20912 206 24X Fiche 50-010,83/10/18, 8310260001

- 8310280147 Forwards 830930 Director's Decision 83-14, denying State of OH & Sierra Club 10CFR2 206 potitions re transportation of spent fuel from West Valley facility, per 830930 request CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 83/10/18 MILLER, F Environmental Policy Institute 2pp 20961 329 24X Fiche 50-000, 83/10/18, 8310280147
- B310250198 Forwards Amends 76 & 67 to Licenses DPR-19 & DPR-29, respectively & safety evaluation Amend changes Tech Specs re operability requirements for ECCS ryng header smubbers CRUTCHFIELD. D Operating Reactors Branch 5 83/10/21 FARRAR, D. L Commonwealth Edison Co 2pp 20893 344 24% Fiche 50-237,83/10/5 Commonwealth Edison Co 8310250188 24x Fiche 50-237,03/10/21,
- --0310250195 Amends 76 & 67 to Licenses DPR-19 & DPR-25, respectively, changing Tech Specs re operability requirements for ECCS ring header snubbers, per 830613 application CRUTCHF[ELD.D. Operating Reactors Branch 5 83/10/21 [4pp 20893 346 24x Fiche 50-237, 03/10/21, 0310250100
- --8310250200 Bafety evaluation supporting Amends 76 & 67 to Litenses DPR-19 & DPR-25, respectively * Office of Nuclear Reactor Regulation, Director 20893 360 24X Fiche 50-237,83/10/21,8310250189
- 0310310052 Denies 830902 request for extension to submit formal response to Generic Ltr 83-28 re Balem ATMB event Info must be submitted by 831105 Participation in owners group for issues requiring long-range planning acceptable GRUTCHFIELD.D Operating Reactors Branch 5 83/10/R6 FARRAR.D L Commonwealth Edison Co. 3pp. 20951 046. 24X Fiche 50-237.83/10/26. Commonwealth Edison Co 8310310082
- G. Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN-E L. Division of Emergency Presaredness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fichs 50-000,83/09/26.8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes" Syc list enci JURDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000.83/09/26.8308300342
- 8308300345 IE Info Notice 83-83, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN, C Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of N York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26.83083003 24X Fiche 50-000, 83/09/26, 8308300345.
- 8306300349 IE Info Notice 83-64. "Lead Shielding Attached to Bafety-Related Sys W/o 10CFR80 59 Evaluation" Svc list enc.) JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York: Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8300300349
- 8310140262 Forwards 1E Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16 No noncompliance noted, PAPERIELLO, C. J. Region 3. Defice of Director 83/09/30 REED, C. Commonwealth Edison Co. 2pp. 20761 295 24X Fiche. 50-207. 83/09/30.
- --8310140267 IE Insp Repts 50-237/83-28 & 50-249/83-26 on 830913-16. No noncompliance noted Major areas inspected emergency preparedness exercise PLOSKI.T., QUOENSEN.W., SNCLL,W. Region 3, Office of Director. 83/09/30 10pp 20761 297 24X Fiche 50-237.03/09/30.8310140262.
- 8310200124 Forwards IE Mot Meeting Repts 50-010/83-18:50-237/83-27; 50-249/83-25:50-254/83-27:50-245/83-26:50-295/83-19; 50-249/83-26:50-254/83-26:50-237/83-39; 50-454/83-44; 30-455/83-33; 50-456/83-14 & 50-457/83-13 NORELIUS:C E Division of Project & Resident Programs REED.C. Commonwealth Edison CO 2pp 20834 098 24X Fichs 50-000:83/10/04:8310200124.
- --8310200148 IE Mgt Maeting Repts 50-020/83-18.50-237/83-27.50-249/83-25, 50-254/83-27.50-265/83-26, 50-295/83-19.50-304/83-20, 50-374/83-38.50-374/83-38.50-454/83-44.50-455/83-33, 50-456/83-14 & 50-457/83-13 NORELUB.C E Division of Project & Resident Programs, DAVIB.A. 3, Region 3, Diffice of Director 83/10/03 4pp 20834 100 24X Fiche 50-000.83/10/04.8310200124

- 83j0110140 Discusses concerns re licenser actions following failure of certain ECCS/containment isolation valves, per review of info in LER 93-006/017-0 & IE Insp Repts 50-237/83-07 & 50-249/83-06 License amend application requested CRUTCHFIELD, D. Operating Reactors Branch 5 93/10/05 FARRAR, D. L. Componwalth Edison Co. 5pp. 20666-293 24x Fiche 50-237.83/10/05.83/10/10/40
- 8310170337 Submits status of as-built reviews of safe shutdown piping supports for IE Bulletin 79~14 As result of review of Guad Cities, two paping sys found to have addl discrepancies Seven new hangers added RYBAK. B Commonwealth Edison Co 83/10/06 MEPPLER, J G Region 2 Price of Director 2pp 20/86 155 24X Fiche 50-000,83/10/06. 83/10/037
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Hestinghouse Plants " Svc list ench JORDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24% Fiche 50-000.83/10/07.8308300378
- 8308300752 JE info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list entl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 83010.3) 83/10/07 Consolidated Edison Co of Nev York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- B310210053 Forwards IE Insp Repts 50-010/83-17.50-237/83-26 & 50-247/83-24 on 830829-31.0701.02 & 08 & notice of violation PAPERIELLO, C J. Region 3. Office of Director B3/10/07 REED, C Commonwealth Edison Co. 2pp 20895
- --8310210061 Notice of violation from insp on 830827-31,0901.02 & GB PAPERICLLO, C J Region 3. Office of Director 83/10/07 2pp 20835 288 24X Fiche 50-010,63/10/07,6310210053
- --0310210074 IE Insp Rept: 50-010/83-17.50-237/83-26 & 50-249/83-24 on 830829-31.0901.02 & 08 Noncompliance noted inadequate calibr of 9-1 & D-2/3 chimbey monitors & failure to follow procedures re-radiation protection PAUL.R A : REFIER.L J : GREGER.L R Region 3. Office of Director 83/10/07 Spp 20855 290 24X Fichs 50-010.83/10/07.8310210050
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matt Defect Causes Production of Nozious Gases "Syr list encl JCRDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3710711 Consolidated Edison Co of New York Inc 117pp 21043 075 24X Fiche 50-000.B3710711,830B300759
 - 8300761 IE Info Notice 83-68, "Respirator User Harning Defective alf-Contained Breathing Apparatus Air Cylinders " Svc list no!
 - ncl DRDAN,E L Division of Emergency Preparadness & Engineering esponse (Post 830103) 83/10/11 Consolidated Edison Co. of New ork, Inc. 120pp 20827 129 24% Fiche 50-000,83/10/11,8308300761
 - 0140036 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-09, 50-237/83-14 & 50-249/83-13 NORELIUS:C Division of Project & Resident Programs 83/10/11 REED.C Commonwealth Edison Co 1p 20767 341 24X Fiche 50-010.83/10/11.8310140036
- --B310140049 Responds to NRC B30823 ltr re violations noted in IE Insp Repts 50-010/B3-09, 50-237/B3-14 & 50-249/B3-13 Corrective actions operations personnel closed & latched all battery charger cabinets FARRARI.D L Commonwealth Edison Co 83/09/22 KEPPLER.J G, Region 3, Opfice of Director 5pp 10767 342 24X Fiche 50-010, 83/10/11, 8310140034
- 310140079 Ac1 receipt of B30916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-12, 50-237/83-20 & 50-249/83-18
 NDRELIUS, C E Division of Project & Resident Programs 83/10/11
 REED. C Commonwealth Edison Co 1p 20766 099 24X
 Fiche 50-010,83/10/11,8310140099
- -8310140104 Responds to NRC 830721 ltr re violations noted in IE Insp Repts 50-010/83-12.50-237/83-20 & 50-249/83-18 Corrective actions scope & general method of training program completely detailed in training procedures FARRAR.B L Commonwealth Edison Co 83/09/16 KEPPLER.J Q Region 3. Office of Director 8pp 20764 100 24X Fiche 50-010,63/10/11,8310140099

- 8310180268 Clarifies NRC position reprocedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every 6 months AXELSON, H. Region 3. Office of Director 83/10/14 RECD, C Commonwealth Edison Co. 7pp. 20802-302 24X Fiche 50-010,03/10/488310180268
- R Periodic operating reports & related correspondence
- B310120273 Monthly operating repts for Sept 1983 W/8310D3 ltr SCHROEDEN.B A . SCOTT.D J Commonwealth Edison Co 63/10/03 Director's Office Office of Inspection and Enforcement 16p; 20693 081 24X Fiche 50-237,83/10/03.8310120273
- S Reportable occurrences, LERs & related correspondence
- 8310260076 Describes facility 821203 flood & corrective actions talm Chronology of events encl.including notification of event & procedure for briefing commissioner assistants
 PERKINS.K E NRC No Detailed Affiliation Given 83/06/08
 DEYGUNG.R C Director's Office of Inspection and Enforcement Tipp 20721 136 247 Fiche 50-010.83/06/23.
- 8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A.responsive to Items 1.2 & 4 NDE should be contacted for matl requested in Item 3 of ltr FELTON, J H Division of Rules and Records 83/06/14 HIATT, B I Ohio Citizens for Responsible Energy 3pp 20706 002 24% Fiche 50-000, 83/06/14, 8310110430
- --8310110478 Responds to 830413 ltr requesting info re use of foreign matts on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vender recommendations & maint practices
 FARRAR.B L Commonwealth Edison (o 83/04/22 KEPPLER.) @
 Region 3. Office of Director, 4pp 20706 063 24X
 Fiche 50-000.83/06/14,8310110430
- 8310260008 Addl response to FOIA request for 17 categories of relors Forwards documents listed in Apps B.C & D Info re fraudulent practices of Ray Miller. Inc evailable in PDR FELTON. J M Division of Rules and Records 83/06/23 CLEHETI. J Public Citizen Littgation Group 15pp 20920 001 24X Fiche 50-000, 83/06/23,8310260008
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EliGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.M J Forbora Corp 83/09/30 Director's Defice, Office of Inspection and Enforcement lipp 20651 064 24X Fiche, 50-000, 83/09/30, 8310070301
- 8310110140 Discusses concerns be licensee actions following failure of certain ECCS/containment isolation valves, per review of info in LER 83-006/01T-0 & IE Insp. Repts 50-237/83-07 & 50-247/83-05 License awand application requested CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/05 FARRAR, Dl. Commonwealth Edison Co. 5pp. 20666-293 24X Fiche 50-237, 83/10/6, 8310110140
- 8310120309 PNO-III-83-073 on B30930, facility shut down for schedulff refueling outage Licensee expected to conduct ultrasonic testing of large diameter stainless steel pipe in drywell. per NRC order Insp will continue for 16 wks
 TONGUE, T. WALMER, R. Region 3. Office of Director 83/10/05 1;
 20701 009 24X Fiche 50-249,83/10/05,8310120309
- 83102:0165 LER 83-035/017-0 on 83:004, during drywell insp.water observed leaking from recirculation pump bowl drain A Caused by 2-inch crack on tea Affected piping will be cut out Isolation valves & tee will be replaced M/83:013 ltr MERRITT.8. SCOTT.D J Commonwealth Edison Co 83/10/13 KEPPLER.J V Region 3, Office of Director 4pp 20856 090 PM Fiche 80-249, 83/10/13.83:102:10165
- 8310270477 LER 83-032/03L-0 on 830921, valve LPCI 1501-iiB closed during installation of terminal jumper Caused by technician inadvartently placing terminal jumper on 903-3 panel instead of 703-10 panel W/831019 ltr CHRISTEL. B. SCOTT, D. J. Commonwealth Edison Co. 83/10/18 KEPPLER, J. G. Region 3, Office of Director 3pp. 20922 013 241 Fichs 50-249, 83/10/18,8310270477

10270424 LER 83-034/03L-0 on 830723, during normal operation, mobile crane hit wet pipe sprinkler drain valve-breaking valve & spraying water on trackway (based by personnel error Valve repaired Personnel counseled W/831017 ltr
MERRITT, S. SCOTT, D. J. Commonwealth Edison Co. 83/10/19
MERRITT, S. 9 (2010) 3, 049100 de Director 3pp. 20723 108 24X
Fiche 50-249, 83/10/17, 8310270424

THET 50-250 TURKEY POINT PLANT, UNIT 3

Security, medical, emergency & fire protection plans

0040145 Forwards supplemental info re 10CFRBO, App R re fire rotaction, per 83040B submittal lhermal fixed temp & rate of ise fire detection will be provided in auxiliary feedwater ontrol valve (fire Zones 113 & 116) areas HRFIGR E Florida Power & Light Co 83/09/30 VARGA, S A lperating Reactors Branch 1 2pp 2060B 024 24X iche 50-250,83/09/30 8310040145

0170240 Forwards "Alternate Shutdown Capability Rept 10CFR50, App R. action III L for Turkey Point Units 3 & 4 " Site visit 11] be arranged for NRC reviewers upon request HRIGR E Florida Fower & Light Co 83/10/07 EIBENHUT.D 0 ivision of Licensing 2pp 20790 309 24% Fiche 50-250,83/10/07, 310170240

310170244 "Alternate Shutdown Capability Rept 10CFR50, App R. Section III L for Turkey Point Units 3 & 4 " W/20 oversize figures Aperture cards are available in PDR * Bechtel Corp B3/10/07 59pp P0790 311 24X Fiche 50-250.83/10/07.8310170240

)270365 forwards corrected Page 3 of IE Bafequards Insp Repts)-250/83-28 & 50-251/83-28 re protected area intrusion *tection sys Encl withheld (ref 10CFR73 P1) *MCE,H C Division of Project & Resident Programs 83/10/18 *RIG,R E Florida Power & Light Co 1p 20924 007 24X *Che 50-250,83/10/18.8310270365

djudicatory correspondence

130164 Forwards status rept on hybrid hearing procedures under ction 134 of Nuclear Waste Policy Act Proposed rule on plementation of procedures awaits Commussion action NNINGHAM. O H Office of the Executive Legal Director 83/10/07 HM. T A Office of the Executive Director for Operations 2pp 724 291 24X Fiche 50-000,83/10/07.8310130164

eneral correspondence

LBOR7B Responds to B30726 request to be added to svc list resposed spent fuel pool expansion & criteria for svc list quest to be added to svc list denied Notification resiminary NSHC will be provided NONALD.D O Operating Reactors Branch 1 83/10/12 LORION.J iter for Nuclear Responsibility 1p 20826 357 24X he 50-250.83/10/12.8310180298

erating license stage documents & correspondence

10530 "Assessment of Radiation Risks," util-medical dialogue sented at 800922-23 Intl Inst of Safety & Health um in Washington-DC P,R E International Institute of Bafety & Health p 20714 141 24X Fiche 50-000,80/09/23,8310(10530

10017 FDIA request for documents re integrated leak rate tests for ted fac(lities to be placed in PDR NER.L. Affiliation Unknown: 63/05/02 NRC - No Detailed iliation Given lp 21004 270 24X Fiche: 50-000.83/05/02.

LOGGI Responds to FOIA request for documents re integrated leak tests for facilities to be placed in PDR forwards ments to be place in PDR & list of facilities for which is are unavailable CNN J M Division of Rules and Records 83/07/06 CDNNER, L listing Unknown. 1p 21004.271 24X Fiche 50-000.83/07/06, 8310031

G10067 "Reactor Containment Blds Integrated Leak Rate Test."
mmary technical rept
MAN.W D Ebasco Services, Inc (subs of Enserch Corp.)
/02/14 Sopp 21006.065 24X Fichs 50-000.83/07/06.8310310031

31006B Operating Procedure 13100 1, "Integrated Leak Rate Yest " MAN.W D Ebasco Services, Inc (subs of Enserch Corp) /11/01 200pp 21006 159 24X Fiche 30-000,83/07/06, 10310031

--8310310070 "Containment Leak Rate Tests," Type B & C test repts
* Florida Power & Light Co 76/02/14 9pp 21006 325 24X
Fiche 50-000.63/07/06.8310310031

8310030659 Requests site visit to continue review of 821027 & 830307 requests for rev to inservice test program for pumps & valves Encl questions & comments will serve as agenda VAROA,S A Operating Reactors Branch 1 83/09/20 UHRIO,R E Florida Power & Light Co 9pp 20626 342 24X Fiche 50-250,83/09/20,8310030659

8310110274 Forwards response to NRC concerns discussed in 830815 telcon re Tech Spec changes to F delta H limit Impact of change limited to expected cycle-wide power distribution differences
UNRIGOR E Florida Fower & Light Ca B3/10/04 EIBENHUT.D 0.
Division of Licensing 5pp 20666 0/5 24x Fiche 50-250,83/10/04.
8310110296

8310130125 Forwards Class II & III amend fecs for 830818 request to amend Licenses DPR-31 & DPR-41 re F delta H/FG UHRIGA E forida Power & Light Co 83/10/06 E18ENHUT D & Division of Licensing 1p 20725 052 24X Fiche 50-250,83/10/06.

8310180324 Forwards revised Toch Spec page re RHR pump operability per 831013 telcon request for add1 info concerning proposed license amend HLCLIAMB, J W Florida Power & Light Co 83/10/13 EIBENHUT, D Q Division of Licensing 3pp 20806 199 24X Fiche 50-280, 83/10/13, 8310180324

--8310180327 Proposed Tech Spec re RHR pump operability * Florida Power & Light Co 83/10/13 ip 20806 161 24X Fiche 50-250,83/10/13,8310180324

8310240258 Forwards order for mod of Licenses DPR-31 & DPR-41.requiring Tach Spec 3 4 16 be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired
VARGALS A Operating Reactors Branch | 83/10/14 UHRIG,R E
Florida Power & Light Co 2pp 20908 003 24X
Fiche 50-250.83/10/14,8310240258

--8310240261 Order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3 4 lb be modified on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired PURPLER A Division of Licensing B3/10/14 Florida Power & Light Co Spp 20908 005 24X Ficha, 50-250,83/10/14,8310240258

--B310240264 Safety evaluation supporting interim Tech Spec mod to permit operation in hot shutdown mode while inoperable RHR pump repaired # Office of Nuclear Reactor Regulation, Director # B3/10/14 | 3pp. 20908 008 | 24X Fiche 50-230,83/10/14,8310240258

8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic testing of mechanical snubbers MCDONALD.D.O. Operating Reactors Branch 1 83/10/14, UHRIG.R.E Florids Power & Light Co 2pp 20939 076 24X Fiche 50-250.83/10/14,8310270129

--B310270153 Amends 96 & 90 to Licensee DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function VAR9A:8 A Dperating Reactors Branch 1 83/10/14 25pp 20939 078 24X Fiche 50-250,83/10/14,8310270129

-83(027016) Bafety evaluation supporting Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation, Director 83/10/14 Spp. 20939 103 24x Fiche 30-250:83/10/14:8310270129.

8310210075 Requests remittance of fee due for 830505 application to delete terrestrial & other monitoring programs from Tech Specs within 15 days.

MILLER, W D License Fee Management Branch 83/10/17 UHRIQ, R. E. Florida Power & Light Co Ip 20883 343 24% Fiche 50-250.
83/10/17.8310210075

Q Inspection reports: IE Bulletins & correspondence

8310040305 Forwards IF Inep Repts 50-250/B3-29 & 50-251/B3-29 on B30804-05 No noncompliance noted DANCE,H C Division of Project & Resident Programs B3/08/30, URRIG,R E Floisia Power & Light Co 2pp. 20612 353 24X Fiche 50-250.83/08/30.8310040305

- ~-8310040316 IE Insp Repts 50-250/83-27 & 50-251/83-27 on 830804-05 No nancompliance noted Major areas inspected welder concerns re unsatisfactory/unsafe welds
 KLEINSORGE, W.P. Region 2. Office of Director BLAKE. J. J. Division of Engineering & Operational Programs 63/09/23 5pp 20612 355 24% Fiche 50-250.03/08/30.8310040305
- 8310040504 Forwards IE Insp Repts 50-250/83-30 & 50-251/83-30 on 830823-26 No noncomplaince noted DANCE.H C Division of Project & Resident Programs 83/09/09 UHRIO.R F Florida Power & Light Co 2pp 20622 353 24X Fiche \$0-250,83/09/09.8310040504
- ~~8310040517 IE lnsp Repts 50-250/83-30 & 50-251/83-30 on 830823-96 No noncompliance noted Major areas inspected GC of analytical measurements, mgt & administrative controls, status review of environ monitoring stations & state/NRC split samples CUNNINGHAM.A L Region 2. Office of Director MONTOOMERY, D M Bivision of Engineering & Operational Programs 83/09/07 Spp 20622 355 24% Fiche 50-250.83/09/09.8310040504
- 8310040405 Confirms telcom re 831021 mgt meeting in MiamirFL to discuss results of first phase of SALP review for period Jul 1782 June 1783 Proposed agenda encl LEWIS.R C Division of Project & Resident Programs 83/09/22 UHRIG.R E Florida Power & Light Ca 2pp 20619 092 24% Fiche: 50-000, 83/09/22, 8310040405
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Yests," Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 1179p 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
 - 18300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas stactors Positioned at Control Room Ventilation Air takes" Syc list encl RDAN.E.L Division of Emergency Preparedness & Engineering sponse (Post 830103) 83/09/26 Consolidated Edison Co of New rk. Inc 116pp 20777 210 24X Fithe 50-000.83/09/26.8308300342
 - 8300345 IE Info Notice 83-63, "Potential Failures of Westinghouse upe SA-1 Differential Relays " Svc list encl
 'URDAN,E L Division of Emergency Preparedness & Engineering esponse (Post 830103) 93/69/26 Consolidated Edison Co of New ork, Inc 118pp. 20778 001 24x Fiche 50-000, 83/09/26, 8308300345
 - 0050078 Ack receipt of 830907 ltr & payment of civil penalty proposed by NRC on 830815 Corrective actions will be examined during future inspective actions will be examined during future inspective actions will be examined for a fibrida examined to the second state of the second se
 - 9300349 lE Info Notice B3-64, "Lead Shielding Attached to afety-Related Sys W/o 10CFR50 59 Evaluation " Syc list not not B300347 not B30103). B3/09/29 Consolidated Edison Co of New ork, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300347
 - Off013B Requests approval to use 1980 Edition & Addenda through inter 1981 Addenda of ABME Section XI Code, per 10CFR50 55a g)(4)(iv), to extend inservice insp interval due to lengthy team generator repair outages HRIO, R E Florida Power & Light Co 83/10/03 EISCNHUT, D Q ivision of Licensing O'REILLY, J P. Region 2, Diffice of Director pp 20665-001. 24% Fiche 50-250, 83/10/03, 8310110138
 - 8300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass cops Used in Westinghouse Flants " Svc list encl. URBAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24% Fiche. 50-000, 83/10/07, 8308300378
- .08300732 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Syc list and Jonathy." Syc list and Jonathy." Syc list and Jonathy. The Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07. Consolidated Edison Co. of New York, Inc. 79pp. 20882 026 24% Fiche 50-000,83/10/07,8108300752
- B310180381 Supple 630720 response to Qeneric Ltr B1~07. "Control of Heavy Loads." in response to NRC finding in IE Inap Rept 83-11. dtd 830620. Info documents util methodology for compliance w/NOREO-0612 t ANSI N 14 6 UHRIO.R E Florida Power & Light Co 83/10/07 EISENHUT, D 0 Division of Licensing. 2pp 20803 201 24X Fiche. 50-250. 83/10/07. 8310180381

- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Notions Gases "Svc list encl URDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/13,8308J00/27
- 8308300761 IE Info Notice 83~68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308/100751
- 8310250426 Ack receipt of 830720 & 0922 ltrs informing NRC of steps taken to correct violations noted in If Insp Repts 50-250/83-19 & 50-251/83-19 LEWIS.R C Division of Project & Resident Programs 83/10/11 UHRIG.R E Florida Power & Light Co 1p 20897 006 24% Fiche 50-250,83/10/11,8310250426
- ---B310250431 Updates 630720 response to NRC 830620 ltr re violations noted in IE Insp Repts 50-250/83-19 & 30-251/83-19 Corrective actions Quality Procedure 16 1 revised to address requirements for audit responses in GP 18 1 UHRIG.R E Florida Power & Light Co 83/07/22 U'RCILLY, J & Region 2, Office of Director 1p 2087/007 24X Fiche 50-250.83/10/11.8310250426
- --8310250437 Responds to NRC 830620 ltr re violations noted in li Insp. Repts 50-250/83-19 & 50-251/83-19 Corrective actions QC personnel responsible for preparing audits instructed to list dates & responsible personnel for all commitments UHRIG.R E Florida Power & Light Co 83/07/20 O'RCILLY, J P. Region 2. Uffice of Director 3pp 20897 008 24X Fiche 50-250,83/10/11,8310250426
- --8310250442 Forwards IE Insp Repts 50-250/83-19 & 50-251/83-19 on 830516-20 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/06/20 UHRIG.R C Florida Power & Light Co 2pp 20897 011 PAX Fiche 50-250,83/10/11.8310250426
- --8310250446 Notice of violation from insp on 830516-20 * Region 2, Office of Director 83/06/20 ip 20697 013 24 Fiche 50-250,83/10/11,8310250426
- --8310250449 IE Insp Repts 50-250/83-19 & 50-251/83-19 on \$30916.50 Noncompliance noted audit responses did not include commitment date for actions not completed.

 DEDBAGE, A G Region 2, Office of Director UPRIGHI.C M Division of Engineering & Operational Programs 83/06/15 7pp 20397 Olt 24X Fiche 50-250,83/10/11,8310250426
- B310270127 Forwards Amends 96 & 90 to Licenses DPR-31 % UPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic testing of mechanical snubbers MCDDNALD, D @ Operating Reactors Branch 1 83/10/14 URRIG. H & Florida Power & Light Co 2pp 20737 076 24X Fiche 50-250, 83/10/14, 8310270127
- --8310270153 Amends 96 & 90 to Licensee DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function VARGA: B A Operating Reactors Branch 1 83/10/14 20pp 20939 078 24% Fiche 50-250,83/10/14,8310270129
- 83102/0365 Forwards corrected Page 3 of IE Bafeguards Insp Repts 50-250/83-28 & 50-251/83-28 re protected area intrusion detection sys Encl withheld (ref 100fR/3 21)
 DANCE.H C Division of Project & Resident Programs 83/10/10 UHR10.R E Florida Power & Light Co 1p 20924,007 24X
 Fiche 50-250.83/10/18.8310270365
- 8310270249 Corrects 831003 Ltr L-83-505 requesting updated endorsed code requirements for sys hydro (& temp) pressure tests & extended insp intervals Insp program based on 1974 edition of Section XI of ASMC Code WILLIAMS, J W. Floride Power & Light Co. 83/10/21 6167NMULD © Division of Licensing 2pp 20923 235 24X Fiche 50-250,83/10/28310270249
- R Periodic operating reports & related correspondence
- B310190023 Monthly operating repts for Aug 1983 W/830915 itr GRANT.N W. WILLIAMS.J W. Florida Power & Light Co. 93/09/15 Office of Resource Manegement, Director 17pp 20822 0i7, 24K Fiche B0-000,83/09/15.8310190023

- S Reportable occurrences, LERs & related correspondence
- 8310050071 Comments on AO rept to Congress for Second Guarter CYB3 containing AO 83-4, "Unavailability of Auxiliary Feedwater Sys (Turkey Point Unit 3) " Marked-up update of AO 75-5 enc!

 DENTON.H K Office of Nuclear Reactor Ragulation, Director Consoling Marked-up (1984) 187-888

BENTON. H & Office of Nuclear Reactor Regulation, Director 83/09/27 HELTEMES, C J Director's Office 8pp 20650 157 24X Fiche 30-230, 83/09/27, 8310090071

8310180357 RD several fire barrier penetrations breached for longer than 7 days, due to implementation of approved design changes, including new computer room, auxiliary power upgrade & App R Hourly fire watch established HILLIANS. J W Florida Power & Light Co 89/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20803 043 24X Fiche 50-250,83/10/13.8310180359

DOCKET SO-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- 8310170240 Forwards "Alternate Shutdown Capability Rept 10CFR50, App R. Section III L for Turkey Point Units 3 & 4 " Site visit will be arranged for NRC reviewers upon request UHR19, R E Florida Power & Light Co 83/10/07 E1SENHUT, D Q Division of Licensing 2pp 20790 309 24X Fiche 50-250,83/10/07, B310170240
- --8310170244 "Alternate Shutdown Capability Rept 10CFR30, App R. Section III L. for Turkey Point Units 3 & 4 " W/20 oversize figures Aperture cards are available in PDR 4 Bechtel Corp 83/10/07 59pp 20790 311 24X Fiche 50-250,83/10/07,83101/0240
- 8310270365 Forwards corrected Page 3 of IE Safeguards Insp Repts 50-250/83-28 & 50-251/83-28 re protected area intrusion detection sys Encl withheld (ref 100FR/7, 21)
 DANCE,H C Division of Project & Rasident Programs 83/10/18
 UHRIG,R E Florida Pawer & Light Co 1p 20924 007 24X
 Fiche 50-250,83/10/18,8310270365
- G Adjudicatory correspondence
- 8310130164 Forwards status rept on hybrid hearing procedures under Section 134 of Nuclear Waste Policy Act Proposed rule on implementation of procedures awaits Commission action CUNNINGHAM, 9 H Office of the Executive Legal Director 83/10/07 REHM.T. A Office of the Executive Director for Operations 2pp 20724 291 24X Fiche 50-000,83/10/07.8310130164
- H General correspondence
- 8310:80298 Responds to 830926 request to be added to svc list re proposed spent fuel pool expansion & criteria for svc list Request to be added to svc list denied Notification re preliminary NSHC will be provided MCDONALD.D O Operating Reactors Branch 1 83/10/12 LORIGN, J Center for Nuclear Responsibility 1p 20826 357 24X Fiche 50-250.83/10/12.8310180298
- P Operating license stage documents & correspondence
- 8310110530 "Assessment of Radiation Risks," util-medical dialogue presented at 800922-23 Intl Inst of Safaty & Health forum in Washington.DC LAPP.R E International Institute of Safety & Health 80/09/23 52pp 20714 161 24X Fiche 50-000,80/09/23,8310110530
- 8310310017 FOIA request for documents re integrated leak rate tests for listed focilities to be placed in PDR CONNER. L Affiliation Unknown 83/05/02 NRC No Datailed Affiliation Given 1p 21004 270 24X Fache 50-000,83/05/02,8310310017
- 8310030657 Requests site visit to continue review of 821027 & 830307 requests for rev to inservice test program for pumps & valves Encl questions & comments will serve as agenda VARGA. S A Operating Reactors Branch 1 83/09/20 UHRIG.R F Florida Power & Light Co 9pp 20676 34P 24X Fiche 50-250,83/09/20,8310030659

- 8310110296 Forwards response to NRC concerns discussed in B30815 telcon re Tech Spec changes to F delta R limit Impact of change limited to expected cycle-wide power distribution differences
 UHRIGAR E Florida Power & Light Co 83/10/04 EISENHUT. D 0
 Division of Licensing 5pp 20666 0/5 24X Fiche 50-250.83/10/04.
 8310110296
- 8310130125 Forwards Class II & III amond fees for 830818 request to amend Licenses DPR-31 & DPR-41 re F delta H/FQ UHRIG.R E Florida Power & Light Co 83/10/06 EISENHUT, D Q Division of Licensing 1p 20725 052 24X Fiche 50-250, 83/10/06, 8310130125
- 8310180324 Forwards revised Tech Spec page or RHR pump operability per B31013 telcon request for addl info concerning proposed license amend MILLIAMS. J W Florida Power & Light Co 83/10/13 EISENHUT. D Q Division of Licensing 3pp 20806 159 24X Fiche 50-250, 83/10/13. 8310180324
- --8310180327 Proposed Tech Spec re RHR pump operability * Florida Power & Light Co 83/10/13 ip 20806 161 24X Fiche 50-250,83/10/13,8310180324
- 8310240258 Forwards order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3 4 1b be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired VARGA: S A Operating Reactors Branch 1 83/10/14 UHRIG:R E Florida Powor & Light Co 2pp 20908 009 24X Fiche 50-250,83/10/14.8310240258
- --8310240261 Order for mod of Licenses DPR-31 & DPR-41, requiring Tech Spec 3 4 lb be modified, on interim basis, to permit operation in hot shutdown mode while inoperable RHR pump repaired PURPLE, R A Division of Licensing 83/10/14 Florida Power & Light Co 3pp 20708 005 24X Fiche 50-250,83/10/14,8310240258
- ---8310240264 Safety evaluation supporting interim Tech Spec mod to permit operation in hot shutdown mode while inoperable RHR pump repaired

 * Defice of Nuclear Reactor Regulation, Director 83/10/14 3pp 20708 008 24% Fiche 50-250-83/10/14.8310240258
- 20708 008 24% Fiche 50-250.83/10/14.8310R40R58
- 8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends add requirements for visual insps & periodic lesting of mechanical snubbers MCDDNALD, D 0 Operating Reactors Branch i 83/10/14 UHRIG, R E Florida Power & Light Co 2pp 20939 076 24% Fiche 50-250,83/10/14,8310270129
- --8310270153 Amends 96 & 90 to Licensee DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function VARQA:8 A Operating Reactors Branch i 83/10/14 25pp 20939 078 24X Fiche 50-250,83/10/14,8310270129
- --8310270161 Safety evaluation supporting Amends 76 & 70 to Licenses DPR-31 & DPR-41 respectively * Office of Nuclear Reactor Regulation, Director 63/10/14 5pp 20737 103 24X Fiche 50-250,63/10/14.6310270127
- 8310210075 Requests remittance of fee due for 830505 application to delete terrestrial & other monitoring programs from Tech Specs within 15 days MILLER.W O License Fes Management Bronch 83/10/17 UHRIQ.R E. Florida Power & Light Co ip 20883 343 24X Fiche 50-250. 83/10/17.8310210075
- Q Inspection reports. IE Bulletins & correspondence
- 8310040305 Forwards IE Insp Repts 50-250/83-29 & 50-251/83-29 on 830804-05 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/08/30 UHRIO, R E Florida Power & Light Co 2pp 20612, 353 24X Fiche 50-250, 63/08/30, 8310040305
- ~-83100403id IE Insp Repts 50~250/B3-27 t 50~251/B3-27 on 830804-05 No noncompilance noted Major areas inspected welder concerns re unsatisfactory/unsafe welds
 KLEINSORGE,W P Region 2, Office of Director BLAKE, J J.
 Division of Engineering & Operational Programs 83/08/23 5pp 20612 355 24X Fiche 50~250,83/08/30,8310040305
- B310040504 Forwards IE Insp Repts 50-250/83-30 & 50-251/83-30 on B30823-26 No noncomplaince noted DANCE.H C Division of Project & Resident Programs 83/09/09. UHRIG.R E Florida Power & Light Co 2pp 20622 353 24X Fiche 50-250.83/09/09.8310040504

- --8310040517 IE Insp Repts 50-250/83-30 & 50-251/83-30 on 830823-26 No noncompliance noted Major areas inspected GC of enalytical measurements, mat & administrative control Sc status review of environ monitoring stations & state/NRC split samples CCMNINGMAM, A. Region 2. Office of Director MONTCOMERY, D M Division of Engineering & Operational Programs 83/09/07 5pp 20622 355 24X Fiche 50-250,83/09/09.8310040504
- 8310040405 Confirms telcon re 831021 mgt meeting in Mi/H.FL to discuss results of first phase of SALP review for period Jul 1982 June 1983 Proposed agenda enci LEMIS.R C Division of Project & Resident Programs 83/09/22 UMRIO.R E Florida Power & Light Co 2pp 20619 092 24X Fiche 50-000.83/09/22.8310040405
- 8308300340 IE Info Notice 83-61. "Allpged Use of Stand-Ins for Welder Gualification Tests" Syr list entl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830[03] 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fishe 30-700, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes "Syc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Editon Co of New York, Inc 116pp 20777 210 24% Fithe 50-000.83/09/26,0308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc (18pp 20778 001 24x Fiche 50-000, 83/09/26, 8308300349
- 8310050078 Ack receipt of 830907 ltr & payment of civil penalty proposed by NRC on 830915 Corrective actions will be examined during future inap AKELRAD. J A Enforcement Staff 83/09/26 ADGMAT. E A Florada Power & Light Co 2pp 20650 187 24X Fiche 50-250.83/09/26, 8310050078
- 308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enci JDROAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fichs 50-000,83/09/29,8308300349
- HOLIOI3B Requests approval to use 1980 Edition & Addenda through Minter 1981 Addenda of ASME Section XI Code, per 10CFR50 55a (g)(4)(iv), to extend inservice insplinterval due to lengthy steam generator repair outages UHRIO, R E Florida Power & Light Co B3/10/03 EISENHUT, D © Division of Licensing OffELLLY, J P Region 2. Dffice of Director 2pp 20465 001 24X Fiche 50-250,83/10/03,8310110138
- W830037B IE Info Notice 83-65, "Survei)lance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York. Inc 76pp 20527 213 24X Fiche 50-000, 83/10/07,8308300378
- lOR300752 IE Info Notice 93-66, "Fatality at Argentine Critical Facility" Byo list entl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07, Consolidated Edison Co. of New York, Inc. 79pp. 20882-024-24X Fichs 50-000, 83/10/07, 8308300752
- Dioi80381 Supple S00720 response to Generic Ltr 81-07. "Control of Heavy Loads." In response to NRC finding in IE Insp Rept 83-11, 4td 800680 Info documents util methodology for compilance w/NUREO-0612 & ANSI N 14 6 UHRIG.R E Florida Power & Light Co 83/10/07 EISENHUT. D 0 Bivision of Licensing 2pp 20803, 201 24% Fiche 50-250, 83/10/07, 8310180381
- G08300759 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Noticus Gases " Syc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 078 24X Fiche 50-000,83/10/11.8308300759
- 8308300761 IE Info Notice 83-69, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Bvc list encl JBRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11.8308300761

- 8310250426 Ack receipt of 830720 & 0922 ltrs informing NRC of slipt taken to correct violations noted in If lusp Repts 50-250/83-19 & 50-251/83-19 LEWIS:R C Division of Project & Resident Programs U3/10/11 URRIG:R E Florida Power & Light Co Ip 20897 006 24% Fiche 50-250.83/10/11.8310250426
- --8310250431 Updates 630720 response to NRC 630620 lt; re violations noted in IE Insp Repts 50-250/63-19 & 50-251/63-19 Corrective actions Quality Procedure 16 I revised to address requirements for audit responses in 0P 18 I UHRIG.R C Florida Power & Light Co 63/09/22 D'ACILLY, J P Region 2. Office of Director 19 20897 007 24X Fiche 50-250 83/10/11.8310250426
- --8310250437 Responds to NRC 830620 ltr re violations nated in If Insp Repts 50-250/83-19 & 50-251/83-19 Corrective actions GC personnel responsible for preparing audits instructed to list dates & responsible personnel for all commitments UMRIO, R E Fighta Power & Light Co 83/07/20 O'REILLY, JP Region 2. Office of Director 3pp 20897 008 P4X Fiche 50-250.83/10/11.8310250426
- --8310250442 Forwards IE Insp Repts 50-250/83-19 & 50-251/83-19 on 830514-20 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/06/20 UMRIC.R C Flotida Power & Light Co 2pp 20897 011 24x Fiche 50-250,83/10/11.8310250426
- --8310250446 Notice of violation from insp on 630516-20

 * Region 2. Office of Director 83/06/20 ip 20897 013 :41
 Fiche 50-250.83/10/11.8310250426
- --8310250449 IE Insp Repts 50-250/83-19 & 50-251/83-19 on 0/80516 to Noncompliance noted audit responses did not include commitment date for actions not completed DEUBAGE.A G Region 2. Office of Director UPRIGHT.C M Division of Engineering & Operational Programs 83/06/15 9pp (2007) (3) 4 24% Fiche 50-250, 83/10/11, 0310230426
- 8310270129 Forwards Amends 96 & 90 to Licenses DPR-31 & DPR-41.
 respectively & safety evaluation Amends add requirements
 for visual insps & periodic testing of mechanical snubbers
 MCDONALD,D & Operating Reactors Branch 1 83/10/14 UMR(0.0 F
 Florida Power & Light Co 2pp 20739 076 24X
 Fiche 50-250.83/10/14,8310270129
- --8310270153 Amends 96 & 90 to Licenses DPR-31 & DPR-41, respectively, adding requirements for visual insps & periodic testing of mechanical snubbers to ensure operability & capability to perform safety-related function VARCA, B & Dperating Reactors Branch 1 83/10/14 25pp 20939 078 24x Ficha 50-250,83/10/14,8310270129
- 8310270345 Forwards corrected Page 3 of 1E Safeguards Ensp Repts 50-250/03-28 & 50-251/63-28 re protected area intrusion detection system; withheld (ref 10CR/J 21)
 DANCE H C Division of Project & Resident Programs B3/10/18
 UHRIG R E Florida Power & Light Co 1p 20924 007 24X
 Fiche 50-250.83/10/18.8310270245
- 8310270249 Corrects 831003 Ltr L-83-505 requesting updated endorand code requirements for sys hydro (& temp) pressure tests & extended insp intervals insp program based on 1974 edution of Section XI of ASME Code WILLIAMS, J W. Florida Power & Light Co. 83/10/21 FIBENNUF, D. O. Division of Licensing 2pp 20923 235 24X Fiche 50-250,83/10/21. B310270249
- R Periodic operating reports & related correspondence
- 8310190023 Monthly operating repts for Aug 1983 W/830915 ltr GRANT.N.W. , MILLIAMS.J W Florida Power & Light Co 63/09/15 Office of Resource Menagement, Director 17pp 20882 017 24X Fiche 50-000,83/09/15,8310190023
- S Reportable occurrences. LERs & related correspondence
- 8310270340 FDIA request for placement of listed LERs in PDR 9RABER, L D NOB Corp 83/09/08 Division of Rules and Records 2pp 20938 058 24X Fiche 50-000,83/09/08,83102/0340
- 8310030262 LER 83-013/03L-0 on 830825, while performing safeguards lead emergency load sequencer 4A failed Caused by normal and of life for open-tircuited timer 4A Agastat relay replaced to sequencer tested & returned to svc W/830926 ltr sequencer tested & returned to svc W/830926 ltr SILLY, J.P. ARIAS. J. Florida Power & Light Co. 03/09/26 O'REILLY, J.P. Region 2, Office of Director 2pp P0591 036 Ray Fiche 50-251,83/09/26,8310030262

- 8310060171 Forwards, for review & comment, "Low Tomp Overpressure Events at Turkey Point Unit 4." draft case study rept HELTEMES, C.J. Director's Office 83/09/26 DENIUN, H.R. Office of Nuclear Reactor Regulation, Director DEYOUNG, R.C. Director's Office, Defice of Inspection and Enforcement MINDOUE, R.B. Office of Nuclear Regulatory Research, Director 2pp 20661-020 24X Fiche 50-251.83/09/26.8310060171
- --83100601/5 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4." draft case study rept HELTEMFS,C J Director's Office 83/09/26 Wil KINSON,E P institute of Nuclear Power Operations 2pp 20661 022 24y Fiche 30-251,83/09/26,8310060171
- --8310060179 Forwards, for review & comment. "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept HELTEMES, C. J. Director's Office 83/09/26 ROSSIN, D. Nuclear Safety Analysis (enter 2pp. 2066) 024 24X Fiche 50-251,83/09/26,8310060171
- --8310060185 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept
 HELTEMES, C.J. Director's Office 83/09/26 UHRIG, R.E. Florida
 Power & Light Co. 2pp 20661 026 24X Fiche 50-251, 83/09/26,
 8310060171
- ---8310060190 Forwards, for review & comment, "Low Temp Overpressure Events at Turkey Point Unit 4," draft case study rept HELTEMES, C J Director's Office 83/09/26 RAME, F P Westinghouse Flectric Corp 20661 028 24X Fiche 30-251,83/09/26,83100601/1
- --8310060194 Forwards, for review & comment, "Low Temp Dverpressure Events at Turkey Point Unit 4," draft case study rept HELTEMES, C.J. Director's Office 83/09/26 MARSHALL.J. Arkansas Power & Light Co. 2pp. 20661-030 24X Fiche 50-251, 83/09/26, 8310060171
- --8310060199 "Low Temp Overpressure Events at Turkey Point Unit 4." draft case study rept LANNING.W D Director's Office 83/08/31 56pp 20661 032 24X Fiche 50-251.63/09/26.8310060171
- B310270347 Responds to FOIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also availabel in PDR One LER canceled Eight LERs not rereived FELTON, J M Division of Rules and Record & B3/09/29 GRABER, L D NUS Corp 19 20938 060 24X Fichs 50-000, 83/09/29, 8310270347
- --B310270354 LER B3-002/01T-O on B30405, spent fuel assembly X-13 dropped back into rack from fully lifted position Caused by cable stress due to limit switch fallure Insp for cladding damage will be conducted W/830417 ltr
 BARRY, Z E., WILLIAMS, J W. Florida Power & Light Co. B3/04/19
 O'REILLY, J P. Region 2, Office of Director. 4pp. 20938-061-24X
 Fiche 50-000,83/09/29,8310270347
- B310180357 RO several fire barrier panetrations breached for longer than 7 days due to implementation of approved design changes including new computer room, auxiliary power upgrade & App R Hourly fire watch established WILLIAMS, JW Floride Power & Light Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 20803 043 24X Fiche 50-250.83/10/13.8310180359
- 8310210223 LER 83-015/03L-0 on 830913, local leak rate test on containment personnel hatch airlock revealed leakage in excess of Tech Specs Caused by equalizing vent valve on inner door not fully closed Valve tightened W/831013 ltr BERRY, Z E , WILLIAMS, J W Florida Power & Light Co B3/10/13 O'REILLY, J P Region 2, Dffice of Director 2pp 20852 0/4 24X Fiche 50-251,83/10/13,8310210223
- 8310270277 LER 83-016/017-0 on 831004.manual discharge valves on containment spray pumps 4A & 4B discovered locked in closed position Caused by personnel error Valve for pump 4B opened W/83101B ltr
 ARIAS, J. WILLIAMS, J.W. Florida Power & Light Co. 83/10/18
 0'RELLY, J.P. Region 2. Office of Director. 3pp. 20723 286 ;
 Fiche 50-251.83/10/18.8310270277
- DOCKET 50 254 GUAD CITIES STATION, UNII 1
- F Security, medical, emergency & fire protection plans
- 8310140261 Forwards IE Insp Repts 50-254/83-24 & 50-265/83-25 on 830822-26 & 31 & 0909 & notice of violation HIMD, J A Division of Radiological & Materials Safety Programs 83/09/29 REDLC Commonwealth Edison Co Epp 20762 048 24X Fiche 50-254,83/09/29,8310140761

- --8310140264 Notice of violation from insp on 830822-26 % 31 % 0909 HIND.J A Division of Radiological & Materials Safety Programs 83/09/28 2pp 20762 050 24X Fiche 50-254,83/09/29,8310140261
- --B310140271 IE Insp Repts 50-254/83-26 & 50-265/83-25 on B30822-26 & 31 & 0909 Noncompliance noted failure to distribute controlled emergency plan procedure revs to NRC PHILLIPS,M P. PLOSKI,T J., PAPERIELLO.C J. Region 3. Office of Director B3/09/29 i7pp 20762 052 24X Fiche 50-254,83/09/29,8310140261
- 8310060541 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20662 001 24X Fiche 50-254,83/09/30, 8310060541
- --8310060545 Public version of revised emergency plan implementing procedures including Procedures GEP 550-0 re emergency equipment & supplies & GEP 550-14 re emergency operations facility supplies & Commonwealth Edison Co 83/09/08 300pp 20662 002 24X Fiche 50-254.83/09/30.8310060541
- 8310110325 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/05 Document Management Branch lp 20685 231 24% Fiche 50-254.83/10/05.8310110325
- --8310110327 Public version of revised Emergency Plan Implementing Procedures GEP 110-2 re acting station director (shift director) & Procedure GEP 310-1 re initial notification TIET. G Commonwealth Edison Co 83/09/08 24pp 20685 232 24X Fiche 50-254.83/10/05.8310110325
- 8310200079 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/14 Document Management Branch 1p 20844 218 24% Fiche 50-254,83/10/14, 8310200079
- --8310200082 Public version of Rev 2 to Emergency Plan Implementing Procedure GEP 450-1, "Environ Surveillance Stations" KOVACK, T J CARSDN.R Commonwealth Edison Co 83/09/28 6pp 20844 219 24X Fiche 50-254.83/10/14.8310200079
- B3i0270024 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records B3/10/21 Document Management Branch 1p 20940 199 24X Fiche 50-254.83/10/21, B310270024
- --8310270028 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 550-1 refirst aid & decontamination facilities & GEP 550-T1 reenviron sampling supplies TIET7.6 , GENMER.L. Commonwealth Edison Co B3/10/06 NRC No Detailed Affiliation Given 2pp 20940 200 24% Fiche 50-204,83/10/21,8310270024
- --8310270032 Public version of revised emergency plan implementing procedures, including Procedures QEP 550-1 re first aid & decontamination facilities, GEP 550-2 re emergency equipment inventory & GEP 550-T1 re environ sampling supplies * Commonwealth Edison Co B3/10/06 24pp 20940 702 24X Fiche 50-254,83/10/21,8310270024
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/21 Document Hanagement Branch ip 20937 216 24X Fiche 50-000,83/10/21, 8310270526
- --B310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6. "Administration & Logistics Manager" W/831017 itr & receipt form NELLIS, C A Commonwealth Edison Co B3/02/18 DENTON, H R NRC No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000, B3/10/21. B3102/0526
- B310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000,83/10/25, 8310280307
- --8310280314 Public version of revised generating stations emergency plan telephone directory GALLE.DP Commonwealth Edison Co 83/08/11. DENTON, HR Dffice of Nuclear Reactor Regulation. Director 64pp 20963 127 24X Fiche 50-000,83/10/25,831028030/

- 8310280191 Releases public version of rovised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000-83/10/26, 8310280191
- --8310280209 Public version of Nev I to Emergency Plan Implementing Procedure EDF-15, "Emergency Operations Facility Activation" MODRE R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000,83/10/26,8310280191
- P Operating license stage documents & correspondence
- B310200273 Forwards schedules for equipment qualification test programs for facilities.per 810528 ltr Dates given for current qualification activities should be viewed as "target dates" & not as firm dates BARNES.P L Commonwealth Eduson Cq B3/10/05 KEPPLER.J 9 Region 3. Office of Director 10pp 20830 034 24% Fiche 50-000.83/10/05. B310200273
- 8310120259 Supple 830531 ltr re containment integrated leak rate test frequency Type A test should be performed during upcoming refueling outage Tests should also be performed during plant shutdowns until 100FR50, App J criteria met SPESSARD, R L Region 3, Office of Director 83/10/07 REED, C, Commonwealth Edison Co 1p 20A91 320 24X Fiche 50-254,83/10/07,8310120253
- 3310170345 Provides add1 info re NUREO-0737. Item II, K 3 P2. justifying Use of HPCI logic for RCIC suction switchover RCIC sys not safety-related & is not intended as backup for HPCI sys RYBAX.B Commonwealth Edison Co 83/10/07 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 20784 3FD 24X Fichs 50-254.83/10/07.8310170545
- B310310054 Advises that pipe stresses & support loads dur to dead weight of water in pipe.concurrent thermal effects & effects of postulated earthquake within design allowables reviewed, per NUREO-0737. Item II D i RYBAK.B Commonwealth Edison Co 83/10/20 DENTON.H R Uffice of Nuclear Reactor Regulation. Director 2pp 20951 146 24X Fiche 50-254.83/10/20,8310310054
- 310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood.consisting of Chapters 7 2 & 8 0 BENNETT.C J Commonwealth Edison Co 83/10/21 CASE.E 0 Office of Nuclear Reactor Regulation. Director ip 20894 259 P4X Fishe 50-000.83/10/21.8310250P93
- -8310250278 Rev 10 to Offsite Dose Calculation Hanual for LaSalle & Quad-Cities * Commonwealth Edison Co 63/09/30 44pp 20894 260 24X Fiche 50-000,83/10/21,8310250293
- -0310250302 Rev 9 to Offsite Dose Calculation Manual for Braidwood. consisting of Chapters 7 2 & 8 0 * Commonwealth Edison Co 03/08/31 56pp 20894 304 24X Fiche 50-000,83/10/21,8310250293
- G Inspection reports: IE Bulletins & correspondence
- 8310140133 Responds to notice of violation & proposed imposition of tivil penalities re insertion of control rads during reactor shutdown on 830310 & ii Shift turnover procedures revised Info sessions for control room personnel conducted THOMAS. B. L. Commonwealth Edison Co. 83/08/12 MEPPLER. J. G. Region 3. Office of Director lipp 20763 356 24X Fiche 50-254,83/08/12,83/0140133
- 8368300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Byo list enol WORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24x Fiche 50-000,03/09/26,8308300340
- 8308300342 IE info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDANA E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 114pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63; "Potential Failures of Meetinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 03/09/26 Consolidated Edison Co of New York, Inc. 118pp. 20778:001 24X Fiche, 50-000, 83/09/26.830830800045

- 8308300347 IE Info Notice 83-64. "Lead Shiplding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list and! JORDAN: E. t. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of N Vork, Inc. 115pp 20716 324 24X Fishe 50-000:83/09/29, 83005003
- 8310140261 Forwards IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 & netice of violation HIND. J & Division of Radiological & Materials Safety Programs 83/09/29 REED.C Commonwealth Edison Co 2pp 20762 048 C4K Fiche 50-254,83/09/27.8310140261
- --83101402/i IE Insp Repts 50-254/83-26 & 50-265/83-25 on 83002P-26 & 0709 Noncompliance noted failure to distribute controlled energency plan procedure revs to NRC PHILLIPS, M.P., PLOSKI, T.J., PAPERIELLO, C.J., Region 3, Defice of Director 83/09/29 17pp 20762-052 24% Fiche 50-254, HJ/09 8310140261
- 8310200124 Forwards 1E Mgt Meeting Repts 50-010/83-18.50-23//83 p/, 50-249/83-25.50-254/83-27.50-265/83-26.50-295/83-19, 50-304/83-20.50-273/83-38.50-454/83-44, 50-455/83-33.50-456/83-14 & 50-457/83-13 NGRELIUS, C E Division of Project & Resident Programs REED, C Commanwealth Edison to 2pp 20834 098 24% Fiche 50-000.83/10/04.8310200124
- --8310200148 TE Mgt Meeting Repts 50~020/83-18,50~237/83~27,50~1447/50~254/83-27,50~265/83-26,50~275/83-19,50~304/83-20,50~373/83-38,50~374/83-38,50~454/83-44,50~455/83-33,50~456/83-14 & 50~457/83-13 NORELIUS, C E Division of Project & Resident Programs 4pp 20834 100 24% Fiche 50~000,83710/04,8310700124
- B310170337 Bubmits status of as-built reviews of safe shutdown pip. supports for IE Bulletin 79-14. As result of review of Guad Cities, two piping sys found to have addl discrepancies Seven new hangers added RVNAK. B Commonwealth Edison Co 83/10/04 KEPPLFR. J O Region of the process of the Science of Director 2pp 20/86 155 24X Fiche 50-000,03/10/06 83:017033/
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RID Bypa Loops Used in Westinghouse Plants" Svc list encl JORDAN, C. L. Division of Emergency Preparadness & Engineering Response (Fost 830103) 83/10/0/ Consolidated Edison Co. of York, Inc. 76pp 20827 213 24X Fichs 50-000,83/10/07,8308300
- B30B300752 IE Info Notice 83-64. "Fatality at Argentine Critical Facility " Svc list encl JGRDAN.E L Division of Emergency Preparedness & Ingineering Response (Post B30103) B3/10/07 Consolidated Edison Co of York Inc 79pp 20882 0P6 24X Fiche 50-000.B3/10/07.B30D3DC
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl De Causes Production of Noxious Gases "Syc list encl JORDANIC L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of York, Inc 117pp 21043 075 24% Fiche 50-000,83/10/11.836820
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defriction Self-Contained Breathing Apparatus Air Cylinders " Svr list encl.

 JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. Cyork, Inc. 120pp 20827 129 24X Fishe 50-000,83/10/11.830803
- 8310180238 Clarifies procedures for admitting NRC personnel to facilities Access lists identifying authorized clearances encl Update will be provided every 6 months AXELSON.W L. Region 9. Office of Director 83/10/14 RLED.C Commonwealth Edison Co 7ap 20808 234 24X Fichs 50-254.03/
- 8310180551 Notification of 831021 meeting w/DWR licensees in Beth MD to discuss future insps for intergranular stress corrosion cracking MIRAOLIA, F.J. Assistant Director for Safety Assessment DIV10 EISENHUT, D.Q. Division of Licensing Dpp 20823-358 EAX Fiche 50-000, 83/10/14,8310180561
- 8310250605 Forwards IE Insp Repts 50-254/83-25 & 80-265/83-24 bis 830802-0930 No moncampliance noted SHAFER: W D Region 3. Office of Director 83/10/18 REED, C Commonwealth Edison Co 2pp. 20900 276 24% Fiche 50-254, 8310250605

- --8310250613 IE Insp Repts 50-254/83-25 & 50-265/83-24 on 830802-09J0 No noncompliance noted Major areas inspected design changes & mods, organization & administration, procedures, onsite review committee operational safety & maint CHRISSOTINDS.N., MORRONOIELLO.A., WALKER.R.D. Region 3, Office of Director 83/10/18 7pp 20900 278 24x Fiche 50-254/8J/10/18, 8310250405
- B310270435 Ack recoipt of 630825 ltr re-schodule for implementation of multiple peak resolution & peak reclassification enhancements to AAIS per IC Insp Repts 50-254/82-13 & 50-265/87-15 PAPERIELLO,C J Region 3, Office of Director B3/10/25 RYBAK,B Commonwealth Edison Co ip 20723 057 24y Fiche 50-254,B3/10/25,B310270475
- R Periodic operating reports & related correspondence
- 8310180:109 Revised monthly operating repts for Jul & Aug 1983 W/831003 ltr XALIVIANAKIS:N Commonwealth Edison Co 83/08/31 Director's Office of Inspection and Enforcement 2pp 20008 169 24X Fiche 50-254,83/08/31/8310180109
- B310170353 Forwards listing of changes, tests & experiments completed during Sept 1783 Summary of safety evaluation reported per 10CFR50 59
 KALIVIANAKIS.N Commonwealth Edison Co 83/10/03 CASE.E G Office of Nuclear Reactor Regulation, Director App 20786 165 24X Fichs 50-254,83/10/03,8310170353
- 8310180263 Monthly operating repts for Sept 1983 W/G71003 ltr MIBAK.A L. KALTVIANAKIS.N Commonwealth Edison Co. 83/10/03 Director's Office Office of Inspection and Enforcement 26pp 20807 052 24X Fichs 50-254.83/10/03.8310180225
- S Reportable occurrences, LLRs & related correspondence
- B310110A30 Responds to F0IA request for four different categories of documents described in B30510 ltr Forwards matl listed in App Arresponsive to Items 1.2 % 4 DDE should be contacted for matl requested in Item 3 of ltr FELTON.J M Division of Rules and Records 83/06/14 HIAFF, 9 L Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000.83/06/14.8310110430
- ~~8310110478 Responds to 830413 ltr requesting info re use of foreign matts on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
 FARRAR, D. L. Commonwealth Edison Co. 83/04/22 KEPPLER, J. G. Region 3, Office of Director App. 20706 063 24X
 Fiche 50-000,83/06/14,8310110430
- 8310120158 LER 83-032/03L-0 on B30701, while preparing for refuel outage, secondary containment capability test revealed varuum attainment of 0 IS-inch water Caused by aged goskets on personnel access doors Gaskets replaced W/B30726 ltr PREUSS, M. XALIVIANAKIS, N. Commonwealth Edison Co. B3/09/26 KEPPLER, J. Region 3, Office of Director. 3pp. 20696-027. 24) Fiche 50-254,B3/09/26.B310120158
- 831017049: LER 83-034/03L-0 on 830908, LPC1 loop select for RHR loop A declared inoperable due to inability to close recirculation pump IA discharge valve MC 1-202-5A Caused by shorted tentrol cables on valve Cables replaced W/831003 ltr IBEN.C , KALIVIANAKIB.N Commonwealth Edison Co 83/10/03 KEPPLER, J. Region 3, Office of Director 4pp 20784 119 24X Fiche 50-254,83/10/03,8310170491
- B3i0170271 LER 83-035/03L-0 on B30915. Target Rock valve 1-203-3A stock open Caused by eroded second-stage pilot seat Valve replaced b tested satisfactorily on B30922 W/R31005 ltr CODK, D. KALIVIANAKIS.N Commonwealth Edison Co B3/10/04 KEPPLER, J & Region 3, Office of Director 4pp 20786 209 24X Fiche 50-204, 83/10/04, 8310170271
- B310270400 LER 83-036/03L-0 on B30920, discovered ripped ventilation & fire stop boot Caused by extended exposure of boot to heat & normal wear Urethane foam metl installed & boot replaced W/B3101B ltr FUHS. A. KALIVIANAKIS, N. Gommonwealth Edison Co. B3/10/IB KEPFLER, J. Q. Region 3, Office of Director 3pp 20924 012 84X Fiche 50-254, 83/10/18.8310270400
- B310270404 LER 83-037/03L-0 on B30723, while inerting primary containment, containment oxygen not reduced to Tech Spec requirement Caused by sample response time & probable source of air in-leakage through compressor W/031020 ltr HBSAK.A. KALIVIANAKIS,N Commonwealth Edison Co 93/10/20 KEPPLER,J G Region 3, Office of Director 4pp 20724 01b PAX Fiche 50-754.83/10/20,8310270404

F,

1

- DOCKET 50-255 PALISADES NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 8310040250 Forwards IE Insp Rept 50-255/BJ-19 on 830801-31 No noncompliance noted SHAFER. N D Region 3. Office of Director 83/09/13 DEWITT, R B Consumers Power Co 2pp 20613 065 24x Fiche 50-255,83/09/13, 8310040250
- --B310040255 IE lnsp Rept 50-255/B3-i9 on 830801-3i No noncompliance noted Major areas inspected operational safety preparations for refueling, maint surveillance, procedures & greparations for union employee strike
 JORGENSEN.B L, HELLER.J K, BDYD.D C Region 3, Office of Director 83/09/13 7pp 20613-067 24X Fiche 50-255,83/09/13,8310040250
- 8310180464 Forwards proposed implementation schedule on intrusion detection sys. in response to NRC 83051P request Schedule withheld (ref 10CFR73 21)
 VANDEWALLE.D J Consumers Power to 83/09/23 CRUTCHFIELD.D Operating Reactors Brench 5 ig 20802 053 24X
 Fiche 50-255,83/09/23.8310180464
- 8310110019 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687 357 24% Fiche 50-000,83/10/05,83(0110019)
- ---B310110024 Public version of Rev & to Emergency Plan Implementing Procedure EDF-7: "Offsite Dose Worksheet (Protective Actions)" W/830922 ltr & receipt form BRADLEY, J Consumers Power Co B3/07/10 Document Management Branch 2pp 20687 358 24X Fiche S0-000,83/10/05,8310110019
- 8310170243 Responds to 830817 ltr re changes to security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable CRUTCHF1ELD.D Operating Reactors Branch 5 83/10/11 VANDEWALLE.D J Consumers Power Co 2pp 20796 265 24X Fiche 50-255.83/10/11.8310170/43
- 8310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/21 Document Management Branch ip 20928 337 24% Fiche 50-000, 83/10/21, 8310270491
- ---B310270510 Forwards public version of Rev 2 to controlled copyholder list of general ofe ctr/emergency operations facility emergency implementing procedures & list depicting location of proprietary info in procedures

 CARLEY. A Consumers Power Co 83/09/15 Office of Nuclear Reactor Regulation. Director 7pp 20928 33B R4X
 Fiche 50-000, 83/10/21. 83102/0491
- B310270590 Releases public version of revised general oft control ctr/ Emergency operations facility emergency implementing procedures FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch ip 20944 322 24X Fiche 50-000, B3/10/25, B310270590
- --0310270593 Forwards public version of revised general oft control ctr/
 emergency operations facility emergency implementing
 procedures including Procedure GEN-2 re emergency telephone
 numbers Receipt form encl
 CARLEY.A Consumers Power Co 03/10/13 Document Management
 Branch 4pp 20944 323 24X Fiche 50-000, 83/10/25, 8310270570
- ~-8310270597 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure OEN-2 re emergency telephone numbers * Consumers Power Co. 83/10/11 42pp 20944 327 24X Fiche 50-000,83/10/25,8310270590
- P Operating license stage documents & correspondence
- B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER, L. Affiliation Unknown B3/03/02 NRC - Nu Detailed Affiliation Given 19 21004 2/0 24X Fiche 50-000.83/05/02, B31031001/

- 8307050511 Forwards proposed generic issue "PORV & Miock Valve Reliability", per NRC Ofc Ltr 40 guidelines PORV & block valve sus established as safety-grade components required to be operable during plant operation DIIANNI, D C Operating Reactors Branch 3 83/06/06 MINNERS, W Safety Program Evaluation Branch App 66852 312 24X Fiche 50-255,83/06/08,8307080513
- --83050600/1 Informs of review of PORV upgrade issued in Board Notification 83-47 Upgrade does not constitute new generic requirements but case-specific application of existing requirements DENTON. If Office of Nuclear Reactor Regulation, Director 83/04/27 SIELLO, V Reguonal Operations & Generic Requirements ip 66770 370 24x fiche to-255,83/06/08,8307050513
- --8304200046 Requests plans for submitting proposed new generic requirement for primary sys depressurization capability in PMRs for CKGR review STCLLO. V Regional Operations & Generic Requirements 83/04/11 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 1p 66753 008 24% Fishe 50-295,83/06/08,8307050513
- --8302090923 Comments on validity of NUREG-0737. Item II K 3 / re evaluation of PORV opening probability during overexposure transients in response to 820417 memo concerning 771004 & 800217 memorated MATTSON.R J Division of Systems Integration (post 811005) 83/01/13 LISENHUT, D Q Division of Licensing 3pp 46613 057 24X Fiche 50-255.83/06/00.0307050513
- --83022J0482 Forwards response to 820401 questions re NUREG-0737. Item
 II K 3 7 re PORV opening probability Challenge frequency
 should be reduced & reliability should be upgraded
 CHOM.E Reliability & Risk Assessment Branch 83/03/14
 THADANI.A Reliability & Risk Assessment Branch 16pp
 66700 076 24X Fiche 30-255.03/06/08.8307050513
- --8205270433 Recommends TMI Item 11 K 3 /. "Power Operated Relief Valve Opening Probability." be re-evaluated for gossible cancellation or redirection from technical viewpoint New contract cannot be justified until matter is resolved DIIANNI, D C Operating Reactors Branch 3 82/04/01 EIEENIMJ. D C Division of Liconsing 3pp 64086 203 24X Fiche 30-255,03/04/08,6307050513
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be place in PDR & list of facilities for which repts are unavailable FELTON, J M Division of Rules and Records 83/07/06 CONNER, L Affiliation Unknown ip 21004 271 24X Fiche 50-000, 83/07/06, 8310310071
- B310090463 Forwards application to amend License DPR-20, modifying basis for limiting wafety sys settings for reactor protection sys VANDEWALLE, D.J. Consumers Power Co. 83/09/29 CRUTCHFIELD, D. Operating Reactors Branch 5 1p. 20630-055 24X Fiche 50-255,8309/29,8310090463
- --83100504A5 Application to amend License DPR-20, modifying basis for limiting safety bys setting for reactor protection bys. required by 830405 LER corrective actions VANDEMALLE, D. J. Consumers Fower Co. 83/09/29 3pp 20630 056 24X Fiche 50-255, 83/09/29, 8310050463
- --8310050469 Proposed Tech Spec changes re limiting safety sys settings for reactor protection sys • Consumers Power Co 83/09/29 Operating Reactors Branch 5 5pp 20630 059 24% Fiche 30-255,83/09/29,8310050463
- --8010050470 "Rod Withdrawal Transient Regnalysis for Polisades Reactor" FRYER, II C., CHANDLER, J.C., KAYBER, W.V. Exxon Nuclear Co., Inc. (aubs of Exxon Corp.) XN-NF-83-87 83/08/26 59pp 20480 044 24 Fishe 50-255,83/09/29,8310050463
- B310060047 forwards commitments for evaluation of mods to MSIV/main steam tya.per SEP Topic XV-2, "Spectrum of Steam Piping Failures Inside & Outside Containment (PMR) "Failures Inside & Outside Containment (PMR) "Forestand of Containment (PMR) "Forestan
- B310070177 Notifies that response to technical evaluation rept. Items 78,80,81 & B2 re 2,400-volt motors mfg by Westinghouse, GF & Louis Allis, will not be submitted until B40228, due to extensive nature of documentation research effort TONER, K A Consumers Power Cn 89/10/03 CRUTCH-IELD, D Operating Reactors Branch 5 p 20659 114 24% Fiche 50-255,83/10/03.

- 8310130137 Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program." pcc 100FR2 7/0 CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/03 LUNDVALL, A E. Baltimore Gas & Flectric Co. App. 2077/ 045 443 Fiche 50-000, 83/10/03, 8310170177
- 8310120274 Advises that FR. containing Commission monthly natices which afford public apportunition for hearing on requests for action, will be transmitted w/o forwarding ltm in future CRUTCHFIELD.D Operating Reactors Draich 5 83/10/0/VANDEWALLE, D.J. Consumers Power Co. 3pp. 20691-047 24X Fiche 50 000.83/10/07.83101202/4
- 8310250433 Forwards safety evaluation of C-L Owners (roup Rept (IN-197 compliance w/NURES-0/37.Item 11 K 2 17, "Voiding in RCS During Transients "Requirements met Item closed CRUTCHF(ELD.) Operating Reactors Brench 5 83/10/19 VANDEWALE, D J Consumers Power Co 7pp 20897 037 24X Fiche 50-255, 83/10/19, 8310250403
- 8310280009 Forwards safety evaluation & Franklin Rescoich Ctr technice evaluation rept re NUREG-0737. Items II K 3 1. "Automatic PORV Isolation" & II K 3 2. "Rept on PORVs " Response acceptable CRUTCHFIELD.D Operating Reactors Branch 5 83/10/20 VANDEHALLE,D J Consumors Power Co 3pp 20934 109 249 Fiche 50-255.83/10/20.8310280009
- 8310250096 Notification of 831025 meetind w/util in Bethesda,MD to discuss proprietary portions of NRC review of Westinghouse safety parameter display sys
 WAMBACH.T V Operating Reactors Branch 5 83/10/21 CRUTCHTILE Operating Reactors Branch 5 3pp 20894 078 24X
 Fiche 50-255,83/10/21,8310250096
- Q Inspection reports: IE Bulletins & correspondence
- 8310120318 Amends 830318 response to NRC 830222 ltr re nuncompliar.cr noted in IC Insp Rept 50-255/B3-01 Add) corrective action new list of effective pages completed for lech Specs & issued to all copy holders to ascertain correct rev status VANDEWALLE, D.J. Consumers Power Co. 83/08/26 KEPPLER, J.G. Regii 3. Office of Director. 2pp. 20700-308-24X Fiche 50-255,83/00/26 8310120318
- 8310040250 Forwards IE Insp Rept 50-255/83-19 on 830801-31 No noncompliance noted SHAFER, D. Region 3, Office of Director 83/09/13 DENITH, R & Consumers Power Co. 2pp. 20613-065 E4X Fiche 50-255, 83/09/12, 8310040250
- --8310040255 IE Insp Rept 50-255/83-19 on 830801-31 No noncompliance noted Major areas inspected operational safety preparations for refueling, maint surveillance, procedures & preparations for union employee strike
 JOROENSEN, B. L. HELLER, J. K., BOYD, D. C. Region 3, Office of Director 03/09/13 7pp 20613-06/ 24X Fiche 50-255, 89/09/13-8310040250
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Gualification Tests " Syc list encl JORDAN & L Division of Lawrgency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of Ne. York, Inc 1:7pp 20754 022 24X Fichs 50-000,83/09/26,8308.400.4
- 8308300342 IE Info Notice 83.62, "Failure of Redundant Toric Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of he York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,83080000.64
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of No. York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,83083003300340034
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Rilated Sys W/o 1006850 59 Evaluation" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Editor Co of No York, Inc 115pp 20716 324 24% Ficho 50-000,83/09/29,830800036
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in 1810 Bupass Loops Used in Westinghouse Plants" Svc list and JORDAN E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison to of Ki York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07,63083003/6

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000.83/10/07.8308300/52
- 8308300759 IE Info Natice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Novinus Cases " Suc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York, Int. 117pp 21043-075 24X Fiche 50-000-83/10/11.8700:00/57
- 83083007A1 1E Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Syr list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 (unsultdated Edison Co of New York, Int 120pp 20827 129 24X Ficho 50-000, 83/10/11, 8308300761
- 8310180203 Clarifies NRC position on procedures for admitting NRC personnel to facility Access to vital areas should be afforded to listed Region III peronnel Update will be provided every & months AKELSON.W. L. Region 3. Office of Director 83/10/14 DEWIYI.P. Consumers Power Co. 7pp. 20807-036 74X Fiche 50-255.83/10/14.8310180207
- 8310270444 Forwards IE Insp Rept 50-255/83-23 on 830919-20 No noncompliance hoted LITTLE:N 9 Region 3. Office of Director 83/10/14 DEWIT1.R B Consumers Power Co 2pp 20923 117 E4X Fiche 50-255.83/10/14, 8310270446
- --B31027045D IE Insp Rept 50-255/83-23 on 830919-20 No noncompliance noted Major areas inspected data developed for SIRW tank support structure surveillance prior to repairs & auxiliary bidg mod procedures & const KEATING, DE , DANIELSON, DH Region (), Office of Director 83/10/14 4pp 20923 119 24X Fiche 50-255, 83/10/14.83102/0446
- 8310200256 Requests extension of 30 days for response to Action Item M of IE Bulletin 82-02. "Degradation of Ihreaded Fasteners in RCPB of PWRs " Threaded fastener insp being performed w/normal component insps during inservice insp program VANDEWALLE, D J Consumers Power Co 83/10/17 CRUTCHFIELD, D Operating Meastors Branch 5 1p 20830 101 24X Fishe 50-255.83/10/17.8310200256
- 8310270473 Ack receipt of 83042, Iti & forwards theck in amount of \$20,000 for payment of civil penalties amposed by NRC 830824
 Ith Corrective actions will be examined during future insps
 AYELRAD. J A Enforcement Staff 83/10/17 B&MITH, R B Consumers
 Power Co 2pp 20938 102 24X Fichu 50-255,83/10/17.8310270493
- B310250191 Forwards final SALP Rept 50-255/83-21 for Jul 1982 June 1983 Licensee improvement since earlier assessments noted KEPPLER. J G Region 3. Office of Director B3/10/20 DEWITT.R D Consumers Power Co 2pp 20894 001 24X Fiche 50-000.83/10/20. B310250191
- --8310250193 6AIP Rept 50-255/03-21 for Jul 1982 June 1983 4 Region 3, Office of Director 83/10/20 29pp 20894 003 24X Fiche 50-000,83/10/20,83102-0191
- --8310250197 Forwards summary of significant findings of SALP rept for Jul 1962 June 1983 as background info for 830916 meeting Comments on BALP rept may be provided within 20 days after meeting HIMD, J A Region 3, Office of Director 83/09/09 DEWITT, R B Consumers Power Co 4pp 20094 032 24X Fiche 50 000 83/10/20 8310256191
- --B310250203 Informs that licensee will meet all commitments in plant regulatory performance improvement program. In response to NRC 830709 It transmitting 8ALP for Jul 1982 - June 1983 VANDEWALLE,D J. Consumers Power Co. 83709726 KEPPLER, J. 0 Region 3, Office of Director 1p. 20894 036 24X Fiche 50-000,83/10/20,8310250191
- R Periodic operating reports & related correspondence
- B310120254 Monthly operating rept for Sopt 1983 W/B31003 1tr PETERBON, D.A., KENNIDY, D.M. Consumers Power Co. B3/10/01 NKC -No Detailed Affiliation Given App. E0491 316 24X Fiche 50-255, B3/10/01. B310120, 54

- S Reportable occurrences, LtMs & related correspondence
- 8310120249 LER B3-062/03L-0 on 830B2B. while plant shut down for refueling noutine refueling Suration surveillance revealed unpredictable zero shifts in pressurizer pressure transmitters Caused by inaccurate settings W/830927 lil JCHN8BN.B D Consumers Power Cn 83/09/27 KEPPLER.J G Region 3. Office of Director 2pp 20692 113 24X Fiche 50-255.83/09/27. 8310120649
- 8310120331 Requests withdrawal of LERs 83-037 % 83-042 Add1 occurrences re loss of control of either auxiliary feedwater control valves CV-0737A y CV-0736A in manner similar to referenced LERs not required to be reported to NIC JOHNSON, B D Consumers Power Co 83/09/2/ KEPPLER, J Q Region 3, Office of Director 2pp 20700 263 24X Fiche 50-255,83/09/27,8310120331
- 8310060221 Potential Part 21 rept re defective ITf-Grinnell hydraulic snubbers initially reported in 830928 teleon Deficient snubber valve blocks will be remachined & snubbers rebuilt JOHNSON.B D. Consumers Power Co. 83/09/30 KEPPLER.J.C. Region 3. Office of Director 4pp 20647 O21 24x Fiche 50-255.83/09/30, 8310060221
- B310120064 Supplemental RD 82-034 panel C.-47 will be modified & fire deluge sys reflash capability will be provided for panel C-13
 JDHNSDN. B D Consumers Power Co 83/10/03 KEPPLER. J C Region 3
 Office of Director 1p 20697 173 P4X Fiche 50-255.83/10/03.
 B310120064
- 8310170391 Telecopy RO on B31006.wolkdown of safety injection sys pipo hangers revealed overloaded condition on base plate & anchor bolts of hanger H214 Coused by error in design analysis Hanger support to be redesigned KRICH,R N Consumers Power Co B3/10/07 Region 3. Office of Director 1p 20786 164 247 Fiche 50-255.83/10/07.8310170351
- 8310210151 PNO-III-83-098 on 831014. Region III informed of discovery of circumferential crack indications in steam generator tubes near & in support plates, identified during eddy current testing Util estimates 20 to 50% of tubes affected HOLZMER.M. 80YD.D. Region 3. Office of Director 83/10/14 ip 20855 318 24% Fiche 50-255.83/10/14.8310210151
- 8310250250 LER B3-063/03L-0 on B30917.during functional testing, ITT-Orthnell hydraulic snubber 52 failed to lock-up as required Caused by generic mfg deficiency in snubber valve block affecting shuttle valve travel W/B31017 itm JOHNSON,B D Consumers Power Co 83/L0/17 KEPPLFR,J G Region 3-07610 of Director 4pp 20899 026 24X Fiche 50-255.83/10/17, 8310250250
- B310250462 LER B3-064/03L O on B30Vib.during routine surveillance test, as-found lift pressure of pressurized relief valve RC-1037 exceeded acceptance criteria range Cause unknown Valve lift setting adjusted to proper value W/B31017 ltr JOHNSON.B D Consumers Power Co B3/10/17 KEPPLER.J G Region G. Office of Director 2pp 20897 079 24x Fiche 50-235.B3/10/17.B310250462
- 8310270162 LER 83-065/017-0 on 831006, during walkdown of safety injection sys pipe hangers discovered overload condition on baseplate % anchor bolts of hanger H214 Caused by design analysis error Hanger support redesigned W/831018 ltr JONNSON B D. Consumers Power Co. 83/10/18 KEPPLER J G. Region 3. Office of Director 2pp 20725 013 24X Fiche 50-255,83/10/18.
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protoction plans
- 83i0R10032 Forwards IE Safeguards Insp Repts 50-259/83-24, 50-260/83-26 & 50-296/83-26 on 830706-07 & natice of violation Natice of violation withheld (ref locfR73 R1) O'REILLY, J. P. Region R. Office of Director 83/09/01 PARRIS, H. G. Tennessee Valley Authority 17pp 20859-320 24x Fiche 50-259, 83/09/01, 83i0R10032
- --8310210034 IE Bafeguards Insp Repts 50-259/83-24,50-260/83-26 & 50-296/83-26 on 830706-0/ Noncompliance noted in area of access control vital areas Details withheld tref 10CFR73 21)
 MODRE-D E Region 2: Office of Director 83/07/29 ip 20055 322 24X Fiche 50-259,83/09/01.0310210032

- 8310040452 Submits central emergency control ctr metrorological data availability statistics for Apr-June 1703 Data availability repts will be discontinued due to consistently high data availability through previous rept periods.

 MILLS-L M Tennessee Valley Authority 83/09/28 ADENSAM, E. Licensing Branch 4 2pp 20623 326 24X Fishe 50-000, 83/07/24, 8310040452
- E310110193 Releases public version of revised emergency plan implementing procedures FELTON. J.M. Division of Ruler and Records 83/10/05 Document Hanagement Branch 1p 20282 113 24% Fiche 50-259, 83/10/05, 83/10/10/195
- --8310110199 Forwards public version of revised emergency plan implementing procedures including Procedures IP-3 re alert. IP-4 re site area emergency & IP-5 re general emergency HILLS.L M Tennessee Valley Authority 83/07/IP DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 20682.114 24% Fiche 50-259,83/10/05,8310110195
- --8310110203 Public version of revised emergency plan implementing procedures, including Procedures IP-3 re alert IP-4 to site area owergency & IP-5 re general emergency WEBB, W.E. Tennessee Valley Authority 83/04/07 168pp 20482 115 24X Fiche 50-259,83/10/05,8310110195
- 8310310387 Forwards revs to security plan Revs withheld (ref 100FR73 21)
 MILLS.L M Tennessee Valley Authority 83/10/06 B'REILLY.J P
 Region 2, Office of Director 1p 20959 327 249
 Fiche 50-259.83/10/06.8310310387
- 3310170187 Forwards IE Safeguards Insp Repts 50-259/83-37,50-260/83-3/ & 30-296/83-37 on 830927-30 No noncompliance noted VERRELLI,D Division of Project & Resident Programs 83/10/12 PARRIE,H & Tennessee Valley Authority 2pp 20786 358 24X Fiche 50-259,83/10/12.8310170189
- --8310170238 IE Bafeguards Insp Repts 50-259/83-37,50-260/83-37 & 50-276/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response Details withheld (ref 10CFR73 21) MOORE.D E Region 2. Office of Director 83/10/11 lp 20786 360 24X Fiche 50-259,83/10/12,8310170189
- 8310240137 Forwards safety evaluation re proposed mods & alternate capabilities for achieving safe shutdown, per 10CFR50. App R, Sections III @ 3 & III L, fire protection rule Proposed mods acceptable
 VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority 2pp 2084 342 24X
 Fiche 50-259, 83/10/12, 8310240139
- -8310240141 Sefety evaluation supporting proposed mods & alternate capabilities for achieving safe shutdown.per 1007R50.App R. Sections III 0 3 & III L. fire protection rule + Office of Nuclear Reactor Regulation. Director 83/10/12 7pp. 20884 344 24X Fiche 50-259.83/10/12.8310240139
- -8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26.50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority 83/09/30 O'REILLY, b P Region 2, Office of Director 1p 20858 193 24X Fiche 50-209,83/10/17.8310210071
- 8310210362 Releases public version of revised emergency plan implementing procedures FELTON, J. M. Division of Rules and Records 83/10/17 Document Management Branch ip 20883 001 24X Fiche 50-257.83/10/17. 8310210362
- --8310210383 Forwards public version of revised emergency plan implementing procedures including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monitoring Procedures"

 MILLB.L M Tennessee Valley Authority 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20883 002 24X Fiche 50-259, 83/10/17,8310210362

- --8310210385 Public version of revised emergency plan implementing procedures, including Noscle Shoals Emergency Ct. Implementing Procedure MEEC IP-9, "Emergency Radiological Monitoring Procedures"

 * Tennessee Valley Authority 87/09/22 150pp 20883 00% [4]
 Fiche 50-259-88/10/17,8310210362
- P Operating license stage documents & currespondence
- B310040583 Comments on proposed design for compliance w/NUREG-0/37, item II K 3 13, "Separate HPCI & RCIC Initiation Levels" re-automatic restart Proposal acceptable VABSALLO, D B Operating Reactors Branch 2 B3/09/19 PARKIS.H & Tennessee Valley Authority 3pp 20461 204 247 Fiche 50-259, B3/09/19, 8310060583
- 8310070395 Requests info describing proposed Tech Sprc mods re addition of analog trip systincipating reliability, accuracy, response time of replacement instrumentation, separation criteria & single failure criterion
 VASSALLO.D B Operating Reactors Branch 2 83/09/20 PARRIS.H & Tennessee Valley Authority Jpp 20664 304 24X
 Fiche 50-259, 83/09/20.8310070395
- 8310070061 Forwards request for addl info re licensee this, analyses repair of pipe cracks, including info requested by IE Mulletin 83-02 Response required to approve startup VASSALLO.D B. Operating Reactors Branch & 83/09/21 PARKIS.N G Temessee Valley Authority 4pp 204/1 340 24x Fiche 50-239, 83/09/21, 8310070061
- 8310070068 Requests submittal of final radiological effluent lock Spr. & offsite dose calculation manual within 30 days
 VASSALLD.D B Operating Reactors Branch 2 83/09/21 PARKIG.H &
 Tennessee Valley Authority Opp 20671 334 24X
 Fiche 50-259, 03/09/21, 83/00/0069
- 8310070397 Forwards request for add1 info re 830713 requested changes to Tech Specs on extensive replacement of critical plant instrumentation w/analog trip sys VASSALLO,D B Operating Reactors Branch 2 83/09/21 PARRIS.H © Tennessee Valley Authority 3pp, 20664 285 24x Fiche 50-259,83/09/21,8310070397
- 8310070063 Forwards request for add1 info re 930713 application For amend to License DPR-33 re reload & plant mods concerning scram discharge vol & scram discharge instrument vol VASSALLO,D B Operating Reactors Branch 2 83/09/27 PARKIS.H & Tennessee Valley Authority 3pp 20671 337 24x
 Fiche 50-259.83/09/27.8310070063
- 8310110521 Forwards Amends 70,86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively 5 safety evaluation Amends change Tech Specs to modify required surveillance interval for standby gas treatment sys CLARK, R. J. Operating Reactors Branch 2 83/09/28 PARRIS, R. G. Tennessee Valley Authority 3pp 20/11 302 24X Fiche 50-259,83/09/28,8310110521
- --8310110536 Amends 90,86 t 59 to Licenses DPR-33.DPR-50 t DPR-68, respectively, revising Tech Specs for testing standby gas treatment sys from once per yr to once per operating cycle VASSALLO, D B Operating Reactors Branch 2 83/09/26: 12pp 20711 305 24X Fiche 50-259,83/09/28,8310110521
- --8310110551 Safety evaluation supporting Amends 90,86 & 59 to Licensed DPR-33, DPR-52 & DPR-66, respectively

 * Office of Nuclear Reactor Regulation, Director 83/09/28 3pp 20711 317 24% Fiche 50-259,83/09/28,0310110521
- 8310180422 Requests relief from schedular reguirements of 830325 confirmatory orders to install redundant in-containment radiation monitors, per NUREG-0737, Item 11 F 1 3 requirement Mod will be completed before startup in Cycle 7 KAMMER, D 9 Tennessee Valley Authority 83/10/12 DENION, H R. Office of Nuclear Reactor Regulation, Director 2pp 20803 308 24X Fiche 50-259, 83/10/12, 8310180422
- 8310240154 Forwards request for add1 info re reactor protection syspower monitoring sysdesign mod.per 811030 request Model Tech Specs for alectric power monitoring & analysis drawings not provided Submittal date requested VASSALLO, D II Operating Reactors Branch 2 83/10/12 PARAIS, H & Tennessee Valley Authority Bpp 20884 329 24% Fiche 50-259, 83/10/12, 8310240154
- 8310240243 Forwards SER & technical evaluation rept re NUREG-0/3),]tpace I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4. "Training for Mitigating Core Damage "Requirements met VASSALLO, D B Operating Reactors Branch 2 83/10/12 PARRIS.]] & Tennessee Valley Authority App 20891 123 24% Fiche 50-259, 83/10/12, 8310240243

- --8208310352 Improvements In Training & Requalification Programs As Required By (MI Action Items 1 A 2 1 & II B 4 for Biowns Ferry Nuclean Plants, Units 1,2 & 3, "technical evaluation rept

 * Science Applications, Inc. NRC-03-82-096 SAI-186-029-50 82/08/25 NRC No Detailed Affiliation Given 15pp 65280 216 237 Fichs 50-000.83/10/12.8310240243
- 8310,280148 Forwards "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Units 1.2 & J Prissure Vestel." in response to NRC request for addl info to support util 830922 request to change Tech Specs 15 191
 MILLS.L M Tennessee Valley Authority 83/10/19 DENTON.H 9
 Office of Nuclear Reactor Regulation. Director 1/pp 20939 063
 24X Fiche 59-259.83/10/19.8310280148
- --8310280149 "Analysis of Vessel Hall Neutron Dosimeter From Browns Ferry Unit I Pressure Vessel " NORRIS.C B., LINDHOLM,U S. Southwest Research Institute 78/08/31 31pp 20929 080 24X Firne 50-259.84/10/19.8310280148
- --8310280150 "Analysis of Vesse) Wall Neutron Dosimeter From Drowns Ferry Unit 2 Pressure Vessel " NORRIS,E B , LINDHOLM U B Southwest Research Institute 79/09/30 26pp 20929 111 24X Fiche 50-259.83/10/19.831028014B
- ---8310280151 "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Unit 3 Pressure Vessel" NORRIS,E 8, LINDHOLM.U 8 Southwest Research Institute 79/09/30 74pp 20929 137 24x Fiche 50-259.83/10/19.8310280148
- 8310310142 Forwards response to 830921 request for add1 info re insp & repair of pipe cracks Listed items not addressed since response would delay rept Response to listed items will be submitted by 840201 Startup approval requested by 831121 MILLS: N Tennessee Valley Authority 83/10/19 DENTON: H R Office of Nuclear Reactor Regulation, Director 225pp 20947 177 24x Fishe 50-259,83/10/19.8310310142
- 8310250082 Forwards responses to 830920 & 21 requests for add1 info re analog instrumentation installation Startup projected for 831128 MILLS.L M. Tennessee Valley Authority 83/10/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 64pp 20096 077 24X Fiche 50-259.83/10/20.8310250082
- B310270523 Notification of B31115 meeting w/util in Dethesda, MD to discuss imap & repairs of cracks in stainless steel plping prior to startup CLARK, R J Operating Reactors Branch 2 B3/10/21 VASSALLO, D B, Operating Reactors Branch 2 2pp 20937 214 24X Fichs 50-259, B3/10/21, B310270523
- Q Inspection reports, IE Bulletins & correspondence
- 8310250227 Updates 830624 response to violations noted in IC Inep Repts 50-257/83-14.50-260/83-14 & 50-296/83-14 Extension of schedule to eliminate backlog of CARS/LRS until 830901 requested MILLS,L M Tennessee Valley Authority 83/08/08 O'REILLY, J P Region 2. Office of Director ip 20899 067 24X Fiche 50-259.83/08/08.8310250229
- 8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26.50-260/83-26 & 50-276/83-26 on 830706-07 & notice of violation Notice of violation withhold (ref 10CFR/3 21)
 D'REILLY, J P Region 2. Diffire of Director 83/09/01 PARR)8,H 0
 Tennesses Valley Authority 2pp 20855 320 24X
 Fiche 50-259,83/09/01,8310210032
- --8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-276/83-26 on 830706-07 Noncompliance noted in area of access control vital areas Details withheld (ref 100FR73 21)

 MODRE, D E Region 2, Office of Director MCGUIRE, D R Division of Engineering & Operational Programs 83/07/29 lp 20855-3P2 24X Fiche 50-269, 83/09/01, 8310210032
- B310040265 Ack receipt of \$30824 ltr informing NRC of steps taken to correct violations noted in It Insp Repts 50-259/83-24. 50-260/83-24 \$50-260/83-24 VERRELLI,D M Region 2, Office of Director 83/09/14 PARRIS,H G Tennessee Valley Authority ip 20613 123 24X Fiche 50-259,83/09/14,8310040265
- --9310040271 Responds to NRC 830725 ltr re violations noted in IE Insp Repts 50-259/83-24,50-260/83-24 & 50-296/83-24 Corrective actions. LMT examiners barred from performing add1 intergranular stress corrosion cracking exams MILLS.L. M Tennessee Valley Authority 83/08/24 0'REILLY, J. P Region 2. Office of Director 3pp 20613 124 24X Fiche 50-259,83/09/14,8310040265

- --8310040275 Forwards IE lnsp Repts 50-259/83-24.50-260/83-24 & 50-276/83-24 on 830621-24 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/07/25 PARRIS,H G Tennessee Valley Authority 2pp 20613
- --8310040278 Notice of violation from insp on 830621-24 * Region 2: Uffice of Director 83/07/24 lp 20613 i29 24X Fiche 50-259.83/09/14.8310040265
- --8310040283 IE Insp Repts 50-259/83-24.50-260/83-24 & 50-296/87-24 on 830621-24 Noncompliance noted failure to follow IE Bulletin 83-02 for requiring documented training in intergranular stress corrusion cracking COLEY, J. L. Region 2. Office of Director BLAKE, J. J. Division of Engineering & Operational Programs 83/07/21 App. 20613 130 247 Fiche 50-259,83/09/14.8310040265
- B310070061 Forwards request for add1 info re licenser insp,analyses repair of pipe cracks including info requested by IE Bulletin 83-02 Response required to approve startup VASSALLO, D B Operating Reactors Branch 2 83/09/21 PARRIS,H @ Tennessee Vallwy Authority 4pp 20671 340 24X Fiche 50-259,83/09/21.8310070061
- 8308300340 lE Info Notice 83-61. "Alleged Use of Stand-Ins for Helder Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engintering Response (Post E330103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 830B300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Enganeering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fichs 50-000.83/09/26,8308300345
- 8310040487 Concurs w/corrective actions taken to rectify violations noted in IE Insp Repts 50-289/83-18,50-280/83-18 & 50-296/83-18 Acceptable finding permits initiation of fuel movement in & out of core O'REILLY,J.P. Region 2, Office of Director 93/09/26 PARRIS.H @ Tennessee Vailey Authority 2pp 20425 165 24X Fichs 50-299,83/09/26.8310040487
- B30B300349 IE Info Notice B3-64, "Lead Shielding Attached to Bafety-Related Sys W/o 10CFR50 B9 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000.83/09/29, B30B300349
- 8310250166 Ack receipt of B30986 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/B3-27, 50-260/B3-27 & 50-296/B3-27 LEHIB,R C Division of Project & Resident Programs 83/10/04 PARRIS.H 0 Tennassee Valley Authority ip 20893 251 24X Fiche 50-259,83/10/04,8310250166
- --8310250170 Responds to NRC 830824 ltr re violations noted in IF Insp Repts 50-259/83-27,50-260/83-27 & 50-296/83-27 Corrective actions test pressure gauges removed, fuse identification program being established & panel 25-32 cleaned MILLS.L M Tennessee Valley Authority 83/09/26 D'REILLY, J P. Region 2. Office of Director 7pp 20893 232 24X Fiche 50-259,83/10/04.8310250146
- --8310250174 Forwards IE Insp Repts 50-259/83-27,50-260/83-27 & 50-296/83-27 on 830626-0725 & natices of violation & deviation to the state of the s
- --8310250179 Notice of violation from insp on 830626-0725 * Region 2. Office of Director 83/08/24 3pp 20873 263 24X Fichm 50-259,83/10/04.8310250166
- --8310250185 Notice of deviation from insp on 830626-0725 * Region 2, Office of Director 83/08/24 ip 20873 266. 24X Fiche 50-257, 63/10/04, 8310250166

- --8310250190 JE Insp Repts 50-259/83-27.50-260/83-27 & 50-296/83-27 on B30624-0725 Noncompliances noted failure to meet requirements for operational safety & absence of safety wires on backup control ctr
 PAULK.0 L Region 2. Office of Director CANTRELL.F 5 Division of Project & Resident Programs B3/08/19 10pp 20893 267 24X Fiche 50-259,63/10/04.8310250166
- 8308300378 IE Info Natice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 930103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp. 20027 213 24% Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24% Fiche 50-000,83/10/07.8308300752
- 8310230131 Ack receipt of 830816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-296/83-11 LEWIS.R.C Division of Project & Resident Programs 83/10/07 PARRIS.H o Tennessee Valley Authority 1p 20897 272 24X Fichs 50-259,83/10/07.8310250131
- --831025013B Responds to NRC 830726 ltr re violations noted in IE Insp. Repts 50-259/83-i1.50-260/83-i1 & 50-296/83-i1 Corrective actions radicatemical lab manual revised to incorporate Reg Guide 4 i5 interim guidance MILLS.L H Tennessee Valley Authority B3/08/16 D'REILLY.J P Region 2. Office of Director. 3pp 20897 273 24X Fiche 50-259.83/10/07.8310250131
- 8310250234 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-28. 50-260/83-28 & 50-296/83-28 & 50-296/83-28 WERRELI, D K Division of Project & Resident Programs 83/10/07 PARRIS.H G Tennessee Valley Authority ip 20899 123 24% Fichs 50-259, 83/10/07, 8310250234
- --8310250240 Responds to NRC 830901 ltr re violations noted in IE Insp. Repts 50-259/83-28,50-260/83-28 & 50-276/83-28 Corrective actions requirements for receipt insp of GA-level mathestablished & wire brushes marked HILLG.L M Tennesses Valley Authority 83/09/30 O'REILLY, J.P. Region 2, Office of Director 4pp 20899 124 24X Fichs 50-259.83/10/07.8310250234
- --8310250247 Forwards IE Insp Repts 50-259/83-28.50-260/83-28 & 50-276/83-28 on 830725-29 & 0808 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/09/01 PARRIS.H 9 Tennessee Valley Authority 2pp 20879 128 24X Fiche.50-259.83/10/07.8310250234
- --8310250251 Notice of violation from insp on 830725-29 & 0808 * Region 2: Office of Director 83/09/01 2pp 20899 130 24% Fiche 50-259.83/10/07.8310250234
- --8310250257 IE Insp Repts 50-259/83-28.50-250/83-28 & 50-294/83-28 on 830725-29 & 0808 Noncompliance noted failure of receiving insp to control welding filler metts & to establish postitive controls for tools used on austenitic steel COLEY, J L. Region 2, Office of Director BLAKE, J J. Division of Engineering & Operational Programs 83/08/29 7pp 20899 132 24X Fiche 50-259.83/10/07.8310250234
- B30B300737 IE Info Notice 83-67, "Emergency Use Respirator Mat1 Defect Causes Production of Mollous Gases " Svc 31st encl.
 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308200757
- B30B300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list anci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp. 20827-129 24X Fichs, 50-000, B3/10/11, B30B300761
- B310170189 Forwards IE Safeguerds Insp Repts 50-259/B3-37:50-260/B3-37 & 30-294/B3-37 on 630927-30 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 63/10/12 PARRIS.H G Tennessev Valley Authority 2pp 20786/358 24X Fiche 30-239,83/10/12,8310170189
- --8310170238 IE Bafeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted Hajor areas inspected saturity organization & mgt & personne) response Datails withheld (ref j00FR73 2) MORE, D E. MCGUIRE, D R Region 2, Office of Director 83/10/11 is 20786 360 24X Fiche 50-259,83/10/12,8310170169

- B310210071 Ack receipt of B30930 itr informing NRC of correct violations noted in 15 lbsp Repts 50-259/801-26.
 50-260/03-26 t 50-296/83-26
 0'REILLY, J.P. Region 2, Office of Director B3/10/17
 Tennessee Valley Authority 1p 20858 192 24X
 Fiche 50-259, B3/10/17, B310210071

οØ

93

_--1

a3

83

83

90

ا اسلامه ا

- --8310210078 Responds to NRC 830901 ltr re violations noted in [E' Repts 50-259/83-26.50-260/83-26.50-276/83-26.00-rective actions withheld (ref 100FR/3 21)

 MILLS.L.K. Tennessee Valley Authority 83/09/30 O'REHLY I' Fiche 50-259.83/10/17.8310210071
- 6310310142 Forwards response to 830921 request for add t info re 192 repair of gipe cracks Listed items not addressed since response would delay rept Response to listed items will be submitted by 840201 Startup approval requested by 83111 be MILESL M Tennessee Valley Authority 83/10/19 DENTON, H 7 Office of Nuclear Reactor Regulation, Director 225pp. 20945:
- 8310270523 Notification of 831115 meeting w/util in Rethesda.MP to discuss insp & repairs of cracks in stainless steel piping prior to startup CLARK.R J Operating Reactors Branch 2 80/10/21 VASSALLO.DF Operating Reactors Branch 2 2pp 20937 214 24X Fiche 50-259,83/10/21,83102/0523
- R Periodic operating reports & related correspondence
- 83:0190186 Monthly operating repts for Aug 1983 W/830909 ltr. THOM.T. JONES.G T Tennessee Valley Authority 83/09/01 of Resource Management. Director 40pp 20820 16% 24x Fiche 50-299.83/09/01.8310190186
- B Reportable occurrences, LERs & related correspondence
- 8310210329 Responds to FDIA request for all documents resignifies. high rate of equipment failures for GE BMR/4 rated at 2.436 MM Forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/07/28. HAFMES B Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000.83/07/28.8310210329
- --8302180539 Discusses results of evaluation of LFRs for Jul 1981-1
 1982. For SALP ropt Quality & quantity of LER4 within range
 of average BHR facility
 SEVERIT, K V Reactor Operations Analysis Branch 83/02/09
 LEWIS.R C Division of Project & Resident Programs
 3pp
 20882 257 24% Fiche 50-000, 83/07/28, 8310210327
- 8310030432 LER 83-051/03L-0 on 830824 during refueling. Continuous & monitor 1-90-250 declared inoperable due to broken drive belt Caused by normal wear due to continuous operation Selt replaced W/B30922 ltr NORWOODD, DW. GREEN.H J. Tennesses Valley Authority. 83/09/22 O'REILLY, J.P. Region 2, Office of Director Spp 20601: 224 % Fiche 50-259, 83/09/22, 8310030432
- B310070301 Patential Part 21 rept re underrange characteristic of Model N-EiiQM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Own of Inspection and Enforcement Tipp 20651 064 24X Fiche 50-000.83/09/30.8310070301
- 8310140129 LER 83-053/03L-0 on 830314, control room emergency ventilation train A flow centrol damper found in full open position Caused by loose damper arm Damper reset to proper position W/831004 ltr.
 MCPHERSON, B R. GREEN, H J. Tennesses Valley Authority.

 D'REILLY, J P. Region 2. Office of Director 3pp 20763 041 % Fiche 50-259, 83/10/04, 8310140129
- 8310210226 LER 83-052/03L-0 on 830912, while performing Surveillants Instruction 4 11 C.9 & 4 on reactor bidg Llevation 573 fixed Instruction 4 11 C.9 & 4 on reactor bidg Llevation 573 fixed spray Jone 16 heat detector relay discovered imperable. Caused by random failure Relay replaced W/831011 ltr. gg/10/11. SOLLEY, S W. GREEN, H.J. Tennessee Valley Authority O'REILLY, J P. Region 2, Office of Director Spp 20052:071. W Fiche 50-259.83/10/11.8310210226

- g310250065 PND-11-83-084 licensee identified & reported to NRC that contractor welding svc employee received 59 mrem occupational oyerexposure during Third Guartor 1983 Licensee reviewing all circumstances associated w/ovent DEBS.B. olbSON, A.F. Region 2. Office of Director 83/10/20 ig 20896 085 24% Fiche 50-259.83/10/20.8310250065
- DOCKET 50-260 BROWNS FERRY NUCLFAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8310210032 Forwards 1E Safeguards Insp Repts 50-259/83-26.50-260/83-26 & 50-296/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10C1R/3 21) 0'REILLY,J P Region 2, Office of Director 83/09/01 PARRIS.H & Tennessee Valley Authority 2pp 208/95 320 24x Fiche 50-259.83/09/01.8310210032
- --8310210034 IE Safoguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26 on 830706-07 Noncompliance noted in area of access control vital areas Details withheld (ref 100FR73 21)
 MOURE.D E Region 2. Office of Directol 83/07/27 ip 20855 322 24X Fiche 50-259, 83/09/01, 0310210032
- @310040452 Submits central emergency control ctr meteorological data availability statistics for Agr-June 1783 Data availability repts will be discontinued due to consistently high data availability through previous rept periods MILLS.t. M. Tennessee Valley Authority 87/09/28 ADENSAM.E. Licensing Branch 4. 2pp. 20623 326 £4X Fiche 50-4000,83/09/26,8310040452
- 8310110195 Releases public version of revised emergency plan implementing procedures FELTON.J N Division of Rules and Records 83/10/05 Documen Management Branch ip 20682 113 24X Fiche 80-259,83/10/05, 8310110175
- --8310110197 Forwards public version of revised emergency plan implementing procedures; including Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency MILLS, L. H. Tennessee Valley Authority 83/07/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 20682 114 24% Ficha 50-257,83/10/05.8310110195
- --8310110203 Public version of revised emergency plan implementing procedures, including Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency WEBN WE Tennessee Valley Authorsty B3/04/07 168pp 20482 115 24X Fiche 50-259, 03/10/05, 03/10/1015
- 8310310387 Forwards rovs to security plan Revs withheld (ref 10CFR73 21)
 MILLS.L M Tennessee Valley Authority 83/10/06 0'REILLY, J P
 Region 2. Office of Director 1p 20959 327 24X
 Fiche 50-259.83/10/06.8310310387
- 8310170189 Forwards IE Safepuards Insp Repts 50-259/83-37, 50-260/83-37 t 50-296/83-37 on 830927-30 No noncompliance noted VERRELLI.D Division of Project & Resident Programs 83/10/12 PARRISH 9 Tompessee Valley Authority 2pp 20/86 358 24X Fiche 50-259,83/10/12,8310170187
- --8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 to 50-296/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization to mgt to personnel response Details withheld (ref 10CFR73 21)
 MODRE D E Region 2. Office of Director 83/10/11 ip 20786 360 24% Fiche 50-259, 83/10/12, 8310170189
- 8310240139 Forwards safety evaluation re proposed mods & alternate capabilities for achieving safe shutdown.per 10CFR50.App R. Sections III 0 3 & III L. fire protection rule Proposed mods acceptable
 VASSALLO.D B Operating Reactors Branch 2 83/10/12 PARR18.H Q Tennessee Valley Authority 2pp 20884 342 24X
 Fiche 50-257.83/10/12.8310240139
- ~-8310240141 Safety evaluation supporting proposed mods & alternate capabilities for achieving safe shutdown, per 10C(R50, App R, Sections III G 3 & III L, fire protection rule # Office of Nuclear Reactor Regulation, Director 83/10/12 7pp 20884 344 24X Fiche 50-259, 83/10/12.8310240139
- 8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 30-260/03-26 & 50-296/83-26
 0'REILLY,J P Region 2, Office of Director 83/10/1/ PARRIS.H GTennessee Valley Authority | Jp 20858 192 24X
 Fiche 50-259,03/10/17,8310210071

- --8310210078 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-239/83-26.50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 100FR73 21) MiLLS.L M Tennessee Valley Authority 83/09/30 O'REJILY, D P Region 2. Office of Director ip 20858 193 24X Fiche 50-299-83/10/17.8310210071
- 8310210362 Releases public version of revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch ip 20883 001 24X Fiche 50-259, B3/10/17. 8310210362
- --8310210383 Forwards public version of revised emergency plan implementing procedures including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9, "Emergency Radiological Monstoring Procedures " MILLS.L M Tennessee Valley Authority 83/10/06 DENYON.H R Office of Nuclear Reactor Regulation, Director ip 20883 002 24X Fiche 50-259, 83/10/17,8310210362
- ---8310210386 Public version of revised emergency plan implementing procedures, including Muscle Shools Emergency Ctr Implementing Procedure MSEC 1P-9, "Emergency Radiological Monitoring Procedures"

 * Tennessee Valley Authority 83/09/22 150pp 20883 003 24X Fiche 50-259,83/10/17,8310210362
- P Operating license stage documents & correspondence
- 8310060583 Comments on proposed design for compliance w/NUREG-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels" re-automatic restart Proposal acceptable VASSALLO, D B Operating Reactors Branch 2 83/09/19 PARRIB, H © Tennessee Valley Authority 3pp 20661 204 24X Fiche 50-259,03/09/19,8310060583
- 831007006B Requests submittal of final radiological effluent Tech Specs & offsite dose calculation manual within 30 days VASSALLO, D B Operating Reactors Branch 2 B3/09/21 PARRIS.H G Tennessee Valley Authority 3pp 20671 334 24X Fiche 50-259,83/09/21.831007006B
- 8310110521 Forwards Amends 90.86 & 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively & safety evaluation Amends change Tech Specs to modify required surveillance interval for standby gas treatment sys CLARK.R J Operating Reactors Branch 2 83/09/28 PARRIS, H G Tennessee Valley Authority 3pp 20711 302 24X Fiche 50-259,83/09/28,8310110521
- --8310110536 Amends 90.86 % 59 to Licenses DPR-33, DPR-52 & DPR-68, respectively, revising Tech Specs for testing standby gas treatment sys from once per yr to once per operating cycle VASSALD, D B Operating Reactors Branch 2 83/09/28 12pp 20711 305 24X Fiche 50-259,83/09/28,8310110521
- 8310240154 Forwards request for add1 info re reactor protection sys power monitoring sys design mod.per 811030 request Model Tech Specs for electric power monitoring & analysis drawings not provided Submattal date requested VASSALLO, D B Operating Reactors Branch 2 63/10/12 PARRIB, H 9 Tennessee Valley Authority Dpp 20884 329 24X Fiche 50-259,83/10/12,8310240154
- 8310240243 Forwards SER & technical evaluation rept re NUREO-0737. Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4. "Training for Mitigating Core Damage "Requirements met VABSALLO. D B Operating Reactors Branch 2 83/10/12 PARRIS. H 9 Tennessee Valley Authority App 20891 123 24X Fiche 50-259, 83/10/12. 8310240243
- --BROBBIO352 "Improvements In Training & Requalification Programs As Required By TMI Action Items I A 2 1 & 11 B 4 for Drowns Ferry Nuclear Plants, Units 1,2 & 3," technical evaluation rept

 * Science Applications, Inc. NRC-03-82-096 SAI-186-029-50 82/08/25 NRC No Datailed Affiliation Olven. 15pp

 66280 216 24X Fiche 50-000,83/10/12,8310240243
- 8310280148 Forwards "Analysis of Vessel Wall Neutron Dosimeter From Browns Ferry Units 1.2 & 3 Pressure Vessel," in reaponse to NRC request for additinfo to support util 830922 request to change Tech Specs TB 191
 MILLS.L M Tennessee Valley Authority 89/10/19 DENTON, H R.
 Office of Nuclear Reactor Regulation, Director 17pp 20929.063
 24X Fiche 50-259.89/10/19.8310280148

- --B310280150 "Analysis of Vessel Hall Neutron Dosimeter From Browns Ferry Unit 2 Pressure Vessel " NORTB.E B . LINDHOUN.U B Southwest Research Institute 79/09/30 26pp 20929 111 24X Fiche 50-259.83/10/19.8310280140
- G Inspection reports: IE Bulletins & correspondence
- 8310250229 Updates 830624 response to violations noted in IE lnsp Repts 50-259/83-14, 50-260/83-14 & 50-296/83-14 Eitension of schedule to eliminate backlog of CARs/DRs until 830901 requested MILLS.L M Tennessee Valley Authority 83/08/08 D'REILLY, J P Region 2, Office of Director ip 20899 067 24X Fiche 50-259, 03/08/08.8310250227
- 8310210032 Forwards IE Safeguards Insp Repts 50-257/83-26.50-260/83-26 & 50-276/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10CRR73 21) G'REILLY, J.P. Region 2. Office of Director 83/09/01 PARRIS, H G Tennessee Valley Authority 2pp 20855 320 24x Fiche 50-257,83/09/01.8310210032
- ~-8310210034 IE Safeguards Insp Repts 50-259/83-26.50-260/83-26 & 50-276/83-26 on 830706-07 Noncompliance noted in area of access control vital areas Details withheld (ref LOCENTS 21) HODRE.D E Region 2. Office of Director MCGUIRE.D fl Novision of Engineering & Operational Programs 83/07/29 ip 20855 022 24X Fiche 50-259,83/09/01.8310210032
- 8310040265 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in IE Thap Repts 50-259/03-24, 50-260/83-24 & 50-276/83-24 VERRELLI, D. M. Region 2, Office of Director 83/09/14 PARRIS, H. G. Tehnessee Valley Authority 1p 20613 123 24X Fiche 50-259, 83/09/14, 8310040265
- --8310040271 Responds to NRC 830725 itr re violations noted in 1E Insp Repts 50-259/83-24,50-260/83-24 & 50-296/83-24 Corrective actions LMT staminers barred from performing add1 intergrapular stress corresion cracking exams MILLS.L M Tennessee Valley Authority 83/08/24 D'REILLY, J P Region 2, Office of Director 3pp 20613 124 24X Fiche 50-259,83/09/14,8310040265
- --8310040275 Forwards IE Insp Repts 50-259/83-24.50-260/83-24 & 50-296/83-24 on 830621-24 & notice of violation VERRELLI, D M Division of Project & Resident Programs 63/07/25 PARRISH G Tennessee Valley Authority 2pp 20613 127 24X Fiche 50-259.83/09/14.8310040265
- --B310040283 IE Insp Repts 50-259/83-24.50-260/83-24 & 50-296/83-24 on 830521-24 Noncompliance noted failure to follow IE Bullstin 83-02 for requiring documented training in intergranular stress corrosion cracking CDLEY, J L Region 2. Office of Director BLAME, J J Division of Engineering & Operational Programs 83/07/21 opp 20613 130 24X Fiche 50-239,83/09/14,8310040265
- G08300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Helder Gualification Texts" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 93/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000.83/09/26.8308300340
- 108300345 IE Info Notice 89-63, "Potential Failures of Mestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 803003) 83/09/26 Consolidated Edison Co of New York, Inc. 1180p 20778 001 24X Fiche 50-000.83/09/26,8308300345
- G10040487 Concurs w/corrective actions taken to rectify violations noted in IE Insp Repts 50-259/83-18, 50-260/83-18 & 50-296/83-18 Acceptable finding permits initiation of fuel movement in & out of core 0'REILLY, J P. Region 2, Office of Director 83/09/26 PARRIS, H & Tennessae Valley Authority 2pp 20625 165 24x
- 308300349 IE Info Notice 83-64. "Lead Shipiding Attached to Bafety-Related Bys W/o IOCFR50 59 Evaluation " Svc list encl Division of Emergency Preparedness & Engineering JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000.93/09/29:830830030347

- 8310250166 Ack rereipt of 830926 ltr informing NRC of steps taken to correct violations noted in It. Insp Repts 50-259/83-27, 50-260/80-27 & 50-269/83-27
 LEMIS.R C Division of Project & Resident Programs 83/10/04
 PARTIS.H G Tennesse Valley Authority ip 20893 251 424X
 Fiche 50-259, 83/10/04.8310250166
- --8310250170 Responds to NRC B30824 ltr re violations noted in IE Jrsp Repts 50-259/83-27,50-260/83-27 & 50-296/83-27 Corrective actions test pressure gauges removed fuse identification program being established & panel 25-32 cleaned HILLS.L M Tennessee Valley Authority 83/09/26 D'REILLY, J P Region 2. Defice of Director 9pp -0093 252 24X Fiche 50-259.83/10/04.8310250166
- --8310250174 Forwards IE Insp Repts 50-259/83-27.50-260/83-27 & 50-296/83-27 on 830626-0725 & notices of violation & deviation LEMB.R C Division of Project & Resident Programs 83/08/74 PARRIS.H 0 Tennessee Valley Authority 2pp 20893 P61 P4X Fiche 50-259,83/10/04,8310250166
- --8310250179 Notice of violation from insp on 830626-0725 * Region 2, Office of Director 83/08/24 3pp 20893 263 24x Fiche 50-259.83/10/04.8310250166
- --8310250185 Notice of deviation from insp on 430626-0725 * Region 2. Office of Director 83/08/24 ip 20893 266 24x Fiche 50-259.83/10/04,8310250166
- --B310250190 IE Insp Repts 50-259/B3-27, 50-260/B3-27 t 50-296/B3-27 on B30626-0725 Noncompliances noted failure to meet requirements for operational safety N absence of bafety wires on backup control ctp.
 PAULK, C L Region 2, Office of Director CANTREL, F S Division of Project & Resident Programs 83/08/19 10pp 20893 P67 P4X Fiche 30-259, B3/10/04, B310250166
- 8308300378 IE info Notice 83-65. "Surveillance of Fibw in RID Bypess Loops Used in Westinghouse Plants " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of No. York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,83083007/8
- 8308300792 IE Info Notice 83-66. "Fatality at Argentine Critical Facility" Syr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Ne York, Inc. 79np 20882 02& R4X Fiche 50-000,83/10/07.8308300752
- 8310250131 Ack roceipt of 830816 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-11, 50-260/83-11 & 50-2946/83-11 LEWIS,R C Division of Project & Resident Programs 83/10/07 PARRIB,H 9 Tennesse Valley Authority ip 20897 P72 P4X Fiche 50-259,83/10/07,8319250131
- --8310250138 Responds to NRC 830726 ltr re violations noted in IF Jns Repts 50-259/83-11.50-260/83-11 % 50-296/83-11 Corrective actions radiochemical lab manual revised to incorporate Reg Quide 4 15 interim guidance MILLSL & Tennessee Valley Authority 83/08/16 O'REILLY.J & Region 2, Office of Director 3pp 20897 273 24X Fiche 50-259/83/10/07,8310250(3)
- 8310250234 Ack receipt of 830930 ltr informing NRC of steps taken to Correct violations noted in IE Insp Repts 50-259/83-28, 30-240/83-28 & 50-295/83-28 VERRELLI.D M Division of Project & Resident Programs B3/10/07 PARRIS,H G Tennesse Valley Authority ip 20899 123 (14X Fiche 50-259, 83/10/07.8310250234
- --8310250240 Responds to NRC 830701 ltr re violations noted in 16 lm Repts 50-257/83-28, 50-260/83-28 & 50-296/83-28 (prective actions requirements for receipt insp of GA-level mattestablished & wire brushes marked MILLS, M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director App 20899 124 24X Fiche 50-259,83/10/07,8310250834
- --8310250247 Forwards IE Insp Repts 50-259/83-28, 50-260/83-28 k 50-296/83-28 on 830725-29 & 9608 & notice of violation LEHIBIR C Division of Project & Resident Programs 63/09/01 PARRIS:H O Tennesse Valley Authority 2pp 20899 128 24% Fiche 50-259, 83/10/07, 8310250234
- --8310250259 IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-296/83-28 B30725-29 & 0808 Noncompliance noted failure of receiving insp to control welding filler matis & to establish positive controls for tools used on anstentic stee!

 COLEY. J L Region 2, Office of Director BLAKE. J J Division Engineering & Operational Programs 83/08/29 7pp 20899 132 24X Fichs 50-259,83/10/07:8310250234

- 8308300759 IF. Info Nutice 83-47. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list and JORDAN, L. L. Division of Laergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consultated Edison Co. of New York, Int. 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83~68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl.

 40080N.C t Division of Emergency Preparedness & Engineering Response (Post 830103) 63/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X fichs 50-000,83/10/11,8308300761
- 8.310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 \$ 50-296/83-37 an 830927-30 No honcompliance noted VERRELLI.D Division of Project & Resident Programs 83/10/12 PARRESH 0 Tennessee Valley Authority 2pp 20786 358 24X Fichs 50-259, 83/10/12.8310170189
- --B31017023B II. Bafeguards Insp Repts 50-259/83-37, 50-260/83-37 & 30-296/83-37 on B30927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response Details withheld (ref 100FR73 21) HMORE, D.E. NCOUIRE, D.R. Region 2, Office of Director B3/10/11 p 20786 360 24X Fiche 50-259, B3/10/12, B310170187
- GJ10180551 Notification of 831021 meeting w/BMR licensess in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking MIRAQLIA.F U Assistant Director for Safety Assessment 83/10/14 ETBCMRUT, D G Division of Licensing 5pp 20823 358 24x Fiche 50 000, 83/10/14,8310180551
- 8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in It Insp Repts 50-259/83-26, 30-260/83-26 & 30-296/83-26 & 0'REILLY, J.P. Region 2, Office of Director 83/10/17 PARRIS,H & Fennessee Valley Authority 1p ROOSB 192 24X Fiche 80-259,83/10/17.8310210071
- --8310210078 Responds to NRC 830901 ltr re violations noted in 1E Insp. Repts 30-239/83-26.50-260/83-26.50-296/83-26. Corrective actions withheld (ref 10CFR/3 21)
 MILLS.L.M. Tennessee Valley Authority 83/09/30 0'REHLY,D P. Region 2. Office of Director ip 20858 193 24X
 Fiche 50-259.63/10/17,8310210071
- R Periodic operating reports & related correspondence
- 9.310170186 Monthly operating repts for Aug 1783 W/830707 ltr THOM: T., JONES. 0 T. Tennesses Valley Authority 83/07/01 Office of Resource Management, Director 40pp 20820 163 24X Fiche 50-237, 83/07/01:8310170186
- S Reportable occurrences. LLRs & related correspondence
- 8910210327 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,436 HW Forwards App A documents Documents also available in PDR FELTON, J.M. Division of Rules and Records 83/07/28 HAFNER, B Suffolk Nuclear Gludy Group 2pp 20002 223 24X Fiche 50-000,83/07/28,8310210327
- --8302180539 Discusses results of avaluation of LERs for Jul 1981 Dec 1982 for SALP mept Quality & quantity of LERs within range of average DWR facility BCYFRITALY V Reactor Operations Analysis Branch 83/02/09 LEMIS.R C Division of Project & Resident Programs Opp 20882 287 24x Fiche 50-000,83/07/28,8310210329
- ODIODO405 LER OD-050/ODL-0 on 030823, while performing 014 2 B-5/, RHR pump 2C cooler fan would not operate Caused by tripping of overload relay, GE Model CRI24CO28 Overload relay roset & surveillance instruction completed W/030721 ltr CHRISTOPHER, W. GREEN, H. J. Tennessee Valley Authority 83/09/21 O'REILLY, J.P. Region 2. Office of Director 3pp 20593 145 24X Fiche 50-260, 83/09/21, 8310030405
- B3100603B0 LER B3-052/03L-0 on B30B27, hydrogen analyzer B H2AN-76-104 found inoperable due to loss of flow Caused by residue collection in sensing line-causing inbeard isolation valve to atick closed. Line blown W/B307B3 lt. CHAMBERS. G T, GREEN. H J Tennessee Valley Authority. B3/09/23 O'REILLY, J P Region 2, Office of Director 3pp 20646 059 24X fiche 50-260, B3/09/R3, B3100603B0

- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EllOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.M J. Foxboro Coip. 83/09/30. Director's Office, Office of Inspection and Enforcement lipp. 20651-064 24% Fiche 50-000,83/09/30,8310070301
- 8310140200 LER 83-053/03L-0 on 830907.during normal operation, while performing whole cure low power range monitor calibr,P-1 indicated R factor less than required Caused by uncalibr monitor due to changes in reactor shape W/B3100A ltr SCHEIB.6 N . OREEN.H J Tennessee Valley Authority 83/10/04 0'REILLY.J P Region 2. Office of Director 3pp 20761 244 24X Fiche 50-260.83/10/04.8310140200
- 83i0140127 Telecopy RO 83061 on 831004. hydrogen-oxygen analyzer sample pump B determined inoperable following notification from Metal Bellows Corp of generic deficiency Pump replaced w/ upgraded model in stock on 831005
 JONES, G T Tennessee Valley Authority 83/10/06 Region 2
 Office of Director 2pp 20763 039 24X Fiche 50-260.83/10/06.
- 8310250360 Telecopy RD on 831013, routine analysis of 831007 scram revealed that 2-LT-85-45A did not initiate trip when SDIV exceeded 50 gallons Dn 831014, testing of transmitter revealed slow & erratic response to measured variable JONEB, Q T Tennessee Valley Authority 83/10/14 Region 2. Office of Director 1p 20898 093 24X Fiche 50-260.83/10/14.8310230360
- B310270073 LER B3-054/03L-0 on 830916.west side scram discharge vol high water level switch LS-B5-45C would not reset following scram Caused by setpoint drift Switch recalibr W/831014 ltr CHAMBERS, G T , GREEN, H J Tennessee Valley Authority 83/10/14 O'RETLLY, J P Region 2, Office of Director 3pp 20924 121 24X Fiche 50-240,83/10/14,8310270073
- 8310250045 PNO-II-83-084 licenses identified & reported to NRC that contractor welding svc employee received 59 mrem occupational overexposure during Third Guarter 1983 Licensee reviewing all circumstances associated w/event DEBS, 8 , GIBSON.A F Region 2, Office of Director 83/10/20 1, 20876 085 24X Fiche 50-259,83/10/20.8310250045

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

- 8310250322 Forwards IE Insp Rept 50-261/83-21 on 830709-0809 & notice of virilation VERRELLI.D M Division of Project & Resident Programs 63/08/31 UTLEY.E E Carolina Power & Light Co 2pp 20897 349 24X Fiche 50-261.83/08/31
- --8310250339 IE Insp Rept 50-261/83-21 on 830709-0809 Noncompliance noted failure to implement procedures for receipt of vendor documents
 WEISE, 8 Region 2, Office of Director BEMIS,P Division of Project & Resident Programs 83/08/30 12pp 20897 352 24X Fiche 50-261,83/08/31,8310250322
- 8310040347 Requests update of encl info re layout of technical support ctrs & amergency operations facilities
 VERRELLI,D M Division of Project & Resident Programs 83/09/12
 UTLEY,E E Carolina Fower & Light Ca 17pp 20425 183 24X
 Fiche 50-000,83/09/12,8310040347
- 83i01i0145 Forwards supplemental info to 830607 ltr re reactor coulant pump lube oil collection App R exemption request, per 830907 & 13 telcons, reflecting commitment to automatically actuate closed-head sys in lieu of manual actuation CUTTER, A B Carolina Power & Light Co. 83/10/05 VAROA, S A. Operating Reactors Branch 1 5pp 20666 282 24X Fiche 50-261,83/10/05,83/0110145
- B310170520 Forwards IE Safeguards 1nsp Rept 50-261/83-29 on B30920-23 No noncompliance noted VERRELLI,D Division of Project & Resident Programs B3/10/13 UTLEY,E E Carbiina Power & Light Co 2pp 20784 239 24X Ficha 50-261,83/10/13,8310170520
- --8310170522 1E Safeguards Insp Rept 50-261/83-29 on 830920-23 Nn noncompliance noted Major areas inspected review of corrective actions to 820119 security response records & barriers Details withheld (ref 100FR73 21) TOBIN.W. MCQUIRE.D R Region 2, Office of Director 83/10/12 ip 20784 241 24X Fiche 50-261,83/10/13,8310170520

- 8310310027 Application for amend to License DPR-23, incorporating radiological effluent Tech Specs & requirements to perform audits of emergency preparedness program & security plan MCDUFFIE.H A Carolina Power & Light Co 83/10/25 VARGA.S A Operating Reactors Branch 1 10pp 20966 028 24X Fiche 50-261,83/10/25,8310310027
- --8310310032 Proposed radiological effluent Tech Space.incorporating requirements to perform audits of emergency preparedness program & security plan Carolina Power & Light Co 83/10/31 272pp 20766 038 24x Fiche 50-261.83/10/25.8310310027
- Q Adjudicatory correspondence
- 8310040473 Affidavit of RB Starkey re util answers to Hartsville Croup first set of interrogatories Certificate of Svc encl STARXEY, R B Carolina Power & Light Co 83/09/08 Hartsville Group 3pp 20622 294 24% Fiche 50-261
- B310050447 Forwards D Basdetas B20429.0504,1203 & 14 correspondence to Commission re Martsville Interrogatories 3-1,3-2 & 3-3 M/o encls
 KARMAN.M Hearing Branch 1 83/09/26 MARGULIES,M B , KLINE, J R , HETRICK,D L Atomic Safety and Licensing Board Panel 10 20631 358 24X Fiche 50-261,83/09/26.6310050447
- B310040282 Further Answers to first set of interrogatories per 830901
 Itr agreement Certificate of Svc enc1
 MCROAN.R E , PARSONG.R H , MEBSTER.B H Carolina Power & Light Co
 83/09/30 Hartaville Group 19pp 20614 216 24X
 Fiche 50-261,83/09/30.B310040282
- 8310940478 Affidavit of CR Dietz re util further answers to Hartsville Group first set of interpogatories Certificate of Svc encl DISTZ.C R Carolina Power & Light Co 83/09/30 Hartsville Group 3p 20623 097 24X Fiche 50-261.83/09/30.8310040478
- P Operating license stage documents & correspondence
- B310030161 Advises that organizational changes for GA program & changes to FSARs & mgt capability rept will be forwarded when completed

 UTLEY.E E Carolina Power & Light Co 83/09/13 DENTON.H R

 Office of Nuclear Reactor Regulation. Director 1p 20590 028 249 Fichs 50-000,83/09/13.8310030161
- 8310040354 Summarizes 830831 meeting w/util re plans for restructuring Corporate organization
 O'REILLY, J.P. Region 2. Office of Director 83/09/22 UTLEY, F. E. Carolina Fouer & Light Co. 2pp 20620 331 24X
 Fithe 50-000.83/09/22.8310040354
- B310070406 Forwards SER re util 791231 submittal concerning design of RCS vents Vent sys in conformance w/guidelines of NUREC-0737, Item II 8 I Item closed VARCA. A Operating Reactors Branch | 83/09/23 UTLEY, E E Carolina Power & Light Co. 14pp 20676-330 24X Fiche 50-261,83/09/23.8310070406
- G10060347 Forwards safety evaluation of util Blill9 response to Generic Ltr Bi-21, "Natural Circulation Cooldown" Reasonable assumance arrets that steam formation at reactor vessel upper head will not occur during cooldown VARGA-S A Licensing Branch 1 B3/09/27 UTLEY.E E Carolina Power & Light Co 2pp 20662 310 24% Fiche 50-261,83/09/27,8310060547
- I310060352 Safety evaluation supporting util Bill19 response to Generic Ltr Bi-21, "Natural Circulation Cooldown "

 NRC No Detailed Affiliation Divon B3/09/27 Bpp 20662 312 24X Fiche 30-261,83/09/27,8310060547
- OG60413 Forwards "HB Robinson Fluence Reduction Analysis for artial-Length Shield Assembly Concept." documenting results 1 flux reduction program to resolve pressurized thermal lock issue
 TITER: AB Corolina Power & Light Co 83/09/30 DENTON: H R
 14tice of Nuclear Reactor Regulation, Director 2pp 20641 26
 1X Fithe 50-261:83/09/30,8310060413
- 310060418 "HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept " " Energy Corp " Caroline Power & Light Co R-83-030 83/09/30 198pp 20641 293 24X Fiche 50-261, 83/09/30,8310060413
- Oigo174 "Robinson Unit 2 Steam Generator Replacement Study for Ol mand Proceeding." Certificate of Syc encl Carolina Power & Light Co 83/09/30 43pp 20809 195 24x iche 50-261.83/09/30.8310180174

- 8310120407 Forwards nonproprietary rept & Suppl 1 to "HB Robinson Unit 2.Cycle 10 SAR "Also forwards proprietary "ECCB & Plant Transsent Analyses " & "Mechanical Design Rept " Repts withheld (ref 10CFR2 790) UTLEY.E E Carolina Power & Light Co 83/10/05 VARGA, & A Operating Reactors Branch 1 14pp 20697 176 24X Fiche 50-261,83/10/05,831012040/
- --8310120415 Nonproprietary "HB Robinson Unit 2,Cycle 10 9AR "
 STONE,I Z . ADAMS:F T . LAMBERT.W L Exxon Nuclear Co . Inc
 (subs of Exxon Corp) XN-NF-83-72 83/09/01 39pp .06.97.10 .
 24X Fiche 50-261.83/10/05,8310120407
- --8310120422 Nonproprietary Suppl 1 to "HB Robinson Unit 2.Cy() 10 BAx STONE, I Z . ADAMS: F T. LAMBERT.W L Exxon Nuclear Co , 10:E (subs of Exxon Corp.) XN-NF-83-72 801 83/09/14 20pn 20497 227 24X Fiche 50-261.83/10/05.8310120407
- 8310210044 Application for amend to License DPR-23, incorporating new heatup & cooldown limitation curves
 MCDUFFIE.M A Carolina Power & Light Co B3/10/14 VARGA & A Operating Reactors Branch 1 2pp 20855 304 247
 Fiche 50-261
- ---8310210048 Proposed Tech Specs revising heatup & cooldown limitation curves * Carolina Power & Light Co 83/10/14 7pp 20855 300 24x Fiche 50-261,83/10/14,8310210044
- 8310210245 Application to amend License DPR-23 revising Yech Spacs to clarify qualification requirements for alternate members of plant nuclear safety committee HCDUFFLEM A Carolina Power & Light Co 83/10/14 VARQA, B A Operating Reactors Branch 1 2pp 20851 277 24X Fiche 50-261,83/10/14,8310210245
- --B310210246 Proposed Tach Spec changes clarifying qualification requirements for alternate members of plant nuclear safety committee

 * Carolina Power & Light Co 83/10/14 23pp 20051 2/7 P4X
 Fiche 50-261,83/10/14,8310210245
- 8310240126 Reviews DES Alternative 1 preferable Rating of LO-1 assigns since no significant adverse environ consequences anticipated MODRE, 8 N Environmental Protection Agency 83/10/19 RLOVA, O Office of Nuclear Reactor Regulation, Director in 20001 151 Page Fiche 50-261,83/10/19,8310240126
- 8310270292 Advises that review of DES re repair of steam generator a resulted in no comments
 ORESHAM.S C Transportation, Dept of, Federal Highway
 Administration 63/10/24 Division of Licensing ip 20/24 24
 24X Fiche 50-261.83/10/24.8310270292
- B310310027 Application for amend to Liceuse DPR-23, incorporating radiological effluent Tech Specs & requirements to perform audits of emergency preparedness program & security plan MCDUFFIE,M A Carolina Power & Light Co B3/10/25 VARGA, B A Operating Reactors Branch I 10pp 20966 028 24X Fiche 30-261.83/10/25,8310310027
- --8310310032 Proposed radiological effluent Tech Specs, incorporating requirements to perform audits of emergency preparedness program & security plan # Carolina Power & Light Co 83/10/31 272pp 20966 039 24 Fiche 50-261,83/10/25,8310310027
- a Inspection reports, IE Bulletins & correspondence
- 8310250322 Forwards IE Insp Rept 50-261/83-21 on 830709-0809 & nuther of violation
 VERRELLI, D M Division of Project & Resident Programs 83/061/18
 VTLEV, E E Carolina Power & Light Co 2pp 2089/ 34v 24x
 Fichs 50-261,83/08/31,8310250322
- --8310250329 Notice of violation from insp on 830709-0809 * Region 2, Office of Director 83/08/31 ip 20697 351 #4x Fiche 50-261.83/08/31.8310250322

- 8310040037 Forwards IE Insp Rept 50-261/83-23 on 830815-19 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/09/02 UTLEY,E F Carolina Power & Light Co 2pp 20608 125 24X Fichs 50-261.83/09/02
- --8310040043 IE Insp Rept 50~261/83-23 on B30815-19 No noncompliance noted Major areas inspected licensee action on previous enforcement matters: 64 program annual review; improvement program, test & experiment program & audit program DEBBAGE.A G. UPRIGHIC M. Region 2. Office of Director 83/08/31 11pp 20608 12/ P4X Fiche 50-261.83/09/02.8310040037
- 8310040166 Forwards IE Insp Rept 50-261/83-17 on 830725-29 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/09/07 UTLEY.E E Carolina Pawer & Light Co 2pp 20608 044 24X Fiche 50-261,83/09/07,8310040166
- --8310040168 IE Insp Rept 50-261/83-17 on 830725-29 No noncompliance noted Major areas inspected corrective action for previous violations, transportation of radioactive matis, breathing air line contamination event & posting, labeling & control ALBRIGHT, R H. HARR.K P. Region 2. Office of Director 83/09/02 Bpp 20608 046 24X Fiche 90-261,83/09/07.8310040166
- 8310040269 Ack receipt of 830901 ltr requesting extension to complete corrective actions in response to violations noted in IE Insp Rept 50-261/82-20
 LEWIS,R C Division of Project & Resident Programs 83/09/13
 UTLEY,E E Carolina Power & Light Co ip 20614 068 24X
 Ficha 50-261,83/09/13.8310040269
- --8310040285 Amends response to NRC 820820 ltr re violations noted in IE
 Insp Rept 50-261/82-20 Completion of flow diagrams &
 corresponding procedures for 0-list portion of sys extended
 to 831231
 STARKEY.R B Carolina Power & Light Co 83/09/01 O'REILLY, J P
 Region 2. Office of Director 2pp 20614 069 24X
 Fiche 50-261,83/09/13,8310040269
- 8308300340 |E Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN.C t Division of Emergency Preparedness & Engineering Response (Post 830103) 83709/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83709/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83709726,8308300045
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related 8ys W/o 10CFR50 59 Evaluation " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24% Fishe 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 RAX Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svr list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300757 IE Info Notice 83-67, "Emergancy Use Respirator Matl Defect Causes Production of Noxious Gases" Syc list encl JORDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308200759
- 8308300761 1E Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York Inc. 120pp 20827 129 24X Fichs 50-000.83/10/11,8308300761

- B310170520 Forwards IE Safeguards Insp Rept 50-261/83-29 on 830920-23 No noncompliance noted VERRELLI, D. Division of Project & Resident Programs B3/10/13 UTLEY, E. E. Carolina Power & Light Co. 2pp. 20784 239 24X Fiche 50-261,83/10/13,8310170520
- --8310170522 IE Safeguards Insp Rept 50-261/83-29 on 830920-23 No noncompliance noted Major areas inspected review of corrective actions to 820119 security response, records & barriers Details withheld (ref 10CFR73 21) TOBIN.W., MCQUIRE, D.R. Region 2. Office of Director 83/10/12, 1p 20784 241 24X Fiche 50-261.83/10/13,8310170520
- B310190162 Forwards proposed scope of 4 5 EFPM eddy current insp program scheduled to begin on B31210 Scope includes insp of all unplugged tubes ZIMMERMAN,S R Carolina Power & Light Ca B3/10/17 VAR9A,B A Operating Reactors Granch 1 4pp 20821 058 24% Fiche 50-261.B3/10/17.B310190162
- B31025058B Ack receipt of supplemental B30930 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-241/83-15 VERRELLI,D M Division of Project & Resident Programs B3/10/17 UTLEV,E E Carolina Power & Light Co ip 20900 090 24x Fiche 50-241,83/10/17,8310250588
- --8310250394 Suppls response to NRC 830824 itr re violations noted in IE Insp Rept 50-261/83-15 Corrective actions six capped instrument tubes & respective caps in Sleeve 18 fitted w/shrink tubing so operators could identify cap tampering MORGAN, R E Carolina Power & Light Co 83/09/30 O'REILLY, J P Region 2. Office of Director Ppp 20900 091 24X Fichs 50-261,83/10/17.8310250588
- --8310250401 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-241/83-15
 VERRELLI.D M Division of Project & Resident Programs 63/08/24
 UTLEY.E E Carolina Power & Light Co Ip 20900 093 24X
 Fiche 50-241,63/10/17.8310250588
- --8310250408 Responds to NRC 830/15 ltr re violations noted in IE Insp Rept 50-261/83-15 Corrective actions daily check of low temp overpressure protection sys nitrogen pressure when sys required operable proceduralized in min equipment list STARKEY, R B Carolina Power & Light Co 83/08/12 D'RCILLY, J. P Region 2. Office of Director 5pp 20900 094 24X Fiche 50-261.83/10/17.8310250588
- --8310250618 Forwards 1E Insp Rept 50-261/83-15 on 830510-0610 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/07/15. UTLEY.E L Carolina Pown & Light Co 2pp 20900 099 24X Fichs 50-261/83/10/17
- --8310250620 Notice of violation from insp on 830510-0610 * Division of Project & Resident Programs 83/07/15 2pp. 20900 101 24% Fiche 50-261,83/10/17,8310250588
- --8310250627 IE Insp Rept 50-261/83-15 on 830510-0610 Noncompliance noted failure to take adequate corrective action re backup nitrogen pressure & failure to establish adequate procedures re instrument tubing lines
 WEISE.S Region 2. Office of Director BEMIS.P Division of Project & Resident Programs 83/07/06 13pp 20900 103 24X Fiche 50-261.83/10/17,8310250588
- 8310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions described in IE Info Notices 83-07 & 83-07 & 83-07 & 83-07 & 83-07 & 83-07 Use of add1 insp & testing during receipt insps investigated MCDUFFIE,M A Carolina Power & Light Co 83/10/21 DEYOUNO,R.C. Director's Office, Office of Inspection and Enforcement ip 20700 347 24X Fiche 50-000,83/10/21,8310250571
- S Reportable occurrences, LERs & related correspondence
- 8310030424 RD on 830916. Tech Spec instantaneous release limit for radioiodins exceeded Investigation continuing MCRGAN.R E Carolina Power & Light Co 83/09/19 O'REILLY, J. P. Region 2. Office of Director 1p 20593 180 24X Fiche 50-261.83/09/19.8310030426
- 8310040516 RO on 830724, svc water leak discovered on containment fan cooler HVH-2 Cooler declared inoperable Repairs initiated Event considered degradation of containment boundary per IE 801letin 80-24 MCROAN, R E Carolina Power & Light Co 83/09/27 O'REILLY, J. P. Region 2. Office of Director ip 20623 092 24X Fiche 50-261, 63/09/27.8310040516

- 8310070308 RD on 830928, syc water leak discovered on containment fan cooler HVH-2 Event considered degradation of containment boundary per IE Bulketin 80-24 MORGAN, R E Carolina Power & Light Co 83/09/29 D'REILLY, J P Region 2, Office of Director ip 20652 214 24X fichs 50-261,83/09/29,8310070308
- 8310070136 Updated LER 80-030/03L-1 on 801202 & 03.charging pumps A.B & C discharge line pressure gauge tap pipe socklets found leating Caused by sys design deficiencies allowing high vibration Leaks repaired & design modified W/830930 1 tr WRIGHT, C L. MDRGAN, R E Carolina Power & Light Co 83/07/30 07/8EILLY, J P. Region 2. Office of Director App 20659 064 247 Fiche 50-261, 83/09/30, 8310070136
- B310070322 EER B3-024/017-0 on B30916. Tech Spec instantaneous release limit for rediciodine exceeded through plant stack Cause not stated Equipment which provided pathway shut down lodine level remained normal during testing W/830930 ltr MRIGHT. C. Carolina Power & Light Co. 83/09/30 U'REILLY, J.P. Region 2, Office of Director. 4pp. 20652 168—24X Fiche 50-261,83/09/30,8310070322
- 8310170541 LER 93-025/01T-0 on 830926, svc water leak discovered on containment fan cooler HVH-2 Svc water isolated & unit declared inoperable Caused by corrosion/erosion of coolant tubing Tube bundle repaired H/H31010 ltr HRIGHT,C t. MORGAN.R E Carolina Power & Light Co 83/10/10 O'REILLY,J P. Region 2, Office of Director 3pp 20782 100 24X Fiche 50-261,83/10/10.8310170541
- OCKET 50-263 MONTICELLO NUCLEAR DENERATING PLANT

 Security, medical, emergency & fire protection plans
- 10060573 Forwards exemption from 10CFR50 48(c) schedular requirements, per 820630,830208 & 0422 requests VASSALLO.D B Operating Reactors Branch 2 83/09/21 MUSCLF, D H Northern States Power Co 3pp 20661 23/ 24X Fich+ 50-263,83/09/21,8310060973
- -8310060576 Examption from 10CFR50 48(c) schedular requirements, per 820630, 830208 to 0422 requests implementation dates for 10CFR50 48(c)(2) & (c)(3) extended 9 months & to before startup of Cycle 12 respectively DENTON, H R Office of Nuclear Reactor Regulation, Director 83/09/21 Northern States Power Co 7pp 20661 240 24% Fiche 50-263, 83/09/21, 8310060573
- B310070157 Notification of B31012 meeting w/util & consultants in Bethesda.HD to discuss design basis for alternate safe shutdown capability NICOLARAS.H Liconsing Branch 2 B3/10/03 VASSALLO,D B Liconsing Branch 2 2pp 20680 304 P4X Fichs 50-263.83/10/03,8310070157
- 3310110176 Releases public version of revised emergency response plan implementing procedures FELTON, J.M. Division of Rules and Records, BD/10/00 Document Hanagement Branch ip 20703 286 24% Fiche 50-283/83/10/05.
 - 10110180 Forwards public version of revised emergency plan implementing procedures including Procedures A 2-001 resembly emergency organization. A 2-204 resembly organization of 2-304 results prophylaxis
 FEY.F.L. Northern States Power Co. 83/09/13 Region 3. Defice of Director ip 20700-287 24X Fiche 50-263.83/10/05, 8310110176
 - iOlio184 Public version of revised emergency plan implementing procedures, including Procedures A 2-001 re emergency organization A 2-204 re offsits protective action recommendations & A 2-304 re thyroid prophylazis MATHIAU, C Northern States Power Co 83/09/01 58pp 20703 28B 24X Fiche 50-263.83/10/05.83iOtiO176
 - 0120269 Ack receipt of 830614.17 & 0720 ltrs forwarding changes to ev 6 to corporate emergency plan & Rev 3 to plant emergency an Changes acceptable.per 10CFR50 54(q) requirements ERIELLO, C J Region 3, Office of Director 83/10/06 80N.C E Northern States Power Co 1p 20690 348 24X hs.50-000.83/10/06.8310120269
 - 50538 Forwards finel SALP 4 Rept 50-263/83-17 for Jul 1982 June 3 PLER, J G Region 3. Office of Director 83/10/20. LARBON, C E thern States Power Co. 2pp. 20902 143 24X he 50-000, 83/10/20, 8310250538

- --9310250542 Final SALP 4 Rept 50-263/83-17 for Jul 1987 June 1997 * Region 3. Office of Director 83/10/20 27pp 2090; 145 P4s Fiche 50-000, 83/10/20, 8310250938
- --8310250550 Forwards summary of significant findings in SALP Mept 50-263/83-17 for Jul 1982 June 1983 to be discussed at 830921 meeting HIND, J.A. Division of Radiological & Materials Safety Programs 83/09/14 CILBERTS, D.E. Northern States Power Co. Jpp 20902 172 24% Fiche 50-000,83/10/20,8310250538
- 8310260431 Releases public version of revised emergency plan implementing procedures
 FELTON, J.M. Division of Rules and Records 83/10/21 Boccursist
 Management Branch ip 20926-253 24X Fiche 50-263,8 1/10/.*1.
 8310260431
- --8310260435 Forwards public version of revised Emergency Plan
 Implementing Procedures A 2-101 re classification of
 emergencies A 2-105 re general emergency & A 2-702 re
 response to emergency at Prairie Island
 FEY.F.L. Northern States Power Co. 83/10/17 Region A. 8310260431
 8310260431
- --8310260438 Public version of revised Emergency Plan Implementing Procedures A 2-101 re classification of emergencies A 2-104 re general emergency & A 2-702 re response to emergency at Prairie Island

 e Northern States Power Co 83/09/28 70pp 207/6 209 244 Fiche 50-263.83/10/21.8310260431
- H General correspondence
- 8310120432 Informs of DE Nevinski promotion to plant superintgudent, engineering & radiation protection Tech Spec Figure 6.1.2 will be revised MUSCLE.D Northern States Power Co. 83/10/04 Office of Muscles Reactor Regulation, Director ip 20698-277 24X Fiche 50-263.83/10/04.8310120432
- J Insurance & indemnity information
- 8310250237 Forwards Endorsements 56 & 57 to MAELU Policy Mf % & Endorsements 68 & 69 to NELIA Policy NF-174 for Monticello & Endorsements 48 & 49 to MAELU Policy MF-68 & Endorsements 56 & 57 to NELIA Policy NF-197 for Problem Island JOHNSON, R G Northern States Power Co 83/10/20 UNITA. # Division of Engineering 9pp 20899 036 24X Fiche 50 (APL). 83/10/20, 8310250239
- P Operating license stage documents & correspondence
- 8310040572 Forwards responses to 830728 request for addition requirator resolve open items in Franklin Research Ctr technical evaluation rept on control of heavy loads Info on Sections 2a & 2b no turbine bidg crame to be submitted by 8,31094 MUSOLFIO Northern States Power Co 83709727 Office of Figure Reactor Regulation, Director Spp 20622 270 ,4X Fiche 50-263.83/09/27.8310040572
- 8310050385 Forwards request for add1 info needed to review 62124.03 request to allow min source range monitor channel count to drop below three counts per second when entire reactor core removed or replaced Info due within 30 days
 VASSALLO, D. B. Operating Reactors Branch 2 83/09/27 Million Fig. 11 Million Fig. 12 Million Fig. 12 Million Fig. 13 Million Fig. 13 Million Fig. 14 Million Fig. 14 Million Fig. 14 Million Fig. 15 Million Fig. 15 Million Fig. 15 Million Fig. 16 Million Fig. 16 Million Fig. 16 Million Fig. 17 Million Fig. 18 Mi
- 8310060216 Submits info on single loop operation issues identified during NRC review of 820702 Tech Spot change request, per NRC/LLL 830926 telcon Multiple setpoints will not be used MUSCLF, D. Northern States Power Co. 83/09/29 Office of Pintie Regulation, Director 2pp. 20647-025 24X Fiche 50-263,83/09/29.8310060216
- 8310070311 Forwards Rev i to request for amond to License IP'R Language setpoint proposed for shutdown cooling isolation logic & revising wording proposed for jet pump surveillance MUSDLF.D Northern States Power Co 83/09/29 Office of Mustly Reactor Regulation, Director ip 20652 193 24X Fiche 50-263,83/09/29.8310070311
- --8310070314 Rev 1 to application for amend to License DPR For them; setpoint proposed for shutdown cooling isolation logic & revising wording for jet pump surveillance * Northern States Power Co 83/09/29 3pp 20652 174 445, Fiche 50-263.83/09/29,83100/0311

- --83100/0316 Proposed Tech Specr changing setpoint for shutdown cooling isolation logic & revising wording for jet pump surveillance

 Northern States Power Co 83/09/29 6pp 20652 197 24X Fiche 80-26383/09/29 83100/0311
- D31024014D Forwards notice of consideration of issuance of amend to License DMR-22 & opportunity for prior hearing re 820702 application changing lech bases to allow operation whone recirculation loop out of svc NICOLARAS, N. Operating Reactors Branch 2 83/10/05 MUSDLE, D.M. Northern States Power Co. 2pp. 20884-334 24X
 Fiche 30-263, 83/10/05, 8310240147
- B310240152 Notice of consideration of issuance of amend to License DPR-22-revising Tech Specs to incorporate revised safety & operating limits associated w/operation w/one recirculation loop out of ave vASSALLO, D.B. Operating Reactors Branch 2 83/10/05 5pp 20804 334 24X Fishe 50-263.83/10/05.8310240147
- O Inspection reports. IE Bulletins & correspondence
- SHOB300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN.L. Division of Emergency Proparedness & Engineering Assponse (Post 8J0103) 83/09/26 Consolidated Edison Co. of New York, Inc. 11/pp. 20754-022 24X Fiche 50-000.83/09/26.8308300J40
- ODOR 300342 IE Info Notice B3-62, "failure of Redundant Toxic Gas Betector's Positioned at Control Room Ventilation Air Intakes" Svc list encl JURDAN, E. L. Divinion of Emergency Preparedness & Engineering Response (Post B30103) B3709/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000, B3709/26, B30B300342
- B308300345 IC Info Notice B3-63, "Potential Failures of Westinghouse Type SA 1 Differential Relays " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 (onsolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fishe 50-000.83/09/26.8308300345
- 030B300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Syx W/o 10CFR50 59 Evaluation " 5vc list encl JORDAN.C t Division of Emerdency Preparedness & Engineering Response (Post 830103) 83709/29 Consolidated Edison Co. of New York. Inc. 115pp 20716-324 P4X Fithe 50-000.83709/29.8308300349
- 0310170476 Forwards IE Insp Rept 50-263/83-16 on 830802 0901 No noncompliance noted
 SHAFER. U D Region J. Office of Director 83/09/29 LARSON, C E
 Northern States Power Co 2pp 20/84 24/ 24X
 Fiche 50-263.83/09/29.8310170476
- --Balol70400 IC Insp Rept 50-263/83-16 on 830802-0701 No nancumpliance noted Major areas inspected operational safety verification, onsite review committee.degraded voltage relay, traversing in-core probe sys squib valve firing & Part 21 rept BROWN.C H. WALKER D. Region 3. Diffice of Director 03/09/21 App. 20784-249 24X Fiche 50-263/83/09/29/8310170476
- 8300.100370 IE Info Notice 83-65. "Surveillance of Flow in RTb Agrass Loops Used in Meetinghouse Plants" Svc list encl JHEDAN. C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 74pp. 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical facility" Svc list encil
 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 93/10/07 Consolidated Edison Co of New York. Inc. 79pp. 20882 026 24X Fichs 50-000.83/10/07.8308300752
- B300000759 IE Info Notice B3-67, "Emergency Use Respirator Hatl Dufect Causes Production of Notious Gases" Suctified encl. JOBDAN, C. Division of Emergency Preparedness & Engineering Response (Fost B30103) B3710711 Consolidated Edison Co. of New Yorl, Inc. 11/pp. 21043 075 24X Fiche 50-000, 83/10711, B308000757
- 0300300761 1E info Notice 83 68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders encl
 JORDAN & U. Division of Emergency Preparedness & Engineering
 Hesponse (Post 830103) 83/10/11 (ombidated Edison Co. of New
 York - Int. 120pp 2082* 129 24X Fiche 50-000.87/10/11/8308/00/61

- 8310180288 Clarifies procedures for admitting NRC personnel to facilities Access list identifying authorized clearances encl Update will be provided every 6 months AXELSON.W L. Region 3 Office of Director 83/10/14 LARSON.C E Northern 5tates Power Co. 7pp. 20804-275 24X Fiche 50-263.83/10/14.8310180288
- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking MIRAGLIA,F J Assistant Director for Safety Assessment 83/10/14 EISEMHUT, D G Division of Licensing 5pp 20823 358 24X Fiche 50-000,83/10/14.8310180551
- 8310250538 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 June 1983 KEPPLER, J G Region 3, Office of Director 83/10/20 LARSON, C E Northern States Power Co 2pp 20902 143 24X Fiche 50-000, 83/10/20, 83/0250538
- --8310250542 Final SALP 4 Rept 50-263/83-17 for Jul 1982 June 1983 * Region 3, Office of Director 83/10/20 27pp 20902 145 24X Fiche 50-000,83/10/20,8310250538
- --8310290550 Forwards summary of significant findings re SALP Rept 30-263/83-17 for Jul 1982 June 1983 to be discussed at 830921 meeting HIND.J A Division of Radiological & Materials Safety Programs 83/09/14 GILBERTS.D E Northern States Power Co 3pp 20902 172 24X Fiche 50-000,83/10/20.8310250538
- -B3}0250561 Submits comments on B30921 meeting w/NRC to discuss SALP Rept 50-263/83-17 for Jul 1782 June 1783 Valuable insights gained on improving performance GILBERTS,D E Northern States Power Co B3/09/30 KEPPLER,J Q Region 3, Office of Director Ip 20902 175 24X Fiche 50-000, B3/10/20, B310250538
- R Periodic operating reports & related correspondence
- B310190021 Monthly operating rept for Aug 1983 W/830908 ltr MYRABO,A L . MUSDLF.D Northern States Power Co B3709701 Office of Resource Management. Director 5pp 20823 135 Fiche 50-263.83709701.8310190021
- S. Reportable occurrences, LEAs & related correspondence
- 8310270340 FOIA request for placement of listed LERs in PDR GRABER, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 058 24X Fithe 50-000.83/09/08.8310270340
- B310070272 Forwards outline of proposed procedure for reanalysis of adequacy of station electric distribution sys voltages. 45 discussed at 830913 meeting w/NRC re B30801 actuation of degraded voltage protection logic MUSOLF, D. Northern States Power Co. 83/09/26 Dffice of Nucle Reactor Regulation. Director 4pp. 20656-353 24X Fiche 50-263 83/09/26 B3100702/2 Diffice of Nuclear
- 8310270347 Responds to FOIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received FELTON. J M Division of Rules and Records 83/09/29 GRADER. L D NUS Corp 1p 20938 060 24X Fiche 50-000.83/09/29.8310270347
- --B310270359 LER B3-002/03L-O on B30109 power loss in RCIC governor control sys occurred Caused by failed Pacific Electric 70-watt resistor Resistor replaced w/imploved design W/B30208 Titr TOLLERSON, J. L. MUSOLF D. Northern States Power Co Region 3, Office of Director 3pg 20938 045 24X Fiche 50-000, 83/09/29, 83102/034/
- --B310270364 LER B3-003/03L-0 on B30207.RHR loop B made inoperable due i unmaintainable RHR 12 HX differential pressure Caused by piston ring wear Graphite rings replaced w/spring loaded Teflon rings W/B30309 ltr CARPENTER G L . HUSOLF, D Northern States Power Co. 83/03/09 Region 3. Office of Director 3pp. 20938 068 14X Fichs 50-000.83/09/29.8310270347
- --8310270390 LER 83-007/03L-0 on 8304l) essential motor control ctr 133 feeder breaker tripped Caused by drifted right phase overcurrent trip device Device replaced & breaker reclosed & replaced WH30511 ltr HUSULF.D Northern States Power Co 8J/05/11 Region 3. Office of Director Jpp 20938 0/4 24X Fiche 50-000,83/09/29,8310270347 8310270347

- --8310270410 LER 83-008/03L-0 on 830413, leak in feedwater heater extraction steam trip outlet pipe 15A found Caused by steam erosion Leaking pipe section replaced & erosion program will be accelerated to amended W/830516 ltr MATER.P. MUSDLF, D. Northern States Power Co. 83/05/13 Region 3. Office of Director 3pp. 20938 077 24X Fiche 50-000. 63/09/29,8310270347
- ~-8310270414 LER 83-009/01T-O on B30504.NPC1 Hoodward Governor EGR hydraulic actuator coil discovered grounded Caused by faulty wire lead insulation Emergency generator reactor & HPCI lube oil replaced Sample being analyted W/830518 ltr WD/MHOUSKI.A V. MUSOLF.D Northern States Fouer Co B3/05/18 Region 3, Office of Director Spp 20938 080 24X Fichs 50-000.83/09/29.8310270347
- B3102:0257 Forwards detailed followup rept re Number 14 bus transfer to emergency diesel generator on undervoltage on 830801.per 830831 confirmatory action ltr Process computer alarm points reset to provide alarm at action point level MUSOLF, D. Northern States Power Co. 837:07/14 Office of Nuclear Reactor Regulation, Director 26pp. 20851-226 24X Fiche 50-263,837:107/14.8310210257
- 8310270283 LER 83-020/03L-0 on 830920 dirsel generator 11 turbocharger auxiliary lube oil pump motor bearing failed Cause not stated Pump-motor assembly replaced W/031019 ltr KDLB.H H . #USDLF.D Northern States Power Co 83/10/19 Region 3. Office of Birector 2pp 20923 259 24X Fishs 50-263.83/10/19.8310270283

V Operator Examinations

831007023B Requests extension to 840215 for implementation of livensed operator staffing requirements
MUSCLE.D Northern States Power Co 83/09/27 Office of Nuclear Reactor Regulation, Director Spp 20659 [19 24X
Fiche 50-263,03/09/29,8310070790

DOCKET 50-265 GUAD CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8310140261 Forwards 1E Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 & notice of violation HIND. J A Division of Radiological & Materials Safety Programs 83/09/29 REED. C Commonwealth Edition Co 2pp 20762 048 *4X Fiche 50-254.83/09/29.8310140261
- --8310140264 Notice of violation from insp on 830822-26 % 31 % 0409 HIND.J A Division of Radiological & Materials Safety Programs 83/09/28 2pp 20762 050 24X Fiche 50-254.83/09/29,8310140261
 - 8310140271 IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 Noncompliance noted failure to distribute controlled emergency plan procedure revs to NRC PHILLIPS, MP Region 3. Dffice of Director 83/09/29 17pp 20762 032 24X Fiche 50-254.83/09/29.8310140261
- GlockOSAL Releases public version of revised emergency plan implementing procedures FELTON, J h Division of Rules and Records 83/09/30 Document Hanagement Branch Lp 20662 001 24X Fiche 50-254,83/09/30, 8310060541
- 8310050545 Public version of revised emergency plan implementing procedures, including Procedures GEP 350-0 re emergency equipment & supplies & GEP 550-TA re emergency operations facility supplies KDVACK.T.J. GERNER.L. Commonwealth Edison Co. 83/09/08 300pp 20652 002 24X Fiche 50-754,83/09/30.8310050541
- 310110325 Releases public version of revised emergency plan implementing procedures FELTON, J M. Division of Rules and Records 83/10/05 Document Management Branch | p. 20685-231 PAX Fiche 50-254.83/10/05.8310110325
- 8310110327 Public version of revised Emergency Plan Implementing Procedures GEP 130-2 relaction director (whift director) & Procedure GEP 330-1 relimited notification TIET. 9 Commonwealth Edison Co. 83709708 24pp 20685 237 PAX Fishe 50-254.83730705,8310180375

10200079 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 93/10/14 Document Management Branch 1p 20844-218 24X Fiche 50-254.83/10/14 8310200079

- --B3102000B2 Public version of Rev 2 to Emergency Plan Implementing Procedure GEP 450-1, "Environ Surveillance Stations" KOVACK,T.J., CARSON.R (componwealth Edison Co. 83/09/28 App 20844 219 247 Fiche 50-254,81/10/14 B310200079
- 8310270024 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Ruler and Records 83/10/21 Document Management Branch ip 20940 199 24X Fiche 50-254.83/10/21, 8310270024
- --8310270028 Forwards public version of revised emergency plan implementing procedures, including Procedures GEP 550-1 refirst aid & decontamination Facilities & GEP 550-11 reenviron sampling supplies
 FIET7.0 GERNER.L. Commonwealth Edison Co. 83/10/06 NKC. N. Detailed Affiliation Given 2pp 20/40 200 24X
 Fiche 50-254.83/10/21.83102/0024
- --8310270032 Public version of revised emergency plan implementing procedures, including Procedures GEP 550-1 re first aid & decontamination facilities, GLP 550-2 re emergency equipment inventory & GEP 550-1; re environ tampling supplies a Commonwealth Edison Co. 83/10/04. 24pp. 20940 002. 24x Fiche 50-254,83/10/21,8310270024
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON J M Division of Rules and Records 83/10/21 Document Management Branch ip 2093/ 216 24% Fiche 50-000.83/10/21. 8310270526
- --8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOJ-6, "Administration & Logistics Manager" W/83101/ Itr & receipt form NELLIS.C A Commonwealth Edison Co 83/02/18 DENFON.H R 1.5C No Detailed Affiliation Given 7pp 2093/ 217 24X Fiche 50 000.83/10/21.8310270526
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch ip 20963 126 24X Fiche 50-000.83/10/25.
- ~-8310280314 Public version of revised generating stations emergency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 83/08/11 DENIGN, H.N. Office of Nuclear Reactor Regulation. Director 64pp 20963 127 24% Fiche 50-000.83/10/25.8310200307
- 8310280191 Releases public version of revised emergency planting procedure
 FECTON J M Division of Rules and Records 83/10/26 Document
 Management Branch ip 20962 266 24X Fiche 50-000,83/10/26,
 8310280191
- --8310280209 Public version of Rev I to Lmergency Plan Implementing Procedure EOF-15. "Emergency Operations Facility Activation" MODRER D. Commonwealth Edison Co. 83/08/02. 50pp. 20962 267 24X Fichs 50-000-83/10/26,8310280191

G Adjudicatory correspondence

- 8310120A09 Forwards list of welds not inspected for intergranular stress corresson cracking during current outage per Section III C 2 of 830826 shutdown order Technical justification also encl RYBAK.8 Commonwealth Edison Co 83/09/30 DENTON.H R Uffice of Recular Reactor Regulation, Director 5pp 20699 076 24X Fiche 50-265.83/09/30.8310120407
- P Operating license stage documents & correspondence
- 8310200273 Forwards schedules for equipment qualification test program for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target dates". It not as firm dates BARNES.P L Commonwealth Editon Co. 83/10/05 KEPPLER.J (; Regin D. Office of Director. 10pp. 20830 0.14 24X Fiche LO-DDO.83/10/083102002/7
- 0310170545 Provides add1 info to NUREQ-0/J7. Item 11 K 3 22, justifying use of HPC1 logic for RC1C suction switchover RC1C sys not safety-related & is not intended as backup for HPC1 sys RYBAK.8 Commonwealth Editor Co. 8J/10/07 DENION.H H. Office o Nuclear Reactor Regulation. Director 1p 20784-320 24X Fichs 50-254.83/10/07 8310170545

- E31C31C054 Advises that pipe stresses & support loads due to dead weight of water in pipe concurrent thermal effects & effects of postulated earthquake within design allowables reviewed, per NUKEG-073, Item II D i RYBAK. B Communwealth Edison Co 83/10/20 DENION, H R Office of Nuclear Heactor Regulation, Director & pp 20751 146 247 Fiche 50-254,83/10/20.8310310054
- 8310250273 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Guad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood.consisting of Chapters / 2 & 8 0 BENNETI.C J Commonwealth Edison Co 93/10/21 CASE.E Q Office of Nuclear Reactor Regulation, Director 1p 20894 259 24X Fiche 50-000,83/10/21.8310250293
- --8310250298 Rev 10 to Offsite Dose Calculation Manual for LaSaile & Guad Cities * Communumealth Edison Co 83/09/30 44pp 20894 260 24X Fiche 50-000,83/10/21,8310250293
- O Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Syc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Ficha 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Gyc list encl JORDAN,F L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- B30B300345 IE Info Notice B3-63, "Petential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past B30103) B3/09/26 Consolidated Edison to of New York Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,830B300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enc! JORNAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison to of New York, Inc. 115pp 20716-324 24X Fishe 50-000.83/09/29.8308300349
- 8310140261 Forwards IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 & notice of violation HIND. J A Division of Radiological & Materials Safety Programs 83/09/29 REED.C Commonwealth Edison Co 2pp 20762 048 24X Fithe 50-254,83/09/29,8310140241
- ---8310140264 Notice of violation from insp on 830822-26 & 31 & 0909 HIND: J A Division of Radiological & Materials Safety Programs 83/09/28 2pp 20762 050 24X Fiche 50-254,83/09/29,8310140261
- --8310140271 IE Insp Repts 50-254/83-26 & 50-265/83-25 on 830822-26 & 31 & 0909 Noncompliance noted failure to distribute controlled emergency plan procedure revs to NRC PHILLIPS, N P. PLOSKI, T.J., PAPERIELLO, C.J. Region 3. Office of Director 83/09/29 17pp 20762 052 24X Fichs 50-254,83/09/29,8310140261
- 8316120407 Forwards list of welds not inspected for intergranular stress corrosion cracking during current outage par Section III C 2 of 830826 shutdown order Technical justification also encl RYBAK.B Commonwealth Edison Co 83/09/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 5pp 20679 036 24X Fiche 50-265, 83/09/30, 8310120409
- 8310120051 Responds to IE Bulletin 83-03 re diesel generator cooling water pump discharge check valve Valve found to operate normally BARNES,P L Commonwealth Edison Co 83/10/04 KEPPLER,J G Region 3. Office of Director 2pp 20697 174 24X Fiche 50-265,83/10/04,8310120061
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18.50-237/83-27, 50-249/83-25, 50-294/83-27, 50-265/83-26.50-295/83-19, 50-304/83-26.50-237/83-39.50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13 NGRELIUE, C E Division of Project & Resident Programs 83/10/04 REED.C Commonwealth Edison to 2pp 20834 098 24% Fiche 50 000, 83/10/04, 8310200124

- --B310200148 IE Mgt Meeting Repts 50-020/83-18,50-237/83-27,50-249/83-25, 50-254/83-27,50-265/83-26,50-275/83-19,50-304/83-20, 50-373/83-38,50-374/83-38,50-455/83-44,50-455/83-33, 50-456/83-14 & 50-457/83-13 NORELIUS, C E Division of Project & Resident Programs B3/10/03 4pp 20834 100 24X Fiche 50-000,83/10/04,8310200124
- 8310170337 Submits status of as-built reviews of safe shutdown piping supports for IE Bulletin 79-14 As result of review of Guad Cities, two piping sys found to have addl discrepancies Saven new hangers added RYBAK. B Commonwealth Edison Co 83/10/06 KEPPLER, J G Region 3, Office of Director 2pp 20786 195 24% Fiche 50-000.83/10/06, 0210/233
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Syc list encl JURDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " 8vc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mat1 Defect Causes Production of Noxiqus Gases" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consultdated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche \$0-000,03/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Int. 120pp 20827 129 24X Fiche 50-000,83/10/11.8308300761
- B31018023B Clarifies procedures for admitting NRC personnel to facilities Access lists identifying authorized clearances encl Update will be provided every 6 months AXELSON.W L. Region 3. Office of Director B3/10/14 REED,C Commonwealth Edison Co. 7pp. 2080B 234 24X Fiche 50-254,83/10/14,8310180258
- 8310250605 Forwards IE Insp Repts 50-254/83-25 & 50-26/83-24 on 830802-0930 No noncompliance noted 8HAFER.W D Region 3. Office of Director 83/10/18 REED.C Commonwealth Edison Co 2pp 20900 2/4 24X Fiche 50-254.83/10/18.8310250605
- --B310250413 1E Insp Repts 50-254/83-25 & 50-245/83-24 on B30802-0930 No noncompliance noted Major areas inspected design changes & mods, organization & administration, procedures, onsite review committee, operational safety & maint CHRISSOTIMOS, N., MORRONOIELLO, A., WALKER, R. D., Region 3, Office of Director B3/10/18 7pp 20900 278 24X Fiche 50-254.83/10/18, B310250405
- 8310270435 Ack receipt of 830825 itr re-schedule for implementation of multiple peak resolution & peak reclassification enhancements to AAIS per 1E Insp Repts 50-254/82-13 & 50-265/82-15 PAPERIELLO, C J Region 3, Office of Director 83/10/25 RYBAK, B Commonwealth Edison Co 1p 20923 057 24X Fiche 50-254.83/10/25, 8310270435
- R Periodic operating reports & related correspondence
- 8310170353 Forwards listing of changes, tests & experiments completed during Sept 1983 Summary of safety evaluation reported per 100FR80 59

 KALIVIANAKIS.N Commonwealth Edison Co 83/10/03 CASE.E Q Office of Nuclear Reactor Regulation. Director 6pp 20786 165 24X Fiche 50-254,83/10/03.8310170393
- 8310180263 Monthly operating repts for Sept 1983 W/831003 ltr M18AK.A L., KALIVIANAKIS,N Commonwealth Edison Co. 83/10/03 Director's Office, Office of Inspection and Enforcement 26pp 20807 052 24X Fiche 50~254,83/10/03,8310180263
- S Reportable occurrences: LERs & related correspondence
- 8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A.responsive to Items 1.2 & 4 DDE should be contacted for matl requested in Item 3 of ltr FELTON.J M Division of Rules and Records 83/06/14 HIATT.S L Dhio Citizens for Responsible Energy 3pp 20706 002 24% Fiche 50-000,83/06/14.8310110430

- --8310110478 Responds to 830413 ltr requesting info re use of foreign matts on valve seating surfaces Lubricants & cleoning solvents used on valve component surfaces per vendor recommendations & maint practices
 FARRAR.D L Commonwealth Edison Co 83/04/22 KEPPLER.J 9
 Region 3. Office of Director 4pp 20706 063 24X
 Fiche 30-000.83/06/14.8310110430
- 8310060249 LER 83-D14/O3L-O on 830906, while performing local leak rate test, 3IV 2-203-2A found leaking in excess of Tech Spectlimic Gause unknown Mork request written to identify cause & corrective action Suppl rept will be submitted WASO928 ltm EAQLE, J , KALIVIANAKIS, N Commonwealth Edison Co B3/09/28 KEPPLER, J Repton 3, Office of Director 2pp 20647 097 24% Fiche 50-265,83/09/28,8310060249
- 8310210016 LER 83-015/03L-0 on 830912 during refueling outage local leak rate testing measured combined leakage rate for penetrations & valves found excessive (ause unknown Repairs & corrective actions will be reported W/831007 ltm MENDENHALL,E , KALIVIAHAKIS,N Commonwealth Edison Co. 83/10/07 KEPPLER.J G Region 3, Office of Director 2pp 20858 263 24X Fiche 50-265,83/10/07,8310210016
- 8310210054 LER 83-016/03L-0 an B30912 temp switch TS-2-2370A tripped above Tech Spec limit & switches TS-2-2370D & TS-2-2371D failed in closed position Caused by setpoint frift & overheating Switches replaced W/83100/ itr LEAVERTON. W. KALIVIANAKIS, N. Commonwealth Edison Co. 83/10/07 KEPPLERN, W. KALIVIANAKIS, N. Commonwealth Edison Co. 83/10/07 Fights 50-265,83/10/07-8310210054
- B3i0170661 Telecopy RO on B3i011, during performance of ultrasonic insp of cleanup sys piping, crack indication discovered in heat affected ions of weld 128-527 of line 2-1202-6"A Further info to be provided within 14 days KALIVIANAKIS, N Commonwealth Edison Co 83/10/12 KEPPLER, J Region 3, Office of Director 1p 20/79 285 24X Fiche 50-265,83/10/12,8310170661
- 8310180446 PNO-III-83-096 on B31011 during routine inservice insp, small crack discovered on 4-inch piping in reactor water cleanup sys Crack nat in sys affected by NRC 030823 order or IE Bulletins 82-03 & 83-02 Situation being evaluated DANIELSON, D. MALKER, R. Region 3. Office of Director 89/10/13 ip R0801 343 24% Fiche 50-245,83/10/13,8310180446
- 8310270419 LER 83-017/03L-0 on 830924, during RCIC turbine area high temp switch calter GIS-28, temp switches T8 2-1350-13B, 16B & 14D tripped above Tech Spec limit Caused by setpoint drift Switches replaced M/831020 ltr
 TODD, P., KALIVIANAKIS, N. Commonwealth Edison Co 83/10/20
 KEPPLERJ, Region 3, Office of Director 3pp 20923 074 94X
 Fichs 50-265,83/10/20,8310270419
- DOCKET 50-266 POINT REACH NUCLEAR PLANT, UNIT &
 F Security, medical, emergency & fire protection plans
- 8310030141 Advises that 820715 & 0930 requests for NRC to concur w/ intent to move emergency support ctr & associated functions from Point Beach Energy Info Ctr to Milwaukee unacceptable, per NURE9-0737; Suppl 1 & Generic Ltr Br-33 EISENHUT.D Q Division of Licensing 83/09/14 BURGIEIN, S Wisconsin Electric Pawer Co App 20604 033 24% Fiche 50-266,83/09/14,8310030141
- 8310170087 Requests that alternate spent fuel routes approved by NRC B30914 ltr be revised to allow use of Interstate 90 Interstate recently approved for use by State of NY, pending consideration of insurance & Indemnification issues BANESE, F.L. Nuclear Assurance Corp. B3/09/21 HILLMAN.C. Division of 8afeguards 4pp. 20798 001 24X Fiche 50-266.B3/09/21, B310170087
- 8310060562 Forwards modified 830722 primary spent fuel route from West Valley,NY to Point Beach.WI SHERR.T 5 Meterial Transfer Safeguards Litensing Branch 83/09/27 DANESE,F 1. Nuclear Assurance Corp 10pp 20661 265 24X Ficha 50-266.83/09/27.8310060562
- 8310030407 Releases public version of revised emergency plan implementing procedures FELTON.JM Division of Rules and Records 83/09/28 Document Management Branch 1p 2060/036 24% Fithe 50-266.83/09/28.8310030609

- --8310030616 Forwards public version of revised emergency plan implementing procedures, including Procedures EP1P 1 3 reestimation of source term. LP1P 1 4 re radiological dese evaluation & LP1P 6 2 re plant evacuation FAY.C W. Hisconsin Electric Power Co. 83/09/19 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p. 20607-03/24X Fiche 50-266.83/09/28, B.110030409
- --8310030424 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 3 re estimation of source term.EPIP 1 4 re radiological dose evaluation & EPIP 6 2 re plant evacuation
 * Wisconsin Electric Power Co 83/09/09 241pp 20607 038
 * Fiche 50-266.83/09/28,8310030409
- 8310180052 Forwards sanitized version of B31003 modified alternate spent fuel route from West Valley, NY to Point Beach, Wi Remaining provisions of NRC 830914 ltr unchanged BHERR, TS Material Transfer Safeguards Licensing Branch 83/10/05 DANESE, FL Nuclear Assurance Corp 10pp 20824 282 24X Fiche 50-246, 83/10/05, 8310180052
- 8310210044 Responds to 830914 ltr denying concurrence w/util plans to move emergency support ctr from lws Creeks, MI to corporate headquarters in Miwaukee. approx 100 miles from facility Potential problems overstated by NRC 8URSTEIN, S Wisconsin Electric Power Co 83/10/14 EISENHUT, D & Division of Licensing 2pp 20855 315 24X Fiche 50-266, 83/10/14, 8310210044
- B310310370 Forwards rovs to modified amended security plan Rovs withheld (ref 10CFR73 21 & 2 740)
 BURSTEIN:5 Wisconsin Electric Power Co B3/10/24 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 1p 20961 111 24x
 Fiche 50-246.83/10/24,8310310370

G Adjubicatory correspondence

- 8310070156 Forwards Director's Decision 83-14 denying 830909 100782 206 petition re transport of spent nuclear fuel from West Valley DAVIS.J © Office of Nuclear Material Safety & Safeguards, Director 83/09/30 CELEBREZZE.A J Ohio. State of 2pp 20690 30H 24X Fiche \$0-000.83/09/30, 8310070154
- --8310070161 Forwards Director's Decision 83-14, denying 830824 10CFR2 206 petition re transport of spent nuclear fuel from West Valley DAVIS.J Q Dffice of Nuclear Material Safety & Safeguards. Director 83/09/30 RESNIKOFF, M Sierra Club 1p 20680 309 24% Fiche 50-000.03/09/30.0310070156
- --8310070167 Notice of issuance of Director's Decision 83-14 danying State of OM & Sierra Club 830707 & 0824 respectively. 100FR2 206 petitions re transport of spent nuclear fuel from West Valley DAVIS. J & Office of Nuclear Material Sofety & Safeguards Director 83/09/30 2pp 20480 310 24X Ficha 50-000.83/09/30,8310070156
- --83:0070171 Director's Decision 89-14 denying State of DH & Sierra Club 830907 & 0824 respectively, 106 R2 206 potitions is transport of spent nuclear fuel from West Valley Request for hearing & for preparation of EIS denied DAVIS.J 0 Defice of Nuclear Material Sofoty & Safeguards. Director 83/09/30 18pp 70680 317 24X Fiche 50-000.83/09/30,8310070156
- 8310060197 Order extending time until 831012 for Commission to act to review ALAB-719
 CHILK 9 J Office of the Secretary of the Commission 83/10/04
 Commissioners 1p 20647 104 24X Fiche 50-266:83/10/04,
 8310060197
- 9310110274 Informs that licensee will file response to Wisconsine Environ Decade, Inc. petition served on 630923 by 831017 Svc. list encl. GMURCHILL, B.W. Shaw. Pittmon. Potts & Trowbridge CHURCHILL, B.W. Wisconsin Electric Power Co. 63710707 CHILK, B.J. Diffico of the Secretary of the Commission App. 20666 200 24X Fiche 50-266, 83/10/07. 83101102/4
- B310170493 Answer in opposition to Misconsin Environ Decade 830/23 petition for review of ASLAB 830907 Decision ALAB-739, affirming ASLB 830204 authorization for issuance of license amend Issue not raised before ASLAB Certificate of Svr encl BACHMANN.R O Hearing Branch 1 83/10/11 Commissioners 1App 20784 123 24% Fiche 50-266,83/10/11,83/0170493

- 8310140250 Order extending time until 831019 for Commission to act to
 - 110140250 Urder extensing time solutions and Education P3/10/12 CHILK, S.J. Office of the Secretary of the Commission 83/10/12 Commissioners ip 20762 041 24X Fiche 50-266.83/10/12.
- 8310200102 Response apposing Wisconsin Environ Decade 830923 petition for review of ALAB-739 re-steam generator tubes repaired by sleeving Nexus between sleeving & tube failure shown
 - Certificate of Syr enci
 CHURCHILL,B W Wisconsin Electric Power Co CHURCHILL,B W Si
 Pittman, Potts & Troubridge 83/10/1/ Commissioners 1/Jpp
 20836 350 24% Fiche 50-266,83/10/17,8310200102
- 8310190091 Order extending time until 831101 for Commission to act to review Directol's Decision DD 83-13
 CHILKS J Office of the Secretary of the Commission 83/10/18
 Commissioners ip 20822 265 24X Fiche 50-266.83/10/18,
- 8310260241 Order extending time until 831123 for Commission to act to review ALAB-739
 CHICK.8 J Office of the Becretary of the Commission 83/10/24
 Commissioners ip 20909 266 24X Fiche 50-266.83/10/24.
 - H310240241
- 8310270297 Order extending time until 831128 for Commission to act to review Director's Decision DD-83-14, denying Sierra Club & State of DH requests CHILK, S.J. Office of the Secretary of the Commission 83/10/25 Commissioners ip 20923 195 24X Fiche 50-000.83/10/25.
 - A310270297

General correspondence

- 8310040623 Forwards rev to health physics organization chart for steam generator replacement project, per request FAY,C W Wisconsin Electric Power Co 83/09/28 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 1p 20625 348 24X Fiche 50-266,83/09/28,8310040623
- J Insurance & indomnity information
- 8310110187 Forwards Endorsement 59 to MAELU Policy MF-53 & Endorsement 72 to NELIA Policy NF-178
 DUNDAS, W J Wisconsin Electric Power Co 83/10/03 NRC No
 Detailed Affilation Given 3pp 20665 011 24X
 Fiche 50-266,83/10/03,8310110187
- P Operating license stage documents & correspondence
- 8310110530 "Assessment of Radiation Risks," util-medical dialogue
- gresented at 800922-23 Int] Inst of Safety & Health forum in Washington DC LAPP.R E International Institute of Safety & Health 52pp 20714 141 24X Fiche 50-000.80/09/23.8310110530
- 8310110904 Ack receipt of 830904 ltr withdrawing request for amends to Fach Space re operation at reduced thermal design flow Safety avaluation & 830408 ltr encl W/o encls MILLER, J R Operating Reactors Branch 3 83/09/20 FAY, C W Wisconsin Electric Power Co 2pp 20715 173 24X Fiche 50-246,83/09/20,8310110504
- B310070020 Ack receipt of B30824 ltr requesting Commission publish notice of pending license amend in FR re New York State Energy R&D Authority license for utils w/irradiated fuel storage facilities
 BAVIS, J 0 Office of Nuclear Material Safety & Safeguards, Director B3/09/22 RESNIKOFF, M Sierra Club tp 2047i 36i 24X
 Fiche 50-000, 83/09/22, 8310070020
- 8310270555 Forwards safety evaluation supporting design of reactor coolant vent sys per requirement of 10CFR50 44(c)(3)(iii) & NUREO-0737. Item II B 1 MILLER, J R Operating Reactors Branch 3 83/09/22 FAY. C W Wisconsin Electric Power Co 7pp 20444 003 24X Fiche 50-266,83/09/22,8310270555
- 8310040310 Forwards add1 info requested in 830810 teleon reliability Research Ctt 830617 draft technical evaluation rept on util response to Phase I of NUREG-0612, "Gentral of Heavy Loads at Nuclear Power Plants"

 FAY.C W Wisconsin Electric Power Co 83/09/28 MILLER, J R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 8pp 20413 096 24x Fiche 50-266,83/09/28.8310040310

- 8310070439 FINAL ENVIRDNMENTAL STATEMENT RELATED TO STEAM GENERATOR REPAIR AT THE POINT BEACH NUCLIAR PLANT.UNIT I Docket No. 50-266 (Hirconsin Electric Power Company) COLLBURNIT G Division of Licensing NUREO-1011 83/09/30 60p Available at NRC \$4 50 20672 299 24X Fiche 50-266 83/09/30. 9310070439
- 8310110446 Forwards FES (HUREG-1011) re repair of steam generators & notice of availability W/a entl HILLER, J R Operating Reactors Branch 3 83/09/30 PERRIN, S Environmental Protection Agency 2pp 20704 351 24X Fiche 50-266,83/09/30,8310110446
- 8310110457 Notice of availability of FES (NUREG-1011) re steam generator repair HILLER.J R Operating Reactors Branch 3 B3/09 20706 317 24X Fiche 50-266.83/09/30.8310110457
- 8310130033 Forwards Amend 75 to License DPR-24, safety evaluation & notice of issuance & availability Amend approves steam generator regair program & requires that repair operations be conducted in accordance w/licensee commitments HILLER, J. R. Dperating Reactors Branch 3 83/09/30 FAY, C. W. Hisconsin Electric Power Co. 4pp. 20776-255 24X Fiche 50-266,83/09/30,8310130033
- --8310130036 Amend 75 to License DPR-24, approving stram generator repair program & requiring that repair operations be conducted in accordance w/licensee commitments identified in approved steam generator repair rept 4td 820809 & revised 830301 MILLER, J. R. Operating Reactors Branch 3 83/09/30 2pp 20776 259 24X Fiche 50-266,83/09/30,8310130033
- --8310130040 Safety evaluation supporting Amend 75 to License DPR-24 * NRC No Detailed Affiliation Given 83/09/30 58pp 20776 261 24% Fiche 50-266,83/09/30.8310130033
- --- B310130044 Notice of issuance & availability of Amend 75 to License MILLER, J. R. Operating Reactors Branch 3 B3/07/30 3pp 20776 319 24X Fiche 50-266,83/09/30,8310130033
- 8310130052 Forwards Amends 74 & 79 to Licenses DPR-24 & DPR-2/, respectively & safety evaluation Amends revise degraded grid voltage relay setpoint & associated time delay in Table 15 3 5-1 of Tech Specs COLBURN, T 9 Operating Reactors Branch 3 83/09/30 FAY, C W Misconsin Clettric Power Co 2pp 20776 220 24X Fichs 50-266.83/09/30,8310130052
- --8310130086 Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively, revising degraded grid voltage relay setpoint & associated time delay in Table 15 3 5-1 of Tech Specs MILLER, J R Operating Reactors Branch 3 83/09/30 App 20776 222 24X Fiche 50-266, 83/09/30, 8310130052
- --8310130062 Safety evaluation supporting Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation, Director 63/09/30 3pp 20776 228 24X Fishs 50-266, 63/09/30, 6310130052
- 8310170723 Forwards FES re-steam generator repair (NUREG-1011) W/o encl MILLER, J R Operating Reactors Branch 3 83/09/30 Wisconsin Electric Power Co 2pp 20798 096 24X Fichs 50-266,83/07/30,8310170723
- 8310240116 Forwards Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends revise Tech Specs to permit location of spent fucl pool neutron absorber surveillance specimen adjacent to divider wall COLBURN, T G Operating Reactors Branch 3 83/10/05 FAY, C & Wisconsin Electric Power Co 2pp 20891 338 24X Fiche 50-266,83/10/05,8310240116 83/10/05 FAY, CW
- --B310240122 Amends 77 & 81 to Licenses DPR-24 & DPR-27, respectively, revising Tech Specs to permit location of spent fuel pool nuetron absorber surveillance specimen adjacent to then fuel pool dividor wall MILLER, J.R. Operating Reactors Branch D. B3/10/17 7pp 20891 340 24% Fiche 50-246,83/10/05,8310240116
- --8310240125 Safety evaluation supporting Amends /7 & 81 to Licenses DPR-24 & DPR-27, respectively # Office of Nuclear Reactor Regulation, Director 83/10/05 3(20871 347 24X Fiche 50-246.83/10/05.8310240116

- 0130199 Forwards Amends 76 & 80 to Licenses DPR-24 & DPR-2/, espectively & safety evaluation Amend clarifies terminology and in limiting condition for operation & language rearrodic calibr interval requirement OLBURN-T G Operating Reactors Branch 3 83/10/06 FAY,C Wisconsin Electric Power Co 2pp 20/77 195 24% iche 50-266,83/10/06,8310130199
- 310130202 Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively, making administrative changes to Tech Specs to clarify terminology used in limiting condition for operation & language re periodic calibr interval requirement Hiller, J R Operating Reactors Branch 3 83/10/06 10pp 20777 197 24X Fiche 50-264,83/10/06.8310130199
- 010130205 Safety evaluation supporting Amenda 76 & 80 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation. Director 83/10/06 2pp 20777 207 24X Fiche 50-266.83/10/06.8310130199
- D180490 Application to amend Licenses DPR-24 & DPR-27 modifying ech Spec Change Request 33 reflecting changes in effluent onitoring instrumentation resulting from recently installed approved radiation monitoring sys

 V/C W Wisconsin Electric Power Co 83/10/07 DENION.H R

 Price of Nuclear Reactor Regulation. Director 3pp 20799 114

 IX Fiche 50-266.83/10/07.8310180490
- 010180492 Proposed rediclogical effluent Tech Specs reflecting mods to radiation monitoring sys * Wisconsin Flectric Power Co 83/09/30 47pp 20799 117 24X Fiche 80-246,83/10/07,8310180490
- 010180495 Rev O to "Offsite Dose Calculation Manual * Wisconsin Electric Power Co 83/09/30 65pp Fiche 50-266.83/10/07.8310180490 20799 164 24 X
- 20799 229 24 X
- 10180502 "Process Control Program " * Wisconsin Electric Power Co 83/09/30 218pp 20799 284 24X Fiche 50-266.83/10/07.8310180490
- 280098 Confirms arrangements for NRC site visit on 831101-03 to tain add1 info to complete evaluation of inservice testing ogram for pumps & valves LLER, J.R. Operating Reactors Branch 3 83/10/07 FAY, C.W. stonsin Electric Power Co. 2pp. 2096; 360 24% che 50-266,83/10/07.8310280098
- 130004 Discusses 831013 meeting to resolve deficiencies noted in anklin Research Ctr technical evaluation rept re environ alification of safety-related electrical equipment Agenda supporting documentation encl
 RETEIN.8 Hisconsin Electric Power Cp 83/10/10 DENTON.H R fice of Nuclear Reactor Regulation. Director MILLER.J R erating Reactors Branch 3 30pp 20726 207 24% che 50-266.83/10/10.8310130004
- 180421 Informs of proposed minor changes to commitments made in sponse to implementation instructions of NUREG-0578, report-term lessons learned Duty technical advisor quarters of the incorporated in boundary control ctr. P.C. W. Wisconsin Electric Power Co. 83/10/10 DENTON, H.R. Fice of Nuclear Reactor Regulation, Director 2pp. 20803 306 (Fiche 50-266,89/10/10,8310180421)
- 170079 Notification of 831013 meeting w/util in Bethesda.MD to scuss method for achieving final qualification of fety-related electrical equipment Final rept will be used based on meeting results
 BURN.T G Operating Reactors Brench 3 83/10/11 MILLEN.JR reating Reactors 3 89/10/11 MILLEN.JR catcors Brench 3 89/10/11 MILLEN GRENCH AND CATCORS BRENCH AND CATCORS BRE
- MO150 Requests to be removed from list of addresses for steam erator repair EIS NY.J Transportation. Dept of 83/10/11 MILLER.JR rating Reactors Branch 3 ip 20915 196 24x he 50-266.83/10/11.8310260150
- B0147 Forwards B30930 Director's Decision B3-14.denying State of & Sierra Club (OCFR2 206 petitions re transportation of nt fuel from Hest Valley facility, per B30930 request NINOHAM, R E Division of Fuel Cycle & Material Safety B3/10/19 LLER. F Environmental Policy Institute 2pp 20961 329 24X he 50-000,83/10/18,8310280147

- G. Inspection reports, IE Bulletins & correspondence
- 8308300340 IE lmfo Notice 83-61. "Alleged Use of Stand-las for Wilder Gualification Tests" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fishe 50-000,83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 114pp 20777 210 24X Fiche 50-000.83/09/26,8308J000342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN,C L Division of Emergency Preparadness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 Ooi 24X Fiche 50-000, 83/09/26, 83080345
- B310030447 Forwards list of Ray Miller products installed at facilities in response to IE Hulletin B3-07 Investigation of subtier suppliers in progress
 FAY.C W Wisconsin Electric Planer Co D3/09/26 KIPPLEK.
 Region 3, Office of Director 4pp 20601 038 24X
 Fiche 50-266.83/09/26.8310030447
- 83i0120089 Responds to 1E Info Notice 82-01 & IE Bulletin 83-07 to investigation of applicability of Ray Miller, Inc Praudulent practices Identified items have no adverse safety significance List of installed products encl FAV.C W Wisconsin Electric Power Co 83/09/26 KCPPLER. J G Region 3. Office of Director 4pp 20696 187 24X Fishe 50-266,83/09/26,83i0120089
- 8308300.149 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR5D 59 Evaluation " Svc 115t encl JORDAN.E & Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300347
- 8308300378 IE info Notice 83-65, "Surveillance of Flow in RTD Bypass Loaps Vsed in Westinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 74pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list enc) JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edition Co of New York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07.8308300/52
- 8308300759 lE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Notious Gases "Syc list encl JORBAN, El Bivision of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison to of New York. Inc 117pp 21043 075 24X Fiche 50-000.83/10/11,8308300759
- 8308300741 IE Info Notice 83-68. "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York. Inc. 120pp 20827 127 24X Fiche 50-000,83/10/11,8308:00761
- 8310180261 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be provided to Region III personnel listed in each Update will be provided every 6 months AXELSON,N L. Region 3, Office of Director 83/10/14 BURSIFIN,S Wisconsin Electric Power Co. 7pp. 20802 275 24X Fiche 50-246,83/10/14.8310180261
- 8310270294 Forwards IE Insp Repts 50-246/83-17 & 50-301/83-16 on 830808-0922 & notice of violation PAPERIELLO, C J Region 3, Office of Director 83/10/14 PURSTEIN S Wisconsin Electric Power Co 2pp 20923 196 Pdy Fiche 50-266
- --8310270303 Notice of violation from insp on 830808-0922 PAPERIELLD, C. J. Region 3. Office of Director 83/10 20923 198 24X Fiche 50-266.83/10/14.8310270294 83/10/13 lp
- ---8310270313 IE Insp Repts 50-266/83-i7 & 50-301/83-i6 on 830808-0922
 Noncompliance noted failure to perform appropriate contamination survey of radioactive matls shipment LOVENDALE, P.C., PAUL, R.A., ILAGUE, R.L. Region 3, Office of Director 83/10/12 8pp 20923 197 24X Fichs 50-266,83/10/14,8310270294

- 8310240042 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE liss Repts 50-266/83-19 & 50-301/83-13 Fuel handling truining must be completed by 831201
 - 831201 SHAFER, W.D. Region 3, Office of Director 83/10/18 BURSTEIN, S Wisconsin Electric Power to 1p 2088; 348 24X Fiche 50-266,83/10/18,8310240042
- --B310240051 Responds to NRC B30823 ltr re violations noted in IE Insp Repts 50-266/83-13 & 50-301/83-13 Corrective actions supervisor instructed on use of procedures & good engineering practices when operating refueling equipment CASSIDY. T. J. Wisconstn Electric Power Co. B3/09/22 KEPPLER, J. G. Region 3, Office of Director. 3pp. 20881 349 24X Fiche 50-266.83/10/18,8310240042

R Periodic operating reports & related correspondence

- B310180119 Monthly operating repts for Sept 1983 W/B31010 ltr FAY.C W Hisconsin Electric Power Co 83/10/05 NRC - No Detailed Affiliation Given 9pp 2080/ 175 24x Fiche 30-266.83/10/05.8310180119
- S Reportable occurrences. LERs & related correspondence
- 8310280079 Responds to FOIA request for AEOD rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Onofre 2." dtd 830429 & documents re fuel rod degradation problem described in 1E Info Notice 82-27 Forwards App A documents FELTON.J M Division of Rules and Records 83/07/28 HIATI.S (Ohio Citizens for Responsible Energy 2pp 20762 156 247 Fiche 50 000.03/07/28.8310280079
- --8310280168 LER 50-266/75-18 on /51217.during Cycle 3-4 refurling, discovered section of fuel rod missing Caused by water impingement through baffle plate while failed assembly in Cycle 2 pasition II-1 Investigation in progress W/751230 ltr BOBE.P E, BURBTEIN,S Wisconsin Electric Pawer Co 75/12/30 RUSCHE,B C Défice of Nuclear Reactor Regulation, Director 10p 20962 253 24X Fiche 50-000,83/07/28,8310280079
- --B310280171 LER 30-266/76-12 on 761222, wall cladding defects noted in one rod of fuel assembly GO7 Caused by rod vibrating against red rotatning grid springs Peening of core baffle plate joints, completed in Nov 19/6, should prevent recurrence GOBE. F E Wisconsin Clectic flower Co 77/01/04 3pp 20962 263 24X Firbe 50-000, B3/07/28, B310280079
- B310270380 LER B3-004/03L-0 on B30210, measured flow of 3,100 cfm for train B standby gas treatment did not meet min Tech Spec requirement of 3,150 cfm Caused by clogged demisters Demisters cleaned & procedure will be revised W/830311 ltr 1VERSON.0 , MUSDLF.D Northern States Power Co B3/03/11 Region 3, Office of Director 3pp 20/38 071 24X Fiche 30-000,83/09/29, 8310270347
- 8310050428 PND-III-B3-089 on 830929, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govts alleged inadequate preparation by local agencies. STRASMALJ, MENCZERLW Region 3, Office of Director 83/09/30 2pp 20641 221 24X Fiche 50-000.83/09/30.8310040428
- 8310070001 Potential Port 21 rept re underrange characteristic of Model N-C116M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End waers notified BERBERIAN.M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20681 064 24X Fiche 90-000.83/09/30.8310070301
- B310060264 PNO-III-83-071 on B31001,6-month outage commenced for refueling, routine maint & replacement of two steam generators Authorization to replace generators received on B30930

 JACKIN I. SHAFER, W. Region 3, Office of Director B3/10/03 ip 20645 265 24% Fiche 50-266. B3/10/03, B310060264
- 8310140295 PND-III-83-094 on 830930, contamination found on empty spent fuel cask shipped from facility Trailer used to transport empty spent fuel casks experienced brake problems on 831005 All shipments under insp LOVENDALE.P., GREGER.L R Region 3, Office of Director 83/10/06 2pp 20759-238 24X Fishe 30-266,83/10/06,8310140255

V. Operator Examinations

8310070303 Requests extension of effective date of compliance w/ 10CFR50 re licensed operator staffing to 871010 FAV.C W Wisconsin Electric Power Cg 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20651 071 24X Fiche 50-266,83/09/30,8310070303

- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- 8310030444 Forwards IE Insp Rept 50-247/83-13 on 830413-14 No noncompliance noted MADSEN G L. Region 4. Office of Director 83/08/08 LEE.U R Public Service Co of Colorado 2pp 20401 022 24X Fiche 50-247.83/08/08.8310030444
- --8310030457 IE Insp Rept 50-24//83-13 un 830613-16 No noncompliance noted Major areas inspected licensee performance & capabilities during elercise of emergency plans & procedures MONTODMERY, J. L., HACKNEY, C. A., WISE, R. Region 4, Diffice of Director 83/08/04 14pp 20601 024 24% Fiche 50-267,83/08/08,8310030446
- 8310180196 Informs that based on review of 830414 submittal, licensee forward command post (emergency operations facility) complies w/requirements of Table 1 to Suppl 1 of NUREG-0737 MADSEN.O L. Region 4. Office of Director 83/08/16 LEE.O R Public Service Co. of Colorado. ip 20808 341 24X Fiche 50-267,83/08/16.8310180196
- 8310040558 Forwards IE Insp Rept 50-267/83-20 on 830725-29 & notice of violation MADSEN,0 L Region 4, Office of Director 83/09/06 LCE,0 R Public Service Co. of Colorado 2pp 20625 344 24X Ficho 50-267.83/09/06.8310040558
- --8310040566 Notice of violation from insp on 830725-27 * Region 4. Office of Director 83/09/06 ip 20625 346 P4X Fiche 50-267,83/09/06,8310040558
- ~~8310040644 IE lnsp Rept 50-26//83-20 on B30725-29 Noncompliance noted failure to distribute security program audit to corporate mgt Details withheld (ref 10CFR73 21) EVANS.C A . KELLY.J . HUNNICUTT, D Region 4. Office of Director 83/09/01 19 20625 34/ 24X Fiche 50-267.83/09/06.8310040558
- B310040169 Responds to NRC 830B19 ltr re violations noted in IL inspon B30B01-05 Corrective actions Change Notice 1377 will be roissued to identify Door 66 as Class 1 & control room door holes filled BREY, N. L. Public Service Co of Colorado B3/09/19 MADSEN, Q. L. Region 4, Office of Director 4pp 2040B-214 24X Fichs 50-267, B3/09/19, B310040169
- 8310040276 Responds to NRC 830902 ltr re violations noted in IE Insp Rept 80-967/83-16 Corrective actions goard force personnel retrained WAREHBOURG, D.W. Public Service Co. of Colorado 83/09/20 COLLINS.J.T. Region 4, Office of Director 3pp 20613 008 24X Fiche 80-267,83/09/20,8310040276
- 8310130236 Responds to NRC 830906 ltr re violations noted in It Insp Rept 80-247/83-20 Corrective actions security program audit distribution matrix developed & utilized beginning 830408 & rev to Procedure G-18 effective 830624 GAHM.J W Public Service Co of Colorado 83/09/23 COLLINS.J T Region 4. Office of Director Jpp 20723,283 24X Fiche 50-267.63/09/23,83101302°26
- 8310110234 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch ip 20606-006 24% Fiche 50-267, 83/10/05, 8310110234
- --8310i10236 Forwards public version of revised emergency plan implementing procedures W/o encl WAREMBURRO,D W Public Service Co of Colorado 83/09/16 COLLINS.J T Region 4, Office of Director 3pp 20686 OOB 24X Ficha 50-267.83/10/05.8310110234
- 8310180385 Forwards list of new licentine actions, completed actions & action summary During Last Guarter FYRM, considerable time spent on Rev 1 to update FSAR & preparation of confirmatory order for NUREG-0/37 Items in Suppl 1 WAGNER, P C Region 4. Office of Director 83/10/06 MADSFN, C.L Region 4. Office of Director 6pp 20803 207 24X Fiche 50-267,83/10/06.8310180385

- Operating license stage documents & correspondence
- 310310384 Forwards Amend 35 to Litense IPR-34 & EIA Amend revises nonradiological ETS by substitution of environ protection plan WAGNER, P.C. Region 4, Defice of Director B3/08/10 LEE, D.9 Public Service Co. of Colorado. 2pp. 20959-328 24X Fiche 50-267, B3/08/10, B310310384
- -8310310388 Amend 35 to License DPR-34.revising nonradiological ETS by substitution of environ protection plan More restrictive scale for aerial photography incorporated MADSEN.G L. Region 4. Defrice of Director 83/08/10
- 310180212 Ack receipt of B30610 ltr transmitting current GA program per 10CFR50 85(f) Program being reviewed MADSEN, G L. Region 4, Office of Director B3/0B/15 LEE, D & Public Service Co of Colorado 1p 20808 316 24X Fiche: 50-267, 83/08/15, 8310180212
- 0310040325 Concurs w/NRC conclusion that lech Spec SK 5 I 1 sufficient to demonstrate control rod operability & NRC recommendation to revise second paragraph re control rod drop max temp monitoring Future license amend rev provided MAREMBOURG, D Public Service Co of Colorado 83/09/21 COLLINS, J T Region 4. 0#fice of Director 2pp 20620 216 PAX Fiche 50-267,83/09/21.8310040325
- 3310040407 Forwards comments & suggestions re rewording Rev | to delegation & assignment to Region IV of certain licensing functions Author does not concur in memo due to belief that authority & responsiveness of Region IV harmfully affected COLLINS.J T Region 4. Office of Director 83/09/22 CASC.E Office of Nuclear Reactor Regulation. Director Jpp 20619 054 24X Fiche 50-267.83/09/22.8310040407
- --8212130165 Delegates & assigns certain licensing functions for plant to region Specific delegations & assignments listed DIRCKS.W J Office of the Executive Director for Operations 82/12/03 COLLINS.J T Region 4. Office of Director 2pp 20619 057 24x Fiche 90-267.83/09/22.8310040407
- 0310040454 Forwards safety evaluation of NUREG-0737. Item II B 3.

 "Post-Accident Sampling Sys " Util meets six of II
 criteria Comments requested within 30 days W/o encl
 MADSEN, G L NRC No Detailed Affiliation Given 83/09/22
 LEE, O N Public Service Co of Colorado ip 20824 225 24
 Fiche 50-267.83/09/22.8310040456
- Biol30193 Forwards revised application for amend to License BPR-34, proposing supplemental changes to administrative controls Tech Spers re min shift crew composition & plant operations review committee, per Generic Ltrs 82-12.82-21 & 82-23 LEC.O R Public Service Co of Colorado 83/09/28 COLLINS, J T Region 4. Office of Director 3pp 20724 332 24X Fiche 50-267.83/09/28.8310130193
- --8310130200 Revised application for amend to License DPR-34.proposing supplemental changes to administrative controls Tech Spect re min shift crew composition requirements & plant operations review committee LEE.O R Public Service Co of Colorado 83/09/28 App 20724 335 24% Fiche 50-267.83/09/28-8310430193
- --8310130204 Proposed Changes to administrative controls Tech Specs we min shift crew composition requirements & plant operations review committee * Public Service Co of Colorado 83/07/28 27pp 20724 337 24X Fiche 50-267,83/07/28,8310130173
- 3310130260 Forwards application for amend to License DPR-34, changing radiological ETS to incorporate changes in nuclear facility safety committee responsibilities & requirements for effluent & environ monitoring LEE, 0. R Public Service Co of Colorado 83/07/28 COLLING. J T Region 4, Office of Director 3pp 20722 107. 24X Fiche: 50-267,83/09/28.8310130240
- -8310130324 Application for amend to License DPR-34, changing radiological ETS to incorporate changes in nuclear facility safety committee responsibilities & requirements for effluent & environ monitoring LEE, 0 R Fublic Service Co of Colorado 83/09/28 4pp 20722 110 24X Fiche 50-267,83/09/28,8310130260

- --8310130328 Proposed Tech Specs re environ monitoring program, radiological disposal sys & radiological monitoring program Significant hazards considerations analysis encl * Public Service Co. of Colorado. 85/09/28, 122pp. 20/22 114 24X Fiche 50-267,83/09/28,8310130260
- B310130272 Forwards application for amend to License DPK-34, authorizing receipt, possession & use of addl activity of Cs-13/ & Kr-85 for calibr of newly acquired portable radiation instrumentation inscrimmentation LEE,O R Public Service Co of Colorado 83/09/28 COLLINS,J I Region 4, Office of Director 2pp 20723-205 24X Fiche 50-267,83/09/28,83101302/2
- --8310330275 Application for amend to License DPR-34, authorizing lecript, possession & use of addl activity of Cs-13/ & Kr 85 for calibr of newly acquired portable radiation instrumentation LEE,O R Public Service Co of Colorado 83/09/28 5pp 20723 207 24X Fiche 50-267,83/09/28.8310130272
- --8310130279 Proposed Tech Specs re add1 activity of Cs-137 & Kr 05 for callbr of newly acquired portable radiation instrumentation Significant hazards considerations analysis encl * Public Service Co of Colorado 83/09/28
- 8310130281 Application for amend to Liceuse DPR-34, ensuring capability of primary RCS components to maintain primary reactor coolant envelope as fission product bairier LEE.O R Public Service Co of Colorado 83/09/28 COLLINS. J 1 Region 4. Office of Director 4pp 20723 147 24% Fiche 50-267,83/09/28.8310130281
- --8310130284 Proposed Tech Specs ensuring capability of primary RCS component to maintain primary reactor coolant envelope as fission product barrier * Public Service Co of Colorado 03/09/28 45pp 20/23 151 24X Fithe 50-267, 83/09/28, 0310130281
- 8310130300 Forwards application for amend to License DFR-3A, changing Tech Specs Sections 4 3 10 & 5 3 B to incorporate supplemental changes re snubber functional testing plons LEE, O R Public Service Co of Coloredo B3/09/28 COLLINS, J T Region 4. Office of Director 3pp 20719 153 24X Fiche 50-267,03/09/28.8310130300
- --0310130303 Application for amend to License DPR-34, changing Tech Specs Sections 4 3 10 & 5 3 8 to incorporate supplemental changes re snubber functional testing plans LEE, O R Public Service Co of Colorado 03/09/28 App 20719 156 24X Fiche 50-267,83/09/28,8310130300
- --B310130304 Proposed changes to Tech Spics Sections 4 3 10 % 5 8 8 to incorporate supplemental changes re snubber functional testing plans

 * Public Service Co of Colorada 83/09/28 44pp 20719 160 24X Fiche 50-267, 83/09/28, 8310130300
- B310210233 Notifies that submittal of addl info for N-451 graphite postponed to B31028,ppr NRC BJ0802 ltr Postponement due to unforeseen difficulties w/computer codes Analysis work, referred to in B30815 ltr.performed BREY.H L Public Service Co of Colorado B3/10/04 COLLINS.J 7 Region 4. Office of Director 2pp 20051 261 24X Fiche 50-267,83/10/04.8310210253
- 8310180385 Forwards list of now licensing actions, completed actions & action summary During Last Quarter FYU3.considerable time spent on Rev 1 to update FSAR & preparation of confirmatory order for NURLG-0737 items in Suppl 1 MAGNER.P C Region 4. Office of Director 83/10/06 MADSHN, G L Region 4. Office of Director App 20003 207 24X Fiche 50-267.83/10/06.8310180385
- 8310310433 Forwards Amend 36 to License DPR-34 & safety evaluation Amend revises administrative Tech Bpcts to incorporate various editorial & format corrections, per NUREO-0737, Item I A 1 3 MAGNER, P C Region 4. Office of Director 83/10/13 LCE, () R Public Service Co. of Colorado 2pp 20959 194 24X Fiche 80-267,83/10/13,8310310493
- --83;0310439 Amend 36 to License DPR-34, revising administrative Tech Specs to incorporate various editorial & format corrections, per NUREG-073/, Item I A 1 3 JOHNSON,E H Region 4, Office of Director 83/10/13 34µp 20959

- O Inspection reports, IE Bulletins & correspondence
- 8310030344 Forwards 1E Insp Rept 50-267/63 18 on 830601-30 & hotice of violation MADSEN G L Region 4, Office of Director 83/07/21 LEF, O R Public Service Co of Coloredo 2pp 20070 185 24x Fiche 50-267,83/07/21,8310030344
- --831003034/ Notice of violation from insp on 830401-30 # Region 4. Office of Director OJ/07/21 3pp 20590 187 249 Fiche 50-267.83/07/21.8310080344
- --8310030350 IE Insp Rept 50-267/83-18 on 830601-30 Noncompliance noted failure to follow procedures re equipment clearances & surveillance terting program DICKERBON M W. PLUNLEE, G L., HUNNICUTT, D M. Region 4, Office of Director 83/07/18 15pp 20590 170 24X Fiche 50-267,83/07/21,8310030344
- 8310030446 Ferwards IE Insp Rept 50-267/83-13 on 830612-16 No noncompliance noted MADSEN.G L Region 4. Office of Director 83/08/08 LEC.O ? Public Service Co of Colorado 2pp 20601 022 24X Fiche 50-267.03/08/08.8310030446
- --831003045/ IE Insp Rept 50-26//03-13 on 830613-16 No noncompliance noted Major areas inspected licensed performance & capabilities during exercise of emergency plans & procedured MONTOUNLEY.J. L. MACKNEY.C. A. WISE.R. Region 4, Office of Director 93/08/04 14pp 20601-074 24X Fiche 50-247.83/08/08.83100.304/6
- 8310040013 Forwards IE Insp Rept 90-267/83 1/ on 830621-24 & notice of violation MADSEN,0 L Region 4. Office of Director 83/08/22 LCE,0 R Public Service to of Colorado 2pp 20649-243 24X Fiche 90-267,83708/22,8310060013
- --8310060014 Notice of violation from incp on 630621-24
 * Region 4. Office of Director 63708/22 ip 20649 245 P4X
 Fiche 50-267.83708/22.8310860033
- --8310060015 IE Insp Rept 50-26//83-17 on 830621-24 Noncompliance noted failure to locate records of reactor bldg exhaust filter tests from previous insp HDLLEY, W.L. MURRAY, B., HUNNICUTT, D. Region 4, Office of Dijector 83/08/15 7pp 20649 246 24% Fille 80-267.83/08/22.8310060013
- 8310040580 Forwards IE Insp Rept 50~267/H3-22 on 830/01 31 & notice of violation MADSEN, G L. Region 4, Office of Director 83/08/24 LEE, () N Public Service Co. of Colorado 2pp 20/22 283 24X Fiche 50~247,83/08/24,8310040080
- --8310040583 Notice of violation from intp on 830701-31 * Region 4, Office of Director 83/08/24 Jpp 20622 285 24% Fiche 50-267,83/08/24,8310040580
- --8310040589 IE Insp Rept 50-267/83-28 on 830701-31 Noncompliance noted failure to follow procedures re safety practices for welding in Blevated alea, issuance of surveillance test deviation rept & entries in operator log PLUMLELS L., HUNNICUTT, D.M. Region 4, Office of Director 83708788 18pp 20822 288 24% Fishe 50-267,83708784.8310040580
- 8310040558 Forwards 1E Insp Rept 50-267/83~20 on 830725-29 & natice of violation MADSEN, C.L. Region 4. Office of Director 83/09/04 LEE.O R Public Service Co. of Colorado. 2pp. 20625-344 24% Fiche 50-267,83/09/06.8310040258
- --8310040566 Notice of Violation from into an 830725-27 * Region 4. Office of Director 83709706 ip 20625 346 24X Fiche 50-267.83709706.8310040556
- --B310040644 It Insp Rept 50-267/B3-20 on 830725-29 Nuncompliance noted failure to distribute security program audit to corporate mgt Details withheld (rof IOCFR73 21)
 EVANS,C A, KELLY,J, HUNNICUIT,D Region 4, Diffice of Director B3/09/01 1p 20625 347 24% Fishe 50-267,83/09/06,831004055B
- 8310040169 Responds to NRC 830819 ltr re violations noted in IE insp on 830801-05 Corrective actions Change Notice 1377 will be reissued to identify Door 66 as Class J & control icom door holes filled RRY.H L Public Service Co of Colorado 83/09/14 MADS N.G t Region 4, Office of Director 4pp 20608 214 24% Fiche 50-267.83/09/19.8310040169

- 8310040210 Responds to NRC 830824 ltr rd violations noted in 1E Insp. Rept 50-267/83-22 Corrective actions welder received documented verbal reprimand re failure to follow proper procedures for welding in elevated area.

 WAREHBOURG, D. W. Public Service to of Colorado 85/09/19 COLLINS, J. T. Regian 4, Office of Director 6pp 20615 001 24X Fiche 50-267, B3/09/19, 83L0040/10
- 8310130286 Responds to IE Bulletin 83-06. "Nonconforming Matls Supplied by Tube-Line Corp " Tube-Line Corp never supplied matl to util for use in safety-related sys BREY.H L Public Service Co of Colorado 83/09/19 WAGNI-R.P C Region 4. Office of Director Ip 20719 148 24% Fiche 50-247.63/09/19.8310130/94
- 8310040276 Responds to NRC 830902 ltr re violations noted in IE lusp Rept 50-267/83-16 Corrective actions quard force personnel retrained HAREMBOURG, D W Public Service Co of Colorado 83/09/20 COLLINS. J T Region 4. Office of Director 3pp 20613 088 24X Fiche 50-267.83/09/20.83100402/6
- 8310130236 Responds to NRC 830706 ltr re violations noted in IE Insp Rept 50-267/83-20 Corrective actions security program audit distribution matrix developed & utilized beginning 830408 & rev to Procedure G-18 effective 830824 GAMM.J W Public Service Co of Colorado 83/09/23 COLLINS, J T Region 4, Office of Director Jpp 20723 283 24X Fiche 50-267,83/09/23,8310130236
- 8308300340 IE Info Notice 83-6; "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN,E L Division of Emergency Preparedness & Ingineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fithe 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000.83/09/26.8308300342
- 8308300345 IE Info Notice 83-43: "Potential Failures of Hestinghouse Type 8A-1 Differential Relays " Byo list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fishe 50-000.83/09/26.8308300045
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related 8ys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 Consplidated Edison Co of New York, Inc. 115pp 20716 324 24% Fishe 50-000, 83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Leeps Used in Westinghouse Plants " Bvc list encl JDRDANL I Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 830B300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/10/07 Consolidated Edison Co. of Net York, Inc. 79pp 20882 026 24X Fiche 50-000, 83/10/07,8308300752
- 8310180180 Notification of 831012 significant licensee meeting in Arlington.TX to discuss potential enforcement action recutrof-svc diesel generator trailure to verify operability of backup diesel generator 8710/07 Region 4, Office of Director 8710/07 Region 4, Office of Director 1p 20808 342 24X Fiche 50-267.83/10/07.8310180180
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svt list entl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/11 Consolidated Edison Co. of New York, Inc. £17pp 21043 075 24X Fishe 50-000, B3/10/11 B30B300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 139 24X Fischs 50-000.83/10/11.8308200761

- 10310422 Confirms commitments from 831012 enforcement confeseign to diesel generator test requirements in Each Spec 4 6 1 Kevs to electrical portions will be submitted prior to end of next refueling outage COLLINS.V T Region 4. Office of Director 63/10/13 LEE.O R Public Service Co of Colorado 2pp 20759 184 24X Fiche 50-247,03/10/13,8310310422
- 10310274 Forwards Structural & Geotechnical Enginerizing Branch SER re IE Bulletin 80-11, 'Masonry Wall Design," bared on entl Franklin Research Ctr technical evaluation rept All masonry Walla, except 17 credited as structural elements, acceptable JOHNBON, E H. Region 4, Office of Director 83/10/18 LEE. D R Public Service Co of Colorado 2pp 20961 234 24X Fiche 50-267,83/10/18,8310310794
- 9310310302 SER re IE Bulletin 80-11, "Masonry Wall Design " Items 2(b) & 3 of bulletin acceptable, w/exception of 17 walls requiring uso of joint reinforcement " Structural & Geotochnical Engineering Branch 83/10/18 Ppp 20961 236 24% Fiche 50-267,83/10/18,8310310294
- 8309200506 "Masonry Wall Design,Fort St Vrain Nuclear Plant," technical evaluation rept
 LE.A K. CON.V N. Frinklin Institute/Franklin Research Cuntci
 NRC-03-81-130 TER-(5506-242 83/09/16 CHOKSHI,N C NRC No
 Detailed Affiliation Given Tipp 20961 238 24X
 Fiche 50-267.83/10/18.8310310794
- 8308310512 "Use of Joint Reinforcement in Block Masonry Walls," technical evaluation rept BEGIA, I J. Franklin Institute/Franklin Research Center HAMID.A A , HARRIS.H Q. Drezol Univ , Philadelphio, PA NRC-03-31-130 83/03/31 NRC No Detailed Affiliation Given 9pp 20961 269 24X Fiche 50-267,83/10/18,8310310274
- 10310298 Ack receipt of 830924 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-267/83-22 Reply responsive to NRC concerns JOHNSON, E.H. Region 4, Office of Director 83/10/18 LEE.O K Public Bervice Co. of Colorado. Ip 20961 134 24X Fiche 50-267.83/10/18.8310310298
- Periodic operating reports & related correspondence
- 10170260 Monthly Operating Rept 116 for Sept 1983 W/831012 ltr FULLER,C H , MAREMBOURG,D Public Bervice Co of Colorado 30/10/07 Director's Office, Office of Inspection and Enforcement 9pp 20707 09t 24X Fiche 50-267,83/10/07.8310170260
- Reportable occurrences. LERs & related correspondence
- 10040315 Forwards LERs 83-031/03L-0 & 83-032/03L-0 & updated LER 82-049/01X-1 Detailed summary encl ARRENBOURG, D Public Service Co of Colorado 83/09/16 COLLINS, J T Regaon 4, Office of Director 25pp 20620 140 24X Fiche 50-267.03/09/16.8310040315
- 3310040322 Updated LER 82-049/01X-1 on B21208, secondary-to-primary side leak discovered in loop 2 steam generator Cause unidentified but appears random in nature Tube ends plugged & capped NOVACHEK, F., HELLER, R. A., MCBRIDE, L. M. Fublic Bervice Co of Colorado B7/09/16 Region 4, Office of Director Spp 20620 165 24X Fiche 50-267, B3/09/16, 0310040315
- 3310040324 LER 83-031/03L-0 on B30818.one hydraulic snubber found inoperable Caused by leaking reservoir fittings allowing loss of oil Bnubber replaced w/rebuilt snubber FRYE, D. L. NDVACHEK, F. J. MCBRIDE-L. M. Public Service Co. of Colorado 83/09/16 Region 4, Office of Director 3pp 20620 170 24X Fiche 50-267.83/09/16.8310040315
- 3310040328 LER 83-032/03L-0 on 830817, motor driven boiler feed pump removed from syc to repair leaking water valve Caused by normal wear Valve, pipe & flange assembly prefabricated &
- normal bear valve-pipe & Flange assembly pre-positions in tailed NOVACHEK, F J. DICKERSON, R A. MCBRIDE, Ł M. Public Service Co. of Colorado 83/09/16 Region 4. Office of Director App. 20620 173 24% Fiche 50-267.83/09/16.8310040315
- OD40207 LER 83-033/03L-0 on 830827, gas waste vacuum tank rupture isc found ruptured Date of rupture undeterminable Cause not tated Disc disassembled, replaced & returned to svt W/83092A tr
 BUACHEK, F.J., WAREMBOURG, D., BANAGAS, L.J. Public Service Co. of olorado 83/09/26 COLLINS, J.T. Region 4. Office of Director pp. 20614-326 24X Fiche 50-267.83/09/26.8310040807

- B310180180 Notification of B31012 significant licensee meeting in Anlington, TX to discuss potential enforcement action to out-off-syc dissel generator & failure to verify operability of backup diesel generator ** Region 4, Office of Director 83/10/07 Region 4, Office of Director 1p 20808 342 24% Fiche 50-267,83/10/07,0310180186
- DOCKET 50-P69 DODNEE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8310070134 Releases public version of revised crisis mot plan implementing procedures FELTON, J N Division of Rules and Records 83/10/04 Dorum Management Branch lp 20670 001 24X Fiche 50~000,83/10/04, 8310070134
- --8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 1 1 Te recovery manager & immediate staff group plan & 5 % A ruscheduling/planning support group TUCKER.H B Duke fower Co. 83707/04 DENTON.R Office on Nuclear Reactor Regulation, Director 3pp 20670 002 .MX Fiche 50-000,83/10/04,8310070134
- --8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 I re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group • Duke Power Co 83/07/01 457pp 20670 005 24X Fiche 50-000, B3/10/04.83100/0194
- 8310110067 Releases public version of revised emergency plan implementing procedures
 FELTON, J. H. Division of Rules and Records 83/10/05 Docum
 Management Branch 1p 20/09 160 24X Fiche 50 269,83/10/05,
 831011006/ Document
- --83101100/6 Forwards public version of levised emergency plan implementing procedures, including Procedure CP/O/B/4003/01 re environ surveillance fellowing large unplanned release of gaseous radioactivity Receipt form encl TUCKER.H I. MCINTOSH.J T. Duke Power Co. 83/09/19 O/REILLY.J P. Region 2, Office of Director 2pp. 20/09 [6] P4X Fiche 50-269,83/10/05,831011006/
- -8310110080 Public version of revised emergency plan implementing procedures, including Procedure CP/D/8/4003/01 re environ surveillance following large unplanned release of gaseous Fiche 50-269.83/10/05.8310110067
- B310110135 Releases public version of rev to emergency procedure FELTON, J M Division of Rules and Records B3/10/05 Decembrangement Branch ip 2070/319 24X Fiche 50-269.03/10/09, 8310110135 Document
- --B310110141 Public version of Rev B3-5 to Emergency Procedure
 AP/D/B/1000/07, "Procedure for Offsite Dose Calculation by
 Control Room Personnel to Emergency (toerdinator During
 Radiological Accident " W/830B30 Itr
 SMITH, J E., TUCKER, H B., MCINTOSH, J F. Duke Power Co. 83/9//22
 O'REILLY, J P. Region 2. Office of Director 17pp 20707 370
 24X Fiche 50-249,83/10/05.8310110135
- 8310250354 Forwards IE Insp Repts 50-269/83-27.50-270/83-2/ & 30-287/83-27 on 830912-16 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/10/05 TUCKER.H B Dake Power Co 2pp 20'(98-123 24X Fiche 50-269.83/10/05.8310250354
- --8310230263 IE Insp Repts 50-269/83-27.50-270/83-27 & 50-287/82 27 on 830912-16 No noncompliance noted Major areas inspected amergency detection & classification, protective action decisionmaking, public info program & shift staffing DECKER, T.R. Rogion 2. Office of Director 83/09/30 5pp 20098 125 24x Fiche 50-269.03/10/05.8310250354
- 8310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation TUCKER.H B Duke Power Co 83/10/10 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 20802 191 24X Fiche 50-000,63/10/10.8310180444
- 8310250635 Informs that periodic evaluation of SALP complete Kept approved
 O'REILLY, J.P. Region 2. Office of Director 83/10/17 TUCKER.H B
 Duke Power Co 3pp 20900 205 24% Fiche 50-000.83/10/17.
 B310250635

- --8310250652 SALP Repts 50-269/63-17.50-270/83-17.50-287/83-17. 50-369/83-24.50-370/83-32.50-413/83-14 % 50-414/83-13 for June 1982 - Api 1983 ** Region 2. Office of Director B3/08/02 56pp 20900 211 24% Fichs 50-000-83/10/17.8310250635
- 8310280029 Forwards request for exemption from fire protection requirements of IOCFR50. App R. Section III J re emergency lighting an control room stairwells/corridors, outside auxiliary bldg & standby shutdown farility TOCKER. H B Duke Power Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branck 4 4pp 20934 285 24X Fishe 50-269, 83/10/24, 8310280029
- 8310280124 Suppls 830603 itr re exemption request from location requirements of emergency operations facility Significant benefits not achieved by near-site facility up to 20 miles from plant Meeting W/RRC requested TUCKER, H B Duke Power Cn B3/10/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 5TOL7, JF Operating Reactor Branch 4 2pp 20929 266 24X Fishe 50-269,83/10/25.8310280124
- P Operating license stage documents & correspondence
- B310040111 Responds to B30531 & 0824 ltrs requesting amend to B30316 confirmatory order re NUREO-0/J7. Item II F 1 5. "Containment Water Level Monitor" Amend not required invison qualification will be addressed in 1001650 49 audit STOLZ. J F Operating Reactors Branch 4 B3/09/02 TUCKER, H B Duke Power Co 5pp 20627 351 24X Fiche 50-269,83/09/02, B310040fil
- 8310040647 Forwards SER accepting Arkansas Power & Light Co (API) B30607 proposed mods to reactor trip breakers for DRW plants Requested info should be provided when APL generic design endorsed in response to Generic Lt 83-28 STOLZ.J F Operating Reactors Branch 4 83/09/12 TUCKER,H B Duke Pawer Co 2µp 20627 303 24X Fiche 50-269,83/09/12,0310040647
- D310110945 Forwards Amends 123,123, & 120 to Licenses DPR-38,DPR-47 & DPR-55, respectively, safety evaluation & EIA Amends allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool STOLZ, J F Operating Reactors Branch 4 83/09/29 10CKER, H R Duke Power Co 2pp 20711 265 24X Fiche 50-269,83/09/27,8310110545
- --8310110561 Amends 123.123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, changing Tech Specs to allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool STOLZ.J F Uperating Reactors Branch 4 83/09/29 11pp 20711 267 24% Fiche 50-269.03/09/29,8310110545
- --8310110567 Safety evaluation supporting Amends 123,123 & 120 to Licenses DPR-38,DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Directo; 83/09/29 14pp 2071 278 24X Fichs 50-269.03/09/29.8310110545
- --8310110575 EIA supporting Amends 123,123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively * OPFice of Nuclear Reactor Regulation, Director 83/09/27 10pp 2071 292 24X Fiche 30-247,83/09/29,8310110545
- 8310140143 Forwards proprietary "Rancho Beco Cycle 7 Relead Rept Vol 1 Mark BZ Fuel Assembly Design Rept," in support of Cycle 9 reload planned for latu 1984 Rept withheld (ref 10CFRZ 790)
 TUCKER, H B Duke Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director BTOLZ, J F Operating Reactors Branch 4 2pp 20766 067 P4X Fiche 50-000, 83/10/07,8310140143
- --B310140145 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept -Vol 1 Mark BZ Fuel Assembly Design Rept." Apr 1983
 Affidavit supporting determination of proprietary nature of
 rept encl
 TAYLOR, J H Babcock & Hilcox Co B3/09/15 MINER, 8 Office of
 Nuclear Reactor Regulation, Director Spp 20766 069 24X
 Fiche 50-000, B3/10/07, B310140143
- 8310140253 Forwards info re inservice pump & valve testing program W/o ent1
 TUCKER:H B Duke Power Co 83/10/10 DENTON:H R Office of Nuclear Reactor Regulation, Director 870LZ.J F Operating Reactors Branch 4 1p 20761 332 24X Fiche 50-269.83/10/10.8310140953
- 8310240151 Forwards steam generator operating history info valid through 821231 TUCKER.H B Duke Power Co 83/10/13 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactors Branch 4 44pp 20881

- 8310310489 Summary of 830826 meeting w/b&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATMS & proposed ATMS jule for P&W plants List of attendees & viewgraphs encl KADAMBI.P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20765 147 24% Fishe 50-000.83/10/20. 8310310489
- 8310280105 Forwards update of progress of control room habitability mods.per 830922 ltr re TMI Item III D J 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedulet ancl TUCKER.H B Duke Power Co 83/10/24 DENTON.H R Office of Nuclear Reactor Regulation. Director STOLZ.J F Operating Reactors Branch 4 2pp 20935 324 24X Fishe 50-269.83/10/24.8310280105
- Q Inspection reports, IE Bulletins & correspondence
- 8310040270 Forwards IE Insp Repts 50-269/83-24,50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/08/30 TUCKER, H B Duke Fower Ca 2pp 20617 268 24X Fiche 50-267,83/08/30,8310040270
- --9310040294 IE Insp Repts 50-269/83-24,50-270/83-24 & 50-287/83-24 on 830725-0803 No nancompliance noted Major areas inspected containment integrated leakage rate testing & followup on previous items
 BROOKS.C H Region 2, Office of Director JAPE,F Division of Engineering & Operational Programs 83/08/26 App 20617 270 24X Fiche 50-269,83/08/30.8310040290
- 8310040575 Responds to IE Bulletin 83-05. "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tuler Pump Co " One Hayward Tyler pump currently installed in Unit 1 & 2 spent fuel cooling sys Twelve pumps to be installed in radwaste facility TUCKER, H B Duke Power Co 83/09/08 D'RETLLY, J P Region 2, Office of Director 5pp 20422 278 24X Fiche 50-249,83/09/08,8310040575
- 8310040247 Forwards 1E Insp Repts 50-269/B3-25,50-270/B3-25 & 50-287/83-25 on B30809-11 No noncompliance noted DANCE.H C Division of Project & Resident Programs D3/09/09. TUCKER.H II Duke Power Co 2pp 20613 194 24X Fiche 50-269, B3/09/09,8310040247
- --B310040253 IE Insp Repts 50-269/83-25,50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted Major areas inspected zero power physics testing & power escalation testing DAVENPORT, K E Region 2. Office of Director JAPE.F Division of Engineering & Operational Programs B3/09/07 5pp 20413 196 24X Fiche 50-269,83/09/09.8310040247
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340.
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300342
- B30B30D345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26,830B300345
- 831025024B Forwards IE Insp Repts 50-269/83-28.50-270/83-28 k 50-287/83-28 on 830811-0910 No nuncompliance noted DANCE H C Division of Project & Resident Programs 83/09/27 TUCKER H D Duke Power Co 1p 20897 074 24X Fiche 50-269,83/09/27,8310250248
- --B310250256 IE Insp Repts 50-269/83-28.50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted Major areas inspected operations, maint surveillance, training & NUREO-0737 items. BRYANT.J. FALCONER.D Region 2, Office of Director BROWNLEE, V Division of Project & Resident Programs 83/09/27 10pp 20899 075 24X Fiche 50-269,83/09/27.8310250248
- 8310040484 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-269/83-26 DANCE H C Division of Project & Resident Programs 83/09/28 TUCKER, H B Duke Power Co ip 20625 170 24X Fiche 50-269, 83/09/28,8310040484

- --8310040492 Responds to NRC 830824 ltr re violations noted in IF Insp. Repts 50-269/83-26, 50-270/83-26 & 50-287/83-26 Corrective actions recirculation & release procedures revised to verify sign off for closing valves.

 TUCKER, H B Duke Power Ca 83/09/19 O'REILLY, J P Region 2, Office of Director 2pp 20425 171 24X Fiche 50-269, 83/09/28.
- --8310040495 Forwards IE Insp Repts 50-269/83-26.80-270/83-26 & 50-287/83-26 on 830711-0810 & notice of violation DANCE, H C Division of Project & Resident Programs 83/08/24 TUCKER, H B Duke Power Ca 2pp 20625 173 24X Fiche 50-269,83/09/28,83100/0484
- --8310040500 Natice of violation from insp on 830711-0810 * Region 2. Office of Director 83/08/24 ip 20625 175 24X Fiche 50-269.83/09/28.8310040484
- --8310040507 IE Insp Repts 50-269/83-26.50-270/83-26 & 50-287/83-26 on 830711-0810 Noncompliance noted failure to follow chanistry procedure resulting in unplanned release of radioactive water
 BRYANT, J. FALCONER, D. Region 2, Office of Director BROWNEFE, V Division of Project & Resident Programs 83/08/23 7pp 20625 176 24X Fiche 50-269,83/09/28,8310040484
- 3308300349 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Sys M/o 10CFR50 59 Evaluation " Syc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fitchs 50-000,83/09/29,8308700349
- 3310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance mated DANCE, H C Division of Project & Resident Programs 03/10/05 TUCKER, H B Dute Power Co 2pp 20898 123 R4X Fiche \$0-269, 83/10/05, 8310250354
- --8310250363 IE Insp Repts 50-269/83-27.50-270/83-27 & 50-287/83-27 on 830712-16 No noncompliance noted Major areas inspected emergency detection & classification, protective action decisionaling, public info program & shift staffing DECKER, T.R. Region 2. Office of Director JENKINS, 0 R Division of Emergency Preparedness & Materials Safety 83/09/30 5pp 20898 125 24X Fichs 50-269, 83/10/05, 8310250354
- 108300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list entl JURBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07. Consolidated Edison Co of New York, Inc. 74pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 200300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 63/10/07. Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 9308300759 IE Info Notice 83-67, "Emergency Uso Respirator Matl Defect Causes Production of Notious Cases" Eve list encl JURBAN.E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11. Consolidated Edison Co. of New Yorks Int. 117pp 21043:075 24X Fichs 50-000, 83/10/11. B300300759
- 3308300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list encl.
 JORDAN, E. L. Division of Emergency Properedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 3310280435 Informs that periodic evaluation of SALP complete Rept approved.
 O'REILLY, J. P. Region 2, Office of Director 83/10/17, TUCKER, H. B. Duke Power Co. 3pp. 20790 205 24% Fiche 50-000, B3/10/17, 8310250435
- -8310250444 Forwards SALF Repts 50-267/83-17, 50-270/83-17, 50-267/83-17, 50-267/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 Apr 1983 LEHIS,R C. Division of Project & Resident Programs 83/08/02 TUCKER,H B. Duke Power Co. 3pp. 20700, 208, 24% Fiche 30-000, 83/10/17, 8310250435
- -8310250452 BALP Repts 50-269/83-17,50-270/83-17,50-287/83-17, 50-369/83-24,50-370/83-32,50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983 * Region 2, Office of Director, 83/08/02 SApp 20900 211, 24X Fichs 30-000,83/10/17,8310250635.

- --8310250665 Responds to 830802 ltr re SALP board rept Rept incomplete & premature in certain areas in general, util endosses observations re facility performance TUCKER, H B Duke Power Co 83708729 O'REILLY, J P Region 2, Office of Director 2pp 20900 267 24% Fiche 50-000,83/10/17,8310250635
- 8310270079 Forwards response to Action Item 3 of IE Bulletin 80 ji.
 "Masonry Wall Design " Design assumptions appropriate considering physical condition of boundary joints TUCKER, H B Duke Power Ca H3/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STULZ, J F Operating Reactor Branch 4 3pp 20724 360 24% Fiche 50-269,83/10/20.8310270079
- R Periodic operating reports & related correspondence
- 8310180167 Monthly operating repts for Scpt 1983 W/831014 lt,
 REAVIS.J A. YUCKER.H D. Duke Power Co. 83/09/30 Director's
 Office. Dffice of Inspection and Enforcement 19pp 20809 095 24X
 Fiche 50-269,83/09/30,8310180167
- 8 Reportable occurrences, LERs & related correspondence
- 8310260008 Addl response to FOIA request for 17 categories of records Forwards documents listed in Apps B.C & D Info re fraudulent practices of Ray Mallon. Inc available in PDR FELTON. J M Division of Rules and Records 83/06/23 CLEWETT, J Public Citizen Litigation Group 15pp 20920 001 24X Fiche 50-000, 83/06/23, 8310260008
- --B207260091 Discusses licensee Mar 1982 testing & evaluations of steam extraction line albow which ruptured on B20288, in response to B20709 request for addl steam line break info EIBENHUT, D.G. Division of Licensing B2/07/14 RLIM, T.A. Office of the Executive Director for Operations 2pp 20920 020 24X Fiche 50-000 G3/06/23, 8310260008
- 8310060426 RD on 830922.w/both Keowee hydro units out of svc for planned maint.lee &C gas turbine, being used to energize buses, tripped off line Both standby buses deenergized & Units i & 3 placed in degraded mode TUCKER.H B Duke Power Co. 83/09/27 O'REILLY.J P Region 2, Office of Director 3pp 20641 224 24X Fiche 50-269.83/09/27, 8310060426
- 8310170596 LER 83-016/03L-0 on 830702, while performing in-place systest for hydrogen purge unit, discharge flow instrument FT-100 demaged Caused by personnel error FT-100 repaired W/830730 ltr PETTY, J C, TUCKER, H B Duke Power Ca 83/07/30 O'REILLY, J P Region 2, Office of Director 4pp 20/84 321 24X Fiche 50-249,63/07/30,8310170536
- 8310140157 Rd on 830929, while energizing 4, i60-volt standby buses, Lee 6C gas turbine trapped off-line, deenergizing both standby buses & placing two operating units in degraded mode. Cause undetermined since unit has no event recorder TUCKER, H B Duke Power Cq 83/10/04 0/RCILLY, J P Region 2, Office of Director 3pp 20765, 067 24X Fiche 50-269, 83/10/04, 8310140159
- B310270412 RO on B31012, standby buses decneralized to allow for operability performance testing of standby bus breakers per Tech Specs Testing caused degraded mode beyond Tech Spec limit
 TUCKER. H. B. Duke Power Co. B3/10/17 D'REILLY, J. P. Region 2. Office of Director 2sp. 20924 010 24X Fiche 50-269, 83/10/17. B310270412
- V Operator Examinations
- 8310040425 Notifies that operator & sonior operator licensing exams scheduled for wk of 831205 NRC requirements for administration of exams encl DANCE.H C Division of Project & Resident Programs 83/09/28 TUCKER.H B Duke Power Co Spp 20619 124 24X Fiche 50-269,83/09/28.8310040425
- DDCKET 50-270 OCONET NUCLEAR STATION, UNIT 2

 F Becurity, medical, emergency & fire protection plans
- 8310070134 Releases public version of revised crisis mgt plan implementing procedures FELTON, J. H. Division of Rules and Records 83/10/04 Document Hanagement Branch ip 20670.001 24X Fiche 30-000,83/10/04,8310070134

- --8310070143 Forwards public version of revised crisis mgt plan implementing procedures including Procedures 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group TUCKER, H B Duke Power Co 83707/06 DENTON, H R Office of Nuclear Reactor Regulation. Director 3pp 20670 002 24x Fiche 50-000,83/10/04,8310070134
- --8310070152 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group # Duke Power Co # 83/07/01 457pp 20670 005 24% Fiche 50-000 83/10/04 8310070134
- 8310110047 Releases public version of revised ømerguncy plan implementing procedures FELTON, JM Division of Rules and Records 83/10/05 Document Management Branch 1p 20709 160 24X Fiche 50-267,83/10/05,
- --8310110076 Forwards public version of revised emergency plan implementing procedures, including Procedure CP/0/8/4003/01 re environ surveillance Pollowing large unplanned release of gassous radioactivity Receipt form encl TUCKER, H B , MCINTOSH, J T Duke Powrt Co 83/09/19 O'REILLY, J P Region R. Office of Director 2pp 20709 161 24y Fichs 50-269,83/10/05,8310110067
- --8310110080 Public version of revised emergancy plan implementing procedures, including Procedure CP/O/B/4003/01 re environ surveillance following large unplanned release of gaseous radioactivity
 SHITH, J E Duke Power Co 83/09/08 50pp 20709 163 24X Fiche 50-269,83/10/05.8310110067
- 8310110135 Releases public version of rev to emergency procedure FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 2070/ 319 24X Fiche 50-269,83/10/05,83/10/10/35
- --8310110141 Public version of Rev 83-5 to Emergency Procedure AP/O/B/1000/07, "Procedure for Offsite Dose Calculation by Control Room Personnel or Emergency Coordinator During Radiological Accident " W/GSOB30 ltr SMITH. J E , TUCKER. H B , MCINTOSH. J T Duke Power Co 83/07/22 O'REILLY, J P Region 2, Office of Director 19pp 20707 320 24X Fiche 50-269, 83/10/05, 8310110135
- 8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-77 & 50-287/83-27 on 830912-16 No noncompliance noted BANCE.H C Division of Project & Resident Programs 83/10/05 TUCKER,H B Duke Power Co 2pp 20898 123 24X Fichs 50-269,83/10/05,8310250384
- --8310250363 IE Insp Repts 50-269/83-27,50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted Majo: areas inspected emergency detection & classification protective action decisionmaking, public info program & shift staffing DECKER, T R Region 2, Office of Director 83/09/30 Spp 20898 125 R4X Fiche 50-269,83/10/05,8310290354
- 8310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation TUCKER. H B Duke Power Ca 83/10/10 DENTON. H R Office of Nuclear Reactor Regulation, Director Epp 20802 12: 24X Fiche 50-000,83/10/10.8310180444
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved O'REILLY, J.P. Region 2, Office of Director 83/10/17 TUCKER, H B Duke Power Co. 3pp. 20700 205 24% Fiche 50-000, 83/10/17, 8310250635
- --8310250452 BALP Repts 50-269783-17,50-270783-17,50-287783-17, 50-369783-24,50-370783-32,50-413783-14 & 50-414783-13 for June 1982 - Apr 1983 * Region 2, Defice of Director 83/08/08 56pp 20900 211 24X Fiche 50-000,83/10/17,8310250635
- 8310280027 Forwards request for exemption from fire protection requirements of IOCFR90.App R. Section III J re emergency lighting in control room, stairwells/corridors, outside auxiliary bldg & standby shutdown facility TUCKER.H B DUR Power Co B3/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 App. 20734 285 24X Fiche 50-264,83/10/24,8310280029

- 8310280124 Suppls 830603 ltr re exemption request from location requirements of emergency operations Pacility Significant benefits not achieved by near-site facility up to 20 miles from plant Meeting w/NRC requested TUCKER, H B Duke Power Co. 83/10/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4 2pp 20929 266 24X Fiche 50-269, 83/10/25, 8310280124
- P Operating license stage documents & correspondence
- 8310040111 Responds to 830531 % 0826 ltrs requesting amend to 830318 confirmatory order re NUREG-0737. Item II F I 5. "Containment Water Level Monitor" Amend not required Environ qualification will be addressed in 10CFR50 49 audit STOLZ, JF Operating Reactors Branch 4 83/09/02 TUCKER, H B Duke Power Co 5pp 20627 351 24x Fiche 50-269,83/09/02,83/09/02
- B310040647 Forwards SER accepting Arkansas Power & Light Co (APL)
 B30507 proposed mods to reactor trip breakers for B&H
 plants Requested info should be provided when APL generic
 design endorsed in response to Generic Ltr B3-2B
 STOLZ, J F Operating Reactors Branch 4 B3/09/12 TUCKER, H B
 Duke Power Co 2pp 20627, 303 24x Fiche 50-269, 83/09/12,
 B310040647
- 8310110545 Forwards Amends 123.123. & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & EIA Amends allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool STOLZ, JF Operating Reactors Branch 4 83/09/29 TUCKER, H B Duke Power Co 2pp 20711 265 24X Fiche 50-269,83/09/29. 8310110545
- --83i0110561 Amends 123.123 & 120 to Licenses DFR-38, DFR-47 & DFR-55, respectively, changing Tech Specs to allow increase in spent fuel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool STOL7.J F Operating Reactors Branch 4 83/09/29 11pp 20711 267 24X Fiche 50-269, 83/09/29, 8310110545
- --8310110569 Safety evaluation supporting Amends 123,123 & 120 to Licenses DPR-38: DPR-47 & DPR-55 respectively * Office of Nuclear Reactor Regulation, Director 83/09/29 14pp 20711 278 24X Fiche 50-269,83/09/29,8310110545
- --8310110875 EIA supporting Amends 123,123 & 120 to Licenses DPR-38, DPR-47 & DPR-55, respectively # Office of Nuclear Reactor Regulation, Director 83/09/29 10pp 2071 292 24X Fichs 50-269,83/09/29,8310110545
- 8310140253 Forwards info re inservice pump & valve testing program.
 W/o enc)
 TUCKER,H B Duke Power Co 83/10/10 DENTON.H R Office of
 Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors
 Branch 4 Ip 20761 332 24X Fiche 50-269,83/10/10,8310140253
- 8310240151 Forwards steam generator operating history Info valid through 821231 TUCKER,H B Duke Power Co 83/10/13 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 44pp 20881
- 8310310489 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATMS & proposed ATMS rule for B&W planta List of attendess & viewgraphs and KADAMBJ.P Operating Reactors Dranch 4 83/10/20 Operating Reactors Branch 4 13pp 20965-147 24X Fiche 50-000.83/10/20, 8310310489
- 8310280105 Forwards update of progress of control room habitability mods.per 830922 ltr re TMI Item III D 3 4 HVAC aquipment operating at approx 2/3 design capacity Updated work list & schedules encl
 TUCKER,H B Duke Power Co 83/10/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 670LZ,J F Operating Reactors Branch 4 2pp 20935 324 24X Fiche 50-269,83/10/24,8310280105.
- O Inspection reports: IE Bulletins & correspondence
- 8310040290 Forwards IE Insp Repts 50-269/83-24, 50-270/83-24 & 50-287/83-24 on 830725-0803 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/08/30 TUCKER, H B Duke Power Co 2pp. 20617 268 24% Fiche 50-269, 83/08/30, 8310040390

- ~-8310040294 IE Insp Repts 50-269/83-24.50-270/83-24 & 50-267/83-24 on 830725-0803 No noncompliance noted Major areas inspected containment integrated leatage rate testing & followup on BROOKS,E H Region 2. Office of Director JAPE,F Division Engineering & Operational Programs 63/08/26 App 20617 27 24% Ficha 50-267,83/08/30,8310040270
- 8310040575 Responds to 1E Bulletin B3-05, "ASME Nuclear Code Pumps & Spare Parts Hfg by Hayward Tyler Pump Co " Une Hayward Tyler pump currently installed in Unit 1 & 2 spent fuel cooling sys. Twelve pumps to be installed in raduaste facility TUCKER, H B Dute Power Co 83/09/08 C'REILLY, J P Region 2, Defice of Director Spp 20622 278 24X Fiche 50-269, 83/09/08, 8310040525
- B310040247 Forwards IE Insp Repts 50-269/B3-25,50-270/B3-25 & 50-287/B3-25 on 830809-11 No noncompliance noted DANCE,N C Division of Project & Resident Programs B3/09/07 TUCKER,N B Dute Power Co 2pp 20613 194 24X Fiche 50-269,83/09/09,8310040247
- --8310040253 IE Insp Repts 50-249/83-25,50-270/83-25 & 50-287/83-25 on 830809-11 No noncompliance noted Major areas inspected ford power physics testing & power escalation testing DAVENPORT, K E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/09/07 5pp 20413 176 24X Fiche 50-249,83/09/09,8310040247
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Gualification Tests " Svc list enc! JORDAN: E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Natics 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intaies " Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777-210 24X Fiche 50-000,83/09/26,8308300042
- 8308300345 IE Info Natice 63-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310250248 Forwards IE Insp Repts 50-269/83-28,50-270/82-28 & 50-287/83-28 on 830811-0910 No noncompliance noted. DANCE, H C Division of Project & Resident Programs 83/09/27 TUCKER: H B Duke Fower Co Ip 20899 074 24X Fiche 50-269,83/09/27,8310250248
- --9310250256 IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted. Major areas inspected operations maint surveillance training & NOREC-0737 items BRYNNI, J. FALCONGR. D. Region 2. Office of Director BROWNLFC, V Bivision of Project & Resident Programs 83/09/27 10pp 20899 075 24X Fichs 50-269, 83/09/27, 8310250248
- 8310040484 Act receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-269/83-26
 DANCE, N C. Division of Project & Resident Programs 83/09/28
 YUCKER, N B. Duke Power Co 1p 20625 170 24X
 Fiche 50-269, 83/09/28, 8310040484
- --8310040472 Responds to NRC 830824 ltr re violations noted in IE lpsp Repts 50-267/83-26.50-270/83-26 & 50-287/83-26 Corrective actions recirculation & release procedures revised to verify sign off for closing valves TUCKER.H B Duke Fower Co 83/09/19 O'REILLY.J P Region 2, Office of Director 2pp. 20625 171 24X Fiche 50-269.83/09/28, 8310040484
- -8310040495 Forwards IE Insp Repts 50-269/83-26,50-270/83-26 & 50-287/83-26 on 830711-0810 k natice of violation DANCE,H.C. Division of Project & Resident Programs 83/08/24 TUCKER,H B Duse Power Co 2pp 20625 173 24X Fiche 50-269,83/09/28,8310040484
- -8310040507 IE Insp Repts 50-269/83-26.50-270/83-26 & 50-287/83-26 on 830711-0810 Noncompliance noted Pailure to follow chemistry procedure resulting in unplanned release of radioactive
- processor reserving in Transport of Director Branton, FALCONER, D. Region 2, Diffice of Director Branton of Project & Resident Programs 83/08/23 7pp 20625 176. 24% Fiche 50-249,83/09/28,8310040484

- 8308300349 IC Info Natice 83 84, "Lead Thredding Attached to Safety-Related Sgs W/o 10(1856 59 Evaluation " five list ence JORDAN, E.L. Division of Emergency Preparedness & Ingenering Response (Post B30103) 817097.79 Consolidated (dison in of New York, Inc. 115pp 20716 3.44 748 fiche 50-000 117097.79 (100.00 149
- 8310250354 Forwards IE Insp.Repts 90 (289/8) (7.90 \$7070) 177 & 90-287/83-37 on 830912 16 No noncompliance noted DANCE, H.C. Division of Project & Resident Programs | 61/10/05 TOCKER H.B. Duke Power to Type (2019) (3.3)4x Fishe 90-269,83710709,8310790.54
- --8310250363 IE Insp Ropts 50 289703-27/50 27070 F 27 & 50 207701 27 on JENKING R Division H 18038 10
- B308300370 lE Info Natice 81-69, "Surveillance of Flow in RID Dypass Logps Used in Westinghouse Plants" for list until JORDAN.E.L. Division of Georgemy Preparadises & Lagineering Response frost B301031 B3/10/0/ Constituted 4 dison Go of New York Inc. 75pp. 2092/ 214 24X Fiche 80 000, 81/10/0/10/808300778
- 8308300752 If Info Natice Of 66. "Fatality at Argentine Critical Facility" Sec list encl.
 JORDANIE L. Division of Leargeby Propereduces & Engineering Response (Past USB(CS) | 11/10/07 | Constituted Little to of Revenue.
 York Inc. 79pp. 20882 026 /44 Fiche 50 000.0 0710/07.000830075.
- B30B300/59 IE Info Notice B) A7. "Emergonsy Use Respirator Matl Defect Causes Production of Natious Gases" but list and JORDAN-E Division of two pensy Proprietation of Lagrangian Color Response (Post B30103) B3746741 (Insolidated Idsun Color Past Vork Inc. 117pp. \$2043.075) \$24X Ficho 50.000.03710/11.0100.00059
- 8308300761 IE Info Notice 83 AU. "Respirator User Harning Defective Belf-Contained Breathing Apparatus Air Cylinders " livi list
- enc) WORDAN, L. Bivision of Emergancy Proporadoess & Engineering Response (Post 030103) 80710711 Connotidated Edison (n. of New York, Inc. 120pp 20027-1272 14X Fiche 50 000, 0.7/10/11.0308,00741
- 8310250635 Informs that periodic evaluation of UALP complete Hept approved O'RESILLY, J.P. Region & Office of Director (63/10/1/ 100 Duke Power Co. 3pp. 20900 POD PAK Fiche DO 000, H.M.10/1/, 83102004/0
- --9310230546 Forwards SALP Repts 50 269784 17:50 270703 17:50 28789 17:50-369783-24:00 370703 32:50 41:783 14 5:50 41478 17:50 28789 17:50 28789 17:50 28789 17:50 28789 17:50 28789 17:50 28789 18:50
- --8310280432 UALP Repts 50 289749-17, 50 170767 17, 50 1207763 17, 50-249763-24, 50-270743-32, 50 44370, 14 & 50 41470, -13 for June 1902 -- Apr 1903 -- Apr 19040 -- Apr 1903 -- Apr 19040 -- Apr
- --0310250545 Responds to 830602 ltr re SALP board rept Hept incomplete & 31020060 Responds to 830602 ltr re SAIP board rept Hept incomplet premature in certain areas in general ofil endorses observations re facility performance TUCKER H B Duke Power Co 43208/39 O'REILLY, J P Agion 2, Office of Director 2pp //0700 267 '4X fiche 50 (000,83/10/17, 831035044)
- 8310270079 Forwards response to Action Jiem 3 of II. Bulletin 80 II.

 "Masonry Hall Dealgn " Design assumptions appropriate
 considering physical condition of boundary joints
 TUCKER, H.B. Duke Power Co. 82/10/20 DEATH MINER MIFFICE OF
 Nuclear Reactor Regulation, Director 97012.J. | Operation Restort
 Branch 4 Spp. 20924-360 24x Licho 50 267.83/10/20.93102/0079
- R Periodic operating reports & related correspondence
- 8310180167 Monthly operating repts for 9rpt 1988 W/GN1014 ltr REAVIB.J A. LUCKER.H 9 Dute Power Co 03/09/30. Direc Office. Office of Inspection and Enforcement. 19pp 20809 Fiche. 30~269.83/09/30.8310180167 Director's 20009 090 24%

S. Reportable occurrences. LERs & related correspondence

- 831026000B Addl response to FUIA request for 17 categories of records Farwards documents listed in Apps B.C & D lafo refraudulent practices of Rau Miller.Inc available in FOR FELTON, J M Division of Rules and Records 83/06/23 CLEWETI, J Public Citizen Litigation Group 15pp 20290 001 247 Fiche 50-000,83/06/23.8310260000
- --8207260091 Discusses licensee Mar 1982 testing & evaluations of steam sytraction line elbow which ruptured on 820628 in response to 820709 request for addl steam line break info EISENHUT.D G Division of Licensing 82/07/14 RCHM.T A Office of the Executive Director for Operations 2pp 20920 020 24X Fiche 50-000.63/06/23.8310260006
- --8310260027 Forwards initial info re 830628 steamline break event at facility, per 830702 telcon request Review of licensee actions continuing MARTIN.R D Region 2. Office of Director 83/07/07 REHN, 7 A Office of the Executive Director for Operations 5pp 20720 022 24% Fiche 50-000.83706/23,8310260008
- 8310060426 RD on 830922.w/both Keowee hydra units out of svc for planned maint, Lee &C gas turbine, beanq used to energize buses, trapped off line Both standby buses deenergized & Units 1 & 3 placed in degraded mode TUCKER.H B Duke Power Co 83/09/27 O'REJLLY, J P Region P. Office of Director 3pp 20641 224 24X Fiche 50-269, B3/09/27, B310060426
- 8310140159 RO on 830929, while energizing 4,160-volt standby buses, Lee 6C gas turbine tripped off-line, deenergizing both standby buses & placing two operating units in degraded mode Cause undetermined since unit has no event recorder TUCKER.H B Duke Power Co 83/10/04 O'REILLY, J P Region 2, Office of Director 3pp 20765 067 24% Fiche 50-269,83/10/04, 8310140157
- 8310270412 RO on 831012, standby buses deenergized to allow for operability performance testing of standby bus broakers per Tech Specs Testing caused degraded mode beyond Tech Speclimit

 TUCKER, H B Duke Power Co 83/10/17 O'REILLY, J P Region 2, Sefice of Director 2pp 20924 010 24X Fiche 50-247, 83/10/17.

V Operator Examinations

- 8310040425 Notifies that operator & senior operator licensing exoms scheduled for wk of 831205 NRC requirements for administration of exams entl DANCE.H C Division of Project & Resident Programs 83/09/28 TUCKER.H B Duke Power Co 3pp 20619 184 24X Fiche 50-269,83/09/28.8310040425
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- 8310140240 Forwards IE Insp Rept 50-271/83-21 on 830801-0905 No noncompliance noted STAROSTCCKI,P Division of Project & Resident Programs 83/09/27 MURPHY.W P. Vermont Yankee Nuclear Power Corp 2pp 20762 006 24X Fiche 50-271,83/09/27,8310140240
- --8310140245 IE Insp Rept 50-271/83-21 on 830801-0905 No noncompliance noted Major areas inspected action on previous insp findings, plant power operations, including status & operational records, physical security & maint activities RAYMOND, W J , HOLDEN, C f , GALLO, R M Region 1, Office of Director 83/09/26 32pp 20762 008 24X Fiche 50-271,83/09/27,8310140240
- B310040259 Advises that assessment of two viable options for location of primary emergency operations facilities.per Suppl 1 to NOMEQ-0737, schedulad for completion in early Nov 1983 Final deciston expected by B31119 MORPHY, W.P. Varmont Yankee Nuclear Power Corp. B3/09/29 WASBALLO, D.B. Operating Reacturs Branch 2 2pp. 20617 266 24X Fiche 50-271.83/09/29.8310040259
- 8310310307 Submits results of engineering evaluation of two possible mods to automatic depressurization sys logic per NVRE0-0737. Item II K 3 18 Problem better add using symptom-based emergency operating procedure MURPHY, W P Vermont Yankee Nuclear Power Corp 83/10/26 VASSALLO, D B Operating Reactors Branch 2 2pp 20761 274 24X Fiche 50-271,83/10/26.8310310307

- P Operating license stage documents & correspondence
- B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER, L Affiliation Unknown 83705/02 NRC No Detailed Affiliation Given ip 21004 270 24% Fiche 50-000,83705/02, B310310017
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON, J M Division of Rules and Records 83/07/06 CONNER.L Affiliation Unknown ip 21004 P71 24X Fiche 50-000,83/07/06,83/073/0731
- --8310310061 "Integrated Primary Containment Leakage Rate Test "
 TARNUZZER:E C Vermont Yankee Nuclear Power Corp YAEC-1055
 72/02/07 67pp 21005 280 24% Fiche 50-000:83/07/06:8310310031
- 8310120312 Forwards technical rept "Mark 1 Containment Program Plant-Unique Analysis Rept of Torus Attached Piping for Vermont Yankee Nuclear Power Plant " SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/10/06 VASSALLO D B Operating Reactors Branch 2 lp 20697 258 24X Fiche 50-271,83/10/06,8310120312
- --8310120315 "Mark I Containment Program Plant-Unique Analysis Rept of Torus Attached Piping for Vermont Yankee Nuclear Power Plant "
 * Teledyne Engineering Services TR-5319-2 83/10/03 95pp 20497 206 24% Fiche 50~271,83/10/04.8310120312
- 83101909/ Forwards Rev 14 to operational OA program Rev addresses organizational & programmatic changes to GA program SHEPARD.A M Vankee Atomic Electric Co. 83/10/12 MURLEY.T F Region 1. Office of Director 1p. 20822 117 24X Fiche 50-000.83/10/12.8310190097
- --8310190105 Rev 14 to operational GA program PETERSON, W.K., SHEPARD, A.M., NURPHY, N.P. Yankee Atomic Electric Co. YOGAP-1-A.R14 83/10/12 134pp. 20822 118 24X Fiche 50-000, B3/10/12, 831019097
- 8310210310 Forwards response to 830104 request for add) info re NUREQ-0737, Item II D 1 "Relief & Safety Valve Test Requirements ""Tee" quencher utilized at discharge pipe exit SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/10/17 VASSALLO, D B Operating Reactors Branch 2 15pp 20851 137 24X Fiche 50-271, 83/10/17,8310210310
- 8310310266 Summarizes key points of 831021 presentation on intergrapular stress corrosion cracking Weld sample selected at facility biased towards susceptible welds All 12-inch riser welds inspected.per IE Bulletin 83-02 MURPHY. W P Vermont Yankee Nuclear Power Corp 83/10/26 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 20947 136 24X Fiche 50-271.83/10/26.8310310266
- @ Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-lns for Helder Qualification Tests " Svc list ent! JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 1179p 20754 022 24X Fichs 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Ras Detectors Positioned at Control Room Ventilation Air Intakes " Svc list wncl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fichs 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,83083000345
- 8310140234 Forwards IE Insp Rept 50-271/83-24 on 830726-28 No noncompliance noted MARTIN.T T Region i. Office of Director 83/09/26 MURPHY.W.P Vermont Yankes Nuclear Power Corp 2pp 20761 314 24% Fiche 50-271.83/09/26.8310140234

- --8310140236 IE Insp Rept 50-271/83-24 on 830726-28 No noncompliance noted Hayer areas inspected licensee evaluations of alpha activity in plant sys & associated radiological health hazards MCBR 106.N JANG, J. THOMPSON, T. Region 1, Office of Director
- hazards MCBRIDE: M. JANG, J., THOMPSON. T. Region 1. Office of Director B3/09/22 5pp 20761 316 24% Fiche 50-271.83/09/26.8310140234
- 8310140240 Forwards IE Insp Rept 50-271/83-21 on 830801-0905 No noncompliance noted STAROBTECKI.P Division of Project & Resident Programs 83/09/27 HURPHY, W P Vermont Yankse Nuclear Power Corp 2pp 20762 006 24X Fiche 50-271,83/09/27,8310140240
- --8310140245 IE Insp Rept 50-271/83-21 on 830801-0705 No noncompliance noted Hajor areas inspected action on previous insp findings.plant power operations, including status & operational records, physical security & maint activities RAYMOND.W J , HOLDEN C F , CALLO, R M Region 1, Office of Director 83/09/26 32pp 20762 008 24X Fiche 50-271,83/09/27,8310140240
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 59 Evaluation " Syc list
- encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/27 Contolidated Edison Co of New
 York, Inc. 115pp 20716 324 24% Fiche 50-000, 83/09/27, 8308300349
- 9310200088 Forwards IE Insp Rept 50-271/83-22 on 930711-15 & 18-20 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 83/09/30 MURPHY,N P Vermont Yankee Nuclear Power Corp 2pp 20936 620 24X Fiche 50-271,83/09/30,8310200088
- --8310200090 Notice of violation from insp in 830711-15 & 18-20 * Region 1. Office of Director 83/09/30 3pp 20836 022 24x Fiche 50-271.83/09/30.8310200088
- --8310200092 IE Insp Rept 50-271/83-29 on 830711-15 & 18-20 Noncompliance noted operational testing & acceptance criteria, required prior to returning equipment to svc.not defined or specified on maint requests & meet issue slip numbers not documented SHAUB.E., NAPUDA, G., GOLDBERG, S. Region 1, Office of Director 83/09/27 23pp 20836 025 24% Fiche 50-271,83/09/30,8310200080
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list entl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24% Fiche 50-000.83/10/07.8368300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility." Syc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Ner York, Inc 79pp 20882-026 24X Fiche 30-000,83/10/07.8308300752
- 9308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl URDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11.8308300759
- B30B3007&1 IE Info Notice B3-68, "Respirator User Marning Defective Self-Contained Breathing Apparetus Air Cylinders " Svt list and JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24% Fiche 50-000, B3/10/11, B30B300761
- B310180551 Notification of B31021 meeting w/BWR licensers in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking, MIRAGLIA.F J Assistant Director for Safety Assessment B3/10/14 E186MHUT.D 0 Division of Licensing 5pp 20820 358 24x Fiche. 50-000, B3/10/14.B310180551
- 8310310266 Summarites key points of 831021 presentation on intergranular stress corrosion cracking Weld sample selected at facility bissed towards susceptible welds All 12-inch riser welds inspected.per IE Bulletin 83-02 HURPHY.W P Vermont Yantee Nuclear Power Corp 83/10/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20947 136 24X Fichs 50-271.83/10/26.8310310266
- R Periodic operating reports & related correspondence
- 6310180096 Monthy operating rept for Sept 1983 W/831009 ltr BURGER, F. J. MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 83/10/09 NRC ~ No Detailed Affiliation Given 7pp 20807 215 24X Fiche 50~271,83/10/09,8310180096

- S Reportable occurrences, LERs & related correspondence
- 6310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for OE BWR/4 rated at 2,436 MW Forwards App A documents Documents also evailable in PDK FELTON, J M Division of Rules and Records 83/07/20 HAFNER, B Suffolk Nuclear Study Group 2pp 20HH2 223 24X Fiche 50-000,83/07/20,8310210329
- --B30&010008 Discusses evaluation of LERs submitted during appraisal period Hay 1982-Apr 1983 for technical accuracy, completeness & intelligibility Screening for trends & patterns produced few cases which could indicate potential mgt weakness SEMFRIT.K V Reactor Operations Analysis Branch B3/05/18 STANDSTECKI.R Division of Project & Resident Programs Jpp 20882 274 24X Fiche 50-000, 83/07/28,8310210329
- B310250531 LER 83-021/03L-O on 830830, during surveillance on drywell pressure ECCS indicators.PT-10-101B(M) actuated at 2 57 psig Caused by instrument drift Trip unit replaced w/calibr unit W/830929 ltr
 PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/09/29 HMRLEY, T E Region 1, 0ffice of Director 3pp 20702 139 P4X Fiche 50-271, B3/09/29, B310250531
- 8310250626 LER 83-025/01P-O on 830928, during normal operation, main steam line radiation monitor RM-17-P51A trip setpoint greater than 3 times normal background at rated power Causad by inadequate procedure Trips reset W/80929 tr PELLETIER. J P Vermont Yankee Nuclear Power Corp 83/09/29 MRRLEY T E Region 1, 0 Pfice of Director 2pp 20700 165 DAX Fiche 50-271,83/09/29,8310250626
- 8310140082 PNO-I-B3-105 on 831007 seismic event occurred in northeastern UB w/magnitude of 5.2 on Richter scale in NY & 4.0 in NH No damage to equipment identified GALLO, R M Region 1, Office of Director 83/10/07 lp 20766 1]6 24X Ficher 50-000.83/10/07.8310140082
- 8310250334 LER 83-025/01T-0 on 830928, mein steam line rod monitor found w/trip setpoint greater than three times normal background required by Tech Bpers Gaused by procedural inadequacy Procedure being revised W/831012 itr PELLETIER, J P Vermont Yanker Nuclear Power Corp 80/10/12 MURLEY, T E Region 1, 0ffice of Director 2pp 80897 333 84X Fiche 50~271,83/10/12,8310250334
- 8310250377 LER 83-023/03L-O on B30923, health physics sampling program revealed high Co-60 concentration at north storm drain outfail Caused by low level airborne releases from turbine bldg roof vents Sample point added M/831012 ltr PECLETIER, JP Vermont Yankes Nuclear Power Corp 63/10/12 HAYNES, R C Region 1. Office of Director 3pp 20090 175 24x Fiche 50-271,83/10/12,8310250379
- 8310250308 LER B3-022/03L-0 on B30913 reactor water cleanup sysoutboard isolation valve malfunctioned Caused by faulty torque switch in valve operator Torque switch replaced & systested satisfactorily W631013 ltr
 PELLETIER, JP Vermont Yankee Nuclear Power Core B3/10/13
 MURLEY, T E Region 1, 0Ffice of Director Jpp 20899 001 24X
 Fiche 50-271.83/10/13.8310250308
- DOCKET 50-272 SALFM NUCLEAR GENERATING STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8309190260 forwards correct page revs to security plan & security training & qualification plan Page revs withheld (ref 10GFR73 21)

 # Public Service Electric & Qas Co of New Jersey 83/09/IR MARTIN. T T Division of Engineering & Technical Programs Ip 20415 368 24X Fiche. 50-272,83/09/12,8309190260
- 8310210195 Forwards marked-up revised 1983 emergency explcise Revinterporates NRC & FEMA comments from 880804 meeting Addition or operational data & engineering problems will be submitted 2 wis prior to exercise MOELLER, P. A. Public Bervice Biectric & Gas Co. of New Jorsey 83/09/12 MURLEY, T. Region 1. Office of Director 143pp 20846 147 24X Fiche 50-272,83/09/12,8310210195
- 8310250512 Forwards IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance nated MARTIN, T I Division of Engineering & Technical Programs 83/10/04 UDERITZ: R A Public Service Clectric & Gas Co of New Jersey 2pp 20901 052 24X Fiche 50-272,83/10/04,8310250512

- --8310250529 IE Safoquards Insp Repts 50-272/83-28 & 50-311/83-28 on 830707-09 No noncompliance noted Mayor areas inspected security sgs power supply, detection aids vital areas & licensee implementing procedure evaluation SMITH.6 C. & CODY.A T. Region 1. Office of Director 83/10/03 2pp 20701 054 24X Fiche 50-272,83/10/04,8310250512
- G Adjudicatory correspondence
- 831025003B Petition for leave to intervene & request for hearing on proposed issuance of amend to License DPR-70 re inservice integrated leak tests Affidavit of Mailing encl SILVERMAN, FS, DELANEY, CL Delawaro, State of 83/10/21 Commissioners 6pp 20894 184 24% Fiche 50-272,83/10/21, 831039038
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310180251 Forwards Rev 2 to updated FSAR, consisting of drawings updated since 830802 Rev I LIDEN.E A Public Service Electric & Gas Co of Now Jersey 83/10/12 VARGA,S A Operating Reactors Branch 1 2pp 20809 238 24X Fiche 50-272,83/10/12,8310180251
- --8310180253 Rev 2 to updated FSAR, consisting of drawings updated since 830802 Rev 1 * Public Service Electric & Gas Co of New Jersey 83/09/Ps 39pp 20809 240 24X Fiche 50-272,83/10/12,8310180251
- P Operating license stage documents & correspondence
- B310050159 Forwards "Plan for Improvement of Nuclear Dept Operations."
 in response to Basic Energy Technology Assoc, Inc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures "
 UDERITZ, R A Public Service Flectric & Gas Co of New Jersey B3708/26 VAROA, S A Operating Reactors Branch | 2pp 20602 178 24% Fiche 50-272,83/08/24,8310050159
- --8310050164 "Plan for Improvement of Nuclear Dept Operations "

 * Public Service Electric & Gas Co of New Jersey B3/08/26
 59pp 20632 180 24% Fiche 50-272,83/08/26,8310050139
- --83:0050174 "Response to Basic Energy Fechnology Assoc..Inc Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station.Unit i " Cross ref encl # Public Service Electric & Q
- 8310060857 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept of util response to TMI Item II K 3 17, "Rept on Dutages of ECCS"

 VARGA.8 A Licensing Branch i 83/09/27 UDERITZ,R A Public Service Electric & Oas Co of New Jersey App, 20444 127 24X Fiche 50-272,83/09/27,8310040557
- --8210010087 "ECCS Repts (F-47) TM1 Action Plan Regirements.PSL&Q, Salem Nuclear Generating Station Unit 1." technical evaluation rept VQSBURY, F W, QUERBECK, O J, LUDINGTON, B W Franklin Institute/Franklin Research Center NRC-03-80-130 IER-C5506-294 82/09/28 CHDM, E NRC No Detailed Affiliation Given 14pp 20464 131 24X Fiche 50-272, 83/09/27, 8310060557
- 8310070097 Forwards safety evaluation of decign of RCB vents Design conforms w/requirements of NUREC-0/37, Item II B 1, GDC 1, 2, 4, 14, 30 & 31 & 10CFRSD 44(c)(3)(111) w/exception of positive valve position indication VARGA, B A Operating Reactors Branch 1 B3/09/27 UDERITZ, R A Public Service Electric & Gas Co of Now Jersey 3pp 20673 349 24X Fiche 50-272,83/09/27,8310070097
- --8310070103 Safety evaluation of RCS vent design Design complies w/ NUREO-0737, Item II B 1,60C 1,2,4,14,30 & 31 & 10CFR50 44 + NRC - No Detailed Affiliation Olven 83/05/17 6pp 20473 352 24X Fiche 50-272,83/07/27,8310070097
- --B3060B0112 "Selected Operating Reactor Issues Program II RCB Vents (NUREO-0737, item II B i)." final technical evaluation rept for Balem is 2 HELD, J T Energy Incorporated FIN A-0250 TF-343/0807A B3/02/23 ALBERTHAL.9 Division of Licensing 6pp 20673 358 24% Fiche 50-272, 83/09/27,8310070097

- 8310070166 Advises that automatic PDRV isolation will not be provided & PORV & block valve control sys will not be modified, based on "Probabilistic Analysis & Operational Data in Response to NUREG-0737, Item II K 3 2 for Westinghouse NSSS Plants "
 LIDEN.E A Public Service Electric & Oas Co of New Jersey 83709/27 VAROA.S Operating Reactors Branch I 2pp 20639 108 24X Fiche 50-272, 8310070166
- 8310070003 Forwards remittance for License Change Requests 83-07,83-10 b 83-11 LIBEN,E A Public Service Electric & Gas Co of New Jersey 93/09/30 VARGA.S A Operating Reactors Branch 1 Jp 20658 245 24X Fiche 50-272,83/09/30,8310070003
- 8310170039 Forwards SER & technical evaluation rept re licensee responses to NUREO-0737. Items II K 3 1. "Automatic PORV Isolation" & II K 3 2. "Rept on PORVs "VAROA.S A Operating Reactors Branch 1 83/10/05 UDERITZ, R A Public Service Electric & Gas Co of New Jersey Spp 20812 162 24X Fiche 50-272,83/10/05,8310170039
- 8310210285 Forwards addl fee required for Class 1 amend re Rev 1 to License Change Request 79-01 Original fee paid for single Class III amend only LIDEN, EA Public Bervice Electric & Cas Co of New Jersey 83/10/13 VARGA, S Operating Reactors Branch I ip 20855 245, 24X Fiche 50-272, 83/10/13, 8310210285
- Q Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JURDAN, E L División of Emergency Preparedness & Engineering Response (Post 830103) 83709/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fichs 50-000, 83/09/26, 8308300340
- B30B300342 IE Info Notice B3-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, B3/09/26, 830B300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Hestinghouse Type SA-1 Differential Relays "Svc list and JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 188p 20778 001 24X Fiche 50-000.83/09/26,8308000345
- 8310140276 Forwards IE Insp Repts 50-272/83-25 & 50-311/83-26 on 830810-0906 No noncompliance noted 87AROSTECKI:R Division of Project & Resident Programs 83/09/26 UDERITZ:R A Public Service Electric & Gas Co of New Jersey 2pt 20761 214 24X Fiche 50-272.83/09/26.0310140276
- --83101402/9 IE Insp Repts 50-272/83-25 & 50-311/83-26 on 830810-0904 No noncompliance noted Major areas inspected conformance w/Tech Specsylog & record reviews, followups on previous inspitems & review of licensee events
 LINVILLE, J C . BUMMERS.R J . JACOBS.R H Region 1. Office of Director 83/09/26 15pp 20741 216 24X Fiche 50-272,833/09/26,8310140276
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 59 Evaluation" Svc list enci JURDAN. E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche, 50-000, 83/09/29, 83083000349
- 8310040214 EN-83-032A on 830805, notices of violation & proposed imposition of civil penalty in amount of \$850,000 issued to util based on violation of Tech Spec requirement & failure to adequately implement aspects of QA program KLINGLER.Q. AXELRAD.J. Director's Office, Office of Inspection and Enforcement 83/09/27 ip 20417 240 24X Fiche 50-272,83/09/29,83:0040214
- 8310110381 Discusses util 830706 & 0722 responses to 830505 motice of violation & proposed imposition of civil penalty identified during review of ATWS events on 830282 & 25 Order encl imposing civil penalty in amount of \$850.000
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 83/09/27 UDENTIA.R A Public Service Electric & Qas Co of New Jersey 2pp 20/13 281 24X Fiche 50-272,83/09/27,83/0110381

- ~-8310110387 Order imposing civil monetary penalties in amount of \$850,000 re violation of Tech Spec 3 3 1 i requiring two reactor trip breakers to be operable when reactor operating in Modes 1 & 2
 DEYDUNG.R C Director's Diffice. Office of Inspection and Enforcement 83/09/27 Public Service Electric & Gas Co of New Jersey 14pp 20713 283 24X Fiche 50-272,83/09/29,8310110381
- 8310250512 Forwards IE Safequards Insp Repts 50-272/83-28 & 50-311/83-28 on 830707-09 No noncompliance noted MARTIN.7 T Division of Engineering & Technical Programs 83/10/04 UDERITZ.R A Public Service Electric & Gas Co of New Jersey Ppp 20901 052 24% Fiche 50-272,83/10/04.83102505)2
- --8310250527 IE Sefeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted Major areas inspected security sys power supply, detection aids vital areas & licensee implementing procedure evaluation SHITH, 9 C . GDDY, A T Region 1. Office of Director 83/10/03 2ps. 20901 054 24X Fiche 50-272,83/10/04,8310250512
- 8310180391 Ack receipt of 830829 & 0922 Itrs informing NRC of steps taken to correct violations noted in IF Insp Repts 50-272/83-13 & 50-311/83-19 STAROSTECKI,R Division of Project & Resident Programs 83/10/09 UDERITZ,R A Public Service Electric & Ons Co. of New Jersey Ip. 20803 313 24X Fiche 50-272,83/10/05.8310180391
- --8310180398 Responds to NRC 830729 ltr re violations noted in 1E Insp Rapts 50-272/83-13 & 50-311/83-19 Corrective actions ECCO throttle valve positions corrected & verified & TRIS worksheet footnote revised re ECCS throttle valves LIDEN.E A Public Service Electric & Oas Co of New Jersey 83/09/22 STAROSTECKI, R Division of Proyect & Restiont Programs 3pp 20803 314 24X Fiche 50-272.83/10/05.8310180391
- 830B300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list enc! JORDAN E L Division of Emergency Preparadness & Engineering Response (Post B30103) 83710/07 Consolidated Edison Co of Ne York, Inc 7App 20927 213 24X Fiche 50-000.83/10/07.83083003/8
- 8308300752 IE Info Notice 83-64, "Fatality of Argentine Critical Facility " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 (E Info Notice 63-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidate Edison Co of New York, Inc 117pp 21043 075 24X Ficher 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68. "Respirator User Marning Defective 8elf-Contained Breathing Apparatus Air Cylinders " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York. Inc 120pp 20827 129 24X Fiche 80-000.83/10/11.8308300761
- R Pariodic operating reports & related correspondence
- 8310030346 "NPDES Discharge Monitoring Rept for Aug 1983 " W/830906 ltr Itr MILLER, L K Public Service Electric & Gas Co of New Jersey 83/09/23. 21pp 20590 164 24X Fiche 50-272,83/09/23.8310030346
- 8310R00174 Monthly operating rept for Sept 1983 W/831010 ltr MILLER, L K , ZUPKO, J M Public Service Electric & Qas Co of New Jersey, 83/10/10 Director's Office, Office of Inspection and Enforcement iopp 20835, 237 24X Fiche 50-272, 83/10/10, 8310200174
- 8 Reportable occurrences, LERs & related correspondence
- 8310050157 Forwards "Plan for Improvement of Nuclear Dept Operations," in response to Basic Energy Technology Assoc. Inc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures "UDERITZ:R A Public Bervice Electric & Gas Co of New Jersey.

 83/08/26 VARQA, 8 A Operating Reactors Brench 1 2pp 20652 17G 24% Fiche 50-272,83/08/26.8310050159.
- --8310050174 "Response to Basic Energy Technology Assoc. Inc Rept on Review of Corrective Action Program to Reactor Trip Breaker Failures at Balem Generating Station. Unit 1 " Cross tof encl.
 4 Public Bervice Electric & Gas Co of New Jersey. 83/08/26 23pp. 20632 241. 24X Fiche 50-272.83/08/26.8310030159

- B310040213 PNB-J-83-019 on B30923.licensee contract security organization suspended two security guards Guard admitted to bringing fillegal substance on site Other quard did not ript inclident Both guards terminated 630926 MADDEN.W. GODY.A Region 1. Office of Director 83/09/28 1 20614 273 24X Fiche 50-272.83/09/28.8310040213
- 6310110179 Notification of Significant Licensee Meeting 83-87 on 631011 at site to discuss ATWS event corrective action program KISTER. H B Region 1. Office of Director 83/09/29 Rogion 1. Office of Director 199 20487 353 24X Fiche 50-2/2.83/09/29. 6310110179
- 8310(1038) Discusses util 830706 & 0722 responses to 830505 notice of violation & proposed impossition of civil penalty identified during review of ATMS events on 830222 & 25 Order encl imposing civil penalty in amount of \$850,000 DEYOUNG: 0 Director's Office of Inspection and Enforcement 83/09/29 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 2pp 20713 281 P4X Fishe 50-272,83/09/29,8310110381
- --8310110387 Order imposing civil monetary penalties in amount of \$850,000 re violation of Tech Spec 3 3 1 1 requiring two reactor trip breakers to be operable when reactor operating in Modes 1 & 2
 BEYOUNG, R C Director's Office. Office of Inspection and Enforcement 83,09729 Public Service Electric & Gas Co of New Jersey 14pp 20713 283 24X Fache 50-272,83/09/29,8310110381
- 8310250325 LER 83-041/03L-0 on 830715, discovered containment all particulate detector filter failure alarm illuminated Caused by inadequate supply of Filter paper New filter paper installed W/631012 ltr FRAIM.R . ZUPKD, J M Public Service Electric & Gas Co of New Jersey 83/10/12 MWALEY, T E. Redion 1. Office of Director 4pg 20897 345 24% Fiche 50-272.83/10/12.8310250325
- 8310250390 LER 83-040/03L-0 on 830916, reactor trip breaker 1 post maint surveillance not completed within 1 h interval Caused by add1 testing incorporated into surveillance Licenso change request will be submitted to increase interval W/831012 ltr FRAMM.R. 20PKO.J M Public Service Liectric & Gas Co of New Jersey 83/10/12 MMRLEY.T. Region 1, Office of Director 4pp 20898 147 24X Fiche 50-272.83/10/12.8310250390
- 8310250236 LER G.3-042/04L-O on 830914, routine release of radioactive liguid from chemical & vol control monitoring tank if performed w/o verification of operability of release line effluent monitor Procedure revised W/G31014 ltr FRANCAR, ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/10/14 /WRLEY, T & Region 1, Office of Director 4pp 20899 139 / 24X Fiche 50-272,83/10/14,8310250238
- 8310260024 LER 83-043/03L-0 on 830720, during routine operation, delta temp/delta pressure station auxiliary performer chart recorder indication failed Caused by P-250 computer electronic lockup Computer rebootstrapped W/831014 ltr FRAHM.R., ZUPKO.J M. Public Service Electric & Gas Co. of New Jersey 83/10714 MVRLEY, T. E. Region I. Office of Director 4pp 20733 204 24% Fiche 50-272,83/10/14.8310280024
- V Operator Examinations
- 831025025/ Responds to J Bury telcon re licensed operator requalification Training Procedure TP-305 Exam will be completely changed at least every 6 wks LIDEN,E A Public Service Electric & Gas Co of New Jersey 83/10/17 VARGA, B A Operating Reactors Branch 1 2pp 209/8 35/ 24X Fiche 50-272, B3/10/17, 8310250257
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 E NRC Sefety Evaluation Report (SER), supple & correspondence
- 8310120404 Provides clarification for certain designations in FSAR figures & tables re steam generator blowdown isolation per SSER 18 Classification & installation of relays will be completed prior to full power operation SCHUVLER, J C Pacific Gas & Electric Co B3/10/06 LISENHUI, D P Division of Licensing 2pp 20699 022 24X Fiche 50-275.83/10/06.8310120404
- 8310170817 Forwards clarifications 2/or add1 info re 830830 t 0708 t 07 responses to SSER I8 open items Items 3,4,7,10 t 17 resolved, Encl info resolves Items 1,16,17,18,23,24 t 27 SCHUYLER, J O Pacific Gas t tlectric Co 83/10/06 EISENHUT, D G Division of Licensing 16pp 20784 218 24X Fiche 50-275,83/10/06,8310170817

- 8308300766 Board Notification 89-154 forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Corrective Action Turbine Bldg."
 Rev 1 to "Information Items re Large Bore Piping" & transcript of 830928 meeting w/uti1
 EISENHUT, D G Division of Licensing B3/10/07 PALLADING, N J , GILINSKY, V , ROBERTS, T M Commissioners 3pp 20782 188 21X
 Fiche 50-275.83/10/07.8308300766
- --8310170318 Transcript of 830928 technical conference w/utilr & PN in Bethesda, MD re SSER open items Pp 1 -104 * Commissioners 83/09/28 416pp 20782 191 24X Fiche 50-275,83/10/07,8308300766
- 8310170514 Forwards revised Attachment 6 re power operated valves to Encl 2 of 830907 response to SSER 18 potential unresolved items Mods to valves FCV-3/ & 38 determined unnecessary Description of mods oncl SCHUYLER.JO Parific Gas & Electric Co 83/10/07 FIGENHUT, D G Division of Licensing 3pp 20784 148 24X Fiche 50-275,83/10/07,8310170514
- B310170657 Forwards clarifications &/or add1 info on SSER 18,Open Item 30 re rupture restraints Crushable bumpers/rupture restraints inside containment designed per Design Criteria Memo DCM-C64
 SCHUYLER, J D Pacific Gas & Electric Co 83/10/11 FIBENHUT, D G Division of Licensing 2pp 20779 280 24X Fiche 50-275,83/10/11,8310170467
- B310180463 Forwards clarification &/or addition on SSER 18 Open Item 29 re jet impingement Uriginal design basis validated No further evaluation necessary SCHUYLER, J O Pacific Gas & Electric Co 83/10/12 ElgENHUI, D C Division of Licensing 9pp 20802 054 24X Fiche 50-275,83/10/12,8310180443
- 8310190137 Forwards clarifications &/or add1 info re SSER 18.0pen ltem 2, "Rosponse Spectra Cutoff Frequency "
 SCHUYLER.J Ø Pacific Gas & Flectric Co 83/10/12 EISENHUT,D @
 Division of Licensing 15pp &0820 261 24X Fiche 50-275.83/10/12,
 8310190137
- B310170063 Informs that util will provide addl info re SSER 18. Open I tems 1.2 % 17 (as listed in SECV-83-366. Encl 5), per NRC review of listed previous responses SCHUYLER, J O Pacific Oas & Electric Co 83/10/14 EISENHUT, N G Division of Licensing ip 20822-334 24X Fiche 50-275, 83/10/14. B310170063
- 8310200131 Forwards Rev 1 to Figures 1 & 2 of 831006 response to SSER 18 on Open Item 1 (SECY-B3-366) re raw response spectra & raw-smoothed response spectra SchuyteR.J O Pacific Gas & Electric Co 83/10/14 FISENHUT.D C Division of Licensing 3pp 20834 104 24X Fiche 50-275,83/10/14,8310200131
- F Security, medical, emergency & fire protection plans
- E310040221 Forwards IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & 0818 No noncompliance noted NORDERHAUG, L R Region 5. Office of Director 83/09/20 SCHUYLER, J D Pacific 6as & Hisctric Co 2pp 20617 250 24X Fiche 50-275,83/09/20,8310040221
- --8310040226 IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & OBIB No noncompliance noted Major areas inspected emergency preparedness program including emergency detection & classification & protective action decisionmaking SCOUN,K SCHUBTER, M D Region 5, Office of Director 83/09/19 13pp 20617 252 24X Fiche 50-275,83/09/20,8310040221
- 8310040141 Forwards addl info re emergency lighting capability & evaluation & reactor coolant pump lube oil sys Info should clarify 830715 rept justifying differences between fire protection features & iOCFR50, App R requirements SCHUYLERJ O Pacific Gas & Electric Co 83/09/23 FISENHUT, D O Division of Licensing 24pp 20417 005 24X Fiche 50-275,83/09/23.
- 8310070236 Forwards add1 info on App R review re fire doors & panels, ctarifying & supplementing 830715 & 0923 submittals. Approx 40 of 120 door & frame assemblies modified for security reasons SCRUYLER. J O Pacific Gas & Electric Co 83/10/03 EISENHUT. D © Division of Lirensing Spp 20658 240 24X Fiche 50-275.83/10/03, 3310070236

- 8310120402 Forwards list of proposed mods to be completed prior to initial criticality which will provide level of compliance equivalent to 10CFR50. App R Fire door requirements will be determined after UL insp scheduled for wk of 831010 SCHUYLER, J D Pacific Oas & Electric Co 83/10/06 EIGENHUT, D O Division of Lirensing 5pp 20699 012 24X Fiche 50-275,83/10/06,8310120402
- 8310170939 Forwards Amend 6 to License DPR-76 & safety evaluation
 Safety evaluation withheld (ref 10CFR73 2)) Amend requires
 implementation of approved physical security plan
 KNIGHTON, G W Licensing Branch 3 83/10/11 FURBUSH, M H Patific
 Gas & Electric Co 4pp 20764 203 24X Fiche 50-275,83/10/11,
 B310170339
- --8310170542 Amend 6 to License DPR-76.changing vita) area access controls EISENHUT, D G Division of Licensing 83/10/11 2pp 20784 207 24X Fiche 50--275, 83/10/11, 8310170537
- B310170965 Provides addl info on App R review re schedule for fire door mods Door manufacturers will inspect unlabeled doors & frames constructed to UL specs on B31010-13 Doors/frames not within specs will be replaced SCHUYLER, J O Pacific Gas & Electric Co B3/10/11 EIBENHUT, D G Division of Licensing 2pp 20780 343 24% Fiche 50-275, B3/10/11, B310170565
- 8310180620 Advises that 830803 proposed changes to Rev II to physical security plan & Rev 2 to safeguards contingency plan acceptable per 100FR30 54(p) Encls to ltr withheld (ref 100FR30 21)
 KNIGHTON.O W Licensing Branch 3 83/10/12 8CHUYLER.J O Pacific Gas & Electric Co 3pp 20817 336 24X Fiche 50-275.83/10/12.
- 8310210154 Requests publication of FR notice of consideration of issuance of amend to License DPR-76 & proposed NSHC determination & opportunity for hearing re-physical security plan NSHC determination available in Central Files KNIGHTON.6 W Licensing Branch 3 83/10/13 MILLER. J R Operating Reactors Branch 3 2pp 20083 357 24X Fiche 50-275.83/10/13.
- B310200144 Bubmits add1 info on App R review re schedule for fire door mods Installation of directional closed head sprintler protection on both sides of panels & transoms suggested SCHUYLER, J D Pacific Oas & Electric Co 83/10/14 EISENHUT, D, Q Division of Licensing 1p 20836 274 24X Fiche 50~2/5, B3/10/14, B310200144
- 8310280061 Provides add1 info to B31014 submittal re App R review of panels, transoms & door mods Actions for components which cannot meet UL approved configurations listed BCHUYLER, J D Pacific Gas & Electric Co 83/10/21 EISENHUT, D Q Division of Licensing 2pp 20933 339 24X Fiche 50-275, B3/10/21, B31020041
- 8310270546 Releases public version of revised corporate emergency response plan & revised emergency response plan implementing procedures
 FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch ip 20945 007 24X Ficher 50-275, 83/10/25, 83/10/27564
- --8310270572 Forwards public version of Rev 2 to corporate emergency response plan & revised emergency response plan implementing procedures ECHUYLER, J @ Pacific Gas & Electric Co 83/10/10 MARTIN, J B Region 5, Office of Director 3pp E0945 008 24X Fiche 50-275,83/10/25,83/03/2056
- --8310270575 Public version of Nev 2 to corporate emergency response plan SCHUYLER, J II Pacific Gas & Electric Co 83/09/12 85pp 20945 011 24X Fiche 50-275,83/10/25.8310270566
- --8310270580 Public version of revised corporate emergency response plan implementing procedures, including Procedures 3 I re governmental relations, 3 2 re corporate communications dept & 3 3 re law SCHUYLER, J O Pacific Gas & Electric Co 83/10/04 300pp 20945 096 24X Fiche 50-275,83/10/25.8310270566
- 8310270582 Releases public version of revised emergency plan implementing procedures FELTON, J.M. Division of Rules and Records 83/10/25 Document Management Branch 1p 20946 099 24X Fiche 50-275,83/10/25, 8310270582

- -8310270586 Forwards public version of revised emergency plan implementing procedures, including Procedures 2 1 re plant maint; 3 4 re insurance & 3 6 re security 8CHULER, J 0 Pacific Cos & Electric Co 83/09/12 MARIIN, J B Region 5. Office of Director 3pp 20946 100 24X Fiche 50-275,83/10/25,8310270582
- -8310270588 Public version of revised emergency plan amplementing procedures, including Procedures 2 1 re plant maint.3 4 re insurance & 3 6 re security
 SCHUYLER.J D Pacific Gas & Electric Co 83/08/16 150pp
 20946 103 24X Fiche 50-275,83/10/25.8310270582

Adjudicatory correspondence

- 310260277 Contentions on design GA re verification of semples for
- IDVP
 STRUMMASSER.H California, State of REYNOLDS.J Joint
 Intervenors-Diable Canyon REYNOLDS.J Center for Lew in the Public
 Interest 83/09/08 Abomic Safety and Licensing Appeal Panel
 103pp 20911 039 24% Fiche 50-275.83/09/08.8310260277
- 310030371 Confirms 830920 telcon re Governor Deukmejian 830902 request for documents List of requested documents will be sent by
- 831004 MCOURREN, H J Hearing Branch 3 83/09/26 DURBIN, S Califor State of 1g 20630 354 24% Fiche 50~275,83/09/26.831005037 California,
- 310050454 Response opposing Joint Intervenors 830926 request for hearing on lifting of license suspension No legal basis presented to support hearing Certificate of Svc encl CHANDLERL J. Hearing Branch 2 83/09/26 Commissioners 15pp 20630 040 24X Fiche 50-275.63/09/26.8310050454
- 310040251 First supplemental responses to interrogatories Cartification of counsel & Carlificate of Svc encl Related correspondence LUBBOCK, D. G. Pacific Oas & Electric Co. B3/09/28 California Btate of 7pp 20613-042 24X Fiche 50-275,83/09/28,8310040251

- 310040288 First supplemental answers to third set of interrogatories Prof qualifications & Certificate of Svc encl Rolated correspondence STRUMMASSER.M California, State of 83/09/28 Pacific Gas & Electric Co 26pp 20614 167 24X Fiche 50-275,83/09/28,8310040288
- 310050396 First supplemental response to third set of interrogatories Certificate of Svc encl Related correspondence LUBBOCK.D Q Pacific Qas & Electric Co 83/09/28 California, State of 66pp 20634 186 24% Fiche 50-275.83/09/28.8310050396
- 310030384 Motion for sanctions against Governor Deukmejian & Joint Intervenors for failure to suppl interrogatories seasonably Intervenors have engaged in concrete course of conduct to delay proceedings Cartificate of Svc encl
 CRANC.P A Pacific Gas & Clectric Co 03/09/29 Atomic Safety
 and Licensing Appeal Panel 18pp 20592 154 24X
 Fiche 50-275,83/09/29.8310030384 :1 93/09/29 Atomic Safety 72 154 24X
- 310040209 Motion for mod of schedule established in ABLB 830907 order re design &A hearing Delay in completion of IDVP renders schedule impossible to meet schedule impossible to meet RAUFMAN.P H Celifornia. State of 83/09/29 Atomic Bafety and Licensing Appeal Panel 17pp 20614 335 24X Fiche 50-27b. 83/09/29.8310040209
- -8310040212 Addi contentions on design QA KAVFMAN,P H California, State of REYNDLDS,J Joint Intervenors-Diablo Cangon REYNOLDS,J Center for Law in the Public Interest B3/09/29 Atomic Safety and Licensing Appeal Panel 4pp 20614 352 24K Fiche 50-275,83/09/29,8310040209
- -8310040219 Application for expedited ruling on motion for mod of hearing schedule Motion should be ruled on quickly since testimony due 831008 Certificate of Svc encl KAMFMAN.P.H Callfornia, State of. 83709729 Atomic Sefet; Licensing Appeal Panel 5pp 20614-356 24X Fiche 30-275,83709729,8310040209 Atomic Bafety and
- 910040539 Bupplemental response to second set of interrogatories Certification of counsel & Certificate of Svc encl Related
- correspondence
 HAVIAN.E.R. Joint Intervenors-Diable Canyon HAVIAN.E.R. Center
 for Law in the Fublic Interest 83/09/29 Pacific Gas & Electric
 Go 7pp. 20624-019 24X Fiche 50-975:83/09/29:8310040539
- 10040302 Order extending time until B31007 for Commission to act to review ALAD-728 CHILK, B.J. Office of the Secretary of the Commission B3709730 Commissioners. ip 20614 168 24X Fiche 50-275.83709730, B310040302

- 8310040525 Forwards author notice of appearance Certificate of Syc encl LUBBOCK.D 0 Pacific Gas & Electric Co 83/09/30 Bocketing & Services Branch 4pp 20624 226 24X Fiche 50-2/5.03/09/30, 8310040525
- 8310070209 Staff requirements memo re 830927 discussion of proceeding schedule Commission will hold 831028 public meeting in Washington DC re issues related to fuel loading CHJLK.8 J Office of the Secretary of the Commission 83/09/30 Office of the Secretary of the Commission 1p 20676 362 24% Fiche 50-275,83/09/30,8310070209
- 8310050421 Fourth supplemental response to first set of interrogatories Certificate of Svc encl REYNOLDS, J. Joint Intervenors-Diable Canyon REYNOLDS, J. Center for Law in the Public Interest 83/10/02 Pacific Gas & Electric Co. 9pp. 20630 334 24X Fiche 50-275,83/10/03,8310050421
- 8310110053 Answer opposing util motion for sanctions for alleged failures to suppl interrogatory answer seasonably Motion wholly unfounded & should be denied Declaration of counsel & Certificate of Byc and STRUMHASSER.M California. State of 83/10/04 Atomic Safety and Licensing Appeal Panel 21pp 20668 244 24% Fiche 50-275, 83/10/04.8310110053
- 8310110058 Forwards Page 41 of Nuclear Svcs Corp audit of Pullman Power Products filed w/Joint Intervenors 830909 suppl to motion to reopen record on const 0A issue REYNOLDS, J Center for Law in the Public Interest REYNOLDS, J Joint Intervenors-Diable Canyon 83/10/04 Atomic Safety and Licensing Board Panel 2pp 20668 239 24X Fiche 50-2/5.03/10/04, 8310110058
- B310110073 Response opposing Governor Deukmeyian & Joint Intervenors B30729 add1 contentions on GA Contentions lack specificity &/or fail to meet criteria for late-filed contentions Certificate of Svc encl LOCKER.R F Pacific Gas & Electric Co B3/10/04 Atomic Safety and Licensing Appeal Panel App 20667 299 24X Fiche 50-275,83/10/04.8310110073 Atomic Safete
- 8310110120 Response opposing Gavernor Deukacjian 830907 motion to modify schedule for conduct of hearings Motion is only another unsubstantiated play for delay Certificate of 8vc encl NORTON. B Pacific Gas & Electric Co NORTON. B Norton, Burke, Berry & French 93/10/04 Abomic Safety and Licensing Appeal Panel 12pp 20466 212 24X Fichs 50-2/5,83/10/04,8310110120
- 8310110127 Response opposing licensee motions for sanctions against Governor Beuxmejian & Joint Intervenors Intervenors supplemented interrogatory answers in timely manner Certificate of Svc encl REYNOLDS, J. Joint Intervenors-Diablo Canyon REYNOLDS, J. Center for Law in the Public Interest 83/10/04 Atomic Safety and Licensing Appeal Panel Bpp. 20666-204 24X Fiche 50-275,83/10/04,8310110127
- 8310110317 Response supporting Governor Deukmejian 830929 motion for mod of hearing schedule Deposition schedule not completed & time for filing contentions expired prior to issuance of IDVP repts Certificate of Syc entl REYNOLDS, J Joint Intervenors-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 83/10/04 Atomic Safety and Licensing Appeal Panel App 20645 358 24X Fiche 50-275,83/10/04,8310110317
- 831012041B Response of IDVP to Interrogatory 57 in third set of interrogatories Certificate of Svc encl Related correspondence correspondence RASKIN.D B Lowenstein, Newman, Reis, Axelrad & Toll B3/10/05 BTRUMMABBER,M California, State of 9pp 20699-044 24X Fichs 50-275,83/10/05,831012041B
- 8310130017 Response apposing Governor Devkmejian 830929 motion for 2-wk extension of discovery schedule set in ABI AB 830907 order Covernor began discovery process only 3 wks before hearing Extension would delay hearing Extension would delay hearing CHANDLER.L J Hearing Branch 2 83/10/05 Atomic Safety and Licensing Appeal Panel 7pp 20725 191 24X Fiche.50-275,83/10/05,8310130017
- --B310130019 Response supporting licensee 830929 motion for sanctions upon Governor Deukmejian/Joint Intervenors Depositions of Apostolalis, Kempthorne & Hubbard should be held during wt of B31010-14, Ceptificate of Byc encl
 CHANDLER.L J Hearing Branch 2 83/10/05 Atomic Safety and Licensing Appeal Fanel App 20729 198 24X
 Fiche 50-275.83/10/05.8310130017

- 8310130163 Response to 830902 document request consisting of computer printput listing documents in docket since 811101 Documents to be copied should be identified MCGURREN.H J. Hearing Branch 1 83/10/05 BURDIN,8 L. Californi. State of 4pp 20724 280 24X Fiche 50-275.83/10/05.8310130163
- G310110298 Application for subpocha for G Apostolakis for 831011 deposition & production of documents NORTON. B Pacific Gas & Electric Co NORTON. B Norton. Burks. Gerry & French BJ/10/66 Atomic Safety and Licensing Appeal Panel 4pp 20666 100 24X Fiche 50-275.83/10/06.8310110298
- --8310110301 Notice of G Apostolakis deposition on 831011 in San Francisco,CA Certificate of Svc encl NORTON:B Pacific Gas & Electric Co NORTON:B Norton, Burke-Berry & French 83710706 App 20746 104 24X Ficho 50 275.83/10/06.8310110298
- 83i0120376 Second supplemental answers to first set of interrogatories Certification of counsel & prof qualifications enc) DURBIN S L. California. State of 83/10/07 Parific Gar, & Electric Co. 28pp. 20699 [32] 24X Fiche 50-275,83/10/07. 8310120376
- --B3101203B1 First supplemental answers to second set of interrogetaries Certification of counsel one 1 DURBIN.S L California, State of B3/10/07 Pacific Gas & Electric Co 17pp 20699 160 24X Fiche 50-275.83/10/0/, B310170476
- --83[0]20J86 first supplemental answers to fourth set of interrogatories Certification of Counsel & (ertificate of Svc enc)
 DURBIN,S | California, State of 03/10/07 Pacific Gas & Electric Co 8pp 20699 177 24X Fiche 50-275, 03/10/07, 83[0]20J76
- 83101203B5 Order confirming B31005 and julings during telcon re respensed proceeding on design GA Governor Deukmejian B30927 motion for mod of schedule granted in part SHBEMAKER.C J Atomic Safety and Licensing Appeal Panel B3/10/07 Bpp 20097 1B5 24X Fiche 30-275.83/10/07.8310120305
- B310120412 Order extending time until B3101/ for Commission to act to review ALAB-/28 CHILK, S J Office of the Secretary of the Commission B3/10/0/ Commissioners Ip 20498 052 24X Fiche 50-275.83/10/07. B310120412
- 8310130243 Fifth supplemental response to first set of interrogatories
 Portions of R8 Hubbard & CJ Schaniego 021221 direct
 testimony & Certificate of Svc encl
 RCYNDLDS, J Juint Intervenors-Diablo Canyon REYNOLDS, J Center
 for Law in the Public Interest 83/10/07 Pacific Cas & Llectric
 Co 19pp 20723 253 24X Ciche 50-2/5, 63/10/07, 8310130243
- 8310180160 Motion for leave to file reply to NRC & util responses to Joint Intervenors 830909 suppl to motion to reopen record on const QA Responses raised defenses & relied on documents not previously part of record Certificate of Svc encl REYNOLDS. J. Joint Intervenors-Diablo Canyon REYNOLDS. J. Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel Spp. 20809 147 24X Fiche 50-275.83/10/13. 80310180160
- 8310180248 Response to Governor Deukmujian, NRC b util replies to Joint Intervenors 836909 suppl to motion to reagen record on const GA NSC audit rept provides irrefutable evidence of breakdown in Pullman QA program Certificate of Sov encl REYNOLDS, J Joint Intervenors-Diablo (anyon REYNOLDS, J Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel 12pp 20802 320 24X Fiche 50-275, 83/10/13,8310180248
- B310170219 Hotion for order of enforcement of ASLAB B31007 order directing Governor Deukmejian & Joint Intervenors to supplinterrogatory responses & documents requested Parties failed to provide required documents Certificate of Svc enci CRANF.P A Pacific Gas & Flectric Co B3/10/13 Atomic Safety and Licensing Appeal Panel Upp 20010-097 24X Fiche 50~275,83/10/13.8310190219
- 8310180328 Second supplemental response to third set of interrogatories Certificate of Svc enc.) Related correspondence LUBBOCK, D.O. Pacific Gas & Flectric Co. 83/10/14 (NEUKHI JIAN California, State of 14pp 20806-16, 24x Fiche 50-275, 83/10/14, 8310180328
- B31021022B Forwards PJ Kempthorne & FI Samaniego testimony
 REYNOLDS, J.R. Center for law in the Public Interest. RFYNOLDS, J.R.
 Joint Intervenurs-Diablo Canyon. B3/10/15. MOURC I B.,
 JOHNSON W.R. BUCK, J.H. Atomic Safety and Licensing Appeal Panel
 Lp. 20852-047. 24X Fiche 50-275,83/10/15.8310210220

- --0310210242 Exhibit list Certificate of Svc encl REYMOLDS, J Joint Intervenors-Diable Cangon REYMOLDS, J Center for Law in the Public Interest B3/10/15 App 20852 065 24X Fiche 30-275,83/10/15 03102102/8
- 8310200178 Testimony of RB Hubbard re design QA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence HUBBARD, R D California, State of HUBBARD, R D HIW Technical Associates 83/10/16 79pp 20835 129 24X Fiche 50-275,83/10/16,83102001/8
- --8310200195 List of exhibits identified per ASLAB B31007 order Certificate of Svc encl STRUMMASSER.M California, State of 83/10/16 9pp 20835 289 24% Fiche 50-275, 83/10/16, 8310200178
- 8310190054 Forwards documents NKC delivered to Commissioner Gilinsky during 831017 briefing on plant design reverification GILINSKY. V Commissioners 83/10/17 Office of the Executive Legal Director 20pp 20823 259 24X Fiche 50-275,83/10/17, 8310190054
- 8310190261 Order extending time until 831028 for Commission to act to review ALAB-72H CHILK, S.J. Office of the Secretary of the Commission 83/10/17 Commissioners ip 20818 082 24X Fiche 50-275,83/10/17. 8310190261
- 8310270338 Forwards addl copies of direct testimony & accompanying matts Sky Courier & Eastern Airlines lost original transmittels inconvenience regretted STRUMHASSER, M. California, State of 83/10/17 MODRE, T.S. Atomic Safety and Licensing Appeal Panel ip 20923-302 24X Fiche 50-275,83/10/17.8310270338
- --B3102/0348 Answer appasing util 831013 motion for order of enforcement Util violated order several times Grounds for requested relief indneristant STRUMWASSER: M. California, State of 83/10/17. Atomic Safety and Licensing Appeal Panel. 7pp. 20923-303 24X Fich 50-275:83/10/17.83102/0338
- --83102703// Affidavit of RB Hubbard re safety-related aspects of QA programs Prof qualifications & Certificate of Svc encl HUBBARD.R B California. State of 83/10/21 17pp 20929 310 24X Fiche 50-275,83/10/17,8310270338
- B3102502B3 Forwards US Court of Appeals.BC Circuit.83100/ amended opinion affirming NRC denia) of Atty General Bellott; petition to intervene GHANDLER.L J Hearing Branch 2 83/10/18 CHILK.5 J Office of the Becretary of the Commission 20pp 20894 232 2/4X Fisch 50-275.83/10/18.8310250/2
- 8310240158 Motion for revocation of License DPR-76.or in alternative, for continuation of suspension Continuing nature of mat1 false statements & unresolved questions re adequacy of const unacceptable Certificate of Sv. enc.

 REVNOLDS, J. Joint Intervenors-Diable Canyon REVNOLDS, J. Center for Law in the Public Interest 83/10/20 Commissioners 68pp 20881 224 24x Fiche 50-275 83/10/20.6310240158
- 8310240174 Objection to Joint Intervenors proposed Ethibits 128 & 129 & State of CA Governor Exhibit II re design OA Ethibits irrelevant & immaterial to proceeding Certificate of bycencl
 CRANC.P A Pacific Gas & Electric Co 83/10/20 Atomic Safety and Licensing Appeal Panel App 20800 030 24X Fische 50-275.83/10/20.83102401/4
- B310250043 Objections to util & NRC exhibits & testimony.per ASLAB
 B31007 order Certificate of Svc enc)
 HAVIAN.E. Joint Intervenors-Diablo Canyon HAVIAN.E. Center for
 Law in the Public Interest B3/10/20 Atomic Safety and Licensing
 Appeal Panel App 20894 OBL 24X Ficks 50-275.83/10/20.
- 83(0250467 Comments on Joint Intervenors & Oovernor Deutwejian testimony & proposed exhibits, per ASLB 83(007 order Governor Exhibits 27-3) not provided for review Fishbits 129 & 132 acceptable CHANDLER, U.J. Hearing Branch & 83/10/21 MOORE, T.S., BUCK, J.H., JOHNSON, W.R. Atomic Safety and Licensing Board Panel 2pp 20897 102 24X Fiche 50-275,83/10/21,83(10250467)

- 8310260236 Submits suppl to 830901 comments on IDVP final rept & SEER IB re relaxuance of suspended license for fuel loading & low power operation License reissuance opposed Certificate of Svc encl REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervency-Diablo Canyon 83/10/24 PALLADINO, N J . GLINSKY, V . ROBERTS, T Commissioners 14pp 20912 192 24X Fiche 30-275.83/10/24,8310260776
- 8310260270 Order denying Joint Intervenors 830510 & Governor Deukmejian 830517 motions to reopen record re adequacy of applicant const QA program Motions fail to meet stds. SHDEMAKER, C. J. Atomic Safety and Licensing Appeal Panel B3/10/24 Joint Intervenors-Diablo Canyon 2pp 20911 309 24X Fiche 50-275.83/10/24.83102602/0
- B310310141 Notice of withdrawal of Contentions 3c.d.p.q.). J.k & n is design QA failures Contentions found to be within licensing criteria or were resolved by addl technical info Certificate of Eve encl
 DURBIN.S L. California, State of REYNOLDS. J.R. Joint Intervenors-Dieblo Cangon REYNOLDS. J.R. Center for law in the Public Interest B3/10/24 18pp 20959 019 24X
 Fiche 50-275.83/10/24.8310310141
- 8310270263 Answer apposing Joint Intervenor 831020 motion for revocation of OL or for continuation of suspension Applicant has not misrepresented or failed to disclose facts Certificate of Svr encl CRANE.P A Pacific Gas & Electric Co 83/10/25 Commissioners 13pp 20922 028 24X Fiche 50~275,83/10/25,8310270263
- 8310270358 Forwards Joint Intervenor & Governor Deutmejian revised contentions on design QA, replacing Exhibit 1 transmitted w/831024 1tr
 REYNOLDS. J.R. Center for Law in the Public Interest REYNOLDS. J.R. Joint Intervenors-Diablo Canyon 83/10/25 PALLADING. N. J. GILINSKY.V. ROBERTS. T. Commissioners 1p 20923 294 24X
 Fiche 50-275.63/10/25.8310270350
- --8310270361 Issues to be contested by Covernor Deukmeyian & Joint Intervenors • Joint Intervenors-Diable Canyon 63/10/24 /pp 20927 295 24X Fiche 50-275,83/10/25.8310270338
- 8310280097 Reply to util objections to Joint Intervenors proposed exhibits Objections should be overruled Certificate of Svc enc!
 HAVIAN,E Joint Intervenors-Diablo Canyon HAVIAN,E Center for Law in the Public Interest 83/10/25 Atomic Safety and Licensing Appeal Panel 8pp 20935 066 24X Fiche 50-275,83/10/25,8310280097
- .310310181 Requests DC Treppa encl 831021 ltr be placed in MDR & copie, served on parties to proceeding.
 SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 83/10/27
 Docteting & Bervices Branch | Ip 20958 361 24X
 Fiche 50-275.83/10/27.83t0310181
- -8310310184 Expresses concern re reissuing low power test license for facility License should be revoked & facility ordered to shut down
 TREPPALD C Affiliation Unknown 83/10/21 ROSENTHAL.A S NRC -No Detailed Affiliation Civen | Ip | 20958 362 24X
 Fiche 50-275-83/10/27,8310310181

1 General correspondence

- 9310180270 Clerifies position of interjurisdictional planning committee for agencies surrounding facility.emphasizing importance of FEMA coordination of federal agency responses to nuclear plant accidents

 COLEMAN.R J San Clemente. CA 83/10/10 NRC No Detailed Affiliation Given 2pp 20807 050 24x Fiche 50-275,83/10/10.
- 2310200175 Responds to 820712 & 830820 ltrs re-safety & redundancy of valve failure modes [E Insp Repts 50-275/82-26, 50-275/82-34 & 50-275/82-42 enc) Further investigation revealed tracting & documentation of repts out of date 818HOPLT W Division of Resident, Reactor Project & Engineering Programs 83/10/17 COOPER. J H Aff31 lation Unknown 2pp 20835 316 24X Fiche 50-275.83/10/17.0310200175
- Operating license stage documents & correspondence
- 310110034 Further response to FDIA request for records to NUHLO OBAP investigative test & investigations concerning facilities. Forwards App A documents Commissioner Bradford GII-217 memo withheld (ref FDIA Elemption 5)
 FELTON, J H Division of Rules and Records 83/06/15 KEYNOLDS, J Center for Law in the Public Interest 4pp 20713 OOI P4X Fiche 50-275,83/06/13,8310110034

- --8208010014 Requests issuance of final statement clearing RL Cloud Associates from allegations of wronddring in preparation of "Preliminary Rept Seismic Verification Program," per NK(investigation results in NUKEG-0862; Issue 7 CLOUD, R L. Robirt L. Cloud Associates, Inc. 82/09/24 PALLADINO, N. J. Commissioners 3pp 20713-032 247 Fiche 50-275,83/06/15-8310110034
- --8310110039 Forwards draft itrs to Subcommittee on Energy & Environ & Subcommittee on Energy Conservation & Power transmitting NR(review of NUREG-0862 Comments requested by 820811 MAMMERER.C Office of Congressional Affairs 9:708/09 BICKMIT.L Office of the General Counsel CUMMING's.J Office of Inspector & Auditor FITZGERAID.J Uffice of Investigation 5pp 20713 008 24% Fiche 50-275.83/06/15.8310110034
- ~~8310110046 Responds to 81121/ 1tr expressing concernite delays in licensing process Immediate issue concern acceptability of util proposed auditors.RI Cloud Assoc Investigation scheduled for completion on 021108 & 030201 KAMMERER.C Office of Congressional Affairs 0.7/01/10 ROUSSEL07.JH House of Rep. 1p 20713 013 24X Fiche 50-275.83/06/15.83101100J4
- --8310110048 "Chionolgy of Events" • Affiliation Unknown 83/06/15 Upp 20713 015 24x Fiche 50-2/5.83/06/15 8310110034
- --8310118057 Draft ltrs re adequacy of NRC investigation into development of RL Cloud Assoc rept.per NUREG-086% "Insp Rept of Preliminary Rept. Seismic Reverification Program at Diahlo Cangon Nuclear Power Plant"

 PALLADING, N. Commissioners 83/06/15 UDALL, M. K. Rouse of Rep., Interior & Insular Affairs OffingER, R. DingELL, J. House of Rep., Energy & Commerce 7pp 20/13 074 24X
 Fiche 50-275,83/06/15,8310110034
- --8310110095 Forwards Rt Cloud 820824 request for final statement on conclusions of Cloud/util investigation to clear Cloud prof reputation Matter presented in NUREG-0862 & SECV-82 89 Commission guidance requested DIRCKS.W J Office of the Executive Director for Operations 83/09/08 PALLADINUN Commissioners ip 20/13 031 24% Fiche 50-275.83/06/15.83101100.14
- --8310110107 Forwards Summary documenting record actions of peer review group REMM.T A Diffice of the Executive Director for Operations, 82/02/18 PALLADIND,N., GILINSKY.V., BRADFORD.P. (ommissioners 1p 20713 034 24X Ficho 50-275.83/04/15.8310110074
- --8310110111 Forwards summary of Region V peer review gloup assistance w/
 investigation of RI Cloud Assoc Related info encl
 CORNELL, E K. Office of the Executive Director for Operations
 CASE, C G. Office of Nuclear Reactor Regulation, Director
 SNIEZER, J. H. Director's Office, Office of Inspection and
 Enforcement 82/02/18 DIRECTS, W. J. Office of the Executive
 Director for Operations //pp //0/13/037 24x
 Fiche 50-275.83/06/19,8310110034
- 8310270255 FOIA request for Polk & Schierling 830218 mimo to Knighton & Lear re reverification program to be placed in PDR BUCKLES,R NUS Corp 83706/30 Division of Rules and Records Ip 20943 066 24% Fiche 50-275.83/06/30.831027025
- 0310270250 Responds to FOLA request for Folk & Schierling 030210 memo to Knighton & Lear re reverification program Memo placed in FOR FELTON.J M. Division of Rules and Records. 83/07/15 BUCKLES.R
- PDR FELTON.J M Division of Rules and Records 83/07/15 BUCKL⁵5,R NUS Corp Ip 20943 065 24% Fiche 10-275,83/07/15,83102/0250
- 8310180609 FOIA request for complete set of BNL repts on seismic design of facilities CALSBYAG, C.D. Affiliation Unknown 83/08/16 Region 5, Office of Director App 20824 315 :4X Fishe 50-275,83/08/16.8310180609
- 8310180610 Responds to FOLA request for complete set of BNL repts on serianic design of facilities flocuments listed in app awailable in PDN
 FELTON, J M Davision of Rules and Records 83/09/01 CALSDYAS, C D
 Affiliation Unknown 2pp 20824 319 24X Fiche 50-275,83/09/01,
 8310180610
- --8310180613 Summary & evaluation rept of Rt Cloud & Ashoc rept, 'Diable Canyon Unit 1 IDVP Verification Program for PC&L Corrective Action "

 Brookhaven National Laboratory 8.//09/01 4pp 20824 J/1 24X Fichs 90 275,03/09/01 030(00010)

- --8310180615 Summary & evaluation rept of RF Reedy rept, "Development of Svc-Related Contractor List for Nonseismic Design Work Performed for Diablo Campon Nuclear Power Plant, Unit 1 Prior to 780601. Phase 11 "

 * Brookhaven National Laboratory 83/09/01 3pp 20824 325 24X Fiche 50-275, 83/09/01, 8310180610
- --8310180617 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP Verification of Design Analysis Hosgii
 - # Brookhaven National Laboratory (24X Fiche 50-275, 83/09/01, 8310180610 83/09/01 3pp 20824 3/8
- --B3101B0619 Summary & evaluation rept of RL Cloud & Assoc rept "Diable Canyon Unit 1 IDVP Soils Intake Structure "
 * Brookhayen National Laboratory 83/09/01 Spp 20824 331
 24X Fiche 50-275, 83/09/01, 8310180610
- -8310180621 Summary & evaluation rept of RL Cloud & Assoc rept, "Diablo Canyon Unit 1 IDVP Soil Outdoor Water Storage Tanks " * Brookhaven National Laboratory 83/09/01 3pp 20824 334 24X Fiche 50-275,83/09/01/8310180610
- --8310180624 Summary & evaluation rept of RL Cloud & Assoc rept, "Diable Canyon Unit 1 INVP HVAC Components"

 * Brookhaven National Laboratory 8.4/09/01 5pp 20824 34.4
 24X Fiche 30-275.83/09/01.8310180610
- --8310180626 Summary & evaluation rept of AL Cloud & Assoc rept, "IDVP Valves 1 * Brookhaven National Laboratory 83/09/01 4pp 20824 348 24X Fiche 50-275,83/09/01,8310180610
- E310060509 Forwards FR monthly notice of applications & amends to OLs involving NSHC, dtd 830823
 # Office of Nuclear Reactor Regulation, Director 83/09/09
 SCHUYLER, J D Pacifit Gas & Electric Co 65pp 20663 187 24X
 Fiche 50-275,83/09/09,8310060509
- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
 EISENHUT.D G Division of Licensing 83/09/29 PALLADIND.N J.
 GILINEKY.V , ROBERTS.T M Commissioners 10pp 20432 104 24X Fiche 50-000,83/09/29,8308300355
- 8308300397 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway EISENHUT, D @ Division of Licensing B3/09/29 PALLADING OILINGKY, V, ROBERTS, T Commissioners 3pp 20632 001 Fiche 50-000, 83/09/29, 8308300357 PALLADINO, N J ,
- 8310040570 Responds to 830328 request for info determining effect of plant operation & maint on archaeological Site Ca-SLO-2 ROs re heavy rainfall & fire causing erosion on 830127 &
- ---8310040578 RO on 830127, personnel noticed erosion near northeastern border of SLD-2 site Caused by excessive runoff from slopes to east due to barren watershed being saturated by heavy rains Corrective actions being assessed CRANE.P A Pacific Qas & Electric Co 83/02/28 ENGELKEN.R H Region 5, Office of Director 2pp 20622,323 24% Fiche 50-275,83/09/29,8310040570
- --8310040585 Submits corrective action plan for erosion incident reported on 830228 Corrective actions gully will be backfulled & new concrate lined drainage ditch will be constructed Actions will be implemented by 830701
 SCRUYLER, J O Pacific Oas & Electric Co 83/05/27 MARTIN, J B Region 5, Office of Director 2pp 20622 325 24X Fiche 50-275,83/09/29,8310040570

- --8310040591 RO on 830427, shell midden for SLO-2 site bladed to max depth of 6 inches Caused by personnel error Disturbed area will be covered w/6 inches of fill Work procedure to increase control being developed
 SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 MARTIN, J B Region 5. Office of Director 2pp 20622 327 24X
 Fiche 50-275,83/09/29,8310040570
- ---8310040598 RO on B30627, penetration approx 20 inches deep & 4-ft wide dug in midden on southern extremity of Site SLD-2 Caused by const personnel error Hole lined w/polyethylene sheet & filled w/road base mat!

 SCHUYLER.J O Pacific Oas & Electric Co 83/07/27 MARTIN, J B Region 5. Office of Director ip 20822 329 24X negion 5. Office of Director 1p Fiche 50-275,83/09/29,8310040570
- 8308300358 Board Notification 83-150 forwards listed repts re facility IDVP Info will be considered in final evaluation of verification of plant mods t matters to be completed for license activities

 EISENHUT.D & Division of Licensing 83/09/30 PALLADIND,N J, QTLINSKY,V , ROBERTS,T M Commissioners 3pp 20644 032 24X

 Fiche 50-275,83/09/30,8308300358
- 8310170185 Trip rept of 830906-07 site visit re mods resulting from verification program to structures, sys & components SCHIERLIND, H Licensing Branch 3 83/09/30 KNICHTON, G W Licensing Branch 3 5pp 20813 027 R4X Fiche 50-275,83/09/30,8310170185
- 8308300763 Board Notification 83-151 provides info re desirability of current ECCB actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT.D 0 Division of Liconsing 83/10/04 PALLADINO,N J, 07LINSKY,V, ROBERTS,T Commissioners 2pp 20698 033 24x Fiche 50-000,83/10/04.8308300763
- 8310120078 Forwards diagram of forces & stresses at OWST foundation, in response to NRC request DENIBONE Robert L Cloud Associates, Inc 83/10/04 SCHIERLING,H Office of Nuclear Reactor Regulation, Director 2pp 20476 165 24X Fiche 50-275,83/10/04.8310120078
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid Valves
 EISENHUT, D O Division of Licensing 83/10/06 PALLADING, N
 Commissioners 31pp 20818 001 24X Fiche 50-000.83/10/06.83083007/1
- 8310140121 Submits current status rept of actions taken in response to Oeneric Ltr 83-28 re generic implications of Salem ATMS event Actions to be taken include surveillance testing required by IE Bulletin 83-01 SCHUYLER
- 8310170489 Forwards addl info re alternate methods of statistical evaluation of Superstrut spot weld shear strength test data, in response to NRC request Test data evaluation presented in 930701 rept remains reasonable & valid SCHUYLER.J O Pacific Cas & Electric Co B3/10/07 EISENHUT, D Ø. Division of Licensing. 3pp 20783 315 24X Fiche 50-275,83/10/07,83/10/07,83/10/0898
- 8310170285 Augments 830701 submittal re masonry walls Addl info re turbine bldg tornado loads sufficient to completely address allegation on tornado design criteria re masonry walls, per DS Fleischaker 830328 ltr
 SCHUYLER.J D Pacific Oas & Electric Co 83/10/11 E18ENNUT, D Q. Division of Licensing 3pp 20/86 194 24X Fiche 50-275,83/10/11, 8310170285
- 8310180458 Forwards additinfo on containment integrity, per NRC request, Description of work involved in adding attachments to containment liner provided SCHUYLER.J D Pacific Gas & Electric Co 83/10/12 FIBENHUT, D C. Division of Licensing 2pp 20802 066 24X Fichs 50-275,83/10/12,83/10/12 8310160458
- 8310210154 Requests publication of FR notice of consideration of issuance of amend to License DPR-76 & proposed NSHC determination & opportunity for hearing re-physical security plan NBHC determination available in Central Files KNIGHTON, 0 W Licensing Branch 3 83/10/13 MILLER, J R Operating Reactors Branch 3 2pp 20883 359 24X Fiche 50-275.83/10/13, 8310210154

- 8310210227 Forwards "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities "
 8CHUYLER, J O Pacific Gas & Electric Co 83/10/13 EISENHUT, D G
 Division of Licensing ip 20852 112 24X Fiche 50-275,83/10/13,8310210227
- --8310210229 "Seismically Induced Sys Interaction Program (915)P)
 Completion of Containment Activities "
 # Bechtel Corp 83/10/13 262pp 20852 113 24X
 Fiche 50-275,83/10/13.8310210227
- B910280197 Forwards transmittal pages to Rev 3 to DCNP-IDVP-PP-007 covering HV-104, "Computer Output," addl info re pad bending stress for support 595/41A & calculations for U-192-1 DENISON, E Robert L Cloud Associates inc 89/10/13 DENYON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Oas & Electric Coopp 20929 242 24% Fiche 50-275, 83/10/13, 8310280157
- B30B300775 Board Notification B3-135A forwards B30919 revised draft of "GA Case Study Working Paper Case C." & cover & transmittal memos re Diablo Canyon
 EISENHUT,D 9 Division of Licensing 83/10/14 PALLADIND,N J.
 GILINSKY,V , ROBERTS,T Commissioners 3pp 20799 001 24X
 Fiche 50-000,63/10/14,8308300/75
- --B3101B0505 Informs that working papers for three GA case studies complete, per B30923 memo Case C re Diablo Canyon, dtd 830919, is rev to B30719 draft transmitted in Board Notification 83-135 on B30902 Papers & transmitted itrs forwarded TAYLOR, J M GA Branch B3/09/28 EISENHUT, D G Division of Licensing 2pp 20799 004 24% Fishe 50-000, B3/10/14, B30B300775
- --B310180311 Forwards case study working papers for site,per review of GA program for plant design & const final Congressional rept will contain consolidated summary of case study conclusions TAYLOR.J M GA Branch 83/08/02 MANEATIS.G A Pacific Gas & Electric Co Ip 20799 006 24% Fiche 50-000.B3/10/14.8308300775
- ~~8310180517 Forwards revised draft of "GA Case Study Working Paper Case C * ALTMAN,W D NRC - No Detailed Affiliation Given 83/09/27 NRC - No Detailed Affiliation Given 1p 20799 007 24X Fiche 50-000,83/10/14,8308300775
- --8310180521 Revised draft of "GA Case Study Working Paper Case C "

 * NRC No Detailed Affiliation Given 83/09/19 NRC No
 Detailed Affiliation Given 42pp 20799 008 24X
 Fiche 30-000,83/10/14.8308300775
- 3310190197 Advises that qualification terts for special rods & couplers revealed straight rods removed from Unit 2 rupture restraints had heat withing the ductilities less than design Rods will be reannealed or replaced SCHUYLER. J D Pacific Gas & Electric Co 83/10/04 EISENHUT, D. 6. Division of Licensing 2pp. 20818 102 24% Fiche 50-275, 83/10/14, 8310190197
- 310200260 Responds to EG&G Phase I recommendations re special lifting device.per NUREO--0612, "Control of Heavy Loads." Util 830509 commitment to restrict crane hoist specds reduced possibility of overstress in lifting devices SCHUYLER, J.O Pacific Gas & Electric Co 83/10/14 KNIOHTON, G, W Licensung Branch S 8pp 20830 078 24X Fiche 50-2/5.83/10/14, 8310200260
- 310210247 Forwards addl info to identify all masonry walls associated w/4 16 kV vital switchgear & cable spreading rooms located in turbine bldg, including clarification of evaluation methods & criteria used.

 SCHUYLER, J D Parific Cas & Electric Co 83/10/14 EISENHUT, D G Division of Licensing App 20851.271 24X Fiche. 50-275, 83/10/14, 8310210247
- 310190034 Forwards documents NRC delivered to Commissioner Gilinsky during 831017 briefing on plant design reverification OILINSKY, Commissioners 83/10/17 Défice of the Executive Legal Director 20pp. 20820-239 24K Fiche 30-275,83/10/17,833118/00-275,83/10/17,
- 308310029 Board Notification 83-161 forwards anonymous ltr alleging errors in design/documentation of safety-related sys, structures & components at Unit 1 EISENHUT.D 0. Division of Lounsing. 83/10/18, PALLADIND,N. GILINSKY,V. ROMERTS.T Commissioners. 4pp. 20700 075 24X Fiche 50-275,83/10/18,8308310029.

- --8310250348 Requests that NRR take lead responsibility for resolution of allegations re errors in design/documentation of safety-related structures, sys & components, documented in encl anonymous ltr
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/12 EISEN/RUT, D 6 Division of Licensing Ip 20700 080 24% Fiche 50-275,83/10/18,8308310027
- --8310250351 Anonymous Itr alleging errors in design/documentation of safety-related structures, sys & components
 * Affiliation Unknown 83/10/07 Region 5, Dffice of Director 3pp 20900 081 24% Fiche 50-2/5.8 //10/18.8308310027
- G Inspection reports: IE Bulletins & correspondence
- B310250416 Forwards std order for DOE work, "Specialized Insp Support - Technical Assistance for Diablo Canyon - Design Verification Program" ADAMS.C Energy, Dept of FIN B-8552 83/09/16 MARTIN, J B Region 5. Office of Director ip 20877 184 24X Fiche 30-275,83/09/16.8310250416
- --B310250423 Std order for DOE work "Specialized Insp Support Technical Assistance for Diablo Canyon - Design Verification Program," issued to LLL MARTIN, J B Region 5. Office of Director MACRUSKY, J Energy, Dept of FIN N-8552 B3/09/16 ip 20897 185 24X Fiche 50-275,83/09/16,8310250416
- 8310040221 Forwards IE Insp Regts 50-278/83-25 & 50-323/83 18 on 830746-22 & 0818 No moncompliance noted NGRERHAUG, L R Region 5, Office of Director 83/07/20 SCHUYLER, J O Parific Gas & Liectric Co 2pp 2061/ 250 /1). Fiche 50-275, 83/09/20, 8310040221
- ---B31004022& IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718 22 & OB18 No noncompliance noted Major areas inspected emergency preparedness program including emergency detection & classification & protective action decisionmaking BCOWN K & BCHUBTER: M D Region 5. Office of Director 83/07/19 13pp 20517 252 24% Fiche 50-275,83/09/20,8310040221
- 8310170473 Forwards IE Insp Repts 90-275/83-28 & 50-323/83-20 on 830731-0903 No noncompliance nated 81940P.T W Division of Resident Reactor Project & Engineering Programs 83707/22 SCHUYLER, J D Pacific Oas & Electric Co 2pp 20783 308 24% Fiche 50-275,83/09/22,8310170473
- --B3101704/9 IE Insp Repts 50-275/B3-28 & 50-323/B3-20 on B30731-0703 No noncompliance noted Major areas inspected plant operations, surveillance testing, maint, independent insp & followup of noncompliances, open items, allegation & preoperational tests CARLSON. J D. MENDDNCA. M. M. KIRSCH. D F. Region 5, Office of Director 83/09/21 Gpp 20783 307 24% Fiche 50-275,83/09/22, B310170473
- 8308300340 IE Info Notice 83-41, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list entl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 839103) 83/09/24 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/24,8306.00340
- 8308300342 IE Info Notice 83-62. "Failure of Rodundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list enci JORDAN, E L. Division of Emergency Preparedness & Lagineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308380342
- B30B300345 IE Info Notice B3-63. "Potential failures of Westinghouse Type SA-1 Differential Relays." Svc list encl JDRDAN.C L Division of Emergency Preparadoness & Engineering Response (Post B30103) B3709724 Consolidated Edison Co of New York, Inc 118pp 20778 001. 24X Fiche 50-000.83/09/26.8308700345
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evaluation " Svc list encl JORDANIC L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Int 115pp 20716 324 24X Fiche 50-000,83/09/29.8308300349
- 8308300378 IE info Notice 83-65, "Surveillance of Flow in R1D Bupass Loops Used in Hestinghouse Plants "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

- 8308300752 IE Info Notice 83-66. "Latality at Argentine Critical
- 6310140121 Submits current status rept of actions taken in response to Fig. 40121 Submits current status rept of actions taken in Generic Ltr 83-28 re generic implications of Salem ATWS event Actions to be taken include surveillance testing required by IE Bulletin 83-01 SCHUYLER, J C. Rochester Gas & Electric Corp. 83/10/07 KNIGHTON, G W. Licensing Branch 3 2pp. 20763-0/6 24 Fiche 50-275,83/10/07,8310140121
- 8308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of Now York, Inc 117pp 21043 075 24X Fiche 50-000, B3/10/11, 8308300/59
- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New Yark. Inc. 120pp 20827 129 24X Fichs 50-000.83/10/11,8308J00/61
- 83i0170539 Forwards Amend 6 to 1 scense DPR-76 & safety evaluation Safety evaluation withheld (ref 10CFR73 21) Amend requires implementation of approved physical socurity plan KNIGHTON.O W Licensing Blanch 3 83/10/11 FURBUSH, M H Pacific Gas & Clectric Co 4pp 20784 203 24X Fiche 50-275.83/10/11, B310170539
- --8310170842 Amend & to License DPR-76, changing vital area access controls EISENHUT.D G Division of Liconsing 83/10/11 2pp 20784 207 24X Fiche 50-275,83/10/11,8310170339
- 8310310332 Forwards IE Insp Repts 50-275/83-29 & 50-323/83-21 on B30827-0902 & 06-09 No noncompliance noted
 BISHOP: | W Division of Resident Reactor Project & Engineering
 Programs B3/10/13 SCHUYLER, J O Pacific Qas & Llectric Co
 20960 311 24X Fiche 50-275, B3/10/13, B310310332
- --8310310341 IE Insp Repts 50-275/83-29 & 50-323/83-21 on 830827 0702 & 110310341 IE Insp Repts 50-27/183-29 & 30-323/83-21 on 830827 0902 & 08-07 No noncompliance noted Major a roas inspected const activities, including licensee action on previous insp findings.IC info notices & deficiencies under 100(1850 55e MERNANDEZ, 0 H . KIRSCH.D F Region 5. Office of Director 83/10/07 11pp 20960 313 24X Fiche 50-275,83/10/13,83103103032
- --8310310346 "Insp Repts." Jul 1983 * EG&G, Inc FJN 8-8552 83/07/31 NRC No Detailed Affiliation Given 12pp 20960 324 24X Fichs 50-275.83/10/13. 8310310332
- --8310310354 "Insp Repts," Aug 1983 * E0&G, Inc FIN 8-8522 83/08/31 NRC No Dutailed Affiliation Given 21pp 20960 336 24% Fiche 50-275,83/10/13,
- 8310200180 Ack receipt of 830927 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-275/83-24 & 50-323/83-17 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/14 SCHUYLER, J O Pacific Gas & Electric Co Jp 20835 072 24X Fiche 50-275, 83/10/14, G310300180
- --8310200183 Responds to NRC 830826 ltr re violations noted in II Insp Repts 50-275/83-24 & 50-323/83-17 Corrective actions locking devices on Unit 1 pipe support 46-9V existed on both spring cans Turnbuckles verified by Pullman Power Products SCHUYLER, J O Pacific Gas & Electric Co 83/09/27 MAR(IN, J R Region B, Office of Director App 20835 073 24X Fichs 50-275.871(0)/4.8310200180 Fiche 50-275,83/10/14,8310200180
- --0310310251 IE Insp Repts 50-275/83-30 & 50-323/83-22 on 830904-1001 No noncompliance noted Major areas inspected surveillance testing, mainto independent insp. followup of open items & allegations, preoperational testing/results & plant tours MENDONCA, M M , KIRBCH, D F Region 5, Office of Director 03/10/13 iOpp 20947 184 24% Fiche 50-275,83/10/14.8310310244

- 8310280036 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-13 & 50-323/83-10

 815809.T W Division of Resident.Reactor Project & Engineering Programs 93/10/21 SCHUYLER.J 0 Parific Gas & Electric Co 1920/934 325 24% Fiche 50-275,83/10/21,8310280036
- --B3102B004B Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-275/83-13 & 50-223/83-10 Corrective actions says for maintaining welder qualification files revised Only qualified welders on active list allowed to draw rods SCHUYLER, J. D. Pacific Ons & Electric Co. B3/09/16 MARTIN, J. B. Region 5. Office of Director 5pp 20934-326 24X Fiche 50-275,83/10/21,8310280036
- B310280060 Ack receipt of 831011 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-275/83 08 BISHOP.T W Divisson of Resident.Reactor Project & Engineering Programs 83/10/21 SCHUYLER.J O Patific Gas & Electric Co ig 20935 051 24X Fiche 50-275/83/10/21.8310280060
- --8310280067 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-275/83-08 Corrective actions Procedure GCP-5A revised to clarify requirements for stamping welders & inspectors Add training conducted SCHUYLIR, J O Pacific Oas & Electric Co 83/10/11 MARTIN, J B Region 5, Office of Director 8pp 20935 052 24X Fiche 50-275,83/10/21,8310280060
- 8310310274 Forwards Allegation RV-83-A-0047 re RHR sys Allegations previously addressed in IE lnsp Rept 50-275/82-42 in response to 820820 ltr Task interface agreement suggested BISHDP, T H Division of Resident, Reactor Project & Engineering Programs 83/10/26 EIBENHUT, b O Division of Licensing App 20761 303 24% Fiche 50-275,83/10/26,8310310274
- --8310310281 Ack receipt of NRC response to 820820 allegations re facility RHR sys Allegations paraphrased by inspector in IE Insp Rept 50-273/82-42 misinterpreted COOPER, J. H. Affilsation Unknown 83/10/20 BISHOP, T. W. Div of Resident, Reactor Project & Engineering Programs 8pg 20961 305 24% Fiche 50-275,83/10/24,8310310274 Division
- R Periodic operating reports & related correspondence
- B310190081 Monthly operating rept for Aug 1983 W/830901 ltm KELLY, W J., THORNDERRY, R C Pacific Gas & Electric Co B: Division of Data Automation & Hanagement Information 5pp 20823 254 24X Fiche 50-275,83709701.8310190051 83/09/01
- 8310040509 Forwards Rev 1 to "IDVP Intake Structures," interim Technical Rept 98 " DENISON.E Robert L Cloud Associates. Inc. 83/10/01 DENTON.H R Office of Nuclear Reactor Regulation. Director MARTIN.J B Region 5. Office of Director MANEALIS.O H Pacific Gas & Flectric Co ip 20627 241 24X Fiche 50-275.83/10/01.8310040509
- --- 8310040915 Rev 1 to "IDVP Intake Structures," interim Technical Rept 58 " ★ Robert L rt L. Cloud Associates, Inc. P105-4-839-058 R01 | 83/10/01 | 20627 242 | 24% Fiche 50-275,83/10/01.8310040509
- 8310070208 Forwards Rev i to "Diablo Canyon Unit i IDVP Verification of Corrective Action, Auxiliary Bldg," Interim Technical Rept 55 55
 DENIGON,E Robert L Cloud Associates, Inc 83/10/01 DENIGN, Poffice of Nuclear Reactor Regulation, Director MANEATIS, G H Pacific Gas & Heatric Co MARTIN, J D Region 5, Defice of Director 19 20457 201 24X Fiche 50-275, 83/10/01, 8310070208 DENT ON H R
- --8310070212 Rev I to "Diable Canyon Unit 1 IDVP Verification of Corrective Action, Auxiliary Bldg," Interim Technical Rept 55 55 STEPHENS, V M , DENISON, E Robert L Cloud Associates, Inc P 103-4-839-055 RO1 83/10/01 110pp 20637 203 P4X Fiche 50-275,83/10/01,83100/0208
- 8310070086 Forwards Rev i to "IDVP Verification of Corrective Action-Small Bore Piping," Interim Technical Rept 61 DENISON,E Robert L Cloud Associates, Inc. 83/10/02 DENTON,H R Office of Nuclear Reactor Regulation, Director MARTIN,J R Region 5. Office of Director MANEA115,0 H Pacific Gas & Electric Co ip. 20658 122 24% Fiche 50-275,83/10/02,8310070086,
- --8310070091 Rev i to "IDVP Verification of Corrective Action-Smell Bore Piping," Interim Technical Rept 51 DENISON.E . BROWNE.C I Robert L Cloud Associates, Inc. P 105-4-839-061 ROI 83/10/02 118pp 20658 123 24X Fiche 50-275,83/10/02,8310070086

- B310070151 Forwards Rev 1 to "IDVP HVAC Ducts, Electrical Raceways, Instrument Tubing & Associated Supports," Interim Technical Rept 63
 BENISON,E Robert L Cloud Associates, Inc. 83/10/02 DENION H R Office of Nuclear Reactor Regulation, Director MARTIN,J B Region 5, Office of Director MANEAIJS, C H Pacific Gas & Electric Co 1p. 20657 089 24X Fiche 50-275.83/10/02,8310070151
- --8310070155 Rev 1 to "IDVP NVAC Ducts Electrical Raceways, Instrument Tubing & Associated Supports," Interim Technical Rept 63 ** Robert L Cloud Associates, Int. P105-4-839-063 ROI 83/10/02 103pp 2065 091 24% Fiche 50-275, 83/10/02.8310070151
- 8310070094 Forwards Rev 1 to "IBVP Verification of Corrective Action-Containment Bidg," Interim Fechnical Rept 54 DENISON, E. Robert L. Cloud Associates, Inc. 83/10/04 DENION, H. R. Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director MANEATIS-8 H. Pacific Cas & Flectric Co 1p. 20458-046 24X Fichs 50-275,83/10/04,8310070094
- --8310070100 Rev 1 to "IDVP Verification of Corrective Action-Containment Bldg," Interim Technical Rept 54 DENISON:E, STEPHENS.V M Robert L Cloud Associates, Inc. P 105-4-839-054 R01 83/10/03 74pp 20658 047 24X Fiche 55-275.83/10/04.8310070094
- 8310070215 Forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Review of Corrective Action, Large & Small Bore Pipe Supports."
 Interim Technical Rept 60
 DENISON, E Robert L Cloud Associates, Inc 89/10/04 DENION, H R
 Office of Nuclear Reactor Regulation, Director MARTIN. J D Region
 5, Office of Director MANEATIS Pacific Gas & Electric Co Ip
 20457 315 24X Fichs 50-275.83/10/04.8310070215
- --8310070227 Rev I to "Diablo Cangon Unit i IDVP Review of Corrective Action.Large & Small Bore Pipe Supports," Interim Technical Rept 60 DEMISSON,E Robert L Cloud Associates, Inc. P105-4-839-060 R01 83/10/03 90pp 20657 317 24X Fiche 50-275,83/10/04.8310070215
- B310070251 Forwards Rev 1 to "Diablo Canyon Unit 1 11979 Verification of Harding Lawson Assoc Boils Work," Interim Technical Rept 68 Rev completes 1079 verification of soils work BENIBON.E Robert L Cloud Associates, Inc 83/10/05 DENTON.H R Office of Nuclear Reactor Regulation, Director MARTIN.J Region 5, Office of Director MARTIN.J Region 5, 20655 029 24% Fiche 50-275,83/10/05,89/10070251
- --8310070297 Rev i to "Diable Campon Unit i IBVP -- Verification of Harding Lawson Assoc Soils Work," Interim Technical Rept 68 STEPHENS: V N . BENTSON. E . MCNEILL. R Robert L. Cloud Associates, Inc P105-4-839-068 ROI B2/10/04 129pp 20655 030 24X Fiche 50-275, B2/10/05, B310070251
- 308300766 Board Notification 83-134 forwards Rev I to "Dioblo Conyon Unit I IDVP Verification of Corrective Action Turbine Bldg," Rev I to "Information Items re Large Dore Piping" & transcript of 830928 meeting w/util EISENHUT. D 0 Division of Licensing 83/10/07 PALLADIND, N J , OfLINSKY, V , ROBERTS, T M Commissioners 3pp 20782 188 24X Fiche 50-275,83/10/07,8308300786
- 8310170214 Forwards Rev O to "Diablo Canyon Nuclear Power Plant IDVP Executive Summary " COOPER: W E Teledyne Engineering Services 83/10/10 DENION, H R Office of Nuclear Reactor Regulation, Director MANEATIS, G A Pacific Gas & Electric Co ip 20784 330 24X Fiche 50-275,83/10/10.8310170214
- --B310170227 Rev O to "Dieblo Canyon Nuclear Power Plant IDVP Executive Summary " * Teledyne Engineering Services 83/10/10 15pp 20784 331 24X Fiche 50-275,83/10/10,8310170214
- 310170646 Forwards Rev O to "Diable Canyon Nuclear Power Plant, Unit 1 10VP," final rept COOPER, H E Teledyne Engineering Services 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director, MARTIN, J II Region 5. Office of Director MANEATIS, O A Pacific Gas & Electric Co App 20781 188 24% Fiche 50-275, B3/10/10, B3101/0646
- -8310170651 Rev 0 to "Piablo Canyon Nuclear Power Plant, Unit 1 1DV/," final rept 4 final rept 4 final rept 50-275, 83/10/10, 8310170646
- 310140117 Forwards Rev 1 to "Diablo Canyon Unit 1 IDVP Verification of Diablo Canyon Plant Activities Rupture Restraints," Interim Technical Rept 65

 DENISON,E Robert L. Cloud Associates, Inc. BD/10/11. DENTON,H R Office of Nuclear Reactor Ragulation, Director MARTIN.J Region b. Office of Director MANEATIS, @ Pacific Gas & Electric Co ip 20762:229 24X Fiche 50-275,83/10/11,8310140117.

- --8310140119 Rev i to "Diablo Canyon Unit i IDVP Verification of Diablo Canyon Plant Artivities Rupture Restraints." Interim Technical Rept 65
 DENISON.E , ANDERSON.P H Robert L Cloud Associates, Inc. P. 105-4-839-065 ROI 83/10/11 65pp 20762 231 /1X
 Fiche 50-275,83/10/11,8310140117
- 8308300781 Board Notification 83-156 forwards RL Cloud Assoc & leledgik Engineering Svcs repts re IDV/ EISENHUT.D G Division of Licensing 83/10/14 PALIADIND,N, GLINSKY,V, RORERTS.T Commissioners 4pp 20875 122 ,44X Fiche 50-275,83/10/14,8308300/ul
- 8310210233 Forwards "Diable Cangen Verification Program, Semimenthly Status Rept 47." per Commission Order CLI-81-30 Rept summarizes progress of technical work from 830920-1010 SCHUYLER, J O Parific Gas & Electric Co 83/10/14 PENTUN, H k Office of Nuclear Reactor Regulation, Director MARCIN, J L Region 5, Office of Director 2pp 20051 307 24X Fich: 10-275,83/10/14,8310-10237
- --8310210235 "Diablo Canyon Verification Program Semimonthly Status Rept 47," summarizing progress from 830920-1010 * Pacific Gas & Electric Co 83/10/14 69pp 20851 304 24y Fiche 50-275,83/10/14,8310210233
- 8310210284 Forwards Rev 14 to "Design Verification Program Phase 1 Final Rept" SCHUYLER, J O Pacific Gas & Llectric Co 83/10/14 FISCNIUT, D & Division of Licensing 2pp 20850 232 24X Fiche 50-275,83/10/14, 8310210284
- --8310210288 Rev 14 to "Design Verification Program Phase 1 Final Rept" * Pacific Gas & Electric Go 63/10/14 171pp 20850 234 24X Ficho 50-275.83/10/14.8310310284
- 8310260260 Forwards "IDVP," second Friday semimonthly rept for Url 1783 COOPER,N E Teledyne Engineering Services 83/10/14 DENIUN.N R Office of Nuclear Reactor Regulation, Director MARTIN.J B Region 5, Office of Director MANEATIS.G A Pacific Gas & Cleatic Co 1p 20911 327 24X Fiche 50-275,83/10/14,8310260260
- --8310260264 "IDVP," second Friday semimonthly rept for Oct 1983 * Teledyne Engineering Services. 83/10/14 13pp 20911 330 24X Fiche 50-275, 83/10/14, 8310260260
- 8310270241 Forwards list of effective pages to 831010 IDVP final rept Matl replaces previous list as App G d in Vol IV of rept COOPER, W F Telegane Engineering Services 83/10/14 DENION, H R Office of Nuclear Reactor Regulation, Director MANEAIIS, G A Pacific Gas & Floctric Co MRRIN, J B Region 5, Office of Director Ripp 20923 006 24X Fiche 50-275,83/10/14,83102/0241
- 8310250115 Forwards replacement pages to 831014 final update to design verification program Phase I final rept SCHUYLER-J C Parific Gas & Clectric Co 83/10/19 EISENHUT, D 0 Division of Licensing 13pp 20896 272 24X Fiche 50-275.83/10/19, 8310250115
- B Reportable occurrences. LERs & related correspondence
- 8310070158 LER 83-017/03L-0 on 830826, we)ding performed on additive tank w/o draining bank of sodium hydroxide solution Caused by lack of communication Lifect of violation being evaluated Additive tank will be drained W/830926 ltr MELLY, W J . SHIFTER J D Pacific Gas & Electric Co 03/09/26 MARTIN, J B Region 5, Office of Director 3pp 20657 081 24X Fiche 50-275,03/09/26,8310070158
- 83i0120280 Updated LER 83-007/017-1 on 830509, during welding of reinforcement pad on branch connection to loop C component cooling water sys, water leaked from weld area Caused by grinding on fillst overweld Overweld removed W/830926 ltn KELLY, W. J. SMIFFER, J. D. Pacific Gas & Electric Co. 83/09/26 MARTIN, J. B. Region 5. Office of Director 3pp. 20693 003 24% Piche 50-275,83/09/26.8310120280
- 8310040570 Responds to 830320 request for info determining effect of plant operation & maint on archaeological Site Ca-SLO-2 RDs re heavy rainfall & fire causing elosion on 830127 & 0427 encl SCHUYLER, J O Pacific Oas & Electric Co 83/09/29 KNIGHTON, G W Licensing Branch 3 3pp 20622 320 24X Fiche 50-275, 83/09/29, 8310040570

- --B310040585 Submits corrective action plan for grosion incident reported on B30428 Corrective actions qully will be backfilled & new concrete-lined drainage ditch will be constructed drainage ditch will be constructed detains will be implemented by B30701 SCHUYLER, J.O. Pacific Gas & Electric Co. B3/05/27 MARTIN, J.R. Region 5, Office of Director 2pp. 20622 325 24% Fiche 50-2/5, D3/09/29, G3100405/0
- --9310040591 RO on 930427, shell midden for 5LO-2 site bladed to max depth of 6 inches Caused by personnel error Disturbed area will be covered w/6 inches of fill Work procedure to increase control being developed SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 MARTIN, J R Region 5, Office of Directo. 2pp 20622 327 PAX Fiche 50-275, 83/09/29, 8310040570
- --8310040598 RO on B30427, penetrotion approx 20 inches deep & 4-ft widt dug in midden on southern extremity of bite SLD-2 Caused by const personnel error Hole lined w/pulyethylene sheet & filled w/mad bore mati SCHUYLER, JO Pucific Gas & Electric Co B3/07/27 MARTIN, J B Region 5, Office of Directol 1p 70622 329 24X Fiche 50-275,83/09/29,83J00405/0
- 9310120136 LER B3-022/03L-O on 830831, volve MU-0-268 shut for 36 minutes, isolating raw water receivoir from fire suppression header, rendering fire suppression water sys inoperable Laused by broken underground water supply line W/830930 lt; KELLY, W. J. SHIFFIR, J. D. Paryfix Gas & Electric Co. 63/09/30 MARTIN J. B. Region 5, Office of Director. 3pp. 20695-287, P4X Fiche 50-275, 83/09/30, 8310120136
- 8310120362 RO on 830902, during underwater environ monitoring, discovered sediment accumulation on sea floor rosulting in mortality of some hottom duciling marine invertebrates Caused by pumping during grout mix discharge norzie transfer SCHUYLEK., J. O. Pacific Gas & Flootiic Co. 83/10/03 MARTIN, J & Region 5. Office of Director 2pp. 20699 300 24X Fiche 50-275,83/10/03.8310120362
- B310120066 PND-V-83-044 on B31003, employee suffered heart attack during work Personnol taken to hosp No news release planned MRRFLLLP J. Region 5 Office of Director 83/10/04 jp 20676 157 24X Fiche 50-2/5,83/10/04,8310120066
- 8310250939 LER 83-020/03L-0 on 830723, prior to fuel load, gaseous radwaste sys noble gas activity monitor RM-22 failed in svc Caused by detector tube failure due to natural end-of-life New tube installed & monitor tested W/831012 ltr KELLY, W. J. SHIFFER, J. D. Pacific Gas & Electric Co. 03/10/12 MARTIN, J. B. Region 5, Office of Director. Spp. 20402-055 MX Fiche 50-275, 03/10/12.8310250537
- 831025010B Advisos that on B31013, Pacific Scientific Co provided infore possible defects in snubbers installed at facility Util determined that 43 snubbers affected Snubbers being replaced SHIFFER. J B Pacific Gas & Lighter Co B3/10/13 MARTIN, J B Region 5. Office of Director ip 26876 249 PAX Fiche 50-275,83/10/13,8310250108
- 8310250639 Updated LER 83-006/01:-1 on 830510, possible undersize condition discovered on reactor coolant piping weld WIB-RC-2-17 during ultrasonic testing Weld confirmed to be above min wall requirements mechanically W/831013 lt; KELLY, W. V. SHIFFLER, J. D. Pacific Gas & Electric Co. 83/10/13 MARTIN, J. B. Region 5. Office of Director. 3pp. 20000 293 24X Fiche 50-275, 83/10/13, 8310250639
- 8310270376 Updated LER 83-019/03L-1 on 8J0826, welding priformed un additive tank w/o first draining tank of sodium hydroxide solution Caused by lack of communication to field No evidence of cracks or corrosion observed W/831020 ttr KELLY,W J. SHIFFER,J D. Pacific Gas & Electric Co. 83/10/20 MARTIN,J B. Region 5. Office of Director 3pp 20923 288 34X Fiche 50 275.03/10/20.83102703/4
- T Hearing transcripts on non-antitrust matters
- B310050442 Transcript of Commission B30987 briefing in Washington, DC jetacility schedule Pp 1-34 Viewgraphs & supporting documentation encl * Commissioners B3/09/2/ 52pp 20440 218 '4% Fiche 50-275.03/09/27.9310050442

- 8308300766 Board Notification B.J-154 forwards Rev I to "Diablo Campon Unit I IDVP Verification of Corrective Action Turbine Didg."

 Rev I to "Information Items re Large bore Piping" & transcript of E30928 meeting w/util

 EISENNUT D G Division of Licensing 83/10/07 PALLADIND, N J , GILINSKY, V , RUBERTS T M Commissioners 3pp 20702 188 24x

 Fiche 50-275.83/10/07.8308300766
- --8310170318 Transcript of 830928 technical conference w/utils & BNL in Bethesda. MD re SSER open items Pp 1 -164 * Commissioners 83/09/28 416pp 20782 191 24X Fiche 50-275.83/10/07.8308300726
- 8310(80354 Forwards IDVP testimony
 AXELRAD.N Lowenstein, Newman, Reis, Azelrad & Toll 83/10/14
 MODRE.T S. BUCK, J H., JOHNSON, W. R. Atomic Safety and Licensing
 Appeal Panel 2pp 20804 104 24X Fiche 50-275,83/10/14.
 8310180334
- --8310180361 Testimony of WE Couper.Rt. Cloud.JF Krechting & HF Reedy on behalf of 1DVP re Contentions 1.2 & 5-8 Describes role of 1DVP in verification of design work of plant & how IDVP performed work COOPER.WE, CLOUD.R L, KRICHTING.J L Lowenstrin. Newman. Rejs. Axelrad & Toll 83/10/14 59pp 20/04/106 24X Fiche 50-275.83/10/14.8310180304
- --8310180369 Testimony of RL Cloud, JM Blugs, MJ Holley & R Wray on behalf of JDVP re Contentions 3 & 4 m n Discusses allegations of internal technical program use of improper engineering stds to determine if license criteria met CLOUD.R L , BIGGS.J M , HDLLEY.J Lowenstein, Nowman, Rejs, Atelrad & Toll 83/10/14 33pp 20004 165 24% Fiche 50-275.83/10/14,8310180354
- ~-8310180375 Testimony of JE Krichting & WE Cooper on behalf of 1DVP rc Contention 4 a ~1 & a ~v Discusses allegations that 1DVP accepted deviations from lirensing criteria w/o adequate engineering justifications Cotificate of Svc encl KRECHTING J E . COOPER.W E Lowenstvin, Newman, Reis, Arelyad & Toll 83/10/14 71pp 20804 198 24X Fiche 50-2/5,83/10/f4,8310180359
- B310210350 Forwards NRC testimony
 MCGURREN.H J Hearing Branch 1 83/10/14 MODRE.T S , BUCK.J H ,
 JOHNSON.W R Atomic Safety and Licensing Appeal Panel 5pp
 20849 140 24X Fiche 50-275.03/10/14.BJ10210350
- --8310210355 Testimony of IP Knight, He. Schierling & JS Wermie) on Governor Deukmejian & Joint Intervenors Contentions lare KNIGHTI, JP Assistant Director for Comp & Structures Engineering (Post 830201) SCHIERLING, H E Division of Licensing WERNIEL, J S Auxiliary Systems Branch 83/10/14 32pp 20849 145 P4X Fiche 50-275, 83/10/14, 8310210330
- ---8310210357 Testimony of JP Knight.HE Schierling & JS Wermiel on Governor Deukmejian & Joint Intervoners Contentions 2a,2b & 2c KNIGHT, JP Assistant Director for Comp & Structures Engineering (Post 830201) SCHIERLING.H E Division of Licensing WERNIEL J S Auxiliary Bystems Branch 63/10/14 7pp 20849 177 24X Fiche 50-275.63/10/14.8310210390
- --8310210358 Testimony of JP Knight, P Kut. H Polk, CA Niller, A.J Philippacopoulus, CJ Constantino & PC Wang re Governor Deutmejian & Joint Interveners Contention 3 KNIOHT, J P Assistant Director for Comp. & Structures Engineering (Post 830201) KUO, P. POLK, H E Structural & Geotechnical Engineering Dranch 83/10/14 25pp 20849 186 24X Fiche 50-275,83/10/14,8310210350
- --8310210371 Testimony of JS Wermiel on Governor Deukmejian & Joint Intervenors Contentions 4a,4h,4p,4q,4r & 4s WERMIEL,J S Auxiliary Systems Bronch, 83/10/14 10pp 20847 211 24X Fiche 50-275,83/10/14,8310210350
- --8310210382 Testimony of JL Knox re Governor Deukmejian & Joint Intervenors Contentions 4b, 4c, 4g, 40, 4c & 4u KNOX, J L Division of Bystems Integration (post 811005) 83/10/14 Bpp 20849 221 24X Fithe 50-275,83/10/14,8310210350
- ---B310210392 Testimony of TO Dunning re Governor Deukmejian & Joint Intervenors Contention 4-Parts 4.e & f DUNNINO.T G Instrumentation & Control Systems Branch 83/10/14 10pp 20849 229 24X Fiche 50-275.83/10/14.8310210350
- --8310210398 Testimony of DJ Kubicki on Governor Deukmejian & Joint Intervenors Contentions 41,43 & 4k KUBICKI,D J Chemical Engineering Branch 83/10/14 14pp 20849 239 24X Fiche 50-275,83/10/14,8310210350

- ---8310210391 Testimony of P Kuo & HE Polk on Governor Deukmejien & Joint Intervenors Contention An KUO.P. POLK.H E Structural & Geotechnical Engineering Branch 83/10/14 3pp 20849 253 24X Fiche 50-275.83/10/14.83J0210350
- --8310210378 Testimony of PJ Morrill on Governor Deukmejian & Joint Intervenors Contentions 5 & 8 MORRILL.P J Division of Resident, Reactor Project & Enginering Programs 83/10/14 App 20849 256 24% Fiche 50-275,83/10/14, 8310210350
- --8310210381 Testimony of WP Hauss on Governor Deukmejian & Joint Intervenors Contentions & & 8 HAASS,W P GA Branch B2/10/14 4pp 20849 262 24X Fiche 50-275,83/10/14.8310210350
- --8310210385 Testimony of JP Knight & HE Schierling on Governor Daukmejian & Jaint Intervenors Contention 7 RNIGHT, JP Assistant Director for Comp & Structures Engineering (Post 803020) SCHIERLING.H E Division of Licensing 83/10/14 6pp 20849 266 R4X Fiche 50-275.83/10/14.8310210350
- --8310210387 Testimony of JS Wermiel on Governor Deukmejian & Joint Intervenors addl contentions on design QA.Contention 9 HERMIEL.J S Auxiliary Systems Branch 83/10/14 168pp 20849 272 24X Fiche 30-275, 83/10/14.8310210390
- 8310210358 Testimony of JP Knight,P Kuo,HE Polk,CA Miller, AJ
 Philippacopoulos,GJ Constantino & PC Wang re Governor
 Deukmejian & Joint Intervenors Contention 3
 KNIGHT,J P Assistant Director for Comp & Structures Engineering
 (Post 830201) MILLER,C.A., PHILJPACOPOULO NRC No Detailed
 Affiliation 91998 83/10/14 25pp 20849 186 24X
 Fiche 50-275,83/10/14.8310210358
- B310210228 Forwards PJ Kempthorne & FI Samaniego testimony REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J, R Joint Intervenors-Diablo Cangon B3/10/15 MODRE, T S , JOHNSON, W R , BUCK, J H Atomic Safety and Licensing Appeal Panel ip 20852,042 24X Fiche 50-275,83/10/15,8310210228
- --8310210241 Testimony of PJ Kempthorne & FJ Samaniago re Contention 1 un IDVP conclusions in light of sampling methodology Prof qualifications enci KEMPTHORNE, P J, SAMANIEGO, F J Joint Intervenors-Diablo Canyon 83/10/15 22pp 20852 043 24X Fiche 50-275.83/10/15.8310210228
- --8310210242 Exhibit list Certificate of Byc enc)
 REYNOLDS, J Joint Intervenors-Diablo Canyon REYNOLDS, J Center
 for Law in the Public Interest 83/10/15 App 20052 045 24X
 Fiche 50-275.83/10/15.8310210228
- B31020017B Testimony of RB Hubbard re design BA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence HUBBARD.R B California, State of HUBBARD.R B MHB Technical Associates B3/10/16 79pp 20835 129 24X Fiche 50-275, B3/10/16, B31020017B
- --8310200184 Testimony of & Apostolakis re design GA IDVP weak since program fails to recognize implications of decision to cart IDVP in probabilistic terms & fails to use appropriate probabilistic analysis principles & methods
 APOSTOLAKIS, & California, State of APOSTOLAKIS, & California, Univ of, Los Angeles, CA 83/10/16 21pp, 20835 208 24X Fiche 50-275,83/10/16.8310200178
- --8310200190 Testimony of JM Roesset re adequacy of util seismic modeling of structures & soils & of review of util work by IDVP four issues remain requiring further verification Affidavits of qualifications encl
 ROESSEY.J M California, State of 83/10/14 61pp 20835 227
 24X Fiche-50-275,83/10/14,8310200178
- -8310200195 List of exhibits identified per ASLAB 831007 order Certificate of Syc encl STRUMHASSER: N California, State of, 83/10/16 9pp, 20835 287 24X Fiche 50-275,83/10/16,8310200178
- 3102503R6 Forwards corrected Pages 5,6 & 8 to NRC 831014 testiming of JP Knight.HE Schierling & JS Hermiel on Governor Deukmejian & Joint Intervenors Contentions 2a-e Errors due to difficulties w/word processing MCGURREN.H J Hearing Branch & 83/10/19 MDORE.T S , BUCK.J H , JCHNSON.W R Atomic Sefety and Licensing Appeal Panel 2pu 20897 340 24% Fiche 50-275,83/10/19.8310250326

- --B310250332 Corrected Pages 5.6 & B to JP Knight, H. Schierling & JS Wermeil testimony on Governor Deukmeijan & Joint Intervenors Contentions 2a-e KNIOHT, JP, BCHIERLING, HE, WERMILL, JS NRC No Detailed Affiliation Given 83/10/17 3pp ±0877 342 24X Fiche 50-275,83/10/19,8310250326
- B310250176 Forwards H Schierling, W Haass & D Kubicki deposition: & corrections to deposition transcripts W/o depositions MCGURHEN.H J Hearing Branch I 83/10/20 Fayloo Assoriatis Ip 20892 354 24% Fiche 50-275.83/10/20.831025017A
- --8310250182 Corrections to WP Haass B30921.DJ Kubicki B30920 & HE Schierling B30921 depositions HAASB.W P. KUBICKI.D J. SCHILRLING.H E. NRC -- No Detailed Affiliation Given B3709/21 4pp 20892 355 2/47 Fiche D0-275.B3/10/20.83102501/4
- B310280057 Transcript of witness testimony, prof qualifications & exhibits for reopened hearing re design GA Certificate of Svc encl Related correspondence # Pacific Os & Fietric Co B3/10/27 554pp 20935 3/0 P4X Fiche 50-275,83/10/27,8310280057
- U Congressional/Executive Correspondence
- B310110114 Ack receipt of comments on plant licensing Commission deferred final consideration of matter until after NRC completes analysis of final livP rept CHILK.8 J Office of the Becretary of the Commission B3/10/0; HART.6 K (MACON.P , DAVIS.0 California, State of Spp 2048 151 24X Fiche 50-275,83/10/05.8310110114
- ---8310110151 Notifies of Commission 831078 mosting to receive comments from util. Joint Intervenors & Governor Drukmejian re IDVP completion & NRC analysis & recommendation to reinstate DPM-76 to load fuel CHILK, B. J. Office of the Secretary of the Commission B3/09/30 CHILBACH, R. Pacific Gas & Electric Co. REYNOLDS, J. R. (out: For Law in the Public Interest STRUMMASSER, M. California, State of 2pg 20668 154 24% Fiche 50-275, 83/10/05, 8310110114
- 8310200442 Responds to 830722 ltr re NRC handling of several working papers for case studies being conducted to support NRC ript to Congress per Section 13 of NRC Authorization Act firer working papers entl
 PALLADINO.N J Commissioners 83/10/07 FORD.W H Senate Upp 20871 295 24X Fiche 30-000.83/10/07.8310200442
- --8310200469 Expresses disappointment re release of draft study on GA programs at Diablo Canyon to licensee Full explanation requested MARKEY, E. J. House of Reg., Interior & Insular Affairs 93/09/21 PALLADINO, N. J. Commissioners 2pp. 20072 217 PAX Fichs 50-000, 83/10/07, 8310200442
- 8310240169 Advises that State of CA legislator ltrs requesting delays in licensing do not represent policy of CA legislature License issuance recommended ALQUIST.A E California, State of 83/10/17 PALLADINO,N J Commissioners 1p 20880 029 24X Fiche 50-275,83/10/17,8310240167
- 8310250045 Urges NRC to proceed w/o delay w/regulatory steps necessary to allow fuel loading low power testing & commercial operation DELLER C California, State of 83/10/19 PALLADING, N.J. Commissioners 2pp 20894 089 24X Fiche 50-275,83/10/19,
- V Operator Examinations
- G310030205 Informs of periodic audits of licensed apprator requalification programs Behedule for requalification training & exams requested by G31020 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 83709726 SCHUYLEH.J D Pacific Gas & Electric Co 2pp 20591 039 24% Fiche 50-275,83709726.8310030285
- DOCKET 50-277 PEACH SOTTOM ATONIC POWER STATION, UNII 2 F Security, medical, emergency & fire protection plans
- B310050004 Advises that NUREG-0737, Item 11 B 2 2, "Design Review of Flant Shielding Corrective Actions for Access to Vital Areas," requirements met based on review of licensee 800102, 31, 1015,810108,820415,0707 k 830513 submittals STOLT, J F Operating Reactors Branch 4 83/09/12 BAUER, E G Philadelphia Electric Co 5pp 20650 242 24X Fichs 50-277,83/09/12,8310050004

- 8310040434 Forwards safety analysis re basis on which selected parameters for safety parameter display sys sufficient to assess safety status of each Function for wide range of events, per Generic Ltr 82-33. Suppl 1 to NUREO-0737 GALLACHER, J W Philadelphia Electric Co 83/09/28 FISENHUT, D 6 Division of Licensing 8pp 20619 108 24% Fiche 50-277,83/09/28,8310040434
- 8310210269 Forwards 1E Enforcement Conference Repts 50-2/7/83-23 & 50-278/83-23 on 830811 & notice of violation STAROSTECKLIR Division of Project & Resident Programs 83/10/07 BDVER.V Philadelphia Electric Co 2po 20855 248 24X Fiche 50-277,83/10/03,8310210269
- --83102102/4 Notice of vaolation associated w/IE enforcement conference on 830011 * Region i, Office of Director 83/10/03 2pp 20855 250 24X Fichs 50-277.83/10/03.8310210267
- --8310210278 IE (nforcement Conference Repts 50~277/83~23 & 50~278/83~3 on 830811 Major areas discussed violations from IE Insp. Repts 50~277/83~16 & 50~278/83~16 re unscaled penetrations in fire barriers
 BLOUGHAR, WILLIAMS, J. H., TRIPP, L. F., Region 1, Uffice of Director 83/08/22 App. 20805 257 24X Fiche 50~277,83/10/03,8310210269
- 9310280252 Releases public version of revised emergency plan implementing procedures
 FELTON. JM Division of Rules and Records 83/10/25 Decument
 Kanagement Branch ip 2096/3 016 24% Fiche 50-277.83/10/25.
- --B310280257 Forwards public version of Levised emergency plan implementing procedures, including Procedures EP-209, App A re immediate notification call list & EP-209, App D I re onsite emergency team leaders Affidavit encl DALTROFF, B L. Philadelphia Electric Co. B3/05/13 ALLAN, J M Region 1, Office of Director 4pp 20963-017 24X Fiche 50-277, B3/10/25, B3/0380252
- --8310280271 Public version of revised emergency plan implementing procedures; including Procedures EP-209, App A re immediate notification call list & EP-209, App D-1 re onsite emergency team leaders

 * Philadelphia Electric Co 83/04/13 42pp 20963 021 24X Fiche 50-277, 83/10/25, 8310280292
- P Operating license stage documents & correspondence
- B310310017 FOIA request for documents re integrated leak rate tests fur listed facilities to be placed in PDR CONNERL Affiliation Unknown 63/05/02 NRC - No Detailed Affiliation Given 1p 21004 2/0 24% Fiche 50-000.63/05/02, B31031017
- 8310110454 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUREC-06412. "Control of Heavy Loads (Phase I) " Phose I acceptable Need for single failure-proof handling equipment will be addressed in Phase II STOLZ, J F Operating Reactors Branch 4 83/09/21 BAUER, L G Philadelphia Electric Ca Jpp 20712 076 24X Fiche 50-277.83/09/21.8310110454
- --8310110459 Safety evaluation re util 810618,1222,820520,1020 & 830810 responses to NUREG-0612, "Control of Heavy Londs (Phase I) "
 Phase I acceptable
 * NRC No Detailed Affiliation Given 83/09/09 Ppp 20712 079 24X Fiche 50-277,83/09/21,8310110454
- --8309020372 "Control of Hoavy Louds (C-10), Philadelphia Electric Co. Peach Bottom Atomic Power Station, Units 2 & 3." technical evaluation rept BARGEN, I H., BUMBERGER, C. Franklin Institute/Franklin Research Center TER-C5506-379/380 83/08/31 SINGH, A. NRC No Detailed Affiliation Given 32pp 20712 081 24% Fiche 50-277, 83/09/21, 8310110454
- 8310040189 Forwards revised pages to 811223 application for amend to Licenses DPR-44 & DPR-56.changing values of surveillance setpoints, per 830726 telcon GALLAGHER, J W Philadelphia Electric Co 83/09/29 STOL2, J F Operating Reactors Branch 4 2pp 20408 089 24% Fichs 50-277,83/09/29,8310040187
- --8310040191 Revised Tach Spec Pages 36 & 36a listing limiting conditions for operation & surveillance requirements for reactor protection sys power supply * Philadalphia Electric Co 83/09/09 2pp 20608 091 P4X Fiche 50-277.83/09/29.8310040189

- 8310040415 Forwards "Implementation of NUHEG-0619 Feedwater Noirle Cracking," b proprietary "Peach Bottom Atomic Power Station. Unit 2. Feedwater Noirle Fracture Mechanics Analysis to Show "Proprietary rept withheld (ref 10CFR2 790)
 GALLAGHER.J W Philadelphia Electric Co 83/09/29 EISENHUT, D 0 Division of Licensing 2pp 20623 303 24X Fiche 30~277.83/09/29, 8310040415
- --B310040429 "Implementation of NUREO-0619 Feedwater Nozile Cracking " Affidavit encl * Philadelphia Electric Co 83/09/30 19pp 20623 305 24X Fiche 50-277,83/09/29.8310040415
- 8310140203 Submits addl info un 830927 presentation to NRC reintergranular stress corresion cracking insplements. Unit will return to sycle operate for 6 months to exhaust present fuel load Pipe will be replaced beginning Mar 1984 DALTROFF, S.C. Philadelphia Electric Co. 83/10/06 STOLZ, J.F. Operating Reactors Branch 4. 2pp. 20762 356 24X Fiche 50-277, 83/10/06, 8310140203
- 8310200016 Forwards draft SER rc NUREQ-0/37, Item II B 3, "Post-Accident Sampling Sys" Response addressing concerns re three outstanding items requested Telcon to discuss early resolution should be arranged within 30 days of ltr receipt STOLZ. J Deprating Reactors Branch 4 B3/10/06 BAVER. E 9 Philadelphia Electric Co 12pp 20844 249 24X Fiche 50-277,63/10/06.8310200016
- 8310260212 Forwards response to 831004 request re NUREG 0737. Item II E 4 2, "Containment Purge & Vent Valves," design evaluation W/13 oversize drawings Aperture cards are available in PDR DALTROFF, S L. Philadelphia Electric Co. B3/10/19 STDLZ, J F Operation Reactors Branch 4 72pp 20/707 277 24X Fiche 50-277.83/10/19.8310260212
- --8310260239 "Instruction Manual Type 9200 T-Ring Butterfly Valve Bodies" * Fisher Controls Co. 74/03/31 14pp 20909 340 24X Fiche 50-277, 83/10/19, 8310260212
- G. Inspection reports: IE Bulletins & correspondence
- B310250419 Submits partial response to It Bulletin 83-02, "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants " Unit will be returned to svc by B31003 KEMPER, J S Philadelphia Electric Co 83/09/15 MURLEY, T E Region 1. Office of Director Spp 20897 186 24X Fiche 50-277.83/09/15,8310250419
- 8310050051 Requests submittal of response to IE Hulletin 83-02, "Stress Corrosion Cracking in Large-Diameter Stainless Stee! Recirculation Sys Piping at BMR Plants " Info needed to complete pipe crack review & analyses STOLZ, JF Operating Reactors Branch 4 83/09/21 BAUER.L Q Philadelphia Electric Co 7pp 20650 138 24X Fiche 50-277,83/09/21,8310050051
- 8310120212 Forwards IE Insp Repts 50-277/83-19 & 50-278/83-19 on 830718-22 & notice of violation MARTIN T T Division of Engineering & Technical Programs 83/09/22 DALTRUFF, 8 Philadelphia Electric Co 2pp 20492 318 24X Fiche 50-277, 83/09/22, 8310120712
- --8310120213 Natice of violation from insp on 830718-22 * Region 1, Office of Director 83/09/22 2pp 20492 320 24X Fiche 50-277,83/09/22,8310120212
- --B310120217 IE Insp Repts 50-277/83-19 & 50-278/83-19 on 830718-28 Noncompliances noted failure to train personnel in accordance w/Tech Specs & to perform safety evaluation for change in solidification of liquid waste procedure. WHITE, J R . COLLINS, D J . LAMASTRA.M Region 1, Office of Director 83/09/12 16pp 20692, 322 24X Fiche 50-277, 83/09/22, 8310120212
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN, E. L. Division of Emergency Praparedness & Engineering Response (Post 830103), 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300342

- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghour: Type 8A-f Differential Relays " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24% Ficha 50-000.83709726.83083003045
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFRSO 59 Evaluation " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310210269 Forwards IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 87/10/03 80YER, V Philadelphia Electric Co 2pp 20855 248 24X Fiche 50-277,83/10/03,8310210269
- ~-8310210274 Notice of violation associated w/IE enforcement conference on 830811 * Region 1, Office of Director 83/10/03 2pp 20855 250 P4X Fiche 50-277,83/10/03.8310210269
- -8310210278 IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 Major areas discussed violations from IE Insp Repts 50-277/83-16 & 50-278/83-16 re unsealed penetrations in fire barriers. BLOUGH.A R. HILLIAMS.J H. TRIPP.L F Region 1. Office of Director 83/08/22 App 20855 25% 24X Ficho 50-277.83/10/03, 8310210269
- 8310140203 Submits add1 info on 830929 presentation to NRC reintergranular stress corresion cracking insp & repairs
 Unit will return to svc & operate for 6 months to sphaust
 present fuel load Pipe will be replaced beginning Mar 1994
 DALTROFF, 8 L Philadelphia Electric Co 83/10/06 STOLZ, J F
 Operating Reactors Branch 4 2pp 20762 386 24x
 Fiche 50-277.83/10/06.8310140203
- B30B300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Dypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000, B3/10/07, B30B30803/8
- 8308300752 IE Info Natice 83-66, "Fatality at Argentine Critica)
 Facility " Svc list enc)
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of New
 York, Inc 79pp. 20882 024 24X Fiche 50-000,83/10/07.8308300752
- B30B300759 IE Info Notice B3-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Dvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Cn of New York, Inc. 117pp 21043 075 24X Fiche 50-000, B3/10/11, B30B300757
- 8308300761 IE Info Notice 83-68. "Respirator User Harning Defective Self-Contained Breathing Apparatus Air Cylinders " Sv. list encl JORDAN E L. Division of Emergency Preparators & Engineering
 - enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Ficho 50-000,83/10/11,8308300761
- 8310200162 Ack receipt of 830811 & 0923 ltrs informing NRC of steps taken to correct violations noted in IF Insp Repts 50-277/83-16 & 50-278/83-16 STAROSTECKI, R Division of Project & Resident Programs 83/10/13 DALTRUFF, B L Philadelphia Electric Co ip 20835 355 24X Fiche 50-277,83/10/13,8310200162
- -8310200172 Responds to NRC 830914 telcon re violations noted in IL Insp Repts 50-277/83-16 & 50-278/83-16 Corrective actions administrative procedures resxamined w/expectation that costly & impractical requirements can be eliminated GALLAGNER, J. W. Philadelphia Electric Co. 83/09/23 STAROSTECKI.R. Division of Project & Resident Programs 2pp 20835:356 24X Fiche 50-277.83/10/13.8310200162
 - NO200196 Responds to NRC B30720 ltr re violations noted in IE lnsp Repts 50-277/83-16 & 50-278/83-16 Corrective actions individual responsible for leaving door unlocked identified k denied access to protected area NALTROFF. B L Philadelphia Electric Co B3/08/11 STAROSTECKI, R Division of Project & Resident Programs 3pp 20835 35B 24X iche 50-277,83/10/13,8310200162

- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethooda.

 MD to discuss future insps for intergranular stiess
 corrusion cracking
 MIRAQLIA.F J Assistant Director for Bafety Assessment 8/1/10/14
 EISENHUT.D @ Division of Licensing 5pp 20823 358 24X
 Fiche 30-000.83/10/14.8310180551
- B310210336 Notification of 831017 meeting w/util.GE,SWR1 & LMf in King of Prussia,PA to review UT inep data on crack indication on 5 post-fikSI welds
 GEARS.G Operating Reactors Branch 4 B3/10/18 STOLZ,JF
 Operating Reactors Dranch 4 2pp 20883 158 247
 Fiche 50-277,B3/10/18,8310210336
- R Periodic operating reports & related correspondence
- 8310120313 Forwards "Regional Radiological Environ Monitoring Program Rept 18:1982" & "Peach Bottom Atomic Power Station Environs Radiation Monitoring Program Rept 40,1902" WILLSEY, W B Philadolphia Electric Co 83/09/22 HAYNES, R C Region 1, Office of Director 1p 20690 094 24X Fiche 50-277,83/09/22,8310120313
- --8310120316 "Regional Radiological Environ Monitoring Program Rept 11, 1992"

 * Radiation Menagement Corp 63/05/31 121pp 20470 095 24X Fiche 50-277,83/09/22,8310120313
- --8310120319 "Peach Bottom Atomic Power Station Environs Radiation Monitoring Program Rept 40,1902 " * Chemical Waste Management, Inc. 83/07/31 120pp 20690 216 24% Fiche 50-277,03/09/22.0310120313
- 8310200297 Forwards monthly operating rept for Sept 1983 & revised rept sheets for Jul & Aug 1983 for Unit 1 COUNEY, M J Philadelphia Electric Co 83/10/13 Director's Office Office of Inspection and Enforcement 1p 20830 086 24X Fiche 50-277.83/10/13.831020029/
- --B310200261 Monthly operating rept for Sept 1983 ALDEN.W M Philadolphia Electric Co 89/10/13 10pp 20800 08/ 24% Fiche 80-277,83/10/13,8310200257
- --8310200263 Revised rept sheets for monthly operating rept for Jul 1903 ALDEN.W M Philadelphia Electric Co 83/08/26 2pp 20830 097 24% Fiche 30-277, 83/10/13, 8310200257
- --8310200244 Revised rept sheets for monthly operating rept for Aug 1783 ALDEN.W M Philadelphia Electric Co 83/08/26 2pp 20830 099 24% Fiche 50-277, 63/10/13,8310200257
- S Reportable occurrences, LERs & related correspondence
- 8310270541 Responds to FOIA request for three categories of documents re 830606 gas leak at facility Forwards App A documents FELTON.J M Division of Rules and Records 83/07/22 AROYROS.D L Chamin, Schottland, Rosen, Cavanagh & Uliano 2pp 2093/225 247 Fiche 50-000,83/07/22.8310270541
- --83102/0547 Submits morning rept for Region I.listing 830606 & 07 events ALLAN.J M Region 1. Office of Director 83/06/07 BLAHA.J Program Support Branch 1p 20737 228 24X Fiche 50-000, 83/07/22.83102/0541
- 8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2,434 MW Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 93/07/28 HAFNER, B Buffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000,63/07/28,8310210329
- --B303240364 Summarizes evaluation of LERs for Mar 1982 Feb 1983 LFR submittals acceptable Supplemental or followup info would improve operational experience analysis SEYRIT.K V Reactor Operations Analysis Branck 63/03/16 STAROSTECKIR Division of Project & Resident Programs 3pp 20862 273 24X Fiche 50-000, 63/07/28, 6310210327
- 8310270340 FOIA request for placement of listed LERs in PDR GRABER, L. D NU8 Corp B3/09/08 Division of Rules and Records 2pp 20738 058 24X Fishe 50-000 83/09/08 8310270340
- B310250382 LER 83-014/03L-0 on B30812, control room fire barrier discovered w/o fire damper in one vantilation duct penetration Caused by damper not incorporated into original ventilation sys installation New damper on order COUNEY, NJ Philadelphia Electric Co 83/09/14 MURLEY, TE Region 1, Office of Director 1p 20097 268 24X Fiche 50-277,83/09/14.8310250382

- 8310270347 Responds to FDIA request for release of 23 LERs to PIR Forwards 12 LERs to be released Documents also available in PDR dne LER canceled Eight LERs not received FELTON. J M Division of Rules and Records 83/09/29 GRARER, L B NUS Corp 1p 20938 060 24X Fiche 0-000,83/09/29.8310270347
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Fuzboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 249 Fiche 50-000,83/09/30,8310070301
- 8310140068 PNO-1-83-104 on 830704 during RHR & recirculation piping weld insp.20 of 126 welds examined evidenced intergranular stress corresion cracking Licensee repairing 16 welds by clad overlay technique BLOUGH A R . TRIPP, L E Region 1. Office of Director 83/10/07 1p 20766 359 24% Fiche 50-277.83/10/07.8310140069
- 8310310361 PND-I-83-109 on 831024. Inconsee reported that radiographs associated w/Class I piping improperly read by vendor during outage mod work in 1981 & 1982 Part 21 implications under evaluation BLOUGH, A R, TRIPP, L E Region 1, Uffice of Director 83/10/25 ip 20961 121 24X Fiche 50-277.83/10/25,8310310361
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8310050004 Advises that NUREG-0737. Item 11 B 2 2. "Design Review of Plant Shielding Corrective Actions for Access to Vital Areas," requirements met based on review of licensee 800102, 31.1015,810108,820415,0707 & 830513 submittals STOLZ, J F Operating Reactors Branch 4 83/09/12 BAUER, L G Philadelphia Clectric Co Spp 20650 242 24X Fiche 90-277,83/09/12.8310050004
- 8310040434 Forwards safety analysis re basis on which selected parameters for safety parameter display sys sufficient to assess safety status of each function for wide range of events, per Generic Ltr 82-33.80ppl i to NUREO-0737 OALLAOHER, J W Philadelphia Electric Co 83/09/28 EISENHUT, P G Division of Licensing 8pp 20619 108 24X Fiche 50-277.03/09/28, 8310040434
- B310210269 Forwards IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-23 on 830811 & notice of violation STARDBITCKI,R Division of Project & Resident Programs 83/10/03 BOYER,V Philadelphia Electric Co dpp 20855 448 24% Fiche 50-277,83/10/03,8310210269
- --8310210274 Notice of violation associated w/IE enforcement conference on BJGB11

 * Region 1, Dffice of Director 83/10/03 2pp 20855 250 24X Fiche 50-277,83/10/03,8310210269
- --B31021027B IE Enforcement Conference Repts 50-277/B3 23 & 50-p78/B3-23 on 830B11 Major areas discussed violations from IE Insp Repts 50-277/B3-16 & 50-278/B3-16 re unsealed penetrations in fire barriers
 BLOUGH.A R Region 1, Office of Director 63/08/22 4pp 20855 252 24X Fichs 50-p77.83/10/03.8310210269
- 8310280252 Releases public version of revised emergency plan implementing procedures FELFON, J M Division of Rules and Records 83/10/25 Document Management βranch 1p 20963 016 24X Fiche 50-277,83/10/25, 8310280252
- --8310280257 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-209, App A re immediate notification call list & EP-209, App D-1 re onsite emergency team leaders Affidavit encl DALTROFF, 6 L. Philadelphia Electric Co 83/05/13 ALLAN, J M Region 1, Office of Director 4pp 20963 017 24X Fiche 50-277,83/10/25,8310260252
- --8310280271 Public version of revised emergency plan implementing procedures. Including Procedures EP-207, App A re immediate notification call list & FP-207, App D-1 re onsite emergency team leaders

 * Philadelphia Electric Co 83/04/13 62pp 20963 021 24X Fiche 50-277,63/10/25 8310280252

- P Operating license stage documents & correspondence
- 8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L Affiliation Unknown 83/05/02 NRC No Detailed Affiliation Given ip 21004 270 24X Fiche 50-000,83/05/02,8310310017
- 8310310031 Responds to FDIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which ropts are unavailable FELTON.J M Division of Rules and Records 83/07/06 CONNER,L Affiliation Unknown ip 21004 271 E4X Fiche 50-000.83/07/06, 8310310031
- --8310310064 "Reactor Containment Bldg Integrated Leakage Rate Test Regt " W/770628 ltr ULLRICH.W T Philadelphia Electric Co 77/04/04 109pp 21005 313 24% Fiche 50-000.83/07/06.8310310031
- 83101i0454 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUREG-0612. "Control of Heavy Loads (Phase II " Phase I acceptable Need for single failure-proof handling equipment will be addressed in Phase II BTOLZ, J.F. Operating Reactors Branch 4 B3/09/21 BAUER, E. G. Philadelphia Electric Co. 3pp. 20/12 076 24X Fiche 50-277.63/09/21.8310110454
- ---8310110459 Safety evaluation re util 810416.1222,820920,1025 & 830810 responses to NUREG-0612. "Control of Heavy Loads (Phase I) "
 Phase I acceptable * NRC No Detailed Affiliation Given 83/09/09 2pp 20712 079 24X Piche 50-27/,83/09/21,83/0110454
- --8309020392 "Control of Heavy Loads (C-10). Philadelphia Electric Co, Peach Bottom Atomic Power Station, Units 2 & 3." technical evaluation rept SARGENT, I H., BOMBERGER, C. Franklin Institute/Franklin Research Center TER-C5506-379/380 83/08/31 SINOH, A. NRC No Detailed Affiliation Given 32pp 20712 081 24X Fiche 50-277,83/09/21,831010454
- 8310040187 Forwards revised pages to 811223 application for amend to Licenses DPR-44 & DPR-56 changing values of surveillance setpoints, per 830726 telcon GALLAGHER, J W Philadelphia Electric Co 83/09/29 STOLZ, J F. Operating Reactors Branch 4 2pp 20608 089 24X Fiche 50-277,83/09/29.8310040189
- --8310040191 Revised Tech Spec Pages 36 & 36a listing limiting conditions for operation & surveillance requirements for reactor protection sys power supply * Philadelphia Electric Co 83/09/09 2pp 20608 091 24X Fiche 50-277.83/09/29.8310040189
- 8310040415 Forwards "Implementation of NUREG-0619 Feedwater Nozzle Cracking." & proprietary "Peach Bottom Atomic Power Station. Unit 2.Feedwater Nozzle Fracture Mechanics Analysis to Show "Proprietary rept withheld (ref 10CFR2 790)

 GALLAGHER, J W Philadelphia Electric Co B3/09/29 CISENHUT, D O Division of Licensing 2pp 20623 303 24% Fiche 50-277.83/09/29, 8310040415
- --8310040429 "Implementation of NUREO-0619 Feedwater Nozzle Cracking " Affidavit enc] * Philadelphia Clectric Co 83/09/30 19pp 20623 305 P4X Fiche 50-277,83/09/29.8310040415
- 8310200016 Forwards draft SER or NUREQ-0/37. Item II B 3, "Post-Accident Bampling Bys " Response addressing concerns re three outstanding items requested. Telcon to discuss early resolution should be arranged within 30 days of lt receipt STOLZ. J F Operating Reactors Branch 4 83/10/06 BAUER, E 9 Philadelphia Electric Co 12pp 20844 249 24X Fichs 50-277,83/10/06,8310200016
- 8310260212 Forwards response to B31004 request re NUNEO-0737. Item
 II E 4 2. "Containment Purge & Vent Valves." design
 evaluation W/13 oversize drawings Aperture Cards are
 available in PDR
 DALTROFF, 8 L Philadelphia Electric Co 83/10/19 BTOLZ. J F
 Operating Reactors Branch 4 72pp R0909 277 24X
 Fiche 50-277. 83/10/19. 8310260212
- @ Inspection reports. IE Bulletins & correspondence
- 8310120212 Forwards IE Insp Repts 50-277/83-19 & 80-278/83-19 on B30718-22 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/09/22 BALTROFF, S Philadelphia Electric Co 2pp 20492 318 24X Fiche 50-277 83/09/09

- -8310120213 Notice of Violation from 105p on 830718-22 * Region 1. Office of Director 83/09/J2 2pp 20692 320 J47 Fiche 50-277, 83/09/22, 8310120212
- ~8310120217 IE insp Repts 50-277/83-19 & 50-278/83-19 on 830718-22 Noncompliances noted failure to train personnel in accordance w/Tech Specs & to perform safety evaluation for change in solidification of liquid waste procedure WHITE. J R . COLLINS. D J . LAMASTRA. M Region I. Diffice of Director 83/09/12 14ep 20692 322 24X Fiche 50-277,83/09/22,8310120212
- 308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Milder Qualification Tests" Svc list encl JORDAN E L Division of Comrgency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. D. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison to of New York, Inc. 116pp. 20777-210 24X Fiche 50-000,03/09/26.8308500342
- 308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-I Differential Relays" Svr list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000, 03/09/26, 8J00300345
- 309300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evaluation " Svc list
- encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Lo of New York, Inc. 115gp 20716-324 24X Fiche 50-000,83/09/29,8708J00349
- 310210267 Forwards IE Enforcement Conference Repts 50-2/7/63-23 & 50-270/63-23 on B30Bli & notice of violation BTAROSTECKIR Division of Project & Resident Programs B3/10/03 B0YER/V Philadelphia Electric Co 2pp 20855 248 24X Fiche 50-277.83/10/03.8310210267
- B310210274 Notice of violation associated w/IE enforcement conference on B30811 # Region 1. Office of Director 83/10/03 2pp 70855 250 24X Fiche 50-277,83/10/03,8310210269
- 8310210278 IE Enforcement Conference Repts 50-277/83-23 & 50-278/83-33 on 830811 Major areas discussed violations from IE Insp. Repts 50-277/83-16 & 50-278/83-16 re unscaled penetrations in fire barriers
 BL009H.A R. WILLIAMS.J.H. TRIPP.L.E. Region I. Office of Director 83/08/22 app 20855 202 24X Fiche 50-277,83/10/03,8310210269
- OBG0037B IE Info Natice 83-65. "Surveillance of Flow in RID Dypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 08300752 IC Info Notice B3-66. "Fatality at Argentine Critical Facility " Byo list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 630103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp. 20882 026 24% Fiche 50-000,83/10/07,8308300752
- 08300759 IE Info Notice 83-47, "Emergency Use Respirator Matl Defect Causes Production of Naxious Gases" Byr list encl JORDAN. E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 079 24X Fiche 50-000.03/10/11.83083000759
- DB300761 IE Info Notice 83-68. "Respirator User Warming Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list and JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827:129 24X Fiche 50-000.83/10/11.8308J00761
- iO200162 Ack receipt of 830811 & 0723 ltrs informing NRC of steps agen to correct violations noted in IE lnsp Repts IO-277/83-16 & 50-278/83-16 ltrAROSTECKI,R Bivision of Project & Resident Programs IMALTROFF:8 L Philadelphia Electric Co ip 20035 355 24X iche 50-277,83/10/13,8310200162

- --8310200172 Responds to NRC 830914 telron re violations noted in I(
 Insp Repts 50-277/83-16 & 50-278/8J-16 Corrective artisms
 administrative procedures regrammed ω/expectation that
 costly & impractical requirements can be eliminated
 GALLAGHER. J M Philadelphia Electric Co 83/09/23
 STARDSTECKI, R Division of Project & Resident Programs 2μμ
 20835 356 24% Fiche 50-27/,83/10/13 8310200162
- --8310200196 Responds to NRC 830720 ltr re violations noted in II Insp Rapts 50-277/83-16 & 50-278/83-16 Corrective actions individual responsible for leaving door unlocked identified & denied access to protected area DALTROFF.8 L Philadelphia Electric Co 83/08/11 STARUS16(K), & Division of Project & Residint Programs 3pp 20095 35H 24X Fiche 50-277,83/10/13,8310200162
- B310180551 Notification of B31021 meeting w/BWR licensees in Bethesda.

 MD to discuss future insps for intergranular stress
 corrosion cracking
 MIRAGLIA: F J Assistant Director for Safety Assessment 83/10/14
 EISENMUT, D G Division of Licensing 5pp 20823 358 248
 Fiche 50-000, 83/10/14, 8310180551
- 8310210336 Notification of 831019 meeting w/util, GE, SWRI & LMF in King of Prussia, PA to review UT inspidate on crock indication on 5 post-IHSI welds GEARS, G. Operating Reactors Branch 4 83/10/18 STULZ, J. F. Operating Reactors Branch 4 2ph 20UH3 158 24X Fichs 50-277,83/10/18,8310210336
- R Periodic operating reports & related currespondence
- 8310120313 Forwards "Regional Radiological Environ Monitoring Program
 Rept 18,1982" & "Peach Bottom Atomic Power Station Environs
 Radiation Monitoring Program Rept 40,1982 "
 WILLSEY.W B Philadelphia Electric Co 83/09/22 HAYNES.R C
 Region 1, Office of Director 1p 20/0/0 094 247
 Fiche 50-277.83/09/22.8310120313
- --8310120316 "Regional Radiological Environ Monitoring Program Rept 18. 1982 " * Radiation Management Corp 03/05/31 121pp 20690 095 24X *fiche 50-27.83/09/22.8310120313
- --8310120319 "Peach Bottom Atomic Power Station Environs Radiation Monitoring Program Rept 40.1982" * Chemical Waste Management, Inc. 83/07/31 120pp 20690 El6 24X Fiche 50-277, 83/09/22, 8310120313
- B310200257 Forwards monthly operating rept for Sept 1983 & revised rept sheets for Jul & Aug 1983 for Unit 1
 CGDNEY, M J Philadelphia Electric Co B3/10/13 Director's Office, Office of Inspection and Enforcement 1p 20030 086 24X Fiche 50-277, B3/10/13, B310200257
- -8310200261 Monthly operating rept for Sept 1983 ALDEN. H M Philadelphia Electric Co 83/10/13 10pp 20830 08/ 24% Fishe 50-277.83/10/13.831020029/
- 8 Reportable occurrences, LERs & related correspondence
- 8310270541 Responds to FOIA request for three categories of decuments re 830606 gas leak at facility forwards App A documents FELTON, J M Division of Rules and Records 83/07/22 ARGYROS, D L Chemiin, Schottland, Rosen, Cavanagh & Uliano 2pp 20937 225 24X Fiche 50-000,83/07/22,8310270541
- --831027054/ Submits morning rept for Region I, listing 830606 & 07
 events
 ALLAN, J M Region I, Office of Director 83/06/07 BLAHA, J
 Program Support Branch 1p 20937 2P8 24X Fiche 50-000,
 83/07/22,8310270541
- 8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GL BWR/4 rated at 2,434 MW Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/28 HAFNER, R Suffalk Nuclear Study Group 2pp 20862 223 24% Fichs 50-000,03/07/28,8310210327
- --8303240364 Summarizes evaluation of LLRs for Mar 1982 Feb 1983 LER submittals acceptable Supplemental or followup info would improve operational experience analysis SEYFRIT, K V Reactor Operations Analysis Branch 83/03/16 STAROSTECKI:R Division of Project & Resident Programs Supp 20882 273 24X Fiche 50-000,03/07/28,8310210329

DOCKETED ITEMS

- 8310250279 Failowup LER 83-008/017-1 on 930214 during refueling outage, surveillance testing indicated combined leakage for listed valves exceeded limits or failed to meet requirements Caused by seat surface degradation W/830913 lti COONEY, M J Philadelphia Electric Co 83/09/13 MURLEY, I E Region 1. Office of Director 4pp 20899 017 247 Fiche 50-278,83/09/13,83102502/7
- B310200137 LER B3-009/01T-0 on BJ090B, during surveillance testing w/onr diesel generator inoperable breaker between diesel generator E-1 & emergency bus E-13 failed to close manually Caure unknown Breaker tested successfully W/830922 ltr COUNEY.M J Philadelphia Electric Co B3/09/22 MURLEY.Ft Region J, Office of Director App 2/08/36 337 24X Fiche 50-278.83/09/22.83102/001J7
- B310070301 Potential Part 21 rept re undurrange characteristic of Model N-EIIOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BEREERIAN.M J Foxboro Coip 83/09/30 Director's Office. Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000.83/09/30.8310070301
- 8310310361 PNO-I-83-109 on 8310,24, licensee reported that radiogr.phs associated w/Class I piping improperly read by vendor during outage mod work in 1981 ; 1982 Part 21 implications under evaluation BLOUGH, A.R., TRIPP, L.E. Region 1, Diffice of Director 83/10/25 1p 20961 121 24X Fiche 50-277,83/10/25,8310310361
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8310040252 Forwards technical support cti & emergency operations facility floor plans route maps to emergency response facilities & telephone listings Requests update of info & submittal of personnel access documents
 DANCE, H C Division of Project & Resident Programs 83/09/12
 STEMART, W L Virginia Electric & Power Co 16pp 20613 049 24X
 Fiche 50-000.03/09/12.8310040252
- 8310290388 Forwards IE Insp Repts 50-280/83-21 & 50 281/83-21 on 830822-26 No noncompliance noted DANCE, H C Division of Project & Rasident Programs 83/09/20 Block Company of Project & Power Co 2pp 20648 15.1 PAX Fiche 50-280,83/09/20,8310250388
- --B310250394 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830827-26 No noncompliance noted Major aleas inspected emergency preparedness including audits 0A manuals & instructions & thorough discussions w/personne)
 MARSTON.R R Region 2. Office of Director JENKINS.G R Division of Emergency Preparedness & Materials Safety 83/09/13 8pp 20898 155 24X Fiche 50-280,83/09/20,8310250388
- 8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83 23 us 830816-17 No noncompliance noted DANCE H C Division of Project & Resident Programs 83/09/23 STEWART,W L Virginia Electric & Power Co 2pp 20900 084 243 Fiche 50-280,83/09/23,8310250320
- --8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of 1Ml Action Item II B 2.plant mods for vital area access, posting, tabelling & control of radiological areas HOSEY, C M. Region 2. Office of Director BARR, K P. Division of Engineering & Operational Programs 83/09/21 App 20900 086 24X Fiche 50-280, 83/09/23, 8310250320
- B310030294 Forwards IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on B30906-09 No noncompliance noted DANCE, H (Division of Project & Resident Programs B3/09/28 STEWART, W L Virginia Electric & Power Co 2pp 20591 035 P4X Fiche 50-280,83/09/28.8310030294
- --8310030305 IE Bafeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830906-09 No noncompliance noted Major creas inspected organization mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR73 21) HALLE L. Region 2. Office of Director MCGUIRE, D.R. Division of Emergency Preparedness & Materials Safety 83/09/28 ip 20591 037 24X Fiche 50-280,83/09/28,8310030294
- 8310060519 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20663 147 24X Fiche 50-280,83/09/30, 8310060519

- --8310060523 Public version of Nev 3 to Emergency Plan Implementing Procedure EPIP-2 01, "Notification of State & Local Govts" W7830916 htt SAUNDERS, R., STEWART, W.L. Virginia Electric & Power Co. 83/08/25 O'REILLY, J.P. Region 2, Office of Director 21pp. 20663 148 24X Fiche 50-280,83/09/30,8310060519
- B310070403 Releases public version of revised corporate emergency response plan
 FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch ip 20675 182 24X Fiche 50-000,83/09/30,8310070403
- --8310070418 Public version of revised colporate emergency response plan W/830614 ltr STEWART,W L Virginia Electric & Power Co 83/05/15 O'REILLY,J P Region 2, Office of Director 114pp 206/5 i83 24X Fichs 50-000, 83/09/30, 8310070403
- B310060566 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20661 248 24X Fiche 50-280,83/10/05, 8310060566
- --8310060577 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-4 20, "Health Physics Actions for Transport of Contaminated Injured Personnel" & Rev 2 to Procedure EPIP-5 01, "Transport of Personnel" " STEWART: N L Virginia Electric & Power Co 83/09/20 O'REILLY, J P Region 2, Office of Director 1p 20661 247 24X Fiche 50-280.83/10/05.83/0040586
- --8310060384 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-4 20, "Health Physics Actions for Transport of Contaminated Injured Personnel" & Rev 2 to Procedure EPIP-5 01, "Transport of Contaminated Injured Personnel" WILSON, J. Virginia Electric & Power Co. 83/09/12 15pp 20661 250 24% Fishe 50-280, 83/10/09, 8310060566
- 8310110186 Releases public version of radiological emergency response plan FELYON.JM Division of Rules and Records 83/10/05 Document Management Branch 1p 20701 020 24X Fiche 30-000.83/10/05. 8310110186
- --8310110170 Public version of radiological emergency response plan W/030621 ltr * Virginia Flectric & Power Co 83/06/30 O'REILLY, J.P. Region 2. Office of Director 301pp 20701 021 24X Fiche 50-000.83/10/05.8310110186
- 8310110237 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20685 126 24% Fiche 50-290,83/10/05,83/10/10217
- --8310110237 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-4 22 re post-accident sampling of containment air & EPIP-4 01 re radiological assessment director DEWANDELE P Virginia Electric & Power Co B3/09/23 Division of Emergency Preparedness & Engineering Response (Post BJ0103) 3pp 20685 127 24% Fiche 50-280, 83/10/05, 8310110237
- --8310110240 Public version of revised emergency plan implementing procedures including Procedures EPIP 4 22 re post-actident sampling of containment air & EPIP-4 01 re radiological assessment director SAUNDERE, R. CDX.F. Virginia Electric & Power Co. 83/09/23 100pp. 20685 130 24X Fiche 50-280.83/10/05.8310110237
- B310110263 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20712 324 24X Fiche 50-280,83/10/05,8310110243
- --8310110268 Forwards public version of Rev 2 to Emergency Plan
 Implementing Procedure EPIP-5 01. "Transportation of
 Contaminated Injured Personnel" & Rev 2 to EPIP-4 70
 "Health Physics Actions for Transport of Prisonnel"
 BEHANDELE P Virginia Electric & Power Co 83/09/14 Division
 of Emergency Preparedness & Engineering Response (Post 830103)
 2pp 20712 325 24% Fichs 50-280,83/10/09,8310110363
- 8310180301 Forwards changes to security program Changes withhold (ref 10CFR73 21) STEWART.W L. Virginia Electric & Power Co. 83/10/05 MCGUIRF.D & Division of Emergency Preparedness & Materials Safety Ip R0806 351 24X Fiche 50-280.83/10/05.8310180301

- 8319260428 Releases public version of revised emergency plan implementing procedures FELTON.J M. Division of Rules and Records 83/10/21 Document Management Branch 1p 20926-124 24X Fiche 50-280.83/10/21, 8319260428
- --8310260432 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-4 01 reradiological assessment director & EPIP-4 09 re-source term assessment STEMART.N L. Virginia Electric & Power Co - 83/10/14 D'REILLY, JP Region 2, Office of Director - 1p - 20926 125 - 247 Fiche 50-280.83/10/21.8310260428
- --8310260426 Public version of jevised emergency plan implementing procedures, including Procedures EPIP-4 01 re radiological assessment director & EPIP-4 09 re source term assessment COX.F. SAUNDERS.R. Virginia Electric & Power CD 83/09/29 127pp 20926 (26 24x Fiche 50-280.83/10/21.8310260428
- P Operating license stage documents & correspondence
- 8310310017 FDIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L Affiliation Unknown 83/05/02 NRC No Dotailed Affiliation Given 1p 21004 270 24% fiche 50-000.83/05/02, 8310310017
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forward documents to be place in PDR & list of facilities for which repts are unavailable FELTON.J M Division of Rules and Records 83/07/06 CONNER, t Affiliation Unknown ip 21004 271 24% Fiche 30-000.03/07/06, 8310310031
- B3i0110078 Forwards Amends 89 & 90 to Licenses DPR-37 & DPR-32, respectively & safety evaluation Amends revise Tech Specs by changing fractional power limit to 0 3 multiplier & restoring rod insertion limits for Unit 1

 NEIOHBORS, J D Operating Reactors Branch 1 83/09/22 STEWART, W | Virginia Electric & Power Co 3pp 20682 326 24X

 Fiche 50-280,83/09/22,8310110078
- --8310110081 Amends 89 & 90 to Licenses DPR-37 & DPR-32 respectively, changing Tech Specs re fractional power limit to 0 3 multiplier instead of 0 2 multiplier & restoring rad insertion limits to pre-Cycle 7 values for Unit 1 VARGA.S A Operating Reattors Branch 1 83/09/22 16pp 20582 329 24% Fiche 50-280.83/09/22.8310110078
- --8310110084 Safety evalvation supporting Amends 89 & 90 to Licinos DPR-37 & DPR-32, respectively * NRC - No Detailed Affiliation Given 83/09/22 3pp 20482 345 24% Fiche 50-280,83/09/22,8310110078
- 8310120003 Summary of 830921 meeting w/util in Bethesda. MD re proposal to reduce boron concentration in boron injection tanks & boric acid sys Info on radiological done savings & use of Westinghouse data will be provided by util MEIGHBURS. J D Operating Reactors Branch 1 83/09/29 Operating Reactors Branch 1 83/09/29 Operating Reactors Branch 1 31pp 20715 283 24% Fishe 50-280.83/09/29, 8310120003
- B310110137 Forwards payment of Class I & 11 fees for review of portion of util B30825 application re addition of supervisor of health physics, per NRC B30915 ltr
 STEWART, W L Virginia Electric & Power Co B3/10/04 DENTON, H R
 Office of Nuclear Reactor Regulation, Director M1LLER, W D Licens;
 Fee Management Branch ip 20446 292 24X Fiche 50-280, B3/10/04, B310110137
- 1310140094 Forwards VEP-FRD-41, "Reactor Sys Transient Analyses Using RETRAN Computer Code." in response to questions raised at 830921 meeting re methodology used to analyse steam line break Reeting proposed for third wk of Oct 1983
 STEMART.W L Virginia Electric & Power Co 83/10/06 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA.S A Operating Reactors Branch 1 2pp 20/66 117 24X
 Fiche 50-280,83/10/06,8310140094
- 310190043 Forwards "VEPCO NUMAD Code & Model " Rept is one of series discussing nuclear reload licensing & core follow support capabilities STEMART.W.L. Virginia Electric & Power Co. 83/10/14 DENION, I R Defice of Nuclear Reactor Regulation, Director EISENNULD C Division of Licensing 2pp 20822-335 24X Fiche 50-000,83/10/14,8310190042
- -8310190057 "VEPCO NOMAD Code & Model "
 BOMMAN,9 M , DZIADOSZ,D , BERRYMAN,R,M Virginia Electric & Power
 Co VEP-NFE-1 83/09/30 118pp 20822 337 24%
 Fiche 50-000,83/10/14,8310190043

- 8310200101 Provides status rept of util progress on lesolving relating of motor-operated valves & plans for further work institution valves will be remated or replaced as needed Schedulm for work completion will be provided by 840120 STEWART. W. L. Virginia Electric & Power Co. 83/10/14 DENIUN.)) R. Office of Nuclear Reactor Regulation, Director. VARGA, S.A. Operating Reactors Branch i. App. 20036-060 24X Fiche 30-280.83/10/14.8310200101
- 8310270300 Suppls 830325 response to 830;11 request for add1 info to NUREO-0737, Item II B 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Westinghouse Guners Group methodology completed by end of 1983 STEWART, W.L. Varginia Electric & Power Co. 83/10/20 DENION, H R Office of Nuclear Reactor Requilation. Director E15LNIU(,) () Division of Licensing 2pp 20923 193 24X Fiche 50-000,83/10/20,8310270300
- 4 Inspection reports. IE Bulletins & correspondence
- 8310040450 Suppls 800730 response to IE Bulletin 80-16, "Fotuntial Misapplication of Rosemount, Inc. Model 1151 & 1152 Pleasure Transmitters W/Either A or D Output Codes "Existing instruments to be upgraded w/Type N circuit boards STEMART, W. L. Virginia Electric & Power Co. 83/09/16 D'RLINY, J. Region 2, Office of Director Spp. 20625 280 24X Fiche 50-280,83/09/16,8310040450
- 831025038B Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on B30822-26 No noncompliance noted DANCE,H C Division of Project & Resident Programs B3/09/20 BTEMARTW L Virginia Electric & Power Co 2pp 20898 15.1 [4X Fiche 50-280,83/09/20.831025038B
- --8310250394 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted Major areas inspected emergoncy preparedness, including addits. GA manuals & instructions & thorough discussions w/personnel MARSTON.R R Region 2. Diffice of Director JENKINS.G R Division of Emergency Preparedness & Materials Safety 83/09/13 8pp 20898 195 24X Fiche 50-280,83/09/20,8310250388
- 8310250459 Forwards IC Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-19 & 29-31 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/22 STEMART, W L Virginia Electric & Power Co 2pp 20097 057 24X Fiche 50-280,83/09/22,8310250459
- --8310250464 IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830814-19 & 29-31 No noncompliance noted Major areas inspected inservice inspethit 2 steam generator A pirth weld ultrasonic test indications & J tube erosion/corrosion CROMLEY.D R , COLEY.J L Repin 2. Uffice of Director BLAKE.J , Division of Engineering & Uperational Programs 83/09/16 Bpp 20897 059 24X Fiche 50-280.83/09/22.8310250459
- 8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830816-17 No noncompliance noted DANCE, R C Division of Project & Resident Programs 83/09/23 BTEMART, W L Virginia Electric & Power Co 2pp 20900 084 24) Fiche 50-280,83/09/23.8310250820
- --8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of TMJ Action Item II B 2.plant mods for vital area access.posting, labelling & control of radiological areas HOSEY.C M Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs 83/09/21 App 20900 086 24X Fichs 50-280, 83/09/23, 8310250320
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stond-Ins for Welder Gualification Tests " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co of New York Inc 117pp 20754 022 24X Fiche 50-000,83/07/26,83083003040
- B30B300342 IE info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JURDAN,E I Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/26 Consolidated Edison Co. of New York, Inc. 114pp. 20777 210 24X Fiche 50-000, 83/04/26, 8308300342
- B30B300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post B30103) B3707/26 Consolidated Edison Co of New York Inc 118pp 20778 001 24X Fiche 50-000,83709/26,8308300345

- 8310030274 Forwards IE Safeguards Insp Repts 50-280/83-74 & 50-281/83-24 on 830906-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/28 STEMART, W L Virginia Electric & Power Co 2pp 20591 035 24) Fiche 50-280,83/09/28.8310030294
- --8310030305 IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830706-07 No noncompliance noted Major areas inspected organization mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR/3 21) HALL, B L Region 2, Office of Director MCOUIRE, D R Division of Emergency Preparedness & Materials Safety 83/09/28 1p 20571 037 24X Fiche 50-280,83/09/28,8310030274
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svr lirt enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Ce of New York, Inc. 115pp 20716 324 24X Fishe 50-000,83/09/29,8308300347
- 8310250429 Forwards IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830913-16 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/10/04 STEMART.H L Virginia Electric & Power Co 2pp 20897 02.3 24X Fiche 50-280,83/10/04.8310250429
- --8310250438 IE Insp Repts 50-280/83-25 & 50-281/83-25 on 83091J-16 No noncompliance noted Major areas inspected radiological environ monitoring, including mpt & administrative controls & status review of environ monitoring CUNNINGHAM, A L. Region 2. Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 63/10/05 7pp 20897 025 24X Fiche 50-280,83/10/04.8310250429
- 8310250456 Supplemental response to IE Bulletin 80-16 Upgrading of Unit 1 Rosemount Model 1151 & 1152 pressure transmitters by installation of Type N circuit boards completed on 830927 STEWART.W L Virginia Electric & Power Co 83/10/06 D'REILLY, J P Region 2, Office of Director ip 20897 104 24X Fiche 50-280.83/10/06.8310250456
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in R1) Dypass Loops Used in Mestinghouse Plants " Svc list encl JCRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fichs 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Bvc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Nel York, Inc 79pp 80882 026 24% Fiche 50-000.83/10/07.8308300/52
- 8308300757 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fishs 50-000.83/10/11,83083000759
- 8308300761 IE Info Notice 83-68, "Respirator User Walning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- R Periodic operating reports & related correspondence
- 8310190016 Monthly operating repts for Aug 1983 W/B30915 ltr JONES V , BIEWART.W L , SAUNDERB.R Virginia Electric & Power Co B3/09/15 HALLER.N M Office of Resource Management, Director 42pp 20822 083 24% Fiche 50-280.83/09/15.8310190016
- S Reportable occurrences LERs & related correspondence
- 9310040208 LER 83-039/03L-0 on 830831, svc water pump 1-6M-P-10A failed to maintain sufficient discharge pressure when control room air conditioning unit C placed in svc Caused by insufficient NP8H Flow throttled W/830926 ltr WILSON, J L Virginia Electric & Power Co 83/09/26 O'REIILLY, J P Region 2, Office of Director 4pp 20614 331 24X Fiche 50-280,83/09/26,8310040208
- 8310070164 LER 83-040/03L-0 on 830830, w/unit at 100% power, fire marshall discovered that Fire Door 42 would not latch Caused by worn hinges Hinges replaced W/830930 ltr WILSON, J L Virginia Electric & Power Co 83/09/30 O'REILLY, J P Region 2, Office of Director 3pp 20/59 105 24% Fiche 50-280, 83/09/30.8310070164

- 8310210306 LER 83-041/03L-0 on 830707, while attempting to energize control room air conditioning chiller A. local control panel caught fire Chiller A removed from svc w/chiller C out of svc for maint.contrary to Tech Specs W/831007 ltr WILSON, J L Virginia Electric & Power Co 83/10/07 O'REILLY, J P Region 2, Office of Director 3pp 20851 131 24X Fiche 50-280, 83/10/07, 8310210J00
- 8310250609 LER83-043/03L-0 on 830914, following reactor trip, flow control valve (FCV) failed to close upon receipt of feedwater isolation signal Caused by malfunctioning solemoid valve & FCV-1488 restricted by antirotation device MILSON, J L. Virginia Electric & Power Co. 83/10/14 O'RCILLY, J P. Region 2, Office of Director 4pp 20099 319 24X Fichs 50-280, 83/10/14, 8310250609
- 8310190236 PND-II-83-082 on 831015, control room operator trainee killed instantly when fist-sized hole blew open in wall of 24-inch carbon steel pipe attached to high pressure feedwater drain pump Cause under investigation tanking NANCE, H. Region 2, Office of Director 83/10/17 2pp 20818 078 24X Fiche 50-280,83/10/17,8310190236
- DOCKET 50-281 SURRY POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8310040252 Forwards technical support ctr & emergency operations facility floor plans route maps to emergency response facilities & telephone listings Requests update of info & submittel of personnel access documents

 DANCE, H C Division of Project & Resident Programs B3/09/12

 STEMART, W L Virginia Electric & Power Co 16pp 20613 049 24)

 Fiche 50-000.83/09/12.8310040262
- 8310250388 Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/09/20 STEMART.W L Virginia Electric & Power Co 2pp 20898 193 24% Fiche 50-280,83/09/20,8310250388
- --8310250374 IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-24 No noncompliance noted Major areas inspected emergency preparedness including audits CA manuals & instructions & thorough discussions w/personne!

 MARSION, R Region 2. Office of Director 83/09/13 Opp 20898 155 24X Fiche 50-280,83/09/20,8310250388
- 8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830816-17 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/23 STEMART, W L Virginia Electric & Power Co 2pp 20700 084 24X Fiche 50-280, 83/09/23, 8310250320
- --8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of TMJ Action Item II B 2. Plant mode for vital area access, posting, labelling & control of radiological areas HOBEY.C M Region 2. Office of Director 83/09/21 4pp 20700 084 24% Fiche 50-280.03/09/23,8310230320
- 8310030294 Forwards IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830904-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/28 STEWARTW L Virginia Electric & Power Co 2pp 20571 035 24X Fiche 50-280,83/09/28,8310030294
- --8310030305 IE Bafeguards Insp Repts 50~280/83-24 & 50~281/83-24 on 830706-09 No noncompliance noted Major areas inspected organization mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR73 2)) HALL, J. L. Region 2, Office of Director 83/09/28 ip 20591 037 24X Fiche 50-280, 83/09/28, 8310030294
- 8310060519 Releases public version of revised emergency plan implementing procedure FELTON,J M Division of Rules and Records 83/09/30 Document Management Branch ip 20663 147 24X Fiche 50-280,83/09/30, 8310060519
- --8310060523 Public version of Rev 3 to Emergency Plan Implementing Procedure EPIP-2 01, "Notification of State & Local Goyts "W/830916 1tr BAUNDERS,R., STEWART,W.L. Virginia Electric & Power Ca 83/08/20 O'REILLY, J.P. Region 2, Office of Director 21pp 20663 148 24X Fiche 50-280,83/09/30,8310040519
- 8310070403 Releases public version of revised corporate emergency response plan
 FELTON,J M Division of Rules and Records 83/09/30 Document Management Branch ip 20675 182 24X Fiche 50-000,83/09/30, 8310070403

- ~~8310070418 Public version of revised corporate emergency response plan
 - W/B30614 1tr STEMART.W L Virginia Electric & Power Co 83/05/15 O'REILLY, J P Region 2. Office of Director 114pp 206/5 183 24% Fiche 50-000,83/09/30.8310070403
- 8310060566 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Hules and Records 83/10/05 Ducum Management Branch Ip 20661 248 24% Fichs 50-280.63/10/05.
- Document
- --8310060577 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-4 20, "Health Physics Actions for Transport of Contaminated Injured Personnel" & Rev 2 to Procedure EPIP-5 01, "Transport of Personnel" 8 TEMART.W L Virginia Electric & Power Co 83/09/23 O'REILLY, J P Region 2, Office of Director 19 20661 247 Fiche 30-280.83/10/05.8310060566
- --8310060584 Public version of Rev 2 to Emergency Plan Implementing Procedure EPJP-4 20, "Health Physics Actions for Transport of Contaminated Injured Personnel" & Rev 2 to Procedure EPJP-5 01, "Transport of Contaminated Injured Personnel" WILSON, J. Virginia Electric & Power Co. 83/09/12 15pp 20661 250 24% Fiche 50-280,83/10/05,8310060564
- 8310110186 Releases public version of radiological emergency response
 - plan FELTON, J.M. Division of Rules and Records 83/19/05 Docum Management Branch ip 20701 020 24X Fiche 50-000.83/10/05, 8310110186
- --8310110190 Public version of radiological emergency response plan
 - W/830621 ltr * Virginia Electric & Power Co 63/06/30 D'REJLLY.J P Region 2. Office of Director 301pp 20701 021 24X Fiche 50-000.63/10/05.8310110186
- 8310110237 Releases public version of revised emergency plan implementing procedures FELTON. J M Division of Rules and Records 83/10/05 Pocum Management Branch ip 20695 126 24X Fiche 50-280,83/10/05, page 126.
- Document
- --8310110237 Forwards public version of revised emergency plan implementing procedures including Procedures EPJP-4 22 repost-accident sampling of containment air & EPJP-4 01 reradiological assessment director DEWANDEL, EP Virginia Electric & Power Co 83/07/23 Div of Emergency Preparedness & Engineering Response (Past 830103) 3pp 20685 127 24X Fiche 50-280, 83/10/05, 8310110237
- -8310110240 Public version of ruvised emergency glan implementing procedures, including Procedures EPIP-4 22 re post-accident sampling of containment air & EPIP-4 01 re radiological assessment director SAUNDERS,R., COX,F. Virginia Electric & Power Co. 83/09/23 100pp 20885 130 24X Fiche 50-280,83/10/05,8310110237
- 9310110263 Releases public version of revised emergency plan implementing procedures
 FELTON-J M Division of Rules and Records 93/10/05 Docum Management Branch Ip 20719 324 24X Fiche 50-280,83/10/05,831010263 Document
- --8310110260 Forwards public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-5 Oi, "Transportation of Contaminated Injured Personnel" & Rev 2 to EPIP-6 PO "Health Physics Actions for Transport of Personnel" DEWANDEL E P Virginia Electric & Power Co 83709/14 Divi of Emergency Preparedness & Engineering Response (Post 830103) 20p 20712 325 24X Fiche 50-280,83710/05,8310110263
- B310180301 Forwards changes to security program Changes withhold (ref 10CFR73 21)

 BTEMART.W L Virginia Electric & Power Co B3/10/05 MCGWIRF.D K Division of Emergency Preparedness & Materials Safety 1p 20804 351 24% Fiche 50-280,83/10/05.0310180301
- 8310260428 Releases public version of revised emergency plan implementing procedures
 fELTON.J M Bivision of Rules and Records 83/10/21 Docum
 Ranagement Branch 1p 20926 124 24X Fiche 50-260.83/10/21,
 8310260428 Document
- --8310260432 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIH-4 Of re radiological assessment director & IPIP-4 OF re source term <u>ausessme</u>nt

- --8310260436 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4 01 re radiological assessment director & EPIP-4 09 re source term assessment COXF, SAUNDERGS, Virginia Electric Power Co. 83/09/29 127pp 20926 126 24% Fiche 50-250.83/10/21.8310260428
- P Operating license stage documents & correspondence
- 83i0110078 Forwards Amends 89 & 90 to Licenses DPR-37 & DPR-32, respectively & safety evaluation Amends revise Tech Specs by changing fractional power limit to 0.3 multiplier & restoring rad insertion limits for Unit 1
 NEIGHBURS.J D. Operating Reactors Branch I 83/09/22 SIEW, Virginia Electric & Power Co. Jpp. 20482 326 24X
 Fiche 50-280,63/09/22,6310110078 83/09/22 STEWART, W.I.
- --8310110081 Amonds 89 & 90 to Liconses DPR-37 & DPR-32, respectively, changing Tech Specs re fractional power limit to 0 3 multiplier instead of 0 2 multiplier & restoring rod insertion limits to pre-Cycle 7 values for Unit 1 VARGA.S A Operating Reactors Branch 1 83/09/22 14pp 20482 329 24% Fiche 50-280,83/09/22,8310110078
- --B3101100B4 Safety evaluation supporting Amends 89 & 90 to Licenses PPR-37 & DPR-32, respectively NRC No Debailed Affiliation Given B3/09/22 Opp 20682 345 24X Fiche 50-280, B3/09/22 8310110078
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design defitiencies in Class I piping sys Info applicable to Diablo Canyon I & 2 Fermi 2 & Callaway EISEN-WIT, D 6 Division of Licensing 83/09/27 PALLADIND, Commissioners 3pp 20632 0(1 24% Fiche 50-000,83/09/29, B308300357
- 8310120003 Summary of 830921 meeting w/util in Bethesda.MD re proposal to reduce boron concentration in boron injection tanks & boric acid sys Info on radiological dose savings & use of Westinghouse data will be provided by util NEIG/BORS.J D Operating Reactors Branch 1 83/09/29 Operating Reactors Branch 1 83/09/29 Operating Reactors Branch 1 31/09/29, 8310120003
- B310110137 Forwards payment of Class I & 11 fees for review of position of util B30825 application of addition of supervisor of health physics, per NRC 830915 ltr
 STEMART.W L Virginia Electric & Power Co B3/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLIR.W D License Fee Management Branch ip 20446 292 24% Fiche 50-280, 83/10/04, 8310110137
- 8310140094 Forwards VEF-FRD-41, "Reactor Sys Transient Analyses Using RETRAN Computer Code," in response to questions raised at 830921 moeting re methodology used to analyse steam line break Keeting proposed for third wk of Qct 1983 STEWART. IL Virginia Electric & Power Co 83/10/06 DENIUN. II R Office of Nuclear Reactor Regulation, Director VAROA, 9 A Operating Reactors Branch 1 2pp 20/66 117 24X Fiche 50-280,83/10/06,83/0140094
- B310170043 Forwards "VEPCO NONAD Code & Node) " Rept is one of stries discussing nuclear reload licensing & core follow support capabilities STEWART, W.L. Virginia Electric & Power Co. B3/10/14 DENTON, H.K. Office of Nuclear Reactor Regulation, Director EISENWIT, D.C. Division of Licensing 2pp 20822 335 24X Fiche 50-000,83/10/14, 83(1):80063 8310190043
- --8310190057 "VEPCO NDMAD Code & Model " BOWMAN,S M . D71ADOS2,D . BERRYMAN,R M Virginia Electric & Power Co VEP-NFE-1 83/09/30 1/18pp 20822 337 24X Fiche 50-000.83/10/14.8310190043
- 8310200101 Provides status rept of util progress on resolving relating of motor-operated valves & plans for further work lhirty-two valves will be rerated or replaced as needed Schedule for work completion will be provided by 840120 STEWART.W L. Virginia Electric & Powor Co. 83/10/14 DENION.H R Office of Nuclear Reactor Regulation, Director VARGA.9 A Operating Neettors Branch 1 App. 206.96 040 24% Fiche 50-280.83/10/14.83100000101
- 8310270300 Suppls 830325 response to 830111 request for add) info re NUREQ-0737, Item II B 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Mestinghouse Owners Group methodology completed by end of 1983 STEWART.W L Virginia Electric & Power Co 83/10/20, DENION, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D & Division of Licensing 2pp 20923 193 24X Fiche 50-000,83/10/20,8310270300

- 4 Inspection reports, IE Bulletins & correspondence
- 0310040450 Suppls 800730 response to IE Builetin 80-16, "Potential Misapplication of Rosemount Inc Model 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Existing instruments to be upgraded w/Type N circuit boards STEWART.N L. Virginia Electric & Power Co. 83/09/14 D'REILLY, J P. Region 2. Office of Director Spp. 20625 280 24X Fiche 50-280,83/09/16.8310040450
- 8310250388 Forwards IE Insp Repts 50-280/83-21 & 50-281/83-21 on 830822-26 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/09/20 STEMART,W L Virginia Electric & Power Co 2pp 20898 15.1 24% Fiche 50-280.83/09/20.8310250308
- --8310250394 IE Insp Repts 30-280/83-21 & 50-281/83-21 on 830822-24 No nancompliance noted Major areas inspected emergoidy preparedness, including audits, QA manuals & instructions & thorough discussions w/personnel MARSTON, R Region 2, Office of Director JENKINS, Q Division of Emergency Preparedness & Materials Safety 83/09/13 Bpp 20898 135 24X Fiche 50-280,83/09/20,8310250388
- 8310250459 Forwards IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-19 & 29-31 No noncompliance nated DANCE.H C. Division of Project & Resident Programs 83/09/22 STENART.W L. Virginia Electric & Power Co. 2pp 20897 05/ 24X Fiche 50-280,83/09/22,8310250459
- --8310280464 IE Insp Repts 50-280/83-22 & 50-281/83-22 on 830816-17 & 29-31 No noncompliance noted Major aleas inspected inservice insp. Unit 2 steam generator A girth weld ultrasonic test indications & J. tube erosion/corrosion.

 CROMLEY.B R . CQLEY.J L. Region 2. Office of Director BLAKE, J. Division of Engineering & Operational Programs 83/09/16 8pp 20897 059 24X Fiche 50-280,83/09/22,8310250459
- B310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-2j or B30816-17 No noncompliance noted DANCE,H C Division of Project & Resident Programs 03/09/23 STEWART,W L Virginia Electric & Power Co 2pp 20900 0B4 24X Fiche 50-280,03/09/23,8310250320
- --8310250328 IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of IMI Action Item II B 2, plant mods for vital area access, posting, labelling & control of radiological areas HOSEY.C M Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs B3/09/21 4pp 20900 086 24X Fiche 50-280, 83/09/23, 83/09250320
- B30B300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Gualification Tests " Svc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- B308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/24 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidate Edison Co. of New York: Inc. 118pp 20778 001 24% Fiche 50-000,83/09/26,8308300345
- 8310030294 Forwards IE Bafeguards Insp Repts 50-280/83-24 & 50-281/83-24 on 830904-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/28 STEWART, M L Virginia Electric & Power Ca 2pp 20591 035 24% Fiche 50-280,83/09/28,8310030294
- --B310030305 IE Safeguards Insp Repts 50-280/83-24 & 50-281/83-24 on B30906-09 No noncompliance nuted Major areas inspected organization-mgt, site orientation, security plan & implementing procedures Details withheld (ref 10CFR73 21) HALL B L Region 2. Office of Director MCGUIRF,D R Division of Emergency Preparedness & Materials Safety 83/09/28 ip 20591 037 24X Fiche 50-280,83/09/28,8310030294
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CPR50 59 Evaluation " Syc list and! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Editor Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349

- 8310250429 Forwards IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830913-16 No moncompliance noted DANCE, H C Division of Project & Resident Programs 83/10/04 STEWART. W L Virginia Electric & Power Co 2pp 20897 023 24X Fiche 50-280,83/10/04,8310250429
- --8310250438 IE Insp Repts 50-280/83-25 & 50-281/83-25 on 830713-16 No noncompliance noted Major areas inspected radiological environ monitoring, including mpt & administrative controls & status review of environ monitoring CUNNINGHAM.A L Region 2. Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 83/10/05 7pp 20877 025 P4X Fiche 50-280,83/10/04.8310250429
- 8310250456 Supplemental response to IE Bulletin 80-16 Upgrading of Unit 1 Rosemount Model 1151 & 1152 pressure transmitters by installation of Type N circuit boards completed on 830927 STEWART.W L Virginia Electric & Power Co 83/10/06 G'REILLY, J P Region 2, Office of Director 1p 20R97 104 24X Fiche 50-280,83/10/06.8310250456
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, C L Divinion of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 77pp 20882 026 24% Fiche 50-000,83/10/07,8308300732
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases "Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list encl USEP State of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 127 24X Fichs 50-000,83/10/11.8300500761
- R Pariodic operating reports & related correspondence
- 8310190016 Monthly operating repts for Aug 1983 W/830915 ltr JONES.V. STEMART.W L., SAUNDERS.R Virginia Electric & Power Co 83/09/15 HALLER.N M Office of Resource Management, Director, 42pp 20822 083 24X Fiche 80-280.83/09/15.8310190016
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B310120269 Ack receipt of B30614.17 & 072B ltrs forwarding changes to Rev & to corporate emergency plan & Rev & to plant emergency plan & Rev & to plant emergency plan & Changes acceptable.per 10CFR50 54(q) requirements PAPERIELLO.C J Region 3. Office of Director B3/10/06 LARSON.C E Northern States Power Co ip 20690 34B 24X Fiche 50-000.83/10/04.8310120269
- 83i03i0123 Forwards safety evaluation based on util submittals re NUREO-0737.II B 2, "Design Review of Plant Shielding Access to Vittal Areas "Requirements met HILLER.J R Operating Reactors Branch 3 83/10/12 HUSOLF.D M Northern States Power Co 3pp 20965 324 24X Fichw 50-282.83/10/12.8310310123
- 8310180195 Clarifies NRC position reprocedures for admitting NRC inspersonnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months AXELSON, W L Region 3. Office of Director 83/10/14 LARSON, C E. Northern States Power Co 7pp 20809 054 24X Fiche 50~282,83/10/14,8310180195
- 8310250538 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 June 1983 KEPPLER, J Q Region 3, Office of Director 83/10/20, LARSON, C E Northern States Power Co Ppp 20902 143 24X Fiche 50-000, 83/10/20, 83/10250538

J. Insurance & indemnity information

- B310250239 Forwards Endorsements 56 & 57 to MAELU Policy MF-51 & Endorsements 68 & 69 to NELIA Policy MF-174 for Monticello & Endorsements 48 & 49 to MAELU Policy MF-68 & Endorsements 56 & 57 to NELIA Policy NF-197 for Prairie Island JOHMSON.R O Northern States Power Co 83/10/20 DINITZ.I Division of Engineering 9pp 20899 036 24X Fiche 50-000.83/10/20.8310250239
- P Operating license stage documents & correspondence
- 8310110498 Forwards safety evaluation re extended fuel burnup reload methodology based on Exxon assessment of potential radiological consequences for high exposure fuel Justification acceptable MILLER, J R Operating Reactors Branch 3 83/09/27 MUSGLF, D M Northern States Power Co 2pp 20714 319 24X Fiche 50-282,83/09/27.8310110498
- --8310110507 Safety evaluation supporting extended fuel burnup reload methodology based on Erron assessment of potential radiological consequences for high expasure fuel * NRC No Detailed Affiliation Given 83/09/27 Spp 20714 321 24x Fiche 50-282.83/09/27.8310110498
- B310130072 Forwards Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change limit of core local flux ratio allowing localized linear heat generation rate increase factor for gower uncertainty DITANNI.D C Operating Reactors Branch 3 B3/10/03 HUSOLF, B M Northern States Power Co 2pp 20/76 137 24X Fiche 30-282,83/10/03.8310130072
- --B310130076 Amends &6 & 60 to Licenses DPR-42 & DPR-60 respectively, changing limit of core local heat flow ratio allowing localized linear heat generation rate increase factor for power uncertainty HILLER.J R Operating Reactors Branch 3 B3/10/03 lips 20776 139 24% Fiche 50-282, B3/10/03, B310130072
- --8310130079 Safety evaluation supporting Amends && & 60 to Licenses DPR-42 & DPR-60.respectively * Defice of Nuclear Reactor Regulation, Director 20776 150 24X Fiche 50-282,83/10/03,83101300/2
- 8310170329 Notification of 831013 meeting w/util in Bethesda.MD to resolve seven open items in inservice test program for pumps & valves DIIAAMI.D C Operating Reactors Branch 3 83/10/11 MILLER.J R Operating Reactors Branch 3 2pp 20795 274 24X Fiche 50-282,83/10/11.8310170329

Inspection reports, IE Bulletins & correspondence

- 108300340 1E Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Qualification Tests" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fichs 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDAN-E Svc Vision of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York. Inc. 118pp 20778 001 24X Fichs 50-000,83/09/26,8308300345
- 1308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 39 Evaluation " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 310240084 Forwards IE Insp Repts 50-282/83-15 & 50-306/83-15 on 830811-0910 No noncompliance noted SHAFER.M D Region 3, Office of Director 83/10/05 LARSON, C E Northern States Power Co 2pp 20861 318 24X

- --B310240102 IE Insp Repts 50-282/83-15 & 50-304/83-15 on G30811 0710 No nancompliance noted Major areas inspected plant operational safety, maint surveillance, followers of reactor trips. IE bulletin & LFRs FEIERABEND, C D., WILLIAMS, D L., JACKIW, I N. Region 3, Office of Director 83/10/04 8pp 20881 320 24% Fiche 50-282,03/10/05, 8310240084
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Dypass Loops Used in Westinghouse Plants" Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fithe 50-000,83/10/07,83084003/9
- B30B300752 IE Info Notice B3-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E I Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/07 Consolidated Edison to of Now York, Inc 79pp 20882 026 24X Fiche 50-000, B3/10/07, B30B300/52
- 8308300759 IE Info Natice 83-67, "Emergency Use Respirator Mail Infect Causes Production of Noxious Gases" Svt list encl JURDANLE L Division of Emergency Precaredness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,0308300757
- B30B300761 IE info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,830B300/61
- 8310310173 Forwards safety evaluation & IR notice re 830624 request for relief from ASME Builer > Pressure Vessel Code concerning inservice insp of reactor coolant pump tasing welds Request granted MILLER, J R Operating Reactors Branch 3 83/10/12 MUSCLE, D N Northern States Power Co 3pp 20965 278 24X Fiche 50-282,83/10/12,8310310173
- --8310310175 Safety evaluation granting util 830524 request for telief from ASME Boiler & Pressure Vessel Code concerning inservice insp of reactor coolant pump casing welds * Office of Nuclear Reactor Regulation, Director 20755 281 24X Fiche 50-282,83/10/12,8310310173
- --8310310177 Notice of granting of relief from ASME Code Section X1 inservice insp requirements MILLER, J.R. Operating Reactors Branch 3 83/10/12 2pp 20945 286 24X Fiche 50-282,83/10/12,8310310173
- B3101B0195 Clarifies NRC position re procedures for admitting NRC inspection personnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months AXELSON,W L. Region 3, Office of Director B3/10/14 IANHUN,C F Northern States Pawer Co 7pp 20809 054 24X
- 8310250275 Forwards SALP Repts 50-282/83-16 t 50-304/83-17 for Jul 1982 - June 1983 KEPPLERI, J G Region 3, Office of Director KEPPLERI, J G Region 3, Office of Director Northern States Power Co 2pp 20895 272 Fiche 50-282,83/10/20,83102502/5
- --8310250278 8ALP Repts 50-282/83-16 & 50-306/83-17 for Jul 1982 June 1983 Overall rating of Category I assigned Region 3. Office of Director 83/10/20 24pp 20895 274 24y Fiche 50-282,83/10/20,8310250275
- --8310250284 Forwards SALP rept for Jul 1782 June 1783 in preparation for 83092/ meeting Written comments may be provided within 20 days following meeting W/o rept HIND. J A Division of Radiological & Meterials Bafety Programs 83/09/16 GILBERTS, D E Northern States Power Co 3pp 20895 318 24X Fiche 50-282, 83/10/20, 8310250275
- --B3102502BB Comments on B30921 meeting w/NRC re SALP repts Pot Jul 1982 - June 1983 GILBERTS.D E Northern States Power Co 83/09/30 KEPPLER.J & Region 3. Office of Director 1p 20895 321 24X Fiche 50-282.83/10/20,83102502/5
- 8310250538 Forwards final SALP 4 Rept 50-263/83-17 fpr Jul 1982 June 1983 KEPPLER,J G Region 3, Office of Director 83/10/20 LARSON,C E Northern States Power Co Rpp 20902 143 24X Fiche 50-000,83/10/20,8310250538

- --B310250561 Submits comments on 830921 meeting w/NRC to discuss SALP Rept 50-263/83-17 for Jul 1982 Junc 1983 Valuable insights gained on improving performance GILBERTS, D E Northern States Power Co 83/09/30 KEPPLER, J 8 Region 3, Office of Director ip 20902 175 24X Fiche 50-000.83/10/20,8310250538
- R Periodic operating reports & related correspondence
- 8310190055 Monthly operating repts for Aug 1983 W/830912 ltr DWGSTAD, D. MUSGLF, D. Northern States Power Co. 83/09/02 Office of Resource Management Director 9pp 20823 189 74X Fiche 50-282, 84/09/02, 8310190059
- S Reportable occurrences, LERs & related correspondence
- B310270340 F0IA request for placement of listed LERs in PDR GRABER, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 058 24% Fiche 50-000.83/09/08.8310270340
- E310190340 Responds to FDIA request for documents re degradation of fuel assemblies while in spent fuel pool in US nuclear power plants Forwards App A documents App B documents available in PDR FELTON, J M Division of Rules and Recurds 83/09/15 MAXWLLL. B Rochester Post-Bulletin, Rochester, MN 5pp 20844 058 24X Fiche 50-282.83/09/15.8310190340
- --8301070386 Informs of preliminary assessment of fuel assembly degradation observed in spent fuel storage pool & actions taken to assess failure mechanism & safety implication potential
 WU.P Chemical Engineering Branch 82/12/22 BENAROYA, V
 Chemital Engineering Branch 3pp 20844 074 24X
 Fiche 50-282,83/09/15.8310190340
- --8304200240 Forwards mat1 presented by util during 830223 meeting 1s fuel assembly failure in spent fuel pool Review establishing NRC position on listed issues requested Working meeting scheduled for 830420 Encl withheld DIIANNI.D C Operating Reactors Branch 3 83/04/08 WU.P NRC No Datailed Affiliation Given 2pp 20844 129 24X Ficha 50-282,83/09/15,8310190340
- --8305050044 Describes plan for review of Northern States Power Co & Westinghouse submittal on fuel assembly degradation while in spent fuel storage pool, prompted by fuel assembly cracking incident at Prairis Island WU,P Chemical Engineering Branch 83/04/20 BENARDYA,V Chemical Engineering Branch 2pp 20844 131 24X Fiche 50-282.83/09/15,8310190340
- --8305240300 Advises of informal preliminary review of potential safety issues that may exist as result of in-core fuel assembly nozzle separations Westinghouse analysis indicates no problem associated w/prevention of control rod insertions TOKAR.M Core Performance Branch 83/05/16 MU.P Chemical Engineering Branch 2pp 20844 154 24X Fiche 50-292.83/09/15, 8310190340
- --8308180258 Forwards 830617 SER re fuel assembly correction in spent fuel pool & draft info notice addressing corrosion problems at BWRs & PWRs fuel assembly bulge joint Bli216 failure w/o precedent & w/o determined cause W/o encis
 BENAROYA,V Chemical Engineering Branch 83/08/02 HOLAHAN. @
 Operating Reactors Assessment Branch 2pp 20844 156 24X
 Fiche 50-282.83/09/15,8310190340
- ---B310190344 Forwards proposed subjs of discussion for upcoming NRC-licensee-vendor meeting on spent fuel assembly failure evaluation Main concern liet in possible generic implication & licensee/vendor conclusion on failure mechanism (MU,P Chemical Engineering Branch 82/01/17 Chemical Engineering Branch 4pp 20844 070 24X Fiche 50-282,83/09/15,8310170340
- --8310190338 Forwards safety evaluation of fuel assembly failure event during fuel handling in spent fuel pool in Dec 1981 Evidence insufficient to deduce generic effect
 JOHNSTON, W. V. Assistant Djrector for Hatls, Chem & Environ Technology (Post 830201) 83/04/20 LAINAS, G.C. Assistant Darector for Operating Reactors 4pp 20844 133 24X
 Fichs 50-282,83/09/15,8310190340
- --8310190360 Safety evaluation concluding that evidence insufficient to draw generic conclusions from Dec 1981 fuel pool assembly failure event

 NRC No Detailed Affiliation Given 83/04/20 17pp 20844 137 24X Fiche 50-287.83/09/15.8310190340

- --8310190361 Safety evaluation of spent fuel assembly degradation Event was isolated incident No generic implications exist Draft IE info notice replacetal contamination of RCS encl * NRC No Detailed Affiliation Given B3/06/17 12pp 20844 160 24X Fiche 50-282,83/09/15,8310190340
- 8310120102 LER 83-021/03L-0 on 830830 during Surveillance Test MV-32035, cooling water header isolation valve II failed to close Caused by failure of GE auxiliary switch, part CR105X100P Switch replaced W/830927 ltr HONSTAD.A A. NUSOLF.D. Northern States Power Co. 83/09/2: Region 3. Dffice of Director 2pp 20496 223 24X Fiche 50-282,83/09/27,8310120102
- 8310270347 Responds to FOIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received FELTON.J M Division of Rules and Records 83/09/29 GRABER.L D NUS Corp Ip 20938 060 24% Fiche 50-000.83/09/29.8310270347
- --8310270415 LER 82-023/03L-0 on 821121, containment pressure sensing line found capped Caused by personnel error Units will be labeled W/831230 ltr
 HUNSTAD, A A Northern States Power Co 82/12/21 Region 3, Office of Director 2pp 20938 085 24% Fiche 50-000, 83/09/29, 8310270347
- --8310270418 LER 82-026/03L-0 on 821115, turbine driven auxiliary fordwater pump 11 failed to deliver full flow of 200 gpm to steam generators Caused by unscrewed governor valve Valve seat reinstalled & staked in position H/821215 ltr HUNSTAD.A A. MUSQLF.D Northern States Power Co 82/12/15 Region 3, Office of Director 2ap 20738 087 24X Fiche 50-000,83/09/29,8310270347
- --B310270421 LER B3-001/01T-0 on B30204.Exxon ECCS analysis error discovered Caused by input error into codes W/83021B ltr HUNSTAD.A A. MUSCLF.D Northern States Power Co B3/02/1B Region 3, Uffice of Director 3pg 20938 089 24X Ficho 50-000.83/09/29.B310270347
- --8310270425 LER 83-007/03L-0 on 830330 steam line radiation monitors discovered inoperable Monitors repaired & surveillance procedure revised to include daily check W/830429 ltr MUSOLF.D Northern States Power Co 83/04/29 Region 3, Office of Director 3pp 20938 092 24x Fiche 50-000,83/09/29, 8310270347
- --8310270427 LER 83-011/03L-0 bit 830510, diesel generator D2 tripped Caused by drift in Dryer pressure switch Model 1822 J Switch recalibr HUNSTAD.A A , MUSOLF.D Northern States Power Co 83/05/24 Region 3, Office of Director 3pp 20938 095 24X Fiche 50-000,83/09/29,8310270347
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-El10M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN. M J Forbaro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement lipp 20451 044 24X Fiche 50-000,83/09/30,8310070301
- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310180242 Forwards IE Insp Rept 50-285/83-21 on 830815-19 No noncompliance noted SEIDLE.W C Region 4, Office of Director 83/09/20 JONES.W.C Omaha Public Power District 2pp 20802 309 24X Fiche 50-285.83/09/20.8310180242
- --8310180246 IE Insp Rept 50-285/83-21 on 830815-19 No noncompliance noted Major areas inspected emergency response program MONTGOMERY, J. L. BAIRD, J. B. JOHNSON, W. D. Region 4. Office of Director 83/09/15 9pp 20802 311 24X Fiche 50-285,63/09/20,8310180242
- 8310130306 Ack receipt of 830729 ltr informing NRC of util inability to meet 830630 commitment dete for conducting sampling & analysis drill Alternate post-accident sample analysis facility must be operational SEIDLE.W C Region 4. Defice of Director 83/09/22 JDNES.W.C Omaha Public Power District 2pp 20719 273 24X Fiche 50~285,83/09/22,8310130306

- 8310050298 Forwards application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of emergency & security plans Certificate of Svc encl MARCQUX, W C LeBosuf, Lamb, Leiby & MacRae MARCQUX, W C Gmaha Public Power District 83/10/03 DENTON, H R Office of Nuclear Resctor Regulation, Director 3pp 20632 087 24X Fiche 50-285, 83/10/03, 83/10050298
- --8310050310 Application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of energency plan, site security plan & safeguards contingency plan JONES, W. C. Omaha Public Fower District 63/09/27 2pp 20432 090 24% Fiche 50-285,83/10/03,8310050298
- --8310050315 Proposed Tech Specs re pressurizer operability.e)ectrical sys, snubbers, surveillance requirements for RCS, reactor core parameter & environ radiological monitoring & administrative controls

 * Omaha Public Power District 83/09/27 14pp 20632 09P 24X fiche 50-285,83/10/03,8310050298
- 83:01:0029 Releases public version of changes to emergency plan implementing procedures FELTON.JM Division of Rules and Records 83/10/05 Document Management Branch Ip 20685-257 24X Fiche 50-285,83/10/05, 83:00:10329
- --B310110330 Forwards public version of changes to emergency plan implementing procedures W/o encl JONES,W C Omaha Public Power District 83/09/12 COLLINS,J.T Region 4, Office of Director 1p 20685 258 P4X Fichs 50-285,83/10/05,8310110329
- 9310130307 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20769 053 24X Fiche 50-205,83/10/06, 8310130307
- --B310130308 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP-DSC-7 repersonnel rescue & EPIP-EOF-3 remergency instruments & equipment Receipt form encl JONES, W C (Emaha Public Power District 83/09/29, COLLINS, J T Region 4, Dffice of Director 3pp 20769 054 24X Fiche 50-285,83/10/06.8310130307
- --8310130309 Public version of revised emergency plan implementing procedures, including Procedures EPIP-DSC-7 repersonnel rescue to EPIP-EPI-3 remergency instruments to equipment to Omaha Public Power District 83/08/30 110pp 20789 057 24X Fiche 50-285,83/10/06,8310130307
- 8310210366 Releases public version of revised emergency plan implementing procedure FELTON.J H Division of Rules and Records 83/10/17 Document Management Branch 1p 20882 356 24X Fichs 50-285.83/10/17, 6310210366
- --B310210370 Public version of Rev 2 to Emergency Plan Implementing Procedure EPIP-DSC-7 W/B30930 ltr & receipt form JONES.W C Omaha Public Power District B3/08/30 COLLINS.J T Region 4. Office of Director 4pp 20882 357 24X Fiche 50-285/83/10/17,8310210366
- 8310250660 Releases public version of section to radiological emergency response plan FELTDN.J H Division of Rules and Records 83/10/20 Document Management Branch 1p 20908.221 24X Fiche 50-285.83/10/20.8310250660
- --8310250667 Public version of Section M to radiological emergency response plan entitled, "Recovery & Reentry Planning & Post-Accident Operations " W/831010 ltr JONES. W C Omaha Public Power District 83/08/31 COLLINS. J T Region 4, Office of Director, dipp 20708 222 24X Fiche. 50-285, 83/10/20, 8310250660
- '. Operating license stage documents & correspondence
- IBIO180405 Authorizes relief, an interim basis, from inservice insp/ testing requirements of ASME Code for pumps & valves, per util 830707 request. SER & notice of granting of relief enci MILLER, J R Operating Reactore Branch 3 83/09/30 JONES, W C Omaha Public Power District 3pg 20825, 346 24X Fiche, 50-285, 83/09/30, 8310180405

- --B3(0180408 Safety evaluation granting relief from ASMF Boiler & Pressure Vessel Code.Section XI insp/testing requirements for pumps & valves # Office of Nuclear Reactor Regulation, Director 83/09/30 4pt 20825 349 24X Fiche 50~285.83/09/30.8310180405
- --8310180410 Notice of granting of relief from cartain ASMC Code insp/testing requirements for pumps & valves MILLER.J.R. Ogerating Reactors Branch 3 83/09/30 2pp 20825 350 24X Fache 50-285, 83/09/30, 8310180405
- 8310310129 Forwards safety evaluation based on review of util responses to NUREG-0737 items Requirements of NUREG-0737. Item II K 3 2 met MILLER, J R Operating Reactors Branch 3 83/09/30 JONES, W C Omaha Public Power District 14pp 21000 079 24X Fishe 50-285, 83/09/30, 8310310329
- 8310050245 Forwards application for amend to License DPR-40 revising Tech Spec Fable 2-6(a) 5 3-7 to update surveillance capsule removal schedule Certificate of Svc encl * LeBosuf, Lamb, Leiby & MacRae 83/10/03 DENIGN.H Office of Nuclear Reactor Regulation, Director Spp 20628 270 24X Fiche 50-285,83/10/03.8310050245
- ~-8310050255 Application for amend to License DPR-40 revising lech Spec Tables 2-6(a) & 3-7 to update surveillance capsule removal schedule JONES, W C Umaha Public Power District 83/10/03 2pp 20628 273 24X Fiche 50-285,83/10/03,8310050245
- --831005027! Proposed changes to Tech Spec Tables 2-6(a) & 3-7 to update surveillance capsule romoval schedule
 * Omaha Public Power District 83/10/03 lip 20628 275 24X
 Fiche 50-285.83/10/03,8310050245
- 8310050298 Forwards application for amend to License DPR-40, revising Tech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequescy of emergency & security plans Certificate of Svc encl MARCOUX.W C LeBopuf Lamb. Leiby & MacRae MARCOUX.W C Omaha Public Power District 83710/03 DENTUN.H R Diffice of Nucleum Reactor Regulation, Director 3pp 20632 087 24% Ficho 50-285, 83/10/03,8310050298
- --8310050310 Application for amend to License DPR-40, revising lech Specs to incorporate administrative changes & NRC requests in Generic Ltrs 82-17 & 82-23 re audit frequency of emergency plan, site security plan & safeguards contingency plan JONES W C Omaha Public Power District 83/09/27 2pp 20432 090 24% Fiche 50-285,83/10/03.8310050298
- --B3100B0315 Proposed Tech Specs re pressurizer operability, electrical sys, snubbers, surveillance requirements for RCS, reactor core parameter & environ radiological monitoring & administrative controls

 * Dmaha Public Power District 83/09/27 14pp 20432 092 24X Fiche 50-289,83/10/03,83100b02/8
- 8310130137 Approves 830731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Ouestions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 790 CRUTCHFIELD, D. Operating Reactors Brossch 5 83/10/03 LUNDVALL, A E. Baltimore Gas & Electric Co. 6pp 20777 060 24X Fiche 50-000, 83/10/03,8310130137
- 8310130061 Notification of 831012-13 meetings w/util in Omaha.NE to discuss proposed radiological effluent Tach Spacs & to resolve open items
 TOURIONY.E @ Operating Reactors Branch 3 83/10/05 MILLER.J R Operating Reactors Branch 3 2pp 20/76 218 24X
 Fiche 50-285,83/10/05.8310130061
- 8310280087 Forwards safety evaluation re review of util submittal addressing NUREC-0737. Item II K 2 17. "Voiding in RCS During Anticipated Transients" Steam void will not result in unacceptable consequences
 MILLER, J R Operating Reactors Branch 3 83/10/17 JONES, W C Doaha Public Power District 9pp 20961 349 24X
 Fiche 50-285.83/10/17.8310280087
- a Inspection reports, IE Bulletins & correspondence
- B310130168 Forwards IE Insp Rept 50-285/83-18 on 830701-29 No noncompliance noted SEIDLE, W C Region 4: Office of Director 83/08/10 JUNES, W C Omaha Public Power District 2pp 20724, 284 24X Fiche 50-285, 83/08/10. 8310130168

DOCKETED ITEMS

- --8310130171 IE Insp Rept 50-285/83-i8 on 830701-29 No noncompliance noted Major areas inspected operational safety verification, surveillance testing, maint activitier & followup of violations YANDELL, L A , JOHNSON, W D Region 4, Office of Director B3/08/08 5pp 20724 286 24% Fiche 50-285,83/08/10,8310130168
- 8310040567 Forwards IE Insp Rept 50-285/83-17 on 830627-0/01 & notice of violation
 SEIDLE, W.C. Region 4. Office of Director 83/08/19 JONL's, W.C. Omaha Public Power District 2pp 20622 257 24X
 Fiche 50-285,83/08/19,8310040567
- --83100405/1 Notice of violation from this on 83062/-0/01
 * Region 4, Office of Director 83/08/19 1p 20622 259 24X
 Fiche 50-289,83/08/19,831004056/
- --B31004097/ IE Insp Rept 50-285/83-17 on B30627-070) Noncompliance noted failure to take prompt corrective action redeficiencies in program for mgt of const records (including design & mfg records)
 BOARDMANJ R. (ROSSMAN, W.A.: JOHNSON, W.D. Region 4, Office of Directur B3/08/17 10pp 20622 260 24X Fich. 50-285.83/08/19, B31004056/
- 8310130272 Forwards IE Insp Rept 50-285/83-19 on 830801-05 No noncompliance Heted SEIDLE, W.C. Region 4. Office of Director 83/08/22 JONES, W.C. Omaha Public Power District App 20/19 335 24% Fiche 50-285,83/08/22,8310130292
- --B310130295 IE Insp Rept 50-285/83-19 an B30801-05 No noncompliance nated Major areas inspected action on previous insp findings.onsite committee.program for calibr & surveillance & implementation of calibr program JAUDDN, J P., JOHNSON, N D Repion 4, Office of Director 83/08/19 App 20719 337 24X Fiche 50-285.03/08/22.8310130297
- 8310180242 Forwards IE Insp Rept 50-285/8J-21 on 830H15-17 No noncompliance noted SEIDLE,W C Region 4. Office of Director 83/07/20 JONES,W C Omaha Public Power District 2pp 20802 309 24X Fiche 50-285.03/07/20.8310180242
- --8310180246 IE Insp Rept 50-285/83-21 on 830815-19 No noncompliance noted Major dreas inspected emergency response program MONTGOMERY, J. L. BAIRD, J.B., JUHNSON, W.D. Region 4, Office of Director 83/09/15 9pp 20802 3ii PAX Fiche 50-285,83/09/20,8310180242
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-ins for Welder Qualification Tests " Svc list ont! JORDAN, E. L. Divinion of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 072 24X Fiche 50-000.83/09/26.8308J00740
- 8308300342 IE Info Notice 83-62, "failure of Redundant Toxic Gas Betectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison to af New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,83083000442
- 8308300345 IC info Notice 83-64, "Potential Failures of Westinghouse Type SA-I Differential Relays " Svc list and JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 P4X Fiche 50-000,83/09/26,8308800345
- 8310210008 Forwards "Omaha Power District.Fort Calboun Station,Unit 1 Inservice (nsp Program Plan for 1983-7J Interval " Plan will be placed into effect on 830076
 JUNES.W C. Omaha Public Power District 83/09/26 MILLER, J R Operating Reactors Branch 3 tp 20054 336 24X
 Fiche 50-285.03/09/26.8310210008
- --83:0210013 "Omaha Public Power Bistrict.Fort Calhoun Station.Unit I Inservice Insp Program Plan for 1983 73 Interval " + Southwest Research Institute 83/08/30 128pp 20834 33/ 24X Fiche 50 285,83/09/26.63102:0008
- B30B300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10C/R50 59 Evaluation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308J00J49

- 8310180405 Authorizes relief.on interim basis, from inservice insp/ testing requirements of ASME Code for pumps & valves.per util 830707 request SER & notice of granting of relief encl MILLER.J R Operating Reactors Branch 3 83/09/30 JDNES.W C Omaha Public Power District 3pp 20825 346 24X Fiche 50-285,83/09/30.8310180405
- --8310180408 Safety evaluation granting relief from ASME Builer & Pressure Vessel Code.Section XI insp/testing requirements for pumps & values * Diffice of Nuclear Reactor Regulation, Director 83/09/30 4pp 20825 349 24X Fiche 50-285.83/09/30.8310180405
- ---8310180410 Notice of granting of relief from certain ASME Code insp/tosting requirements for pumps & valves HILLER, J. R. Operating Reactors Branch 3 83/09/30 2pp 20825 353 24% Fiche 50-285,83/09/30,8310180405
- B310120094 Forwards Class III payment for approval of relief requests from ABME Boiler & Pressure Code, Section XI inservice image requirements

 JONES, W.C. Omaha Public Power District 83/10/05 MILLER, J.R. Operating Reactors Branch 3 2pp 20696-185 24X
 Fiche 30-285, 83/10/05, 8310120094
- B30B300378 IE Info Notice B3-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co. of New York. Inc. 74pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Mat) Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043-075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fichs 50-000, 83/10/11.0308300761
- 8310180500 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-17

 OAGLIARDOJ E Region 4. Office of Director 83/10/13 JONE9.W C Omaha Public Power District ip 20801
- --B31018050A Responds to NRC 800819 ltr re violations noted in IF lnsp
 Rept 50-285/83-17 Corrective actions const mods to correct
 deficiencies re GA records file room completed on 820723 &
 recordkeeping improved Schedules provided
 JDNES.W C Omaha Public Power District 83/09/19 SEIDLE.W C
 Region 4, Office of Director Opp 20801 190 24X
 Fiche 50-285.83/10/13.8310180500
- R Periodic operating reports & related correspondence
- B3101B0162 Monthly operating rept for Sept 1983 W/B31013 ltr MATTHEWS, T P , JONES, W C Omaha Public Power District 83/09/30 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 10pp 20B09 137 24X Fiche 50-285,83/09/30, 83101B0162
- S Reportable occurrences. LERs & related correspondence
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EliQM transmitter Underrange iero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.M J Folboro Corp 83/09/30 Director's Office, Dffice of Inspection and Enforcement 11pp 20651 964 24X Fiche 50-000,83/09/30,83100/0301

- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8310050548 Forwards post-exercise/post-drill assessments, per US Bragg 830608 commitment Previously noted deficiencies corrected MCLOUGHLIN, B Federal Emergency Management Agency 83/09/29 DIRCKS W J Office of the Executive Director For Operations Ppp 20829 267 24% Fiche 50-003, 83/09/29, 8310050548
- --B310030552 Post-exercise assessment of B30924-25 exercise,Rockland County,for Indian Point Nuclear Power Station * Federal Emergency Management Agency 83/09/26 56pp 20429 248 Fiche 50-003,83/09/29,8310050548
- -8310050554 Post-drill assessment of 830823 drill of Westchaster County bus evacuation procedures for Indian Point Nuclear Power Station * Federal Emergancy Management Agency 83/09/1 20529 328 24% Fiche 50~003.83/09/29.8310050548 83/09/15 988
- 8310130305 Forwards FEMA 830929 ltr transmitting FEMA Region II postrevercise assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County HASEELL.D F Hearing Branch I 83/10/04 QLEASON, 0 P Atom Safety and Licensing Board Panel 1p 20719 204 24X Fichm 50-247, 83/10/04, 8310130305
- 8310140195 Act receipt of 830722 ltr re corrective actions taken in response to 830822 ltr re IE Insp Rept 50-286/83-12 Corrective actions uill be withheld (ref 100F873 21) MARTIN.T T Division of Engineering & Technical Programs 83/10/880NS.J C Power Authority of the State of New York 2pp 20762 331 24X Fiche 50-286.83/10/04.8310140195
- 8310170321 Staff requirements memo re Commission 831000 briefing by FERA on recent emergency planning exercises in vicinity of facilities Commission noted successful completion of exercise Enforcement action unnecessary CHILK-8 J Office of the Secretary of the Commission 83/10/11 Office of the Secretary of the Commission 83/10/11 Fiche 50-247,83/10/11-8310170321
- 3310240155 Forwards implementation schedule for security plan, per 830727 request Procedural portion implemented, effective 830501 NVS study re hardware portion expected 831130 Schedule for remaining hardware items espected by 840331 BAYNE, J.P. Power Authority of the State of New York 83/10/17 VARCA, S. Operating Reactors Branch 1 2pp 20881 721 24X Fiche 50-286, 83/10/17. 8310240155

Adjudicatory correspondence

- G10130305 Forwards FEMA 830927 lts transmitting FEMA Region 11 post-esercise assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County HASSELLO F Hearing Branch | 83/10/04 QLEASON, 9 P. PARRISO H . SHOW.F J Atomic Safety and Licensing Board Panel 20719 204 24X Fiche 50-247.83/10/04.8310130305
- 310190145 Advises that SM Schinki & JF Heyer employed as legel & technical assistants, respectively Schinki & Meyer under recusal re Indian Point special proceeding due to previous employment contact BERNTHAL.F Commi PERNTHALIF Commissioners Board Panet Ip page . |signers | 83/10/17 | 20809 169 | 24% Fict 93/10/17 Atomic Safety and Licensing 24X Fiche 50-247,83/10/17.8310180145
- 10190085 Order advising that ABLB expects to issue recommendations to Commission by 831024
 GLEASON, J.P. Atomic Safety and Licensing Board Panel
 1p. 20822 267 24X Fiche 50-247, 83/10/17,83:0170085
- 10240187 Forwards RH Bogardus 930920 ltm re adequacy of radiological embrygency response plan
 HEBBEK.R F New York, State of 83/t0/17 NRC - No Detailer
 Affiliation Given 3pp 20878 089 24X Fiche 50-24/.83/10/17.
- 10260224 Opinion & recommendations to Commission on societal significance of risk estimates ASLB recommended safety improvements necessary to ensure plant will be operated itreasonable assurance that public safety will be protected iMON.F J. PARIS, D.H. OLEASON, J.P. Atomic Safety and Licensing loand Panel 83/10/24 306pp 20913 033 24X (che 50-247,83/10/24,8310260224

- P Operating license stage documents & correspondence
- B310310017 FDIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER. L Affiliation Unknown 83/05/02 NHC No Detailed Affiliation Given lp 21004 2/0 24X Fiche 50 000/83/05/02. B31031001/
- B310030663 Forwards evaluation of & current NRC guidelines for bu061/ process control program Final program within 30 days requested Final radiological officent lech Specs due 60 days requested rinal raciological errivant leth spets of from 870802 VARCA,S A Operating Reactors Branch I 83/09/19 Pawer Authority of the State of New York 15pp 2 Fiche 50-286,83/09/19,8310030663 50%56 751
- 8J10040035 Forwards safety evaluation of licensee responses to requirements of NUREG-0737. Item II B 1, "RCS Vents " Item completed ILL technical evaluation rept enci VARGA, B A Operating Reactors Branch | 83/09/19 BAYNE, J P Power Authority of the State of New York 9pp 20634 3/1 2 Fiche 50-286,83/09/19.8310040035
- --B306030372 "Selected Operating Reactor Issues Program II RCS Vents (NUREC-0737. Item II B 1): "final trchnical evaluation rept HELD. J Energy Incorporated * Lawrence Livermore Laboratory FIN A-0250 TF-324/0806A B3/02/14 ALBERTHAL.6 Division of Licensing 6pp 20634 330 24X Fichs 50-286.83/09/19.87100400.15
- 8310130041 Summary of 830817 meeting w/util in Bethesda.MD re suc interaction program Util advised that mgt level meeting should be expected in near future d be expected in near future P J Operating Reactors Branch 1 83/07/29 Operating ors Branch 1 11pp 20/76/242 24% Ficho 50-286,83/09/2°4, POLK P J
- 8310070340 Forwards Suppl i to plant-specific evaluation of LPR1 safety & relief valve performance testing submitted on 821215
 Suppl details adequacy of inlet & discharge piping for pressurizer safety & relief valves per TMI Item II D 1
 BAYNE, J. P. Power Authority of the State of New York 83/09/30
 VARGA, S. A. Operating Reactors Brunch I 8pp 20452 157 24X Fiche 50-286, 83/09/30, 8310070340
- 8310070349 Forwards payment of fees for 830503 & 0601 applications for amends to License DPR-64 Payment made under protest pending final determination of logality of fee schedule BAYNE.JP Power Authority of the State of New York 83/09/30 MILLER.W D License Fee Management Branch 2pp 20651 077 (AFICHE 50-286.83/09/30-8310070349
- 8310110222 Forwards application for amend to License DPR-64.changing radiological ETS Sections 6 5.6 8.6 7 & 6 10 to reflect draft Rev 3 to NRREG-0472.in response to NRC 820907 ltr BAYNE.J P Power Authority of the State of New York 83/09/30 VARSA.S A Operating Reactors Branch 1 2pp 20669 138 24X Fichs 50-286.83/09/30.8310110222
- --8310110228 Application for amond to License DPR-64, changing radiological ETS Sections & 5.6 B.4 9 & 6.10 to reflect draft Rev 3 to NUREG-0472, in response to NRC 82090/ Hr BAYNE, J P Power Authority of the State of New York B.4 Ppp 20669 140 24% Fiche 50-286, 3J/09/30, 8J101102/22 83/09/30
- ~-8310110231 Proposed Tech Spec changes revising Sections 6 5.6 U. 6 9 & 6 10 to reflect draft Rev 3 to NUKEG-0472 * Fower Authority of the State of New York 83/09/30 96pp 20669 149 24% Fiche 50~286,83/09/30,8310110222
- 8310170200 Requests site visit be acheduled for 831101 03 to review surinteraction study Lists personnel necessary for productive wisit
 - VARGA, 5 A Operating Reactors Branch 1 83/09/30 BAYNE, J.P. Power Authority of the State of New York 3lpp 20817 309 Fiche 50-286, 83/09/30, 83101/0200
- 8308300763 Roard Notification 83-151 provides info re desirability of current ECCS actuation logic for Hestinghouse plants in light of recent info concerning steam generator tube rupture procedure for Borskele Nuclear Power Station EISENHUT.D 0 Division of Licensing 83/10/04 PALLADINO,N J . of LinkKy. V. ROBERTS.T. Commissioners 2pp 20498 URJ 247 Fiche 50-000.63/10/04/8308300763
- 8308300771 Doard Notification BJ-178A forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid V41V84
 EISENHUT.D Q Division of Licensing 83/10/06 PALLABINO,N J
 Commissioners 31pp 20818 UOL 24x Fiche 50-000, 83/10/06,
 8308300//1

- 8310170554 Confirms telcon agreement re submittal of final rev to snubber surveillance Tech Spocs by 831209 8AYNE J P Power Authority of the State of New York 93/10/07 VARGA.5 A Operating Reactors Il Ponch I 2pp 20780 211 247 Fiche 50-286,63710/07.8310170554
- 8310240114 Forwards revised sections to QA program in response to NKC 800923 questions Revised portions will be incorporated into 1984 annual FSAR update BAYNE, J P Power Authority of the State of New York 83/10/17 VARGA, S A Operating Reactors Dronch 1 38pp 2088 102 24x Fiche 50-286,83/10/19,8310240114
- 8310310066 Responds to 830815 request for add1 info re NUREG-0/3/, Item 11 B 3, "Post-Accident Sampling Sys," providing supplemental info concerning two of four open criteria & schedule for responding to remaining requests

 BAYNE, J P Power Authority of the State of New York 83/10/26

 VARGALS A Deparating Reactors Branch 1 8pp 20951 03P 24X

 Fiche 50-286,83/10/26,8310310064
- Q Inspection reports: IE Bulletins & correspondence
- 8310120178 Forwards IE Insp Rept 50-286/83-16 on 830816-0715 Nu noncompliance noted STARDSTECKI, R Division of Project & Resident Programs 03/09/20 8680NS.J C Power Authority of the State of New York 2pp 20695 335 24% Fiche 50-286/83/09/20,8310120198
- --8310120199 IE Insp Rept 50-286/83-16 on 830816-0915 No nencompliance noted Major areas inspected maint review of monthly operating rept. (MI task action plan status licensee actions on previous insp findings.plant tour & surveillance KENNY.T J . ROSSBACH.L W . NORRHOLM.L Region 1, Office of Director 83/09/19 12pp 20695 337 24X Fichs 50-286,83/09/20,8310120198
- 8310110A65 Forwards safety evaluation & technical evaluation rept re completion of IE Bulletin 80-11, "Masoniy Wall Design" All work associated w/subj hulletin completed VARGA, S. A. Operating Reactors Branch I. 83/09/23 BAYNE, J.? Power Authority of the State of New York. 3pp. 20712 238 24X Fiche 50-286,83/09/23,8310110465
- --8309180203 "Masonry Wall Design (B-59), Indian Point Noclear Power Plant, Unit 3," technical evaluation rept TRICLO.S Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05506-261 83/09/14 CHCMSHI, N C NRC No Detailed Affiliation Given 23pp 20712 241 74X Fiche 50-286,83/09/23,8310110465
- 830B300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests" Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,830G.00340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes "Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co of New York, Inc 114pp 20777 210 P4X Fiche 50-000,83/09/26,8308400342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list and JORDAN-E 1 Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fichs 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 39 Evaluation " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310140195 Ack receipt of 830722 ltr re corrective actions taken in response to 830622 ltr re IE Insp Rept 50-286/83-12 Corrective actions will be withheld (ref 100FR73 21) MARTIN.T T Division of Engineering & Technical Programs 83/10/04 BRONS, J C Pawer Authority of the State of New York 2pp 20762 331 24% Fiche 50-286/83/10/04.8310140195
- BJ0B30037B IE Info Notice B3-65. "Surveillance of Flow in RID Bypass Loops Used in Westinghouse Plants " Evc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07. Consolidated Edison Co of New York, Inc. 76pp 20827 213 24% Fiche 50-000.83/10/07.83083080378

- 8308300752 IE Info Notice 83-66, "fatality at Argentine Critical Facility" Syc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 63-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Bvc list encl JORDAN, E. D. Division of Emergency Preparedness & Enganeering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043-079 24X Fiche 50-000,83/10/11,8308300757
- 8308300761 IE Info Notice 83-68, "Respirator User Marning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl URBAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000.83/10/11,8308300761
- R Periodic operating reports & related correspondence
- 8310190202 Monthly operating rept for Aug 1983 W/830909 ltr KELLEY,L : BRONS,J C Power Authority of the State of New York 83/09/01 Office of Resource Management. Director 7pp 20818 104 24X Fiche 50-286.83/09/01.8310190202
- 8310170603 Monthly operating rept for Sept 1983 W/831007 ltr KELLY,L , BRONS,J C Power Authority of the State of New York 83/10/01 Director's Office, Office of Inspection and Enforcement 7pp 20782 098 24X Fiche 50-226.83/10/01.8310170403
- S Reportable occurrences. LERs & related correspondence
- 831007030i Potential Part 21 rept re underronge characteristic of Model N-EliOM transmitter Underrange zero offset may occur uhen transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERDERIAN M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 1 ipp 20451 064 24X Fiche 50-000.83/09/30,8310070301
- 8310140082 PNO-I-83-105 on 831007, seismic event occurred in northeastern U5 w/magnitude of 5 2 on Richter scale in NY 5 4 0 in NH No damage to equipment identified GALLOR M Region i. Office of Director 83/10/07 ip 20766 116 24X Fiche 50-000, 83/10/07, 8310140082
- T Hearing transcripts on non-antitrust matters
- B310120029 Transcript of B31003 open session in Washington.DC re emergency planning Pp i-28 Supporting documentation enci * Commissioners B3/10/03 Ilipp 20750 076 24X Fiche 50-003,83/10/03.8310120029
- V Operator Examinations
- B31007024B Requests schedular exemption from NRC rulemaking re licensed operator staffing until B40331 Exemption would allow persons schedulad for exam in Dec 1983 to complete testing & become qualified to stand watch B4NB. J P Power Authority of the State of New York B3/09/30 VARQA.S A Operating Reactors Branch 1 ip 20659 127 24X Fiche 50-286,83/09/30,831007024B
- DOCKET 50-287 DOONEE NUCLEAR STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- B310070134 Releases public version of revised crisis mgt plan implementing procedures FELTON, J.M. Division of Rules and Records B3/10/04 Document Management Branch 1p 20670 001 24X Fichs 50-000, B3/10/04. B310070134
- ---8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 1 rerecovery manager & immediate staff group plan & 5 3 4 rescheduling/planning support group TUCKER:H B Duke Power Co 83/07/06 DENTON,H R Office of Nuclear Reactor Regulation. Director 3pp 20670 002 24x Fiche 50-000,83/10/04,83100/0134
- --B310070152 Public version of revised crisis mgt plan implementing procedures including Procedure 5 3.1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group # Duke Power Co #83/07/01 457pp 20670 005 24X Fich 50-000, B3/10/04, B310070134

- 8310110067 Releases public version of revised emergency plan implementing procedures
 FELTON. JR Davision of Rules and Records 83/10/05 Decument Management Branch ip 20709 160 24% Fiche 50-269, 83/10/05, 83/10/067
- --8310110076 Forwards public version of revised emergetrcy plan implementing procedures, including Procedure CP/0/B/4003/0) re environ surveillance following large unplanned release of gaseous radioactivity Rereipt form encl TUCKER: H B . MCINTOSH. J T Duke Power Co 63/09/19 O'REILLY, J P Region 2. Office of Director 2pp 20709 161 249 Fiche 50-269.83/10/05.8310110067
- --8310110080 Public version of revised emergency plan implementing procedures, including Procedure CP/O/B/4003/OL re environ surveillance following large unplanned release of gaseous radioactivity SMITH.J E Duke Power Co 83/09/08 50pp 20709 IA3 24X Fiche 50-249,83/10/05.8310110067
- 8310110135 Releases public version of tev to emergency procedure FELTON, J H Division of Rules and Records 83/10/05 Document Management Branch Ip 20707-317 24X Fiche 50-269.83/10/05.8310110135
- --B310110141 Public version of Rev 83-5 to Emergency Procedure AP/D/ID/1000/07, "Procedure for Offsite Dase Calculation by Control Room Personnel or Emergency Coordinator During Radiological Accident " M/830830 ltr SMITH-J E , TUCKER-H B , MCINTOSH-J T Duke Power Co 03/07/22 O'REILLY, J P Region 2. Office of Director 19pp 2070/ 320 24X Fiche 50-269,83/10/05.83/0110135
- 8310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance nated DANCE.H C Division of Project & Resident Programs 83/10/05 TUCKER.H B Duke Pawer Co 2pp 20898 123 24X Fiche 50-269, 83/10/05, 8310250354
- --9310250363 IE Insp Repts 50-269/83-27.50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted Major areas inspected emergency detection & classification protective action decisionmaking public info program & shift staffing DECKER.1 R Region 2. Office of Director 83/09/30 5pp 20896 125 24X Fiche 50-269.83/10/05.8310250354
- 8310180444 Responds to request for crisis mgt ctr staff to pasticipate in emergency exercises at some frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation TUCKER, H B Dute Power Co 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director Epp 20802 121 24X Fiche 50-000,83/10/10,8310180444
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved O'REILLY, J.P. Region 2, Office of Director B3/10/17 TUCKEN, H. N. Duke Power Co. Spp. 20900 205 24X Fiche 50-000, 83/10/17, B310250635
- --8310250652 SALF Repts 50-249/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/03-13 for June 1982 Apr 1983 * Region 2, 0ffice of Director 83/08/02 56pp 20900 211 24X fiche 50-000, 83/10/17, 8310250635
- G3i0280029 Forwards request for exemption from fire protection requirements of IOCFR30. App R. Section III J re emergency lighting in control room, stainwells/colridors, outside auxiliary bldg & standby shutdown facility TUCKER. H B Duke Power Cn B3/10/24 BENTON: H R. Defice of Nuclear Reactor Regulation, Birector STGLZ, J C Operating Reactors Branch 4 App 20934 285 24X Fiche 50-269, 83/10/24, 8310280029
- 8310280124 Suppls 830603 ltr re exemption request from location requirements of emergency operations facility Bignificant benefits not achieved by near-site facility up to PO miles from plant Meeting w/NRC requested TUCKER.H B Duke Power Co 83/10/25 DENTON.H R Office of Nuclear Reactor Regulation, Director STOLZ.J F Operating Reactor, Branch 4 2pp 20929 266 24X Fiche, 50-269, 83/10/25, 0310280124

G Adjudicatory correspondence

B310130164 Forwards status rapt on hybrid hearing procedures under Section 134 of Nuclear Maste Policy Act Proposed rule on implementation of procedures awaits Commission action CUNNINGHAM, 9 H. Office of the Executive Legal Director B3/10/0/REHMIT. A. Office of the Executive Director for Operations 2pp 20724 291 24X Fiche 50-000, 83/10/07, 8310130164

- P Operating license stage documents & correspondence
- 8310040111 Responds to 830531 & 0826 ltrs requesting amond to BANJB confirmatory order re NURED-0/37. Item II F 1 5. "Containment Hater Level Monitor" Amend not required Environ qualification will be addressed in IOCF650 49 audit STOLZ, U F Operating Reactors Branch 4 83/09/02 TUCKER, R h Duke Paper Co Spp 2062/351 24X Fiche 50-269, B3/09/02. G310040111
- 831004064/ Forwards SER accepting Arkansus Power & Light Co (AM) 830607 proposed mods to reactor trip breakers for BAU plants Requested info should be provided when APL generit design endorsed in response to Generic Ltr 83-28 STOLZ. J T Operating Reactors Branch 4 83/09/12 INCKER.H D Duke Power Co 2pp 2062/ 303 24X Fiche 50-269, 83/09/12, 8360040647
- B310110545 Forwards Amends 123, 123, & 120 to Licensor UPR~18, DPY 4/1 DPR-55, respectively, safety evaluation & FIA Amends allow intrease in spont fuel storage capacity from 4/4 to mar of 825 fuel assembles in Unit 3 upent fuel pool STOLZ, J. F. Dperating Reactors Branch 4 B3/09/29 TUCKER, H. P. Duke Power Co. 2pp. 20711 265 24X fithe 50-267, 63/09/29, 8310110545
- --B310110561 Amends 123,123 & 100 to Licenses DPR-30,DPR-47 & propertively, changing Tech Specs to allow increase in spent feel storage capacity from 474 to max of 825 fuel assemblies in Unit 3 spent fuel pool STBLZ,J P Uperating Reactors Branch 4 B3/09/24 Tipp 20711 267 PAX Fiche 50-249,03/09/29,8310110545
- --8310110569 Safity evaluation supporting Amends 123,123 & 170 to Licenset IPR-38, DPR-47 & DPR-55, respectively * Office of Nuclear Reactul Regulation, Director 63/69//7 14pp 20711 278 24X Fiche 50-269,83/09/29,8310110545
- 8310140253 Forwards info re inservice pump & valve testing program Was enci.

 Was enci.

 TUCKER. H.B. Duke Power Co. 83/10/10 DENTON, H.R. Office of Nuclear Reactor Regulation, Director SCULZ, J.F. Operating Reactor Branch 4 1p. 20761 332 24X Fiche 50-269,83/10/10,63101402.d
- 8310240151 forwards steam generator operating history info valid through 821231 TUCKER.H B Duke Power Co 89/JO/13 DENTON.H R (Iffice of Nuclear Reactor Regulation, Director & FULZ, J F (Operating Institu-Branch 4 44pp 20881 176 24X Fiche 50-269,83/10/13.831024015
- 8310310489 Summary of 830826 merting w/b&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATMS & proposed ATMS tule for B&W plants List of attendees & viewgraphs enc! KADAMBI.P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20765 147 247 Fiche 50-000, 83/10/10/45
- 8310280105 Forwards update of progress of control room habitability mods.per 830929 ltr re TMI Item III D 3 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedulet enci TUCKER.H D Duke Power Co 83/10/24 DENTON.H R Office of Nuclear Reactor Regulation, Director STULZ.J F Operating Reactor Branch 4 2pp 20935 324 24% Fiche 50-269.83/10/24.8310280105
- Q Inspection reports. IE Bulletins & correspondence
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Laergency Preparedness & Engineering Response (Post 830103) 83/09/226 Consolidated Edison Co. of Ma. York, Inc. 118pp 20778 001 24X Fiche 50-000.83/09/26.8388X035
- 8310040290 Forwards IE Insp Repts 50-269/83-24, 50-270/63 24 & 50-287/83-24 on 830725-0803 No noncompliance noted DANCE.H (Division of Project & Resident Programs B3/08/30 TUCKER:H 8 Dake Power Co 2pp 206/7 268 24X Fiche 50-269, 83/08/30, 8310040290
- --B310040294 IE Inap Repts 50-269/B3-24.50-270/B3-24 & 50-287/B3 24 or 830725-0B03 No noncompliance noted Major areas inspected containment integrated leakage rate testing & followup on previous items
 BROOKB.F H Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs 83/08/26 4pp 20417.270 24X Fichs 50-269, B3/08/30.0310040270

- 9310040575 Responds to IE Bulletin 83-05, "ASNE Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co "One Hayward Tyler pump currently installed in Unit 1 & 2 spent fuel cooling sys Twelve pumps to be installed in Tadwaste facility TUCKER, H B Duke Power Co 83/09/08 D'REILLY, J P Region P, Office of Director 5pp 20622 278 E4X Fiche 50-265,83/09/08,8310040575
- 9310040247 Forwards IE Insp Repts 50-269/03-25, 50-270/03-25 & 50-287/83-25 on 830809-11 No noncompliance noted DANCE, H C Division of Project & Resident Programs 07/09/07 TUCKER, H B Duke Power Co 2pp 20610 194 24X Fiche 50-269, 83/09/09, 8310040247
- --8310040253 [E Insp Repts 50-269/83-25, 50-270/83-25 & to-287/83-25 m 830809-11 No noncompliance noted Major aleas inspected zolo power physics testing & power escalation testing DAVENPORT.K.L. Region 2. Office of Director JAPE. Division of Engineering & Operational Piograms 83/09/07 5pp 20613 196 24X Fiche 50-249,83/09/09,0310040247
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification lests " Syc list ont! JORDAN C L Division of Emerging Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison to of New York Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,0308,00340
- 8308300342 IE Info Natice 83-62, "Tailure of Redundant foxic Gas Detectors Positioned at Control Room Ventilation All Intakes "Syx list entl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83/09/26,8308,0034;2
- 8310250248 Forwards IE Insp Repts 50-269/83-28, 50-270/83-28 & 50-287/83 28 on 830811-0910 No noncompliance noted DANCLIM C Division of Project & Resident Programs 03/09/2/TUCKER, H k Duke Power Co Ip 2007/9 074 24X Fiche 50-269, 83/09/27, 83/0250/48
- --8310250254 IE Insp Repts 50-249/83-28.50-270/83-28 & 50-28//83 28 on 830811-0910 Na noncompliance noted Major areas inspected operations, miint surveillance, training & NUREO-0737 items GRYWNI, J. I ALCONEN, D. Region 2. Office of Director BROWNLEE, V Division of Project & Residint Programs B3/09/27 10pp 20897 075 24X Fiche 50-249,83/09/27,83/0250248
- 8310040A84 Ack receipt of B30917 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-269/83-26 DANCE.H C Division of Project & Resident Programs 83/09/28 TUCKER, H R Duke Power Co 1p 20625 170 24X Fiche 50-269,83/09/28,8310040444
- --B310040492 Responds to NRC B30824 ltr re violations noted in If Insp. Repts D0-249/83-26.50-270/83-26.50-28/93-26. Corrective actions recirculation / release procedures revised to veryfy sign off for cloting valves
 TUCKER.II B. Dirke Power Co. B3/09/19. O'REILLY, J.P. Region P. Office of Director. 2pp. 20625-171. PAX Fiche 50-269.83/09/28.8310040484
- --9310040495 Forwards IE Insp Rupts 50-247/83-26,50-270/83 26 & 50-287/83-26 un 830711-0810 & notice of violation DANCE.II t. Division of Project & Resident Programs 83/08/24 TUCKER, H B Duke Pawer Ca 2pp 20625 173 24X Fiche 50-269,83/09/28,8310040484
- --831004050/ IE Insp Repts 50-269/83-26.50-2/0/83-26 to 50-287/83 26 on 830711-0810 Noncompliance noted failure to follow chemistry procedure resulting in unplanned release of radioactive water BRYANT, J. FALCONER, D. Region 2. Office of Director BRUDANIII.V Division of Project & Resident Programs 83/08/25 7pp 20625 176 24% Fische 50-269,81/09/28,8310040484
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related 8ys W/o 1008850 59 Evaluation " Svc lift enc! JORDAN, E L Division of Lamerency Picparedness & Engineering Response (Post 830103) 80309729 Consolidated Edison Co. of New York, Inc. 11bpp 20716 324 24X Fiche 50-0000 03709729, 8380 00049
- #310250354 Forwards IE Insp Repts 50-269/83-27, 50-270/80-27 & 50-287/83-27 on 830912-16 No noncompliance noted DANCE.H C Division of Project & Resident Programs 03/10/05 TUCKER.H B Duke Power Co 2pp 2049H 123 24X Fichs 50-269, 83/10/05 8310950354

- --8310250363 IE insp Repts 50-269/83-27.50-270/83-27 & 50-287/83-27 on 830912-16 No noncompliance noted Major areas inspected emergency detection of classification.protective action decisionmaking.public info program & shift staffing DECKER, F R Region 2. Office of Director Jenkins 0 R Division of Emergency Preparedness & Materials Safety 83/09/30 Spp 20898 125 74X Fiche 50-269.83/10/00.8310250354
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Suc list encl JORDAN, L L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fich. 50-000,83/10/07,8308300378
- 8308300752 IC Info Notice 83-66. "Fatality at Argentine Critica)
 Facility " Svc list encl
 JCRDAN.E [Division of Emergenry Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Ldison Ca of New
 York Inc 79pp 20882 026 24X Fiche 30-000.83/10/07.8308300752
- 830B309759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Notious Gases" Sv. list ench
 JORDAN, EL Division of Emergency Presarcines & Engineering
 Response (Post 830103) 83/10/11 Chancelidated Edison Co of New
 York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300757
- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders" Svi list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved O'REILLY, J.P. Region 2. Office of Director 63/10/17 TUCKER. H B Duke Power Co. 3pp. 20900 20% 24% Fiche 50-000,83/10/17, 8310250635
- ---8310280646 Forwards SALP Rept. 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-287/83-17, 50-269/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 Api 1983 LEWIS.R C Division of Project & Resident Programs D3/08/02 TUCKER.H B Duke Power Co 3pp 26900 208 24X Fiche 50-006, 83/10/17, 8310250635
- --8310280682 SALP Repts 50-269/83-17,50-270/83-17,50-28//83-17, 50-369/83-24,50-370/83-32,50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983 * Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000,83/10/17,8310250635
- --8310250465 Responds to 830802 Itr re SALP board rept Rept incomplete & premature in certain areas in general, util endorses observations re facility periormance
 TUCKER.H B Duke Power Co 03/08/29 D'REILLY, J P Region P,
 Office of Director 2pp 20900 267 24X Fiche 50-000.83/10/1/,
 8310250635
- B310270079 Forwards response to Action Item 3 of 1E Bulletin B0-11,
 "Masonry Wall Dusign " Design assumptions appropriate
 considering physical condition of boundary joints
 TUCKER: H B Duke Power Co B3/10/20 DENTON, H R Office of
 Nuclear Reactor Regulation, Directon SfUC7, J F Operating Reactors
 Branch 4 3pp 20924 360 24X Ficho 50-269, B3/10/20, B310270079
- R Periodic operating reports & related correspondence
- 8310180167 Monthly operating repts for Bopt 1983 W/831014 ltr REAVIS.J A., TUCKER.H B. Duke Power Co. B3/09/30 Director's Office. Office of Inspection and Enforcement 17pp 20809 098 24X Ficha 50-269, 83/09/30.8310180167
- S Reportable occurrences. LERs & related correspondence
- 8310260008 Add1 response to FOIA request for 1/ categories of rocords Forwards documents listed in Apps B.C & D Info referandulent practices of Ray Millor. Inc available in PDR FELTON.J M. Division of Rules and Records 83/06/23 CLEMETI, J. Public Citizen Litigation Group 15pp 20920 001 24X Fiche 50-000, 03/06/23, 8310260009
- ~-8207260091 Discusses licentee Mar 1982 testing & evaluations of steam extraction line albow which ruptured on 820628, in response to 820709 request for addl steam line break info EISENHUT.D @ Division of Licensing 82/07/14 REHM.T A Office of the Executive Director for Operations 2pp 20920 ORO PAX Fiche 50-000,83/06/23,8310260008

- 8310030423 Updated RO 287/83-07 Investigation incomplete Next rept expected by 831030 TUCKEN-H B Duke Power to 13709736 G'PEILLY, J P Region 7. Office of Director 19 (10593-162 PAX Fiche 50-267,83709716, 8310030423
- 8310060426 RO on B36922, w/both Recover hydro units out of svc for planned maint. Lee &C gas turbine, being used to energize buses, tripped off line Both standby bures deenergized & Units i & 3 placed in degraded mode TUCKER, H & Dute Power Co 87/09/27 O'REILLY, J P Argion & Office of Director 3pp 20/41 224 24X Ficha 50-269, 83/09/27, 831004024
- B310140159 RD on B30927, while energizing 4,160-volt standby buses, ice &C gas turbine, tripped off-line, deenergizing both standby buses & placing two operating units in degraded mode Cause undetermined since unit has no earnt recorder TUCKER, H B Duke Power Co B3/10/04 D'REILLY, J P Region 2, Office of Director 3pp 20/45 06/ 24X Fiche 50-767,83/10/04, B310140159
- 83(0270412 RO on B31012, standby buses dervergized to allow for operability performance testing of standby bus breakers per Tech Specs Testing caused degraded mode togond fech Spec limit TUCKER-H B Oake Power Co 83/10/17 O'REILLY, J.P. Region 7, 0ffice of Director 2pp 10924 010 24X Fiche 50-267,83/10/1/,8310270412
- V Operator Claminations
- 8310040425 Notifies that operator & senior operator licensing rivms scheduled for wk of 831205 NRL requirements for administration of plams and DANCE, H C Division of Project & Resident Programs 03/09/28 TUCKER-H B Duke Power Co Sup 20519 124 24% Fiche 50-269, 83/09/28,8310040405
- DOCKET 50-207 THREE MILE ISLAND NUCLEAR STATION, UNIT 1 F. Socurity, medical, emergency & fire protection plans
- 8310040061 Board Notification 83-132 Forwards NRC 839705 ltr & II- Insp Rept 50-289/83-13 rd energency preparadoess open items EISENHULD 6 Division of Litensing 87/97/99 PALLADING, N . GILINSKY, P . ROBERTB, T Commissioners App 20440 33B 24X Fiche 50-289.83/09/09.8310040041
- 8310200218 Forwards IF Insp Repts 50-289/83-18 & 90-320/83-10 on 830622-24 & 0711-20 & notice of violation MARTENIT Region I. Office of Director 83/09/14 KANOA, B M General Public Utilities GPU Service Corp 2pp 20830 1/3 //4x Fiche 50-289/83/09/14 8310200/18
- --8310200237 Nobice of violation from into on 830622-0720 * Region 1. Office of Director 83/09/14 1p 20830 175 24x Fiche 50-289,83/09/14,8310/00218
- ~~8310200270 IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830822-14 & 0711-20 Noncompliance noted failure to perform quarterly fire brigade training PAOLING, R. PLISCO, L. ANDERSON, C. J. Region 1, Uffice of Director 83/09/04 19pp 20830 126 247 Fichs 50-289, 83/09/14,
- B310170028 Forwards GPU vs 05W lawsuat review SER input for emergency planning Documents do not contain info w/pstential to alter conclusions on restart certification issue MATTHEMS.0 B Emergency Preparadness Branch 83/09/17 RUSSELL.W T 0PU/B&W Lawsuat Review Team 0pp 20790 340 24X Fiche 50-207,03/07/17,8310170008
- 8310050327 Releases public version of revised emergency plan implamenting procedures
 FELTON. J.M. Division of Roles and Records 83/09/26 Document Management Branch 1p 20639 216 24% Fichs 50-289, 83/09/26, 8310080329
 - --8310080334 Public version of revised smergency plan implementing procedures, including Procedures 1004 22. "Tornado/High Hinds," 1004-20. "Activation of Technical Support Ctr" & 1004-31. "Airborne Radioactivity Sampling & Analysis "STANCE,S J General Public Utilities GPU Service Corp 83/09/08 60pp 20639 217 EAX Fiche 50-289, 83/09/26, 831006032/
 - 8310060529 Releases public version of revised emergency plan implementing procedure FELTON. J M Division of Rules and Records 83/09/30 Decument Management Dranch 19 2066/355 24% Fiche 50-287,83/09/10, 8310060529

- --8310060532 Public version of Nev 5 to Emergency Plan Employing Procedure 1004 10. "Onsite/Officite Radiological Monitoring STANGELS of General Public Utilities GPU Service (on p. 83/07/14 7pp. 20641-356 .24X Fishe 50-289 83/09/30.846 444
- 8310040549 Releases public version of revised emergency planting temptementing procedures
 FELTON, M. Division of Rules and Records 83/09/30 Process
 Management Branch 1p 20463-071 24X Fiche 50-749, 07/07711
 8310040549
- --8310060551 Public version of revised emergency plan implementing procedures, including Procedures 1004 4 to General emergency & 1004 6 re addl assistance & notification STANGLE U General Public Utilities GPU Service Co.p. 83706/29 67pp 20663 072 24X Fithe 50-289,03/09/30.0394 (c.
- B310170006 Releases public version of revised Emergency plon implementing procedures FELTON, J M. Division of Rules and Records B3/10/06 Pour Management Branch 1p 20813-299 PAX Fiche 50-087, 87/10/06 B3/10170006
- ~-83101/000/ Public version of revised emergency plan implements; procedures including Procedures 1005 to maintaining emergency preparedness 1004 if the unusual event & 1004 if a left NELSON, M.A., TOOLE, R.J., HUKILL, H.D., General Public Utility, GPU Service Corp. 83/09/26 93pp. 20813 300 24% Ficho 50-289, 83/10/06, 83101/0006
- 8310200426 Releases public version of revised emergency plan administrative & implementing procedurs FCLTON, J M. Division of Rules and Records B3/10/f/ Better t Management Branch ip 20839 102 24y Fiche 50-289, 0.3/10/f/ B310200426
- "-8310200430 Public version of revised emergency plan procedure including Administrative Procedure 1003 re emergency equipment readiness & Implementing Procedure 1004 Mg in ansito/effsite radiological monitoring NELSON, M & TOOLE, R J & HUKILL H D General Public Utility OPU Sovice Corp 83/10/04 100pp 20059 103 44% Fiche 90-207, 83/10/17, 6310200426
- 0310210304 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/17 December Management Branch ip 2000/ 342 PAX Fiche 50-207.03/10/17 8310210304
- --8310210370 Public version of Rev 4 to Embigency Plan Implemating Procedure 1004 34, "Activation of Parsippany Technical Functions Ctr " STANGE: 8 J General Public Utilities - GPU Service Corp 03/09/29 6pp 20882 343 24% Fithe 50-289,83/10/17.1140.joid
- #310270119 Releases public version of revised emergancy plan implementing procedures FCLTON-U M Division of Rules and Rucoids #3/10/21 Below t Hanagement Branch Ip 20942 110 24X Fiche 50-2097 #3/10/21 #310270119
- --B310270125 Public version of revised Emergency Plan Implementing Procedures 1004 3 re site emergency,1004 4 re general emergency,1004 4 re general emergency & 1004 (2 re environ monitoring STANDE, B J General Public Utilities GPU Service Loip B3/10/06 24pp 20942 111 24X Fiche 50-289,83/10/21.01102-011
- 8310270393 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 83/10/21 Division Management Branch 1p 20943 089 24% fishe 50-287-83/10/76. 83102/03/3
- ~-8310270396 Public version of Nev 7 to Emergency Plan Implementary
 Procedure 1004 6. "Unit 2 Unsite Emergency Response
 Directory" & Nev 2 to 1004 39. "Activation of Amner to
 Near-site Emergency Operations Facility (Crawford Station)"
 BRADY. J A. STANGE.S J General Public Utilities ~ GPU (credite
 Corp. B3/10/10 21pp 20943 090 24X Fichs 50~69.83/10/0)
 83102/0392
- Q Adjudicatory correspondence
- 8310110632 Expresses appreciation for meeting to review GPU vr BIV lawsuit document record RAWSON, R. J. Office of the Executive Legal Director 83/07/29 WISE, R. F. Dovis, Polk & Mardwell 1p 20714-343 PAX Fiche 50~289,83/07/22,8310110632

- 3310140302 Forwards listing of lawsuit documents by subj area significant to GPU vs 0°W record to support position to reopen restart hearing Evaluation of documents contained in
- Teography restart nearing transfer of the Ser requested SER requested EISENHUI, D. G. Division of Licensing 83/08/15 MATTSON, R.J. Division of Systems Integration (post (11005) THIMPSON H.C., TAYLOR, J. E. Division of Human Factors Safety 22pp 2079) 2079 L tota 24X Fiche 50-289,83/08/15,8310140302
- ISJO170012 Forwards NRC produced transcripts of RW Keaten taped interviews Tape entry into document control sys as BAW Exhibits 347a-347a requested W/o entl RUSSELL.W T GPU/BAW Lawsuit Review Trom 83/08/24 SCATFOLINI, t SCUDER, J Public Document Brunch BLUNE, M Office of the General Counsel (p. 20798-361 24X Fiche 50-289.83/08/24.8710170012 SCATIOUINLE .
- 31002045J Comments on NRC SER is steam generator repair & return to operation NRC should perform independent assessment of acceptability of potential addl steam generator leakage GERUBKY.T M Pennsylvania. Commonwealth of. 83/09/26 Dockets & Services Branch 2pp 20601-042 24X Fiche 50-289,83/09/26,8310030453
- 310030408 Advises that idea that plant will be run by CPU in future should be abandoned Gutside organization should take over operation Qualifying outside organization would be lost difficult than requalifying GPU GLINSKY.V Commissioners 89/09/28 Commissioners 1p 20602 216 24% Fichs 30-209,03/09/28,0310030408
- 310030351 Forwards documents relevant to GPU vs B&W lawsuit heine JIDO30331 Forwards documents relevant to GPO vs 0xW lawsuit heing reviewed by NR BLAKE.E L Shaw, Pittman, Potts & Prombridge BLAKE.E L Hetropolitan Edison Co 89/04/29 EDLES.G J , UUCK.J H , KO'N .C N Atomic Safety and Licensing Appeal Panel 130pp 20592 001 24X Fiche 50-289,83/09/29,8310030501
- 310030403 Forwards GPU news release & ER Stier 830973 ltr to GPU commenting on Ofc of Investigations rept, "TMI-2 Allegations re Safety-Related Mods, GA Procedures & Use of Polar Crane "Svc list encl BLAKE, EL Shaw, Pittman, Potts & Trowbridge BLAKE, EL Shaw, Pittman, Potts & Trowbridge BLAKE, EL Matropolitan Edison Co 83709/27 EDILS, G.J., BUCK, J.H., KOHL, C.N. Atomic Safety and Licensing Board Panel 13pp 20601 211 24% Fiche 50-289, 83/09/27, 8310030403
- 310030413 Statement on Commissioner Gilinoky 830928 memo to Commission Opposes memo being made public since collegial process would be impaired process would be impaired PALLADING, N J Commissioners 83/09/30 ip 20602 215 24X Fiche 50-289,83/09/30,8310030413
- 310030417 Forwards draft NUREG-1020, Vol 1, "GPU vs 88& Lawsuit Review & Effect on 1MI-1" Portions of Category 10 withheld since info pertains to angoing investigations CHILK, S. J. Office of the Secretary of the Commission 83/09/30 Atomic Safety and Licensing Board Panel 111pp 20602 10J 24X Fiche 50-207, 83/09/30, 8310030417
- 110040280 Order extending time until 831024 for Commission to act to
- CHILK.S J Office of the Secretary of the Commission B3/ Commissioners Ip 20614 076 24X Fiche 50-287, BJ/07/30, B310040280 83/09/30
- H10040392 Advises that 830929 ltr wrongly captioned Unit 2 instead of Unit 1 Documents being sent for Commission use include press release & records on B&W vs QPU lawsuit review Svc list enc.
- First enc)
 BLAKE E L Shaw, Pittman, Potts & Frombridge BLAKE E L
 Metropolitan Edison Co B3/09/30 EDLES G J . BUCK, J H . KDHL C N
 Atomic Bafety and Licensing Appeal Panel 2(9pp 20619 18J 24X
 Fiche 50-289,83/09/30,8310040392
- |10070437 GPU V B&W LAWSUIT REVIEW AND ITS EFFECT ON TMI-1 General Public Utilities Corporation et al V The Babcock & Wilcox Company et al Three Mile Island Nuclear Station Unit I Docket No 50-289 * Office of Nuclear Reactor Regulation, Director NURFG-1020 VOI 83/09/30 65pp Available at NRC \$5 00 P0674 126 P4X Fiche 50-289, 63/09/30, 8310070437

- 8310040188 Memorandum & order denying TMI Alert 830921 motion for postponement of G31018 prehearing conference in remaided proceeding ASLB on steam generator repair & ASLB on remaind of mgt issues will not schedule simultaneous hearings GHITH, I W. Atomic Safety and Licensing Board Panel 83/10/03 Three Mil Esland Alert 2pp 20608 252 24X Fiche 50-289, 83/10/03.8310040188
- 8310040395 Forwards J Lee ltrs sent to Commissioner Gillisky ofc w/o formal indication of parties served CLEMENTS.W L. Docketing & Services Branch 83/10/03 Office o the Executive Legal Director 4pp 20619 044 24X Fiche 50-289.83/10/03.8310040395
- 8310050528 Motion to open Commission 831006 meeting to public Meeting topic is status of investigations & adjudicatory matters re TMI restart Discussion required to be upon Certificate of Svc encl HEISS,E R Union of Concerned Scientists 83/10/04 Commissioners 4pp 20630 355 24X Fiche 50-289,83/10/04, Svc encl Commissioners 8310050528
- B310110056 Requests release of full unexpurgated version of recently completed NURFG-1020, "GPU vs B&W Lawsuit Review & Effect on TMI-1." INI-I "DIECKAMP.H General Public Utilities - OPU Service Corp 83/10/04 PALLADING.N. ASSELSTINE.J.K. DERNTHAL.F Commissioners 3pp 20645 003 24X Fiche 50-289,83/10/04,8310110056
- 8310110047 Memorandum & Order ALAB-744, denying UCS 830918 petition for reconsideration of ASLB 830526 opinion affirming ASLB decision that issue of environ qualification of safety-related equipment be resolved outside hearing SHOEMAXER.C J. Atomic Safety and Licensing Appeal Panel 83/10/06 Uniton of Concerned Scientists App. 20668 273 24X Fiche 50-289,83/10/06,8310110047
- 8310110050 Order denying UCS 831004 motion to open closed Commission 831006 meeting on status of investigations & adjudicatory matters re THI restart Portion of meeting closed since disclosure might interfere w/investigations CHILK. B J Office of the Secretary of the Commission 83/10/06 Union of Concerned Scientists 3pp 20668 269 24% Fiche 50-289,03/10/04,8310110050
- 8310110205 Response apposing TMI Alert 830921 suppl to petition to intervene Contentions satisfy mone of epecificity requirements Certificate of Sve encl BLAKE, E.L. Metropolitan Edison Co. BLAKE, E.L. Shaw, Pittman, Potts & Trawbridge 83/10/04 Atomic Safety and Licensing Board Panel 42pp 20845 089 24X Fiche 50-289, 83/10/04, 8310110205
- B310110224 Response to proposed contentions re-steam generator repair Joint potitioners fail to identify concerns which warrant consideration Certificate of Svc encl
 BLAKE, E. L. Metropolitan Edison Co. BLAKE, E. L. Shaw, Pittman, Pot & Trowbridge B3/10/06 Atomic Safety and Licensing Board Panel 18pp 20666-110 24X Fiche 50-289, 83/10/06, 8310110224 BLAKE,E L. Shaw, Pittman, Potts
- 8310110272 Notice of appearance in proceeding Certificate of Evo encl TROMBRIDGE.Q F . RIDGMAY.D A . BLAKE.E L Metropolitan Edison Co 83/10/06 6pp 20466 158 24X Fiche 50-289.83/10/06.8310110272
- 8310120395 Forwards info INPO provided to util at INPO conference of chief executive officers TMI-I rated as average or in top one-sixth of all operating plants in US Svc list encl BLAKE.E L Shaw, Pittman, Potts & Trawbridge BLAKE.E L Matropolitan Edison Co B3/10/06 EDLES.G J. BUCK.J H. XOHL.C Matropolitan Edison Edison Co B3/10/06 EDLES.G J. BUCK.J H. XOHL.C Matropolitan Edison Edis JH : XOHL : C N 699 057 P4X
- 831013004B Response to TMI Alert (TMIA) & J Lee et al contentions re steam generator repair TMIA should be admitted as party since Contentions 1 b & 2 b 2 admissible Certificate of Svc encl
 HAGNER, M.F., RAWSON, R.J. Hearing Branch 4 83/10/06 Safety and Licensing Board Panel Fiche 50-289,82/10/06/8310130048 22pp
- 8310110182 Responds to 830914 memorandum & order re testimony on Hartman allegations Clients not legally required to testify Author will appear before ASLB at 831018 preparing conference VOIGT. H H LeBoeuf. Lamb. Leiby & MacRae 83/10/07 SMITH.) W. MDLFE.S. LINKNBERGER.O. Atomic Safety and Licensing Board Panil 3pp 20666 2R4 24X Fiche 50~289.83/10/07.8310110182
- 83i0(10223 Notice of current schedule re mgt competence & intrgrity issues in restart proceeding Decision on restart expected in latter half of CY84 Tentative projections of completion dates enct S J Office of the Secretary of the Commission 83/10/07 20466 128 24% Fiche 50-289 83/10/07 8310110223

- 8310110225 Order scheduling 831201 oral argument in Bethesda, MU rc various appeals from ASLB Partial Initial Decisions
 LBP-81-32 & LBP-82-36 on mgt competence & integrity Parties
 must provide name of representative by 831117
 SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel 83/10/0/
 Office of the Executive Legal Director 2pp 20666-108 24X
 Fiche 50-289, 83/10/07, 8301010025
- 8310110238 Order requesting views of parties on whether Commission should stay ASLE hearing on Hortman allegations re leak rute data falsification pending Off of Investigation rept completion Hearing stayed pending comme
- 8310130209 Memorializes 831011 telcon in which ASLB canceled directions for submissions & scheduling of conference per ASLB 8,10914 memorandum & order ASLB 833011 telcon w/MH Volgt.counsel for TMI-2 employees before 790328. also memorialized HOLFE.S J Abomic Safety and Licensing Board Panel 93/10/19 OCLOBERG.JR Haaring Branch 2 BLARE.E L Shaw. Pittman, Potts & Troubridge HOEFFLING. M Penngulvania, Commonwealth of, Jpp 20725 024 24X Ficho 50-289,83/10/12.8310130209
- 8310140026 Memorandum transmitting Oft of Investigations 831007 ltr advising that oft does not anticipate participating in any proceeding prior to completion of investigative repts relevant to issues pending before ASLB S
- --8310140035 Advises that ofc does not anticipate participating in any proceeding prior to completion of investigative repts relevant to issues pending before ASLB in response to 830914 memorandum HAYES B Diffice of Investigation 83/10/0/ SMITH, I W Atomic Safety and Licensing Board Panel 1p 20768 0/9 24X Fishe 50-289,83/10/13,8310140026
- 8310180355 Requests add1 guidance re ASLAB 8J1007 order & oral argument scheduled for 831201 (dentification of issues of concern to ASLAB would assist parties in preparation & in oral argument Svc list encl
 BLAKE,E L. Shaw, Pittman, Potts & Troubridge BLAKE,E L
 Metropolitan Edison Co 83/10/14 EDLES,G J, BUCK,J H, KOTR,C N
 Atomic Safety and Licensing Appeal Panel 4pp 20803 016 24X
 Fiche 50-289,83/10/14.8310180355
- 8310250338 Notices of appearance in proceeding Certificate of Syc encl WAGNER, M.E., RANSON, R. J. Hearing Branch A 83/10/14 4pp 20878 026 24X Fiche 50-289,83/10/14.8310250338
- 8310200211 Forwards INFO evaluations on util mot Svc list enc.)
 BLAKE,E L Show, Pittman, Potts & Trombridge BLAKE,E t
 Metropolitan Edison Co 83/10/18 EDLES,G J, BUCK,J H, KOR,C N
 Atomic Safety and Licensing Appeal Panel 47pp 20832-351 24X
 Fiche 50-000,93/10/18,83102003/11
- B310200231 Motion to establish criteria for judging reasonable progress All long-term actions found by ASLD & ABLAB to be necessary & sufficient to protect public must be completed prior to restart Certificate of Svc encl HEISB.E A Union of Concerned Scientists B3/10/1B Commissioners 5pp 20833 047 24X Fiche 50-287,83/10/1B.8310200231
- B31021014B Forwards util "TMI-1 Ence-Through Steam Generator Failure Analysis Rept." IDR-241.referenced in util responses to petitioner progosed contentions W/o encl TROWBRIDGE, O F Shaw. Pittman, Potts & Trowbridge TROWBRIDGE, O i Hetropolitan Edison Co. B3710718 WOLFE.S J, LAMB.J C. Atomic Safety and Licensing Board Panel DORGSHOW, J. Three Milo Island Alert. 3pp. 20856-094 24% Fiche 50-289,83/10/18.8310210148
- B310210249 Forwards corrected pages to INPO rept provided on (/31016) BLAKE,E L Shaw, Pittman, Potts & Trombridge BLAKE,E L Hetropolitan Edison Co (B3/10/19 EDLES,G J , DUCK,J H , KUM, C N Atomic Safety and Licensing Appeal Panel 6pp 20051 049 24X Fiche 50-000,63/10/19.8310210249
- 8310240166 Comments on disagreement w/N Admodt concerning rev to joint petitioner Contention i re steam generator repair Licensce will respond in writing if N Admodt submits proposed rev Certificate of 8 by encil ROWBRIDGE, GF Shaw, Pittman, Potts & Trumbridge IMOWBRIDGE, G J Hetropolitan Edison Co. 83/10/20 WDFE, S J , HEIRICK, D L , LAMS, J C. Atomic Safety and Licensing Spard Panel 3pp 20881 315 24X Fiche 30-289, 83/10/20, 83/10240166

- 8310240184 Submits correction to statement re availability of IDR 388 to TDR-417 documents.made at 831017 prehearing conference Documents not available in PDR Release requested Svc list enci TROMBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROMBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROMBRIDGE, G I Metropolitan Edison Co. 83/10/20 WOLFE, S J . METRICK, D L . LAMB. J C . Atomic Safety and Licensing Doord Panel 3pp .20978 086 24X Fiche 90-289, 83/10/20, 83/0240184
- B310250046 Requests B31201 oral argument be rescheduled due to author outside rommitments HEISS,E R. Haimon & Weiss B3710720. Atomic Safety and Licensing Appeal Panel. 1p. 20894-197. 24X Fishe 50-289,83710720,8310250046
- 8310250042 Order memorializing 831017 special prehearing conference Objections due from licensee. TMI Alert & Joint Petitipners within 5 days & from NRC within 10 days (CLEE): 4 Atomic Safety and Licensing Board Panel 03/10/21 4pp. 20895 275 24X Fiche 50-289.83/10/21.8310250042
- 8310270372 Informs that Technical Data Repts 388 & 417 not distributed to LPDR.contrary to licensee 031017 assertion BRADFORD.L Three Mile Island Alert 03/10/21 Atomic Safety and Licensing Board Panel 2pp 20923 271 247 Fiche 50-209.83/10/21, 8310270372
- B310260294 Restatement of proposed Contentions 1, 2 & 3 to physical & chemical processes employed to return tubes to design basis Certificate of Svc encl
 AMMODIN 0 Amendts B3/10/22 Atomic Safety and Licenting Robid Panel 4pp 20911 353 24X Fishe 50-289.83/10/22.8310260494
- 8310260274 Response to Commission B3100/ request for views on whether hearings re Hartman allegations on leak rate falsifications should be stayed Hearing process should not be stayed pending completion of Ofc of Investigations rept DOROSHUH.J Three Mile Island Alert B3/10/23 App 20711 307/24X Fiche 50-289, 83/10/23, 8310740274
- 8310260306 Motion for leave to file response to Commission 83100/ order staying remanded hearing on "Hartman allegations" pending views on continuing stay until completion of Ofc of Investigations rept HEISB.E N. Union of Concerned Scientists 83/10/24 Commissioners 5pp 20910 378 24X Fiche 50-289,83/10/24.
- --8310260308 Response to Commission 831007 order temporality staying remanded ASLB hearings re "Hartman allegations" & icquested views of parties whether stay should lemain in effect pending completion of investigation W/Certificate of Svc WEISS.E R Union of Concerned Scientists 83/10/24 5pp 20910 333 24X Fiche 90-289,83/10/24,0310260300
- 8310270259 Order extending time until 831110 for Commission to act to review ALAB-729
 CHILK 5 J Office of the Secretary of the Commission 83/10/24
 Commissioners 1p 20923 246 24X Fiche 50-289,83/10/24,83/10/20259
- 8310260256 Order rescheduling 831201 oral arguments for 849111 in Bethesda, MD on appeals from ASLD partial initial decisions re mgt competence & integrity SHDEMAKER, C.J. Atomic Safety and Licensing Appeal Panel 83/10/.15 Union of Concerned Scientists 2pp 20912 022 247 Fiche 50-289, 83/10/25, 8310260256
- 8310310198 Response to Commission 83100/ order re reopened issues for restart hearings Issues do not provide basis for continued suspension of license nor basis for reopening record Certificate of Bvc enci BLAKE, E.L. Metropolitan Edison Co. BLAKE, E.L. Shaw, Pittmen. Potts & Troubridge 83/10/27. Commissioners 200pp 20748 153 P4X Fiche 50-289.83/10/27.8310310198
- 8310310302 Notice of H Dieckamp speech to be delivered at AIF 831101 annual conference Speech & syr list en: 1
 BLAKE.E L Metropolitan Edison Co BLAKE.E L Shaw, Pittman, Potts & Troubridge 83/10/28 20pp 20959 25:: 24X
 Fichs 50-289,83/10/28,8310310382

H General correspondence

8310110062 Responds to 830920 ltr expressing concerns or THI-1 restort Commissioner Bernthal cannot address matter outside formal deliberative process Related correspondence INGRAM.F Diffice of Public Affairs 83/10/05 HURSI, A Affiliation Unknown 1p 20667 305 24X Fiche 50-289,83/10/05,83/10/062

- --8310110074 Opposes TM1-1 restalt HWRST.A Affiliation Unknown 83/09/20 BERNIHAL I M Commissioners Ip 20667 306 247 Fiche 50-289,83/10/05, 8310110062
- B310130219 Forwards Cumberland County Board of Commissioners H30919 Resolution B3-7 requesting NRC to proceed w/TMI-2 decontamination to close Units 1 & P PUNT: N A Cymberland County, PA B3/10/06 PALLADIND, N J Commissioners 2pp 20725 050 24X Fiche 50-289,83/10/06, B310130219
- B310240159 Comments on 83092/ public meeting in Middletown,PA re
 TMT-1 restart & CPU vs BiW lawruit Meeting completely
 dominated by GPU/Bechtel
 OSBORNM A Affiliation Unknown 03/10/14 DENTON,H R NRC No
 Detailed Affiliation Given 2pp 20881 292 24X
 Fiche 50-289, 83/10/14,8310240157
- P Operating license stage documents & correspondence
- 9310200026 FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests News article dtd 030523 from Patriot News encl VOIGT.H H LeRoeuf, Lamb, Leiby & MacRae 83/05/26 Office of Administration 2pp 20844 23B 24X Fiche 50-289,83/05/26,8310200076
- 8310140296 Forwards TMI-1 GPU/BEW lawsuit review organization chart Overtime for personnel connected w/GPU vs BEW lawsuit authorized as noted FUSSELL, W.T. Systematic Evaluation Program Branch 83/06/28 NKK No Detailed Affiliation Oliven 1p 20794 095 24X Fiche 50-289, 83/06/28, 8310140296
- 8310140294 Requests estimate of time needed to review documents of TM1-2 accident & to prepare lists Info needed to respond to Congressman Udall request OHILK.5 J Office of the Secretary of the Commission 83/06/00 DIRCKS
- 9340130114 Agrees to provide NR(w/access to computerized second of GPU vs DAW trial record & deposition transcripts to check completeness of NRC independent review of trial documents ARNOLD, R C Queneral Public Utilities GPU Service Cosp 03/07/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20777 073 24% Fiche 50-289, 83/07/08.8310130114
- B310130342 Identifies NRR div responsibilities for reviewing documents re OPU/B&W lawsuitiper Commission 830628 directive Review due by 830901 Overview of goneral scope & objectives of lawsuit review task encl
 EISERMUT, D © Division of Licensing 83/07/08 MATISON, R J
 Division of Systems Integration (post B11005) THOMPSON, H I
 Division of Human Factors Safety VULLMER, R H Division of Engineering 52pp 20768 280 24X Fishe 50-289,83/07/08,
- 8310270011 Add1 response to FOIA request for four documents or TMI restart & SECY-83-988 & SECY-83-980 Items 1,2,4 & b encl Item 3 included within Item 2 Review of Item & incomplete FELTON, J M Division of Rule; and Records 83/07/15 DANIELSON, L M MH8 Technical Associates 1p 20940 309 24X Fiche 50-289,83/07/15.8310270011
- B310120050 Requests individual to manage & control access to haid copies of documents for OPU vs B&W lawsuit review RUSSELL.W T NRC No Detailed Affiliation Given B3/07/22 BESAW.W J Division of Technical Information & Document Control 2pp 20749 352 24X Fiche 50-289.83/07/22.8310120058
- G310130175 Forwards summary of 830721 meeting re GPU vs B&W lowsujt documents Comments on meeting summary welcomed RAMSON,R J NKC - No Detailed Affiliation Given B3/07/26 WARTZW E Davis, Polk & Wardwell ip 20/77 171 P4X Fiche 50-289, 83/07/26, 8310130175
- ~-B310130184 Summary of 830/21 mreting w/Davis, Polk & Wardell in New York, NY re info relevant to NRC review of GPU vs B&W lawshit record or to reactor safety in general RUSSELL,W I NRC - No Detailed Affiliation Given 83/07/26 EISENHUI D & Division of Licensing 3pp 20/// 1/2 24X Fache 50 289.83/07/26 83101(10175
- 8310170043 Summary of 830-21 meeting w/N&W counsel re review of GPU vi 85W lawsuit record & general leactor sefety Operator reliance & responsibility for procedure writing identified as possible general safety is ne RUSSELL.W T GPU/BSW Lawsuit Review Tram 83/07/26 EISTNHUI, D.G. Bivision of Licensing 3pp 20812-155 24X Fiche 50-289.03/07/26, 8310170043

- B310140290 Forwards emergency planning contentions.ALAB-729.830429 rept on NRC requirements for restart & latest status rept on THI-1 restart items W/o encis List of documents being forwarded enci HICHAELS-T S NRC - No Detailed Affiliation Given B3/07/29 HERNAN, R. SUERMANN.J J. THADANI.M NRC - No Detailed Affiliation Given 2pp 20794 106 24X Fiche 50-289.83/07/29.8310140290
- B310140291 Forwards final installment of review packages & updated list matching GPU vs B&W lawsuit documents w/responsible divs Draft input to rept requested within 30 days W/o encls EISENHUT,D G Division of Licensing B3/08/02 MATISON,R J Division of Systems Integration (post 811005) THUMPSON.H L Division of Human Factors Safety TAYLOR,J M Division of QA, Safeguards & Inspection Programs (Post 830103) 2pp 20794 108 24X Fiche 50-289.83/08/02.8310140291
- 8310140292 Comments on Operating Reactors Assessment Branch responsibilities & participation in GPU vs B&W lawsuit roview Table for disposition of operating experience issues encl MIRAGLIA.F Assistant Director for Safety Assessment 83/08/05 RUSSELL, W T GPU/B&W Lawsuit Roview Team 5pp 20794 100 24X Fiche 50-289, 03/08/05, 8310140292
- B310170717 Memorializes B30B09 telcon w/N Hyers of Congressman Udall staff re Chairman Palladino B30B03 ltr on significant info in OPU vs Baw record RUSEELL.W T OPU/B&W Lawsuit Review Timm 83/0B/09 DENTON.H R . CASE.E G Office of Nuclear Reactor Regulation. Director EISEMVIL.D G Division of Licensing 1p 2079B 116 24X Fiche 50-289.83/08/09.8310170717
- B310130326 Forwards list of long-term actions that should be addressed in SER input Only noncertification items to be addressed in review
 EISENHUT, D.G. Division of Licensing 83/08/12 MATISON, R.J.
 Division of Systems Integration (post B11005) THOMPSON, H.L.
 Division of Human Factors Safety JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 5pp 20754 332
 24% Fiche 50-289, 83/08/12, 8310130326
- 8310170751 Informs that D Horisseau will be acting for F Allenspach as leader for GPU vs B\$M lawsuit review BOOHER, H R Licensee Qualifications Dranch 83/08/12 THOMPSON, H L Division of Human Factors Safety ip 20798 219 24X Fiche 50-289,83/08/12.8310170751
- 8310130108 Forwards list of specific exhibits requested on 830812 to be used in GPU vs D&W lawsuit review RUSSELL W T Division of Litensing \83768/16 LLQYD.R D Debevoise & Liberman LLQVD.R D General Public Utilities GPU Service Corp 2pp 20777 071 24X Fiche 50-289,83708/16.
- 8310170014 Forwards revised listing of subjarea contents for OPU vs
 0kW lawsuit review.per 830727 & 0805 & 12 ltrs
 RUSSELL.W T GPU/B&W Lawsuit Review Tram 83/08/18 MORIBSEAU.D ,
 PICKETT, D , HAASS, W NRC No Detailed Affiliation Given 14pp
 20813 285 24X Fiche 50-289.83/08/18.0310170014
- B310170747 Identifies GPU vs B&N lawsuit documents not held by NRC & recommends no further action to obtain documents CAPRA-R A GPU/B&N Lawsuit Review Team B3/08/29 RUSSELL, W 1 GPU/B&N Lawsuit Review Team A4pp 20/76 318 24X Fiche 50-289, 83/08/29, 8310170747
- 0310170022 Advises of receipt of legible B&W lawsuit documents requested of B&W in NRC 030016 ltr Documents received listed CAPRA,R A GPU/B&W Lawsuit Review Team 03/09/00 NRC No Detailed Affiliation Given 1p 20/98 35/ 24% Fiche 50-209, 03/09/08,0310170022
- 8310170032 Requests assistance in arranging resources for production & publication of NR(evaluation of GPU vs B&H lawsuit review & impact on IMI-1 restart (NUREG-1020) RUSSELL.W T GPU/B&H Lawsuit Review learn 83/07/08 BESAH.W J Division of Technical Information & Document Control 3pp 20798 334 24X Fiche 50-289.83/09/08.8310170032
- 8310170001 Forwards 830908 memo requesting support for NRC rept on GPU vs 8AW lawsuit review Arrangements should be made to accommodate requested schedule STEELE, M L Division of Technical Information & Dacument Control 83/09/09 MCVEAGE, M D Division of Technical Information & Document Control JOHANSEN, J Cress 81 anch 1p 20814 046 24X Fiche 50-289, 83/09/09, 8310170001

- --8310170002 Requests assistance in arranging resources for production & publication of NRC evaluation of OPU vs 8&W lawsuit review & impact on restart of TMI-1 (NUREO-1020) Flow chart w/projected milestones encl RUSSELLNI OPU/B&W Lawsuit Review Team 83/09/08 DE5AW V J Division of Technical Information & Document Control 3pp 24X Fiche 50-284,83/09/09.8310170001
- 8310050144 Discusses B30307 % 17 ltrs re pressurized thermal shock flux reduction Commitment to fuel mgt plan for Cycle 6 % estimated schedules for fuel mgt plans to be used in subsequent cycles requested in 30 days EISENHUT.D 0 Division of Lirensing B3/09/12 HUKILL.H D Command Public Utilities GPU Service Corp 5pp 20650 209 24X Fichs 50-289.B3/09/12.B310050144
- 8310030418 Forwards SER on generic mods to reactor trip breakers for B&N plants to provide automatic actuation of shunt trip attachments Plant-specific info should be provided when generic design endorsed in response to Generic Ltr 83-28 STDLZ.J F Dperating Reactors Branch 4 83/09/15 HUKILL.H I) Ceneral Public Utilities GPU Service Corp 4pg 20626 309 74) Fichs 50-289.83/09/15.8310030410
- --B31003042i SER on generic mods to reactor trip breakers for UAW plants to grovide automatic actuation of shunt trip attachments • NRC - No Detailed Affilintion Given B3709/15 14pp 20626 313 24X Fiche 50-289.83/09/15.8310030418
- 8310200032 Responds to FGIA request for correspondence between Chairman Pallading & DDJ re investigation of alleged falsification of RCS lear rate tests Forwards App A documents Portions of requested documents withheld (ref FGIA Examption 7) FELTON, J M Division of Rules and Records 83/09/15 VDIGT. H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20844 236 24X Fiche 50-289,83/09/15.8310200032
- --B31020003B Ack receipt of B30517 ltr re DUJ investigation into allegations re possible criminal wrongdoing Separate NRC investigation will be initiated PALLADINO.N J Commissioners B3/05/27 JENSON.D L Justice. Dept of ip 20844 240 24% Fiche 50-289, 83/09/15, 8310200032
- --8310200044 Requests that DOJ investigation on allegations re falsification of RCS leak rate tests be completed by 830515 Response within 2 was requested info partially deleted PALLADINO, N J Commissioners 83704711 SMITH, N F Justice, Dept of 2pp 20844 241 24X Fiche 50-289,83709715,8310200002
- --B31020004B Responds to B30411 ltr re TMI-1 restart & DOJ investigation into allegations re mgt competence investigation being pursued diligently but will not be completed by requested date info partially deleted JENSON,D L Justice, Dept of B3/05/17 PALLADINO,N J Commissioners 4pp 20844 243 24X fiche 50-289,83/09/15,8310200032
- 8310170018 Forwards draft NUREG-1020, "GPU vs 8&H Lawsuit Review & Effect on TMI-1" Draft does not include Chapter 10 io mgt competence/integrity Comments or concurrence requested W/o encl
 RUSSELL, M T OPU/B&M Lawsuit Review Team 83/09/19 EISCNHUL, D G Division of Licensing MATTSON, R J Division of Systems Integration (post 811005) THOMPSON, H L Division of Human Factors Safety 2pp 20798 358 24% Fishe 50-289, 83/09/19, 8310170018
- 8310280169 Appeals partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests
 VOIGT.H H LeBosuf. Lamb. Leiby & MacRae 83/09/19 CHILK. 9 J
 Office of the Secretary of the Commission 2pp .20965 055 .24X
 Fiche 50-289.83/09/19.8310/80169
- B310310097 Responds to FG[A request that 16 SECYs be placed in FDR Forwards App A documents SECY-02-466 withheld (ref FU]A Exemption 5) FELTON, J K Division of Rules and Records B3/09/19 SHOLLY, S C Union of Concerned Scientists 3pp 21000 146 24% Fiche 50-320, B3/09/19, B310310097
- --8310310131 Informs of present status of TMI-1 restart certification affort & provides update on NUREO-0737 Items status
 DIRCKS.H J. Office of the Executive Director for Operations
 SECY-82-483 82/12/07 16pp 21000 260 24X
 Fiche 50-289.83/09/19.8310310097
- IBIO170025 Forwards funal draft Chapter 10 to NUREQ-1020 entitled "Mgt Competence/Integrity " Changes, comments or concurrence requested by B30922 M/o ent.] EISENNUT. DO Division of Litensing 83/09/20 MAFISON, R J Division of Systems Integration (post 811005) THUMPSON, H L Division of Human Factors Bafety TAYLOR, J M Division of GA, Safeguards & Inspection Programs (Post 8300103) 2pp 20798 Test 24X Fiche 30-289, 83/09/20, 8310170025

- 8310040650 Advises that changes re sonic flow devices meet requirement, of NUREG-0737. Item II E 1 2. "Auxiliary Fredwater Sys. Automatic Initiation & Flow Indication" & are acceptable based on review of licensee 83.0524 8 08-5 1 trs. STOLZ JF Operating Reactors Branch 4 83/09/22 HUKILL, H D General Public Utilities GPU Service Corp. Spp. 2062/ 319 24X Fiche 50-287,83/09/22,8310040650
- B310110246 Board Notification B3-146 forwards info re mgt competence & integrity identified in Board Notifications 83-71 & 83-71A Addl info re failure to satisfy NRC operator training requirements identified in OPU vs B&W lawsuit required EISENHUT.D G Division of Licensing B3/09/22 PALLADINO,N J, GLLINSKY,V, RUBERTS,T M Commissioners 3pp 20682 356 24X Fichs 50-289,83/09/22.6310110/46
- 8310110554 Forwards marked-up copy of draft NUREG-1020, "GPU vs D&W Lawsuit Review & Effects on TMI-1" W/o oncl
 THOMPSON, H C Division of Human Factors Safety 83/09/22
 EISCNHUT, D G Division of Licensing 1p 2077/70/24X
 Fiche 50-289, 83/09/22, 8310110554
- B310110630 Forwards comments on NUREQ-1020 to GPU vs B&W lawsuit tovious beffects on TMI-1 Errors in App B should be corrected to reflect findings concerning relevance & materiality of lawsuit documents MATTSON.R J Division of Systems Integration (post 81100°) 83/09/22 EISENHUID 0 Division of Licensing Jpp 20/14 2/8 24% Fiche 50-289,83/09/22,8310110630
- B310030571 Board Notification B3-138A informs of change to previously stated position in NUREG-0680. Suppl 2 KCS leak rate tests contain inadequacies & deviations from regulatory & procedural requirements EIBENHUT.D G Division of Licensing B3/09/23 FALLADIND,N. OILINSKY,V. ROBERTS T Commissioners Spp 2060/ JC5 249 Fiche 50-207.83/09/23.8310030571
- B310120057 Forwards IE/Region I comments re Subj Area 5 of NUREG-1020 "OPU vs B&W Lawsuit Review & Effect on TMI-1." constituting concurrence w/NUREG TAYLOR.J M Division of OA. Safeguards & Inspection Programs (Post B30103) B3/09/23 EISENMUT.D 0 Division of Licensing Ip 20749 354 24% Fichs 50-289.B3/09/23.B310120057
- 8310130155 Discusses review of add) GPU vs B&W lawsuit documents No changes to original SER necessary HATTBON.R J Division of Safety Technology 83/09/27 EISEMBUT, D Q Division of Licensing 2pp 2077/ 17B 24X Fiche 50-289,83/09/23.8310130155
- 8310030103 Informs of plans to perform analytical evaluation of natural circulation cooldown (Generic Lti 81-21) w/o formation of voids in upper head using HCTRAN computer code in response to 830720 its Analysis will be completed in Dec 1983 HUKICL.H D General Public Utilities GPU Service Colp 83/09/26 STGL7.T | Operating Reactors Branch 4 ip 20390 055 24X Fiche 50-207,83/09/26.83/0030103
- 9310030620 Advises that encl IBW rept. "Response to GPU Nuclear Questions Concerning MPI Actuation at TMI-2 About 5 41 AM on 790328." completed assessment of EDS Nuclear analysis Rept provided to util on 830909 % to NRC on 830915 DIRCKS.W J DEFICE of the Executive Director for Operations 83709726 PALLADINO.N Commissioners 3pp 20624 351 P4X Fiche 50-289.83709726.8310030620
- --8310030622 Requests B&W be contacted to determine necessary steps for B&W to complete review & to prepare formal rept PALLADINO, N J Commissioner & 83/09/06 DIRCKS, W J Office of the Elecutive Director for Operations 1p 20676 and 24x Fichs 30-289.83/09/26.8310030620
- 8310120054 Concurs in draft NUREG-1020 "GPU vs BSW Lawsuit Review & Effect on TMI-1"

 VOLLMER.R M Division of Engineering 83/09/26 RURSELL,W (NR/ No Detailed Affiliation Olven 1p 20749 355 24X

 Fiche 50-289.83/09/26.8310120054
- B310120051 Advises that comments re NURLG-1020 "GPU vs R&W Lawfust Review & Effect on IM1-1" were faxed to R Capra on B30920 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/27 EISENNUT, D. G. Division of Licensing Lp 20715-327 ,44% Fiche 50-289,83/09/27,831012008:1
- Licensing ip 20715-327 .4X Fiche 50-289,83/09/27,8310120051

 8310120060 Forwards NUREG-1020 "GPU vs BAW Lawsuit & Effect on Irll 1 "
 Distribution of Category 10 section "Mgt Competence/
 Integrity" should be limited pending Ofc of Investigations
- Integrity" thouse of similar pending of a strategy, and completion of sinvestigation
 DIRCKS, U J Office of the Executive Director for Operations
 B3/09/28 PALLADING, N J Cummissioners 2p 20/15 JAP 24X
 Fich 50-209, 03/09/28, 8310120040

- 8310030403 Forwards GPU news release & EH Stier 830923 itr to GPU commenting on Ofc of Investigations rept. "TMI-2 Allegations re Safety-Related Mods, GA Procedures & Use of Polar Crane " Svc list encl
- BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, F L
 Metropolitan Edison Co B3/09/29 EDLES, G J , BUCK, J H , KOHL, C N
 Atomic Safety and Licensing Board Panel 13pp 20601 211 24x
 Fiche 50-209, G3/09/29, G310030403
- 8310040392 Advises that 830929 ltr wrongly captioned Unit 2 instrad of Unit 1 Documents being sent for Commission use include press release & records on 88W vs GPU lawsuit review Svc list enci
 BLAKE,E L Shaw, Pittman, Potts & Trowbridge BLAKE,L t
 Hetropolitan Edison Co 83709/30 EDLES:G J , BUCK,J H , KUIN,C N
 Atomic Safety and Licensing Appeal Panel 217pp 20619 18:1 24X
 Fiche 50-289.83/09/30,8310040392
- B310060390 Discusses results of B10905 testing of onsite safety related electrical distribution sys Acceptability of voltage conditions & undervoltage relay setting on safety electric distribution sys reconfirmed HUMILL.H D General Public Utilities QPU Service Corp BJ/09/30 STOLIAJF Operating Reactors Branch 4 5pp 20646 054 24X Fishe 50-289.83/09/30.8310060390
- 8310070074 Forwards response to 830825 safety evaluation on plant return to svc w/repaired steam generators
 MUKILL.HT D General Public Utilities QPU Service Colp 83/09/30
 STOLI.J F Operating Reactors Branch 4 7pp 20658 248 24X
 Fishe 50-289.83/09/30.8310070074
- --8310070082 Rev 2 to Procedure TDR 406, "Steam Generator lube Rupture
- B310270369 Responds to FDIA request for bECY-83-278 & SECY-83-270, transmitting B30624 "Rept on Adequacy & Bafey of Relief Valve Testing & Performance " Forwards requested documents FELTON, J M Division of Rules and Records B3/10/04 WEISS, I R Union of Concerned Scientists ip 20943 129 P4X Fiche 50-289,83/10/04,8310270369
- --8307270430 Forwards revised certification & noncertification status tables per 830622 request Table I revised to clarify inspiratus of certification items for which inspirationsly noted as not applicable DIRCKS.W J. Office of the Executive Director for Operations SECY-83-278 83/07/11 43pp 20943 130 24X Fiche 50-289.63/10/04.8310270369
- B310110200 Provides results of preliminary evaluation of steam generator hot test program Completed series of cooldowns to place axial loads associated w/operating transients on repaired steam generator tubes described M1LSON.R F General Public Utilities QPU Service Corp 83/10/05 STOLZ, J F Operating Reactors Branch 4 2pp 20665 306 24X Fiche 50-289,83/10/05.8310110200
- 8310170304 Forwards Amend 87 to License UPR-50 & safety evaluation Amend adds limiting condutions of operation & surveillance requirements for hydrogen recombiner sys per restart requirements for nyorogen recommune, 55, 50.

 requirements

 VAN VLIET.J Operating Reactors Branch 4 83/10/05 HUKILL.

 Deneral Public Utilities — OPU Service Corp 4pp 20794 2P4

 Fiche 50-289,83/10/05,83/0170304 HUKILL, H. D.
- --83i0170307 Amend 87 to License DPR-50, adding limiting conditions of operation & surveillance requirements for hydrogen recombiner sys per restart requirements STOLIJ F Operating Reactors Branch 4 B3/10/05 7pp 20796.230 24X Fiche 50-209.83/10/05.8310170304
- --B3i017031i Safety evaluation supporting Amend B/ to License DPR-50 * Dffice of Nuclear Reactor Regulation, Director 83/10/05 P 20794 234 24X Fiche 50-289,83/10/05,8310170304
- 8308300771 Board Notification 80-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT.D C Division of Licensing B3/10/06 GILINSKY,V , ROBERTS,T M Commissioners 31pp Fiche 50-000.83/10/06.83083007/1 PALEADING, N. J., 20818-001 - P4X
- G310120375 Forwards info INPO provided to util at INPO conference of chief executive officers IMI-1 rated as average or in top one-sixth of all operating plants in US Svc list encl
 BLAKE.E.L. Shaw, Pittman, Potts & Troubridge BLAKE, Et
 Metropolitan Edison Co. B3/10/06 EDLES, G. J., BUCK, J. H., KUIK, C. N.
 Atomic Safety and Licensing Appeal Panel. 48pp. 20697-037 24X
 Fiche 50-289, B3/10/06, 8310120395

- 8310170695 Staff requirements memo re 831006 briefing on results of GPU vs 88W trial matl & other uncontested matters re TMI-1 restart Commission made no requests & took no action CHILK, S J Office of the Secretary of the Commission 83/10/06 Office of the Secretary of the Commission 1p 20798 158 24X Fiche 90-289,83/10/06,8310170695
- B310180092 Ack receipt of 830915 request for info conceining open issues re mpt integrity identified in 830519 k 0715 memos to Commission NRC evaluation of papen issues proceeding w/ exception of GPU vs B&W lausuat record
 DIRCKS,W J Office of the Executive Director for Openations
 B3/10/07 DICKAMP.H General Public Utilities GPU Service Corp
 1p 20824 125 24% Fiche 50-289,83/10/07,8310180092
- --B310180099 Requests NRC provide identification & evaluation of specific concerns remaining or developed as result of evaluation of open issues Also requests all related recent insp repts & basis for concern in other areas
 DICCKAMP, H General Public Utilities GPU Service Corp
 B3/09/15 DIRCKS,W J Office of the Executive Director for Deparations 4pp 20824 128 24X Fiche 50-289,83/10/07, B310180092
- 8310140251 Requests extension to Mar 1984 for response to Item 2 2 2 of Generic Ltr 83-28, "Required Action Based on Generic Implications of Salem ATMS Events " Response to all other items will be submitted by 831108 MCMILL, H D General Public Utilities GPU Service Corp 83/10/10 EISEMUT. D G Office of Nuclear Reactor Regulation, Director lp 20761 331 24X Fichs 50-289, 83/10/10, 8310140251
- 8310310476 Approves request for withholding Rev 3 to 8&W Topical Rept 008. "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair" (ref 10CFR2 770) STOLZ. J F Operating Reactors Branch 4 83/10/11 HUKILL.H D General Public Utilities GPU Service Corp 5pp 20765 183 24% Fiche 50-287.83/10/11.8310310476
- B310180347 Comments on NUREG-1020 re GPU vs B&W lawsuit review NRC did not make reasonable technical judgments, leaving issues that should have been resolved re mgt integrity as issues potentially involving integrity pieckAMP, H General Public Utilities GPU Service Corp 83/10/14 PALLADINGIN J. ASSELSTINE. J K. BERNYHAL, F Commissioners 35pp 20804 301 24% Fiche 50-289.83/10/14.8310180347
- 8310260334 Forwards Amend 88 to License DPR-50 & safety evaluation Amend revises Tech Bpec to ref new liquid effluent discharge monitor RM-112.in lieu of presently referenced monitor RM-6 VAN VLIET. J Operating Reactors Branch 4 83/10/14 HUKILL, H E General Public Utilities GPU Bervice Corp 5pp 20921 172 E Fiche 50-289, 83/10/14, 8310260334 HUKILL H D
- --8310260337 Amend 88 to License DPR-50, revising Tech Spec to ref now liquid effluent discharge monitor RM-112, in lieu of presently referenced monitor RM-L7 STOL7. J F Operating Reactors Branch 4 83/10/14 8pp 20921 177 24% Fiche 50-289, 83/10/14,8310260334
- --8310260342 Safety evaluation supporting Amend 88 to License DPR-50
 * Office of Nuclear Reactor Regulation, Director 83/10/14 B
 20921 185 24X Fiche 50-289, 83/10/14, 8310260334
- B3102B0172 Responds to appeal re partial denial of FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests Info partially withheld (ref FUIA Exemption 3) CHILX, B. J. Office of the Secretary of the Commission 83/10/14, VOIOT, H. LeBoeuf, Lamb, Leiby & MacRae 2pp 20945 057 24X Fiche 80-289, 83/10/14, 8310280172
- --8310280179 Comments on questions raised in 830517 ltr to Chairman Palladino re communication between agencies DDJ should commit to completion date for investigation Bupporting documentation encl CUMMINGS,J,J Office of Inspector & Auditor 8: JEMSEN,D L Justice, Dept of 4pp 20965 064 Fiche 50-269,83/10/14,8310280172 83/05/31
- 8310210085 Advises that commitments to resolve each apparent deficiency indicated in Table 4-1 of 821210 technical evaluation rept on environ qualification will be provided in Jan 1984 HUKILL, H D General Public Utilities GPU Service Corp 83/10/17 870LZ, J F Operating Reactors Branch 4 1p 20857 275 24X Fiche 50-289,83/10/17.8310210085
- 8310280143 Requests review of encl draft restart licensing conditions Public meeting following review suggested to receive addl info & to discuss comments on wording STOLZ. J F Operating Reactors Branch 4 83/10/17 HUKILL, H D General Public Utilities GPU Service Corp 17pp 20965 100 24x Fiche 50-289.83/10/17.8310280143

- 8310200211 Forwards INPD evaluations on util mgt Svc list enc)
 BLAKE.E L Shaw, Pittman, Potts & Troubridge 83/10/18 CDLF5.6 J
 Atomic Safety and Licensing Appeal Panel 47pp 20832 351 24X
 Fiche 50-000,83/10/18.8310200211
- 8310210249 Forwards corrected pages to INPO rept provided on 831010 BLAKE,E L. Shaw, Pittman, Potts & Trowbridge BLAKE,E L. Metropolitan Edison Co. 63/10/17 EDLES,G J. BUCK,J H., KO.H.,C N. Atomic Safety and Licensing Appeal Panel 6pp 20851 049 24X Fishe 50-000,63/10/17.6310210249
- 9310250261 Forwards add1 info re NRC Safety Issue 8-24, "Furge Valve Operability," per NRC 830708 request Items from NRC 830708 Itr requiring amend to Tech Specs will be forwarded as rev to Tech Spec Change Request 116 by separate ltr HUXILL.H D General Public Utilities GPU Service Corp 83/10/17 870LZ.JF Operating Reactors Branch 4 22pp 20898 247 24% Fiche 50-289,83/10/19.8310250261
- 8310310489 Summary of B30826 meeting w/RKW Dunbrs Group re implementation of Generic Ltr 83-28 concerning defenses against ATMS & proposed ATMS rule for B&W plants List of attendees & viewgraphs enc! KADAMBI.P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20765 147 24X Fiche 50-000.83/10/20, B310310489
- 8310260143 Requests guidance of reportability of BETA & SHR repts
 Intermofe memo describing reporting obligations for util
 emplayees encl
 CLARKIP R General Public Utilities GPU Service Corp 83/10/21
 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
 20915 243 24% Fiche 50-289,83/10/21,8310260143
- 8310270130 Requests review & concurrence w/proposed gost-accident shielding alternate solution mod (NUREO-0/37.1tem II B 2). per 830521 & Odi5 responses to Generic Ltr 82-05 MUKILL.H D General Public Utilities GPU Service Corp 83/10/21 8TOL7.J F Operating Reactors Branch 4 6pp 20925 022 24X Fiche 50-289.83/10/21.8310270130
- 8310280108 Forwards application for amend to License DPR-50 consisting of Tech Spec Change Request 134 changing manager, plant training, TMI-1 position to manager, plant training, TMI RUKILL. H D General Public Utilities GPU Service Corp 83/10/21 8TOLZ. J F Operating Reactors Branch 4 Ip 20727 209 24X Fiche 50-287,83/10/21,8310280108
- --8310280115 Application for amend to License DPR-50 consisting of Tech Spec Change Request 134 changing manager plant training, TMI-1 position to manager plant training TMI HUKILLH P General Public Utilities - GPU Service Corp 83/10/21 App 20727 210 24X Fiche 50-287.83/10/21.8310780108
- B310310410 Forwards B&W Owners Group Analysis Committee/Core
 Performance Committee Rept "Ununding Analytical Assessment
 of NUREG-0820 Models on LOCA tW/ft Limits M/Use of FLECSET"
 HUKILLH D General Poblic Utilities GFU Service Corp B3/10/P1
 NUVAK-T Assistant Director for Licensing 1p 20961 001 24X
 F1(chs.50-289.83/10/21.8310310410)
- --8310310413 "Bounding Analytical Assessment of NUREO-0630 Models on LOCA kW/ft Limits W/Use of FLECSET" * Babcock & Wilcox Operating Plants Owners Group 77-1140898-01 83/09/30 104pp 20961 002 24X Fiche 50-289,83/10/21, 8310310410
- 9310280123 Responds to 830912 ltr refuel mgt plan for Cycle 6 & estimated schedules for fuel mgt plans used to meet pressurised thermal shock flux reduction Commits to in-out-in fuel mgt plan HUKILL, H D General Public Utilities GPU Service Corp 83/10/24 EISEMUT, D Q Division of Licensing 2pp 20929 264 24X Fiche. \$0-289.83/10/24.8310280123
 - Inspection reports. IE Bulletins & correspondence
 - 027029B Appeals deniel of FOIA request for placement of 1E vestigation Rept 1-83-003 in PDR. [LCGYNE.J J. Kilcoyne. J J. 83/05/91. Office of the Secretary the Commission 1p 20942-356 24X Fiche 50-289.83/05/31. 11027029B
 - 0040061 Board Notification 83-132 forwards NRC 830725 lts & IF Inspiret 50-289783-13 re emergency preparedness upon items SENHUT.D 0 Division of Licensing 83/09/09 PALLADINO,N . LINSKY,P., ROBERTS,T Commissioners App 20640 338 24X che 50-289,83/09/09.8310040061

- 831020021B Forwards IE Inap Repts 50-289/83-18 % 50-320/83-10 on 830622-24 & 0711-20 & notice of violation MARTIN, T I Region 1. Office of Director 83/09/14 KANGA, E K General Public Utilities GPU Service Corp 2pp 20830 123 24) Fiche 50-289,83/09/14,831020021B
- ~-8310200237 Notice of violation flow insp on 830622~0720 * Region 1. Office of Director 83/09/14 lp 20830 1.75 .48 Fiche 50-289,83/09/14,8310200218
- --8310200270 IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 b 0711-20 Noncompliance noted failure to perform quarterly fire brigade training PAGLINDER: PLISCOL: ANDERSON.C J Region 1. Office of Director 83/09/06 19pp 20830 126 24% Fiche 50-289,83/09/14, 8310200218
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Bualification Tests" But list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 P4X Fiche 50-000,83/09/26,8308000040
- 8308300342 IE Info Notice 83-62, "Failure of Redundant loxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300742
- B30B300345 IE Info Notice B3-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York: Inc 118pp 20778 001 24X Fiche 50-000.83/09/26.8308300345
- 8310140162 Forwards IE Insp Rept 50-289/83-22 on 830/19-0829 No noncompliance noted STARGSTECKI, R Division of Project & Resident Programs 83/09/27 HUKILL. H D General Public Utilities - GPU Service Corp 2pp 20765 078 24X Fiche 50-289.83/09/27.8310140162
- --B310140166 IE Insp Rept 50-289/83-22 on B30719-0829, No noncompliance noted Major areas inspected licensee action on previous insp findings & shutdown plant operations for steam generator post-repair testing & restart valve lineups CONTE.R., BAUNACK, W. BELL., Repion J. Office of Director 63/09/26 10pp 20765 080 24X Fiche 50-289,83/09/27,8310140162
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310270304 Responds to appeal re denial of FOIA request for If
 Investigation Rept 1-83-003 Forwards document Document also
 available in PDR Portions of rept withheld (ref FOIA
 Exemptions 5 & 7)
 CHILK: J Dffice of the Secretary of the Commission
 KILCOYNE, J J Kilcoyne, J J 2pp 20942 359 24X
 Fiche 50-289,83/10/03.8310270304
- --B310270324 IE Investigation Rept 1-83-003 on 830125-0211 Status closed Major area investigated alleged compromise of preemployment psychological exams CHRISTOPHER R. HAYES. B B Office of Investigation 83/02/25 58pp 20942 361 24X Fiche 50-289.83/10/03.8310270304
- 8310180366 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/83-19 MARYIN.T T Division of Engineering & Technical Programs 83/10/05 HUKILL.H D General Public Utilities - GPU Service Corp lp 20803 192 24X Fichs 50-289.83/10/05.8310180366
- --8310180372 Responds to NRC 830817 ltr re violations noted in 1£ Insp Rept 50-289/83-19 Corrective actions production & GC personnel reinstructed in requirements for proper installation & insp of supports HUKILL,H D General Public Utilities - GPU Service Corp 83/09/16 MURLEY.T E Region 1, Office of Director 2pp 20803 180 24X Fiche 50-289,83/10/05,8310180364
- 8308300378 IE info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 837/10707 Consolidated Edisson Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co
 - 103) 83/10/07 Consolidated Edison Co. of Ne 20882 026 24% Fiche 50-000,83/10/07,8308300752
- B30B300759 IE Info Notice B3-67. "Emergency Use Respirator Natl Defect Causes Production of Noxious Gases "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison to of New York, Inc 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300757
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list
 - enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24% Fiche 50-000,83/10/11,8308300/61
- O310210280 Ack receipt of 031005 ltr informing NRC of steps taken to correct violations noted in It Insp Rept 50-209/03-23

 MARTIN, Y T Division of Engineering & Technical Programs 03/10/14

 HURICLI, II D General Public Utilities GPU Service Corp 2pp

 20848 213 24X Fiche 50-209/03/10/14/0310210280
- --8310210283 Responds to NRC 830902 ltr re violations noted in IE lasp Rept 50-289/83-23 Corrective actions production personnel Will be instructed to obtain engineering evaluation & direction prior to anchor installation MUKILL.H D General Public Utilities GPU Service Corp 89/10/05 MUKIEV.T E Region 1, Office of Director 2pp 20848 215 24X Fiche 50-209,83/10/14.8310210280
- R Periodic operating reports & related correspondence
- 9310120125 Forwards "TMI Aquatic Study, Monthly Rept for Aug 1783 " RESSLER, W C General Public Utilities GPU Service Copy 83/16 HICKEY, C NRC No Detailed Affiliation Given 1p 20696 126 24x Fiche 50-289, 83/10/07, 8310120125 83/10/07
- --8310120128 "TMJ Aquatic Study, Monthly Rept for Aug 1983" NARDACCI.O A Ichthyological Associates, Inc 83/08/31 18pp 20696 127 24X Fiche 50-289,83/10/07,8310120125
- 8310120360 Submits quarterly update of steam generato; long-term corresson test program All four test loops at normal operating temp for Cycles 2 & 4 Two addl cycles will be run on each loop & should be completed by 840515

 HUKILL.H D General Public Utilities OPU Service Corp 83/10/07

 STOLZ.J F Operating Reactors Branch 4 2pp 20699 321 247

 Fiche 50-209,83/10/07,8310120360
- 83:0:40:08 Submits annual replica simulator status rept per 8:0827 partial initial decision on mgt issues Contract for simulator awarded to Singer-Link Corp Delivery expected BSIZES BURILL.H D General Public Utilities - GPU Service Corp 83/10/10 STDLZ.J F Operating Reactors Branch 4 ip 20766 110 24X Fiche 50-289.83/10/10.8310140100
- 8310210037 Monthly operating rept for Sept 1983 W/831014 ltr MUXILL.H D , SMYTH,C W General Public Utilities OPU Service Corp 83710714 MCDDNALD.W C Office of Administration 7pp 20855 323 24X Fiche 50-289,83/10/14,8310210037
- S Reportable occurrences, LERs & related currespondence
- 8310200008 RD 83-23 on 830916, containment isolation valve found open while containment integrity required No threat to health & safety since second boundary remained closed Cause & corrective actions expected in 14-day followup rept TOOLE, R J General Public Utilities GPU Service Corp 83/09/19 MURLEY, T E. Region 1. Office of Director 1p 20830 234 24% Fiche 50-289,83/09/19,8310200008
- 6310200011 RO 63-26 on 830917-18.all main steam safety valves tested All but one valve lifted above allowed lift point tolerance of +1% of setpoint Caused by using incorrect main steam measer TOOLE,R J General Public Utilities - GPU Service Corp E MURLEY,T E Region 1. Defice of Director 1p 20830 235 Fiche 50-289,84/09/19.8310200011 83/09/19

- 8310190161 LER 83+023/99X-0 on B30B27, while locally checking control
- 8310190164 LER 83-020/03L-0 on 830826.while taking once per shift readings.operator found no sample flow to condensor exhaust monitor Caused by moisture condensor; in monitor sample line flow increased to blow out moisture W/830926 ltr SZCZECH, R A . HUKILL, H D General Public Utilities GPU Service Corp 83/07/26 MWRLEV, T E Region 1. Office of Director 3pp 20821 062 24X Fiche 50-289.83/09/26.8310190164
- 8310250253 LER 83-021/03L-0 on B30825, outbuildings auxiliary operator observed no flow rate on outlet valve RM-L-7 Caused by corrosion clogging valve Pipping will be replaced U/stainless steel to prevent recurrence W/B30930 ltr SZCZECH.R A . HUKILL.H D General Public Utilities QPU Service Corp 83/09/30 MURLEY.T E Region 1, Office of Director 4pp 20878 228 24% Fiche 50-289, 83/09/30, 8310250253
- 8310250589 LER 83-028/01T-0 on 830915, during once-through steam generator testing, 3/4-inch verit valve which serves as containment isolation valve found open Caused by personnel error Operators counseled W/830930 ltr
 STEPHENBON, C J HUKILL, H D General Public Utilities GPU Service Corp 83/09/30 MURIEY, T E Region 1. Defice of Director 3pp 20901 250 24% Fiche 50-289, 83/09/30.8310250589
- 8310070263 RO 83-032 on 830930, thermal & seismic stress criteria on instrument tubes not met Fatique characteristics revealed allowable number of cycles exceeds actual number of heatup & cooldown cycles experienced TOOLE, R. J. General Public Utilities OPU Service Corp. 83/10/03 MCRLEY, T. E. Region 1, Office of Director. 2pp. 20651-058 24X Fiche 50-289,83/10/03,8310070263 83/10/03
- 8310230552 RO 83-032 both thermal & seismic stress on instrument tubes regvaluated as followup to internal math nonconformance rept Operability stresses below ASME III criteria revealed TOOLE, R J General Public Utilities GPU Service Corp 93/10/03 MURLEY, T E Region 1, Office of Director 2pp 20700 312 24X Fiche 50-287,83/10/03.8310250552
- 8310250430 LER 83-026/017-0 on 830919.while testing main steam safety valves, all valves except one lifted above allowed lift setpoint tolerance of +1% Caused by personnel error which resulted in defective procedure W/831004 ltr KNIGNT.M R. HUKILL-H D. Genoral Public Utilities GPU Service Corp. 83/10/04 HUKIEV.T E. Region 1. Office of Director Spp. 2087/032 P4X Fische 50-289.83/10/04.8310250430
- 8310250606 LER 83-028/01T-0 on 830920.manual inside containment isolation valve IA-V20 in instrument air sys found open caused by threaded stem bushing backed partially out of yoke & paint buildup on stem Parts replaced W/831004 ltr SZCZECHLR A , HUKILL H D General Public Utilities GPU Service Corp 83/10/04 MURLEY T A Region 1 Office of Director 4pp 20900 154 24X Fiche 50-289, 83/10/04,8310250606
- 8310250274 LER 83-024/97x-0 on B30B27.while in cold shutdown condition. engineered safeguards actuation sys actuation relay 6321B/RB2A coil found smoking Probably caused by end of coil life or incomplete pull-in of armature W/B31010 itr KNIGHT.M R, HUKILL.H D General Public Utilities GPU Service Corp 83/10/10 MURLEY.T E Region 1. Diffice of Director 5pp 20B77 008 24X Fiche 50-289.83/10/10.8310250274
- T Hearing transcripts on non-antitrust matters
- 8310130372 Transcript of 831006 briefing in Washington, DC re results of GPU & B&W trial matt Pp 1-42 Supporting documentation encl enci * Commissioners 83/10/06 6ipp 20/70 052 24X Fiche 50-289/83/10/06/83i0130372
- 8310200189 Transcript of B31017 prehearing conference re steam generator regair in Harrisburg.PA Pp I=179 * Atomic Safety and Licensing Board Panel B3/10/17 182pp 20833 077 24% Fiche 50-289, B3/10/17, B310200189
- V Operator Examinations
- 8310070309 Forwards changes to licensed operator requalification program, per 82010A meeting Program to be consistent w/ current NRC exam administration Exams will be administered on 831208,09 % 10
 HUKILL, H D general Public Utilities OPU Service Corp 82/12/02
 BECKHAM, D K Operator Licensing Branch 4pp 20652 215 24X
 Fiche 50-289.68/12/02.8310970309

- DOCKET 50-293 PILGRIM NUCLEAR POWER STAFION, UNI! 1

 F. Security, medical, emergency & fire protection plans
- 8310180479 Application for amond to License DPR-35 consisting of Proposed Change 83-11 to Tech Specs Proposed mod should be treated as third segment of seven submittals addressing fire protection issue Requests single amond be issued HARRINGTON, W.D. Boston Edison Co. 83710713 VASSALLO, D.D. Operating Reactors Branch 2. 2pp. 20003 159 24X Fiche 50-293,83710713,8310180477
- ~~8310180483 Proposed Change BJ-11 to Tech Specs re Halon 1301 fire protection sys.App A. Section 3 12 + Boston Edison Co 83/10/13 5pp 20803 160 24X Fiche 50~293.83/10/13.8310180479
- 8310180435 Forwards Rev O to "Detailed Control Room Design Review Program Flan, per NUREG-0737, Suppl I (Generic Ltr E2-33)
 HARRINGTON, W D Boston Edison Co 83/10/14 VASSALLO, D B
 Operating Reactors Branch 4 1p 20803 358 24X
 Fichs 90-293,83/10/14, 9310180439
- --8310180438 Rev O to Procedure 2 2 11/090983. "Dotailed Control Room Design Review Program Plan." • Boston Edison Co. 83/10/31 100pp 20803 359 24X Fiche 50-293.83/10/14/8310180435
- **G** Adjudicatory correspondence
- 8310040481 Petition of JF Doherty to intervene & request for hearing on util requested amend to License DPR-35 re operation w/one recirculation loop out of svc Certificate of 8vc encl DOHERTY.JF Doherty, JF 83/09/30 Commissioners 3pp 20623 120 24X Fiche 50-293.83/09/30.8310040481
- 8310250286 Response supporting JF Deherty 830930 petition to intervene & for public hearing Standing established based on location of residence, vacation activities in Cape Cod & consumption of fish from Massachusetts Day W/Certificate of 5vc CHAN; E. I. Hearing Branch 2 83/10/20 Atomic Safety ond Licensing Board Panel 7pp 20895 357 24% Fiche 50-293.03/10/20.8310250286
- 8310260305 Notice of ASLB constitution.BP Cotter.chairmen & CA Linenberger & OH Paris.members COTTER.BP Atomic Safety and Licensing Board Panel 83/10/21 2pp 20910 326 24X Fichs 50-293.83/10/21.8310240305
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310250544 Forwards Rev 3 to updated FSAR Rev outlines intention to update Chapter #4 & App 0 List of errors identified since 830719 submittal encl Errors will be corrected in 840722 Rev 4 HARRINGTON N D Boston Edison Co 83/10/11 DENTON H R Dffice of Noclear Reactor Regulation, Director 3pp 20902 345 247 Fichs 50-293,83/10/11,8310250544
- --8310250549 Rev 3 to updated FYAR

 + Boston Edison Co 83/09/30 18Upp 20902 346 24X
 Fiche 50-293,83/10/11,8310250544
- P Operating lacense stage documents & correspondence
- 8310070045 Forwards mod to 810113 & 820117 orders extending completion date to 850221 for installation of mods to torus catuals extension support legs & rung girder to torus shell welds VASSALLO,D O Operating Reactors Branch & 83/09/22 HARRINGTON,W D Boston Colson Co Opp 20671 350 P4X Fiche 50-293,83/09/22.8310070045
- --8310070048 Mad of 810113 & 820119 orders extending completion date for installation of design mods from mid Lyrle 7 mod outago to before restart EISENHUT,D G Division of Licensing 83/09/22 Boston Edison Co 5pp 20671 353 24% Fiche 50-293,83/09/22,83100/0045
- tension to Apr 1984 to comply w/final rule to 1MJ
 - 83/09/27 DENIGN.H R Office of Sep 20592 340 249

- 8310120307 Forwards latest change to NPDE5 permit effective 830900, pri request HARRINGTON, W.D. Boston Edison Co. 83/10/05 VASSALIG, D.B. Operating Reactors Branch 2. 45pp. 20700-320 24X Fichs 50-293, 83/10/05, 8310120307
- B310120330 Requests that open time limit on 20-inch containment purge 2 yent valves be extended to 160 h to allow for possibility of openational problems during planned outlage & any unscheduled outlages required prior to 83/10/07 by Wilson HARRINGTON W D Boston Edison Co 83/10/07 VAGSALLD D B Operating Reactors Branch P 2pp Fiche 50-293, 63/10/07, 8310120, 30
- 8310180491 Application to amend ticense DPR-35 containing Proposed Change 83-10 to Toch Specs re administrative changes to nuclear operations organizations
 HARRINGTON, W.D. Doston Edison Co. 83/10/12 VASSALLO, D.B. Operating Reactors Branch 2. App. 20801 196. 247
 Fiche 50-293,83/10/12,8310180491
- 8310180479 Application for amend to License DPR-35 consisting of Proposed Change 83-11 to Tech Specs Proposed mod should be treated as third segment of seven submittals addressing fire protection issue Requests single amend be issued HARRINGTON.W D Boston Edison Co 83/10/13 VASSALLO.D D Operating Reactors Branch 2 2pp 20803 158 24X Fiche 50-293,83/10/13.83101604/7
- --8310180483 Proposed Change 83-11 to Tech Specs re Halon 1301 file protection sys.App A.Section 3 12 * Buston Edison Co 63/10/13 5pp 20803 160 24X Fichs 50-293.83/10/13.83101804/7
- 8310260437 Notification of Significant License Meeting 63-90 (m (cs)10°1 in King of Prussia, PA to discurs refueling outage plans GALLG.R M Region 1, Office of Director 83/10/20 Region 1, Office of Director 1pp 20926 335 EAX Fiche 50-293,83/10/20, 8310260447
- 9310310144 Provides agenda & list of util attendees for upcoming meeting.per 931020 commitment Meeting topics include status of long-term program license amend & update of refueling outage schedule
 HARRINGTON.W D Boston Edison Co 83/10/25 VASSALLO.D 9
 Operating Reactors Branch 2 2pp 20759 007 247
 Fiche 50-273,83/10/25.8310310444
- 8310310270 Forwards draft procedure "Single Loop Operation Oreating than 24 H " Flow bias derived from recirculation pump flow measurement Idle loop automatically accounted for in flow bias HARRINGTON, W D Boston Edison Co 83/10/25 VASSALLO, D B Operating Reactors Branch 2 12pp 20761 148 247 Ficho 50-273, 83/10/25,8310310270
- B310310306 Responds to B30706 request to reevaluate position on NUREQ-0737. Item II E 4 2(7) Manitor capable of promptly & reliably providing isolation signal would not be sufficiently sensitive to detect release rates HARRINGTON W D Boston Edison Co B3710/25 VASSALLO, D B Operating Reactors Branch 2 2pp 20961 227 24X Fiche 50-293,83/10/25,0310310306
- Q Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Gualification lests " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308,800,440
- 8308300342 IE Info Notice 83-62, "Failure of Redundant loxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E t Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison to of New York, Inc. 116pp 20777 210 24X Fichs 50-000,83/09/26,83083034P
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26.8308J00345
- B308300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list encl JORBAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 2016 324 24X Fiche 50-000.83/09/29.8308300047

- B310070321 Forwards minutes of B30B31 mgt meeting w/util in Plymouth, MA reprogress rept on implementation of performance improvement program Procedure revs will be revalidated after station receipt of design document update packages STAROSTECKI, R Division of Project & Resident Programs B3709730 MARRINGION, W D Boston Edition Co 5pp 20452 172 249 Fiche 50-273, 83709730, 8310070321
- BJOB300378 IE Info Notice B3-65, "Surveillance of Flow in HID Dyphis Loops Used in Westinghouse Plants "Sv. list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Pust B30103) B3710707 Consolidated Edison Co. of New York, Inc. 74pp 20827 213 24X Fiche 50-000,83710707,8308300378
- B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E I Division of Emergency Preparedness & Engineering Response (Post 820103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 076 24X Fishe 50-000, B3/10/07, B30B300/5p
- B308300759 IE info Notice 83-67. "Emergency Use Respirator Matl Defect Gauses Production of Noxious Gases " Svc. list encl JORDAN, E.L. Bivision of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Courdidated Edison Cn. of New York, Inc. 117pp 21043 075 24X Fiche 50~000,83/10/11,8308300/59
- 8308300761 IE Info Notice 83-60, "Respirator User Maining Defective Belf-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 2087 189 24X Fiche 50-000.83/10/11.83083.00/81
- 9310270225 Ack receipt of 83090/ ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50~293/83-17 HARTIN.T T Division of Engineering & Technical Programs 83/10/20 HARRINGION.N U Beston Edison (o Ppp 20924-0/4 24X Fiche 80~293.83/10/20.8310270/25
- --B3102/02/0 Responds to NRC 83(815) itr re violations noted in it insp Rept 50-293/83-(3 Corrective actions Tech Spec change being prepared to clarify revious approval of vendor (supplier) procedures Change expected by 831101 PARRINSTON W D Boston Edison Co 83/09/07 STAROSTECKI, k Division of Project's Resident Programs 1, 20924-076 24% Fichs 50-293,83/10/20,83102/0325
- R Periodic operating reports & related correspondence
- D309190140 Monthly operating rept for Aug 1983 W/830913 ltr WHITNEY, G Q . HARRINGTON. W D Boston Edison Co 83/09/13 Director's Office, Office of Inspection and Enforcement /pp 20410 142 24X Fiche 50-293,83/09/13,8309190140
- B310180111 Monthly operating repts for Stpt 1983 W/B31012 1ti HAM1LTON.P., HARRINGTON.W D. Boston Ldison Co. 83/09/J0 Director's Office Office of Inspection and Enforcement 7pt 20800 164 24X Fiche 50-293,83/09/30.8310180111
- S Reportable occurrences, LfRs & related correspondence
- 8310200226 Telecupy LER 93-047/01X-0 on 830913.rectrculation pump Low-low water trip relay (16AKBA) found smoking Power deenergized Failure of relay contacts due to coating of Smoke & Varnish Relay replaced WHITMEY.0 G Boston Edison Co. 83/09/15 Region 1, Office of Director 1p 20833 039 24X Fiche 50-293.83/09/15.8310200228
- #350060051 PNG-J-B3-100 on 8309.49, potential overpressurplation of low pressure piping at pump suction occurred Event attributed to malfunctioning check valve Seal leak repaired Valve apparently stuck partially open JOHNSON-J GALLO, R. Region 1, Office of Director 83/09/30 1p 20847-0/3 24X Fiche 50-293,83/09/30 8310060051
- E-310280045 LER B3-048/Olk O on B30929, while conducting HPC1 legic surveillance. HPC1 high suction pressure alarm & HPC1 area single detector alarm received Caused by leaking in-line check valve in HPC1 pump discharge line Director Ip 20927 COB 24X Fiche 50-293.83/07/30 8310280045

- 8310250137 LER 83-049/02L-0 on B30909, during steady-state operation, recirculation pump A MG set inadvertently tripped While changing out generator brushes on A MG set brush pigtail inadvertently shorted out W/831005 ltr
 WHITMEY.G G . HARRINGTON.W D Boston Edison Co B3/10/05 Region 1, Office of Director 2pp 20896 346 24X Fiche 50-293,83/10/05,8310250137
- 8310140082 PNO-I-83-105 on 83100/, seismic event occurred in northeastern US w/magnitude of 5 2 on Richter scale in NY 5 4 0 in NH No damage to equipment identified SALLO, R M Region i. Office of Director 83/10/07 ip 20766 116 24X Fiche 50 000, 83/10/07. 8310140082
- 8310250282 LER 83-048/01T-0 on 830929, while conducting investigation into apparent overpressure condition in HPCI sys. turbine stop valve would not operate (aused by failed coil in turbine stop valve Coil replaced W/831014 ltr
 WHITNEY. G. HARRINGTON. W D. Roston Edison Co. 83/10/14 Region i, Office of Director 4pp. 20894 255 247 Fiche 50-293,83/10/14,8310250282
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/07/01 PEDRO,J NUS Corp 2pp 20704 (37 24% Fishe 50-000.83/07701.8310110004
- --8310110010 "Appraisal of Fire Effects from Aircraft Crash At Zion Power Reactor Facility " PINKEL.1 1 Atomic Energy Commission 72/07/17 35pp 20704 139 24% Fiche 50-000.83/07/01.8310110004
- 8310140173 Ack receipt of B31003 ltr informing NRC of steps taken to correct violations noted in IE losp Repts 50-295/83-13 & 50-304/83-13 SHAFER, M D Region 3. Office of Director B3/10/04 REED.C Commonwealth Edison Co ip 20745 001 24X Fiche 50-295.83/10/06.8310140173
- --83|0140|75 Responds to NRC 830829 ltr re violations noted in IE Insp Repts 50-295/83-|3 & 50-304/83-|3 Corrective actions surveillance conducted on fire young diesel engine & starting j2-volt battery bank & charger LENTINF,F Q Commonwealth Edison Co 83/10/03 KEPPLER,J Q Region 3, Office of Director 2pp 20765 002 24X Fiche 50-295.63/10/06.83|0140|73
- B310240087 Forwards IE Insp Repts 50-295/B3-17 & 50-304/B3-18 on B30810-0920 & notice of violation NORELIUS: C E Division of Project & Resident Programs B3/10/07 REED. C Commonwealth Edison Co 2pp 20880 348 24x Fiche 50-295, B3/10/07. B310240087
- ""8310240096 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 Noncompliance noted Unit 2 operated w/diesel generators 2A: 28 & O inoperable on 830704-11 & 21-27; contrary to surveillance requirements HATERS, J. R., DUNAHAY F. R., HARIMANN.P. L. Region 3, Office of Director 83/10/04 lipp 20880 352 24X Fiche 50-295,83/10/07,8310240087
- 8310210374 Releases public version of revised emergency plan implementing procedure FELTON, J.M. Division of Rules and Records 83/10/17 Document Management Branch 1p 20882 349 24% Fiche 50-295,83/10/17, 8310210374
- "-B310210377 Public version of Rev 1 to Lmergency Plan Implementing Procedure EP1P 360-4. "Radiodine Sampling Under Accident Conditions" W/B30926 ltr.receipt form & procedure change request form PLIML.G Commonwalth Edison Co BJ/09/22 DENTON.H R NAC No Detailed Affiliation Gaven App 20882 350 24x
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON.JM Division of Rules and Records 83/10/21 Document Management Branch 1p 2093/216 24X Fiche 50-000,83/10/21, 83102705/6
- --B310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6. "Administration & Logistics Manager "W/B31017 ltt & receipt form NELLIS.C A Commonwealth Edison Co. B3/02/18 DENTON.R R NRC No Detailed Affiliation Given 7pp 20737-217 24X Fiche 50-000.83/10/21 B3102/05/6

- 8310280307 Releases public version of revised generating stations amergency plan telephone directory FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24% Fiche 50-000,83/10/25,8310
- --0310280314 Public version of revised generating stations emergency plan telephone directory GALLE.D P Commonwealth Edison Co 83/08/11 DENIUN.H R Diffici of Nuclear Reactor Regulation, Director 64pp 20963 12/ 24X Fiche 50-000.83/10/25:8310280307
- 831028019t Releases public version of revised emergency plan implementing procedure FELTON J N Division of Rules and Records 83/10/26 Decument Management Branch Lp 20962 266 24X Fiche 50-000.83/10/26, 8310280191
- --8310280207 Public version of Rev I to Emergency Plan Implementing Procedure EOF-15, "Emergency Operations Facility Activation"
 HODRER D Commonwealth Edison Co 83/08/02 50pp 20962 26/24X Fiche 50-000.83/10/26.8310280191
- P Operating license stage documents & correspondence
- B310130415 Forwards FR notice of consideration of issuance of amonds to Licenses DPR-39 & DPR-48 to permit operation wighly three of four primary coolant loops in svo VAROALS A Operating Reactors Branch 1 B3/D9/23 FARRARID (Commonwealth Edison Co. 2pp. 20769 008 24% Fichs 50-295.83/09/23 B310130415
- ~-8310130416 Notice of consideration of issuance of amends to Licenser DPR-37 & DPR-48 & proposed NSMC determination & opportunity for hearing VAROA. S A. Operating Reactors Branch 1 83/09/23 App 20769 010 24x Fiche 50-295.83/09/23.8310130415
- 93i0110117 Supplite 830808 request for amend to Licenses DPN-39 & DPR-48, revising Tech Specific containment leakage test acceptance criteria Info clarifies 1001k50 App J calculations
 LENTINE, G Commonwealth Edison Co 03/10/05 DENION, H & Office of Nuclear Reactor Regulation, Director 5pp 20667 169 24x
 Fiche 50-293,83/10/05,8310110117
- 8310170042 Forwards request for addition or use of optimized furl assembly Response required to complete evaluation.

 VARGALS A Operating Reactors Branch I 83/10/05 FARRAR, D L Commonwealth Edison Co. 4pp. 20812-150 24% Fiche 50-275, 83/10/05, 8310170042
- 8310200273 Forwards schedules for equipment qualification test programs for facilities.per 810528 ltm Dates given for current qualification activities should be viewed as "target dates" to not as firm dates 8ARMES.P L Commonwealth Edison Co 83/t0/05 KEPPLER.J & Region 3. Defice of Director 10pp 20830 0J4 24x Fiche 50-000.83/10/05.8310200273
- 8310200151 Application for immediate & temporary amend to Licenses DPR-39 & DPR-48. changing Tech Specs to allow preventive maint to be performed on where dieset generator O during current refueling outage LENTINE: F G Commonwealth Edison Co 80/10/14 DENIUN.H R Office of Nuclear Reactor Regulation, Darector 10pp 20896-282 74X Fiche 50-295,80/10/14-8010200151
- 8310310049 Forwards response to NRC 801006 request for add1 info re 830822 application for license amend to permit use of optimized fuel assemblies Structural analysis of mized reactor core during seismic event encl
 LENTINE F 9 Commonwealth Edjson Co 03/10/21 DENION & R Office of Noclear Reactor Regulation, Director 14pp 20/51 131 04X Fiche 50-295.83/10/21.8310310047
- B3103100A0 Bubmits info re Edison rod sunp analysis method for review & approval Hethods employed in support of control rod worth measurements using rod swap bethnique during reload physics testing Criteria tables ent!

 LENTINE: F 0 Commonwealth Edison Co B3/10/R4 DENTUN.H R (Ffice of Nuclear Reactor Regulation. Director (pp. 2095) 024 24y
 Fiche 50 000.83/10/24.8310310060

- g Inspection reports, IE Bulleting & conferendence
- 8310:10456 Forwards safety evaluation & technical evaluation rept results responses to IC Gulletin 80-11. "Masonry Wall Design "Requests actions planned & scheduled for resolution of issue within 30 days

 VARGA.5 A Operating Reactor's Branch 1 83/09/12 FARRAR.D L

 Commonwealth Edison Co. 4pp. 20712 197 24X Fiche 50-295 83/09/12 8310110456
- -8308030016 Revised "Masonry Wall Design (B-59), Zion Units 1 & 2." technical evaluation rept SUBRAMONIAN.N Franklin Institute/Franklin Research Contro NRC-03-81-130 TER-05506-243 ROI 83/07/27 CHOKSHI,N C NRC No Detailed Affiliation Given 25pp 20712 202 24X Fiche 50-295.83/09/12.8310110456
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand Ins for Wilder Qualification Tests" Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison (or of New York, Inc. 117pp. 20754-022 24X Fiche 50-000.83/09/26.8308.000440
- 8308300342 IE Info Notice 83-62 "Faiture of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8309300342
- 8308300345 IE Info Notice 83-63. "Potential failures of Westinghouse Type 8A-1 Differential Relays." Svc. list encl. JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 63/09/26. Consolidated Edison Co. of New York, Inc. 118pp. 20778 001. 24% Fishe 50-000.83/09/26.8308.80245
- 8308300349 IE info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svt list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 119pp 20716-324 24x Fiche 50-000,83/09/29.8308/00349
- 8310200124 Forwards 1E Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-30483-20, 50-378/83-38, 50-474/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83 13 NDRELIUS, C E Division of Project & Resident Program: 83/10/04 REED. C Commonwealth Edison Co 2pp P0834 098 24X Fache 50 000, 81/10/04, 8310200124
- --8310200148 IE Mgt Meeting Repts 50-020/83-18.50-237/83-27.50-244/84.5.50-254/83-27.50-245/83.26.50-275/83-19.50-304/83-20.50-373/83-38.50-374/83-38.50-454/83-44.50-455/83.37.50-454/83-14.50-457/83-13.NDRELIUS.C E Division of Project & Resident Programs BJ/10/03 4pp 20834 100 24% Fiche 50-000.83/10/04.8310200124
- 8310140173 Ack receipt of 831003 ltr informing NRC of steps taken to correct violations noted in It lnsp Repts 50-295/83-i3 & 50-304/83-i3 SHAFER.W D Region 3, Office of Director 83/10/06 RLED.(Commonwealth Edison Co. 1p. 20765 001 24X Fichs 50-295,83/10/06,83101401/3
- --83101401/5 Responds to NRC 830829 ltr re violations noted in II likp Repts 50-295/83-13 & 50-304/83-13 Corrective actions surveillance conducted on fire pump diesel engine & starting 12-volt battery bank & charger LENTINE, F 0 Commonwealth Edison Co 83/10/03 KfPPLER, J G Region 3. Office of Director 2pp 20765 002 24X Fiche 50-295,83/10/04,83101401/3
- B30B30097B lE Info Natice 83-65. "Surveillance of Flow in RID Dypuss Loops Used in Hestinghouse Plants " Svc list encl JORDAN E t Division of Emergency Precaredness & Engineering Response (Post B301031 B3/10/07 Consolidated Edison Co of Niu York Inc 76pp 20827 213 P4X Liste 50-000-83/10/07.8388360J78
- B30B300/52 IE Info Notice B3 66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30L03) B37L0707 Consolidated Edison Co. of New York, Inc. 79pp 2082 0P6 24% Fich. 50-000.83/10/07 G30B300752
- 8310240087 Forwards 1E Insp Repts 50-295/83-17 & 50-304/03 18 on 830810-0920 & notice of violation MCRELIUS, C E Division of Project & Resident Program: 83/10/0/ PEED.C Commonwealth Edison Co 2pp //0880 348 //4X Fiche 50-295,83/10/07-8310240087

- ~~8310240091 Notice of violation from insp on 830810-0920 NOREL 105, C E Division of Project & Resident Programs 8J/10/07 2pp 2080 350 24% Fiche 50-295,83/10/07,8310240087
- --8310240096 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810 0920 Noncompliance noted Unit 2 aperated w/diesel generators 24:28 & 0 inoperable on 830704-11 & 21-2/, contrary to surveillance requirements HATERS, J R . DUNAMAY, F R . HARTHANN, P L Region 3, Office of Director 83/10/04 lipp 20880 337 24X Fiche 50-295,83/10/07,8310240087
- 830B300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Sv. list encl JORDAN E L Divinion of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300741 IE Info Notice 83-48, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83710711 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24y Fiche 50-000.83710711,8308300761
- 8310180110 Advises that plans & schedule for resolution of horizontal joint reinforcing, per IE Bulletin 80-11. "Masonry Walls" & NRC 930912 1tr.will be provided by 831111 Util presently riamining design of 18 walls affected by issue LENTINE, F C Commonwealth Edison Co 83/10/12 DEN1ON, H R Uffice of Nuclear Reactor Regulation, Director in 20802 258 .4X Fiche 50-295,83/10/12,8310180110
- B310180283 Clarifies NRC position reprocedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON, W.L. Region 3. Office of Director B3/10/14 REED, C. Commonwealth Edison Co. 7pp. 20801 115 24X Fiche 50~275,83/10/14,8310180283
- R Pariodic operating reports & related correspondence
- 8310120108 Monthly operating repts for Sept 1783 W/831007 ltr AUSTIN. 0., GRAESSER.K L. Commonwealth Edison Co. 83/10/07 Director's Office. Office of Inspection and Enforcement 12p; 20676 228 24X Fiche 50-275.83/10/07.8310120108
- S Reportable occurrences, LERs & related correspondence
- B310i10430 Responds to FOIA request for four different categories of documents described in B30510 ltr Forwards matl listed in App A.responsive to Items 1.2 & 4 DDE should be contacted for matl requested in Item 3 of ltr FELTON.J M Division of Rules and Records B3/06/14 HIATT.S L. Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000.83/06/14.8310110430
- --3310110478 Responds to 830413 ltr requesting info re use of foreign matls on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices FARRAR.D L. Commonwealth Edison Co. 83/04/22 KEPPLER.J G. Region 3. Uffice of Director 4pp. 2070& 063 24% Fiche 50-600.83/06/14.8310110430
- 8310120174 LER 83-034/03L-0 on 830911 MSIV 1C closure time exceeded 5 s during MSIV full closure test Valve closed in 31 s Caused by nitrogen precharge leak in closing side of accumulator Precharge restored W/B30928 ltr OAJIC. 2 GRAESSER. K. L. Commonwealth Edison Co. B3/09/28 KEPPLER. J. Q. Region 3 Office of Director 2pp 20696 001 PAX Fiche 50-295,83/09/28,8310120174
- 8310170588 Updated LER 82-047/03X-1 on 821205.RCS loop C indication changed delta temp pegged low & average temp pegged high Caused by failed resistance temp detector (RTD) Rosembunt 176KF RTD replaced W/831006 lt; PETRAX.1 G . GRAEBBER.K L. Commonwealth Edison Co 83/10/06 KEPPLER.J G . Region 3. Office of Director 2pp 20780 231 24X Fiche 50-295.83/10/06.8310170588
- 931017056: LER 83-036/03L-0 on 830910, during hot shutdown, penetration pressurization Zone 4 found below allowable Tech Spec limit of 47 psig Caused by leak in buried channel weld Weld channel xeolated W/831007 itr KELLY-T, ORAESSER, K L Commonwealth Edison Co 83/10/07 KEPPLER, J & Region 3, Office of Director 2pp 20780 225 24X Fiche 50-275, 83/10/07, 8310170561

- 8310270289 LER 83-038/03L-0 on 830921.during refueling recalibr.Loop A of reactor coolant flow transmitter IFT-414 found out of tolerance Caused by instrumentation zero shift Transmitter recalibr & returned to svc W/B31021 lt.
 WILHITE.M., GRAESSER.K.L. Commonwealth Edison Co. 83/10/21
 KEPPLER.J G. Region 3, Office of Director 2pp. 20923 233 24x
 Fiche 50-295.83/10/21.8310270289
- B310270384 PNO-lII-B3-102 on B31020, security officer received bomb threat phone call from unidentified male Shift engineer instituted emergency procedures Search of vital areas conducted w/negative results Threat determined hoax BELANGER. J. CREED, J. Region 3, Office of Director 83/10/21 1p 20923 287 24% Fiche 50-295, 83/10/21.8310270384
- T Hearing transcripts on non-antitrust matters
- 8310110004 Responds to FDIA request for five documents Forwards documents Documents also available in FDR FELTON, J M Division of Rules and Records 83/07/01. PEDRO, J NUS Corp 2pp 20704 137 24x Fiche 50-000:83/07/01.8310110004
- --8310110011 Testimony of DO Eisenhut re Zion/Haukegan Airport interaction * Atomic Energy Commission 83/07/01 10pp 20704 174 24X Fiche 50-000.83/07/01.8310110004
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3
 F Security, medical, emergency & fire protection plans
- 8310210032 Forwards IE Safeguards Insp Repts 50-259/83-26,50-260/83-26 & 50-296/83-26 on 830706-07 & notice of violation Notice of violation withheld (ref 10CFR73 21) O'REILLY, J P Region 2. Office of Director 83/09/01 PARRIS,H 0 Tennessee Valley Authority 2pp 20855 320 24X Fiche 50-259,83/09/01,8310210032
- --8310210034 IE Safeguards Insp Repts 50-259/83-24.50-260/83-26 & 50-276/83-26 on 830706-07 Moncompliance noted in area of access control vital areas Details withheld (ref JOCFR73 21) MODRE.D E Region 2. Office of Director 83/07/29 ip 20855 322 24X Fiche 50-259.63/09/01.8310210032.
- 83i0040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1983 Data availability repts will be discontinued due to consistently high data availability through previous rept periods MILLS.L. M. Tennessee Valley Authority 83/07/28 ADENSAM, E. Licensing Branch 4. 2pp. 20623 326 24X Fiche 50-000.83/09/28, 8310040452
- 8310110195 Releases public version of revised emergency plan implementing procedures FELTON, JM Division of Rules and Records 83/10/05 Document Management Branch 1p 20682 113 24X Fiche 50-259,83/10/05, 8310110195
- --B310110199 Forwards public version of revised emergency plan implementing procedures, ancluding Procedures IP-3 re alert, IP-4 re site area emergency & IP-5 re general emergency MILLS, L. M. Tennessee Valley Authority B3/07/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Darector ip 20482 114 24X Fiche 50-259,83/10/05,8310110193
- --8310110203 Public version of revised amergency plan implementing procedures, including Procedures IP-3 re aiert, IP-4 re site area smergency & IP-5 re general smergency WEBS.M E Tennessee Valley Authority 83/04/07 168pp 20682 115 24X Fiche 50-259.83/10/05.8310110195
- 8310310387 Forwards revs to security plan Revs withheld (ref 10GFR73 2))
 MILLS,L M Tennessee Valley Authority 83/10/06 O'REILLY,J P
 Region 2. Office of Director ip 20959 327 24X
 Fische 50-259.83/10/06.8310310387
- 8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted VERRELLI.D Division of Project & Resident Programs. 83/10/12 PARRIES HO Tennessee Valley Authority 2pp 20786 358 24% Fiche 50-259, 83/10/12,8310170189
- --B310170R38 IE Safeguards Inap Repts 50-259/83-37,50-260/83-37 & 50-296/83-37 on B30927-30 No noncompliance noted Hajor areas inspected security organization & mgt & personne) response Details withheld (ref 10CFR73 21) MODRE, D E Region 2, Office of Director 83/10/11 lp 20786 360 24X Fiche 50-259,83/10/12,8310170189

- 6310240137 Forwards safety evaluation re proposed mods & alternate capabilities for achieving safe shutdown.per IOCFR50.App R. Sections III G 2 & III L. Fire protection rule Proposed mods acceptable

 VASCALLO.D.B. Operating Procedure Franch 2 87/10/12 PADRIS.W.
- acceptable
 VASSALLO,D B Operating Reactors Branch 2 83/10/12 PARRIS.N G
 Tennessee Valley Authority 2pp 20884 342 24X
 Fiche 50-259,83/10/12,8310240139
- --8310240141 Safety evaluation supporting proposed mods & alternate capabilities for achieving safe shutdown.per 10CFRSO, App R. Sections III 0 3 & III L. Fire protection rule 4 Office of Nuclear Reactor Regulation, Director 83/10/12 7pp 20884 344 24X Fiche 50-259.83/10/12.8310240137
- 8310210071 Ack receipt of B30930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26. 30-260/83-26 & 50-296/83-26 O'REILLY,JP Region 2, Office of Director 83/10/1/ PARRIS.H O Tenness
- --8310210078 Responds to NRC 830701 ltr re violations noted in IC Insp Repts 50-259/83-26.50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 100FR73 21) MILLS.L M Tennessee Valley Authority 83/09/30 O'REILLY, P Region 2. Office of Director | p 20858 193 24X Fiche 50-299.83/10/17.8310210071
- 8310210362 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20883 001 24X Fiche 50-259.83/10/17.8310210362
- --8310210383 Forwards public version of revised emergency plan implementing procedures, including Muscle Shoels Emergency Ctr Implementing Procedure MSEC IP-9. "Emergency Radiological Monitoring Procedures"

 MILLS.L.H. Tennesse Valley Authority 83/10/06 DENTON, H.R. Office of Nuclear Resctor Regulation. Director ip 20883 COP 24% Fiche 50-259, 83/10/17, 8310210362
- --8310210386 Public version of revised emergency plan implementing procedures including Muscle Shoals Emergency Ctr Implementing Procedure MSEC IP-9. "Emergency Radiological Monitoring Procedures"

 * Tennesses Valley Authority 93/09/22 150pp 20893 003 24x Fiche 50-259.83/10/17.8310210362
- P. Operating license stage documents & correspondence
- 8310060383 Comments on proposed design for compliance w/NUREO-073/.

 Item II K 3 13, "Separate HPC) & RCIC Initiation Levels"
 re automatic restart Proposal acceptable
 VASSALLO, D B Operating Reactors Branch 2 83/09/17 PARRIS, H G
 Tennessee Valley Authority 3pp 20661 204 24X
 Fiche 50-259,83/09/19.8310060583
- 8310070068 Requests submittal of final radiological effluent Tech Sprct & offsite dose calculation manual within 30 days VASSALLO,DB Derating Reactors Branch 2 83/09/21 PARRIS,H G Tennesse Valley Authority 3pp 20671 334 24x Fiche 50-259,83/09/21.8310070068
- B310110521 Forwards Amends 90.86 & 59 to Licenses DPR-33.DPR-52 & DPR-68.respectively & safety evaluation Amends change Tech 8 pecs to modify required surveillance Interval for standby ges treatment sys CLARK.R J Decrating Reactors Branch 2 83/09/28 PARRIS.H & Tennesse Valley Authority 3pp. 20711 302 24% Fiche 50-259.63/09/28.6310110521
- --B310110536 Amends 90,86 & 59 to Licenses DPR-33, DPR-52 & DPR-60, respectively, revising Tech Spacs for testing standby gas treatment sys from once per up to once per operating cycle VASBALLO, D B Operating Reactors Dranch 2 B3/09/28 12pp 20711 305 24X Fich 50-259,83/09/28,8310110521
- --8310110551 Safety evaluation supporting Amends 90,86 & 59 to Licenses DPR-33.DPR-52 & DPR-68 respectively * Office of Nuclear Reactor Regulation, Director 83/09/28 3pp 20711 317 24% Fichs 50-259,83/09/28,8310110521
- 8310240154 Forwards request for add1 info re reactor protection syspower monitoring sys design mod.per 811030 request Model Tech Specs for electric power monitoring & analysis drawing, not provided Submittal date requested VASSALLD, D B Operating Reactors Branch 2 83/10/12 PARRIS, H G Tennessee Valley Authority Spp 20884 329 24X Fiche 50-259, 83/10/12, 8310240154

- 8310240243 Forwards SER % technical evaluation rept re NUREG-0737, ltems
 I A 2 1 4. "Upgrading of Reactor Operator & Senior Reactor
 Operator Training" & II B 4. "Training for Mitigating Core
 Damage " Requirements met
 VASSALLO.D B Operating Reactors Branch 2 83/10/12 PARRIS.In &
 Tennessee Valley Authority 4pp 20891 123 24X
 Fiche 50-259.83/10/12.8310240243
- --B20B310352 "Improvements In Training & Requalification Programs As Required By FMI Action Items I A 2 i & 11 B 4 for Browns Ferry Nuclear Plants. Units 1,2 & 3." technical evaluation rept

 * Strence Applications, Inc. NRC-03-B2-096 SAI-186-029-50 B2/08/25 NRC No Detailed Affiliation Given 15pp
 642B0 216 24X Fiche 50-000.83/10/12.8310240243
- 8310280148 Forwards "Analysis of Vessel Woll Neutron Dosimeter Flom Browns Ferry Units 1.2 % 3 Pressure Vessel," in response to NRC request for add1 info to support util 830922 request to change Tech Specs FS 191

 MILLS.L M Tennessee Valley Authority 83/10/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 17pp 20929 063
 24X Fiche 50-259, 83/10/19, 8310280148
- --8310280151 "Analysis of Vessel Wall Neutron Dosimeter From Hrowns Ferry Unit 7 Pressure Vessel" NORTS.E B . LINDHOLM U S Southwest Research Institute 79/09/30 /4pp 20929 137 24X Fiche 50-259,83/10/19,8310200140
- G Inspection reports, IE Bulletins & correspondence
- 8310250229 Updates 830624 response to vibilations noted in IL Insp Repts 50-259/83-14,85-260/83-14 & 50-26/83-14 Extension of schedule to eliminate backlog of CARs/liks until 830901 requested MILLS, L.M. Tennessee Valley Authority 83/08/08 D'RLILLY, J.P. Region 2, Office of Director ip 208/9 067 24X Fiche 50-259,83/08/08,8310250227
- B310210032 Forwards IE Bafeguards Insp Repts 50-259/B3-26, 50-260/83-26 & 50-296/B3-26 on B30706-07 & notice of violation Notice of violation withheld (ref 100FR/3 21) G'REILLY,J P Region 2, Office of Director B3/09/01 PARRIS,H & Tennessee Valley Authority 2pp 20855 320 24X Fiche 50-259,83/09/01,8310210032
- --8310210034 IE Safeguards Insp Repts 50-259/83-26, 50-260/83-26 & 50-294/83-26 on 830706-07 Noncompliance noted in area of access control vital areas Details withheld (ref 10CFR73-21)
 MODRED C Region 2. Office of Director MCGUIRE, D.R. Division of Engineering & Operational Programs 83/07/29 ip 20855-372-24X Fichs 50-259, 83/09/01, 8310210032
- 8310040265 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-259/83-24. 50-260/83-24 & 50-260/83-24 VERRELLI,D M Region 2, Office of Director 83/09/14 PARRIS.H G Tennessee Valley Authority ip 20613 123 24% Ficher 50-259,83/09/14,8310040265
- --8J1004027i Responds to NRC 830725 ltr re violations noted in 1F losp Repts 50-259/83-24.50-260/83-24 & 50-296/83-24 Corrective actions LMT examiners beared from poinforming addi intergranular stress corresion cracking exams MILLS,L M Tennessee Valley Authority 83/08/24 D'REILLY,J P Region 2, Office of Director 3pp 20613 124 24X Fiche 50-259.83/09/14,8310040265
- --8310040275 Forwards IE lnsp Repts 50-25Y/83-24.50-260/83-24 & 50-296/83-24 on 830621-24 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/07/2: PARRIS.H G Tennessee Valley Authority 2pp 20613 12/ 24X Fiche 50-259.83/09/14.8310040265
- --B310040283 IE Insp Repts 50-259/83-24,50-260/83-24 & 50-296/83-24 on B30621-24 Noncompliance noted failure to follow IE Bulletin B3-02 for requiring documented training in intergranular stress corrosion cracking COLEY, J L Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/07/21 App 20413 130 24X Fichs 50-259,83/09/14,8310040265
- B30B300340 IE Info Natice B3-64, "Alleged Use of Stand Ins for Welder Qualification Tests" Syc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fichs 50-000, B3/09/26, B30B300340

- 8308300342 IE Info Notice 83-62, "Failure of Redundant loxic 8a*,
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Syc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308200342
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, & L Division of Emergency Preparedness & Engineering Response (Pagt 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,03/09/26,8308300345
- 63100404B7 Concurs w/corrective actions taken to rectify violations noted in IE Insp Repts 50-259/B3-IB 50-260/B3-IB & 50-294/B3-IB Acceptable finding permits initiation of fuel mayment in & out of core
 O'REILLY, J P Region 2. Office of Director 83/09/26 PARRIG.H & Tennessee Valley Authority 2pp 20625 165 24X
 Fiche 50-259,83/09/26,8310040487
- 9308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl encl JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fichs 50-000,83/09/29,8308,60347
- 8310250166 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 30-259/83-27, 50-260/83-27 & 50-296/83-27 LEHIS.R C Division of Project & Resident Programs 83/10/04 FARRIS.H 6 Tennessee Valley Authority ip 20093 251 24X Fichs 50-259,83/10/04,8310250166
- --B310230170 Responds to NRC 830824 ltr re violations noted in II lusp Repts 50-259/83-27.50-260/83-27 & 50-296/83-27 Corrective actions test prossure gauges removed, Fuse identification program being established & panel 25-32 clasmed HILLS-L M lennessee Valley Authority 83/09/26 O'REILLY, J P Region 2, Office of Director 7pp 20893 252 24% Fichs 50-259.83/10/04.8310250166
- --8310250174 Forwards IE Insp Repts 50-259/83-27,50-240/83-27 & 50-294/83-27 on 830426-0725 & notices of violation & deviation LEMIS.R C Division of Project & Resident Programs 83/ PARRIS.H C Tennessee Valley Authority 2pp 20093 261 Fiche 50-259,83/10/04.8310250166
- ---8310250179 Notice of Violation from insp on 830626-0725 * Region 2, Office of Director 83/08/24 3pp 20 Fiche 50-259,83/10/04,8310250166 20873 263 24X
- --8310R50185 Notice of deviation from insp on 830A24-0725 * Region 2. Office of Director 83/08/24 1p 20893 266 Fiche 50-259.83/10/04.8310R50166
- --0310230190 IE Insp Repts 50-299/83-27,50-240/83-27 & 50-296/83-27 on 830624-0725 Noncompliances noted failure to meet requirements for operational safety & absence of safety wires on backup control ctr
 PAULK,G L Region 2. Office of Director CANTRELL,F S Division of Project & Resident Programs 83/08/19 10pp 20893 267 24X Fiche 50-259,83/10/04,8310250166
- 6308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 30-000,83/10/07,8308300378
- 8309300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 30-000,83/10/07,8308300752
- 63:0250131 Ack receipt of 830816 ltr informing NRC of steps taken to correct violations noted in IF Insp Rapts 50-259/83-11, 50-260/83-11 & 50-296/83-11 LEWIS,R C Division of Project & Resident Programs, 83/10/07 PARRIS,H O Tennessee Valley Authority ip 20897 272 24X Fiche 50-259,83/10/07,8310250131
- --8310250138 Responds to NRC 830726 ltr re violations noted in IF lnsp Repts 50-259/83-11, 50-240/83-11 & 50-276/83-11 Corrective actions radiochemical lab manual revised to incorporate Reg Guide 4 15 interim guidance MILLS, L. M Tennessee Valley Authority 83/08/16 O'REILLY, J P Region 2, 0ffice of Director 3pp 20877 273 24X Fiche 50-259,83/10/07.8310250131

- 8310250234 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-28, 50-260/83-28 & 50-294/83-28
 VERRELLI, D.M. Division of Project & Resident Programs B3/10/07 PARRIS. H.O. Tennessee Valley Authority ip 20099 123 24X
 Fiche 50-259,83/10/07,8310250234
- --B310250240 Responds to NRC B30901 ltr re violations noted in IE Imap Repts 50-259/83-28,50-260/83-28 & 50-296/83-28 Corrective actions requirements for recript imap of GA-level mat1 established & wire brushes marked MILLS.L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 4pp 20899 124 24X Fichs 50-259,83/10/07,8310250234
- --8310250247 Forwards IE Insp Repts 50-259/83-28,50-260/83-28 & 50-276/83-28 on 830725-27 & 0808 & notice of violation LEWIS,R C Division of Project & Resident Programs 83/09/01 PARRIS,R G Tennessee Valley Authority 2pp 20897 128 24 Fiche 30-257,83/10/07,8310250204
- ~-8310250259 IE Insp Repts 80~259/83~28, 90~240/83~28 & 50~294/83~28 on 830725~29 & 0808 Noncompliance noted failure of receiving insp to control welding filler matls & to establish positive controls for tools used on austenitic steel COLEV.J L Region 2. Office of Director BLAKE.J J Division of Engineering & Operational Programs 83/08/29 7pp. 20899 132 24X Fiche 50~259,83/10/07,8310250234
- G30B300799 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11.B30B300759
- 8308300761 IE Info Natice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Byr list enti JORDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83710/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11.8308300741
- 8310170189 Forwards IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-296/83-37 on 830927-30 No noncompliance noted VERRELLI,D Division of Project & Resident Programs 83/10/12 PARRISH O Tennessee Valley Authority 2pp 20786 358 24X Fichs 50-259,83/10/12,8310170189
- --8310170238 IE Safeguards Insp Repts 50-259/83-37, 50-260/83-37 & 50-276/83-37 on 830927-30 No noncompliance noted Major areas inspected security organization & mgt & personnel response. Details withheld (ref 100FR73 21) MODRE, D E . MCQUIRE, D R . Region 2, Office of Director. 83/10/11. 1p 20786 360 24X Fiche 50-259, 83/10/12, 8310170189
- 8310210071 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-26, 50-260/83-26 & 50-296/83-26
 D'REILLY, J.P. Region 2. Office of Director 83/10/17 PARRIS, H O Tennessee Valley Authority 1p 20858 192 24X Fiche 50-259,83/10/17,8310210071
- --831021007B Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-259/83-26,50-260/83-26 & 50-296/83-26 Corrective actions withheld (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 83/09/30 O'REILLY, D P. Region 2, Office of Director ip. 20858 193 24X Fiche 50-259,83/10/17,8310210071
- R Periodic operating reports & related correspondence
- 8310190186 Monthly operating repts for Aug 1983 W/830909 ltr THOM.T. JONES.O T Tennessee Valley Authority 83/09/01 of Resource Management, Director 40pp, 20820 163 24X Fiche 50-259.83/09/01.8310190186 Office
- 8 Reportable occurrences, LERs & related correspondence
- 8310210327 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE DWH/4 rated at 2,436 MW Forwards App A documents Documents also available in FDR FELTON, J M Division of Rules and Racords 83/07/28 HAFNER, B. Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000.83/07/28,8310210327
- --B302180539 Discusses results of evaluation of LERs for Jul 1981 Dec 1982.for SALP rept Quality & quantity of LERs within range of average BHR facility SEYFRIT.K V Reactor Operations Analysis Branch 63/02/09 or average use facility
 SEYFRITIK V Reactor Operations Analysis Branch 83/02/09
 LEMIS.R C Division of Project & Resident Programs. 3pp
 20882 257 24% Fiche 50-000,83/07/28,8310210327

DOCKETED ITEMS

- E310030376 Telecopy RO on E30719, Surveillance 4 7 A 2 G3 determined leakage rates exceeded for MSIV lines A.C & D Caused by leakage past main valve seat Beating surfaces modified JONEB.G T Tennessee Valley Authority E3707/20 Region 2. Office of Director 1p 20592 142 24x Fiche 50-296.E3/09/20. E310030376
- B310060377 LER 83-054/01T-0 on B30919, during refueling outage, while performing leakage test, combined leakage of MSIV lines A.C & D exceeded limit Caused by 26-inch global valve leaking past main seat Valve repaired W/B30929 ltr HOLDER, E.T. GREEN, H.J. Tennossee Valley Authority 83/09/29 O'RETLLY, J.P. Region 2, Office of Director 3pp 20646 062 24X Fiche 50-296, 83/09/29, 83100603/7
- 8310060407 LER 83-053/03x-0 on 830931.hudrogen analyzer declared inoperable due to loss-of-flow light 76-8 Caused by moisture collection in sample lines Lines blown down & dried Sys restored M/830929 ltr GOODHIN,D C. GREEN,H J. Tennessee Valley Authority 83/09/29 O'REILLY,J.P. Region 2, Office of Director 3pp 20641 260 24x Fiche 50-296,83/09/29,8310060407
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EliOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
 BERBERIAN.M J Foxboro Corp 83/09/30 Director's Office. Office of Inspection and Enforcement lipp 20651 044 24X
 Fichs 50-000,83/09/30,8310070301
- 8310250065 PNO-II-03-084 licenses identified & reported to NRC that contractor welding swc employee received 59 mem occupational overexposure during Third Guarter 1963 Licensee reviewing all circumstances associated w/event DEBS, B Region 2, Office of Director 83/10/20 ip 20896 085 24X Fiche 30-259,83/10/20,8310250065
- DOCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- 8310180156 Forwards IE Insp Rept 50-298/83-11 on 830509-13 No noncompliance noted MADSEN.O L. Region 4. Office of Director 83/07/00 PILANT.J M Nebraska Public Power District 2pp 20807 083 24X Fiche 50-298,83/07/08.8310180156
- --8310180161 IE Insp Rept 50-298/83-11 on 830509-13 No noncempliance mated Major areas inspected radiation protection program during refueling, including procedures, advanced planning & preparation, training, exposure control & ALARA program BAER, R. E. MURRAY, D., HESTERMAN, J. F. Region 4, Defice of Director 83/06/28 11pp 20807 085 24X Fiche 50-298,83/07/08,8310180136
- ~~8310070393 Exemption from certain JOCFR50 App A & JOCFR50 48 requirements for 3 h fire-rated boundaries for separation of fire area EIBENHUT.D 0 Division of Licensing 83/09/21 Nebraska Public Power District 12pp 20681 012 24X Fichs 50~298.83/09/21.8310070391
 - 0180225 Forwards IE Insp Rept 50-298/83-18 on 830701-0831 & notice f violation
 ADSEN, G L Region 4, Office of Director 93/09/22 PILANT. J M
 ebrasia Public Fower District 2pp 20808 259 24X
 iche: 50-298, 83/09/22, 8310180225
 - #310180228 Notice of violation from insp on 830701-0831 # Region 4, Office of Director 83/09/22 ip 20808 261 24% Fich# 80-298.83/09/22.8310180825

- 8310200350 forwards advance notification documentation of shipments of spent nuclear fuel to GE Morris Operation after mid-Oct & per 10CFR73 21 regulations governing safeguards life PILANT, J M Nebraska Public Power District 83/09/26 COLLINS, J Region 4. Office of Director KEPPLEN, J G Region 3. Office of Director KOMMETSCHER, E Nebraska State of 9pp 20874 261 24% Fiche 50-298,83/09/26,8310200750
- B310030358 Urges aggressive purbuit of corrective actions to energency plan items vital to safety (identified in Enforcement Action 82-16), including 1tem LP-1 re empryency planning coordinator COLLING, UT Region 4, Office of Director 63/09/28 SHAUFEL MEMORY Nebrasks Public Power District 2pp 20592 331 24X Fiche 50-298,83/09/28.8310030398
- B310310279 Forwards IE Insp Rept 50-298/8J-21 on B30821-24 No moncompliance noted JBHNBON,E H. Region 4, Dfficr of Director B3/10/14 P1IAN1,J N Nebraska Public Power District 2pp 20941 290 24X Fiche 30-298,63/10/14.83103102/9
- --B310310286 IE Insp Rept 50-298/B3-21 on 830821-26 No noncompliance noted Major areas inspected public info & emergency worker protection portions of emergency response program HACKNEY, C A . NAIRD, J B . HUNNICUFF, D M Region 4. Office of Director B3/10/14 5pp 20961 292 24X Fichs 50-298/B3/10/14, 6310310279
- 8310210302 Forwards Rev 3 to implementation schedule in 830415 response to Generic Ltr 82-33 Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability "
 WEAVER. J D Nebraska Public Power District 83/10/18 SIEGEL. U
 Operating Reactors Branch 2 Spp 20851 061 24%
 Fiche 50-298,83/10/18.8310210302
- P Operating license stage documents & correspondence
- 8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER. L. Affiliation Unknown 83/05/02 NRC No Detailed Affiliation Given Ip 21004 270 24% Fiche 50-000.63/05/02 B310310017
- 8310.310.031 Responds to FDIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be place in PDR & list of facilities for which repts are unavailable FELTON, J M Division of Rules and Records 83/07/06 CONNEQ.L Affiliation Unknown ip 21004 271 24X Fichs 50-000, 83/07/06, 8310310031
- --8310310056 "Reactor Containment Bldg Integrated Leak Rate Test" * Nebraska Public Power District 76/11/30 250pp 21004 272 24X Fiche 50-000, 83/07/06, 8310310031
- 8310110178 Proposed Tech Spec Change 5 to License DPR-46, allowing relief from inservice insp requirements of IOCFR50 55a(g) KUNCL.L O Nebraska Public Power District 83/09/26 VASSALLG.D N Operating Reactors Branch 2 3pp 20665 015 24% Fiche 50-298,83/09/26,8310110178
- --8310110183 Proposed Tech Spec changes, allowing relief from inservice inspiraquirements of 10CFRSO 55a(g)

 * Nebraska Public Power District 83/09/26 App 20665 018 24% Fiche 50-298, 83/09/26. 8310110178
- 8310040574 Requests extension to 831101 to meet shift manning criteria of 10CFR50 55 Currently util meets licensed operator criteria on five-shift basis In order to effect improvement in crew training, six-crew rotating shift desired PILANT, J M Nebraska Public Power District 83/09/30 VASSALUB, D B Operating Reactors Branch 2 3pp 20622 275 24X Fiche 50-298,83/09/30,83100405/4
- B310130106 Forwards safety evaluation supporting uti) response to TMI Item II D i. "Safety & Relief Valve Testing " Issue resolved VASSALLO,D D Operating Reactors Branch 2 83/07/30 PILANT, J M Nebraska Public Power District 17pp 20/77 027 24X Fiche 50-298.83/09/30.9310130106
- 8310180569 Forwards exemption from schedular requirements of 1007R50 49 re environ qualification of electrical equipment, per 830624 request VASSALLO, D 8 Operating Roactors Branch 2 83/10/03 KUNCL, L 8 Nebraska Public Power District 2pp 20827 110 24X Fiche 50-298,83/10/03,8310180967

- ~~8310180572 Exemption from schedular requirements of IOCFR50 49 re environ qualification of electrical equipment CASE.E G Office of Nuclear Reactor Regulation, Director 83/10/03 Nebiaska Public Power District 4pp 2082/112 2/4y Fiche 50-298 83/10/03.8310180569
- 8310140190 Informs that splice repairs completed on essential systems of the splices of the splices removed to new splices covered w/snvironmentally qualified heat shrinkable tubing at the splices of t
- B310210101 Informs of decision to refund fee submitted w/B304,9 application for extension of completion date for installation of Mork I mods
 MILLER, W O License Fee Management Branch B3/10/17 PILANE, J N Nebraska Public Pawer District 2pp 20083 321 24X
 Fiche 50-298,83/10/17,8310210101
- G Inspection reports, IE Bulletins & correspondence
- 9310180156 Forwards IE Insp Rept 50-298/83-i1 on 930509-i3 No moncompliance noted MADSEN.G L. Region 4. Office of Director 83/07/08 PILANT, J M Nobraska Public Power District 2pp COB07 083 247 Fiche 50-298,83/07/08,8310180156
- --83:0180161 IE Insp Rept 50-298/83-11 on 830509-13 No noncompliance noted Major areas inspected radiation protection program during refueling including procedures advanced planning & preparation, training, exposure control & ALARA program BAER, R E . MURRAY, B . MESTEMMAN, I f Region 4, Office of Director 83/06/28 11pp 20807 085 24X Fiche 50-298, 83/07/08, 8310180156
- B31004034B Forwards response to recommendations presented in LRS Consultants. Inc rept re appraisal of site & corporate nuclear mpt organizations & functions, per B20809 order modifying license

 SCHAUFELBERGER Nebraska Public Power District 83/08/15

 SCHLINS. J T Region 4, Office of Director 38pp 20620 1/7 24X

 Fiche 50-298, 83/08/15.8310040248
- 8310130206 Forwards IE Insp Rept 50-298/83-22 on 830826-27 No noncompliance noted MADSEN, C.L. Region 4. Office of Director 83/09/13 PILANT, J M Nebraska Public Power District 2pp 20/25 012 24X Fiche 50-298,83/09/13,8310130206
- --8310130211 IE Insp Rept 50-29H/83-22 on 830826-27 No noncompliance noted Major areas inspected performance of containment integrated leak rate test & independent review of test results
 HUNNICUTT.D M , HALLER E , MADSEN.Q L Region 4, Diffice of Director 83/09/12 4pp 20725 014 24X Fiche 50-298.03/09/13, 8310130206
- 9310310310 Confirms BALP 831004 meeting in Columbus NE MUNCLL 0 Nebraska Public Power District 83/09/16 COLLINS J T Region 4, Office of Director 1p 20961 171 24X Fiche 30-298 83/09/16 8310310310
- 9310180225 Forwards IE Insp Rept 50-298/83-18 on B30701-0831 & natice of violation HADSEN, 6 L. Region 4. Office of Director B3/09/22 PILANI, J N Nebraska Public Power District 2pp 20808-259 24X Fithe 50-298.83/09/22.8310180225
- --8310180228 Notice of violation from insp on 830701-0831 * Region 4. Office of Director 83/09/22 ip 20808 261 24X Fiche 50-298,83/09/22,8310180225
- --8310(80202 IE lnsp Rept 50-298/83-18 on 830701-0831 Noncompliance noted failure to assure integrity of fire barrier penetration seal DUBOIS.D.L. HUNNICUTT.D M Region 4, Office of Director 63/09/22 8pp 20808 262 24% Fiche 50-298.83/09/22.8310180225
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Cn of New York, Inc 117pp 20754 022 24% Fiche 50-000,03/09/26,0/00/00340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant foxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 (onsolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000.83/09/24.8308300342

- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Lamergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24% Fiche 50-000,83/09/26,8308/00345
- B310110178 Proposed Tech Spec Change 5 to License DPR-46, allowing relief from inservice insp requirements of 10CFR50 55a(g) KUNCL, L G Nebraska Public Power District B3/09/26 VASSALLO, D B Operating Reactors Branch 2 3pp 20645 015 24X Fiche 50-298, 83/09/26, 83101101/8
- --8310110183 Proposed Tech Spec changes, allowing relief from inservice insp requirements of 10CFR50 55s(g)

 * Nebraska Public Power District 83/09/26 6pp 20665 018 24% Fiche 50-298, 83/09/26, 8310110178
- 831003035B Urges aggressive pursuit of corrective actions to emergency plan items vital to safety (identified in Enforcement Action 82-16), including Item EP-1 re emergency planning coordinator CULLINS.J T Region 4. Office of Director 83/09/28 SHAUFELBERSCK Nebraska Public Power District 2pp 20592 331 24X Fiche 50-298,83/09/28,831003035B
- 8308300349 IE Info Notice 83-44. "Lead Shiolding Attached to Safety-Related Sys W/o 10CFRSO 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8310180471 Provides followup response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," Item 5 Detailed insp of svc water check valve internals showed traces of rust on seating surfaces KUNCL.L G Nebraska Public Power District 83/09/30 COLLINS, J 1 Region 4. Office of Director 2pp 20002 026 24% Fiche 50-298,83/09/30,8310180471
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Dypass Loops Used in Westinghouse Plants " Svt list encl JURDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24x Fiche 50-000,83/10/07.8308300752
- 8308300757 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxidus Gases " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 832/10/11 Consolidated Edison Co of New York, Inc 117gp 21043 075 24X Fiche 50-000.83/10/11.8308300757
- 9308300761 IE Info Notice 63-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " 8vc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 93/10/11 Consolidated Edison Co of New York. Inc 120pp 20927 127 24X Ficha 50-000,83/10/11,8308300761
- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps Fp1 intergranular stress corrosion cracking MIRAGLIA,F J Assistant Director for Safety Assessment 83/10/14 EISENBUT, D 9 Division of Licensing 5pp 20823 358 24X Fiche 50-000,83/10/14.8310180551
- 8310310279 Forwards IE Insp Rept 50-298/83-21 on 830821-26 No noncompliance noted JOHNSON, E H. Region 4. Office of Director 83/10/14 PILANT, J M Nebraska Public Power District 2pp 20961 290 24X Fiche 50-298,83/10/14,8310310279
- --8310310286 IE Insp Rept 50-278/83-21 on 830821-26 No noncompliance noted Major areas inspected public info & emergency worker protection portions of emergency response program HACKNEY, C A , BAJRD J B , HUNNICUTT, D. M Region 4, Office of Director 83/10/14 5pp 20961 29% 24% Fiche 50-298,83/10/14,8310310279
- R Periodic operating reports & related correspondence
- B310170024 Monthly operating rept for Aug 1783 H/830708 lti BALLINGER.P L . THOMASON.P V Nebraska Public Power District B3/09/08 NRC - No Datailad Affiliation Given 5pp 20822 049 24% Fiche 50-298, B3/09/08, B310170024

6 Reportable occurrences, LERs & related correspondence

- 8310060376 Forwards LER 83-013/03L-O Detailed event analysic encl THOMASON, P. V. Nebraska Public Power District 83/09/27 THOMASON, P. V. Netrocke Public Power District 83/09/27 COLLINS, J. T. Region 4, Office of Director App. 20646 087 24X Fiche 50-298,83/09/27,831006001/6
- --8310060381 LER 83-013/03L-0 on 830831 during local leak rate Procedure 6 3 I 1.20, penetrations found leaking erressively Caused by discs & seats being lapped Valves repaired MALKEN, HA Netraska Public Power District 83/09/27 Region 4, Office of Director 1p 20646 089 24X Fichs 50-298.83/09/27,
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EliOM transmitter Underrange zero offset may occur when transmitter underly pressurized from atmospheric to suppressed zero input End users notified

 BERBERIAN.M J Forboro Coip 83/09/30 Director's Office, Diffice of Inspection and Enforcement | Tipp 20651 064 24X Fiche 50-000,83/09/30,8310070301
- 8310210174 LER 83-014/03L-0 on 830915 during surveillance testing-pressurization of suppression chamber dir space noted during HPCI turbing operation Caused by error in vacuum breaker design/installation Breaker replaced W/201012 ltr MACE,E M . THOMASON.P V Nebiaska Public Power District 83/10 COLLINS.J T Region 4. Defice of Director 3pp 20855 123 2 Fiche 50-298,83/10/12.8310210174

V Operator Examinations

8310040574 Requests extension to B31j01 to meet shift manning criteria of 10CFR50 59 Currently util meets licensed operator criteria on five-shift basis in order to effect improvement in crew training, six-crew rotating shift desired PILANT. J N Nebraska Public Power District B3/09/30 VASSALD. D B Operating Reactors Branch 2 3pp 20622 275 24X Fiche 50-278,83/09/30,8310040574

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans

- B310030141 Advises that B20715 & 0930 requests for NRC to concut w/intent to move emergency support ctr & associated functions from Point Beach Energy Info Ctr to Milwaukee unacceptable, per NUREG-0737, Suppl 1 & Generic Ltr 82-3,3 EISENHUT.D Q Division of Licensing 83/09/14 DURBIEIN, S Wisconsin Electric Power Co App 20604 033 24X Fiche 50-266,83/09/14.8310030141
- 310030609 Releases public version of revised emergency plan implementing procedures FELICON. J M Division of Rules and Records 83/09/20 Datum Management Branch ip 20607 036 24X Fiche 50-266.83/09/24. Documen t Management Branch 8310030609
- -8310030616 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP 1 3 re estimation of source term. EPIP 1 4 re radiological dose evaluation & EPIP 6 2 re plant evacuation FAV.C W Histonsin Electric Pawer Co 83/09/19 DENTON. H R Office of Nuclear Reactor Regulation, Director 1p 20607 03/24X Fiche 50-266.83/09/28.8310030607
- --B310030624 Public version of revised emergency plan implementing procedures including Procedures EPIP 1 3 re estimation of source term.EPIP 1 4 re radiological dose evaluation & EPIP 6 2 re plant evacuation **

 * Hisconsin Electric Power Co 83/09/09 241pp 20607 03B 247 Fiche 50-266.83/09/28,8310030609
- 3310210044 Responds to B30914 ltr denying concurrence w/util plans to move emergency support ctr from lwo Creeks, WI to corporate headquarters in Milwaukee, approx 100 miles from facility Potential problems overstated by NRC BURSTEIN. S Wisconsin Electric Power Co 83/10/14 EISENNUT, D G Division of Licensing 2pp 20855 315 24X Fiche 50-266, 83/10/14, 8310210044
- 8310310370 Forwards revs to modified amouded security plan Revs withheld (ref 10CFR73 21 & 2 790) BURSTEIN,S Histonsin Electric Power Co B3/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20961 111 Fiche 50-266.83/10/24.83103103/0

G Adjudicatory correspondence

- B310070156 Forwards Director's Decision B3-14, denying B30709 10cH2 706 petition re transport of spent nuclear fuel from Hest Vallry
 DAVIS.J G Office of Nuclear Material Safety & Safeguards. Director 83/09/30 CELEBREZZE, A J Ohio, State of 2pp 20680 300 247 Fiche 50-000,03/09/30,8310070156
- --B3100/0161 forwards Director's Decision 83-14, denying 830824 foot RD ,406 petition re transport of spent nuclear fuel from West Valley DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 83/09/30 RESNIKULF, M Sierra Club Ip 20680 309 P47 Fische 50 000, 83/09/30, 8310070156
- --831007016/ Notice of issuance of Director's Decision 89-14, denying State of ON & Bierra Club 830909 & 02-4, respectively.

 10CFR2 206 petitions re transport of spent nucleur fuel from DAVIS, J G Office of Nuclear Naterial Safety & Safeguards, Director 83/07/10 Ppp 20480 310 747 Fich 30-000, 83/07/30, 83100/015-6
- --8310070171 Director's Decision 83 14 denying State of GH & Sierra Club 830909 & 0824, respectively, 1001 82 206 petitions 10 transport of spent nucleor fuel from West Valley Request fm hearing & for preparation of 6.3% denied DAVI5.J G Office of Nuclear Material Safety & Safequards, Director 83/09/JO 18μμ 20690 31. 24X Fiche 50-000, 03/09/JO, 83100/0156
- 8310110274 Informs that licensee will file response to Wisconsin Environ Becade Inc potition served on 830923 by 9J101/ Svc list enci list enc)
 CHURCHILLO W Show, Pittman, Potts & Troubridge CHURCHILLO W
 Wisconsin Electric Power Co B3/10/07 CHILKS J Diffice of the
 Secretary of the Commission 4pp 20866 200 24X
 Fiche 50-286-03/10/07/83/1010/7
- B310170493 Answer in apposition to Misconsin Environ Decade 8,0923 petition for review of ASLAB 830907 Decision ALAB-7.39, affirming ASLAB 830204 authorization for issuance of license amend Issue not raised before ASLAB Certificate of Svc oncl BACHHANN.R G Hearing Branch 1 B3/10/11 Commissioners 14 20784 123 24X Fishe 50-266.83/10/11.8310170493
- 8310200102 Response opposing Wirconsin Environ Decade 930923 petition for review of ALAB-739 resteam generator tubes repaired by sleeving Nexus between sleeving & tube failure shown Certificate of Svc enri Certificate of Svc enri CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge #3710/17 Commissioners 13pp 20836 350 24% Ficho 50-266.83/10/17.8310800102
- 8310170071 Order extending time until BJ1101 for Commission to act to review Director's Decision DD 83-13 CHILK-8 J Office of the Secretary of the Commission 83/10/18 Commissioners in 20822 265 24X Fiche 50-266,0J/10/18, B310170071
- 8310260241 Order extending time until 831123 for Commission to act to review ALAU-737 CHILK-5 J Dffice of the Secretary of the Commission 83/10/24 Commissioners Ip 20909-866 247 Fiche 50-266-83/10/24 8310260241
- 831027029/ Order extending time until 83112H for Commission to act to review Director's Decision DD-83-14. denying Sierra Club & State of OH requests
 CKILK, 8 J Office of the Secretary of the Commission 09/10/25
 Commissioners Ip 20723 19; 24X Fiche 50-000, 83/10/25, 8310270297

J Insurance & indemnity information

- B310110187 Forwards Endorsement 59 to MATLU Policy MI-53 & Endorsement 72 to NECIA Policy NF-178
 DUNDAB; WI J Wisconsin Electric Pawer Co 83/10/03 NKC No Detailed Affiliation Given 3pp 20655 011 24X
 Fiche 50-266,83/10/03,8310110187
- P Operating license stage documents & correspondence
- 8310110930 "Assessment of Radiation Risks," util-medical dialogue presented at 800922-23 Intl lost of Salety & Health forum in Wathington DC LAPP.R L International Institute of Safety & Health 80/09/당 92pp 20714 161 24X Fiche 50 (200,80/09/23,8310110530

- B310270555 Forwards safety evaluation supporting design of reactor coolant vent sys per requirement of locable 44(c)(j)(jii) & NUREG-0737, Item II B I Operating Reactors Branch 3 83/09/22 FAY.C W MILLER, J.R. Operating Reactors Dranch 3 63/09/22 Historian Electric Power Lo. /pp. 20744 003 247 Fiche 50-266.03/09/22.83102/05/29
- #310040310 Forwards add1 info requested in #30810 teleon re Franklin #Assearch Ctr #3061/ draft technical evaluation rept on util response to Phose 1 of NURIC -061P, "Continl of Heavy Loads at Nuclear Fower Plants" at Nuclear Power Plants '
 FAY.C N Wisconsin Electric Power Co 83/09/28
 Office of Nuclear Reactor Regulation, Director MI
 Operating Reactors Branch 3 Epp 20413-096 247
 Fische 50-266.03/09/28.8310040410 MILLER, J R
- B31006056B Requests remittance of Class III fee for review of EU070R application for Tech Spec change re component cooling HX imap & maint program
 HILLER, W.O. License Fee Monagement Branch 83/07/30 IAY, C.W.
 Hisconsin Electric Power Co. 1p. 20661 247 247
 Fiche 50-301.63/07/30.8310060560
- B310130052 Formalds Amends 74 & 79 to Licenses DPR-24 & DPR-21, respectively & safety evaluation Amends revise degraded grid voltage relay setpoint & associated time delay in Table 15 3 5-1 of Tech Specs COLBURN, T G Operating Reactors Brench 3 83/09/30 fAY.C W Histomasin Electric Power Co 2pp 20/76 220 247 Fiche 50-246.83/09/30.8310130052
- -8310130096 Amends 74 & 79 to Licenses DPR-24 & DPR-27, respectively. revising degraded grid voltage relay setpoint % associated time delay in Table 15 3 5 1 of Tech Specs MILLER.JR Decreting Reactors Branch 3 83/09/30 6pp 20776 222 24X Fiche 50-266, 03/09/30, 0310130052
- --8310130062 Gafety evaluation supporting Amends 74 & 79 to Licenser DPR-24 & DPK-27, respectively * Office of Nuclear Reactor Regulation, Director 03/09/30 & 20776 228 24X Fiche 50-266.83/09/30.8310130052 03/07/30 Opp
- B310240116 Forwards Amends 7/ % 8) to ticenses DPR-24 & DPR-24, respectively & safety evaluation Amends revise Tech Specs to permit location of spent Puel pool neutron absorber surveillance specimen adjacent to divider wall COLBURN.T @ Operating Reactors Branch 3 B3/10/05 JAY, (W Hasconaim Electric Power Co 2pp 2089) 338 249 Fiche 50-266.83/10/05.8310240116
- --8310240122 Amends 77 & 81 to 1 icenses DPR-24 & DPR-27, respectively. revising Tech Specs to permit location of spent fuel pool nuetron absorber surveillance specimen adjacent to spent fuel pool divider wall MICLER, J.R. Opriating Reactors Branch J. 83/10 20871 340 24X Fiche 50-266,83/10/05,8310240116 83/10/17 7pm
- --8310240125 Safety evaluation supporting Amends 7/ & 81 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation, Director 03/10/05 3 20891 347 24X Fiche 50-266,83/10/05,8310240116 03/10/05 366
- 8310130199 Forwards Amends 76 & 80 to Lirenses DPR-24 & DPR-27, respectively & Safety evaluation Amend clarifies terminolopy used in limiting condition for operation & language reperiodic calibi interval requirement COLBURN-T Q Operating Reactors Branch 3 83/10/06 FAY.C Wisconsin Electric Power Co. 2pp. 20777 195 24X Fiche 30 266.87/10/06.8310130199 83/10/06 FAY.C W
- --6310130202 Amends 75 % 80 to Licenses DPR-24 & DPR-27, respectively, AIDIADAR Amends /5 & 80 to Licenses DMR-24 & DMR-2/, ret making administrative changes to Tech Specs to clarify terminology used in limiting condition for operation & language re periodic calibr interval requirement MILLER, J. R. Operating Reactors Branch 'S 83/10/06 20777 197 24X Fiche 50 266,03/10/06,8310130199 83/10/06 10pp
- --8310130,705 Safety evaluation supporting Amends 76 & 80 to Licenses DPR-24 & DPR-27, respectively * Office of Nuclear Reactor Regulation, Director 63/10/06 2pp 20/77 20/ ,*4X Fiche 50-266,83/10/06.8310120199
- B310180490 Application to amend Licenses DPR-24 & DPR-27 modifying Tech Spec Change Request 33 reflecting changes in effluent monitoring instrumentation reculting from recently installed improved radiation monitoring tys

 FAY.C W Histonian Electric Power Co 83/10/07 DLNION.H R

 Bffice of Nuclear Reactor Regulation, Director 3pp 20/99 114

 24X Fiche 50-266.83/10/07.8310180490

- -8310180492 Proposed radiological effluent Tech Specs reflecting mode to radiation monitoring sys # Wisconsin Fictoric Power Co 83/09/30 47pp 20799 117 P4X Fiche 50-266 83/10/07.8310180490
- --8310180495 Rev 0 to "Offsite Dase Calculation Manual" * Wisconsin Flectric Power Co 83/09/30 Abpp & Fiche 50-266.83/10/07.8310180490 20799 161
- --8310180499 Rev 2 to "Environ Monitoring Manual"

 * Wisconsin Flectric Power Co 82/06/30 33pp 20799 229 24X
 Fiche 50-266.83/10/07.8310140490
- 8310280098 Confirms arrangements for NRC site visit on B31101-03 to obtain add1 info to complete evaluation of inservice testing program for pumps & valves
 MILLER, J R Operating Reactors Branch J 83/10/07 FAY.C W Wisconsin Electric Power to 2pp 20/61 360 24X Fiche 50-266,83/10/07,8310280090
- 8310130004 Discusses 831013 meeting to resolve deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment Agenda & supporting decimentation end!

 BURSTEIN.S Wisconsin Electric Power (o 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 30pp 20/26 207 24X

 Fiche 50-266, 83/10/10, 8310130004
- 8310180421 Informs of proposed minor changes to commitments made in response to implementation instructions of NUREO-05/8, re short-term lessons learned Duby technical advisor quarters will be incorporated in boundary control ctr FAY, C W Hisconsin Electric Power Co 83/10/10 DENION. H R Office of Nuclear Reactor Regulation. Director Rpp 20803 306 24X Fiche 50-266,83/10/10.8310180421
- 83i0170079 Notification of 83i013 meeting w/util in Dethesda, MD to discuss method for achieving final qualification of safety-related electrical equipment Final rept will be issued based on meeting results.
 COLBURN.T G. Operating Reartors Branch 3 83/10/11 MILLER, J.R. Operating Reartors Branch 3 83/10/11 MILLER, J.R. Fiche 50-246, 83/10/11, 8310170077
- 8310200202 Forwards addl review & approval fees re 830708 application concerning Tach Spec Change Request 92 on component cooling HX FAY.C W Wisconsin Electric Power Co 83/19/14 DENION.H R Office of Nuclear Reactor Regulation. Director MILLER.W D licen Fee Management Branch Ip 20834 126 24% Fiche 50-301.83/10/14. 83102002027 License
- 8310280147 Forwards 830930 Director's Decision 83-14, denying State of OH & Sierra Club JOCFR2 206 petitions re transportation of spent fuel from West Valley Fucility, per 830930 request CUNNINGHAM, R C Division of Fuel Cycle & Material Safety 83/10/11 MILLER, F Environmental Policy Institute 2pp 20961 3,99 24X Fiche 50 000, 83/10/18, 8310280147 83/10/10
- @ Inspection reports: IE Builetin: & correspondence
- 8308300340 IE Info Notice 83~61. "Alleged Use of Stand Ins for Welder Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Propercioness & Engineering Response (Post 830103) 83/09/25 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,03/09/26.8308000340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventslation Air Intakes " Byo list enci JORDAN, E L Division of Emergency Freparodness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pg 20777 210 24X Fiche 50-000,83/09/26,8308300341
- 8308300345 IE Info Notice 83-63. "Patential Failures of Westinghouse Type SA-I Differential Relays" SVC list encl JORDAN, E.L. Division of Emergency Freparednoss & Engineering Response (Post 830103) 8J/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24% Fiche 50-000,83/09/26,8308300345
- 8310030447 Forwards list of Ray Miller products installed at facilities, in response to IE Bulletin 83-07 Investigation of subtier suppliers in progress FAY, C. W. Wiscomain Electric Power Co. 83/09/26 KEPPLER, J. G. Region 3, Office of Director. App. 20601 03B 24X Fiche 30-266, 83/09/26, 8310030447

- 8310120089 Responds to IE Info Notice 83 01 % IE Bulletin 83 07 reinvestigation of applicability of Ray Miller. Inc fraudulcht practices identified items have no adverse safetu significance List of installed products encl
 FAY.C W Wisconsin Electric Power Cu 83/09/26 KEPPLER. J c
 Region 3, Office of Director App 20696 187 24%
 Fiche 50-266 83/09/26.8310120087
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evalvation " Svc list and! JORDAN. C.L. Division of Emergency Pregaredness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24X Fiche 50-000.83/09/29.8303300.447
- 8310060568 Requests remittance of (lass lll fee for review of 870408 application for lech Spec change re component cooling HX insp & maint program HILLER.W O License Fee Management Branch 83/09/30 FAY.(W Wisconsin Electric Power Co ip 20261 247 24X Fiche 50-301.83/09/30.8310060368
- 8310240001 Forwards IE Mgt Meeting Rept 50-301/83-11 on 83082/ & notice of violation from insp on 830601-0/31 NORELIUS, C.E. Division of Project & Resident Programs 83/10/05 BURSTRIN,S Wisconsin Electric Fower Co. 2pp. 20880 342 24% Fiche 50-301,83/10/05.8310240001
- --8310240002 Notice of violation from insp on 830801-0/31 NORELIUS, C E Division of Project & Resident Programs BJ/10/05 ip 20880 344 24% Fiche 50-301.83/10/05.8310248001
- --8310240003 IE Mgt Meeting Rept 50-301/83-11 on 8308/2 Items discussed concerns re noncompliance involving licensee exceeding limiting conditions for operation re inoperable radiation monitors

 MAGUE, R. L., JACKIH, I. N. Region 3, Office of Director GJ/10/04

 3pp 20880-345 24X Fiche 50-301,83/10/05,8310240001
- 8308300378 [E Info Notice 83-65, "Surveillance of Flow in Alb Bupass Loops Used in Hostinghouse Plants " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 8301031 83/10/07 Convolidated Edison Co of Not York, Inc. 76pp 20827 213 24X Fiche 50-000.83/10/07.83083007/8
- #308300752 IE Info Notice #3-64. "Fatality at Argentine Critical Facility " Byo last end!
 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post #30103) #3710/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24% Fiche 50-000.#3/10/07.#2083007(2)
- 8308300759 JE Info Notice 83-47. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 837/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000, 63/10/11, 6308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enc!
 JORDÁN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison (a of New York, Inc. 120pp 20827 129 E4X Fiche 50-000, 83/10/11. 830830076)
- 9310180261 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be provided to Region III personnel listed in encl Update will be provided every 6 months AXELSON.W L. Region 3. Office of Director 83/10/14 BURSTEIN.S Wisconsin Electric Power Co. 7pp. 20002 275 PAX Fiche 50-266.83/10/14.8310180261
- 8310270294 Forwards | E Insp Repts 50-266/83-17 % 50-401/83-16 on 830808-0922 % notice of violation PAPERIELLO.C J. Region 3. Office of Director 83/10/14 BURSTELLO.S Wisconsin Electric Power Co. 2pp. 20923 196 24% Fiche 50-266,83/10/14.8310270294
- --8310270303 Notice of violation from insp on 830800-072P PAPERICLLO,C J Region 3, Office of Director 83/10/13 lp 20923 198 24% Fishe 50-266.83/10/14.8310270294
- --8310270313 IE Insp Repts 50-266/83-17 & 50-301/83-16 on 830806 07% Noncompliance noted failure to perform appropriate contamination survey of radioactive maths shipment LOVENDALE, P.C., PAUL, R.A., HAGUE, R.L., Hegion 3, Office of Birector 83/10/12 8pp 20923 199 24X Fiche 50-266,83/10/14,8310270294

- 8310240042 Ack receipt of 83092/ ltr informing NRC of stips taken to correct violations noted in It Insp Repts 50-266/83 13 % 50-301/83-13 Fuel handling training must be completed by 831201
 SHAFER,W D Region 3, Office of Director 83/10/18 BURSIEIN,S Wisconsin Electric Fower Co. 1p. 20081 #48 24X
 Fiche 50-266, 63/10/18, 8310240042
- --8310240051 Responds to NRC BJ0829 it is eviolations noted in If Imp Repts 50-266/83-13 & 50-301/83-13 Corrective actions supervisor instructed on use of procedures & good engineering practices when operating refueling equipment CASSIDY, I J Wisconsin Electric Power Co BJ09/22 KEPPIER, J (Region 3, Dffice of Director Jpp 20881 349 24X Fiche 50-266,83/10/18.8310240042
- R Periodic operating reports & related (orrespondence
- S Reportable occurrences, LERs & related correspondence
- 8310060428 PNG-TII-83-089 on 830929, temporary restraining order requested to prevent shipment of spent reactor fuel thiough State of 8H denied Pretrial conference set for 831006 Local govts alleged inadequate preparation by local agencies STRASHA, J Region 3, Office of Director 8309730 Ppp 20641 221 24% Fiche 50-000,83707730,8310060428
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EilOM transmitter Underrange zero offset may occup when transmitter initially pressurized from atmospherize to suppressed zero input End users notified DERBERIAN.M J. Foxborn Corp. 83/09/30 Director's Office. Office of Inspection and Enforcement 1 Jpp. 20451-044 A4X Fiche 50-000.83/09/30.8310070301
- 8310170380 Updated LER 83-011/03X-1 on 830817.RHR pump EP108 declared inoperable due to high bearing vibration levels Unit placed in degraded mode Cause uncertain lailed pump replaced M/831005 ltr
 FAY, C W Wisconsin Electric Power Co 83/10/05 KEPPLER, J G Region 3, Office at Director 4pp 20785 012 P4Y Fishe 50-301.83/10/05.8310170380
- B310140255 PND-III-83-094 on 830930 contemination found on empty spent fuel cask shipped from facility (railer used to transport empty spent fuel casks experienced brake problems on 831005 All shipments under inter LOYENDALE.P. GREGER.L R Region 3, Office of Directul 83/10/06 2pp 20759 238 24% Fiche 50-246.83/10/06.8310140255
- V Operator Examinations
- 8310070303 Requests extension of effective date of compliance w/
 10CFR50 relicensed operator staffing to 871010
 FAV.C W Wisconsin Ciectric Power Co 83/07/30 NENTON.H H
 Office of Nuclear Reactor Regulation, Director 8pp 20691 070
 24X Fiche 50-266.83/09/30.8310070303
- DOCKET 50-302 CHYSTAL RIVER NUCLEAR PLANT. UNIT 3

 F. Security, medical. emergency & fire protection plans
- B310040466 Ack receipt of B30909 ltr informing NRC of steps taken to carrect violations noted in 1t Insp Rept 50-302/83-13 LEWIS.R C Division of Project & Resident Programs B3/09/2.J WILGUE,W S Flortda Power Corp ip 20623 100 24X Fiche 50-302,03/09/23,8310040466
- --8310040472 Responds to MRC 830810 ltr re violations noted in II Insp Rept 50-302/63-13 Corrective actions INPO contacted to request rapid dose assessment procedures which will be used as guidelines Procedure EM-204 will be revised by 831101 WEBTAFER, G.R. Florida Power Corp. 85/09/09 D'RCILLY, J.P. Region 2, Optice of Director. App. 20623 101 24X Fiche 50-302-83/09/23,8310040466
- --8310040475 Forwards IE Insp Rupt 50-302/83-13 on 830627-0701 & notice of violation LEWIS,R C Division of Project & Resident Programs 83/08/10 WILGUS,W S Florida Power Corp Spp 20623 105 247 Fiche 50-302,83/09/23,8310040464
- --8310040477 Notice of violation from insp on 830627-0701 * Region 2, Office of Director 83/08/10 lp 20623 107 PAX Fiche 50-302, 03/09/23, 8310040466

- --8310040480 IE Insp Rept 50-302/83-13 on 830627-0701 Noncompliance noted failure to establish procedure implementing emergency plan requirement for prompt notification HUFFMAN, G N Region 2. Office of Director JENKINS, G R Division of Emergency Preparedness & Naterials Safety 83/08/05 10pp 20623 108 24X Fiche 50-302 83/09/23,8310040466
- 8310040420 Confirms that technical support ctr designed to be continuously habitable for 30 days following post accident release described in Reg Guide 1 4.18ev 2.04d June 1774 Shielding conforms w/NUREO-0737.1temm 11 B 2 & III A 1 2 RESTAFER.0 R Florida Power (uip 83/09/30 DENION.H R Nuclear Reactor Regulation, Director 1p 20619 040 249 Fiche 50-302.83/09/30.8310040420 Uffice ni
- 8310180025 Determines that refund appropriate for review of 800111 & 820319 applications for amend to License DPR-72 re environ sampling analysis for detection capabilities & socurity training & qualification plan
 MILLER, W.O. License Fee Management Branch 83/10/07 WILCUS, W.S. Florida Power Corp. 1p. 20825-054 249 Fichs 50-302-83/10/07, 83/10/0805 6310180025
- J Insurance % indemnity information
- 8310140260 Forwards Endorsement 60 to NLITA Policy NF-195 & Endorsement 46 to MAPLU Policy MF-91

 DUCK, J.R. March & McLennan, Inc. 83/10/06 SALTZMAN Dffile of State Programs, Director 3pp. 20/61 J33 24X

 Fiche 50-302,83/10/06.8310140260
- P Operating license stage documents № correspondence
- B310050277 Forwards safety evaluation on installation of RCS high point vents por NUREG-0/37, item It It is, "RCS Vents" is final technical evaluation rept Vent sys acceptable subj to post implementation audit 7.J F. Operating Reactors Branch 4. 83/08/08. WILGUS,W & ida Power Corp. Opp. 20650-057. 24% Fiche 50-302,03/08/08. STOLENJE
- --8310050304 Safety evaluation supporting installation of RCS high point vents per NONEC-0737. Item IJ D. L. "RC's Vents" * NRC No Detailed Affiliation 61ven 83/08/26 10pp 20650 060 24X Fiche 50-302.83/08/08.8310050297
- --B306080106 "Selected Operating Reactor Issues Program II RCt, Vents (NUREG-0/37:Item II B 1)," final technical evaluation rept HELD, J T Energy Incorporated HELD, J T Lawrence Livermore Laboratory FIN A-0250 FF-370/081/A B3/03/14 ALBERIHAL, C Division of Licensing App 20650 070 24X Fiche 50-307, 83/08/08, 8310050297
- 8310050060 Forwards BER accepting Arkanson Power & Light Co (APL.)
 83060/ proposed mods to reactor trip breakers for DRW
 plants Requested info should be provided when APL generic
 design endorsed in response to Generic Ltr 83-28
 8TOLZ.J F Operating Reactors Branch 4 83/09/12 WILGUS.W S
 Florids Power Corp 2pp 20639 322 24X Fiche 50-302,83/09/12,8310050060
- B310210116 Forwards notice of denial of amend to License DPR-72 & opportunity for hearing is B30331 amend application concerning Cycle 5 reload, extending time interval for shutdown surveillance to once each 1/4 months

 MERNAN, R. Operating Reactors Branch 4 83/09/20 WILGUS, W.S. Florida Power Corp. 3pp. 20883 331 24X Fichs 50~301,83/09/20,83/
- --B310210117 Notice of denial of amend to License DFR-72 & opportunity for hearing re 830331 amend application concerning Cycle 5 reload.extending time interval for shutdown surveillance to once each 24 months inadequate justification provided 5TOLZ.J F Operating Reactors Branch 4 83/09/20 3pp 20883 334 24X Fiche 50-302,83/09/20.8310210116
- 83±0040301 Forwards B&W "Bounding Analytical Assessment of NUREG 0630 Models on LOCA kW/Ft Limits W/Use of FLFCSET," completing response to NUREG-0630 Compensating models documented & justification for model use provided HESTAFER, 0.8 Florida Power Corp. 83/09/29 STOLZ, J.F. Operating Reactors Branch 4. 2pp. 20612-227 24X Fiche 50-302,83/09/29, 83£0040301
- --8310040304 "Bounding Analytical Assessment of NUREQ-0630 Models on III(A kW/Ft | Imits W/Vse of FLTCGET "

 ** Batcock & Wilcox Ca 77-1140898-01 83/09/30 109pp 20612 229 24X Fiche 50-302, 63/09/29, 8310040301

- 8310040463 Modifies 791109 commitment for nuclear support svcs dept to perform multiple equipment failure analysis Plant staff, rather than nuclear support svcs dept will perform review MESTAFER. OR Plorida Power Corp 83/09/29 EISEN.UT.D G Division of Licensing 2pp 20623 125 24X Fiche 50-302,83/09/29, 20000463 8310040463
- 8310130421 Forwards safety evaluation & technical evaluation rept to NUREQ-0737.TMI Items II K 3 1. "Automatic PORV Isolation" & II K 3 2. "Rept on PORVs " Requirements met STOLIJ F Operating Reactors Branch 4 83/09/30 WILGUS, W 8 Florida Power Corp 3pp 20/69 167 24X Fiche 50-302.83/09/30, 831013003
- 8310130070 Notification of 831019-20 meetings w/util & Gilbert Assoc in St Petersburg, FL to inspect present emergency feedwater sys & associated sys & to discuss planned emergency feedwater sys upgrade project
 HERNAN.R Operating Reactors Branch 4 83/10/06 STDLZ.J F
 Operating Reactors Branch 4 2pp 20776 155 24y
 Fiche 50-302,83/10/06,8310130070
- 8310180436 Informs that util will respond to all applicable sections of Generic Ltr 83-28 re ATMS events at Salem by 831104 W/exception of Section 2 2 2 Requests extension until 840302
- 840302 SIMPSDN.E C Florada Power Corp 03/10/06 EISENHUT, D 9 Division of Licensing 2pp 20802 161 24X Fiche 50-302,83/10/06, 8310180436
- 8310200064 Forwards SER re NUREG-0737.1tem II K 3 17, "Rept on Dutages of ECCS" Review complete.however.improvement needed in area of LPIS availability Response requested within 90 days of ttr roceipt STOLZ.J F Operating Reactors Branch 4 83/10/06 WILGUS.W S Florida Power Corp 5pp 20844 277 24X Fishe 50-302.83/10/06,
- --B306160602 "ECCS Repts (F-47) TM1 Action Plan Requirements, Holida Fower Corp. Crystal River Unit 3." technical evaluation . FER-05506-272
- 8310120191 Forwards info re NUREG-0/37. Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling," in response to 830906 request Add1 info will be submitted by 840215
 BIMPSON.E C Florida Power Corp 83/10/0/ STOLZ.J F Operating Reactors Branch 4 Spp 20495 320 24% Fiche 50-302,83/10/07, 8310120191
- 8310120387 Submits status of required litems to upgrade seismic capability of emergency feedwater system 830809 request b Generic Ltr 81 14 Schedule for completion of seismic upgrades to emergency feedwatur system 1810/07 BTGLZ, J F Operat Reactors Dranch 4 7pp 20699 121 24X Fiche 50-302,83/10/07,831030307 8310120387
- 8310180025 Determines that refund appropriate for review of 800111 to 820319 applications for amend to Licenso DPR-72 re environ sampling analysis for detection capabilities & security training & qualification plan MILLER.W O Licenso Fee Management Bronch 83/10/07 WILQU5.W G Florida Power Corp 1p 20825 054 24X Fiche 50-302.83/10/07, 8310180025
- 8310140079 Forwards "Reactor Containment Bidg Integrated Leak Rate Test," Jul 1983 WESTAFER, G.R. Florida Power Corp. 83/10/11 DENTUN, H.R. Nuclear Reacto: Regulation, Director 1p. 20766 297 24 Fiche 50-302, 83/10/11, 8310140079
- --B3101400B0 "Reactor Containment Dldg Integrated Loak Rate lest," Jul 1983 BLESSING.J. SHIRK.R E Qilbert/Commonwealth Com COLLINS.M C Florida Powel Corp 83/07/31 58pp 20766 298 24X Fiche 50-302 83/10/il.8310140079
- 6310180473 Responds to 831006 request for add1 info re changes to emergency & abnormal procedures following review of Preliminary Safety Concern 22-82. "Potential for Piessurized Thermal Shock" WESTAFER, G R Florida Power Corp 83/10/14 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20802 028 24% Fiche 50-302,03/10/14,8310180473

- 8310310444 REVIEW OF CRYSTAL RIVER NUCLEAR GENERATING STATION UNIT 3
 EMERGENCY FEEDMATER SYSTEM RELIABILITY ANALYSIS
 YOUNGBLOOD, R. PAPAJOGLOU, I. A. Brookhaven National Laboratory FIN
 A-3393 NUREG/CR-3081 83/10/31 Division of Safety Technology
 43pp Available at NRC \$3.75 21001 016 24x
 Fiche 50-302.83/10/31.8310/310/44
- O Inspection reports. IE Bulletins & correspondence
- 8310250458 Advises that commitment to redraw elisting flow diagrams on computer aided drafting sys complete per IE Insp Rept 50-302/82-11 Drawings incorporate Refuel IV mods.including field verification wall/down markings MESTAFER.6 R Florida Power Corp 83/08/04 D'REIL4 V.J.P Region 2, Office of Director 1p 20897 036 24X Fiche 50-302.03/08/04, 8310250458
- 8310040476 Confirms 831020 mgt meeting in St Petersburg, FL to review results of first phase of annual regulatory performance apprecial SALP Board assessment for Jul 1982 June 1983 will be forwarded Proposed agenda enc!

 LEMIS, RC Division of Project & Resident Programs 83/09/21

 WILGUS, WS Florids Power Corp 2pp 20623 118 24X

 Fiche 50-302,83/09/21,83100404/6
- 8310040466 Ack receipt of 830909 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-302/83-13 LEWIS.R C Division of Project & Resident Programs 63/09/23 MILOUS.W S Florida Power Corp 1p 20623 100 24X Fiche 50-302,83/09/23.8310040466
- --B310040472 Responds to NRC B30810 ltr rs violations noted in IF lusp Rept 50-302/83-13 Corrective actions fNPO contacted to request rapid dose assessment procedures which will be used as guidelines Procedure EM-204 will be revised by 831101 WEBTAFFR, 0 R Florida Power Corp 83/09/09 O'REILLY, J P Region 2, Office of Director 4pp 20423 101 24X Fiche 50-302,83/09/23,8310040466
- --B310040475 Forwards IE Insp Rept 50-302/83-13 on 830627-8701 & notice of violation
 LEHIS.R C Division of Project & Resident Programs 83/08/10
 HTLGUS,H S Fiorida Power Corp 2pp 20623 105 24X
 Fishe 50-302.83/09/23.8310040466
- --8310040477 Notice of violation from insp on 830627-0701 * Region 2. Office of Director 83/08/to 1p 20623 107 24% Fiche 50-302.83/09/23.8310040466
- -8310040480 IE Insp Rept 50-302/83-13 on 830687-9701 Noncompliance noted failure to establish procedure implementing emergency plan requirement for prompt notification HUFFMAN.G N Region 2. Office of Director JENKINS.G K Divisio of Emergency Preparedness & Materials Safety 83/08/05 10pp 20623 108 24% Fiche 50-302,83/09/23,8310040464
- 3308300340 IE Info Notice 83-6; "Alleged Use of Stand-ins for Welder Qualification Tests" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Pespanse (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20784 022 24X Fiche 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Byo list encl JORDAN,E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison to of New York, Inc. (16pp. 20777-210 EAX Fiche 50-000,83/09/26,83083003041)
- 1308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 84-1 Differential Relays" Svc list encl JORDAN: E.L. Division of Energency Preparedness & Engineering Response (Post 830103) 83/09/24 Consultdated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 1008300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10067850 59 Evaluation " Svc list encl JORDANIE L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29 Consolidated Editor Co of New York, Inc. 115pp 20716 324 24% Fiche 50-600, 83/09/29, 8308300349
- 310130070 Notification of B31019-20 meetings w/util & Gilbert Assoc in Bt Petersburg.FL to inspect present emergency feedwater sys & associated sys & to discuss planned emergency feedwater sys upgrade project HERNAN, R Deposing Reactors Branch 4 B3/10/06 STOLZ.U F Operating Reactors Branch 4 B2/20/06 STOLZ.U F Fiche 50-302,83/10/06,6310130070

- #30#300378 (E Info Notice #3:45, "Surveillance of Flow in RTD Byrass, Loops Used in Westinghouse Plants " Svs list end! JORDAN, C L Division of Emergency Preparedness & Ingineering Response (Post #330103) #33/10/07 consolidated Edison to of New York, Inc 76ρp 20827 213 24% Fiche 50-000, #33/10/07, #30#30030/#
- 8308300752 IE Info Notice 83 66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison (n of New York, Inc. 79pp 20802 026 24% Fiche 50-000.83/10/07.8308300/52
- 8310130136 Comments on apparent increase in scape of freedulent v. substandard activities by uncorrupulous suppliers Reliabilitu emphasized SCOTT.L H. Flurida Power Coip. 83/10/10 DEYDUNG.R (Director's Office. Office of Inspection and Enforcement 1p. 20726 300 24% Fiche 50-308.83/10/10.8310130136
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Nozious Gases" Svc list encl JGRDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche S0-000.B3/10/11.B30BJ00757
- B30B300761 IE Info Notice B3-6B, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. (20pp. 20827 129 24X Fiche 50-000,83/10/11,8300700/61
- B310250350 Ack receipt of 830909 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-29 Violation A re functional test of ESF sys withdrawn O'REILLY, J.P. Region 2, Office of Director 83/10/13 WilkUs, W.S. Florida Power Corp. 2pp. 20898 077 24X Fichs 50-302.83/10/13. 8310250350
- --B310250374 Updates response to NRC 830210 lt) re violations noted in 1L Insp Rept 50-302/82-29 Violation A re failure to perform surveillance testing denied WESTATER.CR Florida Power Carp 83/09/09 O'REBLEY, J PRegion 2, Office of Director 4pp 20898 079 24X Fiche 50-302,83/10/13,8310250350
- R Periodic operating reports & related correspondence
- 8310140243 Forwards Rev 1 to monthly operating rept for Aug 1743 & monthly operating rept for bept 1983
 WESTAFER O R Florada Power Corp 83/10/11 DEYOUNG R C Director's Office, Office of Inspection and Enforcement 1p 20761 231 24% Fiche 50-302,83/10/11,8310140243
- --8310140266 Rev 1 to monthly operating rept for Aug 1983 BOOART, A. Florida Power Corp. 83/09/01 1p. 20761 232 247 Fishe 50-302 83/10/11,8310140243
- --8310140268 Monthly operating rept for Sept 1983 GRAMAM.D., FIELDS.D. Florida Power Corp. 83/10/04 App 20761 233 24% Fiche 50~302.83/10/11.8310140243
- S Reportable occurrences. LERs & related correspondence
- B310070306 LER 83-035/03L-0 on B30830, stram generator water level accepted Tech Spec 3 4 5 requirement Caused by misaligned linkage arm EWP-2A manually tripped allowing water level to drop within limits W/830929 ltr
 BUFE, J L. CULLEN D P. WESTAFER Florida Power Corp 83/09/29
 0 MEILLY, J P. Region 2. Office of Director 3pp 20652 203 MX Fiche 50-302,83/09/29.8310070306
- 8310070307 RO 83-023 responding to NRC 830817 itr refire damper discrepancies Fire protection sys designed per 10CFR50 App R mods to protect safe shutdown sys Audit verifying fire protection criteria implemented performed in early Sept HESTAFER. 8 R. Florida Power Cosp. 63/10/03 LEWIS.R. C. Division of Project & Resident Programs 8pp. 20652 206 24X Fiche 50-302,83/10/03.8310070307
- 8310120301 Updated LER 83-023/01X-2 on 830613 personnel discovered first damper FD-86 missing Caused by personnel error Engineering evaluation espected by 840331 CR-3 fire protection design considered adequate W/831003 ltr
 TMOMPSON.R H , WESTAFER.G R Florada Power Corp 83/10/03 O'REILLY.J P. Region 2. Office of Director 10pp 20490 336 247 Fiche 50-302,83/10/03,8310120301

- 6310140187 LER 83-036/01T-0 on B30921, fuel storage pool area surveys discovered not performed at least once every 24 h from B30915-21 Caused by personnel error Procedures will be revised W/831005 ltr BUFE, J. L. HUGHES, P. G. WILGUS, W. S. Florida Power Coip B1/10/05 O'REILLY, J. P. Region 2, Office of Director 4pp 20764 315 24) Fiche 50-302,83/10/05,8310140187
- 8310140123 LER 83-038/01T-0 on 830922, followup investigation of quality audit finding uncovered procedural inadequacy allowing requirement for surveillance of certain fire barrier penetration seals to be overlooked W/031006 ltr
 BUFE.J.L. SIMPSON, E.C. Florida Power (orp. 83/10/06 Q'REILLY, J.P. Region 2. Office of Director. 4pp. 20764 Q05 24X Fiche 50-302, 83/10/06, 83101401/J
- 8310140233 LER 83-037/03L-0 on 830707, during performance of Survetllance Procedure SP-340 re ECC8 pump operability, BMV-ILO breaker tripped while cycling valve from open to closed Cause unknown Breaker replaced 830922 W/831007 It; BUFE-J L . HUGHES, P 9 . 51MPSON. E C florida Power Corp 83/10/07 G*REILLY. J P Region 2. Office of Director 3pp 20762 042 24X Fiche 50-302.83/10/07.8310140233
- 8310170519 Updated LER 83-034/01X-1 on B30912 during performance of SP-110, RP5 functional testing, both reactor coolant pump wonitors for RCP-110 bypassed, contrary to Tech Spec 3 3 1 1 Caused by interim change W/831010 ltr CARBEINER, R E . MCSTAFER, G R florida Power Coip 83/10/0/ O REILLY. J P Region 2, Office of Director 4pp 20784 242 24X Fiche 50-302,83/10/07,8310170*,19
- 8330210021 LER 83-039/03L-0 on 830913.during Mode 4 surveillance testing, twelve instruments discovered out of calibi Cause under investigation Instruments will be recalibe from their replaced W/031013 ltr
 BUFE.J.L., CULLEN.D.P., WESTAFER.G.R. Florida Power Corp. 83/10/3
 D'REILLY.J.P. Region 2. Office of Director. 2pp. 20855-336. 24
 Fiche 50-202.83/10/13.8310210021
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 9310110004 Responds to FOIA request for five documents Forwards documents Documents also available in fbk
 FELTON, J. M. Division of Rules and Records 83/07/01 PEDRO, J. NUS Corp. 2pp. 20704 137 24X Fiche 50-000.83/07/01.8310110004
- 9310140173 Ack receipt of 831003 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-275/83-13 & 50-304/83-13 SHAFER, H D Region 3, Office of Director 83/10/06 RFED, C Commonwealth Edison Co ip 20765 001 24X Fiche 50-275.03/10/06, 8310140173
- --2310140175 Responds to NRC 830829 ltr re violations noted in If Insp Repts 80-295/83-13 & 50-304/83-13 Corrective actions surveillance conducted on fire pump diesel engine & starting 12-voit battery bank & charger ŁENTINE, F O Commonwealth Edison Co 83/10/03 KHPPLER, J G Region 3, Office of Director 2pp 20765 002 24X Fiche 50-295.83/10/06.83101401/3
- B310240087 Forwards IE Insp Repts 50-295/93-17 & 50-304/83-18 on B30810-0920 & notice of violation NDRECIUS: C E Division of Project & Resident Programs 83/10/07 REED.C Commonwealth Edison Cn 2pp 20880 348 24X Fiche 50-295.83/10/07.8310240087
- --8310240076 IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0970 Noncompliance noted Unit 2 open bed w/diesel generators 2A.2B & O inoperable on 830/04-11 & 71-27, contrary to surveillance requirements WATERS, J. R., HOVD.D.C. Repjon 3, Office of Director 83/10/04 11pp 20880 352 247 Fichs 50-295/83/10/07.8310240087
- 8310210374 Releases public version of revised emergency plan implementing proceduru FELTON J M Division of Ruler and Records 83/10/17 Document Management Branch 1p 2088/2007 24X Fiche 50-295.83/10/17, 8310210374

- --8310210377 Public version of Kev 1 to Emergency Plan Implementing Procedure EPIF 360-4. "Radindine Sampling Under Accident Conditions" W/830926 ltr.receipt form & procedure change request form PLIML-8 Commonwealth Edison Co Detailed Affiliation Given App Fiche 50-295, 83/10/17, 83102103/4
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/21 Document Management Branch 1p 2093/ 216 24% Fiche 50-000,83/10/21, 8310270526
- --8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure ECF-6. "Administration & Engistics Manager" W/831017 ltr to receipt form NELLIS.C A Commonwealth Edison Co 83/02/18 DENTON.H R NRC -No Detailed Affiliation Given 7pp 2093/217 24X Fiche 50-000,83/10/21,8310270526
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Documen Management Branch 1p 20963 126 24% Fiche 50-000,83/10/25, 8310280307
- --8310280314 Public version of revised generating stations emergency plan telephone directory GALLE, D. Commonwealth Edison Co. 83/08/11 DENTON, H.R. Officiof Nuclear Reactor Regulation, Director 64pp 20963 127 P4X Fiche 50-000,83/10/25,8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON.J M. Division of Rules and Records 83/10/26 Document Management Branch 1p 20962 266 24X Fiche 50-000,83/10/26, 8310280191
- ~~8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EOF-15, "Emergency Operations Facility Activation" MODRC: R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000.83/10/26.8310280191
- P Operating license stage documents & correspondence
- 8310130415 Forwards FR notice of consideration of issuance of amends to Licenses DPR-39 & DPR-48 to permit operation w/only three of four primary coolant loops in svc VARGA.S A Operating Reactors Branch I 83/09/23 FARRAR, D L Commonwealth Edison Co. 2pp. 20769-008 24X Fiche 50-295.83/09/23, 8310130415
- --B310130416 Notice of consideration of issuance of amends to Licenses DPR-39 & DPR-48 & proposed NSHC determination & apportunity for hearing VAROA: S A Operating Reactors Dranch 1 B3/09/23 4pp 20769 010 24x Fiche 50-275.B3/09/23.B310130415
- 8310110117 Buppl to 830808 request for amend to Licenses DPR-39 & DPR-48.revising Tach Spec re containment leakage test acceptance criteria Info clarifies 10GFRSO App J calculations
 LENTINELF G Commonwealth Edison Co 83/10/05 DENION, H R Office of Nuclear Reactor Regulation, Director 5pp 20667 169 24X Fiche 50-295,83/10/05;8310110117
- 8310170042 Forwards request for addl info re use of optimized fuel assembly Response required to complete evaluation VARQA.5 A Operating Reactors Branch 1 83/10/05 FARRAR.D L Commonwealth Edison Co App 20812 158 24% Fiche 50-295,83/10/05,8310170042
- 8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates

 BARNES, P. L. Commonwealth Edison Co. 63/10/05 KEPPLER, J. G. Region 3, Defice of Director. 10pp. 20830-034, 24X Fiche 50-000, 83/10/05, 8310200273
- 8310200151 Application for immediate & temporary amend to Licenses DPR-39 & DPR-49, changing Teth Spres to allow preventive maint to be performed on shared diesel generator O during current refueling outage LENTINE.F G Commonwealth Edison Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Directol 10pp 20836 282 24% Fiche 50-295.83/10/14/83/0200151

- 8310310049 Forwards response to NAC 831006 request for addl info se 830822 application for license amend to permit use of optimized fuel assemblies Structural analysis of mixed reactor core during seismic event encl
 LENTINE, FO Commonwealth Eduson Co 83/10/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 20951 131 24x
 Fiche 50-295,83/10/21,8310310049
- 8310310060 Submits info me Edison and swap analysis method for review A approval Methods employed in support of control and worth measurements using rod swap technique during reload physics testing Criteria tables encl
 LENTINE, F. G. Commonwealth Edison Co. 83/10/24 DENION, H. K. (If Fice of Nuclear Reactor Regulation, Director Spp. 20951-024 24), Fiche 30-000,03/10/24,8310310060

Q Inspection reports. IE Bulletins & correspondence

- B310110456 Forwards safety evaluation & technical evaluation rept re util responses to IE Bulletin 80-11. "Masonry Hall Design "
 Requests actions planned & scheduled for resolution of issue within 30 days
 VARGAS A Decrating Reactors Branch 1 B3/09/12 FARRAR, D L
 Commonwealth Edison Co 4pp 20712 197 24X Fiche 50-295,83/09/1/7,8310110456
- --B308030016 Revised "Masonry Wall Design (B-59).Zian Units 1 & 2." technical evaluation rept SUBRAMONIAN.N. Franklin Institute/Franklin Research Center ARC-03-B1-130 TER-05506-243 R01 B3/07/27 CHOKSHI.N C MRC No Detailed Affiliation Given 25pp 20712 202 24X Fiche 30-293.83/09/12.8310110456
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc jist encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fithe 50-000, 83/09/26, 8308300340
- 830B300342 IE info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26.830B.100342
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Syc list encl JORDAN EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26.8308300345
- B308300349 IE Info Notice B3-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc 11st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300J00J4?
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-295/83-19, 50-204/83-20, 50-373/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13

 NDRELIUS, C E Division of Project & Resident Programs 83/10/04 REED.C Commonwealth Edison Co 2pp 20834 098 24% Fiche 50-000, 83/10/04, 8310200124
- --8310200148 IE Mgt Meeting Repts 50-020/83-18,50-23/83-27,50-249/83-,",
 50-254/83-27,50-265/83-26,50-295/83-19,50-304/83-20,
 50-373/83-38,50-374/83-38,50-454/83-44,50-455/83-33,
 50-455/83-14 & 50-457/83-13
 NORELIUS,C L Division of Project & Resident Programs 83/10/03
 4pp 20834 100 24X Fiche 50-000,83/10/04,8310200124
- B310140173 Ack receipt of B31003 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-17 BHAFER.H D Region 3. Office of Director B3/10/06 REED.C Commonwealth Féison Co Ip 20765 001 24X Fiche 50-295.83/10/06, B310140173
- --8310140175 Responds to NRC 830827 ltr re violations noted in IE Insp Repts 50-295/83-13 & 50-304/83-13. Corrective actions surveillance conducted on fire pump diesel engine & starting 12-volt battery bank & charger LENTINE,F.O. Commonwealth Edison Co. 83/10/03 KFPPLER,J.C. Region 3, Office of Director 2pp 20765,002 24X Fiche 50-295,83/10/06,8310140173

- 8308300378 IE Info Notice 83-65. "Surveillance of flow in Nib Byjuss Loops Used in Westinghouse Plant: "Svc list encl JORDAN.E L Divisian of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Ne York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300752 IE (nfo Notice 83-64, "Fatality of Argentine Critica)
 Facility " Svc list encl
 JORDAN,EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of New
 York, Inc 79pp 20882 024 24X Fiche 50-000,83/10/07,8368300752
- 8310240087 Forwards IE Insp Repts 50-295/83-17 & 50-304/83-18 on 830810-0920 & notice of violation NORELIUS C E Division of Project & desident Programs 83/10/0/REED.C Commonwealth Edison (o 2pp 2080 348 24X Fichs 50-295.83/10/07/8310240087
- --8310240091 Notice of violation from insp on 830810-0920 NORELIUS, C. E. Division of Project & Resident Programs 83/10/07 2pp 20880 390 24% Fiche 50-295,83/10/07,8310240087
- --B310240096 IE Insp Repts 50-395/83-17 & 50-304/83-18 on B30810 09/0 Noncompliance noted Unit 2 operated w/diesel generators 2A:28 & 0 insperable on B30704-11 & 21-27. contrary to surveillance requirements MATERS.J R . DUNAWAY, F R . HARTNANN, P L Region 3. Office of Director B3/10/04 ilpp 20880 3% 24X Fiche 50-295, 83/10/07, 8310240087
- 8308300759 IE Info Notice 83-67, "Emergency Uso Respirator Mail Defirt Causes Production of Notious Gases" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison CV of New York, Inc 117pp 21043-075 24X Fiche 50-000,83/10/11.8308300/59
- 8308300741 IE Info Notice 83-48, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000.83/10/11.8389900/61
- #310180110 Advises that plans & schedule for resolution of holizontal joint reinforcing.per IE Bulletin 80-11, "Masonry Walls" & NRC 830912 ltr.will be provided by #33111 Util presently examining design of 18 walls affected by 15500 LENION.H K Difficult of Nuclear Reactur Regulation. Directo: 10 20002 258 24X Fiche 50-295.83/10/12.8310180110
- 8310180283 Clarifies NRC position re-procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON.W L Region 3, Office of Director 83/10/14 REUD. Commonwealth Edison Co 7pp 20801 115 24X Fiche 50-295,83/10/14,8310180283
- R Periodic operating reports & related correspondence
- B31012010B Monthly operating repts for Sipt 1983 W/031007 lts AUSTIN.G., GRAESSER.K.L. Commonwealth Edison Co. 63/10/0/ Director's Office. Office of Inspection and Enforcement 12pp 20898-22B 24X Fiche 50-295.83/10/07.8310120108
- S Reportable occurrences, LERs & related correspondence
- B310110430 Responds to FOIA request for four different categories of documents described in B30510 ltr Forwards matl list(d):

 App A. responsive to Items 1.2 & 4 DOE should be contacted for matl requested in Item 3 of ltr

 FELTON, J. M. Division of Rules and Records B3/06/14 HIATT, 5 (Ohio Citizens for Responsible Energy Jpp 20/06 Out 24% Fiche 50-000, 83/06/14, 8310110430
- --83101104/8 Responds to 830413 ltr requesting info re use of foreign matts in valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
 FARRAR, D. L. Commonwealth Edison Co. 83/04/22 KEPPLER, J. C. Region 3, Office of Director App. 20706-063 24X
 Fiche 50-000, 83/06/14, 8310810430
- 8310140256 LER 83-034/03L-0 on 830906, unit operated during first half of Cycle 7 w/nonconservative IR channel 2N%6 setpoints for high flux trip & rodstop Caused by inadequate quidelines leading to new setpoints Guidelines developed W/831006 ltr GEORGE, D.E., GRAESSER, K.L. Commonwealth Edition Co. 83/10/06 KEPPLER, J.G. Region 3, Office of Director 3pp. 20761 337, 4X Fiche 50-304, 83/10/06, 8310140256

- B310170609 LER 83-036/03L-0 on 830911.stram generator 2B level channel 2L-549 spiked high repeatedly Deviation nonconservative for steam generator level Caused by plugging of sensing line Line blown down & channel returned to svc W/B31006 ltr CANTMELL,P F. GRAESSER,K L. Commonwealth Edison Co. B3/10/06 KEPPLER,J G. Region 3, Offsice of Director 2pp. 20782 170 P4X Fiche 50-304.83/10/06.8310170609
- 8310170577 LER 83-033/03L-0 on 830914, during heat trace surveillence, heater failure alarm discovered on discharge from boild acid filter 2 to Boron injection tank Caused by deteriorated trace on discharge line Trace replaced W/B3/011 ltm MAPLAN, 6, GRAESSER/K L Commonwealth Edison Co B3/10/11 KEPPLER, J G Region 3, Office of Director 2pp 20/80 327 £4X Fiche 50-304, B3/10/11, B3/10/70579
- B310170557 LER 83-035/03L-0 on B30912.during performance test on diesol generator 2A.output breaker tripped open Operator unable to increase or decrease load Caused by eriatic motor Motor replaced & test rerun W/B31012 lti
 FANNING.O , GRAEBSER.K L Commonwealth Edison Co 83/10/12
 KEPPLER.J Q Region 3, Office of Birector 2pp 20780 34/ £4X
 Fiche 50-304.83/10/12.8310170557
- 8310210218 LER 83-037/03L-0 on 830915.during instrument mechanic surveillance testing of passive gas failure monitor 2RT-FRIS.no flow observed through monitor Cause unknown Investigation underway W/831014 ltr KUECHLE,C. GRAESSER.K.L. Commonwealth Edison Co. 83/10/14 KEPPLER.J G. Region 3, Office of Director. 2pp. 20852 0/9 74X Fiche 50-304.83/10/14.8310210218
- 9310270384 PND-III-83-102 on 831020, security officer received bemb threat phone call from unidentified male Shift engineer instituted emergency procedures Search of vital areas conducted w/negative results [hreat determined hoax BELANGER, J., CREED, J. Region 3, Office of Director 03/10/21 ip 20923 287 24X Fiche 50-295,83/10/21,8310270384
- T. Hearing transcripts on non-antitrust matters
- 8310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/01 PEDRD, J NUS Corp 2pp 20704 137 24% Fichs 30-000, 83/07/01, 8310110064
- --0310110011 Testimony of DQ Eisenhut re Zian/Waukegan Airport Interaction * Atomic Energy Commission 83/07/01 10pp 20/04 174 24X Fiche 50-000,83/07/01.8310110004
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8310140092 Forwards 1E Insp Rept 50-305/83-13 on 830829 0902 Nu noncompliance noted Protective action weaknesses in emergency plan discussed PAPERIELLO.C J Region 3, Office of Director 83/09/28 0165LER.C W Wisconsin Public Service Corp 4pp 20768 036 24X Fiche 50-305,83/09/28.8310140002
- --8310140013 IE Insp Rept 90-305/83-13 on 830829-0902 No nencompliance noted Major areas inspected emergency preparedness program, including actions on previously identified items, emergency detection & classification & public info program SNELL M G . LICKUS R M . PHILLIPS M P Region 3. Office of Director 83/09/28 14pp 20768 040 24X Fiche 50-305,83/09/21, B310140002
- B310120206 Forwards 830621 revs to emergency plan implementing procedures Index encl
 BAETSEN.L A Wisconsin Public Service Corp 83/09/29 SMITH M
 Region 3, Defice of Director 6pp 20692 239 24%
 Fithe 50-305,83/09/29,8310120:06
- --B310120209 Rev C to Procedure EP-AD-11 "Emergency Radiation Controls " MARCHI, M L Wisconsin Public Service Corp B3/06/21 Gpp 20892 245 24X Fiche 50-305,03/09/29,8310120206
- --B310120214 Rev H to Procedure EP-ENV-DA "Environ Protection Director Actions & Directives " MARCHI.ML Wisconsin Public Service Corp 83/06/21 17pp 20672 203 24% Fiche 50-305,83/09/29,8310120206
- --83:0120216 Rev E to Procedure EP-ENV-38 "EM Team Actions " MARCHI, M L Wisconsin Public Service Corp 83/06/21 Bpp 20692 270, 24X Fiche 50-305,83/09/29,8310120206

- --8310120220 Procedure EP-ENV-3C "Primary Dose Projection Calculation -IBM Personal Computer "
 MARCHI, M L Wisconsin Public Service Corp 83/06/21 4pp
 20692 278 247 Fiche 50-305,83/09/29,8310120206
- --9310120227 Rev E to Procedure EP-ENV-3E "Manual Determination of X/G (KNPP Metgorological Data) " MARCHI,N L Wisconsin Public Service Corp 83/06/21 6pp 20692 285 24X Fiche 50-305.83/09/29.8310120206
- --B310120232 Rev D to Procedure EP-ENV-3F "Manual Determination of X/G (Green Bay Meteorological Data)" MARCHI, M L. Wisconsin Public Service Corp B3/06/21 7pp 20672 271 24X Fiche 50-305.03/09/29.8310120206
- --8310120235 Rev D to Procedure EP-ENV-30 "Manual Projection Calculation" MARCHI,M L Wisconsin Public Service Corp 83/06/21 Opp 20692 298 24X Fiche 5D-305.03/09/29,8310120206
- --831012023B Rev B to Procedure &P-ENV-3H "Protective Action Recommendations" MARCHI, M L Wisconsin Public Service Corp 83/06/21 6pp 20472 306 24X Fiche 50-30t, 83/09/29, 8310120206
- --8310120240 Rev A to Procedurg EP-RET-3D "Containment Air Sampling Analysis Using CASP" WINSQUESKI, W S Wisconsin Public Service Corp 83/06/21 App 20692 312 24X Fiche 50-3Q5, 83/09/29,8310120206
- 8310110027 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20684 138 24X Fiche 50-305.63/10/05. 8310110027
- --B31011002B Forwards public version of revised emergency plan implementing procedures, including Procedures EP-AD-7 re notification of unusual event. EP-AD-8 re notification of alert & EP-AD-9 re notification of site emergency GIESLER, C W Wisconsin Public Service Corp. 83/08/31 DENTON-14 R Office of Nuclear Reactor Regulation, Director 2pp 30/686 139 24X Fiche 50-305,83/10/05,83/10/10027
- --831011003; Public version of revised emergency plan implementing procedures, including Procedures EP-AD-7 re notification of unusual event EP-AD-8 re notification of alert & EP-AD-9 re notification of site emergency wisconsin Public Service Corp 83/08/16 124pp 20686 141 24X Fiche 50-305,83/10/05,8310110027
- 8310120241 Ack receipt of 830811 exercise objectives for emergency exercise scheduled for 83101 Objectives acceptable Comments will be provided re 830916 detailed exercise scenario PAPERIELLO,C J Region 3, Office of Director 83/10/06 OlesLen,C W Wisconsin Public Service Corp 1p 20692 164 PAX Fiche 50-305,83/10/06,8310120241
- --8310120244 Forwards list of objectives for 831101 emergency exercise, per 820112 request for advance notice of scheduled exercise objectives
 GIEGLER, C W Wisconsin Public Service Corp. 83/08/11
 KEPPLER, J G Region 3, Office of Director. 5pp. 20492-145 24X
 Fiche 50-305-83/10/06.83(0)20241
- B310210389 Releases public version of revised emergency plan implementing procedures
 FELTON.J M Division of Rules and Records B3/10/17 Document Management Branch 1p 20882 279 24X Fiche 50-305,83/10/17, B310210389
- --B310210394 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-AD-3 re unusual avent, EP-AD-4 re alert & EP-AD-5 re site emergency GIESLER, C W Wisconsin Public Service Corp B3/10/05 DENTON.H R Defice of Nuclear Reactor Regulation, Director 1p 20882 280 24X Fiche 50-305, 83/10/17,8310210389
- --83i0210396 Public version of revised emergency plan implementing procedures, including Procedures EP-AD-3 re unusual event, EP-AD-4 re alert & EP-AD-5 re site emergency # Misconsin Public Service Corp 83/09/29 46pp. 20882 201 24X Fiche 30-305,83/10/17,8310210389

- 8310310325 Discusses IE Emergency Preparedness Insp Rept 50-305/83 13 on 830829-0902 & forwards notice of violation HIND J A Region 3. Office of Director 83/10/18 GIESLEM. C W Misconsin Public Service Carp 2pp 20951 114 24X Fiche 50-305,83/10/18,8310310325
- --8310310333 Notice of violation from insp on 830829-0902 Nancompliance noted shift supervisors incopable of determining when & what type of protective measures should be considered outside site boundary due to inadequate training in procedures HIND. / A Region 3. Office of Director 83/10/18 jp 20761 116 24% Fiche 50-305,83/10/18 8310310325
- P Operating license stage documents & correspondence
- 8310040048 Forwards safety evaluation closing DHR issue based on 800620.810713.830824 & 0909 submittals VAROA.S A Operating Reactors Branch I 83/09/20 GIESLEH.C W Misconsin Public Service Corp 2pp 20640 325 24X Fiche 50-305.83/09/20.8310040068
- --8310040072 Bafety evaluation closing DHR issue that IE Bulletin 80°1/2)

 * NRC No Detailed Affiliation Given 83/07/20 lipp
 20840 327 24X Fiche 50-30b.83/07/20.831004008B
- 8310040417 Requests extension to 840701 for implementation of 10CFR30 54(m)(i) & (iii) requirements be licensed operator staffing One addl group of candidates must be prepared by examined to provide two senior reactor operators per shift OIESLER,C W Wisconsin Public Service Corp 63/09/30 DENTUN,H H Office of Nuclear Reactor Regulation, Director 5pp 20626 176 24X Fiche 50-305,83/09/30,8310040617
- 8310120337 Forwards revised Surveillance Procedures SP 34-1450 t SP 34-1450 re low temp overpressure protection, inadvertently detached from 630923 ltr OIEBLER,C W. Misconsin Public Service Corp. 83/10/05 VARGA,S A Operating Reactors Branch 1 ip. 20700 233 24X Fiche 50-305,83/10/05,8310120337
- --83id120341 Rev D to Surveillance Procedure SP 34-1450, "RHR Suction Pressure Interlock Test & Calibr for Valves RHR-1A-1B-2A. 28 & 11 "
 MACSHAIN.D H Wisconsin Public Service Corp 82/05/21 14pp 20700 234 24X Fiche 50-305.83/10/05-8310120337
- --8310120345 Rev C to Surveillance Procedure SP 34-145C. "RHR Suction Pressure Transmitter PT 417 & PT 420 Calibr " MACSMAIN,D N Hisconsin Public Service Corp 82/07/30 bpp 20700 248 24X Fiche 50-305,83/10/05.8310120337
- 8310180583 Forwards Amend 50 to License DPR-43 & safety evaluation Amend adds requirement for secondary water chemistry program & deletes previous water chemistry requirements OROYENHUIS M Operating Reactors Branch | 83/10/06 GIESLER, C W Misconsin Public Bervice Corp 2pp 20824 030 24X Ficha 50-305,83/10/06,8310180583
- --8310180589 Amend 50 to incense DPR-43, adding requirement for secondary water chemistry program & deleting previous water chemistry requirements
 VAR9A.S A Operating Reactors Branch I 83/10/06 5pp
 20824 032 P4X Fiche 50-305,83/10/06-8310180583
- --8310180598 Safety evaluation supporting Amend 50 to License DPR-43 * Office of Nuclear Reactor Regulation, Director. 63/10/04 3pp 20824.037 24X Fiche 50-305.83/10/06.8310180583
- G Inspection reports. 1E Buildtins & correspondence
- 8310040031 Forwards safety evaluation of B30308 & 0717 requests for felief from exam of reactor coolant pump Relief from impractical requirements granted Notice of granting of relief encl
 VAROA, S.A. Decrating Reactors Dranch J. B3/09/16 GIESLER.C W. Wisconsin Public Service Corp. 2pp. 20040-350 24X
 Fiche 50-305, B3/09/16.8310040031
- --831004005& Safety evaluation granting relief from exam of reactor coolant pump * NRC - No Detailed Affiliation Given 83/09/16 5pp 20640 352 24% Fiche 50-305,83/09/16,8310040051
- -8310040060 Notice of granting of relief from ASME Code XI requirements re inservice insp program Relief effective as of B30916 VAROA.8 A Operating Reactors Branch (B3/09/16 2pp 20640 357 24X Fiche 50-305,83/09/16,8310040051

- 8310040068 Forwards safety evaluation closing DHR is ue based on 800420.810713.830824 & 0909 submittals VARGA.5 A Operating Reactors Branch 1 83/09/20 GIESLEM.C W Hisconsin Public Service Corp. 2pp. 20440 325 247 Fiche 50-305,83/09/20.8310040068
- --8310040072 Safety evaluation closing DHR issue (lef 16 Bulletin B0 1/2) * NRC - No Detailed Affiliation Civer 83/09/20 llpp 20540 327 24% Fiche 50-305.83/09/20.8310040060
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests" Svc list encl JORDAN.E L Division of Emergency Prederedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 247 Fiche 50-000.83/09/26.8308-00540
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gar Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24% Fiche 50-000,83/09/26.8308000.44
- 8308300345 IE Info Notice 83-63, "Potential Failures of Wertinghouse Type SA-1 Differential Relays" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- B310140002 Forwards IE Insp Rept 50-305/83-13 on B30829-0902 No noncompliance noted Protective action weaknesses in emergency plan discussed APPERIELLO.C J Region 3. Diffice of Director 83/09/88 of CIESLER.C W Wisconsin Public Service Corp 4pp 20/68 0.76 2/4% Fiche 50-305.83/09/28.8710140002
- --8310140013 IE Insp Rept 50-305/83-13 on 830829-0902 No noncompliance noted Major areas inspected emergency preparedness program, including ections on previously identified thems, emergency detection & classification & public info program SNELL, W.G., LICKUS.R.M., PHILLIPS.M.P. Region 3, Defice of Director B3/09/28 14pp 20768-040 24x Fiche 50-305,83/09/28,8310140002
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Bvc list enc! JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison to of New York Inc 115pp 20716 324 24X Fichs 50-000.83/09/29.8308J00349
- 8310040330 Ack receipt of 830822 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-305/83-09 Supplemental response describing certification program for Reg Ouide I 58 compliance requested SPESSARD, R L Division of Engineering 83/09/30 GIESLER, C W Misconsin Public Service Corp 2pp 20646 028 P4X Fiche 50-305.83/09/30.8310060330
- --8310060334 Responds to NRC 830720 ltr re violations noted in If Insp Rept 50-305/83-09 Corrective actions formal review of Tech Specs & license conditions will be performed to ensure that all appropriate requirements included in procedures OIESLER.C W Wisconsin Public Service Corp 83/09/22 STREETER.J F Region 3. Office of Director 8pp 20446-030 PAX Fiche 50-305.83/09/30.8310040330
- B30B30037B lE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B37/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000,83/10/07.83083003/8
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 024 24X Fiche 50-000, 83/10/07.8308300752
- 8310120276 Confirms 831017 mgt meeting in Glen Ellyn, IL to discuss will 830923 response to IE Insp Rept 50-305/83-11, per 831004 telcon
 HIND. J A Division of Radiological & Materials Safety Programs 83/10/07 GIESLER. C W Wisconsin Public Service Corp 19 20691 050 24X Fiche 50-305, 83/10/07, 8310120276
- 8308300757 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Froduction of Noxious Gases " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consultated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300757

- 8308300761 IE Info Notice 83-68; "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Syc list
 - PORTION EL Division of Emergency Preparedness & Engineering Response (Past 830103) BJ/10/11 Consolidated Edison to of New York, Inc. 120pp 20827-129 24% Fiche 50-000, 83/10/11, 8308300761
- 931027043B Forwards IE Insp Rept 50~305/83~14 on 830912~16 No noncompliance noted STREETER, J F Region 3, Office of Director 83/10/13 GIESLER.C W Wiscansin Public Service Corp 2pp 20923 031 24X Fiche 50~305,83/10/13.8310270438
- --831027044G IE Insp Rept 50-305/83-14 on 830912-16 No noncompliance noted Major areas inspected maint program. Implementation of maint program & nonroutine reporting program CHOULES.W C , KISH.J N , HUNTER.D R Region 3, Office of Director 83/t0/12 9pp 20923 033 24X Fiche 50-305.83/10/13.8310270438
- 8310180205 Clarifies NRC position on procedures for admitting NRC personnel Site-specific orientation re issuance of badges, escort duties, security briefings & emergency evaluations should be available to listed Region III personnel AXELSON, W. L. Region 3, Office of Director 83/10/14 GIESLER, C. W. Hisconsin Public Service Corp. 7pp. 20808 324 24X Fiche 50-305, 83/10/14, 8310180205
- #310310325 Discusses IE Emergency Preparedness Insp Rept 50-305/83-13 en 830829-0902 & forwards notice of violation MIND, J A Region 3. Office of Director 83/10/18 @IESLER.C W Hisconsin Public Service Corp 2pp 20961 114 24X Fiche 50-305,83/10/18.83103103∂5
- --8310310333 Notice of violation from insp on 830829-0902 Noncompliance noted shift supervisors incapable of determining when & what type of protective measures should be considered outside site boundary due to inadequate training in procedures HIND, J A Region 3, Office of Director 83/10/18 ip 20961 116 24X Fiche 50-305,83/10/18.8310310325
- R Periodic operating reports & related correspondence
- B310170341 Monthly operating rept for Sept 1983,W/831010 1tr RVITTER G H . GIESLER, C W Wisconsin Public Service Corp Director's Diffice of Inspection and Enforcement 5pp 20786 157 24X Fiche 50-305,83/09/30,8310170341
- S Reportable occurrences, LERs & related correspondence
- 0310070301 Potential Part 21 rept re underrange characteristic of Model N-EilGM transmitter Underrange zero offset may order when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN DJ Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30.8310070301
- 8310210304 LER 83-019/03L-0 on 830916, component cooling water pump 1A taken out of svc on 3 separate occasions to perform corrective maint on inboard bearing oil soal leak Caused by misalignment of motor to pump Pump realigned W/831014 ltr BERNHOFT.S L., GIESLER.C W. Wisconsin Public Service Corp 83/10/14 KEPPLER.J G. Region 3. Office of Director 2pp 20831 070 24X Fiche 50-305,83/10/14,8310210304
- 8310210317 LER 83-019/03L-0 on B30915, bonnet set screws on valve MS-100A failed to close Caused by Joose electrical Insulating math Math & contact cleaned W/B31014 ltr BERN/MDFT.S L. THORGERSON, J G. GIEBLER, C W. Wisconsin Public Service Corp. 93/10/14 KEPPLER, J G. Region S. Office of Director 2pg. 20951 161 24X Fiche 50-305,83/10/14,8310210317
- DOCKET 50-304 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8310120269 Ack receipt of 830614.17 & 0728 ltrs forwarding changes to Rev & to corporate emergency plan & Rev 3 to plant emergency plan & Rev 3 to plant emergency plan Changes acceptable, per 1007R50 54(q) requirements PAPERIELLO.C J Region 3. Office of Director 83/10/04 LARBON.C.E Northern States Power Co 1p 20490 348 24X Fiche 50-000.83/10/06.8310120269
- 8310310123 Forwards safety evaluation based on util submittals re NUREG-0737. II B 2, "Design Review of Plant Shielding Access to Vital Areas " Requirements met MILLER.J R Operating Reactors Branch 3 83/10/12 MUSOLF, D H Northern States Power Co 3pp 20965 324 24X Fichs.50~282,83/10/12,8310310123

- 8310180195 Clarifies NRC position re procedures for admitting NRC insp personnel to facilities Lists identifying NRC personnel requiring escorted & unescorted access to vital plant areas encl Update will be provided every 6 months AXELSON.W L. Region 3. Office of Director 83/10/14 LARSON.C E Northern States Power Co. 7pp. 20809-054 24X Fiche 50-282.83/10/14.8310180195
- 8310250538 Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 June 1983 KEPPLER,J G Region 3, Office of Director 83/10/20 LARSON,C E Northern States Power Co 2pp 2090P 143 24X Fiche 50-000,83/10/20.8310250538
- --B310250561 Submits comments on B30921 meeting w/NRC to discuss SALP Rept 50-263/B3-17 for Jul 1982 - June 1983 Valuable insights gained on improving performance GILBERTS, D. E. Northern States Power Co. B3/09/30 KEPPLER, J. Q. Region 3. Office of Director ip 20902 175 24X Fiche 50-000, 83/10/20, 8310250538
- J Insurance & indemnity information
- 8310250239 Forwards Endorsements 56 & 57 to MAELU Policy MF-51 & Endorsements 68 & 69 to NELIA Policy NF-174 for Monticello & Endorsements 48 & 49 to MAELU Policy NI-68 & Endorsements 56 & 57 to NELIA Policy NF-19/ for Prairie Island JOHNSON, R G Nurthern States Power Co B3/10/20 DIN172.I Division of Engineering 9pp 20899 036 24X Fiche 50-000, B3/10/20, B310250237
- P Operating license stage documents & correspondence
- 8310110498 Forwards safety evaluation re extended fuel burnup reload methodology based on Exxon assessment of potential radiological consequences for high exposure fuel Justification acceptable MILLER, J. R. Operating Reactors Branch 3 83/09/27 MUSOLF, D. II Northern States Power to 2pp 20714 319 24X Fiche 50-282,83/09/27,8310110498
- --8310110507 Safety evaluation supporting extended fuel burnup reload methodology based on Exxon assessment of potential radiological consequences for high exposure fuel * NRC - No Detailed Affiliation 61/09 83/09/27 5pp 20714 3P1 24X Fiche 50-28P,83/09/27,8310110498
- 8310130072 Forwards Amends 46 & 60 to Lirenses DPR-42 & DPR-40, respectively & safety evaluation Amends change limit of core local flux ratio allowing localized linear heat generation rate increase factor for power uncertainty DIIANNI, D C Operating Reactors Branch 3 83/10/03 MUSOLF, B M Northern States Power 60 2pn 20776 137 24X Fiche 50-282,83/10/03,8310130072
- --8310130076 Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively, changing limit of core local heat flux ratio allowing localized litnear heat generation rate increase factor for power uncertainty MILLER, J R Operating Reactors Dranch 3 83/10/03 lipp 20776 139 24X Fiche 50-282,83/10/03,8310130072
- --83101300/9 Bafety evaluation supporting Amends 66 & 60 to Licenses DPR-42 & DPR-60, respectively
 " Office of Nuclear Reactor Regulation, Director B3/10/03 Spp. 20776 150 24X Fichs 50-202,83/10/03,8310130072
- 8310170329 Notification of B31013 meeting w/util in Bethesda.HD to resolve seven open items in inservice test program for pumps & valves DIIANNI.D C Operating Reactors Branch 3 83/10/11 MILLER.J R Operating Reactors Branch 3 2pp P0/95 274 24X Fiche 50-282.83/16/11.8310170289
- Q Inspection reports: IE Bulletins & correspondence
- B30B30C340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engintering Response (Post 83C103) B3/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24% Fiche 50-000, B3/09/26, B30B300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JURDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342

- 8308300345 IE Info Notice 83-43, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" 8vc list enc!
 JURDAN C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24% Fiche 50-000,83/09/26,8308/100345
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 100FR66 59 Evaluation " Sve list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8310240086 Forwards IE Insp Repts 50-282/83-15 & 50-306/83-15 pm 830811-0910 No noncompliance moted 814FER.W D Region 3. Office of Director 83/10/05 LARSON, C C Northern States Power Co 2pp 20881 318 24X Fichs 50-282,83/10/05,8310240086
- --8310240102 IE Insp Repts 50-282/83-15 & 50-306/83-15 on 8308() 0710 No noncompliance noted Major areas inspected plant operational safety, maint, surveillance, followups of reactor trips.

 IE builetin & LERs
 FEIERABEND, C D , WILLIAMS, D L , JACKIM, I N Region 3, Office of Director 83/10/04 Bpp 20881 320 24X Fiche 50-282,83/10/05,8310240086
- 9308300378 IE Info Notice 82-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.83083003/8
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list enci JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Gauses Production of Nozique Gasos " Suc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043-075-24X Fiche 50-000,83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enc!

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 127 24X Fiche 50-000, 83/10/11, 8308300761
 - 10173 Forwards safety evaluation & FR notice re 830624 request for ief from ASMC Boiler & Pressure Vessel Code concerning ervice insp of reactor coolant pump casing welds Request need
 - nteo LER, J. R. Operating Reactors Branch 3 83/10/12 MUSOLF, D. M. thern States Power Co. 3pp. 20985 278 24X he, 50-282, 83/10/12, 8310310173
 - 310310176 Bafety evaluation granting util 830624 request for relief from ABME Boiler & Pressurs Vessel Code concerning inservice insp of reactor coolant pump casing welds * Office of Nuclear Reactor Regulation, Director 83/10/12 5pp 20965 201 24% Fiche 50-282.83/10/12.8310310173
- --B310310177 Notice of granting of relief from ASME Code Section XI inservice insp requirements HILLER.J R Operating Reactors Branch 3 B3/10/12 App 20965 286 24X Fiche 50-202.B3/10/12.B310310173
 - 10:80:95 Clarifies NRC position re procedures for admitting NRC inspersonnel to facilities Lists identifying NRC personnel requiring escorted & Unescorted access to vital plant areas enc. Update will be provided every 6 months AXELSON.W L Region 3. Office of Director 63/10/14 LARSON.C E Northern States Power Co 7pp. 20809.054 24X Fiche 50-282.83/10/14.8310180195
- 3310250275 Forwards SALP Repts 50-282/83-14 & 50-306/83-17 for Jul 1982 - June 1983. KEPPLER, J. G. Region 3, Office of Director. β3/10/20. LARSON, C € Northern States Power Co. 2pp. 20898 292 24X Fiche, 50-282, 83/10/20, 8310250275
- -8310250278 SALP Repts 50-282/83-16 & 50-306/83-17 for Jul 1982 Julie 1983 Overall rating of Category I assigned 8 Region 3. Office of Director 83/10/20 24pp 20895 294 24X Fiche, 50-282, 83/10/20, 8310250275

- --8310250284 Forwards SALP rept for Jul 1982 June 1983 in preparation for 830921 meeting Written comments may be provided within 20 days following meeting W/o rept
 HIND, J A Division of Radiological & Materials Safety Programs
 83/09/16 GILBERTS.D E Northern State Power Co Typ
 2085 318 24X Fiche 50-282,83/10/20.8310250275
- --8310250288 Comments on 830921 mosting w/NRC re SALP repts for Jul 1982 - June 1983 GILDERTS.D E. Northern States Power Co. 83/09/30 KEPPLEK, J & Region 3. Office of Director. 1p. 20895-321 24X Fiche 50-282,83/10/20,83102502/5
- 831025053B Forwards final SALP 4 Rept 50-263/83-17 for Jul 1982 ~ June 1983 KEPPLER,J G Region 3, Office of Director 83/10/20 LARSON,C (Northern States Power Co 2pp 20902 143 24X Fiche 50-000, 03/10/20, 8310250038
- --8310250561 Submits comments on 830921 meeting w/NRC to discuss SALP Rept 50-263/83-17 for Jul 1982 - Juno 1983 Valuable insights galmed on improving performance GLBERTS, D.E. Northern States Power Co. 83/09/30 KEPPLER, J.C. Region 3, Office of Director 1p. 20902-175 24X Ficht 50-000,83/10/20,8310250538
- R Periodic operating reports & related correspondence
- 8310190055 Monthly operating repts for Aug 1983 W/830912 ltr DUGSTAD.D. MUSCLE.D. Northern States Power Co. 83/09/02 Office of Resource Malagement. Director 9pp 20823 189 24X Fiche 50-282,83/09/02.8310190055
- S Reportable occurrences, LERs & related correspondence
- 8310270340 FOIA request for placement of listed LERs in FDR ORABER, L D NUS Corp 83/09/08 Division of Rules and Records 2pp 20938 098 24% Fiche 50-000, 83/09/08, 8310270340
- 8310170340 Responds to FDIA request for documents re degradation of fuel assemblies while in spent fuel pool in US nuclear power plants Forwards App A documents App B documents available in PDR FELTON, J M Division of Rules and Recolds 83/07/15 MAXHELL, B Rochester Post Bulletin, Rochester, MN 5pp 20844 098 74X Fiche 50-282,83/07/15,8310170340
- --8304200240 Forwards matl presented by util during B30P20 merting refuel assembly failure in spont fuel pool Review establishing NRC position on listed issues requested Working meeting scheduled for B30420 Encl withhold DIIANNI,D C Operating Reactors Branch 3 B3/04/08 WU,P NRC No Detailed Affiliation Given 2pp 20844 129 24X Fiche 50-282,83/09/15.8310190340
- --8305050044 Describes plan for review of Northern States Power Co & Westinghouse submittal on fuel assembly degradation while in spent fuel storage pool, prompted by fuel assembly cracking incident at Prairie Island WU.P Chemical Engineering Branch 83/04/20 BENARDYA.V Chemical Engineering Branch 2pp 20844 131 24X Fiche 50-282,83/09/15,8310190340
- --8305240300 Advises of informal preliminary review of potential sofety issues that may exist as result of in-core fuel assembly notice separations. Meetinghouse analysis indicates no problem asseciated w/prevention of control rod insertions. TOKAR.M. Core Performance Branch. 80/05/16. WU.P. Chemical Engineering Branch. 2pp. 20844. 154. 24% Fiche. 50-282, 83/09/15. 83101970340.
- --8308180228 Forwards 830617 SER refuel assembly correction in spent furl pool & draft info notice addressing correction problems at BHRs & PHRs Fuel assembly budge joint 811216 failure w/o precedent & w/o determined cause W/o cacls
 BENAROYA, V. Chemical Engineering Branch 83/08/02 HOLAHAN, C. Operating Reactors Assessment Branch 2pp 20844 156 24X
 Fiche 50-282,83/09/15,8310190340
- --B31019035B Forwards safety evaluation of fuel assembly failure event during fuel handling in spent fuel pool in Dec 1981 Evidence insufficient to deduce generic effect JOHNSTON, W. V. Assistant Director for Matls, Chem & Environ Technology (Post B30201), B3/04/20 LAINAB.0 C Assistant Director for Opporating Reactors 4pp 20844 133 24X Fich 50-282,83/09/15,6310190340
- --8310190360 Safety evaluation concluding that evidence insufficient to draw generic conclusions from Dec 1981 fuel pool assembly failure event * NRC No Detailed Affiliation Given 83/04/20 17pp 20844 137 24X Fiche 50-282.83/09/15.8310190340

- 8310120340 LER 83-020/03L-0 on 830829, maint air lack daor exhibited leakage of 21,000 with exceeding Tech Spec limit Caused by deterioration of Grafoil packing at inboard shaft seals Packing will be replaced prior to startup W/83092/ltr MUNSIAD.A A , NUSULF.D Northern States Power Co 83/09/27 Region 3, Office of Director 2pp 20700 229 24X Fiche 50-306,83/09/27,8310120340
- B310270347 Responds to FOIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also availabel in PDR One LER canceled Eight LERs not received FELTON.J M Division of Rules and Records 83/09/29 GRABER.L D NUB Corp ip 20938 040 24X Fiche 50-000.B3/09/29.G310270147
- --8310270429 LER 83-008/03L-0 on 830410 right hand stop valve failed Caused by soparation of valve disc from clapper arm disc Valve repaired & will be replaced at next refueling outage Left hand stop valve also inspected W/830510 ltr HUNSTAD. A A . MUSOLF. D Noithern States Power Co 83/05/10 Region 3. Office of Director 3pp 20438 098 24X Fiche 50-000.83/09/29.8310270347
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified

 BERSERIAN.N J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement lipp 20651 064 24X

 Fiche 50-000,83/09/30,8310070301
- 9310170541 LER 83-022/03L-0 on 830909, steam flow transmitter found out of calibr low by 1/ Cause unknown Transmitter returned to vendor for analysis Rosemount Model 1153MA6 differential pressure transmitter replaced W/831004 ltr HUNSTAD.A A . NUSOLF.D Northern States Power Co 83/10/04 Region 3, Office of Director 2pp 20/82 068 24% Fiche 50-306.83/10/04.8310170641

DOCKET 50-309 MAINE VANKEC ATOMIC POWER PLANT

- F Security, medical, emergency & fire protection plans
- 8310270200 Provides objectives for 1983 full-scale emergency preparedness exercise scheduled for 831022, per 811026 requestronstituting first milestone in development of exercise scenario package

 GARRITY, J II Maine Yankee Atomic Power Co 83/08/08 MURLEY, T E Region 1. Office of Director SPARKES, D M Federal Emergency Hanagement Agency 3pp 20724 197 24X Fiche 50-309,83/08/08, 9310270200
- --B31027020B Forward, "1983 Maine Yankee Emergency Response Exercise & Evaluation Plan" for 831022 emergency preparedness exercise Exercise objectives (Attachment A of plan) revised to clarify objectives, per 830826 meeting w/NRC & FEMA WHITTIER.G D Maine Yankee Atomic Power Co 83/09/12 MURLEY, T E Region 1, Office of Director SPARKS, D M Federal Emergency Management Agency 2pp 20924 200 24% Fiche 50-309.83/08/08.8310270200
- --8310270214 "1983 Maine Yankee Emergency Response Exercise & Evaluation Plan "

 * Maine Yankee Atomic Power Co 83/10/09 29pp 20924 202 24X Fiche 50-309,83/08/08,8310270200
- B310060053 Informs that based on FEMA B30811 memo & rept.deficiencies identified in B21211 emergency exercise adequately addressed or corrected during B30601 mini-exercise No enforcement actions re deficiencies will be taken MURLEY.T. E Region I. Office of Director B3/09/27 RANDAZZO, J B Taine Yankee Atomic Power Co 2pp 20647 056 24% Fiche 50-309.83/09/27.8310060053
- 8310180020 Forwards comments on 820812 detailed control room design review program plan Plan unacceptable per NUREG-073/.
 Suppl I Comments & response will be basis for teleon within L5 days of ltr date
 HILLER, J R Operating Reactors Branch J 83/10/04 GARRITY, J H Mains Yankee Atomic Power Co 10pp 20825 055 24X
 Fichs 50-309,83/10/04,8310180020
- ©310110064 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/05 Document Hanagement Branch Jp 2068/ 152 24X Fiche 50-309,83/10/05, B310110064
- --B3[0110066 Forwards public version of revised emergency plan taplementing procedures. Including Procedures 2 50 1 ve motification of unusual events. 2 50 2 re alert & 2 50 3 re site area emergency Recupt form encl ** Haine Yankes Atomic Power Co. B3/09/07 Document Management Branch 1p 20687 153 24X Fiche 50-309, 83/10/05, 8310110064

- --8310110069 Public version of revised emergency plan implementing procedures, including Procedures 2 50 i re notification of unusual events, 2 50 2 re aiert & P 50 3 re site area emergency

 Maine Yankee Atomic Power Co 83/08/26 164pp 20687 154 248 Fiche 50-309, 83/10/05, 8310110064
- B310170163 Ack receipt of B30915 ltr supplementing response to Confirmatory Action Ltr 82-27 Lung-term corrective actions will be examined during future ineps
 STARDSTECKI.R Division of Project & Resident Programs 83/10/07
 RANDAZZA.J B Mains Vankee Atomic Power Co ip 20786 361 24X
 Fiche 50-309,83/10/07.8310170163
- --8310170168 Suppls 821221 response to Confirmatory Action Ltr 82-27 re equipment tampering incident Encl withheld (ref 10CFR73 21) WHITTIER'S D Maine Yankee Atomic Power Co 83/09/15 MURLEY,T E. Region i, Office of Director 1p 20786 362 24X Fiche 50-309,83/10/07,8310170163
- 8310210265 Forwards IE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/10/07 RANDAZZA.J B Maine Yankee Atomic Power Co 2pp 20855 258 24X Fiche 50-309,83/10/07.8310210265
- --8310210266 lE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted Major areas inspected public prompt notification sys COMEN. I . CROCKER. H W Region 1. Office of Director 83/10/03 5pp 20855 260 24% Fiche 50-309,83/10/07,8310210265
- 8310270039 Releases public version of change to emergency plan FELTON, J M Division of Rules and Records 83/10/20 Document Management Branch ip 20940 226 24X Fiche 50~309.83/10/20, 8310270039
- --8310270042 Public version of Change 5 to emergency plan W/831007 ltr & receipt form MARKT,D Yankee Atomic Electric Co MARKT,D Maine Yankee Atomic Power Co 83/09/01 Document Management Branch 59pp 20940 227 24X Fiche 50-309, 83/10/20, 8310270039
- G Adjudicatory correspondence
- 8310130169 Forwards util latest submittal on reactor vessel embrittlement, per 831005 telton request Document being reviewed by NRC W/o encl GODDARD, R J. Hearing Branch 3 83/10/11 STERN, P. Maine, State of tp. 20724 297 24X Fiche 50-309,83/10/11,8310130169
- 8310180338 Order extending time until 831028 for Commission to act to review Birector's Decision DD-83-15 CHILK, S.J. Office of the Secretary of the Commission 83/10/17 Commissioners ip 20803 001 24% Fiche 50-307,83/10/17.
- 8310200225 Forwards NUB Corp rept. "Verification of GFLOW Computer Code Using Experimental Data From Maine Yankee Spent Fuel Storage Paol "Rept referenced in Stubmiller & Sargis testimony GALLO, J Isham, Lincoln & Beals GALLO, J Consumers Power Co 83/10/17 BLOCH, P B. PARIS, O H. SHON, F J Atomic Safety and Licensing Board Panel 84pp 20833 262 24x Fiche 50-309,83/10/17.8310200225
- P Operating license stage documents & correspondence
- 8310110492 Requests brief summary of key points made during 830818 telcom & results of flux reduction program due to revised results for surveillance wall capsule 263 Submittal requested within 120 days of ltr receipt MILLER, J R Operating Reactors Branch 3 83/09/24 GARRITY, J H Maine Yankse Atomic Power Co. 3pp 20714, 357 24X Fiche 50-309, 83/09/24, 83/0110492
- B310040339 Informs that state finds no objections to proposed mods to Tech Specs re fuel handling accident inside containment MARTIN.R G Maine, State of B3/09/27 HEITNER.K. Office of Nuclear Reactor Regulation, Director 1p 20617 2/8 24X Fiche 50-309,83/09/27.8310040339
- B310070202 Forwards sketch depicting current auxiliary feedwater sys w/planned mods (TMI Item II E | 1),per B30922 ltr
 HHITTIER, G B Masne Yankee Atomic Power Co. B3/09/2B MILLER, J R
 Operating Reactors Branch B 2pp 20659 117 24X
 Fiche 50-309.83/09/28.8310070202

- 8310140272 Forwards interim regulatory position on 100FR55 Olde) recentor operator & senior reactor operator functions Plant manager or designee should review qualifications of operators returning to licensed functions STARCSTECKI.R Division of Project & Resident Programs 83/09/30 RANDAZZA.J B Haine Yankee Atomac Power Co 4pp 20761 239 249 Fiche 50-309,83/09/30.8310140272
- 8310070159 Forwards schedule for proposed changes to lech Specs & listing of Tech Spec changes under review by NRC Requests schedule for completion of review HHITTIER.9 D Maine Yankee Atomic Power Co 83/10/04 MILLLE.J R Operating Reactors Branch 3 3pp 20659 084 24X Fichs 50-309,83/10/04-8310070159
- 8310170708 Advises that requirements of NUREG-0737. Item II K 3 P re rept on PORVs met w/existing PORV safety valve & reactor high pressure trip setpoints Automatic PORV isolation sys (Item II K 3 i) not needed (Item II K 3 i) not needed MILLER. J R Operating Reactors Branch 3 83/10/04 GARRITY. J H Maine Vanker Atomic Power Co. 3pp. 20813 200 24K Fiche 50-309,83/10/04.6310170708
- 8310260427 Forwards request for add1 info re valve inservice testing program based on review of 830808 submittal Response required within 30 days of receipt of 1tr HILLER.JR Operating Reactors Branch 3 83/10/07 GARRITY,JH Maine Yankee Atomic Power Co 7pp 20/26 328 24X Fichs 80-309,83/10/07.8310260429
- 8310250677 Forwards SER re 830427 submittal on NUREC-0737, Item Item II K 2 17 re voiding in RCS during anticipated transients in C-E plants Voids generated in RCS accounted for in present analysis modes Review complete NILLER, J R Operating Reactors Branch 3 83/10/11 GARRITY, J H Maine Yankee Atomic Power Co 10pp 20908 339 24% Fiche 80-309.83/10/11,8310250677
- B310240216 Requests final submission of radiological effluent Tech Specs using NRC comments in B20901 the & encl Draft 7 of Rev 3 to NUREC-0472 as guidance Submittal schedule requested in 60 days W/o encl HILLER, J.R. Operating Reactors Branch 3 B3/10/12 GARRITY, J.H. Maine Yankee Atomic Power Co. Opp. 2070/ 315 24X Fiche 50-309, B3/10/12, 8310240216
- 8310200225 Forwards NUS Corp rept. "Verification of OFLOW Computer Code Using Experimental Data From Maine Yankee Spent Fuel Storage Fool "Rept referenced in Stohmiller & Sargis testimony GALLO." Isham Lincoln & Beale GALLO." Consumers Fower Co 83/10/17 BLOCH.P B , PARIS.D H , SHON.F J Atomic Safety and Licensing Board Panel 84pp 20833 262 24X Fiche 50-309,83/10/17,8310200225
- 9310260358 Crants 830826 request for withholding "Swismblogical & Geological Studies, Miramich Area, New Brunswick & Central New Hampshire" Vols 1 & 2." From public disclosure per OCFR2 790
 ILLER, J.R. Gperating Reactors Branch 3 83/10/17 GARRITY, J.H. sine Yankes Atomic Power Co. 3pp 2091B 348 24X iche 50-309, 83/10/17, 8310260358
 - 2250063 Responds to 831004 comments on util 830812 detailed control opm design review plan NRC comments will be addressed in inal rept
 HITTIER, O D Maine Yankee Atomic Power Co 83/10/19 MILLER, J R Jerating Reactors Branch 3 2pp 20896 074 24X
 Tiche 50-309, 83/10/19, 8310250063
 - Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 82/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 83083000340
 - B300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas electors Positioned at Control Room Ventilation Air ntakes " Svc list and JORDANE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- IO8300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Releas " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778-001 24X Fiche 50-000,83/09/26,9308300345

- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 59 Evaluation " Svc list encl JGRDAN E L Byvision of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York Inc 115pp 20716-324 24X Fiche 50-000.83/09/29.83808300349
- 8310190139 Forwards IE Insp Rept 50-309/83-10 on 830703-0904 & notice of violation STAROSTECKLR Division of Project & Resident Programs 83/10/04 RANDAZZA, J B Maine Yankee Atomic Power Co 2pp 20820 247 24K Fiche 50-309,83/10/04,8310190139
- --8310190143 Notice of Violation from insp on 830703-0904 * Region 1, Office of Director 83/10/04 1p 20820 249 24X Fiche 50-309,83/10/04,8310190139
- --B310190109 IE Imsp Rept 50-309/83-10 on 830703-0704 Noncompliance noted failure to perform safety evaluation re secondary component cooling HY B in 3 h in accordance w/100FR50 99 SMETLAND.P , HOLDEN,C F , TRIMBLE.D Region 1, Uprice of Director B3/10/03 11pp 20820 250 24X Fiche 50-309,83/10/04,8310190139
- 830B30C378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 8301C3) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,83085003/G
- 8308300752 IE Info Notice 83-65, "Fatality at Argentine Critical Facility " Syc lint encl JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8310170163 Ack receipt of 830919 ltr supplementing response to Confirmatory Action Ltr 82-27 Long-term corrective actions will be examined during future insps
 STAROSIECKLY Division of Project & Resident Programs 63/10/07
 RANDAZZA: J B Maine Yankeo Atomic Power Co ip 20786 361 24X
 Fiche 50-309,83/10/07,8310170163
- --B31017016B Suppls 821221 response to Confirmatory Action Ltr (82-27) is equipment tampering incident Encl withheld (ref 10CFR73 21) WHITTIERS D Maine Yankee Atomic Power Co 83/09/15 MURLEY, T E Region 1. Office of Director 1p 20786 362 F1X Fiche 50-309,83/10/07,8310170163
- 8310210265 Forwards IE Insp Rept 50-309/03-14 on 830823-25 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/10/07 RANDAZZAJJ B Maine Yankee Atomic Power Co 2pp 20805 258 24X Fiche 50-309.83/10/07.8310210265
- ~-8310210266 IE Insp Rept 50-309/83-14 on 830823-25 No noncompliance noted Major areas inspected public prompt notification sys COHEN.1. CROCKER.H W Region 1. Office of Director 83/10/03 5pp 20855 260 24X Fiche 50-309.83/10/07.8310210265
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list enc.)
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 P4X Fiche 50-000, 83/10/11, 8308360759
- 83083007&1 IE Info Notice 83-&8, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Int. 120pp 20827 129 24X Fiche 50-000.83/10/11.83083007&1
- 8310210105 Ack receipt of 830708 & 1003 ltrs informing NRC of steps taken to correct violations noted in II; Insp Rept 50-30740743-06 STAROSTECKI.R Division of Project & Resident Programs 83/10/17 RANDAZZAJB Maine Yankee Atomic Power Co ip 20855 105 24X Fiche 50-307,83/10/17.8310210185
- --8310210174 Responds to NRC 830808 ltr re violations noted in 1E Insp Rept 50-309/83-06 Corrective actions sys drawings will be placed in control room far ref Operators & engineers reviewed containment integrity valve list HHITTIER, 0 D Maine Yankes Atomic Power Co 83/09/08 NURLEY.I E Region 1, Office of Director 3pp 20855 106 24X Fiche 50-309.83/10/17.8310210185

- --831021020B Provides addl info in response to 83080B ltr re violations nated in It Insp Rept 50-309/83-06 Recommendations resulting from broad stope operations reviews will be included in quality improvement program WHITTIER, 0 D. Maine Yankee Atomic Power Co. 83/10/03 MMRFY.T E. Region 1. Office of Director. 1p. 20855 109—24% Fiche 50-309.83/10/17.8310210185
- E310210286 Ack receipt of 830902 ltr informing NRC of steps taken to correct violations noted in II. Insp Rept 50-309/83-1.2 MATTIN.T T Division of Engineering & Technical Programs 83/10/17 RANDAZZA.JB Maine Vankee Atomic Power Co 1p 20848 207 24X Fiche 50-309.83/10/17.8310210286
- --8310210294 Responds to NRC 830802 ltr re violations noted in II Insp Rept 50-309/83-12 Corrective actions procedures for control & implementation of inservice testing activities developed & operation dept procedures revised GARRITY, JH Maine Yankee Atomic Power Co 83/09/02 MURLEY, I L Region 1, Office of Director 4pp 20848 208 24X Fache 50-309.83/10/17.8310210206

A Periodic operating reports & related corréspondence

- 8310190033 Monthly operating rept for Aug 1983 W/830908 lts BATTERSON, S., GRACE,R H. Maine Yankee Atomic Power Co. 83/09/08 HARTFIELD, R. A. Management Information Branch. 5pp. 20823 249 24X Fiche 50-309,83/09/08.8310190033
- S Reportable occurrences, LERs & related correspondence
- 631003030B Forwards response to 830816 memo re 830125 main feedwater line break Response based on NUREG-0918, NUREG-0691 & proposed rev to Jan-Mar AO rept DIRCKE W J Office of the Executive Director for Operations 837097/21 ASSELSTINE, J K Commissioners 13pp 20604 039 24X fithe 50-309, 837097/21,8310030108
- ~~830&020357 Operating Reactor Event Memorandum 83-01 re 830325 Joss-of-main-feedwater event which resulted in rupture of main feedwater line 2 Plant-specific PRA studies addressing Generic Issue A-01 on water hammer recommended EISEN:MUT, D G Division of Licensing 83/05/20 SPEIS, T Division of Sefty Technology VOLLNER, R Division of Engineering MATTSON, R Division of Gystems Integration (post 81005) 17pp 20604 052 24X Fiche 50-309,83/09/21,8310030308
- --8310030314 Requests responses to listed questions re main fredwater line break due to water hammer ASSELSTIME.J K Commissioners 83/08/14 DIRCKS.W J Office of the Executive Director for Operations 3pp 20604 071 24X Fiche 50-309.83/09/21.8310030308
- 8310040455 PNO-I-B3-099 on 830930, contract for bargaining unit (Util Workers Union of America, Local 497) expires If strike accurs, insp will be provided to confirm of plant transition by mgt personnel HOLDEN, C., H100INS. J., GREENMAN, E. Region I. Office of Director 83/09/29 1p 20629 325 24X Fichs 50-309, 83/09/29, 8310040485
- 8310190231 LER 83-031/03L-0 on 630830, while at steady-state full power operation, excessive packing leokage discovered in HPSJ loop injection stop valves Caused by loss of packing Related events occurred on 830891,0912 & 19 W/830929 ltr HGALLISTER, S A . WHITTIER, G D . Mains Yankee Atomic Power Co 83/09/29 MURLEY, T E. Region 1. Office of Director 3pp 20818 052 24X Fiche 50-309,89/09/29,8310190231
- B310250584 Forwards LER 83-031/03L-0 re HPS1 valve repairs W/o encl HHITTIER. © D Maine Yankee Atomic Power Co 83/09/29 MURLEY.T E Region 1. Defice of Director ip 20400 362 24X Fithe 50-309,83/09/29,8310250584
- 8310060253 PNO-I-83-0098 on 830930, licensee & Util Workers of America negotiations failed to produce settlement Operations turned over to supervisory personnel Settlement approved by union membership on 831001 MCLDEN.C., H1601NS.J., GREENMAN.E. Region 1, Office of Director 83/10/03 1p 20647 033 24X Fiche 50-309,83/10/03,8310060253

- 8310120165 Provides add1 info re instances where design of main feedwater trip did not meet single failure criteria reported in LER 83-028/01T-1 Continued operation until next shutdown justified MHITTER:0 D Maine Yankee Atomic Power Co 83/10/03 MILLER,J R Operating Reactors Branch 3 4pp 207.95 354 24X Fiche 50-309,83/10/03.8310120165
- 831020010B LER 93-033/03L-0 on 830706.couling water outlet stop valve SCC-M165 to RMR HX failed to open by use of control soutch from main control board Caused by internal valve mechanical problem Upgraded maint program developed W/831006 ltr STEVENS.JL . WHITTIER.9 D Maine Yankee Atomic Power Co 83/10/06 MURLEY.T E Region 1. Office of Director 4pp 20837 078 24X Fiche 50-309.83/10/06.831020010B
- 8310140082 PNO-I-83-105 on B31007, seismic event occurred in northeastern US w/magnitude of 5 2 on Richter scale in NY & 4 0 in NH No damage to equipment identified GALLOR & Region i, Office of Director B3/10/07 ip 20/66
- 8310250280 LER 83-034/017-0 while at steady-state full power operations, containment integrity inadvertently compromised when inner personnel hatch door opened No containment weight of air deviations encountered HODD, E.C. Maine Yankee Atomic Power Co. 83/10/14 Region I. Office of Director 1p 20874 231 24X Fiche 50-309.83/10/14, 8310250280

V Operator Examinations

- 83:0040516 Request extension to Jul 1984 for compliance w/increased shift manning rulr 10CFR50 54 due to incligible senior reactor operator license candidates Region I evaluation not final HHITTIER, 0 D. Maine Yankee Atomic Power Co. 83/09/30 MILLER, J R Operating Reactors Branch 3 2pp. 20626 181 24X Fiche 50-309, 83/09/30, 83/0040616
- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8309190260 Forwards correct page reva to security plan & security training & qualification plan Page revs withheld (ref 100FR73 21)

 * Public Service Electric & Gas Co of New Jersey B3/09/12

 MARTIN T T Djylsion of Engineering & Technical Programs Ip 20415 342 24X Fiche 50-272.83/09/12,8309190240
- 8310210195 Forwards marked-up revised 1983 emergency exercise Revincorporates NRC & FEMA comments from 830894 meeting Addlinfo re operational data & engineering problems will be submitted 2 wks prior to exercise
 MDELLER.P A Public Service Electric & Oas Co of New Jersey
 83/09/12 MURLEY.T Region 1. Office of Director 143pp
 20846 147 24X Ficho 50-272.83/09/12.8J10210195
- 8310290512 Forwards IE Safeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted MARTIN, T T Bivision of Engineering & Technical Programs 83/10/04 UDERITZ, R A Public Service Electric & Oas Co of New Jersey Rpp 20901 052 24X Fiche 50-272,83/10/04,8310250512
- --8310250529 IE Bafeguards Insp Repts 50-272/83-28 & 50-311/83-28 on 830907-09 No noncompliance noted Major areas inspected security sys power supply detection elds vital areas & licenage implementing procedure evaluation SMITH, 9 C Region 1, Office of Director 83/10/03 2pp 20901 054 24X Fiche 50-272,03/10/04,8310250512
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 8310180251 Forwards Rev 2 to updated FSAR, consisting of drawings updated since 830802 Nev 1 LIDEN.E A Public Service Electric & Qas Co of New Jersey 83710712 VARQA.S A Operating Reactors Branch 1 2pp 20809 238 24X Fiche 50-272,83/10/12.8310180251
- --8310180253 Rev 2 to updated FSAR.consisting of drawings updated since 830802 Rev 1 * Public Service Electric & Gas Co of New Jersey 83/09/23 39pp 20809 240 24X Fiche 50-272.83/10/12.8310180251

- P Operating license stage documents & correspondence
- 8310050187 Forwards "Plan for Improvement of Nuclear Dept Uperations," in response to Basic Energy Technology Associanc rept & cross ref document, "Rept on Review of Corrective Action Program re Reactor Trip Breaker Failures "UDERITZ: R A Public Service Electric & Gas Co of New Jersey 83/08/26 VARGA: S A Operating Reactors Branch 1 2pp 20532 170 24% Fiche 50-272.83/08/26.8310050159
- ~-8310050164 "Plan for Improvement of Nuclear Dept Operations "
 * Public Service Electric & Gas Co of New Jersey 63/08/26, 5760 20632 180 24% Fithe 50-272,83/08/26,8310050159
- B310070077 Forwards safety evaluation of design of RCS vents Design conforms whrequirements of NUREQ-0737, Item II B 1,6DC J.P.4, 14,50 & 31 & 10CFR50 44(c)(3)(1ii) whexception of positive valve position indication
 VARQALB A Operating Reactors Branch 1 83/07/27, UDERITZ, R A Public Bervice Electric & Gas Co of New Jersey 3pp 2047/347 24X Fiche 50-272,83/09/27,8310070097
- --8310070103 Safety evaluation of RCS vent design Design complies \(\sigma \) NVRE9-0737, Item II B 1.08C 1.2.4.14.30 & 31 & 10CFR50 44 \\
 N NRC No Detailed Affiliation Given B2/05/17 \(6pp \) 20673 352 \(24X \) Fiche 50-272,83/09/27.8310070097
- --B306080112 "Selected Operating Reactor Issues Program II RCS Vents (NUREO-0737: Item II B II." Final technical evaluation rept for Salem i & 2 HELD.J.T Energy Incorporated FIN A-0250 TF-343/0809A B3/02/23 ALDERTHAL @ Division of Licensing App 20673 358 24% Fiche 50-272:83/09/27.6330070097
- 8310070166 Advises that automatic PDRV isolation will not be provided & PDRV & block valve control sys will not be modified, based on "Probabilistic Analysis & Operational Data in Response to NUREG-0737, Itam II. K 3 2 for Westinghouse NSSS flants " LIDENIE A Public Bervice Electric & Gas Co of New Jersey 83/09/27 VARGAS Operating Reactors Branch I 2pp 20659 100 24X Fiche 50-272,83/09/27,8310070166
- 8310060327 Application to amend License DPR-75, changing surveillance test requirement for maintaining control room at positive pressure of 1/4-inch to 1/8-inch W 0 relative to outside atmosphere
 LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/09/28 VARQA.S Operating Reactors Branch 1 6pp. 20246 021 24X Fiche 50-311,83/09/28,8310060327
- ~-8310060328 Proposed Tech Spec re surveillance test requirement for maintaining control room at positive pressure of 1/4-inch to i/8-inch W 0, relative to outside stmosphere Public Service Electric & Gas Go of New Jersey 83/07/28 lp 20444 087 24X Fiche 50-311.83/07/28,8310040327
 - No.325 Application to amend License PPR-75, deleting generic irement for steam generator upper insp ports irement previously determined unnecessary by NRC (J.E.A. Public Service Electric & Qas Co. of New Jersey 1/29 VARCA, S. Operating Reactors Branch 1. 3pp. 20646 018 iche 50-311,83/09/27,8310060325
 - 003 Forwards remittants for License Change Requests 83-07,83-10
 11
 I.E.A. Public Service Electric & Gas Co. of New Jersey
 7/30 VARGA: 8 A. Operating Reactors Branch (ip 20658 245
 Fichs 50-272,83/09/30,8310070003
 - 70039 Forwards SER & technical evaluation rept re licensie gonses to NUREG-0737. Items II K 3 1. "Automatic PORV lation" & II K 3 2. "Rept on PORVs "
 ROA.8 A Operating Reactors Branch 1 83/10/05 UDERIT7. R A ublic Bervice Electric & Gas Co of Now Jersey 3pp 20812 162 4X Fichs 50-272.83/10/05.8310170039
 - G18 Forwards "Reactor Containment Bidg First Inservice rated Leak Rate Test & Type B & C Surveifience Test." red during first refueling outage on S30523 Summery of leak prior to first inservice Tape A test also encl. EA Public Service Electric & Oes Co of New Jersey //13 VAROA, B A Operating Reactors Branch 1 5pp 20030 15%. Fiche 30-311.83/10/13.8310200318
 - 10023 "Reactor Containment Bldg First Inservice Integrated Loak r Test & Type B & C Surveillance Test "
 *ublic Bervice Electric & Gas Co of New Jersey B3/05/31
 1. 20830 164 24x Fichs 50-011 83/10/10,8310200018

- 8310210285 Forwards addl fee required for Class I amend re Rev I to License Change Request 79-01 Original fee paid for single Class III amend only LIDEN,E A Public Service Electric & Cas Co of New Jersey 83/10/13 VARGA,S Operating Reactors Branch 1 10 20055 265 24X Fiche 50-272.83/10/13.8310210285
- G Inspection reports: IE Bulletins & coirespondence
- 8310310225 Forwards "Rept of Exams, Insps & Tests Conducted During 1983 First Refueling of Salem 2." per IL Circular /6-06 LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/09/21 MURLFy.T E Region 1. Office of Director 2pp 20947 231 24K Fiche 50-3[1.83/09/2].8310310225
- --8310310227 "Rept of Exams, Insps & Tosts Conducted During 1983 First Refueling of Salem 2 " * Public Service Electric & Oas Co of New Jersey 83/07/15 fp 20947 232 247 Fiche 50-311.83/07/21,8310310225
- 8308300340 IE Info Notice 83-6i, "Alleged Use of Stand Ins for Welder Qualification Tests" Svc list entl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24% Fiche 50-000,83/09/26,8300J00340
- 8308300342 IE Info Notice 83-62, "Failure of Redundent Toxic Gas Detectors Positioned at Control Hoom Ventilation Air Intakes " Svc list encl JORDAN. EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26.8308300J4/
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " but list encl JORDAN, E L. Division of Emergency Preparadeness & Engineering Response (Post 830103) B3/09/26 Consolidated Edizon (o of New York, Inc. 118pp 20778 001 24% Fiche 50-000, 83/09/26, 8308380345
- 6310140003 Discusses IE Insp Rept 50-311/83-18 on 830509-18 & forwards notice of violation Insp conducted to review loss of reactor vessel overpressure protection MURLEY, T E Region 1. Office of Director 83/09/26 UDERITZ, R A Public Bervice Electric & Oas Co of New Jersey 3pp 20/67 001 24X Fiche 50-316,83/09/26,8310140003
- ~**B310140004 Notice of violation from incp on B30509-18 Noncompliance noted RCS not depressurized w/designated RCS vent of greater than or equal to 3 14 square inches
 * Region I. Office of Director 83/09/26 2pp 20767 004 24X Fiche 50-311,83/09/26,8310140003
- --8310140277 IE Insp Repts 50-272/83-25 & 50-311/83-24 on 830810-0906 No noncompliance noted Major areas inspected conformance w/fock Specs, log & record reviews, followups on previous inspitems & review of licensee events
 LINVILLE, J C. SUMMERS, R J. JACOBS, R H. Region 1, Dffsco of Director 83/09/26 15pp 20761 216 24x Fiche 50-273,83/09/26,8310140276
- 8308300347 IE Info Notice 83-64, "Lead Bhielding Attached to Safety-Related Sys W/o 10CFR50 57 Evaluation " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 Consolidated Edison Co of Now York, Inc. i15pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310060325 Application to amend License DPR-75, deleting generic requirement for steam generator upper insp ports Requirement previously determined unnecessary by NRC LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/09/29 VARGA, S Operating Reactors Branch 1 3pp 20646 01R 24X Fiche 50-311.83/09/29.8310060325
- 8310110381 Discusses util 830706 & 0722 responses to 830505 notice of violation & proposed imposition of civil penalty identified during review of ATWS events an 830222 & 25 Order enclingosing civil penalty in amount of \$850,000 DEYOUNG.R.C Director's Office, Office of Inspection and Enforcement 83/09/29 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 20713 281 24X Fiche 50-272,83/09/29,8310110381

- 8310110387 Order imposing civil monetary penalties in amount of 4850,000 re violation of lech Spec 3 3 1 1 requiring two reactor trip breakers to be operable when reactor operating in Modes 1 & 2

 EYVOUNG & C Director's Office. Office of Inspection and Enforcement 87/09/29 Public Service Electric & Cas (o of Juresey 14pp 20713 283 24X Fiche 50-272,83/09/29,831011008)
- 10250512 Forwards IE Safequards Insp Repts 50-272/83 28 & 50-311/83-28 on 830907-09 No nancempliance noted MARTIN T 1 Division of Engineering & Technical Programs 84/10/04 UDERITZA A Public Service Electric & Gas Co. of New Jersey 2pp. 20901 052 24% Fishes 50-272,83/10/04.8310250512
- H310250529 IE Safeguards Insp Repts 50-E72/83-28 & 50-311/83-28 on B30907-09 No noncompliance noted Major areas inspected security sys power supply, detection ands vital areas & licensee implementing procedure evaluation SMITH.6 C . GODY.A T Region 1. Office of Director 83/10/03 2pp 20901 054 24% Fiche 50-272,83/10/04,8310250512
- i0180391 Ack receipt of 930829 & 0922 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-13 & 50-311/83-19 STAROSTECKI,R Division of Project & Resident Programs 03/10/05 JDERITZ,R A Public Service Electric & Oas Co of New Jersey ip 20803 313 24X Fichs 50-272,85/10/05.0310180391
- 331018039B Responds to NRC 830/29 ltm is violations noted in IL Insp Repts 50-272/83-13 & 50-311/83-19 Corrective actions ECCS throttle valve positions conrected & verified & TRIS worksheet fontonte revised mp FCCS throttle valves LIDEN.t A Public Service Clettric & Gas Co of New Jersey 83/09/22 SFAROSECKIR Division of Project & Resident Programs 3pp 20803 314 24% Fichs 50-272,83/10/05,8310180391
- DB30037B lE Info Notice 83-65, "Surveillance of Flow in HTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, & L Division of Emergoncy Preparedness & Engineering Response (Post 80103) B3/10/0/ Consolidated Edison Co of Nei Fork, Inc 74pp 20827 213 24X Fiche 50-000,83/10/07,83083003/0
- 08300752 IE Info Notice 83-66, "Fatality at Argentino Critical Facility " Syc list encl ACRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison to of New Forty Inc 77pp 20882 026 24% Fiche 50-000,83/10/07,8308300/52
- 18300757 IE Info Notice 83-67, "Fmeroency Use Respirator Matl Defect Causes Production of Noxious Goses " Svc list encl IBRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New Fork, Inc 117pp 21043 075 24X Fiche 90-000,89/10/11,8388800759
- B300761 IE Info Notice 83-68, "Respirator User Warning Defective ielf-Contained Breathing Apparatus Air Cylinders " Gvc list incl
 PCRDAN,E L Division of Emergency Preparedness & Engineering
 PERDAN,E L Division of Emergency Preparedness & Engineering
 PERDAN,E L Division of Emergency Preparedness & Engineering
 PCRDAN,E L Division of Emergency Preparedness & Engineering
 PCRDAN,E L Division of New
 PCRDAN,E L Division Co. of New
 PCRDAN,E L DIVISION CO. ST. DIVISION CO. OF New
 PCRDAN,E L DIVISION CO. ST. DIVISION CO. OF New
 PCRDAN,E L DIVISION CO. ST. DIVISION CO. OF New
 PCRDAN,E L DIVISI
- O280119 Forwards "1983 Inservice Exam of Class i & 2 Components: Sys of Salem Generating Station.Unit 2," final rept, "cls i & 2
 TOEN.E A Public Service Electric & Gas Co of New Jersey
 13/10/20 VARGA.S A Operating Reactors Branch i JUpp
 10929 281 24X Fiche 50-311.83/10/20.8310280119
- 310280122 "1983 Inservice Exam of Selected Class 1 & 2 Components & Sys of Salem Generating Station, Unit 2." final rept, Volu 1 & 2
 RICHTER, 8 W Southwest Research Institute FLACH, W T Public Service Electric & Gas Co of New Jersey 83/07/31 1054pp 20929 299 24X Fiche 50-311,83/10/20,8310280119
- Periodic operating reports & related correspondence
- O310225 Forwards "Rept of Exams, Insps & Tests Conducted During 983 First Refueling of Salem 2." per IE Circular 76-06 IDEN.E A Public Service Electric & Oas Co of New Jersey 3709/21 MMRLEY, T E Region 1. 0ffice of Director 2pp 0947 231 24X Fiche 50-311.83/09/21.8310310225
- 310310227 "Rept of Exams, Inspr & Tests Conducted During 1983 first Refueling of Salom 2" Public Service Electric & Gas Co. of New Jersey 83/09/19, Ip 20947 232 24% Fiche 50-311.83/09/21,8310310225
- 0030346 "NPDES Discharge Monitoring Rept for Aug 1983 " W/830906 tr 1LLER.1 K Public Service Electric & Gas Co of New Jersey 3/09/23 21pp 20590 164 24X Fiche 50-272,83/09/23.8310030346

- 8310180114 Revised monthly operating rept for Aug 1983 W/830920 ltr Miller, L. K., ZUPKO, J. M. Public Service Diectric & Gas Co. of New Jersey 83/10/10 Director's Office, Office of Inspection and Enforcement 2pp 20807 173 24X Fiche 50-311.83/10/10.8310180114
- 8310210041 Monthly operating rept for Sept 1983 W/831010 ltr MILLER, L K , ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/10/10 Director's Office, Office of Inspection and Enforcement 18pp 20955 348 24X Fiche 50-311,83/10/10, B310210041
- S Reportable occurrences. LLRs & related correspondence
- 8310050159 Forwards "Plan for Improvement of Nuclear Dept Operations," in response to Basic Energy Technology Assoc. Inc rept & cross ref document. "Rept on Review of Corrective Action Program re Reactor Frig Breaker Failures"

 UDERITZ.R A Public Service Electric & Gos Co of New Jersey 83/08/26 VARCA.S A Operating Reactors Branch 1 2pp 20632 170 24X Fiche 50-272,83/08/26.8310050159
- 8310190178 LER 83-038/03L-0 on 830827, vital bus 28 hydrogen analyser channels 12 & 22 failed to restart Caused by voltage transient Channel circuits replaced & restarted & action statement terminated W/830926 ltr FRAMMeR, ZUPKO.J M Public Service Electric & Gas Co of New Jersey 83/09/26 MURLEY,T E Region 1, Office of Director 4pp 20820 207 24% Fiche 50-311,83/09/26,8310190178
- 8310250407 LER 83-04B/03L-0 on 830927, attempts to demonstrate operability of pressurizer overpressure protection sys valves failed Caused by problems w/valve position indicators PORV circuitry modified W/030927 itr FRAHN.R . ZUPKO.J M Public Service Electric & Cas Co of New Jersey 83/09/27 MRLEV.T E Region 1. Office of Director 20897 240 24X Fiche 50-311,83/09/27,8310250407
- 0310250470 Supplemental LER 82-034/03X-1 on 820501 during routine operation, two feedwater sys snubbers seized Caused by excessive shock load on sys Snubbers replaced W/830927 ltr FRAMM.R . ZUPKO.J N Public Bervice Electric & Qas Co of New Jersey 83/09/27 MURLEY, T E Region 1, Office of Director 20897 120 24X Fiche 50-311,83/09/27,8310250470
- 8310250567 LER 83-047/031-0 on 830829. various 2A safeguards equipment control (SEC) alarms received On 830830 vital bus 2A tripped w/o automatic transfer Cause under investigation SEC channel reset Power restored to bus W/830927 ltr FRAHM.R. ZUPKO.J M Public Service Electric & Qas Co of New Jersey 83/09/27 MURLEY.T E Region 1. Office of Director 5pp 20901 016 24X Fiche 50-311,83/09/27.8310250567
- 8310040213 PNS-I-83-019 on 830922, licensee contract security organization suspended two security guards Guard admitted to bringing illegal substance on site Other guard did not rept incident Both guards terminated 830925 MADDEN.W. GODY.A Region 1. Office of Director 83/09/28 Ip 20614 273 24X Fiche 50-272, 03/09/28.8310040213
- 8310110177 Notification of Significant Licensee Meeting 83-87 on 831011 at site to discuss ATMS event corrective action program KISTER.H B Region 1. Office of Director 83/09/29 Region 1. Office of Director 1pp 20487 383 24% Fiche 50-272,83/09/29, 8310110179
- 8310140038 PND-I-83-106 on 831007, plant shutdown from 100% power due to apparent hydrogen leakage into generator stator water cooling sys Similar occurrence on 830819 resulted in 5-wk outage States of NJ & DE informed LINVILLE, JACCHS, R. NBRRBULM, L. Region 1. Office of Director 83/10/07 1p 20768 083 24% Fiche 50-311, 83/10/07, 8310140038
- 8310200279 LER 83-049/01T-0 on 830923 containment compressed air supply isolation valve discovered not locked closed Caused by personnel error during verification of equipment status during mode change Operators counseled W/831007 ltr FRAHM.R . ZUPKO.J M Public Service Llectric & Gas Co of New Jersey 83/10/07 MRLEY.T E Region 1. Office of Director Spp 20829 322 24X Fiche 50-311.83/10/07.8310200279
- 8310250244 LER 83-050/03L-0 on 830916, pressure drop test surveillance of containment isolation valves 2VC5 & 2VC6 revealed that leakage past valves greater than max range of test equipment Caused by deformed elastomer liming M/B1012 ltr FRAHM.R. ZUPKO.J M Public Service Electric & Oas Co of New Jersey 83/10/12 MMLEY, T E Region 1. Office of Director 4pp 20899 146 24X Fiche 50-311.83/10/12.8J10250244

V Operator Examinations

- B310250257 Responds to J Buzy telcon re licensed operator requalification Training Procedure TP-305 Exam will be completely changed at least every 6 wks.

 LIDEN.E A Public Service Electric & Cas Co of New Jersey
 B3/10/17 VARGA,S A Operating Reactors Branch 1 2pp 2007B 357
 24X Fiche 50-272,83/10/17.8310250257
- DUCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B310030436 Forwards legible Pages 35 & 37 to SER transmitted on B30%? LESSY.R P Hearing Branch 3 B3/09/28 ROSENTHAL.A S . BUCK.J H . KOHL.C N Atomic Safety and Licensing Appeal Panel 3pp 20633 337 24X Fiche 50-312,83/09/28.8310050436
- Security, medical, emergency & fire protection plans
- 9310030602 Forwards evaluation of 820528 request for exemption from Subsection III 0 2 of App R re electrical penetration area of auxiliary bldg Level of Pire protection does not meet requirement Exemption denied EISENHUT.D 0 Division of Licensing 83/09/19 RODRIGUE Sacramento Hunsicpal Utility District 8pp 20626-285 (Fiche 30-312,83/09/19,8310030602 RODRIGUEZ-R J
- 8310050117 Requests schedule for completing responses to Generic Ltr 81-12 re alternative shutdown capability, schedule for installing mods & compensatory measures to achieve hot standby & cold shutdown info requested within 2 wks STOLZ, J.F. Operating Reactors Branch 4 83/09/19 RODRIQUEZ, R. Sacramento Municipal Utility Blatrict 5pp 20650 204 20X Fiche 50-312,63/09/19,8310050119
- 8310060021 Forwards "Control Room Design Review Program Plan." per 830418 & 0720 commitments in response to Suppl 1 to NUREO-0737 ROBRIOUEZ.R J Sacramento Municipal Utility District 83/09/30 BTGLZ.J F Operating Reactors Branch 4 ip 20649 262 Fiche 50-312,83/09/30.831006002!
- --8310040022 "Control Room Design Review Program Plan"

 * Bacramento Municipal Utility District 83/07/30
 2049 263 24% Fiche 50-312,83/09/30,8310040021 14pp

Q Adjudicatory correspondence

- 8310030401 Forwards util 830921 ltr to NRC reporting on radiographic
 - 310030401 Forwards util B30921 itr to NRC reporting on radiographi
 insp of HPI noizles C & D Svc list encl Related
 correspondence
 TRAVIESD-DIAZ Shaw, Pittman, Potts & Trowbridge TRAVIESD-DIAZ
 Sacramento Municipal Utility District B3/09/27 ROSENTHAL, A S
 BUCK, J H , KDHL, C N Atomic Safety and Licensing Appeal Panel
 20593 070 24X Fiche 50-312,83/09/27,8310030401
- 8310050512 Responds to ASLAB request for NRC final position on review of upgraded auxiliary feedwater sys & related questions Util rescheduled completion of upgraded sys to refueling Dutage B currently estimated in Apr 1986
 LESSY, R. P. Hearing Branch 3 83/09/27 ROSENTHAL, A 8 BUCK, J. H. KOHL, C. N. Atomic Safety and Licensing Appeal Panel, 3pp 20634-050 24X Fiche 50-312,83/09/27,8310050512
- --8310050517 Affidavit of 9 Miner re ABLA8 questions on installation of upgraded auxiliary feedwater sys Util rescheduled installation completion for refueling Outage 8 estimated in Apr 1986 MINER, S Apr 1986 IINER:S - Operating Reactors Branch 4 24X Fiche 50-312:83/09/27:8310050512 83/09/27 4pp 20634 053
- -8310030521 Affidavit of ED Sylvester re ASLAB questions on anstallation of upgraded auxiliary feedwater sys per IMI Item II E i i Upgraded design will not meet current reliability guidelines SER encl BYLVESTER. E D Auxiliary Systems Branch 83/09/27 46pp 20634 076 24X Fiche 50-312,83/09/27,8310050512
- B310050436 Forwards legible Pages 35 & 37 to SER transmitted on B3092/ LESSY:R P Hearing Branch 3 B3/09/28 RGENTHAL.A 8 . BUCK.J H . KOHLO N Atomic Safety and Licensing Appeal Panel 3pp 20633.337 24X Ficher 50-312; B3/09/28; B310030436

- P Operating license stage documents & correspondence
- 8310030611 Forwards SER on generic mods to reactor trip breakers roll B&H plants to provide automatic actuation of shunt trip attachments Plant-spacific lines should be provided when generic design endorsed in response to Generic Ltr 83-28 STOLZ/J F Operating Reactors Branch 4 83/09/12 RODR(QUEZ/R L Sacramento Municipal Utility District 2pp 20607 298 24% Fiche 50-312,83/09/12 8310030611
- 8310250991 Forwards Std Order for DUE Work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Shubbers for Trojan & Rancho Seco" ADAMS, C. Energy, Dept of FIN 8-8559 83/09/14 MARIIN. J.B. Region 5, Office of Director Ip 20900 124 24X Fiche 50-000,83/09/16,8310250591
- --8310250400 Std order for DDE Work "Operating Reactors Licensing Action Tech Specs for Hydraulic & Mechanical Snubbers for Irojan & Rancho Seco." Issued to LLL MARTIN, J.B. Regian 5. Defice of Director MACRUSKY, J. Lawrence Livermore Laboratory FIN B-8559 83/08/31 ip 20900 125 24X Fiche 50-000.83/09/16.8310250591
- -8310250625 Forwards project & budget proposal for NRC work "Upriating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Raniho Seco" STUART, K J Lawrence Livermore Laboratory FIN 8-8562 83/08/19 BISKOP, T W Region 5. Office of Director 1p 20900 126 .4X Fiche 50-000.83/09/16.83102:0591
- --8310250631 Project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Raucho Seco "
 CLELAND.L L , WHITE,R , JOHNSON.J N Lawrence Livermore Laboratory FIN B-8562 93/08/18 PADDVAN.M L , THETZIG.G Region 5, Office of Director 2pp 20900 127 24X Fiche 50-312.83/09/16,8310250591
- 8310040547 Withdraws 790920 request for proposed Rev 1 to Tech Specs Amend 45.per conversation between 8 Niner & R Colombo RODRIOUEZ,R J Sacramento Municipal Utility District 83/07/20 EISENHUT.D G Division of Licensing ip 20623 209 24X Fiche 50-312,83/09/20,831004054/
- 8310070133 Forwards, for consideration, project & budget proposal, "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco Facilities "
 TUSZKA, M E Lawrence Livermore Laboratory FIN 8-8562 83/0 BISHD, T W Region 5, Office of Director 10pp 20659 025 Fiche 50-000, 83/07/20, 8310070133 83/09/20
- 8310210038 Submits results of plant review committee investigation of Cycle 6 administrative operating limits Addl conservation of retaining penalty for 30 EFPD imposed RDDRIGUEZ, R J Sacramento Municipal Utility District 83/09/20 MINER, S NRC ~ No Detailed Affiliation Given 2pp 20856 004 eV Fiche 50-312,83/09/20,8310210030
- 8310040317 Application for amend to License DPR-54, extending deadline to 830601 for implementing 10CFR50 54 changes re shift staffing RODRIGUEZ,R J Socramento Municipal Utility District 83/09/22 STOLZ.J F Operating Reactors Branch 4 5pp 20AEO 219 Fiche 50-312.03/09/22.8310040317
- 8310040033 Confirms procedure for estimating core damage since restart from recent outage in response to NRC 830902 ltr Procedure not formalized but wall be incorporated as normal plant not rormalized but will be incorporate as normal plant operation procedure
 LATHAM, R K Socramento Municipal Utility District 83/09/26
 STOLZ, J F Operating Reactors Branch 4 ip 20608 124 24
 Fiche 30-312,83/09/26,8310040033
- B310110471 Forwards safety evaluation of util responses to NUREG 0/37. Item II E t 1. "Auxiliary Feedwater Sys " Item 1 reprotection From internal missiles unacceptable Requests commitment to NIC position within 30 days STOL7. J F Operating Reactors Branch 4 B3/09/26 RODRICUEZ.R J Sacraments Municipal Utility District 46pp 20711 320 24% Fiche 50-312.83/09/26.8310110471
- B31011047A Forwards safety evaluation supporting installation of RCS high point vents per NUREG-0737. Item II B 1 STDLZ, J F Dyerating Reactors Branch 4 B3/09/27 RODRIQUEZ, R J Sacramento Monicipal Utility District 7pp 20712 2A5 24X Fiche 50-312, 83/09/27, 83101104/4

- --8304080055 "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0/37. Item II B 1)." final technical evaluation rept for Rancho Seco I HELD, J T. Energy Incorporated FIN A-0250 TF-367/0817A 83/03/14 ABERTHALIG NRC No Detailed Affiliation Given typ 20712 274 P4X Fiche 50-312,83/09/27,0310110476
- 6310030485 Forwards schedule for responding to 830824 request for add1 info on inadequate core cooling instrumentation sys,pt; NUREG-0/37, Item II F 2, "Inadequate Lore Cooling " HODRIQUEZ.R J Sacramento Municipal Utility District 83/09/26 STOLI.J F Operating Reactors Branch 4 2pp 20201 07/ 24X Fiche 50-31P,83/09/28.8310030485
- 8310120394 Forwards response to 830824 request for addlinfo to complete review of spent fuel pool expansion Turbine gantry will be used to move loads in & out of spent fuel bldg MATTIMUE.JJ Sacramento Municipal Utility District 83/10/03 STOLZJJ Operating Reactors Branch 4 5pp 20/00 191 247 Fiche 50-312,83/10/03.8310120394
- 8308300771 Board Notification 80-128A Forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid
 - Valves
 EISENNUT, D.O. Bivision of Litensing 03/10/06 PALLADINO, N.J.
 Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 83083007/1
- 8310120087 Forwards response to 830831 request for addl info re pump & valve instruce testing program Roviced request for relief from ADME Bection XI Code & revised Section 4 of valve testing program included RODRIGUEZ.R J Bacramento Municipal Utility District 85. STOLE.J F Operating Reactors Branch 4 29pp 20696 194 Fiche 50-312.B3/10/04.8310120087 83710706
- 6310140143 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept Vol 1 Mork BZ Fuel Assembly Besign Rept." in support of Cycle 7 reluad planned for late 1984 Rept withhold (ref 10Cl RZ 770)

 IUCKER.H B Duke Power Co 83/10/07 DINTON H R Office of Nuclear Reactor Regulation, Director STDL2.JF Operating React Branch 4 2pp 20766 067 24X Fiche 50-000.83/10/07.8310140143
- --8310140145 Farwards proprietary "Rancho Soco Cycle 7 Roload Rept Vol 1 -- Mark NZ fuel Assembly Design Rept," Apr 1983 Affidayit supporting determination of proprietary nature of rept chcl TAYLOR, J H Babcock & Wilcox Co 83/09/15 MINER,8 Office of Nuclear Reactor Regulation, Director 8pp 20766-069 24X Fiche 50-000,83/10/07.8310140143
- 6310210020 Forwards proprietary version of "Rancho Seco Cycle 7 Reload Rept. Vol 1. Mark D2 Fuel Assembly Design Rept " Vol 2 will be submitted in Fall 1984 Rept withheld MATTIMOL. J. Gacramento Municipal Utility District 83/10/18 EISENHUT. D. 9 Division of Licensing ip 20898 POI 24X Fiche 50-312.83/10/18.8310210020
- 8310250210 Withdraws proposed Amend 81 to License DPR-54 re Guneric Item B-24, "Containment Isolation Dependability," per NRC 830914 request Vil Will continue to use equalizing line valves when qualified MATTIMOE. J. J. Sagramento Nunicipal Utility District 83/10/16 870617. J. F. Operating Reactors Branch 4 ip 20892 352 24X Fiche 50-312.83/10/18.8310250210
- B310010489 Bummary of B30826 meeting w/b&W Dumors Group reimplementation of Generic Ltr B3-28 concerning defenses against A7WS & proposed A7WS for B&W plants List of attendoes & viewgraphs encl MADAMB1.P Operating Reactors Branch 4 B3/10/20. O3/10/20.
- B310280099 Forwards D&N Owners Group rept "Bounding Analytical Assessment of NUREG-0630 Models on LUCA kW/Ft Limits H/Use of FLEGGE(" of FLEGGE! "
 RODRIGUE2, R J Sacramento Municipal Utility District B3/10/P1
 STOLZ.J F Operating Reactors Branch 4 ip 20935 P12 24X
 Fithe 50~312,83/10/21,8310280099
- B3102B0072 Notification of B31109 meeting w/util in Bethesda.MD to discuss methodology used to prepare integrated living schedute MINER.S Operating Reactors Branch 4 83/10/26 STOLZ.J F Operating Reactors Branch 4 2pp 20764 110 24X Fiche 50-312.83/10/26.83102800/2

- Q Inspection reports. IE Bulletin- & correspondence
- 9310170674 Forwards IE Insp Rept 50-312/93-16 on 830606-10.13 & 21-22 No noncompliance noted

 No noncompliance noted

 WENSLAMSNI,F A Region 5, Office of Disector 83/09/14

 RODRIQUELR J Socramento Municipal Utility District

 20779 295 24X Fiche 50-312,83/09/14,8310170474
- ---8310170678 IE Insp Rept 50-312/83-16 on 830606-10,13 & 21-22 No noncompliance noted Major areas inspected environ protection, followup on ROs.info notices, onsite events, noncompliance items & NUREG-0737. Items II B 3 & II F I NORTH, H S . MENSLAWSKI, F A Region 5. Office of Director 83/09/16 10pp 20779 297 24X Fiche 50-312.83/09/16.8310170674
- 8310040300 Forwards IE Insp. Rept 50-312/83-24 Portions of post-accident sampling sys (NUREG-0737, Item II B 3) inoperable Reasonable degree of sys reliability remains undemonstrated HENSLANEKI,F A Region 5, Office of Director 83/09/23 STOLZ,J F Operating Reactors Branch 4 ip 20612 338 24X
- --8310040308 Forwards IE Insp Rept 50-312/83-24 on 830912-16 MgL attention should be directed to insp findings re post-accident sampling sys
 WENSLAWSKI,F A Region 5, Office of Director 83/09/26
 RODRIGUEZ,R J Sacramento Municipal Utility District 3pp
 20612 339 24X Fiche 80-312/83/09/24/8310040300
- --8310040311 IE Insp Rept 50-312/83-24 on 830712-16 Noncompliance noted licensee unable to sample containment atmosphere using post-accident sampling sys, hydrogen monitors or reactor bldg atmosphere monitor NORTH.H S. YUHAS.G F. Region 5. Office of Director NORTH.H S. YUHAS.G F. Region 7. Office of Director 83/09/23 12pp 20612 341 24X Fiche 50-312,03/09/23.0310040300
- 830B300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754-022 24X Fiche 50-000.83/09/26.830B300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant loxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26.8308300342 116pp
- B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list entl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310030401 Forwards util 830921 ltr to NRC reporting on radiographic insp of HPI nozzles C & D Svc list encl Related Insp of API notifies C & D SYE 1184 ent Related correspondence
 TRAVIESO-DIAZ Bhaw, Pittman, Potts & Trowbridge TRAVIESO-DIAZ Sacramento Municipal Utility District B3/09/27 ROBENTHAL, A S . BUCK, J H . KOHL, C N Atomic Safety and Licensing Appeal Panel . 20593 070 247 Fiche 50-312-83/09/27,8310030401
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFRSO 59 Evaluation " Syc list UNIONAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New Yark, Inc 115pp 2071& 324 24% Fiche 50-000,83/09/29,8308300349
- 8310140247 Supple response to IC Bulletin 82-02 "Degladation of Threaded Casteners in RCPB of PWR Plants " Maint procedures revised to include requirements for torque valves & gasket Installation
 MATTIMOE, J.J. Barramento Municipal Utility District 83/10
 MARTIN, J.B. Region 5, Office of Director opp 20761 325
 Fiche 50-312,83/10/04,83/10140249 83/10/04
- 8310120355 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-312/83-12 WENSLANSKI,F A Region 5, Office of Director 83/10/04 LATHAM.W K Sacramento Municipal Utility District ip 20700 20/ 24X Fiche 50-312,83/10/04.8310120355 20700 209
- --831012035B Responds to NRC 830517 & 0801 ltrs re violations noted in 310120308 Responds to NRC B3051/ & OB01 Itrs re vibiations and IE Insp Rept 50-312/83-12 Corrective actions Administrative Procedure AP | re responsibilities & authorities revised to emphasize necessity for procedure adherence LATHAM.W Sacramento Municipal Utility District B3/09/21 MARTIN.J B Region 5. Office of Director 1p 20700 210 Ficho 50-312.83/10/06.8310120355

- 8308300378 JE Info Notice 83-65, "Burvei)lance of Flow in RTD Bupass Loops Used in Westinghouse Plants " Svc last encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.83083003/8
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Notious Gases " Bvc list entl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 8301031 83/10/11 Consolidated Edison Co of New York Inc 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc tist and!

 JDRDAN,E L Division of Cherquicy Preparedness & Engineering Response (Post 830103) 83/10/11, Consolidated Edison Co of New York, Inc. 120pp 20827 129 P4X Firm 50-000.83/10/11.8308300761
- 83:03:040: Forwards IE Insp Repts 50-3:12/82-41 on 82:11:6-8:302:17 No noncompliance noted
 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs. 83/10/12 RODRIGUEZ.R J Sacramento Municipal Utility District 2pp 20959 297 24X Fiche 50-3:12:83/10/12:8310310401
- --8310310405 IE Insp Repts 50-312/82-41 on 821116-830217 No noncompliance noted Major areas inspected safety-related concrete placement & electrical installation D'ANGELO, A J. YOUNG, T. Region 5, Office of Director 83/10/11 4pp 20959 299 24% Fiche 50-312,83/10/12,8310310401
- 9310310296 Forwards IE Insp Rept 50-312/83-05 on 930514-20 No noncompliance noted BISHOP.T M Division of Resident.Reactor Project & Engineering Programs 83/10/13 RDDRIGUEZ.R J Sacramento Municipal Utility District 2pp 20961 127 24X Fiche 50-312.83/10/13,8310310296
- ---B310310304 IE Insp Rept 50-312/83-05 on B30516-20 No noncompliance noted Major areas inspected allegations associated u/welding activities performed by Nuclear Power Bys D'ANGELO, A. YOUNG.T. Region 5. Office of Director B3/10/11 5pp 20961 127 24X Fishe 50-312.83/10/13.8310310296
- 8310180094 Advises that final submittal re implementation of environ qualification equipment upgrades.per 830720 & 0520 ltr. & 1E 8031atin 79 018, will be delayed until 831031 due to unexpectedly high post-outage workload RODRIGUEZ, R. J. Bacramento Municipal Utility District 83/10/14 STOLZ, J.F. Operating Reactors Dranch 4 1p 20807 153 24X Fiche 50-312,83/10/14.8310/80094

Periodic operating reports & related correspondence

- OO40419 Nonthly operating rept for Aug 1983 H/830909 ltr CLGMBO.R., RODRIGUEZ.R J Sacramento Municipal Utility District 3/08/31 Director's Office of Price of Inspection and Enforcement 7pp. 20419 021. 24X Fiche 50-312.83/08/31.8310040419
- i10120160 Forwards corrected Table 28 listing liquid effluent batch mode isotopes in "Semiannual Effluent Release Rept, Jon-June 1783"
 RODRIGUEZ,R J Sacramento Municipal Utility District 83/09/16 MARTIN. J B Region 5. Office of Director 1p 20676 023 24X Fiche 50-312.63/09/16.8310120160
- --8310120161 Corrected Table 20 listing liquid effluent batch mode isotopes in "Semiannual Effluent Release Rept, Jan-June 1980" **

 * Sacramento Municipal Utility District, 83/06/30 | Jp 20476, 024 | 24X Fiche, 50-312, 83/07/16, 8310120160
- 310170314 Monthly operating rept for Sept 1983 W/831007 ltm COLOMBO.R., RODRIGUEZ.R.J. Sacramento Municipal Utility District. 83/09/30 Director's Office. Office of Inspection and Enforcement app 20787 001 24% Fiche 50-312.83/09/30,8310170214
 - ear Power Station Unit 1 Quarterly Repts - MOIO ltr cipal Utility District 03/09/W0 ip 20899 323 24X

- S Reportable occurrences. LHKs & related correspondence
- B310070275 RO B3-07 on B30818, heat tracing for hydrogen monitoring sys found deenergized Tracing reenergized tracing sys to operable status Check of hudrogen monitor operability on shift Frequency implemented RODRIGUEZ, R J Bacramento Municipal Utility District B3/09/13 MARTIN J B Region 5. Office of Director 19 2065/075 71X Fiche 50-312,83/09/13,8310070.75
- B310120145 LER B3-030/03L O on #30829, weekly surveillance of nitrogen gas syr discovered Xe-137 contamination Caused by installed spool piece left in place Spool piece removed & operating procedures rewritten W-830928 its COLOMBO.R W. RODRIOUEZ.R J Sarramento Municipal Utility District 83/09/27 MARTIN.J B Rogion 5. Office of Director 2pp 20694-014 Z47 Fiche 50-312.03/09/27.8310120145
- 8310120167 LER 83-033/03L-0 un 830901. Surveillance Test SF 203 O/A for NBRW pump A incorrectly signed acceptable Caused by personnel misinterpretation of data Personnel cautioned W/830930 ltr COLOMBD.R W , RODRIGUEZ.R J Sacramento Municipal Utility District 83/09/29 ARTIN.J B Region 5. Office of Director 2pp 20696 025 24X Fiche 50-312,83/09/29,8310120167
- 8310120150 LER 83-032/017-0 on 830917.RCS unidentified leakage citerded 1 gpm Caused by leaking tube 79-2 in once-through steem generator A Tube plugged & sy: stabilized W/830930 lt; CQLDM30.R W. HATTIMDE, J. J. Sacramento Municipal Utility District 83710703 MARIIN.J D. Region. 5, Office of Director 3pp 20696 008 24% Fiche 50-312.83/10703.8310120150
- 8310120186 LER 83-028/017-0 on 830919, PURV failed open & could not be closed Caused by weight of pointer attached to pilot valve actuating arm Pointer removed & alternate method to observe arm position used M/831003 lti
 CGLOMBO, R W. MATIIMOE, J J Bacramento Municipal Utility District 83/10/03 Marifold Region 5, Office of Director App 20695 328 24% Fiche 50-312,03/10/03.6310120186
- 8310120251 PNO-V-83-038A on B30917, plant shut down following discoving of steam generator A tube leak One insplane tube (70-P) plugged on B30927 Two of 360 tubes inspected showed localized thinning of approx 257 JOHNSON, P., YOUNG, T. Region 5, Office of Director 83/10/03 lp 20692 107 24% Ficho 50-312.83/10/03, 8310120251
- 8310120321 PNO-V-83-039A on 830919, PORV opened at 29 psig due to add1 weight of indicating rod added to operating handle during recent refueling outage Rod removed PORV closed on 830929 by placing V nitrogen bubble in pressuriur JOHNSON, P. YULUNG, T. Region 5, Office of Director 83/10/03 ip 20700 297 24X Fiche 50-312, 83/10/03, 8310120321
- 8310250398 LER 83-084/03L-0 on 830912, monthly auxiliary feedwater systemic Surveillance SP 210 010 not performed in correct time interval Operations personnel instructed re schedule to perform surveillance test W/R31011 Itr COLOMBO, R W. LATHAM. W K. Sacramento Municipal Utility District 83/10/11 MR3TIN, J F. Repion. 5. Office of Director Spp 20900 359 24X Fiche 50-31P, 83/10/11, 8310250598
- 8310270451 LER 83-035/03L-0 on 830920, component cooling water showed presence of trifium Xe-133.1-131 & 1-133 Caused by apparent leak in letdown conler B Cooler isolated W/831018 tr COLOMBO, R W., RODRIGUEZ, R. V. Sacramento Municipal Utylity Bystrict 83/10/18 MARTIN, J. B. Region, S. Défice of Director Spp 20923 137 247 Fiche 50-312, 83/10/18,8310270451
- 8310270452 LER 83-036/03L-0 on 830919, outboard seal in decay heat pump B (P-2618) failed, resulting in minor leakage Cause attributed to normal & expected wear on seal Seal removed & replaced W/871018 ltr CCLOMBO.R W. NORRIGUEZ, R. J. Sacramento Municipal Utility District 83/10/18 MRTIN. J B Region 5, Office of Director 2pp 20923 097 24X Fiche 50-312,83/10/18,8310270452
- 8310270206 Part 21 rept rg enging mounted electrical cobles Driective coble not installed as 830927 ltr states Parts shipped & installed on Gulf States River Brid Site (Engine Sorial 74039740 DSR 48) Instruction for coble changeout due in Nov BOYER.R & Transamerica Bolaval, Inc. 83/10/20 Director's Office. Office of Inspection and Enforcement ip 20/24 ICB PAX Fiche 50-000,83/10/20,8310270206

V Operator Examinations

- 8310040317 Application for amend to License DPR-54, extending deadling to BSO&01 for implementing 10(1850-54 changes re-shift staffing RODRIOUEZ.R J Sacramento Municipal Utility District 83/09/22 STOLZ.J Uprioting Reactors Branch 1 Spp 20620-219 24% Fiche 50-312,03/09/22,8310040317
- B3t0030149 Requests schedule by 831028, for requalification training & sears for 1984 in order to coordinate Region V audit of operator requalification programs
 SISHOP.T W Division of Resident Reactor Project & Engineering Programs 82/09/26 RODRIGUELR J Secremento Municipal Utility District 29p 20590 032 247 Fiche 50-312,83/09/26,8310030149
- DOCPET SO-DID ARKANSAS NUCLEAR UNE, UNIT 1
- f Security, medical, emergency & fire protection plans
- 8310060520 Forwards clarification of NRC positions on certain requirements of App R to 100/R50 48 STOLZ. J F , MILLLER J R Openating Reactors Branch 4 83/09/14 GRIFFIN J M Arkansas Power t Light Cu Opp 20663 139 24X Fache 50-313,03/09/14,8310060520
- 8310030416 Submits add1 info re mods to lire Zones 2100-Z & 2101-AA, per 830/13 request for App R schedular exemption Delivery of pump switchgear expected in late Jah 1964 MARSHALL, J R Arkansas Power & Light Co 83/09/27 STOL2, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 2pp 20593 166 24% Fiche 50-313.83/09/27,8310030416
- 8310040243 Releases public version of revised emergency plan implementing procedures FELTON, J.M. Division of Rulos and Records 83/09/30 Docum Management Branch ip 20660 276 24% Fiche 50-313,83/09/30, 6310060243 Document
- --8310050280 Public version of Kev 4 to Imergency Plan Implementing Procedure 1903 01. "Organization & Use of Emergency Plan Implementing Procedures" & Kev 10 to Procedure 1903 10. "Emergency Action Level Response" LEVINL.J N Arkansas Power & Light Ca 83/09/19 32pp 20460 277 24X Fiche 50-313.03/09/30.8310060243
- 631004059/ Releases public version of revised emergency plan FELTON.J M Division of Rulet and Records 63/10/05 Docum Management Branch 1p 2044 092 24% Fichs 50-313.63/10/05 631006059/7 Darument
- ~-B310060601 Public version of Rev 8 to Emergency plan W/830922 ltr MARSHALLJ R Arkansas Power & Light Co B3/09/14 COLLINS J T Region 4. Office of Director 56pp 20661 093 24x Fiche 50-313 83/10/05 83/0060897
- 6310110437 Releases public version of rev to emergency plan implementing procedure FELTON.J N Division of Rules and Records 83/10/05 Document Hanagement Branch 1p 20704 353 24) Fiche 50-313.83/10/05. Management Branch 8310110487
- --8310:10440 Public version of Rev 5 to Emergency Plan Procedure 1703 PR. "Fite or Explosion" W/83091; ltr & receipt
 - form LEVINL, J N Arkansas fower & Light Co 93/08/11 Detailed Affiliation Given 3pp 20704 394 24X Fithe 50-313,83/10/05.8310110437
- 8310250557 Withdraws request for schedular exemption until 830501 to complete installation of certain 1 h rated fire barriers Mods completed by 830422 MARSHALL.J R Arkansas Power & Light Co 83/10/07 STOLZ.J F Operating Reactors Branch 4 MILLER.J R Operating Reactors Branch 3 Lp 20700 344 247 Fiche 50-313,83/10/07.8310250559
- 8310170271 Releases public version of amind to emergency plan FELTON, J.M. Division of Rules and Records 83/10/14 Docum Management Branch 1p 20840 143 24% Fiche 50-313,83/10/14, 8310170271 Document
- --B310190292 Public version of Amond 8 to emergency plan # Arkansas Power & Light Co B3/09/14 60pp 20840 144 24X Fiche 50-313-83/10/14-83101402/1
- 8310170294 Releases public version of revised emergency plan implementing procedure
 FELTON, J M Division of Rules and Recurds 83/10/14 Docum
 Management Branch ip 2084) 341 24X Fiche 50-313,83/10/14.
 8310190294

- --8310190295 Public version of Nev 11 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response" W/B31002 to & receipt form LEVINE.J M. Alkansas Power & Light Co. 83/10/01 70pp 20841 342 24X Fiche 50-363,83/10/64,8310190294
- B310250274 Updates present status & describes tasks performed over previous 6 months per requirements of Generic Ltr 82-33 & Suppl 1 to NURLO-0/37 re control room design review Figure 2-2 encl

 MARSHALL. J R Arkansas Power & Light Co 83/10/20 FISENHUT, D C

 Division of Licensing 4pp 20902 340 24X Fiche 50-313,83/10/20,8310250274
- J Insurance ∿ indomnity information
- 8310240035 Forwards Endorsements 53,54 & 55 to NELIA Policy NF-210 & Endorsements 46 & 47 to MALLU Policy MF 74 MARSHALL J R Arkansas Power & Light Co 83/10/12 DINITY, 1 Assistant Director for State & Licenser Relations App 20881 353 24X Fishe 50-313,83/10/12,8310240035
- P Operating license stage documents & correspondence
- 8310060402 Forwards NPDES Permit AROGO1392, effective 830606 860705, per NRC 830831 ltr & util 830820 confirmation MARSHALL, J R Arkansas Power & Light Co. 83706/10 COLLINS, J T Region 4. Office of Director 3pp 20641 229 24X Fiche 50-313.83706/10.8310060402
- --8310060406 NPDES Permit AR0001372 Issued to Arkansas Power & Light Co KNUDSON N D Environmental Protection Agency 83/05/05 20pp 20641 232 P4X Fiche 50-31% 83/06/10 8310060402
- 8310050049 Forwards safety evaluation accepting Arkansas Power & Light #30607 proposed mods to reactor trip breakers Schedule for submittal of plant-apecific info needed in 10 days \$TOLZ.JF Operating Reactors Branch 4 83/09/12 GRIFFIN.J M Arkansas Power & Light Co App 20650 122 24X Fiche 50-313.83/09/12.8310050047
- 8310030353 Forwards B&W Duners Group final rept. "Bounding Analytical Assessment of NURLG-0630 Models on LDCA kW/ft Limits W/Use of FLEGEET" Approval requested MARSHALL-JR Arkansas Power & Light Co 83/09/23 STOLZ, Jf Operating Reactors Branch 4 Jp 205/i/ 200 24X Fishe 50-31% 03/09/23.8310030 (5)
- --B310030356 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft limits W/Use of FLECGET" * Babcock & Wilcox Operating Plants Owners Group 77-1140898-01 B3/09/30 108pp 20592 201 24% Fiche 30-313,83/09/23, 8310030353
- 8310110472 Forwards Franklin Research Ctr "Operating Reactor PORV Reptr (F-37)TM1 Action Plan Requirements Generic Rept-B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting D&W response to TMI Item II W 3 2 STOLZ-J F Operating Reactors Branch 4 83/09/26 (RIFFIN, J M Arkansas Power & Light Co 3pp 20/12 004 24X Fiche 50-313.83/09/26.8310110472
- 8310110472 Forwards Franklin Research Cti "Operating Reactor PORV Repts (F-37)TMI Actinn Plan Requirements Genetic Rept-B&W Designed Units:" technical evaluation rept & NRR safety evaluation accepting B&W response to [MI Item II & 3 2 STOLZ.J F Operating Reactors Branch 4 83/09/26 GRIFFIN.J M Arkansas Power & Light Co Dpp 2071P 004 24X Fiche 50-313,83/09/26.83101104/2
- --8308310422 Forwards safety evaluation accepting D&W licensee content that requirements of NURLG-0737. Item 11 K 3 2 met w/rxisting PORV, safety valve & high pressure reactor trip setpoints RQW50MF, F H Assistant Director for Technology Review 83/08/24 LAINAS. G C Assistant Director for Operating Reactors 14pp 20712 007 24X Fiche 50-313.83/09/26.8310110472
- --8307250463 "Operating Reactor PDRV Repts (F-37) TMI Action Plan Requirements Generic Rept B&W Designed Units," technical evaluation rept OVERBECK, G J., DELGAIZO, T J. Franklin Institute/Franklin Research Center NRC-03-61-130 TER-C5506-410 83/07/20 CHOW, E NRC -No Detailed Affiliation Given 58pp 20712 019 24X Fiche 50-313,83/09/26.83/01J04/P
- 8310030332 Updates 830520 request for extension of deadline for environ qualification of equipment Status of specific items enumerated enumerated MARSHALL.JR Arkansas Powur & Light Co 83/09/28 STOLZ.JF Operating Reactors Dranch 4 MILLER.JR Operating Reactors Branch 3 App 20592 311 24X Fiche 50-313.83/09/28.8310030332

- 8310120447 Responds to 930912 request for schedule for providing sufere reactor trip breaker automatic shunt trip actuation mods info will be provided as part of 120-day response to Cenotic Lth 83-28 HARSHALL, J.R. Arkansas Power & Light Co. 83/09/29 STOLZ, J.J. Operating Reactors Branch 4 1p. 20598-253 24X Fiche 50-313, 83/09/29, 8310120447
- 8310110618 Summary of B30823 meeting w/util in Bethesda.MD rellich Specs for mechanical & hydroulic snubbirs Agenda & marked-up Tech Specs encl VISSING.0 S Operating Reactors Branch 4 B3/09/30 Operating Reactors Branch 4 13pp 20715 160 24X Fiche 50-313,83/09/30. B310110618
- 8310120079 Forwards updated radiological efficient Tech Specs & offsite dose calculation manual.per 830510 request Implementation date of 850101 established ORIFFIN.J M. Arkansas Power & Light Co. 83/09/30 SfOLZ, J. Operating Reactors Branch 4 MILLER.J R. Operating Reactors Branch 3 3pp 20696 241 24X Fithe 50-313.83/09/30.8310120079
- --8310120081 Revs to radiological effluent Fech Specs * Arkansas Power & Light Co 83/09/30 | HAPP 20696 244 PAX Fiche 50-313,63/09/30-831012003/
- --8310120083 Revs to offsite dase calculation manual * Arkansas Power & Light Co 83/09/30 99pp \$0696 360 24X Fishe 50-313 83/09/30 8310120079
- 8310140225 Informs that Tech Specs for low temp overpressurization protection sys will be submitted by 831121 in response to NRC 830826 request for submittal schedule HARSHALL JR Arkansas Power & Light Co 83/09/30 STOLZ JF Operating Reactors Branch 4 lp 20/41 1/4 24X Fiche 50-313.83/09/30.8310140F25
- 8310180611 Forwards SER accepting licensee responses to NUREG-0/3/.ltum II E 1 i re emergency feedwater sys Two open items reredundent flow gaths & tormadn missile protection lemain Compliance schedule needed within 30 days STOLZ.J F Operating Reactors Branch 4 83/10/06 GRIFFIN.J N Arkansas Power & Light Co. 29pp. 20824 001 24x Fiche 50-313.83/10/06.6310180611
- 8310170096 Forwards Amend 81 to Lirense EPR-51 & safety evaluation Amend changes Tech Specs re schedules & locations of insertions of property capsules into reactor VISSING.0 S Operating Reactors Branch 4 83/10/07 GRIFFIN.J M Arkansas Power & Light Co 2pp 20813 12/ 24% Fiche 50-313.83/10/07.8310170096
- --B310170100 Amend 81 to License DPR-51, changing Tech Specs re schedules & locations of insertions of vessel mot! property capsules into reactor
 ETOL7.J F Operating Reactors Branch 4 83/10/07 3pp 20813 129 24X Fiche 50-313.83/10/07.8310170096
- --83:0170106 Safety evaluation supporting Amend 81 to License DPR-51 * Office of Nuclear Reactor Regulation, Director 83/10/07 Ppp 20813 133 24X Fiche 50-313.83/10/07.8310170096
- 8310200054 Requests written confirmation of current plectrical distribution sys configuration as discussed on 830707 as result of load shedding process not being utilized & one unit being locked off of startup transformer 2 STOLZ, J.F. Operating Reactor Branch 4 83/10/12 GRIFFIN, J.N. Arkansas Power & Light Co. 3pp. 20844 225 24X Fiche 50-313.83/10/12.8310200054
- B310210080 Requests remittance of fee due for B30215 application redeletion of terrestrial monitoring programs within 15 days MILLER. M D License Fee Management Bronch 83/10/17 GRIFFIN. J M Arkansas Power & Light Co ip 20883 251 24% Fiche 50-313.83/10/17.8310210080
- 8310310489 Summary of 830826 meeting w/B&W Duners Group reimplementation of Generic itr 83-28 concerning defenses egainst ATMS & proposed ATMS pulp for P&W plants List of attendees & viewgraphs encl
 KADAMBI.P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 83/10/20 The Standard Reactors Branch 4 13pp 20965 147 24X Fiche 50-000,83/10/20,83/10/310489

- G Inspection reports. IF Bulletins & correspondence
- 8310250141 Responds to 1E Bulletin 82-02, "Degradation of threaded Fasteners in RCPB of PNR Plants," Action Item 4 Commitments re-future insps withdrawn lnsp will continue as appropriate under applicable codes & std. MARSHALL JR Arkansas Power & Light (v. 83/07/25 (OLLING, J.1 Region 4, Office of Director App. 2/496-356 24X Fiche 50-313,83/07/25,8310250141
- 8310060020 Forwards JE Insp Repts 50-313/03-13 & 90-468/83-13 on 830606-10 No noncompliance noted SEIDLE,N C. Region 4. Office of Director 83/08/01 GRIH IN, J M Arkansas Power & Light Co. 2pp. 20647 11/6 24% Fiche 50-313.83/08/01.83100600/0
- --8310060026 IE Insp Repts 50-319/83-13 & 50-368/83-13 on 830606 16 No noncompliance noted Major areas inspected action on previous violations, outsite radiation protection organization, staff qualifications & training, exposure control & ALARA program CHANEY.H D. HOLLEY.W.L. NUKKAY.B. Region 4, Office of Dillite 83/07/20 19pp 20647 158 247 Fiche 50-313.83/08/01.8310760020
- 8310250153 Provides status of work accomplished in response to II Bulletin 79-02, "Pipe Support Base Plate Designs Unjug Concrete Expansion Anchor Bolts: "& IL Bulletin 79-14 "Seismic Analyses for As-Duilt Safety-Related Piping Sys "MARSHALL.)R Arkansas Power & Light (o. 83/08/05, COLLING.) TRegion 4, Office of Director ip 20076 343 247 Fiche 50-313.83708/05.8310250153
- 8310130220 Forwards IE Insp Repts 50-319/83-15 & 50-468/83-15 on 830701-31 No moncompliance noted SEIBLE,N C Region 4: Office of Director 83/08/10 GRIFFIN. J & Arkansas Power & Light Co 2pp 20/04 10b 24X Fiche 50-313,03/08/10,8310130720
- --8310130228 IE Insp Repts 50-313/83-15 % 50-368/83-15 on 830/81-31 No noncompliance noted Major areas inspected operational sofety verification, surveillance, maint & followup on previously identified items

 CALLAN-L J . CUMMING. J E . JOHNSON, W D . Region 4. Office of Director 83/08/95 12pp 20724 107 24X Fiche 50-313,83/08/10,8310130270
- 8310250417 Forwards "Exam of Once-Through Steam Generator Tubes O7.1 & & BI12-19 From ANO-1, " final rept Insp adequate to determine conditions & will provide sufficient data to further evaluate failure mechanism
 MARSHALL, JR Arkansas Power & Light Co B3/09/15 \$TOL2, J I Opporating Reactors Branch 4 Spp 20/02 176 24X
 Fiche 50-313,83/09/15.8310250417
- --8310280424 "Exam of Once-Through Steam Generator Tubes 873-8 & 8412 19 From AND-1: " final rept INMAN,8 C Babcock & Wilcox Co RDD 84 5303-04 02 83/06/10 161pp 2090F 179 24X Fiche 50-313-83/09/15-8310250417
- 8310130330 Forwards IE Insp. Repts 50-313/83-21 & 50-368/63-21 etc. 830801-31 & notice of violation BETDLE, W.C. Region 4: Office of Director 83/09/16 GRIFI IN. J. M. Arkansas Power & Light Co. 2pp. 20719 343 24X Fiche 50-313.83/09/16:8310130330
- --8310130333 Notice of violation from insp on 830801-31 # Region 4. Office of Director 83/09/16 4pp 20/19/045 7/4) Fiche 50-313/83/09/16/8310130330
- --Bdj0130335 IE Insp Repts 50-313/83-21 & 50-368/83 21 on 930801 ()]
 Noncompliance noted failure to properly identify calculation & design change to perform maint activities when then procedure & to install electrical cables per procedures CALLANL J. CUMMINS.J.C., JOHNSON.W.D. Region 4, Office of Director D3/09/15 lipp 20719 349 24X Fiche 50-313,83/09/16.8310130330
- B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification fests " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post E30103) B3/09/26 Consolidated Edison Co
- 8308300342 lE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syx list encl JORDAN,E L Division of Laergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 11699 20777 210 24% Fiche 50-000,03/09/26,830GC00J47

- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." Sec list anci JORDAN, L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co. of New York, Int. 118pp. 20778-001 24X Fichs 50-000.83/09/26.8309300 My.
- 8310130140 Summary of 830831 meeting w/util in Betherda.ND relicible of Dec 1982 tube inspired lungical exem of tubes pulled in Dec 1982 inspired to 5 Jul 1783 inspirance of tube degradation & corrective actions Vicualians on the VISSING C S Operating Reactors Branch 4 83/09/27 Operating Reactors Branch 4 83/09/27 Operating Reactors Branch 4 83/09/27 Reactors Branch 4 77pp 20777 073 24X Fishe 50-313.83/09/27, 8310130140
- 8308300349 IE Info Notice 83-64, "Lead Shreiding Attached to Safety-Related Syr W/o 10ClRSO 59 Evaluation " Svc list and JORDAN, E & Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 247 Fithe 50-000,87/09/29,8306000049
- 8308360778 IC Info Notice 83-45. "Surveillance of Flow in RTD Bypess Loops Used in Mestinghouse Plants " Sur list encl JORDAN,E L Division of Loopsency Preparedness & Engineering Response (Past 030103) 63710/07 (onsolidated Edison to of New York, Inc. 74pp 20827 213 24x Fache 50-000,83/10/07.8368360303
- B30B300752 IC Info Notice 83-66. "Tatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Embryancy Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 076 24X Fishe 50-000,83/10/07.8308300752
- B30B30G759 IE Info Notice B3-67, "Emergency Use Respirator Matl Befect Causes Production of Noxious Cases" Svc list enci JDRDAN, C 1. Division of Leergency Preparedness & Engineering Response (Host B30103) B3/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fichs 50-000, B3/10/11, 830B300759/
- B308300761 IE Info Notice 83-68, "Respirator User Waining Defective Solf-Contained Breathing Apparatus Air Cylinders" Svc list enci JORPAN. C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 2002/129 24X Fiche 50-000.03/10/11,8308200/41
- A Periodic operating reports & related correspondence
- GDIO190117 Monthly operating rept for Aug 1983 W/830915 ltr MARSHALL, J.R., MORTON, K.L., Arkansas Prwer & Light Co. 83/09/15 BASSETT, H.B. Division of Data Automation & Management Information 7pp 20920 333 24X Fiche 50-313,83/09/15,8310190117
- S Reportable occurrences. LLRs & related correspondence
- O310040134 LER 83-080/03L-0 on B30828, lead hydrogen purge fan VEI-37A indicated law output flow Caused by debris collected at vaive HPA-132 Valve internals cleaned W/830920 ltr RDGERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 83/09/20 SCIBLE, W. C. Region 4, Office of Director 2pp 20608 037 24X Fiche 50-313, 63/09/20, 83/09/40154
- DUCKET 50-315 DDNALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, Emergency & fire protection plans
- 8310030391 Forwards description of Cluss A radiation dase assessment model, per util 830415 jtr Mutcorological info & dose assessment sys Class A (ACRISH) program will be primary dose assessment model in emergency operations facility ALEXICH.MP Indiana & Michigan Electric Co 83/09/27 DENIUN, H k Office of Nuclear Reactor Regulation, Director 7pp 20593 056 24X Fiche 50-315.03/09/27.0310030391
- B310030544 Releases public vorsion of revised emergency plan (FSAR Chapter 12 3)
 FELTON, J M Division of Rules and Records 83/09/28 Document Hanagement Branch 1p 2060b 338 24X Fiche 50-315,83/09/28, 8310030564
- ---83100305/9 Public version of Nev 2 to theigency plan (ISAR Chapter 12 3) W/830916 ltm ALEXICH.H P Indiana & Michigan Electric Co 83/09/16 DEMYON.H R Office of Nuclear Reactor Regulation, Director 417pp 20605 339 24X Fiche 50-315,83/09/28,8310030564

- --B310060479 Public version of revised index for plant manager procedures W/830919 ltr # Indiana & Michigan Electric Co. B3/09/19 NRC No Certain M Affiliation Given 15pp 20660 173 24X Fiche 50-315 83/4 ** 8310060474
- B310110433 Releases public version of revised pages to App A net emergency plan procedures FELTON J M Division of Rules and Records B3/10/05 Dollars and Management Branch | 1p | 20704 357 | 24X Fithe 50-315, 83/10/05 | 8310110433
- --B310110434 Public version of Rev B to Pages 9a % 7b of emerger plan procedures, App A Receipt form encl
 # Indiana & Michigan Electric Co B3/07/20 App 20/04 IFra
 24X Fiche 50-315, 83/10/05, 8310110433
- 8310240093 Forwards IE Insp Repts 50~315/83-14 & 50~316/83-15 on 830722-0909 No honcompliance noted SHAFER: W D Region 3: Office of Director 83/10/05 DDLAN : « American Electric Power Service Corp DDLAN. J E Indiana & **Liniag* Electric Co 2pp 20881 005 24% Fichs 50~315,83/10/05 831.4.4.
- --8310240100 IE Insp Repts 50-315/83-14 & S0-316/83-15 on 830 12 / C / Tu etc., noncompliance noted Major areas inspected operational safety, maint surveillance, LCRs, design changes, fire protection/prevention program & refueling activities SHANSON, E R / DUBRY, N E / BDYD, D C Region 3, Office of Ulrert 5 83/10/03 10pp 20881 007 24y Fiche 50-315,83/10/05 8310 4
- 8310250391 Forwards FEMA 83092B ltr providing status of final fixed of offsite preparedness State & local plans & preparedness adequate to protect public PAPERIELLO,C J. Region 3. Office of Director 83/10/21 Ltd. American Electric Power Service Corp. BOLAN.J E. Indiana & Michigan Electric Co. 1p. 20897-280 24X Fishe 50-315-83/17....1
- --8310250401 Comments on status of offsite emergency preparedness at we.

 10cal plans & preparedness adequate to protect health &
 safety of public Approval conditional on verification of
 public alerting & notification sys per NUREG-0054
 MCLAUGHLIN.D Federal Emergency Management Agency 83/09/204
 DIRCKS,W J Office of the Executive Director for Operations 1 &
 20897 281 24X Fiche 50-315,83/10/21,8310250391
- B310270190 Ack receipt of B30916 & 30 ltis transmitting scree & objectives for B31130 emergency preparedness exercise Exercise scenario should be submitted by B31211 & completed controller package by B40105 PAPERIELLO, C J Region 3. Office of Director B3/10/24 ALEXICH.H P Indiana & Michigan Clectric Co ALEXICH.H P Acceptable Corp 2pp 20924 185 24X Fiche 50-315,83/10/24,8310270190
- J Insurance & indemnity information
- B310240119 Forwards Endorsement 5 to NELIA Certificates N-45 k M 企本 是 MAELU Certificates M-45 k M-64
 BUCKLES, J A Marsh & McLennan, Inc 83/10/12 SALTZMAN, J
 Assistant Director for State & Licensee Relations 5pp 200余3 1 年均
 24X Fiche 50-315,83/10/12,8310240119
- K Utility Final Safety Analysis Report (FSAR) & amends
- B310030564 Releases public version of revised emergency plan අම උදේශ් Chapter 12 3) FELTON.J M Division of Rules and Records B3/09/20 පිරුද මෙළේ ල ක Kanagement Branch ip 20605 33B 24X Fiche 50-315,83/09/ථක්ඛ B310030564
- --B310030579 Public version of Rev 2 to Emergency plan (FSAK Chapter 12 3) W/B30916 ltr ALEXICH, M P Indiana & Michigan Electric Co B3/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Directs 417pp 20605 339 24X Fiche 50-315.83/09/28.8310030364

F Operating license stage documents & correspondence

- B310310017 FDIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L. Affiliation Unknown B3/05/02 NRC Nn Detailed Affiliation Given lp 21004 2/0 24% Fiche 50-000.83/05/02. B310310017
- B310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be place in PDR & list of facilities for which repts are unavailable FELTON.J M. Division of Rules and Retords 83/07/06 (ONNER, L. Affiliation Unknown is 21004 27) 24% Fiche 50-000.83/07/06.8310310031
- --8310310077 "Reactor Containment Blog Integrated Leak Rate Test"

 * Indiana & Hichigan Power Co 75/02/26 67pp 21007 215 24x
 Fiche 50-000,83/07/06.8310310031
- 8310050963 Addendum to 830511 application to amend License DPN-50 re Cycle 8 startup operations Addendum includes revs to 830511 proposed Tech Specs Attachments 8-41 includes safety evaluation replacement & answers to NRC questions ALEXICH.M P Indiana & Michigan Electric Co 83/07/29 DENIUN.H: Office of Nuclear Reactor Regulation, Director 4pp 20633 001 24X Fiche 50-315,83/07/29,83100505063
- --B310050567 Proposed Tech Spec revs reanalyzing worst large break LDCA case using initial fuel rod conditions determined from currently approved PAD fuel thermal safety model Attachments B-H encl

 4 Indiana & Michigan Electric Co 83/07/29 150pp 20633 00% 24X Fiche 50-315.83/07/29.8330050563
- 8310050102 Advises that 830908 submittal of revised calculation results re-cladding strain, oxidation & pellet cladding interaction using RODEX2 code meets requirements of license condition Request for extended license condition unnecessary VARQA.S A Operating Reactors Branch 1 83/09/20 DDLAN.J Indiana & Michigan Electric Co DDLAN.J American Electric Power Service Corp 2pp 20650 240 24X Fiche 50-315.83/09/20.
- 8310070408 Forwards BER re control of heavy loads based on util response to 801222 generic ltr Guidelines in NUKEG-0612. Section 5 1 1 & 5 3 satisfied VARGA.8 A Operating Reactors Branch I 83/09/20 DOLAN, J Indiana & Michigan Electric Co 2pp 20675 332 24X Fiche 50-315,83/09/20,8310070408
- --8310070409 Safety evaluation re control of heavy roads Guidolines in NUREG-0612, Section 5 1 1 & 5 3 satisfied * NRC - No Detailed Affiliation Given 83/09/20 2pp 20675 334 24X Fiche 50-315,83/09/20,8310070408
- ~~B309060263 "Control of Heavy Loads (C-10) Indiana & Michigan Electric Co.DC Cook Nuclear Plant Units i & 2," technical evaluation rept VOSBURY.F W , BDMBERGER.C R Franklin Institute/Franklin Research Center NRC-03-Bi-130 IER-C5506-344/345 83/09/01 \$1NGH.A NRC - No Detailed Affiliation Given 33pp 206/5 336 24X Fiche 50-315,83/09/20,8310070400
- HOt10333 Forwards Amend 74 to License DPR-58 & safety evaluation Amend approves Cycle 8 reload & changes related Tech Specs WIGGINTON D. L. Operating Reactors Branch | B3/09/20 DOLAN, J. Indiana & Michigan Electric Co DDLAN, J. American Flectric Power Service Corp. 3pp. 20685-259 24X Ficho 50-315,83/09/20,8310110333
- --83i0110334 Amend 74 to License DPR-58, approving Cycle 8 reload & changing related Tech Specs VAROA, S.A. Operating Reactors Branch 1 83/09/20 65pp 20685 262 24X Fiche 50-315,83/09/20,8310110333
- --8310110335 Safety avaluation supporting Amend 74 to License DPR-58 * Office of Nuclear Reactor Regulation, Director 03/09/20 24pp 20685 326 24% Fiche 50-315.83/09/20,8310110333
- 3310030386 Supple & amends 830520 & 0810 requests for extensions required in 10CFR50 49 re equipment environ qualification ALEXICH.M P Indiana & Michigan Electric Co 83/09/26 DENION,H R Office of Nuclear Reactor Regulation, Director 4pp 20592 323 24X Fiche 50-315,83/09/26,8310030386
- 8310060028 Summary of 830913 meeting w/util in Bethesdo. HD re environ qualification of electrical equipment & hydrogen control H1001NTON.D Operating Reactors Branch I 83/09/27 Operating Reactors Branch I 11p 20664 JiO 24X Fiche 50-315.83/09/27, 8310060028

- 8310060946 Approves 830902 requist to use later editions of ABMI Section XI Gode for test temp requirement for hydrostatic tests of Class 1 & 2 austernitic stainless steel piping & components

 VARGA,S A Operating Reactors Blanch 1 83/09/20 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Siectric Power Service Corp Dep 20661 284 Fiche 50-315,83/09/28,
- 8310130217 Forwards Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively Amends change Tech Spec to require redundant containment hydrogen analyzers to satirfy requirements of NUREG-0737. Thi Action Item II F i 6
 VARGA. S A Operating Reactors Branch I 83/09/30 DDLAN, J Indiana & Michigan Electric Co DDLAN, J American Electric Power Service Corp 3pp 20777 100 249 Fiche 50-315,83/09/30.
- --8310130222 Amends 75 & 56 to Licenses bPR-58 & DPR-74, respectively, changing Tech Spec to require redundant containment hydrogen analysers to satisfy requirements of NUREG-0737, TMI Action Item II F I 6
 VARCA, S A Operating Reactors Branch I 83/09/10 9pp 20777 183 24% Fiche 50-315,83/09/30,8310130217
- 9310060006 Application to amend License MPR-98, revising Tech Spec 4 5 2 f to increase total flow limit to four branch lines from 470 ypm to 500 gpm on boron injection sys (single centrifugat charging pump)
 ALEXICH.H P Indiama & Michigan Electric Co 83/10/03 DLN108.31.

 Office of Nuclear Reactor Regulation, Director VARGA.5 A NRC No Detailed Affiliation Given 3pp 20645 266 24X
 Fiche 50-315,83/10/03.8310060000
- --B310060329 Proposed Tech Spec re ECCS * Indiana & Michigan Electric Co 83/10/03 2pp 20645 269 24X Fiche 50-315,83/10/03,8310060006
- 8310140040 Forwards response to SA Varga 820730.0916 & 830810 requests for add1 info re hydrogen combustion & control during degraded core accidents
 ALEXICH.H.P Indiana & Michigan Electric Co 83/10/10 DENTUN.II R
 Defice of Nuclear Reactor Regulation, Director 99pp 20/68 685
 24X Fiche; 50-315, 83/10/10, 8310140040
- --8310140042 "Fog Inerting Analysis for PWR Ice Condenser Plants " TSA1,9 9 Westinghouse Electric Corp 81/11/30 107pp 20748 145 24% Fiche 50-315,83/10/10,8310140040
- --8310140046 Speech entitled "Fog Inerting Criteria for Hydrogen/Air Mixtures," presented at 821003-07 Second Intl Workshop on Impact of Hydrogen on Water Reactor Safety in Albuquerque, NM TSAI.8 8 , LIPARULO, N J Westinghouse Electric Corp 82/10/03 15pp 20768 255 24X Fiche 50-315,83/10/10.8310140040
- 8310210034 Summarizes actions taken during scheduled refueling outage beginning 830715 Eddy current exam performed on steam generators before refueling activities Westinghouse rept on steam generator tube degradation mechanism awaited SMITH.W 0 Indiana & Michigan Electric Co 83/10/10 KEPPLER, J 0 Region 3, Defice of Director 5pp 20/856 006 24X Fiche 50-315.83/10/10.8310210034
- 831020015B Requests extension until 831215 to submit rept on plant-specific evaluation of relief & safety valve, & associated piping sys-per NURFG-0737, Item II D 1 2
 ALEXICH,M P Indiana & Michigan Electric Co 83/10/14 DENTIN, H & Office of Nuclear Reactor Regulation, Director 2pp 20036 313
 24X Fichs 50-315, 83/10/14, 8310200158
- O Inspection reports. IE Bulletins & correspondence
- 8310120293 Ack receipt of 830906 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-315/83-12 & 50-316/83-13 & SHAFER.W D Region 3. Office of Director 83/09/19 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michiga Electric Co 19 20692 341 24X Fiche 50-315.83/09/19.8310120293
- 8310130025 Forwards SER & technical evaluation rept re respondet to II Bulletin 80-11. "Masonry Wall Design " Joint reinforcement masonry walls not well established Structural element not acceptable Response requested VARGA.S A Operating Reactors Branch I 83/09/20 DOLAN./ Indiana & Michigan Electric Co DOLAN.J American Electric Fumer Service Corp 3pp 20772 146 24X Fiche 50-315,83/09/20,8310130025
- --8310130026 Safety evaluation supporting mods re IE Bulletin BO·ll, "Masonry Wall Design" * Office of Nuclear Reactor Regulation, Director 83/09/20 Ppp 20772 149 24% Fiche 50-315/83/09/20,8310130025

- --B368030382 Revised "Masonry Wall Design (B-59).DC (ook Nucliar Plant, Units i & 9," technical evaluation rept TRICLO.S., CON.V.N. Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-05506-241 ROL 83/07/27 CHOKSHIN NRC No Detailed Affiliation Given 38pp 20772 151 ,4X Fiche 50-315,83/09/20.8310130025
- 8308300340 IE lnfo Notice 83-61. "Alleged Use of Stand Ins for Welder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 (unsolidated Láison Co. of New York Inc 117pp 20754 022 24% Fiche 50-000.83/09/26.8308/400340
- 8308300342 IE info Notice B3-62. "Failure of Redundant foxic (.as Detectors Positioned at Control Room Vent; lation A;) Intakes "Gvc list encl JORDAN, E L Division of Lmergency Preparedness & Engineering Response (Post 830103) 83/09/26 (onsolidated Edison Co. of New York, Int. 116pp 20777 P10 24X Fiche 50-000.03/09/26.8308/0034)
- 8308300345 IE Info Notice 83-63. "Potential failures of Westinghouse Type 8A-1 Differential Relays " Svc list oucl JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York Inc. 118pp 20778 001 24X Fiche 50-000.83/09/26.8308.30034/,
- 8308300349 IE info Notice 83-64, "Lead Shie)ding Attached to Safety-Related Sys W/o 10CfR50 59 Evaluation " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison to of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8388400447
- 8310240093 Forwards IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909 No noncompliance noted SHAFER.W D Region 3, Office of Director 83/10/05 DOLAN, J L American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co
- --8310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830/2P 0707 No noncompliance noted Major aleas inspected operational safety, maint, surveillance, Lttps, design changes, fire protection/prevention program & refueling activities SMANSONE R , DUBRY, N E , BUYD, D C, Region 3, Office of Director 63/10/03 10pp 20881 007 24x Fiche 50-315,83/10/05,8310240093
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Flants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Ldison Co of New York, Inc 76pp 20827 213 24% Fiche 50-000,83/10/07,8308300378
- B308300752 IE Info Notice 83-66, "Tatality at Argentine Critical Facility " Svc)ist encl J0828N.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fishe 50-000,83/10/07.8308300/52
- 8310210036 Summarizes actions taken during scheduled refueling outage beginning 830715 Eddy current exam performed on steam generators before refueling activities Westinghouse rept on steam generator tube degradation mechanism awaited SMITH.W G Indiana & Michigan Electric Co 83/10/10 KEPPLER.J C Region 3. Office of Director Sup 26896 006 24X Fiche 50-315,83/10/10.8310210036
- 8308300757 lE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Goses" Stt list entl JCRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York. Inc. 117pp 21043-075 PAX Fiche 50-000.83/10/11.8308300759
- B308300761 IE Info Notice 83-68, "Respirator Usor Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Syr list enc!

 JORDAN, E. Division of Emergency Preparedness & Engineoring
 Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp. 20827 129 24X Fiche 50-000, 83/10/11,8309500741
- 8310180374 Clarifies NRC position on procedures for admitting NRC personnel to facility Access to vital areas should be afforded to listed Region III personnel Update will be provided every 6 months

 AXELSON: W.L. Region 3. Office of Director 83/10/14 DDLAN, J I American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 7pp 20803 185 24X Fichs 50-315,83/10/14,8310180374

- R Periodic operating reports & related correspondence
- 8310190070 Monthly operating rept for Aug 1983 W/830914 ltr GlLETT.W T , SMITH.W G 3VENSON.B A Indiana & Michigan Electric Co 83/09/14 Division of Data Autimation & Management Information 6pp 20822 282 24X Fichs 50-315,83/09/14.8310170070
- S Reportable occurrences, LERs & related correspondence
- 8310120260 LER 93-091/03L-0 on 830829, dusing refueling outage, fire door leading to contractor access area inadvertently damaged when door closed w/piece of steel between door jam & edge of door Caused by personnel error Door repaired W/830928 Itr WELCHER, D.W. SMITH-W.C. Indiana & Michigan Electric Co. 83/09/28 KEPPLER, J.O. Region 3, Office of Director 2pp. 20693 008 P4X Fiche 50-315,63/09/28,8310120260
- 8310120343 LER 83-0B9/0GL-0 on B30628.31-day visual verification of blind flangs over fuel transfer tube uPN-1 deleted from all revs Caused by verification deleted in 750407 rev Change sheet written to include CPN-1 in procedure W/830927 Itr STEPHENS.TR . SMITH.W © Indiana & Michigan Electric Co B3/09/28 KEPPLER.J @ Region 3. Office of Director 3pp 20700 260 24% Fiche 50-315.83/09/28.8310120343
- 8310060369 RO on B30929, during insp of containment lower velone drop per second leak discovered on nonessential svc water sys Leak originated at packing on manual isolation valve Followup rept will be submitted within 14 days BMITH.W 0 Indiana & Michigan Electric Co 83/09/29 KEPPLER, J 0 Region 3, Office of Director 1p 20646 120 24X Fiche 50-315,83/09/29.8310060369
- 8310120177 RO on B30930, while making pre-startup valve lineups, discovered pump reversal on component cooling water supply & return prints for containment H sampling sys Sys being reviewed to determine effect during accident conditions SMITH.W © Indiana & Michigan Electric Co 83/10/03 KEPPLER, J © Region J, Office of Director 1p 20674 103 24X Fiche 50-315.83/10/03.83(0120197
- 8310140027 Updated LER 83-054/0JX-1 on 830526, during surveillance valve lineup on diesel generator IAB. Fuel oil day tank level column high side isolation Found closed Cause unknown investigation continuing W/B31005 ltr KRAUSE.D.F., SMITH.W.O. Indiana & Michigan Electric Co. 89/10/05 KEPPLER, J.O. Region 3, Office of Director ... Jpp. 2076B 080 24X Fiche 50-315,83/10/05.83/0140027
- 8310140084 LER 83-092/03L-0 on 830912, essential svc water pump (W relay timer exceeded Tech Spec tolerance Caused by instrument drift Timer recalibr W/831005 ltr PALMER, R A , BMITH, W O Indiana & Michigan Electric Co B3/10/05 KEPPLER, J O Region 3, Office of Director 2pp 20766 295 24X Fiche \$0-315,83/10/05,8310140084
- B310170387 NPDES noncompliance notification on 830917,24 h composite sample from turbine room sump not collected Caused by stuck valve Notification to State of MI encl
 SMITHLW G Indiana & Michigan Electric Co B3/10/05 KEPPLEH, J G Region 3. Diffice of Director 2pp 20785 031 24X
 Fiche 50-315,83/10/05.8310170487
- 8310170357 RG on 831007, whong valves used for Ep(Z) in-core detector computer code during Cycle VIII operation 8MITH.W G Indiana & Michigan Electric Co 83/10/10 KEPPLLR.J G Region 3. Opfice of Director ip 20764-319 24X Fiche 50-315.83/10/10.8310170357
- B310210137 RO on B31003.24 h rept notification made to incorrect installation of containment hydrogen monitoring sys Gys modified & reinstalled correctly on 831005
 SMITH.W G Indiana & Michigan Electric Co 83/10/11 XEPPLER, J G Region 3, Office of Director ip 20056 079 24X
 Fiche 50-315.83/10/11.8310210137
- 8310210040 LER 83-075/01T-0 on 830928.3-inch gate valve manual isolation to 1-CIT-1 containment cleanup for charcoal bed spray nozzles found w/packing leak Caused by packing wear Adjustment stopped leak Leaks unavoidable W/831012 ltm PIEHLR H , SMITH, W 9 Indians & Michigan Electric Co 83/10/12 KEPPLER, J G Region 3. Office of Director 2pp 20855 330 24) Fiche 50-315,83/10/12.8310210040
- 8310210187 Forwards updated LERt 83-043/03X-1 & 63-055/03X-1 & LERs 83-093/03L-0 & 63-094/03L-0 SMITH W 0 Indiana & Michigan Electric Co 83/10/12 KEPPLER, J Q Region 3, Office of Director ip 20856 100 24X Fiche 50-315,83/10/12.8310210187

- --8310210191 Updated LER 83-043/03X-1 un 830513 control room emergenty pressurization chartoal filter Fire/trouble alarm activated Caused by high prealarm & alarm resistance settings edjusted PALMER, R A Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 1p 20896 101 24X Fiche 50-315,83/10/12. 8310210187
- --8310210197 Updated LER 83-055/03X-1 on 830529, west motor-driven auxiliary feed pump low suction pressure switches failed Cause unknown Reset values high out of spec Switch replaced PALMER, R A Indiana & Michigan Electric Co 83/10/12 Region 3, Office of Director 2pp 20855 102 24X fiche 50-315, 83/10/12,8310210197
- --8310210199 LER 83-093/03L-0 on 830915, false event recorded on diesel generator CD room peak recording accelerameter Cause not stated Personnel cautioned PALMER.R A Indiana & Michigan Electric Co 83/10/12 legion 3. Office of Director 2pp 20856 104 24X Fiche 50-315, 83/10/12,8310210187
- ---8310210202 LER 83-094/03L-0 on 830922,4-kV loss of voltage relays 27-1-TijD & 27-3-TijD exceeded tolerance Caused by instrument drift Relays reset PALMER.R A Indiana & Michagan Electric Co 83/10/12 Region 3. Office of Director jp 20856-106 24X Fiche 50-315.83/10/1/,8310210187
- 83i0200i65 Part 21 rept re static temp calibr check on transmittorn Initially reported on 83i013 Caused by irregular setpoint for pressurizer pressure safety injection function New 1.824 paig setpoint recommended RAME.E.P. Mestinghouse Electric Corp. 83/10/13 DEYGUNG.R.C. Director's Office, Office of Inspection and Enforcement 2pp 20834 078 24X Fiche 50-000.83/10/13.8310200165
- 8310210113 Interim deficiency rept re calibr technique for temp compensation on Barton transmitters Westinghouse Part 21 rept described undefined errors at abnormal & accident temps. Nest rept in 14 days
 SMITH.W G Indiana & Michigan Electric Co 83/10/14 KEPPLIK, J G Region 3, Office of Director 1p 20858 234 24X
 Fiche 50-315,83/10/14,8310210115
- 9310270204 Forwards updated LER 93-077/03X-1 & LERS 93-096/03L-0 & 83-097/03L-0 83-097/03L-0 SMITH.W © Indiana & Michigan Electric Co 83/10/18 KEPPLEN, J G Region 3. Office of Director Ip 20923 282 24X Fiche 50-315, 83/10/18, 8310270204
 - '310270213 Updated LER 83-077/03x-1 on 830810, two nonessentia) evoluter valves missing from containment integrity procedure & one cap needed Instrument isolations identified on air lock Caused by personnel error
 KRAUSE.D F Indiana & Michigan Electric Co 83/10/18 Region
 3, Office of Director 2pp 20923 283 24x Fiche 50-315, 83/10/18,8310270204
 - 10270223 LER 83-096/03L-0 on 830924, during refueling outage. Fire Door 517 would not latch properly between contractor access control & auxiliary bidg Caused by lonse active leaf latching mechanism Mechanism tightened HIZMER. D 9 Indiana & Michigan Electric Co 83/10/18 Region 3, Office of Director 1p 20923 285 24% Fiche 50-315, 83/10/18, 8310270204
- -8310270271 LER 83-097/03L-0 on 830921.during refueling outage.Fire Door 373 would not latch properly to 591 elevation vestibule area Caused by sticky latch mechanism Muchanism adjusted.lubricated.tested & returned to svc PIEHL.R H Indiana & Michigan Electric Co 83/10/18 Region 3, 0ffice of Director 1p 20923 286 24% Fiche 50-315.83/10/18, 3310270204
 - 70226 LER 83-078/017-0 on 931006 notified by vendor that wrong Jes for Ep(2) used for in-core detector computer code ised by failure of personnel to update input data set card E to reflect Tech Spec changes W/831019 ltr
 MERR A . SMITH, W G Indiana & Michigan Electric Co 83/10/19
 PLER. J G Region 3, Office of Director 4pp 20924 036 24X he 50-315,83/10/19.8310270226

- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UN11 P F Security, medical, emergency & fire protection plans
- 8310030391 Forwards description of Class A radiation dose assessment model.per util 830415 Itr Meteorological info & dose assessment sys Class A (ACRISU) program will be primary dose assessment model in emergency operations facility ALEXICH, M P Indiana & Michigan Electric Co 83/09/27 DENIUN, H & Office of Nuclear Reactor Regulation, Director 7pp 20993 (156 24X Fiche 50-315,83/09/27,8310030391
- B310030544 Releases public version of revised emergency plon (ISAM Chapter IP 3)
 FELTON, J M Division of Rules and Records B3/09/20 Document Management Branch Ip 20605 338 24X Fichs 50-315, 83/09/20, 831000544
- --8310030579 Public version of Rev 2 to emergency plan (FSAR Chapter 12 3) W/830916 ltr ALEXICH M P Indiana & Michigan Electric Co 83/09/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 417pp 20605 339 24X Fiche 50-315.83/09/28.8310030564
- 83:0060474 Releases public version of revised index for plant manager procedures FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20660 172 24% Fiche 50-315,83/09/30, 83100604/4
- --8310060479 Public version of levised index for plant manager procedures W/B30919 ltr

 Indiana & Michigan Electric Co. 83/09/19 NRC No Detailed Affiliation Given. 15pp. 20660-173 24X Fiche. 50-315.83/09/30, 8310040474
- B310110433 Releases public version of revised pages to App A of emergency plan procedures
 FELTON, J. M. Division of Rules and Records B3/10/05 Document Management Branch 1p 20704 357 24% Fiche 50-315, B3/10/05, B310110433
- --8310110434 Public version of Rev 8 to Pages 9a & 9b of emergency plan procedures, App A Receipt form enc 1 * Indiana & Michigan Electric Co 83/07/20 4pp 20704 358 24X Fiche 50-315.83/10/05.8310110434
- B310240093 Forwards IE Insp Repts 50-315/83-14 & 50-316/83-15 on B30722-0909 No noncompliance noted SHAFER, W D Region 3, Office of Director 83/10/05 DOLAN, J G American Electric Power Service Corp 2pp 20881 005 24X Fiche 50-315,83/10/05,8310240093
- --8310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909 No noncompliance noted Major areas inspected operational safety, maint surveillance, Lifts, design changes, fite protection/prevention program & refueling activities SWANSON, E.R. Region 3, Office of Director 83/10/03 10pp 20881 007 24X Fiche 50-315.83/10/05.8310240093
- 8310250391 Forwards FEMA 830928 ltr providing status of final findings of offsite preparedness State & local plans & preparedness adequate to protect public PAPERIELLO, C. J. Region 3, Office of Director 83/10/21 DDLAN, J. American Electric Power Service Cosp DDLAN, J. E. Indiana & Michigan Electric Co. 1p. 20897 280 24% Fiche 50-315,83/10/21.
- --8310250401 Comments on status of offsite emergency preparedness 'Statu' local plans & preparedness adequate to protect health & safety of public Approval conditional on verification of public alerting & notification sys per NUREO-0654 MCLAUGHLIN,D Federal Emergency Management Agency 83/09/28 DIRCKS,W J Office of the Executive Director for Operations Ip 20897 281 24X Fiche 50-315,83/10/21,8310250391
- 8310270190 Ack receipt of 830916 & 30 ltrs transmitting scope & objectives for 831130 emergency preparedness exercise Exercise scenario should be submitted by 831211 & completed controller package by 840105
 PAPERIELLO, C. J. Region 3, Office of Director 83/10/24
 ALEXICH.M.P. Indiana & Michigan Electric Co. ALEXICH.M.P. American Electric Power Service Corp. 2pp. 20924 185 24X
 Fiche 50-315.83/10/24.8310270190
- --8310270196 Forwards scope & objectives for 831100 pmergency
 preparedness exercise Scenario will be submitted by 83101/
 & completed controller/prompter package by 831110
 ALEXICH.M P Indiana & Michigan Electric Co 93/09/16
 KEPPLER.J G Region 3. Office of Director 7pp 20724 187 348
 Fiche 50-315,83/10/24,8310270190

- ♪ Insurance % indemnity information
- 8310240119 Forwards Endorsement 5 to NELIA (ertificates N-45 & N 64 & MAELU Certificator M-45 & N-64 BUCKLES, J A Marsh & McLennan, Jac 83/10/12 SALI/HAN, J Assistant Director for State & Licensec Relations 5pp 20881 140 24% Fiche 50-315,83/10/12,8310240119
- F Utility Final Safety Analysis Report (FSAR) & amends
- G310030564 Releases public version of revised emergency plan (1'Add Chapter 12 3) FELTON,J M Division of Rules and Records 83/09/28 Decument Management Branch 1p 20605 338 247 Fiche 50-315, 03/09/28,
- --8310030579 Public version of Nev 2 to emergency plan (FGAR Chapter 12 3) W/830916 ltr ALEXICHM P Indiana & Michigan Electric Co 83/09/16 BERTON, H R Office of Nuclear Reactor Regulation, Director 417pp 20605 339 24X Fishe 50-315,83/09/28,8310030564
- P Operating license stage documents & correspondence
- 8310310017 FOIA request for documents re integrated leak rate to the Placed in PUN
 Listed facilities to be placed in PUN
 COMMER.L. Affiliation Unknown 63/05/02 NRC No Detailed
 Affiliation Given ip 21004 2/0 24% Fiche 50-000,63/05/02,
 8310310017
- B310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be place in PDR & list of facilities for which repts are unavailable FELTON. J M Division of Rules and Records B3/07/06 (ONNER. t. Affiliation Unknown ip 21004 271 24X Fiche 50-000.83/07/06.
- --8310310080 "Reactor Containment Bldg Integrated Loak Rate lent (Preoperational) "

 * Indiana & Michigan Power (o * American Electric Power Co.;
 Inc. 76/04/10 121pp 21007 283 24X Fiche 50-000,83/07/05.
 9310310031
- 8310050102 Advises that 830908 submittal of revised calculation results re-cladding strain, exidation & pellet-cladding interaction using RODEX2 code meets requirements of license condition Request for extended license condition unuecessary VARGA:B A Operating Reactors Branch 1 83/09/20 DDLAN,J Indiana & Michigan Electric Co DDLAN,J American Liectric Power Service Corp 2pp 20650 P40 24X fiche 50-315.83/09/20, 8310050102
- 8310070408 Forwards BER re-control of heavy loads based on ut))
 response to 801222 generic ltr Guidelines in NURC9-06J2.
 Section 5 1 1 & 5 3 satisfied
 VARGALE A Operating Reactors Branch 1 83/09/20 DOLAN., I
 Indiana & Nichigan Electric Co 2pp 80675 332 E4X
 Fiche 50-315,83/09/20,8310070408
- --8310070409 Bafety evaluation re control of heavy loads Guidelines in NUREG-0612. Section 5 1 1 & 5 3 satisfied

 NRC No Detailed Affiliation Given 83/09/20 2pp
 20475 334 24X Fiche 50-315.83/09/20.8310070400
- --8309060263 "Control of Heavy Loads (C-10) Indiana & Michigan Electric Co.DC Cook Nuclear Plant Units 1 & 2." technical evaluation rept VOSBURY, F W . DOMBERGER, C R Franklin Institute/Franklin Research Center NRC-03-61-130 TEK-05906-344/345 83/09/01 SINGH, A NRC No Detailed Affiliation Given 33pp 206/5 336 24X Fache 50-315,83/09/20,83100/0408
- 9310030386 Supple & amends 830520 & 0810 requests for extensions required in 10CFR50 49 re equipment environ qualification ALEXICH.M P Indiana & Michigan Electric Co 83/09/26 DENTUN.H & Office of Nuclear Reactor Regulation, Director 4pp 20592 323 24X Fiche 50-315,83/09/26,8310030386
- 8310060028 Summary of 830913 meeting w/util in Bethesda, MD re environ quælification of electrical equipment & hydrogen control WIGGINTON D Operating Reactors Branch 1 83/09/27 Operating Reactors Branch 1 11p 20664 110 24X Fiche 50-315,83/09/27, 8310060028

- 8310060546 Approves 830702 request to use later editions of ASME Section XI Code for test temp requirement for hydrostatic tests of Class 1 & 2 austenitic stainless steel piping & companents
 VARQA. S A Operating Reactors Branch 1 83/09/20 DDLAN, J Indiana & Michigan Electric Co DDLAN, J American Electric Power Service Corp 3pp 20661 284 24X Fishe 50-315,83/09/28,8310040546
- 8310070225 Notification of 831013 meeting w/util & Exxon in Brthcsda,MD to discuss resolution of license conditions imposed on Cycle 4 aperation & content of Cycle 5 reload submittal HIGGINTON,D Operating Reacturs Branch 1 83/09/30 VARGA,S A Operating Reacturs Branch 1 2pp 20664 360 24X Fiche 50-316,83/09/30,8310070225
- 8310130217 Forwards Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively Amends change fach Spec to require redundant containment hydrogen analyzers to satisfy requirements of NUREG-0737.TMI Action Item II F I & VARGA.S A Operating Reactors Branch I 83/09/30 DDLAN, J Indiana & Michigan Electric Cn DDLAN, J American Electric Power Service Corp 3pp 20777 180 P4X Fiche 50-315,83/09/30.
- --8310130222 Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively, changing Tech Spec to require redundant containment hydrogen analyters to satisfy requirements of NUREG-0737, TMI Action Item II f i & VARGA: G A Operating Reacture Branch 1 83/09/30 7pp 20777 183 24X Fiche 50-315.03/09/30,8310130217
- 8310140040 Forwards response to SA Varga 820730,0716 & 830810 requests for add1 info re hydrogen combustion & control during degraded core accidents

 ALEXICH.M P Indiana & Michigan Electric Co 83/10/10 DENTON, H & Office of Nuclear Reactor Regulation, Director 59pp 20768 OB5 24X Fiche 50-315,83/10/10,8310140040
- 8310200158 Requests extension until 831215 to submit rept on plant-specific evaluation of relief & safety valvet & associated piping systeper NURIC 0727/Item II D 1 2 ALEXICH.M P. Indiana & Michigan Electric Co. 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20836 313 24X Fiche 50-315,83/10/14.8310900158
- 9 Inspection reports: IE Dulletins & carrespondence
- 8310120293 Ack receipt of 830904 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 50-315/83-12 & 50-316/83-13 SHAFER, M D Region 3. Office of Director 83/09/19 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 1p 20692 341 24% Fiche 50-315,83/09/19,8310120293
- B310130025 Forwards SER & technical evaluation rept re responses to II. Bulletin B0-11. "Masonry Wall Design " Joint reinforcement masonry walls not well established Structural element not acceptable Response requested VARGA: B A Operating Reactors Branch 1 83/09/20 DDLAN.J Indiana & Michigan Electric Co DDLAN.J American Electric Power Service Corp 3pp 20772 146 24X Fiche 50-315,83/09/20, 8310130025
- --B310130026 Safety evaluation supporting mods re IE Bulletin 80-11,
 "Masonry Wall Design"

 * Office of Nuclear Reactor Regulation, Director B3/09/20 Ppp
 20772 149 24X Fiche 50-315,83/09/20.8310130025
- --8308030382 Revised "Masonry Wall Design (8-59).DC Cook Nuclear Plant, Units 1 & 2." technical evaluation rept TRIOLO.S. CON.V N Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-241 ROI 83/07/27 CHOKSHI.N NRC - No Detailed Affixiation Given 38pp 20772 ISI 24X Fiche 50-315.83/09/20,8310120025
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308500340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list and JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

DOCKETED ITEMS

- 8308300345 IE Info Notice 83-62, "Potential Failures of Westinghouse Type 8A-t Differential Relays " Svc list enc! JORDAN, E. Davisian of Emergency Preparedness & Enginetring Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 207/8 001 24% Fiche 50-000,83/09/26,8308300245
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evaluation" Syr list encl JORDAN, E. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X fishe 50-000,83/09/29,8308300349
- 8310240093 Forwards IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830722-0909 No noncompliance noted 8HAFER, W D Region 3. Office of Director 83/10/05 DDLAN, F I American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 20881 005 24X Fiche 50-315,83/10/05,8310240073
- --8310240100 IE Insp Repts 50-315/83-14 & 50-316/83-15 on 830/22 0909 Nu noncompliance noted Major areas inspected operational safety, maintraurveillance. LERs, design changes, fire protection/prevention program & refueling activities SMANSDN, E R. DUBRY, N E , BUYD, D C Region 3, Office of Directumes 83/10/03 10pp 20881 007 24% Fiche 50-315,83/10/05,83/10/09
- B30B300378 IE Info Notice B3-65. "Surveillance of Flow in RID Bypass Loops Used in Mestinghouse Plants " Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post B30103) B37/10/07 Consolidate Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,83083803/8
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp. 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Natl Defect Causes Production of Notious Gases" Svc list enct JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043-075 24X Fiche 50-000,83/10/11,8368300757
- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison to of New
 York, Inc. 120pp. 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310180375 Clarifies NRC position on procedures for admitting NRC personnel to facility Access to vital areas should be afforded to listed Region III personnel Updata will be provided every 5 months

 AKELSON,W L. Region J. Office of Director B3/10/14 DDLAN,JE American Electric Power Service Corp DDLAN,JE Indiana & Michigan Electric Co 7pp 20803 189 24X Fiche 50-315,83/10/14.8310180376
- R Periodic operating reports & related correspondence
- 8310190064 Monthly operating rept for Aug 1983 W/830914 lt; QILLETT.W T . SMITH.W Ø Indiana & Michigan Electric Co 83/09/14 Office of Resource Management. Director 11pp 20822 320 24X Fiche 30-316.83/09/14.8310190064
- S Reportable occurrences, LERs & related correspondence
- 8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards mat! listed in App Arresponsive to Items 1,2 k 4 DDE should be contacted for mat! requested in Item 3 of ltr FELTON.J M Division of Rules and Records 83/06/14 HIATI,S L Dhio Citizens for Responsible Energy 3pp 20706 002 24x Fichs 50-000.83/06/14.8310110430
- --B310110443 Forwards PNO & morning rept re faulty Borg-Warner valve radiographs Problem may be generic Related info encl LITTLE,W 8 Region 3, Office of Director 83/04/13 POTAPOVS.U Region 4, Office of Director 15pp 20706
- 8310120193 RD on B30926.carbon dioxide sys for diesel generator room left in isolated condition w/no personnel in attendance Upon discovery, sys immediately returned to operable status SMITH.W.O Indiana & Michigan Electric Co. 83/09/27 KEPPLER.J & Region 3. Office of Director ip 20695 332 24X Ficher 50-316.83/09/27.8310120193

- 8310120234 RB on 830927, during sumpling process, sample valve on boron injection tank found partially open allowing boric acid solution to drain out Caused by personnel error Boron injection tank brought back into spcc
 SMITH, W G Indiana & Michigan Cleetris Co 83/09/27 KEPPLER, J (Region 3, Office of Director 1p 20/91 327 24X
 Fiche 50-316,83/09/27,8310120/14
- 8310120443 Forwards LERs 83-084/03L-0.83-085/03L-0.8 83-086/03L-0 SMITH,W 0 Indiana & Michigan Electric Co 63/09/28 KEPPLCW, J 6 Region 3. Office of Director ip 20698-321 24X Fiche 50-316, 83/09/28, 8310120443
- --8310120445 LER 83-084/03L-0 on 930901, during controlled shutdown at approx 10E-8 power. I average decreased below Tech Spec min of 941 F Conidown terminated at 535 F lemp would not return to 541 F within 15 minutes Reactor trip breakers opened BRAPER.D M Indiana & Michigan Electric Co. 83/09/28 Regim 3, Office of Director. 1p. 20498-322 24X Fiche 50-316, 83/09/28, 8310120443
- --B310120448 LER B3-0B5/03L-O on B30902, during startup at 20% power.office turbine generator paralleled w/sys grid, generator load increased to prevent motoring, resulting in pressure drop below Tech Specs Caused by heater breaker trip MURPHY.C E Indiana % Michigan Electric Co B3/09/20 tegion 3, Office of Director 1p 20698 323 24X Fiche 50-316.83/09/24, 8310120443
- --8310120449 LER 83-086/03L-O on 830905, chart paper on containment sump flow monitoring recorder 168-00L would not advance Cause but determined Chart paper adjusted & recorder verified operable Design change submitted STEPHENS, T.R. Indiana & Michigan Electric Co. 83/09/28 Region 3, Office of Director. 1p. 20698 3.74 24X Fiche 50-316,83/097/98, 8310120443
- 831012018B LER 83-087/03L-0 on 830904.pressurizer level channel 1 (NLP-151) indication drifted high Caused by water leaking from low side drain valve on pressurizer told caliby level transmitter (NLT-151) Valve tightened W/B31004 ltr PALMER, R.A., SMITH, W.G. Indiana & Michigan Electric Co. 83/10/04 KEPPLER.J 9. Region 3. Office of Director. 3pp. 20072 23/- F4Y Ficho. 50-316, 83/10/04.8310120188
- B310120379 RD on B31004.steam jet air bjector monitor (BRA-2405) determined indperable & 8 h grab sample not completed within required time frame Followup rept expected within 14 days
 SMITH.W G Indiana & Michigan Electric Co B3/10/04 KEPPLEH.J C Region 3. Office of Director 10 20499 200 247
 Fiche 50-316.83/10/04.8310120379
- 8310140137 Forwards LERs 83-088/03L-0,83-089/03L-0,83-090/03L-0 & 83-091/03L-0
 8M17H-W 9 Indiana & Michigan Electric Co 83/10/05 KEPPLEW, J C Region 3, Office of Director ip 20763-052 247
 Fiche 50-314,83/10/05.8310140137
- --83i0140i38 LER 83-088/03L-0 on 830912 nonfunctional fire sen) discovered Caused by fire seal pulled while installing another cable fire seal repaired & contractor personnel retrained SMITH.H L. Indiana & Michigan Electric Co. 63/10/05 Region 3/0/fice of Director ip 20/63-053 24X fiche 50-316/83/10/05. 8310140137
- --8310140139 LER 83-089/03L-0 on 8J0915, west containment spray pump discharge valve position lights noted out & breaker open Cause could not be determined No corrective action plannel KRAUSE DF Indiana & Michigan Electric Ca 83/10/05 Region 3. Defice of Director 1p 20763 054 24X Fiche 50-316,83/10/05, 8310140137
- ---B310140140 LER 83-090/03L-0 on 830920, during surveillance test on solid-state protection sys, two logic positions tested unsatisfactorily Caused by defective eniversal card A-311 Logic card replaced PALMER, R A Indiana & Michigan Electric Co 83/10/05 Region 3, Office of Director ip 20763-055 24x Fiche 50-316,83/10/05,8310140137
- --8310140141 LER 83-091/03L-0 on 830906, pressuriter pressure dropped below Tech Spec limit Caused by combination of individual pressuriter heater circuit breakers tripping & high valve seat leakage Load reduced PALMER:RA Indiana & Michigan Electric Co 83/10/05 Region S. Office of Director 2pp 20763 056 24X Fiche 50-316. 83/10/05,8310140137

- 8310170387 MPDES noncompliance notification on 830917.24 h composite sample from turbine room sump not collected Laused by stuck walve Notification to State of MI entl SHITH, W G Indiana & Michigan Electric Co 83/10/05 KEPPLER, J G Region 3. Office of Director 2pp 20785 031 24X Fiche 50-315.83/10/05.831017038/
- 8310170607 Forwards LERS 83-092/01f-0 & 83-093/01T-0 SMITH,W G Indiana & Michigan Electric Co 83/10/10 KEPPLER, J G Region 3. Office of Director 1p 20782 094 24y Fichs 50-016.83/10/10.8310170607
- --B3:0170611 LER B3-092/01T-0 on B30926, during routine sampling of beron injection tank, sampling valves at tank outlet left partially open Caused by personnel error Appropriate administrative actions taken against individual involved PALHER. R A. Indiana & Michigan Electric Co. 83/10/10 Region 3. Office of Director 2pp 20782 095 24X Fiche 50-316, 83/10/10, 8310170607
- --8310170619 LER B3-093/01T-0 on B30926, during normal operation, security officer found carbon dioxide switch for diesel generator room in isolate position & unattended Cause being investigated RICHARD, D D Indiana & Michigan Electric Co 83/10/10 Region 3, Office of Director Ip 20/82 09/ 24X Fichu 50-316,83/10/10,8310170607
- B310210206 Forwards updated LER 83-072/03X-1 & LER 83-094/03L-0 SMITH.W G Indiana & Michigan Electric Co 83/10/12 KEPFLEN.J G Region 3. Office of Director 1p 20852 081 24X Fiche 50-316.83/10/12.8310210F06
- --B310210212 Updated LER 83-072/03X-i on 830730, bloudown containment isolation valve 2-DCR-320 found w/coupling separated from valve stem & valve stem bent Probable cause is sys vibration Coupling valve stem & packing replaced PIEHL.R H Indiana & Michigan Electric Co 83/10/12 Region J. Office of Director ip 20852 082 24X Fiche 50-314.83/10/12, 8310210206
- -8310210215 LER 83-094/03L-0 on 830914 during normal operation. Loop 4 steam line pressure Channel 2 removed from svc because of indications instrument line obstructed Cause not stated Instrument isolation valve bonnet removed HIZNER. D G Indiana & Michigan Electric Co 83/10/12 Requon 3. Defice of Director ip 20852 083 24X Fiche 50-316,83/10/12,8310210204
- 8310210120 LER B3-095/01T-0 on B31003.discovered that Tadiation monitor for turbine condenser evacuation sys inoperable due to sample pump feed breaker tripping open Caused by operator failure to recognize monitor failure alarm W/B31014 ltr MURPHY.C E , SMITH.W G Indiana & Michigan Electric Co 83/10/14 KEPPLER.J G Region 3, Office of Director 3pp 20858 251 24% Fiche 50-314.83/10/14.8310210120
- 8310210122 PNO-III-83-099 on 831015, unit shut down for stoam generator tube leak exam & repair Unit will be shut down for 2-3 wks Region & resident inspector will monitor course of action BOVD.D , SHAFER, W Region 3, Office of Director BO/10/17 Ip 20858 250 24X Fiche 50-316,83/10/17,8310210122
- 8310270172 LER 83-096/03L-0 on 830918 during attempt to rectify order of procedural steps re containment apray surveillance tests concerning lineup of valve A, water drained to containment Caused by personnel error W/831018 ltr KRAUSE DF , SMITH W 0 Indiana & Michigan Electric Co 83/10/18 KEPPLER J Q Region 3, Office of Director 2pp 20925 001 24% Fiche 50-316,83/10/18,8310270172
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B3LC040447 Accepts, in part, revs to safeguards plans addressed in 1 icensee B30223 & 0316 ltrs Certain sections not acceptable & should be modified Corrected page revs requested within 3D days Bafeguards info withhold (ref 100FR73 21) MARTIN, T T. Division of Engineering & Torbnical Programs B3/09/23 B3MAKER, N J Baltimore Qas & Electric Co 4pp 20625 276 24X Fiche 50-317.83/09/23.8310040449
- 8310050340 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/09/26 Documen Management Branch 1p 20635-047 24X Fiche 50-317,83/09/26. 8310050340

- ~~B310050344 Public version of Rev 10 to Emergency Plan Implementing Procedure ERPIP 3 1: 'Immediate Action Procedures ' W/B30915 1ti
 WALL, C.F. RUSSELL, L.B. Baltimore Gas & Electric Co. 83/08/31
 Director's Office, Office of Inspection and Enforcement 33pp. 20635 048 24% Fiche 50-317,83/09/26,8310050340
- 8310200099 Forwards IE Insp Repts \$0-317/83-21 & 50-318/83-21 on 830809-0913 & notice of violation 81AR08TECKI.R Division of Project & Resident Programs 83/10/03 LUNDVALL.A E Baltimore Oas & Electric Co 2pp 20837 103 24X Fiche 50-317,83/10/03,8310200099
- 8310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913
 Noncompliance noted failure to follow chemistry procedures
 ARCHITZEL, R E , TRIMSLE, D C , HIGGINS, J C Region 1, Office of
 Director 83/09/27 19pp 20837 106 24X Fiche 50-317,83/10/03,
 8310200079
- 8310110244 Releases public version of revised emergency plan implementing procedures FELYON, J.M. Division of Rules and Records 83/10/05 Document Management Branch 1p 20685 350 24X Fiche 50-317, 03/10/05, 8310110244
- ~-8310110254 Forwards public version of Rev O.Change I.to Emergency Plan Implementing Procedure ERPIP 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10.Change 3.to ERPIP App 8 1, "Emergency Response Plan Implementation Procedures,"
 USI.V Daltimore Gas & Electric Co 83/09/27 Assistant Director for Derrating Reactors lp 20485 351 24X
 Fiche 50-317,83/10/05,8310110244
- ~-83i0110258 Public version of Rev O.Change 1.to Emergency Plan Implementing Procedure ERPIP 4 i 22 l. "CR/TSC Plant Parameter Rept" & Rev 10.Change 3.to ERPIP App B 1. "Emergency Response Plan Implementation Procedures " RUSSELL.L B Baltimore Gas & Electric Co 83/09/21 13pp 20685 352 24% Fiche 30-317.83/10/05.8310110244
- 8310130312 Releases public version of licensee ltr forwarding notice canceling emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/06 Document Management Branch 1p 20754 337 24X Fiche 50-317,83/10/06, 83(01303)2
- ~-B910130313 Forwards public version of B30927 notification canceling Emergency Plan Implementing Procedure ERPIP 4 2, "Notification" USI,V Baltimore Gas & Electric Co 83/09/29 Assistant Director for Operating Reactors 29p 20734 338 24X Fiche 50-317,83/10/06.83(0130312
- 8310170003 Releases public version of revised emergency plan implementing procedures FELTON-J M Division of Rulps and Records 83/10/06 Document Management Branch 1p 20814 031 24X Fichs 50-317,83/10/06, 8310170003
- --9310170005 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10 to ERPIP App & 1 Receipt form enc) USL.V Baltimore Gas & Electric Co 83/09/27 Director's Office, Office of Inspection and Enforcement ip 20814 032 24X Fiche 50-317.83/10/06.8310170003
- 8310270481 Releases public version of revised emergency response plan FELTON.J M Division of Rules and Records 83/10/21 Document Management Branch lp 20938 104 24% Fiche 50-317,83/10/21, 8310270481
- --8310270485 Public version of Rev 2 to emergency response plan W/820819 ltr * Baltimore Qas & Electric Co 82/00/31 KANTOR,F EP Licensing Branch 331pp 20938 105 24% Fiche 50-317,83/10/21,831027048)
- B310310014 Forwards safeguards info Encl withheld (ref 10CFR73 Pl)
 JDLLEY, J R Baltimore Pas & Electric Co B3/10/24 CLARK, R A
 Operating Reactors Branch 3 ip 20751 145 24X
 Fiche 50-317,83/10/24,8310310014
- 8310310055 Forwards revs to security plan & training & qualification plan Encls withheld (ref 100FR73 21)

 BOWNAKER,N J Baltimore Qas & Electric Co 83/10/24. DENTON,H R. Office of Nuclear Reactor Regulation, Director. 2pp 20750 339

 24X Fiche 50-317,83/10/24,8310310055.

- P Operating license stage documents & correspondence
- 8310310063 FOIA request for documents re const & operation of C-C plants List of info required submitted BELL.N Cualition for Safe Power 83/03/31 Defice of Administration 1p 20998 I/J 24X Fiche 50-000.83/03/31.8310310042
- 8310070176 Forwards Amends B7 & 69 to Lirenses DPR-53 & DPR-69 & safety evaluation Amend revises Tech Specs re required containment isolation valve response time.

 JAFFE-D H. Operating Reactors Branch 3 83/09/22 LUNDVALL.A C. Baltimore Gas & Electric Co. 2pp. 20/80 277 24X
 Fiche 50-317.03/09/22.8310070176
- ~-B310070179 Amends B7 & 69 to licenses MPR-53 & DPR-69, reflecting mod to valve 1/23-5V-6529 response closure time HILLER.J R Operating Reactors Branch 3 B3/09/22 App 20680 279 24x Fiche 50-31/,03/09/2P.B310070176
- --8310070180 Safety evaluation supporting Amends 87 & 69 to Liceuset PPR-53 & DPR-69

 * Office of Nuclear Reactor Regulation, Director 83/09/22 2pp 20680 289 24% Fiche 50-317,03/09/22,8310070176
- 8310040080 Forwards Page 4.Section 11 I of procurement & storinge manual covering Level A & Level C items
 HOPPA, J L Baltimore Gas & Electric Co 83/09/26 MEYER, C Region
 1. Office of Director 2pp 20608 001 24% Fiche 50-317.83/09/26,
 8310040080
- 8310040333 Forwards "Pressurizer Relief Valve Qualification," & Rev 1 to "Pressurizer Safety Valve Operability Rept." per NUREG-0737, Item II D 1 Design load stresses on piping & fittings within allowable limits LUNDVALLA E Baltimore Oas & Electric Co 83/09/28 MILLER. I (t Operating Reactors Branch 3 App 20615 036 247 Fache 50-317,83/09/28,8310040753
- --8310040355 "Pressurizer Relief Valve Discharge Piping Qualification." rept on Task 05088
 SMITH, J V , VENTURA, J C Bechtel Corp 83/09/23 154pp 20415 040 24% Fiche 50-317,83/09/28.8310040353
- --8310040357 Rev I to "Pressuriter Safety Valve Operability Rept "
 Combustion Engineering, Inc. CEN-248(8) RO1 83/09/30 100pp
 20615 194 24X Fiche 50-317,83/09/28,8310040353
- 1310130137 Approves 830731 request on behalf of C-E Dwners Group For withholding from public disclosure App A to "Response to Guestions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 790 CRUTCHP IELD D Operating Reactors Braich 5 93/10/03 LUNBVALLA E Baltimore Gas & Electric Co 6pp 20777 06% 24X Fiche 50-000, 83/10/03, 8310130137
- 10310479 Notice of consideration of issuance of amend to License JPR-53 & proposed NSMC determination & opportunity for hearing Initial NSMC determination available in Central Files JAFFE-D. HILLER, J.R. NRC No Detailed Affiliation Diven HOODHEAD, C.P. Office of the Executive Legal Director 83/10/03 16pp 20965 341 24% Fiche 50-317.83/10/06.8310310479
- 8310240072 Application for amend to Licenses DPR-53 & DPR-69 revising Surveillance Requirement 4.7.6 i & replacing Page 3/4.3-26 incorporating god to Assaurement range for gaseous & particulate activity monitors Marked-up Tech Specs encl LUNDVALL.A E Baltimore Gas & Electric Co. 83/10/12 MILLER, J.R. Operating Reactors Branch 3. 7pp. 20881 328 24X Fiche 50-317.83/10/12.8310240072
- 310310180 Forwards safety evaluation based on review of util responseto MARCO-0737. Items II K 3 i. "Automatic PORV Isolation" & II K 3 2. "Rept on PORVs " Requirements met KILLER.) R Operating Reactors Branch 3 83/10/12 LUNDVALL.A E Baltimore Gas & Electric Co 14pp 21000 037 24X Fichs 30-317.83/10/12,8310310180
- 8310200241 Provides proprietary & nonproprietary "Revised Zirraloy-4 Growth Correlations," per evaluation of shoulder gap clearance for Cycle 7 reload engineering & analysis Proprietary version withheld (ref 100/82 790) LUNDVALL.A E Baltimore Gas & Electric Co 89/10/14 MILLER.J R Decating Reactors Branch 3 App 20800 145 24% Fiche 50-317,83/10/14,8310200241
- --8310200245 Nonproprietary "Revised Zircalog-4 Growth Correlations "
 Proprietary info deleted
 Combustion Engineering: Int 83/10/04 Spp 20030.151 24X
 Fiche 50-317.83/10/14.8310200241

- 8310210157 Informs that refund for review of 830427 amend appplications forthcoming MILLER.N G License Fee Management Branch 00/10/14 LUNDVALL A f Baltimore Gas & Llectric Co ip 20003 061 247 Fiche 50-317,83/10/14.8310210357
- 8310240134 Provides status of mods required for Generic Lti (R) , We can inadequate core cooling instrumentation & NURLO-07.7. Item II F 2 Issues include environ qualification of two lc(subsystems & installation of core exit thermocouple LUNDVALLIA E Baltimore Gas & Flectric Co. 83710714 MR418.3 H Operating Reactors Branch 3 3pt. 20801 167, 249 Fishe 50-317,83710714.8310240134
- 8310240162 Notifies of resolution of NURIC-0/37.1MI Action Plan | L+m | If K 2 17. "Potential for Voiding in ACS During Francients "Results of analysis presented in CEN-197 applicable to facilities w/stated exception LUNDVALL, A E Haltimore Gas & Electric Co | 83/10/19 | MILLIA-, L & Operating Reactors Branch | J | p | 20881 312 24X | Fiche 50-317.83/10/19.8310240162
- 8310310303 Forwards response to NRC questions le reload pubmittal (a) Cycle 7, per 831014 telcon Intirnal rod pressure bolow nominal sys pressure throughout Cycle / LUNDVALLA E Daltimore Oas % Electric Co 83/10/24 Milita, a k Operating Reactors Branch 3 3pp 20961 229 247 Fiche 50-317,83/10/24,8310310003
- 9 Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand -Inc for Wilder Qualification lests " Svc list enci JORDAN,E I Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Computated Edison (a. of Ples, York, Inc. 117pp 20754-022 PAX Fische 50-000, 03709726, (100) NO 150
- 8308300342 IE Info Notice 83 62. "Failure of Redundant Toxic Gambetectors Positioned at Control Room Ventilation Air Intakes " Svc list oncl JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison (o of fire York, Inc. 116pp. 20777-210 24x Fiche 30-000, 8,1/09/26, 01018-000.4.
- 8308300345 IE Info Natice 83-63, "Potential Failules of Westinghnut; Type SA-E Differential Relays" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 89709726 Consolidated Edition Co. of New York, Inc. 118pp 20778 001 24X Firhe 50-000,83709726,8300100 155
- 8308300349 IE Info Notice 83-64, "Lead Shiolding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 930103) 83/09/29 Concolldated Edison Co. of New York, Inc. 115pp. 20716-324 24X Fiche 50-000,83/09/29 (1301480.12)
- B310200099 Forwards IE Insp Repts 50-317703-21 & 50-318703 21 un B30609-0913 & natice of violation STAROSTECHI, R Division of Project & Resident Programs (B.1/10/6) LUNDVALL.A E Baltimore Gas & Llectric Co 2pp 20037 103 14x Fiche 50-317,83/10/03,8310200099
- --8310200103 Natice of violation from into on 830807 0713 * Region 1, Office of Director 83/10/03 ip 2083/ 105 **4% Fich* 50-317,83/10/03.8310200077
- --8310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on 8J8807 69[.s. Noncompliance noted failure to follow chemistry procedure: ARCHITZEL.R E. IRIMBLE, D.C., HIGGINS, J.C. Region J. Office of B310200079 (9pp 20837 106 24X Fiche 50-317,83/10/6)
- 8310210207 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-317/83-22 & STARDSTECKI, R. Division of Project & Resident Programs 437/10/05 LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 20858 117 24X
- --8310210210 Responds to NRC ltr re viblations noted in It. Inap
 Repts 50-317/83-22 & 50-318/83-32 Corrective actions
 training in areas of sys descriptions, staffing, facilities &
 feedback of plant events upgraded
 LUNDVALL.A E Baltimore Gar & Electric Co 83/09/16
 STARGETECKIR Division of Project & Resident Programs App
 20855 119 24X Fishe 50-317,83/10/05,831021020/

- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RID Bypuss Loops Used in Westinghouse Plant: "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/10/07 Consolidated Edison Co of New York: Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " 8vc list encl JORDAN,E (Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 lE Info Notice 83-67, "Emergency Use Respirator Math Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 11/pp 21043 075 24X Fiche 50-000,83/10/11,8308300757 24X Fiche 50-000, 83/10/11, 8308300757
- 9308300761 IE Info Notice 83 6B. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list
 - JORDAN,E L. Division of Emergency Preparedness & Engineering Ressonse (Post 800103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24% Fiche 50-000,83/10/11,8308000/61
- 6310310927 Forwards IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-22 on 830902 STAROBTECKI, R Division of Project & Resident Programs 83/10/LUNDVALL, A E Baltimore Gas & Electric Co 2pp 20/47 224 Process 50-317
- --8310310P30 IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-02 on 830902 Major areas discussed results of NRC special insp which identified violation of Tech Spec limiting conditions for operation re emergency dissel generators Higgins, J., ARCHITZEL, R., TRIMBLE, D., Region 1, Office of Director 83/09/27 Spp 20947 226 24X Fiche 50-317.83/10/13.831031022/
- A Periodic operating reports & related correspondence
- 8310190148 Monthly operating repts for Sept 1983 W/831014 lti LOTITO.E M Baltimore Gas & Electric Co 89/10/14 Directo Office, Office of Inspection and Enforcement 12pp 20820 22/ Fitch 50-317.83/10/14/8310190148 Iti Director's
- S Reportable occurrences. LERs & related correspondence
- B310270341 Responds to FOIA request for three categories of documents re 830606 gas leak at facility forwards App A documents FELTON, J N Division of Rules and Records 83/07/22 ARGYROS, D L Chambin, Schuttland, Rosen, Cavanagh & Uliano 2pp 20937 225 2 Fichs 50-000,03/07/22,8310270541
- --8310270547 Submits morning rept for Region I, listing 830404 & 07 events ALLAN.J H Region I, Office of Director 83/06/07 BLAHA, J Program Support Branch Ip 20937 228 24X Fiche 50-000, 83/07/22,83102/0541
- B310250410 LER 83-049/03L-0 on B30818.while performing post-maint testing on flow path from condensate storage tank 12, auxiliary feedwater pump 11 found inoperable Caused by "stage & shaft pince-balance" from in place W/830916 ltr PORTER, 8 . FARRELL, E V . RUSSELL, L B Baltimore Gas & Electric Co 83/09/16 MURLEY, T E Requen 1. Office of Director 2pp 20897 254 24X Fiche 50-317,83/09/16,8310250410
- 8310280081 Updated LER 82-035/01X-1 on 820717, discrepancy noted in marrow-range & wide-range indications for safety injection tank IIB Narrow-range indication subsequently dropped offscale Caused by \$trcking indicator W/830921 ltr ANDROSIK,R , RUSSELL,L B Baltimore Cas & Electric Co B3/09/2: HURLEY,T E Region 1. Offsca of Director 3pp 20935 074 24: Fiche 50-317,83/09/21,8310280081 83/09/21
- B310200147 LER 83-047/03L-0 on 830822, during normal operation, control room air conditioner compressor 12 would not run when start signal initiated Investigation revealed compressor tripped on high pressure High pressure control reset W/830922 Itr JUNOE, M A. HANDN.C R. R. RUSSELLL B. Baltimore Gas & Electric Co 83/09/22 MURLFY, T. E. Region 1. Office of Director 2pp 20836 292 24X Fiche 50-317,83/09/22,8310200147
- 8310120262 RO on 830831, reactor & turbine manually tripped due to large impingement episode, clogging travelling screens Detailed explanation, in util 830914 rept to State of MD Ofc of Environ Programs encl
 BAUEREISE I Baltimore Gas & Electric Co 83/09/23 Region
 Office of Director 8pp 20693 137 24% Fiche 50-317.83/09/24
 B310120267

- 83i0040542 RO syster samples collected during Aug 1983 from Camp Coney location showed presence of Ag-110m concentration of 1184/BpC1/Kg (wet) Monthly percent capacity factors listed Doses considered insignificant consequence to public health FUHRMAN.6 R Bultimore Cas & Electric Co 83/09/26 Region 1, Office of Director 2pp 20623 301 24X Fiche 50-317,83/09/26, 8310040542
- 8310250587 LER 83-045/03L-0 on 830829, containment atmospheric gaseous & particulate radiation monitor discharge solenoid valve found damaged, venting portion of flow to auxiliary bldg Cause under investigation Valve replaced W/830928 itr JUNGE.M A. ANDROSIK.R. RUSSELL.L. B. Baltimore Gas & Electric Co. 83/09/28 MRLEY.T E. Region i. Office of Director 2pp 20901 256 24X Fiche 50-317.83/09/28.0310250587
- 8310070301 Potential Part 21 rept re underrange characterístic of Model N-EilOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.M J Fozbora Corp 83/09/30 Director's Office. Office of Inspection and Enforcement 1 lipp 20651 064 24X Fiche 50-000.83/09/30.8310070301
- 8310250247 LER 83-050/03L-0 on 830712, during normal operation, hydrogen analyzer 12 found inoporable Caused by out of adjustment reagent gas flow controller Controller readjusted Surveillance procedures revised W/831012 ltr PORTER, R. SYDNOR, R. RUSSELL-L B. Baltimure 0as & Electric Co 83/10/12 MURLEY, T. E. Region I. Office of Directo: 2pp 20879 150 24X Fiche 50-317,83/10/12.8310250249
- 8310240267 Responds to 830706 memo re AEOD/T314, "Improper Size of Inlet Piping to Primary Safety Valves at Milistone 2 & Calvert Cliffs 1 & 2 " Flow limiting devices for code safety valves 1 7/8-inch bore siameter discussed EISENHUT.D 0 Division of Licensing 83/10/18 THOMPSON,H L Division of Human Factors Safety 1p 20707 338 24X Fiche 50-000.83/10/18.8310240267
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT P F Security, medical, emergency & fire protection plans
- 8310040449 Accepts, in part, revs to safeguards plans addressed in licensec 830223 & 0316 ltrs Certain sertions not acceptable & should be modified Corrected page revs requested within 30 days Safeguards info withheld (ref 10CFR73 21) MARTIN, T T Division of Engineering & Technical Programs 83, 80WMAKER, N J Baltimore Cas & Electric Co 4pp 20625 276 Fiche 50-317,83/09/23,8310040447 83/09/23
- 8310050340 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/09/26 Docum Management Branch ip 20638 047 24X Fiche 50-317,83/09/26. B310050340
- --8310050344 Public version of Rev 10 to Emergency Plan Implementing Procedure ERPIP 3 1, "Immediate Action Procedures" W/830915 ltr
 WALL.C F , RUSSELL L B Deltimore Gas & Electric Co 83/08/31
 Director's Office. Office of Inspection and Enforcement 33pp 20435 048 24% Fiche 50-317,83/09/26.8310030340
- 8310200079 Forwards IE Insp Repts 50-317/83-21 k 50-3[8/83-21 on 830809-0913 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 83/1* LVNDVALL, A E Baltimore Gas & Electric Co 2pp 20837 103 Fiche 50-317, 83/10/03, 8310200099 83/10/03
- --8310200107 IE Insp Repts 50-317/83-21 & 90-318/83-21 on 830809-0913 Noncompliance noted failure to follow chemistry procedures ARCHITZEL.R E Region 1. Office of Director 83/09/29 19pp 20837 106 24% Fiche 50-317.83/10/03.8310200099
- 83i01i0244 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/05 Docum Hanagement Branch lp 20688 350 24X Fiche 50-317,83/10/05, 83101i0244 Dacument
- --8310110254 Forwards public version of Rev O.Change 1, to Emergency Plan Implementing Procedure ERPIP 4 1 22 1. "CR/TSC Plant Parameter Rept" & Rev 10.Change 3, to ERPIP App 1: "Emergency Response Plan Implementation Procedures "USI, V Baltimore Gas & Electric Co 83/09/27 Assistant Director for Operating Reactors 1p 20685 351 24% Fiche 90-317.83/10/05.8310110244

- --8310110258 Public version of Nev O.Change 1.to Emergency Plant Implementing Procedure ERPIP 4 1 22 1, "CR/TSC Plant Parameter Rept" & Rev 10.Change 3.tu ERPIP App B 1. "Emergency Response Plan Implementation Procedures" RUSSELL.L B Baltimore Gas & Liectric Co 83/09/21 Ihpp 20685 352 24% Fiche 50-317.83/10/05.8310110244
- B310130312 Releases public version of licensee itr forwarding notice canceling emergency plan implementing procedure
 FELTON.J M Division of Rules and Records 83/10/04 Document
 Hanagement Branch 1p 20754 337 24X Fiche 50-317.83/10/06,
 B310130312
- --8310130313 Forwards public version of 830927 notification canceling Emergency Plan Implementing Procedure ERPIP 4 2, "Notification"
 USI.V Baltimore Gas & Electric Co 83/09/29 Assistant Director for Operating Reactors 2pp 20754 338 24X Fiche 50-317,83/10/06.8310130312
- 8310170003 Re)wases public version of revised emergency plan implementing procedures FELTON.J B Division of Rules and Records 83/10/06 Document Management Branch Lp 20814 031 24X Fiche 50-317,83/10/06.
- --8310170005 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 4 1 22 1, "CR/ISC Plant Parameter Rept" & Rev 10 to ERPIP App B 1 Receipt form ent. USLV Baltimore Cas & Electric Co 83/09/27 Director's Office Office of Inspection and Enforcement 1p 20814 032 24X Fiche 50-317.83/10/06.8310170003
- 8310270481 Releases public version of revised emergency response plan FELTON, J M Division of Roles and Records 83/10/21 Document Management Branch 1p 20938 104 24% Fiche 50-317,83/10/21,831027081
- 8310310014 Forwards safeguards info Encl withheld (ref 10CFR73 21)
 JOLLEY, J. R. Baltimore Gas & Electric Co. 83/10/24 CLARK, R. A.
 Decrating Reactors Branch 3 lp. 20951 145 24X
 Fiche 50-317,83/10/24,8310310014
- 8310310099 Forwards revs to security plan & training & qualification plan Encls withheld (ref 10CFR73 21)
 BUMMAKER,N J Baltimore Gas & Electric Co 83/10/24 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 2pp 20950 339
 24X Fiche 30-317,83/10/24,8310310035
- P Operating license stage documents & correspondence
- 8310310063 FOIA request for documents re const & operation of C-C plants List of info required submitted BELL.N Coalition for Safe Power 83/03/31 Office of Administration Ip 20998 173 24X Fiche 50-000.83/03/31.8310310063
- 8310070176 Forwards Amends 87 & 67 to Licenses DPR-53 & DPR-69 & safety svaluation Amend revises Tech Specs re required containment isolation valve response time JAFFE, D H Operating Reactors Branch 3 83/09/22 LUNDVALL, A E Baltimore Cas & Electric Co 2pp 20660 277 24X Fiche 50-317, 83/09/22, 8310070176
- --8310070179 Amends 87 % 67 to Licenses UPR-53 & DPR-69, reflecting mod to valve I(2)-89-6527 response closure time HILLER.J R Dereting Reactors Branch 3 83/09/22 8pp 20680 279 24% Fiche 50-317, 83/09/22, 8310070176
- --B3100701BO Safety evaluation supporting Amends 87 & 69 to Licenses DPR-53 & DPR-69
 * Office of Nuclear Reactor Regulation, Director 83/09/22 Ppp 20680 289 24X Fiche 50-317, B3/09/22, B310070174
- B310040080 Forwards Page 4, Section 11 1 of procurement & storage manual covering Level A & Level C items HOPPA.J L Baltimore Gas & Electric Co 83/09/26 HEYER, 9 Region 1, Office of Director 2pp 20608 001 24X Fiche 50-317.03/09/26.8310040080

- B310040353 Forwards "Pressurize: Rollef Valve Qualification," & Rev J
 to "Pressurizer Safety Valve Operability Rept." per
 NUREG-0/37. Item II D 1 Design load stresses on piping &
 fittings within allowable limits
 LUNDVALL.A E Baltimore Gas & Electric Co 83/09/28 MILLER. J &
 Departing Reactors Branch 3 4pp 20615 036 24X
 Fiche 50-317.83/09/28.8310040353
- --8310040357 Rev I to "Pressurizer Safoty Valve Operability Rept "
 -- Combustion Engineering. Inc. (EN-248(B) ROI 83/09/30 100pp
 20415 194 24x Fiche 50-317,83/09/20,8310040353
- 8310130137 Approves 830731 request on behalf of C-E Owners Group For withholding from public disclosure App A to "Response to Questions on RCS Asymmetric Loads Evaluation Program," per 10CFRZ 790 CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/03 LUNDVALL, A E. 8altimore Oas & Electric Co. App. 20777 045 24% Fiche 30-000,83/10/03.8310130137
- 8310240072 Application for amend to Licenses DPR-53 & DPR-69 revising Surveillance Requirement 4.7.6.1 & replacing Page 3/4.3-26 incorporating mod to measurement range for gaseous & particulate activity monitors Marked-up lech Spres encl LUNDVALL.A E Baltimore Gas & Electric Co. 83/10/12 MILLER.J.R. Operating Reactors Branch 3.7pp. 20801-328. 24X Fiche 50-317.83/10/12.83102400/2
- B310310180 Forwards safety evaluation based on review of util responseto NUREG-0737. Items II % 3 1. "Automatic PDRV Isolation" & II % 3 2. "Rept on PORVs " Requirements met MILLER, J R Operating Reactors Branch 3 83/10/12 LUNDVALL, & F Baltimore Oas & Electric Co 14pp 21000 037 24X Fiche 50-317, 03/10/12.8310310180
- 8310210167 Informs that refund for review of 830427 amend appplication forthcoming MIRLER, W O License Fee Management Branch 83/10/14 LUNDVALL, A J Baltimore Oas & Electric Co ip 20883 361 247 Fiche 50-317,83/10/14,8310210167
- B310240134 Provides status of mods required for Generic Lt; S2-20 to inadequate core cooling instrumentation & NUREG-073). Hem II F 2 Issues include environ qualification of two ICCI subsystems & installation of core exit thermocouple LUNDVALL, A E Baltimore Gas & Clectric Co B3/10/14 MILLER, J R Operating Reactors Branch 3 3pp 20461 146 24% Fichs 50-317,83/10/14,8310240134
- 8310240162 Notifies of resolution of NUREG-0/3/,TM1 Action Plan Item II K 2 17. "Potential for Voiding in KCS During Transients "Results of analysis presented in CEN-199 applicable to facilities w/stated exception LUNDVALLA E Daltimore Gas & Clettric Co 83/10/19 MILLER,J R Operating Reactors Brench 3 1p 20081 312 24X Fiche 50-317.83/10/19.8310240162
- O Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN.E L Divicion of Emergency Preparedness & Engineering Response (Post 830103) 837/09/26 Consolidated Edison to of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24% Fiche 50-000,83/09/26,8308*0034;
- 8308300345 lE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Syc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26.8308380345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR90 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308380349
- 8310200099 Forwards IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830809-0913 & motice of violation STARDSTECKI.R Division of Project & Resident Programs 83/10/03 UNDVALL,A E Baltimore Gas & Electric Co 2pp 20837 103 E4X Fiche 50-317,83/10/03,8310200099

- --B310200107 IE Insp Repts 50-317/83-21 & 50-318/83-21 on 830807-0713
 Nancompliance noted failure to follow chemistry procedures
 ARCHITZEL.R E . TRIMBLE.D C . HIGGINS.J C Region 1. Office of
 Director B3/09/27 19pp 20837 106 24X Fiche 50-317,83/10/0J.
 B310200077
- B310210207 Ack receipt of B30916 ltm informing NRC of steps taken to correct violations noted in If Insp Repts 50-317/83-22 & 50-318/83-22 STARDSTECKI, R Division of Project & Resident Programs 03/10/05 LUNDVALL, A E. Baltimore Gas & Electric Co. 2pp. 20855 117 ,4X Fiche 50-317,83/10/05,8310210:07
- --8310210210 Responds to NRC 1th re violations noted in IC insp Repts 50-317/83-22 % 50-318/83-22 Corrective actions training in areas of sys descriptions, staffing, facilities & feedback of plant events upgraded LUNDVALLA C. Baltimore Gas & Electric Co. 83/09/16 STARCSTECKI, R. Division of Project & Resident Programs 4 20855 119 24X Fiche 50-317.83/10/0% 831021020/
- B30B3Q037B IE Info Notice B3-65. "Surveillance of Flow in RTD Byomst Loops Used in Mestinghouse Flants " Svt list encl JORDAN, E L Division of Emergency Preservedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 830B30037G
- 8308300752 IE info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/10/07 (onsolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Ficho 50-000.83/10/07.8308300752
- 830B300759 IE Info Notice 83-67, "Emergency Usa Respirator Hatl Defect Causes Production of Noxious Gases" Syc list encl JORDAN. E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24x Fiche 50-000.83/10/11.0308300759 117pp
- 8308300761 IE Info Notice 83-68, "Respirator Usor Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl encl JGRDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 127 24X Fiche 50-000,83/10/11,8308,300761
- 8310310227 Forwards IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-22 on 830902 STAROSTECKI, R Division of Project & Regident Programs 83/10/ LVNDVALLA E Baltimore Gas & Electric Co 2pp 20947 224 Pr Fichs 50-317,83/10/13,8310310227 83/10/13
- --8310310230 IE Enforcement Conference Repts 50-317/83-22 & 50-318/83-P2 on 830902 Major areas discussed results of NRC special incpublic identified violation of Tech Spec Ilmiting conditions for operation re emergency dissel generators HIGOINS, J. ARCHITZEL, R., TRIMBLE, D., Region 1. Office of Director 83/09/27 5pp 20947 276 24X Fiche 50-317,83/10/13,831031022/
- A Periodic operating reports & related correspondence
- 6310190148 Monthly operating repts for Sept 1983 W/831014 ltr LOTITO.E M Baltimore Gas & Electric Co 83/10/14 Dir Office, Office of Inspection and Enforcement 12pp 20820 Fichs 50-317.83/10/14/8310190148 83/10/14 Directo nt 12pp 20820 27/ Director's
- S. Reportable occurrences, LERs & related correspondence
- 6310250221 LER 83-045/01T-0 on 830906, discharge dampers to both penetration room exhaust fans failed to open during surveillance testing & dampers declared inoperable Caused by failure of pressure controller W/B30914 if the PIERINGER.P, RAYNUR.J W, RUBSELL,L B Baltimore Gas & Electric Co 83/09/16 MURICY.T E Region 1, Office of Director 1pp 20899 085 24X Fiche 50-318,83/09/16,6310250221
- 8310200004 Updated LER 83-002/03X-1 on 830101, pressure indicator PIC-103 failed low Caused by transmitter leads inadvertently lifted, rendering ERV-402 inoperable Personnel counseled W402002 1-1-WARDLEZ IV RAYNOR, J W , RUSSELL, L B Baltimore Gas & Electric Co 83/ MURLEY, T E Region 1. Office of Director 2pp 20837 010 Fiche 50-318,83/09/22,8310200004
- 8310200047 LER 83-044/03L-0 on 830823, motor driven auxiliary feedwater 310200047 LER 83-044/03L-Q on B30823, motor driven auxiliary reedwater flow indication declared inoperable Caused by low zero ref Zero ref recalibr W/830922 ltr PIERINGER.P, RAYNOR.J W, RUBBELL,L B Baltimore Gas & Electric Co B3/09/22 MURLEY,T E Region 1, Defice of Director 2pp 20837 006 24X Fiche 50-218,83/09/22,8310200047

- 8310200154 LER 83-048/03L-0 on 830901, hydrogen recombiner 21 found inoperable Caused by loose hex nut allowing terminals on back of potentiometer to be twisted & pulled Potentiameter replaced 4/830722 ltr PORTER.R. BASSD.L F. RUSSELL.B Baltimore Gas & Electric Co 83/09/22 MRLEY.T E Region 1, Office of Director 2pp 20836 319 24X Fiche 50-318,83/09/22,8310200154
- B310040542 RO oyster samples collected during Aug 1983 from Camp Conog location showed presence of Ag-110m concentration of 118+/- BpCr/Kg (wet) Monthly percent capacity factors listed Doses considered insignificant consequence to public health FUHRMANIC R Baltimore Gas & Electric Co 83/09/26 Region 1. Office of Director 2pp 20623 301 24X Fiche 50-317.83/09/26, 322.062632 Office of Director 8310040542
- B310250411 LER B3-051/OSL-0 on B30901, dose equivalent I-131 determined to be 1 05 uCi/g Caused by small number of leaking fuel gins & change in power level Sampling frequency increased W/B30927 ltr MV83092/ ITT JUNGE,M A. RUSBELL.L. B. Baltimore Gas & Electric Co. 83/0° MURLEY, T. E. Region 1. Office of Director. 8pp. 20897 219 Fiche 50-318, 83/09/27,8310250411
- 8310250369 LER 83-046/03L-0 on 830906 penetration room exhaust fan 21 nousousof the Gardas/Color on Badyoos generation from exhaust five would not start on CIS signal while performing Surveillance Test STP-0-22 Caused by malfunctioning CIS logic module & associated power relay W/830929 itr
 LDHR.J. BASSOL F. RUSSELL.L B Baltimore Gas & Electric Co 83/09/29 MURLEY, T E Region 1, Office of Director 2pp 20898 084 24X Fiche 50-318,83/09/29,8310250369
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-Ei10M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.M J Foxboro Corp 83/07/30 Director's Office, Office of Inspection and Enforcement 1 lipp 20651 064 24X Fiche 50-000,83/09/30,8310070301
- 8310250443 LER 83-049/03L-0 on 830909, pin hole leak discovered in reactor coolant charging line weld at reducing insert on tee in discharge header Caused by vibration of line Repair weld completed W/83100/ ltr PIERINGER.P. UNKLE.T J. RUSSELL, L. B. Baltimore Cas & Electric Co. 83/10/07 MURLEY, T. E. Region i. Office of Director Spp. 20897 053 24X Fiche 50-318,83/10/07.8310250443
- 8310250579 LER 83-053/03L-0 on 830914 control power fuse for starter Royalogy Let M3-033/03-0 on B30914, control power row starter cabinet blew cousing containment conter 21 to trip Caused by Rowan 2084-EPR1-1120 indicating light socket short circuit Socket replaced W/831007 ltr
 JUN0E,M A. BASSO,L F., RUSSELL,L B. Baltimore Gas & Electric Co. 83/10/07 MURLEY, T. E. Region 1. Office of Director 2pp
 R0900 310 24X Fiche 50-318,83/10/07.8310230597
- 8310180467 PNO-1-83-107 on 831011, trip from full power occurred when nain feedwater pump 22 tripped Containment sump pumping frequency increased due to stopping & restarting of reactor coolant pump Plant cooldown began 831012 to repair seal TRIMBLE.D , SMCTLAND, P. Region 1, Office of Director 93/10/12 p. 20802 031 24% Fiche 50-318,83/10/12,8310180467
- 8310240269 Responds to 830906 memo re AEUD/T314, "Improper Size of Inlet Piping to Primary Safety Valves at Milstone 2 & Calvert Cliffs 1 & 2 "Flow limiting devices for code safety valves 1 7/8-inch bore diameter discussed EISENNUT.D 6 Division of Licensing 83/10/18 THDMF90N,H L Division of Human Factors Safety 1p 20907 338 24X Fiche 50~000,83/10/18,8310240269
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8310200218 Forwards IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830422-24 & 0711-20 & notice of violation MARTIN,T T Region i, Office of Director 83/09/14 KANGA, D. General Public Utilities CPU Service Corp 2pp 20830 123 Fiche 50-289, 63/09/14,8310200218 KANGA, B. K

- --8310200270 IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 & 0711-20 Noncompliance noted failure to perform quarterly fire brigade training PABLING.R Region 1. Office of Director 83/09/06 19pp 20830 126 24X Fishe 50-289.83/09/14.8310200218
- 8310170028 Forwards GPU vs B&W lawsuit review SER input for emergency planning Documents do not contain info w/potential to alter conclusions on restart certification issue MATTHEWS, D B Emergency Preparedness Branch 83/09/19 RUSSELL,W T @PU/B&W Lawsuit Review Team 5pp 2079U 343 24X Fiche 50-289, 83/09/19,8310170028
- 8310110102 Releases public version of revised emergency plan implementing procedure FELTON. JM Division of Rules and Records 83/10/05 Decument Management Branch 1p 20697 321 24% Fiche 50-320,83/10/05,83/10/002
- --8310110108 Public version of Rev 1 to Emergency Plan Implementing Procedure 1054 22: "Tornado/High Winds" KANBA.B K General Public Utilities - GPU Service Corp 83/07/17 7pp 20687 322 24X Fichs 50-320.83/10/05.8310110102
- 8310200437 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20859 295 24X Fiche 50-320,83/10/17; 8310200437
- --8310200443 Public version of revised emergency plan implementing procedures, including Procedures 1054 10 re onsite/offsite radiological monitoring & 1054 30 re activation of environ assessment command ctr

 BRADY, J A . STANCE, S J General Public Utilities GPU Sprysca Corp 83/07/23 35pp 20859 296 24X Fiche 50-320,03/10/17,8310200437
- 8310270393 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/21 Document Management Branch lp 20943 089 24X Fiche 50-289, 83/10/21, R10370393
- --8310270396 Public version of Rev 7 to Emergency Plan Implementing Procedure 1004 6. "Unit 2 Onsite Emergency Response Directory" & Rev 2 to 1004 32. "Activation of Amies to Nearsite Emergency Operations Facility (Crauford Station) "BRADY.J A . STANGE, 8 J General Public Utilities CPU Service Corp 83/10/10 21pp 20943 090 24% Fiche 50-289,83/10/21,8310270393
- 8310310161 Ack receipt of 830902 & 09 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-08
 Responsible technical reviewer process implemented 831010 as independent review of administrative controls
 STAROSTECKI, R Division of Project & Resident Programs 83/10/25
 KANDA, B K Oeneral Public Utilities OPU Service Corp 2pp
 20959 050 24% Fiche 50-320,83/10/25.8310310161
- --B310310164 Responds to NRC B30803 ltr re violations noted in 1E Insp Rept 50-320/B3-08 Corrective actions administrative procedures modified so only one temporary change notice may be effective on any given procedure KANOA.B K General Public Utilities - GPU Service Corp B3/09/02 MURLEY,T E Region 1, Office of Director 4pp 20959 05P P4X Fiche 50-320.83/10/25.8310310161
- C Adjudicatory correspondence
- 8310110692 Expresses appreciation for meeting to review QPU vs B&W lawsuit document record RAMBON,R J Office of the Executive Legal Director 83/07/22 WISER F Davis, Polk & Mardwell 1p 20714 343 24X Fiche 50-267,63/07/22,8310110632
- 8310140302 Forwards listing of lawsuit documents by subject a significant to GPU vs 8&W record to support position to reopen restart hearing Evaluation of documents contained in SER requested EISENHUF, D © Division of Licensing 83/08/15 MATEON, R J Division of Systems Integration (post 811005) THOMPSON, H C . TAYLOR, J L Division of Human Factors Safety 22pp 20793 300 24X Fiche 80-289,83/08/15,8310140302
- 8310170012 Forwards NRC produced transcripts of RH Meaten taped interviews Tape entry into document control sys as B&W Exhibits 347a-347o requested W/o encit RUSECLL, N T OFU/D&W Lawsuit Review Team 83/08/24 SCATTUL)N1, L SOUGER, J Public Document Brench BLUME, N Office of the Goneral Counsel 1p 20798 361 24X Fiche 50-289, 83/08/24, 8310170012

- 8310030419 Forwards draft NUREO-1020.Vol 1, "OPU vs B&W lawsoit Review & Effect on TME-1" Portions of Category 10 withheld since info pertains to ongoing investigations CHILK-S J Office of the Secretary of the Commission 83/09/30 Atomic Safety and Licensing Board Panel 111pp 2060± 103 24x Fiche 50-289,83/09/30.8310030419
- 8310130028 Notice of NRR 830919 issuance of amend to 790720 & BOUPII orders & motion to conform proposed leth Specs re changer to administrative controls Certificate of Svc encl HILCOVERIN N Hearing Branch 2 83/10/11 6pp 20725 077 F4X Fiche 50-320.83/10/11.8310130028
- 8310210200 Response to NRC 831011 matter to conform proposed Tech Specs in accordance w/amend to 800211 order Metion net opposed Certificate of Svc encl TROMBRIDGE 6 F Metropolitan Edison Co TROMBRIDGE 6 F Shaw Pittman, Patts & Trowbridge 83/10/19 Atomic Safety and Licensing Board Panel 5pp 20856 082 24X Fiche 50-320.83/10/19, 03102102000
- B310250048 Memorandum & order granting NRC motion to conform proposed Tech Specs w/830919 amend of 800211 order WOLF, J.F., PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Hoald Panel B3/10/20 Dffice of the Executive Legal Director 3pp 20894 151 24% Fiche 50-320,83/10/20.8310250048

H General correspondence

- 8310040483 Expresses futility of NRC 630927 meeting in Middletown.PA me polar crane safety Few positive or enlightening results gained from meetings

 LEE.J Affiliation Unknown 83/09/27 PALLADING.N J. GILINGKY.V., ROBERTB.T Atomic Safety and Licensing Board Panel 2pp

 20623 123 24X Fiche 50-320,83/09/27,8310040483
- 8310120171 Forwards Resolution 70-83 calling for decontamination & plant closing MINNIGH, J C. HETRICK, N P. HOCHENDONER, L. Dauphin County, PA 83/10/04 PALLADING, N J Commissioners 2pp 20696 003 Pex Fiche 50-320, 83/10/04.8310120171
- 6310240159 Comments on B30927 public meeting in Middletown, PA re TMI-1 restart & GPU vs B&W lawsuit Meeting completely dominated by GPU/Bechtel GSBORN, M Affiliation Unknown B3/10/14 DENTON, H R NR(- No Detailed Affiliation Given 2pp 209H1 292 24X Fiche 50-209, B3/10/14, B310240159
- P Operating license stage documents & correspondence
- E310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L Affiliation Unknown 83/05/02 NRC No Detailed Affiliation Given 1p 21004 270 24X Fishs 50-000.83/05/02-831031001/
- 8310180537 Forwards License Amend Request 3 requesting deletion of Section 2 E(3) of License DPR-73 re reserve tankage requirements ARNGED,R C General Public Utilities ~ GPU Service Corp E3/05/2/ SNYDER.B J TMI Program Office 1p 20799 095 24X Fiche 50~320,83/05/27,8310180537
- --8310180548 License Amend Request 3, requesting deletion of Soction 2 E(3) of License DPR-73 or reserve tankage requirements Class III fee entl W/Certificate of Svc ARNOLD, R C Genoral Public Utilities GPU Service Corp ARNOLD, R C Metropolitan Edison Co ARNOLD, R C Jersey Central Power & Light Co 83/05/27 Dpp 20799 094 24X fiche D0-320,83/05/27.8310180537
- 8310270035 FDIA request for all documents containing info re emission of radioactive iodine & other fission products during accident at facility ROGERS. H A Affiliation Unknown 83/06/07 Office of the Centra Counsel ip 20940 344 24X Fiche 50-320,83/06/07.83102700.15
- 8310140276 Forwards TMT-1 GPU/B&W lawsuit review organization chart
 Overtime for personnel connected w/GPU vs B&W lawsuit
 authorized as noted
 RUSSELL, W T Systematic Evaluation Program Branch 83/06/20 Mi
 No Detailed Affiliation Given 1p 20/74 095 24X
 Fiche 50-287,83/06/28,8310140296
- 8310140274 Requests estimate of time needed to review documents re TMT-2 accident & to prepare lists Info needed to respond to Congressman Udall request CHILK.S J Office of the Secretary of the Commission 83/06/30 DIRCKS

- 8310270040 Responds to FOIA request for documents containing info re emission of radioactive todine & other fission products during reactor accidents forwards App A documents App D documents can be purchased from NRC FELTON. J M Division of Rules and Records 83/07/04 ROGINS. II A Affiliation Unknown 4pp 20940 345 24X Fiche 50-320. 83/07/06. 8310270040
- --8310270041 Forwards draft "Comparison of lodine Behavior During TMI / Accident W/Predictions Based on WASH-1400 Methodology " POSTMA:A K Benton City Terhnology 82/04/13 PASEDA6, W! Accident Evaluation Branch 41pp 20940 349 24X Fiche 50-320,83/07/06,83102/0040
- --B310270044 Draft "Comparison of hodine Behavior During 1MI-2' Accident W/Predictions Based on WASH-1400 Methodology " POSTMA.A K Benton City Technology 8,1/04/13 40pp 20/940 050 24X Firhe 50-020.83/07/06.0310270040
- 83i0310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON.J M Division of Rules and Records 83/07/06 (ONNE'), t Affiliation Unknown ip 21004 271 24X Fiche 50-000.83/07/06, 8310310001
- B310130114 Agrees to provide NM(w/access to computerized record of GPU vs D&W trial record & deposition transcripts to check completeness of NMC independent review of trial documents ARNOLD, R C General Public Utilities GPU Service Corp B3/07/08 D&MIDN H R Office of Nuclear Reactor Regulation, Director ip 20777 073 24X Fiche 50-287,83/07/08.8310130114
- 83i0130342 Identifies NRP div responsibilities for reviewing documents re GPU/B&H lawswither Commission 830628 directive Review due by 830901 Overview of general scope & objectives of lawswith review task encl EISENHUT.D G Division of Licensing 83/07/08 MATTBON,R J Division of Systems Integration (post 81005) THOMPSON,R L Division of Ruman Factors Safety VOLLMER,R H Division of Engineering 52pp 20768 280 24X Fiche 50-289,83/07/08.
- 8310120058 Requests individual to manage & control access to hard copies of documents for GPU vs B&W lawsuit review RVSSELL.W T NRC No Detailed Affiliation Given 83/07/22 BESAW.W J Division of Technical Information & Document Control 2pp 20749 35° 24X Fiche 50-289.83/07/22.83/0120058
- 0310130175 Forwards summary of 630/21 meeting re GPU vs DMM lawsuit documents Comments on meeting summary welcomed RAMSON.R J NRC No Detailed Affiliation Given 83/07/26 HARTE.N E Days, Polk & Mardwell ip 20777 171 24X Fiche 50-269.03/07/26.8310130175
- --8310130186 Summary of 830721 meeting w/Davis,Polk & Hardell in New York,NY re info relevant to NRC review of GPU vs 8&W lawsuit record or to reactor safety in general RUBSELL,N T NRC No Detailed Affiliation Given 63/0//26 EISENNU1.D G Division of Licensing 3pp 2077/172 24X Fiche 50-289,83/07/26,8310130175
- 83t0170043 Summary of 830721 meeting w/bsW counsel releview of 82U vs 8tM lawsuit record & general reactor safety Operator reliance & responsibility for procedure writing identified as possible generic safety issue RUSSCLL.W T GPU/8tW Lawsuit Review Toam 83/07/26 EISCNHUI.D O Division of Licensing 3pp 20812 155 24X Fiche 50-287.83/0//26, 8310170043
- 831014029t Forwards final instablment of review packages & updateo list matching OPU vs B&W lawsuit documents w/responsible divs Draft input to rept requested within 30 days W/o and is EISENNHUT.D Q Division of Liconsing 83/08/02 MATISON.R J Division of Systems Integration (pist Bilo05) THOMPSON.H L Division of Human Factors Safety TAYLOR.J M Division of QA Safeguards & Inspection Programs (Post B30103) 2pp 20794 108 24% Fithe 50-289.03/08/02.8310140x91
- 8310140292 Comments on Operating Reactors Assessment Branch responsibilities & participation in GPU vs BAW lawsuit review Table for disposition of operating experience assues end?
 MIRAGLIA: P. Assistant Director for Safety Assessment B3/08/05 RUSSELL-W T. GPU/BAW Lawsuit Review Iram bpp 20794 100 24)
 Fiche 50-289:83/08/05.8310140292

- 8310170717 Memorializes 830809 telcon w/H Myers of Congressman Udall staff re Chairman Palladino 830803 ltr on significant info in GPU vs 8tW recoid RUSSELL.W T GPU/BM Lawsuit Review Team 83/08/07 DENTON, H R , CASE, E G Dffice of Nuclear Reactor Regulation, Directon EleSCHMUT, D G Division of Licensing Ip 20798 116 24X Fiche 50-289, 83/08/09,8310170717
- 8310170751 Informs that D Moris-eau will be acting for C Allenspach ac leader for GPU vs B&W lawsuit roview BODHER.H R Licensee Qualifications Dranch 83/08/12 THOMPSON.H L Division of Human Factors Safety 1p 20798 219 24x Fiche 50-289,83/08/12.8310170751
- 8310130108 Forwards list of specific exhibits requested on 830812 to be used in GPU vs B&W lawsuit review RUSSELL.W T Division of Licensing 83/08/16 LLOYD,R D Debevoise & Liberman LLOYD,R D General Public Utilities GPU Bervice Corp 2pp 20777 071 24X Fiche 50-289.83/08/16. 8301038108
- B310170014 Forwards revised listing of subjarea contents for GPU vs B&W lawsuit review, per B30727 & 0805 & 12 ltrs RUSSELL,W T GPU/B&W Lawsuit Review Team B3/08/18 MDRIBBEAU, D. PICKETT, D. ; MANS, W. NRC - No Detailed Affiliation Given 14pp 20813 285 24X Fiche 50-289, B3/08/18, B310170014
- B310170747 Identifies GPU vs BBW lawsuit documents not held by NRC & recommends no further action to obtain documents CAPRA.R A GPU/DBW Lawsuit Review Team B3/08/29 RUSSELL,W T GPU/BBW Lawsuit Review Team 34pp 20796 318 24X Fiche 50-209.03/08/29.8310170747
- 8310170022 Advises of receipt of logible NAW lawsuit documents requested of BAW in NRC 830816 ltr Documents received listed CAPRA-R A GPU/BAW Lawsuit Review Team 83/09/08 NRC No Detailed Affiliation Given ip 20798 357 24X Fiche 50-289,83/09/08.8310170022
- 8310170032 Requests assistance in arranging resources for production & publication of NRC evaluation of OPU vs 8&W lawsuit review & impact on TMI-1 restart (NURFG-1020)
 RUSSELL,W T GPU/D&W Lawsuit Review Team 83/09/08 DESAW,W J Division of Technical Information & Document Control Spp 20798 334 24X Firbs 50-289.83/09/08.0310170032
- 8310170001 Forwards 830908 memo requesting support for NRC rept on OPU vs B&W lawsuit review Arrangements should be made to accommodate requested schedule
 STEELE.H L Division of Technical Information & Document Control
 83/09/09 MCVLACH.H D Division of lechnical Information & Document
 Control JOHANSCN, J Cress Brench ip 20814 048 24X
 Fiche 50-289.83/09/09.8310170001
- ---B310170002 Requests assistance in arranging resources for production & publication of NRC evaluation of GPU vs NRM lawsuit review & impact on restart of THI-1 (NUREG-1020) Flow chart w/projected milestones encl RUSSELL.N T GPU/D&W Lawsuit Review Team B3/09/OB DESAM.W J Division of Technical Information & Nocument Control 3pp 20014 049 24X Fiche 50-289.83/09/09.B310170001
- B310200032 Responds to F01A request for correspondence between Chairman Palladino & DDJ rr investigation of alleged falsification of RCS leak rate tests Forwards App A documents Portions of requested documents withheld (ref F01A Exemption 7) FELTON. J N Division of Rules and Records B3/09/15 V010T.H H LeDoeuf, Lamb. Leiby & MacRae 2pp 20844 236 24X F1che 50-289,83/09/15,83102000032
- ---B31020003B Ack receipt of B30517 ltr re B0J investigation into allegations re possible criminal wrongdoing Separate NRC investigation will be initiated PALLADINO, N J Commissioners B3/05/27 JENSON, D L Justice, Dept of 1p 20844 240 24X Fishe 50-289, 83/09/15, 83102000032
- --8310200044 Requests that DOJ investigation on allegations re falsification of RCS leak rate tests be completed by 830515 Response within 2 wks requested Info partially delated PALLADINU, N Commissioners 83/04/11 SMITH, W F Justice, Dept of 2pp 20844 241 24X Fiche 50-289,83/09/15,8310200032
- --8310200048 Responds to 830411 itr re TMI-1 restart & DOJ investigation into allegations re mot competence investigation being pursued diligently but will not be completed by requested date info partially deleted JENBON.D L. Justice, Dept of 83/05/17 PALLADING, N. J. Commissioners 4pp 20844 243 24X Fishe 50-289,83/09/15,8310200032

- 83i0170018 Forwards draft NUREC-1020, "GFU vs B&W Lawsuit Review & Effect on TMI-1" Deaft does not include Chapter 10 re mgt competence/integrity Comments or concurrence requested W/o encl RUSSELL,W T OPU/B&W Lawsuit Review Team 83/09/19 EISENHUT_D C Division of Licensing MATTSON,R J Division of Systems Integration, post 811005) THOMPSON, N L Division of Human Factors Safety 2pp 20798 358 24X Fiche 50-289, B3/09/19, B310170018
- 8310280169 Appeals partial denial of FOIA request for correspondence petween Chairman Palladino & BOJ re investigation of alleged falsification of RCS leak sate tests
 VOIGT.H H LeBneuf. Lamb. Leiby & MacRae 83/09/19 CHILK.S J
 Office of the Secretary of the Commission 2pp 20965-055 MAX
 Fiche 50-289,83/09/19.8310280169
- 8310310097 Responds to FOIA request that IA SECYs be placed in PDR Forwards App A documents SECY-82-486 withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/09/19 SHOLLY, S C Union of Concerned Scientists 3pp 21000 146 24X Fiche 50-320,83/09/19,8310310097
- --8204070171 Advises of current status of studies assessing potential technical, regulatory & socioeconomic impacts of proposed alternatives for accident water disposition

 * Office of the Executive Director for Operations SECY-82-121
 82/03/18 13pp 21000 147 24X Fiche 50-320.83/09/19.831031009/
- 8310170025 Forwards final draft Chapter 10 to NUREO-1020 entitled "Mgt Competence/Integrity" Changes.comments or concurrence requested by 830922 M/o encl.
 EISEMINITED C Division of Licensing 83/09/20 MATISON.N J Division of Systems Integration (post 811005) THUMPSON.H L Division of Ruman Factors Safety TAYLOR.J M Division of GA. Safeguards & Inspection Programs (Post 830103) 2pp 20778 305 24X Fiche 50-289.83/09/20,8310170025
- 8310110536 Forwards marked-up copy of draft NUREQ-1020. "GPU vs 1164 Lawsuit Review & Effects on TMT-1" W/o encl THOMPSON.H L Division of Human Factors Safety 83/09/22 EISENMUT.D G Division of Licensing Ip 20777 209 14x Fiche 50-289.83/09/22.8310110556
- 8310110630 Forwards comments on NUREO-1020 re GPU vs 8½H lawsuit seview & effects on TMI-1 Errors in App B should be corrected to reflect findings concerning rejevance & materiality of lawsuit documents
 MATISON.R J Division of Systems Integration (post 811005)
 83/09/22 EISENHUT, D O Division of Licensing Jpp 20714 2/8
 24X Fichs 50-289.83/09/22, 8310110630
- 8310120057 Forwards IE/Region I comments re Subj Area 5 of NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," constituting concurrence w/NUREG TAYLOR, J M Division of QA, Bafeguards & Inspection Programs (Post 830103) 83/09/23 EISENHUT, D G Division of Licensing jp 20749 354 24X Fiche 50-289,83/09/23,8310120057
- 8310130138 Forwards Rev 4 to Procedure 13987-2-L01-t00, "Design Criteria Documents." containing changes committed to in 830525 It wesception that Bechtel nuclear GA menual will still be referenced KANOA.8 K General Public Utilities GPU Service Corp 83/09/23 SNYDER.8 J TMI Program Office Ip 20724 351 24X F(che 50-320,83/09/23,8310130138
- --8310130141 Rev 4 to Procedure 13587-2-t01-100, "Design Criteria Documents" • General Public Utilities -- GPU Service Corp 83/08/11 58pp 20726 352 24X Fiche 50-320.03/09/23,8310130138
- 8310130155 Discusses review of add1 QPU vs B&W lawsuit documents No changes to original SER necessary MATTSON.R J Division of Bafety Technology 83/09/23 EISENHUT.D 0 Division of Licensing 2pp 20777 178 24X Fiche 50-289.83/09/23.8310230155
- 8310120054 Concurs in draft NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1."

 VOLLHERIR H Division of Engineering 83/09/26 RUSEELL.N 7 NRC

 No Detailed Affiliation Given ip 20749 355 24X

 Fiche 50-289,83/09/26.8310120054
- 8310120051 Advises that comments to NUREG-1020 "GPU vs B&W Eausuit Review & Effect on TMI-1." were faxed to R Capra on B30920 JORDAN.6 t Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 EISEMBUTID 6 Division of Licensing ip 20715 327. 24X Fiche 50-289,83/09/27.8310120051

- 8310110531 Requests addl info on polar crane refurbishment Util should perform review of polar crane mods % testing prior to routine operational use BARRETI H TMI Program Diffice 83/09/28 KANGA, N K General Public Utilities GPU Service Corp 3p 20704 348 24X Firths 56-320, 83/09/28 310110531
- 6310120060 Forwards NUREG-10/0 "OPU vs B&W lawsuit & iffect on IM1 | *Distribution of Category 10 section "Mgt Competence/ Integrity" should be limited pending life of Investigations completion of investigation DIRCKS.W J Office of the Executive Director for Operations 83/09/28 PALLADING.W J Commissioners 2p 20/15 362 24X Fiche 50-289.03/09/28.8310120060
- 8310030500 Forwards safety evaluation for first pass detensioning & removal of up to five studs in reactor vessel first pass detensioning can be accomplished w/o undue risk to public Fee for evaluation of safety issue to be provided KANGA:B K General Public Utilities CPU Service Corp 83/07/2/SNYDER,B J TNI Program Office 3pp 20601 197 24X Fiche 50-320,83/09/29,8310030500
- 0310130005 Forwards for review & approval, 95% re ongoing containment bldg decontamination & dose reduction activities Evaluation addresses in-containment decontamination & dose reduction activities for remainder of 1703 & all of 1904 KANGA.B K General Public Utilities CPU Service Coip 87/07/29 SAYDER D THI Program Office 21pp 20725 214 24X Fiche 50-320,03/09/29,0310130005
- 8310050055 Recovery Operations Plan Change Request 4P, submitted in conjunction w/lech Spec Change Request 43
 KANGALB K General Public Utilities 6PU Service Corp 63/07/36
 BARRETTL H TRI Program Office 7pp 20628 310 74X
 Fiche 50-320.83/09/30.8310050055
- --8310050061 Proposed Tech Specs 4 1/4 3 t 4 7 rs recovery operations plan

 # General Public Utilities GPU Service Corp 83/07/30 24pp 20628 317 24X Fiche 50-320, 83/07/30, 83(0050055
- B310(30082 Requests extension until funding for 1784 established to allow time to prepare appropriate plan & schedule for ALARA exception to Tech Spec surveillance Delay due to uncertainty of funding project in 1784 KANGA-B K General Public Utilities GPU Service Corp B'1/07/36 SAYDER-B J TMI Program Office 2pp 20725 061 74X Fiche 50-320.83/09/30.8310130082
- 8310130088 forwards application for amend to License DPR-/3, consisting of Tech Specs Change Request 43, deleting sys no longer necessary for present/future plant conditions & refs to accupational exposure considerations
 ARNOLD,R C General Public Utilities OPU Service Corp 83/07/J6 SNYDER,B J TMI Program Office ip 20/26 177 24X
 Fiche 50 320,83/09/30,8310130088
- --8310130093 Application for amind to License DPR-73, consisting of lech Spec Change Request 43 deleting sys no longer necessary for present/future plant conditions & refs to occupational exposure considerations

 * General Public Utilities GPU Service Corp 83/09/30 Ppp 20726 178 P4X Fiche 50-320,83/09/30,8310130088
- --8310130099 Proposed Tech Spec re deletion of sys no longer necessary for present/future plant conditions & rev to recovery operations plan deleting refs to occupational exposure * General Public Utilities GPU Service Corp 83/09/30 27pp 20726 180 24x Fiche 50-320,83/09/30,8310130088
- 8310190245 Advises that Generic Ltr 81-38, "Storage of Low Level Radwaster at Power Plant Reactor Sites," applicable to facility Response due within 30 days advising how util meets guidance in generic ltr
 BARRETT.L H [MI Program Diffice 83/07/30 KANGA, B K General Public Utilaties GPV Servic Corp Zpp 20838 085 2/9X
 Fiche 50-320.83/09/30.8310190245
- B310130064 Forwards fee for first pass stud detensioning SER, per 6/209/7 itr Determination of fee based on single safety issue KANGA, B K General Public Utilities GPU Service Corp 8/1/10/04 SNYDER, B J TMI Program Office ip 20726 293 1/4X Fiche 50-320.83/10/04.83/0130064
- 8310180046 Forwards info on calibr of Dillon load cells 5/N 443 & 11011 to be used in polar crane load testipes 830928 discussion Load cell data accurate POINDEXTERIT C TMF Program Office 83/10/04 MORRISIA L. Lancaster, PA App 20825 02ff 24X Fiche 50-320,83/10/04,8310180046

- ∷10140025 Resigns as chairman of Advi<ory Panel for Decontamination of TMI-2 Facility should be closed Public decerves faster
- cleanup MIANICH J E Advisory Council for Decontamination of TMI Unit P 03/10/05 PALLADINO N J Commissioners ip 20/68 077 247 Fiche 50-320, 03/10/05 8310140025
- 310170695 Staff requirements mad be 831006 briefing on results of GFC vs B&W trial mati & other uncontested matters be IMI-1 restart Commission made no requests & took no action CHILK.S J Office of the Secretary of the Commission 83/10/06 Office of the Secretary of the Commission 83/10/06 Fice 50-287, 83/10/06, 8310170675
- 83:0:3040B Staff requirements memo re 830/16 periodic meeting in Washington, DC w/Advisory Panel on decontamination of IM1-2 CHILK,S J. Office of the Secretary of the Commission 83/10/07 DIRCKS,W J. Office of the Executive Director for Uperation, FOUCHARD, J. Office of Public Affairs FRALEY,R F. ACRS Advisory Committee on Reactor Safeguards 2pp 20769 348 24X Fiche 50-320, 83/10/07, 8310130400
- 0310180092 Ack receipt of 630915 request for info concerning open issues re mpt intogrity identified in 630919 % 0715 memos to Cormission NAC evaluation of open issues proceeding w/erception of 6PU vs 1840 lawsuit record OTRCKS.W J Office of the Crocutive Director for Operations 83710/07 DIECKANP.H General Public Utilities 0PU Service Corp 1p 20824 125 24X Fiche 50-289.83/10/07.8310180092
- 8310180099 Requests NRC provide identification & evaluation of specific concerns remaining or developed as result of evaluation of open issues Also requests all related recent inspirepts & basis for concern in other areas

 DIECKANP, H. General Public Utilities OPU Service Corp.

 B3/09/15 DIRCKS.W J. Office of the Executive Director for Openstions 4pp 20824 12H 24X Fishe 50-287, 83/10/07.

 B310100092
- F310170639 Forwards Rev 3 to "SIR for Removal of TMI-2 Reactor Vessel Head." per Tech Spec Change Request 41 KANGA.B K. General Public Utilities GPU Service Corp. 83/10/11 SK4DER.D J. TMI Program Office ip. 20790 139 24X Fiche 50-320,83/10/11,8310170639
- CIOLBO200 Submits partial response to request for info re polar crene refurbishment No matl or design problems found Mods, testing & refurbishment under careful scrutiny Supplemental info forthcoming #ANGA.B % General Public Utilities CPU Service Corp 83/10/11 SARPETT, H TMI Program Uffice 3pp 20809 04% P4% Fiche 50-320,63/10/11.8310180200
- 8310180347 Comments on NUREC-1020 re GPU vs B&W lawsuit review NRC did not make reasonable technical judgments leaving issues that should have been resolved ro mgt integrity as issues potentially involving integrity DIECKAMP.H General Public Utilities GPU Service Colp 83/10/14 PALLADINO.N J. ABSELSTINE, J. K. BERNIMAL:F Commissioners Sopp 20804 301 24X Fiche 50-289, 83/10/14, 8310180347
- Bilo280172 Responds to appeal re partial denial of FDIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests info partially withheld (ref FDIA Exemption 3) CMELM, S. J. Office of the Secretary of the Commission 83/10/14 VOIGT, H. LeBoeuf, Lamb. Leiby & MacRae 2pp 20965 057 24X F(che 50-209,83/10/14.8310280172
- --8310280179 Comments on questions raised in 830517 ltr to Chairman Palladino re communication between agencies DOJ should commit to completion date for investigation Supporting documentation encl
 CUMMINGS.J J Office of Inspector & Auditor 83/05/31
 JENSEN,D L Justice. Dapt of 4pp 20765 064 24X
 Fiche 50~320,83/10/14.8310280172
- 8310240256 Advises that Rev 2 to QA plan acceptable for implementation, subj to completion of enumerated items
 SMYDER-B J TMT Program Office 63/10/17 KANGA.B K General Public Utilities QPU Service Corp Ppp 20907 35/ 24X
 Fiche 50~320,83/10/17.8310240256

- B310310213 Responds to B30914 ltr requesting NRC to stop lift of reactor vessel head Once polar crane qualified reactor vessel head lift would not occur until util safety evaluation reviewed & approved by NRC FR notice encl DENTON; HR Office of Nuclear Reactor Regulation, Director B3/10/19 LEWIS, MI Affiliation Unknown ip 20965 299 ; Fiche 50-320, B3/10/19, 8310310713
- --8310310214 Notice of receipt of ML tewis request for action under IOCFR2 206 to stop lifting of reactor vessel head DENION.H R Office of Nuclear Reactor Regulation. Director 83/10/19 2pp 20945 300 24% Fiche 50-320,83/10/19.8310310213
- 8310280102 Updates status of Items 2 & 3 in util 831011 ltr re polar crane refurbishment ECMs approved & available for insp Test working group approval of polar crane no-load test formally documented KANGA,B K General Public Utilities - CPU Service Corp 83/10/25 BARRETT,L H TMI Program Office 1p 20935 204 24X Fiche 50-320,83/10/25,8310280102
- @ Inspection reports: IE Bulletins & carrespondence
- 831020021B Forwards 1E Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 & 0711-20 & notice of violation MARTIN,T T Region 1, Office of Director 83/09/14 KANOA,B K General Public Utilities GPU Service Corp 2pp 20830 123 24X Fiche 50-289, 83/09/14, 8310200218
- --83102002/0 IE Insp Repts 50-289/83-18 & 50-320/83-10 on 830622-24 & 0711-20 Noncompliance noted failure to perform quarterly fire brigade training PADLING:R . PLISCO,L . ANDERSON.C J Region 1. Office of Director 83/09/06 19pp 20830 126 24X Fiche 50-289,83/09/14, 8310200218
- 8308300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709/26 Consolidated Edison Co
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list enci JORDAN,E L Division of Emergency Proparedness & Engineering Responso (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24% Fithe 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 5A-1 Differential Relays" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345 1 l Bpp
- 8310140132 Forwards IE losp Rept 50-320/83-12 on 830807-0905 & notice of violation
 STARDSTECKI, R Division of Project & Resident Programs
 KANQA, B K General Public Utilities - GPU Service Corp
 20763 001 24X Fiche 50-020,83/09/27,8010140132
- --8310140134 Notice of violation from insp on 830807-0705 * Region 1. Office of Director 83/09/27 ip 207 Fiche 50-320.83/09/27.8310140132
- --B310140170 IE Insp Rept 50-320/B3-12 on BJ0B09-0909 Noncompliance noted failure to provide indoctrination & training program for personnel performing safety-related activities & failure to maintain & implement procedures por Tech Spec & B 1 WEBEJJ BARRIK : MOSLAKIT Region I, Office of Director B3/09/27 10pp 20763 004 24% Fithe 50-320,83/09/27.8310140133
- 8308300347 IE Info Notice 83-64, "Lead Shielding Attacked to Bafety-Related Sys W/o 100FR30 59 Evaluation " Syc list encl) JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Firhe 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E i Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24% Fiche 50-000,83/10/07,83083080378
- B30B300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Resgonse (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000,83/10/07,830B300752

- 8310140028 Forwards Ofc of Investigations rept. "THI Nuclear Generating Unit 2 Allegations re Safety-Related Muds.QA Procedures & Use of Polar Crane Proopt attention should be given to mgt controls over Bechtel cleanup activities W/o entl PALLADINO,N J Cammissioners 83/10/07 KWHNS.W General Public Utilities QPU Service Corp 2pp 20767-347 24% Fiche 50-320,83/10/07.8310140028
- 8310200454 Comments on results of IMI-2 investigation on alleged procedural & managerial issues Rept comprehensively addresses technical issues Commission should conduct special team insp to provide overall assessment of OA program GALLAGHER, E. J. Office of Policy Evaluations 83/10/07 JAYES, B. R. Office of Investigation ip 20857 341 24% Fiche 50-320,83/10/0/,8310200454
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Mati Defect Causes Production of Noticous Goses " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Int 117pp 21043 075 24X Fiche 50-000,83/10/11.8308700779
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enc!

 JORPAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Cansolidated Edison Co. of New Yor). Inc. 120pp 20827 127 24X Fire 50-000.83/10/11.8208J00761
- 8310310161 Ack receipt of 830902 & 09 ltrs informing NRC of steps taken to correct violations noted in IL Insp Rept 50-320/83-08
 Responsible technical reviewer process implemented 831010 as independent review of administrative controls
 STAROSTECKI, R Division of Project & Resident Programs 8J/10/25
 KANGA, B K General Public Ubilities CPU Service Corp 2pp
 20939 050 24X Fiche 50-320,83/10/25,8310310141
- ---8310310164 Responds to NRC 830803 ltr re violations noted in IE Ensp.
 Rept 50-320/83-08 Corrective actions administrative
 procedures modified so only one temporary change notice may
 be effective on any given procedure
 MANOALB K. General Public Utilities GPU Service Corp. 83/09/07
 HURLEY.T E. Region t. Office of Director. 4pp. 20959 052 247
 Fiche 50-320,83/10/25.8310310161
- R Periodic operating reports & related correspondence
- 9310050146 Forwards TM1 Program Dfc weekly status rept for uk of 830928-0902 BARRETT,L H TMI Program Office 83/09/02 DENTUN.H K Office of Nuclear Reacto, Regulation, Director SNYDEK,B J TM1 Program Office 10p 20629 338 24X Fiche 50-320.83/09/02.8310050146
- 8310060181 Forwards TMI Program Oft weekly status rept for wk of 830903-10 BARRETIL H TMI Program Office 83/09/12 DENTUNIN R Office of Nuclear Reactor Regulation, Director SNYDER, B J 1MI Program Office 7pp 20460-314 24X Fiche 30-320,83/09/12,8310040181
- 8310060164 Forwards (MI Program Oft weekly status rept for wk of 830911-17 BARRETT, L H TAI Program Office 83/09/19 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 12p 20660 333 24X Fiche 80-320,83/09/19,8310060164
- 8310050326 Forwards TMI Program Ofc weekly status rept for wk of 830918-24
 830918-24
 BERRETT, L. H. THI Program Office BS/09/26 DENIUN, H. R. Office of Nuclear Reactor Regulation, Director SNYDER, B. J. THI Program Office 11pp 20639 348 24X Fichs 50-320, 83/09/26, 8310040326
- 8310180122 Forwards TM1 Program Oft weekly status rept for wk of 830925-1001
 BARRETT.L H TM1 Program Office 83/10/03 DENTUN:H R Office of Nuclear Reactor Regulation, Director SNYBER.D J 1M1 Program Office 12pp 20827 096 24X Fich∉ 90-320,83/10/03,83101801≥2
- 8310120125 Forwards "TMI Aquatic Study,Monthly Rept for Aug 1783 "
 RESSLER.W C General Public Utilities GPU Service Corp 83/10/0/
 HICKEY.C NRC No Detailed Affiliation Given 1p 20696-126
 24X Fiche 50-289.83/10/07.8310120125
- --8310120128 "TMI Aquatic Study, Monthly Rept for Aug 1983 " NARDACCI.G A lighthyological Associates, Inc. 83/00/31 | 13pp 20896 127 | 24% Fiche 50-289, 83/10/07, 8310120125
- 8310180007 Forwards TMI Program ofc weekly status rept for wk of 831002-08 BARRETF,L H TMI Frogram Office 83/10/10 DENIUN.H R Uffice of Nuclear Reactor Regulation, Director SNYDER,B J TMI Program Office 9pp 20825 079 24X Fiche 50-320,83/10/10,8310180007

- S Reportable occurrences Lilks & related correspondence
- 8310190060 LER D3-039/01t-0 on H30820, several hourly file watches determined not performed during replacement of deteriorated fire barrier seels Caused by personnel error Personnel counseled & roving fire watch established W/830919 lts CHAPLIN,S KANKA,B K General Public Utilities QPU Service Corp 83/09/19 NURLEY, F & Regini 4. Office of Director Jup 20022 331 24X Fiche 50-320, D3/09/19, B3/10190060
- 8310190975 LER 83-040/03L-0 on 8J0B18, standby pressure control (i) surge tank level transmitter 5PC-LT-JA Failed low (arred by loose terminal block swill be installed & procedure will be changed W/BJ09PP lts (BULD, T. L. KANA, J. K. General Public Utilities GPU Service Corp 83/07/19 MURLEY, T. C. Region L. Office of Director Jpp 20822 279 24X Fishe 50-320, 83/09/19, 8310190075
- 8310200095 LER 83-038/01L-0 on 8J0819.hourly firewatch not in effect for genetration fire seal 4-065-80 in auxiliary bldg Scal monfunctional pending replacement Caused by inaccurate communications Firewatch reestablished W/830921 ltm GOULD T i KANGA, B K General Public Utilities CPU Service Corp 83/09921 MURICY, T & Region i, Office of Director 3pp 20817 001 24% Fishe 50-320,83/09/21.8310200095
- 9310200155 LER 93-044/03L-0 on 830822.concrete block accidentally dropped on transformer for lighting panel LPF-4E & feed breaker for panel LPF-4E did not trip before feed breaker for panel PDP-2R tripped #/830921 ltr CHAPLIN.S D . KANGA.B K General Public Utilities GPU Solvite Corp. 93/09/21 MRREV.f E Region I. Uffice of Director App. 20836-315 24X Fiche 30-320,83/09/21,8310200155
- 8310190173 LER 8.3-043/03L-0 on 830827.28 & 0912.air intake tumnel Maluisys partially disarmed Caused by interim protective action during lightning storms Air intake tumnel structure levers installed W/830923 ltr
 GOULD.T L KANOA, B K General Public Utilities GPU Service Cosp
 83/09/23 MURIEY.T E Region 1, Office of Director 4pp
 20821 090 24X Fiche 50-320,83/09/23.8310190173
- 8310250317 LER 83-045/03L-0 on 83082/, reactor bldq pressure transmitter 85-PT-4388-2 found out of calibr Caused by instrument drift Transmitter recalibr & returned to sec W/850923 ltr OOULD, T(, KANGA, B K General Public Utilities GPU Service Corp 83/09/23 MURLFy, T E Region 1. Office of Director 3pp 20898 014 24% Fiche 50-320,83/09/23,8310250317
- B310190205 Updated LER 83-029/0 JX-1 on 830717, standby pressure control pressure transmitter SPC PT-10 failed low & declared inoperable Disconnected wire interrupted current loop, causing transmitter to fail low Mire connected W/830926 lth GOULD, T. L., KANGA, B. K., General Public Utilities GPU Service Corp. 83709726 MURCEY, T. E. Rogion I. Office of Director ... 3pp. 20818 111 24X Fiche 50-320, 83709726, B310190205
- 8310250629 LER 83-046/03L-0 on 830831 t 0401, standby pressure control surge tank level transmitter 5PC-L(-3A failed low Caused by losse or broken conductor between level transmitter to junction between level transmitter to junction between level transmitter to guident surger of B3/09/30 NMRFFY, TE Region 1. Office of Director App 20900 209 24X Fishe 50-320,83/09/30,8310250629
- 8310250434 LER 83-042/01L-C on 830701. directored that only one of two required isolation valves between RCS & non-RCS grade water sources closed on three occasions during feed & bired operations, contrary to approved SER W/831003 Itr CHAPLIN,S D. KANDA, D. & General Public Utilities QPU Service Corp. 6/1/10/03 MUREY,7 E. Requon i, Office of Director App. 20897 075 24X Fiche 50-320.63/10/03.8360250434
- 8310250478 Updated LER 83-036/03X-1 on 830808.boom of hydraulic truty crane struck & grounded 230 kV bus 4 feedline resulting in loss of power from unit auxiliary transformer 2A Caused by personnel error W/B31004 lt.

 GOULD,TI: KANGA,B K General Public Utilities CPU Service Corp 83/10/04 MURIFY,TE Region 1, Office of Director 4pp 20897 098 24X Fiche 50-320,84/10/04,8310250478
- 1 Hearing transcripts on non-antitrust matters
- 8310040117 Transcript of 830916 meeting w/Advisory Panel on Decontamination of TM1-2 in Washington DC Pp 1-65 * Commissioners 83/09/16 69pp 20634 252 24X Fiche 30-320,83/09/16/831004011/
- B31(0)703)2 Transcript of B3092/ meeting in Middletown, PA re reacted bldg polar crane 3p 1-72 Viewglaphs enc1 * NRC - No Detailed Affiliation Given B3/09/27 210pp 20795 277 24X Fichs 50-320,03/09/27,6310170312

- B310190341 Transcript of 83092/ public meeting in Middletown.PA re reactor blde polar crane Pp 1-172 Supporting documentation encl Commissioners B3/09/27 212pp 20842 306 24X Firm 50-320,83/09/27.8310190341
- 8310200347 Transcript of Advisory Panel for Decontamination of (MI-2 830928 public meeting in Harrisburg, PA Pp 1-109 Supporting decomentation encl 4 Advisory Causell for Decontamination of (MI Unit 2 83/09/28
- umentation encl Advisory Council for Decontamination of FMI Unit 2 83/09/20 769 20873 095 24X Fiche 50-320.87/09/28.83(0200347
- 8310[30372 Transcript of 831006 bijefing in Washington, NC release) to of GPU & R&W trial matt Pp 1-42 Supporting documentation entl
 - enc1 + Commissioners 83/10/06 61pp 20/70 052 24X Fiche 50-209,83/10/06.83101304/2
- U Congressional/Executive Correspondence
- 8310170888 Responds to 830914 ltr expressing concern re proposed release of radwasta water containing significant amounts of tritium into bisquehanna River Proposal for disposal of processed accident water not yet received
 DIRKKS.H J Diffice of the Executive Director for Operations
 83/10/03 SARBANES.F S Senute 4pp 20798 166 P4X
 Fiche 50-320.03/10/03.8310170686
- --8310170690 Expresses concern re proposed release of radwasto water containing significant amounts of tritium into Busquehanna River. citing potential impact on Chesapeake Bay SARBANES, P. B. Sprate 83/09/14 PALLADING, N. J. Commissioners ip 20798 1/0 24% Fiche 50-320, 8J/10/03, 8310170486
- EGGMET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT I F Security, medical, emergency & fire protection plans
- B310040351 Forwards technical support cti & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings Requests update of info & submittal of personnel access documents

 DANCE: H C Division of Project & Resident Programs 63/09/1;
 KELLY: R J Georgia Power Co Spp 20620 323 24X

 Fiche 50-3P1, 63/09/12, 8310040381
- 8310040356 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 50-321/03-17 & 50-366/03-17 LEMIS.R C Division of Project & Resident Programs 83/09/19 MELLY.R J Georgia Power Co Ip 20625 304 24X Fiche 50-321,63/09/19.8310040356
- --8310040499 IE Insp Repts 50-321/83-17 & 50-344/83-17 on 830523-27 floriompliance nuted failure to dispose of radwaste per COCFR20 3DI
 KAHLE, J B Region 2, Office of Director BARR.K P Division of Engineering & Operational Programs 03/06/20 7pp 20625 312 24X Fiche 50-221.83/09/19.0310040056
- 8310170741 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 83/10/06 Docum Management Branch 1p 2079/ 272 24X Fiche 80-321,83/10/06, 83101/0741
- --B310170743 Forwards public version of revised emergency plan implementing procedures, including Procedures RNP-B034 to contaminated tool storage & control & HNP-4861 re emergency notification Metwork

 NIX.H C . SORRELL.E C Georgia Power Co 83/09/16

 Nuclear Reactor Regulation, Director App 2079/ E

 Fiche 50-321.83/10/06.83/01/0741
- --8310170746 Public version of revised emergency plan implementing procedures including Procedures INP-8034 re contaminated tool storage & control & HNY-4861 re emergency notification network GREENE, 1 , ROGERS, W H , NIX.II C Georgia Power Co 83/09/14 26pp 20797 277 24X Fiche 50-321,83/10/06,8310170741
- 8310270012 Forwards IE Safeguards Insp Repts 50-321/B}-26 & 50-366/83-28 on 830926-30 No noncompilance noted DATICE.H C Division of Project & Resident Programs 03/10/20 MELLYR J Georgia Power Co 2pp 20924 331 24X Fiche 30 321.83/10/20.8310270012

- --B310270023 IE Safequards Insp Repts 50-321/83-26 & 50-366/83-28 on 839926-30 No noncompliance noted Major areas inspected site orientation, review of security plan & procedures & security organization Details withheld (lef 100/8/3 2))
 HALL, D. t. MCGUIRE, D. R. Region 2. Dffice of Director 83/10/20
 1p 20924 333 24% Fiche 50-321,83/10/20,8310270012
- 9 Adjudicatory conscippedence
- 8310180364 Forwards info re util questioning of validity of notice of violation for violating 10CFH20 301 Util requested afficial interpretation & claimed NRC transferred regulatory authority to State of SC LIEDERMAN, J. Regional Operations & Enforcement Division 83/10/13 DLMSTEAD, B. Regulations Division 32pp 20803 044 24X Fiche 50-321,83/10/13,8310180344
- J. Insurance & indemnity information
- 8310030301 Forwards Endorsements B1 & 82 to NELIA Policy NF-215 & Endorsements 66 & 67 to MARLU Policy MF-78
 FIELDER.J Marsh & McLennan, Inc. 83709726 SALTIMAN, J. Assistant Director for State & Licenses Relations 5pp. 20591 008 24X
 Fiche 50-321.83709726.8310030301
- P Operating license stage documents & correspondence
- 8310070279 Application to amend License NPR-57, changing Tech Specs to allow increased flexibility in core design for core reconstitution schedule for New 1783 replacement of damaged fuel HEAD.O F Georgia Power Co 83/09/29 STOLZ, J F Operating Reactors Branch 4 2pp 20657 802 248 Fiche 50-321/83/09/29. 8310070279
- --8310070280 Proposed changes to Tech Space of MAPLHOR curve design for * Georgia Powoj Co 83/09/29 16pp 20457 005 247
- provisional informs that commitment to add high radiation signal for purge & vent valve isolation meets requirements of NURCO-0217. Item IJ E 42 7, "Primary Containment High Radiation to Close Vent & Purge Valves "
 STOLZ.J F Operating Reactors Branch 4 03/09/29 BECKMAN.J T Georgia Power Co 2pp 20706 319 24% Fiche 50-321.83/09/29, 0310110442 8310110442 Informs that commitment to add high radiation signal for
- 8310070264 Forwards proprietary "Dresden 2/9 Nuclear Generating Plant Suppression Pool Temp Response," "CI Hatch Nuclear Power Station Units 1 & 2 Suppression Fool Temp Response" & Haix I B30025 meeting viewgraphs Repts withheld fref 10CFR2 790) PFEFFERLEN, H C General Electric Co B3/09/30 WASSALLO, D B Operating Reactors Branch 2 Sipp 20611 292 24% Fiche 50-000,83/09/30,8310070264
- 831007028/ Requests that 810226 ltm re proposed Tech Spec changes concerning scram discharge sys be superseded by 820919 submittal GUCWALL T Georgia Power Co 83/10/04 STOLZ,J F Operating Georgia Power Co 83/10/03 STOLZ, J F Operating Reactors Branch 4
- B310110126 Withdraws proposed amend to Tech Specs changing requirements for HPCI & RCIC sys to require operability at pressure greater than 150 parsy per B20405 1th OCCHAL T Georgia Power Co B3/10/03 STOLZ, J F Operating Reactors Branch 4 1p 20646 298 24X Fiche 50-321,83/10/03.
- 8310140241 Provides schedule for plant outages & activities associated w/rectroulation puping inspired by IE Bulletins 02-03 & 830-02, as discussed at 830940 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl NIX.H C Gaorgia Power Co 83/10/05 STOLZ.J F Operating Reactors Branch 4 23pp 20761 345 E4X Fiche 50-321,83/10/05,8310140241
- 8310120265 Application for amend to Licenses DPR-57 & NPF-5 revising Tech Specs by transferring radiological effluent Tech Specs from App A to App B.per 781221 submittat Marked-up Tech Specs encl HEAD:0 F Georgia Power Co 63/10/06 STOLZ:J F Operating Reactors Branch 4 158pp 20698 092 24X Fiche 50-321.83/10/06:83101202/66
- 8310310439 Responds to B30907 request for mod to NRC B30701 order confirming util commitments to implement certain post-TMI-related items set forth in NUREG-0737 to ottens completion date for Item 11 R 3 to 831201 Request acceptable 8700.7.7 Operating Reactors Branch 4 B3/10/14 BECKHAM, J 3 Georgia Power Co. 29p. 24X Fiche 50-321, B3/10/14, B310310439 RECKHAM, J. T.

DOCKETED ITEMS

- --8310310440 Order granting extension until 831201 to complete
 Item II B 3. "Post-Accident Sampling " Commitments on
 applicable NUREG-0737 requirements from Generic Ltr 82-05
 encl
 EISENHUT, D G Division of Licensing 83/10/14 Peurgia Power
 Co 5pp 20765 164 24X Fiche 50 321,83/10/14,8310310439
- 8310210270 Application for amend to Licenses DPR-57 & NFF-5 transferring radialogical effluent Tech Spec from App B to App A GUCMA. L T Georgia Power Co 83/10/17 STOLZ, J F Openating Reactors Branch 4 App 20846 290 24X Fiche 50-321.83/10/17, 8310210270
- --8310210277 Proposed Tech Spec transferring radiological effluent Tech Spec from App B to App A * Georgia Power Co 83/10/17 120pp 20846 296 24X Fiche 50-321,83/10/17.8310210270
- --8310210279 E18 Poi fac; litips * Ocorgia Power Co 83/10/17 21pp 20847 053 24x Fiche 50-321.83/10/17.8310210270
- 8310310308 Clarification to 830929 application to amend License DPR-57, revising Tech Specs to support planned shutdown for core reconstitution OUCHA: LT Georgia Power Co. 83/10/24 STOLZ: JF Operating Reactors Branch 4 1p 2094; 826 24% Fiche 50-321,83/10/24, 8310310300
- a Inspection reports. IE Bulletins & correspondence
- 8310040012 Forwards IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/09/08 KELLYR J Georgia Power Co 2pp 20608 113 24X Fiche 50-321.03/09/08.8310040012
- --8310040042 IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted Major areas inspected licensee action on previous insp findings, follower on IL Bulletin 80-11 & review of bidg settlement data

 LEMMHAN, J. Region 2. Office of Director CONLON, T.E. Division of Engineering & Operational Programs 83/09/06, 4pp 20408 115 24X Fiche 50-321,83/09/08,8310040012
- 8310040174 Forwards IE Enforcement Conference Repts 50-321/83-22 & 50-366/83-27 on 830810 O'REILLY:J P Region 2. Office of Director 83/09/15 KELLY:R J Deorgia Power Co Ip 20608 222 24X Fithe 50-321:83/09/15. 8310040174
- --8310040178 IE Enforcement Conference Repts 50-321/83-22 & 50-366/83-27 on 830810 Major areas discussed MBIV leakage sys. HPCI main flow valve & ATMS rectriculation pump trip signal DANGE. H C Division of Project & Resident Programs 83/09/12, 2pp 20608-223, 24X Fiche 50-321-83/09/15,8310040174
- 3310040356 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-1/ & 50-366/83-17

 LEMIS R C Division of Project & Resident Programs 83/09/17

 KELLY R J Georgia Power Co ip 20625 304 24X

 Fiche 50-321,83/09/19,8310040356
- -8310040366 Resonds to NRC 830713 ltr re violations noted in IF insp Repts 50-321/83-17 & 50-366/83-17 Corrective actions boxes prepared for shipment elevated on one end w/drain plug removed for 24 h to allow for liquid drainage NIX:H C Georgia Power Co 83/08/19 O'REILLY, J.P. Region 2, Office of Director 4pp 20625 305 24X Fichs 50-321:83/09/19, 8310040356
- 8310040468 Forwards IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830523-27 & notice of violation LENIS,R C Division of Project & Resident Programs 83/07/13 KELLY,R J Wengia Power Ca 2pp 20625 309 24X Fiche 50-321-83/09/19
- -8310040479 Notice of violation from insp on 830523-27 * Region 2: Office of Director 83/07/13 ip 20625 31; 24X Fiche 50-321:83/09/19:8310040356
- -8310040499 IE Insp Repts 50-321/83-17 & 50-366/83-17 on 830023-27
 Noncompliance noted; failure to dispose of radwaste per
 100FRRO 301
 KAMLE, J B Region 2, Office of Director BARR, K f. Division of
 Engineering & Operational Programs 83/06/20 7pp 20695, 312
 24X Fichs 50-321, 83/09/19, 8310040356

- --8310250560 tE Training Assessments Repts 50-321/83-23 % to-366/83 24 on 83080-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training requalification programs & onshift/real-time training & mgt training HEML, C W , MYERS, D O , SKINNLR, P H Region 2, Office of Director 83/09/15 10pp 20901 023 24X Fiche 50-321,83/09/19,8410650519
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Tests" Svc list onel JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 (onsolidated Edison to of New York, Inc. 117pp 20754 022 24X Fiche 50-000.83/09/26,8308/00/40
- 8308300342 IE info Notice 83-62. "Failure of Redundant Toxic (ac Detectors Positioned at Control Room Ventilation Air Intakes" Svc list encl JORDANIC L. Division of Emergency Precaredness & Engineering Response (Post 830103) 83709/26 Consolidated Edison Co. of New York, Inc. | 116pp | 20777 210 | 24X Fiche 50-000, 83709/26, 8308300342
- 8308300345 IE info Notice B3-63. "Potential Failures of Westinghnuse Type SA-1 Differential Relays" Svc list end United State of Legislating Response (Post 830103) 83/09/24 Consolidated Edison Co. of New York. Inc. 118pp 20778 001 24X Fishe 50-000.83/09/24,8308/00/445
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o (OCFRSC 59 Evolution " Syc list enc! JORDAN, E L Division of Emergency Proporedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison (n of New York, Inc. 115pp 20716 324 247 Fiths 50-000.83/09/29,8308.003479
- 8310140241 Provides schedule for plant outages & activities associated Wirecirculation piping inspirequired by IE Bulletins 82-03 & 83-02. as discussed at 830928 meeting w/NRC Replacement of Piping planned for Unit 2 Viewgraphs encl NIX.H C Georgia Power Co 83/10/05 STOLZ.J F Operating Reactors Branch 4 23pp 20761 345 24X Fiche 50-321.83/10/05, 8310140241
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl JORDAN,E L. Division of Emergency Properedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list enc] JORDAN E Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Offect Causes Production of Naxious Gases" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308000759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Sv. list uncl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310180364 Forwards info re util questioning of validity of notice of violation for violating 100FR20 301 Util requested official interpretation & claimed NRC transferred regulatory authority to State of SC LIESERMAN.J. Regional Operations & Enforcement Division 83/10/13 ULMSTEAD.B Regulations Division 32pp 20803 044 24X Fiche 50-321,83/10/13.8310180.144
- 8310180951 Notification of B31021 meeting w/bWR licensees in Betherda, MD to discuss Future insps For intergranular stress correston cracking MIRAQLIA.F J Assistant Director for Safety Assessment 83/10/14 E18ENHUT.D G Division of Licensing 5pp 20823 3bu 24% Fiche 50 000,83/10/14.83101H0551
- 8310270012 Forwards IE Safeguards Insp Repts 50-321/83 PA & 50-366/83-28 on 830726-30 No noncompliance noted DANCE: H C Division of Project & Resident Programs 83/10/20 KELLY, R J Georgia Power Co Spp 20/24 331 24% Fiche 50-321.83/10/20.83102/0017

- --8310270023 IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-78 un 830726-30 No noncompliante noted Major areas inspected site orientation, review of security plan & procedures & security organization Details withheld (ref IOCFR73 21) HALL, B L , MGVIRE, D R Region 2, Office of Director B3/10/20 1p 20724 333 24X Fiche 50-321,83/10/20,83102/2012
- R Periodic operating reports & related correspondence
- 8310190014 Monthly operating repts for Sept 1983 W/830710 ltr CURTIS.C M . NIX.H C Georgia Power Cn 83/10/10 Director's Office, Office of Inspection and Enforcement 14pp 10823 284 2/49 Fiche 50-321,83/10/10,8310190014
- S Reportable occurrences. LLNs & related correspondence
- 8310210329 Responds to FOIA request for all documents re significan(ly high rate of equipment failures for GE BWR/A rated at 2,436 MW Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/28 HAFNE's B Suffolk Nuclear Study Group 2pp 20002 223 24X Fiche 50-000,03/07/28.8310710329
- --8301180513 Evaluates LERs for Jul 1961 Oct 1982 in support of upcoming SAIP review LERs minimally adequate in narrative sections Large number considered mpt deficiency related SEYERIT.K V Director's Officer 80/01/12 LEMIB.R Division of Project & Resident Programs 'ppp 20892 225 24X Fiche 50-000.83/07/28.8310210327
- 8310030304 Updated LER 83-023/03X-1 on BJ0224,25 & 0824,various valves on reactor water cleanup mys failed to either open or close as required by lech Spors Caused by limit switch out of adjustment & burned up motor W/B307.4: 1tr
 TIPPS,S B, NIX.H C Georgia Power Co B3/09/22 D'REJLLY, J P
 Region 2. Office of Director Spp P0591003 P4X
 Fiche 50-321.83/09/22.8310030304
- 8310030410 Updated LER 83-084/03x-1 on 830813 main steam line radiation monitors found to have high setpoint greater than three times normal operating background Caused by procedural inadequacy Procedure changed W/830922 1r TIPPS, S.B., NIX, H.C. Georgia Power Co. 83/09/22 0'RCILLY, J.P. Region 2. Office of Director 5pp 20593 127 24X Fiche 50-321, 83/09/22, 83/0030410
- 63100304B1 LER 83-086/03L-0 on 830830, during routine control ponel check, control room air intake monitor indicated downscale 2 alarmed Caused by monitor radiation source located too far from sensor Source repositioned W/83072P ltr TIPPS.S 8 , NIX.H C Georgia Power Ca 83/09/22 O'RCJLLY, J PRegion 2. Office of Director 4pp 20601 067 24X Fiche 50-321, 83/09/22,8310030481
- B310030247 LER 83-090/O3L-O on 830825, during performance of RCIC pump operability Procedure HNP-1-3405, RCIC tripped on low bearing oil pressure Caused by setpoint drift & component failure W/830926 ltr NIX.H C. TIPPS, 8 B Georgia Power Co 63/09/26 O'RCILLY, J P Region 2, Office of Director 5pp 201-91 064 2/A Fiche 50-321, 83/09/26, 8310030247
- 8310040524 LER 83-099/03L-0 on 830901, drywell torus recorder indicated downscale & declared inoperable due to lack of power Caused by personnel error Power restored by closing power link W/830927 ltr
 TIPPS 8 8, NIX, H C Georgia Power Co 83/09/27 O'REILLY, J P Region 2, Office of Director 3pp 20624 230 24X
 Fishe 50-321,63/09/27,8310040524
- 83i0140014 LER 83-088/03L-0 on B30913, fire protection instrumentation supervisory circuit panel 1743-P001 gave trouble light & alarm & could not be reaet & cleared Caused by improperly closed relays Relays adjusted W/831006 ltr
 YIPPG.S B , NIX.H C Georgia Power Co 83/10/06 D'REILLY, J P Region 2, Office of Director Spp 20768 060 24X
 Fiche 30 321.83/10/06,8310140014
- 83i0140144 LER 83-095/03L-0 on 830913, during hydrogen & oxygen analyzer A 1933-NOO2A found out of calibr Caused by instrument drift Analyzer recalibr W/83i006 ltm TIPPS, S B, NIX,H C Georgia Power Co. 83/10/06 O'REILLY, J P Region 2, Office of Director 4pp 20763 021 24X Fiche 50-321,83/10/06,83i0140144
- B310170397 LER B3-097/03L-0 on B3091B, optrating personnel determined that position of control rod 14-43 could not be ascertained Caused by Failed position switch in position indicator probe Rod moved to Fosition 18 WFB1006 btr TIPPS, S. B., NIX.H C. Georgia Power Co. B3/10/06 O'REJLLY, J. P. Region 2, Office of Director 4pp 20789 071 24X Fiche 50-321, B3/10/06, B310170397

- 8310170582 Updated LER 83-096/01X-1 on 830616.drywell svc air primary containment inboard isolation valve 1P51-F514 opened during plant shutdown & not closed prior to startup on 830618 Caused by procedural inadequary Valves closed W#831006 ltr TIPPS.S B . NIX.H C Georgia Power Co 83/10/06 D'REJLLY, J P Region 2. Dffice of Director 4pp 20780 331 24X Fiche 50-321.83/10/06.83/10170582
- B310310297 LER B3-094/03L-0 on B30929, HPCI steam line pressure switches CMD actuated below Tech Spec requirements Caused by setpoint drift Switches recallbr W/B31020 ltr TIPPS, 8 B , NIX, H C Georgia Power Co B3/10/20 O'REJLLY, J P Region 2, Office of Director 4pp 20/361 27B 24X Fiche 30-321,83/10/20,8310310297

V Operator Examinations

- B310250519 Forwards IE Training Assessment Ropts 50-321/83-23 50-346/83-24 on 830802-05 No noncompliance noted LEWIS.R C Division of Project & Resident Programs 83/09/19 KELLY.R J Georgia Power Co 2pp 20701 021 24X Fiche 50-321,83/09/19.8310250519
- --8310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on 83080-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training, requalification programs & onshift/real-time training & mgt training HEML, C W, MYERS, D O, SKINNER, P H Region 2, Office of Director 83/09/15 10pp 20901 023 24X Fiche 50-321,83/09/19.8310250517
- DOCKET 50-322 BHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- 8310180597 FDIA request for list of mods to containment undertaken by util in response to NUREQ-0487 HAFNER, B Buffolk Nuclear Study Group 83/04/25 Office of Administration ip 20827 124 24X Fiche 50-322,83/04/25,8310180597
- 8310110436 Responds to FOIA request for RFP RS-ORM-83-500 & SECY-83-157 RS-ORM-83-500 placed in PDR BECY-83-157 partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Racords B3/07/20 GRABER, L NUS Corp 2pp 20706 308 24% Fiche 50-322,83/07/20,8310110436
- --8310110439 Requests approval of proposed order re low power license for facility PLAINE, H H Office of the General Counsel SECY-83-157 83/05/02 4pp 20706 310 24% Fiche 50-322,83/07/20,8310110436
- 8310180600 Responds to FOIA request for info re mods to containment undertaken by util Info contained in Rev 5 to Flant Design Assessment Rept Util not required to rept changes but must comply w/acceptance criteria in Rev 5 FELTON, J N Division of Rules and Records 83/09/06 HAFNER, B Suffolk Nuclear Study Group 1p 20827 125 24% Fiche 50-322,83/09/06,8310180600
- 8310030590 Forwards request for add1 info on proposed Tech Specs re instrumentation trip setpoints, allowable values & on-line testing capability Response within 30 days requested SCHMENGER, A Licensing Branch 2 83/09/23 POLLUCK, M S Long Island Lighting Co 2pp 20407 341 24X Fiche 50-322, 83/09/P3, 8310030590
- 8310050443 Forwards Region I morning repts re emergency diesel generators for 830909-26 ODDOARD.R J Hearing Branch 3 83/09/28 BRENNER, L, FERGUSON.G A. MORRIS.P A Atomic Safety and Licensing Board Panel 5pp 20631 345 24X Fiche 50-322.83/09/28.8310050443
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Camyon i & 2.Fermi 2 & Callaway EIBENHUT, D @ Division of Licensing 83/09/29 PALLADING, N J Commissioners 3pp 20632 001 24X Fiche 50-000,83/09/29, B308300357
- 8310060300 Forwards "Preliminary Metallurgical Evaluation of Failed Crankshaft From Diesel Generator 102" EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lightin Co 83/10/03 BRENNER, L. MORRIS, P A , FERGUSON, G A, Atomic S, and Licensing Board Panel 15pp 20646 181 24% Fiche 50-322,83/10/03.8310060300

- 8308300771 Board Notification 83-128A forwards Equipment Gualification Branch conclusions repotential problems w/ASCO solenoid PALLADING N J
 - TEISENHUT, D G Division of Licensing 83/10/06 PALLADING.) Commissioners 31pp 20818 001 24% Fiche 50-000, 83/10/06. 83088007/1
- 8310190003 Forwards revised FSAR Section 13 1 3 25 re qualification requirements for technicians, revised in response to concern of NRC resident inspector info will be incorporated in next FSAR amend SMITH, J L Long Island Lighting Co 83/10/17 DENTON, H R Off of Nuclear Reactor Regulation, Director 3pp 20822 102 24x Fiche 50-322,83/10/17,8310190003
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310070116 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE SHOREMAM NUCLEAR POWER STATION, UNIT NO 1 DOCKET NO 50-322 (Long Island Lighting Company) * Division of Licensing NUREC-0420 S04 83/09/30 71pp Available at NRC 44 50 20671 122 £4% Fichs 50-322.63/09/30,
- B310170009 Forwards Suppl 4 to NUREC-0420, "SER Te Operation of Shoreham Nuclear Power Station.Unit 1" SCHLENCER, A Licensing Branch 2 83/09/30 PDLLCCK, M S Long Island Lighting Co 3pp 20814 067 24% Fiche 50-322.83/09/30. 8310170009
- 8310120284 Forwards Rev 14 to list of active safety-related equipment at qualification level for Sept 1983, per 821123 commitment List includes belance-of-plant & NSSS equipment to assist NRC in review of SER Issue 8

 SMITH.J. L. Long Island Lighting Co. 83/10/05 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 52pp 20893 021 24x

 Fiche 50-322,83/10/05,8310120284 Office
- 8310140231 Submits confirmatory info to facilitate NRC closeout of SER Dutstanding Issue 8 Mods to RCIC turbine completed Detailed NSS3 qualification documentation delivered to site for placement in permanent site file SMITM, J L Long Island Lighting Co 83/10/07 DENTUN, H R Dffice of Nuclear Resctor Regulation, Director 3pp 20762 045 24X Fiche 50-322.83/10/07.8310140231.
- F Security, medical, emergency & fire protection plans
- 831005037B Forwards NRC memo requesting FEMA Regional Assistance Committee (RAC) review of applicant transition plan by 831201 Hearings on admitted contentions may commence as scheduled on 831205. In absence of completion of RAC review 80R0ENICK, B M Hearing Branch 3 83709/28 LAURENGON, J A , LIVINOSTON, M, S , KLINEL J R Atomic Safety and Licensing Board Panel, 3pp 20632 348 24X Ficher 50-322, 83709/28, 8310050376
- 8310050437 Forwards EL Jordan 830715 ltr requesting Regional Assistance Committee review of util transition plan of offsite emergency preparedness Findings & determinations expected by emergency prepareoness raisonys SS 201.

 REPKA, D A Hearing Branch 3 83/09/28 ROSENTHAL, A 8 , EDLES.6 J , WILBER, H A Atomic Safety and Licensing Appeal Panel 3pp 20530 360 24% Fiche 50-322,83/09/28,8310050439
- 8310050427 Forwards T Urbanik 830915 ltr correcting inadvertesst failure to mark as adequate Section III C, "Traffic Capacity Adverse Meather Conditions," of evaluation of evacuation time estimate BDRDENICK, B M Hearing Branch 3. 83/09/30 BIRKENHEIER, J Kirkpatrick, Lockhart. Hill, Christopher & Phillips 3pp 20633 187 24X Fiche 50-322,83/09/30,8310050427
 - 10140027 Urges Commission to reject util emergency preparedness plan State of NY will not impose radiologycal emergency preparedness plan on Buffolk County County will refrain from implementing plan Public safety cannot be assured. CUOMO. M New York, State of 83/10/04 PALLADINO, N. J. Commissioners 2pp 20767.349 24X Fichs 50-322,83/10/04,8310140027

Adjudicatory correspondence

10050359 Forwards NRC 830920 memo re "Huber allegations " W/o encl BORDENICK, B M Hearing Branch 3 83/09/26 BRENNER, L., FERGUSDN. 6 A , MORRIS, P A Atomic Sefety and Licensing Board Panel 2pp 20629 361 24% Fiche 50-322, 83/09/26, 8310050397

- B310030456 Notice of resolution of discovery dispute w/util which was sub; of Suffolk County B30916 & 23 motions to compol answer to interrogatory on local emergency response organization workers & to depose workers Certificate of Svc enci (ETSCHE.K J Buffolk County, NY LETSCHE.K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips B3/09/28 App 20601 044 24X Fiche 50-322,83/09/28,8310030456
- 8310050378 Forwards NRC memo requesting FEMA Regional Assistance Committee (RAC) review of applicant transition plan by 831201 Hearings on admitted contentions may commence as scheduled on 831205, in absence of completion of RAC review BORDENICK, B M Hearing Branch 3 83/09/28 LAURENSON, JA, LIVINOSTON, MS, KLINE, JR, Atomic Safety and Licensing Board Pane) 3pp 20632 348 24X Fiche 50-322,83/09/28,6310050378
- 8310050439 Forwards EL Jordan 830915 ltr requesting Regional Assistance Committee review of util transition plan of offsite energency preparedness Findings & determinations expected by B31201 831201 REPKA,D A Hearing Branch 3 83/09/28 ROSENTHAL,AS, EDLES GJ, WILBER, HA Atomic Safety and Licensing Appeal Panel Upp 20630 360 24X Fiche 50-322,83/09/28,8310050439
- 8310050443 Forwards Region I morning repts re emergency diese)
 generators for 830909-26
 GDDDARD,R J Hearing Branch 3 83/09/28 BRENNER,L,
 FERGUSDN.G A, MORRIS,P A Atomic Safety and Licensing Board Point I
 5pp 20431 345 24X Fiche 50-322,83/09/28,8310050443
- 8310030474 Decision ALAB-743, affirming ASLB 830728 Order LDP-83-42 denying Citizens for Orderly Energy Policy petition to intervene Petition untimely Judge Edles dissenting opinion SHOEMAKER, C J KER.C J Atomic Safety and Licensing Appeal Panel 2060| 116 24X Fichy 50-322.83/09/29.8310030496 H3/09/29
- 8310040199 Response to requests for admissions Certificate of Svc encl LETSCHE,K Suffalk County, NY LETSCHE,K Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/09/29 Long Island Lighting Co 9pp 20415 019 24X Fiche 50-322,83/09/29,8310040199
- G310050375 Forwards Transamerica Delaval 830721 ltr re potential defect in component of standby diesel generator & in mounted furl oil line BORDENICK, B M Hearing Branch 3 83/07/27 BRENNER, L , FEROUSDN. G A , MDRR IS, P A Atomic Safety and Licensing Board Panel 4pp 20627 337 24X Fiche 50-322,63/07/27,8310050375
- 8310040196 Order ruling on objections to ASLB 830819 special prehearing conference order intervenor objections denied as to Contentions 22.12, 13.26 B.35-3B & 43 Objection to Contention 85 grented & contention admitted LAURENSON-J A Atomic Safety and Licensing Board Pancl 83/09/30 Suffolk County, NY 8pp 20608 225 24X Fiche 50-322.83/09/30. 8310040196
- B310040202 Memorandum & order demanding NRC explanation of possible delay of completion of hearing due to FEMA review of util transition plan
 LAURENSON. J.A. Atomic Safety and Licensing Board Panel 83/09/30
 Office of the Executive Legal Director 2pp 20614 274 247
 Fishe 50-322,83/09/30.8310040202 rd Panel 83/09/30 20614 274 247
- 8310040286 Order dismissing Suffolk County motions to crmprl util response to interrogatory & production of local emergency response organization workers for deposition Second discovery conference scheduled for 831003 canceled LAURENSON. J. A. Atomic Safety and Licensing Board Panel. 83/09/20. Suffolk County. NY 2pp 20612 360 24X Fiche 50-322.83/09/20.
- 8310040618 Forwards LILCO counsel 830929 ltr re resolution of pending discovery dispute. Encl ltr accurately reflects resolution, w/listed clarifications Certificate of Svc encl DYNNER. A R Kirkpatrick, Lockhart Hill, Christopher & Phillipt DYNNER. A R Suffolk County, NY 83/09/30 BRENNER, L, FERGUSON. G A, MORRIS. P A Atomic Safety and Licensing Board Panel 7pp 20625 337 24X Fiche 50-322.83/09/30.8310040618
- 8310040430 Rept on mod of automatic depressurization sys logic in response to ASLB request ASLB should defer further consideration pending status rept on implementation of Option 2 due by 840115 Certificate of Syc encl ELLIS.T S Long Island Lighting Co ELLIS.T S Hunton & William 83/07/30, 7pp 20626 055 24X Fiche 50-322.83/07/30,8310040670 Hunton & Williams

63:0050427 Forwards T Urbanik 830915 ltr correcting inadvertent failure to mark as adequate Section III C, "Traffic Capacity - Adverse Weather Conditions," of evaluation of evacuation time estimate BORDENICK, B M Hearing Branch 3 83/09/30 91RHENHEIER, J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 20633 187 24X Fiche 50-322,83/09/30,8310050427

B310050416

- 8310050416 Responses to 830825 interrogatories & request for production of documents & to 830919 interrogatories Certificate of Svc enc!

 LETSCHE.K J Suffolk County, NY LETSCHE.K J Kirkpatrick.
 Lockhart, Hill, Christopher & Philips B3/10/03 Long Island Lighting Co 31pp 20634 019 248 Fiche 30-322.83/10/03.
- 8310050537 Memorandum & order granting util request to defer further consideration of mod to automatic depressurization syslogic pending receipt of util status rept on progress of implementation of mods by 840116
 BRENNER: 1. Atomic Safety and Licensing Board Panel 83/10/03
 Long Island Lighting Co 4pp 20629 354 24X Fiche 50-32.7, 83/10/03,8310050537
- BG10060300 Forwards "Preliminary Metallurgical Evaluation of Failed Crankshaft From Diesel Generator 102" EARLEY,AF Hunton & Williams EARLEY,AF Long Island Lighting Ca B3/10/03 BRENNER,L, MORRIS,PA, FERGUSON,GA Atomic Safety and Licensing Board Panel 15pp 206/6 181 24X Fiche 50-322,83/10/03.8310060300
- 9310060192 Memorandum & order confirming rulings made during 83092/ telcon re Suffolk Gounty 830826 motion to compel discovery on diesel crankshaft failura Util did not give timely notice of opportunity to observe disassembled diusel generaturs BRENNER, L. Atomic Safety and Licensing Board Panel 83/10/04 6pp 20647 037 24X Fiche 50-322,83/10/04,8310060192
- 8310130035 Forwards deposition of EB Lieberman & contentions ro evacuation shadow phenomenon in preparation for testimony Testimony due 831118 Draft should be submitted earlier for review W/o encl REPKA,D A Hoaring Branch 3 83/10/06 URBANIK,(Texas Transportation Institute 2pp 20/25 075 24X Fiche 50-322.83/10/06.8310130035
- 9310120119 Forwards util diesel generator status rept,per 830912 commitment EARLEY,A F Hunton & Williams LARLEY,A F Long Island Lighting Co 83/10/07 BRENNER,L Atomic Safety and Licensing Board Panel 1p 20696 140 24% Fiche 50-322,83/10/07,8310120119
- --8310120121 Diosel generator status rept * Long Island Lighting Co 83/10/07 App 20A9A 141 24X Fiche 50-322,83/10/07,8310120117
- B310140016 Advises that util believes funl load can occur during late First Quarter 1784 or early Second Guarter 1784 REVELEY, W T Hunton & Williams REVELEY, W T Long Island Lighting Co 83/10/07 BRENNER, L, FERGUSON, O A, MORRIS, P A Atomic Safety and Licensing Board Panel 1p 20748 035 24X Fiche 50-322,83/10/07.8310140016
- 8310130245 Response to ASLB 830930 memorandum & order requesting NRC explanation of possible delay in hearing completion NRC does not anticipate that FEMA review will delay hearings Certificate of Syc encl BORDENICK, BM Hearing Branch 3 83/10/11 App 20723 247 P4X Fiche 50-322,83/10/11,8310130245
- B3) 0170365 Schedule for completion of training matls Initial set of drill scenarios should be completed by B31021 Certificate of Svc encl CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams B3/10/11 5pp 20786 177 24X Fiche 50-322,83/10/11, 8310170365
- B310170409 Exceptions to ASLB 830921 partial initial decision Certificate of Svc encl ELLIS.TS Louisiana Power & Light Co ELLIS.TS Hunton & Williams 83/10/11 Atomic Bafety and Licensing Appeal Panel 5pp 20784 325 24X Fiche 50-322, 83/10/11, 8310170409
- 8310170500 Response opposing Suffolk County 830717 motion to compel discovery re emergency planning Matl not relevant but is subj to privilege Requisite showing for privilege made Unexecuted affidavit & Certificate of Syc and CLASB.8 M Federal Emergency Management Agency 83/10/12 Atomic Safety and Liconsing Board Panel 8pp 20784 001 24% Fiche 50-322.83/10/12.8310170500

- B310170401 Prehearing order re proposed preliminary findings of fact & conclusions of law Preliminary findings should be comprehensive & precise in order to narrow & define issues LAURENSON. J A Atomic Safety and Licensi
- 8310190056 Requests util provide Suffalk County w/prior notification of drills & practice exercises which are part of local emergency response organization training program County representatives request permission to observe BIRKENHEIER, J. Kirkpatrick, Lockhart, Hill, Christupher & Phillips BIRKENHEIER, J. Suffalk County, NY 83/10/14 MUNAGHAN, J. A. Hunton & Williams MUNAGHAN, J. A. Long Island Lighting Co. 1p. 20823 222 24X Fiche 50-322,83/10/14,8310190056
- 8310240168 Informs that sys of advisors to each operating shift will be replaced w/experienced BWR operators UML.W O Long Island Lighting Co 83/10/14 ABSELSTINE, J K Commissioners ip 20880 028 24X Fiche 50-322, 83/10/14, 8310240168
- 8310190209 Exceptions to ASLAB 830921 Partial Initial Decision LBP-83-57 Certificate of Svc encl LANPHER.L C Long Island Lighting Ca LANPHER.L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/10/17 Atomic Safety and Licensing Appeal Panel 94pp 20818 138 24X Fiche 50-322,83/10/17.8310190209
- 8310200103 Informs that Shoreham Opponents Coalition will join in Suffolk County exceptions for ASLB 830921 partial initial decision Certificate of Svc encl DOUGHERTY, J B Dougherty, J B DDUGHERTY, J B Shoreham Opponents Coalition 83/10/17 ROSENTHALLA S, EDLES, Q J, WILBER, H A Atomic Safety and Licensing Appeal Panel 3pp 20836 064 P4X Fiche 50-322,83/10/17.8310200105
- 8310200217 Corrected Certificate of Svt to Suffolk County B31017 exceptions to partial initial decision LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips. B3/10/18 Atomic Safety and Licensing Appeal Panel 4pp 20833 065 24X Fiche 50-322,83/10/18,8310200817
- 8310200262 Motion for 60-day extension to file appeal brief & for permission to exceed page limitation re ASLB B31017 Partial Initial Decision LBP-B3-57 Decision voluminous & issues complex Certificate of Svc encl LANPHER.L C Long Island Lighting Co LANPHER.L C Kirkpatrick. Lockhart, Hill, Christopher & Phillips B3/10/18 Atomic Bafety and Licensing Appeal Panel 9pp 20830 069 24X Fiche 50-322,83/10/18.8310200262
- 8310250491 Forwards final FEMA rule on review & approval of state & local radiological emergency plans & preparedness Rule effective 831028 BORDENICK, B M Hearing Branch 3 B3/10/18 LAURENSON, J A , KLINE, J R , BHON, F J Atomic Safety and Licensing Board Panel 15pp 20897 127 24X Fiche 50-322,83/10/18,8310250491
- 8310240160 Supplemental response supporting Suffolk County 830919 motion to compel FEMA to produce certain documents remergency planning FEMA 831012 response fails to comply w/privilege assertion Certifficate of Svc encl LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 833/10/19, Atomic Safety and Licensing Board Panel 14pp 20981274 24X Fiche 50-322,83/10/19,8310240160
- 8310250122 Forwards util 830811 application for amend to Matl/Byproduct License 31-17432-01 & draft Amend 7, permitting remuval of neutron sources from shipping casks & storage in spent fush storage pool W/Certificate of Byc BORDENICK, B M Habring Branch 3 83/10/17 BRENNER, L, FERQUSDN, Q A, MORRIS, P A Atomic Safety and Licensing Board Panel 7pp. 20899 269 24% Fiche 80-322,83/10/19,8310250122
- 8310310128 Forwards diesel generator status rept per 830712 commitment. Related correspondence EARLEY,A F Hunton & Williams EARLEY,A F Long Island Lighting Go B3/10/20 BRENNER,L Atomic Safety and Licensing Board Panel Ip 20949,099 24% Fiche 50-322,83/10/20,8310310128
- --8310310133 Diesel generator status rept * Long Island Lighting Co 83/10/20 7pp 20949 100 24X Fiche 50-322,83/10/20,8310310128
- 8310270239 Joint scheduling submission of util.NRC.FEMA & Buffolk County re emergency planning issues Expeditious ABLB action requested Certificate of Svc encl REPKA.D A Hearing Branch 3 MCCLESKEY, K E Long Island Lighting Co GLASS, 8 M Federal Emergency Management Agency. 83/10/21 App 20924 062 24% Fichs 50-322.83/10/21.8310270239.

- 8310310124 Reply supporting Suffolk County B31018 motion for extensions to file brief re Contention 7B Page limit should not be raised Certificate of Svc encl IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams 83/10/25 Atomic Bafety and Licensing Appeal Panel Bpp 20949 169 24% Fiche 50-322.83/10/25,8310310124
- 8310280118 Order establishing briefing schedule & page limitations for appeals to ASLB 830921 partial initial decision SHOEMAKER,C J Atomic Safety and Licensing Board Panel 83/10/26 3pp 20929 217 24X Fiche 50-322:83/10/26
- 8310310248 Order revising schedule contained in 830830 revised special prehearing conference order All parties ordered to submit proposed schedule for filing cross-motions for summary disposition of Contentions J-10

 LAURENSON, J A Atomic Safety and Licensing Board Panel 83/10/26
 Atomic Safety and Licensing Roard Panel 4pp 20747 178 24X

 Fiche 50-322.83/10/26.8310310248
- 8310310190 Amended notice of hearing Hearing will commence on 831206 & 840103 in Hauppauge.NY & on 831212 in Riverhead.NY LAURENBON.J A Atomic Safety and Licensing Board Panel 83/10/27. 1p. 20758 360 24% Fiche 50-322.83/10/27.8310310190

H General correspondence

- 8310260217 Forwards school board 830727 resolution identifying weaknesses in emergency evaluation plan Licensing should not be permitted until plan assures adequate protection for children & school personnel
 D'ANICOLL, Middle Island, NY 83/10/03 LAURENSON, J A Atomic Safety and Licensing Board Panel. 4pp 20712 107 24X
 Fiche 50-322,83/10/03,8310260217
- O Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Qualification Tests" Syc list encl JORDAN, E. L. Division of Emergency Pregaredness & Engineering Response (Fost 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Cas.
 Detectors Positioned at Control Room Ventilation Air
 Intakes "Syr list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/07/26 Consolidated Edison Co of New
 York, Inc 116pp 20777 210 24X Fiche 50-000,63/09/26,63083003042
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl, JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp, 20778 001 24X Fichs S0-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shaelding Attached to Safety-Related Sys Wo 10CFR80 37 Evaluation " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 30-000,83/09/29,8308300349
- 8308300378 IE Info Natice 83-65. "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Syc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/07 Consolidated Edison Co of Net York, Inc 74pp 20827-213. 24X Fiche-50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " 8vc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/10/07. Consulidated Edison Co of Not York, Inc 79pp 20882 026 24X Fiche, 80-000, 83/10/07, 8308300752
- 8308300757 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl.
 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 630103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp. 21043 075, 24X Ficher 50-000, 83/10/11, 83080000757
- 8308300761 IE Info Notice 83-68, "Respirator User Marning Defective Self-Contained Breathing Apparatus Air Cylinders " Syc list encl.
 JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/10/11 Consolidated Edison Co of New York, Inc. 120pp. 20827 127 24X Fiche: 50-000,83/10/11,8308300761

- 8310310222 Ack receipt of 830915 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/83-21 STARDSTECKLR Division of Project & Resident Programs 83/10/25 POLLOCK.M S Long Island Lighting Co 2pp 20947 23J 24X Fiche 50-322,83/10/25.8310310222
- --8310310224 Responds to NRC 830815 ltr re violations noted in II lasp. Rept 50-322/83-21 Corrective actions util performing complete walkdown of relay room to ansure that method used to identify separation violations adequate MUSELER. W J Long Island Lighting Co 83/09/15 STAROSTECK1.R Division of Project & Resident Programs 5pp 20947 235 24x Fiche 50-322,83/10/25,8310310222
- S Reportable occurrences, LERs & related correspondence
- B30B310050 Board Notification B3-160 provides info re 830812 failure of main crankshaft on one of thise Transamerica Delaval emergency dissel generators at Shoreham ETSENHUT,D @ Division of Licensing 83/10/14 PALLADING,N J . GILINSKY,V , ROBERTS,T Commissioners 15pp 20966 312 24X Ficae 50-000,B3/10/14,B30B310050
- --B310310454 "Shoreham Emergency Diesel Generator 102 Cranksheft Failure Analysis/Recovery Master Plan " Stop work authorizations encl MILLIGAN,M H , ROSE,J T , YOUNGLING,E J Long Island Lighting Co B3/08/23 17pp 20966 338 24X Fiche 50-322,83/10/14,8308310059
- T Hearing transcripts on non-antitrust matters
- B310250375 Forwards transcripts of T Urbanik & JR Sears 630914 depositions & errata sheets W/o transcripts REPKA.D A Hearing Branch 3 B3/10/13 B1LLINGSLY.W E Alderson Reporting 1p 20897 298 24% Fiche 50-322, B3/10/13, B310250375
- --8310250381 Errata sheet for T Urbanik 830914 deposition URBANIK.T NRC - No Detailed Affiliation Given 83/09/30 Ip 20897 299 24X Fiche 50-322,83/10/13,8310250375
- --8310250384 Errota sheet for JR Sears 830914 deposition SEARS:JR NRC - No Detailed Affiliation Given 83/10/13 1p 20897 300 24% Fiche 50-322,83/10/13-8310250375
- U Congressional/Executive Correspondence
- B310280144 Ack receipt of 830926 ltr to President Reagan re offsito emergancy preparadness Emergoicy plan which does not require participation of Suffolk County govt, under review by FENA Fuel load & low power license not permitted by ABLB CUNNINGHAM, G H Office of the Executive Legal Director B3/10/75 BEHAN, J L New York, State of 2pp 20727 046 24X Fiche 50-322,83/10/25.8310280144
- --8310280144 Forwards VL Behan 830726 request for info from President Reagan re offsite emergency preparedness Direct response requested KELLEY.8 President of UB & Executive Offices 83/10/11 NRC ~ No Detailed Affiliation Given 6pp 20727 057 24X fiche 50-322.83/10/25.8310280144
- X Onsite Storage of Low Leve) Waste
- B310250122 Forwards util B30B11 application for amend to Matl/Byproduct License 31-17432-01 & draft Amend 7, permitting removal of neutron sources from shapping casks & storage in spent fuel storage pool W/Certificate of Bvc B0RDENICK, B M Hearing Branch 3 83/10/19 BRENNER, L, FERGUSON, G A. MORRÍS, P A Atomic Safety and Licensing Board Panel 7pp 20879 269 24% Fiche 50-322, 83/10/19, 8310250122
- DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8310110034 Further response to FOIA request for records re NUREO-0862 investigative rept & investigations concerning facilities Forwards App A documents Commissioner Bradford 811217 memo withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/06/15 REYNOLDS, J Center for Law in the Public Interest 4pp 20713,001 24X Fiche 50-275,83/06/15,8310110034

DOCKETED ITEMS

- --8208010014 Requests issuance of final statement clearing RL Cloud Associates from allegations of wrongdoing in preparation of "Preliminary Rept. Seismic Verification Program." per NRC investigation results in NUMEG-0862. Issue 3 CLOUD.R L. Robert L. Cloud Associates. Inc. 82/08/24 PALLADING.N. J. Commissioners. 3pp. 20713-032 24X Fiche 50-275.83/06/15.8310110034
- --8310110037 Forwards draft ltrs to Subcommittee on Energy & Environ & Subcommittee on Energy Conservation & Power transmitting NRC review of NUREG-0862 Comments requested by 820811 HAMMERER. C Office of Congressional Affairs 82/08/09 BICKWIT.L Office of the General Counsel CUMMINGS. J Office of Inspector & Additor FITZOFRALD. J Office of Investigation 5pp 20713 008 24% Fiche 50-275.83/06/15.8310110034
- --B310i10D46 Responds to B11217 ltr expressing concern re delays in licensing process Immediate issue concerns acceptability of util proposed auditors.RL Cloud Assoc Investigation scheduled for completion on B2110B & D30201 KAMMERER,C Office of Congressional Affairs B2/01/10 RQUSSCLOT,J H House of Rep 1p 20713 013 24X Fiche 50-275,83/06/15,8310110034
- --8310110048 "Chronolgy of Events "

 * Affiliation Unknown 83/06/15 8pp 20713 015 24X
 Fiche 50-275.83/06/15.8310110034
- --8310110057 Draft ltrs re adequacy of NHC investigation into development of RL Claud Assoc rept.per NUREG-0862. "Insp Rept of Preliminary Rept. Beismic Reverification Program at Diable Cangon Nuclear Power Plant"

 PALLADING, N Commissioners 83/06/15 UDALL M K Hause of Rep. Interior & Insular Affairs OTTINGEN.R., DINGELL.J House of Rep. Energy & Commerce 7pp 20713 024 24X

 Fiche 50-275,83/06/15.8310110034
- --8310110095 Forwards RL Cloud 820824 request for final statement on conclusions of Cloud/util investigation to clear Cloud prof reputation Matter presented in NUREO-0862 & SECY-82-89 Commission guidance requested DIRCKS.W J Office of the Executive Director for Operations 83/09/08 PALLABINO.N Commissioners ip 20713 031 24X Fiche 50-275,03/06/15,8310110034
- --8310110107 Forwards summary documenting record actions of peer review group REMM,TA Office of the Executive Director for Operations 82/02/18 PALLADINO.N . GILINGKY.V . BRADFORD.F Commissioners Ip 20713 036 24X Fiche 50-275.83/06/15.8310110034
- --B3i01101ii Forwards summary of Region V peer review group assistance w/
 investigation of RL Cloud Arsoc Related info entl
 CORNELL,E K Office of the Executive Director for Operations
 CABE,E & Office of Nuclear Reactor Regulation, Director
 SNIEZEK,J H Director's Office, Office of Inspection and
 Enforcement 82/02/18 DIRCKB, J Office of the Executive
 Director for Operations /App 20713 037 24X
 Fiche 50-275,83/04/15,83i0ii0034
- 8310270255 FDIA request for Polk & Schierling 830218 memo to Knighton & Lear re reverification program to be placed in PDR BUCKLES,R NUS Corp 83/06/30 Division of Rules and Records ip 20943 066 24% Fiche 50-275,83/06/30,8310270255
- B310270250 Responds to FOIA request for Folk & Schierling B30218 memo to Knighton & Lear re reverification program Memo placed in PDR FELTON, J M Division of Rules and Records B3/07/15 BUCKLES.R. NUB Curp ip 20943 065 24% Fithe 50-275.83/07/15.8310270250
- B310180609 F01A request for complete set of BNL repts on seismic design of facilities CALSOYAS,C D Affiliation Unknown B3/08/16 Region 5, Dffice of Director App 20824 315 24X Fiche 50-275, B3/08/16, B310180609
- 8310180410 Responds to FOIA request for complete set of BNL repts on seismic design of facilities Documents listed in apparatible in PDR FELTON, J H Division of Rules and Records 83/09/01 CALBOYAS, (AFfiliation Unknown 2pp 20824 319 24X Fiche 50-275.83/09/01, 8310180610
- 8308300335 Board Notification B3-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle ETBENHUT.D 0 Division of Licensing 83/07/29 PALLADING,N J, QTLINBKY,V, ROBERTS.T M Commissioners 10pp 20632 106 24X Fishe 50-000,83/09/29,8308300755

- B308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Cangon i & 2.Fermi 2 & Callaway EISENHUT.D 0 Division of Licensing B3/09/29 PALLADIND.N J OILINSKY, V. ROBERTS.T Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300357
- 8308300358 Board Notification 83-150 forwards listed repts re facility IDVP Info will be considered in final evaluation of verification of plant mods & matters to be completed for license activities
 EISENNUT.D & Division of Licensing 83/09/30 PALLADINO,N J.
 OILINSKY,V. ROBERTS.T M Commissioners 3pp 20644 032 24X
 Fiche 50-275,03/09/30.83083003398
- 8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Mestinghouse plants.in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT D C Division of Licensing 83/10/04 PALLADING.N J Commissioners 2pp 20698 033 24X Fiche 50-000,63/10/04.
- 8308300771 Doard Notification 83-128A forwards Equipment Gualification Branch conclusions repotential problems w/ASCO solenoid valves EISENHUT.D G Division of Licensing 83/10/06 PALLADINO,N J . GILINGKY.V . ROBERTS.T M Commissioners 31pp 20818 001 24X Fiche 50-000,83/10/06.8308300771
- B310170471 Forwards design review effort description discussing interrelationship of design verification program w/Unit 2. Review provides assurance that design conforms w/licensing commitments SCHUYLER.J D Pacific Oas & Electric Co B3/10/06 EISENHUT.D G Division of Licensing 12pp 20783 272 24X Fiche 50-323.83/10/06.B310170471
- 8310170489 Forwards additinfore alternate methods of statistical evaluation of Superstrut spot weld shear strength test data, in response to NRC request Test data evaluation presented in 830701 rept remains reasonable k valif SCHUYLER, J D Pacific Gas & Flectric Co 83/10/07 EISENHUT, D C Division of Licensing 3pp 20783 315 24X Fiche 50-275, 83/10/07, 8310170489
- 8310210227 Forwards "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities "
 6CHVYLER.J O Pacific Gas & Electric Co 83/10/13 EISENHUT, D 0
 Division of Licensing lp 20852 112 24X Fiche 50-275.83/10/13,
 8310210227
- --8310210227 "Seismically Induced Sys Interaction Program (SISIP) Completion of Containment Activities " # Bechtel Corp 83/10/13 262pp 20852 113 24X Fiche 50-275,83/10/13.8310210227
- 830 8300775 Board Notification 83-135A forwards 830919 revised draft of "QA Case Study Working Paper Case C." & cover & transmittal memos re Diablo Canyon EISENHUT, D. G. Division of Licensing 83/10/14 PALLADINO, N.J., GLLINBKY, V., ROBERTS.T. Commissioners 3pp 20799 001 24X Fiche 50-000, 83/10/14, 8308300775
- --B310180505 Informs that working papers for three GA case studies complete, per B30923 memo Case C re Diablu Canyon, dtd B30919, is rev to B30719 draft transmitted in Board Notification B3-135 on B30902 Papers & transmittal ltrs forwarded TAYLOR, J M GA Branch B3/09/28 EISENHUT, D 9 Division of Licensing 2pp 20797 004 24X Fiche 50-000, 83/10/14, 83083007
- --8310180311 Forwards case study working papers for site-per review program for plant design & const Final Congressional rept will contain consolidated summary of case study conclusions TAYLOR, J M GA Branch B3/08/02 MANEATIB, O A Pacific Gas Electric Co 1p 20799 006 24X Fiche 50-000, 83/10/14, 8308300775
- --8310180517 Forwards revised draft of "QA Case Study Working Paper Case C " ALTMAN, W D NRC - No Detailed Affiliation Given 83/09/27, - No Detailed Affiliation Given ip 20799 007 24X Fiche: 50-000, 83/10/14, 8308300775
- --8310180521 Revised draft of "QA Case Study Working Paper Case (
 * NRC No Detailed Affiliation Given 83/09/19 NRC No Detailed Affiliation Given 42pp 20799 008 24X Fichs 50-000.83/10/14,8308300775

- 8310190197 Advises that qualification tests for special rods & couplers revealed straight rods removed from Unit 2 rupture restraints had heat exhibited ductilities less than design Rods will be reannealed or reglaced SCHUYLER, J.O. Pacific Gas & Electric Cp. 83/10/04 EISENHUT, D.G. Division of Licensing 2pp. 20818 102 24X Fiche 50-275,83/10/14,831019(0):97
- 8310190054 Forwards documents NRC delivered to Commissioner Gilinsky during 831017 briefing on plant design reverification OILINSKY, V Commissioners 83710/17 Office of the Executive Legal Director 20pp 20823 259 24X Fiche 50-275,83/10/17,8310190054
- B30B310029 Board Notification B3-161 forwards anonympus 1th alleging arrors in design/documentation of safety-related systemation of safety-related systems tructures & components at Unit 1
 EISENHUT, D. G. Division of Licensing B3/10/18 PALLADINO, N. GILINSKY, V. RODERTS. T. Commissioners 4pg 20900-075 24X
 Fiche 50-275, 83/10/18, 830B310029
- Security, medical, emergency & fire protection plans
- 1310040221 Forwards IE Insp Repts 50-275/83-25 & 50-323/83-18 on 830718-22 & 0818 No noncompliance noted NORDERHAUGL R Region 5, Office of Director 83/09/20 SCHUYLER, J O Pacific Gas & Electric Co 2pp 20617 250 24X Fiche 80-275,83/09/20.8310040221
- -8310040226 IE Inap Repts 50-275/83-25 & 50-323/83-18 on 830710-22 & O818 No noncompliance noted Major areas inspected emergency preparedness program including emergency detection & classification & protective action decisionmaking SCOHN.K Region 5. Office of Director 83/09/19 13pp 20417 252 24X fithe 50-275.03/09/20,8310040221
- OiO:80620 Advises that 830803 proposed changes to Rev II to physical security plan & Rev 2 to safeguards contingency plan acceptable per IOCFR50 54(p) Encls to Itr withheld (ref IOCFR73 21)
 KNICHTON, O R Licensing Branch 3 83/10/12 SCHUYLER, J D Pacifix Oas & Electric Co 3ep 20817 336 24X Fiche 50-275,83/10/12,8310180620
- 310270566 Releases public version of revised corporate emergency response plan & revised emergency response plan implementing procedures
 FELTON.J M Division of Rules and Records 83/10/25 Document
 Management Branch 1p 20945 007 24X Fichs 50-275,83/10/25.
- -8310270572 Forwards public version of Rev 2 to corporate emergency response plan & revised emergency response plan implementing procedures SCHUYLER: J O Pacific Oas & Electric Co 83/10/10 MARTIN, J B Region 5, Office of Director 3pp 20945 008 24X Fiche 50-275,83/10/25.8310270566
- -B310270575 Public version of Rev 2 to corporate emergency response plan BCHUYLER, J. D. Pacific Qas & Electric Co. 83/09/12 85pp 20945 011 24% Fiche 50~275,83/10/25,8310270566
- -8310270580 Public version of revised corporate emergency response plan implementing procedures, including Procedures 3 i re governmental relations, 3 2 re corporate communications dept & 3 3 re law SCHUYLER, J O Pacific Gas & Electric Co 83/10/04 300pp 20945-096 24X Fiche 50-275, 63/10/25, 8310370866
- 10270582 Releases public version of revised emergency plan implementing procedures FELTON, J H Division of Rules and Records B3/10/25 Document Management Branch ip 20946-099 24X Fichs 50-275, 83/10/25, 8310270582,
- 8310270586 Forwards public version of revised emergency plan implementing procedures, including Procedures 2 1 re plant maint; 3 4 re insurance k 3 6 re security BCHUYLER, J O Pacific Qe's & Electric Co 83/09/12 MARTIN, J B Region 5, Office of Director 3pp 20946 100 24X Fiche: 50-275, 83/10/25, 83102/0582
- B310270588 Public version of revised emergency glan implementing procedures; including Procedures 2 1 re plant maint, 3 4 re insurance & 3 6 re security SCHIVLER, J D Pacific Oss & Electric Co. 83/08/14 150pp 20946-103. 24X Fiche 50-975, 82/10/25, 83/0270582

- G Adjudicatory correspondence
- 8310260277 Contentions on design QA re verification of samples for TDVP STRUMMASSER, M. California, State of REYNDLDS, J. Joint Intervenors-Diablo Cangon REYNDLDS, J. Center for Law in the Public Interest 83/09/08 Atomic Safety and Licensing Appeal Panel 103pp 20911 039 24x Fiche 50~275,83/09/08,8310260277
- B310050371 Confilms B30920 telcon re Governor Deukmejian B30902 request for documents List of requested documents will be sent by B31004 MCGURREN, H J Hearing Branch 3 B3/09/26 DURBIN, S California, State of lp 20630 354 24X Fiche 50-275, B3/09/26, B310050371
- 8310050454 Response opposing Joint Intervenors 830926 request for hearing on lifting of license suspension No legal basis presented to support hearing Certificate of Svc encl CHANDLERL J. Hearing Branch 2 83709726 Commissioners 15pp 20630 040 24% Fiche 50-275,83709726,8310050454
- 8310040251 First supplemental responses to interrogatories Certification of counsel & Certificate of Svc encl Relatid correspondence LUBBOCK,D & Pacific Gas & Llectric Co 83/07/20 California. State of 7pp 20613 042 24X Fiche 50-275,83/09/28,8310040251
- 8310040288 First supplemental answers to third set of interrogatories Prof qualifications & Certificate of Syc encl Related correspondence STRUMMASSER: M California, State of 83/09/28 Pacific Gas & Electric Ca 25pp 20514
- 8310050396 First supplemental response to third set of interrogatories Certificate of Evc encl Related correspondence LUBBOCK, D 0 Pacific Oas & Electric Co. 83/09/28 Collifornia, State of 66pp 20634 186 24X Fiche 50-275,83/09/28,8310050396
- 8310030384 Motion for sanctions against Covernor Deukmejian & Joint Intervenors for failure to suppl interrogatories seasonably Intervenors have engaged in concrete course of conduct to delay proceedings Certificate of Svc encl CRANE.P A Pacific Cas & Electric Co B3/09/29 Atomic Safety and Licensing Appeal Panel 18pp 20372 154 2AX Fiche 50-275,83/09/29.8310030384
- 8310040209 Motion for mod of schedule established in ASL8 83090/ order re design QA hearing Delay in completion of IOVP renders schedule impossible to meet KAUFMAN.P H California. State of 83/09/29 Atomic Safety and Licensing Appeal Panel 17pp 20614 335 24X Fiche 50-275. 83/09/29,8310040207
- --B310040212 Addl contentions on design QA

 KAUFMAN,P H California, State of REYNOLDS,J Joint
 Intervenors-Diable Canyon REYNOLDS,J Center for Law in the
 Public Interest B3/09/29 Atomic Safety and Licensing Approl
 Panel App 20614 352 24X Fiche 50-275,83/09/29,8310040209
- --8310040219 Application for expedited ruling on motion for mad of hearing schedule Motion should be ruled on quickly since testimong due 831008 Certificate of Svc encl KAUFMAN, P H California, State of 83/09/29 Atomic Safety and Licensing Appeal Panel 6pp 20614 356 24X Fiche 50-275,83/09/29,8310040209
- 8310040539 Supplemental response to second set of interrogatories Cartification of counsel & Certificate of Svc encl Related correspondence HAWIAN, E.R. Joint Intervenors-Diable Canyon HAVIAN, E.R. Center For Law in the Public Interest 83/09/29 Pacific Oas & Electric Co. 7pp. 20824-019 24X Fiche 50-275, 83/09/29, 8310040539
- 8310040302 Order extending time until 831007 for Commission to act to review ALAB-728 CHILK.8 J Office of the Secretary of the Commission 83/09/30 Commissioners 1p 20614 168 24X Fiche 30-275,83/09/30,8310040302
- 8310040525 Forwards author notice of appearance Certificate of Svc encl LUBBOCK,D Q Pacific Gas & Electric Co 83/09/30 Docketing & Services Branch 4pp 20624 226 24X Fiche 50-275,83/09/30, 8310040525
- 8310070209 Staff requirements man re 830927 discussion of proceeding schedule Commission will hold 831028 public meeting in Hashington, DC re issues related to fuel loading CHILK, 8 J Office of the Secretary of the Commission 84/09/30 Office of the Secretary of the Commission 1p 20676 362 21X Fiche 30-275,83/09/30,8310070209

- #310050421 Fourth supplemental response to first set of interrogatories Gentificate of Svc encl #EXYNOLDS. J Joint Intervenors-Diable Conyon #REYNOLDS. J Lenter for Law in the Public Interest #3710/03 Pacific Gas & Electric Co 9pp 20630 334 24X Fiche 50-275,83/10/03,8310050421
- 8310110053 Answer opposing will motion for sanctions for alleged failures to suppl interrogatory answer seasonably Motion wholly unfounded & should be denied Declaration of counsel & Certificate of Syc encl STRUMMASEER,M California, State of 83/10/04 Atomic Safety and Licenoing Appeal Panel Pipp 20668 244 24% Fiche 50-275, 83/10/04,8310110053
- B31011005B Forwards Page 41 of Nuclear Svcs Corp audit of Pullman Power Products filed W/Joint Intervenors 830909 suppl to motion to reopen second on const 0A issue REYNOLDB. J Center for Law in the Public Interest REYNOLDB. J Joint Intervenors-Diable Canyon 83/10/04 Atomic Safety and Licensing Board Panel 2pp 2066B 239 24% Fiche 50-275.83/10/04, 8360110008
- #310110073 Response opposing Governor Deukmejian & Joint Intervenors #30929 add1 contentions on GA Contentions lack specificity #5/or fail to meet criteria for late-filed contentions Certificate of Svc encl LOCKER, R F Pocific Oas & Electric Co #3/10/04 Atomic Sofot, and Licensing Appeal Panel Opp 20567 299 24X Fiche 50-275.83/10/04.8310110073
- B310110120 Response opposing Governor Deukmejian 830907 motion to modify schedule for conduct of hearings Motion is only another unsubstantiated play for delay Certificate of Svc encl NORTON, B Pacific Gas & Llectric Co NORTON, B Norton, Bulke, Berry & French 83/10/04 Atomic Safety and Licensing Appeal Panel 12pp 20666 212 24X Fiche 50-275,83/10/04.8310110120
- G310110127 Response opposing licenses motions for sanctions against Covernor Deukmejian & Joint Intervenors Intervenors supplemented interrogatory answers in timely manner Certificate of Byc encl REYNOLDB. J Joint Intervenors-Diablo Canyon REYNOLDB. J Center for Law in the Public Interest 63/10/04 Atomic Safety and Licensing Appeal Panel 8pp 20666 204 24X Fiche 50-275.83/10/04, 831011012/
- OBJIO110317 Response supporting Governor Deukmejian B30929 motion for mod of hearing schedule Deposition schedule not completed & time for filing contentions expired prior to issuance of IDVP repts Certificate of Bvc oncl
 REYNOLDS.J Joint Intervenors-Diable Canyon REYNOLDS.J Center for Law in the Public Interest 83/10/04 Atomic Bafety and Litersing Appeal Panel App 20645 358 24X Fiche 50-275,83/10/04,83(0110317
- B310120418 Response of IDVP to Interrogatory 57 in third set of interrogatories Certificate of Svc encl Related correspondence RASKIN, D.B. Lawenstein, Nowman, Reis, Axelrad & Toll 83/10/05 STRUMWABSER, M. California, State of 7pp 20699 044 24X fiche, 50-275, 83/10/05, 8310120418
- 8310130017 Response apposing Governor Deukmejian 630927 motion for 2-wk extension of discovery schedule set in ASLAB 630907 order Governor began discovery process only 3 wks before hearing Extension would dolay hearing CHANDLER.L J Hearing Branch 2 83/10/05 Atomic Safety and Licensing Appeal Panel 7pp 20725 191 24X Fichs 50-275,83/10/05,8310/3037.
- ---9310130017 Response supporting licensee 830929 motion for sanctions upon Governor Daukmejian/Joint Intervenors Depositions of Apostolakis, Kampthorne & Hubbard should be held during wk of 831010-14 Certificate of 8vt encl
 CHANDLER, L. J. Hearing Branch 2 83/10/05 Atomic 8afety and Licensing Appeal Panel 6pp 20725 198 24X
 Fiche. 50-275, 83/10/05, 8310130017
- B310130163 Response to 830902 document request consisting of computer printout listing documents in docket since 811101 Documents to be copied should be identified HCGURREN.H J. Hearing Branch 1 83/10/05 DURBIN.S L California, State of 4pp 20724 280 24X Fiche 50-275,83/10/05,8310130163
- 8310110298 Application for subpoema for 9 Apostolakis for 831011 deposition & production of documents NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burks, Berry & Crench 83/10/06 Atomic Safety and Licensing Appeal Panel App 20666 190 24X Fiche 50-275,83/10/06,8310110798

- --8310110301 Natice of G Apostolakis deposition on 831011 in San Francisco,CA Certificate of Svc encl NORTON,B Pacific Gas & Electric Co NORTON,B Norton, Burke, Berry & French 83/10/06 4pp 20666 104 24% Fiche 50-275,83/10/06,8310110298
- 8310120376 Second supplemental answers to first set of interrogatories Certification of counsel & prof qualifications encl DURBIN'S L California, State of 83/10/07 Pacific Gas & Electric Co 2Bpp 20699 132 24X Fiche 50-275, 83/10/07, 8310120376
- --8310120381 First supplemental answers to second set of interrogatories Certification of counsel encl DURBIN:9 L. California, State of 83/10/07 Pacific Gas & Electric Co 17pp 20699 140 24X Fiche 50-275, 83/10/07, 8310120376
- --8310120386 First supplemental answers to fourth set of interrogatories Certification of counsel & Certificate of Svc encl DURBIN.S L. California, State of 83/10/07 Pacific Gas & Electric Co 8pp 20699 17/ 24X Fiche 50-275,83/10/07,8310120374
- 8310120385 Order confirming 831005 oral rulings during telcon re reopened proceeding on design QA Covernor Deukmejian 830929 motion for mod of schedule granted in part 8H0EMAKER.C J Atomic Safety and Licensing Appeal Panel 83/10/07 8pp 20699 185 24X Fiche 50-275,83/10/07,8310120385
- 8310120412 Order extending time until 831017 for Commission to act to review ALAB-728 CHILK, S. J. Office of the Secretary of the Commission B3/10/07 Commissioners ip 20698 052 24X Fiche 50-275,83/10/07, 8310120412
- 8310130243 Fifth supplemental response to first set of interrogatories Portions of RB Hubbard & FJ Samaniego 821221 direct testimony & Certificate of Svc encl REYNOLDB, J Joint Intervenors-Diablo Canyon REYNOLDB, J Center for Law in the Public Intervest 83/10/07 Pacific Gas & Electric Co 19pp 20723 253 24X Fiche 50-275,83/10/07,8310130243
- 8310180160 Motion for leave to file reply to NRC & util responses to Joint Intervenors 830707 suppl to motion to reopen record on const QA Responses raised defenses & relied on documents not previously part of record Certificate of Svc encl
 REYNDLDS, J Joint Intervenors-Diablo Canyon REYNDLDS, J Center for Law in the Public Interest 83/10/13 Atomic Safety and Licensing Appeal Panel App 20807 147 24% Fiche 50-275,83/10/13,8310180160
- 8310180248 Response to Governor Deukmejian.NRC & util replies to Joint Intervenors 830909 suppl to motion to reopen record on const GA NSC audit rept provides irrefutable evidence of breakdown in Pullman GA program Certificate of Bvc encl REYNOLDS, J Joint Intervenors-Diablo Canyon REYNOLDS, J Center for Law in the Public Interest 89/10/13 Atomic Safety and Licensing Appeal Panel 12pp 20802 320 24X Fiche 50-275, 83/10/13.8310180248
- 8310190219 Motion for order of enforcement of ASLAB 831007 order directing Governor Deukmejian & Joint Intervenors to suppl interrogatory responses & documents requested Parties failed to provide required documents Certificate of 800 enci CRANE.P A Pacific Gas & Electric Co 83/10/13 Atomic Safety and Licensing Appeal Panel 8pp 20818 037 24X Fiche 50-275,83/10/13,8310190219
- 8310180328 Second supplemental response to third set of interrogatories Certificate of Syc enci Related correspondence LUBBOCK,D G Pacific Oas & Electric Co B3/10/14 DEUMMEJIAN California, State of 14pp 20806 162 24X Fiche 50-275,83/10/14, 8310180328
- B31021022B Forwards PJ Kempthorne & FI Sameniego testimony REYNOLDS, JR Center for Law in the Public Interest B3/10/15 MODRE T S Atomic Safety and Licensing Appeal Panel 1p 20852 042 24X Fiche 50-275, B3/10/15, B31021022B
- ---8310210242 Exhibit list Certificate of Svc encl REVNOLDSIJ Joint Intervenors-Diablo Cangon REVNOLDSIJ Center for Law in the Public Interest 83/10/15 App 20852 045 24X Ficher 50-275,83/10/15,8310210228
- B31020017B Testimony of RB Hubbard re design GA Verification program has not yet demonstrated plant design complies w/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence HUBBARD, R B California, State of 8J/10/16 79pp 20835 127 24X Fishe 50-275,83/10/16,831020017B

- --8310200195 List of exhibits identified per ASLAB 831007 order Centificate of Svc encl STRUMMASER.M California, State of 83/10/16 9pp 20839 209 24% Fiche 50-27%,83/10/16,8310200178
- 8310190054 Forwards documents NRC delivered to Commissioner Gilinsky during 831017 briefing on plant design reverification OILINSKY. V Commissioners 83/10/17 Office of the Executive Legal Director 20pp 20823 289. 24X Fiche 50-275.83/10/17.83/10/2054
- 8310190261 Order extending time until 831028 for Commission to act to review ALAB-728 Period of the Secretary of the Commission 83/10/17 Commissioners ip 20818 082 PAX Fiche 50-275.83/10/17.8310190261
- 8310270338 Forwards addl copies of direct testimony & accompanying matls 8ky Courier & Eastern Airlines lost original transmittals Inconvenience regretted STRUMMASSER, M California, State of 03/10/17 MODRE.TS Atomic Safety and Licensing Appeal Panel 1p 20923 302 24% Fiche.50-275,83/10/17.8310270338
- --8310270348 Answer opposing util B31013 motion for order of enforcement Util violated order several times Grounds for requested relief nonexistent STRUMHASSER: M California, State of. 83/10/17 Atomic Safety and Licensing Appeal Panel 7pp 20723 303 24X Fiche 50-275,83/10/17,8310270338
- --8310270377 Affidavit of RB Hubbard re safety-related aspects of QA grograms Prof qualifications & Certificate of Svc enc1 HUBBARD.R B California. State of 83/10/21 17pp 20923-310. 24X Fiche-50-275.83/10/17.8310270338
- 8310250283 Forwards US Court of Appeals.DC Circuit, 831007 amended opinion affirming NRC denial of Atty General Bellotti petition to intervene CHANDLER.L J Hearing Branch 2 83/10/18 CHILK, 8 J Office of the Secretary of the Commission 23pp 20894 232 24X Fiche 50-275, 83/10/18, 8310250283
- 6310240138 Motion for revocation of License DPR-76, or in alternative, for continuation of suspension Continuing nature of matl false statements & unresolved questions re adequacy of const unacceptable Centificate of Svc encl REYNOLDS. J Joint Intervenors-Diablo Canyon. REYNOLDS, J Center for Law in the Public Intervet 83/10/20 Commissioners 68pp 20881 224 24X Fiche 50-275,83/10/20,8310240158
- 8310240174 Objection to Joint Intervenors proposed Exhibits 128 & 129 & State of CA Governor Exhibit II re design GA Exhibits irrelevent & immaterial to proceeding Contificate of Svc encl
 CRANG.P A Pacific Gas & Electric Co 83/10/20, Atomic Safety and Licensing Appeal Panel 4pp 20880 030 24X Fiche 50-273,83/10/20.8310240174
- 9310250043 Objections to util & NRC exhibits & testimony, per ABLAU 831007 order Certificate of Byc encl HAVIAN, E. Joint Intervenors-Biablo Conyon HAVIAN, E. Center for Law in the Public Interest 83/10/20 Atomic Bafety and Licensing Appeal Ponel 6pp 20894 081 24X Fiche 50-275,83/10/20,8310280043
- 3(0250467 Comments on Joint Intervenors & Governor Deutmejian testimony & proposed exhibits.psr ASLB 831007 order, Governor Exhibits 27-31 not provided for review Exhibits 127 & 132 acceptable CHANDLER, L J. Hearing Branch & 83/10/21 HOORE, T S., BUCK, J N., JOHNSON, H R. Atomic Safety and Licensing Board Panel 2pp 20897 102 24X Fiche 50-275,83/10/21,83/10250467
- 8310260236 Submits suppl to 830901 comments on IDVP final rept & SBER 18 re reissuance of suspended license for fuel loading & low power operation License reissuance opposed Cartificate of Svc encl REYNOLDS, J.R. Center for Law in the Public Interest REYNOLDS, J.R. Joint Intervenors-Diablo Compon 83/10/24 PALLADIND, N.J., QILINSKY, V.R. RBERTS, T. Commissioners (4pp 20912 192 24X Fiche 30-275, 83/10/24, 8310260236.
- 3310260270 Order denying Joint Intervenors 630510 & Covernor Desimblian 630517 motions to respen record re adequacy of applicant const 0A program. Motions fail to meet stds SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel B3/10/24 Joint Intervenors-Diable Canyon 2pp 20911.309. 24X Fiche 50-275,83/10/24,8310260270

- 8310310141 Notice of withdrawal of Contentions 3c.d.e.g.i.j.k & n redesign GA failures Contentions found to be within licensing criteria or were resolved by addl technical info Certificate of Svc encl DURBIN, S L California. State of REYNOLDS, J R Joint Intervenors-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 83/10/24 16pp 20959 019 24% Fiche 50-275.83/10/248310310141
- 8310270263 Answer opposing Joint Intervenor 831020 motion for revocation of UL or for continuation of suspension Applicant has not misrepresented or failed to disclose facts Certificate of Svr encl CRANE.P A Pacific Gas & Electric Co 83/10/25 Commissioners 13pp 20922 028 24% Fiche 50-275,83/10/25.8310270263
- B31027035B Forwards Joint Intervenor & Governor Deukmejian Tevisod contentions on design QA.replacing Exhibit I transmitted w/B31024 1tr REYNOLDS, J R Center for Law in the Public Interest REYNOLDS, J R Joint Intervenors-Diable Congon 83/10/25 PALLADINU, N J . GILINSKY, V . ROBERTS T Commitseiners ip 20923 294 24X Fiche 50-275,83/10/25,8310270258
- --8310270361 Issues to be contested by Governor Deukmejian & Joint Intervenois * Joint Intervenors-Diablo Canyon 83/10/24 /pp 20923 295 24X Fiche 50-275.83/10/25.0310270358
- 8310280097 Reply to util objections to Joint Interveners proposed exhibits Objections should be overruled Certificate of Svc encl
 HAVIAN, E Joint Intervenors-Diablo Canyon HAVIAN, E Center for Law in the Public Interest 83/10/25 Atomic Safety and Licensing Appeal Panel 8pp 20935 066 24X Fiche 50-275,83/10/25,83/1080097
- 8310310181 Requests DC Treppa encl 831021 ltr be placed in PDR & copioserved on parties to proceeding SHOEMAXEM.C J. Atomic Safety and Licensing Appeal Panel 83/10/2/Docketing & Services Branch 1p 20958 361 24X Fiche 50-275.83/10/27.8310310181
- --8310310184 Expresses concern re reissuing low power test license for facility License should be revoked & facility ordered to shut down
 TREFPA:D C Affiliation Unknown 83/10/21 ROSENIHAL A S NKC No Detailed Affiliation Queen Ip 20958 362 24X
 Fiche 50-275,83/10/27,8310310181
- H General correspondence
- B310180270 Clarifies position of interjurisdictional planning committee for agencies surrounding facility emphasizing importance of FEMA coordination of federal agency responses to nuclear plant accidents COLEMAN, R J San Clemento, CA 83/10/10 NRC No Detailed Affiliation Given 2pp 20807 050 24X Fiche 50-275,83/10/10.8310180270
- 8310200175 Responds to 820717 & 830820 Itrs re safety & redundancy of valve failure modes IE Insp Repts 50-275/82-24, 50-323/82-13 & 50-275/82-42 encl Further investigation revealed tracking & documentation of repts out of date BISHOP.T W Division of Resident Reactor Project & Engineering Programs 93/10/17 COOPER. J H Affiliation Unknown 2pp 20835 316 24X Fiche 50-275,83/10/17.8310200175
- d Inspection reports: IE Bulletins & carrespondence
- 83(0250416 Forwards std order for DDE work, "Specialized Insp Support - Technical Assistance for Diablo Canyon - Design Verification Program " ADAMS.C Energy, Dept of FIN 8-8552 83/09/16 MARTIN.J B Region 5. Office of Director ip 20897 184 24X Fiche 50-275.83/09/16.83(0250416
- --8310250423 Std order for DDE work "Specialized Insp Support Technical Assistance for Diablo Canyon Design Verification
 Program," issued to LLL
 MARTIN. J B Region 5, Office of Director MACRUSKY, J Fnergy,
 Dept of FIN B-8552 83/09/16 ip 20877 185 24%
 Fiche 50-275,83/09/16,8310250416
- 8310040221 Forwards IE Insp Repts 50-275/83-25 & 80-323/83-18 on 830718-22 & 0818 No noncompliance noted NORDERHAUG, L R Region 5. Office of Director 83/07/20 SCHUYER, J D Pacific Oss & Flectric Co 2pp 2061/ 250 24% Fichs 50-275/83/07/20,8310040221

- -8310040226 IE Insp Repts 50-775/83-25 % 50-323/83-18 on 830/18 2 % OSIB No nancompliance noted Major arros inspected emergency preparedness program.including emergency detection & classification & protective action decisionmaking SCOWN.K. SCHUSTER.M D. Region 5. Office of Director 83/09/19 13pp 20617 252 24% Fichs 50-275.83/09/20.8310040521
- H310170473 Forwards IE Insp Repts 50-275/83-28 & 50-323/83-20 on B30731-0903 No noncompliance noted BISHOPLT W Division of Resident.Reactor Project & Engineering Programs B3/09/22 SCHUYLEN, J D Pacific Cas & Electric Co 2pp R0783 305 24X Fiche 50-275,83/09/22,8310170473
- -0310170479 JE Insp Repts 50-275/03-28 & 50-323/03 20 on 830731 0903 No concempliance noted Major areas inspected plant operations, surveillance testing, maint independent insp & follower of concempliances, open items, allegation & preoperational tests CARLSON, J D. MENDONCA, M N. KIRSCH, D F. Region 5, Office of Director 93/09/21 Spp 20783 307 24X Fiche 50-275,83/09/22, 8310120473 8310170473
- 308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Sve list encl JORDAN,E L Division of Lorgency Preparadness & Engineering Response (Post 830103) 83/09/26 (Ensolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 30E300342 IC Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 114pp 20777 210 24X Fiche 50-000.83/09/26.8308300342
- 30.8300345 1E Info Notice 83-43, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Concolidated Edison Co. of New York, Inc. 118pp 20778 001 24% Fiche 50-000,83/09/26,8308300345
- 30B300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
- erci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300347
- 300300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Mestinghouse Plants " Svr list encl JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07,8308300378
- 308300752 IE Info Nutice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/0/ Consolidated Edison Co of Net York, Inc 79pp 20882 026 24X Fiche 50-000.83/10/07.8308000/52
- 308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Coses "Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308000757
- 308300761 IE Info Notice 83-68, "Respirator User Warning Defective 5 elf-Contained Breathing Apparatus Air Cylinders " Svc list
- encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 127 P4X Fiche 50-000.83/10/11.8308/300761
- 910310332 Forwards IE Insp Repts 50-275/83-29 & 50-323/83-21 on 830829-0902 & 06-09 No noncompliance noted 8 EBHOP: T W Division of Resident/Reactor Project & Engineering 8 Frograms 83/10/13 SCHUYLEN, J O Pacific Gas & Electric Co 2pp 20960 311 24X Fichs 50-275.83/10/13.8310310332
- -B310310341 IE Insp Repts 50-2/5/83-27 & 50-323/83-21 on 830827 0702 & 06-09 No noncompliance noted Major areas inspected const activities including licensee action on previous insp findings. IE info notices & deficiencies under 10CFR50 556 HERNANDEZ. G H , KIRSCH, D F Region 5, Office of Director 63/10/07 ilpp 20760 313 24X Fiche 80-275,83/10/13,8310310338
- -9310310346 "Insp Repts." Jul 1983 * EG&G, Inc FIN B 8552 83/07/31 NRC No Detailed Affiliation Given 12pp 20940 324 24X Fiche 50-275,83/10/13, B310310332

- --B310310354 "Insp Repts." Aug 1983 * EG&G. Inc FIN B-8522 B3/08/31 NRC No Detailed Affiliation Given 21pp 20940 336 24X Fiche 50-275.83/10/13,
- 8310200180 Ack receipt of B3092/ ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-275/83-24 & 30-323/83-17
 BISHOP,T W Division of Resident Reactor Project & Engineering Programs B3/10/14 SCHUYLER, J O Pacific Gas & Electric Co ip 20835 072 24X Fiche 50-275,83/10/14,8310P00180
- --8310200183 Responds to NRC 830826 Itr re violations noted in IC Insp Repts 50-275/83-24 & 50-322/83-17 Corrective actions locking devices on Unit I pipe support 46-9V existed on both spring cans Turnbuckies verified by Pullman Power Products SCHUYLER, J O Pacific Oas & Electric Co 83/09/27 MARTIN, J B Region 5, Office of Director 4pp 20835 073 24X Fiche 50-275,83/10/14.8310200180
- 8310310246 Forwards IE Insp Repts 50-275/B3-30 & 50-323/B3-22 on 830904-1001 No noncompliance noted BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 83/10/14 SCHUYLEH.J O Pacific Gas & Electric Co 20947 182 24X Fiche 50-275,83/10/14.8310310246
- --8310310251 IE Insp Repts 50-275/83-30 & 50-323/83-22 on 83D904-1001 No noncompliance noted Major areas inspected surveillance testing, maint, independent insp. followup of open items & allegations, preoperational testing/results & plant tours MENDONCA: M M . KIRSCH.D F Region 5. Office of Director 83/10/13 10pp 20947 184 24X Fiche 50-275,83/10/14,8310310244
- B3102B003A Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-275/83-13 & 50-323/83-10
 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs B3/10/21 SCHUYLER, JO Pacific Gas & Electric Co 1p 20934 325 24% Fiche 50-275, 83/10/21. 8310280036
- --8310280048 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-275/83-13 % 50-323/83-10 Corrective actions sys for maintaining welder qualification files revised Only qualified welders on active list allowed to draw rods SCHUYLER. J D Pacific Oas & Electric Co 83/09/16 MARTIN. J B Region 5, Office of Director 5pp 20934 326 24X Fiche 50-275,83/10/21.8310280034
- 8310310274 Forwards Allegation RV-B3-A-0047 re RHR sys Allegations previously addressed in IE Insp Rept 50-275/82-42 in response to 820820 ltr Task interface apreement suggested BISHOP.T W Division of Resident Reactor Project & Engineering Programs 83/10/26 EISENNUT.D 0 Division of Licensing 2pp 20761 303 24% Fiche 50-275,83/10/26.8310310274
- B3103102Bi Ack receipt of NRC response to 820820 allegations re facility RHR sys Allegations paraphrased by inspectur in IE Insp Rept 50-275/82-42 misinterpreted COOPER.J H Affiliation Unknown 83/10/20 B19HOP.T W Division of Resident, Reactor Project & Engineering Programs 8pp 20961 305 24X Fiche 50-275,83/10/26,8310310274
- R Periodic operating reports & related correspondence
- 8308300781 Board Notification 83-156 forwards RL Cloud Assoc & Teledyne Engineering Svcs repts re IDVP EISENHUI, D C Division of Licensing 83/10/14 PALLADIND, N . GILINSKY, V . ROBERTS. T Commissioners 4pp 20875 122 24X Fiche 50-275.83/10/14.8308300781
- 8310210284 Forwards Rev 14 to "Design Verification Program Phase I Final Rept "
 SCHUYLER. J D Pacific Gas & Liectric Co 83/10/14 FIBENHUT, D Q
 Division of Licensing 2pp 20850 232 24% Fiche 50-279, 83/10/14,
- --8310210288 Rev 14 to "Design Verification Program Phase 1 Final Rept "
 * Pacific Gas & Electric Co 83/10/14 171pp 20850 234 24X
 Fiche 50-275,83/10/14,8310210284
- S Reportable occurrences, LLRs & related correspondence
- 8310120066 PND-V-B3-044 on 831003, employee suffered heart attack during work Personnel taken to hosp No news release planned MORRILL.P J. Region 5. Office of Director B3/10/04 ip 20696 157 24X Fiche 50-275,83/10/04.B310120066

- T Hearing transcripts on non-antitrest matters
- 8310090442 Transcript of Commission B30927 briefing in Washington, DC 16 facility schedule Pp 1-34 Viewgraphs & supporting documentation enc.l * Commissioners 83/09/27 52pp 20640 218 24X Fiche 50-275.83/09/27.8310050442
- 8310180354 Forwards 1DVP testimony
 AXELRAD.H Lowenstein. Newman. Reis. Azelrad & Toll 83/10/14
 MDORET F S. BUCK.J H. JUNNSON.W R Atomic Safety and Licensing
 Appeal Panel 2pp 20804 104 24X Fiche 50-275.83/10/14.
 8310180354
- --B310180361 Testimony of HE Cooper.RL Cloud, JE Krechting & RF Rendy no behalf of IDVP re Contentions 1.2 & 5-B Describes role of IDVP in verification of design work of plant & how IDVP performed work COOPER.W E. CLDUD.R L. KRECHTING.J E Lowenstein, Newman, Reis. Arelrad & Toll B3/10/14 57pp 2004 104 24X Fiche 50-275.83/10/14.8310180354
- --8310180369 Testimony of RL Cloud, JM Biggs, MJ Holley & R Wray on behalf of IDVP re Contentions 3 & 4 m n Discusses allegations of internal tachnical program use of improper engineering stds to determine if license criteria met CLOUD, R L . BIOOSS J M . HOLLEY J Lowenstein, Newman, Reis, Arelrad & Toll B3/10/14 33pp 20004 165 24X Fiche 50-275,83/10/14.8310180354
- ---B3101B0375 Testimony of JE Krechting & WE Cooper on behalf of IDW re Contention 4 a -1 & o -u Discusses allegations that IDW accepted deviations from licensing criteria w/o adequate engineering justifications Certificate of Svc encl KRECHTING.JE, CDOPER.W E Lowenstein, Newman, Neis, Axelred & Toll B3710/14 71pp 20804 198 24X Fiche 50-275,83/10/14, B3101B0334
- 8310210350 Forwards NRC testimony.
 MCGURREN.H J Hearing Branch | 83/10/14 MOORE,T S , BUCK,J H ,
 JOHNSON.W R Atomic Safety and Licensing Appeal Panel 5pp
 20849 140 24% Fiche 50-275.83/10/14.8310/210350
- --8310210355 Testimony of IP Knight.HE, Schierling & JS Hermiel on Governor Deukmejlan & Joint Intervenors Contentions la-e KNICHT.JP Assistant Director for Comp & Structures Engineering (Post 830201) SCHIERLING,H E. Division of Licensing HERMIEL.JS Auxiliary Systems Branch 83/10/14 32pp 20847 145 24X Fiche 50-275,83/10/14,8310210350
- --B310210357 Testimony of JP Knight.HE Schierling & JS WermieJ on Governor Deukmejian & Joint Intervenors Contentions 2a.2b & 2c KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) SCHIERLING,H E Division of Licensing HERMIEL.J S Auxiliary Systems Branch B3/10/14 9pp 20849 177 24X Fiche 50-275,83/10/14.0310210350
- --831021035B Testimony of JP Knight, P Kub, HE Polk, CA Miller, AJ
 Philippacopoulos, CJ Constanting & PC Wang re Governor
 Beulme jian & Joint Intervenors Contention 3
 KNIGHTJ P Assistant Director for Comp & Structures Engineering
 (Post 830201) KUO, P, POLK, H E Structural & Geotechnical
 Engineering Branch 83/10/14 25pp 20849.186 24X
 Fiche 50-275,83/10/14,8310210350
- --8310210371 Testimony of JS Wermiel on Governor Deukmejian & Joint Intervenors Contentions 4a.4h.4p.4q.4r & 4s MERMIELLJ S Auxiliary Bystems Branch 83/10/14 10pp 20849 211 24X Fiche 50-278,63/10/14,8310210350
- --B310210382 Testimpny of JL Knox re Governor Deukmejian & Joint Intervenors Contentions 4b.4c.4g.4o.4t & 4u KNOX.J & Division of Systems Integration (post 811005) 83/10/14 8pp 20849 221 24X Fiche 50-275.83/10/14.8310210350
- --8310210392 Testimony of TG Dunning re Governor Daukmejian & Joint Intervenors Contention 4.Parts dee & f DUNNING.T & Instrumentation & Control Systems Branch 10pp 20849 229 24X Fiche 50-275.83/10/14.8310210350
- --B310210398 Testimong of DJ Kubicki on Governor Deukmejian & Joint Intervenors Contentions 41,4, & 4k. KWBICKI.D J Chemical Engineering Branch B3/10/14, 14pp 20849 239 24X Fiche 50-275,83/10/14,8310210350
- --8310210391 Testimony of P Kuu & HE Polk on Governor Deukmegian & Joint Intervenors Contention 4n KUO.P., POLK.H E Structural & Geotechnical Engineering Branch 83/10/14 3pp 20849 253 24X Fiche 50-275,83/10/14.8310210350

- ~-8310210378 lestimony of PJ Morrill on Governor Deukmejian & Joint Intervenors Contentions 5 & 8 MORRILL. P. J. Division of Resident, Reactor Project & Engineering Programs 83/10/14 Spp. 20849 256 24X Fiche 50-275,83/10/14,8310210350
- --8310210381 Testimony of WP Hauss on Governor Deukmejian & Joint Intervenors Contentions 6 & 8 HAASS, W P G A Branch 83/10/14 4pp 20849 262 24X Fiche 50-275,83/10/14,8310210350
- --B310210385 Testimony of JP Knight & HE Schierling on Governor
 Daukmejian & Joint Intervenors Contention 7
 KNIGHT. J P Assistant Director for Comp & Structures Engineering
 (Post 830201) SCHIERLING.H E Division of Licensing 8J/10/14
 6pp 20849 266 24X Fiche 50-275.8J/10/14.8310210350
- --B310210387 Testimony of JS Weimiel on Governor Deukmejian & Joint Intervenors addl contentions on desion GA Contention 9 WERNICL.J S Auxiliary Systems Branch B3/10/14 168pp 20849 272 24X Fiche 50-275,83/10/14,8310210310
- 8310210228 Forwards PJ Kempthorne & FI Semaniego testimony REYNOLDS.J R Center for Law in the Public Interest REYNOLDS.J R Joint Intervenors-Diable Canyon 83/10/15 MODRC.T S. JOHNSON.W R. BULK.J H. Atomic Sefety and Licensing Appeal Panel 1p 20852 042 24X Fiche 50-275, 83/10/15, 8310210228
- --8310210241 Testimony of PJ Kempthorne & FJ Samaniego re Contention: J on IDVP conclusions in light of sampling methodology Pref qualifications oncl KEMPTHORNE.P J . SAMANIEGO, F J. Joint Intervenors-Diablo Cangon 83/10/15
- 8310200178 Tostimony of RB Hubbard re design GA Verification program has not yet demonstrated plant design complies d/all applicable NRC regulatory requirements & all util licensing criteria Related correspondence HUBBARD, R B California, State of HUBBARD, R B MHB Technical Associates B3/10/16 79pp 20835 1P9 24X Ficho 50-275,83/10/16,8310200178
- ~~8310200184 Testimony of G Apostolakis re design QA IBVP weak since program fails to recognize implications of decision to cart IBVP in probabilistic terms & fails to use appropriate probabilistic analysis principles & methods APOSTOLAKIS. G California, State of APOSTOLAKIS. G California, Univ of, Los Angoles, CA 89/10/16 21pp 20835 208 24X Fiche 50-273,83/10/16,8310200178
- --8310200190 Testimony of JM Rocsset re adequacy of util seismic modeling of structures & soils & of review of util work by IDVP Four issues remain requiring further verification Affidavits of qualifications encl ROESSET, J M California, State of 83/10/14 61pp 20835 229 24X Fiche 50-275,83/10/14,8310200178
- 8310250326 Forwards corrected Pages 5,6 & 8 to NRC 831014 testimony of JP Knight, NC Schiorling & J8 Wermiel on Opvernor Deukmajian & Joint Intervenors Contentions Pa-e Errors due to difficulties w/word processing McGurren, H J Hearing Branch | 83/10/19 MCURE, T G , BUCK, J N , J0HNSDN, W R Atomic Safety and Licensing Appeal Panel 2pp 20877 340 24% Fichs 50-275,83/10/19,8310250326
- --8310250332 Corrected Pages 5.6 & 8 to JF Knight.HE Schierling & J8 Wermail testimony on Governor Deukmejian & Joint Intervenore Contentions 22-e KNIGHT.JP. SCHIERLING.HE. WERMICL.JS NRC No Detailed Affiliation Given 83/10/19 3pp 20897 342 24X Fiche 50-275.83/10/19.8310250326
- 8310250174 Forwards H Schierling, W Haars & D Kubicki depositions & corrections to deposition transcripts W/o depositions MCGURREN.H J Hearing Branch I 83/10/20 Tayloe Associates ip 20892 354 24X Fiche 50-275,83/10/20,8310250176
- --83102501B2 Corrections to WP Haass 830921.DJ Kubicki 630920 & HE Schierling 830921 depositions HAASS.W P , KUBICKI.D J , SCHIERLING.H E NRC - No Detailed Affiliation Given 83/09/21 4pp 20892 355 24X Fiche 50-275,83/10/20,8310250176
- 8310280057 Transcript of witness testimony.prof qualifications & bxhibits for reopened hearing re design GA Certificate of Svc encl Related correspondence * Pacific Gas & Electric Co 83/10/27 554pp 20935,328 P4X Fiche 50-275,83/10/27.8310280057

- U Congressional/Liecutive Correspondence
- 0310110114 Ack receipt of comments on plant licensing Commission deferred final consideration of matter until after NRC completes analysis of final IDVP rept CHILKS J Office of the Secretary of the Commission 03/10/05 HART.6 K , CHACON.P , DAVIS.G California, State of Jpp 20669 131 24X Fiche 50-275,83/10/05.8310110114
- 8310200442 Responds to 830727 ltr re NRL handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers encl PALLADIND.N J Commissioners 83/10/07 FORD.W H Senate 3pp 20871 295 24% Fiche 50-000, 0J/10/07.8310200442
- ---8310200469 Expresses disappointment re release of draft study on GA programs at Diable Canyon to licensec Full explanation requested MARKEY, E. J. House of Rep., Interior & Insular Affairs 83/07/21 PALLADINO, N. J. Commissioners 2pp. 20872 217 24X Fiche 50-000.83/19/07.8310200442
- 8310240169 Advises that State of CA legislator ltrs requesting delays in licensing do not represent policy of CA legislature License issuance recommended ALGUISTA C California, State of 87/10/17 PALLADING, N J Commissioners ip 20880 029 24X Fiche 50-275,83/10/17,8310240149
- B310250045 Urges NRC to proceed w/o delay w/regulatory steps necessary to allow fuel loading, low power testing & commercial operation
 BILLS.R.C. California, State of B3/10/19 PALLADINO, N J
 Commissioners 2pp 20894 089 24X Fiche 50-275,83/10/19,
 B310250045
- V Operator Examinations
- 8310030285 Informs of periodic audits of licensed operator requalification programs Schedule for requalification training & exams requested by 831028
 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 83/09/24 SCHUYLER, J O Pacific Qas & Electric Co 2pp 20591 039 24X Fiche 50-275,83/09/24,8310030285
- DOCKET 50-324 BRUNSWICK STEAM ELFCTRIC PLANT, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 0310250120 Forwards add1 info re pending requests for exemption from iOCFR50, App R & IOCFR50 4B Info clarifies request for nine exemptions, schedule for alternate shutdown study & completed mods
 HDME, P W Carolina Power & Light Co 03/05/02 VASSALLO, D R
 Operating Reactors Dranch 2 21pp 2009/248 24X
 Fiche 50~324,83/05/02,8310250120
- 8310110157 Ack receipt of 830420 ltr transmitting Rev 8 to physical security plan Portions inconsintent w/10CFR50 54(p) Encl comments should be accommodated to modify plan Comments withheld (ref 10CFR73 21)
 LEWIS.R C Division of Project & Resident Programs 83/07/12
 UTLEY.E E Carolina Power & Light Co 3pp 20666 279 24X
 fiche 50-324,83/07/12.8310110157
- 8310070273 Forwards IE Safeguards Insp Ropts 50~324/83-24 & 50~325/83-24 on 830707 & notice of violation of REILLY, J P Region 2. Office of Director 83/09/01 UTLEY, I F Carolina Power & Light Co 2pp 2045A 349 24X Fiche 50~324,83/09/01.83100702/3
- ~-8310070282 Notice of violation from insp on 830707 * Region 2, Office of Director 83/09/01 ip 20656,351 24% Fiche 50-324,83/09/01,83100/0273
- --8310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 Noncompliance noted authorized amplayee entered protected area w/o badge & w/o being physically searched Details withheld (ref 10CFR/3 21)
 HALL, B L Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Enfety 83/09/01 ip 20456 352 24X Fiche 50-324,83/09/01,8310070273
- 8310040347 Requests update of encl info re layout of technical support ctrs & emergency operations facilities
 VERRELLI.D M Division of Project & Resident Programs 89/09/1P
 UTLEY, E E Carolina Power & Light Co 17pp 20625 183 24X
 Fiche 50-000,83/09/12,8310040347

- 8310250565 Forwards IE Insp Repts 50-324/83-29 & 50-325/83-29 pn 830815-19 No noncompliance noted O'REILLY, J.P. Region 2, Office of Director 83/09/21 UTLEY, E. Carolina Power & Light Co. 2pp 20902 059 Fiche 50-324, 83/09/21, 8310250565
- --8310250578 IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-19 No noncompliance noted Major areas inspected emergency preparedness CLINC.W E Region 2. Office of Director JENKINB,0 R Division of Emergency Preparedness & Naterials Safety 83/09/13 9pp 20902 061 24X Fiche 50-324,83/09/21,8310250565
- 8310040298 Ack receipt of 830830 ltl informing NRC of steps taken to correct violations noted in IC Insp Repts 50-324/83-26 & 90-325/83-26 VERRELLI.D M Division of Project & Resident Programs 83/09/22 UTLEY, E C Carolina Power & Light Co ip 20621 001 24X Fiche 50-324,83/09/22.8310040298
- ~~9310040306 Responds to NRC B30801 ltr re violations noted in IC Insp. Repts 50-324/83-26 & 50-325/83-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed DIETZ. C.R. Carolina Power & Light Co. B3/08/30. O'REILLY, J.P. Region 2. Office of Director 2pp E0621 002 24X Fiche 50-324,83/09/22,8310040298
- ---8310040321 Forwards IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 & notice of violation
 VERRELLI,D M Division of Project & Resident Programs 83/08/01
 UTLEY,C E Carolina Power & Light Co 2pp 20621 004 24X
 Fiche 50-324,83/09/22.8310040298
- --8310040326 Natice of violation from insp on 830615-0715

 * Division of Project & Resident Programs 83/08/01 1p
 20621 006 24X Fiche 50-324.83/09/22.8310040298
- --B310040332 IE Insp Repts 50-324/B3-26 & 50-325/B3-26 on B30615 0715 Noncompliance noted Fire Protection Procedure OP-41 Inadequately established MYERB.D O , GARNER,L W , ORDERS,W T Region 2, Office of Director B3/07/27 10pp 20621 007 24% Fiche 50-324, B3/09/22, B310040290
- B310050451 Notification of 831006 meeting w/util in Bethesda,MD to discuss progress rept on fire protection, alternative shutdown sys, associated circuits, cable routing, addl analyses, field verification & sprinkler sys MACKAY,S D Operating Reactors Branch 2 83/09/29 VASSALLO,D B Operating Reactors Branch 2 2pp 20650 037 24X Fiche 50-324,83/09/29,8310030451
- 8310060535 Releases public version of revised emergency plan & emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20663 001 R4X Fiche 50-324.83/09/30, 8310060555 -
- ---8310060561 Forwards public version of Rev 9 to emergency response plan & revised emergency plan implementing procedures, including Procedures PEP-03 4 i re initial dose projections & PEP-App A ra emergency response resources ZIMMERMAN.S R Carolina Power & Light Co 83/07/15 O'REILLY, J P Region 2. Dffice of Director 2pp 20463 002 24X Fiche 50-324,83/09/30,8310060555
- --B310060564 Public version of Rev 9 to emergency response plan BDVER.L E Carolina Power & Light Ca B3/06/16 29pp 20463 004 24X Fiche 50-324.83/09/30.8310060555
- --B310060567 Public version of revised emergency plan implementing procedures, including Procedures PEP-03 4 1 re initial dose projections & PEP-App A re emergency response resources BOYER, L Carolina Power & Light Co B3/06/22 3Bpp 20663 033 24X Fiche 50-324.83/09/30,0310060555
- 8310070291 Forwards "Position Paper on Reg Guide 1 97" & "Response to NUREG-0737, Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities "
 ZIMMERMAN, S R Carolina Power & Light Co 83/09/30 VA8SALLO, D B Operating Reactors Branch 2 in 20655 177 24X
 Fiche 50-324, 83/09/30, 8310070291
- --8310070293 "Position Paper on Reg Quide 1 97 "
 BROWN.W E , WASENKO.M Carolina Power & Light Co 83/08/09
 33pp 20655 178 24X Fiche 50-324.83/09/30,8310070291
- --8310070295 "Response to NUREO-0737. Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities " BROWN. W E . MASENKOM M Carolina Power & Light Co 83/08/09 77pp 20655 211 24X Fiche 50-324.83/09/30.8310070291

- 6310070211 Ack receipt of 63092/ ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-24 & 30-325/83-21

 0'REICLY, J.P. Region 2, Orfice of Director B3/10/05 UTLEY, E Carolina Power & Light Co. ip. 20659-124

 Esche 30-924-83/10/05-8310070-41
- --B31G070245 Responds to NRC B30901 ltr re violations noted in IF lnsp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73 21 & 10CFR2 790) UTLET,E E Carolina Power & Light Co B3/09/27 O'REILLY, J P Region 2, Office of Director 2pp 20659 125 24X Fiche 50-324 B3/10/05 83:0070241
- 6310180427 Provides supplemental response to Generic Ltr 82-33 re energency response capability Addi interim milestones & clarification of 830415 response re safety parameter display sys & emergency operating procedures provided UTLEV.E E Carolina Power & Light Co 83/10/14 VASSALLO, D B Operating Reactors Branch 2 3pp 20803 300 24x Fiche 50-324,83/10/14.8310180427
- 8310210064 Forwards IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 890927-29 VERRELLI.D Division of Project & Resident Programs 83/10/1/UTLEY.E Carolina Power & Light Co 2pp 20857 266 24x Fiche 50-324.83/10/17.8310210064
- --8310210070 IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 No noncompliance noted Hajor areas inspected review of licensee action to correct prior violations & testing Details withheld (ref 10CFR73 21)
 TOBIN,W J. MCGUIRE,D R Region 2, Office of Director 83/10/14 ip 2085/ 268 24% Fiche 50-324,83/10/17,8310210064
- B3102400B0 Summary of B30907 meeting w/util in Bethesda.HD re outstanding items & util progress on alternate shutdown capability assessment & mods required by IOCRESO,App R MACKAY.S Operating Reactors Branch 2 83/10/17 Operating Reactors Branch 2 4pp 20903 205 24X Fiche 50-324.83/10/17. B3102400B0
- 6310280129 Notification of B31103 meeting u/util in Bethesda.MD to discuss alternate shutdown sys.associated circuits.addl analyses.field verification.dap R deviations & options & high-low pressure interfaces MACKAY.S D Operating Reactors Branch 2 B3/10/25 VASSALLO.D 1 Operating Reactors Branch 2 2pp 20964 026 24X Fiche 30-324.83/10/25.8310280129
- P Operating license stage documents & correspondence
- 8310030161 Advises that organizational changes for QA program & changes to FSARs & mgt capability rept will be forwarded when completed

 UTLEY.E E Carolina Power & Light Co B3/09/13 DENTON.H R

 Office of Nuclear Reactor Regulation. Director 1p 20590 028 24X

 Fichs 30-000.83/09/13.8310030161
- 8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
 O'REILLY, JP Region 2. Office of Director 83/09/22 UTLEY, F E
 Carolina Power & Light Co 2pp 20620 331 24X
 Fiche 50-000.83/09/22.8310040354
- 8310060031 Forwards Amend 81 to License DPR-62 & safety evaluation Amend revises Tech Specs or instrumentation used to monitor water level in suppression chamber of primary containment says (NUREC-0737, Item II F I 5)
 MACYAY. S D Operating Reactors Branch 2 83/09/22 UTLEY, L E Carolina Power & Light Co 2pp 20664 101 24x
 Fiche 50-324.83/09/22.8310060031
- --8310060043 Amend B1 to License DPR-62, changing Tech Specs re instrumentation used to maintain water level in suppression chamber of primary containment sys MACKAY, S D Derating Reactors Branch 2 83/09/22 5pp 20664 103 24X Fiche 50-324,83/09/22,8310060031
- --B310060049 Safety evaluation supporting Amend 81 to License DPR-62 PRC No Detailed Affiliation Olven B3/09/22 Ppp 20644 108 24X Fiche 50-324, 83/09/22, 8310060031
- 8310040380 Application for amend to License DPR-62, revising Faragraph 2 H of license re required operability date of augmented offgas sys mods HOME.P W Carolina Fower & Light Co 83/09/29 VASSALLO.D D Operating Reactors Branch 2 4pp 20620 284 24X

- 8310040385 Application for amend to Licenses DPR-62 & DPR-71, changing Tech Spec re feedwater & main turbine trip/bypaes sys HOME,P W Carolina Power & Light Co 83/09/29 VASSALLO, D B Operating Reactors Dranch 2 3pp 20617 209 24X Fiche 50-324.83/09/29.8310040585
- --B3100403B8 Proposed Tech Spec changes re feedwater/main turbing tilg sys actuation instrumentation & main turbine trip sys • Carolina Power & Light Co. 63/09/29 28pp .061/21; .4X Fiche 50-324,83/09/29,8310040385
- 8310060054 Application for amend to Licenses DPR-71 & DPR-62, politing 18-month interval surveillance requirements & primary containment leakage requirements
 HOWE,P W Caroline Power & Light Co B3/10/03 VASSALLO, D R
 Describer Reactors Branch 2 Spp 20647 043 P4X
 Fiche 50-324,83/10/03,8310060054
- --8310060066 Proposed Tech Spec changes for primary containment leaking testing * Carolina Power & Light Co 83/10/03 10pp 20647 046 2/4X Fiche 50-324,83/10/03,8310060054
- 8310240138 Forwards notice of consideration of issuance of amind to License DPR-62 & opportunity for prior hearing on 12:07:03 application re Tech Specs to permit operation up to 50% of rated thermal power whome recirculation pump out of two MACKAY.S D. Operating Reactors Branch 2 83/10/05, UTLEY.L & Carolina Power & Light Co. 2pp. 20884 351 24% Fiche 50-324,03/10/05,8310240138
- --8310240144 Notice of consideration of issuance of amend to licroll DPR-62 & apportunity for prior hearing rev to Tech Speca to permit reactor operation at power levels up to 50% of rated thermal power whome recirculation pump out of svc VASSALLO, D B Operating Reactors Branch 2 83/10/05 5pp 20884 353 24% Fiche 50-324, 83/10/05, 8310240138
- 8310310137 Forwards safety evaluation to review of util submittal addressing NUREG-0737 Item II K 3 17. "Rept on Dutages of ECCS " Requirements met VASSALLO, D B Operating Reactors Branch P B3/10/14 UTIEY, I I Carolina Power & Light Co 4pp 20765 250 24x Fiche 50-324, 83/10/14, 8310310137
- --8306160513 "ECCS Repts (F-47) TMJ Action Plan Requirements. Brunswick Steam Electric Plant, Units 1 & 2," technical evaluation rept VDSBURY, F W. OVERBECK, 0 J Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05506-174/175 83/06/13 CHUH. F NRC No Detailed Affiliation Given Rapp 20965 254 224X Fiche 50-324, 83/10/14, 8310310137
- 8310200058 Ciarifies licensee intentions of installation of effluent monitoring instrumentation referenced in 821213 proposed radiological affluent Tech Specs Summary of installation schedules encl ZiMMERMAN.S R Carolina Power & Light Co 83/10/17 VASSALL/I.D & Operating Reactors Branch 2 4pp 20896 005 24X Fiche 50-324,83/10/17,8310200058
- 8310200206 Requests extension until 831130 to provide response to 830901 request for addl info re electric distribution sys voltages. HOME.P W Carolina Power & Light Co 83/10/17 VASSALLO,1 B Operating Reactors Branch 2 ip 20834 127 24x Fiche 50-324,83/10/17,8310200206
- 8310210264 Application for amend to Licenses DFR-71 & DFR-62, evising radiological effluent Tech Specs Justification for proposed changes & summary of revs encl HOME.P & Carolina Power & Light Co 83/10/17 VABBALLO.D B Operating Reactors Branch 2 15pp 20848 282 24X Fiche 50-324,83/10/17.8310210264
- --8310210268 Proposed changes to radiological effluent fech Specs * Carolina Power & Light Co 83/10/17 200pp. 20848 897 PAX Fiche 50-324.83/10/17.8310210264
- 83i0250036 Requests approval to perform short duration integrated look rate test (Type A) Test would meet criteria of Bechtn)
 Topical Rept NB-TOP-1, Tech Specs, 10CFR80, App J & ANSI Btd
 N53 4-1972 Approval requested by 840101
 HOME,P W Carolina Power & Light Co 83/10/20 VASSALLU, I) B
 Operating Reactors Branch 2 2pp 20895 272 24X
 Fiche 50-324,83/10/20,8310250036

- B310260141 Forwards program outlines, "Demonstration of Raychem Cable for Qualified Use in Class IL Svc " & "Measure of Voltage Withstand Level on Raychem Cable Samples After Exposure to Simulated LOCA" Programs expected to begin by Jan 1984 HDME.P W Carolina Power & Light Co 83/10/20 VAS9ALLO,D R Operating Reactors Branch 2 2pp 20915 197 24X Fiche 50-324.83/10/20.8310260141
- --8310260145 Rev 2 to "Demonstration of Raychem Cable for Guillified Usc in Class IE Svc Primary & Secondary Containment for Brunswick Steam Clactric Plant Units ! & 2 " PARKS, B. WAI DORF, J. Carplina Power & Light Co 83/08/24 2/pp 20915 199 24X Ficha 50-324.83/10/20,8310260141
- --8310240148 Rev O to "Measure of Voltage Withstand Level on Kaychem Cable Samples After Exposure to Simulated LDCA " PARKS, B., WALDURF, J. M. Carolina Power & Light Co. 83/08/24 Spp 20715-226 24% Fiche 50-324,83/10/20,8310260141
- 3 Inspection reports, IE Bulletins & correspondence
- 3310040182 Forwards IE Insp Repts 50-324/83-28 & 50-325/83-28 on 830801-05 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/08/30 UTLEY, E E Carolina Power & Light Co 2pp 20617 241 24X Fiche 50-324.83/08/30.8310040182
- --8310040203 IE Insp Repts 50-324/83-28 & 50-325/83-28 on 830801-05 No noncompliance noted Major areas inspected licensee action on previous enforcement matters; GA program annual review & audit program implementation
 DEBBAGE, A G Region 2. Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 83/08/25 7pp 20517 24% 24X Fiche 50-324,83/08/30,8310040182
- 3310070273 Forwards 1E Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 030707 & notice of violation D'REILLY, J P Region 2, Office of Director B3/09/01 UTLEY, F E Carolina Power & Light Co 2pp 20056 349 24X Fiche 50-324,83/09/01.83100702/3
- -8310070282 Notice of violation from insp on 830707

 * Region 2, Diffice of Director 83/09/01 ip 20454 351 24X
 Fichs 50-324,83/09/01,83100702/3
- -8310070294 IE Bafequards Insp Repts 50-324/83-24 & 50-328/83-24 on 830707 Noncompliance noted authorized employee entered protected area w/o badge & w/o being physically searched Details withhold (ref 10CFR/3 21) HALL, B L Region 2. Office of Director MCOUIRE, D & Division of Emergency Preparedness & Makertals Safety 83/08/01 ip 20656 352 24X Fiche 50-324.63/09/01.8310070273
- |310250565 Forwards | E | Insp. Repts | 90-324/83-29 & 50-325/83-29 on | 830815-19 No noncompliance nated | 0'REILLY, J. P. Region 2, Office of Director | 83/09/21 | UTLEY, F. F. Carolina Power & Light Co. 2pp. 20902-059 | 24X | Fiche | 50-324, 83/09/21, 8310250565
- -83102505/8 IE lnsp Repts 50-324/83-29 & 50-325/83-29 on 830815-19 Nu noncompliance noted Major areas inspected emergency preparedness CLINC.WE Region 2, Office of Director JENKINS, QR Division of Emergency Preparedness & Materials Eafety 83/09/13 9pp 20902 061 24X Fiche 50-324.63/09/21,8310250565
- 310040298 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-325/83-26 VERRELLI.D M Division of Project & Resident Programs 83/09/42 UTLEY.E E Carolina Power & Light Ca ip 20621 001 24X Fiche 50-324.83/09/42.8310040298
- -B310040306 Responds to NRC B30801 ltr re violations noted in IE Insp Repts 50-324/B3-26 & 50-325/B3-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed DIETZ.C.R. Carolina Power & Light Co. B3/08/30 O'REILLY, J.P. Region 2, Office of Director 2pp 20621 002 24X Fiche 50-324, B3/09/22, B310040298
- -8310040321 Forwards IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/08/01 UTLEY,B.E Carolina Power & Light Co 2pp 20621 004 24X Fiche 50-324,83/09/22,8310040298
- *B310040326 Notice of violation from insp on 830615-0715
 * Division of Project & Resident Programs B3/08/01 ip 20621:006 24% Fiche 50-324.83/09/22.8310040290

- --8310040332 IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 Noncompliance noted Fire Protection Procedure OP-41 Inadequately established MYERS.D O GARNER.L W ORDERS.W T Region 2, Office of Director 83/07/29 10pp 20621 007 24X Fiche 50-324,83/09/22, 8310040290
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830:03) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000.83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Cas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co. of New York, Inc. 114pp 20777 210 24X Fiche 50-000,83/09/26,8388300342
- 8308300345 IE Info Notice 83-63. "Potential Failures of Hestinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fishe 50-000,83/09/29,8308300349
- B310070241 Ack receipt of 830927 ltr informing NRC of steps taken to correct violations noted in It Insp Repts 50-324/B3-24 & 50-325/B3-24 O'REILLY, J.P. Region 2, Office of Director B3/10/05 UTLEY, F.E. Carolina Power & Light Co. 1p. 20659 124 24X Fiche 50-324.83/10/05.8310070241
- --8310070244 Responds to NRC 830901 ltr re violations noted in IE Insp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 100FR73 21 & 100FR2 790) UTLEY,E E Carolina Power & Light Co 83/09/27 O'REILLY,J P Region 2, Office of Director 2pp 20459 125 24X Fiche 50-324,83/10/05,8310070241
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/07 Constitated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IC Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 024 24X Fiche 50-000.83/10/07.8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 82/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IC Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enci JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310250474 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23 O'REILLY, J P Region 2, Office of Director 83/10/11 UILEY, E E Carolina Power & Light Co ip 20900 061 24X Fiche 50-324,83/10/11,8310250474
- --8310250480 Responds to NRC 830825 ltr re violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23 Corrective actions procedure will be implemented by 831130 to ensure revs to certificates of compliance will be identified HQME.P W Carolina Power & Light Co 83/09/83 O'REILLY, J P. Region 2, Office of Director 3pp 20900 062 ; Fiche 50-324.83/10/11,83102504/4

- --B31025048B Forwards IE Insp Repts 50-324/83-23 & 50-325/83-23 on B30626-30 & notice of violation Requests response to circumstances surrounding radioactive matl shipment to another licensee.ger 830727 enforcement conference at site O'REILLY, J P Region 2. Office of Director 83/08/25 UTIFY, E Carolina Power & Light Co 2pp 20900 055 24x Fiche 50-324,83/10/11,8310250474
- --8310250493 Notice of violation from insp on 830626-30 * Region 2. Office of Director 83/08/25 ip 20700 067 24X Fiche 50-324.83/10/11.8310250474
- --B310250501 IE Insp Repts 50-324/83-23 & 50-325/83-23 on B30626-20 Moncompliance noted large quantity shipment in CMS-3-55 shipping cask not leak tested prior to delivery of package to carrier for transport ALBRIGHT,R N. BARRIK P. Region 2. Office of Director B3/08/05 7pp 20900 068 24X Fichs 50-324.83/10/11.8310250474
- 8310200166 forwards Rev 13 to Engineering Procedure ENP-16. "Procedure for Administrative Control of Inservice Insp Activities"
 List providing status of existing relief/elemption requests enc1
 HOME.P W Caroline Power & Light Co 83/10/12 VASSALLU, D &
 - enci. HOWE.P H Carolina Power & Light Co 83/10/12 VASSALLU,U & Operating Reactors Branch 2 2pp 20828 001 24X Fiche 50-324.83/10/12.8310200164
- --831020014B Rev 13 to Engineering Procedure ENP-16, "Procedure for Administrative Control of Inservice Insp Activities " * Caroline Power & Light Co 83/08/26 280pp 20828 003 24X Fiche 50-324,83/10/12,8310200166
- 8310200143 Responds to 830826 confirmatory order re intergranular stress corrosion cracking insps of BMR stainless steel piping List of recirculation & reactor water cleanup sys welds to be inspected in Nov 1983 & Mar 1984 encl
 UTLEY.EE Carolina Power & Light Co 83/10/14 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 11pp 20836 326
 24X Fiche 50-324,83/10/14,8310200143
- 8310210064 Forwards IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 VERRELLI.D Division of Project & Resident Programs 83/10/17 UTLEY.E Carolina Power & Light Co 2pp 20857 266 24X Fiche 50-324,83/10/17.8310210064
- --8310210070 IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 No nancompliance noted Major areas inspected review of licensee action to correct grior violations & testing Details withheld (ref 10CFR73 21) TOBIN.M J. MCGUIRE.D R Region 2. Office of Director 83/10/14 ip 20837 268 24% Fiche 50-324,83/10/17,8310210064
- 831025045i Ack receipt of 830804 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-18 % 50-325/83-18 Violation re worker whole body count remains 0'REILLY.J P. Region 2. Office of Director 83/10/17 UTLEY.E F. Carolina Power & Light Co. 2pp 20897 OB1 24X Fiche 50-324,83/10/17.8310250451
- --8310250487 Ack receipt of 830804 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-324/83-18 & 50-325/83-18 LEMIS, R C Division of Project & Resident Programs 83/08/30 UTLEY, E E Carolina Power & Light Co Jp 20897 083 24X Fichs 50-324, 83/10/17, 8310250451
- --8310250460 Responds to NRC 830705 ltr re violations noted in 1E Imag Repts 50-324/83-18 & 50-325/83-18 Corrective actions special ventilation hood installed from HEPA filtration unit in bag cutting/imag station DIETZ.CR Carolina Power & Light Co 83/08/04 UREILLY, J P Region 2. Office of Director 4pp 20897 084 24X Fiche 50-324.83/10/17,8310250451
- --B310250468 Forwards IE Insp Repts 50-324/83-18 & 50-325/83-18 on 830523-27 & nutice of violation LEMIS,R C Division of Project & Resident Programs 83/07/05 UTLEY,E E Carolina Power & Light Co 2pp 20897 OBB 24X Fiche 50-324,83/10/17,8310250451
- --8310250473 Notice of Violation from insp on 830523-27

 Region 2: Office of Director 83/07/05 ip 20897 090 24X
 Fiche:50-324,83/10/17,8310250451
- --B310250477 IE Insp Repts 50-324/B3-18 & 50-325/B3-18 on B30523-27 Noncompliance noted failure to perform adequate air sampling ALBRIGHT, R H , BARR, K P Region 2, Office of Director B3/07/01 7pp 20897 091 24X Fiche 50-324.B3/10/17.B310250451

- 8310250571 Comments on detection of deficiencies in quality resulting from suppliers froudulent actions described in IC Info Notices 83-07 & 83-01 & IC Bulletins 81-06 & 83-07 Use of addlines & testing during receipt iness investigated MCDUFFIE,M A Carolina Power & Light Co 83/10/21 PEYBUNG,N C Director's Office, Office of Inspection and Enforcement Ip 20900 347 24% Fichs 50-000/83/10/21.8310250571
- R Periodic operating reports & related correspondence
- B310130124 Monthly operating repts for Sept 1983 W/831006 ltr HARRISON,F, DILT/,CR Carolina Power & Light Co &3/10/06 DEYBUNG,R C Director's Office, Office of Inspection and Enforcement 14pp 20726 311 24X liche 50-324, 03/10/06, 0310130124
- S Reportable occurrences. LERs & related correspondence
- 8310210327 Responds to FDIA request for all documents re significantly high rate of equipment failures for GC BWR/4 rated at 2,430, MH Forwards App A documents Dacuments also available in PDR FELTON.J M Division of Rules and Records 83/07/20 PMFNLT, B Suffolk Nuclear Study Group 2pp 20802 223 24X Fiche 50-000,83/07/28,8310210327
- --8303240341 Summarizes evaluation of LERs for 1982 LER submitterly usually acceptable Potential myt weakness indicated by large number of procedural deficiencies lark of followup repts committed to & possible training problems SEYFRIT. K V Reactor Operations Analysis Branch 83/03/15 LEWIS.R C Division of Project & Resident Programs App 20882 269 24% Fiche 50-000.83/07/29,8310210329
- 8310040362 LER 83-078/03L-0 on 830807, during startup, reactor recirculation sys jet pump operability discovered not performed while in Mode 2.in violation of leth Bpcc requirement Cause by misinterpretation H/830906 ltr PASTVA:H J. DIETZ.C R. Carolina Power & Light Co. 83/09/06 0'REILLY, J P. Reqion 2, Office of Director 2pp 20620 23; 24x Fiche 30-324,83/09/06.8310040362
- 8310040593 RD 2-83-83 on 830905, wookly fire protection test determined valve 2-FP-V39 shot & under clearance Clearance valve tap inadvertently placed on wrong valve Valve opened investigation pending DIETZ.C R Carolina Power & Light Co 83/09/06 U'RFILLY.J P Region 2. Office of Director ip 20625 324 24x Fiche 50-324.83/09/06.8310040593
- 8309200175 LER 82-123/03L-2 on 821010, while attempting to sutumatically transfer bus 2D to startup transformer.loss of 4160-volt emergency bus E-3 occurred Diesel generator 3 determined inoperable Caused by breaker failure to close W/83091P ltr PDULK.R N , DIETZ.C R Carolina Power & Light Co 0/09/L2 O'REILLY.J P Region 2, Office of Director 4pp 20431 16H 24% Fiche 50-324,83/09/12,8307200175
- B310030202 LER B3-069/03L-0 on B30825, while attempting to place P3M room coolers 2A & 2B into svc.neither room cooler would start Caused by fan start switch of 2A out of adjustment w/airflow dampers of 2B mechanically binding W/830921 ltr PASTVA.M J. DICTI.C R. Carolina Power & Light Co. B3709/31 07RELLV.J P. Region 2. Office of Director 3pp 20590 340 .74% Fiche 50-324,83707/21,8310030202
- 8310030209 LER B3-059/03L-0 on B30022.distovered automatic degressurization sys initiation logic A switch 2C11-PG-N016A would not respond to applied test signal Caused by corrosions of switch internals & setpoint drift W/BG3921 ltr DIETZ, C.R.; PASTVA, M.J. Carolina Power & Light Co. 83/09/21 O'REILLY, J.P. Region 2, Office of Director 2pp 10590 151 (4x) Fiche 50-324, B3/09/21, B310030209
- 8310030422 LER 83-073/03L-0 on 830824, during surveillance, instructed indication of reactor water cleanup sys differential flow indicator 2-831-R615, GE Model 180, indicated high Caused by entrapped air in transmitter sensing lines W/830921 ltt PASTVA, M J. DIETZ, C R. Carolina Power & Light Co. 83/09/PJ O'REILLY, J P. Region 2, Office of Director 3pp 20593 1611 24x Fiche 50-324,83/09/21,8310030422
- 8310060237 LER 83-082/03L-0 on 830902, suppression pool level exceeded specs w/value of -26 25 inches Caused by failure of operator to adequately monitor level while instrumentation out of sev due to plant mod Level returned to specs W/830929 ltr PASTVAM J. DIETZ, CR Carolina Power & Light Co 83/09/29 O'REILLY, J. P. Region 2. Office of Director 3pp 2044/099 24x Fiche 50-324,83/09/29,8310060277

- B310060383 LER 83-080/03L-0 on B30B3L following scram, while utilizing HPCI sys as heat sink for reactor, suppression pool water level exceeded Tech Specs Caused by HPCI pump min flow valve failing in open position Valve closed W/B30929 ltr PASTUM, J. POULK, R M. DIETZ, C R. Carolina Power & Light Ca B3/09/29 G'REILLY, J P. Region 2. Office of Director App 20646 065 24X Fiche 50-324, B3/09/29, B310060383
- 8310060075 LER 83-084/03L-0 on 830902, rod worth minimizer went to control and Group 4 while last two control ands of Group 3 still fully inserted Cause to be determined during future reactor startup W/630930 ltr
 PQULK.R M. DITIZ.C R. Carolina Power & Light Co. 8,4/09/30 0.48ELLY.J P. Region 2. Office of Director 2pp 20647 149 24; Fiche 50-324.83/09/30.83100600/5
- B310120426 LER 83-070/03L-0 on B30907, core spray or RHR pumps running annunciation received w/ma abnormalities or pumps running Caused by microswitch ND20A failure Switch replaced W/831003 lt;
 PASTVA, M J, DICT7, C R Caralina Power & Light Co B3/10/03 O'REILLY, J P. Region 2, Office of Director 2pp ±0648 278 24X Fiche 50-324,83/10/03,8310120426
- 6310170404 LER 83-084/03L-0 on 830916, during power operation, main steam line radiation monitor 2-D12-LRM-K603D showed indication less than indicated by redundant instrumentation Caused by instrument drift Channel recalibr W/831006 ltr PASTVA.M J , D1CTJ, C R Carolina Power & Light Co 83/10/06 O'REILLY, J P Region 2, Office of Director 2pp 20782 105 24X Fiche 50-324,83/10/06.6310170604
- 8310470596 Updated LER 83-069/03L-1 on 830825.while attempting to plant RHR room coalers 2A & 2B into secondition coaler would start Caused by fan start limit switch out of adjustment & mechanical binding of airflow dampers W/831007 ltr PASTVALM J , DIETZ C R Carolina Power & Light Co 83/10/07 O'/BEILLY, J P Region 2, Office of Director 3pp 20782 110 24X Fiche 50-324.83/10/07.8310170594
- 8310190238 Updated LER 81-118/03L-1 on Bi1201 five secondary containment fire seals unable to meet test acceptance criteria & declared inoperable Caused by degradation due to cracking or shrinking Seals repaired W/U31011 ltr ALLEN.M T., DIFTZ.C R. Carolina Power & Light Co. 83/10/11 D'REILLY.J P. Region 2. Office of Director 2pp. 20818 080 24X Fiche 50-324,83/10/11.8310190298
- 8310250237 Updated LER 83-042/03L-1 on 830330; supprecsion pool level indicators 2-CAC-L1-2601-1,2601-3 & 2-CAC-L1-3342 showed upward trend in level indication Caused by closed demineralized water root valve Valve responsed W/831017 ltr PASTVA; M J , DIFTZ, C R Carolina Power & Light Co 85/10/17 O'AETLLY, J P Region 2, Office of Director 2pp POU99 068 74X Fiche 50-324,83/10/17,8310250277
- 8310250396 Updated LER 83-054/03L-1 on 830530, following high/low alarm annunciation.RTGB suppression pool level indicator 2-CAC-L-1-2601-1.0 & 2-CAC-L-1-26342 levels found below Tech Spec limit Caused by spraying water W/831017 ltr PASTVA, M J, DIETZ, C R Carolina Power & Light Co 83/10/17 O'REILLY, J P Region 2, Diffice of Director 3pp 20897 293 24X Fishe 50-324,83/10/17,8310250396
- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B310250120 Forwards addl info re pending requests for exemption from LOCFR50. App R & 10CFR50 4B Info clarifies request for nine exemptions, schedule for alternate shutdown study & completed mods
 HOME, P W Carolina Power & Light Co 83/05/02 VA95ALLO, D B Operating Reactors Branch 2 21pp 20097 24B 24X
 Fichs 50-324,83/05/02,8310250120
- 8310110157 Ack receipt of 830420 itr transmitting Rev B to physical security plan Portions inconsistent w/JOCFR50 54(p) Encl comments should be accommodated to modify plan Comments withheld (ref lOCFR73 21)

 LEWIS.R C Division of Project & Resident Programs 83/07/12

 UTLEY.E E Carolina Power & Light Co 3pp 20666 2/9 P4X

 Fiche 50-324,83/07/12,8310110157
- 8310070273 Forwards IE Safequards Insp Repts 50-324/89-24 & 50-325/83-24 on 830707 & notice of violation O'REILLY, J P Region 2. Office of Director 83/09/01 UTLEY, F Carolina Power & Light Co. 2pp. 20456-349 24X Fiche. 50-324,83/09/01.83100702/3
- ~-8310070282 Notice of violation from incp on 830707 * Region 2. Diffice of Director 82/09/01 ip 20456 Jv1 24X Fiche 50-324,83/09/01,83100/0273

- --8310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 Noncompliance noted authorized employee entered protected area w/o badge & w/o being physically searched Details withheld (rof 10CFR73 21) HALL.B L Region 2. Office of Director 83/08/01 ip 20656 352 24X Fiche 30-324/83/09/01/8310070273
- 8310040347 Requests update of encl info re layout of technical support ctrs & emergency operations facilities VERRELLI,D M Division of Project & Resident Programs 83/09/12 UTLEY,E E Carelina Fower & Light Co 17pp 20625 183 247 Fiche 50-G00,83/09/12,831G040347
- 8310250545 Forwards IE Insp Repts 50-324/83-29 & 90-325/83-29 on B30815-19 No noncompliance noted O'REILLY, J P Region 2. Office of Director 83/09/21 UTLEY, F E Carolina Power & Light Co 2pp 20902 059 24X Fiche 50-324,83/09/21,8310250365
- --B310250578 IE Insp Repts 50-324/B3-29 & 50-325/B3-29 on B30B15-19 No noncompliance noted Major areas inspected emergency preparedness CLINE.W E Region 2, Office of Director B3/09/13 9pp 20902 061 24X Fiche 50-324.63/09/21,8310250565
- 8310040298 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-26 & 50-328/803-26 WERRELLI,D N Division of Project & Resident Programs 83/09/22 UTLEY,E E Carolina Power & Light Co ip 20621 001 24X Fiche 50-324.83/09/22.8310040298
- --B31004030& Responds to NRC 830801 ltr re violations noted in If Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed DIETZ.C R Carolina Power & Light Co 83/08/30 D'REILLY, J P Regison 2. Office of Directon 2pp 20621 002 24X Fiche 50-324.83/09/22.8310040298
- --8310040321 Forwards IE Insp Repts 50-024/83-26 & 50-325/83-26 on 830615-0715 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/08/01 UTLEY, E. C. Carolina Power & Light Co. 2pp. 20621 004 24X Fiche 30-324,83/09/22,8310040290
- --8310040326 Natice of violation from insp on 830615-0715 * Division of Project & Resident Programs 63/08/01 1 20621 006 24X Fiche 50-324.83/09/22.8310040299
- --8310040332 IE Insp Repts 50-324/83-26 & 50-325/83-26 on 830615-0715 Noncompliance noted Fire Protection Procedure OP-41 inadequately established MYERS,D O Region 2, Office of Director BEMIS,P R Division of Project & Resident Programs B3/07/29 10pp 20621 007 P4X Fiche 50-324,83/09/22,8310040298
- 8310050451 Notification of 831006 meeting w/util in Bethesda. HD to discuss progress rept on fire protection, alternative shutdown sys. associated circuits, cable routing, addl analyses, field verification & sprinkler sys MACKAY, S D Operating Reactors Branch 2, 83/09/27 VASSALLO, D B Operating Reactors Branch 2, 2pp 20450 037 24X Fiche 50-324, 83/09/27, 8310050451
- 8310060555 Releases public version of revised emergency plan & amergency plan implementing procedures FELTON J M Division of Rules and Records 83/09/30 Document Management Branch | p 20663 001 24% Fiche 50-324,83/09/30,8310060555
- --B310060561 Forwards public version of Rev 9 to emergency response plan & reviewd emergency plan implementing procedures including Procedures PIP-03 4 1 re unitial dose projections & PEP-App A re emergency response resources ZIMMERMAN.S R Carolina Power & Light Co B3/07/15 O'REILLY,J P Region 2, Dffice of Director 2pp 20663 002 24X Fiche 50-324,83/09/30.8310060555
- --8310060564 Public version of Rev 9 to emergency response plan BOYER, L E Carolina Power & Light Co 83/06/16 £9pp 20663 004 24X Fiche 50-324,83/09/30.8310060555
- --8310060567 Public version of revised emergency plan implementing procedures including Procedures PEP-03 4 1 re initial dose projections & PEP-App A re emergency response resources BOYER, 1. Carolina Power & Light Co 83/06/22 3Bpp 20663 033 24X Fishe 50-324,83/09/30,8310060555

- 8310070291 Forwards "Position Paper on Reg Guide 1 97" & "Response to NUREG-0737. Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities "
 ZIMMERMAN.S R Carolina Power & Light Co 83/09/30 VASSALLO.D B Operating Reactors Branch 2 1p 20655 177 24X Fiche 50-324.83/09/30.8310070291
- --8310070293 "Position Paper on Reg Ouide 1 97 "
 BROWN W E , WASENXO.M Carolina Power & Light Co 83/08/09
 33pp 20655 178 24X Fichs 50-324.83/09/30.8310070291
- --8310070295 "Response to NUREO-0737. Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities " BROHN, H E . MASENKO, M Carolina Power & Light Co 03/08/07 77pp 20658 211 24x Fichc 50-324, 83/09/30, 83100/0291
- 8310070241 Ack receipt of 830927 ltr informing NRC of steps taken to correct violations noted in IE Jusp Repts 50-324/83-24 & 50-325/83-24 O'RBILLY,J P Region 2, Office of Director 83/10/05 UTLEY,F & Carolina Power & Light Co Ip 20697 124 24X Fiche 50-324,83/10/05.83100702/41
- --8310070246 Responds to NRC 830901 ltr re violations noted in 1E lisp Repts 50-329/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73 21 & 10CFR2 770) UTLEY.E E Carolina Power & Light Co 83/09/27 D'REILLY.J f Region 2. Diffice of Director 2pp 20659 125 24X Fiche 50-324,83/10/05.8310070241
- 8310180427 Provides supplemental response to Generic Ltr B2-33 response response capability Add1 interim milestones & clarification of 830415 response re safety parameter display sys & emergency operating procedures provided UTLEY.E E Carolina Power & Light Co 83/10/14 VASSALLO.D B Operating Reactors Branch 2 3pp 20803 300 247 Fiche 50-324.83/10/14.8310180427
- 8310210064 Forwards IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-29 VERRELLI.D Division of Project & Resident Programs B3/10/1/UTLEY.E E Carolina Power & Light Co 2pp 2085/ P66 24X Fiche 50-324,83/10/17.8310210064
- --B310210070 IE Bafeguards Insp Repts 50-324/B3-33 & 50-325/BJ-3J on B30727-29 No moncompliance noted Major areas inspected review of licensee action to correct prior violations & testing Details withheld (ref 10CFR73 21)
 TOBIN.W J Region 2. Office of Director B3/10/14 lp 2087 268 24X Fiche 50-324, B3/10/17, B310210044
- 8310240080 Summary of B30707 merting w/util in Bethesda, MD re outstanding items & util progress on alternate shutdown capability assessment & mods required by 10CFR30. App R MACKAY. S Operating Reactors Branch 2 83/10/17. Operating Reactors Branch 2 4pp 20703 205 24X Fiche 50-324.83/10/17.
- 8310280129 Notification of 831103 meeting w/util in Rethesda. MD to discuss alternate shutdown sys. associated circuits.addl analyses. field verification. App R deviations & options & high-low pressure interfaces
 MACKAY. S.D. Operating Reactors Branch 2 83/10/25 VASSALLO. P.B. Operating Reactors Branch 2 2pp 20/64 026 24X
 Fiche 50-324.83/10/25.8310280129
- P Operating license stage documents & correspondence
- 9310030161 Advises that organizational changes for QA program & changer to FSARs & mpt capability rept will be forwarded when completed
 UTLEY,E E Carolina Power & Light Co 83/09/13 DENION.II R
 Office of Nuclear Reactor Regulation, Director Ip 20390 QPH 24X
 Fiche 50-000,83/09/13:8310030161
- 8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
 O'REILLY, J.P. Region 2, Office of Director 83/09/22 UTLEY, F.F.
 Carolina Power & Light Co. 2pp. 20620 331. 24X
 Ficha 50-000,83/09/22,8310040354
- 8310040385 Application for amend to Licenses DPR-62 & DPR-71, changing Fech Spec re feedwater & main turbine trip/bypass sys HOME: F W Carolina Power & Light Co 83/09/29 VASGALLO, D B Operating Reactors Dranch 2 Spp 20617 209. 24X Fiche: 50-324,83/09/29,8310040385
- --8310040388 Proposed Tech Spec changes re feedwater/main turbine trip sys actuation instrumentation & main turbine trip sys * Carolina Power & Light Co 63/09/29 28pp 20617 212 24X Fichs 50-324,83/09/29,8310040385

- --B310060066 Proposed Tech Spec changes for primary containment leadant testing * Caroline Power & Light (o 83/10/03 10pp 2064/046 24x Fiche 50-324.83/10/03.8310060054
- 8310310137 Forwards safety evaluation re review of util submittal addressing NUREG-0/37 ftem II K 3 17, "Rept on Outages of ECCS" Requirements met VASSALLD.D B Operating Reactors Branch 2 83/10/14 UTLLY.I L Carolina Power & Light Co. App. 20965 240 24X Fiche 50-384.03/10/14.831031013/
- --8306160513 "ECCS Repts (F-47) TMI Action Plan Requirements in unswict Steam Electric Plant, Units 1 & P." technical evaluation rept VOSBURY, F.W., OVERDECK, G.J. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-174/175 83/06/13 (HOW.E. NRC-0-911-84) TER-C5506-174/175 83/06/13 (HOW.E. Fiche 50-324,83/10/14,8310,10137
- 8310200058 Clarifies licensee intentions re installation of efficient monitoring instrumentation referenced in 821213 proposed radiological effluent Tech Specs Summary of installation schedules enci ZMMERMAN, 5 R Corolina Power & Light Co 83/10/17 VASSALLG, D persting feactors Branch 2 4pp 20894 005 247 Fichs 50-324, 83/10/17, 8310200058
- 8310200206 Requests extension until 831130 to provide response to 830901 request for addl info to electric distribution by: voltages

 HOWE.P b Carolina Power & Light Co. 03/10/17 VASSALLO, b B
 Operating Reactors Branch 2 Ip 20034 127 24X
 Fiche 50-524, 63/10/17, 8310200206
- 8310210264 Application for amend to Licenses DPR-71 & DPR-62.revising radiological efficient Tech Sprcs Justification for proposed changes & summary of revs encl HOME.P W Caroling Power & Light Co 83/10/17 VA69AL(U.D HOPERTHING Reactors Branch 2 15pp 20848 282 24X Fiche 50-324.83/10/17.8310210264
- --8310210268 Proposed thanges to radiological effluent Trub Specs * Carolina Power & Light Co 83/10/17 200pp 24848 297 24x Fiche 50-324,83/10/17,8310210244
- 8310250036 Requests approval to perform whost duration integrated lask rate test (Tupe A) Test would meet criteria of Becktel Tapical Rept NB-TUP-1. Tech Sprcs. IOCFRED. App J & ANSI 5td N45 4-1972 Approval requested by 84010/HOME.P W Carolina Power & Light Co 83/10/20 VABSALLU.D D Operating Reactors Branch 2 2pp 20095 272 24X Fische 50-324.83/10/20.8310250036
- 8310260141 Forwards program outlines. "Demonstration of Raychim table for Qualified Use in Class II. Svc " & "Measure of Voltage Withstand Level on Raychem Cable Samples After Exposure to Simulated LOCA" Programs expected to begin by Jan 1784 HCME.P W Carolina Power & Light Co 83/10/20 VASSALLO,D & Operating Reactors Branch 2 2pp 20/15 197 24X Fiche 50-324,83/10/20,8310260141
- --8310260145 Rev 2 to "Demonstration of Raychem Cable For Qualified Usi in Class IS Svc Primary & Secondary Containment for Brunswick Steam Electric Plant Units I & 2 " PARKS B. WALDOMF, J. Carolina Power & Light Co. 33/08/20 2/pp 20915 199 24X Fiche 50-324.83/10/20.8310260141
- ~-8310260148 Rev O to "Measure of Voltage Withstand Level on Hajrhem Cable Bamples After Exposure to Simulated LOCA " PARKS, B. WALDONE, J. M. Cappling Power & Light Co. 83/08/24 http: 20915 226 24X Fiche 50-324,83/10/20,8310260141
- G Inspection reports. IE Bulletins & correspondence
- 8310040182 Forwards IE Insp Repts 50-324/83-28 & 50-325/83-28 on 83080J-05 Na noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/08/20 UTLEY-E E Carolina Power & Light Co 2pp 20417 241 24X Fiche 50-324,83/08/30,8310040JH2

- --8310040203 IE Insp Repts 50-324/83-28 % 50-325/83-28 on 830801-05 No noncompliance noted Najor areas inspected licensee action on previous enforcement matters (AA program annual sevice & audit program implementation DEBBAGE-A O Region 7, Office of Director UPRIGHT (M. Division of Enqueering & Operational Program 83/08/25 /pp 20617 243 24X Fishe 50-324.83/08/30,0310040102
- 8310070273 Forwards IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 % notice of violation 0 REILLY, J. P. Region 2. Office of Director 83/09/01 UfLEY, F.C. Carolina Power & Light Co. 2pp. 20696 049 24X Fiche 50-324.83/09/01.83100707/3
- --8310070288 Notice of Violation from into on 830707
 * Region 2, Office of Director 83/09/01 ip 20696 351 24X
 Fiche 50-324.83/09/01,83100/02/3
- --8310070294 IE Safeguards Insp Repts 50-324/83-24 & 50-325/83-24 on 830707 Noncompliance noted authorized employee entered protected area w/o badge & w/o being physically ceatched Details withhold (ref 1001R/J.*1)

 HALL.B L Region 2, Office of Director MCGUIRF, D.R. Division of Emergency Preparedness & Materials Safety 83/08/01 Ip 20656 352 24X Fiche 50-324,83/09/01,8310070273
- 8310250965 Forwards IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-19 No noncompliance noted O'REILLY, J P Region 2, Office of Director 83/09/21 UYLEY, C Carolina Power & Light Co Epp 2090; 059 24X
- --B310250578 IE Insp Repts 50-324/83-29 & 50-325/83-29 on 830815-19 No noncompliance noted (lajor aleas inspected emergency preparedners CLINE.W E Region 2. Office of Director JENKINS.O R Division of Emergency Preparedness & Materials Safety 83/09/13 9pp 20902 061 24X Exche 50-324.03/09/21.0310250345
- E310040298 Ack receipt of B30830 ltr informing NRC of steps taken to correct violations noted in If Inc. Repts 50-324/03-26 & 50-325/03-26 William Programs of Project & Resident Programs UTLEY.E L Carolina Power & Fight Co
- ~-8310040306 Responds to NRC 830801 lt; re violations noted in 1E Insp Repts 50-324/83-26 & 50-325/83-26 Corrective actions fire protection sys walkdown will be performed to verify sys drawings Revised drawings will be prepared as needed DIETZ, C.R. Carolina Power & Light Co. 83/08/30 O'REILLY, J.P. Region B. Office of Director Epp. 20621-002 24X Fiche 50-324,83/09/22,8310040278
- 8310040321 Forwards IE Insp Repts 50-324/83-28 & 50-325/83-28 on 830415-0715 & notice of violation VERRELII.D M Division of Project & Resident Programs 83700/01 UTLEY,E L Carolina Power & Light Co 2pp 20621 004 24X Fiche 50-324,83709/22,8310040898
- --8310040326 Notice of violation from insp on 830615-0715 * Division of Project & Resident Programs 83/08/01 Ip 20621 006 24% Fiche 50-324.83/09/20.8310040298
- --8310040332 IE Insp Repts 80-324/83-26 & 50-329/83-26 on 830615 0715 Noncompliance noted Fire Protection Procedure UP-41 inadequately established MYERS.D.D. GARNER.L.W. ORDERS.W.T. Repins 2, Office of Director 83/07/29 10pp 20621 00/ 24X Fithe 50-324.83/09/22, 83100402/80
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification (ests " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/09726 Consolidated Edison Co of New York, Inc 11/pp 20754 022 P4X Fishe 50-000.83/09/26.8308200340
- 8308300.342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes." Syx list end JORDAN, El Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Wastinghouse Type 84-1 Differential Relays " 8vc list encl JORDAN, C L Division of Laergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24% Fiche 50-000,83/09/26,8308300345

- 8308300349 IE Info Notice 83-54. "Lead Shielding Attached to Safety-Related Sub W/o 1000850 59 Evaluation " Svc list encl JORDAN,E I Division of Emerginia Preparedness & Engineering Response (Post 830103) 83/09/29 Cunsolidated Edison Cn of New York, Int. 115pp 20716 324 247 Fichs 50-000.83/09/29,8308300349
- --83100/0246 Responds to NRC B30901 ltr re violations noted in IE lnsp Repts 50-324/83-24 & 50-325/83-24 Corrective actions withheld (ref 10CFR73 21 & 10CFR2 770) UTLEY,E E (urolina Power & Light Co 83/09/27 D'REILLY, J P Region 2, Office of Director 2pp 20659 125 24X Fiche 50-324, G3/10/05, B3100/0241
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bupass Loops Used in Westinghouse Plants" Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24% Fiche 50-000.83/10/07.8308300378
- B30B300752 IE Info Notice B3-66, "Patality at Argentine Critical Facility " Svc list and JORDAN,L L JUVISION of Lorgency Preparedness & Engineering Response (Past B30103) B3/10/07 Consolidated Edison Co of Net York, Inc 79μp 20882 024 24X Fiche 50-000,83/10/07,830B300752
- 8308300759 IE Info Natice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Syc. list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 183083) 83710711. Consolidated Edison Co. of New York, Inc. 117pp. 21043-075. 24X Fiche 50-000,83710711,8308300759
- 8308300761 IE Info Notice HJ-68, "Respirator User Waining Defective
 Self-Contained Breathing Apparatus Air Cylinders " Svc list
 encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
 York, Inc. 120pp. 20827 129 24X Fiche 50-000.83/10/11.8308300761
- B310250474 Ack receipt of 83092% ltr informing NRC of steps taken to correct violation; noted in Il linsp Repts 50-324/83-23 & 50-324/83-23 OREILLY, J.P. Region 2. Office of Director 83/10/11 UTLEY, E. Carolina Power & Light Co. 1p. 70900 O61 24X Fiche 50 324, GJ/10/11, 83107504/4
- --8310250480 Responds to NRC 83082b ltm re violations noted in 1E Insp Repts 50-324/83 29 \$ 50-325/83-23 Corrective actions procedure will be implemented by Bill30 to ensure revs to certificates of compliance will be identified HOME.P W Carbina Power & Light Co 83/09/23 O'REILLY, J P Region 2, Office of Director 3pp 20900 042 24X Fiche 50-324,83/10/11.83102504/4
- --8310250488 Forwards IE insp Repts 50-324/83-23 & 50-325/83-23 on B30626-30 & notice of violation Requests response to carcumstances surrounding radioactive matl shipment to another licensee.per 83072/ enforcement conference at situ O'REILLY, J.P. Region P. Office of Director 83/08/25 UTLEY, E.C. Carolina Power & Light Co. 2pp. 20700 065 24X Fiche 50-324,83/10/11,83102-04/4
- --8310250493 Notice of violation from insp on 830626-30 * Region 2. Office of Director 83/08/25 ip 20700 067 24X Fiche 50-324.83/10/11.8310250474
- --8310250501 IE Into Repts 50-324/83-23 & 50-325/83-23 on 8306PA-30 Noncompliance noted large quantity shipment in CNB-3-55 shipping cask not leak tested prior to delivery of parkage to carrier for transport ALBRIGHI, R H , BARRIK P Rigion 2. Office of Director 83/08/05 7pp 20900 068 24X Fiche 50-324, 83/10/11,8310250474
- B310200166 Forwards Rev 13 to Engineering Procedure ENP-16, "Procedure for Administrative Control of Inservice Insp Activities "List providing status of existing relief/exemption requests enc!
 HOMELP W. Carnling Power & Light Co. B3/10/12 VASSALLO,D R. Operating Reactors Branch & 2pp. 201828 001 24X
 Piche 50-324,83/10/12,83(0200166
- --8310200148 Rev 13 to Engineering Protedure ENP-14. "Procedure for Administrative Control of Inservice Insp Activities " * Carolina Power & Light Co 83/08/26 280pp 20028 003 P4X Fiche 50-324,03710712,8310200146

- 8310160551 Notification of 831021 meeting w/BWR licensees in Bethesda. MD to discuss future insps for intergranular stress corrosion cracking
 MIRAGLIA.F J Assistant Director for Safety Assessment 83.
 EISENHUT.O G Division of Licensing 5pp 2082,3 558 24x
 Fiche 50-000,83/10/14.8310180551
- 8310210064 Forwards 1E Safequards Insp Repts 50-324/83-33 & 50-325/83-33 on 840927-29 VERRELLI.D Division of Project & Resident Programs 83/10/UTLEY.E Carolina Power & Light to 2pg 20857 266 24X Fiche 50-324/83/10/17/8310210064
- --8310210070 IE Safeguards Insp Repts 50-324/83-33 & 50-325/83-33 on 830927-27 No noncompliance noted Major areas inspected review of licensee action to correct prior violations & testing Details withheld (ref 10CFR// 21) TOBIN,W J , MCGUIRE,D R Region 2, Office of Director 83/10/14 ip 20857 268 24X Fiche 50-324.83/10/17.8310216054 83/10/14
- 8310250451 Act receipt of 830804 ltr informing NRC of steps taken to correct violations noted in It Insp Repts 50-324/83-18 & 50-325/83-18 Violation re worker whole body count remains O'REILLY, J P Region 2. Office of Director 83/10/17 UTLEY, E Carolina Power & Light Co. 2pp 2089/081 24X fiche 50-324.83/10/17.8310250451
- --8310250457 Ack receipt of 830804 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-324/83-18 & 50-325/83-18 SUBSTRUCT Division of Project & Resident Programs & UTLEY, E E Carolina Power & Light Co ip 20097 003 Fiche 50-324-83/10/17.8310250451 83/08/30
- ~~8310250460 Responds to NRC 830705 ltr re violations noted in II Insp Repts 50-324/83-18 & 50-325/83-18 Corrective actions special ventilation hood installed from HEPA filtration unit in bag ventilation hood inscalled from mark filteration blice cutting/insp startion
 DIETZ.C.R. Carolina Power & Light Co. 63/08/04 D. Region 2. Office of Director App. 20897 084 24X
 Fiche 50-324.83/10/17.8310250451 O'RETILY, J P
- --8310250468 Forwards IE Insp Repts 50-324/83-18 & 50-325/83-18 on 830523-27 & notice of violation LEMIS, R C Division of Project & Resident Programs 83/07/05 UTLEY, E E Carolina Power & Light Co 2pp 20897 088 24X Fiche 50-324,83/10/17,8310250451
- --8310250473 Notice of violation from 1859 on 830523-27 Region 2. Office of Director 83/07/05 ly 2 Fiche 50-324,83/10/17.8310250451 20877 090
- --8310250477 IE hisp Repts 50-324/83-18 % 50-325/83-18 on 830523-27 Noncompliance noted failure to perform adequate air sampling ALBRIGHT, R H. BARK, K.P. Ruyon 2. Office of Director 83/07/ AR.K.P. Region 2. Office of Director 24X Fiche 50-324.83/10/17.8310250451 F0897 091
- 8310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions described in IE Info Notices 83-07 & 83-01 & IE Bulletins 83-04 & 83-07 Use of addlines & 85-07 & 85-07 & 85-07 Use of addlines & 85-07 & 85-07 Use of addlines & 85-07 & 85-07 Use of Addlines & 85-07 & 85-07 Use of Hospital Results & 85-07 & 85-0

persodic operating reports & related correspondence

0130124 Monthly operating repts for Sept 1983 W/831006 ltr ARRISON,F, DIFTZ,C R Carolina Power & Light Co 83/10/06 JEYOUNG,R C Director's Office, Difice of Inspection and Enforcement 14pp 20726 311 24X Fiche 50-324,83/10/06.

Reportable occurrences. LERs & tolated correspondence

- iO2iO329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GL BHR/4 rated at 2.436 MM Forwards App A documents Documents also available in FDR FELTON.J H Division of Ruler and Records 83/07/28 HAFNER, B Suffolk Nuclear Study Group 2pp 20HH2 223 24X Fiche 50-000,84/07/28,83102105/29
- 8303240341 Summarizes evaluation of LEKs for 1982 IER submittals usually acceptable Potential mot weakness indicated by large number of procedural deficiencies, lack of followup repts committed to & possible training problems
 EEYRITIK V Reactor Operations Analysis Branch 83/03/15
 LEWIS.R C Division of Project & Resident Programs App 20882 269 24X Fiche 80-000, 83/07/28, 8310210327

- 8310040412 LER 83-037/031-0 on 830831, control red 18-35 did not have full-out indication while fully withdraws caused by defective position indication switch indication will be repaired during future unit outone W/8 109/6 lite PASTVA, N J. DILTZ, C. Guroline Power & Light Co. 65/09/6 O'REILLY, J.P. Region 2, Uffice of Director. App. 2064/360 Paricks 50-325, 85/09/28, 8310040412
- B3100405B2 LER BU-033/03L 0 on Ha0829, during power optration, discovered primary containment isolation sur reactor low level? instrument iB21-LIM-NO24B-1 showing higher level than expected Caused by instrument drift WASA97B ltr PASTVA, M J. DILTZ, C.R. Carolina Power & Light to G2/09/2B D'REILLY, J.P. Region 2 Office of Director 2pp 20625 375 24X Fiche 50 325, G3/09/2B, 8310040842
- 8310060218 RD rs HP(1 sys, reported on 830404 Condition determined ant reportable
 DIETZ, C.R. Carolina Power & Light Co. 03/09/30 O'REINLY, J &
 Region 2, Office of Director 1p 20647 094 247
 Fiche 50-325,83/09/30,83100/60/18
- 8310120300 LER 03-042/03L-0 on 850909, rod full-out position indication and cation did not work when rod fully withdraw Caused by position indication probe connector or portion indication red soutch problem W/831003 ltr
 PASTVALM J. DIFT/. C.R. Carolina Power & Light Co. 65/10/07
 O'REILLLY, J.P. Region 2. Diffic of Director 2pp 20/91 014 24X
 Fiche 50-325.87/10/03.8310120300
- B310140011 Updated LER B3 036/03(-1 on B50800; during reactor (tortup, control power supply fuse on motor openator breaks) of syrfibm control valve 1-811-F068 bits Cauced by broken open position lampluse replaced W/B31004 lt;
 PASTVA. N.J., DITTA: C.R. Carolina Pawer & Light Co. (55/10/04)
 O'REILLY, J.P. Region P. Office of Director. 2pp. 20/66 360 ,749
 Fiche 50-325, B3/10/04, B310140011
- 8310140053 Updated IIR 82-629/03L-1 on 600718. Following reactor scrom. RCIC sys turbine automatically started on reactor low level, but immediately tripped on high turbine exhaust pressure Caused by calibi discrepancies N/RSI000 ltr PASIVA.M.J. Diltr.C.R. Canalina Power & tight Ca. 69/10/0 Of Fiche 50-32b, GJ/10/04, GJ/10/00bJ 107710707 3pp 20767 011
- 8310170414 LER 83-044/03L-0 on 630917, reactor recriculation pump 18 notor generator set tripped Caused by high motor generator set fluid drive temp Control air to valve isolated W/0/31005 PASTVA, N.J., DICTZ, C.R. Careline Power & Light Go (8.3/10/0), O'REILLY, J.P. Region 2, Office of Director (2pp. 20/79 1/2) Fiche 50 325, GJ/10/05, 8310170414
- B310190141 LER B3-045/03L-0 on B30919 & 24, while performing reacted vessel level loop calibrationard PCIV stoom supply to RCIC sys E51-F007 would not reapen past dual open-close position Cause outbrown 1007 repaired W/B31011 lt. PASTVA, M.J. BHT7.C.R. Carolina Power & Light Co. B3/10/11 O'REILLY, J.P. Region 2. Office of Director. 2pp. 20420 245 \$7 TAX Fiche 50 325,83/10/11,8310190141
- 8310190227 LER 83-039/03L-0 on 8309P3 during equipment & instrument channel checks.PT-01 14 revealed drywoll & suppression chamber water temp indications different Cavased by misdliqued point indicator Re-778 Indicator adjusted W/831011 lt. PASTVA.M v. DIETZ.C R Carolina Power & Light Co. 83/10/11 0'ABILLV.J P. Region 2. Offsice of Director 2pp 26018 048 pt. Fiche 50-325.83/10/11.8310190/227 24 X
- B310250521 Updated LER 83-018/03L-1 on 830503, during refueling outage, average gover range monitor D discovered insperable due to failed power supply Caused by defective diode, therister & capacitor W/B31017 tt:
 PASTWA: M J . POULK, R N . DILT/.C R Carolina Power & Light Ca B3/10/17 O'REILLY. J P Region 2. Office of Director Jpp 20901 293 24X Fiche 50-325.83/10/17.8310250521
- 8310270224 PNO-II-83-085 during ultrasonic exam of 28-inch recirculation sys discharge piping, suspect indications identified in two welds Addl analyses of data for pioper categorization continuing State of NC informed BLAKE, J. HARDIN, A. Region 2. Office of Director 83/10 20924-044 24X Fiche 50-325,83/10/21,8310270224 03/10/21 1 p

- DOCKET SO 3P7 SEQUOYAH NUCLEAR PLANT, UNIT I
- F. Security, medical, emergency & fire protection plans
- 8310040452 Submits central emergincy control ctr meteorological duta availability statistics for Apr June 1963 Data availability repts will be discontinued due to consistently high data availability through previous rept periods
 MILLS.L.M. Tennessee Valley Authority 83/09/28 ADENDAN.E.
 Licensing Branch 4 2pp 20823-326 (4X Fiche 50-000,83/09/2), 831004045
- 8310110094 Releases public version of revised emergency plan
- implementing procedure retrievable measurement plan implementing procedure retrievable model of Relea and Records 83/10/05 Decom Management Branch lp 2068/ 389 /45 Fiche 50-3.7.83/10/05, 8310110996 FELTON, J N
- 8310110100 Public version of Nev 1 to Imergency Plan Implementing Procedure SGN-IP-19, "Radiological Emergency Plan Training " W/830721 11: MARGOREL IVI CRAMLEY,D C . KAMMER,D S (Processee Valley Authority 83/0 DENTON.H R Office of Nucleat Reactor Regulation, Director 20687 J.70 24X Fiche 50 327/83/10/05,8310110096
- G310250563 Furuards IE Insp Repts 00-327/83-21 % 50-328/83 21 on B30713-16 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs B3/10/ PARRISH 6 (innessee Valley Authority 2pp 20901 144 24% Fiche 50-32/ 83/10/06/8310/50063
- 8310250569 IE Inap Repts 50-37/83-21 & 50-328/83-21 on 830913-16 No noncompliance noted Major areas inspected fire protection/ prevention program & implementation GIBBONS, I D Region 2. Office of Director COMION, T E Division of Engineering & Operational Programs 83/10/04 Sept 20701 146 24% Fiche 50-327, 83/10/06, 8310780553
- P. Operating license stage documents & correspondence
- 8310030504 [prwards SER re response to Generic Lir [4]-21, "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cooldown
 NOVAK,T M Assistant Director for Lictusing 83/09/23 PARVIS.H (
 Tennessee Valley Authority Ppp 20/0/208 24X
 Fiche 50-000,83/09/23,83100/30604
- --8310030607 SER accepting 811201 response to Generic Ltr 81-21. 'Natural Circulation Cooldown "

 NRC - No Detailed Affiliation Given 83/09/23 Upp 20607 290 24x Fiche 50-000.83/09/23,8310030604
- 8310120043 Forwards Amends 31 & 22 to ticenses DPR-7/ & DPR-7% respectively & safety evaluation Amends revise die...! generator surveillance requirements to reflect actual as-designed logic ADENSAM.L 0 Licensing Brunch 4 83/09/30 PARRIS.H 0 Jenn Valley Authority 3pp 20/51 259 24X Fiche 50-327, 83/09/30. lennesser Valley Authority 8310120047
- ---0310120044 Amends 31 & 2P to licenses DPR-77 & DFR-79, respectively, revising diesel generator surveillance requirements to reflect actual as-designed legit ADENSAMIC & Licensing Branch 4 83/09/30 Bpp 20/51 267 & Fiche 50-327, B3/09/30, B310120043 83/09/30 Bpp 20/51 269 84X
- --B31012004B Safety evaluation supporting Amends 31 & 22 to Licenses DPR-77 & DPR 79, respectively # Office of Nuclear Rearton Regulation. Director 63/09/30 Epp 20/51 2/0 2/4X Fichs 30-327.63/09/30.8310120043
- --B310120050 Requests FR publication of notice of consideration of issuance of amouds to Licenses DPR-7/ & DPR-79 & proposed NBMC determination & opportunity for hearing on 8.0615 & 0.729 requests re diese) generator surveillance requirements ADEMBARIC 0 Licensing Braich 4 83/10/04 NILLIK. J R Operating Reactors Branch 4 83/10/04 NILLIK. J R Fiche 80-327,83/09/30,8310120043
- --8310120086 Requests FR publication of notice of consideration of sequence of amends to Licenses DPR-// & DPR-/7 & proposed NSHC determination & apportunity for hearing on 830615 request re-diesal generator surveillance requirements ADENBANIC G Licensing Branch 4 83/07/22 CLARKIR A Operat Reactors Branch 3 Ppp 20781-273 24X Fiche 50-327,83/09/30,8310120043

- 8310190197 Forwards safety evaluation re-util response to Generic I to 81-21 "Natural Circulation Cooldown" Upon acceptable implementation of emergency response quidelines, procedures adequate for safe natural circulation cooldown NDVAR, T M Assistant Director for Licensing 83/09/30 (UCKER, H B Duke Power Co. 2pp. 20838-098-247 Fiche 50-000, 83/09/JD, 83/019/199 8310190199
- --8310170208 SER re response to Generic Ltr 81~21 "Natural Circulation Cooldown " Response acceptable * NRC No Detailed Affiliation Givin 83/07/30 8pp 20838 100 24X Fiche 50-000.83/07/30.8310190197
- 6310170133 Forwards notice of consideration of issuance of amend to Licenses DPR-7/ % DPR-79 % proposed NOHC determination % opportunity for hearing Amends change lech Specs re DNR parameters & hydrogen igniter surveillance tost ADENSAMLE G Licensing Branch 4 83/10/11 PARRIS.H G Tennese Valley Authority 2pp 20813 044 24X Fiche 30-327.83/10/11. Tennessev Valley Authority 83101/0133
- --8310170254 Notice of consideration of issuance of amend to Licenses DPR-77 & DPR-79 & proposed NSHC determination & opportunity for keering ADENSAM C G Licensing Branch 4 83/10/04 App 20813 044 2/ Fiche 50-327.83/10/11.8310170133 83/10/04 Spp 20813 045 24%
- 8310170261 Forwards NRC comments on TAYCO igniter spray environ program to be performed by Factory Mutual Response requested prior to test program completion
 NOVAK.T M Assistant Director for Licinsing 83/10/11 PARRIS.N ()
 Tennessee Valley Authority App 20776 261 24X
 Fiche 50-327.8J/10/11.8310170/46
- 8310180443 Requests extension until 840120 to submit final summary technical rept on results of surveillance capsule : in reactor vessel testing & analysis KAMMER.D 8 Tennessee Valley Authority 83/10/13 ADENSAN, F Licensing Branch 4 ip 20802 123 PAX Fiche 50-327.83/10/13.8310180443
- 8310280021 Application for amend to Licenses DPR-77 & DPR-79 changing Tech Specs 3/4 7 9 for snubbers ref to tables & deletion of DIVERVUEL Application for amend to Licenses DPR-77 & DPR-79 changi Tech Specs 3/4 7 9 for snubbers, ref to tables & deletion of ref to 51-162 MILLS,L M Tennessee Vailey Authoraty 83/10/24 ADENBAM, E Licensing Branch 4 2pp 20934 183 24X Fiche 50-327,83/10/24, 8310280021
- --83:0280040 Proposed Tech Specs re Tables 3/4 7 9 on Snubbers, dejetion of Tables 4 7 9a,4 7 9b & 4 / 9c from Limiting Condition for Operation 3 / 9, ref to tables & deletion of ref to 31-16P * Tennessee Valley Authority 83/10/24 13pp 20934 185 24X Fiche 50-32/,83/10/24,831020021
- 8310280022 Forwards proposed Teth Specs.levising 830817 amend request re-accident monitoring instrumentation MILLB.L M Tempessee Valley Authority 83/10/24 ADENSAM, E Licensing Branch 4 1p 20934 179 24X Fiche 50-327, 83/10/24, B31 02B0025
- ---B310280027 Proposed Tech Specs, revising 830819 submittal re-accident monitoring instrumentation * [ennesses valley Authority B3/10/24 3pp 20934 180 24X Fiche 50-327, 83/10/24, 8310280022
- 8310310429 Application for amend to Licenses DPR-77 % DPR-79, changing allowable value for diesel generator start & load shed timer MILLS, L M Tennessee Valley Authority 83/10/24 ADENSAM, E. Licensing Branch 4 2pp 20959 187 24X Fiche 50-327,83/10/24, Licensing Branch 4 2pp 83103104P9
- --8310310438 Proposed Tech Specs, changing allowable value for diesel generator start & load shed timer Highlicant hazards determination consideration entl 83/10/24 5pp 20959 189 24X * Tennessee Valley Authority Fiche 50-327,83/10/24,8310310429
- Q Inspection reports, IE Bulletins & correspondence
- 8310040442 Discusses WD DeFord discrimination case avising from unlawful actions against employer for participation in Jul 1980 NRC insp described in IL Insp Repts 50-327/80-24 & 50-328/80-15 dtd 800806 & forwards notice of violation O'REILLY, J P Region 2. Office of Director B3/09/20. PARRIS, H O Tennessee Valley Authority 2pp 20619 048 24X Fiche 50-327,83/09/20.8310040442

- --0310040446 Notice of violation arising from MD Deford discrimination case reunlawful actions against employee for participation in Jul 1980 NRC insp O'REILLY, J P Region 2, Dffice of Director 03/09/20 2pp 20619 050 24X Fiche 50-327,03/09/20,0310040/442
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Wilder Qualification Tests " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 820103) 87/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754-022 24x Fishe 50-000.89/09/26.8308290.440
- 8308300342 IE Info Notice 83-62, "Failure of Redondant Toxic Cus Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Limergency Preparedness & Engineering Response (Post 830103) 83/09/26 Cinsolidated Edison Co. of New York, Inc. 116pp 20777-210 24X Fiche 50-000, 83/09/26, 8308/40014,2
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " 5vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778-001 24X Fishe 50-000,83/09/26.8308.00345
- 8310250299 Forwards IE Insp Repts 50-32//63-17 & 50-328/63-17 on 830904-09 Nn noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/09/20 PARRISH 6 Tennessee Valley Authority 2pp 20895 331 24X Fiche 50-327.83/09/28.0310250299
- --8310250300 IE Insp Repts 50-32//83-17 & 50-328/83-17 on 830906-09 No noncompliance noted Major areas inspected inservice testing of pumps & valves & plant water chemistry ROSS, H J Region 2. Office of Director BLAKE, J J Division of Engineering & Technical Programs 83/09/26 App 20895 33.4 24X Fiche 50-327, 83/09/28, 8310250299
- 830B300349 IE Info Natice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Inquintering Response (Post 830103) 82/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308000347
- 8310250475 Ack receipt of 830822 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-12 & 50-328/83-12 &
- --8310250484 Responds to NRC 830725 ltr re violations noted in IF Insp. Repts 50-327/83-12 & 50-328/83-12 Corrective actions all piping capped or sealed to prevent damage or deterioration & all stainless steel piping in storage shed sealed MILLS.L M. Tennessee Valley Authority 83/09/23 D'REILLY, ! P. Region 2, Office of Director 3pp. 20902 104 24X Fiche 50-327.83/10/03.8310250475
- --B310250494 Responds to NRC B30/25 ltr re violation noted in IF Insp Repts 50-327/B3-12 & 50-328/B3-12 Corrective actions all plying corrected & verified capped or sealed to prevent damage or deterioration KAMMER.D S Tennessee Valley Authority B3/08/22 O'REJLLY.J P Region 2. Offsce of Director 2pp 20902 107 24X Fiche 50-327.B3/10/03.B310250475
- --8310250502 Forwards IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830606-0705 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/07/25 PARRIS.H G Tennessee Valley Authority 2pp 20702 110 24X Fiche 50-327.83/10/03.8310250475
- --8310250509 Notice of violation from insp on 830404-0705 + Region 2, Diffice of Director 83/07/25 ip 20902 iii 24X Fiche 50-327,83/10/03,8310250475
- --8310250517 IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830406-0/05 Noncompliance noted failure to properly store GA matl FORD, E. J., BUYLER, S. D. Region 2, Diffice of Director GUICK, P. R Division of Project & Resident Programs 83/07/22 Epp 20902 113 24X Fiche 50-327,83/10/03,8310250475
- 8310250403 Ack receipt of B30923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14
 LEHIS, R C Division of Project & Resident Programs 83/10/05
 PARRIS, H 0 Tennessee Valley Authority 1p 20897 199 24X
 Fiche 50-327,83/10/05,8310250403

- --B310250436 Responds to NRC B30B24 ltr re violations noted in IF Imap Repts 50 327/83-14 & 50-328/83 14 Corrective actions all late audit repts issued by 8:0630 & instructions arrived that deferment of responses unacceptable MILLS.L.M. Tennessee Valley Authority B3/09/23 P/BLWLY.UP Region 2, Office of Director Spp 20877-200 2/4X Fiche 50-327, B3/10/05, B3102/0403
- --8310250454 Forwards IE Insp Repts 50-3,7783-14 & 50-30968-14 on 830718-22 & notice of violation LEMIS.R C Division of Project & Resident Programs 837087.44 PARRIS.H G Tennessee Valley Authority 2pp 2087/205 ,*AX Fiche 50-327, 53710705.8310250403
- --8310250466 Notice of violation from 1850 an 830710-22 * Region 2, Office of Director 83708/24 2pp 20897 207 24) Fiche 50-327, 83710/05, 8310250403
- --B310250492 IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830/18 20 Noncompliance noted failure to assure that audit repts issued within 30 working days & failure to assure responses to audit findings issued within 30 days DEBBAGL.A G. UPRIGHT.C M Division of Engineering & Operational Programs B3/08/18 /pp 2089/ 209 24% Fiche 50-3/7,83/10/08,8310250403
- 8310250569 Forwards IE Insp Repts 50-327/83-21 & 50-328/83 21 on 830913-14 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 89710/06 PARRISH & Tennessee Valley Authority 2pp 20901 144 219 Fiche 50-327,83710/06.8310250563
- --B310250569 IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830913-14 No noncompliance noted Major areas inspected fire protection/prevention program & implementation OIBBDNS.T D Region 2. Office of Director COM UNITE Division of Engineering & Operational Programs 83/10/04 9pp 20/01 144-24% Fiche 50-327/83/10/06, B310250561
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in Rl) Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/0/ Consolidated Edison Co. of Nov York, Inc. 76pp 20827 213 24X Fiche 50-000, 83/10/0/, 83083001/0
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critica)
 Facility " Svc list encl
 JDRDAN,E L Division of Emergency Prenaredness & Ingineering
 Response (Post 830103) 83/10/07 Consolidated Edison (a of Non
 York, Inc. 79pp. 20882 026—24X Fiche 50-000,83/10/07,8388/300/56
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Naxious Gases " Svc list encl JORDAN E L Division of Emergency Preparodness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison (a of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300/57
- 8308300741 IE Info Notice 83-48, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svr list encl JORDAN, E. Division of Emergency Precaredness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 127 24X Fiche 50-000,87/10/11,8308700761
- 8310250593 Ack receipt of 83100/ ltr informing NRC of steps taken to correct violations noted in 1t Insp Repts 50-327/83-14 & 50-328/83-16 WERRELLI, D M Division of Project & Resident Programs 83/10/19 PARRISH 9 Tennessee Valley Authority ip 20900 139 ,24x Fiche 50-327, 83/10/19, 8310250573
- --8310250602 Responds to NRC 830913 ltr le violationr noted in IL Insp. Repts 50-327/83-16 & 50-328/83-16 Corrective actions A8015 fan control switches placed in auto position A upon discovery & outboard bearing disassembled for QC insp. MILLS.L.M. Tennessee Valley Authority 83/10/07 O'REILLY.J.F. Region 2, Office of Director 4pp 20400 140 24X Fiche 50-327,83/10/19,8310250593
- --8310250611 Forwards IE lnsp Repts 50-327/83-16 & 50-328/83-16 on 830706-0805 & notice of violation VERRELLID M Division of Project & Resident Programs 83/07/13 PARRIE.H 0 Tennessee Valley Authority 2pp 20700 144 24X Fiche 50-327.83/10/19.8310250593
- --8310250417 Notice of violation from insp on 930704-0005 * Region 2. Office of Director 83/09/13 2pp 20900 146 P4Y Fiche 50-327.83/10/19.8310250393

- --8310250624 IE Insp Repts 50-327/83-16 & 50-328/83-16 on 830706-0005 Noncompliance noted failure to follow 501-30 & for calibr of main & auxiliary feedwater pumps FORD, E. J. DUTLER, S. D. Region 2, Office of Director JULIAN, C. A. Division of Project & Resident Programs 83/09/13 &pp 20900 148 24X Fiche 50-327,83/10/19,8310250593
- R Pariodic operating reports & related correspondence
- B310190066 Monthly operating repts for Aug 1983 W/830915 ltr EDDINGS,M G . DUPRCE.D C . MAION.C C Tonnessee Valley Authority 83/09/15 Office of Resource Management, Director 19pp 20822 301 24X Fiche 50-327.83/09/15.8310190066
- S Reportable occurrences, LERs & related correspondence
- B310030218 LER 83-111/03L-0 on 830831, while performing 8I-102, direct generator 1A2 found w/oil in glycol expansion tank Caused by oil on top of water from prior lube oil cooler leak & failed culinder head Coolant isplaced W/830928 lit DUGOIN, G E., #MRDING.N R . GREEN, H J Tennessee Valley Authority 83/09/28 0.78ELLLY, J P. Region 2. Office of Director 2pp 20970 149 24X Fiche 50-327, 83/09/28, 8310030218
- 8310060083 LER 83-113/03L-0 on B30901.steam generator blowdown effluent line radjation monitor (1-RM-90-120/121) declared inoperable Caused by loss of effluent flow during steam generator flushing process W/130923 lt ROGERS, H R , HARDING, H R , GRIEN, H J Tenhessee Valley Authority 83/09/28 0'RCILLY, J P Region 2, Office of Director 2pp 20647 178 24X Fiche 50-327.83/09/28.8310040083
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EilOM transmitter Underrange zero offset may occur when transmitter initially prossurized from atmospheric to suppressed zero input End users notified BERDERIAN.M J Foxboro Corp B3/09/30 Director's Office, Office of Inspection and Enforcement lipp 20631 064 24X Fiche 50-000.83/09/30.8310070301
- 8310170276 LER 80-120/03L-0 un 830710, all ice condenser doors opched when containment sump isolation valve 1-FCV-63-73 stroked Caused by bockflowed water causing small pressure surge in lower containment Doors closed W/831007 bt, OREEN.H J Tennessee Valley Authority 83/10/07 O'RETLLY, J P Region 2. Office of Director 4pp 20/86 205 24X Fiche 50-327, 83/10/07, 8310170776
- 8310170892 LER 83-117/017-0 on 830926, monthly power range in-core/ pr-core channel comparison found not performed Caused by personnel error Surveillance performed Personnel reinstructed W831007 1 tr QREEN.H J Tennessee Valley Authority 83/10/07 D'REILLY, J P Regian 2. Office of Director 3pp 20780 190 24X Fiche 50-327,83/10/07,8310170592
- 8310170897 LER B3-119/03L-0 on 830910, containment internal pressure limit for annulus pressure exceeded Caused by normal air leakage into containment w/o venting Cantainment pressure returned to within 1/mit W/830070 itr GREEN.H J Tennessee Valley Authority 83/10/07 O'REILLY, J P Region 2, Office of Director 3pp 20/82 107 24X Fiche 50-327,03/10/07,8310170597
- 8310190124 Updated LER 83-063/03L-1 on 830912, while in Mode 3, following maint, PORV 1-PCV-68-340 found leaking Caused by associated block valve not closing fully PDRVs will be replaced during refueling outage W/831011 itr KIRK, C . HARDINO, M . OREEN, M . Tennessee Valley Authority 83710/11 078ELLY, J P Region 2, Office of Director Spp. 20821 121 24% Fiche 50-327,83/10/11,8310190124
- 8310230077 LER 83-128/03L-0 on 830920 & 22.condensor exhaust flow rate monitor 1-FT-2-257 failed high Caused by sonse lines containing buildup of condensate which caused channels to read high & erratic Lines blown down, W/831017 ltr ROOERS, H R , HARDING, M R , GREEN, H J Tennessee Valley Authority 837/10/17 0'REILLY, J P Region 2. Office of Director 2pp 20896 163 24X Fiche 50-327.83/10/17.8310250077
- DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT Q

 F Security, medical, emergency & fire protection plans
- 8310040452 Submits central emergency control ctr meteorological data availability statistics for Apr-June 1783 Data availability repts will be discontinued dur to consistently high data availability through previous rept periods MILS.L M Tennessee Valley Authority 83/09/28 ADENSAM, E. Licensing Branch 4 2pp 20623 326 24% Fiche 50-000, 83/09/28, 8310040452.

- 831021034! Forwards Amend 2.3 to ticense EPR-79 & safety evaluation Amend changes conditions re post-accident sampling (TMI Item II B 3), instruments for core cooling, addi accident monitoring instrumentation & upgrades support facilities ADENSAM, E 0 Licensing Branch 4 B3/09/30 PARRIS. H 0 Tennessee Valley Authority 3pp 20883 150 24X Fiche 50-328,83/09/30,8310210341
- --8310210344 Amend 23 to License DPR-79, changing post-accident sampling (TMI Item II B 3), add) accident monitoring instrumentation, instruments for core cooling & upgrading emergency support facilities EISENMUT, D C Licensing Branch 4 83/09/30 2pp 20883 154, 24X Fiche 50-328,83/09/30,8310210341
- 8310110076 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Receids 83/10/05 Document Management Branch ip 20687 327 24X Fiche 50-327,83/10/05, 8310110076
- --8310110100 Public version of Rev 1 to Emergency Plan Implementing Procedure SQN-IP-19, "Radiological Emergency Plan Training " W/830921 ltr CRAMLEY.D E , KAMMER.D S Tennessee Valley Authority. 83/09/16 DENTON.H R Office of Nuclear Reactor Regulation, Director. App. 20487 330 24X Fiche 50-327.83/19/05.8310110996
- 8310250563 Forwards IE Inap Repts 50-327/83-21 & \$0-328/83-21 on 830913-16 No moncompliance noted VERRELLI,D M Division of Project & Resident Programs. 83/10/06 PARRIS,H G Tennessee Valley Authority 2pp 20901 144 24X Fiche 50-327,83/10/06.8310250563
- --9310250569 IE Insp Repts 50-327/83-21 & 20-328/83-21 on 830913-16 No noncompliance noted Major areas inspectrd fire protection/prevention grogram & implementation GIBHONS,T D Region & Office of Director 83/10/04 5pp 20901 146 24X Fiche 50-327/83/10/06/8310250563
- P Operating license stage documents & correspondence
- B310030604 Forwards BER re response to Generic Ltr 81-21, "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cooldown NOVAK.T M Assistant Director for Licensing 83/09/23 PARRIS.H G Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000,83/09/23,8310030604
- -~8310030607 SER accepting 811201 response to Generic Ltr 81-21, "Natural Circulation Couldown"

 * NRC No Detailed Affiliation Given 83/09/23 8pp 20607 290 24X Fiche 50-000.63/09/23.8310030604
- 8310130029 Forwards Amend 21 to License DPR-79 & safety evaluation Amend changes Tech Specs to accommodate Cycle 2 reload operations & changes requirement for testing containment protective fuses to visual insp ADENSAM, E O Licensing Branch 4 83/09/29 PARRIS, H O Tennessee Valley Authority 3pp 20776-324 24X Fiche 50-328,83/09/29,8310130029
- --8310130039 Amend 21 to License DPR-79, changing Tech Specs to accommodate Cycle 2 reload operations & changing requirement for testing containment protective fuses from destructive type testing to visual insp ADEMBAME 0 Licensing Branch 4 83/09/29. 28pp. 20776 326 24X Fiche 50-328,83/09/29,8310130029
- --8310130043 Bafety evaluation supporting Amend 21 to License DPR-79
 * Office of Nuclear Reactor Regulation, Director 83/09/29. 9pp
 20776 335 24% Fiche 50-328,83/09/29,8310130029
- 8310120043 Forwards Amends 31 & 22 to Licenses DPR-77 & DPR-79, respectively & safety evaluation Amends revise diesel generator serveillance requirements to reflect actual as-designed logic ADENSAM. E Q Licensing Branch 4. 83/09/30 PARRIS. H Q Tennessee Valley Authority. Spp 20751 259 24X Fiche 80-327,83/09/30,8310120043
- ~-8310120046 Amends 31 & 22 to Licenses DPR-77 & DPR-79, respectively, revising dissel generator surveillance requirements to reflect actual as-designed logic ADENBAME 0 Licensing Branch 4 83/09/30 Bpp. 20751 262 24K Fiche 50~327.63/09/30, 8310120043
- ~-833012004B Safety evaluation supporting Amends 31 & 22 to Litenses pPR-77 & DPR-79, respectively * Office of Nuclear Reactor Regulation, Director, 83/09/30 2pp. 20751 270 24X Fiche 50-327,83/09/30,8310120043.

- --B310120054 Requests FR publication of notice of consideration of issuance of amends to Licenses DPR-77 & DPR-79 & proposed NSHC determination & appartunity for hearing on B30615 request re diesel generator surveillance requirements ADENBAH:E 9 Licensing Branch 4 B3/07/22 CLARA:R A Decrating Reactors Branch 3 2pp 20751 273 24X Fiche 50-327.83/09/30, B310120043
- 8310190199 Forwards safety evaluation re util response to Generic Lti 81-21 "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures adequate for safe natural circulation cooldown NOVAK,T M Assistant Director for Licensing 83/09/30 TUCKER,H B Duke Power Co 2pp 20838 098 24X Fiche 50-000, 83/09/30, 8310190199
- --8310190208 SER re response to Generic Ltr 81-21 "Natural Circulation Cooldown" Response acceptable * NRC - No Detailed Affiliation Olven 83/09/30 App 20838 100 24X Fiche 30-000,83/09/30,8310190199
- 8310210341 Forwards Amend 23 to License DPR-79 % safety evaluation Amend changes conditions me post-accident sampling (IMI Item II B 3), instruments for core cooling, addl accident manitoring instrumentation & upgrades support facilities ADENSAM.E 0 Licensing Branch 4 B3/09/30 PARRIS.H @ Tennescer Valley Authority 3pp 20883 150 24% Fiche 50-328,83/09/30,8310210341
- --8310210344 Amend 23 to License DPR-79, changing post-accident sampling (THI Item II B 3), add1 accident monitoring instrumentation, instruments for core cooling & upgrading emergency support facilities EISENHUT, D G Licensing Branch 4 83/09/30 2pp 20883 152 24X Fiche 50-328, 83/09/30, 8310210341
- --8310210347 Safety evaluation supporting Amend 23 to License DPR-79 * Office of Nuclear Reactor Regulation. Director 83/09/30 3p; 20883 184 24X Fiche 50-328.83/09/30.8310210341
- 8310170133 Forwards notice of consideration of issuance of amend to Licenses DR-77 & DRR-79 & proposed NSFIC determination & opportunity for hearing Amends change Tech Specs re DNB parameters & hydrogen igniter surveillance test ADENSAM.E Q Licensing Branch 4 83/10/11 PARRIS.H Q Tennesset Valley Authority 2pp 20813 044 24X Fiche 50-027.83/10/11, 8310170133
- --8310170254 Notice of consideration of issuance of amend to licenses BPR-77 & DPR-79 & proposed NSHC determination & opportunity for hearing ADENBAM, E O Licensing Branch 4 83/10/04 App 20813 046 24X Fiche 50-327.83/10/11,8310170133
- 8310170261 Forwards NRC comments on TAYCO igniter spray environ program to be performed by Factory Mutual Response requested prior to test program completion
 NOVAK,T M Assistant Director for Licensing B3/10/11 PARRIS,H G
 Tennessee Valley Authority 4pp 20796-261 24X
 Fiche 50-387,83/10/11,8310170261
- HO280021 Application for amend to Licenset DPR-77 th DPR-79 changing Tech Specs 3/4 7 9 for snubbers, ref to tables & deletion of ref to SI-162
 MILLS, L.M. Tennessee Valley Authority 83/10/24 ABENSAM, E. Licensing Branch 4 2pp 20934 183 24x Fiche 50-327, 83/10/24, 8310280021
- --B310280040 Proposed Tech Specs re Tables 3/4, 7 9 on anobbers, deletion of Tables 4 7 9a, 4 7 9b & 4 7.9c from Limiting Condition for Operation 3 7 9; ref to tables & deletion of ref to 91-162 * Tennessee Valley Authority B3/10/24 13pp 20934 185 24X Fiche 50-327,83/10/24,8310280021
- 310280022 Forwards proposed Tech Specs.revising 830819 amend request re-accident monitoring instrumentation MILLS.L M Tennessee Valley Authority 83/10/24. ADENSAM.E. Licensing Branch 4 1p 20934 179 24% Fiche 50-327.83/10/P4.8310280022
- -8310280027 Proposed Tach Apecs, revising 830819 submittal re accident monitoring instrumentation * Tennessee Valley Authority 83/10/24 Spp 20934·180 24X Fiche 50-327,83/10/24,8310280022
- 310310429 Application for amend to Licenses DPR-77 & DPR-77, changing allowable value for diesel generator start & load shed timer MILLS,L M. Tennessee Valley Authority 83/10/24 ADENSAM.E Licensing Branch 4 2pp 20959 187 24X Fiche 30-327.83/10/24, 8310310429

- --8310310438 Proposed Tech Specs, changing allowable value for dissel generator start & load shed timer Significant hazards determination consideration end 1 * Tennessee Valley Authority 83/10/24 5pp 20959 189 24X Fiche 50-327,83/10/24,8310310429
- G. Inspection reports: IE Bulletins & correspondence
- 8310040442 Discusses WD DeFord discrimination case alising from unlawful actions against employee for participation in Jel 1980 NRC insp described in IL Insp Repts 50-327/80-24 & 50-328/80-19 dtd 800806 & forwards notice of violation O'REILLY, J F Region 2, Office of Director 83/09/20 PARRIS.H G Tennessee Valley Authority 2pp 20619 048 24X Fiche 50-327,83/09/20.8310040442
- --B310040446 Notice of violation arising from WD Deford discrimination case re-unlawful actions against employee for participation in Jul 1980 NRC insp O'REILLY, J P Region 2, Diffice of Director B3/09/20 2pp 20619 050 24X Fiche 50-327, B3/09/20, B310040442
- 8308300340 If Info Notice 83-61. "Alleged Use of Stand-Ins for Hilder Qualification Tests" Syc list entl JORDAN,C L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308J00J40
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83/09/26,8308800342
- 0308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83709726,8308300345
- 0310250299 Forwards IE Insp Repts 50-327/83-17 & 50-328/83-17 on 830906-09 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 03/09/26 PARRIS, H G Tennessee Valley Authority 2pp 20095 331 24X Fiche 50-327,83/09/28,8310250299
- --B310250300 IE Insp Repts 50-32//83-17 & 50-328/83-17 on 830904-09 No noncompliance noted Major areas inspected inservice testing of pumps & valves & plant water chemistry ROSS,W J Region 2, Office of Director BLAKE,J J Division of Engineering & Technical Programs 83/09/26 App 20895 333 24% Fiche 50-327,83/09/28,8310250299
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evaluation " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20714-324 24X Fiche 50-000,83/09/29,8308900347
- 8310130029 Forwards Amend 21 to License DPR-79 & safety evaluation Amend changes Tech Specs to accommodate Cycle 2 reload operations & changes requirement for testing containment protective fuses to visual inspective ADENSAM, E. G. Licensing Branch 4 83/09/29 PARRIS, H. G. Tennesser Valley Authority 3pp 20776-324 24% Fiche 50-328, 83/09/29, 8310130029
- ~-8310130039 Amend 21 to License DPR-79, changing Tech Specs to accommodate Cycle 2 reload operations & changing requirement for testing containment protective fuses from destructive type testing to visual insp ADENSAN.E & Licensing Branch 4 83/09/29 28pp 20776 326 24X Fiche 50-328, 83/09/29, 8310130029
- --8310130043 Bafety evaluation supporting Amend 21 to License DPR-79
 * Office of Nuclear Reactor Regulation, Director 83/09/27 9pt
 20776 355 24X Fiche 50-328.83/09/29.8310130029
- 8310250475 Ack receipt of 830822 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-12 & 50-328/83-12 LEWIS,R C Division of Project & Resident Programs, 83/10/03 PARRIS,H G Tennessee Valley Authority 1p 20902 103 PAX Fiche 50-327,83/10/03.8310250475

- --8310280484 Responds to NRC 830725 itr re violations noted in 15 Insp Repts 50-327/83-12 & 50-328/83-12 Corrective actions all piping capped or sealed to prevent damage or deterioration & all stainless steel piping in storage shed sealed MILLS.L.M. Tennessee Valley Authority 83/09/23 0'REILLY, J.P. Region 2. Office of Director 3pp 20902 104 24X Fiche 50-327.83/10/03.8310250475
- --8310250494 Responds to NRC 830725 ltr re violation noted in 1E Insp Repts 50-327/83-12 & 30-328/83-12 Corrective actions all pining corrected & verified capped or scaled to prevent damage or deterioration KAMMER.D 5 Tennessee Valley Authority 83/08/22 0'REILLY.J P Region 2, Office of Director 2pp 20902 107 24X Fiche 50-327,63/10/03,83102*0475
- --8310250502 Forwards IE Insp Repts 50-307/83-12 & 50-308/83-12 on 830404-0705 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/07/25 PARRIS.H G Tennessee Valley Authority 2pp 20902 110 24X Fiche 50-327,83/10/03.83102:0475
- ~-8310250507 Notice of Violation from insp on 830404-0705 * Region 2, Office of Director 83/07/25 ip 20902 ii2 24X Fiche 50-327,83/10/03.83102504/5
- ---8310250517 IE Insp Repts 50-327/83-12 & 50-328/83-12 on 830606-0/05 Noncompliance noted failure to properly store GA mat1 FORD,E J. BUTLER,S D. Region 2. Office of Director QUICK,D R Division of Project & Resident Programs 83/07/22 Spp 20902 113 24X Fiche 50-327,83/10/03.8310250475
- B310250403 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-14 & 50-328/83-14 & EWIS,R C Division of Project & Resident Programs 03/10/05 PARTIS.H 0 Tennessee Valley Authority 1p 20897 179 P4X Fiche 50-327,83/10/05.8310250403
- --8310250436 Responds to NRC 830824 ltr re violations noted in IC Insp Repts 50-327/83-14 & 50-328/83-14 Corrective actions all late audit repts issued by 830630 & instructions issued that deferment of responses unacceptable MILLS: L M Tennossee Valley Authority 83/07/23 O'REILLY: J P Region 2, Office of Director 5pp 20897 200 24X Fiche 50-327.83/10/05,8310250403
- --83i0250454 Forwards IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830718-22 & notice of violation LEMIS:R C Division of Project & Resident Programs 83/08/24 PARTIS:H G Tennessee Valley Authority 2pp 20897 205 24% Fithe 50-327:83/10/05,8310250403
- --8310250466 Notice of violation from insp on 830718-22 * Region 2, Office of Director 83/08/24 2pp 20847 207 24X Fiche:50-327,83/10/05,8310250403
- --8310250492 IE Insp Repts 50-327/83-14 & 50-328/83-14 on 830718-22 Noncompliance noted failure to assure that audit repts issued within 30 working days & failure to assure responses to audit findings issued within 30 days BEBBAGE, A G , UPRIGHT, C M Division of Engineering & Operational Programs 83/08/18 7pp 20877 207 24X Fiche 50-327,83/10/05, 8310250403
- 8310250563 Forwards IE Insp Repts 50-32//83-21 & 50-328/83-21 on 830913-16 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/10/06 PARRIS,H & Tennesses Valley Authority 2pp 20901,144 24X Fiche 50-327,83/10/06,8310250563
- --8310250567 IE Insp Repts 50-327/83-21 & 50-328/83-21 on 830910-16 No noncompliance noted Major areas inspected fire protection/prevention program & implementation G1800N6.T D Region 2, Office of Director CONLON.T E Division of Engineering & Operational Programs 83/10/04 5pp 20701 146 24X Fiche 50-327.83/10/06.8310250563
- 83083003/8 IE Info Notice 83-65. "Surveillance of Flow in RID Bypass Loops Used in Mestinghouse Plants." But list enri JERDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- B30B300752 IE Info Notice B3-66, "Fatality at Argentine Critical Facility " Svc list encl JDRDAN,E L Division of Cmergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000.83/10/07.8308300752

- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York. Inc 11/pp 21043 075 24X Fiche 50-000,83/10/11.8308300757
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310250593 Ack receipt of B31007 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-16 & 50-328/83-16 & VERRELLI, D M Division of Project & Resident Programs 83/10/19 PARIS. H G Tennessee Valley Authority 1p 20900 139 24X Fiche 50-327, 83/10/19, 8310250593
- ~-8310250602 Responds to NRC 830913 ltr re violations noted in 1E Insp Repts 50-327/83-16 & 30-328/83-16 Corrective actions A8078 fan control switches placed in auto position A upon discovery & outboard bearing disassembled for GC insp MILLS.L M Tennesse Valley Authority 83/10/07 D'REILLY, J P. Region 2, Office of Director 4pp 20900 140 24X Fiche 50-327,83/10/19,8310250593
- --8310250611 Forwards IE Insp Repts 50-327/83-16 & 50-328/83-16 on 830704-0805 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/09/13 PARRIS.H 0 Tennessee Valley Authority 2pp 20900 144 24X Fiche 50-327,83/10/19,8310250593
- --8310250417 Notice of violation from insp on 830704-0805 * Region 2, Office of Director 83/07/13 2pp 20900 146 24X Fiche 50-327,83/10/19,8310250593
- --8310250624 IE Insp Repts 50-327/83-16 & 50-328/83-16 on 630704-0805 Noncompliance noted failure to follow 601-30 6 for calibr of main & auxiliary feedwater pumps FORD, E. J., BUTLER, B. D. Region 2, Office of Director JULIAN, C. A. Division of Project & Resident Programs 83/09/13 4pp 20900 148 24X Fiche 50-327.83/10/19.8310250593
- R Periodic operating reports & related correspondence
- S Reportable occurrences, LhRs & related correspondence
- B310030240 LER B3-114/03L-O on B30823, during testing of safety injection sys (SIB) & centrifugal charging pumps (CCP).BJB pump 2A & both CCPs failed to meet min head curve requirements Caused by normal pump operation W680921 ltr HARDING.M R . MIRK.G B . GREEN.H J Tennessee Valley Authority B3/09/21 07REILLY.JP Region 2. Office of Director App 20590:075 24X Fiche 50-328,83/09/21,8310030240
- B310070301 Potential Part 21 rept re underrange characteristic of Model N-Ei10M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIANN J Foxboro Corp B3/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30,8310070301
- 8310140087 LER 83-118/03L-0 on 830907.81-214 re uncontrolled boron dilution not performed within required 72 h frequency Caused by personnel error Operations personnel reinstructed W/831006 ltr OREEN.H J Tannessee Valley Authority 83/10/06 0'REILLY, J P. Region 2. Office of Director 2pp 20767 009 24X Fiche 50-328,83/10/06,8310140087
- 8310170658 LER 83-121/03L-0. on 830911. during Mode 5, lower containment airlock failed overall leakage Test 81-159 1 Caused by leakage through four handwheel packings due to normal wear. Doors overhauled H/831007 ltr OREEN.H J Tennessee Valley Authority B3/10/07 0'REILLY, J P Region 2, Office of Director 3pp 20779 282 24X Fiche 50-328,83/10/07.831017065B

- DOCKET 50-329 MIDLAND PLANT. UNIT 1
- A Application/construction stage documents & correspondence
- 8310190311 FOIA request for documents re casehoad forecast panel 830417 meeting on plant const GARDE.B P Government Accountability Project 83/07/11 Office of Administration 2pp 20840 329 24% Fiche 50-329.83/07/11.
- B31018061B FOIA request for documents submitted by util for consideration of candidate companies or methodologies to perform const implementation overview of const completion plan
 OARDE.B P Government Accountability Project 83/08/05 Dffact
 of Administration 2pp 20839 110 24% Fiche 50-329.83/08/05,
 831018061B
- B310130390 FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Lendsman in ASLB proceedings GARDE, B F Oovernment Accountability Project B3/08/08 Office of Administration 2pp 20769 352 24% Fiche 50-329,83/08/09,8310130390
- 8310190316 Responds to FOIA request for documents re caseload forecast panel 830419 meeting on plant const Info partially withheld JR Cook draft lir to TM Novak (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/08/09 GARDE, R P Government Accountability Project 6pp 21116 001 24X Fichs 50-329,83/08/09,8310190316
- 8310190300 Appeals denial of FDIA request for documents re caseload forecast panel 830419 meeting on plant const Danial effectively denied bulk of documents requested OARDE,8 P Government Accountability Project 83/09/10 DIRCKB,W J Office of the Executive Director for Operations 2pp 20840 324 24X Fichs 50-329.83/08/10.8310190300
- 8310130394 Responds to FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ABLU proceedings Forwards
 App A documents Documents also in PDR
 FELTON, J M Division of Rules and Records 83/08/25 CARDE, B P Covernment Accountability Project 2pp 20769 354 24X
 Fichs 50-329,83/08/25,8310130394
- --8308150338 Advises of assignment as member of task group to recyalizate structural design & const adequacy of plant diesel generator bldg MUO,F T Structural & Geotechnical Engineering Branch 83/08/08 TAN.C P. Structural & Geotechnical Engineering Branch Jp 20769 362 24X Fiche 50-329,83/08/25,8310130394
- --B308270027 Requests meeting on B30822 to discuss Landsman concerns that dissel generator bldg inadequate to return to svc based on inability to meet design requirements VOLLHER, R NRC No Detailed Affiliation Given. 83/08/15 KNIGHT, J NRC No Detailed Affiliation Given. 1p 20/69 361 24% Fiche 50-327,83/08/25,8310130394
- B310180625 Responds to FOIA request for records submitted by util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents Documents also available in PDR FELTON.J M Division of Rules and Records. 83/09/01. GARDE, B P COvernment Accountability Project 3pp 20839-112 24X Fiche 50-329,83/09/01,8310180625
- --B210280450 Forwards util B21005 three-part independent review programs consisting of blennial quality audits. INPD-type const evaluation & independent design verification of auxiliary feedwater sys Meeting scheduled for B21019 to discuss plan NOVAK, T M Assistant Director for Licensing B210/07 VOLLMER.R H Division of Engineering. 1p. 20839:124 24X Fichs 50-329.83/09/01.8310180625
- -8212300076 Documents conclusions reached at 821207 meeting in Betherda, MD rs GA implementation at facility Region 3 insp of diesel generator bldg & util decision to stop certain safety-related work being performed by Bechtel.

 HERNAM, R W Licensing Branch 4 82/12/21 NOVAK, T M Assistant Director for Licensing 3pp 20639 125, 24X
 Fiche 50-329,83/09/01.8310180625
- -8310180630 Forwards util revised plan for const completion Program includes measures to be taken as result of work slowdown & elements of GA implementation & third-party assessments requested by NRC W/o encl.

 NERNAN, R. Division of Licensing, 83/01/12 ADENSAM, E. NRC No. Detailed Affiliation Given 1p. 20839-128 24X

 Fiche, 50-329, 83/09/01, 8310180625

- --B310170034 Rev i to Quality Control Instruction 10 01, "(onst Implementation Overview Assessment " THDM950N.J C Stone & Webster Engineering Corp B3/06/2/ App 20837 134 24X Fiche 50-329, B3/09/01, B310180625
- --8310190036 Rev 0 to Verification Attribute Checklist P-2 20V, "Pipe Supports" BARANDH,8 W Stone & Webster Engineering Corp 83/07/21 (Opp 20839 140 24X Fiche 50-329,03/09/01.8310180625
- --831019003B Rev i to third-party const implementation overview approval KELLY.R B Stone & Webster Engineering Corp 83/08/05 5mp 20839 150 24X Fiche 50-329,83/09/01.8310180625
- --8310190042 Rev 1 to Quality Control Instruction 15 01, "Nonconformance Identification & Reporting " BARAMORE'S Stone & Webster Engineering Corp 83/08/05 5pp 20839 155 24X Fiche 50-329,83/09/01.8310180625
- --8310190047 Rev 1 for third-party const implementation overyiow to 0A plan
 plan
 BARAMORE,S., WALTERS,C., KELLY,R.D. Stone & Webster Engineering
 Corp. 83/08/05 4pp. 20839 160 24X Fiche 50-327,83/09/01,
- 8310030542 Memorializes 830902 telcon re rescheduling of Sept 1983 followup meeting on const completion dates Meeting will not be held in Sept HODD.D Licensing Branch 4 83/09/08 ADENSAM.E 6 Licensing Branch 4 ip 20602 353 24X Fiche 50-329,83/09/08,8310030502
- 8310190305 Responds to appeal re denial of FDIA request for documents on caseload forecast panel 830419 moeting on plant cunst All documents identified subj to request Appeal re 7 Novak draft lit to JW Cook moot
 DIRCKS.H J Office of the Executive Director for Operation:
 83/09/13 GARDL.B P Government Accountability Project 1p
 20840 328 24X Fiche 50-329,83/09/13,8310190305
- 9310240029 Confirms transmittal of controlled copies of PQCI &/m changes to B&W SM-1 70. Rev i to CNAA00079. C-2 10. Rev i 2 & MM-1 00. Rev 2 PUCCI. J A Consumers Power Co B3/09/15 BARANDW. 8 Stone & Webster Engineering Corp ip 20881 J60 24% Ficho 50-329. B3/09/15. B3102400079
- 8310240033 Confirms transmittal of computer printout containing info on MPOAD (balance of plant) inspector records Print covers all training, exams, performance demos & certifications BOTIMER.L A Consumers Power Co B3/09/20 BARANOW, B Stone & Webster Engineering Corp ip 20881 359 24% Fiche 50-329, 83/09/20,8310240033
- 8310240033 Confirms transmittal of controlled copies of POCI &/or changes to S&W control log for wk ending 830916,PF-1 10.
 Rev 4 to CNAA00043 & E-1 60.Rev & followup to inactive ltr
 PUCCI.J A Consumers Power Co. 83/09/20 BARANDW.S Stone &
 Webster Engineering Corp. ip 20881 347 24X Fiche 50-329,
 83/09/20,8310240050
- B310240050 Confirms transmittal of controlled copies of PGCI &/or changes to S&W control log for wk anding B30916, PF-1 10, Rev 4 to CNAA00043 & E-1 60, Rev 6 follower to inactive 1t; PUCCI, J A Consumers Power Co 83/09/20 BARANDW, B Stone & Webster Engineering Corp 1p 20881 347 24X Fiche 50-329, 83/09/20,8310240050
- 8310240063 Confirms transmittel of controlled copies of PGC1 &/or changes to S&W procedures PUCC1.J A Consumers Power Co 83/09/22 BARANDW.S Stone & Webster, Inc 1p 20881 346 24X Fiche 50-329.83/09/22.8310240063
- 8310040122 Requests quthorization for listed remedial soils work activities
 MODNEY, J. A. Consumers Power Co. 83/09/26 HARRISON, J. J. Region J. Office of Director. 1p. 20608-278 24X Fiche 50-324,83/09/26,8310040122
- 8310050294 Requests authorization to perform listed remedial soils work re-solid waste processing sys, Soldier Piles 1-30 MDONEY, J.A. Consumers Power Co. 83/09/28 MARRISON, J.J. Region G. Office of Director. 1p. 20628 351 24X Fiche 50-329, 83/09/28, 8310050296

- 8310050322 Discusses 830927 telcon re moving check valves & pipe supports in svc water bldg Work involves minor change to benchmark installation & can be completed as agreed MODNEY, J A Consumers Power Co 83/09/28 HARRISON, J Reni Office of Director 1p 20634 001 24X Fiche 50-329,83/09/24. Region 3.
- 8310070109 Notification of 831004-06 meetings w/util & Bechtel in Midland.NI to review structural adequacy of as-constructed MVAC sys MOOD D 8 Licensing Branch 4 83/09/28 ADENSAM.E & Licensin Branch 4 5pp 20671 310 24X Fiche 50-329.83/09/28 8310070109
- B310070142 Forwards response to 830526 request for addl 111fo 10 Question 130 28 for Vol I of seismic margin review rept entitled "Methodology & Criteria" COUK.J W Consumers Power Co 83/09/28 DENION.H R Office of Nuclear Reactor Regulation, Director 22pp 20659 038 24X Fiche 50-329.83/09/28,8310070142
- B30B300357 Board Notification 62-109A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway EISENHUT, D B Division of Licensing B3/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24x Fiche 50-000, B3/09/29, B30B300357
- 8310030341 Forwards evaluation of util proposal to have SAM perform third-party independent overview of const completion program Proposal approved MEPPLER.J G Region 3. Office of Director 83/09/27 COOK.J W Consumers Power Co 7pp 20632 337 24X Fiche 50-329,83/09/29,8310050341
- 8310110377 Summarizes 830926 telcon w/M Capicchioni of util re location of safety-related equipment in local break iones Applicant will submit info indicating no subjective adultion the submit info indicating no subjective adultion of the submit info indicating no subjective adultion of the submit info indicating no subjective adultion of the submit info indicating no subjective submit indication of the submit indicat
- E310050393 Issues authorization to proceed w/remedial soils work activities schoduled for Oct 1983

 HARRISON, J. Region 3, Office of Director 83/09/30 MILER, D.B. Consumers Power Co. 2pp. 206,32 163 24X Fiche 50-329,83/09/JO, 9310080393
- 8310120320 Responds to NRC concerns re equipment qualification & seismic margin review program, as discussed at 830208 meeting w/NRC w/NRC COOK.J W Consumers Power Co 83/09/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 24pp 20700 2/5 24X Fiche 50-329,83/09/30,8310120320
- 8310170624 Forwards resumes for insertion into GA program, App C for LEYIN.H A TERA Corp 83/09/30 KEPPLER, J 0 Region 3, Office of Director EIBENHULD G Division of Licensing CODK, J W Gonsumers Power Co 8pp 20782 072 24X Fiche 30-329,83/09/30,
- B310110635 Summary of B30913 meeting w/util & Bechtel re util compliance w/GDC 51 re fracture toughness characterization MILLER.M Licensing Branch 4 B3/10/04 Licensing Branch 4 20pp 20706 329 24X Fiche 50~329,83/10/04,831010635
- 8310170721 Discusses NRC concerns re delaus in establishing firm schedule for plant completion Estimate developed by NRC will be utilized for planning purposes if response not forthcoming NDVAK.T M Assistant Director for Licensing 83/10/04 CDOX.J Consumers Power Co 5pp 20/48 110 24x Fiche 50-329.83/10/04. 8310170721 COOK, J W
- 8310240136 Confirms transmittal of PGCI &/or changes to PGCI, including control logs for wks ending 830923 & 30

 PUCCI J A Consumers Power Co 83/10/04 BARANOW, 9 Stone & Webster, Inc 1p 20881 167 24X Fiche 50~329,83/10/04.8310240136
- B310120179 Provides info re licrosee 830928 decision to stop all "G" soil drilling & pile driving imposed as result of unknowingly drilling into structural concrete Info provided par board notification procedures WARNICK.R F. Region 3, Office of Director B3/10/05 EISENHUT, D G. Division of Licensing App 20695 326 24X Fiche 50-329,83/10/05,8310120179
- B310170048 Advises that Option 1 in H Levin 630815 ltm acceptable reselection of independent design & const verification program associated w/Baction 13 of Public Law 97-415 (Ford Amend) NOVAK, T M Assistant Director for Licensing B3/10/05 COOK, J W Consumers Power Co. Levin, H A TERA Corp 4pp 20798 024 24X Fiche 50-327,83/10/05.8310170068

- 8310170714 Documents 830927 telcon re removal of all soil & drift sets above Elevation 600 ft on north side of drift from KC2 to KC3 after drift invert is poured MILLER, D B Consumers Power Co 83/10/05 HARRISON, J J Region 3, Defice of Director ip 20779 230 24X Fiche 50-329,83/10/05, Region 3. 8310170714
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ABCO solenoid
- 8310130045 Notification of 831017-21 meetings w/util.Interlock.Inc & LLL in Midland.MI to audit control room & related documentation prior to implementation of human factors
- 8310140270 Authorizes critical work activities presently scheduled for Oct 1983, per 831005 request HARRISON, J. Regian 3, Office of Director 83/10/06 MILLER, D. B Consumers Power Co. 3pp. 20761 264 24X Fiche 50-329, 83/10/06, 8310140270
- --8310140273 Requests authority to proceed w/work authorization Procedures 752050001 & 752050002 for drilling, replacing & installing anodes MILLER.D B Consumbrs Power Co 83/10/05 HARRISON, J J Region 3. Office of Director 1p 20761 266 24X Fiche 50-327,83/10/06,
- B310200375 Forwards confirmatory order for mod of CPPR-B1 & CPPR-B2 due to continued problems in implementation of QA program DEYQUNG,R C Director's Office, Office of Inspection and Enforcement B3/10/06 CUDK, J W Consumers Power Co 4pp 20859 069 24X Fiche 50-329,83/10/06,8310200375
- --8310200380 Confirmatory order for mod of CPPR-81 & CPPR-82 due to continued problems in implementation of QA program DEVQUNO,R C Director's Office, Office of Inspection and Enforcement 83/10/04 Consumers Power Co 5pp 20839 073 24X Fiche 50-329,83/10/06,8310200375
- --8310200386 Decision DD-83-16 re UP Garde of Govt Accountability Project on behalf of Lone Tree Council 2 206 request that NRC take immediate action w/Midland project due to continued problems in implementation of GA program DEY/GUNO.R C Director's Office. Office of Inspection and Enforcement 83/10/04 23pp 20859 078 24X Fiche 50-329, 83/10/06. B310200375
- ---8310200392 Nobice of issuance of Director's Decision DD-B3-16 re 830Ai3 2 206 petition filed by BP Carde of Govt Accountability Project on behalf of Lone Tree Council re Midland project DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 33710/06 lp 20859 101 24% Fiche 50-329, 83/10/06, 8310200375
- 8310240084 Confirms transmittal of controlled copies of &/or changes to PGCI.as listed PUCI.JA Consumers Power Co 83/10/07 8ARANOM.8 Stone & Webster, Inc 1p 20881 004 PAX Fiche 50-329,83/10/07,8310240084
- 83i0170257 Requests that encl DBW Site Ofc Hanager Ltr 490 re torque wrench for replacement of CSA flow distributor bolts be forwarded to DBW HILLER, D B Consumers Power Co 83/10/10 HIERZER, O A Bechtel Corp 2pp 20787 087 24X Fiche 50-329,83/10/10,83i0170257
- B310240023 Confirms transmittal of three computer printouts containing info on MPGAD (balance of plant) inspector records Printout covers #11 training.exams.performance demos & certifications
 BOTIMER.L.A Consumers Power Co B3/10/10 BARANDH.S Btone & Hebster Engineering Corp ip 20880 341 24X Fiche 50-329. BOTIMER, L. A Gonsumers P. Webster Engineering Corp 83/10/10, 8310240023
- 8308300767 Board Notification 83-153 suppls info re R Landsman concerns on structural adequacy of diesel generator bldg NOVAK-T M Assistant Director for Licensing 83/10/11 Atomic Safety and Licensing Board Panel 3pp 20717
- --8310050059 Responds to 830815 memo re R Landsman concerns on inadequate diesel generator bldg Task group rept scheduled to be completed in Oct 1983 KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Post 830201). 83/09/23 VOLLMER, R.H. Division of Engineering 2pp. 20717 156 24X Fiche 50-329,83/10/11.8308300767

- --8310130269 Requests identity of any consultant or NRC employee sharing Landsman concern that diesel generator bldg inadequate Hatters to be discussed on 830822 VOLLMER, R NRC No Detailed Affiliation Given 83/08/15 KNIGHT, J NRC No Detailed Affiliation Given 1p 20717 158 24X Fiche 50-329,83/10/11,8308300767
- 8310170436 Authorizes listed remedial soils work activities scheduled for Oct 1983 HARRISON,J J. Region 3. Office of Director 83/10/11 Miller,D B Consumers Power Co 2pp 20779 222 24X Fiche 50-329,83/10/11,
- --8310170439 Requests remedial soils work authorization for emergency personnel locks
 MILLER, D.B. Consumers Power Co. 83/10/06 HARRISON, J. Region
 3. Office of Director 1p. 20779 2P4 24X Fiche 50-329, 83/10/11.
- 8310210134 Forwards summary of 830912-13 meetings w/DNL & Bechtel in Ann Arbor, HI re structural adequacy of diesel generator bldg HOOD, D 8 Licensing Branch 4 83/10/12 Licensing Branch 4 4pp 20884 096 24X Fishe 50-329, 83/10/12, 8310210134
- --8310070007 Trip rept of 830912-13 visit to Bechtel ofcs in Ann Arbor, MI to conduct audit of structural design calculations of diesel generator bldg Attendance list & chronological list of svents before & after NRC order modifying CPs encl ROMNEY, N D Structural & Opetechnical Engineering Branch 83709729 LEAR, Q E Structural & Geotechnical Engineering Branch 19pp 20884 100 24X Fiche 50-329,83/10/12.8310210134
- --83102:0142 "Midland Plants, Units 1 & 2 Diesel Generator Bidg. Executive Summaru "
 - Summary "

 * Bechtsl Corp 83/08/24 48pp 20884 119 24X
 Fichm 30-329,83/10/12:8310210134
- 8310200265 Forwards quality action requests on NIRs 002-003, describing actions taken to resolve deficiencies, per 831007 ltr. Review expected to be completed by 831216
 WELLS:R A Consumers Power Ca 83/10/13 BARANOW, S W Stone & Webster, Inc 18pp 20830.051 24% Fiche 50-329, 83/10/13, 8310200265
- 8308310050 Board Notification 83~160 provides info re 830812 failure of main crantshaft on one of three Transamerica Delaval energency diesel generators at Shoreham EISENHUT,D © Division of Licensing 83/10/14 PALLADINO,N J Commissionera 15pp 67056 070 24X Fichs 50-000,83/10/14,8308310050
- B310210027 Responds to B30712 request for add1 info re comparison of rebar stresses resulting from two 40-yr estimated settlement analyses performed on diese) generator bldg finite-element model ERHARDT.R J Comsumers Power Co B3/10/14 DENTON, N R Office of Nuclear Reactor Regulation, Director 5pp 20856 012 24X Fiche 50-329,83/10/14.8310210027
- 831025003B Discusses current const status of project, in lieu of submitting yellowbook update for Third Guarter 1983 On 831006; ASLB order to complete project received Completion schedule being developed Update submittal requested MILLER.D.B Consumers Power Co 83/10/14 HARTFIELD.R A NRC No Detailed Affiliation Given 1p 20894 169 24X Fiche 30-329,83/10/14,8310250058
- B310270066 Confirms transmittal of control copies of PGCI &/or changes as listed EWERT, G.F., PUCCI, J.A. Consumers Power Co. B3/10/17 BAHANDM.S Stone & Webster, Inc. ip. 20924 120 24% Fiche. 50-329, 83/10/17, B310270066
- 310310366 Requests authorization for listed remedial soils work QUANNELD L. Consumers Power Co. 83/10/17. HARRISON, J. J. Region 3. Office of Director 2pp 20761 112 24X Fiche 50-329, 83/10/17. 8310310366
- 8310240107 Informs that S&W meets independence & competence criteria for third-party reviewers & that proposed const overview adequate for assessment of const completion plan.in response to 830925 ltm.NRC orders encl. KEPPLER.J.O. Ragion 3, Office of Director. 83/10/18 RDMO.L.R Lone Tree Council. 2pp 20081.022 24% Fiche 50-327,83/10/18,8310240107
- B310250499 Authorizes listed remedial soils work activities for Oct 1983 HARRISON, J.J., Region 3, Office of Director. B3/10/19 HILLER, D.B. Consumers Power Co., Rpp 20902.086 24X Fiche: 50-329, 83/10/19, B310250499

- --8310250507 Requests authorization for listed remedial soils work GUAMME, D. L. Consumers Power Co. 83/10/17 HARRISON, J. Region 3. Office of Director 2pp 20902 088 24% Fiche 50-329, 83/10/19, 8310250499
- 831026033) Forwards procedures for performing calculations & technical studies, resolution of spatial sys interaction program/seismic postulated interactions & preparation of project technical repts

 ERMARDI, R. J. Consumers Power Co. 83/10/19 DENTON, H. R. Office of Nuclear Reaction Regulation, Director. 7pp. 20909-224 24X

 Fiche 50-329, 83/10/19, 8310260331
- --8310260335 Rev 1 to Procedure ATP-12-G. "Procedure for Performing Calculations & Jechnical Studies"
 * Mark Technologies Corp B3/08/26 13pp 20909 231 24X
 Fiche 50-329, 83/10/19,6310260331
- --8310260340 Rev 1 to Procedure 8301 WTP-4-Q, "Procedure for Resolutions of Spatial Sys Interaction Program/Seismic Postulated Interactions"

 DURAND: R J Mark Technologies Corp 83/08/26 7pp 20909 244 24X Fiche 50-329, 83/10/19, 8310260331
- --8310260344 Rev 1 to Procedure ATP-13-9, "Procedure for Preparation of Project Technical Repts" * Mart Technologies Corp 83/08/26 10pp 20909 251 24y Fiche 50-329,83/10/19,8310260331
- B310310369 Confirms transmittal of controlled GA program manual for Vol I, "Policies" & Vol II "Procedure for Design & Const " EWERT, G F Consumers Power Co B3/10/19 BARANDM, B Stone & Mebster, Inc 1p 20957 241 24X Fiche 50-327, 83/10/19,0310310367
- 8310310489 Summary of 830826 meeting w/B&W Owners Group to implementation of Generic Ltr 83-28 concerning defenses against ATWS & proposed ATWS tule for B&W plants List of attendees & visugiaphs enc!
 KADAMBI.P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 83/10/20, 8310310489
- 8308310032 Board Notification 83-155 forwards info re util 830928 stop work order on Q-soil drilling & pile driving after drilling into structural concrete
 NGVAK.T M Assistant Director for Licensing 83/10/24 Alomic Safety and Licensing 80ard Panel 3pp 20909 261 24X
 Fiche 50-329,83/10/24,8308310032
- --8310260285 Submits new info & math relevant to DM/OL proceeding re licensee 830928 decision to stop all 0-soil drilling & pile driving after unknowingly drilling into structural concrete Drilling procedures will be revised WARNICK.R F Region 3. Office of Director 83/10/05 EHERNRUT, 0 0 Division of Licensing 2pp 20909 264 24X Fiche 30-329,83/10/24,8308310032
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310190263 Summary of 831003 telcon meeting w/ptil & Energy Technology Engineering Ct: re resolution of SER Confirmatory Issue 4, "Independent Analysis of Piping Bys" MILLER, M A Licensing Branch 4 83/10/17 Licensing Branch 4 6pp 20843 257 24X Fiche 50-329,83/10/17,8310190263
- F Security, medical, emergency & fire protection plans
- 8310030601 Forwards comments on 830331 detailed control room design review final rept per Suppl 1 to NUREO-0737 Rept acceptable Meeting to discuss comments before 831017 preimplementation audit recommended ADENSAM.E Q Licensing Branch 4 83/09/19 COOK, J W Consumers Power Co 10pp 20607 343 24X Fiche 50-329/83/09/19.8310030601
- B310030606 Advises of compliance w/requirements of Suppl 1. Table 1. to NVREG-0737 rs habitability & location of smergency operations facility Approval of other features will be determined during post-implementation appraisal ADENSAM, E. G. Licensing Branch 4 B3/09/21 CODK, J. W. Consumers Power Co. 3pp. 20607 353 24X Fiche 50-327, 83/09/21, 8310030606
- B310110019 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 2068/ 357 24X Fiche 50-000,83/10/05, 8310110019

- --8310110024 Public version of Kev & to Emergency Plan Implementing Procedure EOF-7, "Offsite Duse Worksheet (Protective Actions) "W/830922 Itr & iccept form BRADLEY, J. Consumers Power to 83/07/18 Document Management Branch 2pp 20487-358 24X Fiche 50-000.83/10/05.8310110017
- 6310120464 Notification of 831026 meeting w/util & Engineering Planning & Mgt in Dethesda.MD to discuss proposal to resolve NRC concerns re safe shutdown capability in event of fire MILLER.M A Licensing Branch 4 83/10/06 ADENSMM.E G Licensing Branch 4 575 24X Fiche 50-329.83/10/06.8310120464
- 8310210030 EN-83-069 on 831026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "G" soils w/o prior NRC authorization KLINGLER.G Director's Office, Office of Inspection and Enforcement 83/10/20 ip 20855 344 24% Fiche 50-329,83/10/20.8310210030
- 8310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures FELTON, J N Division of Rules and Records 83/10/21 Document Management Branch lp 20928-337 2/4X Fiche 50-000,83/10/21, 8310270491
- --B310270510 Forwards public version of Nev 2 to controlled copyholder list of general ofc ctr/emorgency operations facility emergency implementing procedures & list depicting location of proprietary info in procedures CARLEY. A Consumers Power Co 83/09/15 Office of Nuclear Reacture Regulation. Director 7pp 20928 338 249 Fiche 50 000.03/10/21.83102/0491
- 83i0270590 Releases public version of revised general ofc control ctr/ emergency operations facility emrrgency implementing procedures FELTON.J N Division of Rules and Records 83/10/25 Document Management Branch ip 20944 322 24% Fichs 50-000.03/10/25, 8310270590
- --B310270593 Forwards public version of revised general ofc control cti/ emergency operations facility emergency implementing procedures including Procedure QEN-2 to emergency telephone numbers Receipt form encl CARLEY.A Consumers Power Co B3/10/13 Document Management Branch 4pp 20944 323 24X Fiche 50-000,83/10/25,8310270570
- --8310270397 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers * Consumers Power Co. 83/10/11 42pp 20944-327 24X Fiche 50-000.83/10/25.83102/0590
- G Adjudicatory correspondence
- 83:0180625 Responds to FOIA request for records submitted by util & reviewed during consideration of candidate companies of methodologies re const implementation overview Forwards documents Documents also available in PDR FELTON. J M Division of Rules and Records 83/09/01 GARUE, R P Government Accountability Project 3pp 20839 112 24% Fiche 50-329,83/09/01.8310180625
- --8310180628 Forwards util 820512 response to Interrogatory IV re Contention B on independent design audit * NRC - No Detailed Affiliation Given 82/10/01 NRC - No Detailed Affiliation Given 1p 20839 115 24X Fiche 90 329/83/09/01/8310180628
- --8310180627 Response to Interrogatory IV re Contention 8 on independent design audit

 * Consumers Power Co 82/05/12 Stamiris, 8 8pp 20339 116 24X Fishe 50-329-83/09/01.8310180685
- 8310050418 Forwards Chief Hearing Counsel 830819 memo to Dfc of Investigations requesting release of rept of investigation of alleged violation of ASIB 820430 order & preliminary notes.

 PATON: W D Hearing Branch 2 83/09/28 BECHHOEFER, C, COMAN: FP, HARBOUR, J Atomic Safety and Licensing Rgand Panel 3pp 20629 358 24X Fiche 50-329,83/09/28,8310050418
- 8310030465 Notice of JL Donnell 831015 deposition in Las Vegas NV, Cartificate of Svc encl WILLIAMS,F C Consumers Power Co WILLIAMS,F C Isham, Lincoln & Beale 83/09/29 3pp 20601 055 24X Fiche 50-329,83/09/29, 8310030465
- 8310030514 Order delineating schedules for proposed findings of fact & conclusions of law BECHHOEFER.C Atomic Safety and Licensing Board Panel 83/09/29 3pp 20601182 24X Fiche 50-329,83/09/29,8310030514

- 831004046/ Requests reply to encl B30921 ltr & advice as to whether L Clark will be produced for deposition on B31004 Svc list encl Related correspondence PROCTOR: S D Isham. Lincoln & Beale B3/09/29 KARR, J W Kerr & Lyons 3pp 20623 288 24X Fiche 50-329,83/09/29,8310040467
- 8310060269 Notice of correction to 830930 motion for reconsideration KARR.J W Government Accountability Project 83/10/03 1p 20646 154 244 Fiche 50-329, 83/10/03, 8310060269
- --8310060291 Errata to 830930 mution for reconsideration Certificate of Svc encl * Government Accountability Project 83/10/03 Atomic Safety and Liceusing Board Panel App 20646 155 24X Fiche 50-329,83/10/03,8310060269
- 8310110310 Application for deposition subpoens duces tecum to JL Donnell Certificate of Syc enc)
 WILLIAMS,F C Consumers Power Co WILLIAMS,F C Isham, Lincoln & Beale 83/10/03 Atomic Safety and Licensing Board Panel 9pp
 20665 346 24% Fiche 50-329,83/10/03,8310110310
- 8310120101 Mation to stay depositions of L Clark, T Devine, BP Garde & L Hallberg as directed in ASLB 830831 order Depositions should be stayed pending review of 830930 motion for reconsideration Certificate of Svc encl KARR, J W Government Accountability Project 83/10/03 Atomic Safety and Licensing Appeal Panel 6pp 20697 103 24X Fiche 50-329, 83/10/03, 8310120101
- 83101100/1 Second supplemental memorandum in support of intervenor Stamaris motion to litigate Dow Chemical Co issues against applicant Dow documents & complaints support litigation of issues raised in original motion Certificate of Svc encl DERNABEILL Government Accountability Project 83/10/05 Atomic Safety and Licensing Board Pauel 104pp 20647 174 24% Fiche 50-329.83/10/05.8310110071
- 8310130010 Forwards BB Hayes 830912 memo transmitting supplemental OPc of Investigations rept re alleged violation of ASLB order W/o rept HASSELL, DF Hearing Branch 1 WRIGHT, N A Hearing Branch 2 83/10/05 BECHHOEFER, C., COWAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel 5pp 20725 209 24X Fiche 50-329,83/10/05,8310130010
- 8310130233 Forwards one oversize revised settlement plot drawing referred to during Kane 830920 testimony, per ASLB 830921 request Drawing should be marked as Exhibit 25 Aperture card available in PDR HASSELL.D F Hearing Branch 1 WRIGHT, N A Hearing Branch 2 83/10/05 DECHROFFER.C., COWAN, F P. HARBOUR, J. Atomic Safety and Licensing Board Panel 3pp 20/19 i50 24X Fiche 50-329.83/10/05, 8310130233
- 8310110210 Memorandum & Order LBP-B3-64, denying Govt Accountability Project deponent motion for reconsideration of ASLB 830831 Order LBP-B3-53 & for stay of depositions, subj to noted conditions
 BECHHOEFER, C. Atomic Safety and Licensing Board Panel, 83/10/06 Government Accountability Project 11pp 20665 062 24X Fiche 30-329,83/10/06.8310110310
- 8310110320 Memorandum explaining reasons for denying Covt Accountability Project (GAP) 831003 motion for stay of ASLB 830831 order denying motion to quash subpoenas of GAP employees Stay of motion already pending before ASLB SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/10/06 3pp 80665-355 24X Fiche 50-329,83/10/06,8310110320
- 8310170383 Interrogatories re Ofc of Investigations rept Certificate of Svc enci BERNABELL Stamurus, B BERNABFI, L Government Accountability Project 83/10/11 Office of the Executive Legal Director 10pp 20785-019 24X Fiche 50-329,83/10/11,8310170383
- 8310170393 Request for production of documents Certificate of Svc encl BERNABEI.L Staminis B BERNABEI.L Government Accountability Project 89/10/11 Carolina Power & Light Co 10pp 20785 035 24X Fiche 50-329,83/10/11,8310170393
- 8310170427 Interrogatories directed to util Certificate of Svc encl BERNABELL Stamiris, B BERNABELL Government Accountability Project 83/10/11 Consumers Power Co 15pp 20779 203 24X Fiche 50-329, 83/10/11, 8310170027
- 8310170524 Request for production of documents Cartificate of Svc encl BERNABEI, L. Stemiris, B. BERNABEI, L. Government Accountability Project 83/10/11 Office of the Executive Legal Director 7pp 20784 207 24X Fiche 50-329,83/10/11.8310170524

- --8310260078 Transcript of JL Donnell 831015 deposition in Las Vegas, NV re alleged violation of ASLR order DONNELL, J. Science , Applications, Inc. 83/10/15 114pp 20733 351 24X Fiche 50-329,83/10/25,8310280073
- 8310280100 Order directing parties to be prepared to respond, during 831031 hearing session, to applicant 831025 motion for admission into evidence of JL Donnell deposition BECHHOEFER.C Atomic Safety and Licensing Board Panel 83/10/26 Intervenors Other Than Dow 1p 20935 205 24X Fiche 50-329,83/10/26,8310280100
- 8310280145 Motion to continue beginning date of hearings schedules for 831031 to 3 days after date Extended hearing necessary to allow time to receive responses to 831011 discovery requests W/Certificate of Svc BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/10/26 Atomic Safety and Licensing Board Panel Opp 20929 248 24X Fiche 50-329.83/10/26.83102800145
- 8310310390 Motion to stay ASLB 830831 & 1006 orders denying deponent motion for reconsideration of motion to quash subposens pending ASLAB decision on deponent 831021 appeal Certificate of Svc encl Related correspondence KARR.J W Government Accountability Project 83/10/26 Atomic Safety and Licensing Appeal Panel 5pp. 20960 011 24% Fiche 50-329.83/10/26,8310310390
- 8310310431 Order denying Govt Accountability Project 831081 motion to stay ASLB 830831 & 1006 orders denying motions to quash subposens & for reconsideration, respectively Motion filed late & fails to show stay warranced SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel B3/10/27 Government Accountability Project 6pp 20939 230 24X Fiche 50-329,83/10/27,8310310431
- 8310310211 Order granting 8 Stamiris 831026 motion to continue evidentiary hearings due to nonreceipt of responses to discovery request Three-day continuance granted BECHMOEFER.C Atomic Safety and Licensing Board Panel 83/10/28 STAMIRIS, 8 Stamiris, 8 2pp 20758 322 24X Fiche 50-329,83/10/28,8310310211

G Inspection reports. IE Bulletins & correspondence

- 8398300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Qualification Tests" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co of New York Inc. 117pp 20754 022 24X Fichs 50-000.83/09/26.8308300340
- B30B300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000,83/09/24,8308300342
- I308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-i Differential Relays " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308360345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related 8ys W/o 10CFR50 59 Evaluation " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp. 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310170558 Forwards I& Insp Repts 50-329/83-12 & 50-339/83-13 on 830523-27,0613-17 & 27-30 & 0701 & notice of violation MARNICK, R. F. Region S. Office of Director 83/09/29 COGK, J W Consumers Power Co 2pp 20780 213 24X Fiche 50-329,83/09/29,8310170558

om insp on 830523-27,0613-17 & 27-30 &

of Director 83/09/29 2pp. 9/29,8310170558

50-330/83-13 on 830523-27, toted failure to

Region 3, Office of Director 50-329, 83/09/29, 8310170558

- 8310180456 Expresses concern re discrepancies in const completion schedule Public metting warranted in light of varying completion dates

 QARDE.B P Government Accountability Project 83/10/13

 DENTON.H R Office of Nuclear Reactor Regulation Director (pp. 2080) 202 24x Fiche 50-327.83/10/13.83/10180456
- --B310180465 Affidavit of BP Garde re discrepancies in const completion dates Exhibits encl
 GARDE, B P Government Accountability Project 03/09/21 Atomic Safety and Licensing Board Pancl 2 bp 20801 310 247 Fiche 50-329, 83/10/13, 8310180456
- 8310190050 Errata to instructions for interrogatories & requests for production filed on 831011 Related correspondence
 BERNABELL Covernment Accountability Project 83/10/13
 PATON W D Hearing Branch 2 STEPTOC, P Isham Lincoln & Beele
 1p 20823 223 24X Fiche 50-329,83/10/13,8310190050
- 8310190048 Response to B Stamiris 831005 second supplemental memorandum supporting Downseves Stamiris Fails to show new & significant info justifying reopening record Certificate of Svc encl
 STEPTOE.P P Consumers Power Co S1CPTOE.P P Isham, Lincoln & Beale 83/10/14 Atomic Safety and Licensing Board Punch iSpp 20823 174 24% Fiche 50-329.83/10/14-8310190048
- 8310200254 Corrects typographical errors found in applicant response to second supplemental memorandum in support of intervenor B Stamiris motion to litigate Now issues STEPTOE.P P Isham, Lincoln & Beale STEPTOE.P P Consumers Power Co 83/10/17 BECH-IOFFER.C , HARBOUR.J , COMAN.F P Atomic Sofety and Licensing Board Panel ip 20830 102 24X Fiche 50-329.83/10/17.8310200274
- 8310240172 Forwards documents not served at 830728 & 0921 hearings Certificate of Syc encl Related correspondence LAUER, R J Isham, Lincoln & Beale LAUER, R J Consumers Power Co 83/10/18 Office of the Executive Legal Director 148pp 20879 240 24x Fiche 50-329, 83/10/18, 0310240172
- 8310250073 Advises of util intent to complete const despite Dow Chemical Co attempted withdrawal from contract to purchase steam generated by facility Unit I could be converted to electric unit Svc list enri BRUNNER.J E Consumers Power Co 83/10/18 BECHHOEFER.C, HARBOUR.J, COMAN, F.P. Atomic Safety and Licensing Board Panel 3pp 20874 112 24X Fiche 50-327,83/10/18.8310280073
- 8310250053 Notice of L. Clark.L. Hallberg.T. Devine & DP Garde B31110.22, 1201 & 15, respectively, depositions in Washington, DC & Hidland.HI Certificate of Svc encl PROCTOR:B D. Consumers Power Co. B3/10/19 App. 20094 105 1/4X Fiche 50-329,83/10/19,8310250003
- 8310250041 Objections to 831011 interrogatories & document production requests Certificate of Svc encl
 BRUNNER, J E Consumors Power Co 83/10/20 STAMIRIS, B Stamilis, B 5pp 20894 190 24% Fiche 50-329, 83/10/20, 8310250041
- 8310270257 Notice of appeal from ASLB orders granting discovery against Govt Accountability Project Certificate of Eyc encl KARRJ W Government Accountability Project 89/10/21 Ppp 20923 268 24X Fichs 50-327,83/10/21
- --8310270266 Memorandum in support of appeal from ABLB orders granting discovery against Govt Accountability Project Subposenas violate common law of privilege Util showed no compelling need for discovery KARR, J W Government Accountability Project 83/10/21 Atomic Safety and Licensing Appeal Panel 10pp 20923 270 24X Fiche 50-329, 83/10/21,83102/0257
- 8310270345 Motion to compel CPC responses to 831011 interrogatories b request for production or investigation of alleged violation Certificate of Ovc one! DERNABELL Stampris, B BERNABELL Government Accountability Project BJ/10/25 Atomic Safety and Licensing Board Panel /pp 20923 345 24X Fiche 50-329,83/10/25.8310270345
- 8310270367 Order extending time until 831130 for Commission to act to review Director's Decision DD-83-16
 CHILK, 8 J Office of the Secretary of the Commission 83/10/25
 Commissioners 1p 20923 293 24X Fiche 50-329,83/10/25,8310270367
- 8310280073 Motion for admission into evidence of transcript of UL Donnell 831015 deposition Certificate of Bvc Rncl WILLIAMS.F C Consumers Power Co. WILLIAMS.F C Isham, Lincoln & Beale 83/10/25 Atomic Safety and Licensing Board Panel 7pp R0933 342 24X Fiche 50-329,03/10/25.8310280073

DOCKETED ITEMS

- 8310170459 Forwards IE Mgt Meeting Repts 50-329/83-16 & 50-339/83-1/ on B30825 re 5&W Engineering const implementation everyzew program program LABNICKER F. Region 3. Defice of Director 83/09/30 COOK, J W
- HARNICK, R F Region 3, Office of Director 83/09/30 COOK, J W Consumers Power Co 2pp 20/84 052 E4X Fichs 50-329, 83/09/30, 8310170459
- --8310170464 IE Mgt Meeting Repts 50-329/83-16 & 50-330/83-17 on 8308.7;
 Major areas discussed util proposed third party overview &
 SYM Engineering const implementation overview program
 GARDNER: R N. HARRISON, J J Region 3, Office of Director
 83/09/29 6pp 20784 054 24% Fiche 50-329,83/09/30,8310170459
- --B3(0170466 Confirms commitments made to NRC at 830825 public meeting in Midland. M1 re third party const implementation overview program Viewgraphs encl WILD. P A Stone & Webster, Inc 83/08/30 KEPPLER, J G Region 3, Office of Director 20pp 20784 060 24X Fiche 50-329, 83/09/30, 8310170459
- 8310170513 Forwards IE Insp Repts 90-329/83-19 & 50-330/83-20 on 830821-0920 No noncompliance noted WARNICK, R F Region 3. Office of Director 83/10/03 COOK, J W Consumers Power Co 2pp 20/81 080 24X Fiche 90-329,83/10/03
- --8310170534 IE Insp Repts 50-329/83-17 & 50-330/83-20 on 830821-0920 No noncompliance noted Major areas inspected review of svc water pump structure instrumentation, remedial soils work activities & plant tours
 BURGESS, B. L. COOK, R. J., GARDNER, R. N. Hegion 3, Office of Director 83/09/30 App 20781 OB: 24X Fiche 50-329,83/10/03,8310170513
- --B310170538 Forwards Weekly Rept 52 of independent assessment of underpinning for period 830911-17 LUCK5.A S Stone & Webster, Inc B3/09/20 CODK,R NRC No Detailed Affiliation Given 14pp 20781 086 24X Fiche 50-329,83/10/03.83101/0513
- --8310170544 Forwards Weekly Rept 51 of independent assessment of underpinning for period 830903-10 LUCKS, A S Stone & Webster, Inc 83/09/14 COOK, R NRC No Detailed Affiliation Given 11pp 20781 100 24X Fiche 50-329,83/10/03,83101/0513
- --0310170549 Forwards Weekly Rept 50 of Independent assessment of underpinning for period 030Hz0-0703 LUCKS,A 0 Stone & Webster, Inc 03/09/00 COOK:R NRC - No Detailed Affiliation Given 18pp 20701 III 24X Fiche 50-329.83/10/03.83101/0513
- --8310170555 Forwards Weekly Ropt 49 of independent assessment of underpinning for period 830821-27 LUCKS.A 8 Blone & Webster, Inc. 83/08/31 CONK.R NRC No Detailed Affiliation Given 13pp 20781 126 24X Fiche 50-327.83/10/03.83101/0513
- --8310170559 Forwards Weekly Rept 48 of Independent assessment of underprinning for period 830814-20 LUCKS.A S Btone & Webster, Inc 83/08/24 CODK.R NRC No Detailed Affiliation Given 14pp 20781 137 24X Fiche 50-329,83710/3013
- --8310170560 Forwards Rept 14 of const implementation overview Por period 830912-16 BARANOW, B W Stone & Webster, Inc 83/09/19 KEPPLER, J Q Region 3, Office of Director 7pp 20781 153 24X Fiche 50-329,83/10/03,83101/0513
- --B310170564 Forwards Rept 13 of const implementation overview for period 830905-07
 BARANOW,S W Stone & Webster, Inc D3/09/12 KEPPLER,J G Region 3, Office of Director App 20781 160, 24X
 Fiche 50-329,83/10/03,8310170513.
- --8310170567 Forwards Rept 12 of const implementation overview for period 830829-0902 BARANDH,S W Stone & Webster, Inc 83/09/06 KEPPLER,J G Region 3, Office of Director 10pp 20/81 166 24X Ficho 50-329,83/10/03,83101/0513
- --8310170571 Forwards Rept 11 of const implementation overview for period 830822-26
 BARANGW:8 W Stone & Webster, Inc 83/08/29 KEPPLER, J G Region 3, Office of Director 5pp 20781 176 24X
 Fiche 50-329,83/10/03,83101/0513

- --8310170575 Forwards Rept 10 of const implementation overview for period 830815-19 BARANDM,5 W Stone & Wobster, Inc Region 3. Office of Director 7pp 20701 181 24X Fiche 50-329.83/10/03.83101/0513
- B3101705B3 Forwards IE Insp Repts 50-329/B3-15 & 50-330/B3-14 on 830721-0820 No noncompliance noted WARNICK,R F Region 3, Office of Director B3/10/03 COOK,J W Consumers Power Co Zpp 20/B0 23/ 24X Fiche 50-329, 83/10/03, B3101705B3
- --8310170591 1E Insp Repts 30-329/83-15 & 50-330/83-16 on 830721-0820 No noncompliance noted Major areas inspected remedial soils activities, team training, 85W hanger installations & 5ALP meeting BURGES9. B L , COUK.R J , GARDNER.R B Region 3. Office of Director 83/09/30 5pp 20780 239 24X Fiche 50-329.83/10/03, 8310170583
- --8310170598 Forwards Rept & of const implementation overview for period 030715-21 BARANOW.5 W Stone & Webster, Inc 83/07/25 KEPPLER.J G Region 3. Office of Director 5pp 20780 244 24X Fiche 50-327.83/10/03.8310170583
- --8310170602 Forwards Rept 7 of const implementation overview for period 830722-28

 BARANOM, 5 W Stone & Webster, Inc 83/08/01 KEPPLER, J G Repton 3. Office of Director 5pp 20780 249 24%

 Fiche 50-329,83/10/03,8310170583
- --8310170606 Forwards Rept B of const implementation overview for period 830729-0804 BARANOW,5 W Stone & Webster, Inc 83/08/08 KEPPLER,J G Region J. Office of Director App 20780 254 24X Fiche 50-329,83/10/03,8310170583
- --8310170610 Forwards Rept 9 of const implementation overview for period 830805-12 BARANOW, 8 W Stone & Webster, Inc. B3/08/15 KEPPLER, J G Region 3, Office of Director App. 20780 260 24X Fiche 50-329,83/10/03.83101/0583
- --8310170616 Forwards Weekly Rept 44 of independent assessment of underpinning for period 830717-23 LUCKS.A 8 Stone & Webster. Inc 83/07/28 COOK.R NRC - N Detailed Affiliation Given 16pp 20780 266 24X Fiche 30-329.83/10/03.8310170583
- --8310170622 Forwards Weekly Rept 45 of independent assessment of underpinning for period 830724-30 LUCKS.A B Stone & Webster, Inc. 83/08/04 CDGK.R NRC No Detailed Affiliation Given 17pp 20780 282 24X Ficha 50-329,83/10/03,8310170583
- --8310170627 Forwards Weekly Rept 44 of independent assessment of underpinning for period 830731-0806 LUCKS:A B Stone & Webster, Inc. 83/08/10 COOK:R NRC No Detailed Affiliation Given 11pp 20780 299 24X Ficha 50-329:83/10/03.8310170583
- --8310170634 Forwards Weekly Rept 47 of independent assessment of underpinning for period 830807-13 LUCKS,A S Stone & Webster, Inc 83/08/17 CDOK,R NRC No Detailed Affiliation Given 14pp 20780 310 24x Fichs 50-327,83/10/03.8310170583
- 8310240067 Confirms transmittal of computer printput containing info on MPGAD (balance of plant) inspector records BOTIMER, L. Commonwealth Edison Co. 83/10/03 BARANOW, B. Stone & Webster Engineering Corp. ip. 20881 344 24X Fiche 50-329, 83/10/03.8310240067
- 8310120317 Notification of 831011 significant licensee meeting w/util in Olon Ellyn, IL to review IC investigation rapt & to discuss alleged violation of ABLB order on remedial soils * Region 3. Office of Director 83/10/05 Region 3. Office of Director, ip 20700 307 24X Fiche 50-329, 83/10/05, 8310120317
- 8310120325 Confirms B31011 meeting in Region III ofc to discuss alleged violation of ASLB order re remedial soils areas & possible IE enforcement actions MARNICOLK F Region 3. Office of Director B3/10/05 COUK, J W Consumers Power Co ip 20/00 273 24% Fiche 50-327:83/10/05. 8310120325

- 8310130010 Forwards BB Hayes 830912 memo transmitting supplemental Off of Investigations mept re alleged violation of ASLN order W/o rept HASSELL.P & Hearing Branch 1 MRIGHLN A Hearing Branch 2 83/10/05 BECHNOEFER.C . COMAN.F P . HARBOUR.J Atomic Safety and Licensing Doard Panel 5pp 20/25 209 24X Fiche 50-329,83/10/05,83210/2014 83/10/05 BECHHOEFER, Licensing Board Panel 8310130010
- 8310210314 Forwards IE Audit Repts 50-329/83-20 & 50-330/83-21 on MARMICK, R F Region 3, Office of Director 83/10/05 COOK, J W Consumers Power Co 2pp 2085! 079 24% Fichs 50-329,83/10/05.
- ~-8310210319 IE Audit Repts 50-329/83-20 & 50-330/83-21 on 830914-15

 Major areas audited calculations of auxiliary bldg based un
 new soil modelus determined from underpinning pier load test
 results Related matts enct
 LANDSMAN.R B . HARRISON.J J Region 3. Office of Director
 83/10/04 50pp 20851 081 24X Fishe 50-329.83/10/05.8310210314
- 8310110191 EN-83-064 on 831006 notice of confirmatory order for mod of CPs issued Order requires const implementation overview program to provide reasonable assurance that facility can be completed in accordance w/regulatory requirements STONE. J. HEISHMAN.R Director's Office Office of Inspection and Enforcement 83/10/06 ip 20665-007 24X Fiche 50-329,83/10/06,000.000.000
- 8308300378 IE Info Notice 83-65, "Survei)lance of Flow in RTD Sypacs Loops Used in Westinghouse Plants " Svc list enc! JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83710/07 Consolidated Edison Co of Nev York, Inc 75pp 20827 213 24% Fiche 50-000.83/10/07.83083003/8
- B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison to of Ne York, Inc 79pp 20882 026 24% Fiche 30-000.83/10/07.8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Nortous Gases " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24% Fiche 50-000.63/10/11.8308300/b9
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list anci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24% Fithe 50-000.83/10/11.8308300761
- B310180265 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON.W L Region 3. Office of Director 83/10/14 CODK, J W Consumers Power Co 7pp 20807 043 24X Fithe 50-329,83/10/14.
- 8310310411 Forwards IE Insp Repts 50-329/83-17 & 50-330/83-18 on 830711-12 & 0816-19 No noncompliance noted WARNICK.R F Region 3, Office of Director 83/10/17 COOK, J W Consumers Power Cp 2pp 20959 304 24% Fiche 50-329,83/10/17,8310310411
- --8310310417 IE Insp Repts 50-329/83-17 & 50-330/83-18 on 830711-12 & 0816-19 No noncompliance noted Major areas inspected review of IBW GC insp & process for installation at ABME III Class 1 pipe SIMON.JA: SATHER,A: HARRISON.JJ Region 3. Office of Director 83/10/17 App 20959 306 24X Fichs 50-329.83/10/17.8310310411
- 8310210030 EN-83-059 on 831026.notice of violation t proposed imposition of civil genalty in amount of \$100.000 to be issued Action based on fireline relocation activities performed in "G" soils w/o prior NRC authorization KLINGLER, G. AXELRAD.J Director's Office, Office of Inspection and Enforcement 83/10/20 ip 20855 344 24X Fiche 50-329,83/10/20.8310210030
- 8310270165 Authorizes will to proceed w/Phase I activaties for const completion program in response to 831020 request Inspector seed as basis for granting authorization documented in NRC/Midland monthly inspector authorization documented in NRC/Midland monthly inspector 83/10/21 QUAMME.D L Consumers Power Co. 2pp. 20924 154 24X Fiche 50-329.83/10/21.

- --8310270171 Advises that status assessment & verification of complited work (Phase I of const completion program) initiated & requests NRC release to initiate Phase I Initial activities will be restricted to five modules

 QUAMMED L Consumers Power Co 83/10/20 HARRISON, J J Region

 3. Office of Director 4pp 20924 156 24X Fiche 50-329, 83/10/21.0310270165
- --8310270176 Provides overview of const completion program Modules (40, 102, 120, 410 & 800 requested for release BARANGE, S W. Stone & Mebster. Inc. 83/10/12 KEPPLER.J G Region 3. Office of Director 11pp 20924-160 24X Fiche 50-329, 83/10/21, 83102/0145
- 8310270341 Advises that review of util 830624 supplemental response to Item B & of 830208 notice of violation completed Response unacceptable Schedule for penetrant tests of welds must be submitted within 25 days of 1tr receipt MARNICKLR F Region 3. Office of Director 83/10/21 (COR. J W) Consumers Power Co 2pp 20923 352 EAX Fiche 50-329,83/10/21. Consumers Power Co 8310270341
- --B310270352 Forwards supplemental info re Item B of B3020B notice of violation, in response to NRC B30523 request Const training procedure revised to establish program assuring appropriate training in instablation procedures

 COUK. J W Consumers Power Co B3/06/24 KEPPLER. J G Region 3. Office of Directur 15pp 20/93 354 24% Fiche 50-329,83/10/21.
- R Periodic operating seports & related correspondence
- 8310210272 Forwards fifth monthly status rept for independent design & const verification program for Sept 1783
 LEVIN.H A TERA Corp 83/10/17 EISENHUT.D 9 Division of Licensing KEPPLER.J 9 Region 3. Office of Director COOK,J W Consumers fower Co 3pp 20848 220 24X Fiche 50-329.83/10/17.
- --8310210275 Fifth monthly status rept for independent design & court verification program for Sept 1983 DAUGHERTY, LEVIN, H.A., BECK, J.W. TERA Corp. 83/10/17 51pp. 20848 923 24X Fishe 50-329,83/10/17,831021027R
- B31031007B Forwards listed documents written or closed during Sept 1983, per condition of Memorandum & Order ALAB-106 & Amend 1 to CPPR-81 & CPPR-82 COOK, J W Consumers Power Co 83/10/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3800pp 20980 COI 24X Fiche 50-329, B3/10/25, B310310078
- S Reportable occurrences. LLRs & related correspondence
- 8307090259 Interim deficiency rept re do backed power supplies for JOGG interlock relays in auxiliary feedwater sys Schematic Diagram E-158(6) revised & issued as of 830727 to provide 120-voit ac power COOKLJ W Consumers fower CO B3/09/02 KEPPLER, J G Region 3. Office of Director App 20310 187 24X Fiche 50-329.83/09/07, 830800350
- 8310120446 PNO-111-83-092 on 831004.mort.jvana found in truck owned by carpenter employed by Bechtel Corp Individual fired by Bechtel & Left site No action planned by Region III State of MI will be notified HARRISON.J., WARNICK.R. Region 3. Office of Director 83/10/04 ip 20498 325 24X Fiche 50-329.83/10/04.8310120446
- 8310140090 PND-111-83-095 on 831005,8&W issued stop work order on STOIROGO PROFILE STOYS ON BESTOR SENER STOR WORK AFORT Class I piping hanger installation Stoy work applies to both small born & large bore piping & is based on deficiencies identified in hangers during Bechtel insp HARRISGNJ, GARDNER, R. Region 3. Office of Director BJ/16 1p 20767 059 24X Fiche. 50~329.83/10/06.8310140090 83/10/06
- 83i0170421 Final deficiency rept re underrated terminal strips on Limitorque valve operators Initially reported on 810213 New valve operators for use inside containment will be purchased w/o terminal blocks or space heaters COOK, J W Consumers Power Co 83/10/06 KEPPLER, J Q Region 3, Office of Director 25pp 20/83 323 24X Fiche, 50-329, 83/10/06, 8310170421
- 8310250101 Final rept re deficiencies in electrical components in that non-Class IE devices wired into Class Ik circuits Engineering production schedule activities will be revised by 831021 GOOK.J W Consumers Power Co 83/10/1 Office of Director 14pp 20896 172 8310250101 83/10/14 KEPPLER, J & Region 3, 96 172 24% Fiche 50-329,83/10/14,

- 8310270265 Interim deficiency ript re reactor bldq spray piping supports initially reported on 791221 Caused by conservative nodeling assumptions made in original water hammer analysis Next rept by 831230 CODK. J W Consumers Power to 83/10/21 KEPPLER, J G Region 3. Office of Director App 20943 247 E4X Fiche 50-349, 83/10/21. 83/10/20245
- T Hearing transcripts on non-antitrust matters
- B310280073 Motion for admission into evidence of transcript of JL Donnell B31015 deposition Certificate of Svc encl WILLIAMS.F.C. Consumers Power Co. WILLIAMS.F.C. Isham, Lincoln & Beale B3/10/25 Atomic Safety and Licensing Board Panel. 7pp 20933 342 24X Fithe 50-327.83/10/25,6310280073
- --8310280078 Transcript of JL Dunnell 831015 deposition in Las Vegas, NY re alleged violation of ASLB order DDNNELL, J L Consumers Power Co DDNNELL, J L Science Applications, Inc 83710715 114pp 20933 351 24X Fiche 50-329, 83/10/25, 8310280073
- DOCKET 50-330 MIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 83L0190311 FDIA request for documents re caseload forecast panel 830419 meeting on plant const GARDE.B P Government Accountability Project 83/0//11 Office of Administration 2pp 20840 329 24% Fiche 50-529,03/0//II, 8310190311
- 8310180618 FDIA request for documents submitted by util for consideration of condidate companies or methodologies to perform const implementation overview of const completion plan GARDE, B P Government Accountability Project 83/08/05 Office of Administration 2pp 20839 110 24X Fiche 50-329,83/08/05,8310180618
- 8310130390 FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLD proceedings GARDE, B P Government Accountability Project 83/08/08 Uffice of Administration 2pp 20769 352 24% Fiche 50-329,83/08/08, 8310130390
- 8310190316 Responds to FOIA request for documents re caseload forecast panel 830419 meeting on plant const Info partially withheld JW Cook draft ltr to TM Novak (ref FDIA Exemption 5) FELTON, J M Division of Rules and Recurds 83/08/09 GARDL, It ! Government Accountability Project Opp 21116 OO; 24X Fiche 50-329, 83/08/09, 8310190346
- 8310170300 Appeals denial of FOIA request for documents re-careload forecast panel 830419 meeting on plant const Denial effectively denied bulk of documents requested OARDE, B P Oovernment Accountability Project 83/08/10 DIRCKS, W J Office of the Executive Director for Operations 2pp 20840 326 24% Fiche 50-329.83/08/10.8310190300
- 8310130394 Responds to FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May bestimony of K Landsman in ASLB proceedings Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/08/25 GARDE, B P Government Accountability Project 2pp 20769 354 24X Fiche 50-329,83/08/25,8310130394
- --830B150338 Advises of assignment as member of task group to reevaluate structural design & const adequacy of plant diesel generator 51dg KVO P T Structural & Geotechnical Engineering Branch 83/08/08
 - NUBLE T Structural & Geotechnical Engineering Branch 83/08/08 TAN, C P Structural & Geotechnical Engineering Branch Ip 20769 362 24% Fiche 50-329, 83/08/25, 8310130394
- ---B308290029 Requests meeting on B30822 to discuss Landiman concirns that diesel generator bldg inadequate to return to svc based on inability to meet design requirements VOLLMER, R NRC No Detailed Affiliation Given 83/08/15 KNIGHT, J NRC No Detailed Affiliation Given ip 20769 361 24X Fiche 50-329,83/08/25,0310130394
- 8310180625 Responds to FOTA request for records submitted by util & reviewed during consideration of candidate Companies or methodologies re-const implementation overview Forwards documents Documents also available in PDR FELTON, J.M. Division of Rules and Records 83/09/01 CARDE, B.P. Gavernment Accountability Project 3pp 20839-112 24X Fiche 50-329,83/09/01,8310180625

- --8210280450 Forwards util 821005 three-part independent review program, consisting of biennial quality audits.INPO-type const evaluation & independent design verification of auxiliary feedwater sys Meeting scheduled for 841019 to discuss plan NOVAK.T M Assistant Director for Licensing 82/10/07 VOLLMER.R H Division of Englineering 1p 20839 124 24X Fiche 50-329.83/09/01.8310180625
- --8212300076 Documents conclusions reached at 821207 meeting in Bethesda, MD re GA implementation at facility Region 3 insp of diese) generator bldg & util decision to stop certain safety-related work being performed by Bechtel
 HERNAN, R W Licensing Branch 4 82/12/21 NOVAK, T M Assistant
 Director for Licensing 3pp 20837 125 24%
 Fiche 50-329,83/09/01.8310180625
- --8310180630 Forwards util revised plan for const completion Program includes measures to be taken as result of work sloudoun & elements of OA implementation & third-party assessments requested by NRC M/o encl
 HERNAN, R Division of Licensing 83/01/12 ADENSAM, E NRC No Detailed Affiliation Given ip 20839 128 24X
 Fiche 50-329,83/09/01,8310180625
- --8310190034 Rev I to Quality Control Instruction 10 01, "Const Implementation Dverview Assessment " THDMFSON.J C Stone & Webster Engineering Corp 83/06/2/ 6pp 20839 134 24X Fiche 50-329,83/09/01,8310180625
- --8310190036 Rev 0 to Verification Attribute Checklist P-2 20V, "Pipe Supports " BARANOM: 8 W Stone & Webster Engineering Corp 83/07/21 10pp 20839 140 24X Fiche 50-329,83/09/01,8310180625
- --8310190038 Rev 1 to third-party const implementation overview approval KELLY,R B Stone & Webster Engineering Corp 83/08/05 Spp 20839 150 24X Fiche 50-329,83/09/01.8310180625
- --8310170042 Rev I to Quality Control Instruction 15 01, "Nonconformance Identification & Reporting " BARAMORE, S Stone & Webster Engineering Corp 83/08/05 5pp 20837 155 24X Fiche 50-329,83/09/01,8310180625
- --8310190047 Rev I for third-party const implementation overview re GA plan BARAHDRE, S , WALTERS, C , KELLY, R B Stone & Webster Engineering Corp 83/08/05 App 20839 160 24X Fiche 50-329,83/09/01,
- 8310030542 Memorializes 830702 telcon re rescheduling of Sept 1983 followup moeting on const completion dates Meeting will not be held in Sept HOOD, D Licensing Branch 4 B3/09/08 ADENSAM, E C Licensing Branch 4 Ip 20602 353 24X Fiche 50-329, 83/09/08, 8310030542
- 83i0190305 Responds to appeal re denial of FDIA request for documents on caseload forecast panel 830417 meeting on plant const All documents identified subj to request Appeal re T Novak draft ltr to JW Conk moot
 DIRCKS,W J Office of the Executive Director for Operations 83/09/13 0ARDE.B P Government Accountability Project 1p 20840 328 24X Fiche 50-329.83/09/13.8310190305
- B310240029 Confirms transmittal of controlled copies of PQCI &/or changes to S&W SM-1 70.Rev 1 to CNA00079.C-2 10.Rev 12 & MM-1 00.Rev 2
 HM-1 00.Rev 2
 PUCCI.J A Consumers Power Co B3/09/15 DARANOH.S Stone & Hebster Engineering Corp 1p 20881 360 24% Fiche 50-329, B3/09/15.B3J0240079
- 8310240131 Confirms transmittal of listed revs to PGCI EWERT.G F Consumers Power Co 83/09/19 BARANOW.S Stone & Webster, Inc ip 20881 165 24X Fiche 50-329.83/09/19.8310240131
- 8310240033 Confirms transmittal of computer grantout containing info on MPGAD (balance of plant) inspector records Print covers all training, exams, performance demos & certifications BOTIMER: A Consumers Power Co 83/09/20 BARANOW, S. Stone & Webster Engineering Corp ip 20881 359 24X Fiche 50-329, 83/09/20,8310240033
- 8310240050 Confirms transmittal of controlled copies of PGC1 &/or changes to 5kM control log for wk ending B30716.PF-1 10.

 Rev 4 to CNAA00043 & E-1 60.Rev & followup to inactive ltr

 PUCCI.J A Consumers Power Co 83/07/20 BARANOM, S Stone & Webster Engineering Corp 19 20881 347 24% Fiche 50-329, 83/09/20, 8310240050
- 8310240063 Confirms transmittal of controlled copies of PQCI &/or changes to B&W procedures PUCCI.J A Consumers Power Cn 83/09/22 BARANOW,8 Stone & Webster, Inc Jp 20881 346 B4X Fiche 50-329,83/09/22,8310240063

- 8310040122 Requests authorization for listed remedial soils work activitles MODNEY, J. A. Consumers Power Co. 83/09/26 HARRISON, J.J. Region 3, Office of Director 1p. 20608-278 - 24X Fiche 50-329, 83/09/26,
- 8310050294 Requests authorization to perform listed remedial soils work re-solld waste processing sys. Solddier Filos 1-30 MOONEY, J.A. Consumers Power Co. 83/09/28 HARRISON, J.J. Region 9, Office of Director 1p 20628 351 24X Fiche 50-329,83/09/28.
- 8310050322 Discusses 830927 telcon re moving theck valves & pipe supports in svc water bldg Work involves minor change to benchmark installation & can be completed as agreed HOONEY, JA Consumers Power Co 83/09/28 HARRISON, J J Regi Office of Director 1p 20434 001 24X Fiche 50-329,83/09/28. HOONEY, J A Consum Office of Director 8310050322 Region &
- 8310070109 Notification of 831004-06 meetings w/util & Bechtel in Midland, All to review structural adequacy of as-constructed
- HVAC sys HOOD,D 8 Licensing Branch 4 83/09/28 ADENSAM,E G Licensin Branch 4 5pp 20671 310 24X Fiche 50-329,83/09/28,8310070109
- 8310070142 Forwards response to 830526 request for add1 info re Question 130 28 for Vol I of seismic margin review rept entitled "Methodology & Crateria" CODK, J W Consumers Power Co 83/09/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 20659 038 24X Fiche 50-329,83/09/28,8310070142
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Camyon i & 2.Fermi 2 & Callaway EISENHUT.D & Division of Licensing 83/09/29 PALLADINO.N J Commissioners 3pp 20432 001 24x Fiche 50-000.83/09/29.
- 8310050341 Forwards evaluation of util proposal to have 95W perform third-party independent overview of const completion program Proposal approved KEPPLER, J G Region 3. Office of Director 83/09/27 COCK, J H Consumers Fower Co 7pp 20632 357 24X Fiche 50-329, 83/09/29, 8310050341
- 8310110377 Bummarizes 830926 telcon w/M Capicchioni of util re location of safety-related equipment in local break zones Applicant will submit info indicating no subj equipment at location MILLER.MA Licensing Branch 4 83/09/27 Licensing Branch 4 3pp 20713 228 24X Fiche 50-329.63/09/29.8310110377
- 9310050393 Issues authorization to proceed w/remedial soils work activities scheduled for Dct 1983 HARRISON,J J Region 3, Office of Director 83/09/30 MILLER,D B Consumers Power Co 2pp 20632 163 24X Fiche 50-329,83/09/30, 8310050393
- 310120320 Responds to NRC concerns re equipment qualification & seismic margin review program.as discussed at 830208 meeting w/NRC W/NNC COOK, J W Consumers Fower Co B3/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 20700 275. 24X Fiche 50-329,83/09/30,8310120320
- 8310170624 Forwards resumes for insertion into GA program, App C for LEVIN.H A TERA Corp 83/09/30 KEPPLER.J G Region 3, Office of Director EISENRUT.D G Division of Licensing COOK.J W Consumers Power Co 8pp 20782 072 24X Fiche 50-329,83/09/30,
- 33:0110635 Summary of 830913 meeting w/util & Bechtel re util compliance w/8DC 51 re fracture toughness characterization MILLER.M Licensing Branch 4 83/10/04 Licensing Branch 4 20pp 20706 327 24% Fiche 50-329, 83/10/04
- 8310170721 Discusses NRC concerns re delays in establishing firm schedule for plant completion Estimate developed by NRC will be utilized for planning purposes if response not forthcoming NOVAK.T M Assistant Director for Licensing 83/10/04 COOK.J Consumers Pawer Co 5pp 20798 HO 24X Fiche 50-329.83/10/04. 8310170721
- 8310240136 Confirms transmittal of PQCI &/or changes to PQCI, including control legs for wks ending 830923 & 30
 PUCCI.J A Consumers Power Co 83/10/04 BARANDW, 8 Stone & Webster, Inc. Ip 2088; 169 24X Fiche 50-329, 83/10/04, 8310240136

- 8310120179 Provides info re licensee 830928 decision to stop all "G" sicularly crovides into re licensee 830928 decision to stop all "G" soil drilling & pile driving imposed as result of unknowingly drilling into structural concrete Info provided per board notification procedures WARNICK, R. F. Region 3. Office of Director 83/10/05 EISENMULD & Division of Licensing 2pp 20695 326 24X Fiche 50-329,83/10/05,83/0120179
- B31017006B Advises that Option I in H Levin B30815 ltr acceptable re selection of independent design & const verification program associated w/Section 13 of Public Law 97-415 (Ford Amend) NOVAK,T M Assistant Director for Licensing B3710705 CUUK,J & Consumers Power Co LEVIN.H A TERA Corp 4pp 20798 024 24X Fiche 30-329,83710705.831017006B
- 8310170714 Documents 830927 telcon re removal of all soil & dilit sets above Elevation 600 ft on north side of drift from KC2 to KC3 after drift invert is poured MILLER,D B Consumers Power Co 83/10/05 HARRISON,J J Region 3, Office of Director ip 20779 P30 24X Fiche 50-329, 83/10/05, 8310170714
- 8308300771 Board Notification 8J-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid yalves VAIVES CISENRUT, D. 0 Division of Licensing 83/10/06 PALLADING, N. J. Commissioners Slpp 20818 001 24X Fiche 90-000, 83/10/06, 8308300771
- 8310130045 Notification of 831017-21 meetings w/util.Interlock,ing & LLL in Midland.MI to audit control room & related documentation prior to implementation of human factors related mods MILLER, M.A. Licensing Branch 4 83/10/06 ADENSAM, F.G. Licenc Branch 4 5pp 20776 237 24X Fiche 50-329, 83/10/06, 8310130045
- 8310140270 Authorizes critical work activities presently scheduled for Oct 1783.per 831005 request HARRISON, J. Region 3, Office of Director 83/10/06 MILLER, D. D. Consumers Power Co. 3pp. 20/61 264 24% Fiche 50-327, 83/10/06, 8310140270
- --8310140273 Requests authority to proceed w/work authorization Procedures 757050001 & 752050002 for drilling, replacing & installing anodes MILLER, D.B. Consumers Power Co. 83/10/05 HARRISON, J.J. Region 3, Office of Director 1p. 20761 266 24X Fiche 50-329,83/10/05, 8310140270
- B310200375 Forwards confirmatory order for mod of CPPR-B1 & CPPR-B2 dut to continued problems in implementation of GA program DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B3710/06 CDDK, J W Consumers Pawer Co 4pp 20859 069 24X Fiche 50-329.83/10/06.8310200375
- --8310200380 Confirmatory order for mod of CPPR-81 & CPPR-82 due to continued grublems in implementation of QA program DEYOUNG, R C Director's Office, Diffice of Inspection and Enforcement 83/10/06 Consumers Power Co 5pp 20859 073 24X Fiche 50-329,83/10/06.8310200375
- --8310200386 Decision DD-83-16 re BP Garde of Govt Accountability Project on behalf of Lone Tree Council 2 206 request that NRC take immediate action w/Midland project due to continued problems immediate action winitians project due to continues proof in implementation of QA program DEVOUNG.R C Director's Office, Office of Inspection and Enforcement 03/10/06 23pp 20059 078 24X Fiche 50-329.83/10/06.8310200375
- --B310200392 Notice of issuance of Director's Decision DD-B3-16 re 83061's 2 206 petition filed by BP Garde of Govt Accountability Project on behalf of Lone Tree Council re Midland project DEYOUNG, R C Director's Dffice, Dffice of Inspection and Enforcement 83/10/06 ip 20859 101 24X Fiche 50-324, 83/10/06,8310200375
- 8310240084 Confirms transmittal of controlled copies of M/or changes to PGCI.as listed PUCCI.J A Consumers Power Co 89/10/07 BARANOW, 8 Stone & Webster, Inc. ip 20881 004 24X Fiche 50-329, 83/10/07, 0310240094
- 8310170257 Requests that encl B&W Site Dfc Manager Ltr 490 re tanque wrench for replacement of CSA flow distributor bolts be forwarded to B&W MILLER, D B Consumers Power Co 83/10/10 HIERZER, G A Brittel Corp 2pp 20787 087 24X Fiche 50-389, 83/10/10, 6310170257

- B310240023 Confirms transmittal of three computer printouts containing info on MPGAD (balance of plant) inspector records Printout covers all training, exams, performance demos & Stone &
 - Certifications
 BOTIMER: A Consumers Power Co 83/10/10 BARANOW, 8 Sto
 Mebster Engineering Corp 1p 20880 341 24% Fiche 50-3P9,
 B3/10/10.83102400P3
- 8308300767 Board Notification 83-153 suppls info re R Landsman concerns on structural adequacy of diesel generator bldg MOVAK.T M Assistant Director for Licensing 83/10/11 Atomic Safety and Licensing Board Panel 3pp 20717
- --8310050057 Responds to 830815 memo re R Landsman concerns on inadequate diesel generator bldg Task group rept scheduled to be completed in Oct 1983 KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Post 830201) 83/09/23 VOLLMER, R.H. Division of Engineering 2pp. 20717 156 24% Fiche 50-329.83/10/11.8308300767
- --8310130267 Requests identity of any consultant or NRC employee shalling Landsman concern that diesel generator bldg inadequate Matters to be discussed on 830822 VOLLMFR, R NRC No Detailed Affiliation Given 83/08/15 KNIGHT, J NRC No Detailed Affiliation Given 1p 20717 158 24X Fiche 50-329,83/10/11.8308300767
- 8310170436 Authorizes listed remodial soils work activities scheduled Hornical National State of Director 83/10/11 MILLEM, D R Consumers Power Co. 2pp. 20779-222 24% Fiche 50-329, 83/10/11.
- --8310170439 Requests remedial soils work authorization for emergency gersonnel locks
 HTLLEH.D B Consumers Power Co 83/10/04 HARKISON, J J Region
 3. Office of Director 1p 20779 224 24X Fiche 50-329,83/10/11,8310170434
- 8310210134 Forwards summary of 830912-13 meetings w/BNL & Bochtel in Ann Arbor, MI re structural adequacy of diesel generator bldg 61dg HGQD. D & Licensing Branch 4 83/10/12 Licensing Branch 4 4ap 20884 096 24X Fiche 50-329,83/10/12,8310210134
- --83100/0007 Trip rept of 830912-13 visit to Bechtel ofcs in Ann Arbot, MI to conduct audit of structural design calculations of diesel generator bldg Attendance list & chronological list of events before & after NRC order modifying CPs encl ROMNEY, N D Structural & Gootechnical Engineering Branch 83/09/29 LEAR, & E Structural & Gootechnical Engineering Branch 19pp 20884 100 24X Fiche 50-329,83/10/12,8310210134
- --B3(0210142 "Midland Plants.Un)ts | & 2 Diesel Generator Bldg. Executive Summary "
 * Bet-tel Corp 83/08/24 48pp 20084 119 24X
 Fiche 50-329,83/10/12.8310210134
- 8310200265 Forwards quality action requests on NIRs 002-005, describing actions taken to resolve deficiencies, per 83100/ ltm Review expected to be completed by 831216
 WELLS, RA Consumers Power Co 83/10/13 DARANOW, S W Stnnr & Webster, Inc 10pp 20830 051 24X Fiche 50-327,83/10/13, B3102002A5
- 8308310050 Board Notification 83-160 provides info re 830812 failule of main crankshaft on one of three Transamerica Dalaval emergency diseal generators at Bhoreham EISENHUT.D G Division of Licensing 83/10/14 PALLADINO,N J Commissioners 15pp 67056,070 24X Fiche 50-000,83/10/14,8308310050
- 8310210027 Responds to 830912 request for addl info re comparison of rebar stresses resulting from two 40-yr estimated settlement analyses performed on diesel generator bldg finite-element Defice of
- mage: ESHARDT.R J Consumers Power Co 83/10/14 DENTON,H R U Nuclear Reactor Regulation, Director 5pp 20856 012 24X Fiche 50-327,83/10/14,8310210027
- 831025005B Discusses current const status of project, in lieu of submitting yellowbook update for Third Guarter 1983 On 831004, AbLB order to complete project received Completion schedule being developed Update submittal requested MILLER, D. B. Consumers Power Co. 83/10/14 HARTFIELD, R.A. NRC No Detailed Affiliation Given 1p. 20894, 149, 24x Fiche 50-329, 83/10/14, 8310250058,

- 8310270064 Confirms transmittal of control copies of POCI &/or changes as listed

 EWERT, G F , PUCCI, J A Consumers Pawer Co 83/10/17 BARANOW, 8

 Stone & Webster, Inc 1p 20924 120 24x Fiche 50-329,83/10/17,8310270066
- 8310310366 Requests authorization for listed remedial soils work QUAMME.D.L. Consumers Power Co. 83/10/17 HARRISON,J.J. Regio Office of Director. 2pp. 20961 112 247 Fiche 50-329.83/10/17,
- 8310240107 Informs that S&W meets independence & competence criteria for third-party reviewers & that proposed const overview adequate for assessment of const completion plan, in response to 830725 ltr NRC orders encl KEPPLER, J. G. Region 3, Office of Director 83/10/18 ROMO,L R Lone Tree Council 2pp 20881 022 24% Fiche 50-329,83/10/18, 8310240107
- 8310250499 Authorizes listed remedial soils work activities for Oct 1983
 HARRISON, J. J. Region 3, Office of Director 83/10/19 MILLER, D.B. Consumers Power Co. 2pp. 20902 0B6 24% Fiche 50-329, 83/10/19, 8310250499
- --8310250907 Requests authorization for listed remedial soils work QUAMME.D t. Consumers Power Co. 83/10/17 HARRISDN.J J. Re. 3. Office of Director 2pp 20902 088 24% Fiche 50-327, 83/10/19,8310250499 1/ HARRISDN, J J Region 24% Fiche 50-329,
- 8310260331 Forwards procedures for performing calculations & technical studies, resolution of spatial sys interaction program/seismic postulated interactions & preparation of project technical repts
 ERHARDI, R. J. Consumers Power Co. 83/10/19 DENTON, H. R. Office of Nuclear Reaction Regulation, Director. 7pp. 20909-224. 24X
 Fiche 50-329,83/10/19,8310260331
- --8310260335 Rev i to Procedure ATP-12-0, "Procedure for Performing Calculations & Technical Studies"
 * Mark Technologies Corp 83/08/26 13pp 20909 231 24X
 Fiche: 50-329, 83/10/19, 831026031
- --8310260340 Rev 1 to Procedure 8301 WTP-4-6, "Procedure for Resolution of Spatial Bys Interaction Program/Scismic Postulated Interactions" DURAND.R J Mark Technologies Corp 83/08/26 7pp 20909 244 24X Fiche 50-329,83/10/19,8310260331
- ~~8310260344 Rev 1 to Procedure ATP-13-0. "Procedure for Preparation of Project Technical Repts " * Mark Technologies Corp 83/08/26 10pp 20909 251 24X Fiche 50-329, 83/10/19,8310260331
- B310310369 Confirms transmittal of controlled QA program manual for Vol I, "Policies" & Vol II "Procedure for Design & Const "
 EWERT, Q F Consumers Power Co B3/10/19 BARANDW, S Btone & Webster, Inc 1p 20959 241, 24X Fiche 50-329, 83/10/19, 8310310367
- 8308310032 Board Notification 83-155 forwards info re util 830928 stop work order on G-soil drilling & pile driving after drilling into structural concrete NOVAK.T M Assistant Director for Licensing 83/10/24 Safety and Licensing 80ard Panel 3pp 20907 26; 24X Fiche 50-329.83/10/24.8308310032
- --8310260289 Submits new info & math relevant to OM/OL proceeding re licensee 830928 decision to stop all G-soil drilling & pile driving after unknowingly drilling into structural concrete Drilling procedures will be revised WARNICK, R. F. Region 3, Office of Director 83/10/05 EISENHUT, D. Q. Division of Licensing 2pp 20909 264 24X Fiche 50-329,83/10/24,8308310032
- E NRC Bafety Evaluation Report (BER), suppls & correspondence
- 8310190263 Bummary of B31003 te)con meeting w/util & Energy Tochnology Engineering Ctr re resolution of SER Confirmatory Issue 4.
 "Independent Analysis of Piping Bys"
 MILLER,M A Licensing Dranch 4 B3/10/17 Licensing Branch 4 bp 20843:257 24X Fichs 50-029,83/10/17,8310190263
- F Security, medical, emergency & fire protection plans
- 8310030601 Forwards comments on 830331 detailed control room design review final rept per Suppl 1 to NURES-0737 Rept acceptable Meeting to discuss comments before 831017 preimplementation audit recommended ADENSAM, E Q mmenowa G Licensing Branch 4 83/09/17 COOK, J W Gonsumers 10pp. 20607 343 24X Fiche 50-327,83/09/19,8310030601

- 8310030606 Advises of compliance w/requirements of Suppl 1. Table 1, to NUREO-0737 re habitability & location of emergency operations facility Approval of other features will be determined during post-implementation appraisal ADENSAM.E G Licensing Branch 4 83/09/21 COUK.J W Consumers Power Co 3pp 20607 353 24X Fiche 50-329.83/09/21.8310030606
- 8310110019 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Aules and Records 83/10/05 Decument Management Branch ip 20687 357 24X Fiche 50 000.83/10/05, 8310110019
- --8310110024 Public version of Rev & to Emergency Plan Implementing Procedure EDF-7, "Offsite Dose Worksheet (Protective Actions) "WB30922 ltr & receipt form BRADLEY, J Consumers Power Co 83/07/18 Document Management Branch 2pp 20687 358 24% Fiche 50-000,83/10/05,8310110019
- 8310120464 Notification of 831026 meeting w/util & Engineering Planning & Mgt in Bethesda, MD to discuss proposal to resolve NRC concerns re safe shutdown capability in event of fire MILLER, M A Licensing Branch 4 83/10/06 ADEMSAME 0 Licensing Branch 4 5pp 20751 275 24X Fichs 50-329, 83/10/06, 8310120464
- 8310210030 EN-83-069 on 831026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "0" soils w/o prior NRC authorization KLINOLER. © Director's Office, Office of Inspection and Enforcement 83/10/20 ip 20855 344 24% Fiche 50-329, 83/10/20, 8310210030
- 8310270491 Releases public version of revised controlled copyholder list of emergency plan implementing procedures FELTON. J M Division of Rules and Records 83/10/21 Document Management Branch 1p 20928 337 24X Fiche 50-000.83/10/21.
- --8310270510 Forwards public version of Rev 2 to controlled copyholder list of general ofc str/emergency operations facility amergency implementing procedures & list depicting location of proprietary info in procedures CARLEY, A Consumers Power Co 83/09/15 Office of Nuclear Reactor Regulation, Director 7pp 20928 338 24X Fiche 50-000.83/10/21,8310270491
- B310270590 Releases public version of revised general ofc control ctr/ Emergency operations facility emergency implementing procedures FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20944 322 24X Fiche 50-000, B3/10/25, 8310270590
- --8310270593 Forwards public version of revised general ofc control ct₁/emergency operations facility emergency implementing procedures including Procedure GEN-2 re emergency telephone numbers Receipt form encl
 CARLEY, A Consumers Power Co 83/10/13 Document Management
 Branch 4pp. 20944 323 24X Fiche 50-000,83/10/25.8310270590
- --8310270597 Public version of revised general ofc control ctr/emergency operations facility emergency implementing procedures, including Procedure GEN-2 re emergency telephone numbers * Consumers Fower Co. 83/10/11 42pp 20944 327 24% Fiche 50-000.83/10/25.8310270590
- G Adjudicatory correspondence
- 8310180625 Responds to FOIA request Por records submitted by util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents. Documents also available in PDR FELTON, J M Division of Rules and Records 83/09/01 CARDE, B P Government Accountability Project 3pp 20839 112 24X Fichs 50-329,83/09/01.8310180625
- -8310180628 Forwards util 820512 response to Interrogatory IV re Contention 8 on independent design audit * NRC - No Detailed Affiliation Given 82/10/01 NRC - No Detailed Affiliation Given p 20839 115 24X Fiche 50-329.83/09/01.8310180625
- 8310180629 Response to Interrogatory IV re Contention 8 on independent design audit

 * Consumers Power Co 82/05/12 Stamiris. 8 8pp 20837 116 24X Fichs 50-329.83/09/01.8310180625

- 8310050418 Forwards Chief Hearing Counsel 830819 memo to Ofc of Investigations requesting release of rept of investigation of alleged violation of ASLB 820430 order & preliminary notes
 PATON, H D Hearing Branch 2 83/09/28 BECHHOEFER. C. COWAN, F / HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 20629 358 24% Fiche 50-329, 83/09/28, 8310050418
- 8310030465 Notice of JL Donnell 831015 deposition in Las Vegas, NV Certificate of Svc encl WILLIAMS,F C Consumers Power Co WILLIAMS,F C Isham, Lincoln & Beale 83/09/29 Jpp 20401 055 24X Fiche 50-329,83/09/29, 8310030465
- 8310030514 Order delineating schedules for proposed findings of fact & conclusions of law BECHHOEFER.C Atomic Sefety and Licensing Board Panel 83/09/29 3pp 20601 182 24X Fiche 50-329,83/09/29.8310030514
- 8310040467 Requests reply to encl 830921 ltr & advice as to whether L Clark will be produced for deposition on 831004 Svc list encl Related correspondence PROCTOR S D Isham. Lincoln & Beale 83/09/29 KARR, J W Karr & Lyons 3pp 20623 288 24X Fiche 50-329,83/09/29,8310040467
- B310060269 Notice of correction to B30930 motion for reconsideration KARR:J W Government Accountability Project B3/10/03 ip 20646 154 24X Fiche 50-329, B3/10/03, B310060269
- --8310060291 Errate to 830730 motion for reconsideration Certificate of Svc enc1 # Government Accountability Project 83/10/03 Atomic Safety and Licensing Board Panel App 20646 155 24X Fiche 50-329,83/10/03.8310060269
- 8310110310 Application for deposition subpoena duces tecum to JL Donnell Certificate of Svc encl WILLIAMS,F C Consumers Power Co WILLIAMS,F C Isham, Lincoln & Seale 83/10/03 Atomic Safety and Licensing Board Panel 7pp 2065 346 24% Fichs 50-329.83/10/03.8310110310
- B310120101 Motion to stay depositions of L Clark, T Devine, BP Garde & L Hallberg as directed in ABLB 830B31 order Depositions should be stayed pending review of 830930 motion for reconsideration Gertificate of Svc encl
 KARR, J W Government Accountability Project B3/10/03 Atomic Bafety and Licensing Appeal Panel App 20697 103 24X
 Fiche 50-329,83/10/03,8310120101
- B310110071 Becond supplemental memorandum in support of intervenor Staminis motion to litigate Dow Chemical Co issues against applicant Dow Occuments & complaints support litigation of issues raised in original motion Certificate of Svc encl BERNABEI-L Government Accountability Project 83/10/05 Atomic Safety and Licensing Board Panel 104pp 20647 174 24X Fiche 50-329.83/10/05,8310110071
- 8310130010 Forwards BB Hayes 830912 memo transmitting supplemental Ofc of Investigations rept re allaged violation of ABLR order W/o rept
 HASSELL, D F Hearing Branch 1 WRIGHI, N A Hearing Branch 2
 83/10/05 BECHHOEFER.C., COMAN, F P., HARBOUR, J. Atomic Safety and Licensing Board Panel 5pp 20725 209 24X Fiche 30-329,83/10/05,83(010010)
- 8310130233 Forwards one oversize revised settlement plot drawing referred to during Kane 830720 testimony, per ASLB 830721 request Drawing should be marked as Exhibit 25 Aperture card available in PDR HABBELL.D F Hearing Branch 1 WRIGHT.N A Hearing Branch 2 83/10/05. BECHHOEFER.C., COWAN.F P. HARBOUR.J Atomic Safety and Licensing Board Panel 3pp 20717 150 24X Fiche 50-327,83/10/05.8310130233
- 8310110210 Memorandum & Order LBP-83-64, denying Govt Accountability Project deponent motion for reconsideration of ASLB 830831 Order LBP-83-53 & for stay of depositions, subj to noted conditions BECHMOEFER, C. Atomic Safety and Licensing Board Panel 83/10/06 Government Accountability Project 11pp 20665 062 24X Fiche 50-329.83/10/06.8310110210
- 8310110320 Memorandum explaining reasons for denying Govt Accountability Project (GAP) 831003 motion for stay of ASLB 830831 order denying motion to quash subpoenas of GAP employees Stay of motion already pending before ASLB SHDEMAKER.C. J. Atomic Safety and Licensing Appeal Panel 83/10/06 3pp 20465-355, 24X Fiche 50-329.83/10/06.8310110320

- 8310170383 Interrogatories re Ofc of Investigations rept Certificate
- of SVC encl
 BERNABEI.L Stamiris, D BERNABEI.L Government Accountability
 Project 83/10/11 Office of the Executive Legal Director 10p
 20785 019 24X Fiche 50-329,83/10/11,8310170383
- B310170393 Request for production of documents Certificate of Svc encl BERNABET.L Stamiris B BERNABET.L Government Accountability Project B3/10/11 Carolina Power & Light Co 10pp 20785 035 24% Fiche 50-329,63/10/11,8310170393
- 8310170427 Interrogatories directed to util Certificate of Svc encl BERNABEILL Stamiris B BERNABEILL Government Accountability Project 83/10/11 Consumers Power Co 15pp 20779 203 24X Fiche 50-329,83/10/11,8310170427
- 8310170524 Request for production of documents Certificate of 6vc encl BERNADEJ.L Stamfris, B BERNADEJ.L Government Accountability Project 83/10/11, Offica of the Executive Legal Director 7pp 20784-209 24X Fiche 50-329.83/10/11.8310170524
- 8310180456 Expresses concern re discrepancies in const completion schedule Public meeting warrantud in light of varying completion dates

 GARDE-B P Government Accountability Project 83/10/13

 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 20801 202 24X Fiche 50-327.83/10/13.8310180455
- --9310180465 Affidayit of BP Garde re discrepancies in const completion dates Exhibits oncl GARDE, BP Government Accountability Project 83/09/21 Atomic Safety and Licensing Board Panel 23pp 20801 310 24X Fiche 80-329,83/10/13,8310180456
- 8310170050 Errata to instructions for interrogatories & requests for production filed on 831011 Related correspondence
 BERNABEILL Government Accountability Project 83/10/13
 PATON-W D Hearing Branch 2 STEPTOE.P Isham, Lincoln & Beale 1p 20823 223 24X Fiche 50-329,83/10/13,8310170050
- 831019004B Response to B Stamiris 831005 second supplemental memorandum supporting Dow issues Stamiris fails to show new & significant info justifying reopening record Certificate of Svc encl STEPTOE, PP Consumers Power Co STEPTOE, PP Isham, Lincoln & Beale 83/10/14 Atomic Safety and Licensing Board Panel 13pp 20823.174 24X Fiche 50-329,83/10/14,831019004B
- 8310200254 Corrects typographical errors found in applicant response to second supplemental memorandum in support of intervenor II Staniris motion to litigate Dow issues STEPTGE, P P Isham, Lincoln & Beale STEPTGE, P P Consumers Power Go 83/10/17 BECHHOEFER C , HARBOUR, J , COMAN, F P Atomic Safety and Litensing Board Fanel ip 20830 102 24X Fichs 50-329,83/10/17,8310200254
- B310240172 Forwards documents not served at B30728 & 0921 hearings Certificate of Svc encl Related correspondence LAUER:R J Isham. Lincoln & Beale LAUER:R J Consumers Power Co B3/10/18 Office of the Executive Legal Director 148pp 20879 240 24X Fiche 50-329.83/10/18.8310240172
- 8310250073 Advises of util intent to complete const despite Dow Chemical Co attempted withdrawal from contract to purchase steam generated by facility Unit I could be converted to alectric unit Svc list encl
 BRUNNER.J E Consumers Power Co. 83/10/18 BECHNOEFER.C, HARBOUR, J. COMAN.F.P Atomic Bafety and Licensing Board Panel 3pp 20894 112 24X Fiche 50-329.83/10/18.8310250073
- 8310250053 Notice of L Clark, L Hallberg, T Devine & BP Gards 831110, 22, 1201 & 15, respectively, depositions in Washington, DC & Hidland, MI Certificate of Syc encl PROCTOR, S D Consumers Power Co 83/10/19 App 20894 105 24X Fiche 50-329, 83/10/19, 8310250053
- B310250041 Objections to B31011 interrogatories & document production requests Certificate of Svc encl BRUNNER, J E Consumers Power Co B3/10/20 BTAMIRIB, B Stamiris, B 5pp 20894 190 24X Fiche 50-329,83/10/20,8310250041
- B310270257 Notice of appeal from ABLB orders granting discovery against Govt Accountability Project Certificate of Svc encl KARR.J W Government Accountability Project B3/10/21. 2pp 20923 268 24X Fiche 50-329,83/10/21.8310270257

- --8310270266 Hemorandum in support of appeal from ASL8 orders granting discovery against Govt Accountability Project Bubgoenas violate common law of privilege Util showed no compelling need for discovery KARR, J W Government Accountability Project 83/10/21 Atomic Safety and Licensing Appeal Panel 10pp 20923 270 24X Fiche 50-329.83/10/21.8310270257
- 8310270345 Motion to compel CPC responses to 831011 interrogatories to request for production re investigation of alleged violation Certificate of Svc encl
 BERNABELL Stamiris, II BERNABELL Government Accountability
 Project 83/10/25 Atomic Safety and Licensing Board Panel 7pp
 20923 345 24% Fiche 50-327,83/10/25,8310270345
- 8310270367 Order extending time until 831130 for Commission to act to review Director's Decision DD-83-16
 CHILK, B. J. Office of the Secretary of the Commission 83/10/25.
 Commissioners 1p 20923 293 24X Fiche 50-329.83/10/25.
 B310270367
- 8310280073 Motion for admission into evidence of transcript of JL Donnell 831015 deposition Certificate of Svc encl WILLIAMB.F C Consumers Pauer Co WILLIAMB.F C Isham. Lincoln & Beale 83/10/25 Atomic Safety and Licensing Board Panel 9pp 20933 342 24X Fiche 50-329.83/10/25.8310280073
- --8310280078 Transcript of JL Donnell B31015 deposition in Las Vegas,NV re alleged violation of A8LB order DONNELL,J L Consumers Power Co DONNELL,J L Science Applications, Inc 83/10/15 114pp 20933 351 24X Fiche 50-329,83/10/25,8310280073
- 8310280100 Order directing parties to be prepared to respond, during 831031 hearing session, to applicant 831025 motion for admission into evidence of JL Donnell deposition.

 BECHHOEFER, C. Atomic Safety and Licensing Board Panel 83/10/26 Intervenors Other Than Dow Ip 20935 205 24X Fiche 50-329, 63/10/26-8310280100
- 8310280145 Motion to continue beginning date of hearings scheduled for 831031 to 3 days after data Extended hearing necessary to allow time to receive responses to 831011 discovery requests W/Certificate of Svc BERNABEI.L Staminis, B BERNABEI.L Government Accountability Project 83/10/26 Atomic Safety and Licensing Board Panel App 20929 248 24% Fiche 50-329, 83/10/26, 8310280145.
- 8310310390 Motion to stay ABLB 830831 & 1006 orders denying deponent motion for reconsideration of motion to quash subposses pending ASLAB decision on deponent 831021 appeal Certificate of Svc encl Related correspondence KARR.J W Government Accountability Project 83/10/26 Atomic Bafety and Liconsing Appeal Panel 5pp 20760 011 24X Fiche 50-327.83/10/26.8310310370
- 8310310431 Order denying Oovt Accountability Project 831021 motion to stay ASLB 830831 & 1006 orders denying motions to quash subpoemas & for reconsideration, respectively Motion filed late & fails to show stay warranted SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/10/27 Government Accountability Project 6pp 20759 230 24% Fiche 50-329,83/10/27.8310310431
- 8310310211 Order granting B Stamiris 831026 motion to continue evidentiary hearings due to nonreceipt of responses to discovery request Three-day continuance granted BECHHOEFER.C Atomic Safety and Licensing Board Panel 83/10/28 STAMIRIS.B Stamiris.B 2pp 20958 322 24X Fiche 50-329,83/10/28,8310310211
- G Inspection reports: IE Bullstins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24% Fiche 50-000,83/09/26,8308300340.
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000.83/09/26.8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 1188p 20778: 001. 24X Fiche 50-000; 83/09/26, 8308300345

- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Bafety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
 - JORDAN, E L Division of Emergency Preparedness & Engineering
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/29 Consolidated Edison Co of New
 York, Inc 115pp 20716 324 24% Fiche 50-000, 83/09/29, 8308300349
- 8310170558 Forwards IE Insp Repts 50-329/83-12 & 50-330/83-13 on 830523-27.0613-17 & 27-30 & 0701 & notice of violation WARNICK.R F Region 3, Office of Director 83/09/29 CDOK.J W Consumers Power Co 2pp 20780 213 24X Fiche 50-329.83/09/29.8310170558
- --8310170562 Notice of violation from insp on 830523-27,0613-17 & 27-30 & 0701 HARNICK, R F Region 3, Office of Director 83/09/27 2pp 20780 215 24% Fiche 50-329,83/09/29,8310170598
- --B310170572 IE Insp Repts 50-329/83-12 & 50-330/83-13 on 830523-27, 0613-17 & 27-30 & 0701 Nuncompliance noted failure to follow hanger & field weld procedures SIMON, J A. SATHER, A. HARRISON, J J. Region 3, Office of Director 83/09/29 8pp 20780 217 24X Fiche 50-329,83/09/29,8310170558
- 8310170459 Forwards IE Mgt Meeting Repts 50-329/83-16 & 50-330/83-17 on 830825 re S&W Engineering const implementation overview program MARNICK, R F Region 3, Office of Director 83/09/30 COOK, J W Consumers Power Co 2pp 20784 052 24X Fiche 50-329,83/09/30, 8310170459
- --8310170464 IE Mgt Heeting Repts 50-329/83-16 & 50-330/83-17 on 830825
 Hajor areas discussed util proposed third party overview &
 SAW Engineering const implementation overview program
 GARDNER,R N , HARRISON, J , Region 3, Office of Birector
 83/09/29 6pp 20784 054 24X Fiche 50-329,83/09/30,8310170459
- --8310170466 Confirms commitments made to NRC at 830825 public meeting in Midland.HI re third party const implementation overview program Vizugraphs encl HILD.P A Stone & Hebster, Inc. 83/08/30 KEPPLER.J © Region 3, Office of Director 20pp 20784 060 24X Fiche 50-329,83/09/30,8310170459
- 8310170513 Forwards IE Insp Repts 50-329/B3-19 & 80-330/83-20 on 830821-0920 No noncompliance noted MARNICK,R F Region 3, Office of Director 83/10/03 CDGK,J W Consumers Power Co 2pp 20761 080 24X Fiche 50-329, 83/10/03, 8310170513
- --8310170534 IE Insp Repts 30-327/83-19 & 50-330/83-20 on 830821-0920 No noncompliance noted Major areas inspected review of svc water pump structure instrumentation, remedial soils work activities & plant tours
 BURGERS, B L . COOK, R J . GARDNER, R N Region 3, Office of Director 83/09/30 4pp 20781 082 24X Fiche 50-329,83/10/03,8310170513
- --8310170538 Forwards Weekly Rept 52 of Independent assessment of underpinning for period 830911-17 LUCKSA.8. Stone & Webster. Inc 83/09/20 COOK.R NRC No Detailed Affiliation Given 14pp Fiche 50-329.83/10/03.8310170513
- --83i0170544 Forwards Weekly Rept 51 of Independent assessment of underpinning for period 830903-10 LUCKB:A 8 Btone & Webster. Inc 83/09/14 COOK.R NRC No Detailed Affiliation Given lipp 20781 100 24X Fiche 50-329.83/10/03.8310170513
- -8310170549 Forwards Weekly Rept 50 of independent assessment of underpinning for period 830828-0903 LUCKS,A S Stone & Hebster, Inc 83/09/08 COOK,R NRC - No Detailed Affiliation Given 15pp 20781 111 24X Fiche 50-329,83/10/03,8310170513
- -8310170555 Forwards Weekly Rept 47 of independent assessment of underpinning for period 830821-27 LUCKS:A 8, Stone & Webster, Inc 83/08/31 CODK,R NRC No Detailed Affiliation Given 13pp 20781 126 24X Fiche 50-329,83/10/03,8310170513
- -8310170559 Forwards Heakly Rept 48 of independent assessment of underpinning for period 830614-20, LUCKS, A S. Btons & Hebster, Inc. 83/08/24 CUOK,R NRC No Detailed Affiliation Given. 14pp. 80781 139 24X Fichs 50-329,83/10/03,8310170513

- --8310170560 Forwards Rept 14 of const implementation overview for period B30912-16 BARANDW, B W Stone & Webster, Inc 83/09/19 KEPPLER, J G Region 3, Office of Director 7pp 20781 133 24X Fiche 50-329,83/10/03,8310170513
- --8310170564 Forwards Rept 13 of const implementation overview for period 830705-07
 BARANCH.S W Stone & Webster, Inc 83/07/12 KEPPLER, J G Region 3, Office of Director App 20781 160 24X
 Fiche 50-329,83/10/03.8310170513
- --8310170567 Forwards Rept 12 of const implementation overview for period 830827-0702
 BARANDM.5 W Stone & Webster, Inc 83/07/06 KEPPLER, J G Region 3, Office of Director 10pp 20781 166 24X
 Fiche 50-327.83/10/03.8310170513
- --8310170571 Forwards Rept 11 of const implementation overview for period 830822-26
 8ARANOW,8 W Stone & Webster, Inc 83/08/27 KEPPLER,J G Region 3, Office of Director 5pp 20781 176 24X
 Fichm 50-329,83/10/03,8310170513
- --8310170575 Forwards Rept 10 of const implementation overview for period 830815-19
 BARANDM.S W Bione & Webster. Inc 83/08/22 KEPPLER, J G Region 3. Office of Director 7pp 20781 181 24X Fiche 50-329.83/10/03.8310170513
- 8310170583 Forwards IE Insp Repts 50-329/83-15 & 50-330/83-16 on 830721-0820 No noncompliance noted WARNICK,R F Region 3, Office of Director 83/10/03 COUK,J & Consumers Power Co 2pp 20780 237 24X Fiche 50-329,83/10/03,8310170583
- --B310170591 IE Insp Repts 50-329/83-15 & 50-330/83-16 on B30721-0820 Na noncompliance noted Major areas inspected remedial soils activities, team training, D&W hanger installations & SALP meeting BURGESS, B. L., CODK, R. J., GARDNER, R. D. Region G. Office of Director B3/09/30 5pp 20780 239 24X Fiche 90-329, 03/10/03, 8310170583
- --B310170598 Forwards Rept 6 of const implementation overview for period 830715-21
 BARANOM,S W Stone & Webster, Inc 83/07/25 KEPPLER,J O Region 3, Office of Director 5pp 20780 244 24X
 Fiche 50-329,83/10/03.8310170583
- --9310170402 Forwards Rept 7 of const implementation overview for period 830722-28.

 BARANOW, 8 W Stone & Webster, Inc 83/08/01, KEPPLER, J G Region 3, Office of Director 5pp 20780 247, 24X Fiche 50-329, 83/10/03,8310170563
- --B310170404 Forwards Rept B of const implementation overview for period 830729-0804 BARANDH.B W Stone & Webster, Inc B3/08/08 KEPPLER, J O Region 3, Office of Director App 20780 254 24X Fiche 50-329, 83/10/03, 8310170583
- --8310170610 Forwards Rept 9 of const implementation overview for period 830805-12
 BARANOH, S W Stone & Webster, Inc 83/08/15 KEPPLER, J G Region 3, Office of Director App 20780 260 24X Fiche 50-329, 83/10/03, 8310170583
- --8310170616 Forwards Weekly Rept 44 of independent assessment of underpinning for period 830717-23 LUCKS.A S. Stone & Webster, Inc 83/07/28 CODK.R NRC - Na Detailed Affiliation Given 16pp, 20780 266 24X Fiche: 50-329, 83/10/03, 8310170583
- --8310170622 Forwards Waskly Rept 45 of independent assessment of underpinning for period 830724-30

 LUCKS, A B Stone & Webster, Inc 83/08/04 CDDK, R NRC No Detailed Affiliation Given 17pp 20780 282 24X

 Fiche 50-329, 83/10/03, 8310170583
- --8310170627 Forwards Weekly Rept 46 of independent assessment of underpinning for period 830731-0806 LUCKB.A.S. Stone & Webster, Inc. 83/08/10, CODK.R. NRC No Detailed Apriliation Given iipp 20780 299 24X Fiche.50-329,83/10/03,8310170583
- --8310170634 Forwards Heekly Rept 47 of independent assessment of underpinning for period 830807-13 LUCKS:A 8 Stone & Webster, Inc 83/08/17 CODK.R. NRC No Detailed Affiliation Given 14pp 20780 310 24X Fichs 50-329,83/10/03,8310170583

- B310240067 Confirms transmittal of computer printout containing info on MPGAD (balance of plant) inspector records BOTIMER.L Commonwealth Edison Co 83/10/03 BARANDW.S Stone & Webstor Engineering Corp 1p 20881 344 24% Fiche 50-329, 83/10/03.8310240067
- 8310120317 Notification of 831011 significant licensee meeting w/util in Glen Ellyn, IL to review IE investigation rept & to discuss alleged violation of ABLD order on remedial soils * Region 3, Office of Director 83/10/05 Ragion 3, Office of Director 19 20700 307 24X Fiche 50-329,83/10/05,8310120317
- 8310120325 Confirms 831011 meeting in Region III ofc to discuss alleged violation of ASLB order re-remedial soils areas & possible IE enforcement actions MARNICK.R F. Region 3, Office of Director 83/10/05 COOK, J W. Consumers Power Co. 1p. 20700 273 24X Fiche 50-329,83/10/05,
- 8310130010 Forwards BB Hages 830912 memo transmitting supplemental Ofc of Investigations rept re alleged violation of ASLB order W/w rept HASSELL,D F Hearing Branch 1 83/10/05 BECHHOEFER,C Atomic Safety and Licensing Board Panel 5pp 20725 209 24X Fiche.50-327,83/10/05,8310130010
- 8310210316 Forwards IE Audit Repts 50-329/83-20 & 50-330/83-21 on 830914-15 MARNICK,R F Region 3, Office of Director 83/10/05 CODK, J W Consumers Power Co 2pp 20851 079 24X Fiche 50-329,83/10/05,83/10/34A
- --8310210319 JE Audit Repts 50-329/83-20 & 50-330/83-21 on 830914-15
 Major areas audited calculations of auxiliary bldg based on
 new soil modulus determined from underpinning pier load test
 results Related matls encl
 LANDSMAN,R B , HARRISON,J J Region 3, Office of Director
 83/10/04 50pp 20851 081 24X Fiche 50-329,83/10/05,8310210316
- 0310110191 EN-83-064 on 831006, notice of confirmatory order for mod of CPs issued Order requires const implementation overview program to provide reasonable assurance that facility can be completed in accordance w/regulatory requirements STONE.J. HEISHMAN.R Director's Office. Office of Inspection and Enforcement 83/10/06 ip 20665 007 24X Fiche 50-329,03/10/06,0310110191
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Lopps Used in Westinghouse Plants " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison Co of New York. Inc 74pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000, 83/10/07. 8308300752
- 8308300757 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases." Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York. Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000.83/10/11,8308300761
- 8310180265 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl. Updates will be provided every 6 months AXELSON.W L Region 3, Office of Director 83/10/14 COOK, J W Consumers Power Co 7pp 20807 043 24X Fiche, 50-329, 83/10/14, 02010160245
- 8310310411 Forwards IE Insp Repts 50-329/83-17 & 50-330/83-18 on 830711-12 & 0816-19 No noncompliance noted HARNICK:R F Region 3, Office of Director 83/10/17, COOK, J H Consumers Power Co Rpp 20759-304, 24X Fiche 50-329,83/10/17, 8310310411
- ~~8310310417 IE Insp Repts 50~329/83-17 & 50~330/83-18 on 830711-12 & OB16-17 No noncompliance noted Major eress inspected review of B&W QC insp & process for installation at ABME III Class i pipe SIMON.J A , SATHER, A , HARRISON, J. J. Region 3, Office of Director 83/10/17 4pp 20957 306 24X Fiche 50-327, 83/10/17, 8310310411

- 8310210030 EN-83-049 on 831026, notice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "G" soils w/o prior NRC authorization KLINGLER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/20 ip 20835 344 24X Fiche 50-329,83/10/20, 83/10/210030
- 8310270165 Authorizes util to proceed w/Phase I activities for const completion program in response to 831020 request Insp results used as basis for granting authorization documented in NRC/Midland monthly insp repts HARRISON J J Region 3, Office of Director 83/10/21 GUAMME, D L Consumers Power Co 2pp 20724 154 24X Fiche 50-327,83/10/21, 8310270165
- ---8310270171 Advises that status assessment & verification of completed work (Phase I of const completion program) initiated & requests NRC release to initiate Phase I Initial activities will be restricted to five modules

 GUAMME.D L. Consumers Power Co 83/10/20 HARRIBON, J J Region
 3, Office of Director App 20924 156 24X Fiche 50-329,
 83/10/21.8310270165
- --8310270176 Provides overview of const completion program Modules 340, 102, 120, 410 & 800 requested for release BARANOM, S W Stone & Webster, Inc 83/10/12 KEPPLER, J Q Region 3. Office of Director 11pp 20924 160 24X Fiche 50-329,83/10/21,8310270165
- 8310270341 Advises that review of util 830624 supplemental response to Item B 6 of 830208 notice of violation completed Response unacceptable Behedule for penetrant tests of welds must be submitted within 25 days of ltr receipt WARNICK.R F Region 3, Office of Director 83/10/21 COOK, J. W Consumers Fower Co 2pp 20923 352 24X Fiche 50-329, 83/10/21, 8310270341
- --8310270352 Forwards supplemental info re Item 8 of 930208 notice of violation in response to NRC 830523 request Const training procedure revised to establish program assuring appropriate training in installation procedures
 CDOK.J W Consumers Power Co 83/06/24 KEPPLER.J 9 Region 3, Office of Director 15pp 20923 354 24X Fiche 50-329,83/10/21,8310270341
- R Periodic operating reports & related correspondence
- 8310210272 Forwards fifth monthly status rept for independent design & const verification program for Sept 1983
 LEVIN.H A TERA Corp 83/10/17 EIBENHUT,D 0 Division of Licensing KEPPLER.J 0 Region 3, Dffice of Director, COOK,J H Consumers Power Co 3pp 20848 220 24X Fiche, 50-329, 83/10/17, 8310210272
- --8310210275 Fifth monthly status rept for independent design & const verification program for Sept 1983 DAUGHERTY, F., LEVIN.H. A., BECK.J W TERA Corp 83/10/17 51pp. 20848: 223 24X Fiche 50-329, 83/10/17, 8310210272
- 8310310078 Forwards listed documents written or closed during
 Sept 1983, per condition of Memorandum & Order ALAB-106 k
 Amend 1 to CPPR-81 & CPPR-82
 COOK, J W Consumers Power Co 83/10/25 DEYDUNO, R C Director's
 Office, Office of Inspection and Enforcement 3800pp 20980 001,
 24X Fiche: 50-329,83/10/25,8310310078
- 8 Reportable occurrences, LERs & related correspondence
- 8307070257 Interim deficiency rept re do backed power supplies for F000 interlock relays in auxiliary feedwater sys Schematic Diagram E-158(0) revised & issued as of 830727 to provide 120-volt ac power.

 COOK. J W. Consumers Power Co. 83/09/02 KEPPLER, J. G. Region B. Office of Director App. 20310 187 24X Fiche 50-329,83/09/02,8309090259
- 8310120446 PNO-IIX-83-092 on 831004.merijuana found in truck dwned by carpenter employed by Bechtel Corp Individual fired by Bechtel & left site No action planned by Region III State of MI will be notified HARRIBON.J. WARNICK.R. Region 3. Office of Director, 83/10/04. ip. 20498 325 24% Fiche. 50-329,83/10/04,8310120446.
- 8310140090 PNO-III-83-095 on 831005.8kM issued stop work order on Class I piping hanger installation. Stop work applies to both small bore & large bore piping & Is based on deficiencies identified in hangers during Benhtel insp HARRIBON.J., GARDNER.R Region 3, Office of Director. 83/10/06. ip 20767 099. 24X Fiche 50-329.83/10/06.8310140090.

- 8310170421 Final deficiency rept re underrated terminal strips on Limitorque valve operators Initially reported on 810213 New valve operators for use inside containment will be purchased w/o terminal blocks or space heaters COGK, J W Consumers Power Co 83/10/06 REPPLER, J G Region 3, Defice of Director 25pp 20783 323 24% Fiche 50-329,83/10/06,8310170421
- 8310250101 Final rept re deficiencies in electrical components in that non-Class IE devices wired into Class IE circuits Engineering production schedule activities will be revised by 831021 COOK.J W Consumers Power Co 83/10/14 XEPPLER, J 0 Region 3, Office of Director 14pp 20896 172 24X Fiche 50-329,83/10/14, 8310250101
- 8310270265 Interim deficiency rept re reactor bldg spray piping supports. Initially reported on 791221 Caused by conservative modeling assumptions made in original water hammer analysis Next rept by 831230 COOK, J W Consumers Power Co 83/10/21 XEPPLER, J 9 Region 3, Office of Director 6pp 20923 247 24X fiche 30-327,83/10/21, 8310270265

T Hearing transcripts on non-antitrust matters

- 8310280073 Metion for admission into evidence of transcript of JL Donnell 831015 deposition Certificate of Svc encl WILLIAMS: F C Consumers Power Co 83/10/25 Atomic Safety and Licensing Board Panel 9pp 20933 342 24X Fiche 30-327,83/10/25, 8310280073
- --8310280078 Transcript of JL Dunnell 831016 deposition in Las Vegas, NV re alleged violation of ABLB order DONNELL, J L. Consumers Power Co 83/10/15 114pp 20933 351 24% Fichs 50-329, 83/10/25, 8310280073

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

- F. Security, medical, emergency & fire protection plans
- 8310040195 Forwards IE Insp Rept 50-331/83-14 on 830808-12 No notice of violation will be issued for activities not complying w/NRC requirements since 10CFR2.App C. Bection IV.A provisions met PAPERIELLO.C J Region 3. Office of Director 83/09/16 LIU.L lowa Electric Light & Power Co 2pp 20608 233. 24X Fiche: 50-331.83/09/16.8310040195
- --8310040198 IE Insp Rept 50-331/83-14 on 830808-12 Noncompliance noted lack of timely offsite notification capability & failure to classify unusual event PATTERBON, J P. GLOERSEN, W B., PHILLIPS, M P. Region 3, Office of Director 83/09/16 14pp. 20608-235 24X Fiche 50-331,83/09/16,8310040195.
- B310110035 Releases public version of revised emergency plan implementing procedures
 FELTON.J M Division of Rules and Records 83/10/05 Document
 Management Branch. 1p 20686 265. 24X Fiche 50-331.83/10/05,
 B310110035
- --B310110036 Forwards public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 3.3s. "Manual Dose Projections" & Rev 3 to EPIP 3 3b. "Computerized Dose Projections "W/B30824 receipt form.
 PORTZ, R Iowa Electric Light & Power Co 83/09/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 20686 266 24% Fiche: 50-331.83/10/05.8310110035
- --8310110038 Public version of Rev 4 to Emergency Plan Implementing Procedure EPIP 3 3s. "Manual Dose Projections" & Rev 3 to EPIP 3,3b. "Computerized Dose Projections." 4 Howe Electric Light & Power Co 83/08/24 47sp. 20686 268 24X Fiche: 30-331,83/10/05,8310110035
- #3310110042 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch. 1p. 20687-001 24X Fiche-50-331,83/10/05,8310110042.
- --8310110055 Forwards public version of revised Emergency Plan Implementing Procedures EFIP 3 3a re injitial dose projections, EPIP 3 3b re followup dose projections & EPIP 6.4 re emergency prepareshess communications testing PORTZ. R. Iowa Electric Light & Power Co. 83/05/31. DENION, H R Office of Nuclear Reactor Regulation, Director 2pp. 20687,002 24X Fiche 50-331,83/10/05,8310110042

- ---8310110060 Public version of revised Emergency Plan Implementing Procedures EPIP 3 3a re initial dose projections. EPIP 3 3b re followup dose projections & EPIP 6 4 re emergency preparedness communication testing # Iowa Clectric Light & Power Co 83/05/25 147pp 20687 005 24% Ficha 50-331,83/10/05,8310110042
- 8310250668 Releases public version of revised corporate plan implementing procedures FELTON, J M Division of Rules and Records 83/10/27 Document Management Branch 1p 20908 053 24X Fiche 50-331.83/10/27, 8310250668
- --83i0250669 Forwards public version of Rev 5 to corporate plan implementing procedures, including Procedures CPIP-1 2 recorporate notification & CPIP-1 3 reactivation & operation of emergency operations facility.
 PORTZ.R Inum Electric Light & Power Co 89/i0/10 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 20908 054 24X Fiche 50-33i.83/10/27,8310250668
- --8310250670 Public version of Rev 5 to emergency plan implementing procedures.including Procedures CPIP-1 2 re corporate notification & CPIP-1 3 re activation & operation of emergency operations facility
 * Ioua Electric Light & Power Co 83/10/07 133pp 20708 056 24% Fiche 50-331,83/10/27,8310250668
- 8310270005 Releases public version of revised emergency plan implementing procedures FELTON,J M Division of Rules and Records 83/10/27 Document Management Branch 1p 20939 120 24% Fiche 50-331,83/10/27,8310270005
- --8310270015 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 i redetermination of emergency action level & EPIP 1 2 renotifications. Receipt form encl
 WILSGN, D L lows Electric Light & Power Co. 83/10/12
 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 20939 122 24X Fichs 50-331.83/10/27.8310270005
- --8310270019 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1 1 re determination of emergency action level & EPIP 1 2 re notifications

 * Iowa Electric Light & Power Co 83/10/03 40pp 20737 124 24X Fichs 50-331, 83/10/27, 8310270005
- P Operating license stage documents & correspondence
- 8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER, L. Affiliation Unknown 83/05/02 NRC - No Detailed Affiliation Given ip 21004 270 24% Fichs 50-000,83/05/02, 8310310017
- 8310170119 Forwards safety evaluation of 780301 request for relief from 10CFR50 85a(g) & ABME Boiler & Pressure Vessel Code inservice testing requirements Relief granted in part VASSALLD, D B Operating Reactors Branch 2 83/09/26 LIU.L. Iowa Electric Light & Power Co 4pp 20813 067 24X Fichs 50-331,83/09/26,8310170119
- --8310170125 Safety evaluation supporting proposed inservice insp/testing program & granting, in part, 780301 request for relief from testing requirements * NRC No Detailed Affiliation Given 83/09/26 8pp 20813 071, 24X Fiche 50-331, 83/09/26, 8310170119
- --8310140258 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr." fourth semiannual rept * Bechtel Corp 83/09/22 592pp 20759 302 24X Fiche 50-331.83/09/30.8310140254
- 8310180178 Forwards response to request for add1 info re single recirculation loop operation. Independent verification of average power range monitor gain adjustment performed daily MCGAUGHY, R W. I now Electric Light & Power Co 83/10/11 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 20808 337 24X Fiche 50-331.83/10/11,8310180178

- 9310180424 Responds to D Vassallo B30823 ltr re automatic closing of containment purps & vent valves on high radiation signal (NVREO-0737. Item II E 4 2(7)) Facility will be modified, as result of evaluation of BWR Owners Group position MCGAVOHY, R. W. Iowa Electric Light & Power Co. B3/10/13 IENTON, H.R. Office of Nuclear Reactor Regulation, Director Ip 20803 305 24X Fiche 50-331,83/10/13.8310180424
- 8310200182 Revised application for amend to License DPR-49, consisting of Proposed Change RT9-115D to Tech Specs re noble gas against annual verification of comulative air dose Class III fee submitted w/770829 application MCGAUGHY, R W Inwa Electric Light & Power Co 83/10/17 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 20835 055 24X Fiche 50-331.83/10/17.8310200182
- --8310200186 Proposed Change RTS-115D to Tech Specs Pages 3 2-3,3 2-4, 3 2-29,3 2-33,3 14-11,3 15-3,3 15-5,3 (5-7,3 15-8,3 15-10, 6 11-4 & 6 11-12 re noble gas & communative air dose, per comments in telcons w/NRC during wk of 830926-30 * Iowa Electric Light & Power Co 83/10/17 14pp 20835 058 24X Fiche 50-331,83/10/17,8310200182
- 8310310117 Rejects 830702 request for extension of time to submit formal, i20-day response to Generic i.tr 83-28 re Salem ATWS events Response due by 831105 Participation in owners group acceptable for long-range planning issues only VASBALLO,D 8 Operating Reactors Branch 2 83/10/19 LIU.L Iowa Electric Light & Power Co 2pp 20965 327 24X Fiche 50-331,83/10/19,8310310117
- B310270535 Notification of B31102 meeting w/util in Bethesda,MD to discuss guldance on requirements for application to upgrade power. FHADANI,M C. Operating Reactors Branch 2 B3/10/21 VASSALLO,D B Operating Reactors Branch 2 2pp 2093B 032 24X Fische 50-031.83/10/21.8310270835
- Q Inspection reports, IE Bulletins & correspondence
- B3i0040195 Forwards IE Insp Rept 50-331/B3-14 on B3080B-12 No notice of violation will be issued for activities not complying w/NRC requirements since 10CFR2, App C. Bection IV A provisions met PAPERIELLO.C J. Region 3. Office of Director B3/09/14 LIU, L. Iowa Electric Light & Power Co. 2pp. 20408 233 24X Fiche 50-331,83/09/14.8310040195
- --B310040196 IE Insp Rept 50-331/B3-14 on B3080B-12 Noncompliance noted lack of timely offsite notification capability & failure to classify unusual event PATTERBON-J P., OLDERSEN-W D., PHILLIPS-M P. Region 3, Office of Director 83/09/16 14pp 2040B 235 24X Fiche 50-331,83/09/16,8310040195
- 83i0060188 Forwards IE Insp Rept 80-331/83-11 on 830627-0830 No noncompliance noted SHAFER: W D Region 3, Office of Director 83/09/21 LIU.L Iowa Electric Light & Power Co 2pp 20647 180 24X Fiche 50-33i,83/09/21,83i0060158
- --B310040145 IE Inep Rept 50-331/B3-ii on 830427-0830 No noncompliance noted Major areas inspected operational safety maint, surveillance.LERs, procedures, plant operations, plant trips, IE circulars, audits, TMI items & licensee meetings CLARDY.L S. WALKER, R.D. Region 3, Office of Director 83/09/16 14pp 20647.182 24X Fiche 50-331,83/09/21,8310040158
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York. Inc 117pp 20754 022 24X Fichs 50-000.83/09/26.8308300340
- B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Byo list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 116pp. 20777,210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 [E Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co of New York, Inc. 118pp 20778-001 24X Fiche 50-000,83/09/26,8308300345
- 8310170119 Forwards safety evaluation of 780301 request for relief from 1DCFR50.55a(g) & ABME Boiler & Pressure Vessel Code inservice testing requirements Relief granted in part VASSALLO.D B Operating Reactors Branch 2 83/09/26 LIU.L. lowa Electric Light & Power Co 4pp 20813:067 24X Fiche: 50-331,83/09/26,8310170119

- --8310170125 Safety evaluation supporting proposed inservice insp/testing program & granting, in part, 780301 request for relief from testing requirements

 * NRC No Detailed Affiliation Given 83/09/26 8pp 20813 071 24X Fichs 50-331,83/09/26,8310170119
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Sys W/o 10CFRSO 59 Evaluation " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24X Fithe 50-000,83/09/29,6308300349.
- B310140254 Forwards fourth semiannual "Rept on Environ Qualification Frogram for Duane Arnold Energy Ctr" covering safety-related electrical equipment MCGAUGHY.R H Iowa Electric Light & Power Co 83/09/30 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 20759 300 24X Fiche 50-331,83/09/30,8310140254
- --8310140298 "Rapt on Environ Qualification Program for Duana Arnold Energy Ctr." fourth semiannual rept * Bechtel Corp 63/09/22 592ap 20759 302 24X Fiche 50-331.83/09/30.6310140234
- 8308300378 IE Info Natice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- B30B300752 IE Info Notice 83-65, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20802 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Cases " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,83083000759
- 830830076.) IE Info Notice 83-6B. "Respirator User Marning Defective Belf-Contained Breathing Apparatus Air Cylinders" Bvc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 (27, 24% Fiche 50-000,83/10/11.8308300761.
- 8310180206 Clarifies NRC position re-procedures for admitting NRC insp personnel to facilities List of NRC personnel requiring access to plant vital areas encl Update will be be provided every 6 months AXELSON, W L Region 3, Office of Director. 83/10/14 LIU.L Iowa Electric Light & Power Co 7pp 20808 317 24X Fiche 30~331.83/10/14.8310180206
- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking MIRAQLIA,F J Assistant Director for Safety Assessment 83/10/14 EISENHUT,D 9 Division of Licensing 5pp 20823 35B 24X Fichs \$0~000,83/10/14,8310180551
- 8310270459 Discusses stram discharge vol Short-term mods in response to IE Bullstin 80-17 Nater added to stram discharge vol & vent procedures & drain valve operablility & closure time test changed from quarterly to monthly MCGAUCHY, R W I Towa Electric Light & Power Co 83/10/18 KEPPLER, J @ Region 3, Office of Director ip 20923 133, 24X Fishe 50-331,83/10/18,8310270459
- R Periodic operating reports & related correspondence
- 8310140254 Forwards fourth semiannual "Rept on Environ Qualification Program for Duane Annold Energy Ctr" covering safety-related electrical equipment MCGAUOHY, R W Inwa Electric Light & Power Co 83/09/30 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 20759-300 24X Fichs 30-331,83/09/30.8310140254
- --8310140288 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr." fourth semiannual rept * Bechtel Corp 83/09/22 592pp 20759:302 24X Fiche 50-331,83/09/30,8310140854.

- 8310170581 "Radiological Analysis of Strontium Samples, Second Quarter MINECK, D.L. Iowa Electric Light & Power Co. 83/10/03 KEPPLER, J.G. Region 3, Office of Director 2pp. 20760 335 24X Fiche 50-331,83/10/03,8310170581
- 831019006B Monthly operating rept for Sept 1983 W/831014 ltr ANDERSEN.M., MINECK,D.L. Iowa Electric Light & Power Co. 83/10/14 Director's Office of Inspection and Enforcement Spp 20822 293 24% Fiche 50-331/83/10/14/831019006B
- 8 Reportable occurrences. LERs & related correspondence
- B310110430 Responds to F01A request for four different categories of documents described in B30510 ltr Forwards matl listed in App A, responsive to Items 1,2 & 4 D0E should be contacted for matl requested in Item 3 of itr FELTON, J H Division of Rules and Records 83/06/14. HIATT, B L Ohio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000,83/06/14,8310110430
- --8310110467 Daily rept re events at three different facilities LACBHR experienced scram due to low water level PNO-III-83-026 updates use of lubricants on valve seats # Region 3. Office of Director 83/04/14 1p 20706 062 24X Fiche 50-000.83/06/14.8310110430
- 8310120380 RD on 830308; radiographic exams conducted on 10 HPCI turbine reversing chambers Beven chambers did not meet augmented acceptance criteria Cracking caused by mfg process & Pressure pulsing fattgue
 MINECK, D.L. Iowa Electric Light & Power Co 83/08/2:
 Region 3, Office of Director 2pp 20699 198 24X
 Fiche: 80-331,83/08/23.8310120380 63/08/23 KERPLER, J. O.
- 8310120400 LER 83-033/03L-0.on 830903, HPCI min flow return to torus Indicated the 83-033/021-0, on 150903. First min from return to the control of the Mo-2318 indication intermittently showed valve open HPCI declared inoperable Caused by cracked valve yoke yoke repaired & tightened W/831003 ltr KIBLER, D R., MINECK, D L Iows Electric Light & Power Co BC KEPPLER, J & Region 3, Office of Director 2pp 20700 202 Fiche 50-321,83/10/03.8310120400 83/10/03
- 8310170490 LER 83-035/031-0 on 830906 during surveillance testing LIB 4531 & 4533 for reactor water low-low tripped nonconservatively at 113 2 & 113 4 inches respectively Caused by instrument drift Switches recalibr W/B31006 ltr HARRISH M S . MINECKLO L low Electric Light & Power Co 83/10/06 KEPPLER.J. Q Region 3, Office of Director 2pg 20784 117 24X Fiche. 30-331,83/10/06.8310170490
- B310120421 LER B3-036/03L-0 on B30909 during normal operation, visual imap of HFA relays revealed relay A718-K18 deteriorated Caused by varnish sticking areature closed Relay replaced M/B31009 itr
 HAMEL, D.B., MINECK, D.L. Idwa Electric Light & Power Co. B3/10/09 KEPPLER, J.O. Region 3, Office of Director. 2pg. 20698 319 24x Fiche, 50-331, 83/10/09, 8310120421.
- 8310210090 LER 83-040/03L-0 on 830913, during surveillance testing, drywell equipment drain line valve CV-9729 did not close on menual closure signal Caused by air operator piston being stuck Valve lubricated & cycled ANDERSEN, M. W. MINECK, D. L. Towa Electric Light & Power Cb 83/10/13 KEPPLER, J. Q. Region 3, Office of Director 2pp 20838 195 24X Fiche 50-331.83/10/13.8310210090.
- 310250481 LER 83-037/03L-0: on 830715, during surveillance test, rod block monitor channel B prevented movement of rod 26-07. Cauting inoperatifity of channel Caused by wiring problem Component replaced W/833017 ltr.
 HARRIS.M. B., MINECK, D.L. Iowa Electric Light & Power Co. 83/10/17
 KEPPLER, J.Q. Resion 3, 07fice of Director 4pp 20897 071. 24X Fiche: 50-331,83/10/17.8310250481

ı pump 1P-233 ofl e d C.

- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 83(0170533 Advises that 1983 annual emergency preparedness exercise tentatively scheduled for 83(012. Exercise will be small scale & involve only limited participation by Oswego County # State of NY

 # State of NY

 # State of NY

 # State of New York # 83

 # State of New York # 83 83/01/04
- ~-9310170655 Forwards "Emergency Response Plan Exercise Manual " Withholding of exercise scenario until exercise completed requested
 BAYNE,J P Jouer Authority of the State of New York B3/0'
 WURLEY,T E Region 1, Office of Director 2pp 20779 324
 Fiche 50-333, 83/01/04, 8310170533 83/07/15
- ~-8310170659 Rev 1 to Procedure BAP-1, "Emergency Response Plan Exercise F Power Authority of the State of New York 83. 20779 326 24X Fiche 50-333,83/01/04,8310170533 83/04/30 213ma
- 8310210126 Forwards "Emergency Response Pian Exercise Manual," for B31012 site preparedness exercise B4NE, JP Power Authority of the State of New York 83/10/07 MUMLEY,T E Region 1, 0ffice of Director 1p 20853 230 24X Fiche 50-333,83/10/07,8310210126
- ~~83(02)0127 "Emergency Response Plan Exercise Manual * Power Authority of the State of New York 83/1 20853 231 24X Fiche 50-333,83/10/07,8310210126 83/10/12 465pp
- 8310280044 Forwards "Detailed Control Room Design Review Program Plan for JA Fitzpatrick Nuclear Power Plant," in response to 821217 Generic Ltrs 82-33 & 83-18, Suppl 1 to NUREG-0737 & Fill Action Item I D 1 8AYNE, J P Power Authority of the State of New York 83/10/24 VABSALLO, D & Operating Reactors Branch 2 2pg 20934 348 24X Fiche: 50-333, 83/10/24, 8310280044
- ~-8310280054 "Detailed Control Room Design Review Program Plan for JA Fitzpatrick Nuclear Power Plant "
 * Power Authority of the State of New York 83/10/19 86pp 20934 350 24X Fiche 50-333,83/10/24,8310280044
- O Adjudicatory correspondence
- 9310060580 Forwards UCS 830912 petition per 10CFR2 206 requesting immediate action to shut down plant Response by 831012 requested requested DENTON.H.R. Office of Nuclear Reactor Regulation, Director 83/09/23 BAYNE,J P Power Authority of the State of New York 3pp 20661 212 24X Fiche 80~333,83/09/23,8310060580
- 8310130113 Responds to 830923 request for response to UCB 830912 petition filed under 10CFR2, 206 re pipe support isques Extension of response date to 831116 requested BAYNE, J.P. Power Authority of the Btate of New York 83/10/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 20726 308 24X Fiche 50-333,83/10/11,8310130113
- P. Operating license stage documents & correspondence
- 8310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNER.L Affiliation Unknown, 83/05/02 NRC No Detailed Affiliation Given lp 21004-270 RAX Fiche, 50-000, 83/05/02, 8310310017
- 8310310031 Responds to FDIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON, J M Division of Rules and Records 83/07/06 CONNER, L Affiliation Unknown ip 21004.271 24X Fiche.50-000.83/07/06, 8310310031
- --B310310058 "Integrated Leak Rate Test Computer Program for Primary Conteinment" Containment * Pouer Authority of the State of New York, 74 21005: 179 24% Fiche 50-000,83/07/06,8310310031 74/03/20 100рр
- 8310180531 FDIA request for Target Tachnology.Ltd documents ro pipe supports WEISB,E.R. Union of Concerned Scientists. 83, Division of Rules and Records 1p 20825,005 Fiche 50-333,83/08/11.8310180531 83/08/11 FELTON, J M

- 8310180534 Responds to FOIA request for Target Technology, Ltd documents re pipe supports Forwards document encl Document also available in PDR FELTON, J M Division of Rules and Records 83/09/06 WEISS, E R Union of Concerned Scientists ip 20825 006 24X Fiche 50-333,83/09/06,8310180534
- --8310180538 Comments on pipe support design noncompliance w/FS Summary of B30627 meeting w/SEW re list of 20 unacceptable supports submitted on B30103 discussed DAINORA. J Target Technology Ltd B3/06/30 GUAGUIL. L Authority of the State of New York 5pp 20829 007 24X Fichs 50-333, 83/09/06, 8310180534
- 8310070084 Forwards safety evaluation of util response to NUREG-0737, Item II D 1, "Reliability Engineering" re safety & relief valve testing Requirements met Item resolved VASSALLO, D B Operating Reactors Branch 2 83/09/22 BAYNE, J P Power Authority of the State of New York 17pp 20671 317 24X Fishs 30-373, 83/09/22 8310070086 Fiche 50-333,83/09/22,8310070084
- B310)10112 Forwards Phase 1 response for Criteria 1,2d,3,6,11a & 11b of NUREC-0737. Item II B 3 re post-implementation review of util post-accident sampling sys Remaining responses will be submitted in 6 months

 BAYNE, J P Power Authority of the Btate of New York 83/10/05 submitted in 6 months
 BAYNE, J P Power Authority of the Btate of New York 83/10/05
 VASSALLO, D B Operating Reactors Branch 2 18pp 20667 278 24X
 Fiche 50-333,83/10/05,8310110112
- 8310140196 Forwards Rev O to "Plant-Unique Analysis Rept of Torus Suppression Chamber." Mark I containment program technical rept.per acceptance criteria in App A to NUREG-0661 BAYNE.J P Power Authority of the State of New York 83/10/11 VASSALLO.D B Operating Reactors Branch 2 ip 20762 084 2-Fiche 50-333.83/10/11.8310140196
- --8310140202 Rev 0 to "Plant-Unique Analysis Rept of Torus Suppression Chamber," Mark I containment program technical rept for James A Fitzpetrick Nuclear Power Plant * Teledyne Engineering Services TR-5321-1 R00 83/08/11 144pp 20762 086 24X Fiche 50-333.83/10/11,8310140196
- 8310310043 Forwards revised offsite dose calculation manual Primary changes reflect recalculated X00/D00 values & mod to calculation methodology
 BAYNE, J P Power Authority of the State of New York 83/10/26
 VASBALLO.D B Operating Reactors Branch 2 Ip 20747:280 24X
 Fiche 50-333,83/10/26.8310310043
- --8310310046 Revised offsita dose calculation manual * Power Authority of the State of New York 83/10/31 232pp 20947 281 24X Fiche 50~333,83/10/26,8310310043
- Q Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder SUBSOUSHO LE Info Notice 83-51, "Alleged Use of Stand-Ins for W Qualification Tests " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co York, Inc. 117pp. 20754,022 24X Fiche 50-000,83/09/26,8308 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORBAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26, Consolidated Edison Co. of New York, Inc. 116pp 20777-210 24X Fiche 50-000,83/09/26,8308300342
- 830B300B45 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche, 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enct JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29. Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche, 80-000, 83/09/29, 8308300349
- 8310190157 Forwards IE Insp Rept 50-333/83-18 on 830801-0905 No noncompliance noted STAROSTECKIR Division of Project & Resident Programs 83, MCNEILLC A. Power Authority of the State of New York 2pp 20820 316 24X Fiche 50-333,83/10/05,8310190157 83/10/05

- --8310190168 IE Insp Rept 50-333/83-18 on 830801-0905 No noncompliance provided le imag Rept 50-333/83-18 on 830801-0903 No mo noted Major areas inspected licensee action on previous insp findings, LER review, operational safety verification review of plant operations & survaillance observations DOERFLEIN, L T Region i, Office of Director KISTER, Division of Project & Resident Programs 83/10/03 11 20820 318. 24X Fiche 50-333,83/10/05,8310190157 KISTER H B
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Sypass Loops Used in Westinghouse Plants" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility "Svc list one!

 JORDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 930103) 83/10/07 Consolidated Edison Co of New

 York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8310170480 Forwards Change 2 to Rev 3 to inservice insp program for pumps & valves, in accordance w/IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators "
 BAYNE, J P Power Authority of the State of New York B3/10/0'
 VASSALLO, D B Operating Reactors Branch 2 6pp 20784 085,
 Fiche 50-333,83/10/07.8310170480.
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Oases." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043.075 24X Fiche 50-000.83/10/11,8308300759.
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Broathing Apparatus Air Cylinders " Bvc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 127 24X Fiche 50-000,83/10/11.8308300761
- 8310310364 Submits supplemental response to IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Transmitters will be replaced BAYNC.JP Power Authority of the State of New York. 83/10/11. MURLEY.TE Region 1. Office of Director 2pp 20757:089 24 Fiche 50-333.83/10/11.8310310364
- B31018D551 Notification of B31021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress corrosion cracking.
 MIRAGLIA:F. J Assistant Director for Sefety Assessment B3/10/14 E1SENHUT.D.4 Division of Licensing 5pp 20823;358 24X Fiche 50-000.83/10/14.8310180551
- R Periodic operating reports & related correspondence
- 8310120435 Monthly operating rept for Bept 1983 W/831006 ltr. GDDX, J., MCNEILL, C. A Fower Authority of the State of New York 93/09/30 NRC No Detailed Affiliation Given 12pp. 20698-301 24X Fiche 50-333, 83/09/30, 8310120435
- S Reportable occurrences, LERs & related correspondence
- 8310210327 Responds to FDIA request for all documents re significantly high rate of equipment failures for QE BWR/4 rated at 2,436 MW Forwards App A documents Documents also available in PDR FELTON.J. M Division of Rules and Records. 83/07/28 HAFNER, B Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche: 50-000, 83/07/28, 8310210329
- ---B302020202 Bummarizes evaluation of LERs for 1982 in support of upcoming BALP review Licensee performance adequate. B3/01/26 BEYFRIT, K V Reactor Operations Analysis Branch. B3/01/26 STARGSTECKI, R Division of Project & Resident Programs 3pp 20882 254 24X Fiche 50-000.83/07/28.8310210329.
- 8310060089 Updated LER 83-023/01X-1 on 830607,water seepage discovered from weld in stainless steel pipe section of control rod hydraulic return line Control rod drive hydraulic return line Control rod drive hydraulic return line cut & capped at vessel nozzla W/8007008 ltr PERNANDEZ.W, MCNEILL.C A Power Authority of the State of New York. 85/09/01. MURLETY.T E Region 1. Office of Director Rep. 20647: 105 24X Fiche 50-333,83/09/01.8310060089

- 8310190150 LER B3-028/03L-0 on 830823, instrument 02-3-PS-528 setpoint found at 444 psip, below Tech Spec limit of 450 psig Caused by instrument drift Switch setpoint immediately adjusted & testing frequency increased W/830919 ltr MCNEILL.C A Power Authority of the State of New York 83/09/19. NURLEY, T E Region 1. Diffice of Director 2pp 20820 222 24X Fiche 50-333.83/09/19.8310190150
- 8310190213 LER 83-032/03L-0 on 830903, during post-mod scram test at 50% rod density two of four scram instrument vol drain valves failed to close in specified time frame Caused by contact between handwheels & object W/830919 ltr BERNSTEIN.B. MCNEILL.C A Power Authority of the State of New York 63/09/19 MCNEY.T E Region 1. Office of Director 3pp 20818 034 24% Fiche 50-333,83/09/19,8310190213
- 8310200134 LER 83-029/03L-0 on 830829, hydraulic snubber Hi2-94 (12-1-8-20) failed to lockup in compression when tested Caused by poppet spring lodged between compression poppet & seat Modified valve assembly installed W/830921 ltr MCNEILL.C A Power Authority of the State of New York 83/07/21 MCNEILL.C A Power Authority of the State of New York 83/07/21 MCNEILL.C A Power Authority of the State of New York 83/07/21 Fiche 50-333,83/09/21,8310200134
- 8310190082 LER 83-034/03L-0 on 830906, during surveillance on average power range monitor C.downscale trip level setting found law Caused by instrument drift. Monitor adjusted Testing frequency increased W/830923 ltr
 LINDSEY, D J MCNEILL. C A Power Authority of the State of New York 83/09/23 MURLEY, T. E Region 1, Office of Director 2pp 20822 268 24% Fiche 50-333, 83/09/23, 8310190082
- B310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN/M J Foxboro Corp 83/09/30. Director's Office, Office of Inspection and Enforcement 11pp 20651.044 24K Fiche. 50-000,83/09/30,8310070301
- B310250412 LER 83-041/04T-0 on 830923, environ radiological monitoring sample revealed mollusks & periphyton exceeded 10 times control sample for Mn-54 & Co-60, respectively Caused by high bloaccumulation factor W/831005 ltr SOLINI, J A. MCNEILL, C A. Power Authority of the State of New York B3/10/05, MURLEY, T E. Region 1, Office of Director 7pp 20897 247. 24X Ficha 50-033,83/10/05,8310250412
- 8310250585 LER 83-040/03L-0 on 830921, while performing valve lineup for sampling using post-accident sampling sys.containment hydrogen & oxygen return line & affected sys isolated Gaused by failure to open solenoid operated valve W/831005 ltr HERRHANN-T, MCNEILL, CA Power Authority of the State of New York 83/10/05 MURLEY, TE Region 1, Office of Director 3pp. 20901 253 24X Fiche 50-033,83/10/05,8310250585
- 9310250614 LER 83-037/03L-0: on 830915, while conducting surveillance testing on drywell high pressure switches for reactor protection & euto depressurization sys. setpoint found less conservative that Tech Specs Setpoint adjusted 4/831005 ltr MCNEILL, C.A. Power Authority of the State of New York 83/10/05, MURLEY, T.E. Region I. Office of Director 3pp 20900 269 24x Fiche 50-333, 83/10/05, 8310250614.
- 8310310203 LER 83-033/03L-0 on 830905 & 07 during startup & escension to power while inerting drywall, torus level fell below Tech Bpec requirements Caused by water block in dry leg of level transactiter Dry leg vented W/831003 ltr.

 MCNEILL.C A Power Authority of the State of New York. 83/10/05 MCRIELY.T E Region 1. Office of Director 3pp 20938 329. 24% Fiche 50-333,83/10/05,8310310203.
 - :0140082 PNG-1-83-105 on 831007, seismic event occurred in sortheastern US w/magnitude of 5 2 on Richter scale in NY 4 4 0 in NH No damage to equipment identified PALLO, R.M. Region 1. Office of Director 83/10/07 ip 20766
- :10250276 LER \$3-036/03L-0 on B30914, during testing on high drywell pressure switches, ECCS actuation occurred, resulting in starting of core spray pumps A & B, HCPI; standby gas treatment sys & emergency dissel generators W/B31014 itm. MCNEILL:C A Power Authority of the State of New York. B3/10/14 MURLEY.T E Region 1 Office of pirector, 3pp. 20895 339, 24X Ficha: 30-333,83/10/14:8310250276

- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310040561 Forwards "Program Plan For Implementation of Control Room Design Review of Beaver Valley Power Station," following guidelines in Suppl 1 to NUREO-0737.per Generic Ltr 82-33 CAREY, J Duquesne Light Co 83/09/29 EISENHUT, D O Division of Licensing 3pp 20622 165 24X Fiche 30-334,83/09/27,8310040561
- --8310040569 "Program Plan For Implementation of Control Room Design Review of Beaver Valley Nuclear Power Station " * Duquesne Light Co 83/09/27 88pp 20622 168 24X Fiche 50-334,83/09/27,8310040561
- 8310140208 Forwards three-shift schedule for manning control room w/existing control room supervisory complement & list of addl personnel undergoing training Forms for addl personnel will be forwarded during wk of 831003 CAREY, J J Duquesne Light Co 83/09/29 MURLEY, T E Region 1, Office of Director 2pp 20762 358 24% Ficha 50-334,83/09/29,8310140208
- 8310180432 Forwards "Comparison of Beaver Valley Power Station Dose Projection Methodology vs NRC Interactive Rapid Dose Assessment Model." due to NRC reported dose projection results from Pecent emergency planning exercise CAREY.J J Duquesne Light Co 83/10/03 VARGA, 8 A Operating Reactors Branch 1 3pp 20797 050 24X Fiche 50-334.83/10/03.8310180432
- --8310180434 "Comparison of Beaver Valley Power Station Dose Projection Methodology vs NRC Interactive Rapid Dose Assessment Model " LA VIE.8 F Duquesne Light Co 83/08/31 41pp 20797 053 24 X Fiche 50-334,83/10/03,8310180432
- 831 0200007 Forwards IE Insp Repts 50-334/83-17 & 50-334/83-23 on 830814-0912 & 0922-23, respectively Enforcement conference scheduled for 831011.per 830926 telcon.

 8TARDSTECKIR R Division of Project & Resident Programs 83/10/03 CAREY, J Duquesne Light Co 3pp 20837 012 24X Fiche 50-334, 83/10/03, 8310200007
- --B310200010 IE Insp Rept 50-334/83-19 on B30816-0912 Noncompliance noted failure to perform surveillance test within required time period & RHR sys inoperable TROSMOSKI W M . TRIPP.L E. Region 1. Office of Director B3/09/29 17pp 20837 015 24X Fiche 50-334.83/10/03.B310200007
- 8310240146 Forwards emergency preparedness plan implementing procedures. Issue 7. Rev 2 W/o encl 81EBER. J D Duquesne Light Co 83/10/07 VAR9A. B A Operating Reactors Branch 1. 2pp 20881 171 24X Fiche 50-334.83/10/07.8310240146
- 83i0280140 Forwards notice of one-time exemption from schedular requirements of 10CFR50, App E. Section IV F. allowing annual emergency preparedness exercise to be conducted no later than 840630 VAR9A:S A Operating Reactors Branch 1 83/10/12 CAREY, J J Duquesne Light Co 3pp 20965 077 24X Fiche 50-334.83/10/12, 8310280140
- --8310280142 Examption from 10CFR50, App E. Section IV. F 1, #llowing annual emargency preparedness exercise to be conducted no later than 840630 EISENHUT. D Q Division of Licensing 83/10/12 Duqueene Light Co 3pp 20965 080 24% Fiche 50-334, 83/10/12, 8310280140
- P Operating license stage documents & correspondence
- B310120257 Forwards proposed rev to updated FSAR re reanalysis of LOCA radiological consequence analysis & supporting documentation set

 CAREY. J J Dequesne Light Co B3/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director. 258pp 20691 052 24X

 Fiche 50-334-83/09/28, 6310120287
- B310130188 Forwards Amend 72 to License DPR-66 & safety evaluation Amend clanifies intent of Amend 49 dtd B20330 adding two footnotes to Sections 37 12 & 4 7 12 re snubbers TAM,P S Operating Reactors Branch 1 83/09/30 CAREY,J J Duqueene Light Co Spp 20777 158 24X Fiche 50-334.83/09/30, B310130188
- --8310130191 Amend 72 to License DPR-66.clarifying intent of Amend 49 dts 820330 by adding two footnates to Sections 3 7 12 & 4 7 12.Footnate 1 defines sys that require operable snubbers during Modes 5 & 6 VAROA, 8 A Operating Reactors Branch 1, 63/09/30 Bpp 20777 161 24X Fichs. 50-334, 83/09/30, 8310130188

- --8310130195 Safety evaluation supporting Amend 72 to License DPR-66 • Office of Nuclear Reactor Regulation, Director 83/09/30 2pg 20777 166 24X Fiche 50-334,83/09/30,8310130188
- S310140171 Forwards interim regulatory position re compliance w/10CFR55 31(e) re reactor operator or senior reactor operator requalification Plant manager or designee should review each operator returning to licensed functions STAROBIECKI, R Division of Project & Resident Programs B3/09/30 CAREY, J J Buquesne Light Co 4pp 20745 004 24X Fiche 50-334,83/09/30.8310140171
- 8310210238 Forwards Rev I to "Reload Safety Evaluation, Beaver Valley Nuclear Plant Unit 1.Cycle 4 " CAREY, J J Duquesne Light Co 83/10/11 VAROA, 9 A Operating Reactors Branch I 3pp 20852 017 24X Fichs 50-334,83/10/11, 8310210238
- --6310210240 Rev 1 to "Reload Safety Evaluation.Beaver Valley Nuclear Plant Unit 1.Cycle 4 " PETRARCA.D J Duquesne Light Co 83/09/30 16pp 20852 020 24X Fiche 50-334;83/10/11,8310210238
- 83i0210351 Requests remittal of addl fees due for B2i123 & B307i4 requests for Tech Spec change re safety-related hydraulic anobsers & main feedwater piping, respectively MELLER.W O License Fee Management Branch B3/10/i4 CAREY, J J Duquesne Light Co ip 208B2 36i 24% Fiche 50-334,83/10/i4, B31021035i
- 8310270154 Forwards response to 830828 request for add1 info re N-1 loop operation Any asymmetries existing due to N-1 loop operation have little or no impact on power distribution, DNB limits & fuel integrity CAREY, J J Doquesne Light Co 83/10/21 VAROA, S A Operating Reactors Branch 1 10pp 20924 142 24X Fichs 50-334.83/10/21, 8310270154
- G Inspection reports, IE Bulletins & correspondence
- B310040400 Forwards two revised pages to "Reactor Vessel Inservice Insp Refueling Outage Core I-II Rept." submitted on 810205 CAREY, J J Duquesne Light Co 83/09/22 VARGA, 8 A Operating Reactors Branch I 1p 20619 029 24X Fiche 80-334,83/09/22, 8310040400
- --8310040411 Revised pages to "Reactor Vessel Inservice Insp Refueling Outage Core I-II Rept " * Duquesne Light Co 83/09/22 3pp 20619 031 24X Fiche 50-334,63/09/22,8310040400
- 8310060341 Forwards IE Enforcement Conference Rept 50-334/83-16 MARTIN.T T Division of Engineering & Technical Programs 83/09/22 CAREY.J J Duquesne Light Co 2pp 20646 131 24X Fiche 50-334.83/09/22.8310060341
- --8310060349 IE Enforcement Conference Rept 50-334/83-16 on 830701 Major areas discussed actions of radiological controls personnel during entry, use of untimely survey of radiation hazards & responsibility of workers to maintain safety practices MCBRIDE.M , SHANBAKY, M Region 1, Office of Director 83/09/15 2pp 20646.133 24X Fiche 50-334.83/09/22,8310060341
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fichs 50-000,83/09/26,8308300340.
- B308300342 IE info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8306300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " 8yc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345.
- 9309300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 59 Evaluation " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 93/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche, 50-000, 83/09/29, 8308300349.

- 8310200007 Forwards IE Insp Repts 50-334/83-17 & 50-334/83-23 on 830816-0912 & 0922-23 respectively Enforcement conference scheduled for 831011.per 830922 telcon STAROSTECKI.R Division of Project & Resident Programs 83/10/03 CAREY.J J Duquesne Light Co 3pp 20837 012 24X Fiche 50-334,83/10/03.8310200007
- --8310200010 IE Insp Rept 50-334/83-19 on 830816-0912 Noncompliance noted failure to perform surveillance test within required time period & RHR sys inoperable TROSHOBKI, W M . TRIPP.L E Region 1. Office of Director 83/09/29 17pp 20837 015 24X Fichs 50-334,83/10/03,8310200007
- --8310200021 IE Insp Rept 50-334/83-23 on 830922-23 Noncompliance noted: failure to follow administrative & managerial controls per Tech Specs re river water sys TROSHOBSKI, M M. TRIPP.L E Region 1. Office of Director 83/09/29 7pp 20837 032 24X Fiche 50-334.83/10/03.8310200007
- 8310190246 Forwards IE Insp Rept 50-334/83-18 on 830822-26 No moncompliance noted.

 MARTIN.T T Division of Engineering & Technical Programs 83/10/05 CAREY, J Duquesne Light Co 2pp 20818 121 24X Fiche 50-334, 83/10/05, 83
- --B310190251 IE Insp Rept 50-334/83-18 on B30822-26 No noncompliance noted Major areas inspected previous insp findings, personnel qualifications, organization & administration, QA program annual review, QA/QC program administration & audits B188ETT, P H . SHAUB, E T Region i. Office of Director. CAPHTON, D L Division of Engineering & Technical Programs B3/09/30 9pp 20818 123 24X Fichs 50-334, B3/10/05, B310190246
- 830830037B IE Info Notice 83-65, "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidate Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07, Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Novious Gases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York. Inc 117pp 21043:079 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" 8vc list encl JORDAN. E. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827-129 24X Fiche 50-000,83/10/11.8308300761.
- 8310180316 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/83-14 STARDSTECKIR Division of Project & Resident Programs 83/10/11 CAREY, J J Duquesne Light Co 1p 2080
- --8310180322 Responds to NRC 830823 itr re violations noted in IE Insp. Rept 50-334/83-14 Corrective actions river water header expansion joints clearly tagged utilizing stainless steel binding type tags
 GAREY, J. Duquesne Light Co. 83/09/22 STAROBTECKI, R. Division of Project & Resident Programs 2pp. 20806:235 24X
 Fiche 50-334,83/10/11,8310180316
- 8310270052 Discusses IE Insp Rept 50-334/83-16 on 830805 & forwards notice of violation. Violation re occupational radiation exposure categorized as Severity Level III Due to prompt reporting, no civil penalty will be issued MURLEY. T. E. Region 1, Office of Director 83/10/11 CAREY, J. Duquesne Light Co. 3pp 20924 115 24X Fiche 50-334,83/10/11,8310270052
- --8310270058 Natice of violation from inspon 830805 Nancompliance noted: radiation protection policies not properly implemented. * Region 1, Office of Director. 83/10/11 2pp 20924 118 24X Fiche 30-334.83/10/11.8310270052
- R Pariodic operating reports & related correspondence
- 8310190019 Monthly operating rept for Aug 1983 W/830907 ltr HOLTZ, J. L., CAREY, J. J. Duquesne Light Co. 83/09/07 NRC - No Detailed Affiliation Given 5pp. 20822.034 24X Fiche 50-334.83/09/07,8310190019

S Reportable occurrences, LERs & related correspondence

- 8310280010 Requests that LER 83-021/03L-O be withdrawn based on investigation which revealed that surveillance test complies w/requisite actions for limiting condition for Tech Spec 3 9 9 re core reload LACEY.W S Duquesne Light Co 83/09/29 ALLAN.J M Region 1, Office of Director 3pp 20934 104 24X Fiche 50-334.83/09/29.8310280010
- 8310060040 PND-I-B3-09BA strike of Intl Brotherhood of Electrical Workers possible after contract expires Union meeting to vote on licensee proposal set for B31005 Licensee contingencies in event of strike acceptable IRIPP.L , KEINIG.R Region L Defice of Director 83/09/30 lp 20647 084 24% Fiche 50-334,83/09/30,8310060040
- 8310130395 Notification of Bignificant Licanses Meeting 83-82 on 831041 in Hing of Prussia.PA to discuss separate events in which RHR sys & svc water pump inoperable TRIPP.L.E Region i. Office of Director 83/10/05 Region i. Office of Director 1p 20770 354 24X Fichs 50-334.83/10/05.8310130395
- 83i0250546 LER 83~022/03L~0 on 830707.flow rate of 36.056 cfm measured through train 8 filter bank Caused by plugged prefilter Prefilter replaced W/83i007 ltr LACEY.M 8 Duquesne Light Co 83/10/07 ALLAN, J M Region 1. Office of Director 4pp 20701 058 24x Fichs 50~334,83/10/07,8310250546
- 8310230595 LER 83~024/03L~0 on 830918, during core subcooling monitor surveillance test to check channel behavior, monitor found to be reading arroneously Caused by loose connector within unit Connector repaired W/831007 ltr DRUGA:R.J., LACEY,N S Duquesne Light Co 83/10/07 ALLAN,J M Region 1, Office of Director 4pp 20700 304 24X Fiche 50-334.83/10/07.8310250595

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8310060490 Releases public version of revised offnormal & emergency operating procedures
 FELTON.JM Division of Rules and Records 83/09/22 Document Management Branch ip 20650 299 24% Fiche 50-335,83/09/22,8310060490
- --8310060492 Forwards public version of revised offnormal & emergency operating procedures including Procedures 1-0910032 re auxiliary transformer offnormal operation & 2-1010030 re loss of instrument air WETHY,C M Florida Power & Light Co 83/09/12 Director's Office, Office of Inspection and Enforcement ip 20650 300 24X Fichs 50-335.83/09/22,8310060490
- ~-8310060494 Public version of revised offnormal & emergency operating procedures including Procedures 1-0910032 re auxiliary transformers offnormal operation & 2-1010030 re loss of instrument air PETRIE, L Florida Power & Light Co 83/09/01 60pp 20650 301 24X Fiche 50-335,83/09/22,8310060490
- 8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830827-0702 No noncompliance noted DANCE:H C Division of Project & Resident Programs 83/10/05 UHRIG.R E Florids Power & Light Co 2pp 20897 256 24X Fiche 50-335.83/10/05.8310250400.
- --8310250409 IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted Major areas inspected changes to emergency preparadness program, shift staffing & augmentation & dose calculations & assessments HUFFMAN.O N. BIODDART.P O Region R. Office of Director JENKINS.O R Division of Engineering & Operational Programs 83/09/30 10pp 20897 258 24X Fiche 50-335,83/10/05.8310250400
- H0170222 Forwards draft emergency operating procedure, "Alternate Shutdown" & indices "App R Cables W/Fire Area Routes" & "App R Equipment & Cables by Fire Area," par 10CFR30, App R, Section III 0 3 requirements UHR10.R E Florida Power & Light Co 83/10/07 EISENHUT, D Q Division of Licensing 9pp 20785 088 24X Fiche 50-335,83/10/07,8310170222
- -8310170224 Draft emergency operating Procedure 1-0030142, "Alternate Bhutdown" # Florida Power & Light Co. 83/09/27 14pp. 20785 097 24X Fiche, 50-335, 83/10/07, 8310170222

- --8310170230 "App R Cables W/Fire Area Routes," for Florida Power & Light Co.Bt Lucie Nuclear Power Station # Ebasco Services, Inc. (subs of Enserch Corp.) 83/09/28 104pp 20785 111 24X Fiche 50-935, 83/10/07,8310170222
- --0310170325 "App R Equipment & Cables By Fire Area," for Florida Power & Light Co.9t Lucie Nuclear Power Station

 * Ebasco Bervices, Inc. (subs of Enserch Corp.) 83/09/28
 171pp 20785 218 24X Fiche 50-335,83/10/07,8310170222
- P Operating license stage documents & correspondence
- \$310070182 Forwards Amend 61 to License DPR-67 & safety evaluation Amend revises limiting conditions for operations & surveillance requirements for 125-volt dc batteries in conjunction w/mods to sys SELLS, D C Operating Reactors Branch 3 83/09/22 UHRIG, R E Florida Power & Light Co 2pp 20680 294 24X Fiche 50-335,83/09/22,8310070182
- ~-8310070183 Amend 61 to License DPR-67, revising limiting conditions for operation & surveillance requirements for 125-volt dc batteries in conjunction w/mods to sys MILLER.J R Operating Reactors Branch 3 83/09/22 5pp 20680.258 24X Fiche 50~335,83/09/22,8310070182
- ~-B310070186 Safety evaluation supporting Amend 61 to License BPR-67 * NRC ~ No Detailed Affiliation Given B3/09/22 2pp 20680 265 24X Fithe 50-335,83/09/22,8310070182
- 8310110483 Forwards safety evaluation to NUREO-0737. Item II 9 3, "Post-Accident Sampling Sys (PASS)" Core damage estimate procedure including comparison of PASS data w/other plant parameters should be provided Item complete MILLER, J R Operating Reactors Branch 3 83/09/28 UHRIG. R E Florida Power & Light Co 13pp 20714 328 24X Fiche 50-335,83/09/28,8310110483
- B310130397 Summary of B30922 meeting w/util, Exxon & C-E re organization & content of final rept baing prepared for NRC review prior to restant Meeting to review entire final rept scheduled for mid-Dec Viewgraphs enti.

 SELLS, D E Decrating Reactors Branch 3 B3/10/05 Operating Reactors Branch 3 15pp 20771 012 24X Fichs 50-335, B3/10/05, B310130397
- 8310310125 Forwards safety evaluation based on review of 820100 submittal adopting C-E Duners Group analysis on TMI Action Item II K 2 17, "Potential for Voiding in RCS During Transients " Analysis acceptable Item complete MILLER, J R Operating Reactors Branch 3 83/10/05 UHRIG, R F Florida Power & Light Co 9pp 20965 332 24X Fiche 50-335,83/10/05,8310310125
- 8310130007 Discusses reactor vessel internals & thermal shield & plant recovery program Gutline of final rept of integrity & stability of internals w/o thermal shield, presented at B30922 meeting, encl Info submittal dates listed, UHRIGER E Florida Power & Light Co B3/10/06 MILLER, J R Operating Roactors Branch 3 15pp 20726, 274 24X Fiche 50-335, 83/10/06, 8310130009
- B3i0170088 Forwards Franklin Research Ctr "Operating Reactor PGRV Repts (F-37) TM1 Action Plan Requirements, C-E Duners Group (CEN-145), "technical evaluation rept & safety evaluation supporting reaponess to TM1 Items 11 K, 3 1 k II K 3.2 MILLER, J R Operating Reactors Branch 3 83/10/06 UHRIO, R E Florida Power & Light Co 3pp 20813 135 24X Fiche 50-335, 83/10/06, 8310170088
- --8310170092 Safety evaluation supporting C-E licensee responses to NUREQ-0737. Item II K 3 2. "Rept on PORVa"

 * NRC No Detailed Affiliation Given 83/10/06 62pp.
 20813-138 24X Fiche 50-335,83/10/06 8310170088
- B310180208 Application for amend to Licenses DPR-67 & NPF-16, revising facility organization chart & modifying definition of shift technical advisor function WILLIAMS.J W. Florida Power & Light Co B3/10/12 EIBENHUT, D 0 Division of Licensing Spp 20808:217. 24X Fichs 50-335,83/10/12.
- --8310180211 Proposed Tech Specs, revising facility organization chart & modifying definition of shift technical advisor function Safety evaluation encl * Fhorida Power & Light Co 83/10/12 App 20808 220 24X Fiche 50-335,83/10/12,8310180208.

- 8310180254 Forwards Rev 5 to recovery plan listing post-core support barrel approximate repair flushing time Remaining info submittal dates listed Thermal shield failure analysis will be submitted by 831027
 HILLIAMS, J W Florida Fower & Light Co 83/10/13 HILLER, J R Operating Reactors Branch 3 3pp 20802 341 24x
 Fiche 50-335,83/10/13.8310180254
- 8310240140 Responds to 830916 telcon request for add1 info on Franklin Research Ctr technical evaluation rept. Item 114 re Fisher & Porter pressure transmitter Transmitter inoperability will not affect safety sys if failure occurs WILLIAMS.J W Florida Power & Light Co 83/10/19 MILLER,J R Operating Reactors Branch 3 ip 20881 170 24X Fichs 50-335.83/10/19.8310240140
- 8310270120 Provides amended safety evaluation & determination of no significant hazards in response to concerns re NSHC determination submitted w/830825 proposed license amend re peaking factor & load follow power peaking penalty WILLIAMS, J W Florida Power & Light Co 83/10/21 EISENHUT, D & Davielon of Licensing 3pp 20924 109 24X Fiche 50-335,83/10/21,8310270120
- 8310280082 Provides schedule for submittal of core damage assessment procedure, eleventh criterion of NUREQ-0737. Item II B 3, "Post-Accident Sampling Sys." Procedure will be submitted prior to startup following Fall 1984 refueling outage WELLIAMB.J.W. Florida Power & Light Co. 83/10/25 MILLER, J.R. Operating Reactors Branch 3 ip 20934 103 24X Fiche. 50-335,83/10/25,8310280088
- 8310280153 Forwards proprietary "Failure Mechanism Analysis Program " Rept withheld (ref 100FR9 9(4)) WILLIAMS.J W Florida Power & Light Co 83/10/25 MILLER.J R Operating Reactors Branch 3 5pp 20929 276 24X Fiche 50-335.83/10/25.8310280153
- 9310310015 Forwards Class I & Class II Pees for 831012 application to amend Licenses DPR-67 & NPF-16 W/o encl WilLIAMB, J. W. Florida Power & Light Co. 83/10/26 EISENHUT, D @ Disvision of Licensing 1p 20947 105 24X Fiche 50-335.83/10/26, 8310310015.
- Q Inspection reports, IE Bulletins & correspondence
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310040447 Forwards IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830611-0710 No noncompliance noted.

 DANCE.H C Division of Project & Resident Programs 83/09/14.

 UHRIO,R E Florida Power & Light Co. 2pp 20625 285 24X

 Fiche: 50-335.83/09/14.8310040447
- --8310040454 IE Insp Repts 50-335/83-27 & 50-387/83-52 on 830611-0710 No noncompliance noted Major areas inspected maint & surveillance observations, plant operations, IE bullstins & circulars, LERS, BER followup & PAB item followup ELROD, B A , BIBD, H E Region 2. Office of Director JULIAN, C. Division of Project & Resident Programs. 83/09/13 17pp 20625 287 24X Fichs 50-335,83/09/14,8310040447
- U310040405 Confirms twicon re B31021 mgt meeting in Miami.FL to discuss results of first phase of SALF revism for period Jul 1982 June 1983 Proposed agenda enci LEWIS.R C Division of Project & Resident Programs 83/09/22 UHRIG.R E Floride Power & Light Co 2pp 20619 092 24X Fiche 50-000,83/09/22,8310040405
- B3iOO4045B Confirms B30916 decision to cancel NRC training assessment team B30926-30 insp Util will be informed of reschedule date.

 LEWIS.R C Division of Project & Resident Programs. B3/09/23 UHRIG.R E Florida Power & Light Co ip 20623 324 24X Fiche: 50-335,83/09/23,831004045B
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co. of New York, Inc 117pp 20754 022 24% Fiche. 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York. Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342

- 8310250615 Forwards IE Insp Repts 50-335/83-31 & 50-389/83-59 on B30830-0902 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/09/27 UHRIG.R E Florida Power & Light Co 2pp 20900 167. 24X Fiche 50-335,83/09/27,8310250615
- --8310250621 IE Insp Rept 50-335/83-31 & 50-387/83-59 on 830830-0902 No noncompliance noted Major areas inspected health physics instruments & equipment. GC audits, thermal shield disposel practices & actions on previous inspector followup items WRAY. J R Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs 83/09/23 Spp 20700 169 24X Fiche 50-335.83/09/27.8310250615
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation," Syc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24% Fichs 50-000,83/09/29,8308300349
- 8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/10/05. UHRIG,R E Florida Power & Light Co 2pp 20897 256 24X Fiche 50-335.83/10/05.8310250400
- --8310250407 IE Insp Repts 50-335/83-30 & 50-389/83-58 on 830829-0902 No noncompliance noted Major areas inspected changes to amergency preparedness program, shift staffing & augmentation & dose calculations & assessments
 HUFFMANJO N . STODDART.P O Region 2. Office of Director JENKINSJO R Division of Engineering & Operational Programs 83/09/30 10pp 20897 258 24% Fiche 50-335,83/10/05,9310250400
- 8310250516 Forwards IE Insp Repts 50-335/83-28 & 50-389/83-55 on 830711-0810 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/10/06 UMRIG, R E Florida Power & Light Co 2pp 20901 310 24X Fiche 50-335,83/10/06.8310250516
- --B310250528 IE Insp Repts 50-335/83-28 & 50-389/83-55 on 830711-0810. No noncompliance noted Major areas inspected maint & surveillance observation: plant operations. IE bulletins, circulars & info notices, LERs & startup testing ELROD-8 A , BIBB, H E , LANDIB, K Region 2, Office of Director B3/10/04 lipp 20901 312 24% Fiche 50-335.83/10/06.8310250516
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07. Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Hasponse (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752.
- 8308300759 IE Info Notice 83-47, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases "Svc list encl, JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp. 21043 075 24X Fichs 50-000,83/10/11:83083000759.
- B30B300761 IE Info Notice B3-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl.

 JORDAN, E L Division of Emergancy Preparedness & Engineering Response (Post B30103), B3/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827-127 24X Fichs 50-000, B3/10/11, B30B300761.
- R Periodic operating reports & related correspondence
- 8310170023 Monthly operating repts for Aug 1783 W/830715 ltr. ORANT.N W. WILLIAMS.J W. Florida Power & Light Co. 83/07/15. Office of Resource Management. Director. 17pp. 20822 017 24X Fiche 50-000,83/07/15.8310170023
- S Reportable occurrences, LERs & related correspondence
- 8310310456 Requests clarification of info provided in 820831 submittal reloss of all nonemergency ac power facility Response should be provided by 831115
 MILLER, J.R. Operating Reactors Branch 3 83/10/12 UHRIG, R.E. Florida Power & Light Co. 2pp. 20765 179 24X
 Fiche: 50-335, 83/10/12, 8310310458

- 8310270531 Notification of 831108 meeting w/util in Bethesda, MD to discuss failure mode analysis associated w/thermal shield & core barrel danage at facility SELLS, D E Operating Reactors Branch 3 83/10/13 MILLER, J R Operating Reactors Branch 3 2pp 20938 026 24X Fiche 50-335,83/10/13,8310270531
- DOCKET 30-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B310060035 Forwards matl for B31005 emergency response exercise Info needed for obtaining security & radiation protection clearances for NRC personnel requested by 830914. Exercise objectives for licensee encl W/o encl COUNSIL.N © Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.N © Northeast Utilities B3/08/08 MXRLEY,T E Resion 1. Office of Director 5pp 20647 245 24X Fiche 50-245,83/08/08,8310060035
- B310050205 Forwards draft exercise controller manual for upcoming 831005 full-scale emergency preparedness exercise Info re NRC personnel participation & roles requested to allow inclusion in final manual W/o encl COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSILW G Northeast Utilities B3/08/22 MURLEY, T E Region 1. Office of Director 2pp 20647 035. 24X Fiche 50-245.83/08/22.8310060205
- 8310120259 Forwards "Re-Entry & Recovery Scenario" section of emergency preparedness exercise controllers manual, Limited distribution requested until completion of 831005 exercise. COUNSIL.W 9 Northeast Nuclear Energy Co (subs. of Northeast Utilities) 83/09/27 MURLEY, T E Region 1, Office of Director 25pp 20693 145 24X Fiche: 50-245, 83/09/27, 8310120259
- J Insurance & indemnity information
- B310270461 Forwards Endorsements B9 & 80 to NELIA Policy NF-173 & MAELU Policy NF-32, respectively. Endorsement 4 to NELIA Certificates NF-15 & NF-16 & MAELU Certificates MF-15 & MF-16 & MF-16 & SINISI, J M Harsh & McLennan, Inc 83/10/21 SALTZMAN, J D Assistant Director for State & Licensee Relations 7pp 20923; 126 24X Fiche 50-245, 83/10/21, 8310270461
- P Operating license stage documents & correspondence
- B310310017 FDIA request for documents re integrated leak rate tests for listed facilities to be placed in FDR CDNNER, L. Affiliation Unknown B3/05/02 NRC No Detailed Affiliation Given is 21004 270 24X Fiche 50-000, B3/05/02, B310310017
- 8310110543 Forwards BER re util 791231.810621 & 820602 responses to NUREG-0737. Item II.B.1. "RCS Vents" & "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737. Item II.S 1)." final technical evaluation rept HILLER.J R Operating Reactors Branch 3 B3/09/20 COUNSIL.W & Northeast Nuclear Energy Co (subs of Northeast Utilities) 11pp 20712 180 24% Fichs 50-336.83/09/20.8310110543
- --B306080065 "Belected Operating Reactor Issues Program II'RCS Vents (NUREO-0737, Itam II, B 1)," final technical evaluation rept HELD, J T. Energy Incorporated * Lawrence Livermore Laboratory FIN A-0250 TF-349/0812A 83/03/02 ALBERTHAL, O NRC No Detailed Affiliation Given 6pp 20712 191 24X Fiche 50-336,83/09/20,6310110543,
 - 10110466 Forwards sefety evaluation re util responses to NUREO-0737, Item II K 3 1. "Automatic PORV Isolation," Item II, K 3 2, "Rept on PORVs" & OE Owners Group generic rept Review complete. Responses acceptable MILLER, J R Operating Reactors Branch 3 83/09/23 COUNSIL, M. 9 Northeast Nuclear Energy Co (subs of Northeast Utilities). 14pp 20712 114 24% Fiche 50-336/83/09/23.8310110466
 - 8307200260 "Operating Reactor PORV Repts (F-37), THI Action Flan Requirements, C-E Owners Group (CEN-145), " technical evaluation rept OVERBECK, G, J, JENKING, S M, DELOAIZO, T J Franklin Institute/Frenklin Research Center NRC-03-81-130 TER-C5506-409 83/07/18 CHOM, E, NRC - No Detailed Affiliation Given 52pp 20712-128 24X Fiche 50-336,83/09/23,8310110466

- B310170556 Requests rev to confirmatory order contained in B30314 ltr for NUREG-0737 Items II F 1 i & II F 1 2 to specify new B40101 completion date Replacement of Geiger-Mueller in detectors will be completed by B40101 COUNSIL,W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W 9 Northeast Utilities B3/09/27 HILLER,J 9 Operating Reactors Branch 3 2pp 20782 070 24X Fichs 50-245,83/07/27,8310170656
- B31013D137 Approves B30731 request on behalf of C-E Owners Group for withholding from public disclosure App A to "Response to Guestions on RCS Asymmetric Loads Evaluation Program," per 10CFR2 790 GRUTCHFIELD, D Operating Reactors Branch 5 B3/10/03 LUNDVALL, A E Baltimore Gas & Electric Co 6pp 20777 065 24X Fiche 50-000, B3/10/03, B310130137
- 8310170504 Application to amend Licenses DPR-21 & DPR-65 revising Tech Spec Section 6 rs administrative controls to comply w/final rule on licensed operator staffing at nuclear power units per 44FR31611 GUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/10/04 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 3pp 20784 137 24X Fiche 50-245,83/10/04,8310170504
- --8310170508 Proposed Tech Bpec Section & re administrative controls for licensed aperator staffing & qualification of radiation protection manager * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/10/04 Bpp 20784 140 24% Fiche 50-245,83/10/04,8310170504
- 8310240103 Forwards Amend 88 to License DPR-65, safety evaluation to request for FR publication Amend modifies Tech 8pec 3 1 2 2 to be consistent w/Tech Spec 3 5 2 requirements re boric acid tanks
 LEECH, P H Operating Reactors Branch 3 83/10/07 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2p; 20903/176 24X Fiche 50-336,83/10/07,8310240103
- --831024010B Amend 8B to License DPR-65, modifying Tech Spec 3 1 2 2 to be consistent w/Tech Spec 3 5 2 requirements that both boric acid tanks & corresponding facility dependent flow paths are operable in modes in which operability required by ECCS MILLER, J R Departing Reactors Branch 3 83/10/11. 9pp 20903 178 24X Fiche, 50-336, 83/10/07, 8310240103
- --B310240109 Bafety evaluation supporting Amend 88 to License DFR-65 * Office of Nuclear Reactor Regulation, Director 83/10/11 2pp 20703 187 24X Fichs 50-334,83/10/07,8310240103
- ~~8310240113 Requests FR publication of notice of consideration of issuance of amend to License DPR-63 & proposed NBNC determination & apportunity for hearing on 820924 request re operability of boric acid tanks
 MILLER.J.R Operating Reactors Branch 3 83/10/07 KREUTZER.P N Operating Reactors Branch 3 1p 20903 189 24X Fiche 50-336,83/10/07.8310240103
- 8310180409 Forwards listed revs to "Corporate Organization for Nuclear Incidents (CGNI) Procedure Manual." per Section V of App E to 10CFR50 W/o encl COUNSIL.H O Connecticut Yankee Atomic Power Co CGUNBIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) CGUNBIL.H O Northeast Utilities 83/10/12 EIRENHUT.D O Division of Licensing. 1p 20803.173 24X Fichs.50-000.83/10/12.
- 8310200187 Requests add1 time to provide info re 6-inch containment purgs & vent valve operability. Info will be provided by 831026 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 83/10/12 HILLER.J R (Berating Reactors Branch 3 1p. 20834 150 24X Fiche 50-336,83/10/12,8310200187
- B310200227 Application for amend to License DPR-65 revising Tech Specs repressurizer level band COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities B3/10/12 MILLER, JR Operating Reactors Branch 3, 4pp, 20833 040 24X Fiche 50-336.83/10/12.8310200229
- --8310200233 Proposed Tech Specs re pressurizer level band, * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/10/31 3pp 20833 044. 24X Fiche 50-336,83/10/12,8310200229

- 8310288112 Denies 830906 request for 120-day extension to respond to Generic i.tr 83-28 re generic implications of Salum ATHS events NRC review schedule does not permit extension Response due by 831105 CRUTCHFIELD.D Operating Reactors Branch 5 83/10/26 COUNBIL.W Connecticut Yankee Atomic Power Co COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 20727 261 24X Fiche 50-000,83/10/26,8310280112
- G Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests" Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- B308300345 TE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300045
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFRSO 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20714 324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svr list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp. 20882 026 24X Fichs 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11 8308300759.
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827-129 24X Fiche 30-000,83/10/11,8308300761.
- R Periodic operating reports & related correspondence
- 6310190207 Monthly operating rept for Aug 1983 N/830915 ltr 01880N.J. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E J. Northeast Utilities 83/09/14 Office of Resource Management. Director 7pp 20818 114 24X Fiche 50-336,83/09/14,8310190207
- B310200167 Monthly operating rept for Sept 1783 W/B31014 ltr GIBSON, J. MROCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) B3/10/13 Office of Resource Management, Director 7pp 20834 071 24% Fiche 30-326, B3/10/13, B310200167.
- S Reportable occurrences. LERs & related correspondence
- 8310070163 Part 21 rept re potential defects in molded case of 100amp frame, multi-pole E & HE series circuit breakers Initially reported on 830902 ESHARDT. J V Geuld. Inc 83/09/26 HURLEY.T E Region 1. Office of Director 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163
- B310070301 Potential Part 21 rept re underrange characteristic of Model N-EliOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
 BERBERIAN.H J Foxboro Corp 83/09/30 Director's Office of Inspection and Enforcement ilpp 20651 064 24X
 Fiche 50-000,83/09/30,8310070301

- 8310240269 Responds to 830906 memo re AEOD/T314, "Improper Size of Inlet Piping to Primary Safety Valves at Millstone 2 & Calvert Cliffs 1 & 2 " Flow limiting devices for code safety valves 1 7/8-inch bore diameter discussed EISENHUT.D G Division of Licensing 83/10/18 THOMPSON.H L Division of Human Factors Safety 1p 20907 338 24X Fiche 50-000, 83/10/18,8310240269
- DUCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8310040252 Forwards technical support ctr & emergency operations facility floor plans, route maps to emergency response facilities & telephone listings Requests update of info & submittal of personnel access documents
 DANCE.H C Division of Project & Resident Programs 83/09/12
 STELART.W L Virginia Electric & Power Co. 16pp 20613 049 24X
 Fiche 50-000.83/09/12,8310040252
- 8310070403 Releases public version of revised corporate emergency response plan
 FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch is 20675 182 24% Fiche 50-800, 83/09/30, 8310070403
- --B310070418 Public version of revised corporate emergency response plan. W/830614 ltr
 STEWART,M L Virginia Electric & Power Co 83/05/15
 O'REILLY,J P Region 2, Office of Director 114pp 20675 183, 24X Fiche 50-000,83/09/30,8310070403
- 8310110186 Releases public version of radiological emergency response plan FELTON, J.M. Division of Rules and Records 83/10/05 Document Management Branch 1g 20701 020 24X Fiche 50-000,83/10/05, 8310110186
- --8310110190 Public version of radiological emergency response plan W/B30621 ltr * Virginia Electric & Power Co 83/06/30 O'REILLY, J.P. Region 2. Dffice of Director 301pp 20701'021, 24X Fiche 50-000, 83/10/05, 8310110186
- 8310180277 Forwards changes to security program Changes withheld (ref 10CFR73 21). STEWART: W.L. Virginia Electric & Power Co. 83/10/06 MCQUIRE, D.R. Division of Emergency Preparadness & Materials Safety 1p 20807 035 24X Fiche 50-338, 83/10/06, 8310180277
- 8310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tech Spets to reflect addition of new fire protection sys STEWART,W L. Virginia Electric & Power Co. B3/10/07. DENTON,W R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3. 3pp. 20717-126. 24X Ficher 50-339.83/10/07.8310130103
- --B310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys

 * Virginia Electric & Power Co. B3/10/07 15pp 20719,130 24% Fichs 50-338.B3/10/07.B310130103

G Adjudicatory correspondence

- 8310190200 Updates status of full core reserve at facility.Full core reserve will be lost during outage scheduled for early 1986 if fuel performs properly during future operating cycles.

 MAUPIN.H W Hunton & Williams MAUPIN.H W Virginia Electric & Power Co 83/10/13 HOLFE.S J Atomic Bafety and Licensing Board Panel 3pp 20818 135 24X Fiche: 50-038.83/10/13.8310190200
- 8310240163 Ack receipt of 831013 ltr updating status of full-core reserve & indicating possible agreement w/DDE re dry cask demonstration program Notification of efforts to expedite case disposition requested by 831104 MOLFE.8 J Atomic Safety and Licensing Appeal Panel. 83/10/20 MAUPIN.8 W Hunton & Williams ip 20880.038 24X Fiche 50-338.83/10/20.8310240463.
- 8310260299 Summarizes 831012 meeting w/NRC.util & Louise County re
 Louise County contentions Mutually agreeable proceeding
 schedule recommended following publication of environ
 analysis & BER Related correspondence
 MAUPIN.H W Hunton & Williams HAUPIN.H.W Virginia Electric &
 Power Co 83/10/20 WICLES 9 Atomic Bafety and Licensing Board
 Panel 2pp 20910 322 24X Fiche 50-338,83/10/20,8310260299.

- 8310270317 Order extending tame for Commission review of ALAB-741 to 831108 CHILK 5 J Office of the Secretary of the Commission 83/10/25 Commissioners ip 20923 188 24X Fiche: 50-338,83/10/25, 23/10/2017
- 8310270326 Order accepting as amended recommendations by counsel restipulated contentions & discovery schedule.

 HOLFE: 8 J Atomic Bafety and Licensing Board Panel 83/k0/25 2pp
 20923. 180 24% Fiche 50-238,83/10/25,8310270326

M Antitrust correspondence

- 8310200289 Suppl to B30310 application to amend Licenses NPF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in appropriate OL sections Cooperative will be partial owner of facilities Supporting documentation encl
 STEMART.H L. Virginia Electric & Power Co. B3/10/17 DENTON, H R
 Diffice of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 524pp. 2083i 159 24X
 Fiche 50-338,83/10/17,8310200287
- P Operating license stage documents & correspondence
- B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CONNERS. Affiliation Unknown. B3/05/02 NRC No Detailed Affiliation Given ip 21004 270 24X Fiche 50-000, B3/05/02, B310310017
- 8310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be place in PDR & list of facilities for which repts are unavailable.
 FELTON.J H Division of Rules and Records 83/07/06 CDNNER.L Affiliation Unknown ip 21004 271. 24X Fiche. 50-000.83/07/06.8310310031
- 8310040587 Application for amend to Licenses NPF-4 & NPF-7, changing fractional thermal power multiplier from 0 2 to 0 3 for 387 8 F operation 8TEWART, W L Virginia Electric & Power Co 83/09/29. DENTON, H R. Office of Nuclear Reactor Regulation, Director MILLER, J. R Departing Reactors Branch 3 lipp 20626 262 24X Fiche: 50-338, 83/09/29, 8310040387
- --8310040590 Proposed Teck Specs changing fractional thermal power multiplier from 0.2 to 0.3 for 587 B F operation * Virginia Electric & Power Co 83/09/29. 12pp 20626 273 24X Fichs 50-338.83/09/29.8310040587
- 8310120114 Advises that extension until 831007 required to complete review & approval of proposed inservice testing program for pumps & valves

 BTEWART, W L Virginia Electric & Power Co 83/10/04. DENTON, H R. Office of Nuclear Reactor Regulation. Director HILLER, J R. Operating Reactors Branch 3 ip. 20676-150 24X

 Fiche, 50-338, 83/10/04, 8310120114
- 8310130143 Application for amend to Licenses NPF-4 & NPF-7 adding exemption which allows engineering evaluation to be performed if failure occurs on steam generator/reactor contant gump support snubber. Amend fee encl.

 BTEWART. H. L. Virginia Electric & Power Co. 83/10/04 DENTON. H. R. Office of Nuclear Reactor Regulation, Director MILLER, J. R. Operating Reactors Branch 3. App. 20749 040 24X

 Fiche 30-338,83/10/04,8310130145
- --B310130148 Proposed Tech Specs adding exemption to allow performance of engineering evaluation if failure occurs on steam generator/reactor coolent pump support snubber to determine if generic deficiencies exist.
 * Virginia Electric & Power Co. B3/10/04 49pp 20749 044. 24% Fiche: 50-338.83/10/04.8310130145.
- ISIO12014O Forwards revised inservice testing program for pumps & valves Revs clarify component listings & relief requests Programs will be fully implemented by 840501 W/o encl STEMART.W.L. Virginia Electric & Fower Co 83/10/05 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3, 2pp. 20695:279, 24X Fiche: 50-338,83/10/05,8310120140.
- 310130103 Application for amend to Licenses MPF-4 k NPF-7 changing Tech Specs to reflect addition of new fire protection sys STENART. W.L. Virginia Electric & Power Co. 83/10/07. DENYON, H.R Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Brench 3. 3pp. 20719 126. 24X Fiche: 50-338,83/10/07,8310130103

- --B310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys * Virginia Electric & Power Co B3/10/07 15pp 20719 130 24x Fiche 50-338.83/10/07.8310130103
- 8310180440 Requests extension to 840601 for submittal of simulator portion of licensed operator requalification program STEMART.W L Virginia Electric & Power Co 83/10/12 DENION.H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 2pp 20802 124 24X Fiche 50-338,83/10/12.8310180440
- 8310190112 Application to amend Licenses NPF-4 & NPF-7, reflecting reorganization in nuclear operations dept.security dept & change in responsibilities & title of pracutive vice president-power STEMART. H. L. Virginia Electric & Power Co. 83/10/13 DENTON. H. Office of Nuclear Reactor Regulation, Director MILLER, J. R. Operating Reactors Branch 3 Dp. 20821 104 24X Fiche 50-338,83/10/13.8310190112
- --8310190130 Proposed Tech Spec changes re reorganization in nuclear operations dept. security dept & responsibilities & title of executive vice president-power # Virginia Electric & Power Co # 83/10/13 15pp 20821 107 24% Fiche 50-338.83/10/13.8310190112
- B310180309 Forwards status rept of progress on resolving rerating motor operated valves (MOV) & plan for addl work per QDC 17, committed to in B30607 ltr Preliminary review determined 74 of 130 MOVs will not need to operate when voltage below 90% STEWART.W L Virginia Electric & Power Co 83/10/14 DEMTDN,H R . MILLER, JR Operating Reactors Branch 3 4pp 20806 291 24% Fiche 50-338,83/10/14,8310180309
- B310190043 Forwards "VEPCO NOMAD Code & Model " Rept is one of series discussing nuclear reload licensing & core follow support capabilities STEWART.W L Virginia Electric & Power Co B3/10/14 DENTON,H R Office of Nuclear Reactor Regulation, Director EISENHUT,D G Division of Licensing 2pp 20822 335 24X Fiche 50-000,83/10/14,8310190043
- --8310190057 "VEPCO NOMAD Code & Model "
 BOWMAN, B M , DZIADOSZ, D , BERRYMAN, R M Virginia Electric & Power
 Co VEP-NFE-1 B3/09/30 118pp 20822 337 24X
 Fiche 50-000, 83/10/14, 8310190043
- 8310200289 Suppl to 830310 application to amend Licenses NPF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in appropriate OL sections, Cooperative will be partial owner of facilities Supporting documentation encl.

 STEMART.W.L. Virginia Electric & Power Co. 83/10/17 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3 824pp. 20831:159, 24X Fiche 50-338,83/10/17.8310200289
- B310270300 Suppls B30325 response to B30111 request for add1 info re NUREO-0737. Item II B 3, "Post-Accident Sampling " Interim cure damage assessment procedure in use until Westinghouse Ouners Group methodology completed by end of 1983 STEWART.N L. Virginia Electric & Power Co 83/10/20 DENTON, N R Office of Nuclear Resettor Regulation, Director EIBENNUT, D G Division of Licensing 2pp 20923.193 24X Fiche 50-000, 83/10/20, 83/10/203000
- G Inspection reports, IE Bulletins & correspondence
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310040550 Responds to IE Bulletin 83-04, "Nonconforming Matls Supplied by Tube Line Corp Facilities "No subj matls in use in safety-related sys SIEWART+W L Virginia Electric & Power Co 83/09/16 O'REILLY, J.P. Region 2, Office of Director ip 20622, 314 24X Fiche 80-338,83/09/16,8310040550.
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Syc list encl.
 JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Poet 830103) 83709/26 Consolidated Edison Co of New York, Inc. 117pp 20754-022, 24% Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/09/26 Consolidated Edison Co. of New York, Inc. 116pg. 20777 210 24X Fiche, 50-000, 83/09/26, 8308300342

- @30@300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
 - ercl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp. 20716-324 24X Fiche 50-000.83/09/29.8308300349
- 8310250414 Forwards IE Insp Repts 50-338/83-22 & 90-339/83-22 on B30815-19 & 0919-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs B3/10/05 BTEMART.W L Virginia Electric & Power Co 2pp 20897 227 24X Fiche 50-338.83/10/05.8310280414
- --8310250428 IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & O919-20 No noncompliance noted Major areas inspected liquid & gaseous effluent releases effluent control instrumentation, reactor coolant water quality & NUREO-0737 HRAY, J R. Region 2: Office of Director BARR, K P Division of Engineering & Operational Programs. 83/09/30 9pp 20897, 229 24X Fiche 50-338, 83/10/05, 8310250414
- 8310250508 Responds to 830628 ltr requesting deletion of Violation B noted in IE Insp Repts 50-336/83-12 & 50-339/83-12 re radiation area posting of auxiliary bldg Entrance not properly gosted Citation stands Present posting adequate O'REILLY, J P Region 2, Office of Director 83/10/06 STEWART, W L Virginia Electric & Power Co 2pp 20902 07: 24X Fiche 50-338,83/10/06,8310250508
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300789
- B30B300761 IE Info Notice B3-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 120pp 20827,129 24X Fiche 50-000, B3/10/11, B30B300761
- R Periodic operating reports & related correspondence
- B310190002 Monthly operating repts for Aug 1983 W/830915 ltr SCHMITEABDRF, G. STEWART, W.L. Virginia Electric & Power Co B3/09/02. MALLER, N M Office of Resource Management, Director 14pp 20823.095 24X Fiche 50-338.83/09/02.8310190002
- S. Reportable occurrences, LFRs & related correspondence
- 8350070328 LER 83-057/03L-0 on 830903 & 12, Fire Door 871-19 between emergency diesel Room iH & turbine bldg would not latch Caused by Paulty latching mechanism & misalignment Latch repaired & realigned W/830928 ltr HARRELL, E W Virginia Electric & Power Co 83/09/28 O'REILLY, J P Region 2, Office of Director 2pp. 20652 224 24X Fichs. 50-338. 83/09/28. 8310070328
- 8310070301 Potential Part 21 rept re underrange characteristic of Kodel N-E110M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified
 BERBERIAN.M J. Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20651 064 24X
 Fiche: 30-000, 83/09/30, 8310070301
- 83:0140141 LER 83-058/03L-0 on 830808, incorrect alignment of charging high head safety injection pump breakers & control switches discovered Caused by inadequate procedural guidance Alignment corrected We31005 itr HARRELL, E W Virginia Electric & Power Co. 83/10/05 0'REJLLY, J P Region 2, Office of Director. Spp 20745 090 24X Fiche: 50-338, 83/10/05, 8310140161

- 8310170091 Forwards repts on 821205 main generator failure & progrietary & nonproprietary repts on seven main transformer failures occurring between 801129 & 821205 Proprietary rept withheld (ref 100FR2 790)
 STEMART, M L. Virginia Electric & Power Co. 83/10/05 DENTON, H R. Office of Nuclear Reactor Regulation, Director HILLER, J R. Operating Reactors Branch 3. 2pp. 20787-207. 24X
 Fiche 50-338.83/10/05,8310170091
- --8310170098 "Generator Rept on VEPCO North Anna Unit 1 Transformer Incident of 821205 ", WEYANT, P A , DALDWIN, M S , WARD, R T Virginia Electric & Power Co 83/10/05 16pp 20789 209 24X Fiche 50-338,83/10/05, 8310170091
- --8310170107 Nonproprietary version of "Transformer Rept on Events at North Anna Power Station" COSSAART, J. PETRIE, E. BKODOLUND, J. Westinghouse Electric Corp 83/06/16 274pp 20787 226 24X Fiche 50-338,83/10/05, 8310170091
- 8310140082 PND-I-83-105 on 831007, seismic event occurred in northeastern US w/magnitude of 5 2 on Richter scale in NY & 4 0 in NH No damage to equipment identified GALLO,R M , GREENMAN,E G Region I, Defice of Director 1p 20766 116 24X Fiche 50-000,83/10/07,831014008R.
- 8310210058 LER 83-059/03L-0 on 830918, while at 100% power, inner seel on containment personnel hatch failed to pass periodic test following containment entry Caused by dirt buildup on seel Seel cleaned relubricated & tested W/831013 ltr HARRELL-E W Virginia Electric & Power Co 83/10/13 0'REILLY, J P Region 2, Office of Director. 2pp 20855 266 24X Fiche 50-338,83/10/13.8310210058
- DOCKET 50-337 NORTH ANNA POHER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8310040252 Forwards technical support ctr & emergency operations facility floor plans, route maps to emergency response facilities & telephone libitings Requests update of info & submittal of personnel access documents DANCE, H C Division of Project & Resident Programs B3/09/12 STEMAT, W L Virginia Electric & Power Co 16pp 20613.049, 24X Fiche 50-000,83/09/12,8310040252
- 8310070403 Releases public version of ravised corporate emergency response plan FELTON, J M Division of Rules and Records 83/09/30 Document Management Branch 1p 20675 182 24X Fiche 50-000,83/09/30,8310070403
- --8310070418 Public version of revised corporate emergency response plan.
 W/830614 ltr
 STEMART,W L. Virginia Electric & Power Co 83/05/15
 O'REILLY,J F Region 2, Office of Director 114pp 20675-183,
 24X Fiche 50-000,83/09/30.8310070403
- 8310110186 Releases public version of radiological emergency response plan FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20701 020 24X Fiche: 50-000, 83/10/05, 8310110186
- --8310110190 Public version of radiological emergency response plan W/830521 ltr * Virginia Electric & Power Co 83/06/30 D'REILLY, J P Region 2. Office of Director 30ipp 20701, 021 24X Fiche 50-000, 83/10/05, 8310110186
- 8310180277 Forwards changes to security program Changes withheld (ref 10GFR73 21) 8TEWART, W L Virginia Electric & Power Co 83/10/06. MCGUJRE, D R. Division of Emergency Preparedness & Materials Safety. 1p 20807 035 24X Fiche 50-338,83/10/06.8310180277
- B310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tech Specs to reflect addition of new fire protection sys STEWART, M. L. Virginia Electric & Power Co. B3/10/07. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 20719:126 24X Fiche. 50-338, 83/10/07. B310130103
- ---8310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys + Virginia Electric & Power Co 83/10/07 15pp. 20719 130 24X Fiche 50-338,83/10/07,8310130103

G Adjudicatory correspondence

- 8310190200 Updates status of full core reserve at facility Full core reserve will be lost during outage scheduled for early 1986 if fuel performs properly during future operating cycles HAUPIN, M W Hunton & Williams MAUPIN, M W Virginia Electric & Power Co 83/10/13 MOLFE, 8 J Atomic Safety and Licensing Board Panel 3pp 20818 135 24% Fichs 50-338.83/10/13.8310190200
- 8310240163 Ack receipt of 831013 ltr updating status of full-core reserve & indicating possible agreement w/DDE re dry cask demonstration program Notification of efforts to expedite case disposition requested by 831104 MOLFE, S. J. Atomic Safety and Licensing Appeal Panel 83/10/20 MAMPIN N W Hunton & Williams ip 20890 038 24X Fiche 50-338,83/10/20,8310240163
- 8310260277 Summarires 831012 meeting w/NRC.util & Louisa County re
 Louisa County contentions. Mutually agreeable proceeding
 schedule recommended following publication of environ
 analysis & SER. Related correspondence.
 MAUPIN. M Whuton & Milliams MAUPIN. M Wirginia Electric &
 Power Co 83/10/20 MOLFE.S J Atomic Safety and Licensing Board
 Panel 2pp 20910.322 24x Fiche.50~338,83/10/20,8310260297
- 83102/0317 Order extending time for Commission review of ALAB-741 to 831108 CHILK,8 J Office of the Secretary of the Commission 83/10/25 Commissioners. Ip 20923.188 24X Fiche.30-338.83/10/25, 8310270317.
- 8310270324 Order accepting, as amended, recommendations by counsel restigulated contentions & discovery schedule MOLFE, S. J. Atomic Befety and Licensing Board Panel 83/10/25 2pp. 20923 180 24X Fiche 50-338, 83/10/25, 8310270326.

M Antitrust correspondence

- 8310200289 Suppl to 830310 application to amend Licenses NFF-4 & NPF-7, adding name of Old Dominion Electric Cooperative in appropriate CL tections Cooperative will be partial owner of facilities. Supporting documentation entl STEWART, W L. Virginia Electric & Power Co. 83/10/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 524pp 20831 159 24X Fiche. 50-338, 83/10/17, 8310200289
- P Operating license stage documents & correspondence
- 8310120016 Add1 response to FOIA request for document re problems w/ Tech Epecs applying to RCS leakage determinations in PWRs Forwards App A documents
 FELTON, J M Division of Rules and Records B3/07/07. VOIGT, H H LeBosuf, Lamb, Leiby & MacRae 2pp. 20751-001 24%
 Fichs 50-000,83/07/07.8310120016
- --8007290669 Forwards SER suppl.Revision i.re periodic leak testing of pressure isolation valves Replaces 800702 transmittel XNIGHT, JP Assistant Director for Comp & Structures Engineering (Pre 830201). 80/07/16 TEDESCO.R L Assistant Director for Licensing 1p 20751 043, 24X Fiche 50-000,83/07/07,8310120016
- --8007270676 SER suppl, Revision 1, reperiodic leak testing of pressure isolation valves Additions to Tech Specs acceptable.

 * Assistant Director for Comp & Structures Engineering (Pressure) 80/07/16 Spp 20751 044 24x Fiche 50-000.83/07/07, 8310120016.
- 8310030625 Advises of refund of fees sent for review of 830418 application for extension to complete License Condition 2.0(21)(i)(iv) Fees refunded since application no longer applicable & will not be received.
 MILLER.W.O. License Fee Hanagement Branch 83/09/27. STEWART.W.L. Virginia Electric & Power Co. ip 20407 340 24X Fiche: 30-339.83/09/27.8310030625
- B310040587 Application for amend to Licenses NPF-4 & NPF-7, changing fractional thermal power multiplier from 0 2 to 0 3 for 587.8 F operation, BTEMART.W L Virginia Electric & Power Co. B3/09/29, DENTON.H R. Office of Nuclear Reactor Regulation, Director. MILLER.J R Operating Reactors Brench 3 11pp 20626 262. 24X Fichs.50-336,83/09/29,8310040587.
 - 8310040390 Proposed Tech Specs changing fractional thermal power multiplier from 0.2 to 0.3 for 587 8 F operation * Virginia Electric & Power Co. 83/09/29 12pp 20626 273, 24X Fichs 50-038 83/09/29,8310040587

- 8310120114 Advises that extension until 831007 required to complete review & approval of proposed inservice testing program for pumps & valves STEMART.W L. Virginia Electric & Power Co. 83/10/04 DENTON.H R. Office of Nuclear Reactor Regulation. Director MILLER.J R. Operating Reactors Branch 3. ip. 20696-150. 24X Fiche 50-338.83/10/04.8310120114
- 8310130145 Application for amend to Licenses NPF-4 & NPF-7 adding exemption which allows engineering evaluation to be performed if failure occurs on steam generator/reactor coolant pump support snubber Amend fae encl STEWART, W.L. Virginia Electric & Power Co. 83/10/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3 4pp. 20749 040. 24X Fiche 50-338,83/10/04,8310130145
- --B310130148 Proposed Tech Specs adding examption to allow performance of engineering evaluation if failure occurs on steam generator/reactor coolant pump support snubber to determine if generic deficiencies exist

 Virginja Flectric & Power Co B3/10/04 49pp 20749 044 24x Fiche 50-338,83/10/04,8310130145
- B310120140 Forwards revised inservice testing program for pumps & valves Revs clerify component listings & relief requests
 Programs will be fully implemented by 840301 W/o encl
 STEMART: W L Virginia Electric & Power Co 83/10/05 DENTON.H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 2pp 20495 279 24X
 Fiche 50-338,83/10/05.8310120140
- 8310130103 Application for amend to Licenses NPF-4 & NPF-7 changing Tach Space to reflect addition of new fire protection sys STEWART, W L Virginia Electric & Power Co 83/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 20719 126 24% Fiche 50-338,83/10/07,8310130103
- --8310130107 Proposed Tech Spec changes to reflect addition of new fire protection sys.

 * Virginia Electric & Power Co 83/10/07 15pp 20719 130 24x
 Fiche 50-338.83/10/07.8310130103
- 8310180440 Requests extension to 840601 for submittal of simulator portion of licensed operator requalification program ETEMART, W. L. Virginia Electric & Fower Co. 83/10/12 DENTON: H. R. Office of Nuclear Reactor Regulation, Director MILLER, J. R. Operating Reactors Branch 3 2pp 20802 124 24X Fiche 50-338,83/10/12,8310180440
- 8310190112 Application to amend Licenses NPF-4 & NPF-7, reflecting reorganization in nuclear operations dept security dept & change in responsibilities & title of executive vice president-power
 STEMART, M L. Virginis Electric & Power Co. 83/10/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director MILLER, J R. Operating Reactors Branch 3 Jpp. 20821 104 24X Fiche 50-338, 83/10/13, 8310190112
- --8310190130 Proposed Tech Spec changes re reorganization in nuclear operations dept, security dept & responsibilities & title of executive vice president-power # Virginia Electric & Power Co 83/10/13 18pp 20821 107 24X Fiche 50-338,83/10/13,8310190112
- 8310180309 Forwards status rept of progress on resolving rerating motor operated valves (MOV) & plan for addl work per ODC 17, committed to in 830607 ltr Preliminary review determined 74 of 130 MDVs will not need to operate when voltage below 90% STEWART, W L Virginia Electric & Power Co 83/10/14 DENTON, H R . MILLER, J R Operating Reactors Branch 3 4pp 20806 291 24% Fichs 50-338,83/10/14.8310180309
- 8310170043 Forwards "VEPCO NGMAD Code & Model " Rept is one of series discussing nuclear reload licensing & core follow support capabilities | ETEWART, W.L. Virginia Electric & Power Co. 83/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 20822 335 24X Fiche 50-000, 83/10/14, 8310190043
- --8310190057 "VEPCO NOMAD Code & Model "
 BOWMAN, S. M. Virginia Electric & Power Co., VEP-NFE-1 83/09/30
 118pp 20822 337 24X Fiche 50-000, 83/10/14, 8310190043
- 8310200289 Suppl to 830310 application to amend Licenses NPF-4 & NPF-7. adding name of Old Dominion Electric Cooperative in appropriate OL sections Cooperative will be partial owner of facilities Supporting documentation encl STEMART.W L. Virginia Electric & Power Co 83/10/17 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3. 324pp 20831 157 24X Fiche. 50-338,83/10/17.8310200289

DOCKETED ITEMS

- 8310270300 Supple 830325 response to 830111 request for addl info re NUREC-073/. Item II 8 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Westinghouse Ounters Group methodology campleted by end of 1983 STEHART. W. Uirginia Electric & Power Co. 83/10/20 DENIGN. H R Office of Nuclear Reactor Regulation, Director App. 20923 193 24% Fiche 50-000,83/10/20,8310270300
- @ Inspection reports. IE Bulletins & correspondence
- 8310040550 Responds to IE Bulletin 83-06, "Nonconforming Matls Supplied by Tube Line Corp Facilities" "No subj matls in use in 310040550 Responds to IE Willetin 83-06, "Nonconforming Matis Supplied by Tube Line Corp Facilities" No subj matis in use in safety-related sys
 STEMART.W.L. Virginia Electric & Power Co. 83/09/14 D'REILLY, J.P.
 Region 2. DFfice of Director ip 20622 314 24X
 Fiche 50-33B,83/09/16,8310040550
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wolder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Consolidated Edison Co of New 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co of New York, Inc 11689 20777 P10 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Natice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 118pp 20778 001 24% Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 83102504i4 Forwards IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No moncompliance noted BANCE, H C Division of Project & Resident Programs 83/10/05 81EHART, W L Vinginia Electric & Power Co 2pp 20897 227 Fiche 50-338,83/10/05,8310250414 03/10/05 1997 24X
- --8310250428 IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & O919-20 No noncompliance noted Major areas inspected liquid & gaseous effluent releases, effluent control instrumentation, reactor coolant water quality & NUREG-073/WRAY, J R Region 2. Office of Director BARR, K P Division of Engineering & Operational Programs 83/09/30 9pp 20897 239 24X Fiche 50-338,83/10/05,8310250414
- B31025050B Responds to 83062B ltr requesting deletion of Violation B noted in IE Insp Repts 50-338/83-12 & 50-339/83-12 re radiation area posting of auxiliary bldg Entrance not properly posted Citation stands Present posting adequate O'REILLY.J P Region 2, Office of Director 83/10/06 STEWART.W Virginia Electric & Power Co 2pp 20902 071 24% Fiche 50-338,83/10/06.8310250508 STEWART, W (
- B308300378 IE Info Notice B3-45, "Surveillance of Flow in RTD Bypass Loops Verd in Westinghouse Plants " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Respanse (Post B30103) B3/10/07 Consolidate Edison Co of Net Vorl. Inc. 74pp 20827 213 24X Fiche 50-000.B3/10/07.B30B30037B
- 9308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Syc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consultdated Edison Co of Nel York, Inc 79pp 20882 026, 24X Fiche, 50-000, 83/10/07, 8308300752 79рр
- 3308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noticus Cases " Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83710711 Consolidated Edison Co. of New
 York, Inc. 117pp 21043 075 24X Fiche 50~000,83/10/11.8308300759
- 1308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761 Response (Post 830103) York, Inc. 120pp 20

- R Periodic operating reports & related correspondence
- B310190002 Monthly operating repts for Aug 1983 W/B30915 ltr SCHMITENDORF, G. STEWART, H. Virginia Electric & Power Ct B3/09/02 HALLER, N.M. Office of Resource Management, Dire 14pp 20823 095 24X Fiche 50-338,83/09/08,8310190002 Director
- S Reportable occurrences, LERs & related correspondence
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EiiGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, G of Inspection and Enforcement 11pp 2045t 064 24% Fiche 50-000, 83/09/30, 8310070301 Director's Office, Office
- 8310170091 Forwards repts on 821205 main generator failure & proprietary & nonproprietary repts on seven main transformer failures occurring between 801129 & 821205 Proprietary rept withheld (ref 100FR2 790)
 STEWART, W. L. Virginia Electric & Power Co. 83/10/05. DENI Office of Nuclear Reactor Regulation. Director. MILLER, J.R. Operating Reactors Branch 3. 2pp. 20769 207. 24X
 Fiche 50-338,83/10/05.8310170091 DENTON. H R
- --8310170107 Nonproprietary version of "Transformer Rept on Events at North Anna Power Station" COSSAART, J. PETRIE, E. SKODOLUND, J. Westinghouse Electric Corp 83/06/16 276pp 20789 226 24% Fiche 50-338.83/10/05. 8310170091
- B310210047 LER S3-069/03L-0 on B30913, individual rad position indicator for rad K-02 in control bank A exceeded zoro step position by 133 steps Caused by personnel error Indicator adjusted W/831012 ltr
 HARRELL,E W Virginia Electric & Power Co B3//0/12 O'REILLY, J P
 Region 2, Office of Directon 2pp 20855 302 24X
 Fiche 50-339,83/10/12,8310210047
- 8310250066 Responds to 830615 request for addl info re status of vandor repair or redesign or provisions for obtaining other qualified resistance temp detectors & proposed schedule for installation installation scheduled for Oct 1984
 STEWART.W.L. Virginia Electric & Power Co. 83/10/19 DENTON.W.R. Office of Nuclear Reactor Regulation, Director MILLER.J.R. Operating Reactors Branch 3 2pp. 20894-176. 24X
 Fichs 50-339.83/10/19.8310250066
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT P A Application/construction stage documents & correspondence
- 8308300357 Board Notification 82-105A forwards evaluation of authordry Board Notification B2-109A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Cangon i & 2, Fermi 2 & Callaway EISENHUT, D & Division of Licensing B3/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000, B3/09/29, B308300357
- 8310130329 Forwards Rev 2 to "Inservice lesting Program for Enrico Fermi Unit 2" Rev to testing program for pumps & valves incorporates necessary mods & clarifications.per NRC 830316 ltr & 830517-18 meetings Related info encl TAUBER.H Detroit Edison Co 83/10/04. YOUNGBLOOD.B J. Licensi Branch 1 7pp 20723 287 24X Fiche 50-341.83/10/04.83i0130229.
- --8310130232 Rev 2 to Procedure DET-16-0201, "Inservice Testing Program for Enrico Formi Unit 2" KIN-J.W., CLAUS8.J M NUTECH Engineers, Inc 83/08/04 160pp 20723 294 24X Fiche 50-341,83/10/04.8310130229
- 8310120098 Requests that NRC defer issuance of proof & review Tech Specs to allow incorporation of current test data & to minimize need to modify specs at later date JENS.W H Detroit Edison Co 83/10/05 YOUNGBLOOD.B J Licens Branch 1 ip 20696 184 24X Fiche 50-341.83/10/05.8310120098
- 83i0120190 Responds to Generic Ltr 83-24 re TMI Action Item 1 G.i,
 "Special Low Power Testing & Training " Util will comply
 w/BHR Cumers Group position w/special test incorporated
 FSAR App H will be revised
 JENS-W H Detroit Edison Co 83/10/05 YOUNGBLOOD, B J. Licensing
 Branch 1 2pp 80495 333 R4X Fiche; 50-341, 83/10/05, 8310120190
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT, D. G. Division of Licensing 83/10/06 PALLADING, N. J. Commissioners 31pp 20818 001 24% Fiche 50-000, 83/10/06,

M308300771

- 8310180470 Forwards revs to nuclear operations training program description, updating BIO603 submittal Future revs to training plan will be documented in Section 13 2 of FSAR TAUBER, H Detroit Edison Co 83/10/12 YOUNGLOOD, B J Litensing Branch I 10pp 20802 041 24X Fiche 50-341.83/10/12.8310180470
- 8310210052 Advises that Preoperational Test PRET 74102 001, "Control Ctr HVAC" will be initiated by 831101 Rev J to test procedure sent to chief of test programs section AGOSTI, F.E. Detroit Eduson Co. 83/10/13 KONKLIN, J.F. Region 3. Office of Director ip 20855 301 24X Fiche. 50~341,83/10/13,8310210052
- 8310210281 Informs that Preoperational Test FRET T4600 001 re standby gas treatment will be initiated on 831101 Test procedure sent to Chief of Test Programs Section A00871. F.E. Detroit Edison Co. 83/10/13 KONKLIN. J.E. Region 3. Office of Director 1p. 20848 212 24X Fiche 50-341.83/10/13. 8310210281
- 8310170589 Forwards Amend 51 to amended & substituted application for license, consisting of Amend 51 to FBAR LANDGRAF,L C LeBourf, Lamb, Leiby & MacRae 83/10/14 DENTUN.H R Office of Nuclear Reactor Regulation, Director 1p 20791 009 24X Fiche 50-341,83/10/14,8310170589
- --8310170594 Amend 51 to amended & substituted application for license, consisting of Amend 51 to FBAR
 HEIDEL, C M Detroit Edison Co B3/10/12 lp 20791 010, 24X
 Fiche 30-341,83/10/14,8310170589
- 8310240105 Notification of 831019 meeting w/util in Bethesda,MD to discuss environ qualification of equipment LYNCH,M D Licensing Branch 1 83/10/18 YOUNGBLOOD,D J Licensing Branch 1 3pp 20891 350 24x Fiche 50-341,83/10/18, 8310240105
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310130018 Forwards SGRT qualification summary of equipment list update & response to SEGR 3 (NUREC-0798) open items
 TAUBER.H Detroit Edison Co 83/10/04 YOUNOBLOOD.R J. Licensing
 Branch 1 48pp 20725 123 24% Fiche 50-341.83/10/04.8310130018
- F. Security, medical, emergency & fire protection plans
- 8310170629 Forwards IE Insp Rept 50-341/B3-17 on 830701-0831 & notice of violation NNOPAC Region 3. Office of Director 83/09/28 WELLS, D A Detroit Edison Co 2pp 20782 080 24X Fiche 50-341.83/09/28, 8310170829
- --8310170643 IE Insp Rept 50-341/83-17 on 830701-0831 Noncompliance noted work performed on emergency diesel generator [] voltage regulator w/illegible & unreadable PN21 & electrical single line sketch had no refs or description BYROM, P MRKER M E . LITTLE, B H Region 3, Office of Director 83/09/28 | 10pp 20782 083 24X Fiche 50-341,83/09/28,8310170629
- 8310180027 Releases public version of revised radiological emergency response preparedness plan & revised radiological emergency response preparedness procedures FELTON, J M Division of Rules and Records 83/10/13. Document Management Branch 1p 20814 304. 24X Ficha 50-341,83/10/13,8310180027
- --8310180034 Forwards public version of Rev 2 to radiological emergency response preparedness plan & revised radiological amergency response preparedness procedures
 JENS, W H Detroit Edison Co. 83/10/04 YOUNGBLOOD, B J. Licensing Branch 1 1p 20814-305 24% Fiche: 50-341, 83/10/13, 8310180029
- -8310180037 Public version of Rev 2 to radiological emergency response preparedness plan

 Detroit Edison Co 83/09/21 300pp. 20814 306 24X
 Fiche 50-341/83/10/13, 8310180029
- -8310180042 Public version of revised emergency plan implementing procedures including Procedures EP-102 rs unusual event, EP-103 rs alert & EP-104 rs site area emergency, # Detroit Edison Co 83/09/21 797pp. 20815,252 24X Fichs: 50-341,83/10/13,8310180029
- 110310342 Forwards IE Preoperational Safeguards Insp Rept 50-341/83-23 on 830926-30 No noncompliance moted AXELBON W L. Region 3: Office of Director, 83/10/26, WELLS, D A Detroit Edison Go 2pp 20961-317, 24X Fichs 50-341,83/10/26, 8310310342.

- --B310310347 IE Preuperational Safeguards Insp Rept 50-341/83-23 on 830926-30 No noncompliance noted Major areas Inspected implementation, installation & operability of security programs Details withheld (ref 10CFR/3 21) MADEDA; T J , KNICELEY, J R , CREED, J R Region 3, Office of Director 83/10/25 2pp 20961 319 24X Fiche 50-341,83/10/26,8310310342
- G Adjudicatory correspondence
- 8310040274 Order extending time until 83100/ for Commission to act to review ALAB-730 CHILK: 3 J Office of the Secretary of the Commission 83/09/JD Commissioners ip 20612 361 24X Fiche 50-341,83/09/30. 83100402/4
- B310120405 Order extending time until B31017 for Commission to act to review ALA9-730 CHILK, S J Office of the Secretary of the Commission B3/10/07 Commissioners 1p 20699 024 24X Fiche 50-341, B3/10/07, B310120405
- 8310280046 Informs that Commission declined to review Decision ALAB-730 Review pariod expired Decision became final agency action on 831017 CHILK:S J Office of the Secretary of the Commission 83/10/27 MINOCK:J I Affiliation Unknown 1p 20935 060 24X Fiche 50-341.63/10/27.8310280066
- H General correspondence
- 8310200109 Informs that OK Earle became util supervisor of licensing on 831001 L Schuerman former supervisor of licensing, promoted to supervisor, sys & plant engineering EARLE, O K Detroit Edison Co. 83710/10 YDUNGBLOOD, B J Licensing Branch 1 1p 20837 102 24X Fiche 50-341.83/10/10.8310200107
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310170589 Forwards Amend 51 to amended & substituted application for license.consisting of Amend 51 to FSAR LANDQRAF,L C LeBoeuf, Lamb, Leiby & MacRae 83/10/14 DENTON.H & Office of Nuclear Reactor Regulation, Director 1p 20771 009 24X Fishe 50-341.83/10/14.8310170589
- --8310170994 Amend 51 to amended & substituted application for license. consisting of Amend 31 to FSAR HEIDEL, C.M. Detroit Edison Co. 83/10/12 tp. 20791 010 24X Fiche 50-341,83/10/14,83101/0589
- --8310170400 Amené 51 to FSAR * Detroit Edison Co 83/10/31 488pp 20791 011 24X Fiche 50-341,83/10/14,8310170589
- @ Inspection reports. IE Bulletins & correspondence
- 8310050472 Forwards IE Insp Rept 50-341/83-18 on 830822-26 No noncompliance noted LITTLE.W S Region 3. Office of Director 83/09/23 WELLG.A Detroit Edison Co 2pp 20628 352 24X Fiche 50-341.83/09/23, 8310050492
- --8310050497 IE Insp Rept 50-341/83-18 on 830822-26 No noncompliance noted Major areas inspected action taken on 10CFR50 55(e) items. IE bulletins. IE circulars, previous insp findings & electrical design review WILLIAMS. C C , AHMED. I H , NAIDU, K R Region 3. Office of Director 83/09/22 Bpp 20628 354 24X Fiche 50-341,83/09/23,830050492
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification fests" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York Inc. 117pp 20754 022 24X Fiche 50-000,63/09/26,8308000340
- 8308300342 IE info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 30-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-i Differential Relays " Syc list ancl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26. Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

- 8310170629 Forwards 1E Insp Rept 50-341/83-17 on 830701-0831 & notice of violation NNOP.R C Region 3. Office of Director 83/09/28 WELLS.D A Detroit Edison Co 2pp 20/82 080 24X Fiche 50-341.83/09/28, 8310170829
- --8310170636 Notice of violation from insp on 830701-0831 KNOP.R C Region 3. Office of Director 83/09/28 1 20782 082 24% Fiche 50-341.83/09/28.8310170629
- --8310170643 IE Insp Rept 50-341/83-17 on 830701-0831 Noncompliance noted work performed on emergency diesel generator 11 voltage regulator w/illegible & unreadable PN21 & electrical single line sketch had no refs or description BYRDN.P M . PARKER M E . LITILE.B H . Region 3. Defice of Director 83/09/28 10pp 20782 083 24X Fiche 50-341.83/09/28, 8310170629
- B30B300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24% Fiche 30-000,83/09/29,830B300347
- 8306300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Sv. list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Int. 76pp 20827 213 24X Fiche 50-000, 83/10/07,8308300378
- 8308300752 IC Info Notice 83-66, "Fatality at Argentine Critical Facility " Syc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103), 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24% Fiche 50-000,83/10/07,8308300752
- --8310120311 Supplemental response to NRC 830713 ltr re violations noted in IE lnsp Rept 50-341/83-07 Corrective actions adequate measures adopted to assure proper control of plant configuration

 WELLS.D A Detroit Edison Co 83/09/21 SPESBARD.R L Division of Engineering 7pp 20701 013 24X Fiche 50-341,83/10/07,8310120305
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Cases " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117sp 21043 075 24% Fiche 50-000,83/10/11,8308300759
- 83083007&1 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 199 24X Fiche 50-000,83/10/11,83083007&1
- B310180287 Clarifies NRC position reprocedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months AKELSON,W L., Region 3, Office of Director B3/10/14 WELLS,D A Detroit Edison Co. 7pp 20806/282 24X Fiche 50-341,83/10/14, B310180289
- 0310310342 Forwards IE Preoperational Safeguards Insp Rept 50-341/83-R3 on 830926-30 No noncompliance noted AXELSON.W L Region 3, Office of Director 83/10/26 WELLS, D A Detroit Edison Co 2pp 20961 317 24X Fichs 50-341,83/10/26, 83103103042
- --8310310347 IE Preoperational Safeguards Insp Rept 50-341/83-23 on B30926-30 No noncompliance noted Major areas inspected implementation, installation & operability of security programs Details withheld (ref 10CFR73 21) MADEDA:1 J. KNICELEY, J.R., CREED, J.R., Region 3, Dffice of Director 83/10/25 2pp 20961 319 24X Fiche 50-341,83/10/26,8310310342

- S Reportable occurrences, LERs & related correspondence
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-E116M transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN M J Forboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp 2051 064 24X Fichs 50-000,03/09/30.8310070301
- 8310120224 Interim deficiency rept re-cracked & broken puffer piston rods in Brown Boveri 5HK 250/350, 1200/2000A circuit breakers Initially reported on 830317 Insps to be conducted at maint intervals Cracked assemblies will be replaced DUVALL, D D Brown Boveri Corp. (subs of Brown Boveri & Co., Ltd.) 83/10/05 DEVOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 20693 130 24X Fiche 50-341,83/10/05,8310120224
- 83i0250114 Final deficiency rept. Item 86 re missing Swaglok fittings in reactor vessel Initially reported on 821229 Missing Swaglok instrument line plug assemblies replaced All plug keepers removed & discarded & Swaglok fittings tightened HELLS.D A Detroit Edison Co 83/10/07 KEPPLER.J @ Region 3. Office of Director 4pp 20876 268 24X Fiche 50-341.83/10/07, 8310250114
- B310210066 Interim deficiency rept re Wismer & Becker inconsistent implementation of UT procedures for flued head structures Initially reported on B30909 Investigation continuing WELLS D A Detroit Edison Ca B3/10/10 KEPPLER. J G Region 3, Office of Director 2pp 20858 190 24X Fiche 50-241.83/10/10, B310210066
- B310270447 Final deficiency rept. Item 14 re action taken on RHR HX relief valves Initially reported on 830503 Listed design changes to reduce water hammer problem implemented Commitment satisfied WELLS.D A Detroit Edison Co 83/10/21 XEPPLER, J G Region 3 Office of Director 2pp 20923 080 24X Fichs 50-341.83/10/21, 8310270447
- B310270487 PNO-III-B3-101 on B31021. licensee employee discovered suspicious looking package near equipment on third level of turbine bldg Portion of bldg evacuated & HI B4ste Police notified Package dismantled & confirmed nonexplosive CREED. J. Region 3, Dffice of Director 83/10/21 ip 20922 001. 24X Fiche 50-341.83/10/21,83/0270487
- DOCKET 50 -344 TROJAN NUCLEAR PLANT
- F Security, medical, emergency & fire protection plans
- 6310060258 Forwards info re radiological emergency plan 1983 annual exercise 870EHL,D J Portland General Electric Co 83/07/18 MARTIN,J 3 Region 5, Diffice of Director 5pp 20645 202 24X Fiche 50-344, 83/07/18.8310060258
- --B310060261 Forwards scenario for B31005 radiological emergency plan exercise WITHERB, D D Portland General Electric Co 83/08/26 MARTIN, J B Region 5, Office of Director 55pp 20645 207 24X Fiche 50-344, B3/07/18, B31006025B
- B310060099 Forwards Rev I to 1983 radiological emergency plan exercise scenario
 WITHERS, II D. Portland General Electric Co. B3/09/15 MARTIN, J.B.
 Region 5. Office of Director. 36pp. 20647 196. 24X
 Fiche: 50-344, 83/09/15, 8310060099
- 8310060471 Forwards info re 1983 radiological emergency plan exercise WITHERB.B D Portland General Electric Co 83/09/15 MARTIN, J B Region 5, Office of Director. 186pp 20641 042 24X Fichs 50-344,83/09/15,8310060491
- 8310170063 Advises of disapproval of exception to habitability requirements for emergency operation facility (EOF), per 820503 ltr Plans for establishing EOF per Suppl I to NUREG-0737 (Generic Ltr BR-33) requested by 831128 EISENNUT, D G Division of Licensing 83/09/29, WITHERS B D Portland General Electric Co 3pp. 20798 035 24X Fiche 50-344,83/09/29,8310170063
- 8310130102 Releases public version of revised radiological emergency plan & procedures manuel FELTON, J. M. Division of Rules and Records 83/10/06 Document Management Branch 1p 20751 340. R4K Fiche 50-344,83/10/06,8310130102

- --8310130104 Public version of Rev 3 to Radiological Emergency Plan & Procedures Manual P6E-1008
 Portland General Electric Co 83/09/30 720pp 20751 341 24% Fiche 50-344, 83/10/06, 8310130102
- 8310180362 Forwards IE Enforcement Conference Rept 50-344/83-26 on 830909 No moncompliance noted MARTIN, J B Region 5, Office of Director 83/10/14 WITHERS, B D Portland General Electric Co Ip 20801 336 24X Ficher 50-344,83/10/14,8310180362
- --B3101B0367 IE Enforcement Conference Rept 50-344/B3-26 on 830909 Major areas discussed violations identified during B30620-24 & 0726-28 insp of compliance w/IOCFR50 App R Sections III G.J.L & 0 SCONN.K., DODDS.R T Region 5, Office of Director BISHOP.T W Division of Resident. Reactor Project & Engineering Programs B3/10/12 5pp 20801 337 24X Fiche 50-344.83/10/14.8310180362
- B31027051B Releases public version of notification that amend to radiological emergency plan forwarded under separate cover FELTON J M Division of Rules and Records B3/10/21 Document Management Branch 1p 2092B 361 24X Fiche 50-344,83/10/21, B31027051B
- --8310270521 Submits public version of notification that Amend 3 to Radiological Emprency Plan PGE-1008 forwarded under separate cover Amended plan continues to meet stds of 100FR47(b) & requirements of 100FR50. App E WITHERS. B D Portland General Electric Co 83/10/04 MARKIN, J. D Region 5. Office of Director ip 20928 362 24X Fich # 50-344.83/10/21.83102/0518
- J Insurance & indemnity information
- 8310140257 Forwards Endorsement 62 to NELIA Policy NF-225 & Endorsement 52 to MAELU Policy MF-86
 JOHANBEN, E Portland General Electric Co 83/10/06 SALTZMAN, J
 Office of State Programs, Director 3pp 20761 336. 24X
 Fiche 50-344,83/10/06.8310140257
- P Operating license stage documents & correspondence
- B310250591 Forwards Btd Order for DOE Hork "Operating Reactors Licensing Actions - Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco " ADAMS. C Energy, Dept of FIN 8-8559 B3/09/16 MARTIN, J B Region 5, Office of Director ip 20900 124 24X Fiche 50-000,83/09/16,8310250591
- --B310250600 Std order for DDE Work "Operating Reactors Licensing Action Tack Spacs for Hydraulic & Mackanical Snubbers for Trojan & Rancho Saco," issued to LLL MARTIN, J B Ragion 5, Office of Director MACRUSKY, J Lawrence Livermore Laboratory FIN 8-8559 83/08/31 1p 20900 125 24X Fiche 50-000,83/09/16,8310250591
- ---8310250625 Forwards project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Hechanical Snubbers for Trojan & Rancho Seco "STUARTIK J Lawrence Livermore Laboratory FIN B-8562 83/08/18 BISHOP,T W Region 5. Office of Director 1p 20900 126 24X Fiche 50-000.83/09/16.8310250591
- ---B31025063i Project & budget proposal for NRC work "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rencho Seco" CLELAND.L L. HMITE.R., JOHNBON.J M Laurence Livermore Laboratory FIN B-6552. B3/06714 PADOVAN.H L., ZHETZIG.@ Region 5. Office of Director 2pp Fiche 50-312,83/09/16.8310250591
- 310070133 Forwards, for consideration, project & budget proposal, "Operating Reactors Licensing Actions Tech Specs for Hydraulic & Mechanical Snubbers for Trojan & Rancho Seco Facilities"

 TUSZKA. M.E. Lawrence Livermore Laboratory FIN 9-8562 83/09/20 31810P.T W Region 3, Office of Director, 10pp 20659 025 24X 71che 50-000,83/09/20,8310070133
- 10180608 Forwards requests for add1 info re spent fuel rack splacement & spent fuel pool storage expansion structural optics to complete review of 830801 application to increase rool capacity Response needed within 45 days of 1tr receipt fILLER, U R Operating Reactors Branch 3, 83/09/30 WITHERS, B D optiand General Electric Co. 5pp 20817 342, 24x iche.50-344,83/09/30.8310180608

- B310110187 Forwards License Change Application 96, amending License NPF-1 re offsite & onsite organizations WITHERS:B D Portland General Electric Co B3/10/04 MILLER: J R Operating Reactors Branch 3 1p 20665 287 24X Fiche 50-344,83/10/04.8310110189
- --8310110176 License Change Application 96 amending License NPF-1 re offsite & onsite organizations WITHERS, B D Portland General Electric Co 83/10/04 jp 20665 288 24X Fiche 50~344, 83/10/04, 8310110189
- --8310110201 Proposed changes to Tech Specs re offsite & onsite organizations
 * Portland General Electric Co 83/10/04 /pp 20665 289 24x
 Fiche 50-344,83/10/04,8310110189
- 8310200188 Forwards License Change Application 95 requesting amend to License NPF-1.changing Tech Spec 4 & 2 P d to allow more practical method of verifying available flow from containment spray additive tank MITHERS.B D Portland General Electric Co 83/10/14 MILLER.J R Operating Reactors Branch 3 1p 20893 069 24X Fiche 50-344.83/10/14.8310200188
- --8310200192 License Change Application 95 requesting amend to License NPF-1, changing Tech Spec 4 6 2 2 d to allow more practical method of verifying available flow from containment spray additive tank UTHER9, B D Portland General Electric Co 83/10/14 Spp 20833 070 24X Fiche 50-344,83/10/14,8310200188
- ~-8310200198 Proposed changes to Tech Spec 4 6 2 2 d to allow more practical method of verifying available flow from containment spray additive tank

 * Portland General Electric Co 83/10/14 2pp 20833 0/5 24x
 Fiche 50-344.63/10/14.8310200188
- 8310260237 Forwards "Trojan Nuclear Plant Cycle & Startup & Power Escalation Physics Testing Rept " WITHERS: B D Portland General Electric Co 83/10/14 MARTIN, J N Region 5, Office of Director ip 20912 024 24X Fiche 50-344,83/10/14,8310240237
- --8310260242 Forwards "Trojan Nuclear Plant Cycle 6 Startup & Power Escalation Physics Testing Rept," & WCAP-10336, "Trojan EOC-5 Onsite Fuel Exam " WCAP-10336 withheld TODD.A J Portland General Electric Co B3/10/14 MARTIN, J B Region 5, Office of Director ip 20912 025 P4X Fiche 50-344.83/10/14.8310260237
- --8310260246 "Trojan Nuclear Plant Cycle & Startup & Power Escalation Physics Testing Rept " * Portland General Electric Co PGE-1040 83/10/31 60pp 20912 026 24X Fiche 50-344.83/10/14.8310260237
- 8310310299 Forwards "Reactor Containment Bldg Integrated Leak Rate Test Final Rept 830629-0702 " WITHERS, B D Portland General Electric Co 83/10/17 MILLER, J R Operating Reactors Branch 3 ip 20957 097 24X Fiche 50-344,83/10/17,8310310299
- --9310310301 "Reactor Containment Bldg Integrated Leak Rate Test, Final Rept 830627-0702" * Portland General Electric Co PGE-1023-(83) 83/10/01 583pp 20957 099 24X Fiche 50-344, 83/10/17, 8310310299
- G Inspection reports, IE Bulletins & correspondence
- 830B300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Guelification Tests" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes "Svc list encl JORDAN" E Wrisson of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,830830034P
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-i Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345

- B30B300349 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation " Svc list
 - enc) JORDAN,E L. Divisson of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New Yark, Inc. 115pp 20716-324 24% Fiche 50-000.83/09/29,8308300349
- 830B300378 | E Info Notice 83-65. "Burveillance of Flow in RTD Bypass Loops Vsed in Westinghouse Plants " Svt list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24% Fiche 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8310120245 Ack receipt of 830930 ltr informing NRC of steps taken to correct violations noted in 830902 rept of insp on 830728-0805 WENSLAMBKI,F.A Region 5, Office of Director 83/10/07 WITHERS, D Portland General Electric Co ip 20492 141 24X Fiche 50-344,83/10/07.8310120245
- ~-8310120247 Responds to NRC 830902 ltr re violations noted in IE inspon 830728-0805 Corrective actions environ contractor instructed to perform specified analyses within 8-day period required by Tech Specs WITHERS, B. D. Portland General Electric Co. 83/09/30 MARTIN, J. B. Region 5, Office of Director 2pp. 20692 162 24X Fiche 50~344, 83/10/07, 8310120245
- 8308300759 IE Info Notice 83-57. "Emergency Use Respirator Matl Defect Causes Production of Noxious Cases " Byc list encl JURDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidate Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- B308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list ancl JGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 6310180362 Forwards IE Enforcement Conference Rept 50-344/83-26 on 630907 No noncompliance noted MARTIN. J.B. Region 5. Office of Director 83/10/14 WITHERS, B.D. Portland General Electric Co. ip 20801 336 24X Fiche 50-344,83/10/14,8310180362
- --B310180367 IE Enforcement Conference Rept 50-344/83-26 on 830909 Major areas discussed violations identified during 830620-24 & 0726-28 insp of compliance w/10CFR50 App R Sections III 0.3.4. & 0 SCOMN.K. DDDDS,R T. Region 5, Office of Director BISHOP,T W Division of Resident.Reactor Project & Engineering Programs B3/10/12 5pp 20801 337 24X Fishe 50-344.83/10/14.8310180362
- A Periodic operating reports & related correspondence
- B310170039 Monthly operating rept for Aug 1983 W/830709 ltr KENT.O J. YUNDT.C P Portland General Electric Co B3/09/08 Office of Resource Management. Director 5pp 20823 279 24X Fiche 50-344,83/09/08,8310190039
- B310310299 Forwards "Reactor Containment Bldg Integrated Leak Rate Fest, Final Rept B30629-0702." WITHERB.B D Portland General Electric Co B3/10/17 MILLER, J R Operating Reactors Branch 3. 1p. 20957, 097 24X Fiche 50-344
- --8310310301 "Reactor Containment Bldg Integrated Leak Rate Test,Final Rept 830629-0702" * Portland General Electric Co POE-1023-(83) 83/10/31 583pp 20957,079. 24X Fiche 50-344,83/10/17,8310310299.
- S. Reportable occurrences, LERs & related correspondence
- B3102B0079 Responds to FOIA request for AEOD rept. "Loss of Bhutdown Gspling & Bubsequent Boron Dilution at San Onofre 2." dtd B30425 & documents re fewl rod degradation problem described in IE Info Notice B2-27 Forwards App A documents FEX.TON, J.M. Division of Rules and Records. B3/07/28. HIATT, S.L. Ohio Citizens for Responsible Energy. 2pp 20942 156 24X Fiche 50-000, G3/07/28. G310280079

- --8310280136 Forwards safety evaluations prepared by licensee & Region V re loose fuel polists & clad pieces in RCS CREMS. J L Division of Resident Reactor Project & Engineering Programs 82/07/22 CLARK, A Operating Reactors Branch 3 6pp 20962 220 24X Fiche 50-000.83/07/28.8310280079
- --8310280138 Safety evaluation re loose fuel pellets & clad pieces in RCS Strong evidence exists that no more than 20 pellets remain in RCS Licensee performed comprehensive evaluation of proposed operation Related info encl # Region 5, Office of Director 82/07/21 12pp 20962 226 24X Fiche 50-000,83/07/28,8310280079
- 8310030440 EN-83-060 on or about 830929, notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licenses Action based on inadequate reassessment of fire protection features, per 10CFR30. App R CRAIG. J., AXELRAD. J. Office of International Programs. Director 83/09/26 1p 20602 089 24X Fiche 50-344,83/09/26,8310030440
- 8310140246 LER 83-013/03L-0 on B3090B, train A boric acid transfer pump deenergized & train B boric acid transfer pump mistakenly valved out Caused by personnel error in preparation of tag-out procedure personnel disciplined W/B31003 ltr BAIR.0 G , YUNDT.C P. Portland General Electric Co E3/10/03 MARTIN.J B Region 5. Office of Director 3pp 20761 342. 24X Fiche 30-344.83/10/03.8310140246
- 8310200165 Part 21 rept re static temp calibr check on transmitters Initially reported on 831013 Caused by irregular setpoint for pressurizer pressure safety injection function New 1.829 psig setpoint recommended RAME.E.P. Westinghouse Electric Corp. 83/10/13 DEYDUNG, R.C. Director's Office, Office of Inspection and Enforcement 2pp. 20834 078 24X Fiche 50-000.83/10/13.8310200165
- 8310250444 LER 83-014/03L-0 on 830916, during routine testing, train A smergency dissel generator failed to control voltages as required & failed flash circuit would not deenergize, rendering generator imoperable W/831014 ltr BAIR. © 0, YUNDT, C.P. Portland General Electric Co. 83/10/14 MARTIN, J. B. Region 5, Office of Director 4pp 20897 160. 24X Fiche. 50-344, 63/10/14, 8310250444
- 8310250549 PNO-V-83-048 on 831013, Region V notified by NRR of temp compensation error w/Barton Model 763 pressure transmitters Same problem exists w/Model 764 steam generator narrow-range water level transmitters Setpoints revised on 831014 HA181. D Region 5, Office of Director 83/10/18, ip 20901:323, 24X Fiche:50-344,63/10/18,6310250543

V Operator Examinations

- 8310030145 Requests schedule, by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs 816H0P.T W. Division of Resident, Reactor Project & Engineering Programs 83/09/26 WITHERE, H. D. Portland General Electric Co 2pp 20590 036 24X Fiche 50-344, 83/09/26, 8310030145.
- DOCKET 50-346 DAVIB-BESSE NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8310050077 Forwards SER supporting util fire protection corrective action program Acceptable level of fire protection achieved to permit resumption of power pending completion of long-term actions
 EISENHUT.D 0. Division of Licensing 83/09/23 CRDUSE,R.P Toledo Edison Co. 6pp 20650 170 24X Fiche 50-346,83/09/23,8310050077.
- --8310050082 BER supporting util fire protection corrective action program Acceptable level of fire protection achieved to permit resumption of power pending completion of long-term actions

 * NRC No Detailed Affiliation Oiven. 83/09/23 lipp. 20650 176 R4X Fichs. 50-346, 83/09/23, 8310050077
- B310060345 Requests exemptions from App R requirements re dil collection sys for reactor coolant pumps, cold shutdown within 72 h w/o use of offsite power & separation of cables & equipment of redundant trains by fire barriers CROUSE, R P Toledo Edison CO 83/09/30 EISENHUT, D 9 Division of Licensing, 12pp, 20646, 139, 24X Fiche 50-346, 83/09/30, 8310060345
- 8310060590 Relmases public version of temporary mod request to emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/05, Document Management Branch 1p 20661 193, 24X Fichs 50-346, 83/10/05, 8310060590.

- ---8310060595 Public version of Temporary Mod Request T-7400 to Emergency Plan Implementing Procedure EJ 1300-05, "Emergency Control Ctr Activation " W/830914 ltr, receipt form & Rev 32 to index MWRRAY,T D , DURDEL,R . DDWNING,G Toledo Edison Co 83/09/06 7pp 20461 194 24% Ficha 50-346.83/10/05,8310060590
- 8310110082 Releases public version of revised emergency plan implementing procedures
 FELTON.J M Division of Rules and Records 83/10/05 Document Management Branch lp 20682 283 24X Fiche: 50-346,83/10/05,8310110082
- --B3101100B5 Forwards public version of revised emergency plan implementing procedures, including Procedure HP 1602 01 reexternal personnal radiation exposure munitoring Receipt form and Tolado Edison Co. 83/08/25 NRC No Detailed Affiliation Given 1p 20682 284 24X Fiche 50-346,83/10/05,8310110082
- --8310110087 Public version of revised emergency plan implementing procedures, including Procedure HP 1602 Of releasternal personnel radiation exposure monitoring HURRAY.T D. BRIDEN.D W. Totado Edison Co. 83/08/15 44pp 20682,285 24X Fiche 50-346,83/10/05,8310110082
- B310110124 Releases public version of revised administrative procedure FELTON.J M Division of Rules and Records 83/10/05 Documen Management Branch ip 20686 337 24X Fiche 50-346,83/10/05, 8310110124
- --8310110131 Public version of Rev 7 to Administrative Procedure AD 1850 04, "Post-Accident Sampling & Counting " W/830921 ltr & receipt form HURRAY, T D Toledo Edison Co 83/09/13 NRC - No Detailed Affiliation Given 20pp 20686:340 24X Fiche: 50-346, 83/10/05, 8310110124
- B310210359 Releases public varsion of temporary mod request to emergency plan supporting procedure.

 FELTON, J N Division of Rules and Records B3/10/18 Document Management Branch 1p 20883:146 24X Fiche: 50-346, B3/10/18, B310210359.
 - -B310210363 Public version of Temporary Mod Request T-7480 to Emergency Plan Supporting Procedure AD 1827 07 re earthquake. W/830930 ltm,receipt form & Rev 191 to index. MURRAY,T.D Toledo Edison Co 83/09/30 3pp. 20883.147 24X Fiche 50-346,83/10/18,8310210389
- P Operating license stage documents & correspondence
- 8310120016 Add1 response to FOIA request for document re problems w/ Tach Specs applying to RCS leakage determinations in PMRs Forwards App A documents FELTON, J M Division of Rules and Records 83/07/07. VOIGT, H H LeBosuf, Lamb, Leiby & HacRae 2pp. 20751:001. 24X Fiche 50-000,83/07/07,8310120016.
- --8310120022 Safety evaluation requiring test of primary coclant sys pressure isolation valves be incorporated into plant Tach Specs * NRC - No betailed Affiliation Given 81/04/20 ip 20751 057 24X Fiche:50-000,83/07/07,8310120016
- 8310040648 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "ECCS Repts (F-47) Action Plan Requirements, Toledo Edison Co, Davís-Besse Nuclear Power Station Unit 1 " NUKEO-0737, Item II K 3 17 requirements met, BTOLZ, J F. Operating Reactors Branch 4 83/09/01, CROUBE, R P Toledo Edison Co 4pp 20627-285, 24X Fiche 50-246,83/09/01, 8310040648
- --8212010152 *ECCS Repts (F-47), TMI Action Plan Requirements, Davis-Besse Nuclear Power Station, Unit 1, * technical evaluation rept VOSBURY, F. W. Franklin Institute/Franklin Research Center NRC-03-Bi-130. TER-05506-273. 82/11/24 CHOM, E. NRC No Datailed Affiliation Olven 14pp. 20627-289. 24% Fiche: 50-346, 83/09/01, 8310040648.
- B31003059B Forwards exemption extending until 851231 date for installation of reactor vessel head vent. Only interim relief from implementation schedule allowed due to lack of supporting sys data STOLZ.J.F. Operating Reactors Branch 4. B3/09/07. CROUSE, R.P. Toledo Edison Co. Spp. 20607: 279. 24X Ficher 50-346, B3/09/07, B310030598.

- --8310030400 Exemption extending until 851231 date for installation of reactor vessel head vent EISENHUT,D 0 Division of Licensing 83/09/07 Toledo Edison Co 4pp 20407 282 24% Fichs 50-344,83/09/07,8310030558
- 8310180567 Forwards SER we generic mods to reactor trip breakers & for B&W plants to provide automatic actuation of shunt trip attachments, per Generic Ltr 83-28 STGLZ.J F Licensing Branch 4 83/09/22 CROUSE, R P Toledo Edison Co 2pp 20825 012 24X Fithe 50-346,83/09/22,8310180567
- ---8310180570 SER supporting generic mods to reactor trip breakers for 8tW plants to provide automatic actuation of shunt trip attachments

 * NRC No Detailed Affiliation Given 83/09/22 14pp 20825 014 24X Fiche 50-344,83/09/22,8310180567
- 8310130382 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37), TMI Action Plan Requirements, Generic Rept B&W Designed Units," technical evaluation rept & NRR safety svaluation accepting B&W response to TMI Item II K 3 2 STOLZ-J F. Operating Reactors Branch 4 83/09/23 CROUSE, R P Toleds Edison Co. 3pp. 20770 120 24X Fiche 50-344, 83/09/23, B310130382
- 8310070080 Forwards documentation which formed basis for exemption granted to util.extending date reactor vessel head vent must be installed.per 830909 request Unit restart began on 830927
 DIRCKS.W J Office of the Executive Director for Operations 83/09/28 GILINSKY, V Commissioners Spp 20671 270 24X Fiche 50-346.83/09/28,8310070080.
- --8306090346 Forwards SER re request for exemption from reactor vessel head vent requirement Util not convinced that noncondensable gases that evolve in primary sys can be safely vented by hot leg high point vents alone.

 HOUSTON.R W Assistant Director for Reactor Safety 83/05/31.

 LAINAS.G C Assistant Director for Operating Reactors 9pp 20671 280 24% Fiche 50-346,83/09/28,8310070080
- --B3100700B5 Requests documentation which formed basis of exemption granted to util for installing reactor vessel high point vents Bpecific date all vents will be in svc also requested by B30923
 GILINSKY, V Commissioners B3/09/09 DIRCKB, W J Dffice of the Executive Director for Operations 1p 20671 299 24X
 Fichs 30-346, B3/09/28, B3100700B0
- 83:01:0540 Forwards Amend 62 to License NPF-3 t safety evaluation Amend adds Surveillance Requirements 4 4 5,7 & 4 4 5 8 to Tech Specs based on discovery of dislodged auxiliary feedwater flow distributor DEAGAZIO.A W Operating Reactors Branch 4 83/09/30 CROUSE, R P Toledo Edison Co 2pp. 20707 333 24X Fiche 50-346,83/09/30. 8310110540
- --8310110544 Amend 62 to License NPF-3, adding Surveillance Requirements 4 4 5 7 % 4 4 5 8 to Tech Specs based on discovery of dislodged auxiliary feedwater flow distributor. BTOL7.J.F. Operating Reactors Branch 4 83/09/30 App 20709 335 24X Fiche: 50-346, 83/09/30, 8310110540
- --B31011054B Safety evaluation supporting Amend 62 to License NPF-3 * Office of Nuclear Reactor Regulation, Director 83/09/30 3pp 20709 341 24X Fiche 50-346,83/09/30,8310110540
- 8310060226 Forwards plan & schedule for resolution of NUREG-0737, Item
 11 K 3 5, "Automatic Trip of Reactor Coplant Pumps,"
 (Generic Ltr 83-10), per NRC 830208 request Operating
 procedures for pumps to be revised
 CROUSE, R P Toledo Edison Co 83/10/03 EISENHUT, D, 9 Division o
 Licensing. 6pp 20647 015 24X Fiche 50-346, 83/10/03, 8310060226
- 8310200041 Forwards BER re NUREG-0737, Item II B 1, "RCG Vents." based on encl LLL technical evaluation rept & info provided in BO0130,810227,0323 & 0413 ltrs concerning vent installation Vent sys design acceptable BTOLI.JF. Operating Reactors Branch 4 B3/10/05, CROUSE,R P Toledo Edison Co 7pp 20844,335 24X Fiche 50-346,83/10/03, B3/10/041
- ---B306i30456 "Belected Operating Reactor Issues Program II,RCS Vents, (NUREQ-0737, Item II B 1)," final technical evaluation rept HELD,J T. Energy Incorporated. * Lawrence Livermore Laboratory FIN A-0250. TF-366/0817A B3/03/14 ALBERTHAL, G. NRC No Detailed Affiliation Given. 6pp. 20844.342. 24X Ficha 50-346.83/10/05.8310200041.

- 8310120103 Responds to NRC 830711 ltr on required actions based on Generic Ltr 83-28 re implication of Balem ATWS event Efforts initiated to ensure satisfactory performance of requested actions & programs Program & schedule expected by 840113 CROUSE, R P Toledo Edison Co 83/10/04 EISENHUT, D C Division of Licensing Ip 20696 240 24X Fiche 50-346.63/10/06.8310120103
- 8310200050 Forwards Franklin Research Ctr draft technical evaluation rept re control of heavy loads, based on 830131.0502.06 & 0510 responses to NRC requests for addl info Telcon will be arranged after 831028 to discuss comments
 STOLZIJF Operating Reactors Branch 4 B3/10/06 CROUSE, R P Toledo Edison Co 3pp 20844 299 24X Fiche 50-346.83/10/06, B310200050
- --8308180560 "Control of Heavy Loads (C-10). Toledo Edison Co.Davis-Besse Nuclear Power Station Unit 1," draft technical evaluation rept BCHBEROER.C., AHMED.N. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-348 DRFF 83/08/09 SINGH, A NRC No Detailed Affiliation Given 33pp 20844 302 24% Fithe 50-346.83/10/06.8310200050
- 8310170599 Provides schedule for responding to info requested in NRC 830906 ltr re instrumentation to detect inadequate core cooling CROUSE. A P Toledo Edison Co 83/10/07 8TOLZ, J F Operating Reactors Branch 4 1p 20782 093 24X Fiche 50-346,83/10/07,8310170599
- 8310170492 Application for amend to License NPF-3, extending temp verification time during & after transport of demineralized water & low boron concentration of liquids of less than 5,000 ppm boron CROUSE. R P Toledo Edison Co 83/10/11 STOLZ, J F Operating Reactors Branch 4 Bpp 20783 348 24X Fiche 50-346,83/10/11,83/10/70492
- --8310170503 Proposed Tech Specs extending temp verification time during & after transport of demineralized water & low boron concentration of liquids of less than 5,000 ppm boron * Toledo Edison Co 83/10/11 4pp 20783 396 24X
 Fiche 50-346,83/10/11.8310170492
- B310250226 Forwards application for amend to License NPF-3, changing Tech Spec Sections 4 1 2 1,4 1 2 2,3 1 2 8 & 3 1,2 7 to extend time for temp verification during & after transport of damineralised water & liquids w/low boron concentration GROUSE.R P Toledo Edison Co B3/10/11 STGLZ, J F Operating Reactors Branch 4 1p 20879 052 24X Fiche 50-344,83/10/11, B310250226
- --8310230235 Application for amend to License NPF-3; changing Tech Spec Sections 4.1 2 1.4 1 2 2.3.1 2 8 & 3 1 2 7 to extend time for temp varification during & after transport of damineralized water & low boron concentration liquid CROUBE, R P Toledo Edison Co 83/10/11 7pp 20877 053 24X Fiche 50-346,83/10/11,8310200226
- --B310250241 Proposed Tech Spec Sections 4 i 2 i.4 i 2 2.3 l 2 8 & 3 l 2 9 re time for temp verification during & after transport of demineralized water & low boron concentration liquid a Toledo Edison Co 83/10/11 4pp 20899 060 24X Fichs 50-346,63/10/11,8310250224
- 6310310487 Summary of 830826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATMS & proposed ATMS rule for B&W plants. List of attenders & viewgraphs encl KADAMBI.P Operating Reactors Branch 4 83/10/20 Operating Reactors Branch 4 13pp 20965 147. 24X Fiche 50-000,83/10/20,
- O Inspection reports, IE Bulletins & correspondence
- B310040176 Forwards IE Insp Rept 50-346/83-17 on B30B23-25 No noncompliance noted L1TTLE.W.B Region 3. Office of Director 83/09/21 CROUSE.R F Toledo Edison Co 2pp 20608 06B 24X Fiche 50-346,83/09/21, B310040176
- --8310040179 IE Insp Rept 50-346/83-i7 on 830823-25 No noncompliance noted Major areas inspected relocation of pressurizer relief valves, followup on previously identified items & snubber & restraint installation
 VIN.I T , DANIELSON.D H Region 3, Office of Director 83/09/19
 6pp 20608 070. 24X Fiche 50-344,63/09/21,8310040176

- 8308300340 IE Info Notice 83-61, "Alleged Use of Btand-Ins for Helder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York. Inc 117pp 20754 022 24% Fiche 50-000.83/09/26.8308300340
- B30B300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/09/26 Consolidated Edison Co of New
 York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,830B300342.
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Consolidated Edison Co of New York, Inc. 118pp 20778 001. 24X Fiche 50-000,83709726,8308300345
- 9309300349 IE Info Notice 83-64, "Lead Shie)ding Attached to Safety-Related Sys W/o 100FRBO 59 Evaluation " Svc list enc!

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp. 20716 324 24X Fiche 50-000,83/09/29,8308300349.
- 8308300378 IE Info Nutice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc. 74pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-64. "Fatality at Argentine Critical Facility " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 30-000,83/10/07.83083080752.
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche; 50-000,83/10/11,8308300761
- 8310180202 Clarifies procedures for admitting NRC personnal to facilities Access lists encl Update will be provided every 6 months AXELBON. H L. Region 3. Office of Director 83/10/14 CROUSE.R P. Toledo Edison Co 7pp 20808 331 24X Fiche 50-346, 83/10/14, 8310180202
- R Periodic operating reports & related correspondence
- 8310190166 Forwards monthly operating rept for Aug 1783 & Rev 1 to monthly operating rept for Jul 1783 MURRAY, T D Toledo Edison Co 83/09/08 HALLER, N Office of Resource Management. Director 1p 20821 068 24X Fiche 50-346,83/09/08,8310190166
- --8310190167 Monthly operating rept for Aug 1983 SARSDUR, B Toledo Edison Co 83/09/08 Spp 20821 069, 24X Fiche: 50-346,83/09/08,8310190166
- ---8310190170 Rev I to monthly operating rept for Jul 1983. SARSDUR: B Toledo Edison Co 83/09/08 2pp 20821 074. 24X Fiche: 50-346,83/09/08,8310190166
- 8310180513 "NPDEB Discharge Monitoring Rept, Sept 1983 " W/831013 ltr. CROUBE, R P Toledo Edison Co 83/10/05 Ohio, State of. 10pp 20801 171 24X Fiche 50-346, 83/10/05, 8310180513
- 8310190020 "Wastewater Rept for Bept 1983." MURRAY: T D : BCOTT: R J. Toledo Edison Co. 83/10/05 9pp 20822:039 24X Fiche: 50-346:83/10/05:8310190020

- S Reportable occurrences, LERs & related correspondence
- 8310120237 LER 83-044/03L-0 on 830822, during containment local leak rate test containment isolation valves CC14078, SA2101, DR2012A & CC1418 found w/leakage rates in excess of Tech Specs Gaussed by component failures W/830921 ltr WISS19, D, LANG, T, MURRAY, T D Tolado Edison Co 83/09/21 KEPPLER, J 0 Region 3, Office of Director 6pp 20691 321 24) Fiche 50-346, 83/09/21, 8310120237
- 8310120391 Corrected LER 83-044/03L-0 on 830822.during local leak rate test, four containment isolation valves found w/leakage rates in excess of limit Caused by component failure due to dirt k rust on seat Valves repaired k retested W/830921 ltr MISSIG.D. LANG.T. MURRAY.T D Toledo Edison Co 83/09/21 KEPPLER.J G Region 3, Office of Director 6pp 20699 107 24X Fiche 50-346.83/09/21.8310120391
- 8310060365 LER 83-046/03L-0 on 830830-0922, during fire protection barrier surveillance test,15 fire dampers found nonfunctional Caused by const installation error or equipment failure Dampers repaired W/830929 ltr.
 RICHTER.L. HURRAY.T D Toledo Edison Co. 83/09/29
 Region 3, Office of Director Bpp. 20646 097 24X
 Fiche 30-346.83/09/29.8310060365
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EliGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.H J Forboro Corp 83/09/30 Director's Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000.83/09/30.8310070301
- B310120222 LER B3-047/03L-0 on B30B31. during independent offsite ac source bus transfer procedure, automatic unit power supply to each 345 kV transmission line failed Caused by dirt in source selector switch W/B30930 ltr
 UEBBING.R. MURRAY.T D Toledo Edison Co B3/09/30 XEPPLER, J G Region 3. Office of Director App 20693 126 24X
 Fiche 50-346,83/09/30,8310120222
- 8310120322 LER 83-048/03L-0 on 830901, four HPI stop check valves found malfunctioning, in violation of Tech Specs Caused by design deficiency Disk in HP49 replaced w/33 degree seat angle design W/830930 ltr BLANKEMEYER, J. HURRAY, T. D. Toledo Edison Co. 83/09/30 KEPPLER, J. G. Region 3, Office of Director. 5pp. 20700 300 24X Fiche 50-346,83/09/30,8310120322
- 8310170369 LER 83-049/03L-0 on 830905.Fuel Handling Area Door 306 found open Caused by broken coordinator mechanism replaced W/831005 ltr WOLFE.R. MURRAY.T D Toledo Edison Co 83/10/05 KEPPLER, J 0 Region 3, Office of Director 3pp 20786 182 24X Fichs 50-346.83/10/05-8310170369
- 8310170375 LER 83-051/03L-0 on 830909, snubber SR-4-R-3 in hanger EBB-1-SR4 found w/o oil in reservoir Caused by bad rod seal Snubber replaced Insp interval reduced w/631005 ltr O'NEILL.J., MURRAY, T D Toledo Edison Co 83/10/05 XEPPLER.J 9 Region 3, Office of Director 3pp 20785 016 24X Fiche 50-346,63/10/05,8310170375
- 8310170498 LER 83-050/03L-0 on 830906, during performance of 8T 5099 02, miscellaneous instrument daily checks, surveillance requirement 4 4 2 b not performed Caused by lack of administrative controls W/831006 ltr
 WILLARD.J. MURRAY.T D. Toledo Edison Ca 83/10/06. KEPPLER.J & Region 3. Office of Director 4pp 20784: 109 24X
 Fichs 30-346,83/10/06.8310170498
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1
 F Security, Medical, seergency & fire protection plans
- 8310040436 Resubmits 830725 ltr transmitting Rev 7 to security plan Original ltr contained safeguards info & could not be docteted.

 CLAYTON,F i Alabama Power Co 83/09/15 D'REILLY, J. P. Region 2, Office of Director ip. 20619 053 24X Fiche 30-348,83/09/15,8310040436
- 8310040581 Advises that review of Rev 7 to radiological emergency plan complete Plan continues to meet planning stds of 10CFR50 47(b) k requirements of 10CFR50, App E. VERRELLI,D.M Division of Project k Resident Programs, 83/09/20 MCDONALD,R,P Alabama Power Co 2pp 20622 306, 24% Fiche 30-348,83/09/20,8310040581

- B310030147 Ack receipt of B30824 ltr documenting results of design description for alternative shutdown capability review refire protection Description acceptable w/exception that source range monitor be added to hot shutdown panel CLAYTON.F.L. Alabama Power Co. B3/09/28 VARGAS A. Office of Nuclear Reactor Regulation. Director 2pp 20590 034 24X Fiche 50-348.83/09/28.8310030147
- 8310250472 Ack receipt of 830921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-348/83-19 Request for 60-day extension for response to violations approved VERRELLI.D M Division of Project & Resident Programs 83/10/04 NCDONALD.R P Alabama Power Co 2pp 20902 121 24X Fiche 50-348,63/10/06,8310250472
- --B310230479 Responds to NRC B30909 ltr re violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Corrective actions detailed review of fire protection program underway Extension of 60 days requested for response CLAYTON,F L. Alabama Power Co. B3/09/21 VERRELLI,D M. Division of Project & Resident Programs 2pp 20902 123 24X Fiche 50-348/83/10/06/8310250472
- --8310250485 Forwards 1E Insp Repts 50-348/83-21 & 50-344/83-19 on 830816-19 & notice of violation VERRELL,D M Division of Project & Resident Programs 83/09/09 MCDQNALD,R P Alabama Power Co 2pp 20902 125 24X Fiche 50-348,83/10/04.8310250472
- --8310250490 Notice of violation from insp on 830816-19 * Division of Project & Resident Programs 83/09/09 App 20902 127 24% Fiche 50-348,83/10/04.8310250472
- --8310250498 IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19
 Noncompliance noted inadequate survoillance test procedures
 for fire detection sys, fire protection control valves &
 carbon distide hose reels & no fire stops for cable trays
 MILLER.W H , GIBBONS.T D , CONLON.T E Region 2, Office of
 Director 83/09/07 10pp 20902 129 24% Fichs 50-348,83/10/6%.
 8310250472
- B310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends consist of administrative changes to Tech Specs re administrative controls for emsite & offsite organization RECVES,E A Operating Reactors Branch 1 89/10/14 CLAYTUN,F & Alabama Power Co 2pp 20765 001 24% Fiche 50-34B,83/10/14,8310280085
- --B3102B0092 Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits

 VARGALS A Operating Reactors Branch | B3/10/14 | 46pp 20765 003, 24x Fiche 50-348, B3/10/14, B3102B00B5
- --8310280114 Bafety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively + Office of Nuclear Reactor Regulation, Director 63/10/14 App 20963 049 24X Fiche 50-348,83/10/14,8310280085
- 8310210022 Informs of inaccuracy in design description for alternative shutdown capability transmitted in util 820701 ltr Local mechanical level indication not installed on condensate storage tank but will be added. CLAYTON.F.L. Alabama Power Co. 83/10/17 VAROA,8 A Office of Nuclear Reactor Regulation, Director 2pp 20856 057 24% Fiche 50-346.83/10/17.8310210022
- P Operating license stage documents & correspondence
- 8310240320 Add1 response to FOIA request for documents re Tech Spec problems applicable to RCB leakage determinations in PWRs. Forwards App A documents Documents also available in FOR FELTON.J M Division of Rules and Records 83/07/14 VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20907 036 24X Fiche 50-348,83/07/14.8310240320
- ---B010010785 Trip rept for site visit re development of portable calculator for RCS leak rates for PWRs Forwards programs for TI 59 & HP 41C calculators used during visit to compute leak rate.

 WOODRUFF, D C Division of Reactor Operations Inspections B0/08/14 JORDANSE L. Division of Reactor Operations Inspections 27pp 20907:039 24X Fiche 50-348, 83/07/14, 83/0240320

DOCKETED ITEMS

- 8310030613 Forwards safety evaluation of shunt trip design for RPS DS 416 reactor trip breakers Design acceptable conditioned on receipt of confirmatory info & completion of action feems listed VAROALS A Depreting Reactors Branch 1 83/09/20 CLAYTON.F L Alabama Power Co 3pp 20607 314 24X Fiche 50-348,83/09/20, 8310030613
- --8310030615 Safety evaluation conditionally accepting short trip design for RPS DS 416 reactor trip breakers * NRC - No Detailed Affiliation Given 83/09/14 18pp 20607 317 24% Fiche 50-348,83/09/20,8310030613
- 8310050017 Forwards safety evaluation denying licensee 830304 application for amend to Licenses NPF-2 & NFF-B to allow continued plant operations w/more than one control rod immovable VARGA.5 A Operating Reactors Branch 1 83/09/21 CLAYTON,F L Alabama Power Co 2pp 20650 268 24X Fiche 50~348.83/09/21, 831030017
- --8310050022 Safety evaluation denying licenses 830304 application for amend to Licenses NPF-2 & NPF-B to allow continued plant operations w/more than one control rod immovable Licenses must resolve potential core-wide mechanical problem * NRC No Detailed Affiliation Given 83/09/21 1p 20450 270 24X Fichs 90-348,83/09/21.8310050017
- 8310030603 Forwards safety evaluation concurring w/licensee conclusions that NUREC-0737, Item II K 3 2 requirements met w/existing PDRV, safety valve & reactor high trip pressure setpoints Automatic PDRV isolation sys (Item II K 3 1) not required VARQA, S A Operating Reactors Branch I 83/09/23 CLAYTON, F L Alabama Power Co 14pp 20404 212 24X Fichs 50-348,83/09/23.8310030603
- 8310060076 Forwards four oversize drawings, in response to NRC request for add1 info re syc water bldg battery sys design, per util 830303 & 0727 proposed Tech Spec changes involving dc distribution sys Aperture cards are available in PDR CLAYTON, F L Alabama Power Co 83/09/23 VAROA, B A NRC No Betailed Affiliation Given 2pp 20446 277 24X Fiche 50-348,83/09/23,8310040094
- 8310030414 Identifies specific Reg Outde 1 97 accident monitoring equipment sys for which extension requested per 830520 & OB24 Itrs Schedules for upgrading equipment provided w/bases for extension request CLAYTON,F L. Alabama Power Co. 83/09/27 VAROA,8 A. Dffice of Nuclear Reactor Regulation, Director 22pp 20593 087 24X Fiche 50-348,83/09/27,8310030414
- B310040387 Submits evaluation of existing Westinghouse BTB provisions, ASME Code Section XI.Reactor Bafety Study (WASH 1400), NUMEG-0677 & EG&G rept. "Inservice Leak Testing of Primary Pressure Isolation Valves." as applicable to plant design CLAYTON.F L. Alabama Power Co. 83/09/27 VARGA.S A. Office of Nuclear Reactor Regulation, Director 16pp 20625-200 24X Fiche 50-348,83/09/27,8310040387
- 8310140194 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Bpecs to delate turbine valve testing requirements Testing program will be replaced w/insp & maint program for all throttip & governor valves CLAYTON, F L Alabama Power Co 83/10/06 VARQA, 8 A Office of Nuclear Reactor Regulation. Director 4pp 20766 077 24X Fiche 50-348, 83/10/06, 8310140194
- --8310140199 Proposed Tech Specs re limiting conditions for operation & surveillance requirements of turbine valve testing Turbine overspeed reliability assurance program encl Program withheld (ref 10CFR2 790)

 * Alabama Power Co 83/10/06 15pp 20766 081 24X
 Fiche \$0-348.83/10/06.8310140194
- 8330170407 Forwards status of licensing items requiring NRC approval CLAYTUN,F L Alabama Power Co 83/10/10 VARGA:S A Office of Nuclear Reactor Regulation. Director lipp 20779 161 24X Fiche 50-348,83/10/10.8310170407
- 8310170416 Application to amend Licenses NPF-2 & NPF-B consisting of changes to Teth Bpec re movable rod control sys requirements Encl clarifiles 830304:0603 & 0728 submittals in response to NRC 830921 request CLAYTON.F L Alabama Power Co 83/10/10 VAROA.S A Office of Nuclear Reactor Regulation, Director 3pp 20777 175 24X Fiche 50-348,83/10/10.8310170416
- --8310170423 Proposed Tech Spec changes re movable rod control systeQuirements

 * Alahama Power Co 83/10/10 5pp 20779 198 24X
 Fiche 50-348, 83/10/10, 8310170416

- 8310180280 Forwards list of application dates, fees paid, fees applicable & NRR fee determination & action on each item Based on NRR fee determinations, total of \$17,500 due Util will be notified of adjustments following final review MILLER, W O License Fee Management Branch 83/10/11 CLAYTON, F. L Alabama Power Co 3pp 20827 126 24X Fiche 50-348, 83/10/11, 8310180280
- 8310180308 Forwards response to 830916 request for most realistic schedule for inservice insp & testing items requiring NRC approval for fifth refueling outage Approval of proposed changes & SER sev by 840101 requested CLAYTON: F. L. Alabama Power Co. 83/10/11 VARGA: S. A. Dffice of Nuclear Reactor Regulation, Director Spp 20803-098 24X Fiche 50-348,83/10/11,8310180308
- 8310210259 Application for amend to Licenses NPF-2 & NPF-8, changing Tech 8pecs to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) below full power CLAYTON.F L. Alabama Power Co. 83/10/13 VARGA.B A. Office of Nuclear Reactor Regulstion, Director 50pp 20851 163 24X Fiche 50-348,83/10/13,8310210259
- ~-8310210261 Proposed Tech Spec changes to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) limit below full power * Alabama Power Co 83/10/13 13pp 20851 213 24X Fiche 50-348,83/10/13,8310210259
- 8310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends consist of administrative changes to Tech Specs re administrative controls for onsiste & offsite organization REEVES, E A Operating Reactors Branch 1 83/10/14 CLAYTON.F.L Alabama Fower Co 2pg 20965.001 24% Fiche 50-348,83/10/14,8310280085
- --B3102B0092 Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits VAROA.S A Operating Reactors Branch 1 B3/10/14 46pp 20965 003 24X Fiche 50-34B.83/10/14.8310280085
- --8310280114 Bafoty evaluation supporting Amends 33 & 24 to Licenses NPF-2 & NPF-Birespectively ** Office of Nuclear Reactor Regulation, Director 83/10/14 App. 20965 049 24% Fiche 50-248,83/10/14.8310280085
- 8310250422 Responds to four items re shunt trip design for D8-416 reactor trip breakers, per NRC 830920 request Environ conditions considered in developing Mestinghouse Owners Group generic design CLAYTON, F. L. Alabama Power Co. 83/10/20 VAROA, S.A. Office of Nuclear Reactor Regulation, Director 2pp 20897:182 24% Fiche 50-348, 83/10/20, 8310250422.
- 8310270374 Application to amend License NPF-2, permitting one-time Tech Spec change re movable in-core detectors Change does not involve significant hazards consideration CLAYTON,F L Alabama Power Co 83/10/21 VARQA,S.A Office of Nuclear Reactor Regulation, Director 4pp 20924-017 24% Fiche 50-348,83/10/21,8310270374.
- --8310270378 Proposed one-time Tech Spec change re movable in-core detectors * Alabama Power Co 83/10/21 2pp 20924 023 24X Ficher 50-348, 83/10/21, 8310270374
- Q Inspection reports. IE Bulletins & correspondence
- 8310040374 Ack receipt of 830707 ltr informing NRC of steps taken to correct violations noted in IA. Insp Repts 50-348/83-20 & 50-364/83-18
 VERRELLI, D M Division of Project & Resident Programs 83/07/19
 MCDONALD, R P Alabama Power Co ip 20617 046 24X
 Fiche: 50-348, 83/07/19, 8310040374
- --8310040377 Responds to NRC 830819 ltr re violations noted in IE Insp Repts 50-348/83-20 & 50-364/83-18 Corrective actions: containment air cooler fan annunciator links 2A & 28 closed & chemistry control Procedure FNP-0-CCP-12 rewritten CLAYTON,F L Alabama Power Co 83/09/09 VERRELLI,D M Division of Project & Resident Programs, 3pp 20617 067 24X Fiche 50-348,83/09/19,8310040374
- --8310040378 Forwards IE Insp Repts 50-348/83-20 & 50-364/83-18 on 830711-0810 & notice of violation VERRELLID M Division of Project & Resident Programs 83/08/19 MCDONALD,R.P Alabama Power Co 2pp. 20617 071. 24X Fiche 50-348,83/09/19.8310040374

- ~~8310040379 Notice of violation from insp on 830711-0810 * Region 2. Office of Director 83/08/19 2pp 20417 073 24X Fiche 50-348,83/09/19,8310040374
- ~~8310040384 IE Insp Repts 50-348/83-20 & 50-364/83-18 on 830711-0810 Noncompliance noted sulfuric acid std used to check hydrometers not listed on licenses test equipment inventory & maint schedule & containment air cooler fan links open BRADFORD, W Hr. RULAND, W Hr. Region 2. Office of Director CANTRELL, F 8 Division of Project & Resident Programs 83/08/18 10pp 20617 075 24X Fichs 50-348,83/09/19.8310040374
- 8310250376 Forwards IE Insp. Repts 50-348/83-22 & 50-344/83-20 on 830829-31 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/09/19 MCDONALD,R P Alabama Power Co 2pp 20898 130 24X Fichs 50-348
- --8310250387 IE Insp Repts 50-348/83-22 & 50-344/83-20 on 830829-31. No noncompliance noted Major areas inspected licenses action on previous insp follows items & two licenses reported events involving spread of contamination.

 DEBB.B.T Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs 83/09/14 4pp 20898 132. 24X Fiche.50-348,83/09/19.8310250376
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests." Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022. 24X Fiche 50-000,83/09/26,83083000340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Svc list encl
 JGRDAN,E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/09/26 Consolidated Edison Co of New
 York, Inc 116pp 20777 210. 24X fiche 50-000.83/09/26.8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778:001 24X Fiche: 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 57 Eveluation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716, 324, 24X Fiche 50-000, 83/09/29, 8308300049
- 83:0140174 Application for amend to Licenses NPF-2 & NPF-8, changing Tach Specs to delete turbine valve testing requirements.

 Testing program will be replaced w/insp & maint program for all throttle & governor valves.

 CLAYTON, F L Alabama Power Co 83/10/06 VARGA, 8 A Office of Nuclear Reactor Regulation. Director App 20766 077 24X

 Fiche: 50-348,83/10/06,8310140194
- --B310140179 Proposed Tech Specs re limiting conditions for operation & surveillance requirements of turbine valve testing Turbine overspeed reliability assurance program encl Program withheld (ref 10CFR2 790).

 * Alabams Power Co. B3/10/04 15pp 20766.081 24X Fiche 50~248.83/10/04.8310140194
- 8310250472 Ack receipt of 830721 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-344/83-17 Request for 60-day extension for response to violations approved VERRELLI, D M Division of Project & Resident Programs 83/10/06/KCDONALD, R P. Alabama Power Co 2pp 20702 121 24% Fiche: 50-348/83/10/06/8310250472
- --8310250479 Responds to NRC 830909 ltr re violations noted in IE Insp. Repts 50-348/83-21 & 50-364/83-19. Corrective actions detailed review of fire protection program underway Extension of 60 days requested for response CLAYTOM.F L. Alabama Power Co. 83/09/21 VERRELLI.D M Division of Froject & Resident Programs 2pp. 20902 123 24X Fichs 50-348,83/10/06,8310200472.
- --8310250485 Forwards JE Insp Rapts 50-348/83-21 & 50-364/83-19 on 830816-19 & notice of violation VERRELLI,D.N Division of Project & Resident Programs 83/09/09 HCDONALD,R.P Alabama Power Co 2pp 20902,125 P4X Ficha: 50-348,83/10/06,8310250472.

- ---B31025049B IE Insp Repts 50-348/83-21 & 50-344/83-19 on B30816-19
 Noncompliance noted inadequate survoillance test procedures
 for fire detection sys, fire protection control valves &
 carbon digide hose reels & no fire stops for cable trays
 MILLER,W H , GIBBONS,T D , CONLON,T E Region 2, Office of
 Director 83/09/07 10pp 20902 129 24X Fiche 50-34B.83/10/06,
 8310250472
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison Co. of New York Inc. 76pp 20827 213 24X Fiche 50-000,83/19/07,8308300378
- 8308300752 IE Info Notice 83-66, "fatality at Argentine Critical Facility " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50~000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310180308 Forwards response to 830716 request for most realistic schedule for inservice insp & tenting items requiring NRC approval for fifth refueling outage Approval of proposed changes & SER rev by 840101 requested CLAYTON,F L. Alabama Power Co. 83/10/11 VARGA, S.A. Office of Nuclear Reactor Regulation, Director 3pp. 20803-098 24X Fiche 50-348.83/10/11.8310180308
- R Periodic operating reports & related correspondence
- 8310180124 Monthly operating rept for Sept 1983 W/831012 ltr HAIRBTON, N G . CLAYTON F L Alabama Power Co 83/10/04 NRC ~ No Detailed Affiliation Given 9pp 20807 154 24X Fiche 50-348, 83/10/04,8310180124
- A Reportable occurrences. LERs & related correspondence
- 831007013B LER 83-058/03L~0 on 830827, instrumentation channels associated w/lovel indicators 1.1-3594A & LI-3594B declared inoperable when indicators turned off Caused by procedural inadequacy Procedure revised W/830927 ltr
 HAIRBTON.W 0 . CLAYTON.F L Alabama Power Co 83/09/27 Region 2, Dffice of Director 3pp 20659 035 24X Fiche 50-348,83/09/27,8310070138
- 8310070296 Forwards LERs 83-057/03L-0 & 83-036/03L-0 CLAYTON.F L Alabama Power Co 83/09/30 Region 2. Office of Director ip 20651 075 24X Fiche 50-348,83/09/30,8310070296
- --8310070299 LER 83-057/03L-0 on 830831. radiation monitor R-11 containment atmosphere particulate activity indication decreased off-scale Caused by increase in containment background radiation Mods made to increase range of R-11 HAIRSTON.W 0 Alabama Power Co. 83/09/30 Region 2. 0ffice af Director ip 20451 074 24X Fiche 50-348.83/09/30.8310076294
- --8310070302 LER 83-036/03L-0 on 830831, following failure alarm on power cabinet 28D, rod control sys déclared inoperable Caused by blown fuse Fuse & blown fuse indicator replaced HAIRETON, N G. Alabama Power Co. 83/09/30 Region 2, Office of Director ip 20651 077 24X Fiche 50-348,83/09/30,8310070296
- 8310070301 Potential Part 21 rept re Underrange characteristic of Model N-EilOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Foxboro Corp 83/09/30. Director's Diffice, Office of inspection and Enforcement lipp 20651 064 24X Fiche 50-000,83/09/30,6310070301
- B310120350 Forwards LERs B3-060/03L-0,B3-061/03L-0,B3-037/03L-0 & B3-038/03L-0 W/o LER B3-038/03L-0 CLAYTON,F L Alabama Power Co B3/10/04 Region 2, Office of Director ip 20679 317, 24X Fichs, 50-348, 83/10/04, 8310120350

- --8310120356 LER 83-060/03L-0 on 830912, instrumentation channel for flow transmitter Ff-415 declared inoperable due to erratic indications Caused by failure of NLP card Card replaced HARRSTON W G Alabama Power Co 83/10/04 Region 2, Office of Director Ip 20699 318 24X Fiche 50-348,83/10/04,8310120350
- --8310120363 LER 83-061/03L-0 on 830913, instrumentation channel associated w/level transmitter LT-459 declared inoperable when found out of tolerance Caused by failure of NLP card Card replaced & channel declared operable HAIRSTON W Q Alabama Power Co 83/10/04 Region 2, Office of Director Ip 20699 319 24X Fiche 50-348,83/10/04,8310120350
- --BD10120371 LER B3-037/03L-0 on B30907, bottery bank 2A declared inoperable Caused by decrease in voltage on cell 56 below Tech Spec 3 8 2 3 requirements Cell cleaned & charged Bys restored HAIRSTON, W. Q. Alabama Powen Co. 83/10/04 Region 2, Dffice of Director ip 20497 320 24X Fiche 50-348.83/10/04,8310120350
- 6310140226 Forwards LERs 83-059/03L-0 & 83-062/03L-0 CLAYTON.F L Alabama Power Co 83/10/06 Region 2, Office of Director 1p 20761 250 24% Fiche 50-348,83/10/06.8310140226
- --8310140229 LER 83-059/03L-0 on 830906, train B control room emergency air cleanup sys declared inoperable when train B air conditioner compressor tripped Caused by solenoid valve linkage on pump down line out of adjustment HAIRSTON, W G Alabama Power Co 83/10/06 Region 2, Office of Director ip 20761 251 24X Fiche 50-348.83/10/06,8310140226
- --83\$0140235 LER 83-042/03L-0 on 830707, during calibr & functional test, train B chlorine detector declared inoperable when sero potentiometer found to be malfunctioning Potentiometer replaced HAIRSTONING Alabama Power Co 83/10/06 Region 2, Office of Directol 1p 20761 252 24X Fiche 80-348,83/10/06,8310140226
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8310210315 Responds to FOIA request for documents re decision to conduct Caseload Forecast Panel movings & only tour facility & any documents re rationale or basis for decision Forwards documents
 FELTON. J M. Division of Rules and Records 83/07/29 SUGARMAN R. Sugarman & Denworth 2pp 20883 170 24X Fiche 50-352,83/07/29,8310210315
- --B303230300 Requests Caseload Forecast Panel site visit to update assessment of const completion status EISENHUT, D C Division of Licensing 83/03/16 HARTFIELD, R A Management Information Branch | Ip 20883 194 24% Fiche 50-352,83/07/29,8310210315
- B310050340 Notification of B30926 meeting w/util in Bethesda,MD to discuss draft BNL rept on core melt frequency MARTIN,R E Licensing Branch 2 83/09/21 SCHWENCER,A Licensing Branch 2 4pp 20650 043 24X Fiche 50-352,83/09/21,8310050360
- 6310050455 Notification of Bignificant Licensee Meeting 83-84 on 831016 w/ubil at site to discuss status of const & preoperational tasting (Module 303018) CONNER, E. L. Region 1, Office of Director 83/09/26 Region 1, Office of Director 83/09/26 Region 1, Office of Director 83/09/26, 8310080455
- B310040296 Provides addl info re thermal hydraulic stability, per 830624 verbal request Enc) revised FBAR tables will be incorporated into FBAR rev scheduled for Oct 1983 MEMPER. J 8 Philadelphia Electric Co. 83/09/28 SCHWENCER. A Licensing Branch 2 App 20614 207 24% Fiche 50-352,83/09/28. B310340296
- 8310040124 Forwards response to Equipment Qualification Branch 820730 request for add1 info re audits by Beismic & Dynamic Qualification & Pump & Valve Operability Review Teams Util will be notified of items selected for 831015 audit KEMPER. J 8 Philadelphia Electric Co 83/09/30 SCHWENCER, A Licensing Branch 2 1225pp 20608 882 RAX Fiche 50-352,83/09/30,8310040184
- --8310040127 Rev O to Procedure 8031-0-14, "General Project Requirements for Beismic Design & Analysis of Equipment Supports " # Bechtel Corp 83/08/17 212pp 20609 215 24X Fiche 50-352.83/09/30.8310040124

- ---8310040129 Rev 1 to Procedure BO31-0-19, "Required Response Spectra (RRS) of Primary Containment for Load Combinations of Seismac & Hydrodynamic Loads"

 * Bechtal Corp 81/08/02 190pp 20610 067 24X
 Fiche 50-352.83/09/30.8310040124
- --8310040131 Rev 2 to Procedure BO3)-G-19, "Required Response Spectra (RRS) of Reactor Bldg & Control Room Structure for Load Combinations of Seismic & Hydrodynamic Loads " * Bechtol Corp B2/01/29 530pp 20610 297 24X Fiche 50-352,83/09/30,8310040124
- B310040431 Forwards response to B20730 ltr re operability qualification of pumps & valves Qualification & installation of active pumps & valves 70% complete, per B30916 telton KEMPER, J S Philadelphia Electric Co B3/09/30 SCHHENCER, A Licensing Branch 2 57pp 20617 276 24% Ficha 50-352, B3/09/30, B310040431
- 8310140093 Forwards analysis of dust loading on first HEPA filter in ESF HVAC filtration train as discussed in 830926 telcon Dust loading capabilities not exceeded KEMPER, J 8 Philadelphia Electric Co 83/10/03 BCHMENCER, A Licensing Branch 2 7pp 20767 052 24X Fiche 50-352,83/10/03,8310140092
- G310070243 Forwards revised draft FSAR Page 13 4-8 adding superintendent.nuclear training section to operating experience assessment committee.per G30927 conference call Rev will be incorporated in Nov 1983 FSAR rev GRADLEY.E J Philadelphia Electric Co G3/10/04 SCHWENCER.A Licensing Branch 2 3pp 20598 335 24x Fiche 50-352.G3/10/04, p3/10/070947
- 8310120062 Advises that operation of facility will not adversely affect significant or archeological resources, provided investigations performed & negative visual impacts aliminated HILLIAMS. D. Pennsylvania: Commonwealth of, 83/10/05 SCHWENCER, A Licensing Branch 2 1p 20696 156 24X Fiche 30-352,83/10/05.8310120062
- B310140197 Discusses actions to be taken to revise & expand upon applicant 811104 ltr. in response to NRC B30B31 request. Areas discussed include pipe replacement, matl corrections & additions & nonconforming welds in Class I sys KEMPER. J S Philadelphia Electric Co 83/10/05 EIBENHUT. D 9 Division of Licensing 14pp 20762 333 24X Fiche 50-332,83/10/05,8310140197
- 8310140278 Forwards draft response to 830915 Request for Add1 Info RAI 271 2 re qualification of automatic depressurization sys accumulators per TMI Item II K 3 28 Response will be incorporated in Nov 1993 FBAR rev BRADLEY.E J Philadelphia Electric Co 83/10/05 BCHWENCER.A Licensing Branch 2 9pp 20761 186 24X Fiche 50-352,83/10/05, 6310140278
- 831012014B Forwards clarification of requested info on misplaced bundle accident analysis, per 830715 telcon braft replacement for FBAR Table 15 4-6 encl Info will be incorporated into next FSAR rev
 KEMPER. J B Philadelphia Electric Co 83/10/07 SCHWENCER, A Licensing Branch 2 4pp 20696 018 24% Fiche 50-352,83/10/07,8310120148
- 8310140097 Forwards Amend 37 to DL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1963, replacing carlier version BRADLEY, E. J. Philadelphia Electric Co. 83/10/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 20755 001 24X Fichs 50-352,83/10/07. 8310140097
- --B310140101 Amend 97 to OL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing earlier version Certificate of Svc encl
 BOYER, V B. BRADLEY, E. J. Philadelphia Electric Co. B3/10/06
 App. 20755 003 24X Fiche 50-352, 83/10/07, 8310140097
- --8310140103 "Electrical Equipment Environ Qualification Rept.Limerick Generating Station Units 1 & 2." Vols 1-3 * NUTECH Engineers, Inc 83/10/31 1.667pp 20755 009 24X Fiche 50-352.63/16/07.8310140097
- C Utility Environmental Report (ER), amends & correspondence
- 8310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept - DL Stage Guestion E451 G.FSAR Guestion 451 9, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class. ." KEMPER, J S Philadelphia Electric Co 83/10/13 SCHWENCER, A Licensing Branch 2 4pp 20803 318 24X Fiche 50-352,83/10/13, 8310180423

- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8310180420 Advises that results of review of BES re water supply consistent w/findings of Delaware River Commission Rept should address low level radwaste storage & disposal PASTOR.R J Pennsylvania. Commonwealth of: 83/10/04 SCHMENCER Licensing Branch 2 3pp 20803 221 24X Fiche 50-352:63/10/04.6310180420
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310070190 Summary of 830615 meeting w/util, Bechtel & GE in Bethesda, HD 310070190 Bummary of B30615 meeting w/utils.Bechtel & we ire open SER issue concerning high radiation signal on containment purge vent valves w/respect to placement of radiation monitors & isolation requirements. MARTIN.R.E Licensing Branch 2 83/09/29 Licensing 13pp 20680 235 24% Fiche 50-352.83/09/29.8310070190 Licensing Branch 2.
- 8310110132 Forwards draft revs to FSAR re SER Open Item Issue 19 concerning frequency classification of generator load rejection w/bypass failure & turbine trip w/bypass failure twents FSAR revs scheduled for Nov 1983 KEMPER, J S Philadelphia Electric Co 83/10/03 SCHMENCER, A Licensing Branch 2 9pp 20666.299 24X Fiche 50-352, 83/10/03, 8310110132
- 9310120392 Forwards draft revs to FSAR Sections 1 8.5 2 & 7 7 & draft revised response to FSAR Question 410 23, per 831222 meeting re SER Open Issue 8 concerning airborne particulate redioactivity agnitoring sys KEMPER, J S Philadelphia Electric Co 83/10/05 SCHWENCER, A Litensing Branch 2 25pp 20698-060 24X Fithe 50-352, 83/10/05, 2310120302 Licensing Branch 2 8310120372
- 8310240316 Summary of 830707 meeting w/util in Bethesda,MD re overpressurization of standby gas treatment sys ductwork & filters Issue resolved Disposition discussed in SER. NUREO-0991 issued in Aug 1983 MARTIN.R E Licensing Branch 2 83/10/19 Licensing Branch 2 199p 20921 220 24X Fiche 50-352,83/10/19.8310260316
- F Security, medical, emergency & fire protection plans
- 8310040110 Forwards final schedule for satisfying requirements of Owneric Ltr 82-33 re Suppl 1 to NUMEG-0737, "Requirements for Emergency Response Capability "
 SCHWENCER: A. Licensing Branch 2 83/09/26 BAUER, E @
 Philadelphia Electric Co 4pp 20634 336 P4X
 Fiche 50-352.83/09/26.8310040110
- 8310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept OL Stage Question E451 B.FSAR Question 451 9, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class . ." KEMPER, J S Philadelphia Electric Co B3/10/13 SCHWENCER, A Licensing Branch 2 4pp 20803 318, 24X Fiche 50~352,83/10/13, 8310180423
- 8310280127 Responds to NRC 830926 ltm ra schedule for meeting emergency response capability requirements. Const schedule will permit fuel loading by 840801 Full scale emergency preparedness exercise rescheduled to 840725

 BOYER, V B Philadelphia Electric Co 83/10/25 9CHWENCER, A Licensing Branch 2 3pp 20929 273 24X Fiche 50-352,83/10/25,83/10/2010 Licensing Branch 2 8310280127.
- 9 Adjudicatory correspondence
- B309;30034 Forwards receipts indicating that draft offsite emergency plans received by City of Philadelphia & by J Dorsey on hehalf of intervenors BRADLEY,E J Philadelphia Electric Co B3/09/07 DRENNER, L, MORRIB, P. A., COLE, R F Atomic Safety and Licensing Board Panel App 20356 177 24X Fiche 50-352,83/09/07,8309130054.
- 1310030437 Motion to modify wording of Contention V-4 on carburator icing.
 ROMANO,F R Air and Water Pollution Patrol 83/09/26 BRENNER,L.
 COLE,R F., MORRIS,P A Atomic Safety and Licensing Board Panel 1
 20602-094. 24X Fiche: 50-352,83/09/26,8310030437
- 110050423 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.

 CHAN, E I Hearing Branch 2 83/09/27, 3pp 20632, 35t R4X

 Ficher 50-352, 83/09/27, 83/0050423
- 10040491 Motion to reword Contention I-62 re pressurized thermal shock, in response to ASLB 830913 memorandum & order Certificate of Svc encl LEMIS, M I Lewis, M 83/09/28. Atomic Safety and Licensing i Panel Spp 20625 162 24X Fiche. 50-332, 83/09/28, 8310040491 l 89/09/28. Atomic Safety and Licensing Board 2 24X Fiche.50-352,83/09/28,8310040491

- 831004049B Respec of Contention I-41 re sys interaction Certificate of 31004049H Respec of Contention 1-41 re sys interaction Certificate of Bvc encil
 DORSEY, J.A. Limerick Ecology Action DORSEY, J.A. Dorsey, J.A.
 B3709728 BRENNER, L. COLE.R F. MORRIS, P.A. Atomic Safety and
 Licensing Board Panel - Opp. 20625 132 24X Fiche 50-352, B3/09/28,
 B310040498
- 83/09/30
- 8310040627 Rept per ASLB 830913 memorandum & order re establishment of hearing schedule & re MI Lewis.Friends of the Earth & Air & Water Pollution Patrol contentions Certificate of Svc entl METICHAHAM, M J Philadelphia Electric Co METICHAHAM, M J Conner & Watterhahn B3/09/30 6pp 20626 163 24X Fiche 50-352,83/09/30, Wetterhahn 8310040627
- 8310050427 Response to Limerick Ecology Action 830831 proposed severe accident assessment rept/environ rept OL stage (SARA/EROL) Section 7 contentions & City of Philadelphia 830780 SARA
 - Concerns
 VOGLER. B H Hearing Branch 2 83/09/30 Atomic Safety and
 Licensing Board Panel 14pp 20633 216 24X Fiche 50-332,83/09/30,
 8310050429
- --B310050432 Rept on behalf of applicant, M Lewis, Air & Hater Pollution Patrol, Friends of the Earth & Limerick Ecology Action, in response to ASLB B30913 memorandom ro hearing schedule proposals Centificate of Svc encl HODGDON, A P Houring Branch 2 83/09/30 Atomic Bafety and Licensing Board Panel App 20633 230 24% Fiche 50-352, 83/09/30, 8310050429
- 8310060305 Forwards author notice of appearance in proceeding Author should be substituted for TY Au on ave list Certificate of Svc ent1
 FERKIN, Z G Ponnsylvania, Commonwealth of, 83/09/30 BRENNEN, L HORRIS, P A . COLE, R F Atomic Safety and Licensing Board Panel 5pp 20444 196 24X Fiche 50-352,83/09/30,8310040305 BRENNER L .
- 8310040193 Memorandum & order shortening schedule for answers to respec of Limerick Ecology Action Contention I-41 re sys interaction Util answer shall be received by NRC by 831007 & by ASLB & Limerick by 83101 BRENNER, L Atomic Safety and Licensing Board Penel 83/10/03 4pp 20608 080 24X Fiche 50-352,83/10/03.8310040183
- 8310050815 Brief apposing Del-Aware Unlimited. Inc exceptions to ASLB B30308 partial initial decision & 830601 memorandum & order denying Del-Aware motion to reapen record Notice of appearance & Certificate of Svc encl CONNER. T B Philodelphia Elsctric Co CONNER. T B Conner & Wetterhahn 83/10/03 Atomic Safety and Liceneing Appeal Panel 120pp 20630 210 24X Fiche 50-352.83/10/03.8310050515
- 8310110052 Memorandum & order re hearing schedules proposed by parties NRC schedule essentially acceptable BRENNER, L Atomic Safety and Licensing Board Panel 83/10/04 4pp 20668 265 24X Fiche 50-352,63/10/04,8310110052
- B310110305 Second interim rept to ABLB re Contention VI-1 METTERHANN, M. J. Philadelphia Electric Co. WETTERHANN, M. J. Conner Wetterhehn 63/10/04 ip 20665 339 24X Fiche 50-352,83/10/04. 8310110305 Conner &
- --B310110307 Affidavit of VB Boyer re review of welds in 1976 under responsibility of GC inspector Certificate of Svc encl BOYER,V S Philadelphia Electric Co 83/09/29 App 20645 340 24% Fiche 50-352,83/10/04.8310110305
- 8310130037 Advises that hearing schedule & rept to ABLB inadvertently stapled to response to Limerick Ecology Action & City of Philadelphia 830930 severe accident risk assessment contentions Inconvenience regretted VOOLER, B. H. Hearing Branch 2 83/10/04 BRENNER, L. MORRIS, P. A. COLE, F. A. Achie Safety and Licensing Board Panel 1p 20726 289 24% Fiche 50-352,83/10/04,8310130037
- B310110291 Supplemental affidavit of ME Smith in support of motion for summary disposition of Contention V-4 SMITH:M E Philadelphia Electric Co. B3/10/05 3pp 20866.080 24X Fichs 50-359,83/10/05,8310110291.
- --8310110297 Revised statement of mat! facts as to which there is no genuine issue to be heard
 HETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner
 & Wetterhahn 83/10/05, 11pp 20646 083 24X
 Fichs 50-352,83/10/05,8310110291

3

- --8310110300 Affidevit of VS Boyer re Contention V-4 concerning cross-flow natural draft evaporative cooling towers BIYER.V S Philadelphia Electric Co 83/10/05 1p 20666 094 24% Fiche 50-352,83/10/05.8310110291
- --8310110312 Forwards executed signature page of affidavit of ME Smith & D Seymour in support of motion for summary disposition re Contention V-4 Encl page should be substituted for page sont on 830926 Certificate of Svc encl WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Fhiladelphia Electric Co 83/10/05 Docketing & Services Branch Dpp 20666 095 24X Fiche 50-352,83/10/05,8310110291
- B310110212 Requests assurance that former employment w/NRC does not preclude appearance as counsel for applicant Response by B31017 requested
 SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel B3/10/06 LAVERTY.J H. Conner & Wetterhahn ip 20665-061 24X Fiche 50-352, 83/10/06-8310110212
- B310110275 Answer to Friends of the Earth B30927 petition for extension of time & scheduling of evidentiary hearings after B40101 & motion to dismiss Contentions V-3a & V-3b, or for other sanctions
 WETTERHARN, M J Philadelphia Electric Co WETTERHARN, M J Conner &
- & Motson vo usances sometimes and the solutions wetterhalm, M J Conner Wetterhalm, M J Philadelphia Electric Co WETTERHAHM, M J Conner Wetterhalm 83/10/06 Atomic Safety and Licensing Doard Panel Lipp 20666 166 24% Fiche 50-352,83/10/06,8310110275
- --8310110277 Answer opposing Air & Water Pollution Control 830926 motion to reword Contentions I-62 & V-4 WETTERHAHN.H J Philadelphia Electric Co WETTERHAHN.H J Conner & Wetterhahn 83/10/06 Atomic 8afety and Licensing Board Panet 3pp 20666 182 24X Fiche 50-352,83/10/06.8310110275
- --8310110284 Forwards VS Boyer 831005 affidavit re Contention V-4 HETTERHANN.M J Conner & Wetterhahn WETTERHANN.M J Philadelphia Electric Co 83/10/06 Docketing & Services Branch 2pp. 20666 185 24X Fiche 50-352.83/10/06.8310110275
- --B310110287 Notice of transmittal of add1 matl re Limerick Ecology Action Contention I-42 PETTERHAMN, M J. Philadelphia Electric Co WETTERHAMN, M J. Conner & Netterham B3/10/04 2pp 20446 18/ 24X Fiche 50-352,83/10/04,8310110275
- --8310110292 Answer opposing Limerick Ecology Action respect of Contention I-41 relexacerbation of accidents Contention lasts basis & specificity Certificate of Svc encl WETTERHAHN, MJ., Philadelphia Electric Co. 83/10/05 Atomic Safety and Licensing Board Panel lips 20666-189 24X Fiche 50-352.03/10/06.8310110275
- 8310120364 Motion for summary disposition of Contentions V-3a & V-3b No genuine issue of motl fact exists & util entitled to favorable decision
 HETTERHAHN,M J Philadelphia Electric Co HETTERHAHN,M J Conner & Hetterhahn B3/10/07 Atomic Safety and Licensing Board Panel 1p 20753 341. 24X Fiche 50-352,83/10/07,8310120364
- --8310120369 Statement of matl facts as to which there is no genuine issue re Contentions V-3# & V-3h WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M J Conner & Wetterhahn 83/10/07 Atomic Bafety and Licensing Board Panel 10pp 20753 342 24X Fiche 50-352,83/10/07,8310120364
- --BJIOL20377 Memorandum supporting util motion for summary disposition of Contentions V-3a & V-3b re postulated failure of two pipelines & effect on plant No substantive enswers provided to util discovery requests
 WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M J Conner & Wetterhahn. B3/10/07 Atomic Bafety and Licensing Board Panel 14pp. 20783 382 24X Fiche 50-352,83/10/07.8310120364
- --8310120384 Affidavit of JD Walsh supporting motion for summary disposition of Contentions V-3e & V-3b No adverse effects on tafety-related structures would occur if natural gas in pipeline detonated One aperture cand available in PDR HALBH, J D Philadelphia Electric Co WALSH, J D Bechtel Corp B3/10/06 11pp 20754 003 24X Fiche, 50-352, 83/10/07, 8310120364
- ---83:0120388 Affidavit of VS Boyer supporting motion for summary disposition ARCO, pipeline owner, agreed to prohibit shipping of propane in & through pipelines on plant premises
 Certificate of Svc encl
 BOYER, V. S Philadelphia Electric Co 83/10/06 8pp 20754 014
 24X Fiche 50-352,83/10/07,8310120364

- 8310180419 Response supporting motions to reword Contention V-4
 Applicant objections to rewording deal w/semantics only
 Effect of steam release not limited to visible plume only
 Certificate of Svr encl
 ROMANO, F. R. Air and Water Pollution Potrol 83/10/08 BREANNER, L.,
 MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 1;
 20803-312 24X Fiche 50-352,83/10/08,8310180419
- 8310140071 Reply to util & NRC responses to Limerick Ecology Action severe accident risk assessment contentions Certificate of Svc encl
 ELLIOTT.C W Limerick Ecology Action 83/10/10 Atomic Safety and Licensing Board Panel 69pp 20747 063 24X
 Fiche 50-332,83/10/10.8310140071
- 8310170511 Brief in opposition to Del-Aware Unlimited Inc exceptions to ASLB Partial Initial Decision LBP~83-11 & to ASLB 630601 order denying motion to reapen record No reversible error committed Certificate of Svc encl HODODON, A P Hearing Branch 2 83/10/12 Atomic Safety and Licensing Appeal Panel 41pp 20784 151 24X Fiche 50-352, 83/10/12,8310170511
- 8310180132 Motion for summary disposition of Contention I-62 WETTERHAMN.M J Philadelphia Electric Co WETTERHAMN.M J Conner & Wetterhamn 83/10/12 Atomic Safety and Licensing Board Panel Ip 20807 097 24% Fiche 80-352.83/10/12.8310180132
- --8310180139 Memorandum in support of motion for summary disposition of Contention I-62 re pressurised thermal shock (PTS) PTS will not be problem due to conservative design matl selection, const.testing.operation & surveillance WETTERHAMN J Philadelphia Electric Co WETTERHAMN, M J Philadelphia Electric Co WETTERHAMN, B3/10/12 Atomic Safety and Licensing Board Panel 15pp 20807 098 24X Fiche 50-352,83/10/12,8310180132
- ~-83:0:80:146 Statement of matl facts as to which there is no genuine issue to be heard re Contention I-62
 WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,H J Conner & Wetterhahn B3/10/12 Atomic Safety and Licensing Board Panel 9pp 20807 113 24X Fiche 50-352,83/10/12.8310:80132
- --8310:80:52 Statement of S Ranganath, LB Burns, FE Cooke & SE Carter in support of mation for summary disposition of Contention I-62 Prof qualifications & Certificate of Svc encl RANGANATH, S., BURNS, LB., CODKE, FE Philadelphia Electric Co. 83/10/11 31pp 20807, 122 24X Fiche 50-382, 83/10/12, 8310:80132.
- B310190040 Request for followup to B30927 application to make limited appearance statement before ASLE ANTHONY.R L Anthony.R L B3/10/12 Atomic Safety and Licensing Board Panel 1p 20823 172 24% Fiche 50-332.83/10/12.8310190040
- ---8310190044 Response to ASLB B30913 & 1005 memoranda & orders & 831007 & 12 telcons w/NRC. Intervenor has no affidavit from util as to exact ARCO pipeline location ANTHONY, R L Anthony, R L 83/10/12 1p 20823 173 24X Fiche 50-352, 83/10/12, 8310190040
- 8310190058 Reply to NRC & util filings of severe accident misk assessment/environ mept OL stage, Section 7 issues
 Assessment grossly deficient impact on environ cannot be properly assessed Certificate of Svc entl
 BUSH, M W Philadelphia, PA 83/10/12 Atomic Safety and
 Licensing Board Panel 13pp 20823 198 24X Fiche 50-352,83/10/12,83(0190058
- 8310250100 Response opposing Limerick Ecology Action 830928 respecified Contention I-41 re sys interaction analysis Contention Lacks required specificity & regulatory basis Notice of appearance & Certificate of Svc encl URIOHT.N.A Hearing Branch 2. 83/10/13 Atomic Safety and Licensing Board Panel 12pp. 20895 279 24X Fiche 50-352,83/10/13,8310250100
- 83i0180234 Answer opposing Air & Water Pollution Control 83i002 motion for production of welder certification & for independent retesting involving reactor Motion unsupported & w/o basis WETTERHAHN.M J Philadelphia Electric Co WETTERHAN.M J Conner & Wetterhahn 83/10/14 Atomic Safety and Licensing Board Panel. 3pp 20806 251. 24X Fiche 50-352,89/10/14.83i0180234
- --8310180237 Proposed schedule of util, NRC & M Lewis for hearing ef Contentions I-62, V-3a, V-3b & V-4 Certificate of Byc encl WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn, 83/10/14 5pp. 20808 254 24X Fiche, 50-352, 83/10/14,8310180234

DOCKETED ITEMS

- 8310180243 Advises of no conflict of interest between previous NRC employment & current employment w/Conner & Hetterheho re literasing proceeding LAVERTY, J H Conner & Wetterheho LAVERTY, J H Philadelphia Electric Co 83/10/14 KOHL, C N . OOTCHY, R L . EBLES, G J . Atomic Safety and Licensing Appeal Panel 2pp 20808 249 24X Fichs 50-352,83/10/14,8310180243
- 8310250342 Response to Intervenor Air & Mater Pollution Patrol 830926 motion to reword Contention V-4 & Intervenor MI Lewis 830928 motion to reword Contention I-62 in response to ASLB 830913 memorandum & order Motions should be denied VOOLER, D M Hearing Branch 2 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20878 030 24X Fiche 50-352.83/10/17, 8310250342
- --8310250364 Response to Friends of the Earth 830927 petition for extension of time to reword Contentions V-3a & V-3b & scheduling of syldentiary hearing after 840101 & to applicant motion to dismiss Centificate of Svc encl VOOLER, B H Hearing Branch 2 63/10/17 Atomic Safety and Licensing Board Panel 7pp 20898 033 24X Fiche 50-352, 83/10/17,8310250342
- B310250289 Forwards revised pages to NRC B31012 brief, correcting four inadvertent errors.

 RUTBERGU. Hearing Branch 2 B3/10/18 KOHL.C N , EDLES.G J , GOTCHY.R L Atomic Safety and Licensing Appeal Panel 4pp 20895 347 24X Fiche 50-352, 83/10/18, 8310250289
- --8310250292 Corrected pages to B31012 brief in opposition to Del-Aware Unlimited appeal * Office of the Executive Legal Director #3/10/18 Atomic Bafety and Licensing Appeal Panel 4pp 20895 351 24X Fiche 50-352,83/10/18,8310250289
- 8310240188 Memorandum & order confirming 831017 & 18 prehearing conference rulings on status of certain parties & schedule re Air & Mater Pollution Patrol.Friends of the Earth & Lawis contentions Courtesy notification encl BREANER.L Atomic Safety and Licensing Soard Panel 83/10/20 Air and Water Pollution Patrol 7pp 20878 092 24X Fiche 50-352,63/10/20,8310240188
- 8310260273 Advises of intention to continue as party to litigation on issues re emergency planning W/o svc list Related correspondence
 HERSHEY, B.P. Community Legal Bervices, Inc. HERSHEY, B.P. CEPA
 83/10/21 BRENNER, L. Atomic Bafety and Licensing Board Panel Jp
 20911 308, 24X Fiche 50-352,83/10/21,8310260273
- 8310310336 Response to util 830917 statement of matl fact as to which there is no genuine issue to be heard re motion for summary disposition of Contention V-4 Cooling tower plume issue unaddressed, W/Certificate of 8vc ROMAND, F.R. Air and Water Pollution Patrol 83/10/21 Atomic Safety and Licensing Board Panel 10pp 20959-071. 24x Fiche, 50-352, 83/10/21, 8310310336
- --8310310353 Statement of matl facts as to which there is genuine issue to be heard re cooling tower plumes. ROMANO,F R Air and Water Pollution Patrol 83/10/21 Atomic 84fety and Licensing Board Panel 5pp 20757 081 24X Fiche 50-352,83/10/21,8310310336
- --8310310371 Affidavit of FR Romano re summary disposition of Contention V-4 ROMANO,F R Air and Hater Pollution Patrol. 83/10/21 3pp 20759 086 24X Fiche 50-352,83/10/21,8310310336
 - 1027026B Bitatement of mail facts as to which there is genuine issue as to Contention I-62 Ceptificate of Svc encl
 LEWIS, M I Lewis, N B3/10/24 Atomic Safety and Licensing Board manel, 2pp 20923 327 24X Fiche 30-352,83/10/24,8310270268
 - 8310270356 Statement supporting response to applicant motion for summary disposition of Contention 1-62 LENIS, M I Lewis, M 83/10/24 Atomic Bafety and Licensing Board Penel. 9pp. 20923.329 24X Fiche, 50-352,83/10/24, 8310270268.
 - 310270362 Rebuttal to applicant 831012 statement of matl facts as to which there is no genuine issue as to Contention I-62 LEHIB, M I Lewis, M 83/10/24 Atomic Bafety and Licensing Board Panel. 3pp 20923.338 24X Fiche 50-352,83/10/24, 8310270268
 - 110270368 Response opposing applicant 830927 motion for summary disposition of Contention 1-62 * Lewis, M 83/10/24 Atomic Safety and Licensing Board Panel. 3pp. 20923 341 24X Ficha 50-352,83/10/24,8310270268

- 8310310231 Request for official notice of federal regulation of ultralight aircraft, 47FR38770 Certificate of Svc encl METTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/27 Atomic Safety and Licensing Board Panel 14pp 20947 210 24X Fiche 50-352, 83/10/27, 8310310231
- H General correspondence
- 83(0210295 Urges NRC to continue local hearings on plant issue ADDISON.E T , ADDISON.J C Affiliation Unknown 83/10/17 NRC No Detailed Affiliation Given 2pp 20851 045 24X Fiche 50-352,83/10/17,8310210295
- 8310250047 Package of seven comments opposing plant licensing LEWIS,S C. NEVILLE,J T., TRENT,N Affiliation Unknown 83/10/21 BRENNER,L NRC - No Detailed Affiliation Given 15pp 20894 154 24X Fiche 50-352.83/10/21,8310250047
- 8310280093 Package of two comments on plant licensing Plants should not by licensed w/o neighborhood referendum DZEDZY, J L, MILLER, W S Affiliation Unknown 83/10/26 NRC No Detailed Affiliation von 2pp 20935 079 24X Fiche 50-352,83/10/26,8310280083
- K Utility Final Safety Analysis Report (FBAR) & amends
- B310050437 Forwards Rev 24 to FBAR BRADLEY,E J Philadelphia Electric Co B3/09/30 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 20631 001 24X Fiche 50-352,B3/07/20,B310050437
- 8310250035 Forwards Affidavit of Svc re distribution of Rev 24 to FSAR BRADLEY,E J Philadelphia Electric Co 83/10/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 20875 274 24X Fiche 50-352,83/10/20,8310250035
- @ Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Helder Gualification Tests " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24% Fiche 50-000,83/09/26.8308300340
- B30B300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Svc list encl
 JORDAN, E L Division of Emergancy Praparedness & Engineering
 Response (Post B30103) B3709/26 Consolidated Edison Co of New
 York, Inc 116pp 20777 210 24X Fiche 50-000, B3709/26, B30B300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR0 59 Evaluation " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000.83/09/29,8308300349
- B3i0i30020 Summary of B3083i meeting w/util in Bethesda.MD reintergranular stress corrosion cracking & preservice inspprogram HARRISON, & Licensing Branch 2 83/09/30 Licensing Branch 2 6pp 20777-003 24X Fiche S0-352,83/09/30,83i0i30020
- 8310190176 Forwards IE Insp Rept 50-352/83-11 on 830801-0902 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 83/10/05 KEMPER.J 6 Philadelphia Electric Co 2pp 20818-083 24X Fiche 50-352.83/10/05
- --8310170185 Notice of violation from insp on 830801-0702 * Region 1, Office of Director 83/10/05 ip 20818 085 24% Fiche 50-352,83/10/05,8310170176
- --8310190203 IE Insp Rept 50-352/83-11 on 830801-0902 Noncompliance noted, unqualified welders worked on in-core housing guide tube socket fillet welds CHAUDHARY, 8 K, REYNGLDS, 8 D, NICHOLAS, H H Region 1, Office of Director 83/09/20 iip 20818 086 24X Fiche 50-352,83/10/05,8310190176

- 8308300378 IE Info Notice 83-45, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,03/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc Jist encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases "Svc list encl JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83710711 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders " Svi list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24% Fiche 50-000,83/10/11,8308300761
- S Reportable occurrences. LERs & related correspondence
- 83:0280013 Final significant Deficiency Rept 91 re divsel oil storage tank interior coatings Existing coatings will be removed from all eight diesel generator fuel oil storage tanks & recoated w/substitute Americat 90 epoxy phenolic coating KEMPER, J 8 Philadelphia Electric Co 83/10/05 MURLEY, T E Region i. Office of Director 5pp 20932 273 24X Fiche 50-332,63/10/05,8310280013
- T Hearing transcripts on non-antitrust matters
- B310120176 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831007 meeting in Pottstown.PA Pp 1-252 Viewgraphs encl # ACRS - Advisory Committee on Reactor Safeguards 83/10/07 272pp 20694 267 24X Fiche 50-352/83/10/07.8310120176
- 83:0120168 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831008 meeting in Pottstown, PA Pp 253-530 = ACRS - Advisory Committee on Reactor Safeguards 83/10/08 278pp 20693 349. 24X Fiche 50-352,83/10/08.8310120168
- 0310200185 Transcript of 831017 prehearing conference in Phoenixville, PA Pp 4,530-4.768 Supporting documentation encl = Atomic Safety and Licensing Board Panel 83/10/17 265pp 20834 151 24X Fiche 50-352.83/10/17.8310200185
- 8310210089 Transcript of 831018 prehearing in Phoenixville, PA Pp 4,749-5,047

 a Atomic Safety and Licensing Board Panel 83/10/18 305pp,
 20845 001 24X Fiche 50-352,83/10/18,8310210089
- 8310310171 Transcript of RW Burcik limited appearance statement Urges Commission to grant requested DL BURCIK,R W Affiliation Unknown 83/10/25 Office of the Swcretary of the Commission 2pp 20959 007 24X Fichs 50-352,83/10/25,8310310171
- V. Operator Examinations
- 8310070229 Notification of Significant Licensee Meeting 83-85 on 831025 at site to discuss schedule for conducting licensing elams, including qualification & training for licensed operators JOHKSON, D.F. Region 1, Office of Director 83/09/29, Region 1, Dffice of Director 19 20664 363 24X Fiche 50-352,83/09/29, 8310070229
- DOCKET 50-053 LIMERICK GENERATING STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 833-0050360 Notification of 830926 meeting w/util in Bethesda,MD to discuss draft BNL rept on core mult frequency MARTEN,R E Licensing Branch 2 83/09/21 BCHWENCEH,A Licensing Branch 2 4pp 20650 043 24% Fiche 50-352,83/09/21,8310050360
- 8310040296 Provides addl info re thermal hydraulic stability, per 830624 werbal request Encl revised FSAR tables will be incorporated into FSAR rev scheduled for Oct 1983 KEMPER, J 8 Philadelphia Electric Co 83/09/28 SCHMENCER, A Licensing Branch 2 6pp 20614 207 24X Fiche 50-352,83/09/28, 8310040296

- 8310040124 Forwards response to Equipment Qualification Branch 820730 request for add1 info re audits by Seismic & Dynamic Qualification & Pump & Vaive Operability Review Teams Util will be notified of items selected for 831015 audit KEMPER.J S Philadelphia Electric Co 83/09/30 SCHWENCER.A Licensing Branch 2 1225pp 20408 282 24% Fichs 50-352,83/09/30.8310040124
- --8310040127 Rev O to Procedure 8031-0-14, "General Project Requirements for Seismic Design & Analysis of Equipment Supports" * Bechtel Corp 83/08/19 212pp 20609 215 24X Fichs 50-332,83/09/30,8310040124
- --8310040129 Rev 1 to Procedure 8031-0-19, "Required Response Spectra (RRS) of Primary Containment for Load Combinations of Seismic & Hydrodynamic Loads " * Bechtel Corp 81/08/02 190pp 20610 067 24X Fiche 50-352,83/09/30,8310040124
- --8310040131 Rev 2 to Procedure 8031-0-19. "Required Response Spectra (RRS) of Reactor Bldg & Control Room Structure for Load Combinations of Seismic & Hydrodynamic Loads " 8 Bechtel Corp 82/01/29 530pp 20610 257 24X Fiche 50-352.83/09/30.8310040124
- B310040431 Forwards response to 820730 ltr re operability qualification of pumps & valves Qualification & installation of active pumps & valves 90% complete, per B30916 telcon KEMPER, J S Philadelphia Electric Co 83/09/30 8CHWENCER, A. Licensing Branch 2 57pp 20617 296 24X Fiche 50-352, B3/09/30, B310040431
- 8310140093 Forwards analysis of dust loading on first NEPA filter in ESF HVAC filtration train as discussed in 830926 telcon

 Dust loading capabilities not exceeded
 KEMPER, J 8 Philadelphia Electric Co 83/10/03 BCHMENCER, A.
 Licensing Branch 2 7pp 20767 052 24X Fiche 50-352, 83/10/03, 8310140093
- 8310070243 Forwards revised draft FSAR Page 13 4-B adding superintendent nuclear training section to operating experience assessment committee, per 830929 conference call Rev will be incorporated in Nov 1983 FSAR rev BRADLEY.E J. Philadelphia Electric Co. 83/10/04 BCHMENCER.A Licensing Branch 2 3pp. 2045B 335 24X Fiche 50-352,83/10/04,8310070243
- 8310120062 Advises that operation of facility will not adversely affect significant or archeological resources, provided investigations performed & negative visual impacts eliminated WILLIAMS, D. Pennsylvania, Commonwealth of. 83/10/05 SCHWENCER, A Licensing Branch 2 lp 20696 156 24X Fiche 50-352,83/10/05,8310120062
- 8310140197 Discusses actions to be taken to revise & expand upon applicant 811104 ltr.in response to NRC 830831 request Areas discussed include pipe replacement meth corrections & additions & nonconforming welfs in Class I sys KEMPER.J S Philadelphia Electric Co 83/10/05 EIBENHUT, D 9 Division of Licensing 16pp 20762 333 24X Fiche 50-352,83/10/05,8310140197
- 8310140278 Forwards draft response to 830915 Request for Add1 Info RAI 271 2 re qualification of automatic depressurization sys accumulators per TMI Item II K 3 28 Response will be incorporated in Nov 1983 FBAR rev BRADLEY, E J Philadelphia Electric Co 83/10/05 8CHMENCER, A Licensing Branch 2 9pp 20761 186 24X Fiche 50-352,83/10/05,8310140278
- 8310120148 Forwards clarification of requested info on Misplaced bundle accident analysis, per 830715 twlcom Draft replacement for FSAR Table 15 4-6 and Info will be interporated into next FBAR rev
 KEMPER, J S Philadelphia Electric Co 83/10/07 BCHMENCER, A
 Licensing Branch 2 4pp 20696 018 24X Fiche, 50-352, 83/10/07, 8310120148
- 8310140077 Forwards Amend 57 to OL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing earlier version BRADLEY, E. J. Philadelphia Electric Co. 83/10/07 DENTON, H.R., Office of Nuclear Reactor Regulation, Director 2pp. 20755-001 R4X Fiche 30-352,83/10/07,8310140097
- --83|0|40|0| Amend 57 to OL application, consisting of "Electrical Equipment Environ Qualification Rept" dtd Oct 1983, replacing sariler version Certificate of Svc encil BOYER, V S. BRADLEY, E.J. Philadelphia Electric Co. 83/10/066pp 20755 003 24x Fiche 50-352,83/10/07,8310140097

- --B310140103 "Electrical Equipment Environ Qualification Rept.Limerick Generating Station Units I & 2," Vols I-3 * NUTECH Engineers, Inc B3/10/31 1.667pp 20755 009 24X Fiche 50-352,83/10/07.B310140097
- C Utility Environmental Report (ER), amends & correspondence
- 8310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept OL Stage Question E451 B.FSAR Question 451 9. Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class KEMPER, J S Philadelphia Electric Co 83/10/13 SCHWENCER, A Licensing Branch 2 4pp 20803 310 24% Fichs 50-352,83/10/13, 8310180423
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8310180420 Advises that results of teview of DES re water supply consistent w/findings of Delaware River Commission Rept should address low level radwaste storage & disposal PASTOR.R J Pennsylvania, Commonwealth of, 83/10/04 SCHMENCEN, A sa low levet radwasse sources a service of SCHWENCE Pennsylvanta, Commonwealth of 83/10/04 SCHWENCE Pench 2 3bg 20803 221 24% Fiche 50-352.83/10/04 Licensing Branch 2 8310180420
- E NRC Bafety Evaluation Report (SER), supply & correspondence
- 8310070190 Summary of 830615 meeting w/util, Bechtri & 6% in Bethesda. MD re open SER issue concerning high radiation signal on containment purge vent valves w/respect to placement of radiation monitors & isolation requirements #ARTIN.R E Licensing Branch 2 83/09/29 Licensing Branch 2 13pp 20680 235 24% Fiche 50-352.83/09/27,8310070190
- 8310110132 Forwards draft revs to FSAR re BER Den Item Issue 19 concerning fraquency classification of generator load rejection w/bupass failure & turbine trip w/bupass failure exerts FSAR revs scheduled for Nov 1983 KEMPER. J S Philadelphia Electric Co 83/10/03 SCHMENCER. A Litensing Branch 2 9pp 20866 299 24% Fiche 50-352.83/10/03, 8310110132
- 8310120392 Forwards draft revs to FSAR Sections 1 8.5 2 & 7 7 & draft revised response to FSAR Guestion 410 23.per 831222 meeting re SER Open Issue 8 concerning airborne particulate radioactivity monitoring sys.
 KENPER.J B Philadelphia Electric Co 83/10/05 8CHHENCER.A
 Licensing Branch 2 25pp 20698 060 24% Fiche 50-352,83/10/05,
 B310120392
- 8310260316 Summery of B30707 meeting w/util in Bethesda: MO re overpressurization of standby gas treatment sys ductwork & filters Issue resolved Disposition discussed in SER. NUREO-0991 issued in Aug 1983 MARTIN: R E Licensing Branch 2 83/10/19 Licensing Branch 2 19pp 20921 220 24% Fiche 50-352,83/10/19,8310260316
- F Security, medical, emergency & fire protection plans
- 8310040110 Forwards final schedule for satisfying requirements of Generic Ltr 82-33 re Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability " SCHMENCER.A Licensing Branch 2 83/09/26 BAUER.E @ Philadelphia Electric Co 4pp 20634 336 24X Fiche 30-352,83/09/26,8310040110
- 8310180423 Forwards "Limerick Generating Station Request For Addl Info Environ Rept UL Stage Guestion F451 8.FSAR Guestion 451 7, Joint Frequency Distributions of Wind Direction & Speed by Atmospheric Stability Class "
- 8310RB0127 Responds to NRC B30926 ltm me schedule for meeting emergency response capability requirements Const schedule will permit fuel loading by 840801 Full scale emergency preparedness exercise rescheduled to 840725
 BOYER.V 8 Philadelphia Electric Co 83/10/25 SCHMENCER.A Licensing Branch 2 Spp 20929 273 24X Fiche 50-352,83/10/25,83/100/137 Licensing Branch 2 8310280127
- Adjudicatory correspondence
- 8309130054 Forwards receipts indicating that draft offsite emergency plans received by City of Philadelphia & by J Dorsey on behalf of intervenors BRADLEY.E J Philadelphia Electric Co 83/09/07 BRENNER.L. MORRIS.P.A., COLE.R.F. Atomic Safety and Licensing Board Panel 4pp 20356 177 24X Fiche 50-352,03/09/07,8309130054

- 8310030437 Motion to modify wording of Contention V-4 on carbureter tring
 ROHAND, F.R. Arr and Water Pollution Patrol. 83/09/26 BRENNER, L.,
 COLE, R.F., MORRIS, P.A. Atomic Safety and Licensing Board Panel. 1p.
 20602-094 24X Fiche 50-352.83/09/26.8310030417
- 8310050423 Notice of withdrawal of appearance in proceeding Certificate of Svc pnci CMAN.E J Hearing Branch 2 83/09/27 3pp 20632 351 24X Fiche 50-352,83/09/27,8310050423
- 8310040471 Mation to reword Contention 1 62 re pressurized thermal shock in response to ASLB 830913 memorandum & order Certificate of Svc encl LENIG, M I Lewis, M 83/09/28 Atomic Safety and Licensing E Panel 3pp 20625 162 24X Fiche 50-352,83/09/28,8310040491
- 9310040498 Respec of Contention 1-41 re sys interaction Certificate of Svc encl
 DORSEY, J.A. Limerick Ecology Action DORSEY, J.A. Dorsey, J.A.
 83/09/28 BRENNER, L., COLE, R.F., MORRIS, P.A. Atomic Safety and
 Licensing Board Panel 8pp 20625 15.º 24% Fiche 50-352,83/09/28,
 8310040498
- 8310040187 Memorandum & order re util 830927 motion for summary disposition of Contention V-4 Util directed to file new statement of math fact w/supporting citations by 831006 DRENNER, L Atomic Safety and Licensing Board Panel 83/09/30 Philadelphia Electric Co 5pp 20608 084 24X Fiche 50-352.83/09/30.8310040187
- 8310040627 Rept per ASLB 830913 memorandum & order re establishment of hearing schedule & re MI Lewis.Friends of the Earth & Air & Water Pollution Patrol contentions Certificate of Svc encl WETTERHAHNAM J Philadelphia Electric Co WETTERHAHNAM J Conner (Wetterhahn 83/09/30 6pp 20626 183 24X Fiche 50-392,83/09/30,8310006677 B310040627
- 8310050429 Response to Limerick Ecology Action 830831 proposed severe accident assessment rept/environ rept OL stage (SARA/EROL) Section 7 contentions & City of Philadelphia 830920 SARA Concerns
 VOGLER: B H Hearing Branch 2 B3/09/30 Atomic Safety and
 Licensing Board Panel 14pp 20633 216 24X Fiche 50-352,83/09/30,
 3310030429
- --B310050432 Rept on behalf of applicant,M Lewis,Air & Water Pollution Patrol, Friends of the Earth & Limerick Ecology Action, in response to ASLB 830913 memorandum re hearing schedule proposals Certificate of Svc encl MODODON,A P Hearing Branch 2 B3/09/30 Atomic Safety and Licensing Board Panel App 20633 230 24% Fiche 50-350. B3/09/30,8310050429
- 8310060305 Forwards author notice of appearance in proceeding Author should be substituted for TY Au on svc list Certificate of Should be substituted in the state of the substitute of the substi
- 8310040183 Hemanandum & order shortening schedule for answers to respec of Limerick Ecology Action Contention I-41 re sys interaction Util answer shall be received by NRC by 831007 & by ASLB & Limerick by 831011

 BRENNER: Atomic Safety and Licensing Board Panel 83/10/03 4pp 20608 080 24X Fiche 50-352,83/10/03.8310040183
- 8310050515 Brief opposing Del-Aware Unlimited, Inc exceptions to ASLB 83030B partial initial decision & 830601 memorandum & order denying Del-Aware motion to reopen record Notice of appearance & Certificate of Svc encl CONNER, T B Philadelphia Electric Co CONNER, T B Conner & Wetterhahn 83/10/03 Atomic Safety and Licensing Appeal Panel 120pp 20630 210 24% Fiche 50-352, 83/10/03, 8310050515
- 8310110052 Memorandum & order re hearing schedules proposed by parties NRC schedule wasentially acceptable BRENNER, L Atomic Safety and Licensing Board Panel Q3/10/04 4pp 20668 265 24X Fiche 50-352.83/10/04.8310110082
- 8310110305 Second interim rept to ASLB re Contention VI-1 WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner Hetterhahn 83/10/04 ip 20645 339 24% Fiche 50-352.83/10/84.
- --8310110307 Affidavit of VS Boyer re review of welds in 1976 under responsibility of GC inspector Certificate of Syc entl BOYER, V S Philadelphia Electric Co 83/09/29 opp 20665 340 24x Fiche 50-352,83/10/04,8310110305

- 831013037 Advises that hearing schedule & rept to ASLB inadvertently stapled to response to Limerick Ecology Action & City of Philadelphia 830930 severe accident risk assessment contentions Inconvenience regretted WOOLER.B H. Hearing Branch 2 83/10/04 BRENNER.L. MORRIS,P.A., COLE.R F. Atomic Safety and Licensing Board Panel ip 20726 289 24% fiche 50-352,83/10/04,8310130037
- B310110291 Supplemental affidavit of ME Smith in support of motion for summary dispusition of Contention V-4
 SMITH:ME Philadelphia Electric Co 83/10/05 3pp 20666 080
 24X Ficho 50-332.83/10/05.8310110291
- --8310110297 Revised statement of mat) facts as to which there is no genuine 1850e to be heard WETTERHAIN, H J Philadelphia Electric Co WETTERHAIN, H J Conner & Wetterhahn 83/10/05 11pp 20466 083 24x Fiche 50-352.83/10/05.8310110291
- --8310110300 Affidavit of V8 Boyer re Contention V-4 concerning crass-flow natural draft evaporative cooling towers DOYER, V 8 Philadelphia Electric Ca 83/10/05 1p 20666 094 24X Fiche 50-352,83/10/05.8310110291
- --8310110312 Forwards executed signature page of affidavit of ME Smith & D Seymour in support of motion for summary disposition re Contention V-4 Encl page should be substituted for page sent on 830926 Certificate of Svc encl HETTERHAHN, M J Conner & Mutterhahn WETTERHAHN, M J Philadelphia Electric Co 83/10/05 Docketing & Services Branch 5pp 20666 095 24X Fiche 50-352,83/10/05,8310110291
- 8310110212 Requests assurance that former employment w/NRC does not preclude appearance as counsel for applicant Response by 831019 requested SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel SA/10/06 LAVERTY.J H Conner & Wetterhahn ip 20665 061 24% Fiche 50-352.83/10/06.8310110212
- 83101(0275 Answer to Friends of the Earth 830927 petition for extension of time & scheduling of evidentiary hearings after 840101 & motion to dismiss Contentions V-3a & V-3b or for other sanctions
 WETTERHAHM, M J Philadelphia Electric Co WETTERHAHM, M J Conner & Metterhahm 83/10/06 Atomic Safety and Licensing Board Panel 11pp 20666 166 24X Fiche 30-352,83/10/06.8310110279
- --8310310277 Answer opposing Air & Hater Pollution Control 830926 motion to raword Contentions I-62 & V-4 WEYTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn B3/10/06 Atomic Safety and Licensing Board Panel 3pp 20666 182 24X Fiche 90-352,83/10/06,8310110275
- --B310110284 Forwards V8 Boyor 831005 affidavit re Contention V-4 WETTERHANN,M J. Conner & Wetterhahn METTERHANN,M J Philadelphia Electric Co 83/10/06 Docketing & Services Branch 2pp 20666 185 24% Fiche 50-352,83/10/06,8310110275
- --8310110287 Notice of transmittal of add1 mat1 re Limerick Ecology Action Contention I-42 WEYTERHAHN.M J. Philadelphia Electric Co & Metterhahn 83/10/06 2pp 20466 187 24X Fiche 50-352,83/10/06,8310110275
- --8310110292 Answer opposing Limsrick Ecology Action respect of Contention I-41 re exacerbation of accidents Contention Tacks basis & specificity Certificate of Svc encl HETTERHAHN, M.J. HETTERHAHN, M.J. Philadelphia Electric Co. B3/10/06 Atomic Safety and Licensing Board Panel ilp; 20464-189 24% Fiche 50-352, B3/10/06, B310110275
- B310120364 Hotion for summary disposition of Contentions V-3a & V-3b No genuine issue of math fact exists & util entitled to favorable decision
 HETTERHAHN, M J Philadelphia Electric Co METTERHAHN, M J Conner & Wetterhahn B3/10/07 Atomic Bafety and Licensing Board Panel ip 20753 341 24X Fiche 50-352,83/10/07,8310120364
- --9310120368 Statement of matl facts as to which there is no genuine issue re Contentions V-3a & V-3b
 WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M J. Conner & Wetterhahn B3/10/07 Atomic Safety and Licensing Board Panel 10pp 20753 342 24X Fiche 50-352,83/10/07.8310120364
- --8310120377 Memorandum supporting util motion for summary disposition of Contentions V-3a & V-3b re postulated failure of two pipelines & effect on plant No substantive answers provided to util discovery requests WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 83/10/07 Atomic Sofety and Licensing Board Panel 14pp 20753 352 24X Fiche 50-352,83/10/07,8310120364

- --83101203B4 Affidavit of JD Walsh supporting motion for summary disposition of Contentions V-3a & V-3b No adverse effects on safety-related structures would occur if natural gas in pipeline detonated One aperture card available in PDR WALSH. J D Philadelphia Electric Co WALSH. J D Bechtel Corp 83/10/06 Lipp 20754 003 24% Fiche 30-352,83/10/07.8310120364
- --0310120308 Affidavit of VS Boyer supporting motion for summary disposition ARCO, pipeline owner, agreed to prohibit shipping of propane in & through pipelines on plant premises Certificate of Svc encl
 BOYER.V S Philadelphia Electric Co 83/10/06 Bpp 20754 014 24X Fiche 50-352, 83/10/07, 8310120364
- B310180419 Response supporting motions to reword Contention V-4
 Applicant objections to rewording deal w/semantics only
 Effect of steam release not limited to visible plume only
 Certificate of Svc encl
 ROMANO,FR Air and Water Pollution Patrol, 83/10/08 BRENNER,L,
 MORRIS,P A, COLE,R F Atomic Safety and Licensing Board Panel. 1p
 20803 312 24X Fishe 50-352.83/10/08.B310180419
- B310140071 Reply to util & NRC responses to Limerick Ecology Action severe accident risk assessment contentions Certificate of Svc encl ELLIGIT.C W Limerick Ecology Action 83/10/10 Atomic Safety and Licensing Board Panel 67pp 20767 063 24X Fiche 50-352,83/10/10,8310140071
- 8310170511 Brief in opposition to Del-Aware Unlimited, Inc exceptions to ASLS Partial Initial Decision LBP-BG-11 & to ASLS 830601 order denying motion to reopen record No reversible error committed Certificate of Syc enc.1
 HODODON, A. P. Hearing Branch 2 83/10/12 Atomic Safety and Licensing Appeal Panel 41pp. 20784 151 24% Fiche 50-352, 83/10/12,8310170511
- 8310180132 Motion for summary disposition of Contention I-62 WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN.M J Conner & Hatterhahn 83/10/12 Atomic Safety and Licensing Board Panel Ip 20807 097 24X Fiche 30-332.83/10/12.8310180132
- --8310180139 Nemorandum in support of motion for summary disposition of Contention I-62 re pressurized thermal shock (PTS). PTG will not be problem due to conservative design, mat1 selection, const.testing, operation & surveillance
 WETTERHAHN.M J. Philadelphia Electric Co. WETTERHAHN.M J. Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 15pp 20807 098 24X Fiche 50-352.83/10/12.8310180132
- ---8310180146 Statement of matl facts as to which there is no genuine issue to be heard re Contention I-62
 WETTERHAHN.N J Philadelphia Electric Co WETTERHAHN.N J Conner & Wetterhahn B3/10/12 Atomic Sefety and Licensing Board Panel 9pp 20807 113 24X Fiche 50-352,83/10/12,8310180132
- --8310180182 Statement of S Rangamath, LS Burns, FE Cooke & SE Carter in support of motion for summary disposition of Contention I-62 Prof qualifications & Certificate of Svc encl RANGANATH, S. BURNS, L. S. CÓDKE, F. E. Philadelphia Electric Co 83/10/11 31pp 20807 122 24X Fithe 50-352, 83/10/12, 8310180132
- 8310190040 Request for followup to 830927 application to make limited appearance statement before ASLB ANTHONY, R L Anthony, R L 83/10/12 Atomic Safety and Licensing Board Panel 1p 20823 172 24X Fiche 50-352,83/10/12,8310190040
- --8310190044 Response to ASLB 830913 & 1005 memorands & orders & 831007 & 12 telcons w/NRC, Intervenor has no affidavit from util as to exact ARCO pipeline location ANTHONY, R L Anthony, R L 83/10/12 ip 20823 173 24X Fiche 50-352,83/10/12,8310190040
- 8310190058 Reply to NRC & util filings re severe accident risk assessment/environ rept OL stage, Section 7 issues
 Assessment grossly deficient Impact on environ cannot be properly assessed. Certificate of Svc enci
 BUSH.M W Philadelphia, PA 83/10/12 Atomic Safety and
 Licensing Board Panel 13pp 20823 198 24X Fiche: 50-332, 83/10/12, 8310190058
- 8310250100 Response opposing Limerick Ecology Action 830928 respectified Contention I-41 me sys interaction enalysis Contention lacks required specificity & regulatory basis Notice of appearance & Certificate of Svc encl
 HRIOHTIN A Hearing Branch 2 83/10/13 Atomic Safety and Licensing Board Panel 12pp 20895 279 24X Fiche 50-352,83/10/13,8310250100

- 8310180234 Answer apposing Air & Water Pollution Control 831002 motion for production of welder certification & for independent retesting involving reactor Motion unsupported & w/o basis WETTERHAHN, M J Philadelphia Electric Co HETTERHAHN, M J Conner & Wetterhahn 83/10/14 Atomic Safety and Licensing Board Panel 3pp 20806 251 24X Fiche 50-352.83/10/14.8310180234
- --8310180237 Proposed schedule of util.NRC & M Lewis for hearing of Contentions I-62.V-3a.V-3b & V-4 Certificate of 8vc encl METTERHAMN,M J Philadelphia Electric Co WETTERHAMN,M J Conner & Wetterhahn 83/10/14 5pp 20808 254 24X Fiche 50-352.83/10/14.8310180234
- 8310180243 Advises of no conflict of interest between previous NRC employment & current employment w/Conner & Wetterhahn relicensing proceeding
 LAVERTY.J H Conner & Wetterhahn LAVERTY.J H Philadelphia Electric Co 83/10/14 KOHL.C N . GDTCHY.R L . EDLES.G J Atom Safety and Licensing Appeal Panel 2pp 20808 249 24X fiche 50-352,83/10/14,8310180243
- 8310250342 Response to Intervenor Air & Water Pollution Patrol 830926 motion to reword Contention V-4 & Intervenor MI Lewis 830928 motion to reword Contention I-42 in response to ASLB 830913 memorandum & order Motions should be denied VOQLER.B H Hearing Branch 2 83/10/17 Atomic 8afety and Licensing Board Panel 3pp 20898 030 24X Fichs 50-352.83/10/17, 8310250342
- --B310250364 Response to Friends of the Earth B30927 petition for extension of time to reword Contentions V-3s & V-3b & scheduling of evidentiary hearing after B40101 & to applicant motion to dismiss Certificate of Svc encl VOCLER, B H Hearing Branch 2 B3/10/17 Atomic Safety and Licensing Board Panel 7pp 20898-033 24X Fiche 50-352, 83/10/17,8310250342
- 8310250289 Forwards revised pages to NRC 831012 brief.correcting four inadvertent errors RUTBERG, J Hearing Inadvertent errors
 RUTBERG, J Hearing Branch 2. 83/10/18 KOHL, C N . EDLES, O J .
 ROTCHY, R L Abomic Safety and Licensing Appeal Panel App.
 ROB95.347. 24% Fiche: 50-352.83/10/18.8310250289.
- --8310250292 Corrected pages to 831012 brief in opposition to Del-Aware Uniimited appeal # Office of the Executive Legal Director #3/10/18 Atomic Safety and Licensing Appeal Panel 4pp 20895 351 24X Fiche 50-332,83/10/18,8310250289
- 8310240188 Hemorandum & order confirming 831017 & 18 prehearing conference rulings on status of certain parties & schedule re Air & Mater Pollution Fatrol. Friends of the Earth & Lewis contentions Courtesy notification encl.

 BRENNER: L. Atomic Safety and Licensing Board Panel 83/10/20 Air and Mater Pollution Patrol. 7pp 20878 092 24X Fiche 50-352,83/10/20,8310240188 83/10/20
- |310260273 Advises of intention to continue as party to litigation on issues re emergency planning W/o svc list Related correspondence.
 HERSHEY, 8 P. Community Legal Services, Inc. HERSHEY, 8 P. CEPA.
 83/10/21. BRENNER, L. Atomic Safety and Licensing Board Panel. 1p
 20911 308. 24X Fichs 50-352,83/10/21.8310260273
- 8310310336 Response to util 830917 statement of matl fact as to which stodiologic response to til 1930/17 statement of matl fact as to whis there is no genuine issue to be heard re motion for summary disposition of Contention V-4. Cooling tower plume issue unaddressed M/Certificate of Svc ROMANO, F.R. Air and Mater Pollution Patrol. 83/10/21 Atomic Safety and Licensing Board Penel 10pp 20959:071. 24X Fichs. 50-352, 83/10/21.83103103133
- --8310310353 Statement of matl facts as to which there is genuine issue to be heard re cooling tower plumes

 ROMAND,F.R Air and Water Pollution Patrol 83/10/21 Atomic Safety and Licensing Board Panel 5pp 20939:081. 24X Fiche 50-352,83/10/21,8310310336.
- -8310310371 Affidavit of FR Romano re summery disposition of Contention ROMANO, F.R. Air and Water Pollution Patrol 83, 20959:086, 24% Fiche:50-352,83/10/21,8310310336. 83/10/21 300
- 310270268 Statement of mat1 facts am to which there is genuine issue as to Contention I-62. Certificate of Bvc enc1 LEMIS, M. I Lewis: M. 83/10/24 Atomic Bafety and Licensing Board Panel. 2pp. 20923. 327 24X Fiche 50-352, 83/10/24, 8310270268
- 8310270356 Statement supporting response to applicant motion for summary disposition of Contention I-62.
 LEMIS.M I Lewis. M 83/10/24 Atomic Safety and Licensing Board Panel 9pp, 20923, 329. 24X Ficher 50-352, 83/10/24.

- --B310270362 Rebuttal to applicant 831012 statement of matl facts as to which there is no genuine issue as to Contention I-62 LEWIS, M I Lewis, M B3/10/24 Atomic Safety and Licensing Board Panel 3pp 20923 338 24X Fishe 50-352.83/10/24.
- --8310270368 Response apposing applicant 83092/ motion for summary disposition of Contention 1-62

 * Lewis, M 63/10/24 Atomic Bafety and Licensing Board Panel 3pp 20928 341 24X Fiche 50-352.63/10/24.8310270268
- 8310310231 Request for official notice of federal regulation of ultralight aircraft.47FR38770 Certificate of Svc encl N. M. J. Philadelphia Electric Co. WETTERHAHN.M.J. Philadelphia Electric Co. WETTERHAHN.M.J. Conner & Wetterhahn 63/10/27 Atomic Safety and Licensing Board Panel 14pp. 20747 210. 24% Fiche 50-352.83/10/27.8310310231

H General correspondence

- 8310210295 Urges NRC to continue lotal hearings on plant ADDISON.E T , ADDISON.J C Affiliation Unknown 83/10 No Detailed Affiliation Given 2pp 20851 045 Fiche 50-352,63/10/17.8310210295 83/10/17 NRC -
- 9310250047 Package of seven comments opposing plant licensing
 LEWIS.S C. NEVILLE.J T. TRENT.N Affiliation Unknown 83/10/21
 BRENNER.L NRC No Detailed Affiliation Given 15pp 20894 154
 24X Fichs 50-352,83/10/21,8310250047
- 8310280083 Package of two comments on plant licensing Plants should not DEDZY, J. L. Miller, W. S. Affiliation Unknown 83/10/26 Detailed Affiliation Olven 2pp 20935 079 24X Fiche 50-352,83/10/26.8310280083 NRC - No
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8310050437 Forwards Rev 24 to FSAR DRADLEY, E.J. Philadelphia Electric Co. 83/09/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 20431 001 24X Fiche 50-352,83/09/30,8310050437
- 8310250035 Forwards Affidavit of Syc re distribution of Rev 24 to FBAR BRADLEY, E J Philadelphia Electric Co B3/10/20 DENYON, H R Office of Nuclear Reactor Regulation, Director Spp 20895 274 24X Fiche 50-352, 83/10/20, 8310250035
- G. Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Natice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- B30B300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Past B30103) B3709/26 Consolidated Edison Co of New York, Inc 116pp 20777, 210 24X Fiche 50-000, B3/09/26, B30B3000342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Bvc list encl JORDANE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 lE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Syc list enci JURDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310130020 Summary of 830831 meeting w/util in Bethesda.MD raintergranular stress corrosion cracking & preservice insp program Harrison, c Licensing Branch 2 83/09/30 Licensi 003 24X Fiche. 50-352, 83/09/30, 8310130020 20777 003
- 830830037B IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants," Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 63/10/07. Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378

- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility "Svc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79p 20882 024 24X Fiche 50-000,83/10/07.8308300752
- B30B300759 IE Info Natice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Oases "Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co. of New York, Inc. 117pp. 21043-075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list
 - VICTOAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New Yark, Inc. 120pp 20827 129 24X Fiche 50-000.83/10/11.8308300761
- S Reportable occurrences, LERs & related correspondence
- 8310280013 Final significant Deficiency Rept 91 re diesel oil storage tank interior coatings Existing coatings will be removed from all eight diesel generator fuel oil storage tanks & recoated w/substitute Americant 90 spoxy phenolic coating KEMPER, J S Philadelphia Elettric Co 83/10/05 MURLEY, T E Region 1, Office of Director Spp 20932 273 24X Fiche 50-352,83/10/05,8310280013
- T Hearing transcripts on non-antitrust matters
- B310120176 Transcript of ACRS Bubcommittee on Limerick Generating Station Units 1 & 2 831007 meeting in Pottstown, PA Pp 1-232 Viewgraphs encl **ACRS **Advisory Committee on Reactor Safeguards 83/10/07 272pp 20694 267 24X Fiche 50-352, 83/10/07.8310120176
- 9310120168 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831008 meeting in Pottstown, PA Pp 253-530
 - 3-530 ACRS Advisory Committee on Reactor Safeguards 83/ 8pp 20673 347 24% Fiche 50-352.83/10/08.8310120168
- 8310200185 Transcript of B3101/ prehearing conference in Phoenisville, PA.Pp 4,530-4,768 Supporting documentation enc1

 * Atomic Safety and Licensing Board Panel 83/10/17 265pp.
 20834 151 24X Fiche 50-352.83/10/17,8310200188
- 8310210089 Transcript of 831018 prehearing in Phoenixville.PA Pp 4.769-5.047 * Atomic Safety and Licensing Board Panel 83/ 20845 001 24X Fiche 50-352,83/10/18,8310210089 83/10/18 305pp
- 6310310171 Transcript of RW Burcik limited appearance statement Urges Commission to grant requested GL BURGIN, R W Affiliation Unknown 83/10/25 Defice of the Secretary of the Commission 2pp 20/59 007 24X Fiche 50-352,83/10/25,8310310171
- BOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8310130411 Forwards request for add1 info re safety review of QL application Response should be submitted within 63 days of 930930 ltr 830930 ltr SCHNENGER,A Licensing Branch 2 83/09/30 MITTL.R.L Pub Service Electric & Oas Co of New Jersey 16pp, 20770 001. Fiche 50-354,83/09/30,8310130411 Public.
- 8310070219 Notification of 831005 meeting w/util in Bethesda.MD to discuss seismological & geotechnical issues for facility MAGNER, D Licensing Branch 2 83/10/03 8CHMENCER.A Licensing Branch 2 4pp 20676 358 24X Fichs 50-354.83/10/03.8310070219.
- 8310070223 Notification of 831005 meeting w/util in Bethesda, MD to 41scus: structural & geobechnical issues for facility MAGNER, D Licensing Branch 2 83/10/03, SCHWENCER, A. Licensing Branch 2 4pp 20676 344 24X Fiche, 50-354, 83/10/03, 8310070223.
- 8310250215 Forwards info re seismic & dynamic qualification test program, per FSAR commitment Seismic & environ test schedule for non-NS88 supplied components summarized HITTL.R.L Public Service Electric & Oas Co. of New Jersey 83/10/05 86HMENGER.A Licensing Branch 2. 23pp 20894 037 24X Fiche 50-354,83/10/05.8310250215

- 8310210125 Forwards updated distribution list for environ rept OL stage.FSAR & general info SCHMENCER.A Licensing Branch 2 83/10/13 HITTL.R L Service Electric & Gas Co of New Jursey 6pp 20883 267 Fiche 50-354,83/10/13.8310210125
- C Utility Environmental Report (ER), amends & correspondence
- 8310210125 Forwards updated distribution list for environ rept OL stags.FSAR & general info SCHWENCER.A Licensing Branch 2 83/10/13 MITTL.R L Service Electric & Gas Co of New Jersey 6pp 20883.267 Fiche 90-354.83/10/13.8310210125
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310200239 Proposes schedule for balance of sefety review questions to aupport 840221 draft SER date Responses could be transmitted to NRC by 840110 if questions finalized by 83111 Two major FBAR chapters still under NRC review.

 MITTL,R L Public Service Electric & Gas Co of New Jersey 83/10/13 SCHMENCER, A Licensing Branch 2 2pp 20833 057. 24X

 Fiche 50-354,83/10/13,8310200239
- F Security, medical, emergency & fire protection plans
- 8310240143 Forwards "Control Room Design Review Program Plan. Hope Creek 310240143 Forwards "Control Room Design Review Program Fiamh Hope Cree Generating Station," in response to Generic Ltr 82-33, Item 5 Summary rept will be submitted by 840815 HITTL,R L Public Bervice Electric & Gas Co. of New Jersey 83/10/17 SCHMENGER,A Licensing Branch 2 2pp 20880,039 24X Fiche 50-354,83/10/17,8310240143
- G Adjudicatory correspondence
- 8310030484 Notice of appearance in proceeding Certificate of Svc encl FRYLING.R Public Service Electric & Gas Co of New Jersey 83/09/29 3pp 20401 074 24X Fiche 50-354,83/09/29,8310030484
- 8310050410 Response to Public Advocate, State of NJ 830707 petition to intervene as party-intervenor in hearing areas re GA & emergency planning Petition not opposed Cortificate of Svc WHEEL GODDARD, R J Hearing Branch 3 83/09/29 Atomic Safety and Licensing Board Panel 4pp 20633 183. 24X Fiche 50-354,83/09/29,8310050410
- B310200247 Memorandum furnishing qualification & prior prof activities of Judges JH Carpenter PA Morris & ME Miller in advance of B31122 special prehearing conference Resumes encl. MILLER, ME Atomic Bafety and Licensing Board Panel B3/10/18 Bpp 20829-298. 24X Fiche 50-354,83/10/18.8310200247
- 8310270381 Informs that updated FBAR will be forwarded as soon as clerical work completed Related correspondence.

 CONNER, T B Conner & Wetterhahn. B3/10/25. MILLER, M.E. Atomic
 Safety and Licensing Board Panel. 1p 20923 344. 24X
 Fichs. 50-354,83/10/25,8310270381.
- G Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Btand-Ins for Welder Qualification Tests " Evc list encl JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp. 20754-022 24% Fiche. 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342.
- B30B300045 IE Info Notice B3-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays," Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103). B3/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche: 50-000, B3/09/26, B308300345

- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Releted Bys W/o 10CFR50 59 Evaluation " Svc list
 - enci JORDAN-E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24% Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-45, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 8030103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300792 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list entl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300799 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Novious Gases" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defettive Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JBRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Int 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- S Reportable occurrences. LERs & related correspondence
- 8310280101 Potential const deficiency rept re shortened Hilti expansion anchors used in raceway support installations Initially reported on 830816 Exams expected to be completed during wk of 830926 Final rept by 8310928 MARTIN.T J Public Service Electric & Cas Co of New Jersey 8310974 MMREV.T E Region 1. Diffice of Director 2pp 20935 326 24X Fiche 50-354,83/09/14,8310280101
- 8310280075 Significant const deficiency rept re four 0E pressure switches containing undercured 0-ring that could allow leakage of process fluid into electrical portion of devices Switches will be replaced by 831216 MARTIN.T J Public Bervice Electric & Gas Co of New Jersey 83/09/29 MURLEY.T.E. Region 1. Office of Director 2pp 20935 077 RAX Fiche 50-354,83/09/28,8310280075
- 8310280093 Potential const deficiency mapt re Basler Electric Coresistors installed in emergency dissel generators Initially reported on 830901 & reported by vendor under Part 21 on 830819 Final rept expected by 831103 MARTIN.T.J. Public Service Electric & Cas Co. of New Jersey 83/09/30 MURLEY.T.E. Region 1. Office of Director 2pp 20935 382 24% Fiche 50-354,83/09/30,8310280093
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8310280212 Responds to appeal re denial of FOIA request for OFC oF Investigation repts concerning facility Grants appeal in part Forwards document Info partially withheld (ref FOIA Exemption 7).
 CHILK, 8 J Office of the Secretary of the Commission 83/08/24.
 DEVINE.T Government Accountability Project 2pp 20944, 198 24X Fiche, 50-358, 83/08/24, 8310280212
- ---B310280224 Bubmits revised proposal for providing completion sycs for facility Rev to proposal, originally submitted on 821108, responds to Commission 821122 order to show cause List of independent review team members encl
 REINSCH.H D Bechtel Corp. 82/11/23 DICKHONER, N H Cincinnati
 Cas & Electric Co 7pp 20964 265 24X Fiche 50-358,83/08/24, 8310280212
- ---8310280227 Supple B21123 ltr in response to JO Keppler 821228 request, directed to util.re Bechtel mgt role Soderholm involvement discussed,

 'AHL.H W Sechtel Corp. 82/12/27 DICKHONER, H H Cincinnati Qas Tlectric Co 6pp 20764 276 24X Fiche: 50-358,83/08/24,
 - B0231 Forwards description of steps to be taken to identify assary organizational & procedural action, resumes of mase I team members, summarizes of Bechtel nuclear experience & contract forms Info deleted REINSCH.H O Bechtel Corp. 82/11/08 DICKHONER.W H Cincinnat Gas & Electric Co 48pp 20964 308 24X Fiche, 50-358, 83/08/24, 8310280215.

- B310040522 Comments on implementation of recommended independent design review Design verification should be conducted in parallel w/verification of const quality
 NEYLAN, J Torrey Pines Technology B3/09/12 WILLIAMS, J Cincinnati Oas & Electric Co 2pp 20624 235 24X
 Fiche 50-358, B3/09/12, 8310040522
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway CISENHUT.D & Division of Licensing 83/09/29 PALLADINO.N J Commissioners 3pp 20432 001 24X Fiche 50-000,83/09/29,
- B310040459 Amend 151 to OL application, consisting of Rev 97 to FSAR WILLIAMS, J Cincinnati Gas & Flettic Co B3709/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20824 031 24X Fiche 50-338, B3709/30, B310040459
- 8310120304 Forwards agends & topics of 830727 prebid meeting for independent design review Attendance list. GA matrix. isometrics of RNR sys & responses to questions raised encl KRAUS.H J Cincinnati Oas & Electric Co B3/09/30 KEPPLFR, J G Region 3, Office of Director 28pp 20690 351 24X Fithe 50-358, 83/09/30,8310120304
- 8310170515 Forwards Rev 24 to "Natl Board Tasks Rept " Rept assembled for tracking progress on concerns raised by Natl Board Interim Repts 1 & 2. Suppls P. 3. 5. 7 & 13
 WILLIAMS. J. Cincinnati Oas & Electric Co. 83/10/03 YOST, R A
 Obio, State of Ip 20784 253 24X Piche 50~358,83/10/03,
 8310170515
- --83101705)B Rev 24 to "Natl Board Tasks Rept "
 # Cincinnati Gas & Electric Co 83/07/30 61pp 20784 254 24x
 Fiche 50-358, G3/10/03, 8310170515
- 8310060497 Declines to approve work requested in 830414 & 0808 & 29 ltrs Revised organization should be in place & program to complete const identified & under NRC review prior to approval KEPPLER, J. Q. Region 3, Office of Director 83/10/04 WILLIAMS, J. Cincinnati Oas & Electric Co. 2pp. 20641 013 24X Fiche 30-358,83/10/04.8310060497
- 8310110286 Forwards 830930 news release stating that Bechtel Power Corp estimates facility completion in range of 24 to 36 months Final date contingent on orderly & timely resolution of Nov 1982 show cause order Related correspondence CONNER, T B Conner & Wetterhahn CONNER, T B Cincinnati Gac & Electric Co 83/10/05 FRVE, J H , HODPER, F F , LIVINGSTON, M S Atomic Safety and Licensing Based Panel 2pp 20665 336 24X Fiche 50-358, 83/10/05.8310110286
- 8310180035 Staff requirements mamo on Torrey Pines, Int 830928 briefing in Washington, DC re independent review of project mgt CMILK-8 J. Office of the Becretary of the Commission. 83/10/05 DIRCKB-M. J. Office of the Executive Director for Operations 1p 20825 038 24X Fithe 50-358,83/10/05.8310180035
- 9308300771 Board Notification 93-128A forwards Equipment Qualification Branch conclusions to potential problems w/ASCO sclends valves.
 EISENNUT, D. 0 Division of Licensing 83/10/06 PALLADIND, N. J. Commissioners. 31pp 20818 001 24X Fichs 50-000, 83/10/06, 83083007/1
- 8310120252 Forwards response to Phase I of NUREG-0612. "Control of Heavy Londs at Nuclear Power Plants." per BJ Youngblood 830811 request for addl info All cranes & holets purchased to Bargent & Lundy specs HILLIAMB.J Cincinnati Oas & Electric Co 83/10/06 DENTON.H R Defice of Nuclear Reactor Regulation. Director. 4pp 20692 102 24X Fiche 50-3358, 83/10/06, 8310120252
- 8310200209 Forwards "Course of Action" responding to 82i112 "Order to Show Cause & Order lamediately Suspending Const." (CLI-82-22) Section IV B (1)(b) W/o enri HILLIAMB, J. Cincinnati Qas & Electric Co 83/10/06 DIRCKS, W J Office of the Executive Director for Operations ip 20832 324 24% Fiche 50-358, 03/10/06, 6310200209
- --8310200212 Forwards "Course of Action" responding to 821112 "Order to 8now Cause & Order Immediately Suspending Const," (CLI-82-33) Section IV B (1)(b) W/o enc! WILLIAMS, J Cinctinnati Gas & Electric Co 83/10/06. DEYOUNG.R C Director's Office of Inspection and Enforcement ip 20832 325 24X Fiche 50-358,83/10/06.8310200207

- --B310200215 Forwards "Course of Action" responding to B21112 "Order to Show Cause & Order Immediately Suspending Const," (CLI-82-33) Section IV B (1)(b) Wo encl MILLIAMS, J. Cincinnati Gas & Electric Co. 83/10/06 STLLIN, V Regional Operations & Generic Requirements ip 20832-326 24X Fiche 50-358,83/19/06,8310200207
- --8310200222 Forwards "Course of Action" responding to 821112 "Order to Show Cause & Order Immediately Suspending Const."
 (CLI-82-33) Section IV B (1)(b) W/n encl
 HILLIAMS.J Cincinnati Gas & Electric Co 83/10/06 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 1p 20832 32/
 24X Fiche 50-358,83/10/06.8310200207
- --8310200227 Forwards "Course of Action" responding to 821112 "Order to Show Cause & Order Immediately Suspending Const." (CLI-82-33) Section IV B (1)(b) W/o encl WILLIAMS, J Cancinnata Gas & Electric Co 83/10/06 EISENIUM, D G Division of Licensing Ip 20832 328 24X Fiche 50-358,83/10/06,8310200209
- --8310200230 Forwards "Course of Action" responding to 821112 "Order to Show Cause & Order Immediately Suspending Const."
 (CLI-82-33) Section IV B (1)(6) W/o enc!
 HILLIAMS.J Cincinnati Gas & Electric Co 83/10/06
 CUNNINGHAN, O H Office of the Executive Legal Director 1p
 20832 329 24X Fiche 50-358,83/10/06,8310200207
- --8310200234 Forwards "Course of Action" responding to B2112 "Order to Show Cause & Order Immediately Suspending Const."
 (CLI-82-33) Section IV B (1)(b) W/o stated encl Util #sternal ltrs eacl #MLLIAMS.J Cincinnati Gas & Electric Co 83/10/06 LIEBERMAN.J MRC No Dotailed Affiliation Given 21pp 20832 330 24% Fiche 80-338,63/10/06.8310200207
- 8310130234 Informs that util proposed "Course of Action" rept will be provided to interested persons for comment Written comments must reach Region III by 831101 Region III will conduct two open meetings on 831101 Distribution list & details encl KEPPLER, J G Region 3, Office of Director 83/10/07 WILLIAMS, J Cincinnati Gas & Electric Co App 20/20 182 24X Fiche 50-358,03/10/07,8310130234
- --8310130237 "Course of Action," Vols 1 & 2 * Cincinnati Gas & Electric Co 83/10/07 639pp 20720 180 24% Fiche 50-358.83/10/07.8310130234
- 8310130242 Forwards Certificate of Svc of Amend 151 to 830930 application for licenses in form of Rev 9/ to FBAR HILLIAMS, J. Cincinnati Gas & Electric Co. 83/10/07 DENION, H. Office of Nuclear Reactor Regulation. Director 3pp. 20719 14/ 24X Fiche 50-358.83/10/07,8310130242
- 93iO140054 Summary of 930914 meeting w/util in Region III oft reactions being taken to strengthen 9A program & to outline plan of action.

 **REPPLEER.J & Region 3. Office of Director 83/10/07 Region 3. Office 95/10/05/10
- --8310\$40055 Summary of 830913 meeting w/util in Washington.DC re plan of action for GA program
 **MURRAY.JP Office of the Executive Legal Director 83/09/14
 **Office of the Executive Legal Director 2pp 20767 352 24%
 **Fiche 50-358.83/10/07.8310140054
- 831-0240133 Notification of 831013 meeting w/util in Bethesda, MD to discuss proposed course of action to verify quality of facility & complete const as described in 831005 rept KENTNER, L Licensing Brench i 83/10/11 YOUNGBLOOD, B. J Licensing Dranch i 4pp 20891 334. 24X Fiche 50-358, 83/10/11, 8310240133
- 8310210003 Symmary of 831011 meeting w/Dayton Power & Light Cd in Glen Ellyn, IL re actions required before const can be resumed. DAVIS.A B Region 3. Office of Director. 83/10/18 Region 3. Office of Director ip 20855 166. P4X Fiche 50-358.83/10/18, 8310210003
- B310210067 Summary of B31005 meeting w/util at Region III ofc re actions taken to strengthen GA program MEPPLERIJ G Region 3, Office of Director 83/10/18 Region 3, Office of Director ip 20857 269 24X Fiche 50-358,83/10/18, B310210067

- F Security, medical, emergency & fire protection plans
- 8310040336 Forwards Procedure AD NP 16, "Nuclear Production Directive Emergency Procedure Generation Program," per NUREG-0737. Suppl 1 (Generic Ltr 82-33) HILLIAMS: J Cincinnati Gas & Electric Ca 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20617 139 24X Fiche 50-358,63/09/30.8310040336
- --8310040341 Procedure AD NP 16, "Nuclear Production Directive Emergency Procedure Generation Program" HALD, J. J. Gincinnati Gas & Electric Co. 83/09/01 73pp 20617 135 24X Fiche 50-336.03/09/30.8310040336
- 83i0180197 Clarifies NRC position procedures for admitting NRC personnel to facility Access to vital areas should be afforded to listed Region 111 personnel Update will be provided every 6 months AKELSDN.N L. Region 3. Office of Director 83/10/14 WILLIAMS, J Cincinnati Qas & Electric Co 7pp 20809 046 24X Fiche 50-338,83/10/14,8310180197

9 Adjudicatory correspondence

- 8310040245 Petition for reconsideration of ASLS 830915 order danying Miami Valley Power Project motion to reopen record for admission of eight proposed contentions. Add1 info provided since original decision Certificate of Svc encl DEVINE, T Miami Valley Power Project DEVINE, T Government Accountability Project 83/10/03 Atomic Safety and Licensing Board Panel 81pp 20645 271 24X Fiche 50-358,83/10/03,83/10/03,83/10/03,83/10/03,83/10/03,83/10/03,83/10/03
- --8310060282 Affidavit of D Jones for Covt Accountability Project protesting Torrey Pines rept chapter on cases studies Ref to author interviews incomplete & thus inaccurate Analysis of whistleblower missed real problem of lack of freedom JONES D Affiliation Unknown 83/09/26 9pp 20645,331 243 Fiche 50-358,83/10/03.8310060845
- --B310060259 Affidavit of T Devine summarizing B30919 discussion w/ C Heaver re summary of interview in Torrey Pines rept Weaver seriously challenges completeness of interview summary DEVINC.T. Qevernment Accountability Project B3/09/26 3pp 2686 009 248 Fiche 50-338.83/10/03.8310060245
- --B310060263 Affidavit of R Reiter for Govt Accountability Project expressing dissatisfaction of w/summarized interview in Torrey Pines rept REITER, R Affiliation Unknown B3/07/24 2pp 20646 012 24X Fiche 50-358,83/10/03,8310060245
- ---8310060266 Motion for extension to file appeal until 10 days after svc of ABLB decision on Miami Valley Power Project petition for reconsideration Certificate of Svc encl
 DEVINE.T Miami Valley Power Project DEVINE.T, Government Accountability Project 83/10/03 Atomic Safety and Licensing Appeal Panal 4pp 20646-014. 24X Fiche 50-358,83/10/03,8310060245
- 8310110286 Forwards 830930 news release stating that Bethtel Power Corp estimates facility completion in range of 24 to 36 months Final date contingent on orderly & timely resolution of Nov 1982 show cause order Related correspondence CONNER, T. B. Conner & Wetterhahn CONNER, T. B. Cincinnati Gas & Electric Co. 83/10/05 FRYE, J. H., HOOPER, F. F., LIVINGSTON, M. B. Atomic Safety and Licensing Board Panel 2pp. 20665:336—24X Fichs 50-358,83/10/05,8310110286
- 8310110043 Order granting Miami Valley Power Project 831003 motion for extension to file appeal from ASLB 830915 order Time extended until 10 days after svc of ASLB decision on Project patition for reconsideration SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/10/06 Miami Valley Power Project. 3pp 20668 277. 24X Fiche 50-358,83/10/06,8310110043
- 8310110208 Natics of JH Laverty employment w/Conner & Wetterhahn, PC Previous employment w/Commissioner Roberts eliminates any contribution to Zimmer case LAVERTY, JH Conner & Wetterhahn 83/10/06 1p 20669 131. 24X Fiche. 50-358, 83/10/06, 8310110208
- --8310110216 Notice of JH Laverty employment w/Conner & Hetterhahn, PC.
 Laverty will not participate in matters leading to DL
 issuance due to previous employment w/Commissioner Roberts
 Certificate of Svc encl.
 CONNER.T B Conner & Wetterhahn 83/10/06 3pp 20665:132 24X
 Fiche, 50-358, 83/10/06, 8310110208.

- 8310110269 Notification to Commission of Miami Valley Power Project mistepresentation in 831003 motion for reconsideration of ASLB 830915 order No util counsel communicated w/Oovt Accountability Project Certificate of Svc encl CONNER. T B Concinnati Gas & Electric Co CONNER. T B Conner & Hetterham 83/10/06 App 20666 140 24X Fiche 50-358.83/10/06, 8310110269
- 8310110214 Requests progress rept on resolution of offsite emergency planning issues/per steps outlined in 830811 ltr FRYE.J H Atomic Safety and Licensing Board Panel 83/10/07 METTERHAMN.M J Conner & Wetterhahn 1p 20665 060 24X Fiche 30-358,83/10/07.8310110214
- 8310200235 Advises that Ofc of Investigations is conducting ongoing investigation Ofc would present fruits of investigation upon ASLB request in camera es parte HAYES B B Office of Investigation B3/10/12 FRYE.J H Atomic Safety and Licensing Board Panel 1p 20832 323 24X Fichs 50-358,83/10/12,8310200235
- 8310170146 Memorandum in support of Miami Valley Power Project (MVPP) patition for reconsideration of ASLB 830715 order MVPP urges ASLB to address stds for reopening record Issues should be included to ensure complete record Certificate of Svr encl MEBB.D F Mentor. KY 83/10/13 Atomic Safety and Licensing Board Panel 6pp 20820 237 24X Fiche 50-358.83/10/13.8310170146
- 8310210153 Answer opposing Miami Valley Power Project 831003 petition for reconsideration of ASLB 830915 memorandum & order denying Project motion to reopen record to Admit eight late filed contentions on GA Certificate of Svc encl CONNER.T B Cincinnati Gas & Electric Co CONNER.T B Conner & Wetterhahn 83/10/18 Atomic Safety and Licensing Board Panel 21pp 20855 142 24X Fiche 50-358.83/10/18.8310210153
- 8310260205 Order granting NRC 831021 oral request for extension until 831031 to respond to Miami Valley Power Project patition for reconsideration of ABLS 830915 memorandum & order FRYE, J H Atomic 82ety and Licensing Board Panel 83/10/24 Office of the Executive Legal Director ip 20912 236 24X Fiche 50-358,83/10/24,8310260205
- B310260230 Responds to B30927 request for actions re agt structure program. Ltr forwarded to J9 Keppler for consideration PLAINE. H. H. Office of the General Counsel 63/10/24 DEVINE. T Miami Valley Power Project 1p 20912

H General correspondence

- B310120287 Forwards IE Insp Repts 50-358/82-10 & 50-358/83-02 re welder qualifications H/o encis SCHWEIBINI.E Region J. Office of Director B3/10/06 STANFIELD.O Affiliation Uninown 1p 20693 001 24% Fiche 50-358/83/10/06
- B310270370 Informs of citizen concern re const defects & QA breakdowns & urgss initiation of further action assuring total safety of plant
 BROWN.J Y Kentucky, Commonwealth of, 83/10/10, PALLADING, N J Commissioners ip 20924-008 24X Fichs 50-358,83/10/10,8310270370
- 8310250109 Forwards 831012 Resolution R/195-1983, creating oversight committee. POSEY, W W Cincinneti, OH 83/10/14. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 5pp 20898-250. 24X Fiche 50-358,83/10/14,8310250109

K Utility Final Bafaty Analysis Report (FSAR) & amends

- 8310040459 Amend 151 to OL application, consisting of Rev 97 to FBAR, MILLIAMB, J Cincinnati Qas & Electric Co. 83/09/30 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pp 20624; O31 24X Ficha: 50-358, 83/09/30, 8310040459.
- --B310040461 Rev 97 to FSAR

 Grundy Electric Cooperative, Inc. 83/09/30 72pp 20624 034.
 24X Fiche 50-358,83/09/30,8310040459.
- 8310130242 Forwards Certificate of Svc of Amend 151 to 830930 application for licenses in form of Rev 97 to FSAR.
 WILLIAMS, J Cincinneti Oas & Electric Co. 83/10/07 DENTON, H
 Office of Nuclear Reactor Regulation, Director, 3pp 20719: 144
 24x Fiche, 50-338, 83/10/07, 8310130242,

- Q Inspection reports, IE Bulletins & correspondence
- 8310280204 Appeals denial of FDIA request for Ofc of Investigation repts re allegations concerning presence of Bechtel representative at facility prior to Nov 1982 DEVINE. T Government Accountability Project 83/06/16 CHILK, S J Office of the Secretary of the Commission 2pp 20944 192 24% Fithe 50-358,83/06/16,8310280204
- 8310270262 Second response to FOIA request for NRC rept on investigation of charges that Bechtel representatives onsite grace to Bechtel nomination to conduct independent mgt review Documents in App A available in PDR FELTON, J M Division of Rules and Records 83/07/14 ANDERSON, P H Shaw, Pittman, Potts & Trowbridge 2pp 20943 06/2 24X Fiche 50~358,83/07/14,8310270262
- 8310280212 Responds to appeal re denial of FOIA request for Oft of Investigation repts concerning facility Orants appeal in part Forwards document Info partialy withhold (ref FOIA Exemption 7) CHILK: B J Office of the Secretary of the Commission 93/08/24 DEVINE: T Government Accountability Project 2pp 20764 198 24X Fichs 50-358,83/08/24,8310280212
- --8310280220 IE Investigation Rept H-83-001 on 830120-0301 No noncompliance noted Major areas investigated allegations re presence of Bechtol representatives at facility prior to Nov 1982 Affidavit encl Info deleted GILBERT.E C. WARD, W J. HAYES B B Office of Investigation 83/03/11 60pp 20964 205 24X Fiche 50-358,83/08/24,83102802112
- 8310050538 Forwards IE Insp Rept 50-358/83-12 on 830801-070R & notice of violation WARNICK, R F Region 3, Office of Director 83/09/22 WILLIAMS, J Cincinnati Qas & Electric Co 2pp 20431 282 24X Fiche. 50-358,83/09/22,8310050538
- --8310050540 Notice of violation from insp on 830801-0702 MARNICK.R F Region 3. Office of Director 83/09/22 20431 284 24X Fiche 50-358,83/09/22,8310050938
- --8310050546 IE Insp Rept 50-358/83-12 on 830801-0702 Noncompliance noted failure to follow requirements of Procedure 16-QA-03 in processing Corrective Action Request 81-25 & other documentation GMYNN.T P. NIGHTINGALE.E., FORNEY, W.L. Region 3. Office of Director 83/09/22 48pp 20631286 24X Fiche, 50-358.83/09/22, 8310030538
- 8310050518 Forwards IE Insp Rept 50-358/83-17 on 830428-29 & 0914-16 & notice of violation MARNICK,R F Region 3. Office of Director 83/09/23, WILLIAMS,J CincInnati Gas & Electric Go 2pp 20634 1/9 24X Fiche 50-358,83/09/23,8310050518
- --8310050522 Notice of violation from insp on 830428-29 & 0714-16 HARNICK:R F Region 3, Office of Director. 83/09/23 Ip 20634 181 24X Fiche 50-358,83/09/23,8310050818
- --8310050530 lE Insp Rept 50-358/83-17 on 830428-29 & 0914-14 Noncompliance noted failure to submit written repts on reportable deficiencies within 30 days of initial notification per 10CFR50 55(e) 86HMEIBINZIE R , FORNEY, W L. Region 3, Office of Director 83/09/23 App 20624 182 24X Fiche 50-358,83/09/23,8310050510
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York Inc 117pp 20754 022 24X Fiche 50-000,83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of Nuw York, Inc. 116pp. 20777 210 24X Fiche: 50-000, 83/09/26, 83/08300342.
- 8308300345 IE Info Notice 83-A3, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list encl
 JDRDAN, E. L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/07/26 Consolidated Edison Co of New
 York: Inc 118pp 20778:001 24X Fiche: 50-000,83/09/26,8308300345
- 9308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Syc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche, 50~000, 83/09/29, 8308300349

- 8310140135 Ack receipt of 830915 interim response informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/83-07 WARNICK,R F Region 3, Office of Director 83/10/06 WILLIAMS, Cincinnati Gas & Electric Co 2pp 20763 044 24X Fiche 50-358,83/10/06,8310140135
 - 83/10/06 WILLIAMS, J
- --8310140136 Responds to NRC 830628 ltr re violations noted in IE Insp Rept 30-358/83-07 Corrective actions Chapter 10 of GA manual revised to require that HJ Kaiser perform GC on pumps &
 - motors HILLIAMS,T Cincinnati Gas & Electric Co 83/09/15 KEPPLER, J 0 Region 3, Office of Director 6pp 20763 046 24X Fiche 50-358,83/10/06,8310140135
- 6308300378 1E Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/10/07 Consolidated Edison Co of Net York, Inc 76pp 20827 213 24X Fishe 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fathlity at Argentine Critical Facility " Svc list encl JRRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fishe 50-000,83/10/07,8308300752
- 8310200276 Forwards IE Insp Rept 50-358/83-ii on 830725-29,0811,0830-31 & 0901-09 No moncompliance noted LITILE.W 8 Region 3. Office of Director 83/10/07 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 20830 027 24X Fiche 50-358,83/10/07,8310200276
- --8310200280 IE Imap Rept 50-358/83-11 on 830725-29,0811,0830-31 & 316200280 IE Insp Rept 50-338/83-11 on BG0/25-27,0811,0830-31 & O901-02 No noncompliance noted Hajor areas inspected open items & unresolved items, proposed insp plane for cable tray hanger & conduit supports
 KEATING.D E. DANIELSON.D H Region 3, Office of Director 83/10/07 Spp 20830 027 24X Fiche 50-358,83/10/07,8310200276
- B3CB300757 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Oases " Svc list encl UCRDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 1E Info Notice 83-69, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co. of New Yart, Ins. 120pp 20827 129 24% Fiche 50-000,83/10/11,8308300761 Response (Post 830103) York, Inc. 120pp 200
- 8310170451 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-358/82-17.

 WARNICK:R F Region 3, Office of Director 83/10/11. WILLIAMS, J Cincinnati Gas & Electric Co ip 20784 043 24X ftche 50-358,83/10/11.8310170451
- -8310170454 Responds to NRC 830610 ltr re violations noted in IE Insp Rept 50-358/82-17 Corrective actions lugs welded by unqualified welders will be reworked & corrective action statement issued re welding control procedure HILLIAMS. J. Cincinnati Gas & Electric Co. 83/09/83 KEPPLER. J. Q. Region 3. Office of Director. 8pp. 20784-044 24X Fiche 50-358,83/10/11.8310170451
- B310240161 Summarizes proposed welding reinsp program of Class I structural steel as discussed during 830811 site merting Melds found w/major deficiencies will be reworked Program details enci HILLIAMS.J Cincinnati Gas & Electric Co 83/10/11 KEPPLER, Region 3, Office of Director 5pp 20081 308 24X Fichs 50-358,83/10/11,8310240161 KEPPLER, J Q
- 8310180197 Clarifies NRC position procedures for admitting NRC personnel to facility Access to vital areas should be afforded to listed Region | 11 personnel Update will be provided every 6 months AXELSON; W. E. Region 3, Office of Director 83/10/14 WILLIAMS, J. Cincinnati 0ss & Flectric Co. 7pp. 20009-046 24X Ficher 50-358, 83/10/14, 8310180197
- 0310200157 Submits portions of draft IE info notice & B30915 ltr re NUREQ-0969 "Rept of NRC Evaluation Team on Quality of Const at Zimmer Nuclear Power Station." For review & comment Response requested by 831104 KEPPLER. J O Region 3. Office of Director B3/10/17 WILLIAMS, J Cinctinnate Gas & Electric Co 19pp ROB34 107 24X Fiche 50-358, B3/10/17, 8310200157

- 8310210105 Ack receipt of 830609 itr & revised 830923 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/92-1050-358/82-10 KEPPLER.J G Region 3. Office of Director 8: Cincinnati Gas & Electric Co 2pg 20858 207 Fiche 50-358,83/10/17.8310210105
- --8310210110 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-358/82-10 Corrective actions personnel changes made & procedures revised for update of welder qualification cards Programs for welder qualification will be audited WILLIAMS, J Cincinnati Gas & Electric Co 83/09/23 KEPPLER, J 0. Region 3. Office of Director 14pp 20858 208 24X fiche 50-358,83/10/17,8310210105
- --8310210113 Responds to NRC 830325 itr re violations noted in IE Insp. Rept 50-358/82-10 Corrective actions welder qualification review program being developed Quality records mgt reviewing all welder qualification related documents WILLIAMS, J. Cincinnati Qua & Electric Cp. 83/06/09 KEPPLER, J. Q. Region 3, Office of Director 10pp 20858 222 24X Fiche 50-358, 83/10/17, 8310210105.
- 8310260078 Responds to IE Bulletin 83-05 re ASME Nuclear Code pumps & spare parts mfg by Hayward Tyler Pump Co After review of purchasing documentabion & investigation of suppliers & subvendors, util determined IE bulletin not applicable MTLLIAMS. J Cincinnati Cas & Electric Co 83/10/18 KEPPLER, J 0 Region 3. Office of Director. 2pp 20712 224 24X Fiche 50-358.83/10/18,8310260078
- 8310250576 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/81-13 Meeting scheduled 831031 to discuss closeout of Item 5 of insp rept re gap dimensions of socket welds KEPPLER, J Q Region 3, Office of Director 83/10/21 WILLIAMS, J Cincinnati Qas & Electric Co Ip 21182 133 24X Fiche 50-358,83/10/21,8310250576
- --8310250386 Responds to NRC 830321 ltr re violations noted in IE Insp Rept 50-358/81-13 Provides add1 info pending changes to ABME Code: Paragraph NX 4427 WILLIAMS, J Cincinnats Gas & Electric Co 83/10/12 KEPPLER, J G Region 3, Office of Director 2pp 20900 357 24X WILLIAMS, J. Cincinnati Gas & Electric Co. 83/ Region 3, Office of Director 2pp. 20900-357 Fiche 50-358.83/10/21,8310250576
- R Periodic operating reports & related correspondence
- 8310170548 Forwards Natl Board Interim Rept 15 dtd 831005 covering audit team activities for Bept 1983
 YOST,R A Dhio, State of 83/10/07 WILLIAMS,J Cincinnati Qas & Electric Co 4pp 20780 351 24X Fiche 50-358,83/10/07,8310170548
- 8310210065 Forwards monthly status rept for Sept 1983 DIRCKS,W J Office of the Executive Director for Operations 83710712 FALLADING, N Commissioners 1p 20884:001 24 Fiche 50-358,83710713,8310210065
- --8310210069 Monthly status rept for Sept 1983 * Region 3. Office of Director 83/09/30, 26pp. 20884.002 24x Fiche 50-358/83/10/13/8310210065
- 8310180267 Forwards util 831005 written plan re course of action to be taken for audit recommendations in Torrey Pines Technology "Independent Review of Zimmer Project Mgt Final Rept " W/o enci KEPPLER, J Q Region 3, Office of Director 83/10/14 NEYL Torrey Pines Technology 4pp 20802 289 24X Fiche 50-358 83/10/14,8310180267 NEYLAN, A J
- S Reportable occurrences. LERs & related correspondence
- 8310120383 Interim deficiency rept. Item E-30 re electrical cable termination, Initially reported on 821027 Approval of procedure rev scheduled for 831015. Failure to incorporate criteria in procedures to be evaluated Next rept by 831231 WILLIAMB, J. Cincinnati Gas & Electric Co. 83/09/30 KEPPLER, J. 9 Region 3, Office of Director 2pp. 20699, 195. 24X Fiche 50-350, 83/09/30, 8310120383
- 8310120442 Interim deficiency rept, Item M-96 re indeterminate qualification of supplier per ASME Section III Initially reported on 820902 Corrective Action Request 471 initiated by HJ Kaiser Correquiring audit of facilities & program. WILLIAMS. J Cincinnati Gas & Electric Co. 83/09/30 KEPPL Region 3. Office of Director. 2pp. 20698: 258 24% Fiche. 50-358.83/09/30.8310120442 KEPPLER, J Q

- G310120256 PNO-III-B3-090 on B30930, litensee notified resident inspector of allegation of improper training & certification of individuals conducting reviews of safety-related records for HJ Kaiser Co.principal site contractor SCHEIBINZ.E. FORNEY, W. Region 3, Office of Director 83/10/03 1p 20691 330 24X Fiche 50-356, 83/10/03.6310120256
- 8310170348 Interim deficiency rept, Item 6-11 re failure to implement QA program corrective action reporting sys Initially reported on B30907. OA Dept reorganized & corrective action requests/trending group established Followup rept by 831130 WILLIAMS. J Cincinnati Oas & Electric Co 83/10/07 KEPPLER, J G Region 3. Office of Director. 2pp 20786 162 24X Fiche 50-358,83/10/07.8310170348
- 8310170649 Interim deficiency rept, Item G-12 re procedures for insp of rework/repair activities Initially reported on 830909 GA personnel developing program to require verification of repair/rework for closed 7000 series nonconformance repts WILLIAMS, J Cincinnati Gas & Electric Co 83/10/07 KEPPLER, J C. Region 3, Office of Director 2pp. 20780 179 24X Fiche 50-358,83/10/07,8310170649
- 8310170404 Interim deficiency rept. Item E-35 re electrical equipment foundation welding. Initially reported on 830104 Const insp plans developed for surveillance of paint removal & insp of electrical panel mounting welds Next rept by 831201.

 MILLIAMS, J Cincinneti Gas & Electric Co 83/10/10. KEPPLER, J G Region G. Office of Director 2pp 20779 154 24X Fiche 50-358,83/10/10,8310170404
- 83i0170448 Interim deficiency rept, Item E-20 re inadequate cable tray hanger insp Initially reported on 820503 Formal submittal of proposed reinep grogram, including request for relaxation of NRC 621i12 show cause order, will be made by 83i108 WILLIAMS. J Cincinnati Oas & Electric Co. 83/10/10 KEPPLER, J 6 Region 3. Office of Director 200 200 20079 228 24% Fiche 50-358,83/10/10,8310170048
- 8310170485 Interim deficiency rept, Item M-45 re intermediate welder qualifications Initially reported on 830430 Computerized welding info sys scheduled for completion by 840215 Followup rept will be submitted by 840321 WILLIAMS. J Cincinnati Cas & Electric Co 83/10/10 XEPPLER, J O Region 3. Office of Director 2pp 20784-091 24X Fiche: 50-358, 83/10/10, 8310170485
- 8310180294 Interim deficiency rept. Item E-53 re discrepancies in 4 16-kV switchgear wiring diagram Initially reported on 830922 Evaluation continuing Followup rept will be submitted by 840120 MILLIAMS. J. Cincinnati Gas & Electric Co. 83/10/10 KEPPLER, J. G. Region 3, Office of Director 2pp 20806-352 24X Fiche: 50-358, 83/10/10, 8310180296
- B310200078 Interim deficiency rept. Item M-97 re jet pump instrumentation bracket welds not installed to design requirements initially reported on B30722 Pf 30 brackets, 24 not completely welder Next rept expected by B31121.
 WILLIAMS. J Cincinnati Qas & Electric Co B3/10/12 KEPPLER, J. Q Ragion 3. Office of Director. Zpp. 20835 361 24X Fiche. 50-358, 83/10/12, 8310200078
- 8310200083 Interim deficiency rept. Item M-56 re inadequate installation of gamma plugs in accessible & embedded piping Initially reported on 820804 HJ Raiser Co completing investigation Final resolution expected by 840130 HILLIAMS: 8 J Cincinnati Gas & Electric Co 83/10/14 KEPPLER, J G Region 3, Office of Director. 2pp 20837.004. 24% Fiche 50-358.83/10/14.8310200083
- 3310200152 PNO-III-83-097 on B31013.13 maint & janitorial workers at site resigned due to internal investigation re marijuana & alcohol use during working hours. All safety-related const suspended.
 HILL.M., FORNEY,W Region 3, Office of Director, 83/10/14, 1p 20834, 321. 24% Fiche: 50-359, 83/10/14, 8310200152
- 8310250487 Interim deficiency rept. Item E-54 re misapplication of control circuit fuses. Initially reported on 830923 Incorrect design documentation will be revised & walkdown program to verify fuses to be developed, Final rept by 840531 WILLIAMS. J Cincinnati Gas & Electric Co 83/10/17. KEPPLER, J G Region 3. Defice of Director. 29p. 20897-049 24X Fiche: 50-358, 83/10/17. 8310250487
- 8310250364 Interim deficiency rept. Item E-46 re lack of Type 818 switchboard wire certification initially reported on 830713 Bargent & Lundy issued Design Document Change 8LE-577 to require Type 818 wire for future use Next rept by 840131 MILLIAMB. J Cincinnati Qas & Electric Co. 83/10/18 KEPPLER. J. C. Region 3. Office of Director. 3pp. 20898-087. 24X Fiche, 50-358, 83/10/18, 8310250366

- T Hearing transcripts on non-antitrust matters
- B310050450 Transcript of B3092B briefing by Torrey Pines, Inc. in Washington, DC re independent review of util project mgt Pp 1-66 Supporting documentation encl.

 * Commissioners B3/09/28 133pp 20640 001 24X Fiche 50-338, 83/09/28, 8310050450
- DOCKET 50-361 BAN DNOFRE NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8310030110 Forwards revs to physical security plan Revs withheld (ref 10CFR73 21).
 MEDFORD.H O Southern California Edison Co 83/09/29 Division of Licensing 2pp 20590 061 24X Fiche 50-206.83/09/29.
 8310030110
- 8310130012 Forwards two errata pages to Rev II to Mar 1981 physical security plan Safeguards contingency plan submitted on 830923 will replace Chapter 8 of physical security plan by 831215 Pages withheld (ref 10CFR73 21)
 MEDFORD.M O Southern California Edison Co 83/10/07 Division of Licensing ip 20725 208 24X Fiche 30-204,83/10/07.8310130012
- 8310130424 Requests fee due per 830211 revised physical security plan be remitted within 15 days of receipt of ltr MILLER, W O License Fee Management Branch 83/10/11 DIETCH, R Southern California Edison Co 2pp 20769 242 24X Fichs 50-206,83/10/11,8310130424
- H General correspondence
- 831019000B Informs of organizational & personnel changes resulting from Jan 1980 centralization of nuclear engineering & operations dept Roys to Tech Specs being prepared for future submittal FOGARTY.D J. Southern California Edison Co. 83/10/17 DENTON.M Office of Nuclear Reactor Regulation, Director 2pp. 20823 304 24% Fiche 50-206.83/10/17.8310190008
- P Operating license stage documents & correspondence
- B310040009 Informs that evaluation re possible mods to prevent/mitigate inadvertent recirculation actuation signal still in progress Completion of study expected by 840228 MEDFURD.M O Southern California Edison Co 83/09/27 KN10HTDN.O Licensing Branch 3 ip 20408 112 24X Fiche 50-341.83/09/27.8310040009
- 8310120278 Forwards response to J Mertens 830805 request for add1 info re open items involving damaged snubbers & water hammer Assessment of areas complete RAY.H B Southern California Edison Co 83/09/29 MARTIN.J B Region 5, Office of Director 3pp 20693 078 24X Fiche 50-204.03/09/29.8310120278
- 8310110128 Forwards application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12 BASKIN, K P Bouthern California Edison Co 83/10/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20666 340 24X Fiche 50-361,83/10/03.8310110128
- --B310110133 Application for amend to Licenses NPF-10 & NPF-15, changing Tech Bpecs to revise administration of work hours for min shift crew personnel per Generic Ltr B2-12 BABKIN.K P Southern California Edison Co HOLCOMBE, J C San Diego Cas & Electric Co. FOHLMAN, D L. Anaheim, CA B3/10/03 Bpp 20666 342. 24X Fiche 50-361,83/10/03,8310110128
- --B3f0110136 Proposed Tech Specs re administration of overtime for min shift crew # Southern California Edison Co. 83/10/03 53pp 20666 350 24% Fiche 50-361,83/10/03,8310110128
- 8310180173 Forwards notice of consideration of issuance of amend to Licensea NFF-10 & NFF-15, proposed NSHC determination & apportunity for hearing & initial NSHC determination & noticing action re DNBR calculations
 ROOD.H Licensing Branch 3. 83/10/04 BASKIN, K E Southern California Edison Co. HOLCOMBE, J C San Diego & & Electric Co Spp 20827 023 24X Fiche 50-361,83/10/04,8310180173
- ---B310180177 Notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15 & proposed NBHC determination & opportunity for hearing re DNBR calculations KNIGHTON, of the Licensing Branch 3 83/07/26 8pp 20827 026 24X Fiche 50-361,83/10/04.8310180173

- 8310120397 Forwards affidavit attesting to direct distribution of Amend Applications 22 & 8 MEDFORD:M D Southern California Edison Co 83/10/07 MNTOHTON:0 W Licensing Branch 3 4pp 20699 053 24X Fishe 50-361,83/10/07:8310120397
- B310200177 Forwards response to NRC 83062/ request for add1 info to satisfy requirements of NUREG-0737. Item 11 D 1, "Relief & Safety Valve Testing"

 MEDFORD.M O Southern California Edison Co B3/10/14

 KNIGHTON.O W Licensing Branch 3 17pp 20835 298 24X

 Ficha 50-361, 83/10/14/8310200177
- 8310250124 Forwards Rev 1 to Calculation SFR-CC-01 i. "Reevaluation of Spent Fuel Storage Racks." in response to NRC 830722 request Racks in fully loaded condition fail to meet seismic critoria MEDFQRD.M D. Southern California Edison Co. 83/10/17 CRUTCHFIELD.D. Operating Reactors Branch 5. 2pp. 20898 185 24% Fishe 50-206,83/10/17.8310230124

G Inspection reports, IE Bulletins & correspondence

- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification (ests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fithe 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New Yorl, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300349 IE Info Notice 63-63, "Potential Failures of Westinghouse Type SA-I Differential Relays " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310120298 Submits comments on 830826 SALP analyses Operator errors primarily result of inadequate procedures or training Actions taken to improve training & operating experience feedback in maint program FOGARTY, D J Southern California Edison Co 83/09/28 MARTIN, J B Region 5. Office of Director 2pp 20693 170 24X Fiche 50-704,83/09/28,8310120298
- B30B300347 IE Info Notice 83-64, "Lead Ghielding Attached to Bafety-Related Sys W/o 10CFR90 57 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/27 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000.83/09/27,8308300349
- 8310200208 Forwards IE Insp. Repts 80-204/83-17, 50-341/83-27 & 50-342/83-27 on 830804-0914 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/04 MCCARTHY, C & Southern California Edison Co 2pp 20834 128 24% Fiche 50-204,83/10/04,8310200208
- --8310200214 IE Insp Repts 50-206/83-19.50-361/83-29 % 50-362/83-27 on 830804-0916 No noncompliance noted Major areas inspected operational safety verification, witnessing precriticality, initial criticality % low power physics testing CHAFFE.A E. D'ANGELO.A. STEWART.J.P Region 5. Office of Director 83/09/30 ISPP 20834 130 24X Fiche 50-206,83/10/04,8310200208
- B30B300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 9308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility," Svc list encl JORDAN: EL Division of Emergency Praparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Syc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New Yorl Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759

- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fichs 50-000.83/10/11.8308300761
- 8310200220 Forwards IE Mgt Neeting Repts 30-206/83-22,50-361/83-36 t 50-362/83-34 on 830908 re SALP rept for Jul 1982 - May 1983, MARTIN.J B Region 5, Office of Director 83/10/14 MCCARTHY,C B Southern California Edison Ca 2pp 20829 327 24X Fiche 50-206,83/10/14.8310200220
- --9310200224 IE Mgt Heeting Repts 50-206/83-22,50-361/83-36 & 50-362/83-34 on 830908 Major areas discussed SALP rept for Jul 1982 May 1983 KIRGCH, D F Region 5, Dffice of Director 83/10/13 2pp. 20829 329 24% Fiche 50-206.83/10/14.8310200220
- --8310200228 SALP rept for Jul 1982 May 1983 * Region 5. Office of Director 83/07/15 42pp 20829 331 24X Fiche 50-206.83/10/14.8310200220
- --B310200232 Summarizes major investigative activities involving facilities for SALP board review covering Jul 1982 May 1983 SHACKLETON, D C Dffice of Investigation B3/06/06 BISHOP, T W Region 5, Office of Director. 2pp 20830 011 24X Fiche 50-206, 83/10/14, 8310200220
- --8306170104 Forwards observations from evaluation of LERs for 820701-830530, to assist in SALP review Licenses submittals above average in terms of reporting completeness & factual accuracy
 SEVFRIT.K V Reactor Operations Analysis Branch 83/04/10
 SIERNBERGO, D Division of Resident.Reactor Project & Engineering Programs App 20830 015 24X Fiche 50-206.83/10/14.8310200220
- R Periodic operating reports & related correspondence
- 83:10030102 Monthly operating rept for Mar 1982 W/undated ltr HANAFORD, T. RAY, H.B. Southern California Edison Co. 82/04/01 Dffice of Resource Management, Director 7pg 20590 056 24X Fiche 50-361,82/04/01.8310030102
- 8310190092 Monthly operating repts for Aug 1983 W/830915 1tr RAY, M B , MAYWEATHER, L Southern California Edison Co 83/09/15 Dlyision of Data Automation & Management Information 13pp. 20822 222 244 Fiche 50-361:83/09/15
- S Reportable occurrences, LERs & related correspondence
- 8310280071 FOIA request for AEQU rept. "Loss of Bhutdown Cooling & Subsequent Boron Dilution at San Onofre 2." dtd 830425 & info re fuel rod degradation problem described in IE Info Notice 82-27
 HIATT.8 L Ohio Citizens for Responsible Energy 83/06/29
 FELTON.J M Division of Rules and Records 1p 20962 135 24X
 Fiche 50-361.83/06/29.8310280071.
- 8310280077 Responds to FOIA request for AEOD rept, "Loss of Shutdown Cooling & Subsequent Boron Dilution at San Dnofre 2," dtd B30425 & documents re fuel rnd degradation problem described in IE Info Notice 82-27 Forwards App A documents FELTON.J M Division of Rules and Records B3/07/28 HIATT, S L, Ohio Citizens for Responsible Energy 2pp 20962 156 24X Fichs 50-000,83/07/28 8310280079
- --B305030115 Forwards "Loss of Bhutdown Cooling & Bubsequent Boron Dilution," engineering evaluation rept CINTULA,T.C. Reactor Operations Analysis Branch B3/04/25. SEYFRIT,K V Reactor Operations Analysis Branch 1p. 20762 239. 24% Ficha 50-000,83/07/28.8310280079
- --8305030120 "Loss of Shutdown Cooling & Subsequent Boron Dilution:"
 engineering evaluation summary
 # Director's Office ACOD/EGIO 83/04/25. 13pp 20962 240
 24X Fiche: 50-000,83/07/28,8310280079
- --8305160184 Forwards draft IE info notice on possible safety concern to all PWRs relence engineering evaluation rept on 830314 & 24 loss of shutdown cooling & subsequent boron dilution HELTENES, C. J. Docketing & Services Branch 83/05/06 JORDANIE, L. Division of Emergency Preparedness & Engineering Response (Post 830103) ip 20942 238 24X Fiche 50-000.83/07/28/8310280079

- 8310070304 LER 83-116/03L-0 on 830823,0702,04 & 08.calculations indicated DNBR margin not within limits Acceptable margin verified within 15 minutes by restoring core operating limit supervisory sys to svc W/830923 ltr RAY.H B Southern California Edison Co 83/09/23 MARTIN, J B Region 5, Dffice of Director 3pp 20651.086 24X Ficha 50-361.63/09/23.8310070304
- 8310120152 LER 83-117/01T-0 on 830905, pressurizer level instrument 2LI-0103A on essential plant parameter monitoring sys panel 2L-411 varied from correct reading by approx 157 Level correction applied W/830919 ltr RAY.H 8 Bouthern California Edison Co B3/09/23 MARTIN, J B Region 5. Office of Director 5pp 20696 011 24X Fichs 50-361,83/09/23,8310120152
- 8310120116 LER 83-113/03L-0 on B30825, while in Mode i, shiftly surveillance on control element assembly calculator 2 revealed that three auto restarts occurred within 12 b Caused by poorly seated disc interface card 4/230926 ltr RAY, H B Southern California Edison Co B3/09/26 MARTIN, J B Region 5. Office of Director 3pp 20696 147 24X Fiche 50-361, 83/09/26, 8310120116
- 8310120130 LER 83-114/03L-0 on 830825, while in Mode 1, containment isolation valve 2HV-0512 gave dual position indication Cause unknown Investigation suspended pending containment antry during next outage H/830926 ltr RAY, H B Southern California Edison Co 83/09/26 MARTIN, J B Ragion 5, Office of Director 3pp 20698 250 24X Fiche 50-361,83/09/26,8310120130
- 8310120146 LER 83-119/03L-0 on 830828, Group 6 control element assemblies (CEA) inserted to control azial shape index Reactor coolant cold leg temp observed below limits Caused by effects of Xanon build-in & CEA insertion W/830927 ltr RAY, H B Southern California Edison Co 83/09/27 MARTIN, J R Region 5, Office of Director 3pp 20676 030 24x Fiche 50-361.83/09/27, 8310120146
- 8310120164 LER 83-115/03L-0 on 830829, toxic gas isolation sys train A ammonia analyzer declared inoperable Failure caused by change in amplifier gain Amplifier board & analyzer recalibr. W/830927 Itr
 RAY. H B Southern California Edison Co 83/09/27. MARTIN, J B Region 5. Office of Director 30p 20695 358 24X
 Fiche 50-361,83/09/27.8310120164
- 8310120070 LER 83-120/03L-0 on 830829 & 31, flow control valve 2FV-031B for iddine removal sys failed to open & declared inoperable Caused by cracked 0-ring allowing high pressure oil to leak to low pressure side, M/830728 ltr
 RAY, H 8 Southern California Edison Co 83/09/28 MARTIN, J. E Region 5, Dffice of Director 3pp 20596 159 24X
 Fiche 50-361,83/09/28,8310120070
- 8310120073 LER 83-075/03L-0 on 830828, regulating control element assembly group & exceeded time allowed for long-term steady-state insertion limit Caused by use of assemblies to control axial shape index oscillations 47830928 ltr RAY, H B. Southern California Edison Co 83709728 MARTIN, J B Region 5. 0ffice of Director 3pp 20696 191 24X Fichs 50-361.83709728,8310120073
- 1310120342 Forwards updated LERs 83-105/03X-1 & 83-076/03X-1 RAY,H B Bouthern California Edison Co B3/09/28 MARTIN, J B Region 5. Office of Director 2pp 20700 253 24X Fichs 80-361,83/09/28.8310120342
- --8310120347 Updated LER 83-105/03X-1 on 830801.pilot flames of trains A & 8 toxic gas isolation sys (TQIS) butane/propans monitors found extinguished Cause of Plameout unknown TQIB failure caused by low alarm setpoint for flame detaction RAY.H B. Southern California Edison Co 83/09/28 Region 5. Office of Director ip 20700.255 24X Fiche 50-361,83/09/28. 8310120342
- --8310120351 Updated LER 83-074/03X-1 on 830703, pilot flames of trains A k B of toxic gas isolation sys butane/propane monitors found extinguished Cause of pilot flameout unknown Failure of sys caused by low alarm setpoint. Pilot flames restored RAY, H B Southern California Edison Co 83/09/28, Region 5, Office of Director 1p 20700 256 24X Fiche, 50-361, 83/09/28, 8310120342
- 9310070301 Potential Part 21 rept re underrange characteristic of Model N-E110M transmitter. Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN,M J. Foxboro Corp. 83/09/30 Director's Office, Office of Inspection and Enforcement. 11pp 20451 044 24X Fiche 50-000,83/09/30,8310070301

- 8310140284 PNO-V-83-045 on 831003, two reactor trip breakers failed 30 day surveillance test Cause of failure under investigation Breakers placed in open position & replaced w/ spares ECKHARDT. J. Region 5, Office of Director 83/10/04 ip 20757 236 24X Fiche 50-361,83/10/04,8310140284
- 8310270454 RO re 1983 land use census, enumerating changes in land use within 5-mile radius of site ref point which have resulted in calculated dose commitments greater than values currently calculated, per Tech Spec 4 11 2 3
 BASKIN.K P Bouthern California Edison Co 83/10/04 MARTIN, J B Region 5, Office of Director 2pp 20923 004 24X
 Fiche 50-361,83/10/04.8310270454
- 8310180477 Requests NRR assume lead responsibility in assessing generic implications of reactor breaker undervoltage trip device failures on 831002 & 03 Previous failures occurred in Mar & Jul 1982 & Mar 1983
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/10/07 EISENHUT, D G Division of Licensing Per 20803 133 24X Fichs 50-361,83/10/07,8310180477
- --8310180486 RO 83-125 on 831002 during surveillance testing of reactor trip breakers (RTB).RTB 4 operated out of spec & removed from svc on 831003.RTB 5 removed from svc after failing to open on undervoltage trip Investigation in progress RAY.H B Southern California Edison Co 83/10/04 MARTIN,J B Region 5, Office of Director 3pp 20803 155 24X Fiche 50-361.83/10/07,8310180477
- 8310250145 LER 83-122/03L-0 on 830714, core protection calculator channel D observed to have more than three auto restarts in previous 12 h period Caused by failure of power supply Power supply replaced W/831014 ltr
 HAYNES, J D Bouthern California Edison Co 83/10/14 MARTIN, J B Region 5, Office of Director 3pp 20896 326 24X Fiche 50-361, 83/10/14, 8310250145
- 8310270463 LER 83-124/03L-0 on 830917 & 23, control element assembly calculator declared inoperable due to spurious position from control element assembly 20 Caused by defective board & connector Equipment replaced W/831017 ltr
 HAYNES.J O Southern California Edison Co 83/10/17 MARTIN.J B
 Region 5. Office of Director 3pp 20923 123 24X
 Fiche 50-361.83/10/17.8310270463
- 8310270434 LER 83-125/01T-0 on 831002, during reactor trip breaker testing, breakers 4, 6 & 7 demonstrated anomalous behavior when undervoltage devices tested Cause undetermined Breakers replaced W/831018 ltr MAYNES, J Q. Southern California Edison Co 83/10/18 MARTIN, J B Region 5, Dffice of Director 6pp 20723 051 24X Fiche 50-361, 83/10/18, 8310270434
- 8310270498 LER 83-123/03L-0 on 830913, w/Unit 2 in Mode 1 & Unit 3 in Mode 3. Insp of electrical penetrations revealed two holles in penetration seals in auxiliary bldg control area Caused by procedural deficiencies during const W/831018 ltr HAYNES. J 0 , RAY, H B Southern California Edison Co 83/10/18 MARTIN, J B Region 5. Office of Director 3pp 20922 002 24% Ficher 50-361, 83/10/18, 8310270498
- B310310326 RD fire doors listed on encl list found imperable during Sapt routine surveillances Compensatory fire watches established Latching mechanism & closing mechanism failures caused by hardware degradation HAYNES, J © Bouthern California Edison Co 83/10/18 MARTIN. J B Region 5. Office of Director App 20961 142 24X Ficher 50-361,83/10/18.8310310326
- 8310310284 PNS-V-83-011 on 831024, Ban Francisto Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be untrue or exaggerated SCHAEFER, D. H., NORDERHAUG, L. R. Region 5, Office of Director 83/10/24, Ip. 20761 282 24X Fiche 50-206, 83/10/24, 8310310284

V Operator Examinations

8310030107 Requests, by 831028, schedule for requalification troining & exams for 1784 Schedule needed for periodic audits of licensed operator requalification programs BISHOP, T H Division of Resident, Reactor Project & Engineering Programs B3707/26 F00ARTY, D J Southern California Edison Co 2pp 20590-053 24X Fishe 50-206,83/09/26,8310030107

- DOCKET 50-362 BAN ONOFRE NUCLEAR STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8310040639 Forwards Amend 8 to License NPf-15 & notice of issuance & availability Amend authorizes operation at power levels up to 1904 of full rated power & revises Tech Spec to reflect changes in fire protection equipment
 EISENRUI.D 0 Division of Licensing 83/09/6 BASKIN, K E
 Bouthern California Edison Co HOLCOMNE, J C San Diego Gas & Electric Co 6pp 20627 324 24% Fiche 50-362.83/09/16.8310040639
- --8310040642 Amend 8 to License NPF-15, authorizing operation at power levels up to 100% of full rated power, revising Tech Spec to reflect changes in fire protection equipment & reflecting installation of copling sys for auxiliary feedwater pump EISENNUT, D 0 Division of Licensing 83/09/16 14pp 20627 329 24x Fiche 50-362,83/09/16,8310040639
- ~-8310040443 Notice of issuance & availability of Amend 8 to License NFF-15 MNICHTON, G W Licensing Branch 3 83/09/16 4pp 20627 343 24X Fiche 50-362, 83/09/16, 8310040639
- R310030110 Forwards revs to physical security plan Revs withheld tref 10CFR73 21) MEDFORD.N B Southern California Edison Co 83/07/27 Division of ticensing 2pp 20590 051 24X Fithe 50-206.83/09/29, 8310030110
- 8310130012 Forwards two errata pages to Rev 11 to Mai 1981 physical security plan Safaguards contingency plan submitted on 830923 will replace Chapter 8 of physical security plan by 831215 Pages withheld (ref 10CFR73 21) MEDFORD, M O Southern California Edison Co 83/10/07 Division of Licensing ip 20725 208 24% Fiche 50-206.83/10/07.8310130012
- 8310130424 Requests fee due per 830211 revised physical security plan be remitted within 15 days of receipt of ltr MILLER.W D License Fee Management Branch 83/10/11 DIETCH.R Southern Callfornia Edison Co. 2pp 20769 242 24X Fiche 50-206.83/10/11.8310130424
- H Geberal correspondence
- 831017000B Informs of organizational & personnel changes resulting from Jan 1980 centralization of nuclear engineering & operations dept Revs to Tech Specs being prepared for future submittal FOGARTY, D J Bouthern California Edison Go 83/10/17 DENTON, H I Gffice of Nuclear Reactor Regulation, Director 2pp 20823 304 24x Fiche 80-206, 83/10/17, 8310170008
- P Operating license stage documents & correspondence
- B310040639 Forwards Amend B to License NPF-15 & notice of issuance & availability Amend authorizes operation at power levels up to 100% of full rated power & revises lech Spec to reflect changes in fire protection equipment E162NHUT, D @ Bivision of Licensing 83/09/16 BASKIN, K F Bouthern California Edison Co. HOLCOMBE. J C Ban Diego Gas & Electric Co. 6pp. 20627-324 24X Fiche 50-362. B3/09/16, B310040639
- --8316040642 Amend 8 to License NPF-15, authorizing operation at power levels up to 100% of full rated power, revising Tech Spec to reflect changes in fire protection equipment & reflecting installation of cooling sys for auxiliary feedwater pump £18EMMUT, D 9 Division of Licensing 83/09/16 14pp 20627 325 24X Fiche 50-362,83/09/16,8310040639
- --8310040643 Notice of issuance & availability of Amend 8 to License NPF-15 KNIOHTON, G. W. Licensing Branch 3 83/09/16 4pp 20627 343 24X Fiche, 50-362, 83/09/16, 8310040639
- B310040007 Informs that evaluation re possible mods to prevent/mitigate inadvertent recirculation actuation signal still in progress Completion of study expected by 840228 MEDFORD, H D. Bouthern California Edison Co 83/09/27 KNIGHTON, O W. Licensing Branch 3 ip 20608 112 24X F1che 50-361,63/09/27,8310040007
- B31006050B Approves B30627 request for delay of loss-of-offsite-power test until after 80% testing but prior to 100% testing in order to include test of uninterruptible power supply sys KNIQHTON, Q H. Licensing Branch 3 83/09/28, BASKIN, K Bouthern C41ifornia Edison Cq HOLCOMBE, J C Ban Diego Qes & Electric Ca 3pp 20663, 253. 24% Fiche 50-362, 83/09/28, 8310060508

- 8308360352 Board Notification 83-144 provides evaluation & recommendations re need for PDRVs on C-E plants Info will be presented to ACRs in Oct 1983 NOVAK, T M Assistant Director for Licensing 83/09/29 Atomic Safety and Licensing Appeal Panel 4pp 20601 230 24X Fiche 50-000,83/09/29.8308300352
- --8310030407 Informs that "Staff Evaluation of Need for Rapid Depressurization Capability for C-E Plants" & Commission 830916 transcript & slides from 8an Onefre briefing should be transmitted to boards & parties for C-E plants EISENHUT.D O Division of Licensing 83/09/27 NOVAK,T M Assistant Director for Licensing 1p 20601334 24X Fiche 50-000.83/09/27.8308300352
- 8310120278 Forwards response to J Mertens 830805 request for additinfore open items involving damaged snubbers & water hammer.

 Assessment of areas complete
 RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B
 Region 5, Office of Director 3pp 20493 078 24X
 Fiche 50-206,83/09/29,8310120278
- 8310110128 Forwards application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12
 BASKIN.K P Southern California Edison Co 83/10/03 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 20666 340
 24X Fiche. 50-361,83/10/03,8310110128
- --8310110133 Application for amend to Licenses NPF-10 & NPF-15, changing Tech Specs to revise administration of work hours for min shift crew personnel per Generic Ltr 82-12
 BASKIN,K P Bouthern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co POPLMAN,D L Anaheim, CA 83/10/03
 Bpp 20866 342 24% Fiche 50-361,83/10/03,8310110128
- --83i0110136 Proposed Tech Specs re administration of overtime for min shift crew * Bouthern California Edison Co 83/10/03 53pp 20666 350 24X Fiche 50-361,83/10/03,83i0110129
- 8310180173 Forwards notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15.proposed NSHC determination & opportunity for hearing & initial NSHC determination & noticing action re DNBR calculations
 ROOD.H Licensing Branch 3 83/10/04 BASKIN.K E Southern
 California Edison Co MOLCOMBE, J C S an Diego Qas & Electric Co
 3pp 20827 023 24X Fichs 50-361.83/10/04.8310180173
- --8310180177 Notice of consideration of issuance of amend to Licenses NPF-10 & NPF-15 & proposed NBMC determination & opportunity for hearing re DNDR calculations KNIOMTON.9 W Licensing Branch 3 83/09/26 8pp 20827.026 24X Fiche 50-361,83/10/04,8310180173
- 8310120397 Forwards affidavit attasting to direct distribution of Amend Applications 22 k 8. HEBFORD.M C Southern California Edison Co 83/10/07 KNISHTON.O W Licensing Branch 3 App. 20699 053 24X Fichs 50-361,83/10/07.8310120397
- B310200177 Forwards response to NRC 830527 request for add1 info to satisfy requirements of NUMES-0737, Item II D 1. "Relief & Safety Valve Testing "
 MEDFORD, M O Bouthern California Edison Co 83/10/14
 KNIGHTON, OW Licensing Branch 3 17pp 20835 298 24X
 Fiche 50-361,83/10/14,8310200177
- 8310250124 Forwards Rev 1 to Calculation SFR-CC-01 1, "Reevaluation of Spent Fuel Storage Racks," in response to NRC 830722 request Racks in fully loaded condition fail to meet seismic criteria.

 MEDFORD, M C Bouthern California Edison Co 83/10/17 GRUTCHFIELD, D Operating Reactors Branch 5 2pp 20878 185 24X Fiche 50-206,83/10/17,8310250124
- 8310210260 Requests concurrence we mod to FSAR Table 14,2-2A concerning power ascension testing sequence of 100X power plateau test program.per 830729 1 tr.to eliminate need for addit plant trip MEDFORD. M D. Bouthern California Edison Co. 83/10/19. KNIGHTON, G.W. Licensing Branch 3. 2pp. 20855-256. 24X Fiche: 50-362, 83/10/19, 8310210260
- Q Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Jests." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754,022 24X Fiche 50-000,83/09/26,8308300340

- 830B30D342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Syc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,830B300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche.50-000.83/09/26,8308300045
- 8310120298 Submits comments on 830826 BALP analyses Operator errors primarily result of inadequate procedures or training. Actions taken to improve training & operating experience feedback in maint program FOOARTY.D J Southern California Edison Co 83/09/28 MARTIN.J B. Region 5. Office of Director 2pp 20693.170 24x Fiche 50-206.83/09/28.8310120298
- 8308300347 IE Info Notice B3-64, "Lead Shielding Attached to Bafety-Related 8ys W/o 10CFR50 59 Evaluation" Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8310200208 Forwards IE Insp Repts 50-206/83-19,50-361/83-29 & 50-362/83-27 on 930804-0916 No noncompliance noted BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 83/10/04 MCCARTHY.C B Southern California Edison Co 2pp 20834 128 24% Fiche 50-206,83/10/04,8310200208
- --B310200214 IE Insp Repts 50-206/83-19.50-361/83-29 & 50-362/83-27 on 830804-0916 No noncompliance noted. Major areas inspected operational sefety verification, witnessing precriticality, initial criticality & low power physics testing CHAFFE.A E., D'ANGELO, A., BIEWART.J P Region 5, Office of Director 83/09/30 18pp 20834 130 24X Fiche 50-206,83/10/04,8310200208
- TOB300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svc list encl.

 JURDAN, E L Division of Energency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Nevert Not. 1nc. 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- OB300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07. Consolidated Edison Co of New York, Inc 79p 20882 026 24X Fichs 50-090,83/10/07,8308300752.
- 1308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Nozious Gases " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043.075 24X Fiche 50-000.83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Harning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl.
 - Pincl.

 RDAN, E.L. Division of Emergency Preparedness & Engineering spanse (Post 830103) 83/10/11 Consolidated Edison Co of New rk, Inc. 120pp. 20827 129 24X Fiche 50-000,83/10/11,8308300761
 - 200220 Forwards IE Mgt Meeting Repts 50-206/83-22.50-361/83-36 & -262/83-24 on 830908 re BALP rept for Jul 1982 May 1983 RTIN, J B Region 5. Defice of Director 83/10/14 MCCARTHY, C B authorn Colifornia Edison Co 2pp 20829 327 24% iche. 50-206.83/10/14.8310200220
 - 10200224 IE Mgt Meeting Repts 30-206/83-22, 50-361/83-36 & 50-362/83-34 on 830908 Major areas discussed: SALP rept for Jul 1982 May 1983 (ARSCH.) F Region 5, Office of Director, 83/10/13 2pp. 20829 329. 24X Fiche: 50-206, 83/10/14, 8310200220
 - [0200228 SALP mept for Jul 1982 May 1983 F Region 5: Office of Director. 83/07/15, 42pp. 20829,331 24X Tiche 50-206:83/10/14,8310200220
 - 0200232 Summarizes major investigative activities involving facilities for BALP board review covering Jul 1982 May 983.

 HACKLETON.O C Office of Investigation. 83/06/06 BISHOP,T Wegion 5. Office of Director. 2pp. 20830.011 24X iche 50-206,83/10/14.8310200220.

- --8306170442 Forwards evaluation of LERs for period 820701 to 830530 in support of ongoing SALP review
 SEYFRIT.K V Director's Office 83/06/10 STERNBERG, D Division of Resident, Reactor Project & Engineering Programs 4pp 20830 021 24X Fiche 50-206,83/10/14,8310200220
- R Periodic operating reports & related correspondence
- B310190092 Monthly operating repts for Aug 1983 W/830915 ltr RAY.H B . MAYWEATHER.L Southern California Edison Co 83/09/15 Division of Data Automation & Management Information 13pp 20822 252 24X Fiche 50-361.83/09/15.8310190092
- S Reportable occurrences. LERs & related correspondence
- 8310120338 LER 83-055/03L-0 on 830824, core protection channel A declared inoperable & bypassed due to failed high reactor coolant cold leg temp input Caused by failed open resistance temp detector 3TE-9179-1 Detector replaced W/830928 ltr RAY.H 8 Southern California Edison Co 83/09/28 MARTIN.J B Region 5. Office of Director 3pp 20700 211 24X Fiche 50-362.83/09/28.8310120338
- #310070333 PNO-V-83-042 on 830929, unusual event declared when unidentified leakage from RCS of i 19 gpm discovered Caused by high penalty factor applied in response to 1 h observation Reactor & sys normal after 20% trip test #KIRSCH.D Region 5. Office of Director 83/09/29 lp 20651 002 24% Fich# 50-362,83/09/29,8310070333
- 8310120172 LER B3-060/03L-0 on 830830, control element assembly calculator 1 % core protection calculator channel B inoperable Caused by failed input amplifier cerd Card replaced W/830929 ltr
 RAY, H B Southern California Edison Co 83/09/29 MARTIN, J B Region 5, Office of Director 3pp 20695 361 24X
 Fiche 50-362,83/09/29,8310120172
- B310070301 Potential Part 21 rept re underrange characteristic of Model N-E110A transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified

 BERBERIANNI J Foxboro Corp B3/09/30 Director's Office, Office of Inspection and Enforcement 11pp 20451 044 24X

 Fiche 50-000,83/09/30,8310070301
- 8310120075 LER 83-106/01L-0 on 830907, surveillance testing resulted in unsatisfactory float voltage for pilot cells 11 & 13 & unsatisfactory total battery terminal voltage Caused by personnel error W/8309730 tr RAY, H B Southern California Edison Co 83/09/30 MARTIN, J B Region 5. Office of Director 29p 20696 162 24X Fiche 50-366. 83/09/30. 8310120075
- 8310120183 LER 83-066/03L-0 on 830829 & 31, while in Mode 2, control element assembly calculator 2 experienced excessive autorestarts First event caused by faulty central processing unit board Cause for mecond event unknown W/830930 ltr RAY. H B Southern California Edison Co 83/09/30 MARTIN, J B Region 5, Office of Director 3pp 20695 298 24X Ficher 50-0362, 83/09/30, 8310120183
- B31014021B R0 B3-073 on B30929, reactor placed in Mode 3 due to stressive unidentified leakage from RCB Conddown commenced in perallel w/continuing efforts to locate leakage source RCB temp held constant at 480 F to measure leakage RAY.H 3 Southern California Edison Co 83/09/30 MARTIN.J B Region 5, Dffice of Director 2pp 20761 B3 24X Fiche 50-362.83/09/30.831014021B
- B310120065 PNO-V-83-043 on 830929, two manual valves incorrectly closed, isolating all charging pump flow to RCS Plant being shut down due to excessive leakage from RCS On 830930, Tech Spec violation recognized & valves opened ECKHARDT. J. Region 5. Office of Director 83/10/03 ip 20698 296 24X Fiche 50-362,83/10/03,8310120065
- 8310140023 LER 83-072/03L-0 on 830831, w/unit in Mode 2, containment water lavel wide range train B instrumentation failed Caused by water trapped in column for level transmitter 3LT-9388-2 instrument recalibr & declared operable W/831003 ltr RAY.H B. Southern California Edison Co 83/10/03 MARTIN.J B Region 5, Office of Director 3pp 20768 002 24X Fiche 50-362,83/10/03,8310140023
- B310140125 LER 83-062/03L-0 on B30901 & 05, during low power physics testing in Hode 2, control element assembly 84 dropped more than 19 inches. Caused by improper timing of assembly grippers Timing adjusted W/831004 ltr RAY, H B Southern California Edison Co B3/10/04 MARTIN, J B Regison 5, 0ftice of Director 3pp 20765 027 24X Fiche 50-362, 83/10/04, 8310140125

- E310140153 FNO-V-83-046 on 831003 while in Mode 3 & attempting to determine why LP turbine stop valve would not fully shut, discovered debris inside moisture separator reheater Turbine not damaged ECHMARDI. J. Region 5. Office of Director 83/10/04 ip 20762 362 24X Fishe 50-362.83/10/04.8310140153
- 8310140167 LER 83-067/03L-0 on 830701, one-phase trip of supply broaker far part-length control element assembly (CEA) 32 rendered CEA incapable of withdrawal Coused by failure of circuitry components Components replaced W/831004 ltr RAY, H B Southern California Edison Co 83/10/04 MARTIN, J B Region 5, Office of Director 5pp 20765 073 24X Fiche 50-362.63/10/04,8310140167
- 8310270454 RO re 1983 land use census, enumerating changes in land use within 5-mile radius of site ref point which have resulted in calculated dose commitments greater than values currently calculated, per Tech Spec 4 il 2 3 BASKIN. K P Southern California Edison Co 83/10/04 MARIIN. J B Region 5, Office of Director 2pp 20923 004 24% Fiche 50-361.83/10/04.8310270454
- \$310250495 Corrected LER 83-065/03L-0 on 830905 & 12, high-range the-containment radiation monitor 3RI-7820-1 declared troperable after discovery in fauled low condution Caused by faulty electrical cable penetration path W/831005 ltr HAYMES.J G Southern California Edison Co 83/10/05 MARTIN, J B Region 5, Office of Director 4pp 2089/ 113 24X Fiche 50-362,83/10/05,8310250495
- M10270495 LCR 83-065/03L-0 on B30905 & 12. w/unit in Mode 2 at zero power.high range in-containment radiation monitor 3HI-7820-1 found in failed law condition & declared inoperable Caused by faulty electrical cable penetration path W/B31006 ltr HANNES. J G Southern California Edison Co 83/10/06 MARTIN. J B Ragion 5, Office of Director 3pp 20922 005 24X Fiche 50-362,83/10/06,8310370493
- 8310270448 LER 83-076/03L-0 on 830907, during shift surveillance, control element assembly calculator 2 declared inoperable Caused by poorly seated circuit board Circuit boards resealed W/83100/ ttr
 HAYNES. 9 Southern California Edison Co 83/10/07 MARTIN. J B Region 5, Office of Director 3pp 20723 134 24X
 Fiche: 50-362, 83/10/07, 8310270448
- 310250465 LER B3-074/03L-0 on 830709, containment airborne radiation agnitor SRI-7804C in continuous alarm state & declared inogerable Caused by alarm setpoint being set too low New setpoint established W/831011 ltr HAYNES. J & Southern California Edison Co 83/10/11 MARTIN. J B Region 5. Dffice of Director 3pp 20897 117 24X Fiche 50-362,83/10/11,8310250465
- G10270416 LER 83-069/03L-0 on 830917, w/unit in Mode 3, condenser air ejector wide-range gas monitor 3RI-3870 declared inoperable Caused by loss of communication between RMBO microprocessor & RM23 control room readout Data base relpaded W/831017 ltr HAYNES, J. 0 Southern California Edison Co. 83/10/17 MARTIN, J.B. Repion 5, Office of Director. 3pp. 20723 077 24X Fiche 50-362,83/10/17,8310870416
- MIO270432 RO 83-068 on 830922, w/unit in Mode 3, control room cabinet area swengency air conditioning train A unit 3ME427 removed from svc for routine preventive maint Maint completed on 830924. within 1 limiting condition for operation HAYMES, J Ø Bouthern California Edison Co 83/10/17 MARTIN, J B Region 5, Office of Director 2pp 20923 042 24X Fiche 50-362,83/10/17,8310270432
- BIO270439 LER B3-073/01T-0 on B30929, charging & letdown flows isolated by closing manual isolation valves B3120BMU084 & B3120BMU091 in violation of limiting conditions of operation Caused by personnel error Valves opened on B30930 W/B31017 ltr MAYMES, J. G., RAY, H. B. Southern California Edison Co. B3/10/17 MARTEN, J. B. Region 5, Office of Director App. 20923 111 24X Fiche 50-362, B3/10/17, B310270439
- B10270428 Updated LER 83-064/00X-1 on 830829, w/unit in Mode 2, ex-core legarithmic power safety channel C declared inoperable & on 830918, channel B declared inoperable Caused by failed cable connectors Connectors replaced W/831018 ltr HAYNES, J & Southern California Edison Co 83/10/18 MARTIN, J B Region 5, Dffice of Director 3pp 20923 062 24X Fiche 50-362, 93/10/18,8310270428
- 310310326 RO firs doors listed on encl list found inoperable during Sept routine surveillances Compensatory fire watches established Latching mechanism & closing mechanism failures caused by hardware degradation MAYNES, J.O. Bouthern California Edison Co. 83/10/18 MARTIN, J.B. Region 5. Office of Director 6pp. 20761 142, 24X Fichs 50-36), 83/10/18:8310310326

- 8310310284 PNS-V-83-011 on 831024. San Francisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries hot cited Repts believed to be untrue or exaggerated SCHAEFER. D W Region 5. Office of Director 83/10/24 lp 20761 28P 24X Fiche 50-206. 83/10/24. 8310310284
- V Operator Examinations
- 8310030109 Requests, by 831028, school for requalification training & exams for 1984 Schedule needed for periodic audits of licensed operator requalification programs BISHOP.T H Division of Resident, Reactor Project & Engineering Programs B3/09/26 FD9ARTY.D J Southern California Edison Co 2pp 20590 053 24% Fiche 50-206,83/09/26.8310030109
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8310040436 Resubmits 830725 itr transmitting Rev 7 to security plan Original ltr contained safeguards info & could not be docketed CLAYTON: FL Alabama Power Co 83/09/15 O'REILLY, J.P. Region 2 Office of Director ip. 20619 053 24X Fiche 50-348,83/09/15,831004034
- B310040581 Advises that review of Rev 7 to radiological emergency plan complete Plan continues to meet planning stds of 10CFR50 47(b) & requirements of 10CFR50 App E VERRELLI.D M Division of Project & Resident Programs B3/09/20 MCDCNALD,R P Alabama Power Co 2pp 20622 306 24X Fiche 50-348, B3/09/20, B310040581
- 8310030147 Ack receipt of 830824 ltr documenting results of design description for alternative shutdown capability review refire protection Description acceptable w/exception that source range monitor be added to hat shutdown panel CLAYTON.FL Alabama Power Co 83/09/28 VAROA S A Dffice of Nuclear Reactor Regulation, Director 2pp 20590 034 24% Fiche 50-348.83/09/28.8310030147
- B310250472 Ack receipt of B30921 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-21 & 50-344/83-19 Request for 60-day extension for response to violations approved VERRELLI.D M Division of Project & Resident Programs B3/10/06 MCDDNALD.R P Alabama Power Co 2pp 20902.121 24X Fiche 50-348,83/10/06.8310250472
- --B310230479 Responds to NRC B30909 ltr re violations noted in IE Inap
 Repts 50-348/83-21 & 50-364/83-19 Corrective actions
 detailed review of fire protection program underway
 Extension of 60 days requested for response
 CLAY10N.F.L. Alabama Power Co. B3/09/21 VERRELLI, D.M. Division
 of Project & Resident Programs 2pp. 20902 123 24X
 Fichs 50-348,83/10/06,8310250472
- ~-8310250485 Forwards IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19 & notice of violation VERRELLI,D M Division of Project & Resident Programs B3/09/09 MCDDMALD,R P Alabama Power Co 2pp 20902 125 24X Fichs 50-348,83/10/06,8310250472
- --8310250490 Notice of violation from insp on 830816-19 * Division of Project & Resident Programs 83/09/09 2pp 20902 127 24X Fishs 50-348.83/10/06.8310250472
- --8310250478 IE Insp Repts 50-348/83-21 & 50-364/83-19 on 830816-19. Nancompliance noted inadaquate surveillance test procedures for fire detection sys.fire protection control valves & carbon dioxide hose reels & no fire stops for cable trays MILLER,W H Region 2. Office of Director 83/09/07 10pp 20902.129 24X Fiche 50-348,83/10/06/8310250472
- 8310280085 Forwards Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively & safety evaluation Amends consist of administrative changes to Tech Spects re administrative controls for onsite & offsite organization REEVES,E A. Operating Reactors Branch 1 83/10/14 CLAYTON,F L Alabama Power Co 2pp 20765 001 24X Fiche 50-348,83/10/14,8310280085
- --8310280072 Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits VARQA: B A Deprating Reactors Branch 1 83/10/14. 46pp 20965 003 24X Fiche 50-348,83/10/14,8310280085

- --8310280114 Safety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-B.respectively # Office of Nuclear Reactor Regulation, Director 83/10/14 App 20965 047 24X Ficher 50-348,83/10/14.8310280085
- 8310210022 Informs of inaccuracy in design description for alternative shutdown capability transmitted in util 820701 ltr Local mechanical level indication not installed on condensate storage tank but will be added CLAYTON.F L Alabama Power Co 83/10/17 VARQA.S A Office of Nuclear Reactor Regulation. Director 2pp 20836:067 24X Fiche 50-348,83/10/17.83102100R2
- P Operating license stage documents & correspondence
- 8310060535 Forwards Rev 1 to 830408 safety evaluation re requests for relief from inservice testing requirements for pumps & valves Add1 info required for remaining items. Revs requested for Unit i will be addressed separately VAROA.8 A Operating Reactors Branch 1 83/09/16 CLAYTON.F L Alabama Power Co Spp. 20661 322 24X Fiche 50-364.83/09/16.8310060535
- --8310060540 Rev 1 to 830408 safety evaluation re requests for relief from inservice testing requirements for pumps & valves; based on licensee 830705 submittal Based on review specified alternate testing acceptable. * Office of Nuclear Reactor Regulation, Director 83/09/16, 9pp 20661 325 24X Fiche 50-364,83/09/16,8310060535
- 8310030613 Forwards safety evaluation of shunt trip design for RPS DS 416 reactor trip breakers Design acceptable conditioned on receipt of confirmatory info & completion of action team listed VAROA, 8 A Operating Reactors Branch 1 83/09/20 CLAYTON, F L. Alabama Power Co 3pp 20607 314 24X Fichs 50-348,83/09/20,8310030613
- --B310030615 Safety evaluation conditionally accepting shunt trip design for RPS DS 416 reactor trip breakers * NRC - No Detailed Affiliation Given 63/09/14 18pp 20607.317 24X Fichs 30-346.83/09/20.8310030613
- 8310050017 Parwards safety evaluation denying licensee B30304 application for amend to Licenses NPF-2 k NPF-8 to allow continued plant operations w/more than one control rod immovable VARGA.8.A Operating Reactors Branch 1. 83/09/21, CLAYTON, F L Alahama Power Co. 2pp. 20650 268 24% Fiche 50-348,83/09/21, 8310050017
- --8310050022 Safety evaluation denying licenses 830304 application for amend to Licenses NPF-2 & NPF-8 to allow continued plant operations w/more than one control rod immovable, Licenses must resolve potential core-wide mechanical problem * NRC No Detailed Affiliation Given, 83/09/21 lp. 20650.270 24X Fichs 50-348,83/09/21,8310050017
- 8310030603 Forwards safety evaluation concurring w/licenses conclusions that NUREO-0737. Item II K 3 2 requirements met w/existing PORV, safety valve & reactor high trip pressure setpoints Automatic PORV isolation sys (Item II K 3 1) not required VAROA. S A Operating Reactors Branch 1 83/09/23 CLAYTON, F L Alabama Power Co 14pp. 20404 212 24X Fiche 50-348, 83/09/23, 8310030603
- 8310060096 Forwards four oversize drawings, in response to NRC request for add1 info re syc water bldg battery sys design, per util 830503 & 0729 proposed Tech Spec changes involving dc distribution sys, Aperture cards are available in PDR. CLAYTON-F L. Alabama Power Co. 83/09/23 VARQA-8 A NRC No Detailed Apfiliation 01ven 2Pp. 20646; 277. 24X Fiche: 50-348,83/09/23,8310060096
- B310030414 Identifies specific Reg Quide 1,97 accident monitoring equipment sys for which extension requested, per B30520 & OB24 ltrs Bchedules for upgrading equipment provided w/bases for extension request CLAYION.F L. Alabama Power Co. B3/09/27, VAROA.B A. Office of Nuclear Reactor Regulation, Director 22pp. 20593 OB7 24X Fiche: 50-348.83/09/27, B310030414.
- 8310040387 Submits evaluation of existing Westinghouse BTS provisions.
 ABME Code Section XI,Reactor Safety Study (MASH 1400),
 NUREO-0677 & EGNO rept. "Inservice Leak Testing of Primary
 Pressure Isolation Valves:" as applicable to plant design
 CLAYTON:F.L. Alabama Power Co. 83/09/27 VARGA,8 A. Office of
 Nuclear Reactor Regulation, Director. 16pp. 20625,200 24X
 Fiche: 50-348,83/09/27.8310040387.

- 8310140194 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Spees to delete turbine valve testing requirements Testing program will be replaced w/insp & maint program for all throttle & governor valves CLAYTON,F L. Alabama Power Co. 63/10/06 VARGA,S A. Office of Nuclear Reactor Regulation, Director. 4pp. 20766-077 24X Fiche 50-348,83/10/06.8310140194
- --8310140197 Proposed Tech Specs to limiting conditions for operation & surveillance requirements of turbine valve testing Turbine overspeed reliability assurance program encl Program withheld (ref 10CFR2 770)

 * Alabama Power Co 83/10/06 15pp 20766 081 24X Fiche 50-288.83/10/06,8310140194
- 8310170407 Forwards status of licensing items requiring NRC approval CLAYTON.F L Alabama Power Co 83/10/10 VARGA.8 A Office of Nuclear Reactor Regulation. Director 11pp 20779 161 24X Fiche 30-348,83/10/10/8310170407
- B310170416 Application to amend Licenses NPF-2 & NPF-8 consisting of changes to Tech Spec re movable rod control sys requirements Encl clarifies 830304,0603 & 0728 submittals in response to NRC 830921 request CLAYTON,F L Alabama Power Co 83/10/10 VARGA.8 A Office of Nuclear Reactor Regulation, Director 3pp 20779 195 24X Fiche 50-348,83/10/10.8310170416
- --8310170423 Proposed Tech Spec changes re movable rod control sys requirements * Alabama Power Co 83/10/10 5pp 20779 198 24X Fiche 50-348.83/10/10.8310170416
- S310180280 Forwards list of application dates, fees paid, fees applicable & NRR fee determination & action on each item Based on NRR fee determinations, total of \$17,500 due Util will be notified of adjustments following final review MILLER, W O License Fee Management Branch B3/10/11 CLAYTON, FL Alabama Power Co 3pp 20827 126 24X Fiche 50-348,83/10/11.
- 8310210259 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Specs to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) below full power CLAYTON, F L Alabama Power Co 83/10/13 VAROA, S A Office of Nuclear Reactor Regulation, Director 50pp 20851 163 24X Fiche 50-348,83/10/13,8310210259
- --8310210261 Proposed Tech Spec changes to allow operation w/slightly positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor (F Delta H) limit below full power # Alabama Power Co #83/10/13 13pp 20851 213 24X Fichs 50-348, 83/10/13, 8310210259
- B310280085 Forwards Amends 33 & 26 to Licenses NPF-R & NPF-8, respectively & safety evaluation Amends consist of administrative changes to Fech Specs re administrative controls for onsite & offsite organization REEVES, E A Operating Reactors Branch 1 83/10/14 CLAYTON, F L Alabama Power Co 2pp 20765 001 24X Fiche 50-348, 83/10/14, 8310280085
- --B310280092 Amends 33 & 26 to Licenses NPF-2 & NPF-8, respectively, making administrative changes to Tech Specs re administrative controls for onsite & offsite organization & environ qualification audits VAROA, B A Operating Reactors Branch 1 83/10/14 46pp 20965 003 24X Fishe 50-348, 83/10/14, 8310280085
- ---B310280114 Bafety evaluation supporting Amends 33 & 26 to Licenses NPF-2 & NPF-B, respectively * Office of Nuclear Reactor Regulation, Director 83/10/14 App 20763 049 24% Fiche 50-348,83/10/14,8310280085
- 8310250422 Responds to four items re shunt trip design for DS-416 reactor trip breakers, per NRC 830920 request Environ conditions considered in developing Westinghouse Dumprs Group generic design CLAYTON, F. Alabama Power Co. 83/10/20 VAROA, S. A. Défice of Nuclear Reactor Regulation. Director 2pp 20897 182 24X Fiche. 50-348, 83/10/20, 8310250422
- Q Inspection reports: IE Bulletins & correspondence
- B310040374 Ack receipt of B30909 ltr informing NRC of steps taken to correct violations noted in It Insp Repts 50-348/83-20 & 50-364/83-18.

 VERRELLI,D M Division of Project & Resident Programs 83/09/19, MCDDNALD,R F Alabama Power Go 1p 20617-066 24X Fiche 50-348, 83/09/19, 8310040374

- --23:0042377 Responds to ARC 830819 itr re violations noted in IE Insp. Repts 50-348/83-20 & 53-344/83-18 Corrective actions containment air cooler fan annunciator linns 24 & 25 closed & chemistry control Procedure EMP-D-CCP-12 remitten CLAYTON.F. L. Alabama Power Co. 63/09/09 VERRELLI.D.II Division of Project & Resident Programs 3pp. 20617 067 24X Fiche 50-348.83/09/19 83100403/4
- --8310040379 Notice of violation from insp on 630711-0810

 m Region 2. Office of Director 83/08/19 2pp 20617 073 24x
 Fiche 30-348.83/09/19.8310040374
- -- 831GC40384 IE Insp Repts 50-348/83-20 & 50-364/83-18 on 830711-0810 Noncompliance noted sulfuric acid std used to check hydrometers not listed on licenses test equipment inventory \$ maint schedule & containment air cooler fan linis open SPADEDORD.W H , RULAND.W H Region 2. Office of Director CANTRELL.F B Division of Project & Resident Programs 83/08/18 IOpp 23617 075 24X Fiche 50-348.83/09/19.8310040374
- #310250376 Forwards IE lnsp Repts 50-348/83-22 & 50-364/83-20 on #31829-31 No noncompliance noted VERFELLI.D M Division of Project & Resident Programs #3/09/15 #200MALD R F Alabama Power to 2pp 20878 130 24X Fiche 50-349.83/09/19.8310250376
- --B3102503B7 IE Insp Repts 50-348/B3-22 & 50-364/B3-20 on B30829-31 No rencompliance noted Major areas inspected licenses action on previous insp following items & two licenses reported events involving spread of contamination IMES. B 1 Region 2. Office of Director BARR, K P Division of Engineering & Devrational Programs B3/09/14 App 2089B 132 24X Fichs 50-348, 83/09/19, 8310250376
- 2010070049 Forwards SER re util 800725 & 830128 requests for relief from inservice inspirequirements of ASME Code, Section XI Requests granted VAR3A.S A Operating Reactors Branch 1 83/09/22 CLAYTON,F L Alabama Power Co 3pp 20680 001 24X Fiche 50-364,83/09/22, E330070049
- -- \$310070052 SER re util 800725 & 830128 requests for relief from inservace inspirequents of ASME Code, Section XI Requests granted

 * Materials Engineering Branch 83/09/20 28pp 20680 004 24X
 Fiche 50-364.83/09/22.8310070049
- --8310070054 Notice of granting of relief from ASHE Code requirements VARCA.5 A Operating Reactors Branch 1 83/09/22 2pp 20680 032 24X Fiche 50-364.83/09/22.8310070049
- 53CB300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN. E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754-022 24X Fiche 50-000.83/09/26.8308300340
- 83C8300342 IE Info Notice 83-62. "Failure of Redundant Toxic Cas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 63/09/25 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26.8308300342
- 83C8G00345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl SCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26.8308300345
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o IOCFR30 37 Evaluation " Svc list encl JCRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 30-000.83/09/29.8308300349
- B310140174 Application for amend to Licenses NPF-2 k NPF-8, changing Tech Specs to delete turbine valve testing requirements Testing program will be replaced winsp k maint program for all throttle k governor valves CLAYTON.F L Alabama Power Co 83/10/06 VARGA.S A Office of Muclear Reactor Regulation. Director 4pp 20766 077 24X Fache 50-348.83/10/06.8310140194

- --8310140199 Proposed Tech Specs to limiting conditions for operation & surveillance requirements of turbine valve testing Turbine correspond reliability assurance program entil Program withheld (ref 10CFR2 790) at Alabama Power Co. 83/10/06. 15pp. 20766-001 24x Fiche 50-348.83/10/06.8310140194
- 8310230472 Ack receipt of 830921 itr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-348/83-21 & 50-364/83-19 Request for 60-day extension for response to violations approved VERFELLI.O M Division of Project & Resident Programs 83/10/06 MCDDNALD.R P Alabama Power Co 2pp 20902 121 24X Fiche 50-348.83/10/06 8310250472
- --8310250479 Responds to NRC 830909 lit re violations noted in IE Insp Repts 50-348/83-21 t 50-364/83-19 Corrective actions detailed review of fire protection program underway Extension of 60 days requested for response CLAYTON-F L Alabama Power Co 80/09/21 VERRELLI.D M Division of Project & Resident Programs 2pp 20902 123 24X Fiche 50-348-83/10/06.8310250472
- --8316250485 Forwards IE Insp Repts 50-348/83-21 & 50-364/83-19 on B30816-19 & notice of violation VERRELLI.D M Division of Project & Resident Programs B3/09/04 MCDCMALD.R P Alabase Power Co 2pp 20902 125 24X Fichs 50-348
- --8310250490 Notice of violation from insp on 830816-19

 * Division of Project & Resident Programs 83/09/09 2p
 20902 127 24X Fiche 50-348,83/10/06,8310250472
- --B31025049B (E Insp Repts 50-348/83-21 & 50-364/83-19 on B30816-19 Noncompliance noted inadequate surveillance test procedures for fire detection sys. fire protection control valves & carbon dioxide hase reals & no fire stops for cable trags HILLER.W H . GIBBOMS.T D . COMLON.T E Region 2. Office of Director B3/09/07 10pp 20902 129 24% Ficke 50-348.83/10/06.B310250472
- B30B300378 IE Info Notice B3-65. "Surveillance of Flow in RTD Bypass Loops Used in Mestinghouse Plants " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York. Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.83083000378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York Inc 79pp 20882 026 24% Fiche 50-000.83/10/07.8308300752
- 8308300757 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fichs 50-000.83/10/11.8308300757
- 8308300761 IE Info Notice 83-68. "Respirator User Marning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp. 20827 129 24X Fiche 50-000.83/10/11.8308300761
- R Periodic operating reports & related correspondence
- 83i0190071 Monthly operating rapt for Aug 1983 W/830912 ltr HAIRSTON:W G. CLAYTON:F.L. Alabama Power Co. 82/09/01 Office of Resource Management. Director 5pp 20822 288 24X Fiche 50-364.83/09/01.8310190071
- 8310180134 Monthly operating rept for Sept 1983 M/831012 ltr HAIRSTON, W 0 . CLAYTON, F.L. Alphama Power Co. 83/10/04 MRC ~ No Detailed Affiliation 91van 9pp 20809 186 24X Fichs 50-364,83/10/04.8310180134
- S Reportable occurrences. LERs & related correspondence
- 8310030439 RO on 830917, while attempting to isolate steam to turbine bidy, three MSIVs failed to close under na-flow conditions Clapper found detached from valve arm Investigation continuing HAIRSTON, W @ Alabama Power Cq 63/09/19 O'REILLY, J P. Region 2a Defice of Director ip 20002 090 24X Fiche 50-364, 83/09/19, 8310030439

- 6310070270 LER 63-039/01T-0 on 830917.MSIVs failed to close under noflow conditions.MSIV 02N11V002B remained partially open & declared inoperable Caused by binding in valve packing & separation of valve disc from disc arm W/830930 ltr HAIRSTON.W C . CLAYTON.F L Alabams Power Co 83/09/30 Region 2. Office of Director App 20655 171 24X Fiche 50-364.83/09/30, 8310070290
- 8310070296 Forwards LERs 83-057/03L-0 & 83-036/03L-0 CLAYTON F L. Alabama Power Co 83/09/30 Region 2, Office of Director 1p 20651 075 24X Fiche 50-348,83/09/30,8310070396
- --8310070302 LER 83-036/03L-0. on 83083; following failure alarm on power cabinet 28D, rod control sys declared inoperable Caused by blown fuse Fuse & blown fuse indicator replaced.

 HAIRSTON, 40 A labama Power Co 83/09/20 Region 2, Office of Birector 1p 20651 077 24X Fiche 50-348,83/09/30,8310070296
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EilOM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified.

 8ERBERIAN, M J Foxboro Corp 83/09/30 Director's Office, Office of Inspection and Enforcement 11pp. 20451 044 24X Fiche 50-000,83/09/30,8310070301
- 8310120350 Forwards LERs 83-060/03L-0.83-051/03L-0.83-037/03L-0 & 83-038/03L-0 W/O LER 83-038/03L-0 CLAYTON.F.L Alabama Power Co 83/10/04 Region 2. Office of Director ip 20659 317 24X Fiche 50-348,83/10/04.8310120350
- --B310120371 LER 83-037/03L-0 on B30907, battery bank 2A declared inoperable Gaused by decrease in voltage on cell 56 below Tech Spec 3 8 2 3 requirements Cell cleaned & charged Sys restored HAIRSTON.W 0 Alabama Power Co B3/10/04 Region 2, Office of Director. Ip 20699 320 24% Fiche 50-348,83/10/04,8310120350
- 8310270061 Forwards LERs 83-040/03L-0 & 83-041/03L-0 CLAYTON,F L Alabama Power Co 83/10/18 Region 2, Office of Director ip 20724-194 24X Fiche-50-364,83/10/18,8310270061
- --D310270108 LER 83-040/03L-0 on 830718, during performance of RCB pressure isolation valve leak test, check valve 02E11V051A declared inoperable when valve found leaking excessively Caused by incomplete centact between valve disc & seat HALRSION, W O Alabama Power Co 83/10/18 Region 2, Office of Director 1p 20724 175 24X Fiche 30-364.83/10/18.8310270061
- --8310270115 LER 83-D41/03L-0 on 830921 instrumentation channel associated w/RCP but underfrequency relay A declared inoperable due to response time being 1.64 s above Tech Spec time of 0.6 s Causad by dirty contacts
 HAIRBTON,# 0 Alabama Power Co 83/10/18 Region 2, Office of Director. 1p 20924-194 24X Ficha 50-364.83/10/18.8310270061
- DOCKET 50-366 EDWIN 1 HATCH NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8310040351 Forwards technical support ctr & emergency operations facility floor plans-route maps to emergency response facilities & telaphone listings Requests update of info & submittal of personnel access documents
 DANCE.H C Division of Project & Resident Programs 83/09/12 KELLYR.J Georgia Power Co 8pp. 20620 323 24X
 Fiche 50~321.83/09/12,8310040351
- 8310040356 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~321/83-17 k 50~366/83-17 LEWIS.R C Division of Project & Resident Programs 83/09/19 KELLY.R.J Georgia Power Co Ip 20625 304 24X Fichs.50~321,83/09/19,8310040356
- ~~8310040499 [E Insp Repts 50-321/83-17 k 50-366/83-17 on 830523-27, Noncompliance noted failure to dispose of radwaste per 100FR20 301. KANLEJ B Region 2, Defice of Director 83/06/20. 7pp 20625 312 24X Fiche 50-321,83/09/19,8310040356
- 8310170741 Releases public version of revised emergency plan implementing procedures.
 FELTON.J.H. Division of Rules and Records. 83/10/06 Document Hanagement Branch. 1p 2079/-272. 24X Fiche-50-321,83/10/06. 8310170741

- --8310170743 Forwards public version of revised emergency plan implementing procedures including Procedures HNP-8024 recontaminated tool storage & control & HNP-4861 re emergency notification network NIX.H C . SORRELL. E C Georgia Power Co 83/09/16 Office of Nuclear Reactor Regulation, Director 4pp 20797 273 24X Fiche 50-321,83/10/06,8310170741
- ---B310170746 Public version of revised emergency plan implementing procedures, including Procedures HNP-8034 re contaminated tool storage & control & HNP-4861 re emergency notification network GREENLT T, RCIGERS, W H, NIX.H C Georgia Power Co 83/09/14 26pp 20797 277 24X Fiche 50-321.83/10/06.8310170741
- 8310270012 Forwards IE Safeguards Insp Repts 50-321/83-26 & 50-366/83-28 on 830926-30 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/10/20 KELL.Y, R J Georgia Power Co 2pp 20924 331 24X Fiche 50-321,83/10/20,8310270012
- --B310270023 IE Bafeguards Insp Repts 50-321/83-26 & 50-366/83-28 on B30926-30 No noncompliance noted Major areas inspected site orientation review of security plan & procedures & security organization Details withheld (ref 10CFR73 21) HALL B L Region 2, Office of Director B3/10/20 ip 20924 333 24% Fiche 50-321,83/10/20,8310270012
- Q Adjudicatory correspondence
- 8310180364 Forwards info re util questioning of validity of natice of violation for violating 1007820 301 Util requested official interpretation & claimed NRC transferred regulatory authority to 98ate of SC LIEDERMAN. J Regional Operations & Enforcement Division 83/10/13 OLMSTEAD. B Regulations Division 32pp 20803 044 24X Fiche 50-321,83/10/13.8310180344
- J Insurance & indemnity information
- 8310030301 Forwards Endorsements 81 & 82 to NELIA Policy NF-215 & Endorsements 66 & 67 to MAELV Policy MF-78 FIELDER: J. Marsh & McLennan; Inc. 83/09/26 8ALTZMAN; J. Assistant Director for State & Licensee Relations. 5pp. 20891 008 24X Fichs.50-321,83/09/26,8310030301
- P Operating license stage documents & correspondence
- 8310110442 Informs that commitment to add high radiation signal for purge & vent valve isolation meets requirements of NUREO-0737. Item II E 4 2 7. "Primary Containment High Radiation to Close Vent & Purge Valves "
 STOLZ.J F Operating Reactors Branch 4 83/09/29 BECKMAN.J T Georgia Power Co 2pp 20704 319 24X Fiche 50-321.83/09/29, 22101442
- 8310070264 Forwards proprietary "Diesden 2/3 Nuclear Generating Plant Suppression Pool Temp Response," "EI Hotch Nuclear Power Station Units J & 2 Suppression Pool Temp Response" & Mark I 630825 meeting viewgraphs Repts withheld (ref 10CFR2 790) PFEFFERLEN.H. C General Electric Co 83/09/30 VASSALLO, D B Operating Reactors Dranch 2 61pp 20811 292 24X Fiche 50-000, 83/09/30, 8310070264
- 8310070287 Requests that 810226 ltr re proposed Tech Spec changes concerning scram discharge sys be superseded by 830919 submittal GUCMAL T Georgia Power Co 83/10/03 STOLZ, J F Operating Reactors Branch 4 ip 20655 J62 24X Ficher 50-321,83/10/03,83100/0387
- B310140241 Provides schedule for plant outages & activities associated w/recirculation piping insp required by IE Bulletins B2-03 & B3-02, as discussed at 830928 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl NIX: H C Georgia Power Co B3/10/05 STOLZ, J F Operating Reactors Branch 4 23pp 20761 345 24X Fiche 50-321,83/10/05-B310140241
- 8310170183 Notifies that plans being developed for replacement/insp of main recirculation stainless steel piping during outage tentatively scheduled to begin Jan 1984 Summary of plans provided, Proposed outline end NIX.H C Georgia Power Co 83/10/05 STOLZ, J F Operating Reactors Branch 4 opp 20787 105, 24x Piche 50-366,83/10/05,83/10/70183

- 8310120265 Application for amend to Licenses DPR-57 & NPF-5 revising Tech Specs by transferring radiological effluent Tech Specs from App A to App B.per 781221 submittal Marked-up Tech Specs entl HEAD.G F Georgia Power Co 83/10/06 STOLZ,J F Operating Reactors Branch 4 158pp 20698 092 24X Fiche 50-321.83/10/06, 8301020265
- 8310310439 Responds to 830907 request for mod to NRC 830701 order confirming util commitments to implement certain post-TMI-related items set forth in NUREC-0737 to extend completion date for Item II H 3 to 831201 Request acceptable STOLZJ F Operating Reactors Branch 4 83/10/14 BECKHAM, J 7 Georgia Power Co 2pp 24X Fichs 30-321,83/10/14,8310310439
- --8310310440 (Inder granting extension until 831201 to complete | Item | Il B | J. "Post-Accident Sampling " Commitments on | applicable NUREG-0737 requirements from Generic Ltr 82-05 | encl EISENHUT. D G) G Division of Licensing 83/10/14 Georgia 20965-164 24X Fiche 50-321.83/10/14.8310310439. Сеогоза Рошег Spp
- 8310210270 Application for amend to Licenses DPR-57 & NPF-5 transferring radiological effluent Tech Spec from App B to App A
 App A
 OUCHA, L T
 Georgia Power Co
 B3/10/17
 BTDLZ, J F
 Operating
 Reactors Branch 4
 A
 App
 B20846
 B20846
- --8310210277 Proposed Tech Spec transforring radiological offivent Tech Spec from App B to App A * Georgia Power Co 83/10/17 128pp 20846 296 24X Fiche 50-321.83/10/17,83102102/0
- --8310210279 ETS for facilities Georgia Power Co 83/10/17 21pp 20847 063 24X Fiche 50-321,83/10/17,83102102/0
- O3i0270327 Application for amend to Liceuse NPF-5, consisting of Tech Spec change request revising applicability of limiting condition for operation of sys & instrumentation associated W/cooling & protection of fuel CAVSEY, J C Georgia Power Co B3/10/20 STOLZ, J F Operating Reactors Branch 4 2pp 20923 152 24X Fiche 50-366,83/10/20, B3/02707373 B310270327
- --8310270334 Proposed Tech Spec re cooling & protection of fuel in reactor vessel after removal of all fuel

 Ocorgia Power Co 83/10/20 26pp 20923 154 24X Fiche 50-366,83/10/20,8310270327
- B310310265 Notifies of possible problem re 10CFR50 49 equipment qualification deadline for electrical components of HPCI control sys Problems first discovered on B30825 Extension of rulemaking deadline may be requested Util awaiting data GUCWALL Y Georgia Power Co B3/10/24 STCLZ, J F Operating Reactors Branch 4 2pp 20947 123 24X Fiche 50-366,83/10/24,8304303085
- O Inspection reports: IE Bulletins & correspondence
- 0310040012 Forwards IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-17 No noncompliance noted
 DANCE H C Division of Project & Resident Programs 83/09/08
 KELLYR J Georgia Power Co Rpp 20608:113 24X
 Fiche 50-321,83/09/08,8310040012
- --8310040042 IE Insp Repts 50-321/83-24 & 50-366/83-25 on 830817-19 No noncompliance noted Major areas inspected licensee action noncompliance noted Major areas inspected licensee action on previous insp findings, followup on IE Bulletin 80-11 & review of bldg settlement data
 LENAHAN, J J Region 2, Office of Director CONLON, T E fof Engineering & Operational Programs 83/09/06 App 20 24X Fiche 50-321,83/09/08,8310040012 CONLON, TE Divis
- 8310040174 Forwards IE Enforcement Conference Repts 50-321/83-27 & 50-366/83-27 on 830810 O'REILLY, J P Region 2, Office of Director 83/09/15 KELLY, R. J. Oeorgia Power Co 1p 20608 222 24X Fiche 50-321/83/09/15, 8310040174
- --8310040178 [E Enforcement Conference Repts 50-321/83-22 & 90-366/83-27 on B30810 Major areas discussed MSIV leakaga sys.HPCI main flow valve & ATMS recirculation pump trip signal.

 DANCE.H C Division of Project & Resident Programs 83/09/12
 2pp 20608 223 24X Fiche 30-321.83/09/15.8310040174

- 8310040354 Ack receipt of 830812 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-321/83-17 & 50-364/83-17 LEHIS.R C Division of Project & Resident Programs 83/09/19 KELLY.R J Georgia Power Co ip 20625 304 24X Fiche 50-321,83/09/19,8310040334
- --8310040366 Resonds to NRC 830713 ltr re violations noted in IE Insp Repts 50-321/83-17 & 50-366/83-17 Corrective actions boxes prepared for shipment elevated on one end w/drain plug removed for 24 h to allow for liquid drainage NIX.H C Georgia Power Co 83/08/12 D'REILLY.J P Region 2. Office of Director 4pp 20625 305 24X Fichs 50-321.83/09/19, 8310040356
- ~~831004046B Forwards IE Insp Repts 30~321/83-17 & 30~366/83-17 on 830523-27 & notice of violation LEMIS.R C Division of Project & Resident Progrems 83/07/13 KELLY.R J Georgia Power Co 2pp 20625 309 24X Fiche 50~321.83/09/19.8310040356
- ---8310040479 Natice of violation from insp on 830523-27 * Region 2. Office of Director 83/07/13 ip 20 fiche 50-321,83/09/19,8310040396 20625 311 24X
- --8310040499 IE Insp Repts 50-321/83-17 & 50-346/83-17 on 830523-27 Noncompliance noted failure to dispose of radwaste per 10CFR20 301 KAHLE, J B Region 2, Office of Director BARR.K P Division of Engineering & Operational Programs 83/06/20 7pp 20625-312 24X Fiche 50-321.83/09/19,8310040356
- 8310250819 Forwards IE Training Assessment Repts 50-321/83-23 50-366/83-24 on 830802-05 Nu noncompliance noted LEWIS,R C Division of Project & Resident Programs 83/09. KELLY,R J Georgia Power Co 2pp 20901 021 24X Fiche 50-321,83/09/19.8310250517 ams 83/09/19 24X
- --B310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on B3080-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training requalification programs & onshift/real-time training & mgt training HEHL, C W, MYERS, D O, SKINNER, P H, Region 2, Office of Director B3/09/15 10pp 20701 023 24X Fiche 50-321,83/09/19,B310250519
- 8308300340 lE Info Notice 83-41, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 117pp 20754 022 R4X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp. 20777 210 24X Fiche 50-000,83/09/26.8308300342.
- B30B300345 IE Info Notice B3-63. "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl JCRDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co. of New York: Inc. 118pp 20778 001 24X Fichs 50-000.63/09/26.830B300345.
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/29 Consolidated Edison Co. of New York, Inc. 115pp. 20716-324 24X Fiche 50-000,83/09/29,8308300349,
- 8310140241 Provides schedule for plant outages & activities associated w/recirculation piping insp required by IE Bulletins 82-03 & 83-02, as discussed at 830928 meeting w/NRC Replacement of piping planned for Unit 2 Viewgraphs encl NIX.H C Georgia Power Co. 83/10/05 STOLZ.J.F Operating Reactors Branch 4, 23pp 20761 345 24X Fiche 50-321.83/10/05, 831014024)
- B310170183 Notifies that plans being developed for replacement/insp of main recirculation stainless steel piping during outage tentatively scheduled to begin Jan 1984 Summary of plans provided Proposed outline encl
 NIX.H C. Georgia Power Co B3/10/05 STOLZ.J.F Operating
 Reactors Branch 4 App 20787 105 24X Fiche 50-364, B3/10/05. 8310170183
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypers Loops Used in Westinghouse Plants " Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of N York, Inc. 74pp 20827 213 24X Fiche 50-000.83/10/07.830830037 24X Fiche 50-000,83/10/07,8308300378

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl
 JORDAN E L Division of Cmergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of Nei
 York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- B308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Byc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, B3/10/11, B30B300759
- 9309300761 IE Info Notice 93-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,93/10/11.8308300761
- 8310180364 Forwards info re util questioning of validity of notice of violation for violating 10CFR20 301 Util requested official interpretation & claimed NRC transferred regulatory authority to State of 5C LIEBERMAN, J. Regional Operations & Enforcement Division 83/10/13 OLMSYEAD, B. Regulations Division 32pp 20803 044 24X Fiche 50-321,83/10/13.8310180364
- 8310180551 Notification of 831021 meeting w/BWR licensees in Bethesda, MD to discuss future insps for intergranular stress COPTOSION cracking
 MIRAGLIA,F J Assistant Director for Safety Assessment 83/10/14
 EISENHUT,D Q Division of Licensing 5pp. 20823 358 24X
 Fiche 50-000,83/10/14.8310180551
- 8310270012 Forwards IE Safeguards Insp Repts 50-321/80-26 & 50-366/83-28 on 830926-30 No noncompliance noted DANCE.H C Division of Project & Resident Programs 03/3 KELLY,R J Georgia Power Co 2pp. 20924 331 24X Fiche 50-321,83/10/20,8310270012
- --8310270023 IE Sefeguards insp Repts 50-321/83-26 & 50-366/83-28 on B30926-30 No noncompliance noted Major areas inspected site orientation review of security plan & procedures & security organization Details withheld (ref 10CFR73 21)

 MALL.B.i., MCGUIRE, D.R. Region 2, Office of Director B3/10/20 ip 20924-333 24X Fiche 50-321.83/10/20.8310270012
- R Periodic operating reports & related correspondence
- 8310190014 Monthly operating repts for Bept 1983 W/830910 ltr CURTIB.C M , NIX.H C. Georgia Power Co 83/10/10. Birector's Office, Office of Inspection and Enforcement 14pp. 20823 284 24X Fiche 50-321,83/10/10.8310190014
- S Reportable occurrances, LERs & related correspondence
- 8310210327 Responds to FOIA request for all documents re significantly high rate of equipment failures for QE BWR/4 rated at 2,425 MM. Forwards App A documents Documents also available in FDR FELTON, J M Division of Rules and Records. 83/07/28 HAFNER, B. Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000,83/07/28,8310210329.
 - 8210180246 Submits preliminary account of events associated w/820825 reactor trip Reactor tripped from 99% power due to overpower condition on average power range monitor Caused by closure of one isolation valve on C main steam line RUBIN.8 D Reactor Operations Analysis Branch 82/09/29 SEYFRIT.K.V Reactor Operations Analysis Branch 5pp 20882 249 24% Fiche. 50-000.83/07/28.8310210329
 - 7301180513 Evaluates LERs for Jul 1981 Oct 1982 in support of upcoming SALP review LERs minimally adequate in narrative sections. Large number considered mgt deficiency-related SEYFRIT. K.V Director's Office. 83/01/12 LEWIB.R Division Project & Resident Programs 5pp. 20882 225 24% Fiche. 50-000, 83/07/28.83102:0329. Division of
 - x03031B LER 63-081/03L-0 on 830829; during performance of Procedure IP-2-0309, personnel determined HPCI turbine exhaupt aphregm pressure switch out of calibr. Caused by instrument typoint drift. Switch recalibr. W/830922 ltr PPS 8. B.: NIX:H. C. Georgia Power Co. 83/09/22, 0 'REILLY, J. P. gion 2. Office of Director. App. 20590 358 24X che 50-366, 83/09/22, 8310030318

- 8310030317 LER 83-092/03L-0 on 830831.RIR svc water pump 2A declared inoperable after motor bearing began to overheat while trying to make up water to circulating water flume (auxed by partially blocked cooling water line W/830922 ltr TIPPS, S.B., NIX,H C. Georgia Power Co. 83/09/22 O'REILLY, J.P. Region 2. Defice of Director 4pp 20590 394 24X Fiche 50-366,83/09/22,8310030319
- 8310030334 LER 83-057/03L-0 on 830824.while pulling control rods during normal reactor startup.rod block monitor A gave rod out block when certain control rods selected Caused by component TipPS.5 B . NIX.H C Georgia Power Co 83/09/22 Region 2. Office of Director 4pp 20590 207 2/ Fiche 30-366.83/09/22,8310030305 2 O'REILLY.JP
- 8310030359 Updated LER 80-106/03X-1 on 800728, w/reactor in cold shutdown, insp of drgwell insulation revealed crystalline deposits around smams on sacrificial shield Cause unknown Investigation inconclusive W/830922 ltm
 TIPPS, S B. NIX.H C Georgia Power Co 83/09/22 O'REILLY, Region 2. Office of Director 4pp 20592 134 24X
 Fiche 50-366,83/09/22.8310030359
- 8310030392 Updated LER 82-088/03X-1 on 820806.control rod reed switch position indicator found inoperable Caused by failed rod position indication sys probe Probe replaced W/830922 ltr TIPPS.8 B , NIX.H C Georgia Power Co 83/09/22 D'REILLY, J P Region 2, Office of Director 4pp 20592 172 24X Fiche 50-366,83/09/22,8310030382
- 8310030415 Updated LER 83-071/03X-1 on 830808.control rod drive low pressure alarm received for HCU 2011-22-19 Accumulator pressure found low Caused by leaking EP-111 nitrogen charging valve Valve replaced W/830922 tr
 TIPPS.S B. NIX.H C Georgia Power Co 83/09/22 0'REILLY, J P. Region 2. Office of Director 5pp 20593 168 24X
 Fiche 50-366.83/09/22.8310030415
- 8310030433 LER B3-093/03L-0 on B30901, remote reactor pressure indicator 2CB2-R006 failed to indicate within 40 psig of control reactor pressure indicator 2B21-R004A & declared inoperable Caused by setpoint drift indicator calibr W/B30922 ltr TIPPB.5 B, NIX.H C Georgia Power Co B3/09/22 O'REILLY, J P Region 2, Office of Director 4pp 20602 099 24X Fiche 50-366.83/09/22,8310030433
- 8310030442 LER B3-095/03L-0 on B30902, control rod drive hydraulic control unit 2C11-34-03 declared inoperable upon discovery of low accumulator pressure while investigating alarm Accumulator recharged & alarm cleared W/830922 ltr TIPPS S B , NIX.H C Georgia Power Co B3/09/22 O'REILLY, J P Region 2, Office of Director 4pp 20402 065 24X Fiche 50-366,83/09/22,8310030442 5 O.UEILLA'1 b fr
- 8310030486 LER 83-060/03L-0 on 830823. RHR loop B min flow valve 2ELI-F0078 found to have no position indication Caused by blown fuse in control circuit of valve, due to loose fuse holder Holder tightened & fuse replaced W/830722 ltr TIPPS S B , NIX H C Georgia Power Co 83/09/22 O'REJLLY, J P Region 2. Office of Director 4pp 20401 079 24X Fiche 50-366, 83/09/22, 8310030486.
- B316030510 LER B3-079/03L-0 on B30B30, during performance of HPCI pump oper-bility procedure, HPCI bearing temp recorder indicated higher temp than allowed Caused by broken wire on HPCI outboard bearing temp element. Wire repaired W/B30922 ltr TIPPS.S B. NIX.H C Georgia Power Co B3/09/22 D'REILLY, J P Region 2. Office of Director App 20601 178 24X Fiche 50-366,83/09/22,8310030510.
- B310040409 LER B3-052/03L-0 on B30B31, drywell particulate fission products monitor 2Dil-K631 declared inoperable when counts per minute continually increased Caused by filter paper drive motor failure Motor replaced W/830927 ltr TIPPS, B B, NIX,H C Georgia Power Co B3/09/27 O'REILLY, J F Region 2, Office of Director 4pp 20619 08B 24X Fiche 50-366,83/09/27,8310040409 O'RETILLY, J.P.
- 8310060011 LER 83-094/03L-0 on B30901.during performance of Procedule MNP-R-3882.hydrogen/exygen analyzer A (2P33-P001A) found out of calibr Caused by setpoint drift Analyzer recalibr W/830927 ltr.
 TIPP8.5 B, NIX.H C Georgia Power Co 83/09/27 G'REILLY, J P Region 2. Office of Director. 4pp 20649 295 24X Fiche 50-366,83/09/27,8310060011
- 8310120408 Revised LER 83-045/03X-1 on 830816, during diesel generator manual start procedure, diesel generator 2R43-8001A failed to start per Tech Specs Caused by bent engine governor shutdown solenoid & plunger, Bent parts replaced W/830930 ltr TIPPS, S.B., NIX.H.C. Georgia Power Co. 83/09/30 G'REILLY, J.P. Region 2. Office of Director. 4pp. 20699 033 24X Fiche 50-366, 83/09/30.8310120408

- B310178509 LER 83-096/030-0 on 830906, plant personnel determined valve 2832-F001P would not open when key lock control switch placed in test position Caused by burned up motor Motor replaced M/831005 ltr
 ICPPS, S D . NEX.H C Georgia Power Co 83/10/05 D'REILLY, J P
 Region 2. Office of Director 4pp 20784 113 24X
 Fiche 50-346,83/10/05,8310170509
- 8310170531 LER 83-097/03L-0 on 830913, plant personnel determined link CC-30 in panel 2Hii-P627 open Cause unknown Standing order issued to prevent recurrence M/831006 ltr TIPPS, 9 B. NIX.H C. Georgia Power Co. 83/10/06 D'REILLY, J.P. Region 2. Office of Director 4pp. 20784 199 24X
 Fiche 50-366.83/10/06.8310170531
- 8310170584 Updated LER 82-068/03X-1 on 820707 & 24, volumetric weighted average drywell air temp exceeded Tach Spec limit of 135 F Caused by high ambient temp & failure of alternate chiller fams 88 & 78 New chilling units installed W/831006 itr TIPPS, S B. NIX:H C Georgia Power Co 83/10/26 O'REILLY, J P Region 2. Office of Director 4pp 20/80 233 24X Fiche 50-366.83/10/06.8310170584
- 8310250343 LER 83-086/03L-0 on 830919, during performances of Procedure MxP-2-3101, reactor vessel water low-low level instruments 2821-NX359, Switch 2 & 2821-NX259, Switch 2 in the switch 1, failed to actuate 9 caperly Caused by setpaint drift W/831014 ltr TIPPS, 8 B , NIX, H C Georgia Power Co 83/10/14 D'REILLY, J P Region 2, Office of Director 4pp 20898 071 24X Fiche 50-366,83/10/14,8310250343
- 8310250212 LER 83-100/03L-0 on 830926, during control panel walkdown, discovered that reactor vessel water level reorder not recording properly Caused by failed chart drive gear Recorder separed W/831017 ltr ITPFS.8 B. NIX.II C Georgia Power Co 83/10/17 O'REILLY.J P Region 2. Office of Director 4pp 20093 319 24X Fiche 50-366.83/10/17,8310280212
- 8310250285 LER 83-099/03L-0 on 830925, while performing Procedure Http-2-3882, hydrogen analyzer A would not calibr Analyzer panel & drywell & torus recorder declared inoperable Caused by worn sample pump diaphragms W/831017 ltr TIFFS.5 B . NIX.H C Georgia Power Co G3/10/17 D'REJLLY, J P Region 2, Office of Director App 20896 001 24X Fiche 50-366.83/10/17,8310250285
- B310250291 LER B3-082/O3L-O on B30922, operations personnel determined RCIC percent demand indication off Un B30925, RCIC failed to reach rated flow & pressure Caused by setpoint drift High current limiter adjusted W/B31017 ltr TIPPE,S B , NIX.H C Georgia Power Co B3/10/17 D'REILLY, J P. Region 2. Office of Director 4pp 20895 343 24X Fiche 50-366,83/10/17,8310250291
- B31025031; LER B3-088/03L-0 on B30922, during control locked valve Procedure HNP-514, noninterruptable instrument air supply valves 2/52 F459 t F460 found unlocked Caused by personnel error Valves locked in position W/B31017 ltr TIPPS, S B , NIX, H C Georgia Power Co B3/10/17 D'REJLLY, J P Region 2. Office of Director 4pp 20094 360 24X Ficha 50-366,83/10/17,8310250311
- 8310250312 LER 83-061/03L-0 on 830921, during RGIC turbine exhaust diaphragm pressure instrument Procedure HNP-2-3414, connection line inadvertently broke off RGIC turbine D eshaust diaphragm pressure switch W/831017 tr TIPP8.8 B . RIX.H C Georgia Power Co 83/10/17 O'REILLY, J P Region 2, Office of Director 4pp 20898 020 24X Fache-50-366,83/10/17.8310250312
- B310250506 LER B3-098/03L-0 on B30924, 2C11-02-27 & 2C11-14-27 accumulators declared inoperable following control rod low pressure or high level alarm Gaused by leaking nitrogen charge valve Valve replaced W/B31017 ltr TIPPB.S B . NIX.H C Georgia Power Co B3/10/17 O'REILLY.J P Region 2. Office of Director 5pp 20902, 073. 24X Fiche 50-366,83/10/17,8310250506
- B310250061 RD on B31018 drywell equipment drain sump pump 2011-00068 became inoperable w/redundant pump also inoperable Cause not stated Increase of 19 gpm unidentified leakage into sump drain requested for 30-day period NIX-H C Georgia Fower Co. B3/10/19 BTDLZ, J F Operating Reactors Branch 4 2pp 20876 072 24X Fiche, 50-366, 83/10/19, 8310250061
- 3310310236 LER 83-101/03L-0: on 830927; reactor bldg exhaust vent radiation monitor D 2D11-K609D indicated decreased semsitivity of GM tube W/831090 ltr T1PP8,8 D; NIX,H G Georgia Power Co 83/10/20 D'REILLY,J P Region 2, Office of Director 4pp 20947 203 24X Ficha 50-366,83/10/20,8310310236

- 8310310259 LER 83-059/03L-0 on 830928, during scram recovery procedure, primary containment isolation valve for traversing in-tore probe B would not close Gaused by failed ball valve Ball valve replaced, tested & returned to svc W/B31020 ltr TIPPS, 5 B, NIX.8 C Georgia Power Co 83/10/20 O'REILLY, J P Region 2. Office of Director 4pp 20947 163 24X Fiche 50-366,83/10/20,8310310259
- 8310310280 LER 83-106/03L-0 on 831001.after personnel backfilled torus water level transmitters 2748-NO21A & B. water level transmitters 2748-NO21A & B. water level determined to be balow Tech Spec requirement Caused by normal evaporation Ref legs backfilled MR831020 ltr TIPPS 8 B. NIX.H C Georgia Power Co 83/10/20 0'REILLY, J P Region 2. Defice of Director 4pp 20961 286 24X Fiche 50-366.83/10/20.8310310280
- 8310310363 LER 83-083/03L-0 on 830928, both recirculation sumps tripped Caused by packing binding inside reactor level instrument 2821-N0318 low pressure side manifold isolation valve Valve operated open-to-close then close-to-open W/831020 ltr TIPPS S B . NIX.H C Georgia Power Co 83/10/20 O'REILLY, J P Region 2. Office of Director 4pp 20961 117 24X Fiche 50-366,83/10/20,8310310363

V Operator Examinations

- 6310250519 Forwards IE Training Assessment Repts 50-321/83-23 & 50-364/83-24 on 830802-05 No noncompliance noted LEWIG.R C Division of Project & Resident Programs 63/09/19 KELLY.R J Georgia Power Co 2pp 20901 Q21 24X Fiche 50-321,63/09/19,8310250517
- --8310250560 IE Training Assessments Repts 50-321/83-23 & 50-366/83-24 on 83080-05 No noncompliance noted Major areas inspected licensed & nonlicensed operator training, requalification programs & onshift/real-time training & mgt training HEML,C W. WATSON,L J. Region 2: Office of Director PANCICRA, V.W. Division of Project & Resident Programs 83/09/15.

DOCKET 50-367 BAILLY GENERATING STATION O Adjudicatory correspondence

83:01:0278 Requests status rept on author fre patition
HHICHER, J M Dusinessmen for the Public Interest HHICHER, J M
Hhicher, J M 82/10/05 PLAINE, H E Office of the General Counsel.
2pp 20465 327 24X Fiche 50-367, 89/10/05,83:01:0278

DOCKET 50-368 ARKANSAS NUCLEAR DNE, UNIT 2 F Security, medical, emergency & fire protection plans

- 8310060520 Forwards clarification of NRC positions on certain requirements of App R to 10CFR50 48 STOLZ, J. F. MILLER, J. R. Operating Reactors Branch 4 83/09/14, 0RIFFIN, J. M. Arkansas Power & Light Co. Bpp. 20663, 139. 24X Fiche 50-313,83/09/14,8310060520
- 8310030416 Submits addl info re mods to Fire Zones 2100-Z & 2101-AA, per 830713 request for App R schedular exemption. Delivery of pump switchgear expected in late Jan 1984 MARSHALL, J R Arkansas Power & Light Co 83/09/27. 8TOLZ. J, F Operating Reactors Branch 4. MILLER, J. R Operating Reactors Branch 3 2pp 20593 166. 24X Fiche 50-313.83/09/27,8310030416
- 8310040243 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records, 83/09/30 Document Hanagement Branch. ip 20400-276 24X Fiche 50-313,83/09/30, 8310040243
- --8310060250 Public version of Rev 4 to Emergency Plan Implementing Procedure 1903, 01. "Organization & Use of Emergency Plan Implementing Procedures" & Rev 10 to Procedure 1903 10. "Emergency Action Level Response"
 LEVINE, J M Arkansas Power & Light Co 83/09/19, 32pp. 20660,277, 24X Fiche 50-313,83/09/30,8310060243.
- #310060597 Releases public vertion of revised emergency plan FELTON, J M Division of Rules and Records. 83/10/05, Document Management Branch. ip. 20661.092. 24X Fiche 50-313,83/10/05, 8310060597.
- --8310060601 Public version of Rev B to emergency plan W/830922 ltr. MARSHALL, J. R. Arkenses Power & Light Co. 83/09/14 CDLLING.J. T Region 4, Office of Director. 55pp 20661:093 24X Fichs 30-313.83/10/05,6310060597.

- B310250599 Withdraws request for schedular exemption until 90050; to complete installation of certain the rated fire barriers Mods completed by B30422 MARCHALLJR Arkansas Power & Light Co 83/10/07 STGLZ.JF Operating Reactors Branch 4 MILLER.JR Operating Reactors Branch 3 ip 20700 346 24% Fiche 50-313.83/10/07.8310250559
- B310140076 Forwards corrected Attachments 24 1 & 27 1 to IAEA design info questionnaire for safeguards program submitted in B30822 ltr MARSHALL J R Arkansas Power & Light Co B3/10/10 EISENHUT, D C
- MARSHALL.J R Arkansas Power & Light Co 83/10/10 EISENHUT.D C Division of Lirensing 2pp 20766 096 24X Fiche 50-368.63/10/10. 8310140096
- 8310190291 Releases public version of amend to emergency plan FELTON.J M Division of Rules and Records 83/10/14 Document Management Branch 1p 20840 143 24% Fiche 50-313.83/10/14, 8310190291
- --B310190292 Public version of Amond B to emergency plan # Arkansas Power & Light Co 83/9/14 60pp 20840 144 24X Fiche 50-313,83710/14,8310190291
- 8310190294 Releases public version of revised emergency plan implementing procedure FELTON.7 M Division of Rules and Records 83/10/14 Document Management Branch 1p 20841 341 24X Fiche 50-313/83/10/14, 9210180924
- ~-8310190275 Public version of Rev 11 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response" W/8/31002 ltr & receipt form LEVINE, J M. Arkansas Power & Light Co. 83/10/01 70pp 20841 342 24X Fiche 50-313,83/10/14.8310190274
- 8310250274 Updates present status & describes tasks performed over previous & months per requirements of Generic Ltr 82-33 & Suppl 1 to NUREG-0737 re control room design review Figure 2-2 encl MARSHALL.J R Artansas Power & Light Co 93/10/20 FISENHUT.D G Division of Licensing 4pp 20702 340 24X Fiche 50-313,83/10/20,8310250274

J Insurance & indemnity information

- 8310240035 Forwards Endorsements 53.84 & 55 to NELIA Policy NF-PIO & Endorsements 46 & 47 to MAELU Policy MF-74 MAREHALLJR Artaneas Power & Light Co 83/10/12 DINITZ, I Assistant Director for Beath & Licensee Relations 6pp 20881 353 24X Fiche 50-313,83/10/12,8310240035
- P Operating license stage documents & correspondence
- 8310060402 Forwards NPDES Fermit AROOOLD92.effective 830606 860705, per NRC 830311 ltr & util 830520 confirmation.
 MARSHALLJR Arkanses Power & Light Co 83/06/10 COLLINB, J T Region 4. Office of Director 3pp 20641 229 24X
 Fiche 50-313,83/06/10,8310060402
- --83100&0406 NPDES Permit ARODO1392, issued to Arkansas Power & Light Co KNUDBON, M D Environmental Protection Agency 83/05/04 28pp 20441.232 24X Fiche 50-313,83/06/10,83100&0402
- 8310030337 Application to amend License NPF-6, changing Tech Spec 4 6 4,1 b & Table 3 3-9 re hydrogen analyzer calibr & remote shutdown panel instrumentation, respectively ORIFFIN-J M Arkansas Power & Light Co 83/09/27 MILLER, J R Operating Reactors Branch 3 4pp 20540 211 24x Fiche 50-368,83/09/27,8310030337
- --B310030340 Proposed Tech Spec 4 6 4 1 b & Table 3 3-9 re hydrogen analyzer calibr & remote shutdown panel instrumentation, respectively a Arkansas Power & Light Co B3/09/27 4pp 20590 215 24X Fiche.50-368.B3/09/27,8310030337
- 8310030332 Updates 830520 request for extension of deadline for environ qualification of equipment Status of specific items enumerated. HARSHALL.J.R. Arkansas Power & Light Co. 83/09/28 870LZ.J.F. Operating Reactors Branch 4 MILLER.J.R. Operating Reactors Branch 3 4pp 20992 311 24X Fiche 50-313,83/09/28.8310030338
- 83i0i10618 Bummary of 830823 meeting w/util in Bethesda,MD re Tech Byers for mechanical & hydraulic snubbers Agenda & marked-up Tech Specs ancl VISSING.0 S Operating Reactors Branch 4 83/09/30 Operating Reactors Branch 4 13pp 20715.160 24X Fichs.50-313.83/09/30.

- 8310120079 Forwards updated radiological effluent Tech Specs & offsite dose calculation manual.per 830510 request Implementation date of 850101 established ORIFFIN.J M. Arkansas Power & Light Co. B300930 STOL7.JF Operating Reactors Branch 4. MILLER.J R. Dperating Reactors Branch 3. 3pp. 20696 241 24X Fiche 50-313.83/09/30.8310120079
- --83101200B1 Revs to radiological effluent Tech Specs

 * Arkanses Power & Light Co 83/09/30 116pp 20696 244 24x
 Fiche 50-313,83/09/30,83101200/9
- --83101200B3 Revs to offsite dose calculation manual * Arkansas Power & Light Co 83/09/30 99pp 20696 360 24x Fiche 50-313,83/09/30,8310120079
- B3i0130097 Forwards nonproprietary & proprietary responses to 830802 telcon request for addl info re proposed Tech Spec change concerning in-core detectors Affidavit encl Proprietary rept withheld (ref 10CFR2 790)
 GRIFFIN.J M Arkansas Power & Light Cn B3/09/30 MILLER.J R Operating Reactors Branch 3 10pp 20725 277 24X fiche 50-368.83/09/30.8310130097
- --8310130109 Nonproprietary "Responses to NRC Guestions re Ariansas Nuclear Unit 2 Cycle 3 Tech Spec Change " Proprietary info deleted (ref 10CFR2 790) a Combustion Engineering, Inc. CEN-255(A)-NP 83/08/31 5pp. 20725 287 24X Fiche 50-368,83/09/30,8310130097
- 8310210080 Requests remittance of fee due for 830215 application red deletion of terrestrial monitoring programs within 13 days MILLER.W O License Fee Management Branch 83/19/17 GRIFFIN, J M Arkansas Power & Light Co 1p 20883 251 24X Fiche 50-313,83/10/17.8310210080
- 8310250281 Advises of delay in providing add1 info re NUREG-0737,
 Item II B 3 concerning post-accident sampling sys.per 830714
 request, due to outage beginning ahead of schedule Info
 expected by 831025
 MARSHALL, J R Arkansas Power & Light Co 83/10/17 STOLZ, J F
 Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch
 3 1p. 2088 362 24X Fische 70-368.83/10/17,8310250281
- 8310250533 Advises of correction of CPC software discrepancy.per 83t011 telcon Mod will be performed prior to initial reactor criticality for Cycle 5 & will not be contingent on schedule for other software changes

 MARSHALLJR Arkansas Power & Light Co 83/10/18 MILLER.JR

 Operating Reactors Branch 3 ip 20902 142 24X

 Fiche 50-368.83/10/18.8310250533
- Q Inspection reports, IE Bulletins & correspondence
- 8310060020 Forwards IE Insp Repts 50-313/83-13 & 50-368/83-13 on 830606-10 No noncompliance noted SEIDLE.W C Region A. Office of Director 83/08/01 GRIFFIN.J M Arkansas Power & Light Co 2pp 20447 156 24X Fiche 50-313.83/08/01.8310060020
- ---8310060026 IE Insp Repts 50-313/83-13 & 50-368/83-13 on 830606-10 N. noncompliance noted Major areas inspected action on previous violations consite radiation protection organization staff qualifications & training exposure control & ALARA program CHANEY.H D , HOLLEY,W L , MURRAY,B Region 4, Office of Director 83/07/20 19pp 20647 158 24X Fiche 50-313,83/08/01.8310050020
- 8310250153 Provides status of work accomplished in response to If Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts," & IC Bulletin 79-14 "Seismic Analyses for As-Built Safety Related Piping Sys "MARSHALL. JR Arkansas Power & Light Co 83/08/05 COLLINS.JT Region 4. Office of Director 1p 20496 343 24X Fiche 50-313.83/08/05.8310250153
- 8310130220 Forwards IE Insp Repts 50-313/83-15 \$ 50-348/83-15 on 830701-31 No noncompliance noted SEIDLE.W C Region 4, Office of Director 83/08/10 981FFIM.J M Arkansas Power & Light Co 2pp 20/24 105 24% Fichs 50-313,83/08/10,8310130220
- --8310130226 IE Insp Repts 50-313/83-15 & 50-368/83-15 on 830/01-31 No noncompliance noted Major areas inspected operational safety verification, surveillance, maint & followup on previously identified items

 CALLAN, L J . CUMMINS, J E . JOHNSON, W D Region 4, Office of Director 83/08/05 12pp 20724 107 24X Fiche 50-313,83/08/10.8310130220

- 8310130330 Forwards IE Insp Repts 50-313/83-21 & 50-368/83-21 on 830801-31 & notice of violation SEIDLE.W C Region 4. Office of Director 83/09/16 GRIFFIN.J M Arkansas Power & Light Co 2pp 20/19 343 24X Fiche 50-313,83/09/16,8310130330
- --83101303J3 Notice of violation from insp on 830801-31 * Region 4, Office of Director 83/09/16 4pp 20719 345 24x Fiche 50-313.83/09/16.8310130330
- --B310130335 IE Insp Repts 50-313/83-21 & 50-368/83-21 on B30801-01 Noncompliance noted failure to properly identify calculation & design change, to perform maint activities w/uritten procedure & to install electrical cables per procedures CALLAN. L J . CUMMINS. J E . JOHNSON, W D . Region 4. Office of Director B3/09/15 lipp 20719 349 24X Fiche 50-313.83/09/16, B310130330
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Syc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 9308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000, 83/09/26, 8308300342
- 6306300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830107) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,83083003045
- 830B30D349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 830B300378 IE Info Notice 83-65, "Survei)lance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JOBDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fishe 50-000,83/10/07.8308300378
- 9308300752 IE Info Notice 83-46, "Fatality at Argentine Critical Facility" Svc list encl JURDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 1178p 21043 075 24% Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc 1:st eacl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- R Periodic operating reports & related correspondence
- 8310190045 Monthly operating rept for Aug 1983 W/830915 ltm BRAMLETT.L S , MARSHALL, J R Arkanses Power & Light Co 83/09/15 BASSETT.H S Division of Data Automation & Management Information 7pp 20823 224 24X Fiche 50-368
- S Reportable occurrences, LERs & related correspondence
- 8310040338 LER 83-038/03L-0 on 830818.core protection calculator Channel A placed in bypass & Channel D tripped Caused by point identification Number 064 for channels reading less than min M/830919 ltr ROGERS.P. HARSHALL.J R Arkansas Power & Light Co 83/09/19 SEEDLE.W C Region 4. Office of Director 3pp 20617 275 24 Fiche 50-368.63/09/19.8310040338

- 9310040149 LER 83-040/03L-0 on 830831, control element assembly 47 dropped to lower electrical limit Caused by blown fuse Opened fuse replaced, current traces taken & tightness of connections checked W/830920 Itr
 ROGERS.P., MARSHALL.J R Arkansas Power & Light Co. 89/09/20 SEIDLE.W C Region 4. Office of Director 2pp 20608 026 24% Fiche 50-368,83/09/20.8310040149
- 8310040206 Corrected LER 83-033/03X-1 on 830828 during full power. Fire Door 274 to cable spreading room had gap of greater than 3/4 inch at bottum Caused by improper installation guidance New threshold plate installed W/830922 ltr ROGERS.P. MARSHALL.J.R. Arkansas Power & Light Co. 83/09/22 SEIDLE.W.C. Region 4. Office of Director 2pp 20614 324 24X Fiche 50-368,83/09/22,8310040206
- 8310030476 PND-IV-83-029 on 830926, unit shut down due to inability to comply w/Tech Spec action statement following discovery that station battery 2011 failed quanterly surveillance test on 830922 Condition not recognized by mgt until 830926. JOHNSON, W D , CALLAN, L J Region 4, Office of Director 83/09/27, ip 20601 066 24% Fiche 50-368, 83/09/27, 8310030476
- B310130180 LER 83-044/01T-0 on 830922, battery 2D11 failed survei]lance Roactor shut down Corrective actions on physical battery impairment & administrative failure under evaluation W/B30927 ltr LEVINE, J M Arkansas Power & Light Co B3/09/27 COLLINS, J Region 4, Dffise of Director ip 20724 325 24X Fiche 50-368,83/09/27,8310130180
- 8310130283 LER 83-043/03L-0 on 8309D7, contract person posted for fire watch duty discovered asleep Individual awakened & relieved Disciplinary actions taken Fire watch policy expanded W/830930 ltr ROGERS.P., MARSHALL.J.R. Arkansas Power & Light Co. 83/09/20 SEIDLE.W.C. Region 4. Office of Director 3pp 20723 144 24; Fiche 50-348,83/09/30.8310130283
- 8310180489 Updated LER 82-007/03X-2 on 820216, leak discovered in weld for drain line of suction bladder of charging pump 2P-36C Caused by vibration-induced cracking Check of pulse inflation added to preventative maint cycle W/830930 ltr ROGERS,P. MARSHALL,J R. Arkaness Power & Light Co. B3/09/30 SEIDLE,W C. Region 4, Office of Director. 3pp. 20800 155 24X Fiche 50-36B, B3/09/30, 8310180489
- 83i0180457 LER 83-04i/03L-0 on 830831, core protection channel D point identification 008 read conservatively high Cause undetermine Evaluation will be performed to determine cause & corrective action W/83i003 ltr ROGERS,P, MARSHALL,J R Artansas Power & Light Co 83/10/03 SEIDLE,W C Region 4. Office of Director 3pp 20801 344 24% Fiche 50-368.83/10/03,8310180457
- 8310180527 Updated LER 83-008/03X-1 on 830207, during walkdown, fire barrier deficiencies discovered On 831006, inadequate fire barrier penetration seals identified Gaused by inadequate work controls fire watch posted W/831006 ltm ROGERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 83/10/06 SEIDLE, W.C. Region 4, Office of Director 4pp. 20801 181 24X Fiche 50-368, 83/10/06, 8310180527
- B310180187 LER 83-044/01T-0 on B30726, battery 2D11 failed quarterly surveillance test Caused by normal aging coupled w/ insufficient equalizing charges Surveillance procedure limits will be treated as Tech Bpec limits 4/831010 ltr. MDEGGENBERG D. MARSHALL JR Arkansas Power & Light Co B3/10/10 SEIDLE W C Region 4. Office of Director 3pp 20808 349 24X Fiche 50-368,83/10/10,8310180189
- 8310310368 LER 83-042/03L-0 on 830913 & 15, junction box for conduits in Fire Zone 2150 discovered open & gap between floor & Fire Doors 340 & 267 exceeded acceptance criteria Caused by exclusion of zones from installation specs W/831012 ltm. ROGERS.F. MARSHALL.J R Arkenses Power & Light Co 83/10/12 GAGLIARDO.J E Region 4. Office of Director 3pp 20959 180. 24X Fiche 50-348,83/10/12,8310310368
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8310040511 Summarizes 830916 mpt meeting in Atlanta.QA re security barrier problems at facility O'REILLY.JP Region 2. Office of Director 83/09/21 TUCKER,H B Duke Power Co ip 20623 096 24X Fiche 50-369.83/09/21.
- 8310060265 Releases public version of revised station directive FELTON.J M Division of Rules and Records. 83/09/30 Document Management Brench 1p 20660 226 24X Fiche. 50-369, 83/09/30, 8310060265

- --B310060268 Public version of Rev 5 to Station Directive 3 8 2,
 "Technical Support Ctr " W/830706 ltr
 MCINTOSM.H D. TUCKER.H B. Duke Power Co. 83/06/24 BENTON.H R.
 Office of Nuclear Reactor Regulation, Director ADENSAM.E G.
 Licensing Branch 4 6pp. 20660 227 24X Fiche 50-369,83/09/30.
 8310060265
- B310070134 Releases public version of revised crists mgt plan implementing procedures
 FELTON J M Division of Rules and Records 83/10/04 Document Ranagement Branch ip 20670 001 24X Fiche 50~000.83/10/04.
 8310070134
- --8310070143 Forwards public version of revised crisis mpt plan implementing procedures, including Procedures 5 3 1 rerecovery manager & Immediate staff group plan & 5 3 4 rescheduling/planning support group
 TUCKER, H B Buke Power Co 83/07/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24%
 Fiche 50-000, 83/10/04, 8310070134
- --B3100701b2 Public version of revised crisis mgt plan implementing procedures including Procedure 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group to B3/07/01 457pp 20670 005 24% Fiche 50-000, 83/10/04, 8310070134
- 83101104k3 Ralewses public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Hanagement Branch ip 20714 001 24% Fiche 50-369,83/10/05,8310110413
- --8310110418 Forwards public version of revised Emergency flan
 Implementing Procedure GP/1/A/4200/48 re operation of
 post-accident liquid sample sys & Station Directive
 2 0 5 re news releases
 TUCKER.H B Duke Power Co 83/06/14 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ABENSAM, E G Licensing
 Branch 4 1p. 20714 002 24X Fishe 50-369, 83/10/05, 8310110413
- --B310110421 Public version of revised Emergency Plan Implementing Procedure OP/I/A/6200/48 re operation of post-accident liquid sample sys & Station Directive 2 0 5 re news releases MCCONNELL, I L. BEAVER, B. Duke Power Co. 83/05/16 21pp 20714 003 24X Fiche 50-369,83/10/05.8310110413
- R310110072 Releases public version of revised emergency plan implementing procedures RELTON, J. M. Division of Rules and Records B3/10/07 Document lanagement Branch ip 20709 084 24X Fichs, 50-369, 83/10/07, 10110072
 - 10110077 Forwards public version of revised emergency plan implementing procedures, including Procedures HP/D/B/1009/02 re alternate method for determining dose rate within reactor bldg & PT/D/A/4600/06 re exercises & drills.
 TUCKER, M B. Duke Power C B3/0B/30 DENTEN, H R Defice of Nuclear Reactor Regulation, Director ADENIAN, E G. Licensing Branch 4, 2pp. 20709 087 24X Fichs 50-349,83/10/07,8310110072
- 8310110079 Public version of revised emergency plan implementing procedures, including Procedures HP/O/8/1009/02 re alternate method for determining dose rate within reactor blog k PT/O/A/4600/06 re exercises k drills OLOVER M 8., MCCONNELL, T L. Duke Power Co. 83/08/05 71pp 20709.089 24X Fichs 50-369,83/10/07,83/0110072
- *OIBO444 Responds to request for crisis mgt ctr staff to participate amergency exercises at same frequency as technical port ctr staff Crisis mgt team will be activated in lescale exercise involving full state participation (ER, H. B. Dube Power Co B3/10/10, DENTON, MR Diffice of lear Reactor Regulation, Director 2pp 20802 121 24X to 50-000, B3/10/10, B310180444
 - 'OAIG Forwards Rev 5 to security training & qualification plan withheld (ref 10CFR73 21) Plans will be updated to lude thanges KER, H B. Duke Power Co. 83/10/10. O'REILLY, J.P. Region 2, ice of Director ip 20789 303 24X Fiche: 50-369, 83/10/10, 0310416
 - 50635 Informs that periodic evaluation of SALP complete Hept royed. EILLY,J.P. Region 2, Office of Director. 83/10/17 TUCKER, H B e Power Co. 3pp. 20900.205 24X Fiche 50-000,83/10/17, 2080435

- 8310270026 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/20 Document Management Branch ip 20942 018 24X Fiche 50-369,83/10/20, 8310270026
- --8310270136 Forwards public version of revised station directives & Change 2 to Emergency Plan Implementing Procedure OP/1/A/6200/48 re post-accident liquid sample sys TUCKER, H B Buke Power Co 83/10/06 DENTON H R Office of Nuclear Reactor Regulation, Director ADENSAM, C G Licensing Branch 4 1p 20942 019 24% Fishe 50-369, 83/10/20, 83102/00%
- --B310270146 Public version of revised station directives & Change 2 to Emergency Plan Implementing Procedure OP/1/A/6200/48 rc post-accident liquid sample sys HCGINKELL, I L. SEAVER. B Duke Power Co B3/07/29 37pp 20742 020 P4X Fiche 50-369.83/10/20.8310270026
- J Insurance & indemnity information
- 8310210312 Forwards Endorsement 28 to NELIA Policy NF-240 & Endorsement 23 to MAELU Policy MF-101
 LAMBON, L T Buke Power Co 83/10/17 SALT/MAN, J NRG No
 Detailed Affiliation Given 2pp 20851 0/6 24X
 Fiche 50-369,83/10/17,8310210312
- P Operating license stage documents & correspondence
- B3i004036B forwards progrietary "McQuire Post-Mod Steam Cenerator Tube Vibration Monitoring Program," preliminary rept, summarizing results of May-June 1983 steam generator tests Rept withheld (ref 10CFM2 790)
 TUCKER, H B Duke Power Co B3/0B/02 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAME C Licensing Branch 4 2pp 20620 333 24X Fiche 50-364, 83/08/02, 8310040368
- 8310040474 Application to amend Licenses NPF-9 & NPF-17, changing lech Specs to increase upper limit for containment lower compartment to 125 F for up to 70 cumulative days provided lower compartment temp less than 120 F TUCKER, H B Duke Power Co 83/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM E G Licensing Branch 4 3pp 20622 308 24X Fiche 50-369, 83/09/22, 83/00404/4
- ---B3100404B2 Proposed Tech Specs increasing upper limit for containment lower compartment to 125 F for up to 90 cumulative days per calendar yr provided lower compartment temp overaged over previous 365 days less than 120 F

 B Duke Power Co B3/09/22 3pp 20622 311 P4X
 Fiche 50-367, B3/09/22, B3100404/4
- B310030604 Forwards BER re response to Generic Ltr B1-2), "Natural Girculation Cooldown." Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cooldown NGVAK, TM Assistant Director for Licensing B3/09/23 PARRIS, H G Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000, 83/09/23, 8310030604
- --8310030607 SER accepting Bil201 response to Generic Ltr B1-21, "Natural Circulation Cooldown" # NRC - Na Detailed Affiliation Given 83/09/23 8pp 20607 290 24% Fiche 50-000,83/09/23,8310030604
- B310050076 Concurs w/dissolution of Model D2/D3 Steam Generator Utal Design Review Panel Panel work complets NOVAK, T M. Assistant Director for Licensing B3/09/P3 BLACKLEY, B K. Design Review Panel 5pp 20650 165 24X Fiche 50-000, 83/09/23, 8310050076
- 8310190199 Forwards safety evaluation on util response to Generic Ltr 81-21 "Natural Circulation Cooldown" Upon acceptable implementation of emergency response guidelines, procedures adequate for safe natural circulation cooldown NOVAK, T M Assistant Director for Licensing 83/09/30 TUCKER, H D Dute Power Co 2pp 20838 098 24% Fiche 50-000, 83/09/30, 8310190197
- ---B310190208 SER re response to Generic Ltr 81-21 "Natural Circulation Caoldown " Response acceptable, * NRC - No Detailed Affiliation Given B3/09/30 8pp 20838-100 24X Fiche 50-000,83/09/30,8310190199

- 8310170710 Forwards Amends 24 & 25 to Licenses NPF-9 & NPF-17, respectively & safety evaluation Amends authorize maintaining hot standby conditions w/o preceding to cold shutdown for Unit 1 ADENSAN.E 0 Licensing Branch 4 83/10/06 TUCKER.H 8 Duke Powel Co 2pp 20798 134 24X Fiche 50-369,83/10/06,8310170710
- --8310170719 Amends 24 & 5 to Licenses NPF-9 & NPF-17, respectively, authorizing maintaining hot standby conditions w/o proceeding to cold shutdown for Unit 1 ADENSAM, E G Licensing Branch 4 83/10/06 7pp 20798 136 24X Fiche 50-369,83/10/06,83101/0710
- --8310170736 Safity evaluation supporting Amends 24 & 5 to Licenses NPF-/9 & NPF-17, respectively -- Office of Nuclear Reactor Regulation, Director B3/10/06 2pp 2079B 143 24% Fichs 50-369, 83/10/06, 8310170710
- 8310140205 Forwards offsite dose calculation manual.Rev 2 Rev corrects typographical errors & updates meteorological info TUCKER.H B Duke Power Co B3/10/07 DENTON.H R Dffice of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 p 20762 349 24X Fichs 50-349.83/10/07.8310140205
- --8310140207 Offsite dose calculation manual, Rev 2 STEWART.J M Duke Power Co 83/09/30 App 20762 350 24X Fiche 30-369.83/10/07.8310140205
- 8310210131 Responds to 830701 request that rod control sys interim operating restrictions be removed based on acceptable results from recent unit & cycle specific analysis Agrees that restrictions no longer apply for first cycle NOVAK.T M Assistant Director for Licenaing 83/10/18 TUCKER.H B Dute Power Co 2pp 20883 327 24X Fiche 50-349,83/10/18, 8310210131
- 8310280037 Forwards Amends 6 & 25 to Licenses NPF-9 & NPF-17, respectively, safety evaluation & request for FR publication Amends authorize transfer of spent fuel between Units 1 & 2 ADENSAM; E 0 Licensing Branch 4 83/10/19 TUCKER, H B Duke Power Co Jpp 20964 120 24X Ficho 50-369, 83/10/19, 8310280037
- O Inspection reports, IE Bulletins & correspondence
- 8310250580 Ack receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Acceptability of response under review LEHIS.R C Division of Project & Resident Programs 83/08/29 TUCKER, H B Duke Power Co Jp 20900 352 24X Fiche 50-369.83/08/29.8310250580
- 8308300342 lE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svr list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche, 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000.83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Sys W/o 100FR80 59 Evaluation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349.
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Mestinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Net York, Inc 76pp. 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp. 20892 026 24X Fiche, 50-000, 83/10/07, 8308300752

- 8310250514 Ack receipt of 830810 ltr informing NRC of steps taken to correct vaolations noted in IE Insp Repts 50-369/83-26 & 30-370/83-33 Evaluation of radiation hazard associated w/ transfer of neutron source adequate Violation withdrawn O'REILLY, J P Region 2, Office of Director 83/10/07 TUCKER, H B. Duke Power Co 2pp 20901 279 24X Fiche 50-369,83/10/07, B310250514
- ~-8310250524 Responds to ARC 830711 ltr re violations noted in IE Insp Repts 50-367/83-26 & 50-370/83-33 Violation re failure to perform adequate neutron radiation survey denied Sound health physics judgment used TUCKER.H B Duke Power Co 63/08/10 O'REILLY.J P Region 2, Office of Director 3pp 20901 281 24X Fiche 50-369,83/10/07, 8310250514
- --B310250530 Ferwards IE Imap Repts 50-369/B3-26 & 50-370/B3-33 on B30606-10 & notice of violation ENTS, R C Division of Project & Resident Programs B3/07/11 TUCKER, H B Duke Power Co 2pp 20901 284 24X Fiche 50-369,83/10/07.8310250514
- --8310280534 Notice of violation from intp on 830606-10 * Region 2: Office of Director 83/07/11 1p. 20901 286 24X Fiche 50-369,83/10/07,8310250514
- --8310250540 IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 Noncompliance noted failure to perform adequate neutron radiation survey to evaluate extent of radiation hazards present prior to permitting worker entry.

 COLLING.T R., JARR.K P. Region 2, Office of Director 83/06/28 6pp 20901 287 24X Fiche 50-369.83/10/07.8310250514
- 8308300759 1E Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Inc 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- B30B300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders" Syc list encl JORDAN. E. L. Division of Emergency Preparadness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 127 24K Fiche, 50-000, 83/10/11, B308330761
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER, H B. Buke Power Co 3pp 20700 208 24X Fiche 50-000, B3/10/17, B310250635
- --8310250646 Forwards SALP Repts 50-269/83-17,50-270/83-17,50-287/83-17, 50-369/83-24,50-370/83-32,50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983 LEWIS.R C Division of Project & Resident Programs. 83/08/02 TUCKER.H B Duke Power Co 3pp 20900 208 24X Fiche 50-000.83/10/17,8310250635
- --8310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 Apr 1983 * Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fichs, 50-000, 63/10/17, 8310250635
- --8310250465 Responds to 830802 ltr rs SALP board rept Rept incomplete & premature in certain areas In general, util endorses observations re facility performance.
 TUCKER, H B Duke Power Co 83/08/29 O'REILLY, J P Region 2, Office of Director 2pp 20900 247 24X Fiche 80-000,83/10/17, 8310250435
- R Periodic operating reports & related correspondence
- 83i0i80i00 Monthly operating repts for Sept 1983 W/83i0i4 ltr REAVIS, J.A., TUCKER, H.B. Duke Power Co. 83/10/14. Director's Office, Office of Inspection and Enforcement. 10pp 20807:163 24X Fiche 50-269,83/10/14.83i0180100
- 8 Reportable occurrences, LERs & related correspondence
- 8310060058 Forwards LERs 83-072/03L-0 & 83-044/03L-0, Detailed event analysis encl
 TUCKER. H B Duke Power Co 83/09/28 0'REILLY, J. P Region 2,
 Dffice of Director 3pp 20648:328 24X Fiche 50-369,83/09/28,
 831006005B.

- ~-8310060063 LER 83-072/03L-O on 830914, while in Mode 1 review determined that inadequate fire barrier provided between electrical penetration rooms located in auxiliary bldg Caused by error during identification of fire barrier penetrations NARDOCI.P B Dute Power to 83/09/28 Region 2, Office of Director 1p 20648 331 24X Fiche 50-369,83/09/28,8310060058
- --8310060068 LER 83-044/03L-0 on 830915, review revealed inadequate fire barrier provided between electrical penetration rooms located in auxiliary bldg Caused by error during identification of fire barrier penetrations NARDCCLP B Duke Power Co 83/09/28 Region 2, Office of Director 1p 20648 332 24X Ficha 50-369,83/09/28,8310060058
- 8310040384 LER 83-073/03L-0 on 830829, surveillance test review determined that monthly test on RCS cold leg accumulator pressure not performed by required date of 830506 Caused by personnel error W/830928 ltr NARDGCI.P B. TUCKER.H B Duke Power Co 83/09/28 O'REILLY, J P Region 2. Office of Director 2pp 20446 052 24X Fiche 50-369, 83/09/28.8310060384
- 8310120413 LER 83-074/03L=0 on 830830.while in Mode I, invalid fire alarm on Fire Detection Zone FFA-80 received in control room & alarm would not reset EFA-80 declared inoperable Caused by dust accumulation in detector W/030929 ltr NARDOCI.P B. TUCKER.H B Dute Power Co 83/09/29 0'REILLY, J P Region 2. Office of Director 2pp 20498 330 24% Fiche 50-349,83/09/29.8310120413
- 8310170248 LER 83-076/03L-0 on 830901. Fire Door 819A found propped up against wall w/scraws removed from door hinges Caused by door deliberately removed from frame due to dragging problem Door repaired W/830930 ltr NARDOCL. P B. TUCKER. H B Dute Power Co 83/09/30 O'REILLY, J P Region 2. Office of Director 2pp 20787 089 24X Fich 50-369,83/09/30,8310170248
- 8310170384 LER 83-075/03L-0 on 830831, while attempting to open valve iNM-2008 for stroke timing during nuclear sampling valve stroke timing quarterly test, valve failed to open Caused by burned up actuator Actuator will be replaced W/830930 ltr NARDOCI.P B. TUCKER:H B Dute Power Co 83/09/30 D'REILLY, J P Region 2. Office of Director 2pp 20785 029 24X Fichs 50-369,83/09/30,8310170384
- 8310170430 LER 83-077/03L-0 on 830907, while in Mode I, Channel 4 of loose parts monitor declared inoperable because of circuit noise & continuous alarm Probably caused by short in acceleromater or flexible cable M/831005 Itr NARDOCI.P 8. TUCKER.H B Dute Power Co 83/10/05 0'REILLY, J P Region 2. Office of Director 4pp 20779 218 24X Fiche 50-369, 83/10/05, 8310170430
- 8310210308 LER 83-078/031-0 on 830906, while in Mode 3, invalld fire alarm on fire detection Zone EFA 152 received Fire alarm would not reset & EFA 152 declared inoperable Cause unknown Alarm reset w/unit at power W/B310060 ltr NARDOCI,P 8. TUCKER,H B Dute Power Co 83/10/06 O'REILLY,J & Region 2, Dffice of Director 2pp 20651 152 24x Fiche 50-369,83/10/06.8310210308
- B310210005 LER 83-079/03L-0 on B30908 & 26, steam line 1C radiation monitor IENF-26 declared inoperable due to sporadic operation of light & checksource function Caused by GM tube load remistor below limit Resistor replaced W/B31007 ltr NARDOC1.P.B. TUCKER.H B Duke Fower Co B3/10/07. 0'REILLY, J P Region 2. Office of Director 2pp 20855 164 24X Fiche 30-369,83/10/07.8310210005
- 8310210307 LER 83-080/03L-0 on 830709, during performance of periodic ice condenser intermediate dest door & monitoring sys insp, two intermediate deck doors discovered frozen shut Caused by unusual syc conditions W/831007 ltr
 NARDOCI.P B. TUCKER.H B Dute Power Co 83/10/07 0'REILLY, J P. Region 2, Office of Director 2pp 20851 072 24X
 Fiche 50-349,83/10/07.8310210309
- '10210028 RD 369/83-81 on 830910 fire detection instrumentation found degraded Investigation & rept preparation incomplete Rept will be submitted by 831028

 TUCKER H B Duke Power Co 83/10/10 D'REILLY, J P Region 2, Diffice of Director 1p 20856 011 24X Fiche 50-369, 83/10/10, 8310210028
- 10270173 LER B3-082/03L-0 on 830911, pressurizer heater group 1B jeclared imperable when operation did not sid in RCB pressure control (gaused by blown 500 amp line fuse in vacuum contractor cabinet Fuse replaced W/831011 ltr vARDOCI,P B , TUCKER,H B Dute Power Co 83/10/11 0'REILLY, J P legion 2, Office of Director 2pp 20724 173 24X iche. 50-369, 83/10/11.8310270173

- B31025007) LER B3-084/01T-0 on 830929, nuclear svc water train A declared inoperable after containment spray sys train B declared inoperable on B30928, constituting degraded mode Caused by water in oil reservoir for pump 1A W/BJ1014 lt; NARDOCT, P B . TUCKER, H B Duke Power Co B3/10/14 0'REILLY, J P Region 2. Office of Director 5pp 20096 0/8 24X Fiche 50-369, 83/10/14, 8310250071
- 8310250074 Forwards LERs 83-085/01T-0 & 63-050/01T-0 Detailed event analysis encl
 TUCKER, H D Duke Power Co B3/10/14 O'REILLY, J P Region D, Office of Director 4pp 20894 133 24X Fiche 50-349, B3/10/14, B310250074
- --8310250076 LER 83-085/017-0 on 830930 discovered that equipment/cable interfaces using Crouse-Hinds conduit coupling as sealing method may be susceptible to moisture seepage Caused by design oversight in failure to test connections NARDOCI-P B Duke Power Co 83/10/14 Region 2, Office of Director 1p 20894 137 24X Fishe 50-369,83/10/14,83102300/4
- ---8310250000 LER 83-050/01T-0 on 830930 discovered that equipment/cmble interfaces using Crouse-Hindr conduit coupling as scaling method may be susceptible to moisture seepage Caused by design oversight in failure to test connections NARDOCLED Dake Power Co 83/10/14 Region P. Office of Director 1p 20094 138 24X Fishe 50-369.83/10/14.8310280074
- DOCKET 50-370 WILLIAM B MCQUIRF NUCLEAR STATION, UNIT P

 F Security, medical, emergency & fire protection plans
- 8310040311 Summarizes 830916 mgt meeting in Atlanta, GA re security barrier problems at facility O'REILLY, J P Region 2. Office of Director 83/09/21 TULKER, JI D Duke Power Co ip 20623 096 24X Fichs 50-369,83/09/21.
- B310070128 Releases public version of revised amergency plan implementing procedure FELTON.J M Division of Rules and Records 83/09/26 Document Management Branch 1p 20671 102 24X Fichs 50-370.83/09/26. 8310070128
- --B310070131 Public version of revised Emergancy Plan Implementing Procedure OP/2/A/6200/48, "Eparating Procedure for Operation of Post-Accident Liquid Sampling Sys " W/830915 ltr MCCONNELL, T. TUCKER, H B Duke Power Co 83/08/19 DENION, N R Office of Nuclear Reactor Regulation, Director 19pp 20671 103 24X Fiche 50-370,83/09/26,8310070120
- B310060265 Releases public version of revised station directive FELTON, J M Division of Rules and Records 93/09/30 Document Management Branch 1p 20660 226 24X Fiche 50-369, 63/09/30.
- --8310060268 Public version of Rev 5 to Station Directive 3 B 2,
 "Technical Support Ctr " W/830706 ltr
 MCINTOSHM D , TUCKER, H B Duke Power Co 83/06/24 DENIUM, H R
 Diffice of Nuclear Reactor Regulation, Director ADENBAN, E G
 Licensing Branch 4 6pp 20660 227 24x Fiche 50-369,83/09/30,
 8310060265
- B310070134 Releases public version of revised crisis mgt plan implementing procedures FELTON.J M Division of Rules and Records B3/10/04 Ducument Management Branch ip 20670 001 24% Fiche 50-000, E3/10/04.
- --8310070143 Forwards public version of revised crisis mpt plan implementing procedures, including Procedures 5 3 1 rerectory manager & immediate staff group plan & 5 3 4 rescheduling/planning support group TUCKER.H B Duke Power Co 83/0//Od DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 20670 002 24X Fiche 50-000,83/10/04,8310070134
- --8310070152 Public version of revised crists agt plan implementing procedures including Procedure 3 3 I re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group 93/07/01 457pp 20670 005 24x Fiche 50-000/83/10/04/8310070134
- 8310110413 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch Ip 20714 001 24X Fiche 50-367, 83/10/05, 8310110413

- --B3101104iB Forwards public version of revised Emergency Plan Implementing Procedure OP/1/A/6200/48 re operation of post-actident liquid sample sys & Station Directive 2.05 re news releases
 TUCKER, H D Duke Power Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAM, C C Licensing Branch 4 lp 20714 002 24X Fiche 50-349,83/10/05,8310110413
- --03|0\$|0421 Public version of revised Emergency Plan Implementing Procedure OP/1/A/6200/40 re operation of post-accident liquid sample sys & Station Directive 2 0 5 re news releases MCCONNELL.T L , IEAVER.B Duke Power Co 83/05/16 21pp 20714 003 24X Fiche 50-369,83/10/05,8310110413
- B310110072 Releases public version of revised emergancy plan implementing procedures FELTON.J H Division of Rules and Records 83/10/07 Document Management Branch 1p 20709 086 24X Fiche 50-369,83/10/07, 8310110072
- --B310110077 Forwards public version of revised emergency plan implementing procedures, including Procedures HP/D/B/3009/02 re alternate method for determining dose rate within reactor bldg & PT/D/A/4600/06 re exercises & drills
 TUCKER.H B Duke Power Co B3/08/30 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Liconsing Branch 4 2pp 20707 087 24X Fiche 50~369,83/10/07.8310110072.
- --9310110079 Public version of revised emergency plan implementing procedures including Procedures HP/0/B/1009/02 re alternate aethod for determining dose rate within reactor bldg & PY/0/A/4600/06 re exercises & drills GLOVER.H 6 . MCCONNELL,T L Duke Power Co 83/08/05 7Jpp 20709 089 24% Fiche 50~369.83/10/07.8310110072
- 8310180444 Responds to request for crisis mgt ctr staff to participate in emergency exercises at same frequency as technical support ctr staff Crisis mgt team will be activated in full-scale exercise involving full state participation TWKER, H B Duke Power Co B3/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20802 121 24X Fiche 50-000, 83/10/10,8310180444
- 8310310416 Forwards Rev 5 to security training & qualification plan Rev withheld (ref 10CFR73 21). Plans will be updated to include changes TUCKER.H B Duke Power Co B3/10/10 O'REILLY, J P Region 2, Office of Director 1p 20959 303 24X Fiche 50-369,83/10/10, 8310310416
- B310250635 Informs that periodic evaluation of SALP complete Rept approved O'RETLLY,J P Region 2, Office of Director 83/10/17 TUCKER,H B Duke Power Co 3pp 20900 205 24X Fiche 50-000, 83/10/17, B310250635
- --8310250652 BALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1992 Apr 1983
 * Repion 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635
- 8310270024 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 89/10/20 Document Management Branch, ip 20942 018 24X Fiche 80-369,89/10/20, 8310274034
- --8310270136 Forwards public version of revised station directives & Change 2 to Emergency Plan Implementing Procedure SP/1/A/6200/48 re post-accident liquid sample sys TUCKER.H B Duke Power Co 83/10/06 DENTON,H R Office of Muclear Reactor Regulation, Director ADENSAM.E 9 Licensing Branch 4 1p 20942 019 24% Fiche 50-369,83/10/20,8310270026.
- --8310270146 Public version of revised station directives & Change 2 to Emergency Plan Implementing Procedure DP/1/A/6200/48 repost-accident liquid sample sys ACCONNELL, T.L., BEAVER, B Duke Power Co 83/09/29, 39pp. 20742 020 24X Fiche 50-369,83/10/20,8310270026
- J Enturance & indemnity information
- 8310210312 Forwards Endorsement 28 to NELIA Policy NF-248 & Endorsement 23 to MAELU Policy MF-101 LAMSON.L T Duke Power Co 83/10/17 SALTZMAN, J NRC No Detailed Affiliation Given 2pp. 20851 076 24X F1the 50-369.83/10/17.8310210312

- P Operating license stage documents & correspondence
- 8310040474 Application to amend Licenses NPF-9 & NPF-17, changing Tech Specs to increase upper limit for containment lower compartment to 125 F for up to 90 canulative days provided lower compartment temp less than 120 F. TUCKER, H B Duke Power Co 83/09/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ABENSAM E Q Licensing Branch 4 3pp 20622 308 24X Fiche 80~369,83/09/22,8310040474
- ---8310040482 Proposed Tech Spacs increasing upper limit for containment lower compartment to 125 F for up to 90 cumulative days per calendar yr provided lower compartment temp overaged over previous 365 days less than 120 F

 * Duke Power Co 83/09/22 3pp. 20622 311 24X
 Fiche 50-369.83/09/22,8310040474
- 8310030604 Forwards SER re response to Generic Ltr Bi-21, "Natural Circulation Cooldown " Upon acceptable implementation of emergency response guidelines, procedures will be adequate to perform safe natural circulation cooldown NDVAX.T M Assistant Director for Licensing. 83/09/24 PARRIB, H 9 Tennessee Valley Authority 2pp 20607 288 24X Fiche 50-000, 83/09/23, 8310030604
- 8310050074 Concurs w/dissolution of Model D2/D3 Steam Generator Util Design Review Panel Panel work complete NDVAK.T M Assistant Director for Licensing 83/09/23 BLACKLEY.B K Design Review Panel Dpp 20650 165 24X Fiche 50-000.83/09/23.8310050076
- 8310190199 Forwards safety evaluation re util response to Generic Ltr 81-21 "Natural Circulation Cooldown." Upon acceptable implementation of emergency response guidelines, procedures adequate for safe natural circulation cooldown NOVAK, T M Assistant Director for Licensing 83/09/30 TUCKER, H. B Duke Power Co 2pp 20838 098 24X Fiche 50-000,83/09/30,8310190199
- 8310170710 Forwards Amends 24 & 25 to Licenses NPF-9 & NPF-17, respectively & safety evaluation. Amends authorize maintaining hot standby conditions w/o preceeding to cold shutdown for Unit I and ADENSAME OF Licensing Branch 4 83/10/06 TUCKER.H B. Duke Power Co 2pp 20798 134 24X Fiche 50-349.83/10/06.8310170710
- --8310170719 Amends 24 & 5 to Licenses NPF-9 & NPF-17,respectively, authorizing maintaining hot standby conditions w/o proceeding to cold shutdown for Unit 1 ADENSAM,E 0 Licensing Branch 4 63/10/06 7pp, 20798-136 24X Fishe 50-369,83/10/06.8310170710
- --8310170736 Safety evaluation supporting Amends 24 & 5 to Licenses NPF-9 & NPF-17. respectively * Office of Nuclear Reactor Regulation, Director 03/10/06 2pp 20798 143 24X Fiche 50-369,83/10/06,8310170710.
- 8310140205 Forwards offsite dose calculation manual, Rev 2 Rev corrects typographical errors & updates meteorological info TUCKER, H B Duke Power Co B3/10/07 DENTON, H, R Dffice of Nuclear Reactor Regulation, Director, ADENSAM, E. G. Licensing Branch 4 ip 20762 349, 24X Fiche 50-369, 83/10/07, 8310140205.
- --8310140207 Offsite dose calculation manual, Rev 2 8TEWART, J M Duke Power Co. 83/09/30 App 20762:350, 24X Fichs 50-369:83/10/07:8310140205
- 8310210131 Responds to 830701 request that rod control sys interim operating restrictions be memoved based on acceptable results from recent unit & cycle specific analysis. Agrees that restrictions no longer apply for first cycle.

 NOVAK, T M Assistant Director for Licensing 83/10/18, TUCKER, H B Duke Power Co. 2pp 20883 327. 24X Fiche: 50-367,83/10/18, 8310210131.
- B3102B0037 Forwards Amends 6 & 25 to Licenses NPF-9 & NPF-17, respectively, safety evaluation & request for FR publication Amends authorize transfer of spent fuel between Units 1 & 2. ADENSAM.E.G Licensing Branch 4. B3/10/19 TUCKER.H B Duke Power Co 3pp 20964 120 24% Fiche 50-369.83/10/19,83102B0037.

d Inspection reports. IE Bulletins & correspondence

- B310250580 Act receipt of B30810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/B3-26 & 50-376/B3-33 Acceptability of response under review LEWIS,R C Division of Project & Resident Programs 83/08/29 TUCKER,H B Date Power Co Jp 20900 352 24X Fiche 50-369,83/08/29,8310250580
- B30B300340 IE Info Notice B3-6). "Alleged Use of Stand-Ins for Welder Qualification Yests * Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fichs 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intales " Svc list encl JORDAM, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type 8A-1 Differential Relays " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York. Inc 118pp 20778.001 24X Fiche 50-000.83/09/26.8308300345
- 830B300349 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Sys Wo 10CFR50 59 Evaluation " Svc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3709729 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000.83709729,8308300347
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8306300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Posts 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000.83/10/07.83083000752
- 8310250514 Act receipt of 830810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-367/83-26 & 50-370/83-33 Evaluation of radiation hazard associated w/ transfer of neutron source adequate Violation withdrawn D'REILLY, J P Region 2, Office of Director 83/10/07 TUCKER, H B Duke Power Co 2pp 20901 279 24X Fiche 50-369,83/10/07, 8310250514
- --8310250524 Responds to NRC 830711 ltr re violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Violation re failure to perform adequate neutron radiation survey denied Sound health physics judgment used TUCKER.H B Duke Power Co 83/08/10 O'REILLY, J.P. Region 2, Office of Director 3pp 20901 281 24X Fiche 50-369,83/10/07, 8310250514
- --8310250530 Forwards IE Insp Repts 50-347/83-26 & 50-370/83-33 on 830404-10 & notice of violation LEWIS, C Division of Project & Resident Programs 83/07/11 TUCKER, H B Dute Power Co 2pp 20901 284 24X Fiche 50-349,83/10/07,8310250514
- --8310250534 Natice of Violation from insp on 830606-10 * Region 2: Office of Director 83/07/11 ip 20901 286 24X Fiche 50-369.83/10/07.8310250514
- ---8310250340 IE Insp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 Noncompliance noted failurs to perform adequate neutron radiation survey to evaluate estant of radiation hazards present prior to permitting worker entry COLLINS, T R . BARR, K P Region 2, Office of Director 83/06/28 App 20901 287 24X Fichs 50-369, 83/10/07, 8310250514
- 8308300759 IE Info Notice 82-67, "Emergency Use Respirator Matl Defect Causes Production of Notices Gases " Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11 Consolidated Edison Co. of New York: Inc. 117pp. 21043:075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning: Defective Self-Centained Breathing Apparatus Air Culinders " Syc list enci. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/10/11 Consolidated Edison Co. of New York, Inc., 120pp 20827, 129 24% Fiche 50-000, 83/10/11, 8308300761

- 8310250635 Informs that periodic evaluation of SALP complete Rept approved O'REILLY, J.P. Region 2. Office of Director 83/10/17 TU[Nffi.H D Duke Power Co. 3pp 20900 208 24X Fiche 50-000, 83/10/17, 8310250635
- --8310250646 Forwards SALP Repts 50-269/83-17.50-270/83-17.50-2887/83-17.50-369/83-24.50-370/83-32.50-413/83-14 & 50-414/83-13 for June 1982 Apr 1983 LEWIS, R C Division of Project & Resident Programs 83/08/82 TUCKER, H B Duke Power Co 3pp 20900 208 24% Fiche 50-000,83/10/17.8310250635
- --8310250452 SALP Repte 50-249/83-17.50-270/83-17.50-287/83-17. 50-349/83-24.50-370/83-32.50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983 * Region 2. Office of Director 83/08/02 54pp 20900 211 24k Fiche 50-000.83/10/17.8310250435
- --8310250645 Responds to 830802 ltr re SALP board rept Rept incomplete to premature in certain areas in general, util endorses observations re facility performance TUCKER.H B Duke Power Co 63/08/29 O'REILLY, J P Region 2. Office of Director 2pp 20900 267 24% Fiche 50-000, 83/10/17. 8310250635
- R Periodic operating reports & related correspondence
- B310180100 Monthly operating repts for Sept 1983 4/831014 ltm REAVIB.J A. TUCKER.H B. Duke Power Co. B3/10/14 Birector's Office. Office of Inspection and Enforcement 10pp 2080/-16/1 P4X Fiche 50-369:83/10/14:8310180100.
- B Reportable occurrences, LERs & related correspondence
- B310040403 Updated LER 83-039/03X-i on 800786, during routine surveillance; two of four upper head injection level switch setpoints found out of tolerance Gaused by design deficiency, Switch recalibr Mod implemented, W/B30921 ltr NARDQCI, P 8, TUCKER, H B Duke Power Co 83/09/21 D'HEILLY, J P Region 2, Office of Director 3pp 20617 354 24X Fiche 50-370, 83/09/21, 8310040403
- 8310040255 LER 83-043/03L-0 from 830427-0707, during isolation valve leak rate test penetrations M259, M322, M327, M330 & M385 failed to mest Tech Specs, Caused by authorized mode & component malfunction, respectively W/830923 ltr NARDOCI,P B , TUCKER, H B Duke Power Ca 83/09/23 O'REHLY, J P Region 2, Office of Director 4pp 20647 027 24X fiche 50-370, 83/09/23, 8310040035
- 8310060058 Forwards LERe 83-072/03L-0 & 83-044/03L-0 Detailed event analysis encl
 TUCKER.H B Duke Power Co 83/07/28 D'REILLY, J P Region 2, Office of Director, 3pp 20648 328 24X Fiche 50-369.83/09/20, 8310060058
- --831006006B LER B3-044/03L-0 on 830915, review revealed inadequate fire barrier provided between electrical penetration rooms located in auxiliary bldg Caused by error during identification of fire barrier penetrations NARDOCI.F B Duke Fower Co 83/09/28 Region 2, Office of Director ip 20648 332 24X Fiche 50-369,83/09/28,8310060058
- 8310210077 LER 83-045/03L-0 on 830907, containment sump level wide-range channel B incorrectly indicated 2 ft of water in containment sump Channel B declared inoperable Caused by low side housing bellows installed wincorrect mat!
 NARDOCLE B , TUCKER H B Duke Power CO 83/10/07 O'REJLLY, J P. Region 2, Office of Director 2pp 20058 202 24X
 Fiche 50-370,83/10/07,8310210077
- 8310270048 LER 93-046/03L-0 on B30912, during removal of tachometer for calibriturbine-driven auxiliary feedwater pump started & could not be stopped from either local panel or control room Caused by blown fuse Fuse replaced W/B31012 ltr NARDOCI.P B. TUCKER, H B Duke Power Co. B3/10/12 O'REILLY, J P. Region 2, Office of Director 3pp 20724 i12 24X Fiche 50-370,83/10/12,8310270048
- 8310250074 Forwards LERs 83-085/01T-0 & 83-050/01T-0 Detailed event analysis encl.

 TUCKER.H B Duke Power Co 83/10/14. O'REILLY, J. P. Region 2. Office of Director 4pp 20894 133. 24X Fiche: 50-369.83/10/14.
- --B3102500B0 LER B3-050/017-0 on B30930.discovered that equipment/cable interfaces using Crouse-Hinds conduit coupling as sealing method may be susceptible to moisture seepage Caused by design oversight in failure to test connections.

 NARDGCI.P B Duke Power Co B3/10/14. Region 2, Office of Director ip 20874 ISB 24X Fiche 50-369, B3/10/14, B310250074

- 8310270207 LER 83-048/03L-0 on 830914,15 % 16, average lower containment temp exceeded Tech Spec requirements Caused by const % design deficiencies 8ys air handling units realigned to to coller source & cooling flow increased W/831014 ltr NARDCCI,P B., TUCKER,H B. Duke Power Co. 83/10/14 D'REILLY, J.P. Region 2. Office of Director App. 20924 097 24X Fiche 50-370,83/10/14,8310270209
- B310270310 LER 83-049/03L-0 on B30914, investigation of cabinst tipuble alarm revealed "operate" light for steam line 2A radiation monitor 2EMF-10 failed & could not be restored Caused by component failure 9M tube replaced W/B31014 ltr NARBOGI,P B, TUCKER,H B Duke Power Co 83/10/14 O'REILLY,J P Region 2, Office of Director 2pp 20923 190 24X Fiche 50-370, B3/10/14, 83102/0310

DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8310030227 Releases public version of revised emergency plan implementing procedure FELION.J M Division of Rules and Records 83/09/28 Document Management Branch ip 20403 057 24% Fiche 50-373,83/09/28,8310030229
- --8310030236 Public version of Rev 4 to Emergency Plan Implementing Procedure LZP 1700-2. "Station Employee List" & Commonwealth Edison Co. 83/06/09 20pp 20603 058 24X Fithe 50-370,83/09/28.8310030229
- B310040444 Forwards Rev 15 to security plan Rev withheld (ref 10CFR73 21)
 FARRAR, D L Commonwealth Edison Co 8,3/09/30 Office of Nuclear Reactor Regulation, Director 1p 20619 052 24X
 Fische 50-373,83/09/30,8310040444
- 8310180250 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 83/10/04 REED.C Commonwealth Edison Co 2pp 20802 332 24X Fiche 50-373,83/10/04,
- --8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted Major areas inspected emergency preparedness program including licensee action on previously identified items & licensee audits ploskI.T., PHILLIPS.M P Region 3, Office of Director 83/10/03 6pp 20802 334 24X Fiche 50-373,83/10/04,8310180250
- 8310110118 Releases public version of revised emergency plan implementing procedure FELTON, J. H. Division of Rules and Records 83/10/05 Document Management Branch 1p 20686-315 24X Fiche 90-373,83/10/05, 8310110118
- --931010123 Public version of Rev 4 to Emergency Plan Implementing Procedure LZP-1700-3, "Btation Phone List " W/830825 Eir & revised index HOLYDAK, R H Commonwealth Edison Co B3/07/01 Office of Nuclear Reactor Regulation, Director 23pp 20686 316 24X Fiche 50-373,83/10/05,8310110118
- B310170664 Responds to B307R2 ltr rs Rav 14 to security plan Portions of plan acceptable Items from previously approved plan should be followed for portions inconsistent w/10CFR50 54 Enci withheld fref 10CFR73,21)
 BCHMENCER,A Licansing Branch 2 B3/10/12 FARRAR,D L Commonwealth Edison Co 2pp 20779 293 24X Fichs 50-373,83/10/12,83343136644
- 8310170707 Releases public version of revised emergency plan
 implementing procedure
 FELTON.J M Division of Rules and Records 63/10/13. Document
 Hanagement Branch ip 20813 242 24X Fiche 50-373.83/10/13.
 8310170707
- --8310170711 Public version of Rev 3 to Emergency Plan Implementing Procedure LZP-1330-24. "Determination of Reactor Coolant Hydrogen Offgas Concentrations at High Radiation Sampling Sys." W/830928 Itr & receipt form HOLYOAK;R M. Commonwealth Edison Co B3/09/16 38pp 20813 243 24X Fiche 50-373,83/10/13,8310170707
- 8310200414 Releases public version of revised emergency plan
 Laplementing procedure
 FELYON-J M Division of Rules and Records 83/10/17 Document
 Management Branch ip 20859-233 24X Fiche-50-373,83/10/17,
 8310200414

- --B310200424 Public version of Rev S to Emergency Plan Implementing Procedure LZP-1110-1. "Station Director (Acting Station Director)" H/B31003 thrreceipt form & 10CFR50 59 format for safety evaluation HDLYOAK, R H Commonwealth Edison Co B3/10/03 27pp 20859 234 24X Fiche 50-373, B3/10/17, B310200416
- 8310270526 Releases public version of revised emergency plantimplementing procedure
 FELTON.J M Division of Rules and Records 93/10/21 Document
 Management Branch 1p 2093/216 24X Fiche 50-000.83/10/21.
 B310270526
- --B310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6, "Administration & Logistics Manager" W/831017 1tr & receipt form NELLIS.C A Commanuealth Edison Co B3/02/1B DENTON, H R NRC No Datailed Affiliation Given 7pp 20737 217 24X Fichs 50-000, B3/10/21, B310270526
- 8310280206 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20764 148 24% Fiche 50-373,83/10/25, 8310280206
- --8310280215 Public version of revised Emergency Plan Implementing Procedures LZP-1320-1 re augmentation of plant staffing, LZP-1550-11 re post-accident sampling equipment inventory & LZP-1700-2 re station employee list a Commonwealth Edison Co. 83/07/25 43pp 20964 147 24X Fiche 50-373,83/10/25,8310280206
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fiche 50-000,83/10/25,8310280307
- --8310280314 Public version of revised generating stations wmergency plan telephone directory OALLE, D.P. Commonwealth Edison Co. 83/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 44pp 20963 127 24X Fiche 80-000, 83/10/25, 8310280307
- 8310280191 Releases public version of revised emergancy plan implementing procedure. FELTON, J M Division of Rules and Records 83/10/24 Document Management Branch 1p. 20962-264. 24X Fiche 50-000,83/10/26, 8310280191
- --8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EOF-15, "Emergency Operations Facility Activation" MORE:R D Commonwealth Edison Co 83/08/02 50pp 20962 267 24X Fiche 50-000,83/10/26,8310280191
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8310180249 Forwards affidevit of distribution of Amend 63 to FBAR SCHROEDER, C W Commonwealth Edison Co 83/10/10 DENTON. H R. Office of Nuclear Reactor Regulation, Director 2pp. 20807:081 24X Fichs: 50-373, 83/10/10, 8310180249.
- P Operating license stage documents & correspondence
- 8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates.

 BARNES, P. L. Commonwealth Edison Co. 83/10/05 KEPPLER, J. Q. Region 3, Office of Director 10pp. 20830 034, 24X Fiche. 50-000,83/10/05,8310500273.
- 8310120433 Discusses proposed rev to primary containment vent & purge valve closure times Util will replace &/or modify eight 26-inch valves & two B-inch valves per unit to permit 10 s or loss e closure time Marked-up Tech Spec enc)

 8CHROEDER, C. W. Commonwealth Edison Co. 83/10/06 DENTON, H. R.

 0ffice of Nuclear Reactor Regulation, Director Spp. 20698 298

 24X Fichs. 50-373, 83/10/06, 8310120433
- 8310180281 Forwards marked-up changes to Amend 63 to FSAR Tables 14, 2-130, 14, 2-124, 14, 2-114 & Figure 14, 2-2 re startup test program. Bummary of changes listed SCHRGEDER, C. W. Commonwealth Edison Co. 83/10/13 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director, 10pp. 20807:028 24X Fiche: 50-373, 83/10/13, 8310180281.

- 9310180397 Confirms 831003 telcon re util decision to perform feedwater pump trip vibration monitoring at two snubber locations in Unit 2 based on Unit 1 test results SCHROEDER.C W. Commonwealth Eduson Co. 83/10/13 DENTON.H R. Office of Nuclear Reactor Regulation, Director ip 20803-317 24X Fiche 50~373.83/10/13.8310180397
- 8310180425 Describes results of main turbine bupass systesting performed to determine position vs flow relationship for main turbine bypass valves, per Tech Spec 3/4 7 10 SCHRDEDER.C W Commonwealth Edison Co 83/10/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 20803 303 24X Fiche 30-373,83/10/13.8310180425
- 8310190258 Forwards proprietory "In-Plant Sofety Reliaf Valve Test, t.85alle County Station Unit 1," final evaluation rept Rept withheld (ref 10CFR2 790)
 SCHROEDER, C W Commonwealth Edison Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 49p 20820 120 24% Fiche 50-373,83/10/14,8310190258
- B310240275 Documents NRC position re elements that must be considered in computation of acceptable closure time for containment purge & vent valves in response to B31006 ltr Justification for interim operation requested BCHWENGER, A Licensing Branch 2 B3/10/18 FARRAR, D L Commonwealth Edison Co 2pp 20907 330 24X Fiche 50-373,83/10/18,8310240275
- 8310250684 Denies request for extension re submittal on Generic Ltr 83-28. "Clarification of Required Actions on Generic Implications of Galem ATWS Events " Required info should be submitted to extent practical by 831105 8CHHENCER A Licensing Branch 2 83/10/18 FARRAR D L Commonwealth Edison Co 2pp 20908 347 24X Fiche 50-373.83/10/18. 8310250684
- 8310280293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaSalle & Guad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 0 BENNETT, C J Commonwealth Edison Co B3/10/21 CASE. E 0 Office of Nuclear Reactor Regulation, Director 1p 20874 259 24% Fiche 50-000.83/10/21.8310250293
- --8310250298 Rev 10 to Offsite Dose Calculation Manual for LaSalle & Quad Cities Commonwealth Edison Co 83/09/30 44pp 20894 260, 24% Fiche 50-000,83/10/21,8310250293
- G Inspection reports: 1E Bulletins & correspondence
- 8310050493 Forwards IE Insp Repts 50-373/83-30 & 50-374/83-29 on B30725-0909 & notice of violation STREETER: JF Region 3. Office of Director B3/09/22 REED.C Commonwealth Edison Co 2pp 20631 350 24% Fiche 50-373,83/09/22,8310050493
- --B310050502 IE Insp Repts 50-373/83-30 & 50-374/83-29 on 830725-0909 Noncompliance noted diesel generator 2A not lined up for startup operation during performance of Preoperational Test PT-AP-203 LANKSBURY.R D . DUPONT.S O . REYES.L A Regton 3. Office of Director B3/09/22 5pp 20631 353 24X Fiche 50-373.83/09/22, 8310050493
- 3308300340 IE Info Natice 83-61, "Alleged Use of Stand-Ins Por Helder Qualification Tests." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24x Fiche 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list and JORDAN E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
 - ~08300345 IE Info Notice 83-63, "Potential Failures of Hestinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001. 24X Fiche 50-000,83/09/26,8308360345

- B310040352 Confirms plans for B30930 enforcement conference in Glan Ellyn. IL to discuss inadvertent heatup event on B30824, which caused unplanned mode change & resulted in procedural violations
 NORELIUS.C E Division of Project & Resident Programs B3/09/26
 REED.C Commonwealth Edison Co ip 20620 215 24X
 Fiche 50-373, B3/09/26, B310040352
- 8308300347 IE Info Notice 83-44. "Lead Shielding Attached to Safety-Raleted 8ys W/o 10CFR90 59 Evaluation " Svc list enc!

 JORDAN C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York Inc 115pp 20716 324 24X Fiche 50-000/83/09/29,8308300349
- 8310140213 Forwards IE lnsp Repts 50-373/83-35 & 50-374/83-34 on 830804.05.08-11 & 15 No noncompliance noted STREETER.J F Region 3. Office of Director 83/09/29 REED.C Commonwealth Edison Co 2pp 20762 307 24X Fichs 50-373, 83/09/29, 8310140213
- --B310140215 IE Insp Repts 30-373/B3-35 & 50-374/B3-34 on 830804.05,08 if & 18 No nancompliance noted Major areas inspected review of previous open & unresolved items & followup on previous items of nancompliance CHOULES,N C . HABSE.R A . HAMTER.D R Region 3, Office of Director 83/09/28 6pp 20762 309 24X Fiche 50-373.83/09/29, 8310140213
- 8310120290 Provides supplementa) response to IE Bulletin 80-14 re misapplication of Rosemount transmitters All changeouts in NSSB sys for Unit 2 complete BARNES, P. L. Communwealth Edison Co. B3/10/04 KFPLER, J. Q. Region 3. Office of Director 2pp. 20692 339 24X Fiche 50-373,83/10/04, B310120290
- 8310180280 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 83/10/04 REED,C Cammonwealth Edison Co 2pp 20802 33% 24X Fichs 50-373,83/10/04.8310180280
- --8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted Major areas inspected emergency preparedness program including licensee action on previously identified items & licensee audits PLOSKI.T , PHILLIPS.M P Region 3, Office of Director 83/10/03 dpp 20802 334 24X Fiche 50-373,83/10/04,8310180250
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-265/83-26, 50-255/83-19, 50-304/83-20, 50-373/83-38, 50-374/83-38, 50-454/83-44, 50-455/83-33, 50-456/83-14 & 50-457/83-13
 NORELIUS, C E Division of Project & Resident Programs 83/10/04 REED, C Commonwealth Edison Co 2pp 20834 098 24X
 Fichs 50-000,83/10/04,8310200124
- --8310200148 1E Mpt Maeting Repts 50-020/83-18,50-237/83-27,50-249/83-75,50-254/83-27,50-265/83-26,50-295/83-19,50-304/83-20,50-373/83-38,50-374/83-38,50-454/83-44,50-459/83-33,50-456/83-14 & 50-457/83-13
 NORELIUS,C E Division of Project & Resident Programs 83/10/03
 App 20834 100 24X Fiche 50-000,83/10/04,8310200124
- 8310200159 Forwards IE Insp Repts 50-373/83-39 & 50-374/83-40 on B30915 No noncompliance noted LITTLE.W S Region 3, Office of Director B3/10/05 REED.C Commonwealth Edison Co 2pp 20834 094 24X Fiche 50-373,83/10/05, 8310200159
- --8310200164 IE Insp Repts 50-373/83-37 & 50-374/83-40 on 830915 No noncompliance noted Major areas inspected fatigue usage factors & stress calculations for main steam drain piping DANIELSON, D H, MUFFETT, J W Region 3, Office of Director 83/10/05 2pp 20834 096 24% Fiche 50-373,83/10/05,8310200159
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/0/ Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 024 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases "Syc list encl JORDAN E L Davision of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 2:043 075 24X Fiche 50-000.83/10/11.8308300757

- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Broathing Apparatus Air Cylinders " Svr list encl JORDAN, E L Division of Emergency Preparedness & Engineering
- CORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000-83/10/11,8308300761
- B3101B01B7 Clarifies NRC position on procedures for admitting NRC personnel Certified access list encl Update will be provided every 6 months
 AXELSON,W L Region 3. Office of Director B3/10/14 REED,C
 Commonwealth Edison Co 7pp 20809 086 24X Fiche 50-3/3,83/10/14,
- 831018055i Natification of B3102i meeting ω/BWR licensees in Bethesda.
 MD to discuss future Inspa for interprenular stress
 correstion cracking
 M1RAOLIA,F J. Assistant Director for Safety Assessment B3/10/14
 E1SENHUT,D 0 Division of Licensing 5pp 20823 358 24X
 Fiche 50-000, B3/10/14/831018055i
- ~~83(025036) Responds to NRC 830922 ltr re violations noted in IE Insp Repts 50-373/83-30 & 50-374/83-29 Corrective actions Procedure LOP-DO-Oi being clarified & step will be added to verify that ESF status panel checked after lineup completed FARRAR, D. L. Commonwealth Edison Co. 83/10/18 KCPPLER, J. Q. Region 3, Office of Director 2pp. 20898 120 24X Fichs 50-373,83/10/20,8310250356
- S. Reportable occurrences, LERs & related correspondence
- 8310110430 Responds to FOIA request for four different categories of documents described in B30510 ltr Forwards matilisted in App A.resgonsive to Items 1,2 & 4 DOE should be contacted for matil requested in Item 3 of itr FELTON.J M Division of Rules and Records B3/06/14 HIATI,S L Uhio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000, B3/06/14, B310110430
- --8310110478 Responds to 830413 ltr requesting info re use of foreign matts on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
 FARRAR D L. Commonwealth Edison Co 83/04/22 KEPPLER, J G Region 3, Office of Director 4pp 20704 063 24%
 Fiche 50-000.83/06/14.8310110430
- B3101B0273 LER 83-100/03L-0 on 830B19, suppression pool nitrogen makeup downstream isolation valve 190050 would not close Caused by 41fty terque switch contacts, preventing closing direction circuit from completing Contacts closined W/830913 ltr DUS, R. DIEDERICH, G. J. Commonwealth Edison Co. B3/09/13 KEPPLER, J. Q. Region 3. Office of Director. 4pp. 20802 292 24X Fiche 50-373,83/09/13.8310180273
- B310120109 LER 83-103/01T-0 on B30714 reactor water level rapidly decreased from 50 inches to 0 inches causing Group VI PCIS initiation at 12 5 inches during valve lineup Caused by an jection check valve being stuck apen W/B30727 ltr HESTPHAL 8 8 DIEDERICH 6 J Commonwealth Edison Co B3/09/27 KEPPLER, J 9 Region 3 Office of Director 4pp 20696 173, 24; Fiche 50-373,83/09/27.8310120109
- 8310040271 LER 83-104/03L-0 on B30B30, blowdown flow recorder found reading low Caused by entrapped air in transmitter sensing lines Air removed & lines vented, W/830928 ltr MASTERSDN V. DEEDERICH O. J. Commonwealth Eduson Co. B3/09/28 KEPPIER, J.O. Region 3. Office of Director 4pp 20641 009 24) Fiche, 90-373, B3/09/28, B3100402/1
- 8310060185 LER 83-107/03L-0 on 830901. w/unit shutdown for planned outage, determined that valve leakage rate limits exceeded in all cases at least one isolation valve in piping line w/acceptable leakage rate W/830929 itm
 HITTENBURG, K.C., DIEDERICH, G.J., Commonwealth Edison Ca 83/09/29
 KEPPLER, J. G. Region 3, Office of Director App 20647 152, 24X
 Ficher 50-373, 83/09/29, 8310060186,
- 8310040178 LER 83-108/03L-0 on 830701, during LOS-RH-Q3, RHR A min flow bypass valve 1E:2-F0644 failed to close. Caused by broken tripper fingers holding motor operator in handwheel operation New fingers installed W/830787 ltr.
 HDUSTQN, R. DIEDERICH.0 J Commonwealth Edison Co 83/09/29 KEFPLER, JQ Region 3, Dffice of Director 3pp, 20647 146 24X F1che.50-373,83/09/29.8310040198

- 8310140045 Updated LER 83-026/03X-1 on 830321.radwaste discharge process radiation monitor declared inoperable Caused by high fixed level of background radiation Equipment design changes investigated W/831003 ltr
 ARAND, J. J. DIEDERICH, G. J. Commonwealth Edison Co. 83/10/03
 KEPPLER, J. G. Region 3. Office of Director. 3pp. 20768-275-24X
 Fichs 50-373,83/10/03,8310140045
- 83:0140069 LER 83-109/03L-0 on 830903, radwaste discharge line hi-hi radiation isolation valve OWLO67 failed to fully close Caused by faulty valve piston Internal valve piston replaced W/831003 itr ARAND.J J. DIEDERICH.G J. Commonwealth Edison Co. 83/10/03 KEPPLER,J G. Region 3, Office of Director. Spp. 20768.012 243 Fiche 50-373,83/10/03,8310140069
- 8310140263 Updated LER 83-052/03X-1 on B30516.during valve calibr Procedure LES-MS-01.HSIV 1821-F028C RPS trip channel.limit suitch A2.Pailed to operate properly Caused by misalignment of limit switch actuating arm Arm readjusted MP31003 1tr HOUSTON,R W . DIEDERICH.0 J Commonwealth Edison Co 83/10/03 KEPPLER.J Q Region 3. Office of Director 3pp 20761 267 241 Fichs 50-373,83/10/03.8310140263
- 8310140057 LER 83-110/03L-0 on 830908, while performing LE8-0M-119, undervoltage relag 1427-APO37B failed to trip consistently within allowable time limits Caused by defective undervoltage relay ITE-27 Relay replaced W/831005 ltr HIETALA, J J DIEDERICH 6 J Commonwealth Edison Co 83/10/05 KEPPLER, J G Region 3, Office of Director 3pp 20767:014 241 Fiche 50-373,83/10/05.8310140057
- 8310140073 LER 83-111/03L-0 on 830821,RHR pump A section valve 1E12-F004A would not operate properly from control room panel 1H13-P601 Caused by broken torque switch in valve motor Motor & torque switch replaced W/831006 1tr HOUSTON,R W . DIEDERICH: 0 J Commonwealth Edison Co 83/10/06 KEPPLER,J G Region 3, Office of Director 3pp 20768 015 24% Fiche 50-373,83/10/06.8310140073
- 8310210222 LER 83-112/03L-0 on 830914, bypass damper OVC13YA of Train A odor eater failed in shut position causing temporary loss of control room ventilation Cause unknown Bypass damper wired shut Investigation underway W/831014 ltr
 LINTAKAS, A. DIEDERICH, G. J. Commonwealth Edison Co. 83/10/14
 KEPPLER, J. G. Region 3, Office of Director 3pp 20852-076 24X
 Fichs 50-373,83/10/14,8310210222
- 8310270274 LER 83-114/03L-0 on B30921, DPIS 1821-N0248 reactor water level switch setpoint exceeded Tech Spec by 2 5 inches Cause undetermined Switch found in proper order Switch recalibr testuned to syc on 830921 W/831014 ltr HOUSTON, R. W. DIEDERICH, 6 J. Commonwealth Edison Co. B3/10/14 KEPPLER, J. O. Region 3, Office of Director 3pp. 20923 261 24X Fiche 50-373,83/10/14,8310270274
- 8310270276 LER 83-115/03L-0 on 830727, Barton Model 288A switches, DPIB 1821-N03/B & DPIB 1821-N03/D, setpoints found to slightly stoeed Tech Spec 3 3 b values, Cause undetermined. Setpoints recall br W/831014 ltr.
 HOUSTON, R W , DIEDERICH, 0 J Commonwealth Edison Co 83/10/14 KEPPLER, J O Region 3, Office of Director 3pp. 20923: 264 24X Fiche 50-373, 83/10/14, 8310270276
- 8310270490 LER 83-116/03L-0 on 830926, control rod drive (CRD) at core location 30-19 indicated overtrayel when withdrawn to full out position Causad by inner filter retainer spring damage due to excessive crud buildup W/831017 ltr WINTERHOFF, D.R., DIEDERICH, O.J. Commonwealth Edison Co. 93/10/17, KEPPLER, J.O. Region 3. Office of Director 3pp. 20722 008 24X Fiche 50-373,83/10/17,8310270490
- 8310270267 LER 83-117/03L-0 on 830930,RHR HX outlet valve failed to open manually or via motor operator. Cause unknown Task force committee assigned to resolve problem H/831019 itr PETERS, M A , DIEDERICH. 9 J. Commonwealth Edison Co. 83/10/19 KEPPLER. J © Region 3, Office of Director. 3pp 20923 253 24) Fiche 50-373.83/10/19.8310270267
- DOCKET 50-374 LABALLE COUNTY BIATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8310040105 Confirms B30921 telcon denying B30909 request to delete feedwater gump trip vibration monitoring test Unit 1 results do not ensure correct snubber installation in Unit 2 BCHMENCER, A Licensing Branch 2 B3/09/27 FARRAR, D L. Commonwealth Edison Co 2pp 20634 355 24X Fiche 50-374, B3/09/27, B310040105.

- 8310130196 Notification of 831007 site visit w/util in LaSalle County. It to discuss mpt prelicensing review BOURNIA: A Licensing Branch 2 B3/16/04 SCHHENCER.A Licensing Branch 2 4pp 20777 154 24x Fiche 50-374.83/10/04.8310130196
- 8310120007 Comments on util 830909 ltr re emergency power redundancy Preoperational Test PT-A103 Concurs w/conclusion that single set voltage readings for verification of transformer tops acceptable

 8CHHENCER, A Licensing Branch 2 83/10/05 FARRAR, D t.
 Commonwealth Edison Co 3pp 20750 297 24% Fiche 50-374,83/10/05,8310120007
- 8310130132 Forwards list of preoperational test deficiencies & time frame for completion Justification for deferral of resolution of items beyond fuel load date provided SCHROEDER, C W Communementh Edison Co 83/10/05 SCHWENCER, A Licensing Branch 2 Spp 20726 345 24X Fiche 50-374.83/10/05, 8310130132
- B310200273 Forwards schedules for equipment qualification test programs for facilities, per B10528 ltr Dates given for current qualification activities should be visued as "target-dates" & not as firm dates BARNES, P.L. Commonwealth Edison Co. 83/10/05 KEPPLER, J.G. Region 3, Office of Director 10pp. 20830.034 24X Fiche 50-000, 83/10/05, 8310200273
- 8310120433 Discusses proposed ray to primary containment vent & purge valve closure times Util will replace &/or modify eight 26-inch valves per unit to permit 15 s or less closure time Marked-up Tech Spec enci SCHROEDER.C W Commonwealth Edison Co 83/10/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 20698 298 24X Fiche 50-373,83/10/06,8310120433
- 8310170426 Forwards status of util request for approval to defer completion of certain preoperational tests, listed in encl to 830721 ltm, beyond fuel load SCHROBERR,C W. Commonwealth Edison Co. 83/10/06 DENTON,H R. Diffice of Nuclear Reactor Regulation, Director 5pp. 20783 318, 24% Fiche 50-374,83/10/06,8310170426
- 8310(8028) Forwards marked-up changes to Amend 63 to FSAR Tables
 14 2-130,14 2-124,14,2-114 & Figure 14 2-P re startup test
 program Summary of changes listed
 8CHROEDER,C. W. Commonwealth Edison Co. 83/10/13, DENTON,H R
 Office of Nuclear Reactor Regulation, Director 10pp 20807 025.
 24X Fiche 50-373,83/10/13,8310180281
- B310180397 Confirms B31003 telcon re util decision to perform feedwater pump trip vibration monitoring at two snubber locations in Unit 2 based on Unit 1 test results BCHROEDER.C W. Commonwealth Edison Co. 83/10/13 DENTON.H R Office of Nuclear Reactor Regulation, Pirector 1p 20803 317 24X Fiche. 50-373,83/10/13.8310180397
- B310240275 Documents NRC position re elements that must be considered in computation of acceptable closure time for containment purge & vent valves: in response to B31006 ltr Justification for interim operation requested BCHMENCER.A Licensing Branch 2 B3/10/18, FARRAR.D.L. Commonwealth Edison Co. 2pp. 20907.330 24x Fiche: 50-373, B3/10/18, B310240275
- 8310250684 Denies request for extension re submittal on Generic Ltr B3-28. "Clarification of Required Actions on Generic Implications of Balem ATMS Events." Required info should be submitted to stent practical by 831105 BCHMENGER. A Licensing Branch 2 B3/10/18 FARRAR, D L Commonwealth Edison Co 2pp 20908 349 24X Fiche 50-373,83/10/18,8310250684.
- 8310250293 Forwards Rev 10 to Offsite Dosm Calculation Henual for LaSalle & Guad Cities & Rev 9 to Offsite Dosm Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 0 BENNETT, C. J. Gommonwraith Edison Co. 83/10/21, CASE, E. G. Office of Nuclear Reactor Regulation, Director. 1p 20894.259 24% Fichs 50-000,83/10/21,8310250293
- --8310250298 Rev 10 to Offsite Dose Calculation Hanual for LaBalle & Quad Cities * Commonwealth Edison Co 83/09/30 44pp. 20894 260 24X Fiche 50-000,83/10/21,8310250293
- F Becurity, medical, emergency & fire protection plans
- 8310030229 Releases public version of revised emergency plan implementing procedure FELTON.U.M Division of Rules and Records, 83/09/28 Document Management Branch. 1p 20603.057 24X Fichs.50-273,83/09/28,8310030229.

- --8310030236 Public version of Rev 4 to Emergency Plan Implementing Procedure L2P 1700-2: "Station Employee List" & Commonwealth Edison Co 83/06/09 20pp 20603 058 24x Fiche 50-373.83/09/28,8310030229
- 8310040444 Forwards Rev 15 to security plan Rev withheld (ref 10CFR73 21) FARRAR,D L commonwealth Edison Co 83/09/30 Office of Norlear Reactor Regulation, Director 1p 20619 052 24X Fiche 30-373,83/09/30,8310040444
- B310180250 Forwards IE Insp Repts 50-3/3/83-36 & 50-374/83-35 on B30914-16 No noncompliants noted PAPERIELLO, C J Region 3, Office of Director B3/10/04 REED. C Commonwealth Edison Co 2pp 20802 332 24% Fiche 50-373, 83/10/04, 8310180350
- --8310180257 IE Insp Repts 80-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted Major areas inspected emergency preparedness program including licentee action on previously identified items & licensee audits PLOSKI, T Region 3. Office of Director 83/10/03 App 20802 334 24X Fiche 50-373.83/10/04.8310180250
- 8310110118 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20686 315 24X Fiche 50-373,83/10/05, 8310110118
- --8310110123 Public version of Rev 4 to Emergency Plan Implementing Procedure LZP-1700-3, "Station Phone List" W/830825 1tr & revised index HCL-YDAK, R H Commonwealth Edison Co 83/07/01 Office of Nuclear Reactor Regulation, Director 23pp 20686 316 24X Fiche 50-373,83/10/05,8310110118
- 8310170664 Responds to 830722 ltr re Rev 14 to security plan Portions of plan acceptable I tems from proviously approved plan should be followed for partions inconsistent w/10CTR50 54 Encl withheld (ref 10CFR73 21)
 SCHWENCER A Licensing Branch 2 83/10/12 FARRAR D L Commonwealth Edison Co 2pp 20779 293 24X Fiche 50-373,83/10/12,8310170664
- B310170707 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/13 Document Management Branch ip 20813 242 24% Fiche 50-373,83/10/13, B310170707
- --8310170711 Public version of Rev 3 to Emergency Plan Implementing Procedure LZP-1330-24, "Determination of Reactor Coolant Hydrogen Offgas Concentrations at High Radiation Sampling Sys " W/830928 ltr & receipt form HDLYOAK.R H Commonwealth Edison Co 83/09/16 38pp 20813 243 24X Fiche 50-373,83/10/13,8310170707
- 8310200416 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20859 233 24X Fiche 50-373,83/10/17, 8310200416
- --B310200424 Public version of Rev 5 to Emergency Plan Implementing Procedure LZP-1110-1, "Station Director (Acting Station Director)" W1931003 ltr.receipt form & 10CFR50 59 format for safety evaluation HCLY0AK.R H Commonwealth Edison Co 83/10/03 27pp 20859 234 24K Fichs 50-373,83710/17,8310200416
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/21 Document Management Branch ip 20737 216 24X Fiche 50-000,83/10/21, 8310270526
- --8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6, "Administration & Logistics Manager" W/831017 ltr & receipt form NELLIS:C A Commonwealth Edison Co 83/02/18 DENTON, H R NRC No Detailed Affiliation Olven 7pp 20937 217 24X Fiche 30-000,83/10/21,83102/0526
- 8310280206 Releases public version of revised emergency plan implementing procedures FELTON.JM Division of Rules and Records 83/10/25 Document Management Branch ip 20964 148 24X Fiche 50-373,83/10/25, 8310280206

- --8310280215 Public version of revised Emergency Plan Implementing Procedures ITP-1320-1 re augmentation of plant staffing. CZP-1550-11 re post-accident sampling equipment inventory & LZP-1700-2 re station employee list * Commonwealth Edison Co 83/07/25 43pp 20964 149 24% Fishe 50-373,83/10/25,8310280206
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J H Division of Rules and Records 83/10/25 Document Hanagement Branch 1p 20763 126 24X Fiche 50-000, 83/10/25, 8310280307
- --8310280314 Public version of revised generating stations emergency plan telephone directory GALLE.D P Commonwealth Edison Co 83/08/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, B3/10/25, 8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON, J N Division of Rules and Records 83/10/26 Document Management Branch ip 20962 266 24X Ficher 50-000, 83/10/26, 8310280191
- --83(0280207 Public version of Rev 1 to Emergency Plan Implementing Procedure EOF-18, "Emergency Operations Facility Activation"

 MORRER D Commonwealth Edison Co 03/08/02 50pp 20962.267
 24X Fiche 50-000,83/10/26,8310280191
- M. Utility Final Safety Analysis Report (FSAR) & emends
- 8310180249 Forwards affidavit of distribution of Amend 63 to FBAR BCHROEDER, C W Commonwealth Edison Co 83/10/10 DENTON H R Office of Nuclear Reactor Regulation, Director 2pp 20807.081 24x Fiche 50-373,83/10/10/8310180249
- O Inspection reports, IE Bulletine & correspondence
- 8310050493 Forwards IE Insp Repts 50-373/83-30 & 50-374/83-29 on 830725-0909 & natice of violation STREETER, J F Region 3, Office of Director 83/09/22 REED, C Commonwealth Edison Co 2pp 20631 350 24X Fichs 50-373, 83/09/22, 8310050493
- --9310050498 Notice of violation from insp on 830725-0909 STREETER, J F. Region 3, Office of Director 83/09/22 1p 20631 352 24X Fiche 50-373,83/09/22,8310090493
- --B310050502 IE Insp Repts 50-373/83-30 & 50-374/83-29 on B30725-0909 Noncompliance noted diesel generator RA not lined up for startup operation during performance of Preoperational Test PT-AP-203

 LANKSBURY, R D , DUPONT, 6 G , REYES, L A Region 3, Office of Director B3/09/22 5pp 20631 353 24X Fiche 50-373/83/09/22, 8340050493
- 8308300340 IE Info Notice 83-41, "Alleged Use of Stand-Ins for Welder Gualification Tests." Evc list encl JORDAN E L Division of Energency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intatab " Syx list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26.8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-I Differential Relays." Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Respense (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 118pp 20778:001 24X Fiche 50-000.83/09/26,8308300345
- 8308300349 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 B9 Evaluation." Svc list enct, JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310140213 Forwards IE Insp Repts 50-379/83-35 & 50-374/83-34 on 830804:09:08-11 & 15 No noncompliance noted STRECTER.J F. Region 3, Office of Director 83/09/29 REED.C. Commenwealth Edison Co 2pp. 20762.307 24X Fichs 50-373,83/09/29,83/0140213

- ~-8310140215 IE Insp Repts 50~373/83-35 & 50~374/83-34 on 830804,05,08-11 & 15 No noncompliance noted Major areas inspected review of previous open & unresolved items & followup on previous items of noncompliance CHOULES, N C . HASSE, R A . HUNTER, D R Region 3, Office of Director 83/09/28 App 20742 309 24X Fiche 50~373,83/09/29,8310140213
- 8310120290 Provides supplemental response to IE Bulletin 80-16 re misapplication of Rosemount transmitters All changeouts in NSSS sys for Unit 2 complete BARNES,P L Commonwealth Edison Co 83/10/04 KEPPLER,J Q Region 3, Office of Director 2pp 20692 339 24% Fiche 50-373,83/10/04, 8310120290
- 8310180250 Forwards IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16 No noncompliance noted PAPERIELLU,C J Region 3, Office of Director 83/10/04. REED,C Commonwealth Edison Go 2pp 20802 332 24X Ficher 50-373,83/10/04, 8310180280
- --8310180257 IE Insp Repts 50-373/83-36 & 50-374/83-35 on 830914-16.No noncompliance noted Major areas inspected gmergency preparedness program including licensee action on previously identified items & licensee audits PLOSKI.7, PHILLIPS.M P. Region 3, Office of Director. 83/10/03 App. 20802 334 24X Fiche 50-373,83/10/04,8310180250
- 8310200124 Forwards IE Mgt Heeting Repts 50-010/83-18.50-237/83-27.50-249/83-25.50-254/83-27.50-265/83-26.50-295/83-19.50-304/83-20.50-357/83-38.50-354/83-83.50-355/83-33.50-355/83-33.50-355/83-33.50-355/83-33.50-356/83-14 & 50-457/83-13 NGRELIUS.C E Division of Project & Resident Programs 63/10/04 REED.C Commonwealth Edison Co 2pp 20834 098 24X Fiche 50-000.83/10/04.6310200124
- --831020014B IE Mgt Meeting Repts 50-020/83-18.50-237/83-27.50-249/83-25. 50-254/83-27.50-245/83-24.50-275/83-19.50-304/83-20. 50-373/83-36.50-374/83-36.50-454/83-44.50-455/83-33. 50-456/83-14 & 50-457/83-13 NORELIUB.C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fichs 50-000.83/10/04.8310200124.
- 8310200159 Forwards IE Insp Repts 50-373/83-39 & 50-374/83-40 on 830915 No noncompliance noted LITTLE: W S Region 3, Office of Director 83/10/05 REED.C. Commonwealth Edison Co 2pp 20834 094. 24X Fiche-50-373,83/10/05, 8310200159
- --8310200164 IE Insp Repts 50-373/83-39 & 50-374/83-40 on 830915 No noncompliance noted Major areas inspected fatigue usage factors & stress calculations for main steam drain piping. DANIELBON.D H. MUFFETTIJ W. Region 3. D
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Sypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/10/07 Consolidated Edison Co. of New York, Inc 76pp 20827 213 24X Fiche, 50-000, 83/10/07, 8308300378.
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026, 24X Fiche 50-000,83/10/07,8308300752.
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl.

 JORDAN, E D Division of Emergency Preparadness & Engineering Response (Fost 830103) 83/10/11 Consolidated Edison Co., of New York Inc 117pp 21043 075 24X Fiche: 50-000,83/10/11,8308300759.
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761.
- 8310180187 Clarifies NRC position on procedures for admitting NRC personnel. Centified access list encl Update will be provided every 5 months.

 AXELSON, W.L. Region 3, Office of Director 83/10/14, REED, C, Commonwealth Edison Co 7pp 20809 085. 24X Fichs 50-373,83/10/14, 83:0180182
- 8310250356 Ack receipt of 831018 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-30 & 50-374/83-27 BIRETER, J F Region 3. Office of Director 83/10/20 REED, C. Commonwealth Edison Co ip 20899 119, 24X Fichs, 50-373, 83/10/20, 8310250356

- ~-8310250361 Responds to NRC 830922 itr re violations noted in IF Insp Repts 50-373/83-30 & 50-374/83-29 Corrective actions Procedure LGP-De-OI being clarified & step will be added to verify that ESF status panel checked after lineup completed FARRAR.D L. Commonwealth Edison Co. 83/10/18 KEPPLER.J 6 Region 3. Office of Director 2pp 20898 120 24X Fiche 50-373,83/10/20,8310250356
- S Reportable occurrences, LERs & related correspondence
- 8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards mati listed in App A, responsive to Items 1,2 & 4 DDE should be contacted for matl requested in Item 3 of ltr FELTON. J M Division of Rules and Records 83/06/14. HIATT, 8 & Dhio Citirens for Responsible Energy 3pp 20706 002 24% Fiche 50-000,83/06/14,8310110430
- --8310110478 Responds to B30413 ltr requesting info re use of foleign matls on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
 FARRAR.D L. Commonwealth Edison Co. B3/04/22 KEPPLER.J & Region 3. Office of Director 4pp. 20706-063 24X
 Fichs 50-000.83/06/14.8310110430
- 8310210056 Final Deficiency Rept 83-06 re AGCO splenoid valves in control rod drive sys Initially reported on 830912 Valves w/defective solenuid plunger housings replaced & spare parts in invantory examined Plant operable SCHROEDER.C W Commonwealth Edison Co 83/10/12 KEPPLER, J & Region G. Office of Director 2pp 20855 284 24X Fiche 50-374,63/10/12.8310210056
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8310310063 FOIA request for documents re const & operation of C-E plants List of info required submitted BELL.N Coalition for Safe Power 83/03/31 Office of Administration ip 20598 173 24X Fiche 50-000.83/03/31, 8310310063
- 8310070140 Discusses util deferral of plant-referenced simulator in training program NRC may reconsider position on training program due to deferral Proposed rule under consideration requiring use of simulator
 EISENHUI.D © Division of Licensing 83/09/22 COLLINS.J T. Region 4. Defice of Director. Spp 20680 344 24X
 Fiche: 50-382,83/09/22,8310070140
- --B310070144 Advises that util must provide plant-specific simulator on more timely basis than presently called for Simulator will improve training program COLLINS.J.T. Region 4. Office of Director B3/07/11, EISENHUT.D 9 Division of Licensing 2pp 20680 348 24X Fiche 50-382,83/09/22,8310070140
- 8310030060 Forwards Amend 33 to QL application.consisting of Amend 33 to FBAR.

 LEDDICK, R. B Louisiana Power & Light Co 93/07/28 Office of Nuclear Reactor Regulation. Director 2pp 20574 345 24X Fiche: 50-382,83/07/28,8310030060
- --8310030063 Amend 33 to OL application. LEDDICK/R 8. Louisiana Power & Light Co 83/09/28 Ip 20594-347 24X Fiche 50-382,83/09/28,8310030060
- 8310200171 Forwards for comment focumentation supporting no adverse effect determination for two archeological sites sligible for Natl Register of Historic Places KNIGHTON, O H. Licensing Branch 3. 83/09/28 WALL, L. S. Advisory Council on Historic Preservation. 6pp. 20844, 172 24X Fichs. 50-382, 83/09/28, 8310200171
- 8310270254 Submits documentation of no adverse effect determination re two archeological sites eligible for Natl Register of Historic Places. Concurred in by Advisory Council on Historic Preservation on B31018 KNIGHTON, 6 W Licensing Branch 3 83/09/28 HALL, L 9 Advisory Council on Historic Preservation. 2pp 20923:280, 24X Fiche: 50-382,83/09/28,6310270254
- 8308300352 Board Notification 83-144 provides evaluation & recommendations re need for FORVs on C-E plants. Info will be presented to ACRs in Oct 1983 NOVAK.T.M Assistant Director for Licensing 83/09/29 Atomic Safety and Licensing Appeal Panel. 4pp 20601:230 P4X Fichs: 50-000.83/09/29,8308300352

- --8310030407 Informs that "Staff Evaluation of Need for Rapid Depressurization Capability for C-E Plants" & Commission 830914 transcript & slides from San Onofre briefing should be transmitted to boards & parties for C-E plants EISENHUT. D & Division of Licensing 83/09/27 NBVAK, T M Assistant Director for Licensing ip 20601 334 24% Fiche 50-000,83/09/29,8308300352
- 8310040372 Forwards response to NRC 830826 request for add1 into Argus Chemical Corp will be contacted re effective date of ltr New GAXT Terminal Corp ltr will be submitted by 831231 DRUMMOND, F. J. Louisiana Power & Light Co. 83/09/29 KNICHTON, C. W. Licensing Branch 3 4pp. 20622 344 24X Fiche 56-382,83/09/29,8310040372
- 83:0040559 Forwards "Independent Safety Engineering Oroup Review of NAC Concerns" & Harstead Engineering Assoc rept. "Analysis of Cracks & Water Seepage in Foundation Mat." in response to NAC 830804 ltr
 CAIN.J M Louisiana Power & Light Co 83/09/29 DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20621 311 24X Ficho 50-382,83/09/29,8310040559
- --8310040545 "Independent Safety Engineering Oroup Review of NRC Concerns."

 DRUMMOND, F. J., ALSWORTH, M., CARVER, A. M. Louisiana Power & Light Co. 83/09/29 Sipp. 20621 313 24X Fiche 50-382,83/09/29, 8310040559
- --8310040573 "Analysis of Cracks & Water Seepage in Foundation Nat ' BU BOUCHET A V . UNSAL A I . HARSTEAD 0 A Harstead Engineering Associates Inc 8304-1 83/09/19 119pp 20422 002 24X Fiche 50-382,83/09/29,8310040559
- B310070247 Application to amend CPPR-103, extending const completion date to 840930 Delay due to exhaustive prerequisite testing, preoperational testing, troubleshooting & retesting to meet acceptance criteria

 LEDDICK,R B Louisiana Power & Light Co B3/09/29 EISENHUT.D @ Division of Licensing 4pp 20698 331 24X Fiche 50-382,83/09/29,8310070247
- 8310070235 Advises of installation of removable section of JBS diesel generator room in south wall Installation of wall will be documented in Amend 34 to FSAR BRUMMOND,F J Louisiana Power & Light Co 83/10/03 KNIGHTON.6 N Licensing Branch 3 12pp 20657 070 24X Fiche 50-382,83/10/03, 8310070235
- 8310110280 Forwards util application for amend to CP to extend latest completion date from 831030 to 840930 Target date for fuel load date is 840931 BLAKE,E.L. Shaw, Pittmen, Potts & Trowbridge BLAKE,E.L. Louisiema Power & Light Co 83/10/04 KOHL,C Atomic Safety and Licensing Board Panel JOHNSTON, WR, WILDER, HA Atomic Safety and Licensing Appeal Panel 7pp 20665 327 24X Fiche 50-382,83/10/04,8310110280
- 8310200070 Forwards INEL technical evaluation repts summarizing activities of EGRT during Bi0914-1B & 830830-0703 seismic & dynamic qualification program audit W/o repts KNIGHTON, 0 W Licensing Branch 3 B3/10/04 LEDDICK, R S Louisiana Power & Light Co 2pp 20844 274 24X Fiche 50-382, 83/10/04, 8310200070
- --8309300044 Forwards INEL technical evaluation repts summarizing activities of seismic & dynamic qualification program for mechanical & electrical equipment during facility audit NGONAN.V B Equipment Qualification Branch 83/09/20 KNIOHTON,Q Licensing Branch 3 Jp 20844 276 24X Fiche: 50-382,83/10/04.8310200070
- 8310120226 Advises that util will participate w/INPO & C-E Owners Group in addressing certain requirements of Generic Ltr 83-28, "Required Actions Based on Generic Implication of Salem ATMB Events." Initial response expected by 840115 COOK, K W Louisiana Power & Light Co 83/10/05 EISENHUT, D C Division of Licensing. Ip 20693, 134 24X Fiche 50-382, 83/10/05, 8310120226
- 8308300771 Board Notification 89-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solenoid valves EISENHUT.D 0. Division of Licensing 83/10/06 PALLADING N J Commissioners 3ipp 20818 001 24X Fiche. 50-000.83/10/06.8308300771
- 8310170869 Forwards revised App A notes to Harstead Engineering Assoc rept, distributed on 830920 Svc list and CHURCHILL, B W Show Pittman, Potts & Troubridge CHURCHILL, B W Louisiana Power & Light Co. 83/10/12 KOHL, C N. JOHNSON, W R. WILBER, H. A Atomic Safety and Licensing Appeal Panel Spp 20780 324 24X Fiche 30-382,83/10/12,83/10/569

- 8310280002 Forwards, for review, "Analysis of Cracks & Mater Seepage in Foundation Mat." covering design adequacy of basemat Design of mat extremely conservative Addl analysis not required CAIN.J M Louisiana Power & Light Co 83/10/20 DEYBUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20935 085 24X Fiche 50-382,83/10/20,83102800002
- --COLO2DODOO "Analysis of Cracks & Water Seepage in Foundation Mat" DU SQUCHET, UNBALA I > HARBTEAD, 0 A Harstead Engineering Associates, Inc. 8304-2 87/10/12 104pp 20735 087 24X Fiche 50-382,83/10/20,8310280002
- 8310310091 Forwards approved nuclear operations organization charts Charts provide means for onsite & offsite mgt & describe technical personnel resources necessary to complete const & conduct preoperational/stantup testing DRUMMOND,F J Louisiana Power & Light Co 83/10/24 KNIGHTON,G W Licensing Uranch 3 ip 20930 344 24X Fiche 50-382,83/10/24, B310310091
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310120072 Discusses actions to be taken to resolve turbine missile issue identified in SEER 4. Section 1 9. including development of turbine & valve maint programs described in NUREG-0800 for main turbine throttle & governing valves DRUMHOND. F J Louisians Power & Light Co 83/10/05 KNIGHTON, 6 W Licensing Branch 3 2pp 20677 161 24X Fiche 50-382,83/10/05, 83101200/2
- 8310250496 Advises that deficiency re failure of CPC software to apply failed CEAC penalty factor to local power density corrected, per NAC request liem should be closed out in next suppl to SER CDOK.X H Louisiana Power & Light Co 83/10/20 KNIGHTON, 0 W Licensing Branch 3 2pp 20097 125 24X Fiche 50-382,83/10/20, 8310250496
- F Security, medical, emergency & fire protection plans
- 8310310367 Responds to NRC 830827 ltr re IE Emergency Preparedness Appraisal Rept 50-382/83-08 Emergency plan & implementing procedures will be revised to reflect flow of authority & responsibility of the procedure of the prepared of the procedure of the prepared of the procedure of the procedu
- 3310310315 Responds to NRC 830527 ltr re IE Emergency Preparedness Appraisal Rept 50-382/83-08 Corrective actions two dedicated vehicles will be provided for field monitoring teams & two-way radios will be installed in vehicles DRUMMOND.F J Louisiana Power & Light Co 83/08/30 MADSEN.C L Region 4. Optice of Director App 20759 066 24X Fiche. 50-382, 63/08/30, 6310310315
- 6310060357 Submits amended implementation schedule for Suppl 1 to NUREQ-073/ requirements for safety parameter display sys & Reg Quide 1 47 Listing of parameters available for display BANKHOND, F J Louisiana Power & Light Co 83/09/29 KNIGHTON.6 ch 3 3pp 20444 107 24% Fiche.80-382.83/09/29. Licensing Branch 3 8310060357
- P Adjudicatory correspondence
- 3310040233 Answer apposing Jaint Intervenors B30722 motion to reopen record re Contention 22 on safety-related concrete Heavy burden in seeking to reopen record not mot CHURCHILL, B H. Louisiane Power & Light Co. CHURCHILL, B W. Shaw, Pittman. Potts & Trowbridge 83/09/30 Atomic Bafety and Licensing Appeal Panel 32pp 20613 224 24X Fiche 50-382. B3/09/30,8318040233
- --0310040239 Affidavit of JL Ehas; supporting util opposition to Joint Entervenors motion to reopen on safety-related concrete Cracks expected to form in concrete mattenabling transfer of tensile load from concrete to embedded steel.

 EMASI.J. L. Louisiana Power & Light Co EHABZ.J.L. Ebasco Services. Inc (subs of Engench Corp) 63/09/27 14pp 20613 256 24% Fiche 50-382,83/09/30,6310040233
- --B310040245 Affidavit of WF Oundaker supporting util opposition to Joint Intervenors motion to respen record on safety-related concrete, Corrosion of reinforcing steel in concrete mat will not occur to significant degree Certificate of Svc enc) GUNDAKER, WF Louisiana Power & Light Co GUNDAKER, WF Ebasco Services, Inc. (subs. of Ensert Corp.) B3/09/27 150pp 20613, 271 24% Fiche 50-382, 83/09/30, 8310040233

- B310110280 Forwards util application for amend to CP to extend latest const completion date from B31030 to B40930 Target date for fuel load date is B40331 fuel load date is 840331
 BLAKE.E L Shaw, Pittman. Potts & Trowbridge BLAKE.E.L Louisiana
 Power & Light Co B3/10/04 KOHL.C Atomic Safety and Licensing
 Board Panel JOHNSTON.W R. WILBER.H A Atomic Safety and Licensing
 Appeal Panel 7pp 20665 329 24X Fichs 50-382,83/10/04.
- 831017047B Motion for further extension until 831121 to respond to Joint Intervenors 830725 motion to reopen Contention 22 in light of cracking & water seepage in concrete basemat Certificate of Svc encl TURK. S E Hearing Branch i 83/10/07 Atomic Safety and Licensing Appeal Panel 8pp 20783 287 24% Fiche 50-382,83/10/07,8310170478
- -8310170484 Affidavit of J Ma & R Pichumani re cracking & water seepage MAIJ PICHUMANI, R Structural & Osotechnical Engineering Branch. 83/10/07 Spp 20783 295 24X Fiche 50-382,83/10/07,8310170478.
- 8310170398 Response to NRC 831007 motion for further extension to 831121 to file response to Joint Intervenors motion to reopen contention Motion not opposed Certificate of Svc encl BLAKE, E. Louisiana Power & Light Co BLAKE, E. G. Blaw, Pittman, Potts & Troubridge 83/10/12 Atomic Safety and Licensing Appeal Panel 5pp 20785 075 24X Fiche 50-382,83/10/12,8310170398
- 8310170569 Forwards revised App A notes to Harstead Engineering Assoc rept distributed on 830920 Svc list encl CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Louisiana Power & Light Co B3/10/12 KDHL, C N , JOHNSON, W R., WILLBER, H A Atomic Bafaty and Licensing Appeal Panel 5pp 20780 324 24% Fiche 50-382,89/10/12.8310170369
- 8310190212 Forwards Harstead Engineering Assoc. Inc rept re design adequacy of foundation basemat Applicant has not yet reviewed rept Design of foundation mat conservative Cracking insignificant M/o rept Svc list encl Related correspondence CHURCHILL, B H Shaw, Pittman, Potts & Trowbridge CHURCHILL, B H Louisiana Power & Light Co 83/10/14 KOHL, C N, JOHNBON, W R. WILBER, H A Atomic Safety and Licensing Appeal Panel App 20818 071 24X Fiche 50-382,83/10/14.8310190212
- B310310195 Informs that DR Lewis formerly ASLB participant in OL proceeding, began working for author on B31024.DR Lewis will not participate in OL proceeding Certificate of Svc enci BLAKE,E L Shaw, Pittman, Potts & Trowbridge BLAKE,E.L Loui Power & Light Co 83/10/26 Commissioners 4pp 20988 356. Fiche 50-382,83/10/26,8310310195
- H General correspondence
- 8310070001 Informs that effective immediately.FJ Drummond, nuclear svcs manager & KW Cook, nuclear support & licensing manager, authorized to sign correspondence to NRC refacility, except under 10CFR80 30(b) requiring corporate officer signature LEDDICK-R S Louisiana Power & Light Co 83/09/30 KNICHTON, 0 W Licensing Branch 3 lp 20651:001 24X Fiche 50-382,83/09/30,8310070001
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 8310030040 Forwards Amend 33 to DL application, consisting of Amend 33 to FSAR. LEDDICK.R S Louisiana Power & Light Co. 83/09/28 Office of Nuclear Reactor Regulation, Director 2pp. 20594 345 24X Fiche: 50-382,83/09/28,8310030060
- -8310030043 Amend 33 to OL application. LEDDICK,R 8 Louisiana Power & Light Co 83/09, 20574 347 24X Fiche 50-382,83/09/28,8310030060 83/09/28 1p
- --8310030047 Amend 33 to FBAR
 * Louisiana Power & Light Co 83/09/30 2191pp 20594 351 24%
 Fiche 50-382,83/09/28,8310030060
- B310060233 Certifies svc of FSAR Amend 33 on B30930, * Louisians Fower & Light Co. B3/10/03. ip. 20647:098 Fiche 50-382,83/10/03:8310060233

- Q Inspection reports: IE Bulletins & correspondence
- 8310110040 FDIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions based on SALP reviews
 RIDENHOUR, R Combit 83/05/04 GRIMSLEY, D C NRC No Detail Affiliation Given 2pp 20713 304 24X Fiche 50-382,83/05/04,8310110040 NRC - No Detailed
- 8310110044 Responds to FOIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions re SALP reviews Forwards App A documents FELTON.J M Division of Rules and Records 83/07/20 RIDENHOU Gambit 2pp 20713 308 24X Fiche 50-000, 83/07/20, 6310110044
- ~-8112170188 Advises that Cycle 2 of systematic evaluation of licensee performance will cover Jul 1980-June 1981 Regional board meetings will be conducted Jul-Dec 1981 All Cycle 2 NRR performance evaluation enci EISEMHUT. D 9 Division of Licensing 81/06/04 Division of Engineering 4pp 20713 310 24X Fiche 50-382.83/07/20, 8310110044
- --8208230434 Requests input & appropriate comments.re systematic assessment of licensee performance, (SALP) for Aug 1981-Jul 1982 Response required by 820806 SALP criteria encl BLACK,8 Licensing Branch 3 82/08/03 Licensing Branch 3 13pp 20713 324 R4X Fiche 50-382.63/07/20.8310110044
- Branch 3 82/08/11 EISENHUT, D 0 Di 20713 331 24% Fiche 50-382, 83/07/20, of Licensing 5pp 8310110044
- --8210050447 Forwards final NRR input for Cycle 3 systematic assessment of licensee performance Performance is rated Category 2 Licensee resources adequate although staffing could be improved BLACK. 8 Operating Reactors Branch 3 82/08/23 EISENHUT Division of Licensing 5pp 20713 336 24X Fichr 50-382, 83/07/20,8310110044 EISENHUT, D Q
- --8310110051 SALP rept for Jul 1980 June 1981. Const allegations SEYFRIT, K V Region 4, Office of Director 83/ 20713 314 24% Fiche 50-382,83/07/20,8310110044 83/07/20. 10pm
- 8310310367 Responds to NRC 830527 ltr re IE Emergency Preparedness Appraisal Rept 50-382/83-08 Emergency plan & implementing procedures will be revised to reflect flow of authority & procedures will be revised to reflect flow of edinority a responsibility DRUMMOND.F.J. Louis.ans Power & Light Co. 83/07/29 MADSEN.Q.L. Region 4. Office of Director 76pp 20959 091 24X Fiche 50-382.83/07/29.8310310367
- 8310060379 Forwards IE Insp Rept 50-382/83-22 on 830627-0701 No noncompliance noted

 MADSEN.9 L Region 4. Office of Director 83/08/19 MAURIN, L V
 Louisiana Power & Light Co 2pp 20646 038 24X

 Fiche 30-382, 83/08/19, 8310060379
- --B310040391 IE Insp Rept 50-382/83-22 on B30427-0701 No noncompliance noted Major areas inspected radwaste program & transportation activities, air cleaning sys.instrumentation Tech Specs.procedures & controls for effluent releases BAER, R E , MURRAY, B , CROSSMAN, W A, Region 4, Office of Director B3/08/10 12pp 20446 040, 24X Fiche 50-382,83/09/19,8310040379,
- 8310060459 Forwards IE Insp Rept 50-382/83-23 on 830711-15 No MADSEN, 9 L Region 1: Office of Director 83/08/22 MAURIN, L V Louisiane Power & Light Co. 2pp 20641 019 24X Fiche 50-382, 83/08/22 8310060459
- --8310060464 IE Insp Rept 50-382/83-23 on 830711-15 No noncompliance noted. Hajor areas inspected: preoperational insp of radiation protection program & actions taken on 12 open items in IE Insp Repts 50-382/82-04 & 50-382/83-04.

 CHANEY, H D . HURRAY, B . CROBSHAN, W A Region 4, Office of Director, 83/08/09 iipp 20641 021 24X Fiche 50-382,83/08/22, 8310060459.
- 310040153 Forwards IE Insp Rept 50-382/83-27 on 830802-05 No 310040153 Forwards IE Insp Rept 50-392/03-2/ c noncompliance noted HADBEN.9.L. Region 4, Office of Director E Louisiana Power & Light Co. 2pp. 20608.028 Fiche 50-382,83/08/27,8310040153. 83/08/29. LEDDICK, N S

- --8310040157 IE Insp Rept SO-382/83-27 on 830802-05 No nuncompliance noted Major areas inspected 10CFR90 55(e) reporting program & repts DBERG, C R. CROSSMAN, W A Region 4. Office of Director DBCOSSMAN, W A Region 4. Office of DBCOSSMAN, W A Region
- 8310310315 Responds to NRC 830527 ltr re IE Emergency Preparedness Appraisal Rept 50-382/83-08 Corrective actions two dedicated vehicles will be provided for field monitoring teams & two-way radios will be installed in vehicles DRUMMOND, FJ Louisiana Power & Light Co 83/08/30 MADSEN, G I Region 4, Office of Director 4pp 20939 066 24X Fiche 50-382,83/08/30,8310310315
- 8310040591 Forwards response to 830727 questions re NRC inquiry twam 830628 meeting in New Orleans.LA Inquiry team 830714 rept on GA allegations & IE 830804 status rept encl PALLADING.N J Commissioners 83/09/08 MARKEY.E J House of Rep. Interior & Insular Affairs 7pp 20461 160 24X Fiche 50~382,83/09/08.8310040591
- ~~8310060593 Forwards inquiry team rept re GA allegations Meeting to discuss followup requested

 DEYOUNG, R C Director's Office, Office of Inspection and

 Enforcement 83/08/04 CAIN, J M Louisiana Power & Light Co

 ip 20661 183 24% Fiche, 80-382,83/09/08,8310060591
- --8310060594 Requests info re circumstances of June 1983 interviews w/ARC investigation team
 HARKEY,E J Hause of Rep , Interior & Insular Affairs
 PALLADING,N J Commissioners ip 20661 192 24X
 Fiche 50-382, 83/09/08, 8310060591
- 830B300340 IE Info Notice 83-61. "Allaged Use of Stand-Ins for Welder Qualification Tests " Svc list onel JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Texto Qas DBB000492 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300,449
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 5A-1 Differential Relays " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche, 50-000, 83/09/26, 83083003045
- 8308300347 IE Info Notice 83-44, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation" Byc list enci JGRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310310402 Forwards IE Insp Rept 50-382/83-24 on 830701-0831 Mg noncompliance noted
 MADBEN.G L Region 4. Office of Director 83/10/05 LEDDICM.R G
 Louisiane Power & Light Co 2pp 20759 287 24X
 Fiche 50-382,83/10/05,8310310402
- --B310310408 IE Insp Rept 50-382/83-24 on 830701-0831 No noncompliance noted Major areas inspected allegations, preoperational test witnessing & structural steel erected by American Bridge nov. to Other CONSTABLE, 0 L , FLIPPO, T A , CROSSMAN, W A Region 4. Office of Director 83/09/30 Bpp 20959 289 24% Fiche 50-382,83/10/05.8310310402 Div. US Steel
- 8310130262 Ack receipt of 830824 ltr informing NRC of steps taken to correct violations noted in It Insp Rept 30-382/83-21 MADSEN.9 L Region 4, Office of Director 83/10/06 MAURIN.R B Louisiana Power & Light Co ip 20723 221 24X Fichs: 50-382,83/10/06.8310130262
- --8310130266 Responds to NRC 830726 itr re violations noted in IE Insp. Rept 50-382/83-21 Corrective actions change to Procedure MM-8-014 implemented to address new stud installation/removal tool. Maint supervisors instructed DRUMMOND, F. J. Louisiana Power & Light Co. 83/08/24. MADBEN. Q l. Region 4. Office of Director. 2pp 20723 222 24X Fichs 50-382,83/10/06,8310130262.
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Ficher 50-000,83/10/07.8308300378

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critica)
 Facility " Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co. of New
 York, Inc. 77pp. 20892 026 24X Fiche 50-000,83/10/07.8308300752
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Caused Production of Noxious Gases " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 83083007&i IE Info Notice B3-&B, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

S Reportable occurrences. LERs & related correspondence

- 8310030259 Fifth interim const Deficiency Rept 66 re GE-type AKR breakers & C-clips possibly falling off Completion of corrective action & review of supporting documentation scheduled for B31014 Final rept by B31102 DRUMMOND, F J Louisiana Power & Light Co B3/09/15 COLLING, J T Region 4. Office of Director 2pp R0591 058 24X Fiche 50-382,83/09/15,8310030259
- 8310030363 Third interim significant const Deficiency Rept 74 re damage to pressurizer heaters during hot functional testing A11 30 pressurizer heaters replaced Welding & NDE testing performed por ASME code Next rept by 831014 DRUMHOND:F J Louisiana Power & Light Co 83/09/15 COLLINB, J T Region 4. DPfice of Director 1p 20591 282 24% Fiche 50-382,83/09/15,8310030303
- B3160303AB Fourth interim significant const Deficiency Rept 79 re unqualified components in hydrogen analyzers Completion of corrective action delayed until 831014 due to design changes Final rept will be submitted by 831110
 DRUMMOND, F J Louisiana Power & Light Co 83/09/15 COLLINS, J T Region 4. Office of Director 1p 20593 039 24X
 Fiche 80-382,83/09/15,8310030368
- 8310030458 Second interim significant const Deficiency Rept 86 re
 burned 3A-8 safety inverter output capacitor wiring
 Supporting documentation Under review Mexpected completion
 by 831007 Final rept expected by 831017
 DRUMHOND, F. J. Louisiana Pawer & Light Co. 83/09/15 COLLINB, J. T.
 Region 4. Office of Director ip 20601 058 24X
 Fiche 50-362,83/09/15,8310030468
- B3100304B2 Final significant const Deficiency Rept 33 re chilled water pipsing supports Caused by overstressed welds & structures & seismic span criteria being exceeded Designs modified DRUMMOND, F.J. Arkansas Power & Light Co. 83/09/15 COLLINS, J. T. Region 4, Office of Director 30p. 20601 071 24X Fiche. 30-382, 83/09/15, 8310030482.
- 8310030507 Final significant const Deficiency Rept 60 re turnover documentation & inadequate hanger weld problems T-B Completion & documentation review scheduled for 831214 Final rept will be submitted by 840116.

 DEDITIONED, F. J. Louisiana Power & Light Co. 83/09/15 CULLINS, J. T. Region 4. Office of Director ip 20601 169, 24X Fiche 50-382,83/09/15,8310030507
- 9310030540 Final Deficiency Rept 123 re fusion of conductor insulation, rendering insulation values indeterminate Initially reported on 830816 Deficiency not reportable per LOCFR50 55(e)
 DRUPHOND, F. J. Louisiana Power & Light Co. 83/09/15 COLLINS, J. T. Region 4. Office of Director 2pp 20401 192 24X
 Fiche 50-362,83/09/15,8310030540
- 83i0040912 Final deficiency rept re Potentially Reportable Deficiency 121 concerning Anthor Darling Valve 28I-V3268 circular indication Initially reported on 830816 Radiographic exam revealed no nonconformances Item determined not reportable ORDAMIND, F. J. Louisiana Power & Light Co. 83/09/15 CDLLINS, J. T. Region 4, 0ffice of Director. 2pp. 20623 094 24% Fiche 50-382.83/09/15.8310040512
- 6310040134 Interim rept re significant coust Deficiency 42-Ri on HMA auxiliary relays Review & verification of supporting documentation scheduled for completion by 831006 Final rept will be submitted by 831020 GERRETS, TF. Louisiana Power & Light Co 83/09/26 COLLING, J. T Region 4, Office of Director 2pp 20408 006 24X Fiche 50-382, 83/09/24, 8310040134

- 8310190151 Final rept re Significant Const Deficiency 53 concerning possible failure of GE-type MFA relays Initially reported on 830725 Levan coil spools in HFA relays replaced by coils made of Tefrel GERRETS. TF Louisians Power & Light Co 83/09/30 COLLLINS. J T Region 4. Office of Director 3pp 20820 224 24X Fiche 50-382,83/09/30,8310190151
- 8310210258 First interim significant const Deficiency Rept 88 re refueling water storage pool liner/nozzle overstressed condition Restraints will be added to deficient nozzles to reduce nozzle load on pool liners Next rept by 831215 GERRETB, T F Louisiana Power & Light Co 83/10/07 CDLLINS, J. T Region 4, Office of Director 4pp 20848 277. 24X Fische 50-382,83/10/07,8310210258
- 8310210290 First interim significant const Deficiency Rept 89 re QE AK50/AK30 switchgear breakers cam sheft bearing retaining ring Interim corrective action taken to prevent bearing movement until repair developed by GE Next rept by 840120 GERRETS.T F Louisiana Power & Light Co 83/10/07 COLLINS, J. T. Region 4, Office of Director 3pp 20835, 245, 24X Fiche 50-382,83/10/07,8310210270
- 8310210293 Fifth interim significant const Deficiency Rept 70 re QC 480-volt trip cells not dropping out after tripping Two of 86 breakers remain to have design change installed & verified Final rept will be submitted by 831221 GERRETS.T F Louisiana Power & Light Co 83/10/07 COLLING, J T. Region 4. Office of Director 2pp 20855-210. 24X Fiche 50-382.83/10/07,8310210293
- 8310280012 Sixth interim deficiency rept of Bignificant Const Deficiency 57 re inadequate instrumentation & control installations & turnover documentation Initially reported on 830729 Final rept will be submitted by 840215 GERRETS.T F Louisiana Power & Light Co 83/10/13 COLLINS.J T Region 4. Office of Director 2pp 20934 107 24X Fiche 50-382.83/10/13.8310280012
- 8310280069 Fifth interim significant const Deficiency Rept 77 re inadequate containment purgs valve closure time & flow rate Review of supporting documentation will be completed by 831126 Final rept will be submitted by 831215 GERRETS, T. F. Louisiana Power & Light Co. 83/10/13 COLLING, J T. Region 4, Office of Director 2pp 20933 340 24X Fiche 50~382.83/10/13.6310280069
- 8310310292 Third interim rept re Significant Const Deficiency 82 concerning bent control element assembly rods Initially reported on 830816 Rods evaluated & reworked by C-E & returned to facility Final rept will be submitted by 840115 OERRETS.T F Louisiana Power & Light Co 83/10/14 COLLING.J. Y Region 4, Office of Director 2pp 20961 232 24X Fiche 50-382.83/10/14.8310310292.
- 8310310300 First interim rept re Significant Const Deficiency 90, "Electrical Conduct Overstressed " Initially reported on 830916 All conduct installations will be physically verified Next rept by 840215 OERRETS, T F Louisiana Power & Light Co 83/10/14 COLLINS, J. T. Region 4, Office of Director, 3pp 20960 359 24X Fiche: 50~382,83/10/14,8310310300

U Congressional/Executive Correspondence

- 8310060571 Forwards response to 830727 questions re NRC inquiry team 830628 meeting in New Orleans, LA. Inquiry team 830714 rept on GA allegations & IE 830804 status rept encl PALLADING, N J. Commissioners 83/09/08, MARKEY, E. J. House of Rep., Interior & Insular Affairs, 7pp 20661 IAO 24X Fiche 50-382,83/09/08,8310040591.
- --9310060593 Forwards inquiry team rept re GA allegations Meeting to discuss followup requested DEYOUND, R C Director's Office, Office of Inspection and Enforcement 83/08/04, CAIN.J M. Louisiana Power & Light Co. ip 20461
- --8310060594 Requests info re circumstances of June 1983 interviews w/MRC investigation team HARKEY,E J House of Rep., Interior & Insular Affairs. 83/07/27. PALLADINO,N J. Commissioners ip 20661 192 24X Fiche 50-382,83/09/08,8310060591.

- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1 F Security, medical, emergency & Pire protection plans
- 831004048: Releases public version of revised emergency plan implementation procedure FELTON.U M Division of Rules and Records 83/09/22 Document Management Branch 1p 20460 086 24X Fichs 50-387,83/09/22, 831004048:
- --8310060486 Public Version of Rev 2 to Emergency Plan Implementation Procedure EP~IP~002, "Emergency Mgt Notifications " M/830915 ltr & Rev 24 to table of contents KAISER, H Pennsylvania Power & Light Co 83/09/15 SCHWENCER, A NRC No Detailed Affiliation Given 75pp 20660 087 24X Fichs 50-387,83/09/22,8310060481
- 8310120037 Forwards Amend 15 to License NPF-14 & safety evaluation Amend incorporates Rev 2 to fire protection review rept & corrects typographical errors in Tech Spec 4 11 2.1 2-1 SCHWENCER, A Licensing Branch 2 83/09/28 CURTIS, N W Pennsylvania Power & Light Co. 3pp 20749 183 24X Fichs 50-387,83/09/28,8310120037
- --8310120041 Amend 16 to License NPF-14. incorporating Rev 2 to fire protection review mept & correcting typographical errors in Tech Spec 4 ii 2 i.2-i, "Radioactive Gaseous Waste Sampling & Analysis Program."

 ETSENNUT, D 0 Division of Licensing 83/09/28 21pp 20749 186 24X Fiche 50-387,83/09/28,8310120037
- 8310170046 Requests publication of FR notice of consideration of issuance of amend to License NPF-14 & proposed NBHC determination & opportunity for hearing refire protection review rept.NSHC determination available in Central Files SCHMENCER.A Licensing Branch 2 83/09/28 MILLER.J R Operating Reactors Branch 3 4pp 20798.060 24x Fiche 50-387,83/09/28.
- 8310060211 Forwards 8AR for safety parameter display sys.in response to Generic Ltr 82-33.per NUREG-0737. Suppl 1 & util 830415 ltr Implementation schedule for safety parameter display sys encl CURTIS.N W Pennsylvania Power & Light Co 83/09/30 8CHWENCER, A Licensing Brench 2. 98pp 20646:279 24X Fiche 50-387.83/09/30. 8310040211
- 8310060533 Releases public version of revised emergency plan implementation procedure FELTON.J M Division of Rules and Records 83/07/30 Document Management Branch 1p 20661 334 24X Fiche 30-387,83/07/30,8310060533
- ~-8310060538 Public version of Rev 2 to Emergency Plan Implementation Procedure EP-IP-007, "Personnel Assembly & Accountability " W/B30720 itr & Rev 20 to table of contents KEISER, H Pennsylvania Power & Light Co. 83/07/18 SCHWENCER, A. NRC No Detailed Affiliation Given 2009 20661 335 24X Fiche: 50-387, 83/09/30, 8310060533
- 8310110091 Releases public version of revised emergency plant implementing procedure FELTON.J M Division of Rules and Records 83/10/05 Document Hanagement Brench. 1p. 20487.337. 24X Fiche 50-387,83/10/05,8310110091
- --8310110094 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-018, "Emergency Call-in & Communication " W/830831 ltr & receipt form * Pennsylvania Power & Light Co 83/08/31, SCHHENCER, A. NRC -- No Detailed Affiliation Oliven 13pp. 20687 338 24X Fiche 50-387,83/10/05,8310110091
- H. General correspondence
- 8310270214 Requests that JW Hillard, project manager, be deleted from sve list 4 ND Weiss be added as new project manager. CURTIS!N.W. Pennsylvania Power & Light Co 83/10/24 SCHWENCER, A Licensing Branch 2 1p 20924-096, 24x Fiche 50-387, 83/10/24, 8310270214.
- P Operating license stage documents & correspondence
- 8310030125 Discusses util response to Condition 4 associated w/TMI Action Plan Item II K 3 18 re automatic depressuritation systimer setting Proposed bypass timer setting of 480 s acceptable, 8sfety evaluation encl.

 8CHMENCER, A Licensing Branch 2 83/07/20. CURTJS, N W Pennsylvania Power & Light Co. 3pp. 20650:175. 24X Fiche, 30-387, 83/09/20, 8310030125

- B310110462 Advises that diesel generator starting times up to 25 s or less acceptable per B20924 Tech Spec change request SCHMENCER.A Licensing Branch 2 83/09/28 CURTIS.N H Pennsylvania Power & Light Co. 3pp. 20706 314 24X Fiche 50-387.B3/09/28.8310110462
- 8310120037 Forwards Amend 16 to License NPF-14 & sefety evaluation Amend incorporates Rev 2 to fire protection review rept & corrects typographical errors in Tech Spec 4 il 2 l 2-j SCHWENCER, A Licensing Branch 2 83/09/28 CURTIS,N W Pennsylvania Power & Light Co. 3pp. 20749 183 24X Fiche 50-387,83/09/28,8310120037
- --8310120041 Amend 16 to License NPF-14, incorporating Rev 2 to fire protection review rept & correcting typographical errors in Tech Spec 4 11 2 1 2-1. "Radioactive Gaseous Waste Bempling & Analysis Program." EISENHUT.D Q Division of Licensing 83/09/28 21pp 20749 186 24X fiche 30-387.83/09/28.8310120037
- --B310120045 Safety evaluation supporting Amend 16 to License NPF-14 * NRC - No Detailed Affiliation Given 83/09/28 5pp 20749 207 24X Fiche 50-387,83/09/28,8310120037
- 8310170046 Requests publication of FR notice of consideration of issuance of amend to License NPF-14 & proposed NSHC determination & opportunity for hearing re fire protection review rept NSHC determination available in Central Files SCHWENCER.A Licensing Branch 2 83/09/28 MILLER.J.R Operating Reactors Branch 3 4pp 20798 060 24X Fiche 50-387,83/09/28,8310170046
- 8310170048 Requests publication of FR notice of consideration of issuance of amend to License NPI -14 & proposed NSHC determination & opportunity for hearing re deletion of grab samples NSHC determination available in Central Files SCHMENCER, A Licensing Branch 2 83/09/28 MILLER, J R Operating Reactors Branch 3 4pp 20814 142 24X Fiche 50~387,83/09/28.
- B3101B0131 Advises that continued operation until completion of mods re NUREO-0737, Item II E 4 2 concerning gang opening of two sys. Justified Licensee committed to modifying logic at first refueling outage SCHWENCER.A Licensing Branch 2 B3/09/27 CURTIE.N W Pennsylvania Power & Light Co 3pp 20827 077 24X Fiche 50-387,83/09/27.8310180131
- 8310130207 Forwards application for amend to License NPF-14 correcting typographical error in design of reactor water Level 2 & revising isolation signal for valves required for reactor water Level 3 only CURTIB.N H Pennsylvania Power & Light Co 83/10/07 SCHHENCER.A Licensing Branch 2 3pp 20725 018 24X Fichø 50-387.83/10/07, 831013020/
- --8310130213 Application for proposed Amend 30 to License NPF-14, correcting typographical error in design of reactor water Level 2 & revising isolation signal for valves required for reactor water Level 3 only W/marked-up Tech Spc CURTIS,N W Pennsylvania Power & Light Co 63/10/07 2pp 20725:021 24X Fiche 50-387,83/10/07,8310130207
- 8310140114 Expresses concern re wording of new iOCFR50 72(b) (2) (VI) effective 840101 Paragraph stated was not included in proposed rule Rev stating that licensee notify NRC as soon as practical should be included CURTIS,N W Pennsylvania Power & Light Co 83/10/10 DENFON.H R Office of Nuclear Reactor Regulation, Director 2pp 20764 007 24X Fichs 50-387,83/10/10.8310140114
- 8310170495 Request that NUREG-0123, "Std BWR Tech Specs," be revised to previous format, based on need to provide adequate time frame for completion of WPPSS-2 power ascension testing program Susquehanna test duration data encl SORENSEN.9 C Washington Public Power Supply System 83/10/10 SCHWENCERA Liconsing Branch 2 3pp 20784 015 24% Fiche 50-000,83/10/10.83(0170495
- 8310140155 Application for Amend 27 to License NPF-14, revising inservice visual insp of snubbers CURTIS,N W Pennsylvania Power & Light Co 83/10/11 SCHWENCER, A Licensing Branch 2 App 20/63 014 24X Fiche 50-387, 83/10/11, 8310140105
- --8310140136 Proposed rev to Tech Specs re surveillance requirements for snubbers * Pennsylvania Power & Light Co. 83/10/11 2pp 20763 018 24X Fiche 50-387,83/10/11,8310140155

- 8310180426 Forwards rev to Section 14 2 of FSAR re proposed startup test program for Unit 2 & clarification of Unit 1 startup test program Revs will be incorporated into next FSAR amend CURISS, N W Pennsylvania Power & Light Co 83/10/13 BCHWENCER, A Licensing Branch 2 70pp 20803 224 24X Ficha 50-387, 83/10/13, 8310180426
- 8310180480 Forwards Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study " Existing sys adequately controls facility CURTIS.N N Pennsylvania Power & Light Co 83/10/14 SCHWENCER.A Licensing Branch 2 2pp 20800 167 24X Fiche 50-387,83/10/14, 8310180480
- --93101804B1 Rev 1 to "Control Sys Power Supply & Sensor Malfunction Study " • EDS Nuclear, Inc 02-0160-1102 R01 82/03/31 25pp 20800 169 24X Fiche 50-387.83/10/14.8310180480
- --8310180485 App A to Rev 1 to "Control Sys Power Supply & Sensor Halfunction Study," "Technical Procedure for Performance of Analysis "

 * EDS Nuclear, Inc 82/03/31 30pp 20800 194 24X Ficha 50-387,83/10/14,8310180480
- --8310180493 App B to Rev 1 to "Control Sys Power Supply & Sensor Halfunction Study." "Control Sys & Sefety Functions" # EBS Nuclear. Inc. 02-0140-1102 RI APPB 82/03/31 10pp 20800 224 24X Fiche 50-387.83/10/14.8310180480
- --B3:0180497 App C to Rev 1 to "Control Sys Power Supply & Bensor Malfunction Study," "Control Sys Identification Diagrams "
 W/five oversize diagrams Aperture cards are available in PDR
 # EDS Nuclear, Inc 02-0160-1102 R1 APPC 82/03/31 lp 20800 233 24% Fiche 50-387,83/10/14,8310180480
- --6310180498 App D to Rev I to "Control Sys Power Supply & Sensor Halfunction Study," "Commonality Diagrams " * EDS Nuclear, Inc. 02-0160-1102 RI APPD 82/03/31 lipp 20800 235 24% Ficha 50-387,83/10/14,8310180480
- --8310180501 App E to Rev 1 to "Control Sys Power Supply & Sensor Halfunction Study," "Failure Modes & Effects Analysis " + EDS Nuclear, Inc 02-0160-1102 R1 APPE 82/03/31 51pp 20800 246 24X Fiche 50-38/,83/10/14,8310180480
- --8310180504 App F to Rev I to "Control Sys Power Supply & Sensor Malfunction Study." "Malfunction Analysis Tables "
 + EDS Nuclear, Inc 02-0160-1102 RI APPF 82/03/31 43pp 20800 297 24X Fiche 30-387,83/10/14,8310180480
- 8310180507 Forwards Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Sys " CURTIS.N W Pennsylvania Power & Light Co 83/10/14 SCHWENCER, A Licensing Branch 2 1p 20800 340 24x Fiche 50-387, 83/10/14, 8310180507
- --8310180509 Rev 0 to "Evaluation of Effects of High Energy Line Breaks on Control Sys " * EDS Nuclear, Inc 02-0160-1131 ROO 83/05/31 36pp 20800 341 24X Fiche 50-387,83/10/14,8310180507
- --B31G180510 App A to Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Technical Procedure for Performance of Analysis" # EDS Nuclear, Inc. 83/05/31 29pp 2080: 015 24X Fiche 50-387,83/10/14,8310180507
- --B310180514 App B to Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Bys." "Control Sys & Safety Functions" * EDS Nuclear, Inc 02-0140-1131 RO APPB 83/05/31, 11pp 20801 044 24X Fiche 50-387,83/10/14,8310180507
- --8310180518 App C to Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Sys." "Control Sys Identification Diagrams & Control System Component Tables " W/four oversize diagrams Aperture cards are available in PDR # EDB Nuclear, Inc 02-0160-1131 RO APPC 83/05/31 13pp 20801 055 24X Fichs 50-387,83/10/14,8310180507
- --8310180520 App D to Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Sys." "Commonality Diagrams " * EDS Nuclear, Inc 02-0160-1131 RO APPD 83/05/31 App 20801 049 24% Fiche 30-387,83/10/14,8310180507

- --8310180923 App E to Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Failure Modes & Effects Analysis " * EDS Muclear, Inc O2-0160-1131 RO APPE 83/05/31 19pp 20801 073 24X Fiche 50-387,83/10/14.8310180507
- --8310180525 App F to Rev O to "Evaluation of Effects of High Energy Line Breaks on Control Sys," "Figures & Tables " * EOS Nuclear, Inc 02-0160-1131 RO APPF 83/05/31 22pp 20801 092 24X Fiche 50-387,83/10/14,8310180307
- 8310250106 Opposes NRC 830928 position on Tech Spec requiring second diesel start to occur in 10 s or less Opportunity for detailed discussion requested CURTIS,N W Pennsylvenia Power & Light Co 83/10/20 SCHWENCER, Licensing Branch 2 1p 20896.248. 24X Fiche: 50-387,83/10/20,8310250106
- 8310250244 Forwards application for Proposed Amend 31 to License NPF-14, changing Tech Spec Table 4 B 1 1 2-2 re settings for emergency svc water pump timers
 KENYON. B D Pennsylvania Power & Light Co 83/10/20 SCHWENCER, A Licensing Brench 2 3pp 20899 030 24X Fiche 90-387, 83/10/20, 8310250246
- --8310250252 Application for Proposed Amend 31 to License NPF-14, changing Tech Spec Table 4 8 i i 2-2 re settings for emergency svc water pump timers KENYON, B D Pennsylvania Power & Light Co 83/10/20 ip 20879 033 24X Fiche 50-387,83/10/20,8310250246
- ~~8310250258 Proposed changes to Tech Spec Table 4.8 i J 2-2 re settings for emergency svc water pump timers * Pennsylvania Power & Light Co 83/10/20 2pp 20899 034 24X Fichs 50~387,83/10/20,8310250246
- B310270449 Forwards application for amend to License NPF-14.consisting of Proposed Amend 32.changing Tech Specs to limit spray pond operating temp to Bi F & to mointain inventory at min of 23 million gallons
 KENYON,B D Pennsylvania Power & Light Co B3/10/24 SCHWENCER,A Licensing Branch 2 2pp. 20723 027 24X Fiche 50-387.83/10/24, 8310270449
- --8310270453 Application for amend to License NPF-14, consisting of Proposed Amend 32, changing Tech Boecs to limit spray pend operating temp to 81 F & to maintain inventory at min of 23 million gallons KENYGN.B D Pennsylvania Power & Light Co. 83/10/24 1p 20923 029 24X Fiche 50-387,83/10/24,8310270449
- --8310270457 Proposed Tech Spacs re limiting condition for operation & surveillance requirements for spray pond operating temp * Pennsylvania Power & Light Co 83/10/24 ip 20923 030 24X Fiche 50-387.83/10/24,8310270449
- 9 Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Gualification Tests." Svc list encl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York: Int 117pp. 20754:022 24X Fiche 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210. 24% Fiche 50~000,83/07/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JORDAN, E. L. Division of Energency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778.001. 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shirlding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl. JORDAN,E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fiche: 50-000, 83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/07. Consolidated Edison Co of New York, Inc 76pp 20827:213 24X Fiche 50-000.83/10/07,8308300378

DOCKETED ITEMS

- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc Just encl JORDAN,E L. Division of Emergency Preparedness & Enganeering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 R4X Fiche 80-000,83/10/07.8308300752
- 8310180349 Ack receipt of 830928 ltr informing NRC of steps taken to correct Violations noted in IE Insp Rept 50-387/83-18

 MARTIM, T. Division of Engineering & Technical Programs 83/10/07

 KENYON, B D Pennsylvania Power & Light Co ip 20803 011. 24X

 Fiche 50-387,83/10/07,8310180349
- --B31018035A Responds to NRC B30829 ltm re violations noted in 1E Insp. Rept 30-387/83-18 Corrective actions importance of complying w/plant procedures & radiation work permit requirements stressed & incorporated into training course KENYON.B D Pennsylvania Power & Light Co B3/09/28 MARTIN.T T Division of Engineering & Technical Programs 4pp 20803 012 24X Fiche: 50-387, 83/10/07, 8310180349
- B30B300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Gauses Production of Noxious Gases" Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post B30103) S3/10/IL. Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000, 83/10/IL 830B300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- 8310140155 Application for Amend 29 to License NPF-14, revising inservice visual insp of anubbers CURTIS, N W. Pennsylvania Power & Light Co 83/10/11 SCHWENCER, A Licensing Branch 2 App 20763 014 24X Fiche 50-387, 83/10/11. 8310140195
- --B310140156 Proposed rev to Tech Spacs re surveillance requirements for stubbers.
 Pennsylvania Power & Light Co. 83/10/11, 2pp. 20763-018-24X Fiche: 50-387, 83/10/11, 8310140155.
- 8310180551 Notification of 831021 meeting w/BHR licensees in Setherda. MD to discuss future insps for intergranular stress corresion cracking MIRAQLIA,F.J Assistant Director for Sefety Assessment 83/10/14 EIBENHUT.D Q. Division of Licensing. Spp 20823 358 24X Fiche.50-000,83/10/14.8310180551
- 8310250476 Advises of plans to revise PSI commitments outlined in Belief Request 4 to delete further efforts w/proposed automated ultrasonic equipment MINAC will be used to radiographically inspect inservice white during refueling. CURTIS, N W Pennsylvania Power & Light Co B3/10/19. SCHWENCER, A Licensing Branch 2 2pp 20897 143 24X Fichs 50-3B7, 83/10/19, 8310250476
- R. Periodic operating reports & related correspondence
- 8310170080 Monthly operating rept for Aug 1783 W/830712 ltr KUCZYMBKI.L A. KENYON, B D Pennsylvania Power & Light Co 83/09/08 BEEBE, H R Management Information Branch 5pp 20822-273. 24X Fiche 50-387,83/09/08,8310190080
- 8310110197 NPDES discharge monitoring hept for Aug 1983 M/830929 ltr KAUFFMAN.J.T Pennsylvania Power & Light Co 83/09/26 Pennsylvania: Commonwealth of: 10pp. 20665 296 24X Fichs.50-387.83/09/26.8310110197.
- 8 Reportable occurrences. LERs & related correspondence
- 8310270541 Responds to FOIA request for three categories of documents re 830606 gas leak at facility Forwards App A documents FELTON.J.M. Division of Roles and Records, 83/07/22. AROYROS.D.L. Chamitin, Schottland. Rosen, Cavenagh & Uliano 2pp 20937 225 24% Fiche: 50-000.83/07/22.8310270541
- --8310270547 Submits morning rept for Region I, listing 830606 & 07 events.

 ALLANJ, M Region I, Office of Director 83/06/07 BLAHAJJ. Program Support Branch Ip. 20937-228. 24X Fichs 80-000, 83/07/22,8310270541
- G10210327 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BHR/4 rated at 2.436 MM. Forwards App A documents Documents also available in FDR FELTON. J. M. Division of Rules and Records 83/07/28 HAFNER. B 80/f01k Nuclear Study Group 2pp 20882 223 24X Fiche: 50-000.83/07/28:83102:0329.

- --8303030103 Comments of LERs submitted from Feb 1982 Jah 1983, in support of SALP review LERs generally prepared adequately w/occasional exceptions Licensee performance typical of average BMR facility in initial phase of plant startup SEYFRIT, K V Reactor Operations Analysis Branch 83/02/22 STAROSTECKI, R Division of Project & Resident Programs 2pp 20882 263 24X Fiche 50-000,83/07/28,8310210329
- 8310250219 LER 83-117/03L-0 on 830815 & 0902 reactor bldg Zone i HVAC supply fans tripped causing Zone i pressure to exceed Tech Specs Caused by opening reactor bldg Zone i supply plenum access door for approx 30 s or longer W/830915 ltr PIEMONTESE.A P. KEISER.H W Pennsylvania Power & Light Co 83/09/15 MURLEY.T E Region i. Office of Director 2pp 20893 305 24X Fiche 50-387,83/09/15.8310250219
- 8310310305 RO on B30811, trouble elarm for Fire Detection Zone 89 annunciated in plant control room Investigation revealed open resistance exists in circuit for Zone 89 End-of-life relay replaced

 KEISER, H W. Pennsylvania Power & Light Co. 83/09/15 MURLEY, T. E. Region 1. Dffice of Director 19, 20961 223 24X

 Fiche 50-387, 83/09/15, 8310310305
- 8310200271 LER 83-116/03L-0 on 830823, check valve in RHM pump A discharge line would not seat properly & suction valve closed resulting in limiting condition of appration Caused by need to seat discharge line check valve W/830922 ltr KUCZYNBKI. L A . KEISER. H W Pennsylvania Power & Light Co 83/09/22 MURLEY. T E Region 1. Office of Director 3pp 20830 044 24X Fiche 50-387.83/09/22.8310200271
- 8310280130 Final deficiency rept re water hammer in essential syr water sys Initially reported on 830505 Vacuum breakers will be installed during first refueling outage Also reported per Part 21 CURTIE, N W. Pennsylvania Power & Light Co 83/09/22 MURLEY, T E Region 1. Office of Director 7pp 20929 254 24X Fiche 50-387,83/09/22,9310280130
- 8310190120 LER 83-120/03L-0 on 830828, during post-scram vessel level fluctuation, RCIC sys turbine automatically initiated & tripped on electrical overspeed Caused by slow response of governor valve Valve linkage travel reduced W/830927 ltr QRAHAM, J J . KEJSER: H W Pennsylvania Power & Light Co 83/09/27 NURLEY, T E Region I. office of Director 3pp 20821 047 24X Fiche 50-387, 83/09/27, 8310190120
- 8310190145 LER 83-119/03L-O on 830828, during drywell vacuum 2 h postinitiation surveillance, anomelous position indication noted
 for two vacuum breakers Caused by loose cam coupling set
 screws Solenoid valve cleaned Screws tightened W/830927 ltr,
 KUCZYNSKI, L A , KEISER, H W Pennsylvania Power & Light Co
 83/09/27 MURLEY, T E Region 1, Office of Director Spp
 20820 313 24X Fichs 50-387,83/09/27,8310190145
- 8310190230 LER 83-118/03L-0 on 830829, during calibr of main steam line A,10w pressure switch PSL-821-1N015A setpoint Pound below Tech 8pec allowable value Setpoint Pailed acceptance criteria Switch replaced W/83092/ ltr PIEMONTESE, A P., MEISER, H W Pennsylvania Power & Light Co 83/09/27 MURLEY, T E Region 1, Office of Director 2pp 20818 Q50 24X Fichs \$Q-387.83/09/27,8310190230
- 8310250574 LER 83-078/03L-0 on 830829, excess flow check valve XV-821-F009 could not be tested to verify operability Caused by present configuration of instrument line not allowing access to valve w/a removing vessel head M/830927 tr PIEMONTESE. A P., KEISER, H W Pennsylvanta Power & Light Co 83/09/27 HURLEY, T E Region 1. Dffice of Director 2pp 20901 056 24X Fiche 50-387,83/09/27,8310250594
- 8310250228 LER 83-122/03L-0 on 830901.reactor bldg Zone IJI ventilation sys isolated & would not restart after radiation detector power supply switched to alternate source Caused by blown fuse on Zone III isolation damper HD17502A M/830930 ltr. PIEMONTEBS.AP, KEISER.H W Pennsylvania Power & Light Co 83/09730 M/88LEY.T E Region i. Office of Director 3pp 20899 118 24X Fichs 50-387,63/09/30,8310250228
- B310250245 LER B3-123/03L-0 on B30901, reactor bldg Zone III ventilation tripped, causing short-duration loss of 0 25 inches Caused by momentary, spurious signal Investigation revealed absence of Zone III isolation signal W/B30930 ltm.
 KUCZYNSKI.L A , KEISER, H W Pennsylvania Power & Light Co B3/09/30 MUNLEY, TE Region 1. Office of Director 2pp 20899 072 24X Fiche 50-387,83/09/30,8310250245
- 8310250386 LER B3-121/O3L-O on 830902, average power range monitor flow biased wimulated thermal power upscale scram & neutron flux upscale control rod block trip setpoints higher than Tech Spec limit Gaused by power peaking W/830930 ltr KUCZYNSKI, A , KEISER, H W Pennsylvania Power & Light Co 83/09/30 MUNLEY, T E Region 1, Office of Director 2pp 20898 143 24X Fiche 50-387,08/09/30,0310250386

- B310250555 LER B3-(P4/O3L-O on B30901, solenoid valve controlling teactor bldg Zone I exhaust fan damper failed Caused by esti wear in solenoid valve Valve rebusit & reinstalled W/B30930 ltr
 #UCZYNEMI.L A. KEISER.H W Pennsylvania Power & Light Co 83/09/30 MURLEY.T E Region 1. Dffice of Director 2pp 20901 010 24X Fiche 50-367.83/09/30.8310250555
- \$310130187 Advises that AEOD engineering evaluation rept re events involving AHR sys in shutdown cooling mode distributed to appropriate ARR branches & project manager
 DENTOW, H.R. Office of Nuclear Reactor Regulation, Director
 \$3910/04 HELTENES, C. J. Director's Office 2pp 20754 340 24X
 Fiche 30-387,03/10/04,8310130189
- B310250402 LER B3-126/03L-0 on 930905, following receipt of fault alarm. control rod scram accumulator 46-07 pressure found below Tech Spec limit Caused by water leak past piston Accumulator repressurized W/831003 ltr
 PIEMONTESE, A P. KEISER, H W. Pennsylvania Power & Light Co. 83/10/05 MURLEY, T E. Region i. Office of Director 2pp. 20697 296 24X Fichs 50-387/83/10/05.8310250402
- 9310250204 LER 83-127/01P-0 on 830927, torque switch spring pack failed to open at specified torque, causing valve operating motor to hurn up on over-torque w/locked rotor Engineering evaluation of thermal overload bupass circuit design under review KEISER. H W Pennsylvania Power & Light Co 83/10/07 MURLEY. TE Region f, Office of Director 2pp 20873 362 24% Fiche 50-387, 63/10/07, 8310250204
- 8310250242 LER 83-132/03L-0 on 830910, during weekly preventive maint activity, analyzer 8 exhibited erratic oxygen concentration resdings & declared inoperable Caused by malfunctioning hydrogen sample cell flow regulator W/831010 ltr WUCZYNSKIL A , KEISER, H W Pennsylvania Power & Light Co 83/10/10 MWRLEY, T E Region 1, Office of Director 2pp 20879 070 24X Fiche 50-387,83/10/10,8310250242
- 6310250&22 LER 83-131/03L-0 on 830910, diesel generator B tripped prior to achieving 600 rpm Three low priority alarms received concurrently w/trip Caused by water & corrosion products in instrument air sys Air dryers to be installed W/831010 ltr WUCZYMSKI,L A , KEISER,H W Pennsylvania Power & Light Co 83710710 MURLEY,T E Region 1, OPFice of Director 2pp 20900 285 24X Fiche 50-387.83/10/10.8310250622
- 8310280125 LER 83-130/01P-0 discrepancies discovered in initiating signals for 10 containment isolation valves Caused by parsonnel omission to make proper FSAR & Tech Spec changes Followup rept will be provided in 14 days KEISER. H W Pennsylvania Power & Light Co 83/10/10 NURLEY, T E Region 1. Defice of Director in 20929 280 24X Fiche 50-387, 83/10/10, 8310280120
- 6310250266 LER 83-134/03L-0 on 830912, during diesel generator monthly operability test-diesel generator C tripped on cvarexcitation Probably caused by voltage perturbation on offsite grid interfacing Investigation ongoing W/831012 ltr. MUCZYNSKIL A . KEIECR, H W Pennsylvania Power & Light Co 83/10/12 NWALEY, T & Region 1, Offsic of Director. Spp 20699 023. 24X Fiche 50-387,83/10/12,8310250266
- 8310200221 NPDES noncompliance notification beginning 830918, drinking water turbidity level ranged from 1 7 to 3 2 turbidity units free available chlorine level indicated maint of disanfection in sys Safe drinking water requirements met FIELDS, J S Pennsylvania Power & Light Co 83/10/13 WHITCRAFT, P. K. Environmental Pobection Agency 1p 20933-044 24x Fiche 50-387,83/10/13,8310200221
- 8310250345 LER 83-128/03L-0 on 830913, reactor bldg Ione III vontilation sys tripped & automatically restarted Caused by spurious activation of differential PDSHH 178018 switch Fnoumatic instruments replaced W/831013 ltr
 PIEMONTERS.A P . KEISER, H W Pennsylvanis Power & Light Co
 83/10/13 MURLEY, T E Region 1, OPFice of Director 2pp
 20898 040 24X Fichs 50-387,83/10/13,8310250345

- DOCKET 50-388 SUBRUEHANNA STEAM ELECTRIC STATION. UNII 2

 A Application/construction stage documents & correspondence
- 8310050125 Discusses util response to Condition 4 associated w/TMI Action Plan Item II X 3 18 re automatic depressurization systimer setting Proposed bypass timer setting of 480 s acceptable Safety evaluation encl SCHWENCER. A Licensing Branch 2 83/09/20 CURTIS, N W Pennsylvania Power & Light Co 3pp 20450 195 24X Fiche 50-387,83/09/20,8310080125
- 8310210292 Forwards summary of 830907 meeting in Allentown, PA repower, voltage & relay study covering cable length deficiency, T-10 & ECCS transformer project CURTIS, N W Pennsylvania Power & Light Co 83/09/21. MURLEY, T E Region 1. Office of Director 23pp 20855 222 24X Fiche 30-388, 83/09/21. 8310210292
- 8310040032 Forwards 9-month response for NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" Electrical interlocks prevent main hoist of reactor bldg crane from buing used over reactor well or spent fuel pool CURTIS.N W Pennsylvania Power & Light Co 83/09/29 SCHMENCER.A Licensing Branch 2 63pp 20608 143 24% Ficha 50-388,83/09/29,8310040052
- 8310040421 Forwards revs to FSAR Section 53 re stainless steel weld cladding & fracture toughness Revs show conformance w/10CFR50 Apps G & H & will be incorporated in next FBAR amend CURTIS.N H Pennsylvania Power & Light Co 83/09/29 SCHHENCER, A Licensing Branch 2 10pp 20619 175 24X Fiche 50-388, B3/09/29, B310040421
- 8310040640 Forwards revised Section 11 3 of FSAR to be incorporated into next amend Rev refs gaseous waste mgt sys diagrams CURTIS.N W Pennsylvania Power & Light Co 83/09/30 SCHWENCER.A. Licensing Branch 2 2pp 20625 350 24X Fiche 50-388,83/09/30,8310040640
- 8310120175 Forwards revised Section 3 13 to FBAR Rev references util previously submitted position on Reg Guide 1 97 Rev will be incorporated in next FSAR amend.

 CURTIS.N W Pennsylvania Power & Light Co 83/09/30. SCHWENCER, A Licensing Branch 2 2pp 20695 290 24X Fiche 50-388.83/09/30.

 8310120175
- 8310070160 Submits rev to FBAR Section / 5 re neutron flux monitoring sys & plant computer sys Revs will be incorporated in next FBAR amend CURTIS, N W Pennsylvania Power & Light Co 83/10/03 SCHWENCER, A Licensing Branch 2 Spp 20/659 OB7 24X Fiche 50~388,83/10/03,8310070160.
- 8310120067 Forwards revised Section 7.6 to FBAR.clarifying pressure indicator monitoring, adding discussion of non-Class IE temp sensors & including info average power range monitor upscale thermal trip Revs will be incorporated into next FBAR rev CURTIS.N W Pennsylvania Power & Light Co 83/10/06 BCHWENCER, A Licensing Branch 2 4pp 20697 165 24X Fiche 50-388,83/10/06,8310120067
- B310120080 Informs that FBAR Section 12 2 revised to reflect that layout of equipment in Unit 2 not significantly different than Unit 1 layout Shielding & roning requirements apply to both units Info will be incorporated into next FBAR amend CURTIS, N W. Pennsylvania Power & Light Co. B3/10/06. BCHMENCER, A Licensing Branch 2 Rpp 20A97 155 24X Fiche. 50-388, B3/10/06, B310120080
- B310120105 Forwards revised FBAR Section 10 4 re regeneration sys.Revs clarify acid strength & verify ultrasonic resin cleaner added to sys Revs will be incorporated in next FSAR amend CURTIS.N W. Pennsylvania Power & Light Cn 83/10/06 BCHWENCER.A. Licensing Branch 2 3pp 20696 225 24X Fiche.50-388,83/10/06,8310120105
- 8310120144 Forwards revised Section 3 AA of FSAR re analysis for HPCI & RCIC pump rooms Info will be incorporated into next FSAR amend CURIE, N W Fennsylvania Power & Light Co 83/10/06 SCHWENCER, A. Licensing Branch 2. 9pp 20696 033 24x Fiche 50-388, 83/10/06, 8310120144
- 8310140077 Forwards revised FSAR Section 7.7 clarifying scram discharge high level vol & computer sys block diagram Revs will be incorporated in next FSAR amend CURFIS,N H Pannsylvania Power & Light Co 83/10/07 9CHWENCER,A Licensing Branch 2 App 20767 134 24X Fiche: 50-388,63/10/07,8310140077

- B310170145 Forwards "UHS Test Interim Rept," conducted to demonstrate that measured performance of spray pend equals or exceeds performance predicted by analysis for two-unit operations CURTIS, N W Pennsylvania Power & Light Co 83/10/12 SCHWENCER, A Licensing Branch 2 lp 20787 007 24X Fiche 50-388, 83/10/12, 8310170145
- --831017014B "UHS Test Interim Rept "

 * Pennsylvania Power & Light Co 83/10/12 5pp 20787 008 247
 Fiche 50-388,83/10/12,8310170145
- 8310180166 Forwards FSAR Section 9 1 re reactor bldg crane, revised in response to NUREG-0612 Changes will be incorporated into next FSAR amend CURTIB, N W Pennsylvania Power & Light Co 83/10/13 SCHWENCER, A Licensing Branch 2 28pp 20809 001 24X Fiche 30-388, 83/10/13, 8310180166
- 8310180426 Forwards new to Section 14 2 of FSAR re proposed startup test program for Unit 2 & clarification of Unit 1 startup test program Revs will be incorporated anto next FSAR amend CURTIS.N H. Pennsylvania Power & Light Co 83/10/13 SCHWENCER.A Licensing Branch 2 70pp 20803 224 24% Fiche 30-387.83/10/13. 83101804826
- 8310180437 Forwards revised FSAR Sections 14 2 12 4 & 14 2 12 5 covering preoperational test program Revs will be incorporated in nert FSAR amend CURTIS, N W Pennsylvania Power & Light Co 83/10/13 SCHWENCER, A Licensing Branch 2 95pp 20802 163 24X Fiche 50-388, 83/10/13, 8310180437
- 8310180454 Forwards revs to Section 9 3 of FSAR covering process sampling sys & design bases Revs will be incorporated in next FSAR amend CURTIS, N. W Pennsylvania Power & Light Co 83/10/14 SCHWENCER, A Licensing Branch 2 5pp 20802 107 24X Fiche 50-388,83/10/14,83101809454
- 9310280155 Informs that util completed installation of modified frywoll to wetwell vacuum breakers
 CURTIS.N W Pennsylvania Pawer & Light Co 83/10/24 9CHWENCER.A Licensing Branch 2 1p 20727:017 24X Fiche 50-388.83/10/24.8310280155
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310070336 Forwards info re reactor pressure vessel beltline plates & welds.closing out SER Issue 112 FBAR changes generated will be submitted under separate cover CURTIS.N W Pennsylvania Power & Light Co 83/10/03 SCHWENCER, A Licensing Branch 2 55pp 20651 003 24x Fiche 50-388,83/10/03,8310070336
- 8310140056 forwards response to SSER 5, Section 1 9 Item 115 & IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " CURTIS:N W Pennsylvania Power & Light Co 83/10/10 BCHWENCER, A Licensing Branch 2 9sp 20767 354, 24X Fiche 50-368,83/10/10, 8310140056
- F. Security, medical, emergency & fire protection plans
- 8310060481 Releases public version of revised emergency plan implementation procedure FELTON.V Division of Rules and Records 83/09/22 Document Management Branch. Ip 20660 086 24X Fiche 50-387,83/09/22, 8310060481
- --8310060486 Public version of Rev 2 to Emergency Plan Implementation Procedure EP-IP-002, "Emergency Mgt Notifications " W/830915 ltr & Rev 24 to table of contents KAISER, H Pennsylvapia Power & Light Co 83/09/15 SCHWENCER, A NRC No Detailed Affiliation Given 75pp. 20660 087 24% Fiche 50-387,83/09/22,8310060481
- 9310060211 Forwards SAR for safety parameter display sys, in response to Generic Ltr 82-33,per NUREG-0737, Suppl 1 & util 830415 itr implementation schedule for safety parameter display sys encl CURTIS,N W. Pennsylvania Power & Light Co. 83/09/30 SCHWENCER, A Licensing Branch 2 98pp 20646-279 24X Fiche 80-387,83/09/30,8310060211
- 310060533 Releases public version of revised emergency plan implementation procedure FELTON-J.M Division of Rules and Records 83/07/30, Document Management Branch 1p 20661 334 24X Ficha 50~387.83/07/30, 8310060533,

- --8310060538 Public version of Rev 2 to Emergency Plan Implementation Procedure EP-IP-007, "Personnel Assembly & Accountability " W/830720 itr & Rev 20 to table of contents KEISER,H Pennsylvania Power & Light Co 83/07/18 SCHMENGER,A NRC No Detailed Affiliation Given 20pp 20661 395 24x Fiche 50-387,83/09/30,8310060533
- B310110091 Releases public version of revised emergency plan implementing procedure FELTON. J H Division of Rules and Records B3/10/05 Document Management Branch Ip 20687 337 24X Fiche 50-387,83/10/05, B310110091
- --9310110094 Public version of Hev I to Emergency Plan Implementing Procedure EP-IP-018, "Emergency Call-in & Communication " W/030831 ltr & receipt form
 + Pennsylvania Power & Light Co 83/08/31 SCHWENCER.A (NYC No Detailed Affiliation Given 13pp 20687 338 24% Fiche 50-387.83/10/05,8310110091
- H General correspondence
- 8310270214 Requests that JW Millard.project manager, be deleted from svc list & ND Weiss be added as new project manager CURTIS.N W Pennsylvania Power & Light Co 83/10/24 SCHWLNLFR.A Licensing Branch 2 lp 20724 076 24X Fiche 50-387.83/10/24, B310270214
- @ Inspection reports: IE βulletins & correspondence
- #310040041 Forwards IE Insp Rept 50-388/83-13 on 830814-18 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs #3709/22 KENYON.B D Pennsylvania Power & Light Go 2pp 20c47 232 24X Ficha 50-388.83709/22.8310040041
- --8310060046 JE Insp Rept 50-388/83-13 on 830816-18 No noncompliance noted Major areas inspected preoperational test program, interface of shared sys & QA/QC interface w/test program NICHOLAS,H H, RETTENHAUSEN,L Region 1, Office of Director 83/08/31 7pp. 20647 234 24% Fiche 50-388,83/09/22,8310060041
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830)03) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26.8J08400340
- 8308300342 If Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26.8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. il8pp 20778 001 24% Fiche 50-000,83/09/26,830830345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR90 59 Evaluation" Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83/09/29,8300J00349
- 8308300378 IE Info Notice 83-65, "Survei)lance of Flow in RID Bupass Loops Used in Westinghouse Plants" Syr list encl JORDAN, E. L. Divisiom of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of Net York, Inc. 76pp. 20827 213 24X Fiche 50-000.83/10/07.8308300378
- B308300752 IE Info Notice B3-66, "Fatality at Argentine Critical Facility," 8vc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co. of New York, Inc. 79pp. 20882 026 24X Fiche 50-000,83/10/07,8309700752
- 8310140056 Forwards response to SSFR 5.Section 1 9 Item 115 & IE.
 Bulletin 79-27. "Loss of Non-Class IE Instrumentation &
 Control Power Sys Bus During Operation "
 CURTIS, N W Pennsylvania Power & Light Co 83/10/10 SCHWENCER. A
 Licensing Branch 2 9pp 20747 354 24X Fiche 50-388,83/10/10,
 8310140056

- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Nozious Gases" Syc list enct JORDAN, C. L. Division of Emergency Preparedness & Inquineering Response (Post 830103) 83/10/11 (Insolidated Edison Co. of New Fork, Inc. 117pp 21043-075 24% Fithe 50-000, 83/10/11, 8308300759
- B308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc. list enc!

 JORDAN, E. L. Division of Emergency Preparatuses & Engineering Response (Post 830103) 83/10/11 (Onsolidated Edison Co. of New York, Int. 120pp. 20827 127 24X Fishe 50-000,83/10/11,8308700761
- A Periodic operating reports % related correspondence
- B3[0][0]97 NPDES discharge monitoring rept for Aug 1983 W/830927 ltr FAMFFMAN.J T Pennsylvania Power & Light Co 83/09/26 Pennsylvania, Commonwealth of, 10pp 20465 296 24X Fiche 50-387,89/09/26.8310110199
- 5 Reportable occurrences, LERs & related correspondence
- 6310310305 RO on 830811.trouble alarm for Fire Detection Zone 87 annunciated in plant control room Investigation revealed open resistance exists in circuit for Zone 87 End-of-life relay replaced KEISER.H W Pennsylvania Power & Light Co 83/09/15 MURLEY.7 L Region 1. Office of Director 1p 20961 223 247 fiche 50 -387.83/09/15.8310310305
- 8310210292 Forwards summary of 830907 meeting in Allentown, PA re power, voltage & relay study covering cable length deficienty, T-10 & ECCS transformer project CURTIE, N W Pennsylvania Power & Light Co 83/09/21 MURLEY, T E Region I, Defice of Director 23pp 20855 222 24X Fiche 50-388,83/09/21,8310210292
- B3102GD130 Final deficiency rept re water hammer in essential syc water sys Initially reported on 030505 Vacuum breakers will be instalted during first refueling outage Also reported per Part 2!

 CURTIS,N W Ponnsylvania Power & Light Co 83/09/22 NURLCY,T & Region 1. Diffice of Director 7pp 20929 254 24X

 Fiche 90-387,837/09/22,8310280130
- B310280065 Second interim deficiency rept re GC reactor mode switch finitially reported on B30407 Mode switch redesigned Sample will be independently tested Also reported per Part 21 Final rept will be submitted by Dec 1783 CURTIS;N W Pennsylvania Power & Light Co B3/09/30 NURLEY;1 F Region i, Office of Director 6pp 20/29 020 24% Fiche 50-388,83/09/30,8310280065
- 6310280137 Interim deficiency rept re isolation of nitrogen makeup sys Also reportable per Part 21 Initially reported on 830912 Permanent design med will be implemented Final rept will be submitted in Der 1703 CURTIE, N.W. Pennsylvania Power & Light Co. 83/10/10 MURLEY: T.E. Region I. Office of Director Spp. 20729 009 24X Fiche 50-388.83/10/10.8310280137
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- 6310060490 Releases public version of revised offnormal & emergency operating procedures FELTON, J M Division of Rules and Records 83/09/22 Document Management Branch 1p 20650 299 24X Fiche 50-335,83/09/22-03662450
- --B310060492 Forwards public version of revised offnormal & smergency operating procedures, including Procedures 1-0910032 re auxiliary transformer offnormal operation & 2-1010030 re loss of instrument air WETHY. 6 M Florida Power & Light Co 83/09/12 Director's Office, Office of Inspection and Enforcement ip 20450 360 24X Fiche 50-335,83/09/22,8310060490
- --B310060474 Public version of revised offnormal & emergency operating procedures, including Procedures 1-0910032 re auxiliary transformers offnormal operation & 2-1010030 re loss of instrument at PERRIEL Florida Power & Light Co B3/09/01 60pp 20650 301 24% Fiche 50-305,63/09/22,6310060490

- 8310070250 Forwards "Detailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station (NUREG-0737, Suppl 1)," per 830415 commitment URRIGOR E Florida Power & Light Co 83/09/30 EISENHUT, D 0 Division of Licensing 19 20459 128 24X Fiche 50-389, 89/09/30, 8310070250
- --8310070253 "Detailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station." summary rept UHRIG.R E Florida Power & Light Co 83/09/30 315pp 20459 129 24X Fiche 50-389, 83/09/30, 8310070250
- 8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-387/83-58 on 830829-0902 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/10/05 UHRIG.R E Florida Power & Light Co 29p 20897 256 24X Fiche 50-335.83/10/05.831025000
- --B310250409 IE Insp Repts 50-335/83-30 & 50-389/83-38 on 830829-0902 No noncompliance noted Major areas inspected changes to emergency preparedness program, shift staffing & augmentation & dose calculations & assessments HUFFNAN, Q N Region 2, Office of Director B3/09/30 10pp. 20897 258 24X Fiche 50-335,83710/05,8310250400
- 8310270049 Releases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 83/10/27 Document Management Branch lp 20940 286 24X Fiche 50-389.83/10/27, 8310270049
- --B3102700B3 Forwards public version of Rev 5 to Offnormal Emergency Operating Procedure 2-0030140, "Blackout Operation" & Rev 0 to Procedure 2-0970031, "Loss of SUPS Nonsafety Vital AC or Fire & Sacurity Inverters" WETHY, C M Florida Power & Light Co 83/10/10 Director's Office, Office of Inspection and Enforcement ip 20940 297, 24X Fiche 50-389,83/10/27,83102/0049
- --8310270067 Public version of Kev 5 to Offnormal Emergency Operating Procedure 2-0030140. "Blackout Operation" & Rev 0 to Procedure 2-0970031. "Loss of BUPS Nonsafety Vital AC or Fire & Security Inverters "

 ** Florida Power & Light Co 63/10/06 21pp 20940 208 24% Fiche 50-389.83/10/27.83102/0049
- P Operating license stage documents & correspondence
- 8310060534 Forwards notice of consideration of issuance of amend to License NPF-16 & proposed NSIC fetermination & opportunity for hearing on 830617 request re Tech Spec administrative & aditorial changes NERSES.V Licensing Branch 3 B3/09/16 UHRIG.R E Florida Powe & Light Co 2pp 20663 279 24X Fiche 50-389.83/09/16.8310060534
- ~~8310060537 Notice of consideration of issuance of amend to License NPF-14 & proposed NSHC determination & opportunity for hearing on 830617 request re Tech Spec administrative & editorial changes RATGHTON.OW Licensing Branch 3 83/09/15 8pp 20663.28i 24X Fiche 30-389,83/09/16.8310060534
- 8310110497 Advises that project mgt responsibility transferred from Licensing Branch 3 to Operating Reactor Branch 3 effective 830919 Personnel changes listed 830919 Personnel changes listed Flucture, J.R. Operating Reactors Branch 3 83/09/26 UM19.R E Florida Power & Light Co. 2pp. 20714 317 24X Fiche 50-389,83/09/26,8310110497
- 8310130423 Advises that effective 830919, mgt responsibility transferred from Licensing Brench 3 to Operating Reactors Branch 3, Div of Licensing MILLSH J.R Operating Reactors Branch 3 83/09/28 O'REILLY, J P Region 2, Office of Director 2pp 20767 240 24X Fiche. 50-389, 83/09/28, 8310130423
- 8310130153 Forwards "Inservice lest Program for Pumps & Valves" & Rey 0 to PNS-CIG Document 002-10. "Inservice Insp.First 10-Yr Flan." Vols 1 & 2 UHRIGR E Florida Power & Light Co 83/10/06 EISENHUT.D. 0 Division of Licensing 1p 20717 137 24X Fiche 50-389.83/10/06, 201012015
- --8310130154 "Inservice Test Program for Pumps & Valves.Bt Lucie Unit 2 "
 # Florida Power & Light Co 83/10/06, 129pp 20717 140 24X
 Ficho 50-389,83/10/06,8310130153

- 8310180208 Application for amend to Licenses DPR-67 & NFF-16 revising facility organization chart & modifying definition of shift technical advisor function HILLIAMS J W Fiorida Power & Light Co 83/10/12 ErsENNUI.D & Division of Licensing 3pp 20808 217 24X Fiche 50-335.83/10/1P, 8310180208
- --83i0180211 Proposed Tech Specs, revising facility organization chart & modifying definition of shift technical advisor function Safety evaluation encl + Florida Power & Light Co 83/10/12 6pp 20808 220 F4X Fiche 50-335
- 8310270211 Forwards list of add1 ESF actuation sys relays not identified in 830926 submittal or FSAN to be nontestable w/o jeoparditing plant safety Sufficient justification provided for not testing relays HELLIAMS. J W Florida Power & 1.3ght Co 83/10/21 FISENNULD & Division of Licensing 3pp 20924 041 24X Fiche 50-389.83/10/21. B310270211
- O Inspection reports. 16 Bulletins & correspondence
- 8310040447 Forwards IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830411-0710 No noncompliante noted DANCE, H C Division of Project & Resident Programs 83/09/14 UHR16, R E Florida Power & Light Co 2pp 20625 285 24X Fiche 50-339,83/09/14,8310040447
- --8310040454 IE Insp Repts 50-335/83-27 & 50-389/83-52 on 830611-0710 No noncompliance noted Major areas inspected maint & surveillance observations.plant operations.IE buljetins & circulars, LERs, SER following & PAB item following ELRDD, 5 A DIBB.H E Region 2. Office of Director JULIAN C Division of Project & Resident Programs 83/09/13 17pp 20525 287 24X Fiche 50-335,83/09/14,8310040447
- 8310040405 Confirms toleon re 831021 mgt meeting in Miami.FL to discuss results of first phase of SALP review for period Jul 1982 June 1983 Proposed agenda entl LEMIS.R C Division of Project & Rosident Programs 83/09/22 UMRIO.R E Florida Power & Light Co 2pp 20619 092 24x Fiche 50-000.83/09/22.8310040405
- 8310040458 Confirms 830716 decision to cancel NRC training assessment team 830726-30 insp Util will be informed of reschedule date

 LEMIS,R C Division of Project & Resident Programs 83/09/23
 UHRIO,R E Florida Power & Light Cn Ip 20623 324 24X
 Fichs 50-335,83/09/23,8310040458
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Us)der Qualification Tests " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/25 Consolidated Edison Co of New York, Ins 117pp 20754 022 24X Fische 50-000,83/09/26,8308200040
- 8308300342 IE Info Notice 83-62: "Failure of Redundant Toxic Cas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 lE Info Notice 83-63, "Potential Failures of Mestinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co. of New York, Inc. 188pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310250615 Forwards IE Insp Repts 50-335/83-31 & 50-389/83-59 on 830830-0902 No noncompliance noted DANCE, N C Division of Project & Resident Programs 83/09/27 UHRIG, R E Florida Power & Light Co 2pp 20900 16/ 24X Fiche, 50-335, 03/09/27, 8310250615
- --8310250621 IE Insp Rept 50-335/83-31 & 50-387/83-59 on 830830.0902 No noncompliance noted, Major areas inspected health physics instruments & equipment, 0C audits thermal shield disposal practices & actions on previous inspector followup items WHAY. J R Region 2. Office of Director BARR. K P. Division of Engineering & Operational Programs, 83/09/23 5pp 20900 169 24X Fiche 50-335,83/09/27,6310200615

- 8308300349 IE Info Notice 83-64, "lead Shielding Attached to Safety-Related Sys M/O 10CH30 59 Evaluation" Svc list enc!

 JORDAN, E. L. Division of Emergy Preparedness & Engineering Response (Post 830103) 83/09/29 Convolidated Edison Co. of New York, Inc. 115pp 20716-324 24X Fishe 50-000,83/09/29,8308300349
- 8310250400 Forwards IE Insp Repts 50-335/83-30 & 50-389/83 58 on B30829-0902 No noncompliance noted DANCE H C Division of Project & Resident Programs B3/10/05 UHRIGR E Florida Power & Light Co 2pp 20897 .56 247 Fiche 50-335 83/10/05 8310250400
- --B310250409 IE Insp Repts 50-335/B3-30 & 50-3B9/B3-58 on B30029 0002 Nr.
 noncompliance noted Mayor areas inspected thanges to
 emergency preparedness program shift staffing & augmentation
 & dose calculations & assessments
 HUFFMAN, O N · STODDART.P G Region 2. Office of Director
 JENKINS, G R · Division of Engineering & Operational Programs
 B3/09/30 10pg 20897 258 24X Fishe 50-335,83/10/05,8310250400
- 63i0130153 Forwards "Inservice lest Program for Pumps & Valves" & Rry O to PNS-CIG Document 002-10, "Inservice Insp.First 10-Yr Plan." Vols 1 & 2
 UHRIGR E Florida Power & Light Co 83/10/06 EJSENEU1.D C
 Division of Licensing 1p 20717 159 24X Fiche 90-389.83/10/06,
- --8310130154 "Inservice Test Program for Pumps & Valves, St Lucie Unit (* * Florida Power & Light Co 83/10/06 129pp 20717 160 24% Fiche 50-389, 83/10/06, 83101.0153
- --8310130157 Rev O to PNS-C10 Document 002-10; "Inservice Insp.First 10-Yr Plan." Vols 1 & 2 HEYCOCKP W., QOTCH, 0; PADUANO, H. N. Florida Power & Light Co 83/107/03 558pp 20717 288 24X Fichs 50-389,83/10/06; 8310130153
- 8310250516 Forwards IE Insp Repts 50-335/83-28 & 50-389/83-55 or 8307i1-0810 No noncompliance noted DANCE.N C Division of Project & Resident Programs 83/10/06 UHRIGR E. Florida Power & Light Co 2pp 20901 310 24X Fiche 50-335.83/10/06.8310250516
- --8310250528 IE Insp Repts 50-335/83-28 & 30-389/83-55 on 830711-0810 No noncompliance noted Major areas inspected maint & surveillance observation.plant operations. IE bulletins, circulars & info notices. LERs & startup testing ELROD. 8 A BIOB. H E . LANDIS. K Region 2. Office of Director 83/10/04 lipp 20901 312 24X Firhe 50-335,83/10/06,8310250516
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in ATD Bypass Loops Used in Westinghouse Plants" Sv. 1;5t encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,83083603/3
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svr list enc! JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Editon Co of New York, Inc 79pp 20882 026 24X Fithu 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Hespirator Matl Defect Causes Production of Noxious Gases " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000.83/10/11,8308300/59
- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fichs 50-000.83/10/11, 8308300761
- R Periodic operating reports & related correspondence
- 8310190023 Monthly operating repts for Aug 1983 W/830915 ltr GRANT,N W Florida Power & Light Co 83/09/15 Office of Resource Management, Director 17pp 20872 017 24X Fiche 50-000,83/09/15.8310190023

- S Reportable occurrences, LERs & related correspondence
- 8310030398 LER 83-050/03L-0 on H30822, during power operation, train A & B containment particulate indine & gascous monitors incoperable Caused by filter paper stuck on instrument sensor Papers freed from sensors & realigned W/830940 ltr ROTELLAIT S., WILLIAMS. J W Florida Fower & Light Co 83/09/20 0 "REILLY. J P. Region 2. Office of Director 2pp 20592 250 24X Fiche 50-369, 83/09/20.8310030398
- 8310030448 LER 83-051/03L-0 on 830822, instrument FT 3306 train A shutdown cooling flow failed Cause unkewn Calibr checks made of associated signa & controller FT-3306 volved out & back into svc W/830921 ltr ROTELLA,T B., WILLIAMS, J W. Florida Power & Light Co. 83/09/21 O'REILLY, J P. Region 2, Office of Director. 2pp. 20602 032 24) Fiche 50-389,83/09/21,8310030448
- 8310030254 LER 83-049/01T-0 on 830911.while performing valve lineup checks for startup, svc air containment isolation valves V28794 & V18796 found open Caused by personnel error Valves that W/830926 ltr HittIAKS.J W., PARKS.B. Flurida Power & Light Co. 83/09/26 O'REILLY.J P. Region 2. Defice of Director 2pp. 20591 062 2. Fithe 50-389, 83/09/26.8310030254
- 8310140217 Suppl to final Deficiency Rept 82-014 re malfunctioning shotdown tooling sys HX bypass valves Valves will be replaced w/zonventional Limitorque operators prior to startup from first refueling UHRIO.R E Florida Power & Light Co 83/10/06 D'REILLY, J R Region 2, Opfice of Director ip 20/61 185 24X Fiche 50-389,83/10/06.8310140217
- 8310250060 LER 83-056/03L-0 on 830707. w/shutdown cooling (SDC) train 28 in operation, SDC train 2A in injection made & loop B reactor coolant pumps inoperable loop A pumps made inoperable Caused by erroneously racking out pumps W/83100/ ltr
 BRANNIN.JF. WILLIAMS.J W Florida Power & Light Co 83/10/07
 0'RESILV.JF Region 2. Office of Director 2pp 20894 174 24X
 Fiche 50-369,83/10/07.8310250060
- 6310250037 LER 83-055/03L-0 on 830910, wide range nuclear instrumentation C failed On 830912, channel D failed Caused by failure of decade dividers in log countrate cards Parts replaced W/831010 1tr
 PARKS.B N, WILLIAMS.J M Florida Power & Light Co 83/10/10 O'REILLY,J P Region 2, Dffice of Director 2pp 20894 087 24X Fithe 50-389, 83/10/10,83102500
- 8310250337 LER 83-053/03L-0 on B30709, while in hot shutdown, containment pressure exceeded 0 4 psig limit Caused by heatup & high pressure Pressure released by purge after obtaining waste gas release permit PARKS, B M. WILLIAMS, J W. Florida Power & Light Co. B3/10/10 O'REILLY, J P. Region 2. Office of Director 2pp 20898 024 24X Fiche 30-389, 83/10/10.8310250337
- 8310190104 LER 83-038/03L-0 on 830914.during 100% power fire doors found open Caused by const activities Continuous fire patrol watch observed since startup W/031013 ltr MCLAUGHLIN,L, WILLIAMS,J W Florida Power & Light Co 83/10/13 0'REILLY,J P Region 2, Office of Director 2pp 20822 110 24% Fiche 50-389,83/10/13.8310190104
- COCKET 50-370 WATTS BAR NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- B310050076 Concurs w/dissolution of Model D2/D3 Steam Generator Util Design Review Panel Panel work complete MOVAN.7 H Assistant Director for Liconsing B3/09/23 BLACKLEY, B K Design Review Panel Spp 20650 165 24X Fiche 50-000.83/09/23,8310050076
- 8310170031 Forwards procedures & protocol to be followed by util, Rlack & Veatch & NRC re completion of review & evaluation of independent review of facility auxiliary feedwater sys NOVAK, T M Assistant Director for Licensing 83/09/30 PARRIS, H & Tennessee Valley Authority 5pp 20798:337 24X Fiche 50-390, B3/09/30, 8310170031
- 8310170725 Forwards request for add1 info re environ equipment qualification program based on util 830819 environ qualification rept Response requested by 831017 ADEMSAM.E Q Licensing Branch 4 63/10/04 PARRIS.H Q Tennessee Valley Authority 9pp 20798 074 24X Fiche 50-390.83/10/04, 8310170725

- 8310140224 Provides info supporting util decision not to install safety-grade manual switches in main control room for closure of isolation valves in upper head injection sys MILLS, L.M. Tennessee Valley Authority 83/10/11 ADENSAM. E. Licensing Branch 4 4pp 20761 175 24X Fiche 50-370.83/10/11.8310140224
- 8310180388 Requests that latest fuel load dates specified in CPPR-91 & CPPR-92 be extended to Jan & Jul 1985 respectively Addl work required prior to projected fuel load dates listed HILLS.L M Tennessue Valley Authority 83/10/11 ADENSAM,E Licensing Branch 4 2pp 20803 213 24X Ficho 50-390.83/10/11, 830180388
- B310210023 Forwards util B31003 ltr to J Robinson of Black & Veatch ra independent review program personal svcs contract Ltr forwarded in keaping w/protocol for handling program, per TM Novak B30930 ltr KAMMER, D S Tonnessee Valley Authority B3/10/14 ADENBAM, E Licensing Branch 4 Spp 20055 33B 24X Fiche 50-390, B3/10/14, B200310023
- 8310290034 Notifies of 831025 meeting in Knoxville, TN to discuss TVA procedures for controlling & implementing corrective action on Black & Veatch findings re auxiliary feedwater sysindependent review MILLS, L M Tennessee Valley Authority 83/10/18 ADENSAM E Q Licensing Branch 4 ip 20897 271 24% Fiche 50-090,83/10/18,8310250034
- 8310280173 Formards latest response to NUREO-0737, Item II D 3, "Direct Indication of Relief & Safety Valve Position." reflecting as-installed location of acoustic monitoring systaccelerometer MILLS.L M Tennessee Valley Authority 83/10/24 ADENSAM.E Licensing Branch 4 2pp 20929 006 24% Fiche. 30-390,83/10/24,8310280173
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8310210301 Forwards Drawings 47H600-26 & 47H600-27, depicting add1 two sensor location changes per BER Confirmatory Item P3, MILLS,L M Tennessee Valley Authority 83/10/18 ADENSAM,E Licensing Branch 4 4pp 20851 057 24X Fiche 50-370,83/10/18, 8310210301
- F Security, medical, emergency & fire protection plans
- B310250347 Supple response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-27 & 50-391/82-26 Guidance defining fire protection GA boundaries delayed delaying completion of drawing rev effort & GA verification KAMMER, D & Tennessee Valley Authority B3/07/25 G'REJLLY, J P. Region 2. Office of Director in 20898 086 24X Fiche 50-390,83/07/25,8310250367
- 8310040452 Bubmits central emergency control ctr meteorological data availability statistics for Aprilune 1983 Data availability repts will be discontinued due to consistently high data availability through previous rept periods HILLB.L M Tennessee Valley Authority B3/09/28 ADENSAM.E. Licensing Branch 4 2pp 20623 326 24X Fiche 50-000.83/09/28.
- 8310040402 Forwards results of greliminary lighting survey for main control room, per 830727 request & NURES-0700 MILE.L M Tennessee Valley Authority. 83/09/29 ADENBAM, E Licensing Branch 4 2pp 20617 352 24X Fiche 30-390,83/09/29,8310040402
- 8310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830904-09 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/09/29. PARRIS.H.O Tennessee Valley Authority 2pp 20895 322 24X Fiche 50-390,83/09/29.8310250303
- --8310250304 IE Insp Repts 50-390/83-34 & 50-391/83-23 on B30906-09, No noncompliance noted Major areas inspected licensee readiness for emergency preparedness appraisal CLINE, W.E., KREH, J.L. Region 2, Office of Director JENKINS, O R Division of Emergency Preparedness & Materials Bafety. B3/09/28 7pp 20895 324 24X Fiche 50-390, 83/09/29, 8310250303
- 8310180315 Forwards response to 830325 request for add1 info re 10CFR50 App R Info includes color-coded line drawings demonstrating compliance w/Section III 9 & L & degree of separation for equipment inside containment KAMMER, D 8 Tennessee Valley Authority 83/10/12. ADENSAM. E. Licensing Branch 4 22pp 20806;244 24X Fiche. 50-370;83/10/12,8310180315

J Insurance & indemnity information

- 8310140130 Forwards secondary financial protection certificates to NELIA Policy N-80 & MAELU Policy N-80 DUCK: J R Marsh & McLennan Inc 83/10/03 BALTZMAN, J Assistant Director for State & Licensee Relations 13pp 20763 343 24X Fiche 50-390,83/10/03.8310140130
- G Inspection reports. IE Bulletins & correspondence
- 83i0250367 Suppls response to NRC 820827 ltr re deviations noted in II Insp. Repts 50-390/82-29 & 50-391/82-26 Ouidance defining fire protection QA boundaries delayed delaying completion of drawing rev effort & GA verification KAMMER, D B Tennessee Valley Authority 83/07/25 O'REILLY, J P Region 2, Office of Director ip 20898 086 24% Fichs 50-390/83/07/25, 83i0250367
- 8310040140 Forwards IE Insp Rept 50-370/83-31 on 830817-17 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/09/09 PARRIS,H G. Tennessee Valley Authority 2pp 20608 013 24X Fiche 50-370,83/09/09,8310040140
- --8310040147 IE Insp Rept 50-390/83-31 on 830817-19 No necomplicane noted Major areas inspected exam of installed supports & restraints.piping vibration program & followup on outstanding items
 WHITENER.H L , JAPE.F Region 2. Office of Director 83/09/07 3pp. 20808 015 24% Fiche 50-390,83/09/09.8310040140
- 8310040423 Forwards IE Insp Repts 50-390/83-29 & 50-391/83-20 on 830815-19 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs. 83/09/12 PARRISH 9 Tennessee Valley Authority 10pp 20619 127 24X Fiche: 50-390, 83/09/12, 8310040423
- --B310040427 IE Insp Repts 50-390/B3-27 & 50-391/B3-20 on B30815-19 No noncompliance noted Major areas inspected licenser action on previous enforcement matters, independent inspector. IE Bulletin 79-14 & inspector followup items
 YORK. W. Region 2. Office of Director BLAKE. J. Division of Engineering & Operational Programs 83/09/08 10pp 20519 129 24X Fiche 50-390,83/09/12.8310040423
- 8310040555 Forwards IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-0826 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/09/12, PARRIS, H O Tennessee Valley Authority Spp 20622, 160 24X Fiche 50-390, 83/09/12, 8310040555
- --8310040563 IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-26
 No noncompliance noted Major areas inspected preoperational test procedure review & results & review & followup on previously identified insp findings
 THOMAS, M. Region 2. Office of Director JAPE, F. Division of Engineering & Operational Programs 83/09/07 5pp 20622.162
 24X Fichs 50-390,83/09/12.8310040555
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Syc list ent? JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp. 20754 022 24X Fiche. 50-000, 83/09/26, 8308300340,
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes "Svc list encl JORDAN," Svc list encl JORDAN, E. D. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co. of New York, Inc. 116pp. 20777 210 24X Fiche 50-000, B9/09/26, 8308300342.
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/49/26 Consolidated Edison Co of New York, Inc. 118pg. 20778 001 24% Fithe 50-000, B3/09/26, 8308300345
- 830B300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Bys W/o 10CFR50 39 Evaluation " Svr list encl. JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp. 20716-324. R4X Fiche 50-000,83/09/29,830B300349
- 8310230303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No noncompliance noted. VERRELLI, D M Division of Project & Resident Programs. 83/09/29 PARRIS. H O Tennessee Valley Authority 2pp. 20895 322 24X Fichs 50-390,83/09/29,8310250303

- ---8310250304 IE Insp Repts 50-390/83-34 & 80-391/83-23 on 830904-09 No nancompliance noted Major areas inspected licensee readiness for emergency preparedness appraisal CLINE, W E , KREH, J L Region 2, Office of Director Jenkins, 6 R Division of Emergency Preparedness & Materials Safety 84/09/28 7pp 20895 324 24X Fiche 50-390,83/09/29,8310250303
- 8310250397 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-25 on 830912-16 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/10/04 PARRISH 6 Tennessee Valley Authority 2pp 20897 191 24X Fiche 50-390,83/10/04/8310250397
- --8310250406 IE Insp Repts 50-390/83-36 & 50-391/83-25 on 830912-16 No noncompliance noted Major areas inspected licenses action on previous enforcement matters & 10CFR21 reportability MCFARLAND, C.R. Region 2. Office of Director UPRIGHT, C.M. Division of Engineering & Operational Programs & 3709/29 dpp 20897 193 24X Fichs 50-390,83/10/04,8310250397
- 8308300378 lE Info Notice 83-65, "Surveillance of Flow in RTD Bupass Loops Used in Westinghouse Plants " Svc list enr! JORDAN, E Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24% Fiche 30-000,83/10/07.8308300378
- B30B300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fishe 50-000,83/10/07.8308300/52
- B30B300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Ficho 50-000, B3/10/11, B30B30075?
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl. JGRDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co of New York Inc 120pp 20827 129 24X Fiche 50-000, 93/10/11, 8308300761
- 8 Reportable occurrences, LERs & related correspondence
- 8310030214 Second interim deficiency rept re seismic analysis of north steam valve room Initially reported on 830502 Natural frequencies not used resulting in clipping peaks of response spectra Reanalysis performed ancomponating deficiencies HILLS.L M Tennessee Valley Authority 83/09/21 0'REILLY, J.P. Region 2. Office of Director 2pp 20592 321 24X Fiche 50-390,83/09/21,8310030214
- 8310030233 Third interim deficiency rept re GA program on Tubrline mat) supplied by Capitol Pipe Initially reported on 830327 Stop work order issued T-L fittings/flanges not installed in safety-related sys Next rept by 831108 MILLBL M Tennessee Valley Authority 83/09/21 O'RETLLY, J P Region 2, Office of Director Spp 20590 343 24% Fichm 50-000,83/09/21,8310030293
- B310030244 Final deficiency rept re offsot lead-in guides on Wachter spent fuel cells Initially reported on B30318. Engineering Change Notice 4043 issued revising Wachter Assoc. Inc drawings Also reportable per Part 21
 MILLS.L.M. Tennessee Valley Authority B3/09/21 O'REILLY, J P Region 2, Office of Director 2pp 20591 069 24X
 Fiche 50-390, 83/09/21, 8310030744
- 8310030252 Supplemental final deficiency rept re main control room habitability Initially reported on 800305 Corrective action in 830906 ltr applicable to Watts Bar only MILLS.L M Tennessee Valley Authority 83/09/21 D'REILLY.J P Region 2, Office of Director ip 20592 310 24X Fiche 50-390, 83/09/21,8310030252
- 8310030257 First interim deficiency rept re broken pin carrier plates on ERCM motors meg by Siemens-Allis Initially reported on 830824 Vendor in process of determining max loading applied to bushings Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 83/09/21 D'REILLY.J P Region 2, Office of Director 2pp 2059: 060 24X Fiche.50-390,83/09/21.8310030257
- B310030338 Second interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on 830327 Problems reamalyzed using Version 2 issued 830506 Users manual revised Next rept expected by 831231 MILLS.L M Tennessee Valley Authority B3/09/21 0'REILLY.J P Region 2. Office of Director 2pp 20590 303 24X Fiche 50-390,83/09/21.8310030338

- E3100303BB Second interim deficiency rept re GA program for personal svc contract Initially reported on 830406 Controlled copies of engineering procedures sent to Oilbert Assoc Next rept espected by B31014
 MILLS.E.M. Tennessee Valley Authority 83/07/21 O'REILLY, J.P. Region 2. Office of Director 2pp 20592 137 24X
 fiche 50-000.83/09/21.831003038B
- \$310030JF9 Third interim deficiency rept re incorrect use of Category [IL1 supports on pipes near water chillers Initially reported on B30117 Shielding structures being designed to protect chillers Next rept expected by B31017 KTLLS.t. M. Tennessee Valley Authority 83/09/21 O'REILLY, J.P. Region 2, Office of Director 2pp 20593 075 24% Fiche 50~390,83/09/21,8310030399
- 6310030404 First interim deficiency rept re fire dampers not adequately shown on design typical drawings initially reported on 830824 Clearances between fire damper & embedded sleeve will be inspected Next rept expected by 831706 MILLS.L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2. Office of Director 2pp 20602 217 24X Fische 50-390,83/09/21.8310030404
- 8310030424 Third interim deficiency rept re failure to provide bolt tightening requirements Initially reported on 830120 Requirements provided in general note drawings structural drawings & manufacturers installation procedures MILLS.L H Tennessee Valley Authority 83/09/22 O'REILLY, J P Region 2, Office of Director 2pp 40593 178 24X Fiche 50-390,83/09/22,8310030424
- B310030473 Final deficiency rept for Unit 1 & fourth interim deficiency rept for Unit 2 re use of digitized response spectra data Initially reported on 820422 Engineering Change Notice 3491 issued to revise drawings Next rept expected by 840630 MTLLS.L M Tennessee Valley Authority B3/09/22 D'REILLY, J P Region 2, Office of Director 3pp 20601 061 24X Fiche 50-390,83/09/22,8310030473
- 8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitarque motor operators Initially reported on 920830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21 HILLS.L M Tennessee Valley Authority 83/09/22 O'REILLY, J P Region 2. Office of Director 3pp 20601 174 24X Fichs 50-000.83/09/22.8310030506
- 8310030519 Final deficiency rept re failure to evaluate operator actions to realign ERCW train A Initially reported on 820510 Amalysis revealed that sys able to deliver design flow to all loads during 10 minutes following DBA MILLS.L M Tennessee Valley Authority 83/09/22 D'REILLY, J P Region 2, Office of Director 2pp 20601 201 24X Fiche 50-390,83/09/22.8310030519
- 8310030538 Final deficiency rept re incorrect max pipe movements contained in TRIPE program initially reported on 830504 Response spectrum utilized in analyzing earthquake affect results in conservative displacements MTLLS.L if Tennessee Valley Authority 83/09/22 O'REILLY, J P Region 2, Office of Director 3pp 20601 207 24% Fighe 50-000.83/09/22,8310030530
- 8310030365 Final deficiency rept re Mariam Instruments orifice plates described in GA program Initially reported on 830510 No safety-related plates mfg for util since subj audit Util will verify implementation of GA MILLS. LM Tennessee Valley Authority 83/09/23 O'REILLY, J. F. Region 2. Office of Director 3pp 20592 327 24X Fiche 50-390.83/09/23.8310030365
- 8310030370 Final interim deficiency rept ra diesel generator electrical equipment temp rating Initially reported on 820601 Engineering change notice issued Ventilation sys can maintain acceptable temp in electrical equipment HILLS.L M Tennessee Valley Authority 83/09/23 D'REILLY, J P Region 2, Office of Director 2pp 20592, 175 24X Fiche 50-390,83/09/23,83100303/0
- 9310030476 First interim deficiency rept re calculation of support design loads in TRIPE Initially reported on B30714, Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220 M1LL5.L M Tennessee Valley Authority, 83/07/23 O'REILLY, J P Region 2. Office of Director 2pp. 20602 095 24X Fiche 50-000.83/09/23.8310030436
- 8310030462 Final deficiency rept re heat loss from Power Bys diesels Initially reported on 820729 Heat loss tests performed on 821120 & 830283 confirmed temps near safety-related sequipment exceeded limits Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 83/09/23 D'REILLY, J P Region 2. Office of Director 3pp 20601 049 24X Fiche 50-370,83/09/23,8310030462

- B310040180 Final deficiency rept re lack of evidence that auxiliary feedwater pump components meet ASME Class 3 or TVA Class C code requirements Initially reported on B20330 Drawings revised to identify ploing & components properly MILLGL M Tennessee Valley Authority 83/09/27 0'REILLY, J P Region 2. Office of Director 2pp 20608 245 24X Fiche 50-390.83/09/27,8310040180
- 8310040544 Final deficiency regt re transfer switches to auxiliary feedwater sys having mondivisional power Initially reported on 830202 Caused by design oversight Engineering change notices issued & design mods made.

 MILLS.L M Tennessee Valley Authority 83/09/27 D'REJLLY, J.P. Region 2, Diffice of Director 3pp 20623 251 24X
 Fiche 50-390.63/09/27,8310040544
- 8310040138 Final deficiency rept re improper classification of ERCW sys piping & components. Initially reported on 810324 Components & drawings will be revised to show correct classification of HVAC equipment by 831115 MILLS.L M Tennessee Valley Authority 83/09/28 0'REILLY, J P Region 2, Dffice of Director 5pp 20408 008 24X Fiche 50-390,83/09/28,8310040138
- 8310040193 Final & second interim deficiency repts for Units 1 & 2, respectively re high pressure fire protection sys piping water danger to shutdown board transformers after postulated earthquake Instially reported on 830616 MILLS.L M Tennessee Valley Authority 83/09/28 O'REILLY, J.P. Region 2, Office of Director 3pp 20608 103 24X Fiche, 50-390, 83/09/28, 8310040193
- 8310040849 First interim Deficiency Rept NRC H-138-P re failure of pressurizer level transmitters to cover process range. Initially reported on 830829 Expected disposition will be new calibr span Next rept will be submitted by 840106 MILLS.L M Tennessee Valley Authority 83/09/28 0'REILLY, J P. Region 2. Office of Director 2pp 20623 249 24X Fiche 50-390,83/09/28,8310040549
- 8310060009 Final deficiency rept re support welds not inspected or documented Initially reported on 830711 List developed of supports requiring weld insp Helds will be Inspected & reworked if necessary by 831130 MILLS.L M. Tennessee Valley Authority 83/09/29 D'REILLY, J P Region 2. Office of Director. 2pp 20647 243. 24X Fichs 50-390.63/09/29.8310060009
- 8310060016 Final deficiency rept re valve position indication problems w/EMD gate valves Initially reported on 830203 Westinghouse equipment engineers porvided w/instructions re valve function Also reportable under Part 2: MILLS.L M Tennessee Valley Authority 83/09/29 O'REYLLY, J P Region 2. Office of Director 2pp 20648 354 24X Fiche 50-390,63/09/29,8310060016
- 8310060027 Final deficiency rept re containment spray miniflow valve design error Initially reported on 820305 Westinghouse internal design assurance & verification procedures revised Also reportable under Part 21 MILLS.L M Tennessee Valley Authority 83/07/29 D'REILLY, J P Region 2, Office of Director 2pp 20847 091 24X Fiche: 50-390, 83/09/29, 8310060027
- 8310060008 Second interim deficiency rept re diesel generator rear bearing problem Initially reported on 630627 Generator repsired. Bearing assembly dimensions will be examined to determine presence of out-of-tolerance parts MILLS.L M Tennessee Valley Authority 63709/30 D'REILLY, J. P. Region 2. Defice of Director 2pp 20647, 241 24X Fiche 50-390, 63/09/30, 6310060008
- B3100600B7 Final deficiency rept to review b updating of piping drawings. Initially reported on 820621 Design Criteria Document HB-DC-40-31 3 revised to add Section 4 3 requiring mod to assure piping has been updated MILLS.L M Tennessee Valley Authority B3/09/30 O'REILLY, J. P. Region 2. Office of Director 3pp 20648 335 24X Fiche 50-390,83/09/30.8310060087
- 8310060095 Final deficiency rept for Unit 1 & fifth interim deficiency rept for Unit 2 re discrepancies in support details. Initially reported on 820302 & 830311. respectively Revs to support drawings with be issued by 840103 MILLS.L M Tennessee Valley Authority 83/09/30. O'REILLY, J. P. Region 2, Office of Director 4pp. 20648-338 24X Fiche 50-390,83/09/30.8310060095
- 8310060331 Final & sighth interim deficiency repts for Watts Bar & Bellefonts, respectively re inconsistent establishment of insp program Initially reported on BiO324 Requirements, control & use of const requirements manual developed MILLS.L M Tennessee Valley Authority 83/07/30, 0'REILLY, J P Region 2. Office of Director 4pp 20441 001. 24X Fiche 50-000,83/09/30,8310060331

- 8310060342 Final deficiency rept re steam generator lower support bolts Initially reported on 820610 Reheat treatments provide adequate strength at operating temp, sufficient fracture toughness & crack resistance Also reportable per Part 21 MILSLL M Tennessee Valley Authority 83/09/30 D'REILLY. J P Region 2. Office of Director 3pp 20646-077 24X Fiche 50-390,83/09/30,8310060342
- 8310060436 Final deficiency rept re failure of safetq-related Westinghouse gate valves Initially reported on 801031 All affected valves modified & applicable drawings revised MILLE, L M Tennesses Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director 2pp 20641 227 24X Fiche 50-390,83/09/30,8310060436
- 8310060474 Fifth interim deficiency rept re setpoint program for overpressure mitigation sys Initially reported on 820521 Util conducted PDRV response time tests Next rept expected by 840103 Also reportable under Part 21 HILLS-L M Tennesses Valley Authority 83/07/30 O'REILLY, J P Region 2. Office of Director 2pp 20641 017 24X Fiche 50-390.83/07/30,8310060476
- 8310040488 Final & third interim deficiency repts for Units 1 & 2, respectively re-postulated accident blowdown of more than one steam generator Initially reported on 821015 Power supply to steam generator PDRV rearranged MILLO, t. M. Tennessee Valley Authority 83/09/30 O'REJLLY, J. P. Region 2, Office of Director 2pe 20441-015 24X Fiche: 50-390, 83/09/30, 8310040488
- 8310070301 Potential Part 21 rept re underronge characteristic of Model N-EliGM transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN M.J. Foxbord Corp 83/09/30 Director's Office of Inspection and Enforcement 11pp 20651 064 24X Fiche 50-000,83/09/30,8310070301
- B310120236 Final deficiency rept re incorrectly installed pressurizer instrument line Initially reported on B30727. Engineering Change Notice 4249 issued to correct Control Diagram 47M610-66-5 F7. Hardware corrections completed by B31130 MILLE, L M Tennessee Valley Authority B3710/03 O'REILLY, J P Region 2. Office of Director 2pp. 20692 170 24X Fiche 50-390.83/10/03,8310120236
- 8310120237 Final deficiency rept re ambiguous outputs from Barton pressure transmitters in RCB Initially reported on 830409 Add1 RCB transmitters installed outside containment Also reportable per Part 21 MILLS,L M Tennessee Valley Authority 83/10/03 O'REILLY, J P Region 2. Office of Director 3pp 20692 172 24% Fiche: 50-390.83/10/03.8310120237
- 8310120332 Final deficiency rept re excessive movement of containment penetration believs initially reported on 811204 Analysis determined that beliew movement may exceed 0 224-inch lateral displacement. Engineering change notice initiated MILLE, L. M. Tennessee Valley Authority 83/10/03 0'REILLY, J. P. Region 2, Defice of Director 3pp 20499, 272 24% Fichs. 50-390, 83/10/03, 8310120332
- 8310120376 Final & fourth interim deficiency rept for Units 1 & 2, respectively, re control of civil engineering support branch shelpsis calculations Initially reported on 820823. Plange qualification requirements incorporated into checklist MILLS,L M Tennessee Vallay Authority. 83/10/03. O'REILLY, J P Region 2. Office of Director 2pp 20700 197 24% Ficher 50-390, 83/10/03, 83/0120376
- 8310120100 Final & seventh interim deficiency repts, for Units 1 & 2, respectively, re-piping sys analysis & pipe support design efforts for Class 1,2 & 3 sys Initially reported on 801217, All Unit i supports designed for current loads MILLS,L. M. Tennesses Valley Authority 83/10/94 O'REILLY, J.P. Region 2, Office of Director 200 20A9A ten 24X

- 8310120336 Final deficiency rept re questionable patches of plastic cement mortar Initially reported on 820429 Sampling of expansion anchored supports proved adequacy of supports Item not reportable per 10CFR50 551e)
 MILLS.L H. Tennesses Valley Authority 83/10/04 O'REILLY, J.P. Region 2. Office of Director Spp. 20699 279 24X fiche 50-390,83/10/04,8310120336
- 8310120389 Final & sixth interim deficiency repts for Units 1 & 2, respectively, re discrepancies in as-built vs as-analyzed piping sys Initially reported on 810226 Support locations evaluated All Unit I rework will be completed by 831201 MILLS,L M Tennessee Valley Authority 83/10/04 0'REILLY, J P Region 2, Office of Director App 20699 128 24X Fiche 50-390,83/10/04.8310120389
- B31014004B Final deficiency rept re mass of HVAC supports not included in frequency calculations Initially reported on B30809 Designs revised Field rework & support work will be completed by B40101 MILLS,L M Tennessee Valley Authority 89/10/05 O'REILLY,J P Region 2, Office of Director 2pp 20768 272 24X Fiche 50-390,83/10/05.831014004B
- 8310140017 Becond interim rept re pump motors supplied w/o seismir smallysis or operability demonstration initially reported on 830428 Addi info received from Westinghouse but analysis not completed Next rept expected by 831230 MILLS,L M Tennessee Valley Authority 83/10/06 O'REILLY, J P Region 2, Diffice of Director 2pp 20767 027 24X Fiche 50-370,83/10/06.83/0140017
- 8310170264 Second interim deficiency rept re routing of radioactive & nonradioactive sys instrument lines Initially reported on 830729 Engineering Change Notice 4287 initiated to remove instrument lines Next rept expected by 831221 MILLS.L M Tennessee Valley Authority 83/10/06 0'RCILLY, J P Region 2, Office of Director 1p 20787 100 24X Fiche 90-370,83/10/06.8310170264
- 8310210096 Final rept re GA program deficiencies in Gilbert Assoc personal sves contract initially reported on 830406, Specific problems not identified by audit Items not reportable per 10CFR50 55(e) MILLS,L M Tennessee Valley Authority 83/10/12 0'REILLY, J P Region 2, Office of Director App 20858 197 24% Fiche 50-000,83/10/12,8310210096
- B31025037B Final deficiency rept re supports not designed or modified as required by Engineering Change Notice 2576 Initially reported on B3011B Support designs reviewed Design mods will be completed by B31230 MILLS,L M Tennessee Valley Author,ty 83/10/12 O'REILLY, J P Region 2, Office of Director 2pp 20099,137 24% Fiche 50-390,83/10/12,8310250378
- 8310190087 Final deficiency rept re discrepancy in interface coordination of design review process Initially reported on 810717 Finding of coordination problem not significant & should not have been reported to NRC per 100FRSD 55(e) MILLS.L.M Tennessee Valley Authority 83/10/13 0'REILLY.J.P. Region 2. Office of Director 3pp 20818 132 24% Fiche 50-000, 83/10/13.8310190087
- 8310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents initially reported on Bil215 Listed changes to design review process will be implemented by 840101
 MILLS.L M Tennesse Valley Authority 83/10/13 G'REILLY, J P Region 2. Office of Director 3pp 20818 045 24X
 Fiche 50-000,83/10/13.8310190224
- 8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 830120 New requirements for assessing piping vibration problems during prooperational testing requirements issued MILLS,L M Tennessee Valley Authority 83/10/13 0'REILLY,J P Region 2, Office of Director 3pp 20855 345 24X Fiche 50-000,83/10/13,8310210011
- 8310210015 First interim deficiency rapt re support for test lines by alternate analysis Initially reported on 830919 Existing support structure being analyzed to determine if mods necessary for DBA loadings Next rept by 831205.
 MILLS-L M Termessee Valley Authority 83/10/13 0'REJLLY, J P Region 2, Office of Director 2pp 20858 261 24% Fiche 50-390,83/10/13.8310210015
- B310210042 Supplemental deficiency rept re-sensing of pipe breaks in component cooling sys. Initially reported on 830624 Typographical error identified in 830709 final rept Engineering change notice number should be 4253,

- 8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4 02 addressing voiding of ECNs changed in Rev 12. issued on 830203 MILLS.L M Tennessee Valley Authority 83/10/13 0'REILLY, J P Region 2. Office of Director 2pp 20055 304 24X Fiche 50-000.83/10/13.8310210047
- 6310210048 Final deficiency rept for Unit 1 & third interim deficiency rept for Unit 2 re loose matl in steam generator Initially reported on 830325 Caused by lack of work controls Also reported be per Part 21 Next rept due by 840706 MILLS.L M Tennessee Valley Authority 83/10/13 O'REILLY, J P Region 2. Office of Director 4pp 20957 270 24X Fiche 50-390,83/10/13.8310210048
- e310190127 First interim deficiency rept re shorted indicating lights in Westinghouse panels Initially reported on 830915
 Westinghouse provided trained wiring separation procedure & wiring sketch Next rept expected by 831215
 MILES.L M Tennessee Valley Authority 83/10/14 O'REILLY.J.P. Region 2. Office of Director 2pp 20821 128 24X
 Fiche 50-390.83/10/14.8310190127
- B310250371 Final deficiency rept for Unit 1 & interim rept for Unit 2 re alternately analyzed piping Verification of all Unit 1 piping corried out by personal svcs contractor & util div of engineering design MILLS.L M Tennessee Valley Authority B3/10/14 O'REILLY, J.P. Region 2. Office of Director 10pp 20898 044 24X Fiche 50-390.83/10/14.8310250371
- 8310250032 Supplemental final deficiency rept re corrosion in high pressure fire protection sys Corrective action will be completed by 831220, per 830930 telcon Vendor math for const rework will not aprive onsite to support original schedule RELES.L M Tembessee Valley Authority 83/10/17 D'REILLY, J P Region 2. Office of Director ip 208/4 183 24X Fiche 50-390,83/10/17.8310250012
- 8310250162 Second revised final deficiency rept re cross-trained diese) generator HX inlet valves Initially reported on 830531 Applicable drawings revised to apply diesel start signal to correct valve Corrections completed MILES.L M Tennessee Vailey Authority 83/10/17 O'REILLY, J P Ragion 2. Office of Director 3pp 20876 273 24X Fiche 50-390,83/10/17.8310250162
- 6310250165 Third interim deficiency rept re spacing & clearance of sprinkler heads in high pressure fire protection sys Initially reported on 830331 Caused by lock of understanding necessity for maintaining adequate spray patterns MILLS.L M Tennessee Valley Authority 83/10/17 0'REILLY, J.P. Region 2. Office of Director Opp 20094 062 24X Fiche 50-390,83/10/17.8310200165
- 8310250173 Final & fourth interim deficiency repts for Units 1 & R, respectively, re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 New spray shields designed to be installed above water chillers MILLS.L M Tennessee Valley Authority 83/10/17 D'REILLY, J P. Region 2. Office of Director 4pp 20893 278 24X Fiche 50-390.83/10/17.8310250173
- B310250233 Revised finel deficiency rept re drawings issued under Engineering Change Notice 2104 w/o adding flexible hose Enittelly reported on B30314 Procedures revised adding checklist for design review MELES:L K Tennessee Valley Authority 83/10/17 D'REILLY, J P. Region 2. Office of Director 2pp 20899 048 24X Fiche 50-390.83/10/17.8310250833
- BGIC270150 Final rept re cable bend radius deficiencies due to use of nemstd fittings Initially reported on 830720 Caused by aisinterpretation of specs Task team appointed to identify, awaluate & resolve problems Rework completed HILLS.L M Tennessee Valley Authority 83/10/18 0'REILLY.J P. Region 2, Office of Director. 3pp. 20725-020 24X Fiche 50-390,83/10/18.8310270180
- 8310270183 Final deficiency rept re welds on structural steel in main steam valve rooms Initially reported on 830921, Util in process of visually reinspecting 100x of all structural steel welds Corrective action will be completed by 841025 MILLS.L. K. Tennessee Valley Authority 83/10/18 O'REILLY, J.P. Region 2. Office of Director 2pp. 20925 031. 24X Fiche 50-390, 83/10/18-8310270183.
- 831031014B Revised final deficiency rept for Unit 1 % first interim deficiency rept for Unit 2 re installation of flow switches & sensing lines Initially reported on 830810 Actual rev to drawings will be accomplished by 831028 for Unit 1. MELLB-L H Tennessee Valley Authority 83/10/19 0'REILLY, J.P. Region 2. Office of Director 5pp 20759 014 24% Fiche 50-370.83/10/19.8310310148

- 8310310320 Final deficiency rept for Unit 1 & fourth interim rept for Unit 2 re improper overlapping analysis techniques Initially reported on 830111 Twenty-nine problems judged unacceptable & reanalyzed to comply w/proper techniques
 MILLS.L. M. Tennesses Valley Authority 83/10/21 D'REILLY, J. P. Region 2. Defice of Director 3pp 20741 210 24X
 Fiche 50-370.83/10/21.8310310320
- 8310310348 Final deficiency rept re Target Rock pressurizer PDRVs failure to open Initially reported on 830922 Analyses could not identify cause for compressed rings Valves modified by vendor Also reportable per Part 2! MILLS.L M Tennesses Valley Authority 83/10/21. D'REILLY, J P Region 2, Office of Director 3pp 20957 074 24X Fiche 50-390.83/10/21.8310310348
- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8310050074 Concurs w/dissolution of Hodel D2/D3 Steam Generator Util Design Review Panel Panel work complete NOVAK.T M Assistant Director for Licensing 83/09/23 BLACKLEY.S K Design Review Panel 5pp 20450 145 24X Fiche 50-000.83/09/23.8310050074
- 8310170725 Forwards request for add1 info re environ equipment qualification program based on util 830817 environ qualification rept Response requested by 831017 ADENSAM.E G Licensing Branch 4 83/10/04 PARRIS.H G Tennessee Valley Authority 7pp 20798 074. 24X Fichs 50-390.83/10/04.8310170725
- 8310140224 Provides info supporting util decision not to install safety-grade manual switches in main control room for closure of isolation valves in upper head injection sys HILLERL M Tennessee Valley Authority 83/10/11 ADEMBAM.E. Licensing Branch 4 App 20761 175 24X Fiche 50-390,83/10/11,8310140224
- 8310180388 Requests that latest fuel load dates specified in CPPR-91 & CPPR-92 be extended to Jan & Jul 1985 respectively Addl work required prior to projected fuel load dates listed MILL9.L M Tennesse Valley Authority 83/10/11 ADENSAM.E Licensing Branch 4 2pp 20803 213 24X Fiche 50-390,83/10/11,8310180388
- 8310210023 Forwards util 831003 ltr to J Robinson of Black & Veatch reindependent review program personal sycs contract Ltr forwarded in keeping w/protocol for handling program.per TM Novak 830930 ltr KAMMER.D S Tennessee Valley Authority. 83/10/14 ADENSAM.E. Licensing Branch 4 Spp 20885 338 24% Fiche 50-390.83/10/14, 8310210023
- 8310250034 Notifies of 831025 meeting in Knoxville. TN to discuss TVA procedures for controlling & implementing corrective action on Black & Vestch findings re auxiliary feedwater sys independent review MILLS.L.M. Tennessee Valley Authority. 83/10/18 ADENSAM, E. O. Licensing Branch 4 ip 20897 271 24X Fiche 50-390,83/10/18,8310250024
- 8310280173 Forwards latest response to NUREO-0737. Item II D 3. "Direct Indication of Relief & Safety Valve Position," reflecting as-installed location of acoustic monitoring systaccelerometer
 HILLS.L.M. Tennessee Valley Authority 83/10/24, ADENSAM.E.
 Licensing Branch 4 2pp. 20929.006 24X Fiche 30-390.63/10/24, 8310280173
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310210301 Forwards Drawings 47H600-26 & 47H600-27, depicting add) two sensor location changes per SER Confirmatory Item 23 MILLS.L.M Tennesse Valley Authority. 83/10/18 ADENSAM.E Licensing Branch 4 App 20851.057 24X Fiche.50-390.83/10/18, 8310210301
- F. Security, medical, emergency & fire protection plans
- B310250367 Supple response to NRC B20827 ltr re deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Guidance defining fire protection GA boundaries delayed, delaying completion of drawing rev effort & GA verification KAMMER, D. S. Tennessee Valley Authority 83/07/25. O'REILLY, J. P. Region 2, Office of Director, ip. 20898, 086 24X Fiche 50-390, 83/07/25, 8310250367.

- 8310040452 Submits central emergency control rtr meteorological data availability statistics for Apr-June 1983 Data availability repts will be discontinued due to consistently high data availability through previous rept persons MILLS.L M Tennessee Valley Authority 83/07/28 ADENSAM.E Licensing Branch 4 2pp 20623 326 24X Fiche 50-000,83/09/28. 8310040452
- 8310040402 Forwards results of preliminary lighting survey for main control room, per 830727 request & NUREC-0700 MILLS, L. M. Tennessee Valley Authority 83/09/29 ADENSAM, E Licensing Branch 4 2pp 20617 352 E4X Ficho 50-390, 83/09/29, 8310040402
- 8310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830906-09 No moncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/09/29 PARRIS.H O Tennessee Valley Authority 2pp 20895 322 24x Fichs 50-390,83/09/29,8310250303
- --8310250304 IE Insp Repts 50-390/83-34 & 50-391/83-23 on 830904-09 No noncompliance noted Major areas inspected licensee readiness for emergency preparedness appraisal CLINE W E Region 2, Defice of Director 83/09/28 7pp 20895 324 24X Fiche 50-390,83/09/29,8310250303
- 8310180315 Forwards response to 830325 request for add1 info re iOCFR50 App R Info includes color-coded line drawings demonstrating compliance w/Section III 0 & t. & degree of separation for equipment inside containment KAMHER.D S Tennessee Valley Authority 83/10/12 ADENSAM.E Licensing Branch 4 22pp 20806 244 24X Fiche 50-390,83/10/12,8310180315

J Insurance & indemnity information

- 8310140130 Forwards secondary financial protection certificates to NELIA Policy N-80 & MAELU Policy M-80 DUCK: J.R. Marsh & McLennan. Inc. 83/10/03 SALTZMAN, J. Assistant Director for State & Licensee Relations. 13pp. 20763-343 24X Fiche 50-390,83/10/03.8310140130
- G Inspection reports. IE Bulletins & correspondence
- 8310280367 Suppls response to NRC 820827 ltm re deviations noted in II Insp Repts 50-390/82-29 & 90-391/82-24 Guidance defining fire protection GA boundaries delayed delaying completion of drawing rev effort & GA verification

 KAMMER, D S Tennesses Valley Authority 83/07/25 O'REILLY, J P

 Region 2, Office of Director 1p 20898 084 24X

 Fiche 50-390,83/07/25,8310280367
- 8310040423 Forwards IE Insp Repts 50-390/83-27 & 50-391/83-20 on 830815-19 No noncompliance noted. VERRELLI,D M Division of Project & Resident Programs 83/09/12 PARRIB,M G Tennessee Valley Authority 10pp 20619 127 24X Fiche 50-390,83/09/12,8310040423
- --B310040427 IE Insp Repts 50-390/83-27 & 50-391/83-20 on 830815-19 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, independent inspector IE Bulletin 79-14 & inspector followup items YORK. W Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/09/08 10pp 20419:129 24X Fiche 50-390,83/09/12.8310040423
- 8310040555 Forwards IE Insp Repts 50-390/83-33 & 50-391/83-22 on 830822-0826 No moncompliance noted VERRELLI, D M Division of Project & Resident Programs. 83/09/12 PARTIS.M 9 Tennessee Valley Authority 5pp 20622 160 24X Fiche 50-390,83/09/12,8310040555
- --8310040563 IE Insp Repts 50-390/83-33 & 50-391/83-22 on 630822-26 No noncompliance noted Major areas inspected preoperational test procedure review & results & review & followed on previously identified insp findings THOMAS, M Region 2. Office of Director JAPE, F Division of Engineering & Operational Programs 83/09/07 Spp 20622:162 24X Fiche 50-390,83/09/12,8310040555
- 8308300340 IE Inho Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list and I JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/09/26 Consolidated Edison Co of New York: Inc 117pp 20754 022 24X Fiche 50-000.83/09/26.8308000340
- 8308300342 IE Into Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fichs 50-000,83/09/26,8308300342

- 8308300345 IE Info Notice 83-63, "Potential failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 (onsolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000.83/09/26.8309:0035
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR90 59 Evaluation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engancering Response (Post 830103) 83/09/29 Consolidated Edison to of New York, Inc. 115pp 20716-324 24X Fiche 50-000,83709/29,8308300349
- B310250303 Forwards IE Insp Repts 50-390/83-34 & 50-391/83-23 on B30906-09 No mancompliance nuted VERRELLI.D M Division of Project & Resident Programs 63/09/29 PARRIS,H 6 Tennessee Valley Authority 2pp 20895 322 24x Fiche 50-390/83/09/29/8310250303
- --B310250304 IE Insp Repts 50-390/B3-34 & 50-391/B3-23 on B30904-09 H, noncompliance noted Major areas inspected licenses readiness for emergency preparedness appraisal CLINE, W E . KREH. J L Region 2. Office of Director JENKINS, 6 R Division of Emergoncy Preparedness & Materials Safety B3/09/28 7pp 20895 324 24X Fiche 50-390.B3/09/29.B310250303
- 8310250397 Forwards IE Insp Repts 50-390/83-36 & 50-391/83-25 on 830912-16 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/10/04 PARRIER H & Tennessee Valley Authority 2pp 20897 J9: 24X Fiche 50-390.83/10/04.8310250397
- --8310280406 IE Insp Repts 50-390/83-36 & 50-391/83-25 on 830912-J6 NJ noncompliance noted Major areas inspected licensee action on previous enforcement matters & IOCFR21 reportability MCFARLAND, C R Region 2, Office of Director UPRIGHT, C M Division of Engineering & Operational Programs 83/09/29 App 20897 193 24X Fiche 50-390,83/10/04,8310250397
- B30B30037B IE Info Notice 83-65, "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3710707 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300370
- B30B300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Cmergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308100/52
- 8308300759 IE Info Notice 83-67, "Emergency Use Respondtor Matl Defect Gauses Production of Notious Gases" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Firbs 50-000, 83/10/11, 8300300757
- 8308300761 IE Info Notice 83-6B, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list and! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20887 129 24X Fichs 50-000-83/10/11.6308309761
- S Reportable occurrences. LERs & related correspondente
- 8310030214 Second interim deficiency rept re seismic analysis of north steam valve room Initially reported on 830502 Natural frequencies not used resulting in clipping peaks of hesponse spectra Reanalysis performed incorporating deficiencies MILLS.L M. Tennessee Valley Authority 83/09/21 O'REILLY.J P. Region 2. Office of Director 2pp 20592 321 24X Fiche 50-390.83/09/21.8310030214
- 8310030233 Third interim deficiency rept to GA program on Tubeline satioupplied by Capitol Pipe Initially reported on 830327 Stop work order issued T-L fittings/flanges not installed in safety-related sys Next rept by 83108
 MILLER, LM Tennessee Valley Authority, 83/07/21 D'REILLY, J Region 2, Office of Director Spp 20590, 343 24X
 Fiche, 50-000, 83/07/21, 8310030233
- 8310030244 Final deficiency rept re offset lead-in guides on Wachter spent fuel cells Initially reported on 830318 Engineering Change Notice 4043 issued reyssing Wachter Associanc drawings Also reportable per Part 21 MILLS.L M. Tennessee Valley Authority 83/09/21 U'REJLLY, J P Region 2, Office of Director 2pp 20591 069 24X Fiche 50-370,83/09/21,8310030244

- 8310030252 Supplemental final deficiency rept re main control room habitability Initially reported on 800305 Corrective action in 830906 ltr applicable to Watts Bar only MILLS.L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director ip 20592 310 24% Fiche 50-390,83/09/21,8310030252
- 8310030257 First interim deficiency rept re broken pin carrier plates on ERCH motors mfg by Siemens-Allis Initially reported on 830824 Vendor in process of determining max loading applied to bushings Also reportable per Part 21 MILLG.L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2. Office of Director 2pp 20591 060 24X Fiche 50-390.83/09/21,8310030257
- B31003033B Second interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on 830329 Problems reanalyzed using Vension 2 issued 830506 Users manual revised Next rept expected by 831231 MILLS.L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2. Defice of Director 2pp 20590 303 24X Fithe 50-390, 83/09/21, 831003033B
- 8310030388 Second interim deficiency rept re QA program for personal svc contract Initially reported on 830404 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
 Mills.L M Tennessee Valley Authority 83/09/21 O'REILLY, J P Region 2, Office of Director 2pp 20592 139 24X
 Fiche 50-000,83/09/21.8310030388
- B310030399 Third interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on B3017 Shielding structures being designed to protect chillers Next rept expected by B31017 M3LLS.1 M Tennessee Valley Authority B3/09/21 O'REILLY, J P Region 2. Office of Director 2pp 20593 075 24X Fiche 50-390, 83/09/21, 8310030399
- 8310030404 First interim deficiency rept re fire dampers not adequately shown on design typical drawings Initially reported on 830824 Clearances between fire damper k embedded sleeve will be inspected Nert rept expected by 831206 MILLS.L M Tennessee Valley Authority 63/09/21 O'REJLLY, J P. Region 2, Office of Director 2pp 20602 217 24X Fiche 50-390,83/09/21,8310030404
- 8310030424 Third interim deficiency rept re failure to provide bolt tightening requirements Initially reported on 830120.
 Requirements provided in general note drawings, structural drawings & manufacturers installation procedures,
 Mill6.L M Tennessee Velley Authority 83/09/22 0'REILLY, J P
 Region 2. Office of Director 2pp 20593 178 24X
 Fiche 50-390,83/09/22,8310030424
- 8310030473 Final deficiency rept for Unit 1 & fourth interim deficiency rept for Unit 2 re use of digitized response spectra data Enitially reported on 820422 Engineering Change Notice 3491 issued to revise drawings Next rept expected by 840630 MILLS.L H Tennessee Valley Authority 83/09/22 D'REILLY, J P Region 2, Office of Director 3pp 20601 061 24X Fische 50-390,83/09/22,8310030473
- 831003050A Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21 MfEL9.L M Tennessee Valley Authority 83/09/22 O'REILLY, J. P Region 2. Office of Director 3pp 20601 194 24X Fiche 50-000,83/09/22,8310030506
- 9310030519 Final deficiency rept re failure to evaluate operator actions to realign ERCW train A Initially reported on 820510 Analysis revealed that sys able to deliver design flow to all loads during 10 minutes following DBA MILLS.L M Tennessee Valley Authority 83/09/22 0'REILLY, J. P. Pegico 2. Office of Director 2pp 20601-201 24X Fiche 50-390,83/09/22,8310030519
- 8310030538 Final deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830804 Response spectrum utilized in analyzing earthquake effect results in conservative displacements MILLS.L.M Tennessee Valley Authority 83/09/22 O'REJLLY, J P Region 2. Office of Director 3pp 20601:207 24X Fiche 50-000,83/09/22,8310030538
- 8310030345 Final deficiency rept re Mariam Instruments orifice plates described in GA program Initially reported on 830510. No tafety-related plates mfg for util since subjaudit Util will verify implementation of GA MILLS.L M Tennessee Valley Authority 83/09/23 D'REILLY, J P Region 2, Office of Director 3pp 20592 327. 24X Fiche: 50-390, 83/09/23, 8310030365

- 8310030370 Final interim deficiency rept re diesal generator electrical equipment temp rating Initially reported on 820601 Engineering change notice issued Ventilation sys can maintain acceptable temp in electrical equipment MILLS, L.M. Tennesses Valley Authority 83/09/23 0'REILLY, J.P. Region 2. Defice of Director. 2 pp 20392 175. 24% Fichs 50-390,83/09/23,8310030370
- 8310030A36 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714. Procedure developed allowing recomputation of design loads near localized phenomena by hand Noxt rept by 831220.

 MILLS, L. M. Tennesse Valley Authority. 82/09/23 8'REILLY, J. P. Region 2, Office of Director 2pp 20402 095 24X

 Fiche 50-000,83/09/23,8310030436
- 8310030462 Final deficiency rept re heat loss from Power Bys diesels. Initially reported on 820729 Heat loss tests performed on 820120 & 830223 confirmed temps near safety-related equipment exceeded limits Also reportable per Part 21. MILLS, L M Tennassee Valley Authority 83/09/23 0'REILLY, J P Region 2. Office of Director. 3pp 20601 049 24X Fiche: 50-390,83/09/23,8310030462
- 8310040180 Final deficiency rept re lack of evidence that auxiliary feedwater pump components meet ASME Class 3 or TVA Class C code requirements Initially reported on 820330 Drawings revised to identify piping & components properly MILLS, L M Tennessee Valley Authority 83/09/27 O'REILLY, J P. Repion 2. Dffice of Director 2pp 20608 265 24X Fiche 50-390,83/09/27,8310040180
- 8310040944 Final deficiency rept re transfer switches to auxiliary feedwater sys having nondivisional power Initially reported on 830202 caused by design oversight Engineering change notices issued & design mods made MILLS,L M Tennessee Valley Authority 83/09/27 O'REILLY, J P Region 2. Defice of Director 3pp 20623 251. 24X Fiche, 50-390, 83/09/27, 8310040544
- 83i0040138 Final deficiency rept re improper classification of ERCM sys plping & components Initially reported an 810324.
 Components & drawings will be revised to show correct classification of HVAC equipment by 83i115
 MILLS.L M Tennesse Valley Authority 83/09/28. O'REILLY.J P Region 2. Office of Director. Spp 20608.008. 24X
 Fiche: 50-390.83/09/28.83i0040138
- 8310040173 Final & second interim deficiency repts for Units 1 & 2. respectively re high pressure fire protection sys piging water danger to shutdown board transformers after postulated earthquake Initially reported on 830616 MILLERL M Tennessee Valley Authority 83/09/28 O'REILLY, J F. Region 2. Office of Director. 3pp 20608.103, 24X Fiche: 50-390, 83/09/28, 8310040193
- B310060009 Final deficiency rept re support welds not inspected or documented Initially reported on B30711 List developed of supports requiring weld insp Welds will be inspected & reworked if necessary by B31130 MILLS.L.M. Tennessee Valley Authority. B3/09/29. O'REILLY, J P Region 2. Defice of Director 2pp 20647 243 24X Fiche 50-390,83/09/29,8310060009
- 8310060016 Final deficiency rept re valve position indication problems w/EMD gate valves. Initially reported on 830203. Westinghouse equipment engineers porvided w/instructions re valve function Aiso reportable under Part 21 MILLS.L M Tennessee Valley Authority. 83/09/29 D'REILLY.J.P. Region 2. Office of Director 2pp. 20648 354. 24X Fiche: 50-390, 83/09/29, 8310060016
- 831006027 Final deficiency rept re containment spray minifiew velve design error Initially reported on 820305 Westinghouse internal design assurance & verification procedures revised. Also reportable under Part 21 MILLB.L M Tennessee Valley Authority 83/09/29. D'REILLY, J.P. Region 2. Defice of Director. 2pp 20647 091. 24X Fiche: 50-390, 83/09/29, 8310060027
- 8310060008 Second interim deficiency rept re diesel generator rear bearing problem Initially reported on 830627. Generator repaired Bearing assembly dimensions will be examined to determine presence of out-of-tolerance parts.
 MILLS.L.M Tennessee Valley Authority, 837/07/30 D'REILLY, J P Region 2, Office of Director 2pp 20647 241 24X Fiche: 50-370, 83/07/30, 8310060008
- 8310060087 Final deficiency rept re review & updating of piping drawings. Initially reported on 820621 Design Criteria Document WB-DC-40-31 3 revised to add Baction 4.3 requiring mod to assure piping has been updated MILLS.L M. Tennesses Valley Authority 83/09/30 0'REILLY.J P Region 2. Office of Director 3pp 20648 335 24X Fiche.50-390,83/09/30,8310060087

- B310060075 Final deficiency rept for Unit 1 & fifth interim deficiency rept for Unit 2 re discrepancies in support details Initially reported on B20302 & B30311. respectively Revs to support drawings will be issued by B40103 MILLS.L.M. Tennessee Valley Authority B3/09/30 D'REILLY.J.P. Region 2. Office of Director App. 20648 338 24X Fichs 50-390.83/09/30.8310060095
- 8310060331 Final & eighth interim deficiency repts for Watts Bar & Bellefonte, respectively re inconsistent establishment of insp program Initially reported on B10324 Requirements, control & use of const requirements manual developed MIELS, L.M. Tennesses Valley Authority 83/09/30 D'REILLY, J.P. Region 2, Office of Director 4pp 20641 001 24% Fiche 50-000,83/09/30,8310060331
- 8310060342 Final deficiency rept re steam generator lower support bolts Initially reported on 820610 Reheat treatments provide adequate strength at operating temp, sufficient fracture toughness & crack resistance Also reportable per Part 21 MILES.L M Tennessee Valley Authority 83/07/30 0'REILLY, J P Region 2. Office of Director 3pp 20646 077 24X Fiche 50-370,63/09/30,8310060342
- 8310060436 Final deficiency rept re failure of safety-related Westinghouse gate valves Initially reported on 801031 All affected valves modified & applicable drawings revised MILLE, L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2. Office of Director 2pp 20641 227 24X Fiche 50-370,83/09/30,8310060436
- 8310060488 Final & third interim deficienty repts for Units 1 & 2, respectively re-postulated accident blowdown of more than one steam generator. Initially reported on 821015 Power supply to steam generator PDRY rearranged MILLS.L M Tennessee Valley Authority 83/07/30 G'REILLY, J P Region 2, Office of Director 2pp 2064; 015 24% Fiche 50-370,63/07/30,8310060488
- 831007030i Potential Part 21 rapt re underrange characteristic of Model N-Ei10M transmitter Underrange zero offset may occur when transmitter instially pressurized from atmospheric to suppressed zero input End users notified
 BERBERIAN, M. J. Foxboro Corp. 83/09/30 Director's Office, Office of Inspection and Enforcement lipp. 20451 044 24X
 Fichs. 50-000, 83/09/30, 8310070301
- 8310120237 Final deficiency rept re ambiguous outputs from Barton pressure transmitters in RCS Initially reported on 830409 Addl RCS transmitters installed outside containment Also reportable per Part 21.

 MILLS.L.M Tennessee Valley Authority 83/10/03, 0'REILLY, J.P. Region 2. Office of Director 3pp 20692 172 24X Ficher 50-390, 83/10/03, 8310120207
- 6310120332 Final deficiency rept re excessive movement of containment penetration bellows Initially reported on SI1204 Analysis determined that bellow mavement may exceed 0 226-intent lateral displacement Engineering change notice initiated. MILG.L M Tennessee Valley Authority B3/10/03 D'REILLY, J P Region 2. Office of Director Spp 20699 272 24X Fiche 50-390.83/10/03.8310120332
- 8310120074 Final & fourth interim deficiency rept for Units 1 & 2. respectively, re control of rivil engineering suggert branch analysis calculations Initially reported on 820823 Flange qualification requirements incorporated into checklist. MILLS.L.M. Tennessee Valley Authority. 83/10/03 0'REJLLY, J.P. Region 2, Office of Director 2pp 20700'197 24X Fiche 50-390,83/10/03,83/10/20396
- 8310120100 Final & seventh interim deficiency repts, for Units 1 & 2, respectively, re piging sys analysis & gipe support design efforts for Class 1,2 & 3 sys Initially reported on 801217 All Unit i supports designed for current loads, MILLS, L.M. Tennessee Valley Authority 83/10/04. O'REILLY, J.P. Region 2, Office of Director. 2pp 20696 180, 24X Fiche 50-390,83/10/04,8310120100
- 8310120169 Fourth interim (Unit 2) & Final (Unit 1) deficiency repts re incomplete/undocumented checking of pipe stress analysis problems Initially reported on 830513. Next rept for Unit 2 expected by 850119.

 MILLSIL M Tennesses Valley Authority 83/10/04 O'REILLY, J. P. Region 2. Office of Director 3pp 20698 089. 24X Fiche: 50-390,83/10/04,8310120169.
- 8310120210 Final & third interim deficiency repts for Units 1 & 2, respectively, re thick walled instrument piping not accounted for in analysis of process piping Initially reported on 820909, Next rept by 840702 ffillS.L.M. Tennessee Valley Authority, 83/10/04, 0'REILLY, J.P., Region 2, Office of Director 2pp 20696 123 24X Fiche 50-390,83/10/04.8310120210,

- 8310120336 Final deficiency rept re questionable patches of plastic cement mortar Initially reported on 820427 Sampling of expansion anchored supports proved adequacy of supports Item not reportable per 10CFR50 55(e)
 MILLS.L M Tonnessee Valley Authority 83/10/04 O'REILLY, J p Region 2, Office of Director 3pp 20697 279 24X
 Fiche 50-370,83/10/04.8310120336
- 8310120389 Final & sixth interim deficiency repts for Units I & 2, respectively, re discrepancies in as-built vs as-analyzed plining sys Initially reported on 810226 Support locations evaluated All Unit I rework will be completed by 831201 MFLLS.L M Tennessee Valley Authority 83/10/04 O'REILLY, J. P. Region 2. Office of Director 4pp 20699 128 24X Fiche 50-390,83/10/04.8310120389
- 8310140048 Final deficiency rept re mass of HVAC supports not included in frequency calculations Initially reported on 830809
 Designs revised Field rework & support work will be completed by 840101
 MTLLS.L M Tennessee Valley Authority 83/10/05 O'REILLY, J P Region 2. Office of Director 2pp 20768 272 24X
 Fiche 50-390.83/10/05.8310140048
- B310140017 Second interim rept re pump maters supplied w/o seismic analysis or operability demonstration Initially reported on B3042B Addl info received from Westinghouse but analysis not completed Nort rept expected by B31230 MILLS.L M Tennessee Vallay Authority B3/10/06 O'REILLY, J P Region 2. Office of Director 2pp 20767 027 24X Fiche 50-390, 83/10/06, 8310140017
- 8310170264 Second interim deficiency rept re routing of radioactive & nonradioactive sys instrument lines Initially reported on 830729 Engineering Change Notice 4287 initiated to remove instrument lines Next rept expected by 831221 MILLS.L M Tennessee Valley Authority 83/10/06 D'REILLY, J P Region 2. Office of Director ip 20787 100 24X Fiche 50-390.83/10/06.8310170264
- 8310210076 Final rept re QA program deficiencies in Qilbert Assoc personal svcs contract Initially reported on 830406 Specific problems not identified by audit Items not reportable per 10CFR80 55(e) MILLS.L M Tennessee Valley Authority 83/10/12 O'REILLY, J P Region 2, Office of Director App 20888 197 24X Fiche 50-000, 83/10/12,8310210096
- 83i0170087 Final deficiency rept re discrepancy in interface coordination of design review process Initially reported on 810717 Finding of coordination problem not significant & should not have been reported to NRC per 10CFRSO 55(e) MILLS.L.M. Tennessee Valley Authority 83/10/13 0'REILLY, J.P. Region 2. Office of Director 3pp 20018 132 24X Fiche 50-000.83/10/13.8310170087
- B310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents Initially reported on 811215 Listed changes to design review process will be implemented by 840101 MILLS.L.M. Tennessee Valley Authority 83/10/13 O'REILLY, J.P. Region R. Office of Director 3pp 20818 045 24X Fiche 50-000, 83/10/13,8310190P24
- 8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 830120 New requirements for assessing piping vibration problems during precaperational testing requirements issued MILLB.L M Tennessee Valley Authority 83/10/13 8'REJILY, J P Region 2, Office of Director 3pp 20895 345 24X Fiche 50-000,83/10/13,8310210011
- 8310210015 First interim deficiency rept ro support for test lines by alternate analysis Initially reported on 830917 Existing support structure being analyzed to determine if mods necessary for DBA loadings Next rept by 831205 MILLB.L M Tennesses Valley Authority 83/10/13 O'REILLY, J P Region 2, Office of Director 2pp. 20858 261 24X Fiche. 50-370, 83/10/13, 8310210015
- 8310210042 Supplemental deficiency rept re sensing of pipe breats in component cooling sys Initially reported on 830624
 Typographical error identified in 830909 final rept Engineering change notice number should be 4253, not 4205
 MTLLS.L M Tennesses Valley Authority 83/10/13 0'REILLY.J P
 Region 2, Office of Director, ip. 20895 317 24X
 Fiche 50-390, 83/10/13,8310210042
- 8310210049 Revised finel deficiency rept re voiding of Engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4 02 addressing voiding of ECNs changed in Rev 12. issued on 830203 MILLB.L.M Tennessee Valley Authority 83/10/13 O'REILLY, J P Region 2. Office of Director 2pp 20855 304 24X Fiche 50-000, 83/10/13, 8310210049

- 8310210068 Final deficiency rept for Unit 1 & third interim deficiency rept for Unit 2 re loose matl in steam generator Initially reported on 830325 Caused by lack of work controls Also reportable per Part 21 Next rept due by 840706 HILLS, L M Tennessee Valley Authority 83/10/13 O'REILLY, J P Region 2. Office of Director 4pp 20857 270 24X Fiche 80-390,83/10/13,8310210068
- 8310190127 First interim deficiency rept re shorted indicating lights in Westinghouse panels Initially reported on 830915 Westinghouse provided trained wiring separation procedure & wiring sketch. Next rept expected by 831215 MikLS.£ M Tennessee Valley Authority 83/10/14 0'REILLY, J P Region 2, Office of Director 2pp 20821 128 24X Fiche 50-390, 83/10/14,8310190127
- B310250371 Final deficiency rept for Unit 1 & interim rept for Unit 2 re alternately analyzed piping Verification of all Unit 1 piping carried out by personal sycs contractor & util div of engineering design HILLELL M Tennessee Valley Authority B3/10/14 O'REILLY, J P Region 2. Office of Director 10pp 20878 044 24X Fishe 30-370, 83/10/14, 8310250371
- 8310250012 Supplemental final deficiency rept re corrosion in high pressure fire protection sys Corrective action will be completed by 831230.per 830730 telcon Vendor matl for const reworl will not arrive onsite to support original schedule MtLLS.L M Tennessee Valley Authority 83/10/17 O'REILLY, J P Regian 2, Office of Director 1p 20894 183 24X Fiche 50-390,83/10/17.8310250012
- 8310250162 Second revised final deficiency rept re cross-trained diesel generator HX inlet valves Initially reported on 830531 Applicable drawings revised to apply diesel start signal to correct valve Corrections completed MILLS,L M Tennessee Valley Authority 83/10/17 0'REILLY,J,P, Region 2. Office of Director 3pp 20896 293 24X Fische 50-390.83/10/17,8310250162
- 6310250165 Third interim deficiency rept re spacing & clearance of aprintler heads in high pressure fire protection sys Institutely reported on 830331 Caused by lack of understanding macessity for maintaining adequate spray patterns
 MILLS.L M Tennesses Valley Authority 83/10/17, D'REILLY, J P Region 2, Office of Director 3pp 20894 062 24X
 Fiche 50-390,83/10/17,8310280165
- 6310250173 Final & fourth interim deficiency repts for Units 1 & 2. respectively, re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 New spray shields designed to be installed above water chillers. HTLBS.L M Tennesses Valley Authority 83/10/17 D'REILLY, J P. Region 2. Office of Director App 20893 278 24X Fiche 50~390.83/10/17.8310250173
- 8310270150 Final rept re cable band radius deficiencies due to use of nonstd fittings Initially reported on 830720 Caused by misinterpretation of specs Task team appointed to identify, evaluate & resolve problems Rewark completed, MILLG.L M Tennessee Valley Authority 83/10/18 D'REILLY, J P Region 2. Office of Director 3pp 20925 020 24% Fiche 50-390,83/10/18,8310270150
- 8310270183 Final deficiency rept re welds on structural steal in main steam valve rooms Initially reported on 830921 Util in process of visually reinspecting 100% of all structural steal welds Corrective action will be completed by 841025 MILLS.t. M. Tennessee Valley Authority 83/10/18 0'REILLY, J. P. Region 2. Deffice of Director 2pp 20929 031 24% Fiche 50-390,83/10/18,8310270183
- B310310148 Revised final deficiency rept for Unit 1 & first interim defictency rept for Unit 2 re installation of flow switches & sensing lines initially reported on 830810 Actual rev to drawings will be accomplished by B31028 for Unit 1, MILES.L M Tennessee Vallay Authority B3/10/19, O'REJLLY,J P. Region 2, Office of Director 3pp 20759 014 24X Fiche 80-390, 83/10/19, 8310310148
- B310310320 Final deficiency rept for Unit 1 & fourth interim rept for Unit 2 re improper overlapping analysis techniques Initially reported on B30111 Twenty-nine problems judged unacceptable is reanalysed to comply w/proper techniques HILLS.L M Tennessee Valley Authority 83/10/21. O'REJLLY, J. P. Region 2. Office of Director 3pp 20961 210. 24X Fiche 50-390, 83/10/21, 8310310320

- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8310280005 Forwards 831006 comments submitted to SC Dept of Health & Environ Control clarifying points of thermal effects study plan as contained in FES
 DIXON.O W Bouth Carolina Electric & Gas Co 83/10/24 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 4pp 20934 289
 24X Fiche 50-395.83/10/24,8310280005
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310250109 Supple response to SER Items 9 & 10 "Generic Design Package for Incorporation of Automatic Shunt Trip Feature into Westinghouse Reactor Protection Sys," as requested on 831003
 - B31003 DIXON: O M South Carolina Electric & Cas Co B3/10/20 DENTON: H f Office of Nuclear Reactor Regulation, Director 2pp 20715 234 24X Fiche 50-395, B3/10/20, 8310260109
- F Security, medical, emergency & fire protection plans
- 8310030573 Releases public version of revised emergency plan implementing procedures FELTON, J.M. Division of Rules and Records 83/09/28 Document Management Branch ip 20604 928 24X Fiche: 50-395,83/09/28,8310030573
- --8310030582 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-002 re communication & notification, EPP-003 re in-plant radiological surveying & EPP-013 re fire emergency DIXON, 0 W South Carolina Electric & Qas Co B3/08/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20604 329 24X Fiche 50-395, 83/09/28, 8310030373
- --8310030587 Public version of revised emergency plan implementing procedures including Procedures EPP-002 re communication & notification, EPP-003 re in-plant radiological surveying & EPP-013 re fire emergency * Bouth Carolina Electric & Gas Co. 83/08/10 347pp 20604:331 24X Fichs 50-395,83/09/28,8310030573
- B310170289 Forwards Amend 17 to License NPF-12 & safety evaluation Amend changes wording of license condition re fire suppression to accurately reflect plant design ADENSAM, E & Licensing Branch 4. B3/10/12 DIXON, D W South Carolina Electric & Oas Co Spp. 2076 245 24X
- --8310170296 Amend 17 to License NPF-12, changing wording of license condition re-fire suppression to accurately reflect plant design EISENHUT, D 0 Division of Licensing 83/10/12 2pp. 20796-248 24X Fiche 50-395,83/10/12.8310170289.
- --8310170301 Safety evaluation supporting Amend 17 to License NPF-12 * Office of Nuclear Reactor Regulation, Director 83/10/12, 3pp. 20796 250 24X Fiche, 50-395, 83/10/12, 8310170289,
- P Operating license stage documents & correspondence
- 8310040120 Forwards "Control of Heavy Loads at Nuclear Power Plants, VC Summer Nuclear Station, Unit 1 (PHASE I)." EQAO technical evaluation rept Synopsis rs NRC interpretation of NUREO-0612 guidelines for resolution of open items encl NUVAK, T.M. Assistant Director for Licensing 83/09/16. DIXON, O. W. South Carolina Electric & Oss Co. 2pp 20640 274. 24X Fiche 50-395,83/09/16,8310040120
- --8310040123 "Control of Heavy Loads at Nuclear Fower Plants,VC Summer Nuclear Station,Unit 1 (PHASE 1)." technical evaluation rept FRIEDERICHS.8. E006. Inc FIN A-6457. E90-H8-6371. 83/08/31 NRC No Detailed Affiliation Given 47pp 20640:276 24X Fichs 50-395.83/07/16.8310040120
- 8310050076 Concurs w/dissolution of Model D2/D3 Bteam Generator Util Design Review Penel Panel work complete. NOVAN.T.M. Assistant Director for Licensing. 83/09/23 BLACKLEY.8 K Design Review Panel Spp 20650:165. 24X Fiche 50-000.83/09/23.8310050076
- B310170289 Forwards Amend 17 to License NPF-12 & safety evaluation Amend changes wording of license condition re fire suppression to accurately reflect plant design.

 ADENSAM, E Q. Licensing Branch 4. 83/10/12, DIXON, O W Bouth Carolina Electric & Qas Co. 3pp. 20796 245. 24X

 Fiche. 50-395, 83/10/12, 8310170289

- --B310170296 Amend 17 to License NPF-12.changing wording of license condition re firs suppression to accurately reflect plant design EIBENNUT.D 0 Division of Licensing B3/10/12 2pp 20796 248. 24X Fiche 50-395, 83/10/12
- --8310170301 Safety evaluation supporting Amend 17 to License NPF-12 * Office of Nuclear Reactor Regulation, Director. 83/10/12 3pp 20796-250 24X Fiche-50-395,83/10/12.8310170289
- 8310260232 Application for amend to License NPF-12 changing Tech Specs relayed water intake structure monitoring/insp Revised License Condition 2 C(5) encl DIXON.O W South Carolina Electric & Gas Co B3/10/21 DENTON.H.R Office of Nuclear Reactor Regulation. Director 3pp 20912 189 24X Fiche 50-395,83/10/21,8310260232
- 8310260255 Application for amend to License NPF-12 revising Tech Specs re-cold overpressure protection sys Marked-up proposed Tech Specs encl DIXON.O M South Carolina Electric & Gas Co 83/10/21 DENTAN.H R Office of Nuclear Reactor Regulation. Director 10pp 20709-267 24X Fiche 50-395,83/10/21,8310260255
- 8310270135 Notification of 831101 meeting w/util in Reading, PA to discuss equipment qualification analyses performed for seismic confirmatory program.

 HOPKINS.J B Licensing Branch 4 83/10/21 ABENSAM, E 9 Licens Branch 4 4pp 20942 190 24X Fichs: 50-395, 83/10/21, 8310270135
- 9 Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-6; "Alleged Use of Stand-Ins for Welder Gualification Tests" Byr list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fichs 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York Inc 116pp 20777-210, 24X Fiche 50-000,83/09/24,83083003042
- 830B300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays," Syc. list encl. JURDAN.E L. Division of Emergency Preperedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,83083060345 20778 001 24X Fich = 50-000, 83/09/26, 8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
- JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York Inc. 115pp, 20716; 324 24X Fiche 50-000, 83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants," Evo list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83710/07. Consolidated Edison Co of Net York: Inc. 76pp. 20827 213. 24X Fache 50-000,83/10/07.8308300378
- 8308300792 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Byc list encl
 JRRDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of Net
 York, Inc. 79pp. 20882.026 24x Fiche.30-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl.
 JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Constitated Edison Co. of New York, Inc. 117pp 21043 075 24X Fichs. 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Harning Defective Self-Contained Breathing Apparatus Air Cylinders" 8vc list
- anci. JORDANIE L Division of Emergency Preparedness & Engineering Response (Post B30103). B3/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129. 24X Fiche 50-000, B3/10/11, B30B300761.
- 3310200252 Forwards SC Dept of Health & Environ Control 830830 ltr & util 830912 response to noncompliances noted during 830711-13 insp of NPDES Permit 800030856. Corrective action will be completed by 831015
 DIXON.O M. Bouth Carolina Electric & Gas Co. 83/10/18 DENTON.H R. Office of Nuclear Reactor Repulation, Director 5pp 20830 [18 24% Fiches 80-395.83/10/18.8310900890. 24X Fiche 50-395, 83/10/18, 8310200252.

- 8310260232 Application for amend to License NPF-12 changing Tech Specs re svc water intake structure monitoring/insp Revised License Condition 2 C(5) encl DIXON.O W South Carolina Electric & Gas Co 83/10/21 DENTWI,H A Office of Nuclear Reactor Regulation. Director 3pp 20912 189 24X Ficha 50-395,83/10/21,8310240232
- R Periodic operating reports & related correspondence
- B310190028 Monthly operating rept for Aug 1983 W/B30912 ltr TAYLOR G J , DIXON O W South Carolina Electric & Gas Co BARRY, L W Dffice of Resource Management, Director 5pp 20823 236 24x Fiche 50-395,B3/09/12,B310190028 83/07/12
- S Reportable occurrences. LERs & related correspondence
- B310030475 RO on B30822, while in Mode 1, fireproofing for Control Bldg RIOGIO-75 KU on B308-2, while in mode i, fireprooting for control sing Room CB-36-02 declared degraded when section removed from structual steel for const mod fire watch established fire proofing repaired & detectors declared operable on B30831 PIXON,O W Bouth Carolina Electric & Gas Co B3/09/17 O'REILLY,J P Region 2, Office of Director 2pp 20501 054 24X Fiche 50-395,83/09/19,8310030475
- 8310030343 LER 83-102/03L-0 on 830823 & 26, while in Mode 1, turbing room sump liquid radiation monitor RM-L8 had insufficient sample flow Caused by clossed solenoid valve on 830823 & closed suction line on 830826 H/830920 ltr KOLB.L E. DIXON.O.W South Carolina Electric & Gas Co 03/09/20 0'REILLY.J P. Region 2. Office of Director 3pp 20590 337 24% Fichs 50-395, 83/09/20.8310030343
- 8310040416 Confirms 830916 mgt meeting in Region II ofc to discuss 830912 event where apparent load rejection at 75% power did not result in proper functioning of related sys.per 830913 telcon. Proposed meeting agenda en
- 8310040465 LER 83-103/03L-0 on 830910, w/unit in Mode 1, plant went from 97% power to 79% within 1 h Required isotopic iodine analysis not performed within 2 to 6 h Caused by personnel error Procedure mods implemented W/830926 Itr 8DUXMIGHT,R J. DIXON.O W South Carolina Electric & Gas Co 83/09/26 0'REILLY.J P. Region 2, Office of Director 3pp 20623 143 24% Fiche 50-395,83/09/26,8310040465
- 8310070002 LER 83-105/03L-0 on 830902, w/unit in Mode 1, refueling water 3100/000k LeM 83-109/03L-0 on 830902, w/unit in Mode i.refuelt storage tank level transmitter LT-99; failed high, declared inoperable & placed in bypassed condition. Caused by water in conduit resulting in electrical short W/830926 ltr MCKINNEY.C J., DIXON.D W South Carolina Electric & Cas Cu 83/09/26 O'REILLY.J P Region 2, Office of Director 2pp 20658 246 24X Fiche 50-395,83/09/26,8310070002
- 8310070278 LER 83-104/01T-0 on 830914, discovered that howrly fire watch patrol not established on 830909 when fire barrier surrounding HVAC ducts in HVAC chiller rooms removed for GA insp. Caused by personnel error W/830927 ltr BOUKNIGHT, R J , DIXON O W South Carolina Electric & Gas Co 83/09/27, O'REILLY, J P Region 2, Office of Director 4pp 20657 021 24X Fiche 50-395,83/09/27,8310070278
- 8310070126 LER 83-107/03L-0 on 830914, reactor bldg internal pressure dropped below Tech Spec min Caused by change of ambient temp Reactor bldg minipurge supply activated to return pressure to within limits W/830727 lt. Rolling E. D. IXON,O W. South Carolina Electric & Gas Co. 83/09/29 O'REILLY, J. P. Region 2, Office of Director. 2pp. 20659 062 24X Fishe 50-395, 83/09/27, 8310070126
- 8310070338 LER 83-106/03L-0 on B30904.post-accident hydrogen analyzer panel A (XPN-7215A) declared inoperable when calibr rotometer ball bearing indicator lodged in pressure regulator Caused by personnel error W/830930 itr KOLB.L E. DIXON.O.W South Carolina Electric & Oas Co B3/09/30 UREILLY.J P. Region 2. Diffice of Director. 3pp 20652 165 24X Fiche 50-393.83/09/30.8310070338
- 8310170568 LER 83-108/03L-0 on 830702,while in Mode 1, diesel generator A output breaker failed to close during performance of surveillance test Cause not determined Tast performed & unit returned to operable status W/830930 ltr MCKINNEY.C J. DIXONO W South Carolina Electric & Gas Co 83/09/30, D'AETILLY, J P. Region 2, Office of Director App 20780: 337 24X Fiche 50-395,83/09/30,8310170368

- 8310170443 LER 83-111/03L-0 on 830911, while in Mode 1, reactor trip occurred following power interruption on 115 kV offsite power source Cause of trip from transient to onsite power source under investigation W/831010 itr HCK/INNEY.C J , DIXON.O W South Carolina Electric & Qas Co 83/10/10 D/REILLY.J P Region 2, Office of Director 3pp 20779 229 24X Fiche 50-395,83/10/10.8310170443
- 8310210128 tER 83-110/03L-0 on 830912, during Mode 1.RCS Tave exceeded power distribution limits by 2-1/2 degrees Caused by failure of parmanent magnet generator 22-volt power supply condenser to almospheric dump valves W/831010 ltm KOON.A R . DIXON.D W South Carolina Electric & Gas Co 83/10/10 0.74E1LLY.J P. Region 2. Office of Director 9pp 20858 241 24X Fiche 50-395.83/10/10.8310210128
- 6310310234 LER 83-112/03L-0 on 630923. signal comparator IPB-953B1
 associated w/containment pressure transmitter IPT-953
 declared inoperable when bistable tripped & would not reset
 Causad by defective bistable electronic card W/631020 ltr,
 KOLB.C. E. DIXON.D W South Carolina Electric & Gas Co 83/10/20
 O'REFICHY.J P Region 2. Office of Director 3pp 20947 207 24)
 Fiche 50-395.83/10/20.8310310234
- 8310310392 LER 83-114/03L-0 on B31004.steam generator C pressure indicator 494 declared inoperable due to spiking causing various alarms & bistable to actuate Caused by faulty electronic loop power supply card W/831020 ltr EDUKNIOH1.R J. DIXON.O W Bouth Carolina Electric & Gas Co 83/10/20 0 7/8FILLY.J P Region 2. Office of Director 2pp 20959 325 24X Fiche 30-395,83/10/20,8310310392
- B310310314 LER B3-113/03L-0 on B30924, operator found personnel escape foor hatch outer door hard to operate & unsecured Caused by sheared right angle gear drive pin Both doors locked & seal leak tested satisfactorily W/B31020 ltr B0P2NIGNI.R J. DIXON.O W Bouth Carolina Electric & Qas Co B3/10/20 0'REILLY.J P Region 2, Office of Director 2pp 20759 282 24X Fiche 50-395,83/10/20,8310310394
- 8310250117 Forwards clarification of why operator did not manually initiate reactor trip when reactor trip window illuminated on first-out annunciator panel on 830912, per NRC request at 830915 meeting DIXON.O W South Carolina Electric & Gas Co .83/10/21 DENTON, Office of Nuclear Reactor Regulation, Director .3pp .20915:23124X Fiche 50-395,83/10/21,8310260117
 - DENTON, H R
- SOCKET 50-397 UPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 831003037 Forwards response to B30907 request for add1 info setpoint methodology Resolution of issue generically w/NRC-recognized util group presently addressing issue requested SORENSEN.O C Washington Public Power Bupply Bystem 83/0 SCHMENCER.A Licensing Branch 2 3pp 20992.337 24X Fiche 50-397.83/09/23.8310030357 83/09/23
- 8310040440 Forwards add1 info re containment "Out-of Roundness" per NRC B30722 meeting SCRENSEN.9 C Mashington Public Power Supply System 83. SCHUENCER.A Licensing Branch 2 29pp 20619 059, 24X Fishe 30-397.83/09/26.8310040440
- 8310070342 Forwards "Design Reverification Program." Vols 1 & 2.final assessment rept Results of program will be presented to NRC in Late Oct 1783
 SDRENSEN.0 C Mashington Public Power Supply System 83/09/27
 DEMION.H R D
- --8310070346 "Design Reverification Program," Vols 1 & 2. final assessment rept 83/09/30 415pp
- B310110332 Forwards draft Tech Specs to require use of shorting limis during initial source range monitors/intermediate range achitors overlap demonstration or post-mod.per **CHARNERS TO STATE OF THE PROPERTY OF THE STATE OF THE S
- 83:0120267 Requests that spent fuel storage pool monitors not be made requirement in Tach Specs, based on recent examption granted for License SNM-1890 Storage in spent fuel storage area aremption predicated on design of storage facility SQREMSEN, 8 C Washington Public Power Supply System 83/10/03. SCHMENGER, A Licensing Branch 2 2pp 20693 135, 24X Fiths 50-397, 83/10/03, 83/10/20267

- 8310120261 Forwards response to FSAR Question 110 43 in NRC 830803 ltr Increased damping & seismic spectra resulting from finite element model utilized to produce Phase II refined loads for each of five sample anchor groups
 SORENSEN, G C Washington Public Power Supply Bystem B3/10/04
 SCHWENCER, A Licensing Granch 2 5pp 20693 114 24X
 Fiche SO-397, 83/10/04, 8310120261
- 83i0170131 Forwards request for add1 info re Outstanding Issue 13
 "Control Sys Failures " Response requested by 83i028
 8CHWENCER: A Licensing Branch 2 83/10/05. MAZUR: D W Washington
 Public Power Supply 8ystem Spp 20811 352 24X
 Fiche 50~377.83/10/05.8310170131
- 8310130212 Notification of 831018 meeting w/util in Bethesda.MD to discuss seismic & dynamic qualification of electrical & mechanical equipment AULUCK.R Licensing Branch 2 83/10/06 BCHWENCER.A Licensing Branch 2 3pp 20777
- 8310170495 Request that NURES-0123, "Std BWR Tech Specs," be revised to sion/0495 Request that North-0-123, "Std BMR lisch Blecs," he reprevious formatibased on need to provide adequate time frame for completion of WPPSS-2 power ascension testing program Susquehanna test duration data encl
 SORENSEN.G C Washington Public Power Supply System. 83/10, BCHWENGER.A Licensing Branch 2 3pp. 20784 015, 24X
 Fiche: 50-000, 83/10/10, 8310170495. 83/10/10.
- --8310170497 Tech Spec Page 3/4 10-5 re oxygen concentration limiting condition for operation ** Washington Public Power Supply System 82/02/01 ip 20784 018 24X Fichs 50-000, 83/10/10, 8310170495
- B310170313 Forwards draft Amend 33 to FBAR consisting of solid waste mgt sys re utilization of interim portable solid radwaste solidification sys Submittal will be incorporated in FBAR Amend 33. W/two oversize drawings Aperture cards in FDR SORENSEN. O C Washington Public Power Supply System B3/10/11 SCHWENCER.A Licensing Branch 2. Ip 20784 345 24X Fiche 50~397,83/10/11.8310170313.
- 8310200031 Forwards request for add1 info re design adequacy for Anchor Oroup 37 identified in 830914 submittal SCHWENCER, A Licensing Branch 2 83/10/12 MAZUR, D W Washington Public Power Bupply System 3pp 20844 233 24X Fichs 50-397, 83/10/12,8310200031
- 8310180449 Forwards Rev O to "Dissolved Gas Analysis " Implementation of post-accident sampling sys & final dissolved gas sampling procedure contingent upon receipt of mod equipment from OE to be delivered by 83130 GORENSEN. G C Washington Public Power Supply System 83/10/13, SCHHENGER, A Licensing Branch 2 2pp 20802:068 24X Fiche: 50-397, 83/10/13, 8310180449.
- --8310180453 Rev O to Procedure 12 10 B, "Dissolved Oss Analysis "
 * Washington Public Power Supply System 83/09/27, 19pp, 20802 070 24X Fiche 50-397,83/10/13/8310180449.
- 8310210168 Forwards "Response to NRC Human Factors Engineering Preliminary Design Assessment Audit Rept of 830826 " SDREMSEN.9 C Washington Public Power Supply System. 83/10/14 8CHWENGER.A Licensing Branch 2 1p 20845.306. 24X Fiche.50~397,83/10/14.8310210168.
- --8310210173 "Response to NRC Human Factors Engineering Preliminary Design Assessment Audit Rept of 830826." DAVALLE:R. G. FREEMAN.G. J. MCGILTONN.C. H. Washington Public Power Supply System 83/10/07 200pp. 20845 307 24X Fiche: 50-397.83/10/14.8310210168
- 8310210305 Provides documentation of util position re reactor pressure vessel surveillance program & recently amended 10CFR50 App H. Coupon removal sys consistent w/1973 version of ASTM-E185 ABIN-RIBB BORENSEN.O C. Washington Public Power Supply System. B: BCHWENCER,A Licensing Branch 2 2pp 20851,074 24X Fiche 30-397,83/10/14.8310210305 83/10/14.
- 8310240150 Provides status info on Branch Technical Position PBB-1 commitments per 8 Rhow 830905 request RE field dispositions refinal Div 3 second level undervoitage protection design to two oversize drawings encl Aperture cards available in PDR. SORENSEN.9 C Washington Public Power Bupply System. 83/10/14 SCHWENCER.A Licensing Branch 2. 2pp. 20878:054 24% Fiche.50-397,83/10/14.8310240150.
- 8310260113 Forwards Offsite Dose Calculation Manual.
 SORENGEN.0 C Washington Public Power Supply System B:
 BCHWENCER.A Licensing Branch 2 lpp. 20912:283, 24X
 Fische 50-397,83/10/17.8310260113 83/10/17

- --83107&0122 "Offsite Dose Calculation Manual "

 * Washington Public Power Supply System 83/10/17 110ap
 2012 204 24% Fiche 50-397.83/10/17.63102&0113
- 8310270444 Advises that quality processes group functions can be assumed by sys completion group in const mgt organization Quality processes group will be disestablished CARLISLE.C S Hashington Public Power Supply System 83/10/18 MARTIN, J B Region 5, Dffice of Director 2pp 20923 115 24) Fiche 50-397,83/10/18.8310270444
- 831025008B Forwards Vols I & 111 of "Independent Evaluation of Plant Verification Program at MPPSS-2" CARLISLE,C 8 Mashington Public Power Supply System 89/10/19 MARTIN,J B Region 5, Office of Director 3pp 20892 001 24X Fiche 50-397,83/10/19.8310250088
- --8310250093 "Independent Evaluation of Plant Verification Program at MPPSS-2 vol I Quality Verification "
 LANEY,R V, RODIIS,L H, SHEETS,H E Tachnical Audit Associates,
 Inc. 1126-F1 VOI 83/09/30 100pp 20892 004 24X
 Fiche 50-397,83/10/19,8310250088
- --8310250097 "Independent Evaluation of Plant Verification Program at HPPSS-2 Vol 3 Technical Audit Assoc.Inc Audit Repts "LANEY,R V, RODDISL H, BHEETS-H E Technical Audit Associates, Inc 1126-FJ VO3 83/09/30 240pp 20892 114 24X Fiche 50-397,83/10/19,8310250088
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- B310030361 Discusses agreement w/NRC affecting surveillance requirements in NUREG-0892. SER Suppl 2 re TMI Action Item II K 3 28 on automatic depressurization sus Bottle pressure varification changed to 31 days SORENSEN. 9 C Washington Public Power Supply System B3/09/23 SCHMENGER. A Licensing Branch 2 3pp 20592 131 24X Ficha 50-397. B3/09/23 B310030361
- 8310110276 Forwards four oversize drawings, closing out NUREO-0892, SER Outstanding Issue 29 re vacuum breaker valves Valve response meets containment design bases for response time & flow capacity, Aperture cards are available in PDR 80RENSEN, 0 C Washington Public Power Supply System 83/09/28 SCHEWOER, A Licensing Branch 2 2pp 20665 325 24X Fichs 50-397, 83/09/28, 83i0110276
- BSIO170298 Forwards loose parts detection sys conformance evaluation, including action requested in NUREO-0892. SER Section 4 4.6 SORENSEN, 0 C Washington Public Power Supply System 83/09/29 SCHHENCER. A Licensing Branch 2 Bpp 20786 186 24X Fichs 30-397, 83/09/29, 8310170298
- 8310180387 Forwards proprietary FBAR Table 3 9-2b re SER Confirmatory Issues 9 & 10 Table contains GE proprietary info Table withheld (ref IOCRR2 770) Affidevit requesting info be withheld & GE 830783 itr also end!
 80REMBEN, 0 C Washington Public Power Supply System 83/09/29 SCHMENGER, A Licensing Branch 2 App 20804 098 24X Fiche 50-397, 83/09/29, 8310180387.
- 8310120155 Forwards response to FBAR Guestion 110.41 re requirements for equipment notale loads per SER Confirmatory Issue 7 on component supports
 80RENSEN.0 C Washington Public Power Supply System 83/10/04
 8CHMENGER.A Licensing Branch 2 3pp. 20696-005, 24X
 Fichs 50-397.83/10/04.8310120155
- 8310120059 Forwards marked-up Tech Spec re ECCS in response to 830923 request for proposed change to surveillance requirements on automatic depressurization sys backup air supply.per SER, NUREO-0892 & Item II K 3.28 SOREMSEN.0, C Washington Public Power Supply System 63/10/06 SCHMENGER, A Licensing Brench 2 2pp 20697 [01, 24X Fiche. 50-397, 83/10/06.8310120059
- B310170212 Forwards marted-up F9AR changes in response to SER Confirmatory Issue 1 re break locations Info based on "status as-built" configuration. Final "as-built" analysis not expected to result in significant differences BDRENBEN. 0. C Washington Public Power Supply System 63/10/11. 83CHMENGER. A Licensing Branch 2. 135pp. 20786 223 24X Fiche 50-397. B3/10/11. 83(0170212
- 8310170235 Forwards response to telcon request for addl clarification of response to Question 640 01 a & b re emergency operating procedures generation package. SER (NUREG-0892) Confirmatory Issue 15 re emergency procedures review closed. 80REMBEN.0 C Washington Public Power Supply System. 83/10/11 80HMENCER.A Licensing Branch 2 49pp 20787:013 24X Ficha 50-397,83/10/11,8310170235.

- F Security, medical, emergency & fire protection plans
- 8310040397 Forwards IE Safeguards Insp Repts 30-397/83-33 & 70-2950/83-02 on 830815-18 & notice of violation Encis withheld (ref 10CFR2 790)
 NORDERHAUG,L R Region 5, Office of Director 83/09/28
 CARLISLE,C S Washington Public Power Supply System 2pp 20620 042 24X Fiche 50-397,83/09/28.8310040397
- 8310040232 Part 21 rept re plant mod implementing fire protection, including blocking vent paths from reactor bldg rooms containing high energy lines Initially reported on 830928 Six rooms require reanalysis CONN.W G Burns & Roc Co 83/09/29 Director's Office, Diffice of Inspection and Enforcement 2pp 20613 201 24X Fiche 50-397,83/09/29.8310040292
- B310170446 Discusses history & background of use of fire dampers not fire rated or tested in const of facility, due to state-of-the-art const at time of installation F5AR will be revised via Amend 33 to document const Marked-up drawings encl SORENSEN, 6 C Washington Public Power Supply System B3/09/29 SCHHENCER, A Licensing Branch 2 27pp 20790 282 24x Fiche 50-397,82/09/29,8310170446
- 8310120335 Discusses proposed implementation of emergency preparedatss training plan First phase, per NUREG-0654, will be completed prior to fuel load Detailed schedules will be completed & made available for review upon concurrence SDRENSEN.9 Washington Public Power Supply System 83/10/04 BCHMENCER, A Licensing Branch 2 2pp 20699 277 24X Fiche 50-397,63/10/04.8310120335
- 8310120027 Forwards request for add1 info re emergency classification scheme in emergency planning program Response requested by 831028
 SCHWENCER, A Licensing Branch 2 83/10/05 MAZUR, D W Washington Public Power Supply System 7pp 20749 345 24X
 Fische 50~397, 83/10/05, 8310120027
- 8310170266 Advises that util position re establishing primary emergency operations facility approx 0.75 miles from site & alternate location at util headquarters 9.5 miles from site acceptable EISENHUT.D 0. Division of Licensing BD/10/07 MAZUR.D H Hashington Public Power Supply System. 2pp 20796-259 24X Fiche 50-397,83/10/07,8310170266
- 8310180503 Clarifies util 820617 ltr describing emergency operations facility vantilation.per NUREG-0696 Charcoal will not be provided in ventilation sys SORENSEN, G C Washington Public Power Supply System 83/10/12 SCHUENCER, A Licensing Branch 2 1p 20801 188 24X Fiche 50-397,83/10/12,8310180503
- G Adjudicatory correspondence
- 8310050216 Notice of withdrawal of appearance in proceeding Cortificate of Evc encl Of Evc encl CHAN E I Hearing Branch 2 83/09/27 2pp 20628-286 24X Fiche-50-397,83/09/27.8310050216
- K Utility Final Safety Analysis Report (FSAR) & amends
- B310070277 Amend 32 to FSAR W/830702 ltr SOREMBEN.G C Washington Public Power Supply System 83/07/30 BCHWENCER.A Licensing Brønch 2 823pp 20652 226 24X Fiche 50-397,83/09/30.8310070277
- Q Inspection reports: IE Bulletins & correspondence
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26.8308300345
- 8310170428 Forwards IE Insp Rept 50-397/83-42 on 830815-18 & 19-0902 No noncompliance noted BISHOP.T W Region 5. Office of Director 83/09/21 MATLOCK,R 9 Washington Public Power Supply System 2pp 20783 258 24X Fiche 50-397
- --8310170432 IE Insp Rept 50-397/83-42 on B30815-18 & 17-0902 No noncompliance noted Major areas inspected, previously identified const deficiencies (100FR50 55(e) repts) BURDOIN, J F., SCOHN, K M., DODDS, R, T Region 5, Office of Director B3/09/19 12pp 20783 240 24X Fiche 50-397, 83/09/21, 8310170428

- 93:9300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder 6.alification Tests" Svc list encl
 WRDAN.E.L. Divinion of Emergency Preparedness & Engineering Response (Post 630103) 63/09/26 Consolidated Edison Co. of New York. Inc. 117pp 20754 022 24X Fichs 50-000.83/09/26.8308300040
- EMB300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Sitectors Positioned at Control Room Ventilation Air Intakes " Svc list end! JORDAN, E. Division of Emergency Preparedness & Engineering Risponse (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300342
- 6310040397 Forwards IE Safeguards Insp Repts 50-397/83-3. & 70-2950/83-02 on 830815-18 & notice of violation Encls withheld (ref 100FR2 790)
 AGACERHAUG, L. R. Region 5. Office of Director 83/09/28
 CARLISLE, C. S. Washington Public Power Supply System 2pp 20220 042
 24X Fiche 50-397,83/09/28,8310040397
- ell0120192 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-38
 BISHOP.T W Division of Resident Reactor Project & Engineering Programs 63/09/28 CARLISLE,C & Washington Public Power Supply System 1p 20692 227 24X Fiche 50-397.83/09/28.8310120192
- -- SJ10120196 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 90-397/83-38 Corrective actions all weldelets on six separate tree risers inspected & found fully welded out No deficiencies encountered CARLISLE, C S Washington Public Power Supply System 83/09/19 MARTINIJ B Region 5. Office of Director 8pp 20692 228 24X Fiche 50-397,83/09/28,8310120192
- ENDIRO249 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-297/83-38 Engineering Pishop. I W Division of Resident/Reactor Project & Engineering Programs 83/09/28 CARLISLE,C S Washington Public Power Suppli System ip 20691 331 F4X Fiche 50-397,83/09/28,8310120248
- --B)10120250 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-397/83-38. Corrective actions honeycombed areas in beans 2B11 & 2025 excavated to sound concrete & will be regained Destructive exam & documentation review conducted CARLIBLE.C 8 Washington Public Power Supply System 83/09/16 MARTIN.J B Region 5. Office of Director 133pp 20691 332 24: Fiche 50-397.83/09/28,8310120248
- 5708300347 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 57 Evaluation " Svc list
- entl. JDBDAN.EL Davision of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New Fort. Inc. (15pp. 20716-324 24X Fiche 50-000.83/09/29.8308300349
- 231017**0**512 Forwards IE Insp Rept 50-397/80-44 during Aug 1983 No nchtompliance noted

 RISHOP-T W Division of Resident, Reactor Project & Engineering

 Programs 83/09/29 MAZUR, D W Washington Public Power Supply

 System 2pp 20782 172 24X Fiche 50-397, 83/09/29, 8310170612
- --F310170621 IE Insp Rept 50-397/83-44 during Aug 1983 No noncompliance noted Major 4reas inspected preoperational test procedure review & independent insp effort, including testing of pipe support & restraint sys FEIL, R A., DODDB, R T. Region 5, Office of Director 83/09/27 bpp 20782 174 24X Fiche 50-397,63/09/29,8310170612
- 3310180331 Ack receipt of 830912 ltr informing NRC of steps taken to correct violations noted in 1t. Insp Rept 80-397/83-14 BISHOP.T W Bivision of Resident: Reactor Project & Engineering Programs 83/10/03 CARLIBLE.C 8 Washington Public Power Buppli System Jp 20802 344 24X Ficher 50-397.83/10/03.8310180331
- --8310180341 Submits interim response to NRC 830403 ltr rm violations noted in IE Insp Rept 50-397783-14 Corrective actions Ovality Class I & II PEDs undergoing reevaluation Sample program expected to be completed by 830930.

 CARLISLE, C S Washington Public Power Supply System 83/09/12 STERNBERG, D M Region 5, Office of Director 2pp 20802 345 24X Fiche 50-397,83/10/03,8310180331
- 310200194 Ack receipt of 830726 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/83-38
 315MCP.TW Division of Resident Reactor Project & Engineering Programs 83/10/04 CARLISLE,C 8 Washington Public Power Supply System. Ip 20833-346 24X Fiche 50-397,83/10/04,8310200194.

- --8310200200 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-397/83-38 Corrective actions deficiencies reviewed against required hanger function Hangers determined adequate
 - abequate CARLISLE,C S Washington Public Power Supply System 83/09/26. MARTIN.J D Region 5, Difice of Director 35pp 20833 347 ; Fiche 50-397.83/10/04,8310200194
- --8310200203 "Engineering Insp & Evaluation of Guality Class II/Seismic Category I Pipe Supports "
 VARANEL B . COOK. J L . PURVIS.F Stone & Webster Engineering Cate 83/09/22 34pp 20834 020 24X Fiche 50-397,83/10/04.
- 8310210055 Forwards IE Insp Rept 50-397/83-34 on 830701-31 No moncompliance noted
 BISHOP,T W Division of Resident,Reactor Project & Engineering
 Programs B3/10/04 MAZUR,D W Washington Public Power Supply
 Bystem 2pp 20855 275 24X Fiche 50-397,83/10/04.8310210055
- -8310210040 IE Insp Rept 50-397/83-34 on 830701-31 No noncompliance noted Major areas inspected preoperational test procedure review.preoperational test witnessing.unrasolved items & independent insp effort FELL, R 4, NODUS, R T. Region 5, Office of Director 93/7pp 20855 277 24X Fiche 50-397.83/10/04.8310210055 83/09/30
- 8310130426 Notification of 831014 meeting w/util in Bethesda, MD to discuss const appraisal team findings in civil & structural const area AULUCK, R Licensing Branch 2 83/10/06 SCHWENCER, A Licensing Branch 2. 3pp 20769 244 24X Fiche 50-397.83/10/06.8310130426
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants "Evc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24% Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- B310170481 Ack receipt of B30929 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/B3-38 BISHOP, TW Division of Resident, Reactor Project & Engineering Programs B3/10/07 CARLISLE, CB Hashington Public Power Supply System Ip 20783 300. 24% Fiche 50-397, B3/10/07, B310170481.
- --8310170507 Responds to NRC 830830 ltr re violations noted in IE Insp Rept 50-997/83-38 Corrective actions specific deficiency noted in Item D of notice of violation placed in project tracking sys Deficiency will be corrected by 831101 CARLISLE, C S Washington Public Power Supply System 83/09/29. MARTIN.J B Region 5, Office of Director 4pp 20783 301 24X Fichs 50-397,83/10/07,8310170481
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consbidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000.89/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310210043 Forwards IE Insp Rept 50-397/83-48 in Sept 1983 No. noncompliance noted BIGHOP: TW Region 5, Office of Director. 83/10/13 HAZUR, D W Washington Public Power Supply System. 2pp 20855 268 24X Fiche 30-397,83/10/13,8310210043.
- --8310210045 IE Insp Rept 50-397/83-48 during Sept 1983 No noncompliance noted Hajor areas inspected preoperational test witnessing & independent insp effort FELL,R A, DODDS,R T Region 5, Office of Director. 83/10/11, 5pp 20855:270. 24X Fiche 50-397.83/10/13.8310210043
- 8310270420 Notification of 831025 significant licensee meeting w/util in Walnut Creek.CA to discuss NRC regional evaluation of licensee performance for Aug 1982 ~ Jul 1988 * Region 5. Office of Director 83/10/25 Region 5. Office of Director 1p 20923.107 24X Fiche 50~397.83/10/25.8310270420

- 8 Reportable occurrences. LERs & related correspondence
- 8309300331 Final deficiency rept, Condition 258 re failure to comply w/GE specs for installation of RHR HX Initially reported on 830609 Deficiencies corrected Final review practices developed by completion contractor CARLIBLE, C 8 Washington Public Power Supply System 83/09/22 ARTIN, J B Region 5, Office of Director 6pp 20548 266 24X Fiche 50-397,83/09/22,830930331
- 8310040331 Part 21 rept re control circuits for safety-related valves CAC-FCV-IA & IB powered from non-Class IE power supply Caused by Failure to recognize valves have two safety-related functions; isolation & organ/hydrogen recombination CONN. W 0 Burns & Rop Co 80/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20617. IIB 24X fichs 50-397,83/09/29,8310040331
- 8310250505 Part 21 rept re safety-related control circuits for CAC-FCV-IA & IB.being powered from non-Class IE power supply Initially reported on 830928 PED 219-E-C105 issued to provide Class IE power supplies to two valves CONN.W 0 Burns & Roe Co m3/09/29 Director's Office, Office of Inspection and Enforcement 2pp. 20902 078 24x Fiche: 50-397.83/09/29.8310250505
- 8310250270 Final deficiency rept, Condition 47 re operation of standby gas treatment sys damper Initially reported on 820817 Caused by AE failure to adequately apply single failure criterion PED-218-E-8137 issued to reroute circuits CARLISLE:C B Hashington Public Power Supply System 83/10/11 MARTIN, J B Region 5, Office of Director 4pp. 20897 013 24X Fiche. 50-397, 83/10/11.8310250290
- 8310250425 Final Deficiency Rept 270 re indeterminate grade matl on ECCS pumps HPCS-P-1. (PCS-P-1. RHR-P-28 & 2C Initially reported on B30707 Operations maint surveillance program implemented to check breakaway torque CARLIBLE, C 8 Washington Public Power Supply System 83/10/13 MARTIN. J. B Region 5. Office of Director 3pp 20897 001. 24X Fiche 50-397,83/10/13.8310250425
- 8310250453 Final deficiency rept.Condition 262 re power piping M-146 near brackets substituted for previously approved & unavailable M-142 brackets Burns & Roe revised Spec 215. Section 1B.App D CARLISLE.C 8 Hashington Public Power Supply System 83/10/13 HARTIN.J B Region 5. Office of Director 3pp 20897 155 24X Fiche 50-397,83/10/13.8310250453
- 8310250092 Interim deficiency rept. Reportable Condition 286 re linear indications in containment weld pads Cause Unknown All 19 weld pads providing support for radial beams being reinspected & repaired Nest rept due by 831111 CARLIBLE, C 8 Washington Public Power Supply System 83/10/14 HARTIN, J B. Region 5. Office of Director 3pp 20894 109 24X Fiche 50-397,83/10/14,8310250092.
- 8310250144 Final Deficiency Rept 290 re diesel generator exciter control cabinet overheating Design Change SPED 8218-M-C247 issued to provide addl ventilation for Div 1 & 2 diesel generator excitation control cabinets.

 GRALISLE: C B Washington Public Power Supply System 83/10/14 MARTIN. J B Region 5. Office of Director 2pp. 20896 324 24X Fiche 50-397,83/10/14.6310250144

V Dperetor Examinations

- 8310030142 Requests schedule by 831028, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs BISHOP.I.W Division of Resident Resector Project & Engineering Programs. 83/09/26 00DFFREY.0 Washington Public Power Supply System 2pp 20590 040 24X Fiche 50-397,83/09/26,8310030142
- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8310280174 F0IA request for all internal nonpublic documentation reconst flaws & improper conduct by inspectors.util contractors or subcontractors MCINNIB.D News & Observer 83/07/19, FELTON, J Division of Rules and Records Ip 20963 287 24X Fiche 50-400,83/07/19,8310280174
- 8310030161 Advises that organizational changes for QA program & changes to FBARs & mgt capability rept will be forwarded when completed.

 UTLEY.E E Caroline Power & Light Co. 83/09/13. DENTON:H R Office of Nuclear Reactor Regulation. Director ip 20590 028 24X Fiche 50-000,83/09/13,8310030161

- 8310040354 Summarizes 830831 meeting w/util re plans for restructuring corporate organization
 O'REILLY, J P Region 2, Office of Director 83/09/22 UTIEY, E E Carolina Power & Light Co 2pp 20620 331 24x
 Fiche 50-000 83/09/22 8310040354
- 8310280176 Responds to FOIA request for internal nonpublic documentation be constitled & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A
 FELTON, J M Division of Rules and Records 83/09/23 VADEN, T
 News & Observer 3pp 20963 288 24% Fiche 50-400, 83/09/23, 8310280176
- --8310280197 Forwards draft Ofc of Inspector & Auditor /81109 rept on inquiry into alleged omission of line inspector views from CP hearing, for germsal Wo encl MURRAY.JP Deputy Executive Legal Director 78/12/18 CUMMINOS,JJ Office of Inspector & Auditor 3pp 20963 292 244 Fiche 50-400,83/09723,8310280176
- --8310280202 Documents telcon w/fC Cantrel) re insp file in preparation for testimony instructions not received to review file Cantrell relief solely on personal notes & records to prepare testimony FOSTER.W H Office of Inspector & Auditor 78/11/01 Diffice of Inspector & Auditor 78/11/01 Biffice of Inspector & Auditor 19 20963 295 24X Fiche 50-400.83/09/23, 8310200176
- --B3102B0207 Advises that ABLAB Chairman, AS Rosenthal will decline interview, claiming purposelessness FOSTER, W M Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 296 24X Fiche 50-400,83/09/23.
- --0310280211 Advises that IE Manual Chapter 94010-B only written policy for preparing testimony for licensing hearings, per 701025 teleon w/RC Paulus FOSTER, W H Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 297 24% Fiche 50-400, 83/09/23, 8310260176
- ~-8310280214 Forwards AS Rosenthal 781024 memo to 00 Abston, for perusal ABSTON.O 6 Dffice of Inspector & Auditor 78/10/25 HENDRIE, J M Commissioners ip 20963 298 24% Fiche 50~400.83/09/23.8310220176
- --8310280218 Advises that ASLAB members not willing to be interviewed due to possible future involvement in case ROSENTHALA 8 Atomic Bafety and Licensing Appeal Panel 78/10/24 ADSTON.0 0 Office of Inspector & Auditor 1p 20963 299 24X Fiche 50-400, 83/09/23, 8310280176
- ---8310280222 Requests interview w/ASLAB members to discuss impact of onission of line inspector views from written & oral testimony ABSTON.0 0 Office of Inspector & Auditor 78/10/24 ROBENTHAL, A § Atomic Bafety and Licensing Appeal Panel Jp 20963 300 24% Fishe 50-400,83/09/24,8310280174
- --8310280225 Farwards info re ()fc of Inspector & Auditor interview of ASLAB (ref Yore 781019 memo to Commissioners)
 FRYE.J H. Atomic Safety and Licensing Board Panel 79/10/20
 ROSENTHAL,A, KELLEY,J L. ABSTON,O G. NRC No Detailed
 Affiliation Given ip 20783 301 24% Fiche 50-400,83/09/23,8310280176
- --8310280236 Forwards DH Gamble 781019 memo, for interest ABSTON.D G Office of Inspector & Auditor 78/10/20 HENDRIE.J M Commissioners ip 20963 312 24X Fiche 50-400,83/09/23.8310280176
- --8310280238 Summarizes A Rosenthal 781019 teleon opposing potential interview w/ASLAB members, citing unpleasantness of ASLB interview Oft of Inspector & Auditor must assure different line of questioning before interview is granted GAMBLE, D H Office of Inspector & Auditor 78/10/19 Office of Inspector & Auditor 78/10/19 Office of S10280176
- --8310280242 Forwards documentation of 781017 conversation w/JM Varein former AEC employee re V Brownlee Conversation connected w/ current investigation DAVIS.J G Director's Office, Office of Inspection and Enforcement 78/10/19 ABSTON.D G Office of Inspector & Auditor ip 20963 315 24X Fiche 50-400.83/09/23.8310280176

- --9310260244 Documents 781017 conversation w/J Varela, former Region II ecployer Brownlee directed Varela to change info in insprept, causing dispute DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 Director's Office, Office of Inspection and Enforcement ip 20763 316 24X Fiche 50-400,63/07/23,831028017A
- --8310280246 Documents 781017 conversation w/C Barth (OELD) re testimony forwarded to ASLD before 771004 hearing ASLB should be required to read testimony before hearing FOSTER,N H Office of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 19 20963 317 24X Fiche 50-400,83/09/23,8310280176
- --B310280248 Advises of Ofc of Inspector & Auditor Inability to procure useful info during interview w/ASLB due to ASLB unresponsiveness
 ABBION.D G Office of Inspector & Auditor 78/10/17
 HENDRIE.J M , GILINGKY.V , KENNEDY.R T Commissioners 20083 024 24% Fiche 50-400,83/09/23.8310280176
- --8310280290 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to QA problems listed in subj insprepts
 FOSTER.W H Defice of Inspector & Auditor 78/10/10 Defice of Inspector & Auditor 1p 20963 326 24X Fiche 50-400.03/09/23.
 8310280176
- --8310280254 Forwards case assignments for ASLB members 9D Bright, JV Leeds & IW Smith, per request FITTI.C J Atomic Safety and Licensing Board Panel 78/30/06 GAMBLE, D H Office of Inspector & Auditor App 20963 327 P4X Fiche 50-400.83/09/23.8310280176
- --0310280256 Forwards Acting General Counsel opinion indicating no exparte problem w/Ofc of Inspector & Auditor interview of ASLB members
 ABSTON.O O Office of Inspector & Auditor 78/10/03 YORC, J.R., POSENTRAL, A S Atomic Safety and Licensing Board Panel Ip 20963 333 24K Fiche 50-400,83/09/23,8310280176
- --9310280299 Informs of 781003 conversation w/I Smith of ASLB re Oft of Inspector & Auditor interview w/ASLB members, to fwlfill Commission order Interview will probably not be granted due to exparte rule FOSTER, H Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 1p 20963 335 24X Fiche 50-400.83/09/23, B310280174
- --8310280263 Summarizes continued attempts to gain ASLB interview through 780927 conversation w/JV Leeds Leeds will not cooperate, citing ex parte rule FOSTER,W H Office of Inspector & Auditor. 78/09/27 Office of Inspector & Auditor. 78/09/27 Office of Inspector & Auditor. 80/09/23, 8310280176
- --B330280265 Informs of alleged impropriaties re deficiency discrepancy repts & corresponding logbook entries
 VDRSE, J Y Diffice of Investigation 83/03/04 ALBERSON, C Y NRC
 No Detailed Affiliation Given 1p 20963 338 24X
 Fichs 50-400,83/09/23.8310280176
- --BJIO280270 Discusses alleged improprieties re deficiency discrepancy repts & corresponding loghook entries BUNCH.R H Office of Investigation B3/03/03 Office of Investigation ip. 20963, 339 24X Fiche 50-400, 83/09/23, 8310200174
- --8310280299 Advises that no new info revealed after inquiry of alleged improprieties re deficiency discrepancy rapts & corresponding logbook entries
 **VORSE.J Y Diffice of Investigation 83/05/06 TDDD.G NRC -- No Detailed Affiliation Given ip 20963 340 24X
 **Fiche 50-400.83/09/23.8310280176
- -- 9310280303 Advises that inquiry into alleged improprieties re deficiency discrepancy repts & corresponding logbook entries closed Util cited for violation BURCH.R H Office of Investigation 83/05/04 Office of Investigation ip 20963;341 24X Fiche. 50-400,83/09/23, 8310280176
- 310070120 Farwards response to requests for add1 info.including response to Rev 1 to "Basis for Auxiliary Feedwater Sys Flow Requirements," in support of safety review Response includes info re main steam turbine valve testing issue MCDUFFIE.M A Carolina Power & Light Co. 83/09/30 DENTON-H R Office of Nuclear Reactor Regulation. Director 41pp 20458-34 24X Fichs 50-400.83/09/30.8310070120

- 8310310172 Forwards NRC 830921 Itr to util advising of acceptance of design, analyses, matls & const aspects of containment vessel weld deficiencies, in response to Resolution 1443-83 NOVAK.T M Assistant Director for Licensing 83/10/18 EULERT, & A Perry, OH 3pp 20965 288 24X Fiche 50-400, 83/10/18, 8310310172
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310130240 Forwards addl info in response to draft BER Open Item 354, including Mcchanical Engineering Branch questions in 830819 & 25 Itrs

 MCDUFFIE.M A Carolina Power & Light Co 83/09/19 BENTON, H R Office of Nuclear Resultation. Director App 20722 236 24X Fiche 50-400, 83/09/19, 8310130246
- --8310130248 GC Procedure 120, "Hydrostatic Testing (Critical Svr) "
 * Goulds Pumps, Inc 80/07/01 3pp 20722 242 24X
 Fiche 50-400,83/09/19,8310130240
- --8310130254 Rev 3 to GA Instruction GAI-212, "Training & Qualification of GA Personnel"
 * Goulds Pumps, Inc 80/06/18 11pp 20722 245 24%
 Fiche 50-400,83/09/19,8310130240
- --8310130261 "Seismic Gualification Envelope Limitorque Valve Actuators "DRAB, J II , DENKONSKI, W J , FORMICA, C D. Limitorque Corp B0037 80/01/11 24pp 20722 256 24X Fiche 50-400, 83/09/19, 8310130240
- --B310130267 Rev 1 to "Rept of Test on Seismic Vibration Testing of One Limitorque SHB-OOO/HOBC Actuator for Limitorque Corp." ESF091170.8., CASAUBON, H., TOLF, H.L. Actor Environ Testing Corp 14331-2 ROI 79/03/13 lapp 20722-280 24X Fiche-50-400.83/09/19.8310130240
- ---B310130271 Rev 1 to "Rept of Test on Seismic Vibration Testing One Limitorque SMB-000/H09C Actuator W/Soismic Adaptor for Limitorque Corp " ESP03170,8 , CASAUBON,M., TOLF,M.L. Acton Environ Testing Corp 14331-3 R01. 79/03/13 12pp 20722 27b 24X Fiche 50-400,83/09/19,8310130240
- --8310130273 "Seismic Test BMB-000/HOBC "
 YOUNG:P T Limitorque Corp B0045 83/09/19 App 20722 308
 24% Fiche 50-400.83/09/19.8310130240
- ---8310130277 Rev i to "Rept of Test on Beismic Vibration Testing of Limitorque SMB-1/H3BC Actuators for Limitorque Corp " ESP091TO, B. OILFOY, R., TOLF, M.L. Acton Environ. Testing Corp 14801-1 ROJ. 79706/11 41pp. 20722 314 24X F1che 50-400,83/09/19,8310130240
- ---8310130280 "Rept of Fragility Test on SMD-1-25/H4BC W/Btd Cast Adapter for Limitorque Corp" * Aero Nav Laboratories, Inc 5-6167-5 75/12/17, 36pp 20722.355 24X Fithe 50-400.83/09/15,8310130246
- --8310130282 Rev 0 to Engineering Spec JSN-T35, "Seat Testing & Disc Hydrostatic Testing - 5 Minute Duration" * Jamesbury Corp. 78/01/24 | 11pp 20723 029. 24X Fiche 50-400.83/09/19,8310130240
- --8310130285 Rev 0 to Procedure 4-106, "Cold Bending of Carbon Steel & Ferritic Alloy"

 * Southwest Fabricating & Welding Co (subs. of IU International Corp) 73/05/04 3pp 20723 040 24X Fiche: 50-400, 83/09/19, 8310130240
- --8310130287 Rev 0 to Procedure 4-107, "Cold Bending of Austenitic Stainless Steel Piping"

 * Southwest Febricating & Helding Co (subs of IU International Corp) 73/05/04 3pp 20723 043 24X Ficher 50-400, 83/09/19, 8310130240
- --8310130289 Rev O to Procedure 4-108, "Hot Bending of Carbon Stee) & Ferritic Alloys "

 # Bouthwest Fabricating & Welding Co (subs. of IU International Corp.) 73/05/04 5pp 20723 046 24% Fiche: 50-400.83/09/17, 8310130240.
- --B310130290 Rev O to Procedure 4-109, "Hot Bending of Austenitic Btainless Eteel Piping" * Southwest Fabricating & Welding Co. (subs of IU International Corp > 73/05/04 11pp 20723 051 24X Fiche: 50-400, 83/09/19, 8310130240
- --8310130291 Procedure MNE-65, "Pipe Line Sixing Guide "
 # Ebasco Services, Inc. (subs. of Emserch Corp.) 70/06/20 7pp
 20723 062 24X Fiche 30-400,83/09/19,8310130240

- --8310130293 Rev 8 to Site Spec 030. "Field Fabrication & Erection of
 - # Carolina Power & Light Co 83/03/29 23pp 20723 069 24% Fiche 50-400, 83/09/19, 8310130240
- --8310130294 Engineering Procedure 3 2. "Design Change Control "

 * Carolina Power & Light Co 83/08/19 52pp 20723 092 24X
 Fiche 50-400,83/09/19,8310130240
- 83:0170:24 Summary of 830825 meeting w/util & Ebasco in Dethesda, MD re Meteorological & Effluents Treatment Sys Branch draft SER
 - Open 1 teams BUCKLEY, B.C., HOLONICH, J. Licensing Branch 3 83/09/29 Licensing Branch 3 8pp 20813 059 24X Fiche 50-400.83/09/29. 8310170124
- 8310110119 Forwards amended response to request for add1 info re draft 8ER Open Item 3B concerning technical basis for GDC-31 compliance Responses to other requests will be provided
 - shortly MCDUFFIE.H A Carolina Power & Light Co B3/09/30 DENTON.H R Office of Nuclear Reactor Regulation. Director 150pp 20667 038 24X Fiche 50-400.83/09/30.8310:10119
- 8310120180 Forwards response to request for add1 info re draft SER open items on resvaluation of PMP, plant area water accumulation & adequacy of electric distribution sys voltages MCDUFFLEM A Carolina Power & Light Co 83/10/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 20695 301 24% Fichs. 30-400, 83/10/05, 8310120180
- 8310140126 Forwards response to NRC Question 210 59 re piping spec, loading combinations & stress limits completing response to 32 Mechanical Engineering Branch questions in 830819 & 25 ltrs for SER Open Item 354 MCDUFFIE.M A Carolina Power & Light Co 83/10/10 DENIGN, H. R Office of Nuclear Reactor Regulation, Director 21pp 20743 045 24% Fiche 30-400,83/10/10,8310140126
- 8310180474 Forwards responses to draft SER Open Items 355-383, discussed at 830921 meeting w/Auxiliary Sys Branch in Bethesda.MD MCDUFFIE.M A Carolina Power & Light Co 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 37pp 20801 351 24X Fiche.50-400,83/10/11.8310180474
- 9310180311 Forwards add1 info re draft SER open items, in response to Machanical Engineering. Power Bys & Reactor Sys Branch concerns Westinghouse Cuners Group Jul 1977 rept & Sept 1977 suppl will be used in derivation of setpoints MCDUFFIE, H A Carolina Power & Light Co 83/10/12 DENTON, H R Office of Nuclear Reactor Regulation. Director 22pp 20803 076 24X Fiche 50-400.83/10/12.8310180311
- 0310210024 Forwards responses to requests for add1 info to draft BER open items MCDUFFIE.M A Carolina Power & Light Co 83/10/14 DENYON, H R Uffice of Nuclear Reactor Regulation, Director 55pp 20806 Oi 24x Fiche 50-400,83/10/14,8310210024
- 8310280638 Forwards supplemental info in response to Biting Analysis Branch concerns re SER Item 7 Besboard Sys Railroad provided assistance in preparation of supplemental info. Encl withheld (ref 100FR2 790) MCDUFFIE,H A Carolina fower & Light Co B3/10/14. DENTON,H Office of Nuclear Reactor Regulation, Director 2pp 20899 3 24X Fiche, 50-400, 83/10/14,8310250638 20999 314
- 8310260259 Forwards proprietary & nonproprietary versions of "Table of Control Rod Drive Mechanism (CRDM) 400 Beries Stainless Steel Items," in response to Matis Engineering Branch draft SER open Items Proprietary table withheld fref 10CFR2 790) MCDUFFIE.M A Canolina Power & Light Co 83/10/14 DENTON, H R Office of Nuclear Resetute High Ton. Director 2pp 20909 209. 24X Fichs. 50-400, 83/10/14. 8310260259
- --8310260267 Application for withholding proprietary "Table of Control Rod Drive Mechanism (CRDM) 400 Baries Stainless Steel Items:" per 10CRB2 770 W/aefidavít WIESEMANN, R.A. Westinghouse Electric Corp 83/10/11 LIAW, B.D. Materials Engineering Branch 10pp 20907 211 24% Fiche 50-400,83/10/14,8310260259
- --8310260283 Nonproprietary "Table of Control Rod Drive Mechanism (CRIM) 400 Beries Steinless Steel Items " * Hestinghouse Electric Corp. 83/10/14 ip 20909 221 24X Fiche:50-400.83/10/14.8310220259

- 8310260147 Forwards responses to requests for addl life re druft SER Open Items 63 & 67 Responses verify containment pressure & justify operation of normal containment purge MCDUFFIE, M A Carolina Power & Light Co 83/10/20 DENION H R Office of Nuclear Reactor Repulation, Director 24X Fiche 50-400,83/10/20,8310260147
- 8310260152 Forwards response to NRC request for add1 info re emergency diesel generator load sequence reliability (draft SLR Open (tem 310) Applicant in process of performing PRA on sequencer MCDUFFIE,M A Carplina Pawot & Light Co 83/10/20 DENTON.H & Office of Nuclear Reactor Regulation, Director 2pp 20912 23/ 24X Ficha 50-400,83/10/20.8310/260152
- 8310260134 Forwards response to request for add1 info re draft SER Open Item 77 Shunt trip attachment mod will be implemented, per Generic Ltr 83-28 MCDUFFIE, M A Carolina Power & Light Co 83/10/21 PENTON, H fi Office of Nuclear Reactor Regulation. Director 2pp 20912 276-24X Fiche 50-400,83/10/21,8310260134
- 8310280014 Forwards nonproprietary & proprietary responses to request for add1 info re criticality analyses for spent fuel racts
 Draft SEK Open Item 360 completed Proprietary response withheld (ref 100fR2 790)
 MCDUFFIE,M A Carolina Power & Light Co 83/10/21 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 4pp 20929 028
 24X Fiche 50-400,83/10/21,8310280014
- --8310280019 Application for withholding proprietary response to request for add1 info re criticality analyses for spent fuel racks Nonproprietary version of response and WIESEMAWN, R.A. Westinghouse Electric Corp. 83/10/11 BERLINGER, C.H. Core Performance Branch. 32pp. 20929 030 24X Fiche 50-400,83/10/21,831020014
- F Security, medical, emergency & fire protection plans
- 8310170070 Summary of 830825 meeting w/util & Ebasco re fire protection program & safe shutdown analysis
 HONDLICH.J Licensing Branch 1 BUCKLEY.B C Licensing Branch 3 83/09/30 Licensing Branch 1 3pp 20790 019 24X
 Fiche 50-400.83/09/30.8310170070
- B310180185 Summary of 630926 & 27 meetings w/util & Ebasco re fire protection open items drawing review & Auxiliary Sys Branch discussion of safe shutdown analysis BUCKLEY. B C Licensing Branch 3 HOLDNICH, J J Licensing Branch 3 83/09/30 Licensing Branch 3 9pp 20827 014 24X Fiche 50-400, 83/09/30, 8310180185
- 8310120266 Forwards Rev 1 to emergency plan Evacuation time study scheduled for completion by 8,3231 UTLEY,E E Carolina Power & Light Co 87/10/04 DENFON,H R Office of Nuclear Reactor Regulation, Director 2pp 20688 001 24X Fiche 50~400.83/10/04,8310120266 20688 001
- --8310120268 Rev 1 to emergency plan * Carolina Power & Light Co 83/09/30 63pp 20688 003 24% Ficho 50-400,83/10/04,8310120266
- 8310210136 Forwards add1 info ro fire protection, including response to Safety Review Question 280 1, revised safe shubdown analysis w/exemptions & mods.info requested in 830926-27 meetings w/ NRC & response to Enforcement Action 89-41 MODUFFIE.M A Carolina Power & Light Co 83/10/14 DENTON, H & Office of Nuclear Reactor Requiaction, Director 475pp 20856 15i 24X Fiche 50-400, 83/10/14, 8310210136
- Q Adjudicatory correspondence
- 8310030441 Response to general interrogatories & interrogatories on Contention BF(1) Related correspondence CARROW.H Carolina Power & Light Co B3/09/23 EDDLEMAN.W Eddleman. W 16pp 20602 069 24X Fiche 50-400.83/09/23. 8310030441
- ~~8310030478 Response to request for production of documents on Contention 8F(1) Certificate of Svc encl CARRON.H Carolina Power & Light Co 83/09/23 EDDLEMAN, W Eddleman, W 4pp 20602 085. 24X Fiche 50-400, 83/09/23, 8310030441
- 8310030367 Response opposing util motion for summary disposition of Eddleman Contention 80 re mixing & dispersion models Statement of facts as to which there are issues to be heard encl EDDLEMAN, W Eddleman, W 83/09/27 Atomic Bafety and Licensing Board Panel App 20593 009 24% Fichs 50-400,83/09/27,0310030367

- --8310030367 Response opposing util motion for summary disposition of Eddleman Contention 75 on clams Statement of facts as to which there are issues to be heard encl EDDLEMAN. W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel Bpp 20593 015 24X Fiche 50-400,83/09/27,8310030367
- --8310030372 Response opposing util motion for summary disposition of Eddleman Contention 83/84 re carcinogenic discharges
 Statement of facts as to which there are issues to be heard enti

enc: EDDLEMAN, W Eddleman, W 83/09/27 Atomic Sofety and Licensing Board Pane) App 20593 024 24X Fishe 50-400,83/09/27, 831003036/

- --8310030375 Response to util motion for summary disposition of Eddleman Contention 647 EDDLEMANH Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 2pp 20593 030 24X Fiche 50-400,83/09/27, 8310030367
- --831003037/ Motion for license condition on spent fuel shortage if Contention 64F withdrawn EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel 5pp 20593 032 24X Fiche 50-400,83/09/27, 8310030367
- --8310030380 Response partly opposing util proposed schedule rev Certificate of Svc encl EDDLEMAN, H Eddleman, W 83/09/27 Atomic Safety and Licensing Baard Panel 2pp 20593 037 24X Fiche 50~400,83/09/27, 8310030367
- \$310040523 Natifies that util counsel & author agreed to negatiate next is on util responses to Eddleman Interrogatories 15AA & BFI Notice tolls time for filing motion to compel ECOLEMAN.W Eddleman. W 83/09/28 KELLEY.J Atomic Safety and Licensing Board Panel 1p 20624 234 24X Fiche 50-400.83/09/28, \$310040523
- BIICO30508 Response to ABLB B30922 inquiry re W Eddleman proffered Contention 24 Opposes contention re terrorist acts directed against irradiated fuel in transit Regulations do not require security plan for shipment Certificates of Svc encl BARTH.C A Hearing Branch 1 B3/09/29 Atomic Bafety and Licensing Soard Panel Bpp 20601 170 24X Fiche 50-400,83/09/29, \$310030508
- ESIDO40518 Response to 10CFR2 758 potition of B30630 on need for power 1 alternatives Cortificate of Svc encl EDMLEMAN.W Eddleman.W B3/09/30 Atomic Bafety and Licensing Spard Panel B9pp 20623 001 24% Fichs 50-400.83/09/30, 8310040518
- B31004053B Forwards Page 10.inadvartently omitted from util 830729 reply to W Eddleman response to ASLB 830824 order D'AEILL.J H Shaw, Pittman, Potts & Trowbridge D'AEILL.J H Carolina Power & Light Co 83/09/30 KELLEY,J L , BRIGHT, & D , CARPENTER.J H Atomic Safety and Licensing Board Panel ip 20623 297 24X Fiche 50-400,83/09/30.8310040538
- --531004094| Page 10. Inadvertently omitted from util 830929 reply to W Eddleman response to ABLB 830824 order 8vc list encl Carolina Power & Light Cn 83/09/30 Atomic Safety and Licensing Board Panel 3pp 20623 298 24X Fiche 50-400, 83/09/30.831004053B
- E310050555 Response supporting util 830912 motion to modify schedule on environ contentions Issuence of FES by 831031 should be factored into schedular mode Certificate of Bvc encl BARTH.C A Hearing Branch 1 83/10/03 Atomic Bafety and Licensing Board Panel. 3pp 20629 037 24X Fiche 50-400,83/10/03,6310050565
- 3010060188 Forwards motion for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 378 on health effects Related correspondence O'NEILL.J H Shaw, Pittman, Potts & Trowbridge O'NEILL.J H Carelina Power & Light Co 83/10/03 KELLEY,J L , BRIGHT, G.D , CARPENTER.J K Atomic Bafety and Licensing Board Panel 2pp 20649 CO1 24X Fiche, 50-400, 83/10/03, 8310060188
- -83100&0193 Motion for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 378 re health effects No genuine issue of matl fact exists & util entitled to favorable decision Related correspondence AMLICK.D D Carolina Power & Light Co AULICK.D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 62pp 20649 003 24X Fiche. 50-400, 83/10/03, 8310060188.

- --8310060203 Statement of matl facts as to which there is no genuine issue re Joint Intervenors Contention II & W Eddleman Contention 378 Related correspondence AULICK, D D Garolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Beard Panel 13pp 20649 071 24X Fiche 50-400,83/10/03,8310060188
- --8310060212 Affidavit of JI Fabrikant re health effects estimates in DES Somatic & genetic health effect estimates in DES are not underestimated Prof qualifications encl Related correspondence
 FABRIKANT, J I Carolina Power & Light Co FABRIKANT, J I Lawrence Livermore Laboratory 83/10/01 120pp 20649 084 24X Fichs 50-400,83/10/03,8310060188
- --8310060222 Affidavit of GH Whipple supporting util motion for summary disposition of Joint Intervenors Contention II NRC models use concentrations, doses & health effects unaffected by incomplete mixing or dispersion Related correspondence WHIPPLE.G H Carolina Power & Light Co 83/09/30 idpp 20649.209 24% Fiche 50-400,83/10/03.8310060188
- --8310040238 Affidavit of JJ Mauro supporting util motion for summary disposition of Joint Intervenors Contention II & Eddleman Contention 378 DES determined max ratio of health effects from plant operation Related correspondence
 MAURO J J Carolina Power & Light Co MAURO, J J Ebesco Services, Inc (subs of Enserch Corp) 83/10/03 18pp. 20447 225 24X Fiche 50-400,83/10/03.8310040188
- 8310060323 Notice of appearance in proceeding Certificate of Bvc encl AULICK, D. D. Carolina Power & Light Co. AULICK, D. D. Shaw, Pittman, Putts & Trowbridgs 83/10/03 5pp 20646 227 24X Fiche 50-400, 63/10/03.8310060323
- 6310110150 Motion for summary disposition of Eddleman Contention 27/30 (App I compliance) No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence O'NEILL, J H Garolina Power & Light Co D'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/05 Atomic 9afety and Licensing Board Panel 50pp 20665 135. 24X Fiche 50-400,83/10/05,8310110150
- --8310110155 Statement of matl facts as to which there is no genuine issue re Eddieman Contention 29/30

 O'NEILL.J H Shaw,
 Pittman, Potts & Trowbridge B3/10/05 Atomic Safety and
 Licensing Board Panel 1 Opp 20665 186 24X
 Fiche 50~400, 83/10/05, 83/01/0150
- --8310110407 Affidavit of JJ Mauro & Q Martin in support of applicant motion for summary disposition of W Eddleman Contention 27/30
 MAURD, J J. MARTIN.G Carolina Power & Light Co 83/10/03 58pp. 20665 176 24% Fichs 50-400,83/10/05,8310110150
- --B310110409 Affidavit of RL Shearin in support of applicant motion for summary disposition of W Eddleman Contention 29/30. SHEARIN.R L Carolina Power & Light Ca B3/09/30. Bpp 20465 254. 24% Fiche 50-400.83/10/05.8310110150
- --8310110412 Affidavit of TJ Grant in support of applicant motion for summary disposition of W Eddleman Contention 29/30 Certificate of Svc encl. GRANT.T.J Carolina Power & Light Co 83/09/30 16pp 2065 262. 24X Fiche 50-400.83/10/09.8310110150
- 8310110209 Memorandum & order ruling on discovery disputes Motions to compel & for protective order granted/denied as noted.
 KELLEY, J.L. Atomic Safety and Licensing Board Panel. 83/10/06
 Eduleman, W. 16pp 20665-073, 24X Fichs 50-400,83/10/06.
 8310110209
- 83i011021B Memorandum & order admitting some of W Eddleman late-filed contentions on detailed control room design review R Wilson 830921 & Conservation Council of North Carolina 830884 mutions to withdraw contentions granted 88IGHT.0 O., CARPENTER.J.H. KELLEY.J.L. Atomic Safety and Licensing Board Panel 83/10/06 Conservation Council of North Carolina. 14pp 20665 042 24X Ficha 50-400/83/10/06/8310110218
- 8310120370 Response to interrogatories on Contentions 15AA & BFi Certificate of negotiations & Certificate of Svc ancl EDDLEMAN,W Eddleman, W 83/10/06 Coroline Power & Light Co. 18pp 20679 254 24% Fiche.80-400.83/10/06
- 8310140072 Revised Contention 16! re safety shutdown sys failure Certificate of Svc encl EDDLEMAN,W Eddleman, W. 83/10/11 Atomic Sefety and Licensing Board Panel 2pp 20766 357 24X Fiche: 50-400, 83/10/11, 8310140078.

- 8310140065 Erratum to ASLB 831006 memorandum & order ruling on W Eddlaman proposed contentions re detailed control room design review & R Milson & Conservation Council of North Carolina motions to withdraw contentions KELLEY. J L Atomic Safety and Licensing Board Panel 93/10/12 EDDLEMAN W Eddleman, W MILSON, R Wilson, R 2pp 20768 CO7 24% Fiche 50-400,83/10/12,8310140065
- 8310170543 Forwards corrected version of util motion for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 378 on health effects
 AULICK,D D Shaw, Pittman, Potts & Frombridge AULICK,D D Carolina Power & Light Co 83/10/12 KELLEY,J L , BRIGHT,G D , CARPENTER,J H Atomic Safety and Licensing Board Panel ip 20780 355 24X Fiche 50-400.83/10/12,6310170543
- --8310170408 Corrected capy of mation for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 378 on health effects Errata sheet encl AULICK.D D Shaw, Pittman. Patts & Trombridge 83/10/03 Atomic Safety and Licensing Board Panel 61pp 20780 356 24X Fiche 50-400.83/10/12.8310170543
- --8310170620 Fourth set of interrogatories & request for production of documents O'NEILL,J H Carolina Power & Light Co O'NEILL,J H Shaw, Pittman, Potts & Trowbridge 83/10/12 Joint Intervenors-Shearon Harris 15pp 20781 055 24X Fiche 50-400,83/10/12,83101/0543
- --8310170630 Reply opposing W Eddleman B30927 motion for license condition on spent fuel storage, ASL8 lacks jurisdiction over issues of health & safety re spent fuel transportation Certificate of Svc encl
 O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/1P Atomic Safety and Licensing Board Panel 10pg 20781 070 24X Fiche \$0-400,83/10/12,8310170543
- 8310170626 Response to 830831 interrogatories re Contention 3/8 concerning health impacts from exposure to radioactive matls BRANAGAN, E.F. Radiological Assessment Branch BARTH, C. Rearing Branch 1 83/10/12 EDDLEMAN, W. Eddleman, W. 3pp. 20782 113 24% Fiche 50-400,83/10/12.8310170626
- --8310170632 Response to 83083; second set of interrogatories Statement of prof qualifications & Certificate of Svc encl SCHIENK, 0 A Radiological Assessment Branch BARTH, C A Hearing Branch i 83/10/12 EDDLEMAN, W Eddleman, W 54pp 20782 116 24X Fiche 50-400,83/10/12,8310170626
- 8310230469 Response opposing W Eddleman 830927 motion for license condition on spent fuel storage Notion premature & not in conformity w/Commission regulations Certificate of Svc enti BARTH, C A Hearing Branch I 83/10/17 Atomic Safety and Licensing Board Panel App 20897 145 24X Fiche 50-400, 83/10/17. 8310820459
- 8310250125 Followsp response to Interrogatory 4 on Contention B(F)(1) Listed document will be placed in PDR BARTH.C A Hearing Branch 1 83/10/19 EDDLEMAN.W Eddleman.W 1p 20896 344 24X Fiche 50-400,83/10/19,8310250125
- 031027035; Notifies that negotiations re adequacy & occuracy of NRC response to 83083; discovery on Contentions 378.15AA.8F1 & BF2 continuing Mattons to compel will be filed within 10 days of breakdown of negotiations if required EDDLEMAN, W Eddleman, W 83/10/19 XELLEY, J Atomic Safety and Licensing Board Panel 1p 20924 009 24% Fiche 50-400.83/10/19, 831027035;
- 8310240183 Third supplemental responses to W Eddleman 831006 general interrogatories & interrogatories on Contentions 27 & 378 Certificate of Svc encl Gt886.J J Shaw, Pittmon, Potts & Troubridge. 83/10/20 Eddleman, W 11pp 20878 104 24% Fiche 50-400.83/10/20.8310240183
- 9310250167 Forwards Pages 26-32 of ALAB-653 re security plan contentions, per 931005 telcon request Pages withheld (ref 10CFR73 2)) BARTH C A. Hearing Branch 1 83/10/20 RUNKLE, J North Carolina, State of 1p 20894 061 24X Fiche 50-400,83/10/20,8310250167
- #310250037 Gameral interrogatories & interrogatories on Contentions 8F1.8F2 & 15AA (sixth set) Related correspondence. EDDLEMAN, M. Eddleman, W. 83/10/21 Carolina Power & Light Co 18pp. 20894-115 24X Fiche 50-400,83/10/21

- 8310250040 Interrugatories re Contention: 8F1.8F2 & 15AA (second round-third set) Nelated correspondence
 EDDLEMAN, W Eddleman W 83/10/21 Office of the Executive teg./
 Director opp 20876 166 C4X Fiche 50-400,83/10/21.8310250040
- 8310250086 Response to applicant interrogaturies on Eddleman Contention 65 (sixth set) Certificate of Svc encl Related Correspondence EDDLEMAN, W. Eddleman, W. 83/10/21 Carolina Power & Light to 8pp 20894 143 248 Fiche 50-400.83/10/21,8310250886
- B310260202 Interrogatories & request for production of documents on Eddleman Contention BF(1) Relaced correspondence CARROW.H Consumers Power Co B3/10/21 EDDLEMAN.W Eddleman.W App 20912 237 24% Fiche 50-400.03/10/21.8310260202
- --B310260207 Becond set of interrogatories & request for production of documents re Eddleman Contention 15AA Certificate of Svc encl Related correspondence
 CARRON.H Consumers Power Co 83/10/21 EDDLEMAN.W Eddlemsii.
 W 7pp 20912 243 24X Fiche 90-400.83/10/21.8310260202
- 8310270319 Memorandum & order modifying schedule on environ contentions KELLEY, J.L. Atomic Safety and Licensing Board Panel 83/10/25 5pp 20923 183 24% Fiche 50-400.83/10/25.8310270319
- 8310280051 Response opposing W Eddleman 831010 proposed rev to Contention 161 re safety shutdown sys failure Rev fails to specify defects in original circuit breaker design Certificate of Svc encl

 O'NEILL, J H Carolina Power & Light Co D'NEILL, J H Show, Pittman, Potts & Trowbridge 83/10/25 Atomic Safety and Licensing Board Panel 14pp 20934 333 24X Fiche 50-400,83/10/25,8310280051
- 8310280164 Fifth set of interrogatories on Joint Contention VI re radiation detection & monitoring & request for production of documents ANDERSON,P H Garolina Power & Light Co ANDERSON,P H Bhaw. Pittman, Patts & Troubridge 83/10/25 Joint Intervenors-Shearch Harris 16pp 20929 226 24X Fiche 50-400,83/10/25.8310280164
- 831031014A Informs that DR Lewis, formerly ASLB participant in CR proceeding, began working for author on 831024 DR Lewis will not participate in OL proceeding BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Garolina Power & Light Co 83/10/26 Commissioners App 20759 056 24X Fiche 50-400,83/10/26,8310310146
- @ Inspection reports, IE Bulletins & correspondence
- 8310040220 Ack receipt of 830831 ltr requesting 3-month extension to complete corrective actions in response to violations noted in E Insp Rept 50-400/82-37 Request acceptable.

 LEMIS, R C Division of Project & Resident Programs 83/07/13 UTLEY, E E Carolina Power & Light Co ip 20614 264 24X Fiche 50-400.83/09/13,8310040220
- --8310040224 Requests extension until 831201 to complete replacement of unidentifiable bolts on all Selsmic I pumps, in response to violations noted in IE Insp Rept 50-400/82-39 PARSONS, R M Carolina Power & Light Co 83/08/31 O'REILLY, J P Region 2, Office of Director Ip 20614 265 24% Fiche 50-400,83/09/13,8310040220
- 8310040595 Ack receipt of 830831 & 0902 ltrs informing NRC of steps taken to correct violations noted in It Insp Repts 50-400/83-22 LEWI8, R C Division of Project & Resident Programs 83/09/13 UTLEY, E C Carolina Power & Light Co Ip 20626 240 24X Fiche 50-400,83/09/13,8310040595
- --8310040600 Responds to NRC 830803 ltr re violations noted in IE Insp. Repts 50-400/83-22 & 50-401/83-22 Corrective actions all shop welded joints requiring inservice insp. will be identified & reworked to meet surface finish requirements PARBONS.R M. Carolina Power & Light Co. 83/09/02 O'REILLY, J. Region 2. Office of Director 3pp. 20626 241 24X Fich 50-400.83/09/13.8310040595
- --B310040603 Responds to NRC B30803 ltr re violations noted in IE lnsp Repts 50-400/83-22 & 50-401/83-22 Corrective actions approx 150 deficiency & disposition repts reviewed by superintendent & GC for closure by GC/GA specialist PARSONS,R M Carolina Power & Light Co B3/09/02 O'REJLLY,J P Region 2, Office of Director. 5pp 20626 244 24X Fichs 50-400,83/09/13,8310040595

- --B310040666 Responds to NRC 830803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions Phase I insps to hanger SA-H-123 declared preliminary & Phase II insps considered insp of record PARSUNS,R M Carolina Power & Light Co 83/08/31 D'REILLY, J P Region 2, Office of Director 2pp 20626 249 E4X Fiche 50-400, B3/09/13, B310040595
- --8310040608 Forwards IE Insp Repts 50-400/83-22 & 50-401/83-22 pn 830620-0720 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/08/03 UTLEY.E E Carolina Power & Light Co 2pp 20626 251 24X Fiche 50-400.83/09/13.8310040595
- --8310040610 Notice of violation from insp on 830620-0720 * Region 2, Office of Director 83/08/03 2pp 20626 253 24X Fiche 50-400.83/09/13.8310040595
- --8310040613 IE Insp Repts 50-400/83-22 & 50-401/83-22 on 830620-0720 Noncompliance noted failure to comply w/procurement requirements.control nonconformance repts & to follow procedure for hanger insp MAXWELL.G F. PREVATTE.R L. Region 2. Office of Director BENIS.P R. Division of Project & Revident Programs 83/08/02 7pp 20626 255 24X Fiche 50-400.83/09/13.8310040595
- 8310280176 Responds to FDIA request re const flaws & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A Review of addl documentation continuing FELTON. J M Division of Rules and Records 83/09/23 VADEN. T. News & Observer 3pp 20963 288 24X Fiche 50-400.83/09/23. B310280176
- --B3j0280193 Documents 9 Zacher 790212 request for current status of remand hearing & NRC actions we recommendations in Ofc of Inspector & Auditor rept Recommendations will be adopted FOSTER.W H Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 1p 80963 291 24X Fiche 50-400.03/09/23, 8310280174
- --9310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to GA problems listed in subj inspects FOSTER.W H Office of Inspector & Auditor 78/10/10. Office of Inspector & Auditor 1p 20763 326 24X Fiche 50-400.83/07/23. 8310280176
- 830-8300340 IE Info Notice 83-61, "Alleged Use of Btand-Ins for Welder Qualification Tests " Svc list ancl JORDAN.E L Pivision of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Gonsolidated Edison Co
- 8308300342 IE info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- B30B300345 IE Info Notice 83-62, "Potential Failures of Westinghouse Type SA-1 Differential Reloys " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York Inc. 118pp 20778 001, PAX Fiche 50-000,83/09/26,830B300345
- 8308300349 IE Info Notice 83-64, "Lead Shiglding Attached to Bafety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN/E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716-324 24X Fiche. 50-000, 83/09/29, 8308300349
- 8310250628 Forwards IE Insp Repts 50-400/83-28 & 50-401/83-28 on 830820-0920 No noncompliance noted VERRELLI,D N Division of Project & Resident Programs 83/10/05 UTLEY,E E Carolina Power & Light Co 2pp. 20900 158 24X Fiche 50-400,83/10/05,8310250628
- --B310250632 IE Insp Repts 50-400/83-28 & 50-401/83-28 on 830820-0920 No mancompliance noted Major areas inspected concrete, storage, welding & steam generator mods MAXMELL, 0 F. P. PREVATTE, R. L. BEMIS, P. R. Region 2, Office of Pirector 83/10/05 5pp 20900 160 24X Fiche 50-400,83/10/05,8310250628
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Svt list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of No. York, Inc. 76pp 20827 213, 24X Fiche 50-000.83/10/07.8308300378

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 930103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Oases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp. 20827 129 24% Fiche 50-000,83/10/11,8308300761.
- 8310250208 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-400/83-16
 LEWIG, R C Division of Project & Resident Programs 83/10/13
 UTLEY, E E Caroline Power & Light Co 1p 20893 323 24X
 Fichs 50-400,83/10/13,8310250208
- --9310250211 Responds to NRC 830517 ltr re violations noted in IE Insp Rept 50-400/83-16 Corrective actions surveillance teams, consisting of GC welding inspector & discipline engineer, will survey cable tray supports & identify problem areas. PARBONS: R M Carolina Power & Light Co 83/09/23 0'REILLY, J P Region 2, Office of Director 3pp 20873 324 24X Fiche 50-400,83/10/13,8310250208
- 8310210136 Forwards add1 info re fire protection, including response to Safety Review Guestion 280 i.ravised safe shutdown analysis w/exemptions & mods.info requested in 830926-27 meetings w/ MRC & response to Enforcement Action 83-41 MCDUFFIE.M A Carolina Fower & Light Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director. 475pp 20834 15: 24% Fiche 50-400,83/10/14,8310210136
- 8310R30571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions, described in IE Info Notices 83-07 k 83-01 k IE Bulletins 83-06 k 83-07. Use of addlines & testing during receipt insps investigated MCDUFFIE,M A Carolina Power & Light Co 83/10/21. DEYCUNO,R.C. Director's Office, Office of Inspection and Enforcement 1p. 20900 347 R4X Fiche 50-000,83/10/21.8310250571
- R Periodic operating reports & related correspondence
- 8310250450 "Beismic Monitoring Program Quarterly Data Rept. Jul-Sept 1983 " M/831019 ltr ZIMMERMAN,S R Carolina Power & Light Co 83/09/30. DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp. 20897-158 24X Fiche-50-400,83/09/30.8310250450
- S Reportable occurrences, LERs & related correspondence
- 8310030524 Final deficency rept, Item 105 re auxiliary relay cabinets supplied by Sys Control Corp Vendor supplied revised drawings w/critical welds identified & has completed seismic analysis to determine structural integrity PARSONS: R M Carolina Fower & Light Co. 83/09/21 D'REILLY, J P. Region R. Office of Director 4ppp 20601 186 24X Fiche 50-400,83/09/21,8310030526
- 8310070163 Part 21 rept re potential defects in molded case of 100amp frame.multi-pole E & HE series circuit breakers initially reported on 830902 ERHARDT.J V Qould, Inc 83/09/26 MURLEY.T E Region 1. Office of Director 10ep 20659 095 24X Fiche 50-000,83/09/26. 8310070163
- 8310060036 Third interim Deficiency Rept 77 re shop welding defects in seismic Class I cable tray.conduit & HVAC hangers. Initially reported on 820802 Final rept expected by 840301. Also reportable per IOCFR21 PARSONBJR M. Carolina Power & Light Co. 83/07/29 O'REILLY, J P Region 2, Office of Director. 4pp 20647.087. 24X Fiche 50-400.83/09/29.8310060036
- 8310060336 Interim deficiency rept, Item 143 re weld deficiencies in sections of ducts CC-1 & CC-2 & transformers 101, iD2, iE1 & iE2 from Gould & Brown-Boveri Util awaiting vendor response, Also reportable per Part 21.
 PARSONE, R M. Carolina Power & Light Cn. 83/09/29 D'REILLY, J, P Region 2, Office of Director. 1p 20646, 092 24% Fiche 30-400, 83/09/29, 83/0060336

- 8310120246 Second interim deficiency rept. Item 96 ra seismic pipe hangers previously accepted by GC inspector & Item 72 re undersize skewed tee fillet welds on seismic pipe hangers Initially reported on 820813 & 1105.respectively PARSONS.R M Carolina Fourr & Light Co 83/10/03 O'REILLY, J P Region 2. OPfice of Director 5pp 20692 108 24X Fiche 50~400.83/10/03.8310120246
- 8310120367 Second interim deficiency rept. Items 95 & 72 & Part 21 rept re shop welding deficiencies in seismic 1 pipe hangers supplied by Bergen-Paterson Initially reported on 820813 & 1105 All active hangers corrected PARSONS, R M Carolina Power & Light Co 83/10/03 D'REILLY, J P Region 3, Opfice of Director 5pp 20499 295 24X Fiche 50~400,83/10/03,8310120367
- 8310190171 Second interim deficiency rept. Item 103 re main control board supplied by Westinghouse Initially reported on 821014 Deficient welding identified & repaired by vendor New scheduled completion date is 831230 Final rept by 840131 PARSONS.R M Carolina Power & Light Co 83/10/12 O'REJLLY. J. P. Region 2, Office of Director App 20821 076 24X Fiche 50-400,83/10/12.8310190171
- 8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Bite (Engine Serial 74039740 DSR 48) Instruction for cable changeout due in Nov. BOYER.R.E. Transamerica Delaval, Inc. 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20924 108 24X Fiche 50-000.83/10/20.8310270206
- DOCKET 30-401 SHEARON HARRIS NUCLEAR POHER PLANT. UNIT 2

 A Application/construction stage documents & correspondence
- 8310280174 FOIA request for all internal nonpublic documentation re const flaws & improper conduct by inspectors, util contractors or subcontractors MCINNIB.D. News & Observer 83/07/17 FELTON.J Division of Rule and Records 1p 20763 287 24X Fiche 50-400.83/07/19.8310280174
- 8310030161 Advises that organizational changes for GA program & changes to FBARs & mgt capability rept will be forwarded when completed UTLEY.E E Carolina Power & Light Co. 83/09/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p. 20590-028-24X Fiche 50-000.83/09/13.8310030161
- 83i0040354 Bummarizes 830831 meeting w/util re plans for restructuring corporate organization
 O'REILLY, J.P. Region 2, Office of Director 83/09/22 UTLEY, E E Carolina Power & Light Co 2pp 20620 331 24X
 Fiche 50-000,83/09/22,8310040354
- 8310280176 Responds to FQIA request for internal nonpublic documentation re const flaws & improper conduct of NRC imprectors & util contractors or subcontractors Forwards documents listed in App A FELTON, J M Division of Rules and Records 83/09/23 VADEN, T News & Observer 3pp 20963 288 24X Fiche 50-400.83/09/23.83/09280176
- --8310280197 Forwards draft Ofc of Inspector & Auditor 761109 rept on inquiry into alleged omission of line inspector views from CP hearing, for perusal W/o encl HURRAY, J P Deputy Executive Legal Director 78/12/18 CUMNINGS, J J Office of Inspector & Auditor 3pp 20963. 292 24X Fiche 50-400, 83/09/23, 8310280176.
- --8310280202 Documents telcon w/FC Cantrell ra insp file in preparation for testimony instructions not received to review file Cantrell relied solely on personal notes & records to prepare testimony FOSTER.W H Office of Inspector & Auditor 78/11/01 Office of Inspector & Auditor 78/11/01 Office of Raio28017A 831028017A
- --8310280207 Advises that ASLAB Chairman, AS Rosenthal will decline interview, claiming purposelessness FOSTER, W.H. Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 1p 20963 296 24X Fiche 50-400, 83/09/23, 8310280176
- --8310280211 Advises that IE Manual Chapter 94010-B only written policy for preparing testimony for licensing hearings, per 781025 telcon w/RC Paulus FOSTER, W. H. Office of Inspector & Auditor 78/10/26 Office of Inspector & Auditor 38/10/26, 211020174.

- --8310280214 Forwards AS Rosenthal 781024 memo to DG Abston, for perusal ABSTON.O G Office of Inspector & Auditor 78/10/25 HENDRIE.J M Commissioners Ip 20963 298 24X Fiche 50-400,83/09/23,8310280176
- --8310280218 Advises that ASLAN members not willing to be interviewed dua to possible future involvement in case ROBENTHAL, A S Atomic Safety and Licensing Appeal Panel 78/10/24 ABSTON.O G Office of Inspector & Auditor ip 20963 297 24X Fiche 50-400.83/09/23.8310280176
- --8310280222 Requests interview w/ASLAB members to discuss impact of omission of line inspector views from written & gral testimony ABSTON:0 © Office of Inspector & Auditor 78/10/24 ROSENTHAL, A B Atomic Safety and Licensing Appeal Panel Ip 20963 300 24X Fithe 50-400.63/09/23.8310/280176
- --8310280225 Forwards info re Ofc of Inspector & Auditor interview of ASLAB (ref Yore 781019 memo to Commissioners) FRYE, J H Atomic Safety and Licensing Board Panel 78/10/20 ROSENTHAL, A KELLEY, J L . AUBTON, D G NRC No Detailed Affiliation Oiven 1p 20963 301 24% Fiche 50-400, 83/09/23, 8310280174
- --8310280236 Forwards DH Gamble 781019 memo, for interest ABSTON, D G Office of Inspector & Auditor 78/10/PO HENDRIE, J M Commissioners 1p 20763 312 24X Fiche 50-400, 83/09/23, 8310280176
- --8310280238 Summarizes A Rosenthal 781019 telcon opposing potential interview w/ASLAB members citing unpleasantness of ASLB interview Dfc of Inspector & Auditor must assure different line of questioning before interview is granted GAMBLE, D H Office of Inspector & Auditor 78/10/19 Office of Inspector & Auditor & Auditor & Auditor & Auditor & Auditor & Auditor & Audi
- --8310280242 Forwards documentation of 781017 conversation w/JM Varele, former AEC employee re V Brownlee Conversation connected w/ current investigation
 DAVIS, J O Director's Office, Office of Inspection and Enforcement 78/10/19 ABSTON, D G Office of Inspector & Auditor ip 20963 315 PAX Fichs 50-400, 83/09/23, 8310280176
- --8310280244 Documents 781017 conversation w/J Varela, former Region II employee Brownlee directed Varela to change info in insprept, causing dispute DAVIS. J 0 Director's Office, Office of Inspection and Enforcement 78/10/19 Director's Office, Office of Inspection and Enforcement 1p 20963 316 24X Fiche 50-400.83/09/23, 8310280176
- --8310280246 Documents 781017 conversation w/C Barth (DELD) re testimony forwarded to ASLD before 771004 hearing ASLB should be required to read testimony before hearing FOSTER, W H Office of Inspector & Auditor 78/10/18 Defice of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 78/10/18 Auditor 1p 20963 317 24X Fiche 50-400,83/09/23,8310280176
- --8310280248 Advises of Ofc of Inspector & Auditor inability to procure useful info during interview w/ABLB due to ASLB unresponsiveness
 ABSTON, O O Office of Inspector & Auditor 78/10/17
 HENDRIE, J M , GILINSKY, V , KENNEDY, R T Commissioners 29p
 20963 324 24X Fiche 50-400,83/09/23,8310280176
- --8310280250 Advises that HA Wilbur perusal of Dance testimony discious no ref to GA problems listed in subj insprepts FOSTER, W H Office of Inspector & Auditor 78/10/10 Dffice of Inspector & Auditor 19 20763 326 24% Fiche 50-400, G3/09/23, 8310280176
- --8310280284 Forwards case assignments for ASLB members 00 Bright, JV Leeds & 1H Amith.per request FITTI.C J Atomic Safety and Licensing Board Panel 78/10/06 GAMBLE.D H Office of Inspector & Auditor App 20963 327 24% Fiche 50-400, 63/09/23, 8310280176
- --8310280256 Forwards Acting General Counsel opinion indicating no ex parts problem w/Osc of inspector & Auditor interview of ASLB members
 ASBTON.O G Office of Inspector & Auditor 78/10/03 YORE, J.R., ROSENTHAL.A S Atomic Safety and Licensing Board Panel 1p 20963 333 24X Fiche 50-400,83/09/23,8310280176
- --8310280259 Informs of 781003 conversation w/I Smith of ASLB re Ofc of Inspector & Auditor interview w/ASLB members, to fulfill Commission order Interview will probably not be granted due to ex parte rule FOSTER, W H Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 19 20963 035 04X Fiche 50-400, 83/09/23, 8310280176

- 2310280263 Summarizes continued attempts to gain ASLB interview the mugh 780927 conversation w/VV Leeds Leeds will not cooperate, titing expants rule FOSTER.H H Office of Inspector & Auditor 78/09/27 Office of Inspector & Auditor 78/09/27 Office of Inspector & Auditor 2pp 20963-336 24X Fiche 50-400, B3/09/23, 8310280176
- -8310280265 Informs of alleged improprieties re deficiency discippancy repts & corresponding logbook entries VORSE.J Y Office of Investigation 83/03/04 ALBERSON.C Y NRC No Detailed Affiliation Given 1p 20963 338 24X Fiche 50-400.83/09/23.8310280176
- --B3:0280270 Discusses alleged improprieties re deficiency discrepancy
- repts & corresponding logbook entrier
 SURCH.R H Defice of Investigation 83/03/03 Office of
 Investigation Ip 20963 339 24% Fiche 50-400,83/09/23, 8310280176
- --B310280299 Advises that no new info revealed after inquiry of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries VORSE, J Y Uffice of Investigation 83/05/06 TODD, G NRC No Detailed Affiliation Given ip 20963 340 24X Fiche 50 400,83/09/23,8310280176
- --03|0280303 Advises that inquiry into alleged improprieties re deficiency discregancy repts & corresponding logbook entries closed Util cited for violation SURCH, R. H. Office of Investigation 83/05/04 Office of Investigation 1p 20763-341 24X Fiche 50-400,83/09/23, colorabor.
 - 83102D017A
- 500070120 Forwards response to requests for add1 info, including response to Rev I to "Basis for Auxiliary Feedwater Sys Flow Requirements," in support of safety review Response includes info re main steam turbine valve testing issue MCOUFFIE.H A Carolina Power & Light Co 83/09/30 DENTON.H R Office of Nuclear Reactor Regulation, Director 41pp 20458 341 24x Fiche 50-400,83/09/30,8310070120
- 83:03:10:172 Forwards NRC 830921 ltm to util advising of acceptance of fesign, analyses, maths & const aspects of containment vescel wild deficiencies, in response to Resolution 1443-83 NDVAK,T M Assistant Director for Licensing 83/10/18 EULERI, & Petry, DH 3pp 20965 288 24X Fiche 50-400, 83/10/18, 8310310172 43-83 -83/10/18 EULERT.G A
- € HRC Safety Evaluation Report (SER), supple & correspondence
- B]]0130240 Forwards addl info in response to draft SER Open Item 354. including Mechanical Engineering Branch questions in B30819 6 25 Ites
- 6 25 ltrs KCCUFFIE.H A. Carolina Power & Light Co. B3/09/19 DENTON.H R Office of Nuclear Reactor Regulation. Director 6pp. 20722-236 24x Fiche 50-400.B3/09/19.B310130240
- --8310130248 GC Procedure 120, "Hydrostatic Testing (Critical Svc) "
 a Gaulds Pumps, Inc 80/07/01 3pp 20722 242 24X
 Fishe 50-400/83/09/19,8310130240
- --8310130254 Rev 3 to QA Instruction GAL-212. "Training & Qualification of QA Personnel"
 - of QA Personnel "

 Could's Pumps, Inc. 80/06/18 | Lipp. 20722 245 24X
 Fiche 50-400, 83/09/19, 8310130240
- 8010130261 "Seismic Qualification Envelope Limitorque Valve Actuators DRAB.J B . DENKOWSKI.W J . FORMIGA.C D Limitorque Corp H0037 80/01/11 24pp 20722 256 24X Fiche 50-400.83/09/19.8310130240
- 8310130267 Rev 1 to "Rept of Test on Spismic Vibration Testing of One Limitarque SMB-000/HOBC Actuator for Limitorque Corp " ESEDSITO, B . CASAUBON.M . IULF.M L. Actor Environ Testing Corp 14331-2 ROL 79/03/13 16pp 20722 280 24X Fishe 50-400.83/09/19.8310130240
- --83i0130271 Rev 1 to "Rept of Test on Beismic Vibration Testing One Limitarque SMB-000/HOBC Actuator W/Seismic Adaptor for Limitarque Corp" ESPOSITO, B., CABAUBON, M., TOLF, M.L. Acton Environ Testing Corp [433]-3 ROI 79/03/13 12pp 20722 296 24X fiche 50-400,83/09/19,8310130240
- --8310130273 "Selamic Test SMB-000/HOBC " YOUNG.P T Limitorque Corp 80045 83/09/19 5pp 20/22 308 24% Fiche 50-400.83/09/19.8310130240
- --83|013|0277 Rev 1 to "Rept of Test on Seismic Vibration Testing of Limitorque SMB-1/M3BC Actuators for Limitorque Corp " ESPOSITO, B GILFOY, R TOLF, M L Acton Environ Testing Corp |4801-1 R01 79/06/11 41pp 2072, 314 24X |Fiche 50-400,83/09/19,831013|0240

- --8310130280 "Rept of Fragility Test on SM8-1-25/H4BC W/8td Cast Adapter for Limitorque Corp "

 * Apro Nav Laboratories, Inc 5-6167-5 75/12/17 36pp A Apro Nav Laboratories, Inc 5-4167-5 75/12/17 20722 355 24X Fiche 50-400.83/09/19.8310130240
- --8310130282 Rev O to Engineering Spec JSN-T35, "Seat Testing & Disc Hydrostatic Testing 5 Minute Duration" # Jamesbury Corp 78/01/24 lipp 20723 029 24X Fishe 50-400.83/09/19.8310130240
- --B310130285 Rev O to Procedure 4-106. "Cold Bending of Carbon Steel & Ferritic Alloy " reitic Alloy ... Southwest Fabricating & Helding Co (subs of 1U International p) 73/05/04 3pp 20723 040 24% Fiche 50~400.83/09/19. Corp) 73/05/04 8310130240
- --8310130287 Rev O to Procedure 4-107, "Cold Bending of Austenitic Stainless Steel Piping "

 * Southwest Fabricating & Welding Co (subs of 1U International Corp.) 73/05/04 3pp 20723 043 24X Fiche 50-400,83/09/19,8310130240 Carp) 7: 8310130240
- --8310130289 Rev O to Procedure 4-108, "Hot Bending of Carbon Steel & Ferritic Alloys "

 # Southwest Fabricating & Welding Co (subs of IU International Corp) 73/05/04 3pp 20723 046 24X Fiche 50-400,83/09/19,8310130240 B310130240
- --8310130290 Rev O to Procedure 4-109, "Hot Bending of Austenitic Stainless Steel Piping" * Southwest Fabricating & Helding Co (10bs. of 1U International Corp.) 73/05/04 lipp 20723 051 24% Fiche 50-400,83/09/19,
- --8310130291 Procedure MNE-65, "Pipp Like Sixing Guide "

 * Ebasco Services, Inc. (subs. of Enserch Corp.) 70/06/20. 7pp
 20723 062 24X Fiche 50-400,83/09/19,8310130240
- --8310130293 Rev 8 to Site Spec 030, "Field Fabrication & Erection of Power Pipe "

 * Carolina Power & Light Co 83/03/27 23pp 20723 069 24x
 Ficha 50-400,83/09/19,8310130240
- --8310130294 Engineering Procedure 3 2, "Design Change Control "

 * Caroline Power & Light Co 83/08/19 52pp 20723 092 24X
 Fiche 50-400/83/09/19,8310130240
- 8310170124 Summary of 830825 meeting w/util & Ebasco in Bethesda,MD re Neteorological & Effluents Treatment Sys Branch draft SER open items BUCKLEY.B C , HOLONICH, J Licensing Branch 3 83/09/29 Licensing Branch 3 8pp 20813 059 24% Fiche 50-400,83/09/29, 8310170124
- B310110117 Forwards amended response to request for add1 is SER Open Item 38 concerning technical basis for QDC-51 compliance Responses to other requests will be provided shortly MCDUFFIE, M.A. Carolina Power & Light Co. 83/09/30 DE addl info re draft DENTON: H R Office of Nuclear Reactor Regulation, Director 150pp 24X Ficha 50-400,83/09/30.8310110119
- 8310120180 Forwards response to request for add1 info re draft SER open items on reevaluation of PMP.plant area water accumulation & adequacy of electric distribution sys voltages MCDUFFIE.M A Carolina Power & Light Co 83/10/05 DENTON.H R. Office of Nuclear Reactor Regulation. Director 8pp 20695 301 24X Fiche 50-400,83/10/05.8310120180
- 8310140126 Forwards response to MRC Question 210 59 re piping spec.
 10ading combinations & stress limits completing response to
 32 Mechanical Engineering Branch questions in 800819 & 25
 1trs for SER Open Item 354
 HCQUETIE.M A Carplina Power & Light Co 83/10/10 DENTON, H R
 Diffice of Nuclear Reactor Regulation, Director 21pp 20765 045
 24% Fiche 50-400.83/10/10.8310140126
- 8310180474 Forwards responses to draft SER Open Items 355-383, discussed at 830921 meeting w/Ausslany Sys Brench in Bethesda MD MCDUFFIE, M A Carolina Power & Light Co 83710711 DENTON, H R Office of Nuclear Resctor Regulation, Director 37pp 2080[351 24X Fiche 50-400.83710711.8310180474
- 8310180311 Forwards add) info re draft SER open items, in response to Mechanical Engineering Power Sys & Reactor Sys Branch concerns Westinghouse Owners Group Jul 1977 rept & Sept 1977 suppl will be used in derivation of setpoints HCDUFFIE.M A Carolina Power & Light Co 83/10/12 DENTON, H R Office of Nuclear Reactor Regulation. Director 27pp 20803 076 24X Fiche 50-400,83/10/12.8310180311

- 8310210024 Forwards responses to requests for add1 info re draft SER
- open items
 MCDUFFIE.M A Carolina Power & Light Co 83/10/14 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 55pp 20856 017
 24x Fiche 50-400 83/10/14.8310210024
- B31023063B Forwards supplemental info in response to Siting Analysis Branch concerns re SER Item 7 Seaboard Sys Railroad provided assistance in preparation of supplemental info Encl withheld (ref LOCFR2 790) MCDLAFFELM A Carolina Power & Light Co 83/10/14 DENTON, 4 R Office of Nuclear Reactor Regulation. Director 2pp 20899 314 24x Fiche 50-400,83/10/14.8310250638
- 8310240259 Forwards proprietary & nonproprietary versions of "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items," in response to Matls Engineering Branch draft SER open items Proprietary table withheld (ref 100FR2 790) MCDUFFIE.M A Carolina Power & Light Co 83/10/14 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 20909 209 24X Fiche 30-400.83/10/14.8310260259
- --8310260267 Application for withholding proprietary "Table of Control Rod Drive Mechanism (CRDM) 400 Series Stainless Steel Items: "per 10CFR2 790 W/affidavit HIEBEMANN R A Hestinghouse Electric Corp 83/j0/11 LIAW. B D Materials Engineering Branch 10pp 20909 211 24X Fiche 50-400-83/10/14.8310260259
- --8310260283 Nonproprietary "Table of Control Rod Drive Mechanism (CRDM)
 400 Series Stainless Steel Items "
 Westinghouse Electric Corp 83/10/14 ip 20909 221 24X
 Fiche 50-400,83/10/14,8310260259
- 8310260147 Forwards responses to requests for add1 info re draft SER Open Items 63 & 67 Responses verify containment pressure & justify operation of normal containment purge MCDUFFIE.M A Carolina Power & Light Co 83/10/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 4pp 20912 228 24X Fiche 50-400.83/10/20.8310260147
- 8310260152 Forwards response to NRC request for addl info re emergency diesel generator load sequence reliability (draft SER Open Item 310) Applicant in process of performing PRA on sequencer HCOUFFIE.H A Caroline Power & Light Co 83/10/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 20912 232 24% Fiche 30-400.83/10/20.8310260152
- B310260134 Forwards response to request for add1 info re draft SER Open Item 77 Shunt trip attachment mod will be implemented, per Ganeric Ltr 83-28 HCDUFFIE.M A Carolina Power & Light Co B3/10/21 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 20912 226 24X Fiche 30-400.83/10/21.8310260134
- 8310280014 Forwards nonproprietary & proprietary responses to request for add1 info re-criticality analyses for spent fuel racks. Draft BER Open Item 360 completed Proprietary response withheld (ref 10CFR2 790) MCDUFFIE.H A Carolina Power & Light Co 83/10/21 DENTON.H Office of Nuclear Reactor Regulation. Director App 20929 02 24X Fiche 50-400.83/10/21.8310280014
- F Hecurity, medical, emergency & fire protection plans
- B310170070 Bummary of 830825 meeting w/util & Ebasco re fire protection program & safe shutdown analysis
 HOMOLECH, J. Licensing Branch 1 BUCKLEY, B.C. Licensing Branch 3
 83/09/30 Licensing Branch 1 3pp 20798 019 24X
 Fiche 50-400,83/09/30,8310170070
- ~310180185 Summary of 830926 & 27 meetings w/util & Ebasco re fire protection open items.drawing review & Auxiliary Sys Branch iscussion of safe shutdown analysis XKLEY.B C Licensing Branch 3 HOLONICH, J J Licensing Branch 1 33/09/30 Licensing Branch 2 9pp 20827 014 24X jche 50-400,83/09/30.8310180185
 - 1120266 Formards Rev 1 to emergency plan Evacuation time study heduled for completion by 821221 LEY.E E Carolina Power & Light Co 83/10/04 DENTON.H R fice of Nuclear Reactor Regulation. Director 2pp 20688 00. X Fiche 50-400.83/10/04.8310120266
 - 10120268 Rev 1 to emergency plan e Carolina Power & Light Co 83/09/30 63pp 20688 00: 24x Fiche 50-400.83/10/04.8310120266

- 8310210136 Forwards addl info rv fire protection, including response to Safety Review Question 280 Lirevised safe shotdown analysis, w/exemptions & mods, info requested in 830926-27 meetings w/ NRC & response to Enforcement Action 83-41 MCDUFFIEM A Carolina Power & Light to 83/10/14 DENTINIA R Office of Nuclear Reactor Regulation, Director 475pp 20896 151 24X Fithe 50-400,83/10/14,8310210136
- G Adjudicatory correspondence
- 8310030441 Response to general interrogatories & interrogatories on Contention SF(1) Related correspondence CARROW, H. Carolina Power & Light Co. 87/09/23 EDDLLMAN, W. Eddleman, W. 14pp. 20602-069 24X Fiche 50-400, 83/09/23, 8310030441
- --8310030478 Response to request for production of documents on Contention BF(1) Certificate of Svc evel CARROW.H Carolina Power & Light Co 83/09/23 EDDLEMAN.W Eddleman.W 4pp 20602 085 24X Fiche 50-400.83/09/23.
- 8310030367 Response opposing will motion for summary disposition of Eddleman Contention 80 re mixing & disportion models. Statement of facts as to which there are issues to be heard EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensing Board Panel App 20993 009 24% Fiche 50-400, 83/09/27, 84100 10 46 F
- ~-B310030369 Response opposing util motion for summary disposition of Eddleman Contention 75 on clams Statement of facts as to which there are issues to be heard entil EDDLEMAN, W. Eddleman, W. B3/09/27 Atomic Gafety and Licetakon Board Panel. Bpp. 20593-015 24X Fiche 50-400, B3/09/.*7.
- --8310030372 Response opposing util motion for summary disposition of Eddleman Contention 83/84 re carcinoponic discharges Statement of facts as to which there are issues to be heard EDDLEMAN, W Eddleman, W 83/09/27 Atomic Safety and Licensium Board Panel Opp 20593 024 24X Fiche 50-400, 83/09/27, 8310010367
- ~-8310030375 Response to util motion for summary disposition of Eddlerin Contention 64F EDDLEMAN, W. Eddleman, W. 83/09/27 Atumic Safety and Licensing Board Panel 2pp 20593 030 24X Fiche 50-400 83/09/27. 8310030367
- ~-8310030377 Motion for license condition on spent fuel shortage if Contention 64P withdrawn EDDLEMAN, W. Eddleman, W. 83/09/27 Atomic Safety and Licensing Board Panel 5pp 20593 032 24X Fiche 50-400, 83/09/27, 8310030367
- --8310030380 Response partly opposing util proposed schedule rev Certificate of Svc encl EDDLEMAN.W Eddleman. W 83/09/27 Atomic Safety and Licenting Board Panel 2pp 20593 037 24X Fiche 50-400:83/09/27. 8310030367
- 8310040523 Notifies that util counsel & author agreed to negotiate next uk on util responses to Eddleman Interrogatories 15AA & BFI Notice tolls time for filing motion to compel EDDLEMAN, W Eddleman, W 83/09/28 KFLLEY, J Atomic Safety and Licensing Board Panel ip 20624 234 DAX Fiche 50-400.83/09/28, 8310040523
- 8310040518 Response re 10CFR2 758 petition of 830630 on need for power & alternatives Certificate of Svc and EpoLEMAN W Eddleman W 63/09/30 Atomic Safety and Licensing Board Panel 89pp 20623 001 24% Fiche 30-400, 83/09/30. 8310040518
- 8310040538 Forwards Page 10.inadvertently omitted from util 830%** JIO0003B Forwards Page 10. inadvertently omitted from util BJU''''
 reply to W Eddleman response to ASLB B30024 order
 O'MEILL.J H Shaw, Pittman, Potts & Trowbridge D'MEILL.J H
 Carolina Power & Light Co B3/09/30 KELLEY.J L . BRIGHT.G).
 CARPENTER.J H Atomic Safety and Licensing Board Panel 1p
 20023 297 24X Fiche 50-400, B3/09/30. B31004053B
- --8310040541 Page 10, inadvertently omitted from util 830929 reply to W Eddleman response to ASLB 830824 order Svc list encile Caroline Power & Light Co. 83709730 Atomic Sefety and Licensing Board Panel Spp. 20623 278 24X Fiche 50-400-83709730.8310040538

- 9316050565 Response supporting util 830912 mation to modify schedule on environ contentions issuance of FES by 831031 should be factored into schedular mods Certificate of Exc encl PARTH.C A Hearing Branch 1 83/10/03 Atomic Safety and Licensing Board Panel 3pp 20629 03/ 24X Fiche 50-400,83/10/03.8310030365
- 6310050188 Forwards motion for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 378 on health effects Related correspondence D'MEILL, J H Shaw, Pittman, Potts & Trowbridge O'MEILL, J H Carolina Power & Light Co 83/10/03 KELLEY, J L , BRIGHT, G O , CAPPERE, J H Atomic Safety and Licensing Board Panel 2pp 20649 001 24X Fiche 50-400.83/10/03.8310060188
- -- @310060193 Motion for summary disposition of Joint Intervenors Contention IJ & W Eddleman Contention 37B re health effects No genuine issue of matl fact exists & util entitled to Favorable decision Related correspondence AULICK, D D Carolina Power & Light Co AULICK, D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 62pp 20649 003 24X Fiche 50-400, 83/10/03, 8310040188
- --B310060203 Statement of matl facts as to which there is no genuine issue re Joint Intervenors Contention II & W Eddleman Contention 378 Related correspondence ALLECK,D D Carolina Power & Light Co AULICK,D D Shaw, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 13pp 20649 071 24X
 Fiche 50-400,03/10/03.831006018B
- -8310060212 Affidavit of JI Fabrikant re health effects estimates in DES Somatic & genetic hoalth effect estimates in DES are not underestimated Prof qualifications encl Related correspondence.

 FABRIKANT. J I Carolina Power & Light Co FABRIKANT. J I Lawrence Livermore Laboratory 83/10/01 120pp 20649 084 24X Fiche 50-400.83/10/03,8310060188
- -8310060222 Affidavit of QH Whipple supporting util motion for summary disposition of Joint Intervenors Contention II NRC models use concentrations, doses & health affects unaffected by incomplete mixing or dispersion Related correspondence 3-HIPPLE, Q H Carolina Power & Light Co 83/07/30 16pp 20449 209. 24X Fiche 90-400,83/10/03-8310060168
- -8310360238 Affidavit of JJ Mauro supporting util motion for summary disposition of Joint Intervenors Contention II & Eddleman Contention 378 DES determined max ratio of health affacts From plant operation Related correspondence MAURO, J J Carolina Power & Light Co MAURO, J J Fbasco Sprytess, Inc (subs of Enserch Corp) 83/10/03 18pp 20447 225 24X Fiche 50-400,83/10/03,8310060188
- ©100&0323 Notice of appearance in proceeding Certificate of Svc encl AULICK, D D Carolina Power & Light Co. AULICK, D D Shaw, Pittman, Potts & Troubridge 83/10/03 Spp 20446 227 24X Fight. 50-400, 83/10/03, 8310060323
- 83:01:01:50 Motion for summary disposition of Eddlemen Contention 29/30 them I compliance) No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence O'MEILL, J N Shaw, Pittean, Potts & Troubridge 83/10/05 Atomic Safety and Licensing Board Panel 50pp 20665 138 24% Fichs 50-400,83/10/05.93/10/050
- -9310110155 Statement of matl facts as to which there is no genuine issue me Eddleman Contention 29/30

 O'MEILL, J H Carolina Fower & Light Co O'MEILL, J H Shaw, Pittman, Potts & Trowbridge 83/10/05 Atomic Bafety and Licensing Board Panel 10pp 20665 186 24X

 Ficha 50-400, 83/10/05, 8310110150.
- -B310180407 Affidavit of JJ Mauro & G Martin in support of applicant action for summary disposition of W Eddleman Contention 29/30 MARTIN.G Carolina Pawer & Light Co. 83/10/03, 58pp 20645:196 24X Fichs 50-400.83/10/05.8310110150.
- -8310110409 Affidavit of RL Shearin in support of applicant motion for summary disposition of W Eddleman Contention 27/30 SHEARIN R L Carolina Power & Light Co. 83/09/30 Spp 20655 254 24% Fiche, 50-400, 83/10/05.8310110150
- -8310110412 Affidavit of TJ Grant in support of applicant motion for twamary disposition of W Eddleman Contention 29/30 Certificate of Svc encl GRANT.T J Carolina Power & Light Co 83/09/30 16pp 20665 262 24% Fiche 50-400,83/10/05,8310110150

- 8310110209 Memorandum & order ruling on discovery disputes Motions to compel & for protective order granted/denied as noted KELLEY, J. L. Atomic Safety and Licensing Board Panel 83/10/06 Eddleman. W. 16pp. 20665-073 24X Fiche 50-400.83/10/06, 8310110209.
- B31011021B Memorandum & order admitting some of W Eddleman late-filed contentions on detailed control room design review R Wilson 830921 & Conservation Council of North Carolina 830824 motions to withdraw contentions granted BRIGHT, 9 D . CARPENTER, J H . KELLEY, J L . Atomic Bafety and Licensing Board Panel 83/10/06 Conservation Council of North Carolina, 14pp 20665 042 24X Fiche 50-400,83/10/06,831011021B
- 8310120370 Response to interrogatories on Contentions 18AA & 8F1 Certificate of negotiations & Certificate of Svc encl EDDLEMAN.W Eddleman.W 83/10/06 Cerolina Power & Light Co 18pp 20699 254 24X Fiche 50-400.83/10/06.8310120370
- 8310140072 Revised Contention 161 re safety shutdown sys failure. Certificate of Svc encl EDDLEMAN.W Eddleman. W 83/10/11 Atomic Safety and Licensing Board Panel 2pp 20766 357 24X Fiche 50-400.83/10/11.8310140072
- B310140065 Erratum to ASLB B31006 memorandum & order ruling on W Eddleman proposed contentions re detailed control room design review & R Wilson & Conservation Council of North Carolina motions to withdraw contentions.

 KELLEY, J L Atomic Safety and Licensing Board Panel. B3/10/12 EDDLEMAN; W Eddleman, W WILBON, R Wilson, R 2pp. 2076B 007 24X Fiche 50-400, B3/10/12, B310140065
- 8310170543 Forwards corrected version of util motion for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 37B on health effects
 AULICK, D D Shaw, Pittman, Potts & Trowbridge AULICK, D D.
 Carolins Power & Light Co 83/10/12 KELLEY, J L. . BRIGHT, G. D ,
 CARPENTER, J H Atomic Safety and Licensing Board Panel lp
 20780 355 24X Fiche 50-400, 83/10/12, 8310170543
- --8310170608 Corrected copy of motion for summary disposition of Joint Intervenors Contention II & W Eddleman Contention 378 on health effects Errota shoet encl AULICK, D D Carolina Power & Light Co. AULICK, D D Shaw, Pittman, Potts & Troubridge 83/10/03 Atomic Safety and Licensing Board Panel 61pp 20780-356 24X Fichs 50-400,83/10/12,8310170543.
- --8310170620 Fourth set of interrogatories & request for production of documents O'NEILL.J H Carolina Power & Light Co. O'NEILL.J H Shaw, Pittman. Potts & Trowbridge 83/10/12 Joint Intervence-Shearon Harris 18pp 20781 055 24X Fiche 80-400,83/10/12,8310170943
- --8310170630 Reply apposing W Eddleman 830927 motion for license condition on spent fuel storage. ASLB lacks jurisdiction over issues of health & safety re spent fuel transportation. Certificate of Svc encl
 O'NEILL, J H Carolina Power & Light Co. D'NEILL, J H Bhaw. Pittman. Potts & Troubridge 83/10/12. Atomic Safety and Licensing Board Panel 10pp. 20781 070
 Fiche 50-400,83/10/12.8310170843.
- 8310170626 Response to 830831 interrogatories ne Contention 378 concerning health impacts from exposure to radioactive matls

 BRANAGANE F Rediological Assessment Branch. BARTH.C. Hearing Branch I 89/10/12 EDDLEHAN.W Eddleman.W 3pp 20782:113 24x Fichs 50-400.83/10/12.8310170626
- --8310170432 Response to 830831 second set of interrogatories. Statement of prof qualifications & Certificate of Svc encl SCHMENK.G. A. Radiological Assessment Branch BARTH.C. A Hearing Branch 1. 83/10/12 EDDLEMN.W Eddleman. W 54pp 20782:116 24X Fiche 50-400.83/10/12.8310170626
- B310250469 Response opposing W Eddlaman B30927 motion for license condition on spent fuel storage Motion premature & not in conformity w/Commission regulations Certificate of Svc ancl BARTH, C. A Hearing Branch 1 B3/10/17 Atomic Bafety and Licensing Board Panel App 20897 145 24X Fiche: 50-400, 83/10/17, 8310250469
- 8310250125 Followup response to Interrogetory 4 on Contention 8(F)(1), Listed document will be placed in FDR BARTH.C.A Hearing Branch 1 83/10/19, EDDLEMAN, W Eddleman, W. 1p. 20896 344 24% Fiche: 50-400, 83/10/19, 8310280125

- 8310240183 Third supplemental responses to W Eddleman 631004 general interrogatories & interrogatories on Contentions 29 & 378 Certificate of Svc encl G1895.J J Carolina Power & Light Co G1885.J J Shaw. Pittman. Potts & Troubridge 83/10/20 Eddleman. W 11pp 20878 104 24% Fiche 30-400.83/10/20.8310240183
- 8310250167 Forwards Pages 26-32 of ALAB-693 re security plan contentions, per 831005 teleon request Pages withheld (ref 100FR73 21)
 BARTMAC A Hearing Branch 1 83/10/20 RUNKLE, J North Carolina, State of 1p 20874 061 24X Fiche 50-400, 63/10/20, 8310250167
- 8310250037 General interrogatories & interrogatories on Contentions 8F1.8F2 & 15AA (sixth set) Related correspondence EDBLEMAN, W Eddleman, W 83/10/21 Carolina Power & Light Co, 18pp 20894 115 24X Fiche 50-400.83/10/21,8310250037
- 8310250040 Interrogatories re Contentions 8Ft.8F2 & 15AA (second round, third set) Related correspondence EDDLEMAN, W Eddleman, W 83/10/21 Office of the Executive Legal Director opp 20896 164 24X Fiche 50-400,83/10/21,8310250040
- 8310250086 Response to applicant interrogatories on Eddleman Contention 65 (sixth set) Certificate of Syc encl Related correspondence EDDLEMAN, W Eddleman, W 83/10/21 Carolina Power & Light Co 8pp 20894 143 24X Fiche 30-400,83/10/21,8310250084
- 8310260202 Interrogatories & request for production of documents on Eddleman Contention 8F(1) Related correspondence CARROW.H Consumers Power Co 83/10/21 EDDLEMAN.W Eddleman.W App 20912 237 24X Fiche 50-400,83/10/21.8310260202
- --8310260209 Second set of interrogatories & request for production of documents re Eddleman Contention 19AA Certificate of Svc encl Related correspondence CARRON.H Consumers Power Co 83/10/21 EDDLEMAN.W Eddleman.H 9pp 20
- 8310270319 Memorandum & order modifying achedule on environ contentions KELLEY, J. L. Atomic Safety and Licensing Board Panel 83/10/25 3pp 20923 183 24% Fiche 50-400,83/10/25,8310270319
- 831028005t Response apposing W Eddleman B31010 proposed rev to Contention 161 re safety shutdown sys failure Rev fails to specify defects in original circuit breaker design Centificate of Svc encl

 D'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Troubridge 83/10/25 Atomic Bafety and Licensing Board Panel 14pp 20934 333 24x Fiche 50-400, 83/10/25, 8310280051.
- 8310280164 Fifth set of interrogatories on Joint Contention VJ re radiation detection & monitoring & request for production of documents ANDERSON, P. H. Carolina Power & Light Co. ANDERSON, P. H. Shaw, Pittman, Potts & Troubridge 83/10/25 Joint Intervenors-Shearon Harris 16pp. 20927 226 24X Fiche 50-400, 83/10/25, 8310280164
- 8310310146 Informs that DR Lewis, formerly ASLB participant in OL proceeding, began working for author on 831024 DR Lewis will not participate in DL proceeding BAXTER. T.A. Shaw, Pittman, Potts & Trombridge BAXTER. T.A. Garolina Power & Light Co. 83/10/26. Commissioners App 20759, 056 24X Fiche 50-400, 83/10/26, 8310310146
- Q. Inspection reports, IE Bulletins & correspondence
- 8310040575 Ack receipt of 830831 & 0902 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-22 LEWIS.R C Division of Project & Resident Programs 83/09/13, UTLEY.E E Caroline Fower & Light Co. Ip. 20626 240 24X Fichs.50-400.83/09/13,8310040595
- --B310040600 Responds to NRC B30803 ltr re violations noted in IE Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions all shop welded joints requiring inservice insp will be identified & reworked to meet surface finish requirements PARSONS.R.M. Carolina Power & Light Co B3/09/02 O'REJLLY.J.P Region 2, Office of Director Spp 20626 241 24X Ficha: 50-400,83/09/13.8310040595

- --8310040603 Responds to NRC 830803 ltr re violations noted in IF Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions approx 150 deficiency & disposition repts reviewed by superintendent & GC for closure by GC/GA specialist PARSONS,R M Carolina Power & Light Co 83/07/02 D'REILLY, JP Region 2. Office of Director 5pp 20626 244 24X Fiche 50-400,83/09/13,8310040595
- --8310040606 Responds to NRC 830803 ltr re violations noted in IC Insp Repts 50-400/83-22 & 50-401/83-22 Corrective actions Phase I insps of hanger SA-H-123 declared preliminary & Phase II insps considered insp of record PARSONS, R M Carolina Power & Light Co 83/08/31 O'REILLY, J P Region 2, Office of Director 2pp 20626 249 24X Fiche 50-400,83/09/13,8310040595
- --8310040408 Forwards IE Insp Repts 50-440/83-22 & 50-401/83-22 on 830620-0720 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/08/03 UTLEY.E E Carolina Power & Light Co 2pp 20626 251 24X Fithe 50-400.83/07/13,8310040595
- --8310040613 IE Insp Repts 50-400/83-22 & 50-401/83-22 on 830620-6720 Noncompliance noted failure to comply w/procurement requirements.control nonconformance repts & to failow procedure for hanger insp MAXHELL, & F. PREVATTE.R L. Region 2. Office of Director BEMIS,P R. Division of Project & Resident Programs 83/08/02 7pp 20626 255 24x Fiche 50-400,83/09/13,8310040595
- 8310280176 Responds to FDIA request re const flaws & improper conduct of NRC inspectors & util contractors or subcontractors Forwards documents listed in App A Review of addl documentation continuing FELTON, J M Division of Rules and Records 83/09/23 VADEN, T News & Observer 3pp 20963 288 24X Fiche 50-400.83/09/23.8310280176
- ---8310280193 Documents 9 Jacker 790212 request for current status of remand hearing & NRC actions re recommendations in Dfc of Inspector & Auditor rept Recommendations will be adopted POSTER.W H Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 1p 20963 291 24X Fiche 50-400,03/09/23,8310280174
- --8310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to GA problems listed in subj inspirepts
 FUSTER.W H Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 19 20763 326 24% Fishe 50-400, 83/09/23. 8310280174
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24x Fiche 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxac Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Condolidated Edison Co of New York, Int 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 63-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 39 Evaluation " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 50-000,83/09/29,8308300349
- 8310250A28 Forwards IE Insp Repts 50-400/83-28 & 50-401/83-28 on B30820-0920 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/10/05 UTLEY,E E Carolina Power & Light Co 2pp 20900 158 24X Fiche 30-400,83/10/05,8310250628
- ~-8310250632 IE Insp Repts 50-400/83-28 & 50-401/83-28 on 830820-0920 No noncompliance noted Major areas inspected concrete, storage, welding & steam generator mode MAXWELL, 0 F. PREVATTE, R L. DEMIS, P R Region 2, Dffice of Director 83/10/05 Spp 20900 160 24X Fiche 50-400,83/10/05, 8310250628

- B30B300378 IE Info Notice B3-65. "Surveillance of Flow in RTD Bypass Laops Used in Westinghouse Plants " Svc list encl JCROAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 830B300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 830B300759 IE Info Notice 83-67, "Emergency Use Respirator Mat) Defect Causes Production of Noxious Oases "Svc list encl JDRDANLE L Division of Emergency Proparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Salf-Contained Breathing Apparatus Air Cylinders" 8vt list encl
 JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310210136 Forwards add1 info re fire protection, including response to Safety Review Question 280 1, revised safe shutdown analysis w/exemptions & mods.info requested in 830926-27 meetings w/ NRC & response to Enforcement Action 83-41 MCDUFFIE.M A Carolina Power & Light Co 83/10/14 DENION, H R Office of Nuclear Reactor Regulation. Director 475pp 20856 151 24X Fiche 50-400,83/10/14,8310210136
- 8310250571 Comments on detection of deficiencies in quality resulting from suppliers fraudulent actions, described in IE Info Notices 83-07 & 83-01 & IE Bulletins 83-06 & 83-07 Use of addl insp & testing during receipt insps investigated MCDUFFIE.M A Carolina Power & Light Co 83/10/21 DEYOUNG.R C Director's Office Office of Inspection and Enforcement ip 20700 347 24X Fichs 50-000,83/10/21.8310250571
- P Periodic operating reports & related correspondence
- 8310250450 "Beismic Monitoring Program Guarterly Data Rept. Jul-Sept L983 " W/831019 ltr ZIMMERMAN. B R Carolina Power & Light Co 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 20897 158 24X Fishe 50-400.83/09/30.8310250450
- S Reportable occurrences, LERs & related correspondence
- 8310070163 Part 21 rept re potential defects in molded case of 100app frame, multi-pole E & HE series circuit breakers Entitly reported on 830902 ERMARDT, J V Gould, Inc 83/09/26 MURLEY, T E Region I, Office of Director 10pp 20659 095 24X Fiche 50-000,83/07/26, 8310070163
- B310040036 Third interim Deficiency Rept 77 re shop welding defects in seismic Class I cable tray, conduit & HVAC hangers Initially reported on B20802 Final rept expected by B40301 Also reportable per 10CFR21 PARSONS: R M Carolina Fower & Light Co 83/09/29, D'REILLY, J P. Region 2. Office of Director App 20647 087 24X Fichs 30-400, 83/09/29, 8310060036
- 8310060336 Interim deficiency rept, Item 143 re weld deficiencies in sections of ducts CC-1 & CC-2 & transformers 101, 102, 181 & IE2 from Gould & Brown-Boveri Util awaiting Vendor response Also reportable per Part 21 PARSONS, R M Carolina Power & Light Co 83/09/29 D'REILLY, J P Region 2. Defice of Director 1p 20646 092. 24X Fiche 50-400, 83/09/29, 8310060336
- B310120347 Second interim deficiency rept. Items 93 & 72 & Part 21 rept re shop welding deficiencies in seismic I pipe hangers supplied by Bergen-Paterson Initially reported on B20813 & 1103 Ali active hangers corrected PAREONS, R M Carolina Power & Light Co. B3/10/03. O'REILLY, J P Region 3. Office of Director Spp 20699 275. 24X Fiche B0-400,83/10/03,8310)20367
- 8310270206 Part 21 rept re angine mounted electrical cables. Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74007/40 DBR 48) Instruction for cable changeout due in Nov BOYER.R E Transamerica Delaval, Inc 83/10/20, Director's Office, Office of Inspection and Enforcement, ip 20924 108, 24% Fiche 50-000, 83/10/20, 8310270206

- DOCKET 50-406 TUBREGEE INST RESEARCH REACTOR
- G Inspection reports. 1E Bulletins & correspondence
- B310110426 Requests closeout insp of facility to verify residual radiological conditions.per 830809 request to terminate License R-122
 THOMAS.C D Standardization & Special Projects Branch VERRELLI.D M Division of Project & Resident Programs ip 20714 342 24% Fiche 50-406, 83/10/03 8310110426
- DUCKET 50-409 LA CROSSE BOILING WATER REACTOR
- F Security, medical, emergency & fire protection plans
- 8310130310 Releases public version of rev to emergency plan implementing procedure FELTON, J M Division of Rules and Records. 83/10/06 Document Management Branch 1p 20769 014 24X Fiche 30-409.83/10/06, 8310130310
- --8310130311 Public version of Issue 2 to Emergency Plan Implementing Procedure EPP-6. "Sample Collection & Analysis During Emergencies " W/830928 ltr SHAFER, P W. LINDER, F. Dairyland Power Cooperative 83/08/31 CRUTCHFIELD.D Operating Reactors Branch 5 38pp 20769:015 24X Fiche 50-409,83/10/06,8310130310
- 8310130203 Forwards summary of 830810 meeting & site tour re changes to physical security program GRUTCHFIELD.D Operating Reactors Branch 5. 83/10/11 LINDER, F. Dairyland Power Cooperative 3pg 20725 009 24X Fiche 50~409,83/10/11,8310130203
- 8310200003 Forwards Amend 34 to License DPR-45 & safety evaluation Amend modifies Tech Space incorporating addl limitations to protect against degraded grid voltage & plac cracking & new requirements to facilitate fire protection CRUTCHFIELD.D Operating Reactors Branch 5 83/10/14 LINDER, F. Dairylland Fouer Cooperative 3pp 20837 042 24X Fiche 30-409,83/10/14,8310200003
- ---B310200005 Amend 34 to License DPR-45 modifying Tech Specs to incorporate add1 limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection & inservice insp CRUTCHFIELD.D Operating Reactors Branch 5 83/10/14 45pp 20837 046 24% Fiche 50-409.83/10/14,8310200003
- --8310200006 Safety evaluation supporting Amend 34 to License DPR-45.

 * Office of Nuclear Reactor Regulation, Director 83/10/14 7pp
 20837 091 24X Fiche. 50-409, 83/10/14, 8310200003
- 8310190131 Forwards comments on detailed control room design review program plan if implemented properly, review will probably produce results that fulfill requirements of Suppl 1 to NUREQ-0737 Response not required CRUTCHFIELD.D Operating Reactors Branch 5. 83/10/17 LINDER,F Dairyland Power Cooperative 10pp 20820, 287 24X Fiche 50-409, 83/10/17, 8310190131
- 8310310158 Ack receipt of 831005 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-409/83-09.

 Severity Level IV violation remeins Violation based on App E to 100FR50 Emergency plan review underway PAPERIELLO, C. J Division of Emergency Preparedness & Operational Support 83/10/25 LINDER, F W Dairyland Fower Cooperative. 2p; 20759 038 24X Fiche 50-409,83/10/25,6310310158.
- --8310310163 Responds to NRC 830906 ltr re violations noted in IE Insp Rept 50-409/83-09 Corrective actions emergency plan procedure revised to notify local authorities within 15 minutes Protective action guidelines will be incorporated LINDER: F Dairyland Power Cooperative. 83/10/03 PAPERIELLO.C.J Division of Emergency Preparadness & Operational Support Bpp. 20939 040 24X Fiche 50-409.83/10/25,8310310159.
- P Operating license stage documents & correspondence
- B310030101 Forwards summary of proposed integrated plant safety assessment (NUREG-0827) & SEP Topics III-3.A, III-4.B & VIII-1 A, Printing error in NUREG-0485 corrected to read 01/01/94
 LINDER:F. Dairyland Power Cooperative B3/09/29 CRUTCHFIELD, D. Operating Reactors Branch 5 21pp. 20628-289 24X
 Fiche 50-409.B3/09/29.8310050101.

- 8310120104 Requests formal update to completion schedules in integrated plant safety assessment rept Intermediate milestones should be established enabling NRC to review evaluation methods & acceptance criteria CRUTCHFIELD.D Operating Reactors Branch 5 83/10/06 LINDER, F Dairyland Power Cooperative 2pp 20696 182 24X Fiche 50-409, 83/10/06.8310120104
- 8310170159 Forwards clarification of evaluation of pipe whip, jet impingement & breaks within pipe tunnel (SEP Topic III 5 B), per 830720 request transmitting integrated plant safety assessment grogram (NUMEG-OB22) LINDER, F Dairyland Power Cooperative 83/10/06 CRUTCHFIELD, D Operating Reactures Branch 5 4pp 20788 347 24X Fiche 50-409,83/10/06.8310170159
- 8310120272 Advises that FR. containing Commission monthly notices which afford public apportunities for hearing on requests for action, will be transmitted w/o forwarding ltr in future CRUTCHFIELD. O Operating Reactors Branch 5 B3/10/07 LINDER. F. Dairyland Power Cooperative 2pp 20490 347 24X Fichs. 50-409, 83/10/07, 83/10/20272
- 8310130276 Forwards evaluation of util 830831 plant design submittal in response to integrated plant SAR (NUREG-0827) Section 4 24 1.App K, "Elsectrical Instrumentation & Control Reviews for LACBER" Issue resolved.
 CRUTCHFIELD.D Operating Reactors Branch 5 83/10/07 LINDER.F Dairyland Power Cooperative 7pp 20723 178 24X Fiche 50-407,83/10/07.8310130276
- 8310200003 Forwards Amend 34 to License DPR-45 & safety evaluation Amend modifies Tech Specs incorporating add1 limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection CRUTCHFIELD D Operating Reactors Branch 5 83/10/14 LINDER.F Dairyland Power Cooperative 3pp 20837.042 24X Fiche 50-409.83/10/14.8310200003
- --8310200005 Amend 34 to License DPR-45, modifying Tech Specs to incorporate add1 limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection & inservice insp CRUTCHFIELD, D Operating Reactors Branch 5 83/10/14 45pp 20837 046 24X Fiche 50-409,83/10/14,8310200003
- --8310200006 Safety evaluation supporting Amend 34 to License DPR-45
 * Office of Nuclear Reactor Regulation, Director 20837 091 24X Fiche: 50-407, 83/10/14, 8310200003
- 8310250566 Forwards "LACBUR Containment Bldg Independent Seismic Analysis " Models & assumptions must reflect actual plant configuration before floor response spectra used CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/18 LINDER, F Dairyland Power Cooperative 2pp 20901 151 24X Fiche. 50-409, 83/10/18, 8310250566
- --8310280570 "LACBUR Containment Bldg Independent Seismic Analysis " BRIDGEB:T L , HARRIS, B L EG&G, Inc. 82/10/18 NRC - No Detailed Affiliation Given. 97pp 20901 153 24X Fiche 50-409, 83/10/18.8310250566
- 8310210303 Responds to B30311 request for extension of deadline for final environ qualification of certain electrical equipment items Extension to no later than 850331 granted, DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/10/19 LINDER, F. Dairyland Power Cooperative 7pp 20851 064 24X Fichs: 50-409, 83/10/19, 8310210303
 - 10280128 Forwards safety evaluation re util 830929 response to NUREQ-0827 re integrated safety assessment rept. Sections 4.26 & 4.26 3 Commitments & Justification for not modifying certain Foxboro & Honeywell recorders acceptable.
 CRUTCHFIELD, D. Operating Reactors Branch 5. 83/10/27. LINDER, F Dairyland Power Cooperative 2pp 20929 038 24X Fiche: 50-409, 83/10/27, 8310280128
 - 8310280134 Safety evaluation re util 830929 response to NUREG-0827 integrated plant safety assessment rept. Bections 4 26 k 4.26 3. Commitments & justification acceptable, * Operating Reactors Branch 5 83/10/27 2pp 20929 040 24X Fiche, 50-409, 83/10/27, 8310280128
- 3310280161 Discusses 831006 response to request for add1 info re integrated plant safety assessment rept (NUREG-0827), Section 4 12, "Pipe Break Dutside Containment," Critaria for jet impingement provided Section complete Evaluation encl. CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/27 LINDER, F Dainyland Power Cooperative. 2pp 20929 221. 24X Fiche 50-409,83/10/27,8310280161

- --8310280163 Safety evaluation supporting integrated plant safety assessment rept (NUREG-0827), Section 4 12, "Pipe Break Dutside Containment"

 * NRC No Detailed Affiliation Given 83/10/27 1p 20729 223 24% Fichs 50-409, 83/10/27, 8310280161
- @ Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26.8308308308
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83~63, "Potential Fajlures of Westinghouse Type 9A~1 Differential Relays " Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830(03) 83/09/26 Consolidated Ldison Co of New York, Inc. 118pp 20778 001, 24X Fiche 50~000,83/09/26,8308300345
- 830B300349 JE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York: Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,830B300449
- 8308300378 [E Info Notice 83-65, "Surveillance of Flow in HTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308360378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentino Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases" Svc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 8,3/10/11 Consolidate Edison Co. of New York, Inc. 117pp 21043 075 24X Fishe 50-000, 83/10/11.0308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83710/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000.83/10/11,8308300761
- 83i0180274 Clarifies NRC position re procedures for admitting NRC personnel to facilities Access should be afforded to Region III personnel listed in encl Update will be provided every & months AXELSON.W.L. Region 3, Office of Director 83/t0/14 LINDER,F W Bairyland Power Cooperative 7pp 20802 295 24X Fiche 50-409.83/10/14.83101802/4
- 8310200003 Forwards Amend 34 to License DPR-45 & safety evaluation Amend modifies Tech Specs incorporating addl limitations to protect against degraded grid voltage & pipe cracking & new requirements to facilitate fire protection CRUTCHFIELD, D. Operating Reactors Branch 5 83/10/14 LINDEH, F Dairyland Power Cooperative 3pp 20837 042 24X Fiche 50-409.83/10/14.8310200003
- ~~8310200005 Amend 34 to License DPR-45, modifying Tech Specs to incorporate addl limitations to protect against degraded grid voltage & pips cracking & new requirements to facilitate fire protection & inservice insp CRUTCHFIELD. D. Operating Reactors Branch 5 83/10/14 45pp 20837 044 24X Fiche 50~409,83/10/14,8310200003
- --8310200006 Safety evaluation supporting Amend 34 to License DPR-45 * Office of Nuclear Reactor Regulation, Director 83/10/14 7pp 20837 091, 24X Fiche 50-409,83/10/14,8310200003
- 8310310397 Forwards IE Insp Rept 50-409/83-13 on 830808-12 & notice of violation Mritten response detailing plans & schedules for addl QA training required SPESBARD,R L Division of Engineering 83/10/17 LINDER,F Dairyland Power Cooperative 2pp 20959 310 24X Fiche 30-409,83/10/17.8310310397

- 3310310400 Notice of violation from insp on 830808-12 SPESSARD, R L Division of Engineering 63/10/17 4pp 20959 312 24% Fiche 50-409,83/10/17,8310310397
- E3t0310407 IE Insp Rept 50-409/83-13 on B30808-12 Noncompliance noted reproper recording of surveillance & callbr data Instrumentation callbr performed w/o adequate guadelines to technicians re prerequisites for performing callbr FAPRELL.R E , KISH.J N , HUNTER D R Region 3, Office of Director 83/10/17 8pp 20959 316 24X Fiche 50-409,83/10/17,8310,31039/
- -10310158 Ack receipt of 831005 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-09

 5everity Level IV violation remains Violation based on App E to 100CFR50 Emergency plan review underway
 FAPERIELLO, C J Division of Emergency Preparedness & Operational
 S.-port 83/10/25 LINDER, F W Dairyland Power Cooperative 2pp 20959 038 24x fiche 50-409,83/10/25.8310310158
- --9310310163 Responds to NRC 830906 ltr re violations noted in IE lnsp
 Rept 80-409/03-09 Corrective actions emergency plan
 procedure revised to notify local authorities within 15
 ainutes Protective action guidelines will be incorporated
 LINDER.F Dairyland Power Cooperative 83/10/05 PAPERIELLO.C J
 Division of Emergency Preparedness & Operational Support Opp
 20959 040 24X Fiche 50-409,83/10/25.8310310188

Periodic operating reports & related correspondence

- ::0190027 Monthly operating rept for Aug 1983 W/830909 ltr vOODMAN L 8 . LINDER: F Dairyland Power Cooperative 83/09/07 Fiche 50-409.83/09/07.8310190027
- Pepartable occurrences, LERs & related correspondence
- F-10|10430 Responds to FDIA request for four different categories of Accuments described in 830510 ltr Forwards mot1 listed in App A.responsive to Items 1.2 k 4 DDE should be contacted for mat1 requested in Item 3 of ltr FELTON. J M Division of Rules and Records 83/06/14 HIAIT.S L dhio Citiens for Responsible Energy 3pp 20706 002 24X Fiche: 50-000.83/06/14.8310110430
- -93]0110467 Daily rept re events at three different facilities LACBWR experienced stram due to low water level PNO-III-83-026 updates use of lubricants on valve seats + Region 3. Office of Director 83/04/14 1p 20706 062 24% Fiche 50-000,83/06/14.8310110430
- IICO7O301 Potential Part 21 rept re underrange characteristic of "adel N-E31GM transmitter Underrange zero offset may occur of the transmitter initially pressurized from atmospheric to suppressed zero input End users notified EFFERIAN.M J. Foxboro Corp. 83/09/30 Director's Office, Office of Inspection and Enforcement lipp. 20651-064 24X Fiche 50-000, 63/09/30, 6310070301
- IDDITOGICAL Updated LER 83-00//01X-1 on 830716, seal injection (SI) systems transient caused gasket in forced circulation pump IA supply time orifice to fail Caused by personnel error SI tys control changes planned W/831003 Itr 700DMAN.L B. LINDER, F. Dairyland Power Cooperative 83/10/03 EPPLER, J. G. Region 3, Office of Director 3pp 20786 174 24X Fiche 50-409,83/10/03,8310170364
- 1:02:00:02 RU on 830:706, high pressure svc water alternate core spray pusp 18 removed from svc more than 7 days to install addl pusp Caused by delay in providing replacement pump feurivalent pump obtained & installed LINDER.F. Dairyland Power Cooperative 83/10/11 KFPPLER.J G Waglon 3. Office of Director 2pp 20058 258 24X fishs 50-409.83/10/11.8310210002
- *FET 50-410 NINF MILE POINT NUCLEAR STATION, UNIT 2

 Application/construction stage documents & correspondence
- NOOSO131 Forwards request for add1 info re operating & maint procedures & ATWS: FSAR Sections 13 5 2 & 15 8 & Items I C 7 4 I C.8 from Section 1 10 Responses should be submitted as changes to FSAR by 831027
 SCHMENCER: A Licensing Branch 2 83/07/20 RHDDE, 0 K Niagara Kahawak Power Corp 6pp 20650 198 24% Ficha 50-410.83/09/20.83(005013)
- 13050007 Formalds request for add1 info needed for FSAR review Responses should be submitted as changes to FSAR by 831215 SCHNENCER.A Licensing Branch 2 83/09/27 RHODE.G K Niagara Ashawi Power Corp 4pp 20650 191 24X Fiche 50-410.83/09/2/.

- 8310110411 Forwards request for add1 info re NUREG-0737 items & safety-related structures, sys & components controlled by GA program (FSAR Table 3 2-1) flesponses should be submitted as changes to FSAR by 831027
 9CHWENCER. A Licensing Branch 2 83/09/27 RHODE, G K Niagara Mohawk Power Corp 7pp 20713 344 24X Ficha 50-410.63/09/27, 8310110411
- 8310070194 Natification of B31013 meeting w/util in Hethesda, MD to discuss geoscience issues for facility HAUGHEY, M F. Licensing Branch 2 B3/09/29 SCHWENCER, A Licensing Branch 2 Jpp 20479 340 24X Fiche 50-410,83/09/29,8310070194
- 8310170045 Forwards request for add1 info re safety review of power sys area Schedule for response should be provided within 14 days of date of itr SCHWENCER, A Licensing Branch 2 83/10/03 RHODE, G.K. Niagara Mohawk Power Corp 33pp 20812 276 24X Fiche 50-410,83/10/03, 8310170045
- 8310170716 Forwards updated distribution list for environ rept.FSAR & general info portion of OL application
 SCHMENCER, A Licensing Branch 2 83/10/04 RHODE, 9 K Niagara
 Mohauk Power Corp Spp 20798 117 24X Fiche 50-410,83/10/04,
 8310170716
- 8310170745 Advises that instrument tubing & supports program acceptable for plant safety-related systematic on review of util 830418 proposal & FSAR Table 3 9A-15 Acceptance subj to listed conditions
 SCHHENCER, A Licensing Branch 2 83/10/05 RMODE, G K Niegara Mohauk Pawer Corp 3pp 20796 352 24X Fiche 50-410,83/10/05.
 8310170745
- 8310310228 Application for Amend 5 to OL application (filed in PDR Category A), consisting of Amend 5 to FSAR (filed in PDR Category K) & Suppl 4 to environ rept OL stage (filed in PDR Category C) Affidavit enc.)
 MANGAN, C V Niagara Mohawk Power Corp 83/10/24 EISENHUT, D. Q
 Division of Licensing 2pp 20932 134 24X Fiche 50-410,83/10/24,8310310228
- C Utility Environmental Report (ER), amends & correspondence
- 8310310228 Forwards Suppl 4 to environ rept OL stage MANGAN, C V Niegara Mohawk Power Corp 83/10/24 EISENHUT, D Q Division of Licensing 2pp 20952 134 24X Fiche 50-410,83/10/24, 8310310228
- --8310310238 Suppl 4 to environ rept OL stage * Niagara Hohawk Fower Corp 83/10/31 63pp 20952 136 24X Fiche 50-410.03/10/24.031031022B
- F Security, medical, emergency & fire protection plans
- 8310050131 Forwards request for add1 info re operating & maint procedures & ATMS.FSAR Sections 13 5 2 & 15 8 & Items I C 7 & I C 8 from Section 1 10 Responses should be submitted as changes to FSAR by 831027
 SCHHENCER.A Licensing Branch 2 83/09/20 RHODE.O K Niagara Mahawk Power Corp 6pp 20450 198 24X Fiche 50-410.83/09/20.8310050131
- X Utility Final Safety Analysis Report (FSAR) & amends
- 8310310228 Forwards Amend 5 to FBAR including proprietary info MANGAN,C V Niagara Mohawk Power Corp. 83/10/24. EIBENHUT,D Q Division of Licensing 2pp 20952.134 24X Fiche 50-410,83/10/24. 8310310228
- ~-8310310243 Amend 5 to FSAR, Vol 2, incorporating certain responses to FSAR & environ rept
 * Niagara Mohauk Power Corp 83/10/31 1316pp 20952-199 24X
 Fichs 50-410,83/10/24,8310310228
- Q Inspection reports. If Bulletins & correspondence
- B310060004 Forwards IE Insp Rept 50-410/B3-11 on B30802-04 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs B3/09/22 RHODE, G K Niegara Mohawk Power Corp 2pp 20649 285 24X Fiche 50-410.B3/09/22.B310060004
- --B310060012 IE Insp Rept 50-410/B3-31 on B30B02-04. No noncompliance noted Major areas inspected installation of electrical cables recembly motor control ctrs.quality records & inspector followup on previously identified items FINKEL.A. ANDERSUN.C. Region I. Office of Director B3/09/09 7pg 20649 287 24% Fichs 50-410.83/09/22,8310060004

- 830B300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York: Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,830B300340

- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toric Gas Datectors Positioned at Control Room Ventilation Air Intates " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York Inc 116pp 20777 210 24x Fiche 50-000.83/09/26.8308J00342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list enc) JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York. Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310040389 Forwards IE Enforcement Conference Rept 90-410/83-14 on 830830 STAROSTECKI.R Division of Project & Resident Programs RHODE.Q N. SEIBERT.C R Niagara Mohawk Power Corp Ppp 20820 044 24% Fiche 50-410.83/09/28.8310040389 83/09/28
- --8310040393 IE Enforcement Conference Rept 50-410/83-14 on 830830 Major areas discussed implementation efforts to improve performance of piping contractor.ITT Grinnel & results of NRC investigation of contractor GRANT, J. CALLOR Region 1. Office of Director 83/09/26 3pp 20620 046 24X Fiche 50-410.83/09/28,8310040389
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Cansalidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 83i0(30)46 Act receipt of 830922 ltr forwarding payment of civil penalty imposed by 830824 ltr AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/09/29 RHODE, 0 Niagara Mohawk Power Corp 2pp 20777 152 24X Fiche 50-410.83/09/29.8310130146
- B31019012B Forwards IE Insp Rept 50-410/B3-12 on 83080B-0921 & notices of violation & deviation M/o notices
 STAROSTECKI. R Division of Project & Resident Programs B3/10/04 RHODE.0 K Niagara Mohawk Power Corp 2pp 20820 297 24X
 Fiche 50-410, B3/10/04, B31019012B
- --8310190135 IE insp Rept 50-410/83-12 on 630808-0921 Noncompliance noted failure to properly inspect cable rework activities & to comply w/FSAR commitments to hold point usage GRAPM, A , GRANT, J . OALLO.R H . Region i. Diffice of Director 83/09/30 14pp 20820 297 24X Fiche 50-410.83/10/04.8310190128
- B30B300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York: Inc 76pp 20827 213 24X Fichs 50-000.83/10/07.830B300378
- 8308300752 IE info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp. 20882 026 24X Fiche 50-000.83/10/07.8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Mail Defect Causes Production of Noticus Gaues " Svc list anci JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 89/10/11 Consolidated Edison Co of New York: Inc 117pp 21043 075 24% Fichs 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-60, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20027-129 24X Fiche 30-000.83/10/11,8308300761
- 8310310338 Discusses IE Investigation Rept 50-410/1-83-005 on 830222-24,28 & 0301-04 & forwards notice of violation Violation rs mgt of GC personnel classified Severity Level STAROSTECKI.R Division of Project & Resident Programs 83/10/13 RHODE.O K Niegara Nohauk Power Corp. 2pp 20961 325 24K Fiche 30-410,83/10/13,8310310338

- --B310310343 Notice of violation from investigation on B30222-24.:8 & 0301-04 Noncompliance noted util personnel did not have sufficient control of QA program to permit ITT Grinnel organizational freedom * Region 1, Office of Director B3/10/13 2pp 20961 327 243 Fiche 50-410,83/10/13,8310310338
- 5 Reportable occurrences, LERs & related correspondence
- B310170153 Interim deficiency rept re Rockwell Intl microswitch in post-LOCA hydrogen recombiners initially reported on B30011 Final rept will be submitted by 850909 Also reported per Part 21 MANNO,S F Niegara Mohawk Power Corp 83/09/01 Division of Project & Resident Programs 2pp 1 Fiche 50-410.83/09/01.8310170153)1 STAROSTECK1.R 20797 114 24X
- B3102B0052 Interim deficiency rept re 40-mil.i.000-volt fire-resistant control cable supplied by Kerite Co Initially reported on B30829 Cause under investigation Final rept to be submitted by 831215
 MANNO.S F Nisgara Mohawk Power Corp 83/09/23 STANDSTECKI.R
 Division of Project & Resident Programs 2pp 20/34 331 24X
 Fiche 30-410,83/09/23-8310280052
- B310070301 Potential Part 21 rept re underrange characteristic of Model N-EilGM transmitter Underrange zero offset may accur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN, M J Foxboro Corp B3/09/30 Director's Dffice. Uffice of Inspection and Enforcement 11pp 20651 064 24X Fiche 30-000.83/09/30.8310070301
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B310050352 Notification of 830928-29 meetings w/util in Shippingport.PA to discuss public concerns of environ interest & to conduct site visits

 LAZOLL Licensing Branch 3, 83/09/19 KNIGHTON, Q W Licensing site visite LAZO,L Licensing Branch 3, 83/09/19 KNIGHTON, G W Licensing Branch 3 8pp 20635 001 24X Fiche 50-412,83/09/19,8310050352
- 8310060514 Forwards request for addl environ qualification info.based on review of FSAR submitted w/830518 DL application Response due by 831123 KNIGHTON O W Licensing Branch 3 83/09/22 WOOLEVER, E J Duquesne Light Co 7pp 20663 169 24X Fiche.50-412.83/09/22 8310060514
- 8310060524 Forwards request for addl seismic & dynamic load info.
 based on review of FSAR submitted w/830518 DL application
 Response due by 831118
 KNIGHTON, 0 W Licensing Branch 3 83/09/22 WDDLEVLR,E J
 Duquesne Light Co 5pp 20662 305 24% Fiche 50-412,83/09/22.
 8310060524
- 8310060830 Forwards comments on FSAR Section 1 9, "BRP Conformance Evaluation " Comments should be considered in responding to 830919 request for add1 structural & geotechnical engineering info KNIOHTON, 6 W Licensing Branch 3. 83/09/22 WDCJLEVER, € J Duguesne Light Co 10pp 20462 295 24X Fiche 50-412,83/09/2≥. 8310040530
- 8310060510 Forwards request for addl plant personnel training info, based on review of FSAR submitted w/830518 OL application Response due by 831125
 KNIGHTON, OW Licensing Branch 3 83/09/28 WOOLEVER, E J
 Duquesne Light Co lipp 20663, 176 24X Fiche, 50-412, 83/09/28, 8310060510
- 8310180121 Notification of Significant Licensee Meeting 83-39 on 831021 in King of Prussia. PA to discuss engineering design control program & compliance w/Reg Guide ! 75, Rev 2 re electrical separation criteria TRIPP. LE Region !, Office of Director 83/10/12 Region !, Office of Director 83/10/12 Region !, Office of Director 83/10/12 Region !, Office of Director 10 20824 040 24X Fiche 50-412.83/10/12.
- 8310310089 Summarizes 830823 meeting w/NRC in Sethesda, MD redevelopment of Tech Specs for plant, Concern raised rehuman factors aspect of attempting to operate two essentially identical units from common control room.

 WOOLEVER, E. J. Duquesne Light Co. 83/10/26 DENTON, H. R. O. Nuclear Reactor Regulation, Director 3pp. 20950 341, 24X Fiche 30-412, 83/10/26, 8310310089 Defice of

Securaty, medical, emergency & fire protection plans

- 10310309 Forwards Amend 1 to fire protection evaluation rept Amend ILC310309 Forwards Amend 1 to fire protection evaluation is consists of mods to text resulting from responses to NRC request for additing operations contained in Encl 1 of SW Knighton B30831 ltr to EV Woolever WCOLEVER, E. V. Duquesne Light Co. B3/10/27 DENTON, H.R. Nuclear Reactor Regulation, Director 2pp 20961 172 Fiche 50-412,83/10/27,8310310309 Office of
- 83/10/27 DENTON H R or 2pp 20961 172 24X
- \$310310312 Amend I to fire protection evaluation rept
 Stone & Webster Engineering Corp 83/10/31 34pp 20961 174
 24% Fiche 50-412.83/10/27.8310310309

Adjudicatory correspondence

- 10050533 Response opposing Ohio Citizens for Responsible Energy \$33906 amended petition for leave to intervene Petition to velve regulations to admit need for power contention is as itless Certificate of Syc encl FERLIS.R G Hearing Branch 3 83/09/26 Atomic Safety and Litensing Board Panel 11pp 20631 334 24X Fiche 50-412,83/09/26,8310050533
- t0050402 Response to 830909 suppl to request of Environ Coalition on Reclear Power (ECNP) for OL hearing & petition for leave to intervene ECNP fails to provide admissible contentions failtion should be denied Certificate of Suc encl FERLIS. R & Hearing Branch 3 83/09/29 Abomic Sofety and Litensing Board Panel 15pp 20633 348 24X Fiche 50-412,83/09/29,
- 10050402 10140019 Forwards ZG Ferkin notice of appearance, substituting for
- 10140019 Forwards 24 Ferrish notice or appearance superior

 Rees & HL Worlfling H/o encl Related correspondence

 FERKIN.Z @ Pennsylvania, Commonwealth of, 83/10/11

 ARGULIESH B Atomic Safety and Licensing Board Panel

 20767 029 24X Fiche 50-412,83/10/11/8310140019
- IO140091 Notice of appearance in proceeding Certificate of Svc encl EFKIN Z 0 Pennsylvania, Commonwealth of, 83/10/11 3pp '0767 023 24% Ficho 50-412,83/10/11,8310140091
- 10:180343 Notice of withdrawal as party from proceeding Certificate of net emel #HITE.Q. 8 Affiliation Unknown 83/10/11 Spp 20802 360 24% ithe 50-412,8310/11,8310180349
- 0180140 Forwards substitution of appearance of 20 Ferkin for D Rees & HK Woelfling for Commonwealth of PA Certificate
- P Mees & to the terminal of te
- 0250297 Clarifies cite to Seabrook decision adverted to at 831012 rehearing conference re consideration of sunk costs [ull itation for decision is CLI-77-8 ERLIS, R.O Hearing Branch 3 B3/10/14 MARQULIES, M.B , HILL.E E MROOM, P. H Atomic Safety and Licensing Board Panel Ip 0898 361 24X Fichs 50-412,63/10/14,8310250297 B3/10/14 MARQULIES M.B , HILL E E .
- Utility Final Safety Analysis Report (FSAR) & amends
- OGLOOGE Forwards Amend 3 to FSAR, consisting of responses to B30B31 equest for add1 info COLEVER, E J Buquesne Light Co B3/10/26 DENTON, H R Office of Itlear Reactor Regulation, Director 2pp 20967 032 24X tche 50-412, B3/10/26, B310310062
- 310310045 Amend 3 to F8AR.consisting of responses to 830831 request for add1 info s Stone & Wobster Engineering Corp 83/10/31 1,300pp 20947 034 24X Fiche 50-412,83/10/26,8310310062

Antitrust correspondence

- 0200036 Forwards notice of receipt of antitrust info re OL ipilication.per Reg Quida 9 3 NICHTON. 0 W Licensing Branch 3 83/10/06 WODLEVER, E J veuesne Light Co 3pp 20844 228 24X Fiche, 50-412, 83/10 310200036 24X Fiche, 50~412, 83/10/04,
- 310200042 Notice of receipt of antitrust info re OL application.per Rig Guide 9 3 PNICHTON O W Licensing Branch 3 83/10/06 2pp 20844,231 24X Fiche 50-412,83/10/06,8310200036

- G Inspection reports, IE Bulletins & correspondence
- 8310030345 Ack receipt of 830825 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-412/83-08 MARTIN T I Division of Engineering & Technical Programs 83/09/84000EVER.E J Duquesne Light Co ip 20592 333 24% Fiche 50-412,83/09/12.8310030345 83/09/12
- -8310030360 Responds to NRC 830725 ltr re violations noted in 1E lnsp Rept 50-412/83-0B Corrective actions Schneider Power Corp assigned special block of numbers applicable to nonconformance & deficiency repts for ASME 111 Program HODLEVER, E J Duquesne Light Co 83/08/25 STARDSTECKI, R Dávisión of Project & Resident Programs 3pp 20592 334 24X Fiche 50-412,83/09/12,8310030345
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24% Fiche 50-000, 83/09/26,8308300340.
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000, 83/09/26, 8308300342
- B30B300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Comsolidated Edison Co of New York, Inc 118pp 20778 OOI 24% Fiche 30-000,83/09/26,830B300345
- G30G300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o (OCFR50 59 Evaluation " Svc list enca JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 50-000,83/09/27,8308300349
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" 8vc list encl JORDAN, El Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Net York Inc 74pp. 20827 213 24X Fiche 50-000.63/10/07.8308300378
- B30B300752 IE Info Notice B3-66. "Fatality at Argentine Critical Facility " Syc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07. Consolidated Edison Co of New York, Inc 79pp. 20882 026 24X Fiche 50-000.83/10/07.830B300752.
- 8308300759 IE Info Notice 83-57, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/10/11 Cansolidated Edison Co of New York, Inc 117pp 21043 075 24% Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24% Fiche 50-000.83/10/11.8308300761
- B310270323 Confirms B31021 meeting w/util at Region I oft to discuss util role in control review & independent assessment of ongoing angineering efforts in response to previous NRC inspfinding & SALP evaluations.

 STAROBECKI, R. Division of Project & Resident Programs B3/10/12. WD0LEVER, E. J. Duquesna Light Co. 1p. 20923 182. 24X Fiche 50-412, 83/10/12, 8310270323
- T Hearing transcripts on non-antitrust matters
- 83:0170442 Transcript of 83:012 special prehearing conference in Pittsburgh.PA.Pp 1-146 * Atomic Safety and Licensing Board Panel 83/10/12 147pp 20778 130 24X Fiche 50-412,83/10/12,8310170442

- DOCKET 50-413 CATANBA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8310050076 Concurs w/dissolution of Hodel D2/D3 Steam Generator Util Design Review Panel Panel work complete.
 NGVAK: T M Assistant Director for Licensing 83/09/23
 BLACKLEY: B K Design Review Panel 5pp 20650 165 24X
 Fiche 50-000,83/09/23,8310080076
- B30B300355 Board Notification 83-66A:advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
 EISENHUT:D 0 Division of Licensing. 83/09/29 PALLADIND,N J Commissioners, 10pp 20632 106 24X Fiche 50-000,83/09/29, 8308300355
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2.Fermi 2 & Callaway EIBENHUT, D O Division of Licensing 83/09/29 PALLADING, N Commissioners. 3pp 20632 001 24X Fiche. 50-000, 83/09/29, 8308300357
- 8310030412 Trip rept of 830920 site visit including plant tour & meeting w/util mgt JOOSTEN, J K Commissioners 83/09/29 Commissioners 18pp 20593-109, 24X Fichs. 50-413, 83/09/29, 8310030412
- 8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Wastinghouse plants in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Fower Station EISENHUT: D 0 Division of Licensing 83/10/04 PALLADING, N J Commissioners 2pp. 20698:033 24X Fiche. 50-000, 83/10/04, 8308300763
- 8310110636 Summary of 830913 site meeting w/util re mods to steam generators JABBOWIN, N. Licensing Brench 4 83/10/04 Licensing Branch 4 3pp. 20706 326 24% Fiche 50-413,83/10/04,8310110636
- 8310210179 Comments on incorrect statements noted in 830929 trip rept Correct milestone date for Unit 1 hot functional testing is Nov 1983 & Hay 1984 for fuel loading. TVCKER, H B Duke Power Co 83/10/13 GILINSKY, V Commissioners 2pp 20856 125 24X Fiche 50-413.83/10/13.8310210179
- 8308310050 Board Notification 83-160 provides info rd 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENHUT.D © Division of Licensing 83/10/14. PALLADIND.N J Commissioners 15pp 67036,070 24X Fithe 50-000,83/10/14. 8308310050
- 8310240245 Forwards notice of receipt of request for action under 10CFR2. 206 for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt sudit of util & independent review of as-built condition of plant DEYOLMO, R C Director's Office, Office of Inspection and Enforcement, 83/10/14 QARDE, B P Government Accountability froject 3pp 20907 280. 24X Fiche 50-413,83/10/14,8310240245.
- --B310240249 Notice of receipt of request for action under 10CFR2 206 for B30914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant DEYOUNG.R C Director's Office Office of Inspection and Enforcement. B3/10/14 1p 20907:283, 24X Fiche 50~413, B3/10/14, B310240245
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310070150 Notification of B30930 meeting w/util in Rethesda. MD to discuss internal correction protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 150).

 JABBOUR. K. N. Licensing Branch 4 B3/09/27. ADENSAM. E Q Licensing Branch 4 2pp 20480/306. 24% Ficher 50-413,83/09/27,8310070150
- B310040016 Forwards one oversize revised flow diagram to comply w/Bection 10.4.9 of SER rs License Condition 20.10ss of primary source of condensate storage water Aperture card is available in PDR TUCKER.H.B. Duke Power Co. 83/09/28. DENTON,H R. Office of Nuclear Reactor Regulation, Director. ADENBAM.E.Q. Licensing Branch 4. 2pp. 20615:034. 24X Fiche.50-413,83/09/28,8310040016

- 8310170264 Natification of 831027 meeting w/util in Bethesda.HD to discuss technical issues re SLR Confirmatory Item 1, "PMP & Effects on Safety-Related Structures & Components " JABBOUR,K N Licensing Branch 4 83/10/12 ADENSAM,E & Licensin Branch 4 3pp 20843 162 24X Fiche 50-413.83/10/12,8310170264
- 8310190165 Advises that design max temp of standby nuclear svc water pond raised from 95 F to 100 F, in response to SSER 1, Open I tem 2 Info will be incorporated in FSAR, Rev 8 TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 9 Licensing Brench 4 3pp 20821 065 24X Fiche 50-413,83/10/13,8310190165
- 8310190195 Advises that installation of voltmeters to determine reactor trip status by measuring P-4 signal in reactor trip breaker cabinets completed, in response to SER Confirmatory Item 27 TUCKER, M D Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Incensing Dranch 4 ip 20820 203 24X Fiche 50-413,83/10/13,83/10/90195
- 8310190262 Forwards description of analysis & results to confirm that sufficient time exists to reestablish DHR if RHR sys inadvertently isolated as result of loss of instrument bus, in response to SSER 1.0pen Item 12
 TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of NUCLEAR Reactor Regulation, Director ADENSAM, E Q Licensing Branch 4 3pp 20818 061 24X Fiche 50-41J, 83/10/13,8310190262
- 8308300779 Board Notification 83-140A forwards Board Notification 83-128 re dwaft test rept on qualification test program of Class IE solenoid valves Resolution will be handled under Outstanding Issue 4 in SER NOVAK, T M Assistant Director for Licensing 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20855 167 P4X Fiche 50-413,83/10/17.8308300779
- B310280096 Responds to SER Open Item 6 re NUREC-0737. Item II F 2,
 "Instrumentation for Detection of Inadequate Core Cooling,"
 providing updated FSAR pages concerning core exit
 thermocouples & reactor vessel level measurement
 TUCKER. H B Duke Power Co 83/10/19 DENTON, H R Office of
 Nuclear Reactor Regulation. Director ADENSAM, E G Licensing Branch
 4 13pp 20935 191 24X Fiche 50-413,83/10/19,8310280096
- F Security, medical, emergency & fire protection plans
- 8310040406 Forwards IE Insp Repts 50-413/63-23 & 50-414/63-20 on B30801-05 No noncompliance noted DANCE.H C Division of Project & Resident Programs B3/09/13 TUCKER.H B Oute Power Ca 2pp 20619 094 24X Fishe 50-413,83/09/13.8310040406
- --8310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 930801-05 No noncompliance noted Major areas inspected preoperational emergency preparedness, including Procedure TI 2513/55 re readiness for emergency plan implementation appraisal HUFFMAN.0 N Region 2. Office of Director JENKINS.0 R Division of Emergency Preparedness & Materials Safety 83/09/08 10pp 20619 094 24X Fiche 50-413.83/09/13.8310040406
- 8310040287 Forwards Rev 2 to 830414 response to Suppl 1 to NUREG-0737, including rept on review of Reg Guide 1 97
 TUCKER.H B Duke Power Co B3/09/26 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E, G Licensing Branch 4 91pp 20614 077 24X Fiche 50-413,83/09/26,8310040287
- 8310070150 Notification of 830930 meeting w/util in Bethesda.MD to discuss internal corrosion protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 150)

 JABBOUR.K N Licensing Branch 4 83/09/27 ADENSAM.E 0 Licensing Branch 4 2pp 20680 306 24X Fiche 50-413.83/09/27.8310070150
- 8310250383 Forwards IE Insp Repts 50-413/83-27 & 50-414/83-25 pn 830914 No noncompliance noted DANCE.H C Division of Project & Resident Programs, 89/09/30 TUCKER.H B Duke Power Co Zpp 20898 139 24X Fiche 50-413,83/09/30
- --B310250392 IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914 No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning HUFFMAN, 9, N Region 2, Office of Director JENKINS, 0 R Division of Emergency Preparadness & Materials Bafety 83/09/28 2pp 20898 141 24X Fiche 50-413,83/09/30,8310250383
- 8310070134 Releases public version of revised crisis mgt plan implementing procedures
 FELTON.J M Division of Rules and Records 83/10/04 Document Management Branch 1p 20670 001 24X Fiche 50-000,83/10/04, 8310070134

- --8310070143 Forwards public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 1 re recovery manager & immediate staff group plan & 5 3 4 re scheduling/planning support group TUCKER: H B Duke Power Co 83/07/06 DENTON, H R Office of Nurlear Reactor Regulation, Director 3pp 20670 002 24X Fiche 50-000.83/10/04.8310070134
- --B310070132 Public version of revised crisis mgt plan implementing procedures, including Procedure 5 3 1 re recovery manager & inmediate staff group plan & 5 3 4 re scheduling/planning support group

 + Dute Power Co 83/07/01 457pp 20670 005 24%
 Fiche 50-000.83/10/04.8310070134
- 8310110607 Notification of 831001-04 site meetings w/util to audit fire protection program JABBOUR.K N Licensing Branch 4 83/10/04 ADENSAM.E G Licensing Branch 4 3pp 20701 357 24X Fiche 50-413.83/10/04.8310110407
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved O'REILLY, J.P. Region 2, Office of Director 83/10/17 TUCKER, H.D. Duke Power Co. 3pp. 20900 205 24X Fiche 50-000,83/10/17, 8310250635
- --0310250652 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1982 -- Apr 1983 -- Apr 1983 -- Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fiche 50-000, 83/10/17, 8310250635
- Adjudicatory correspondence
- B3083004B0 Forwards answer to util & NRC motions for summary disposition of Contentions 11.17 & 27 Proposed schedule for emergency planning proceeding encl GUILD, R Guild, R GUILD, R Palmette Alliance B3/08/26 KELLEY, J L , FOSTER, R F , CALLIHAN, D Atomic Bafety and Licensing Soard Panel 3pp 20210 327 24X Fiche 50-413,83/08/26,83083004B0
- --8308300485 Answer opposing util & NRC motions for summary disposition of Contentions 11.17 & 27 Many substantial & matl issues of fact exist affecting public health & safety & environ Certificate of Svc sncl Culto.R Guild, R 83/08/25 Atomic Safety and Licensing Board Panel 25pp 20210 330 24X Fiche 50-413-83/08/26-8308300480
- 3310050406 Submits list of NRC witnesses to appear at hearing on Palmetto Alliance Contention 16 & Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 W/o enck
- enck JOHNSON.G E Hearing Branch 4 83/09/23 KELLEY.J L , FORTER.R F , CALLIHAN.D Atomic Safety and Licensing Board Panel 3pp 20630 123 24X Fiche 50-413,83/09/23,8310050406
- --B3\$0030409 Affidavit of PA Evans in response to Palmetto Alliance allegations that self-initiated evaluation identified problems which are symptomatic of systematic deficiencies in plant const EVANS, PA Duke Power Co 83/09/27 12pp 20593 133 24X Fiche 80-413,83/09/27,8310030406
- G10030412 Trip rept of 830920 site visit including plant tour & meeting w/util mgt
 JOOSTEN.J K Commissioners 83/09/29 Commissioners 18pp
 20593 109 24X Fiche 50-413,83/09/29,8310030412
- 310060275 Ack receipt of 830816 ltr requesting info on util spent fuel agt plans Area is ever changing so precise mix of options util will adopt is difficult to predict Flexibility must stist in future Related correspondence GRIFFITH.S C Duke Power Co 83/09/29, WILSON,R P South Carolina, State of 3pp 20641 005 24% Fiche 50-413,83/09/29, 8310060295
- 310040177 Memorandum & order ruling on objections to ASLB 830914 prehearing conference order Hearing will commence on 831004 KELLEY, J.L. Atomic Safety and Licensing Board Panel 83/09/30. Palmetto Alliance lipp 20608 254 24X Fiche 50-413,83/09/30. B310040177

- 8310050562 Objection to Palmetto Alliance 830924 request for issuance of ASLB subpoena to JP D'Reilly,Region II administrator, based on ASLB 830912 denial of identical request Partial transcript of 830831 telcon & Certificate of Svc encl JDNNSGN.6 E Hearing Branch 4 83/10/03 Atomic 8afety and Licensing Board Panel 35pp 20629 001 24X Fiche 50-413,83/10/03,8310050562
- 83i0110294 Requests B31017 meeting in Charlotte, NC to discuss discovery needs re emergency planning contentions & projected schedule for completing discovery for all parties before 840201 Related correspondence CARR.A V Duke Power Co 83/10/04 GUILD, R Palmetto Alliance RILEY, J L Carolina Environmental Study Group 1p 20665 338 24X Fiche 30-413,83/10/04.83i0110294
- O Inspection reports. IE Bulletins & correspondence
- 8310110044 Responds to FOIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions re SALP reviews Forwards App A documents FELTON, J M Division of Rules and Records 83/07/20 RIDENHOUR, & Gambit 2pp 20713 308 24X Fiche 50-000, 83/07/20, 8310110044
- --83i0110057 Forwards case chronology re allegations concerning welding issues at facilities W/o encl
 ALDERSON,C E Region 2, Office of Director 83/02/23
 JOHNSON,O E Office of the Executive Legal Director ip
 20713 341 24X Fiche 50-413,83/07/20,8310110044
- 8310040329 Forwards IE Insp Repts 50-413/83-24 & 50-414/83-21 en 830816-19 No noncompliance noted DANCE: H C Division of Project & Resident Programs 83/09/02 TUCKER: H B Duke Power Co 2pp 20617 085 24X Fiche 50-413,83/09/02.8310040329
- --8310040345 IE Insp Repts 80-413/83-24 & 50-414/83-21 on 830814-19 No noncompliance noted Major areas inspected verification of as-builts & insp of lOCFR21 regulations MCFARLAND,C R, WRIGHT,R W Region 2. Office of Director UPRIGHT.C H Division of Engineering & Operational Programs 83/09/01 7pp 20617 087 24X Ficho 50-413,83/09/02.8310040329
- 8310040146 Forwards IE Insp Rept 50-413/83-25 on 830822-26 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/08 TUCKER, H B Duke Power Co 2pp 2060B 018 24X Fiche 50-413,83/09/08,8310040146
- --8310040150 IE Insp Rept 50-413/83-25 on 830822-26 No noncompliance noted Major areas inspected preoperational test program/procedure verification to plant tour TAYLOR,P A. JAPE,F Region 2. Office of Director 83/09/06 3pp 20608 020 24x Fiche 50-443.83/09/08.8310040146
- 8310040406 Forwards IE Insp Repts 50-419/83-23 & 50-414/83-20 on E30801-05 No noncompliance noted DANCE.H C Division of Project & Resident Programs B3/09/13 TUCKER H B Duke Power Ca 2pp 20419 094 24X Fiche 50-413.83/09/13.8340040406
- --B310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted Major areas inspected preoperational emergency preparedness, including Procedure TI 2515/55 re readiness for emergency plan implementation appraisal HUFFMAN.9 N Region 2, Office of Director JENKING.0 R Division of Emergency Preparedness & Materials & 84649 & 83/09/08 | 10pp 20619-076 24X Fiche 50-413.83/09/13.8310040406
- 8310040599 Forwards supplemental response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Bafety Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel) " Final rept re infestation to be available by 831101
 TUCKER, H B Duke Power Co B3/09/16 O'REILLY, J P. Region P. Office of Director 2pp 20626 174 R4X Fichs 50-413.83/09/16, 8310040597
- 8310040313 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 LEHIS, R C Division of Project & Resident Programs 63/09/22 TUCKER, H B Duke Power Co 1p. 20649 299 24X Fiche 50-413,83/09/22,8310040313
- --8310040319 Responds to NRC 830811 ltr re viplations noted in 1E Insp. Repts 30-413/83-17 & 30-414/83-16. Corrective actions signoff for const engineer-civil restricted to eight experienced personnel TUCKER. H B Duke Power Co 83/09/08 O'REILLY, J P Region 2, Office of Director 4pp 20549 300 24X Fiche 50-413, 83/09/22, 8310040313

- --8310040323 Forwards IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15 & notice of violation LEWIS,R C Division of Project & Resident Programs 83/08/11 TUCKER,H B Duke Power Co 2pp 20649.304 24X Fiche 50-413,83/09/22,8310040313
- --8310040327 Notice of violation from insp on 830711-15 * Region 2, Office of Director. 83/08/11 2pp 20449 306 24X Fiche 50-413,83/09/22,8310040313
- --8310040335 IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15
 Noncompliance noted improper concrete mix placed & checklists for certification of structural inspector, concrete, Level I, improperly labeled as Level II WRIGHT, R. W. JACKSON, L. H. Region 2. Office of Director WRIGHT, C. M. Division of Emergency Preparadness & Materials Safety 83/08/08 10pp 20447 308 24% Fiche 50-413,83/09/29,8310040313
- 8308300340 IE Info Notice 83-61, "Alteged Use of Stand-Ins for Welder Qualification Tests " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 87/09/26. Consulidated Edison Co of New York, Inc 117pp. 20754 022 24X Fishe 50-000.83/09/26.8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Cas Datactors Positioned at Control Room Ventilation Air Intakes " Svc list enti JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 114pp 20777 210. 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " 8vc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 59-000,83/09/26,8308300343
- 8310250398 Forwards IE Insp Rapts 50-413/83-27 & 50-414/83-24 on 830906-09 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/26. TUCKER, H B Duke Power CO 2pp 20897 284 24% Fiche: 50-413,83/09/26,8310250398.
- --8310250404 IE Insp Repts 50-413/83-27 & 50-414/83-24 on 830706-09 No noncompliance noted Major areas inspected: const progress, licenses action on previous enforcement matters, steam generator mod & review of GA implementing procedures.

 KLEINSORGEN P Region 2, Diffice of Director BLAKE, J J Division of Engineering & Operational Programs 83/09/21 7pp 20877 286 24% Fichs: 50-413, 83/09/26, 8310250398
- 830B300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation." Syc list encl JORDAN, E.L. Division of Emergency Praparedness & Engineering Response (Post 830103) 83/07/27 Consolidated Edison Co of New York, Inc 115pp 20716-324, 24X Fiche 50-000,83/09/29,8308300949
- 8310250383 Forwards IE Insp Repts 50-413/83-27 & 50-414/83-25 on 830914 No noncompliance noted DANCE,H C Division of Project & Resident Programs B3/09/30, TUCKER HB Duke Fower Co 2pp. 20898-139, 24X Fiche-50-413,83/09/30,8310250383
- --B310250392 IE Insp Repts 50-413/83-29 & 50-414/83-25 on 830914. No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning.

 HUFFMAN,0 N. Region 2. Office of Director, JENKINB, G R. Division of Emergency Preparedness & Materials Bafety. 83/09/20 2pp 20898 141 24X Fiche: 50-413.83/09/30,8310250383
- 8310250225 Forwards IE Insp Rept 50-A13/83-30 on B30912-16 No noncompliance noted. DANCE:M.C Division of Project & Resident Programs 83/10/06 TUCKER, H B Duke Power Co. 2pp 20899:113, 24X Fiche 50-413, 83/10/06:8310250225
- ---8310250230 IE Insp Rept 50-4(3/83-30 on 830912-16 No noncompliance noted. Major areas inspected preoperational test witnessing & test procedure review (integrated hot functional sequencing document)

 TAYLOR.P. A Region 2, Office of Director. JAPE.F. Division of Engineering & Operational Programs 83/10/04. 3pp. 20899-115

 24X Fiche. 50-413, 83/10/06, 8310250225.
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Dypass Loops Used in Mestinghouse Plants." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07. Consolidated Edison Co. of New York, Inc. 76pp 20827:213 24X Fiche.50-000.83/10/07.8308300378.

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 63-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases "Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300757
- B308300761 IE Info Notice B3-66. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000, B3/10/11, B308300761
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved. O'REILLY, J P Region 2, Office of Director 83/10/17 TUCKER.II B Duke Power Co 3pp 20700 205 24% Fiche 50-000.83/10/17, 8310250635
- --8310250646 Forwards SALP Repts 50-269/83-17.50-270/83-17.50-281/83-1/.
 50-369/83-24.50-370/83-32.50-413/83-14 & 50-414/83-13 for June 1982 Apr 1983
 LEHIS,R C Division of Project & Resident Programs Ø3/08/02
 TUCKER,H D Duke Power Ca 3pp 20900 208 24X
 Fiche 50-000.83/10/17.8310250635
- ---8310250652 BALP Repts 50-269/83-17,50-270/83-17,50-287/83-17, 50-369/83-24,50-370/83-32,50-413/83-14 & 50-414/83-13 for June 1982 - Apr 1983 * Region 2, Office of Director B3/08/02 56pp 20900 211 24% Fiche 50-000,83/10/17,8310250635
- --B310250465 Responds to B30802 ltr re SALP board rept Rept incomplete & premature in certain areas in general.util endorses observations re facility performance TUCKER.H B. Duke Power Co. B3/08/29 O'REILLY, J.P. Region 2, Office of Director 2pp. 20700 267 24X Fiche 50-000.03/10/17, 8310250635
- S Reportable occurrences, LERs & related correspondence
- B310040038 Interim significant Deficiency Rept 80 413-414/83-10 refailure of power supply printed circuit card adhesive bond of heat sink assembly for inverter transistors Initially reported on B30415 Assemblies will be replaced by B31201 TUCKER,H B Duke Power Co B3/09/27 O'REILLY,J P Region 2, Office of Director 2pp 20647 085 24X Fiche 50-413,83/09/27,8310040038
- 8310060052 Significant Deficiency Rept SD 83-11 re faulty Westinghouse NSSS process instrumentation & control systemp channel test card mercury relays initially reported on 830829 Replacement relay testing underway TUCKER.H B Duke Power Co 83/09/27 D'REILLY.J P Region P. Office of Director 2pp 20648 326 24X Fiche 50-413.83/09/27, 8310060052
- 8310210111 Significant Deficiency Rept SD 413-414/83-12 re metal file found in diesel generators 1B & 2A Initially reported on 830913 File found in air gap between rotor & stator during preliminary checkout TUCKER.H B Dute Power CD 83/10/13 O'REILLY, J P Region 2, Office of Director 3pp 20838 255 24X Fiche 50-413.83/10/13.83/10/13.83/10/13.
- 8310270482 Revised interim Significant Deficiency Rept 8D 413-414/82-06 re socket welds dtd 820415 Required work on Unit 1 completed Unit 2 incomplete due to incomplete list of affected socket welds Completion expected by 850201 TUCKER, H. B. Duke Power Co. 83/10/17 O'REILLY, J. P. Region 2, Office of Director 1p 20722 011 24X Fiche 50-413,83/10/17, 8310270482
- 8308310045 Board Notification 83-147 supplies new info re apparent diesel generator deficiency On 830914 metal file found in diesel generators Investigation underway to determine circumstances surrounding incidences
 NOVAK.T M Assistant Director for Licensing 83/10/25 Atomic Safety and Licensing Board Panel 5pp 20929 014 24X
 Fichs. 50-413, 83/10/25, 8308310045

Hearing transcripts on non-antitrust matters

- ### 10240012 Partial response to FUIA request for transcripts of deposition testimony prepared in discavery in UL proceeding far facilities forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/08/10 AHLERS, D M Faleetto Alliance 3pp 20885 001 24% Fiche 50-417,83/08/10, 6310240012
- -8310240014 Transcript of M Birch deposition in Charlotte,NC re Contention 27 BIRCN.M Duke Power Co B3/05/11 126pp 20885 008 24X Fiche 50-413,B3/08/10.B310240012
- -8310240017 Transcript of CW Graves deposition in Charlotte, NC re Contention 8

 GRAYES.C W Duke Power Co 83/05/12 44pp 20885 134 24X

 Fiche 50-413,83/08/10,8310240012
- -8310240018 Transcript of PK Vandoorn deposition in Charlotte, N. 1e Contention & VANDOORN.P K Duke Power Co 83/05/19 150pp 20885 178 24X Fiche 50-413.83/08/10.8310240012
- #310240021 Transcript of WR McAfee deposition in Charlotte.NC re Contention & MCAFEE.N R Palmetto Alliance 83/05/19 128pp 20885 328 24X Fiche 50-413.83/08/10.8310240012
- 8310240022 Transcript of NL Hoopengardner deposition in Charlotte.NC re Contention 6
 HOOPENGARDNER Palmetto Alliance 83/05/19 47pp 20886 074
 24X Fiche 50~413.83/08/10.8310240012
- 8310240024 Transcript of NR Hoopingarner deposition in Charlotte, NC re Contention 6 HDOPINGARNER, N Palmatto Alliance 83/05/20 109pp 20886 142 24% Fiche 50-413,83/08/10,8310240012
- 9310240030 Transcript of GE Vaughu deposition in Charlotte.NC rc Contention 7 VAUGHN.G E Duke Power Co 83/05/20 41pp 20886 251 24X Fiche. 50-413, 83/08/10, 8310240012
- 8310240032 Transcript of JC Bryant deposition in Charlotte,NC re Contentions 6 & 7 BRYANTJ C NRC No Detailed Affiliation Given 83/05/20 80pp 20886 292 24X Fiche 50-413,83/08/10.8310240012
- 9310240038 Transcript of PK Vandoorn deposition in Charlotte.NC re Contention 6.Vol II VANDOORN.P K Duke Power Ca 83/05/20 137pp 20887 011 P4X Fiche:50-413.83/08/10.8310240012
- 8310240040 Transcript of BG Addis deposition in Charlotte,NC re Contention 6 ADDIGS B 0 Duke Pawer Co 83/06/27 129pp 20887 139 24X Fische 50-413-83/08/10,8310240012
- 3310240043 Trenscript of GH Bell deposition in Charlotte.NC re Contention & BELL. G H Duke Power Co 83/06/27 75pp 20087 269 24X Fithe: 50-413, 83/08/10, 8310240012
- 3310240047 Transcript of JC Rogers deposition in Charlotte,NC re Contention 6
 RDOERS.J C Duke Power Co 93/06/2/ 32pp 20887 346 24X
 Fiche 50-413,83/08/10,8310240012
- 3310240049 Transcript of WO Henry deposition in Charlotte.NC re Centention 6
 HENRY W O Duke Power Co 83/06/28 133pp 20888 017 24X
 Fiche 50-413,63/00/10,83102/00/12
- 310240053 Transcript of DQ Beam deposition in Charlotte.NC re Contention 6
 BEAH. D C Duke Power Co 83/06/28 81pp 20888 152 24X
 Fiche 50-413.83/08/10.83/0240012
- GIO240085 Transcript of WO Henry deposition in Charlotte.NC re Cantention 6
 HEARY, N O Duke Power Co 83/06
 F1che 50-413,83/08/10,8310240012 83/06/29 65pp 20888 235 24X
- 310240056 Transcript of AE Allum 830629 deposition in Charlotte,NC re Contention 6 ALLUM, A E Duke Pawer Co 83/06/29 114pp 20888 300 24X Fiche 50~413:83/08/10:8310240012

- -8310240057 Transcript of CR Baldwin 830629 deposition in Charlotte, NC re Contention & BALDWIN, C.R. Duke Power Co. 83/04/27 191pp 20889 052 24X Fiche 50-413:83/08/10,8310240012
- --831024009B Transcript of JE Grogan deposition in Charlotte, NC Related info enc1 GROSAN.J E Dute Power Co 83/07/01 27pp 20889 241 24X Fiche 30-413.83/08/10.8310240012
- --8310240057 Transcript of WH Bradley deposition in Charlotte,NC re Contention & BRADLEY,W H Duke Power Co 83/07/07 5App 20889 270 24X Fiche 50-413,83/08/10,8310240012
- -8310240060 Transcript of CN Alexander deposition in Charlotte,NC re Contention & Related info encl ALEXANDER.C N Dute Power Co 83/07/07 110pp 20089 327 24X Fiche 50-413,83/08/10,8310240012
- --831024004i Transcript of WS Lee deposition in Charlotte.NC Related info entl LEE,W B Duke Power Co 83/07/12 78pp 20890 074 24X Fiche 50-413,83/08/10.8310240012
- --8310240062 Transcript of RA Morgan deposition in Charlotte,NC re Contention 6 MOROAN,R A Duke Power Co 83/07/13 120pp 20890 153 24X Fiche 50-413.83/08/10.8310240012
- --8310240045 Transcript of BW Deaton deposition in Charlotte, NC re Tochton 6

 DEATON B W Duke Power Co 83/07/14 49pp 20890.274. 24X

 Fiche 50-413.83/08/10.8310240012
- --8310240068 Transcript of S Ledford deposition in Charlotte.NC re Contention 6 LEDFORD, S Duke Power Co 83/07/14 26pp 20890.325 24X Fiche 50-413,83/08/10,8310240012,
- --9310240073 Transcript of JC Shropshire deposition in Charlotte,NC re Contention 6 Related info encl SHROPSHIRE,J C Dute Power Co 83/07/14 89pp 20890.353 24X Fiche 30-413.83/08/10.8310240012
- --8310240076 Transcript of L Sifford deposition in Charlotte,NC re Contention 6 SIFFORD,W L Duke Power Co 83/07/14 38pp 20891 083 24X Fichs 50-413,83/08/10,8310240012
- 8310050386 Forwards testimony of BJ Elliot.WL Brooks.A Singh, F Clemenson,RJ Serbu & F Jape on Palmetto Alliance
 Contention 16 & Carolina Environ Study Group Contention 18/
 Palmetto Alliance 44
 JOHNSON.O E Operations Administrative Division B3/09/30
 KELLEY.J L. FOSTER.R F. CALLIHAN.D Atomic Safety and Licensing
 Board Panel 1p 20630 140 24X Fiche 50-413.83/09/30,8310050386
- --8310050392 Testimony of BJ Elliot on Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 re reactor embrittlement. ELLIOT.B J Materials Engineering Branch 83/09/30 22pp 20630 141 24X Fiche 50-413,83/09/30.8310050386
- --8310050401 Testimony of WL Broaks on Palmetto Alliance Contention 16 recriticality BROOKS, H L. Core Performance Branch 83/09/30 12pp. 20630 163 28% Fiche 50-413,83/09/30,0310050386
- --8310050415 Joint testimony of A Singh & F Clemenson on Palmetto Alliance Contention 16 re spent fuel pool cooling sys. SINGH.A , CLEMENSON.F Auriliary Systems Branch, 83/09/30 18pp. 20630 175 24X Fiche 50-413.83/09/30.8310050386
- --8310080419 Joint testimony of RJ Berbu & F Japa on Palmetto Alliance Contention 16 re spent fuel handling. SERBU,R J Radiological Assessment Branch JAPE,F. Division of Engineering & Operational Programs 83/09/30 17pp 20630 193 24X Fiche 50-413,83/09/30,8310050386
- B310110270 Testimony of JL Riley re Contention 18 concerning unanticipated rapid embrittlement Affirmation of Svc encl Related correspondence RILEY, L. Carolina Environmental Study Group, 83/10/03 14pp 20666 144 24X Fiche 50-413.83/10/03.8310110270

- 8310060310 Testimony of TR Mager & TA Meyer re Carolina Environ Study Oroup & Palmetto Alliance Contention 18/44 Ref temp will not eithbit more rapid increase than calculations show due to radiation effects on vessel W/Certificate of Svc MAGER, T.R. MEYER, T.A. Duke Power Co. MAGER, T.R. Westinghouse Electric Corp. 83/10/04, 26pp. 20646, 201 24X Fiche \$0-413, 83/10/04, 8310060310
- 831011009B Transcript of 831004 hearing in Rock Hill, SC Pp 1, 535-1,734 * Atomic Safety and Licensing Board Panel 83/10/04 202pp 20467 312 24X Fiche 50-413, 83/10/04, 831011009B
- 8310120352 Transcript of 831005 hearing in Rockhill, SC Pp 1,735-1,962 * Atomic Bafety and Licensing Board Panel 83/10/05 228pp 20699 323 24X Fiche 50-413,83/10/05,8310120352
- 8310130013 Yranscript of B31004 hearing in Rockhill, 8C Pp 1,963-2,207 * Atomic Safety and Licensing Board Panel 83/10/06 245pp 20725 292 24X Ficho 50-413,83/10/06,831D130013
- 8310120295 Transcript of 831007 hearing in Rockhill.80 Pp 2,208-2,379 * Atomic Safety and Licensing Board Panel 83/10/07 172pp 20593 172 24X Fiche 50-413,83/10/07,8310120295
- 8310170137 Transcript of 831011 hearing in Rockhill, SC Pp 2,380-2,592 * Atomic Safety and Licensing Board Panel 83/10/11 213pp 20788 354 24% Fiche 50-413,83/10/11,8310170137
- 8310170455 Transcript of 831012 hearing in Rockhill, 9C Pp 2.593-2,832 * Atomic Safety and Licensing Board Panel B3/10/12 241pp 20778 279 24X Fiche 90-413,83/10/12,8310170456
- 8310190115 Transcript of 831013 hearing in Rockhill, SC Pp 2,833-3,060 * Atomic Safety and Licensing Board Panel 83/10/13 228pp 20818 232 24X Fiche 50-413,83/10/13,8310190115
- 8310190119 Transcript of 831013 hearing in Rockhill, 8C Pp 1-67
 * Atomic Safety and Licensing Eward Pauel 83/10/13 68pp 20820 340 24% Fiche 50-413,83/10/13,8310190119
- 8310190122 Transcript of 831014 hearing in Rockhill, SC Pp 3,061-3,277 * Atomic Gafety and Licensing Board Panel 83/10/14 237pp 20819 244 24X Fiche 50-413,83/10/14,8310190122
- 8310210050 Transcript of 831017 hearing in Rockhill, SC Pp 3.298-3.495 * Atomic Safety and Licensing Board Panel 83/10/17 198pp 20874 281 24X Fiche 50-413.83/10/17.8310210050
- 8310210186 Testimony of WH Bradley re quality or safety concerns expressed by welding inspectors Helated correspondence BRADLEY.W H Dute Power Co 83/10/17 5pp 20856 107 24X Fiche 50-413,83/10/17.8310210186
- --8310210192 Testimony of WD Henry re quality or safety concerns expressed by welding inspectors Certificate of Svc encl Related correspondence HENRY, W G Duke Power Co 83/10/17 9pp 20856 112 24X Fiche 50-413,83/10/17,8310210184
- 8310240013 Transcript of 831018 hearing in Rockhill, SC Pp 3,496-3,740 * Atomic Safety and Licensing Board Panel 83/10/18 245pp 20880 093 24% Fiche 50-419,83/10/18,8310240013
- #310250003 Transcript of #31019 hearing in Rock Hill, EC Pp 3,741-3,999 # Atomic Safety and Licensing Board Panel #3/10/19 254pp, 20895 001 24X Fiche 50-413,83/10/19,8310250003
- 8310250001 Transcript of 831020 hearing in Rock Hill, SC Pp 4.000-4, 248 * Atomic Safety and Licensing Board Panel 83/10/20 248pp 20893 001 24X Fiche 50-413, 83/10/20, 8310250001
- 8310280031 Transcript of 831021 hearing in Rock Hill, SC Pp 4,249-4,361 * Atomic Safety and Licensing Board Panel 83/10/21 112pp 20933:209 24X Fiche 50-413.83/10/21.8310280031
- 8310310358 Transcript of 831025 hearing in Rock Hill,80 Pp 4.362-4.628 * Atomic Safety and Licensing Board Panel 83/10/25 267pp 20960 016 24% Fiche 50-413.83/10/25.8310310358

- DOCKET 50-414 CATABBA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8308300355 Board Notification 83-66A advises that position re-rod drep issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
 EISENNUTID Q Division of Licensing 83/09/29 PALLADIND, N J Commissioners 10pp 20632-106 24X Fiche 50-000,83/09/29, 8308300355
- 8308300357 Board Notification 82~105A forwards evaluation of allegations re design defictioncies in Class I piping sys Info applicable to Diablo Canyon 1 & 2 Form 2 & Callaway EISENNUT.D G Division of Licensing 83/09/29 PALLADINO,N J Commissioners 3pp 20632 001 24X Fiche 50-000.83/09/29.
- B310030412 Trip rept of B30920 Site visit including plant tour & meeting w/util mgt
 JD05TEN.J K Commissioners B3/09/29 Commissioners 18pp
 20593 109 24X Fiche 50-413,83/09/29.8310030412
- 8308300763 Soard Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants in light of recent info concerning steam generator tube rupture procedure for Dorssele Nuclear Power Station EISENHUT, D.C. Division of Licensing 83/10/04 PALLADING, N.J. Commissioners 2pp 20678 033 24% Fiche 50-000, 83/10/04, 8308300763
- 8310210179 Comments on incorrect statements noted in 830929 trip lept Correct milestone date for Unit 1 hot Functional testing is Nov 1983 & May 1984 for fuel loading TUCKER.H B Duke Power Co 83/10/13 GILINSKY,V Commissioners 2pp 20856 125 24X Fiche 50-413,83/10/13.8310210179
- 9309310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENHUT.D G Division of Licensing 83/10/14 PALLADINO:N J Commissioners 1'pp 67056 070 24X Fiche 50-000, 83/10/14.
- 8310240245 Forwards notice of receipt of request for action under 10CFR2 206 for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant DEYGUNG.R C Director's Office Office of Inspection and Enforcement 82/10/14 QARDE.B P Guvernment Accountability Project 3pp 20907 280 24X Fiche 50~413,83/10/14,8310240245
- --8310240249 Notice of receipt of request for action under 10CFR2 POS for 830914 petition submitted on behalf of Palmetto Alliance, requesting mgt audit of util & independent review of as-built condition of plant DEYGUNG.R C Director's Office of Inspection and Enforcement 83/10/14 1p 20907 263 24X Fiche 50-413, 83/10/14, 83/14,
- E NRC Bafety Evaluation Report (SLR), suppls & correspondence
- 8310070150 Notification of 830930 meeting w/util in Bethesda, MD to discuss internal corrosion protection for fuel oil storage tanks (SER License Condition 18) & emergency lighting (SER Open Item 150) JABBOURK N Licensing Branch 4 83/09/27 ADENSAM, L G Licensing Branch 4 2pp 20480 304 24X Fiche 50-413,83/09/27,8310070150
- 8310040016 Forwards one oversize revised flow diagram to comply w/Section 10 4 9 of SER re License Condition 20.loss of primary source of condensate storage water Aperture card is available in PDR TUCKER. H B Duke Power Cn 83/09/28 DENTON. H R Uffice of Nuclear Reactor Regulation, Director ADENSAM. E G Licensing Branch 4 2pp 20615 034 24X Fache 50-413,83/09/28.8310040016
- B310170264 Notifacation of B31027 meeting w/util in Bethesda,MD to discuss technical issues re SER Confirmatory Item 1, "PMP & Effects on Bafety-Related Structures & Components " JABBOURK N Licensing Branch 4 B3/10/12 ABENSAM,C G Licensing Branch 4 3pp 20843 162 24% Fiche 50-413.83/10/12.8310170764
- 83(0190165 Advises that design max temp of standby nuclear svc water pand raised from 95 F to 100 F, in response to SBER 1. Open Item 2 Info will be incorporated in FSAR, Rev B TUCKER, H B Duke Power Co 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 3pp 20821 045 24% Fithe 50-413,63/10/13,8310170145

- BJIC190195 Advises that installation of voltmeters to determine reactor trie status by measuring P-4 signal in reactor trip break 27 cabinets completed in response to SER Confirmatory 18em 27 TUCKER, N D Duke Power Co 83/10/13 DENTON, H R Office of fuctear Reactor Regulation, Director ADENSAME & Licensing Branch 4 tp 20820 203 24X Fiche 50-413,83/10/13.8310190195
- 5:10190262 Forwards description of analysis & results to confirm that sufficient time exists to reestablish DiR if RRR systradvertently isolated as result of loss of instrument bus, in response to SSER 1.0pen Item 12
 TUCKER, H B Buke Power Co. 83/10/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADBNSAM, E G. Licensing Branch, 4 3pp. 20818 061 24X Fiche 50-413,83/10/13,8310190262
- 33CB300779 Board Notification B3-140A forwards Board Notification B3-128 re draft test rept on qualification test program of Class II solenoid valves Resolution will be handled under Outstanding Issue 4 in SER NOVAK.TM Assistant Director for Licensing 83/10/17 Atomic Safety and Licensing Board Panel 3pp 20855 167 24X Fiche 50-413.83/10/17.83083007/9
- \$310280096 Responds to SER Open Item 6 re NUREG-0737, Item II ; 2, "Instrumentation for Detection of Inadequate Core Codling," providing updated FBAR pages concerning core exit thermacouples & reactor vessel level measurement TUCMER.H B Duke Power Co 83/10/19 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch 13pp 20935 191 24X Fiche 50-413.83/10/19.8310280096
- Security, medical, emergency & fire protection plans
- 210040406 Forwards IE Insp Repts 50-413/83-23 & 50-414/83-20 on 630801-05 No noncompliance noted ENNCE.H C Division of Project & Resident Programs 83/09/13 TUCHER.H B Duke Power Co 2pp 20617 074 24X Fishe 30-413,83/09/13
- -8310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 830801-05 No noncompliance noted Major areas inspected preoperational Emergency preparedness, including Procedure TI 2518/55 reteadiness for emergency plan implementation appraisal HUFFHAN, ON Region 2, Defice of Director 83/09/08 10pp 20617 096 24X Fiche 50-413, 83/09/13,83100404046
- G10040287 Forwards Rev 2 to B30414 response to Suppl 1 to NUREG-0737.
 arcluding rept on review of Reg Guide 1 9/
 TUCKER.H B Duke Power Co G3/09/26 DENTON.H R Office of
 Nuclear Reactor Regulation. Director ADENBAM.E 0 Licensing Branch
 4 91sp 20414 077 24X Fiche 50-413.83/09/26.8310040287
- 310070150 Notification of 930930 meeting w/util in Bethesda, MD to discuss internal corrosion protection for fuel oil storage tanks (BER License Condition 18) & emergency lighting (SER Open Item 150)

 JABBOUR, K N Licensing Branch 4 83/09/27 ADENSAM; C G Licensis Branch 4 2pp 20680 306 24X Fiche 50-413,83/09/27,8310070150
- J102503B3 Forwards IE Insp Repts 50-413/83-29 & 50-414/83-25 on B30914. No noncompliance noted BANCE.H C Division of Project & Resident Programs 83/09/30 TUCKER.H B Duke Power Co 2pp 20898 139 24% Fiche 50-413,83/09/30
- -8310250392 IE Insp Repts 50-413/83-27 & 50-414/83-25 on 830714.No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning ##FFMAN.O N Region 2. Office of Director 83/09/28 2µp 20898 141 24X Fiche 50-413.83/09/30.8310250383
- BIOO70134 Releases public version of revised crisis mgt plan maplementing procedures
 FELTON.J M Division of Rules and Records 83/10/04 Document
 Management Branch 1p 20670 001 24% Fiche 50-000,83/10/04,
 8310070134
- -3310070143 Forwards public version of revised crisis mgt plan implementing procedures including Procedures 5.3 1 re recovery manager & immediate staff group plan & 5.3 4 re scheduling/planning support group TUCMER.H B Duke Power Co B3/07/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 20470 002, 24X Fiche 50-000.83/10/04.8310070134.
- -B310070132 Public version of revised crisis mgt plan implementing procedures including Procedure 5 3 1 re recovery menager & Immediate staff group plan & 5 3 4 re scheduling/planning support group # Dute Power Co 83/07/01 407pp. 20470.005 24X Fithe 30-000.83/10/04.8310070134

- 8310110607 Natification of 831001-04 site meetings w/util to audit fire protection program
 JABBOUR.X N Licensing Branch 4 83/10/04 ADENSAM,E Q Licensing
 Branch 4 5pp 20701 357 24X Fiche 50~413,83/10/04,8310110607
- 8310250635 Informs that periodic evaluation of SALP complete Rept approved D'REILLY, J P Region 2. Office of Director 83/10/17 TUCKER. H B Duke Power Co 3pp 20900 205 24X Fiche 50-000.83/10/17. 8310250635
- --8310250452 SALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 % 50-414/83-13 for June 1782 Apr 1983 * Region 2, Office of Director 83/08/02 56pp 20900 211 24% Fichs 50-000, 83/10/17, 8310250635

G Adjudicatory correspondence

- 8308300480 Forwards answer to util & NRC motions for summary disposition of Contentions 11.17 & 27 Proposed schedule for emergency planning proceeding encl GUILD,R Guild, R GUILD,R Palmetto Alliance B3/08/26 KELLEY,J L , FOSTER,R F , CALLHIAN,D Atomic Safety and Licensing Board Panel 3pp 20210 327 24X Fiche 50-413,83/08/26,8308300480
- --8308300486 Answer opposing util & NRC motions for summary disposition of Contentions 11:17 & 27 Many substantial & matl issues of fact exist affecting public health & safety & environ. Centificate of Evc encl
 GUILD.R Palmetto Alliance GUILD.R Guild. R 83/08/26
 Atomic Safety and Licensing Board Panel 25pp 20210:330. 24X
 Fiche 50-413,83/08/26,8308300480
- 8310050406 Bubmits list of NRC witnesses to appear at hearing on Palmetto Alliance Contention 16 & Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44. W/a encl
 JOHNSON, O & Hearing Branch 4 83/09/23 KELLEY, J L , FOSTER, R f , CALLIHAN, D Atomic Safety and Licensing Board Panel 3pp
 20430 123 24X Fiche 50-413.83/09/23,8310050406
- 8310030406 Forwards signed & corrected PA Evans affidavit.Related correspondence MCOARRY, J M Duke Power Co 83709/27 KELLEY, J. L., CALLIHAN, A. D., FOSTER, R. F. Atomic Safety and Licensing Board Panel 1p 20393 132 24X Fiche 50-413, 83/09/27, 8310330406
- --B310030409 Affidavit of PA Evans in response to Palmetto Alliance allegations that self-initisted evaluation identified problems which are symptomatic of systematic deficiencies in plant const EVANG P A Duke Fower Co 83/09/27, 12pp 20593 133 24X Fiche 50-413,83/09/27,831003040A
- B310030412 Trip rept of B30920 site visit including plant tour & meeting w/util mgt
 JDG5TEN.J K Commissioners B3/09/29, Commissioners 18pp
 20593 109 24X Fiche 50-413.83/09/29.8310030412
- 8310060295 Ack receipt of 830816 ltr requesting info on util spent fuel mgt plans Area is ever changing so precise mix of options util will adopt is difficult to predict. Flexibility must exist in future Related correspondence.

 ORIFFITH 8 C Duke Power Co 83/09/29 WILSON, R P. Bouth Caroline, State of 3pp 20641 005 24X Fiche, 50-413, 83/09/29, 8310060295
- 8310040177 Memorandum & order ruling on objections to ASLB 830914 prehearing conference order Hearing will commence on 831004 KELLEY, J L Atomic Bafety and Licensing Board Panel. 83/09/30 Palmetto Alliance lipp 2060B 254 24X Fiche: 50-413,83/09/30,8310040177.
- 8310050562 Objection to Palmetto Alliance 830924 request for insuance of ASLB subposes to JP O'Reilly, Region II administrator, based on ASLB 830912 denial of identical request Partial transcript of 830831 telcon & Certificate of Svc encl. JOHNSON, Q. E. Hearing Branch 4. 83/10/03 Atomic Safety and Licensing Board Panel 36pp 20629 001 24X Fiche: 50-413, 83/10/03, 8310050562
- 8310110294 Requests 831017 meeting in Charlotte, NC to discuss discovery needs re emergency planning contentions & projected schedule for completing discovery for all parties before 840201. Related correspondence.

 CARR, A V Duke Power Co 83/10/04 GUILD, R Palmetto Alliance. RILEY, JL Carolina Environmental Study Group Ip. 20465 338 24X Fiche 50-413.03/10/04,8310110294

- Q Inspection reports. IE Bulletins & correspondence
- 8310110044 Responds to FOIA request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide into on SALP insp findings or conclusions re SALP reviews Forwards App A documents FELTON, J M Division of Rules and Records 83/07/20 RIDENHOUR, R Gambit 2pp 20/13 308 24% Fiche 50-000, 83/07/20, 8310110044
- --8310110059 Forwards case chronology re allegations concerning welding issues at facilities W/o encl
 ALDERSON,C E Region 2. Office of Director 83/02/23
 JOHNSON,G E Office of the Executive Legal Director 1p
 20713 341 24x Fiche 50-413.83/07/20.6310110044
- 8310040327 Forwards IE Insp Repts 50-413/83-24 & 50-414/83-21 on 830814-19 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/02 TUCKER, H B Duke Power Co 2pp 20617 085 24X Fiche 50-413, 83/09/02, 8310040329
- --8310040345 IE Insp Repts 50-413/83-24 & 50-414/83-21 on 830816-19 No noncompliance noted Major areas inspected verification of as-builts & Insp of locFR2; regulations MCFARLAND,C R. WRIGHT,R W. Region 2. Office of Director UPRIGHT,C M. Division of Engineering & Operational Programs 83/09/01 7pp 20517 087 24X Fichs 50-413,83/09/02,8310040327.
- 8310040406 Forwards IS Insp Repts 50~413/83-23 & 50~414/83-20 on 830801-05 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/09/13 TUCKER.H B Duke Power Co 2pp 20619 094 24X Fiche 50-413,83/09/13,8310040406
- --0310040413 IE Insp Repts 50-413/83-23 & 50-414/83-20 on 030801-05 No noncompliance noted Major areas inspected preoperational emergency preparadness, including Procedure TI 2515/55 re readiness for emergency plan implementation appraisal HUFFHAN.6 N Region 2. Office of Director JERKINS.0 R Division of Emergency Preparedness & Materials Safety 63/09/08 10pp 20419 096 24% Fiche 50-413.83/09/13.8310040406
- 8310040577 Forwards supplemental response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Bafety Components by Corbicula Sp (Asiatic Clam) & Mytilus Bp (Mussel) "Final rept reinfestation to be available by 831101
 TUCKER, H B Duke Power Co 83/09/16 O'REILLY, J P. Region 2, Difice of Director Rop 20626 174 24X Fiche 50-413.83/09/16, 8310040599
- 8310040313 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 LEWIS, R C. Division of Project & Resident Progrems 83/09/22 TUCKER, H B. Duke Power Co. ip 20647 299 24X Fiche 50-413,83/09/22,8310040313
- --8310040319 Responds to NRC 830811 Itr re violations noted in IE Insp. Repts 80-413/83-17 & 50-414/83-16 Corrective actions signoff for const engineer-civil restricted to eight experienced personnel TUCKER. H B. Duke Power Co. 83/09/09 O'REILLY, J. P. Region 2, Diffice of Director 4pp. 20649 300 24X Fiche 50-413,83/09/22,8310040313
- ---8310040323 Forwards IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15 & motice of violation LEWIS.R C Division of Project & Resident Programs 83/08/11 TUCKER:H B Duke Power Co. 2pp 20649 304 24X Fiche 50-413,83/09/22,8310040313
- --83i0040327 Notice of violation from insp on 830711-15 * Region 2, Office of Director 83/08/11 2pp 20649 306 24X Fiche: \$0-413, 83/09/22, 8310040313
- --B310040335 IE Insp Repts 50-413/83-17 & 50-414/83-16 on 830711-15 Noncompliance noted improper concrete mix placed & checklists for certification of structural inspector, concrete, Level 1, improperly labeled as Level II. WRIGHT, R W. JACKSON, L, H. Region 2, Office of Director UPRIGHT, C M. Division of Emergency Preparedness & Materials Safety, 83/08/08 10pp 20647-308 24X Fiche, 50-413,83/09/22,8310040313
- 830B300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Bvc list encl JORDAN,E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co of New York, Inc 117sp. 20754-022 24X Fiche,50-000,83/09/26,830B309340

- B308300342 IE Info Notice B3-62, "Failure of Redundant loxic Gas Detectors Positioned at Control Room Ventilation Air Intakes "Svc list encl JORDAN.C.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison on of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308 0834.
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN: E.L. Division of Emergency Preparadness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308/90.45
- B310250398 Forwards IE Insp Repts 50-413/B3-27 & 50-414/83-24 on 830906-09 No noncompliance noted DANCE,H C Division of Project & Resident Programs B3/09/26 TUCKER.H B Duke Power Co 2pp 20897 284 24X Fiche 50-413,83/09/26
- --B310250404 IE Insp Repts 50-413/B3-27 & 50-414/B3-24 on B30906-09 Nn noncompliance noted Major aleas inspected const progress, licensee action on previous inforcement matters, steam generator mod & review of GA implementing procedures KLEINEDROE, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/09/21 7pp 20897 286 24X Fiche 50-443,83/09/26,8310250390
- 8308300347 IE Info Notice 83-64, "Lead Bhielding Attached to Safety-Related Sys W/o 100FK50 59 Evaluation " Svc list encl JORDAN.E L Davision of Emergency Preparedness & Ingineering Response (Post 830103) 83/07/27 Cunsolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000.83/09/27.83883003037
- 8310250393 Forwards IE Insp. Repts 50-419/83-29 & 50-414/83-25 on 830914 No noncompliance nated DANCE,H C Division of Project & Resident Programs B3/09/30 TUCKER,H B Duke Power Co App. 20848 139 24X Fiche 50-413,83/09/30
- --8310250392 IE Insp Repts 50-413/83-27 & 50-414/83-25 on 830914 No noncompliance noted Mgt meeting held to discuss NRC insp program for emergency planning HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/09/20 2pp 20898 141 24X Fiche 50-413,63/09/30,6310250383
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E t Division of Emergency Preparedness & Engineering Response (Post B330103) 83/10/0/ Consolidated Edison Co of New York, Inc 76pp. 20827 213 24X Fiche B0-000,83/10/07,83883003/8
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.830830075?
- 8308300759 IE Info Natice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Cn of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11.8308300757
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders" See list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000, 03/10/11, 8308300761
- 8310250635 Informs that periodic evaluation of SALP complete Hept approved O'REILLY, J.P. Region 2, Office of Director 83/10/17 1UCKER, H.D. Duke Pawer Co. 3pp. 20900 205 24X Fiche 50-000, 83/10/17, 8310250635
- --8310250646 Forwards SALP Repts 50-269/83-17,50-270/83-17,50-287/83-17,50-369/83-24,50-370/83-32,50-413/83-14 & 50-414/83-13 for June 1782 Apr 1983 LEWIS,R C Division of Project & Resident Programs 83/08/09 TUCKER,H B Duke Power Co 3pp 20700 208 24X Fiche 30-000,83/10/17,8310250635
- --8310290632 8ALP Repts 50-269/83-17, 50-270/83-17, 50-287/83-17, 50-369/83-24, 50-370/83-32, 50-413/83-14 & 50-414/83-13 for June 1782 Apr 1783 * Region 2, Office of Director 83/08/02 56pp 20900 211 24X Fichs 50-000, 83/10/17, 8310250635

- -- B310250A65 Responds to B30802 Itr re SALP board rept Rept incomplete & productions responds to 830802 ltr re SALP board rept Rept incomplet premature in certain areas in general, util endorses observations re facility performance. TUCKER.H B. Duke Power Co. 63/08/29. O'REILLY, J.P. Region 2. Office of Director. 2pp. 20900-267. 24X Fiche 50-000.83/10/17, 831025835
- : Reportable occurrences, LERs & related correspondence
- 2310050038 Interim significant Deficiency Rept 8D 413-414/83-10 refailure of power supply printed circuit card adhesive bond of heat sink assembly for inverter transistors Initially reported on 830615 Assemblies will be replaced by 831201 TUCAER.H B Duke Power Co 83/09/27 D'REILLY, J P Region 2, Office of Director 2pp 20647 085 24X Fiche 50-413,83/09/27,8310560000 Office of Director
- B10080052 Significant Deficiency Rept SD 83-11 re faulty Westinghouse NSSS process instrumentation & control sys temp channel test card mercury relays Initially reported on 830829 Replacement TELOW Lesting underway
 TUCKER.H B Duke Power Co 83/09/27 O'REILLY, J.P. Region 2.
 Office of Director 2pp 2064B 326 24X Fich# 50-413,83/09/27,
 8310060052
- Ologiolii Bignificant Deficiency Rept SD 413-414/83-12 re metal file found in diesel generators IB & 2A Initially reported on 830913 File found in air gap between rotor & stator during preliminary checkout TUCKER. H B Duke Power Co 83/10/13 D'REILLY, J P Region P, Office of Director 3pp 20858 255 24X Fichs 50-413,83/10/13,8310210111
- JIO270482 Revised interim Significant Deficiency Rept SD 419-414/62-06 re-soctet welds dtd 620415 Required work on Unit I completed Unit 2 incomplete due to incomplete list of affected socket welds Completion expected by 850201 TUCKER, H B Duke Power Ca 83/10/17 D'REILLY, J P Region 2, Office of Director 1p 20922 011 24X Fiche 50-413,83/10/17, e21027463 0310270492
- 308310045 Board Notification 83-14/ supplies new info re apparent dieset generator deficiency On 830914 metal file found in dieset generators investigation underway to determine CIFCUMStances surrounding incidences
 NDVAM, F M Assistant Director for Licensing 83/10/25
 Safety and Licensing Board Panel 5pp 20929 014 E4:
 Fichs 50-413.83/10/25.8308310045 Atomic

Hearing transcripts on non-antitrust matters

- 310240012 Partial response to FUIA request for transcripts of deposition testimony prepared in discovery in OL proceeding for facilities Forwards App A documents Documents also available in FDR FELTON J M Division of Rules and Records 83/08/10 ARLE Palmetto Alliance 3pp 20885 001 24X Fiche 50-413,83/088310240012 Division of Rules and Records 83/08/10 ARLERS, D M liance 3pp 20885 001 24X Fiche 50-413,83/08/10,
- -8310240014 Transcript of M Birch deposition in Charlotte.NC re Contention 27. BIHCH.M Duke Power Co 83/05/11 126pp 20885 008 24X tche 50-413,83/08/10,8310240012
- -8310240017 Transcript of CW Graves deposition in Charlotte, NC re GCOntention B
 GRAVES, C W Duke Power Co 03/05/12 44pp 20885:134 24X
 Fiche 50-413,83/08/10.8310240012
- 9310240018 Franscript of PK Vandoorn deposition in Charlotte, NC re Contention 6
 VANDODRN.P K Duke Power Cn 83/05/19 150pp 20885-178 24X
 Fich= 50-413,83/08/10,833/0240012
- 8350240021 Transcript of WR McAfee deposition in Charlotte, NC re Contention 6
 MCAFEE, W R Palmetto Alliance 83/05/19 129pp 20885 328 24X
 Fiche 50-413,83/08/10,8310240012
- 93]0240022 Transcript of NL Hoopengardner deposition in Charlottm.NC re Contention 6
 HOOPENGARDNER Palmetto Alliance 8
 24% Fiche. 80-413, 83/08/10, 8310240012 83/05/19 47pp. 20886 094
- 8350240024 Transcript of NR Hoppingarner deposition in Charlotte, NC re Contention 6. HODP INVARNER, N. Palmetto Alliance, 83/05/20 109pp R0886 142. 24% Fiche 50-413.83/08/10.8310240012

- --- 8310240030 Transcript of GE Vaughn deposition in Charlotte, NC re Contention 7
 VAUGHN.G E Duke Power Co 83/05/20 41pp 20886-251 24% Fiche 50-413,83/08/10,8310240012
- --8310240032 Transcript of JC Bryant deposition in Charlotte.NC re Contentions 6 & 7 BRYANT.J C NRC No Detailed Affiliation Civen 83/05/20 80pp 20886 292 24X Fiche 50-413.83/08/10.8310240012
- --8310240038 Transcript of PK Vandoorn deposition in Charlotte, NC re Contention 6, Vol II VANDORN, P K Duke Power Co 83/05/20 137pp 20887 011 24X Fiche 50-413,83/08/10,8310240012
- --8310240040 Transcript of BG Addis deposition in Charlotte, NC re Contention 4 ADDIS:B Q Duke Power Co 83/06/27 129pp 20887 139 24X Fiche 50-413.83/08/10.8310240012
- --8310240043 Transcript of GH Bell deposition in Charlotte, NC re Contention 5 bk Power Co 83/06/27 75pp 20887 269 24X Fisher 50-413,83/08/10,83/08/2012
- --8310240047 Transcript of JC Rogers deposition in Charlotte.NC re Contention 6
 ROGERS, J C Duke Power Co 83/05/27 32pp 20887 346 24X
 Fiche 50-413,83/08/10,8310240012
- --8310240049 Transcript of WO Henry deposition in Charlotte, NC re Contention 6 HENRY, N D Duke Power Co 83/06/28 133pp 20888 017 24X Fiche 50-413,83/08/10,8310240012.
- --8310240053 Transcript of DQ Beam deposition in Charlotte, NC re Contention 6 BEAM D 9 Duke Power Co. 83/06/28 81pp 20888 152. 24X Fiche 50-413,83/08/10.8310240012
- --8310240055 Transcript of WO Henry deposition in Charlotte, NC re Contention 6
 HENRY, H D Duke Power Co 83/06/29 65pp 20888 235 24X
 Fiche 50-413,83/09/10,8310240012
- --8310240056 Transcript of AE Allum \$30629 deposition in Charlotte.NC re Contention & ALLUM, A E I JONESTIAN DUKE POWET CO 83/06/29 114pp. 20888 300 24X Fiche 50-413,83/08/10,8310240012,
- --8310240057 Transcript of GR Baldwin 830629 deposition in Charlotte. NC re Contention & BALDWIN, C R Duke Power Co 83/06/29 191pp 20889 052 24X Fiche 50-413,83/08/10,8310240012,
- --- 8310240038 Transcript of JE Orogan deposition in Charlotte, NC Related info encl E Duke Power Co 83/07/01 27pp 20889.241 24x Fiche 50-413.83/08/10.8310240012.
- ---8310240059 Transcript of WH Bradley deposition in Charlotte.NC re Contention 6

 BRADLEY, W H Duke Power Co 83/07/07 56pp 20889.270 24X

 Fiche 50-415,83/08/10,8310240012,
- ~-8310240060 Transcript of CN Alexander deposition in Charlotte, NC re Contention & Related info encl ALEXANDER, C. N Duke Power Co 83/07/07. 110pp. 20889: 327 24X Ficha 50-413.83/08/10.8310240012.
- --8310240061 Transcript of WS Lee deposition in Charlotte.NC Related info encl LEE,W S Duke Power Co 83/07/12 78pp 20890.074. 24X Fiche 50-413,83/08/10.8310240012
- --8310240062 Transcript of RA Morgan deposition in Charlotte,NC re Contention 6
 MCRCAN,R A Duke Power Co 83/07/13 120pp. 20890 153 24X
 Fiche, 50-413, 83/08/10, 8310240012.
- -- 8310240065 Transcript of BW Deaton deposition in Charlotte, NG re Contention 6
 DEATON, B W. Duke Power Co 83/07/14 49pp. 20890.274 24X
 Fiche 50-413,83/08/10,8310240012.
- --8310240068 Transcript of 8 Ledford deposition in Charlotte, NC re Contention 6 Contention D LEDFORD, 8 Duke Power Co. 83/07/14. 24pp 20890 325 24X Fiche 50-413,83/08/10,8310240012,

- --8310240073 Transcript of JC Shropshire deposition in Charlotte.NC re Contention & Related info encl SHROPSHIRE.J C Duke Power Co 83/07/14 89pp 20890 353 24X Fiche 50-413,89/08/10.8310240012
- --8310240074 Transcript of L Sifford deposition in Charlotte,NC re Contention & BIFFORD,N L Duke Power Co 83/07/14 38pp 20871 083 24X Fiche 50-413,83/08/10,8310240012
- B310050386 Forwards testimony of BJ Elliot.WL Brooks, A Singh, F Clamenson, RJ Serbu & F Jape on Palmetto Alliance Contention id & Carolina Environ Study Group Contention 18/ Palmetto Alliance 44
 JOHNSON, O & Operations & Administrative Division B3/09/30
 KELLEY, J L. FOSTER, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 1p 20630 140 24X Fiche 50-419,83/09/30,8310050386
- --9310050392 Testimony of BJ Elliot on Carolina Environ Study Group Contention 18/Palmetto Alliance Contention 44 re reactor embrittlement ELLIOT.B J Materials Engineering Branch 83/09/30 22pp 20630 141 24X Fiche 50-413,83/09/30,8310050386
- --B310050401 Testimony of WL Brooks on Palmetto Alliance Contention 14 re-criticality BRDOKS-W L Core Performance Branch B3/07/30 12pp 20A30 163 24% Fichs 50-413.B3/07/30.B3100503B6
- --8310050415 Joint testimony of A Bingh & F Clemenson on Palmetto Alliance Contention 16 re spent fuel pool cooling sys BINGH.A. CLEMENBON.F Auxiliary Systems Branch 83/09/30 IBpp 20630 175 24X Fishe 30-413.83/09/30.8310050386
- --8310050419 Joint testimony of RJ Berbu & F Jape on Palmetto Alliance Contention 16 re spent fuel handling SERBULR J Radiological Assessment Branch JAPE.F. Division of Engineering & Operational Programs. 83/09/30 17pp 20630 173 24X Fiche, 50-413, 83/09/30, 8310050386
- 8310110270 Testimony of JL Riley re Contention 18 concerning unanticipated rapid embrittlement Affirmation of Svc encl Related correspondence RILEY, JL Carolina Environmental Study Group 83/10/03 14pp 20666 144. 24X Fiche 50-413,83/10/03.8310110270
- 8310060310 Testimony of TR Mager & TA Mayer re Carolina Environ Study Ordup & Palmetto Alliance Contention 18/44 Ref temp will not exhibit more rapid increase than calculations show due to radiation effects on vessel W/Certificate of Svc MAGER, TR Mestinghouse Electric Corp 89/10/04 26pp. 20646-201 24X Fiche 50-413,83/10/04,8310060310
- 8310110098 Transcript of 831004 hearing in Rock Hill, 8C Pp 1,535-1,734 * Atomic Safety and Licensing Board Pamel 83/10/04. 202pp. 20667 312. 24X Fiche 50-413,83/10/04,8310110098
- 8310120352 Transcript of 831005 hearing in Rockbill.SC Pp 1.735-1.962 * Abomic Safety and Licensing Board Panel 83/10/05 228pp 20699 323 24% Fiche 50-413.83/10/05.8310120352
- 8310130013 Transcript of 831006 hearing in Rockhill, SC Pp 1.763-2.207
 * Atomic Bafety and Licensing Board Panel 83/10/06 245pp
 20725 292 24X Fiche 50-413.83/10/06.8310130013
- 8310120275 Transcript of 831007 hearing in Rocthill.8C Pp 2:208-2:379
 * Atomic Safety and Licensing Roard Panel B3/10/07 172pp
 20693.172 24X Fiche 50-413.83/10/07:8310120295
- 8310170137 Transcript of 831011 hearing in Rockhill.86 Pp 2.380-2.592 * Atomic Safety and Licensing Board Panel 83/10/11 213pp 20788.354 24X Fichs 50-413,83/10/11.83/10170137
- 8310170456 Transcript of 831012 hearing in Rockhill.80 Fp 2,593-2,832 * Atomic Safety and Licensing Board Fanel 83/10/12 241pp. 20778:279. 24% Fiche:50-413,83/10/12,8310170456
- 8310190115 Transcript of 831013 hearing in Rockhill, SC. Pp 2,833-3,060 * Atomic Bafety and Licensing Board Panel 83/10/13 228pp 20818, 232, 24X Fighe 50-413,83/10/13,8310190115.
- 8310190119 Transcript of 831013 hearing in Rockh(11,80 Pp 1-67 * Atomic Safety and Licensing Board Fanel 83/10/13. 68pp 20820-340. 24X Fichs. 50-413,83/10/13,8310190119

- 8310190122 Transcript of 831014 hearing in Rockhill, SC Pp 3,961-3,297 * Atomic Safety and Licensing Board Panel 83/10/14 237pp 20819 244 24% Fiche 50-413,83/10/14,8310190122
- 8310210050 Transcript of B3101/ hearing in Rockhill, SC Pp 3,298-3,495 * Atomic Safety and Licensing Board Panel 83/10/17 198pp 20874 281 24% Fiche 50-413,83/10/17,8310210050
- 8310210186 Testimony of WH Bradley re quality or safety concerns expressed by welding inspectors Related correspondence BRADLEY, W H Duke Power Co 83/10/17 5pp 20856 107 .44X Fiche 50-413, 83/10/17, 8310210186
- ~-8310210192 Testimony of WD Henry re quality or safety concerns expressed by welding inspectors Contribicate of Svc enc)
 Related correspondence
 HENRY, H D Duke Power Co 83/10/17 9pp 20856 112 24X
 Fishe 50-413, 83/10/17, 8310210186
- 8310240013 Transcript of 831018 hearing in Rockhill, SC Pp 3,496-3,740 * Atomic Safety and Licensing Board Panel B3/10/18 245pp. 20880 073 24X Fiche 50-413,83/10/18.8310240013
- 8310250003 Transcript of 831019 hearing in Rock Hill, SC Pp 3,741-3,999 * Atomic Safety and Licensing Board Panel 83/10/19 254pp 20895 001 24X Fiche 50-413,83/10/19,8310250003
- 8310250001 Transcript of 831020 hearing in Rock Hill.6C Pp 4,000-4,240 * Abomic Safety and Licensing Board Panel 83/10/20 248pp 20893 001 24% Ficho 50-413,83/10/20,8310250001
- 8310280031 Transcript of 831021 hearing in Rock Hill,80 Pp 4,249 4,361 * Atomic Safety and Licensing Board Panel 83/10/21 112pp 20933 209 24X Fiche 50-413,83/10/21,8310280031
- B310310358 Transcript of 831025 hearing in Rock Hill, SC Pp 4,382-4,688 * Atomic Safety and Licensing Board Panel 83/10/25 267pp 20960 016 24% Fiche 50-413,83/10/25,8310310358
- DOCKET 50-414 GRAND GULF NUCLEAR STATION, UNIT 1

 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310180330 Provides add1 info on SER Confirmatory Item I 10(4) re soil structure interaction in fulfillment of commitments made in response to NRC 830112 ltr Util committed to utilizing elastic half-space methodology

 DALE.L F Mississippi Power & Light Co 83/10/14 DENTON-H R
 Office of Nuclear Reactor Regulation. Director 4pp 20802 348
 24% Fiche 50-416,63/10/14,8310180330
- F Security, medical, emergency & fire protection plans
- B3i0040394 Forwards summary of B30909 meeting in Region II ofc re proposed physical security plan mods LEMIG.R C Division of Project & Resident Programs B3/09/26 RICHARD.J B Mississippi Power & Light Co 3pp 20619 041 P47 Fiche 50-416.83/09/26.8310040394
- 8310180430 Forwards Rev 9 to physical security plan Rev withheld (ref 10CFR2 790 & 10CFR9 5) DALE.L F Mississippi Power & Light Co 83/09/30 D'REILLY.J P Region 2. Office of Director 2pp 20803 297 24X Fiche: 50-416,83/09/30,8310180430
- 8310120349 Advises that due to uncertainty in instrumentation availability & manpower resources, instrumentation necessary to meet Reg Guide 1 97 requirements will be implemented by third refueling outage per Suppl 1 to NUREG-0737 DALE, L F Mississippi Power & Light Co 83/10/10 DENYON, H R. Office of Nuclear Reactor Regulation, Director 2pp 20700 231 24X Fiche 50-416,83/10/10.8310120349
- 8310170141 Forwards IE Safeguards Insp Rept 50-416/83-40 on 830912-\$6 No noncompliance noted VERRELLI, D. Division of Project & Resident Programs B3/10/11, RICKARD, J. B. Mississippi Power & Light Co. 2pp. 20788-351 24X Fiche: 50-416, 83/10/11, 8310170141
- ---B310170147 IE Bafeguards Insp Rept 50-416/83-40 on 830912-16 No noncompliance noted Major areas inspected review of security organization-response, security program sudit, records & repts Details withheld (ref 10CFR79 21)
 ENNIS, J D Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/10/04 Ip 20788 353 24x Fiche 50-416,83/10/11,8310170141

- H General correspondence
- \$310190222 Responds to 830906 telephoned comments re NRC proposed NSHC fetermination on amend requests NRC made final NSHC determination on 830923 Opportunity for hearing will be afforded after FR notice published SCHMENCER, A Licensing Branch 2 83/10/07 LAWRENCE, K Affiliation Unknown 5pp 20838 164 24X Fiche 50-416,83/10/07, B310190222
- P Operating license stage documents & correspondence
- 8310030081 Forwards Amend 9 to License NPF-13, safety evaluation & notice of issuance & availability Amend corrects editorial & nomenclature errors to achieve consistency w/as-built condition of plant
 SCHWENCER. A Licensing Branch 2 83/07/15 MCGAUGHY, J P Mississippi Power & Light Co 5pp 20603 258 24% Fiche 50-416, 83/09/15.8310030081
- --8310030085 Amend 9 to License NPF-13, correcting editorial & nomenclature errors to achieve consistency w/as-built condition of plant SCHMENCER, A Licensing Branch 2 83/09/15 122pp 20603 262 24X Fiche 50-416, 83/09/15, 8310030081
- --B310030088 Safety evaluation supporting Amend 7 to License NPF 13

 * Office of Nuclear Reactor Regulation, Director 83/09/15 App. 20004 023 24X Fishe 50-416.83/09/15.8310030081
- --B310030104 Notice of issuance & availability of Amend 9 to License NPF-13 SCHHENCER, A Licensing Branch 2 83/09/15 4pp 20604 029 24X Fiche 50-416.83/09/15,8310030081
- 6310040046 Forwards request for add1 info re 830610 QA program update LEMIS.R C Division of Project & Resident Programs 83/09/23 RICHARD.J D Mississippi Power & Light Co 5pp 20608 138 24X Fiche 30-416.83/09/23.8310040046
- 8310050067 Agrees that pneumatic testing of containment isolation valves more conservative than hydrostatic testing & represents acceptable alternative per 830926 Its ECHMENCEN.A Licensing Branch 2 83/09/23 MCGAUGHY, J P Mississippi Power & Light Co. 2pp 20650 155 24X Fiche 50-416.03/09/23.8310050067
- 8310050073 Advises that 830721 & 0823 rovs to startup test program acceptable
 SCHMENCER.A Licensing Branch 2 83/07/23 MCGAUGHY.J P
 Hististippi Power & Light Co 2pp 20649 361 24X
 Piche 50-416.83/09/23.8310080073
- 83100&0033 Forwards Amend 10 to License NPF-13 & safety evaluation Amend changes Tech Specs & grants one-time exceptions to Tech Specs for relief needed for restart SCHMENCER.A Licensing Branch 2 83/09/23 MCGAUGHY, J P Mississippi Power & Light Co App 20464 073 24% Fiche 50-416,03/09/23.8310040033
- -8310040037 Amend 10 to License NPF-13 changing Tech Specs & pranting one-time exceptions to Tech Specs for restart SCHMENCER, A Licensing Branch 2 03/09/23 12pp 20644 078 24X Fiche 50-416, 83/09/23 0310060033
- -3310060050 Safety evaluation supporting Amend 10 to License NPF-13 * NRC No Detailed Affiliation Given 83/09/23 11p 20564 090 24% Fiche 50-416,83/09/23,8310060033.
- MIQO60057 Forwards Amend ii to License NPF-13 & safety evaluation. Amend grants change to license condition re completion of control room envelope leak tightness test BCHMENCER. A Licensing Branch 2 83/09/23 MCGAUGHY. J P Mississippi Power & Light Co. 3pp 20644 064 24X Fiche 30-416.83/09/23.8310060057
- -8310060064 Amend 11 to Licanse NPF-13 changing Tech Specs re completion of control room envelops leak tightness test EISENHVT, D. D. Davision of Licensing 83/09/23 3pp 20664:067 24X Fichs 50-416,83/09/23,8310060057
- -83:0060071 Safety evaluation supporting Amend 11 to License NPF-13 # NRC - No Detailed Affiliation Given 83/09/23 3pp 20664 070 24X Fiche 50-416,83/09/23,8310060057

- 8310130343 Requests publication of FR notice of consideration of issuance of amend to License NPF-13 & proposed NSHC determination & opportunity for hearing re restart changes to Tech Specs NSHC determination available in Central Files SCHMENCER. A Licensing Branch 2 83/09/23 HILLER. J R Operating Reactors Branch 3 5pp 20754 327 24% Fiche 50-416.83/09/23, 8310130343
- 8310170167 Requests publication of FR notice of consideration of issuance of amend to License NPF-13 & proposed NBHC determination & opportunity for hearing re control room leak test NBHC determination available in Central Files SCHHENGER, A Licensing Branch 2 83/09/23 MILLER, J R Operating Reactors Branch 3 3pp 20811 360 24X Fiche 50-416.83/09/23, 8310170167
- 8310060227 Responds to 830828 request re reasons for length of extended outage Substantial mods to drywell cooling capability indicated during non-nuclear heatup. Mods included extensive design & installation work MCGAUCHY. J P Mississippi Power & Light Co 83/09/30 DENTON. H R Office of Nuclear Reactor Regulation, Director 4pp 20647 094 24X Fiche 50-416,83/09/30,8310060227
- 8310120444 Responds to NRC 830819 concerns over isolation of instrument air sys & response of certain components Isolation of instrument air will not prevent accident mitigation under present design DALE.L. F. Mississipi Power & Light Co. 83/10/04 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 20698 254 24X Fiche 50-416,83/10/04,8310120444.
- 8310120281 Confirms installation of mechanical pressure gauge on automatic depressurization sys air makeup line & performance of associated surveillance
 DALE,L F Mississippi Power & Light Co 83/10/07 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 20693-347, 24X Fiche 50-416.83/10/07.8310120281.
- 8310120436 Application to amend License NPF-13, revising changes to proposed Tech Specs to update Table 3 7 4-2 re safety-related mechanical snubbers Change involves NSHC DALE, L.F. Mississippi Power & Light Co. 83/10/07 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director 2pp. 20498 260 24% Fiche 50-416,83/10/07.8310120436
- --8310120438 Revised changes to proposed Tech Specs updating Table 3 7 4-2 re safety-related mechanical snubbers 4 Mississippi Power & Light Co 83/10/07 15pp 20698 262 24X Fiche 50-446.83/10/07,8310120436
- 8310130117 Application for amend to License NPF-13, revising Tech Baecs to change Action 50 of RGIC sys actuation instrumentation to reflect only one trip sys MCOAUGHY, J P Mississippi Power & Light Co 83/10/11 DENTON, H R Defice of Nuclear Reactor Regulation, Director 4pp 20725 053 24X Fiche 50-416,83/10/11,8310130117
- ---8310130121 Proposed Tech Bpsc Table 3 3 5-1 rs RCIC sys actuation instrumentation # Mississippi Power & Light Co. 83/10/11 2pp 20725 057 24X Fiche 50-416,83/10/11,8310130117.
- 8308310050 Board Notification 83-160, provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENHUT, D 9 Division of Licensing 83/10/14 PALLADING, N J , OILINSKY, V , ROBERTS, T Commissioners 15pp 20966-312 24X Fiche 50-000, 83/10/14, 8308310050
- 8310180306 Forwards responses to informal NRC concerns on containment structural integrity test per 830706 conference w/Bechtel & NRC Test performed in compliance w/provisions of Reg Quide i 18.Rev 1 DALE: U.F. Mississippi Power & Light Co 83/10/14 DENTON, H.R Deffice of Nuclear Reactor Regulation, Director 30pp 20806.295 24X Fichs 30-416,83/10/14,8310180306
- 8310180352 Forwards addl info re fuel assembly liftoff, schedule for implementing mitigating measures for interprenular stress corrosion cracking & dynamic qualification of equipment per 831004 request, Info will be incorporated into FSAR update DALE, L. F. Mississippi Power & Light Co. 83/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. Spp. 20803:147 24X Fiche. 50-416, 83/10/14. 8310180352
- 8310190037 Forwards response to 830912 request for info re min number of operable channel requirements for isolation actuation instrumentation. Due to revisu to provide info, util identified need to modify procedures. Tech Spacs & FSAR DALE, L. F. Mississippi Power & Light Co. 63/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp. 20823 167 24% Fiche 50-416, 83/10/14, 8310190037.

- B310260276 Forwards info to assist in NRC evaluation of adequacy of hydrogen control sys to support full-power operation info provided includes scaling of convective heat fluxes & addi CLASIX-3 & MARCH analyses.

 DALE.L. F Mississippi Power & Light Co 83/10/17 DENTON.H R Office of Nuclear Reactor Regulation, Director 162pp 20711 140 24X Fiche 50-416,83/10/17.8310260276
- 8310260220 Provides add1 info re qualification of automatic depressurization sys (ADS) accumulator & related air sys, in response to 830811 ltr ADS leak test frequency of 18 months anticipated DALFIL F Mississippi Power & Light Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20912 113 24X Fiche 50-416,83/10/24,8310260220
- 8310310044 Forwards revised FSAR App 13A incorporating staff changes involving key personnel Info will be incorporated into next FSAR amend DALE L.F Mississippi Power & Light Co 83/10/26, DENTON, H R Office of Nuclear Reactor Regulation, Director 32pp 20951 049 24X Fichs 50-416,83/10/26,8310310044
- @ Inspection reports, IE Bulletins & correspondence
- 8310250389 Provides supplemental final response to viplation noted in IE Insp Rept 50-416/83-12 Bechtel GA svaluated & verified that corrective actions respond to concerns raised All corrective actions completed on 830607 MCGAUGHY.J P. Mississippi Power & Light Co 83/06/15 G*REILLY.J P Region 2. Office of Director. 2gp 20898 145 24% Fiche: 50-416, 83/06/15, 8310250387
- 8310250262 Responds to NRC 930727 ltr re violations noted in IE Insp Rept 50-416/83-30 Corrective actions surveillance testing activity completed on Div I load shedding & sequencing panels & M&TE removed DALE: L F Mississippi Power & Light Co. 83/08/26 D'REILLY, J P Region 2. Office of Director 2pp 20898 235 24X Fiche. 50-416, 83/08/26, 8310250262
- ~-8310250268 Forwards IE Insp Rept 50-416/83-30 on 830616-0714 & notice of violation
 LEWIS.R C. Division of Project & Resident Programs 83/07/27 RICHARD.J B Mississippi Power & Light Co 2pp 20898 237 24x Fiche 50-416,83/08/26.8310250262
- --8310250247 Notice of violation from insp on 830616-0714 * Division of Project & Resident Programs 83/07/27 ip 20898:237 24X Fiche 50-416,83/08/26,8310250262
- --8310250271 IE Insp Rept 30-416/83-30 on 830616-0714 Noncompliance noted failurs to perform iOCFR50, 59 review.

 WAONERAG Region 2, Office of Director QUICK, D.R. Division of Project & Resident Programs, 83/07/26, 7pp 20898:240 24X Fiche 50-416.83/08/26,8310250262
- 8310040163 Forwards IE Insp Rept 50-416/83-37 on 830822-24 No noncompliance noted VERRELLI, D M Division of Project & Resident Programs 83/09/08. RICHARD, J B. Mississippi Pawer & Light Co. Epp 20608, 204 24X Fiche, 50-416, 83/09/08, 8310040163
- --B310040167 IE Imap Rept 50-416/83-37 on 830822-26 No noncompliance noted. Major areas inspected completed presperational & sys acceptance tests, proposed startup test & local leak rate test procedures
 BURNETT, P. T., JAPE, F. Region 2, Office of Director 83/09/06
 6pp 20608-208, 24X Ficher 50-416,83/09/08,8310040163
- 8310040502 Confirms 830723 mpt masting at Region II to discuss results of util investigation of Agastat relay failures, proposed corrective artion & other topics Proposed meeting agenda encl.

 LEWIG-R.C. Division of Project & Resident Programs 83/07/21
 REGIOARD, J.B. Mississippi Power & Light Co 200 20622 340 24X
 Fiche: 50-416, 83/07/21, 8310040502.
- 8310280439 Forwards 1E Insp Rept 50-416/83-39 on 830830-0902 No noncompliance noted VERELLI, D. M. Division of Project & Resident Programs. 83/09/21 RICHARD. J. B. Mississippi Power & Light Co. 2pp 20897-046. 24) Fiche. 50-416, 63/09/21, 6310250439.
- ---B310250452 IE Insp Rept 50-414/83-37 on B30830-0902 No noncompliance noted Major areas inspected: diesal generator engine, relays, relay bases, hydrablic control unit, solenoid valves & TMI Item II.D.3, "Coolant Bys Valve Test Requirements "HUNT, M.D. Region 2, Office of Director CONLON, T.E. Division of Engineering & Operational Programs. 63/09/20 Spp 20897 048 24X Fiche. 50-416, 83/09/21, 8310250439

- 8310040263 Concurs in planned schedule for attaining recriticality outlined in util 830829 & 0913 ltrs Items contained in NRC 821020 confirmation of action ltr verified as completed Conditions to satisfy concurrence listed 0'REILLY.JP Region 2. Office of Director 83/09/23 RICHARD, JB Mississippi Pawer & Light Co. 2pp. 20613 003 24X Fiche 50-416.83/09/23.8310040263
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Velder Gualification Tests" Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Past 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8303300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Cas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308500342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26,8308300345
- 8310040528 Confirms 831004 mgt meeting at Region II oft to discuss vii) investigation of failure to conduct maint activities & other topics of current interest, per 830926 telcon Proposed meeting agenda encl
 0'REILLY, J P. Region 2, Office of Director 89/09/28 RICHARD, J B. Mississippi Power & Light Co. 2pp. 20624 029 24X
 Fiche 80-416,83/09/28,8310040528
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716:324 24X Fiche 50-000.83/09/29.8308308349
- 8310250214 Forwards IE Insp Rept 50-416/83-42 on 830912-16 No noncompliance noted VERRELLI,DM Division of Project & Resident Programs 83/10/04 RICHARD,J B Mississippi Power & Light Co 2pp 20893 310 24) Fichs 50-416,83/10/04,8310250214
- --8310250216 IE Insp Rept 50-416/83-42 on 830912-16 No noncompliance noted Major areas inspected emergency procedures, operating procedures & surveillance testing KRUG. H E. Region 2. Office of Director JAPE.F. Division of Engineering & Operational Programs 83/09/29 7pp 20893 312 24X Fichs 50-416.83/10/46.8310250214
- 8308300378 lE Info Notice 83-69, "Surveillance of Flow in RTD Bypass Loops Used in Mestinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07. 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JRBDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche, 50-000, 83/10/07, 8308300/52
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JORDAN, E. | Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Inc 117pp, 21043 075 24X Fichs 50-000,83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Englasering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc., 120pp. 20827,129, 24X Fiche 50-000,83/10/11.8308300761
- 9310170141 Forwards IE 9afeguards Insp Rept 50-414/83-40 on 830912-16 No noncompliance noted VERRELLI,D Division of Project & Resident Programs 83/10/11 RICHARD,J,B Mississippi Power & Light Co 2pp 20788 351 24X Fichs 50-416.83/10/11,8310170141
- --8310170149 IE Sefeguards Insp Rept 50-416/83-40 on 830712-16 No noncompliance noted Major areas inspected, review of security organization-response, security program audit, records & repts Details withheld (ref 10CFR73 21), ENNIS, J D Region 2, Office of Director MCOUIRE, D R Division of Emergency Preparedness & Materials Safety 83/10/06 ip 20788 353 24X Fiche 50-416,83/10/11,8310170141

- 8310210314 Forwards "Applicability of Shoreham Delaval Diesel/ Generator Crankshaft Failure to Grand Gulf Nuclear Station," in response to IE Info Notice 83-58 Rept concludes that failure will not occur at facility DALE.t. F Hississippi Power & Light Co. 83/10/19 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 7pp. 20851 154 24% Fiche 50-416.83/10/19.8310210314
- 6310310126 Forwards "Rept on Div I,II & III Diesel Generators," in response to NRC request & generic problems identified in IE Info Notice 83-51 CALE.L F Mississippi Power & Light Co 83/10/26 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 20949 110 24% Fiche 50-416,83/10/26,8310310126
- --8310310130 "Rept on Div I.II & III Diesel Generators "
 STALSBERG,D . HARDESTY,D . TAYLOR.J Mississippi Power & Light Co
 83-024 83/10/22 56pp 20949 112 24X Fiche 50-416,83/10/26,
 8310310126
- A Periodic operating reports & related correspondence
- 831019000& Monthly operating rept for Sept 1983 H/831014 ltr CESARE. J G : DALE. F Mississippi Power & Light Co 83/10/15 DEYOUNG.R C Director's Office Office of Inspection and Enforcement 8pp 20823 110 24X Fichs 50-416,83/10/15.8310190006
- S Aeportable occurrences, LERs & related correspondence
- 8309060068 LER B3-107/03L-0 on B30727.Div I dissel generator turbecharger mounting buits found loose, broken & missing during 24 h test run Caused by cracked welds on intercooler adapter between intercooler & turbocharger H/B30826 ltr CATHEY, D E , DALE, L F Mississippi Power & Light Co 83/08/26 O'REILLY, J P Region 2, Dffice of Director 3pp 20262 105 24% Fiche 50-416,83/08/26,8309040068
- 830 PO 90416 RO 83-072/O on 830729, 30 & 0814-16 control room air temp excepted Tuch Spac limit Caused by lack of operating control room HVAG subsystems & low Freen in subsystem 8, respectively No corrective action stated DALE, L.F. Mississippi Power & Light Co. 83/08/27 0'REILLY, J. P. Region 2, Office of Director 2pp 20314 348 24X Fiche 50-416, 83/08/27, 8309090416
- 8310030276 LER B3-123/017-0 on 830706, inadequate design flow paths identified from drywell cooler drip pans to leak detection against Caused by inadequate sys design Mods completed, W/B30920 ltr BYRO.R . BALE.I. F. Mississippi Power & Light Co. 83/09/20 O'REILLY, J.P. Region 2, Office of Director. 4pp. 20591 031 24X Ficher 50-416, 83/09/20, 8310030276
- B310030438 Updated LER 83-113/03X-1: on 830729, standby fresh air unit 8 to control room intentionally lost w/simulated loss of power Caused by performance of ECCS loss of power surveillance test Unit restarted W/830920 Itr CATHETY, D., DALE, L. F. Mississippi Power & Light Co. 83/09/20 D'REILLY, J. P. Region 2, Office of Director 3p 20602 091 24X Fichs 50-416,83/09/20.8310030438
- 8310030472 Updated RO 83-066/1 on 830709 & 13, triaxial peak recording accelerograph used for seismic monitoring of auxiliary bldg foundation & reactor vessel support failed surveillance New Enstruments installed DALE.E. F. Mississippi Power & Light Co. 83/09/20 D'REILLY, J.P. Region 2, Office of Director 2pp. 20601 099 24X Fiche 80-416,83/09/20.8310030472
- B310030470 LER B3-122/017-0 on B3070B, discovered valve P64F461, which supplies operating pressure to carbon dioxide protection asstar splector volve, closed Causad by personnel error Valve lacked open & procedure revised W/B30920 ltr SYRD, M., DALE, L. F. Mississippi Fower & Light Co. B3/09/20 D'RETLLY, J.P. Region 2. Office of Director. 3pp. 20601 083. 24X Fiche 50-416,83/09/20,8310030490
- 33:0030317 LER B3-127/03L-0 on 830822 during surveillance testing, control room ventilation radiation monitor channel B & channel C hi-hi setpoints exceeded allowable values Caused by instrument drift W/830921 ltr CATHEY. D E . DALEL F Missipsippi Power & Light Co 83/09/21 O'REILLY, J P. Region 2, Office of Director 2pp 20591 001. 24X Fiche 30-416,83/09/21.8310030317
- 310030325 RD 83-083/0 on 830817, penetration AP-126C at southwast stairwell of euxiliary bldg on Elevation 139 ft.discovered open Fire watches maintained until penetration restored on 830827 DALE.L F Mississippi Power & Light Co 83/09/21 D'REJLLY, J P Region 2, Office of Director 2pp 20590 352 24X Fiche 50-414, 63/09/21, 6310030325

- 8310030373 Final & interim defictioncy rept for Units 1 & 2, respectively re incorrect operation of Div I & II diesel generator load shedding & sequencing sys panels w/automatic test feature on line Initially reported 830721 Also reportable per Part 21 MCGAUGHY. J P Mississippi Power & Light Co 83/09/21 O'REILLY. J P Region 2, Office of Director 4pp 20593 083 24X Fiche 50-416.63/09/21,8310030373
- 8310030430 RD 83-084/0 on 830819, during performance of fire protection surveillance procedure, 16 of 20 G-rated fire dampers discovered, w/'8" shaped hoots connecting fusible links w/damper instead of required vice-crimped straps DALE, L.F. Mississippi Power & Light Co. 83/09/21 O'REILLY, J.P. Region 2. Office of Director 2pp. 20593 174 24X Fichs 50-416,83/09/21,8310030430
- B310040502 Confirms 630723 mgt meeting at Region II to discuss results of util investigation of Agastat relay failures, proposed corrective action & other topics Proposed meeting agenda encl
 LEWIS.R C Division of Project & Resident Programs 63/09/21.
 RICHARD.J R. Mississippi Power & Light Co 2pp 20622 360 24X
 Fiche 50-416.63/09/21.6310040502
- 8310030374 Second interim deficiency rept re failure of Agastat QP series relays to change state when called to operate Caused by svc aging in mild environ in combination w/mechanical configurations & tolerances of internel parts
 MCGAUGHY, J. P. Mississippi Power & Light Co 83/09/22
 07HELLY, J. P. Region 2, Office of Director 5pp. 20592, 190 24X
 Fiche 50-416,83/09/22:8310030374
- 8310030461 PND-II-83-078 on 830725, recriticality echieved after 1-yr shutdown to modify drywell cooling sys & other Areas Low power physics testing will be conducted during next 3-wk period WATBON, L. JULIAN, C.A. Region 2, Office of Director 83/07/26 1 20601 048 24% Fiche 50-416, 83/07/26, 8310030461
- 8310070169 RO 83-085/0 on 830823, latch to Fire Door ID302 of Div 1 diesel generator room damaged Fire watches established.per Tech Bpc 3 7 7 until door restored on 830910 DALE.L F Mississippi Power & Light Co 83/09/26 O'REILLY, J P. Region 2, Office of Director ip 20659, 110 24% Fiche 50-416, 83/09/26, 8310070169
- 8310070170 LER 83-128/01T-0 on 830912.during routine maint.control bldg fire rated penetrations CE428B & CE77E found unswaled.Cause Unknown Penetrations rescaled.Investigation continuing W/830926 ltr
 BYRD.R. DALE.L.F. Mississippi Power & Light Co. 83/09/26
 D'REILLY.J.P. Region 2. Office of Director. 3pp 20659 111. 24X
 Fiche 50-416.83/09/26.8310070170
- 8310070192 LER 83-132/03L-0 on B30827, component cooling water radiation monitor failed to meet calibr procedure. Caused by out-of-tolerance count rate meter readings due to faulty diodes & capacitors in circuit W/830926 ltr
 BYRD.R, DALE, L.F. Hississippi Power & Light Co. B3/09/26
 0 (REILLY, J.P. Region 2, Office of Director. 2pp. 20659.115 R4X
 Fichs 50-416,83/09/26,8310070192
- 8310070239 LER 83-129/03L-0 on 830827. HPCB diesel generator tripped due to high jacket water temp Caused by personnel error Standby svc water valves reopened W/830926 ltr GATHEY.D E. DALE,L F. Mississippi Power & Light Co. 83/09/26 O'REILLY,J P. Region 2. Office of Director, 3pp. 20658, 338, 24X Fiche, 50-416, 83/09/26, 8310070239
- 8310070305 Updated LER 83-084/03X-1 on 830718, unenticipated activation of Div II LOCA logic occurred All automatic actions occurred except for RHR pump C. Caused by malfunctioning inverter for LOCA signal Inverter replaced W/830726 ltr
 BYRD,R, DALE,L,F. Mississippi Power & Light Co 83/09/26
 0/REILLY,J,P. Region 2, Office of Director App. 20651 089, 24%
 Fiche. 50-416. 83/09/26. 8310070308.
- 8310040364 LER 83-130/03L-0 on 830829, shutdown cooling sys isolated twice when suction valve received erroneous isolation signals Caused by personnel error Update rept expected by 831215 W/830928 ltr
 8YRD.R , DALE.L F. Mississippi Power & Light Co 83/09/28,
 0 'REILLY.J P Region 2. Office of Director 3pp 20620 277, 24X Fiche 50-416,83/09/28,8310040364
- B310040417 LER B3-131/01T-0; on B30913, w/radioactivity monitors inoperable, Action 110 of Tech Spec 3 3 7 11 not fully met Caused by personnel error Chemist reinstructed on requirements W300928 itr.
 BYRD,R, DALE,L F Mississippi Power & Light Co B3/09/28
 0 'REILLY,J,P Region 2, Office of Director, Spp 20619 172, 24X Fiche: 50-416, 83/09/28, 8310040417.

- B310060001 LER 83-135/03L-0 on 830913, temporary connection from discharge of Div 2 diesel generator starting air storage tank D to Div 1 diesel generator made w/o proper review Caused by personnel error W/830928 ltr BYBD. R. DALE.L.F. Mississippi Power & Light Co. 83/09/28 O'REILLY, J.P. Region 2, Office of Director 4pp. 20648 359 24X Fichs 50-416,83/09/28,8310060001
- 8310060002 Updated LER 83-094/03X-1 on 830711.RHR pump A breaker tripped during first test start after maint to clean rack to breaker auxiliary contacts Caused by misaligned breaker worm gear rod Rod realigned W/830728 ltr
 87RD.R. pALE.LF Mississippi Power & Light Co 83/09/28
 0 TREILLY.J P. Region 2. Office of Director 4pp 20649 277 24X
 Fithe 50-416.83/09/28.8310060002
- B310060112 LER B3-134/03L-0 on B30829, output of RPS reactor water level channel B loop discovered out of tolerance Caused by Instrument droff Instrument loop recalibr WB3092B its CATHEY, D E . DALE-L F Mississippi Power & Light Co B3/09/2B U-REILLY-J P. Region 2, Office of Director 2pp 2064B 342 24X Fiche 50-416, B3/09/2B, B310080112
- B310060401 LER B3-133/03L-0 on 630829 & 31.diesel generator declared inoperable when air receiver C pressure dropped below Tech Spec paig limit Caused by seepoint drift & sticking check vaive Relief valve replaced d/830728 ltr
 BYRD.R., DALE-L F Mississippi Power & Light Co 83/09/28
 0 'REILLY-J P Region 2. Office of Director 4pp 20646 121 24x
 Fiche 50-416.83/09/28.8310060401
- 8310060025 LER 83-136/03L-0 on 830830, Div I diesel generator shutdown when right bank 1 & left bank 5 cylinder exhaust gaskets failed. Crack & two broken welds discovered on intercoolers Caused by normal deterioration of gaskets W/830929 ltr CATHEY. D E , DALEL F. Hissassippi Power & Light Co 83/09/29 O'REILLY, J P Region 2, Office of Director 3pp 20648 356 24X Fiche 50-416,83/09/29,8310060025
- 83:0190257 LER 83-138/03L-0 on 830831. Div I diesel generator failed to automatically trip following unexpected high bearing temp alarm & was shutdown Caused by leaty pneumatic temp sensor mfg by California Controls Davice replaced W/830930 ltr CATHEY, D E. DALELL F. Mississippi Power & Light Co. 83/09/30 G.REILLY, J.P. Region 2. Office of Director 3pp. 20818 075 24X Fiche: 50-416, 83/09/30, 8310190257
- 8310120419 LER 83-140/03L-0 on 830902, power to Div I ESF bus intentionally removed to perform loss of power test on diesel generator Diesel generator auto started, but did not regulate bus voltage during load shedding M/831003 ltr. CATHEY, D E , DALE, L F Mississippl Power & Light Co 83/10/03 D'REILLY, J P Region 2, Office of Director. 4pp 20678 292 24X Fiche 50-416, 83/10/03, 8310120419
- B310140061 LER 83-142/03L-0 on B30903.RHR low pressure alarm trip unit A setpoint discovered less than Tech Spec limits Cause unknown. Instrument recalibr W/B31003 ltr CATHEY.D E. DALE,L F. Mississippi Power & Light Co. B3/10/03 O'REILLY,J P. Region 2. Office of Director 2pp. 2076B 005 24X Fiche 50-416,83/10/03.B310140061
- USIO140122 LER 83-14i/OIT-0 on 830919, determined containment spray timers could operate less conservatively than Tech Spec Limit Caused by containment spray & core cooling mades functioning w/less conservative limits W/831003 ltr BYRD, R. . DALEL F. Hississippi Power & Light Co. 83/10/03 O'REILLY, J.P. Region 2. Office of Director Spp. 20763 082, 24X Fichs 50-416,83/10/03,8310140122
- 8310170474 LER 83-137/03L-0 on 830901, after shifting reactor protective says power supply to alternate source for surveillance testing, supply breater tripped, causing isolation of shutdown cooling, reactor half-scram & control room SFAU W/831002 ltr BYRD,R., DALE,L.F. Mississippi Power & Light Co. 83/10/03 D'REILLY,J.P. Region 2, Office of Director 3pp. 20783 284 24X Fichs 50-416,83/10/03.6310170474
 - O170408 RD 83-088/0. on 830904, control room temp exceeded 77 Fimit Upper cabinet area on elevation 189 ft of control room 189 also exceeded limit Excessive temps sporadic from 330904-10. Cause under investigation JALE, L F Hississippi Power & Light Co 83/10/04 D'REILLY, J P tegion 2. Office of Director 2pp 20779 159 24X
 - 140051 Updated LER 83-136/03X-1. on B30B30, Div I diesel generator ytdown when right bank 1 & left bank 5 cylinder eshaust lasts failed & cracked Two broken welds discovered on iercoolers. Causad by losse manifold bolts W/G31005 ltr (PEY. D E , DALE. L F Mississippi Power & Light Co 83/10/05 EEILLY, J. P. Region 2. Office of Director 3pp. 20768, 269. 24x he 50-416, 83/10/05, 8310140051

- B310140075 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re-potential rupture of high pressure fuel injection lines on Div I & II diesel generators during engine operation Also reportable under Part 21 for Unit 1 MCGAUGHY.J P Mississippi Power & Light (a 83/10/45 O'REILLY,J P Region 2, Office of Director 5pp 20/68 O'JH 4/4x Fiche 50-416.83/10/05.83101400/5
- 8310140160 RD 83-08//O on 830831. Fire Door 1A204 blocked open to support planned maint activities Fire watches established per Tech Specs until door restored on 630910 DALE.L F Mississippi Power & Light Co G3/10/05 D'ARTHLY. J P Region 2. Office of Director ip 20765 070 24% Fiche 50-416.83/10/05.8310140160
- B310140169 RO 83-086/O on B30829, listed fire barriers apened to support planned maint activities fire watches ustablished & bairiers restored DALE, L. F. Mississippi Power & Light Co. 83/10/05 10'RFILLY, J. P. Region 2, Office of Director 2pp. 20769 071 24X Fiche 50-416,83/10/05,8310140169
- 83i0170498 Updated LER 83-089/03X-1 on 83070B discovered carbon dividing the detector surveillance test did not exist Caused by delays w/ongoing surveillance review program Procedure issued on 830720 & completed on 830712 W/031005 ltr CATHEY.D E , DALE.L F Mississippi Power & Light Co 83/10/05 O'REILLY, J F Region 2, Office of Director 3pp 20/83 247 24x Fiche 50-416.83/10/05.8310170458
- 9310170512 Updated LER 83-078/03X-1 on 830/01, diesel generator tl ail receiver pressure could not be maintained greater than fech Spec limit Caused by relief valve sotpoint drift Valves to be replaced by B31231 W/B31005 ltr BYRD.R. DALE.L. F. Mississippi Power & Light Co. (33/10/05 O'REILLY, J. P. Region 2, Office of Director. 3pp. 20/84 236. 44X Fiche 50-416,83/10/05,8310170512
- 83i0170400 Final Deficiency Rept PRD-B3/15 to defective Sprague Type 40D capacitor on Brown Boveri Electric low voltage circuit breakers equipped w/solid state trip devices Initially reported on B3i002 Also reportable per Part 21 MCGAUGHY.J P Mississippi Power & Light Co B3/10/10 G/REILLY.J P Region 2. Office of Director 3pp P07B5 0R0 24X Fiche 50~416,83/10/10.83i0170400
- 8310190109 LER 83-144/03L-0 on B30911, loop A of RHR sys piaced in shutdown cooling made while standby syc water loop A radiation monitor inoperable Cause under investigation Radiation monitor reworked & returned to syc W/B31011 ltr BYRD,R . DALEL F Mississippi Power & Light Ca B3/10/11 O'REILLY,J P Region 2, Office of Director 2pp. 20022 105 24X Fiche 50-416.83/10/11.8310190109
- 8310210017 LER 83-143/01T-0 on B3092B, component rooling water process radiation monitor sample pump found not operating properly Cause of pump being secured not yet identified Pump restarted Pumps added to daily surveillance W/B31011 ltr BYROR, P. DALE, L. F. Mississippi Power & Light Co B3/10/11 G'REILLY, J.P. Region 2, Office of Director 3pp 20055 333 P4X Fiche 50-416.83/10/11.8310210019
- 8310270397 Updated LER 83-080/03X-1 on 830626, due to problems w/HVAL systemp in control room exceeded required limit sevaral times Caused by malfunctioning condensor cooling water flow control valve Limit switch adjusted W/831011 ltr BYRD, R . DALEL F Mississippi Power & Light Co 83/10/11 O'REILLY, J P Region 2, Office of Director 3pp 20724 025 24X Fiche 50-416,83/10/11.8310270397
- B310190098 Updated LER 83-092/03X-1 on 830709 discovered inappropriate maint retest performed on 830708 for both control room chlorine detectors 8ys released for work at same time on 830707 Caused by personnel error W/831012 itr CATHEY.D.F. DALE.L.F. Mississippi Power & Light Co. 83/10/12 D'REILLY.J.P. Region 2. Office of Director App. 20822 113 24X Fiche 50-416,83/10/12,8310190078
- 8310170111 Updated LER 83-095/03X-1 on 830713. during Div 1 standby diesel generator functional test, diesel tripped on high Jacket water temp Caused by temp switch out of calibr due to loose set screw Switch adjusted W/831012 ltr.
 BYRD, R., DALELL F. Mississippi Power & Light Co. 83/10/12
 O'REILLY, J. P. Region 2, Defice of Director. 3pp. 20821 101 24X
- 8310190234 Updated LER 83-136/03X-2 on 830830, during 24 h surveillance test run, Div 1 diesel generator shutdown when right benk 1 k left bank 5 cylinder exhaust gaskets failed & crack & two broken welds discovered on intercoolers W/831012 ltr CATHEY, D E , DALE, L F Mississippi Power & Light Co 83/10/12 O'REILLY, J P Region 2, Office of Director 4pp 20818 056 24X Fiche 50-416, 83/10/12, 8310190234

- 8310240247 Forwards request for add1 info re inoperable Agastat relays identified during recent surveillance testing SCHACKCEN.A Licensing Branch 2 83/10/13 MCOAUGHY.J.P. Mississippi Power & Light Co. 4pp. 20907 399 249 Fiche 50-416.83/10/13.8310240P47
- 8310270167 RD 83-073/0 on 830914 & 15, control room upper cable spreading room ambient air temp exceeded area temp limit of 77 F in Tech Spri 3 7 8-1 c duiling 36 h period Max qualification temp not exceeded DALE.L F Mississippi Power & Light Co 83/10/14 O'REILLY, J P Rigion 2, Office of Director 2pp 20924 171 24X Fishe 50-416,83/10/14,8310270167
- 8310270229 RD 83-070/0 on 830910 during surveillance testing file Doors 1A320 & OCRIL found inoperable & Fire Door 1A320 in auxiliary bidg could not be locked Locking mechanism & hinges replaced Hourly fire watch established for durabidn DALE.L F Mississippi Power & Light Co 83/10/14 O'REILLY, J P Region 2. Office of Director 2 pp 20924 068 24X Fiche 50-416.83/10/14.8310270229
- 8310270037 RO 83-09210 on 830710, listed control room fire-rated penetrations opened to implement design change package Fire watch established Penetrations resealed on 831007 DALE;t. F Mississippi Power & Light Co. 83/10/17 O'REILLY, J P Region 2. Office of Director 2pp 20924 336 24X Fiche 50-416,83/10/17,8310270037
- 6310270140 RO 83-071/0 on 830910, during surveillance testing, Fire Door OC713 on elevation 189 ft in control bldg found w/o lock Fire Door OC713 not designed to lock Door deleted from Procedure 06-0P-8964-W-0045, Roy 20 Fire watch established DALE, L. F. Mississippi Power & Light Co. 83/10/17 O'REILLY, J. P. Reglan 2. Office of Director 2pp. 20924 182 24X Fiche 50-416, 83/10/17, 8310270160
- E310270336 LER 83-145/03L-0 on 830915.Div II diesel generator starting air pressure dropped below 160 psig Windings in electric actor overheated & shorted Caused by incorrect pressure signal tap location Motor replaced W/831017 ltr CATMEY.D E. DALE.L F. Mississippi Power & Light Co. 83/10/17 D'REZILLY.J P. Region 2. Office of Director 2pp. 20923 143 24X Fiche 80-416.83/10/17.8310270334
- 8310270433 Final Deficiency Rept PRD-83/12 for Unit i & interim rept for Unit 2 re failure of Agastat GP series relays to switch Initially reported on 83092 Deficiency reportable per Part 21 for Unit 1 Investigation ongoing for Unit 2 HCGAUGHY, JP Hississippi Power & Light Co 83/10/17 GPEILLY, JP Region 2, Office of Director 5pp 20923 044 24% Fiche 50-416,63/10/17,6310270433
- ESIO210182 LER 83-139/03L-0 on 830912. Div 1 reactor protective sysmotor generator set tripped causing half scram signal & loss of shutdown cooling Caused by motor winding short Motor replaced W/831011 ltr
 BYRD.R. DALE.L.F Mississippi Power & Light Co 83/10/18
 0-REILLY.J.P Region 2. Office of Director 2pp. 20856-122 24X
 Fiche 30-416,83/10/18.8310210182
- 8310270235 LER 83-146/03L-0 on 830918, alarma failed to annunciate following shutdown cooling loop pump B trip due to isolated surtion valve Caused by open circuit breaker investigation centinuing Updated rept expected by 831130 W/831018 ltr BYND.R. DALE.L.F Mississippi Power & Light Co 83/10/18 0.REILLY.J.P Region 2. Dffice of Director 2pp 20924 045. 24X Fiche 50-416.83/10/18.8310270235
- 8310260186 Part 21 rept re potentially defective Presnay airlock seal in drywell personnel airlock supplied by WJ Woolley Initially reported by vendor on 830719 New seal being designed by Presnay Corp will be installed when available DALE.L. F. Mississippi Power & Light Co. 83/10/24 DENTON. H.R. Office of Nuclear Reactor Regulation. Director Spp. 20719 250 24% Fiche 50-416.83/10/24.8310260186

/ Operator Examinations

310040494 Discusses operator & senior operator requalification exams on 830729,0816 & 17 Summary of exam results encl W/o encl VERRELLI,D M Division of Project & Resident Programs. 83/08/29. RICHARD,J B Mississippi Power & Light Co 2pp. 20625,160 24X Fiche 50-416,63/08/29,8310040494

- DOCKET 50-417 GRAND QULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8310040046 Forwards request for addl info re 830610 GA program update LEWIS.R C Division of Project & Resident Programs 83/09/23 RICHARD.J B Mississippi Power & Light Cn 5pp 20608 138 24X Ficks 50-416.83/07/23.8310040046
- 8310120444 Responde to NRC 830819 concerns over isolation of instrument air sys & response of certain components Isolation of instrument air will not prevent accident mitigation under present design DALE-L F Mississippi Power & Light Co 83/10/04 DENTON, H R. Office of Nuclear Reactor Regulation, Director, 4pp 20698 254 24X Fiche 50-416, 83/10/04, 8310120444
- 8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delayal emergency diesel generators at Shoreham EISENHUT, D. G. Division of Licensing 83/10/14 PALLADIND, N. J. GILINGKY, V. J. ROBERTS, T. Commissioners 15pp. 20766 312 24x Fiche 50-000,83/10/14,8308310050
- 8310180352 Forwards add1 info re fuel assembly liftoff, schwdule for implementing mitigating measures for intergranular stress corrosion cracking & dynamic quelification of equipment per 831004 request info will be incorporated into FSAR update DALE.L F Mississippi Power & Light Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director. 6pp 20803 147 24X Fiche 50-416,83/10/14,8310180352
- 8310260220 Provides add1 info re qualification of automatic depressurization sys (ADS) accumulator & related air sys, in response to 830811 ftr ADS leak test frequency of 18 months anticipated DALE.L F Mississippi Power & Light Co 83/10/24 DENYON, H. R Office of Nuclear Reactor Regulation, Director 7pp 20912 110 24X Fiche 50-416, 83/10/24, 8310260220
- 8310310044 Forwards revised FSAR App 13A incorporating staff changes involving key personnel Info will be incorporated into next FSAR amend DALE L F Mississippi Power & Light Co 83/10/26, DENTON.H R Office of Nuclear Reactor Regulation, Director 32pp 20951 049 24X Fiche 50-416,83/10/26,8310310044
- E NRC Sofety Evaluation Report (SER), auppls & correspondence
- 83i0180330 Provides add1 info on SER Confirmatory Item 1 10(4) re soil structure interaction in fulfillment of commitments made in response to NRC 830i12 ltr Util committed to utilizing elastic half-space methodology.

 DALG/L F Miswissippi Power & Light Go 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20802, 348 24X Fiche 50-416,83/10/14,83101800330
- F Security, medical, emergency & fire protection plans
- 8310040394 Forwards summary of 830909 meeting in Region II after proposed physical security plan mods
 LEWISHR C Division of Project & Resident Programs 83/09/26
 RICHARD.J B Mississippi Power & Light Co 3pp 20619 041 24X
 Fiche: 50-416, 83/09/26, 8310040394
- B310180430 Forwards Rev 9 to physical security plan. Rev withheld (ref 10CFR2 790 & 10CFR9 5) DALELL F. Mississippi Power & Light Co B3/09/30 O'REILLY, J P Region 2, Office of Director 2pp 20803 297. 24X Fiche 50-416,83/09/30,8310180430
- B310120347 Advises that due to uncertainty in instrumentation availability & manpower resources, instrumentation necessary to meet Reg Quide 1 97 requirements will be implemented by third refueling outage per Suppl 1 to NUREQ-0737 DALE, L F Mississippi Power & Light Co B3/10/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 20700: 231, 24x Fiche 30-416, 83/10/10, 8310120349
- G Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl. JORDAN.E (Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340.

- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toric Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300042
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Syc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering
- encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/27 Consolidated Edison Co of New York. Inc. 115pp 20716-324 24% Firbe 50-000.83/09/29.8308300349
- 8308300378 IE Info Notice 83-65, "Survesilance of Flow in RTD Bypass Loops Used in Westinghouse Plants" Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Nev York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07,83083003/8
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Math Defect Causes Production of Notious Gases." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fich# 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enci enci JORDAN: E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310210314 Forwards "Applicability of Shoreham Delaval Diesel/ Oenerator Crankshaft Failure to Grand Gulf Nuclear Station," in response to IE Info Notice 83-58 Rept concludes that failure will not occur at facility DALE.L F Mississippi Power & Light Co 83/10/19, DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20851 154 24X Fiche 50-416,83/10/19.8310210314

B Reportable occurrences, LERs & related correspondence

- 8310030373 Final & interim deficiency rept for Units t & 2, respectively reincorrect operation of Div I & II diesel generator load shedding & sequencing sys panels w/automatic test feature on line Initially reported 830921. Also reportable per Part 21 MCGAUGHY, J P Mississippi Power & Light Co 83/09/21 O'REILLY, J P Region 2, Office of Director 4pp 20593 083 24X Fichs. 50-416, 83/09/21, 8310030373
- 8310140075 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re potential rupture of high pressure fuel injection lines on Div I & II diesel generators during engine operation Also reportable under Part 21 for Unit 1 MCGAUGHY, J P Mississippi Power & Light Co 82/10/05 D'REILLY, J P Region 2, Office of Director 5pp 20768 018 24X Fiche 30-416,83/10/05.8310140075
- 8310140007 Supplemental interim Deficiency Rept PRD-B1/29.Rept 2 re Temp Flex penetration bellows assemblies exhibiting cracked & broken welds between shroud support spokes & bellows and sleeves Initially reported on 810529 Final rept by 840815 MCGAUCHY.J.P Mississippi Power & Light Co 83/10/07 O'REILLY.J.P Region 2. Office of Director. 4pp 20768:056 24X Ficher 50-417.83/10/07.8310140007
- B310270439 Final Deficiency Rept PRD-83/12 for Unit I & interim rept for Unit 2 re fellure of Agastat OP series relays to switch. Initially reported on 830902. Deficiency reportable per Part 21 for Unit 1 Investigation ongoing for Unit 2 MCOAUCHY. J P Mississippi Power & Light Co 83/10/17 O'REILLY. J P. Region 2, Office of Director 5pp 20923.044 24X Ficher 30-416,83/10/17.8310270433

8310260186 Part 21 rept re potentially defective Presnay airlock seal in drywell personnel airlock supplied by WJ Woolley Initially reported by vender on 830919 New seal being designed by Presnay Corp will be installed when available DALE.L F Mississippi Power & Light Co 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 20915 250 24X Fiche 50-416.83/10/24,8310260186

V Operator Examinations

- 8310040494 Discusses operator & sensor operator requalification stans on B30729.0816 & 17 Summary of exam results encl W/o encl VERRELLI.D M Division of Project & Resident Programs B3/08/29 RICHARD.J B Mississippi Power & Light Co 2pp 20625 160 24X Fiche 90-416.83/08/29.8310040494
- DOCKET 50-423 MILISTONE NUCLEAR POWER STATION, UNIT 3

 A Application/construction stage decuments & correspondence
- 8310030335 Forwards remaining responses & corresponding FSAR changes to A40 series questions not forwarded by util 830829 ltr Responses will be formally submitted along w/Amend 5 by 831101 COUNSIL.H & Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.H & Northeast Utilities 83/09/27 YOUNGBLOOD, B J Licensing Branch 1 84pp 20590 219 24X Fiche 80-423,83/09/27,83100030335
- 8310050453 Notification of 831011 & 12 meetings in Waterford, CT to support NRC review of probabilistic safety study & to conduct site tour BOOLITTLE, E L Licensing Branch 1 83/09/28 YOUNGBLOOD, B J Licensing Branch 1 3pp 20450 034 24X Fiche 50-423, 83/09/28, 8310050453
- 8310170069 Authorizes use of ASME Code Case N-310-1 in const of component support bolting under Section 111.Div 1.Class I of code
 YOUNGBLOOD, B J Licensing Branch 1 83/09/30 COUNSIL. W @
 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pt
 20798 022 24X Fiche 50-483,83/09/30.8310170069
- 8310170190 Forwards Rev F to QA program manual Historical document containing all changes to QA manual since first edition issued in Aug 1973 ancl COUNSIL, H Q Northeast Utilities Sérvice Co COUNSIL, W G Northeast Utilities 83/09/30 MURLEY, T E Region 1. Office of Director 2pp 20787 116 24X Fiche 50-423,83/09/30,8310170190
- --8310170198 Rev F to GA program manual KELLY,R B . ALLEN,W F . SMITH L 8 Stone & Webster Engineering Corp 81/04/06 587pp 20787 118 24X Fiche 50-423,83/09/30. 8310170190
- 8310170193 Forwards request for add1 info re application for (IL resulting from review of FBAR & design basis response to Reg Outde 1 97, Rev 2 Response to Questions 230 6 & 420 6 required within 30 days of receipt of ltr YOUNOBLOOD, B J Licensing Branch 1 83/10/03 COUNSIL.W 6 Northeast Nuclear Energy Co (subs of Northeast Utilities) 8pp 20813 004 24X Fiche 50-423,83/10/03,8310170193
- 83i0170726 Forwards request for add1 info required to complete evaluation of environ & safety portions of application for OL Response requested within 30 days YOUNOBLODD, B J Licensing Branch I 83/10/07 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 10pp 20798 064 24% Fiche 50-423, 83/10/07, 8310170726
- B310170563 Deters responses to three acceptance review questions & Encl 4, Item 7 as committed to in B30331 & 0630 ltrs Rev to responses to Questions 311 1, 311 4 & 220 6 will be forwarded w/Amend 5 to F9AR in Nov 1983
 COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W G Northeast Utilities 83/10/11
 YOUNGBLOOD, B J Division of Licensing ip 20780 227 24X
 Fiche 50-423,83/10/11.8310170563
- 8310240044 Summary of 830602 meeting w/util,5&W & Westinghouse in Bethesde,MD to discuss objectives of Instrumentation & Control Bys Branch review process for DL application DOOLITHE,E L Licensing Branch i B3/10/11 Licensing Branch i 4pp 20703 234 24X Fiche 50-423,83/10/11,8310240044
- 8310310170 Notifies that NRC will conduct site visit on 831025-27 to obtain info re const *tatus Agenda encl YOUNOBLOOD, B J Licensing Branch i 83/10/18 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 20965 304 24X Fichs 50-423,83/10/18,8310310170

- 8310280112 Denies 830706 request for 120-day extension to respond to Deneric Ltr 83-28 re generic implications of Salem ATMS events NRC review schedule does not permit extension Response due by 831105 CAUTCHFIELD.D. Operating Reactors Branch 5 83/10/26 COUNSIL,W C Connecticut Yankee Atomic Power Co. 2pp. 20729 261 24X Fiche 50-000,83/10/26,8310280112
- S Utility Environmental Report (ER), amends & correspondence
- 8310040521 Forwards Amend 4 to environ rept OL stage COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 83/09/27 YOUNGELOOD, D J Licensing Branch 1 2pp 20621 229 24X Fiche 30-423,83/09/27,8310040521
- -83[004052] Amend 4 to environ rept OL stage * Northeast Utilities Service Co 83/09/23 79pp 20621 231 24% Fiche 50-423,83/09/27,8310040521
- E NRC Bafety Evaluation Report (SER), supply & correspondence
- B310110602 Requests technical editing assistance in preparing draft SER Draft SER inputs from technical review branches scheduled for submittal by 831101 w/draft SER to be issued on 831201 YOWNGELOOD, D. J. Licensing Branch 1 83/09/29 SINOH, N.H. Policy & Publications Management Branch 1p 20714 348 24X Fiche: 50-423, 83/09/29, 8310110602
- w Utility Final Safety Analysis Report (FSAR) & amends
- 8310040161 Forwards Amend 4 to FSAR, consisting of responses to splected requests for addl info COUNSIL.H G Northeast Nuclear Energy Co (subs of Northeast Utilities 83/09/30 YOUNGELOOD, IJ Licensing Branch I 2pp 20415 284 24X Fiche 50-423, 83/09/30, 8310040161
- --8310040164 Amend 4 to FSAR • Mortheast Nuclear Energy Co (subs of Northeast Utilities) 83/09/30 439pp 20618 286 24X Fiche 50-423,83/09/30, 8310040161
- 3 Inspection reports. IE Bulletins & correspondence
- 8309300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests." Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754-022 24X Fiche 50-000,03/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Officials Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDANEL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26.8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays." Svc list and JCROAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York. Inc 118pp 20778 001 24x Fiche 50-000,83/09/26,8308300345
- 8308300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys M/o 100FR50 57 Evaluation." Svc list encl JCRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Enc. 1159p 20716-324 24X Fiche, 80-000,83/09/29,8308300347
- B310190182 Forwards IE Insp Rept 80-423/83-10 on 830613-0731 No mancampliance noted.
 STAROSTECKI.R Blytsion of Project & Resident Programs 83/10/03.
 COUNSEL.H G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 2pp 20820 211 24X Fiche 50-423,83/10/03,8310190182
- "B3i0190188 IE Insp Rept 50-428/83-10 on 830413-0781 No noncompliance noted Major areas inspected EBF as-built comparison; severance of control cables, battery discharge & containment liner stud spacing requirements REBELONSKI,T., FORD,E J. Region 1. Office of Director ELEASER, T. Division of Project & Resident Programs 83/09/29, 7pp 20820 213, 24% Fiche. 50-423, 83/10/03, 8310190182.

- 8310180077 Forwards draft NRR BALP input for Sept 1982 Aug 1983
 Comments received by 831006 will be considered in final rept Category 2 assigned in area of licensing activities DOOLITILE.E L Licensing Branch 1 83707074 EISENHUT.D 0.
 Division of Licensing MATT80N.R J Division of Systems Integration (post 811005) VOLLMER, R H Division of Engineering 4pp 20827 036 24X Fishe 50-423.83/10/04.8310180077
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Swc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07, Consolidated Edison Co. of New York, Inc. 76pp. 20827 213 24% Fiche 50-000,83/10/07,8308300378
- B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752.
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Nuxious Gases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043:075 24X Fiche 50-000,83/10/11.8308300759.
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11, Consolidated Edison Co. of New York, Inc 120pp 20827-127 24% Fiche, 50-000, 83/10/11, 8308300761.
- S Reportable occurrences. LERs & related correspondence
- 8310070163 Part RI rept re potential defects in molded case of 100amp frame, multi-pole E & HE series circuit breakers. Initially reported on 830902 ERHARDT, J V Gould. Inc 83/09/26 MURLEY, T E Region 1. Office of Director 10pp 20659 095 24X Fiche 50-000, 83/09/26, 8310070163
- 831007030i Potential Part 21 rept re underrange characteristic of Model N-Ei10M transmitter. Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN.N J Foxboro Corp B3/09/30 Director's Office, Office of Inspection and Enforcement i tipp 20651 064 24X Fiche 50-000,83/09/30.8310970301
- DOCKET 50-424 ALVIN W VOGILE NUCLEAR PLANT, UNIT 1

 A Application/construction stage documents & correspondence
- 8310110374 Clarifies question contained in 830906 ltr which indicated PSAR sections referenced in FBAR Table 1 8-1 did not provide adequate evaluation of differences w/BRP. Format containing specific subsection devoted to BRP differences preferred, NOVAN-T.N Assistant Director for Licensing, 83/09/28, FDBTER, D. D. Georgia Power Co. 3pp 20713 222 24X Fiche 50-424,83/09/28.
- 8310180604 Forwards notice of receipt of 830713 OL application for CPPR-108 & CPPR-109 Notice sent for publication in FR ADENBAM, E. Q. Licensing Branch 4 83/10/11. F09YER, D. Georgia Power Co. 2pp 20817:347 24X Fithe 50-424,83/10/11.8310180604.
- --8310180606 Notice of receipt of 830913 OL application for CPPR-108 & CPPR-109, authorizing applicants to possess, use & operate two PMRs onsite at 3,411 MHz reactor core power ADENBAM, E 0 Licensing Branch 4 83/10/06 3pp. 20817:349 24X Fiche:50~424,83/10/11,8310180604.
- G3DG300778 Board Notification G3-135A forwards B30919 revised draft of "QA Case Btudy Norking Paper Case C." & cover & transmittal memos re Diablo Canyon.
 EISENNUT.D 9 Division of Licensing B3/10/14 PALLADINO, N J, OZLINSKY, V, ROBERTB.T Commissioners. 3pp. 20799, OCI 24X Fiche' 50-000, B3/10/14, B30B30078
- --8310180505 Informs that working papers for three QA case studies complete, per 830923 memo. Case C re Diablo Canyon, dtd 830919, is rev to 830719 fraft transmitted in Board Notification 83-135 on 830902, Papers & transmittel ltrs forwarded, TAYLOR, J M. QA Branch. 83/09/28, EISEMMUT. D. © Division of Licensing. 2pp 20799, 004 24x Fiche, 50-000, 83/10/14, 8308300775.

- 8310190125 Forwards application for amend to CPPR-108 & CPPR-109, authorizing sale of add1 5% undivided interest to Municipal Electric Authority of Georgia FORTER: D 0 Georgia Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20821 124 24% Fiche 50-424,83/10/14,8310190125
- --B310190126 Application for amend to CPPR-108 & CPPR-109, authorizing sale of add1 5% undivided interest to Municipal Electric Authority of Georgia FUSTER, D D Georgia Power Co B3/10/14 3pp 20821 125 24X Ficha 50-424,83/10/14,8310190125

M Antitrust correspondence

- 8310210106 Forwards FR notice of receipt of antitrust info associated w/application for OLs ADENSAM.E G Licensing Branch 4 83/10/13 FOSTER.D Georgia Power Co 2pp 20883 323 24X Fiche 50-424,83/10/13.8310210106
- ~-83102(0109 Notice of receipt of antitrust info associated w/application for OLs ADENBAN E. G. Licensing Branch 4 83/10/07 Rpp 20883 325 24X Fiche 50-424,83/10/13.8310210106
- O Inspection reports. IE Bulletins & correspondence
- 8310040215 Forwards IE Insp Repts 50-424/83-17 & 50-425/83-17 on 830711-0815 No noncompliance noted DANCE.H C. Division of Project & Resident Programs 63/09/01. KELLY.R J. Georgia Power Co. 2pp. 20614 266 24X Fiche: 50-424,83/09/01,8310040215
- --8310040222 IE Insp Repts 50-424/83-i7 & 50-425/83-17 on 8307i1-0815 No noncompliance noted Major areas inspected observation of work in progress re fitting & welding NSSB primary coolant piping & sturage of critical equipment SANDERS.W F Region 2. Office of Director PANCIERA.V Division of Project & Resident Programs. 83/09/01 5pp 20614 268. PAX Fichs 50-424.83/09/01.8310040215
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wolder Qualification Tests " Syc list encl JURDAN 6.4. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fichs 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp. 20777:210 24X Fichs 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl.

 JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 1188p 20778-001 24K Fiche 50-000,83/09/26,8308300345
- 8310040588 Forwards summary of 830822 mgt meeting at util headquarters of re findings concerning investigation of subcontractor QA performance at plant List of attendees also encl GYREILLY, J. P. Region 2, Office of Director. 83/09/28 KELLY, R. J. Georgia Power Co. 4pp 20626 236, 24X Fiche 50-424,83/09/28,8310040588
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Sefety-Related Sys W/o 100FR50 59 Evaluation " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29, Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24x Fichs 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Mestinghouse Plants " Svc list encl. JDRDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp. 20827-213 24% Ficher 50-000,83/10/07,8308300378
- 308300782 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Syc list encl.
 JORDAN E L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/10/07. Consolidated Edison Co. of New York
 - 8300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect auses Production of Noxious Gases " Svc list encl ORDAN, E. L Division of Emergency Preparedness & Engineering esponse (Post 830103). 89/10/11, Consolidated Edison Co of New ork, Inc 117pp. 21043.075. 24x Ficher 50-000,83/10/11,8308300759

- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defective Self-Contained Breathing Apparatus Air Cylinders" Sec list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Int. 120pp 20827 129 24X Fiche 50-000, 83/10/11, 8308300761
- S Reportable occurrences, LERs & related correspondence
- 8310120296 Interim deficiency rept re Brown Bovers reactor coolant pump switchgear reported in GN-247 Resolution rescheduled from 830923 to 1014 due to delay in regimeering evaluation FDSTER, D. D. Georgia Power Co. 83/09/28 0'REILLY, J.P. Region 2. Office of Director ip 20692 338 24% Fiche 50-424, 83/09/28, 8310120296
- B310170566 Deficiency & Part 21 repts re GE BFF~30 relays Evaluation concluded deficiency & substantial safety hazards do not exist
 FOSTER, D D Georgia Power Co B3/10/06 Q'REILLY, J P Region 2, Office of Director 1p 20780 189 24X Fiche 50~424, 03/10/06, 6310170966
- 8310270315 Interim deficiency rept re defective weld wire Engineering evaluation will be completed & conclusions re reportability will be submitted by 831028
 FDSTER.D D Georgia Power Co 83/10/17 O'REILLY, J P Director's Office, Office of Inspection and Enforcement 1p 20923 189 P4X Fiche: 50-424, 83/10/17, 8310270315
- U Congressional/Executive Correspondence
- B310200442 Responds to B30922 ltr re NRC handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers enc1
 PALLADINO.N J Commissioners B3/10/07 FORD.H H Senate 3pp 20871 295 24X Fiche 50-000,83/10/07.8310200442
- ~-8310200455 Expresses appreciation for cooperation w/IC activities to comply w/Congressional directive to NRC to perform GA studies Draft working paper for study encl
 TAYLOR, J M Division of GA, Bafeguards & Inspection Programs (Post 830103) 83/08/02 KELLY, R J Georgia Power Co 1p 20871 307 24X Fiche 30-000,83/10/07,8310200442
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8310110374 Clarifies question contained in 830906 ltr which indicated FSAR sections referenced in FSAR Table 1 8-1 did not provide adequate evaluation of differences w/SRP Format containing specific subjection devoted to SRP differences preferred NDVAK-T M Assistant Director for Licensing 83/09/28 FDSTER-D 0 Georgia Power Co 3pp 20713 222 24% Fichs 50-424.83/09/28, 83101103/4
- 8310180604 Forwards notice of receipt of 830713 OL application for CPPR-108 & CPPR-109 Notice sent for publication in FR ADENSAME O Licensing Branch 4 83/10/11 FORTER D Georgia Power Co 2pp 20817 347 24X Fiche 50-4R4,83/10/11,8310180604
- --8310180606 Notice of receipt of 830913 UL application for CPPR-108 & CPPR-109, authorizing applicants to possess, use & operate two PNRs onsite at 3,411 MHt reactor core power AJENSAM E G. Licensing Branch 4 83/10/06 3pp 20817 349 24X Fiche 50-424,83/10/11,8310180604
- B30B300775 Board Notification B3-135A forwards B30919 revised draft of "GA Case Study Horking Paper Case C," & cover & transmittal memor re Diablo Conyon ETSENHUT.D Q Division of Licensing 83/10/14 PALLADINO,N J Commissioners 3pp 20799 001 24% Fiche 50-000,B3/10/14, B30B300775
- --83]0180805 Informs that working papers for three QA case studies complete, per 830923 memo Case C re Diable Canyon, dtd 830919, is rev to 830719 draft transmitted in Board Notification 83-135 on 830902 Papers & transmitted ltrs forwarded TAYLOR, J. M QA Branch 83/09/28 EISENHUT, D G Division of Licensing 2pp 20799 004 24X Fichs 50-000, 83/10/14, 8308300775
- 8310170125 Forwards application for amend to CPPR-108 & CPPR-109, authorizing sale of add1 5% undivided interest to Municipal Electric Authority of Georgia FOSTER.D.O Georgia Power Co 83/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20821 124 24X Fiche 50-424,83/10/14.8310170125

--8310190126 Application for amend to CPPR-108 & CPPR-109, authorizing sake of addl 57 undivided interest to Municipal Lloctric Authority of Georgia FOBTER,D O Georgia Power Co 83/10/14 Spp 20821 125 pay Ficha 50-424,83/10/14,8310190125

M Antitrust correspondence

- 8310210106 Forwards FR notice of receipt of antitrust info associated w/application for ULs ABENSAMLE 9 Licensing Branch 4 83/10/13 FOSTER, D Georgia Pawer Co 2pp 20883 323 24% Fiche 50-424, 83/10/13 8310210106
- --8310210109 Notice of receipt of antitrust info associated w/application for OLs ADENSAN,C O Licensing Branch 4 03/10/07 2pg 20883 325 24X Fiche 50-424,83/10/13,8310210106

G. Inspection reports: IE Bulletins & carrespondence

- 8310040215 Forwards IE Insp Repts 50-424/83-17 & 80-425/83-17 on 830711-0815 No noncompliance noted DANCE,H C Division of Project & Resident Programs 83/09/01 KELLY,R J Georgia Power Co 2pp 20614 266 24X Fishe 50-424,03/09/01.8310040215
- --8310040222 IE Insp Repts 50-424/83-17 & 50-425/83-17 on 830711-0815 No noncompliance noted Major areas inspected observation of work in progress re fitting & welding NSSS primary coolant piping & storage of critical equipment SANDERS,W F Region 2, Office of Director PANCIERA,V Division of Praject & Resident Programs 83/09/01, 5pp 20614 268 24X Fiche 50-424,83/09/01,8310040215
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JERDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20784 022 24X Fiche 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308300345
- 8310340588 Forwards summary of 830822 mgt meeting at util headquarters ofere findings concerning investigation of subcontractor OA performance at plant List of attendees also encl O'REILLY, J P Region 2, Office of Director 83/09/28 KELLY, R J Georgia Power Co App 20626, 236 24X Fiche 50-424, 83/09/28, 8310040588
- 8308300347 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 57 Evaluation." 8vc list encl I JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716.324 24X Fiche 50-000.83/09/29.8308300347
- 8308300378 IE Info Notice 83-45, "Burveillance of Flow in RTD Sypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York. Inc 76pp 20827 213, 24% Fiche 50-000.83/10/07.8308300378
- B30B300752 IE Info Notice B3-66. "Fatality at Argentine Critical Facility " Bvc list encl JORDAN.E L Division of Emergency Praparadness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases," Byc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering Response (fost 830103) 83/10/11. Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " 8vc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11, Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761

S Reportable occurrences, LERs & related correspondence

- 8310120296 Interim deficiency rept re Brown Boveri reactor conlant pump switchgear reported in SN-247 Resolution rescheduled from 830923 to 1014 due to felay in engineering evaluation FOSTER, D D Georgia Power Co 83/09/28 D'REILLY, J P Region 2, Office of Director 1p 20692 338, 24X Fiche 50-424,83/09/28,8310120296
- 8310170566 Deficiency & Part 21 repts re GE BFF-30 relays. Evaluation concluded deficiency & substantial safety hazards do not exist FOSTER. D.O. Georgia Power Co. 83/10/06 O'REILLY, J.P. Ragion 2, Office of Director 1p 20780 189 24X Fich. 50-424,83/10/06,8310170366
- 8310270315 Interim deficiency rept re defective wald wire Engineering evaluation will be completed & conclusions re reportability will be submitted by 831028 FOSTER.D O Georgia Power Co 83/10/17 O'REILLY, J P Director's Office. Office of Inspection and Enforcement 1p 20923-189. 24X Fiche 50-424,83/10/17.8310270315

U Congressional/Executive Correspondence

- 8310200442 Responds to 830722 itr re NRC handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers encl
 ### PALLADINO, N J Commissioners 83/10/07 FORD, N. H Senate, 3pp. 20871 295 24X Fiche, 50-000, 83/10/07, 8310200442
- --8310200455 Expresses appreciation for cooperation w/IE activities to comply w/Congressional directive to NRC to perform GA studies Draft working paper for study encl TAYLOB.J M Division of GA, Befaguards & Inspection Programs (Post 830103) 83/08/02 KELLY,R J Georgia Power Co ip 20871 307. 24X Fiche 50-000.83/10/07.8310200442

DUCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

- A Application/construction stage documents & correspondence
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Dieblo Canyon 1 & 2.Fermi 2 & Callaway EISENHUT.D 0 Division of Licensing 83/07/29 FALLADING,N J. Commissioners 3pp 20632 001 24X Fiche 50-000,83/09/29,8308300357

DOCKET 50-434 SURRY POWER STATION, UNIT 3

- A Application/construction stage documents & correspondence
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys. Info applicable to Diablo Canyon I & 2.Fermi 2 & Callaway EISENHUT,D 0 Division of Licensing 83/09/29, PALLADING,N J. Commissioners 3pp 20432 001 24X Fichs 50-000,83/09/29, 8308300357

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 831021017B Advises that scheduled fuel load date remains May 1985 for Unit 1.per NRC 810803 request. Any changes will be reported in next quarterly update MILLES. M Tennessee Valley Authority 83/10/17 EISENHUT. D. O. Division of Licensing 1p. 20856 124 24X Fiche: 50-438,83/10/17, projectors
- 8310310443 Requests info to datermine if operation of plant may affect cultural resources listed or eligible for listing in Natl Register of Historic Places
 ADENBAM,E 0 Licensing Branch 4 83/10/18 OAKS,L Alabama, State of, 1p 20765,169 24X Ficha,50~438,83/10/18,8310310443.
- B310310489 Summary of 830826 meeting w/BtM Dwners Oroup re implementation of Generic Ltr 83-28 concerning defenses against ATMS & proposed ATMS rule for BtM plants.List of attendees & viwugraphs enc! KADAMBI,P Operating Reactors Branch 4 83/10/20. Operating Reactors Branch 4 13pp 20945.147. 24X Fiche 50-000,83/10/20, 8310310489

- F. Security, medical, emergency & fire protection plans
- 8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Records revised to delete Item B of violation re maint of cleaniness control
 VERRELLI.D N Division of Project & Resident Programs 83/10/19
 PARRISH & Tennessee Valley Authority 2pp 20897 301 24X
 Fiche 50-438.83/10/19.8310230301
- --B310250305 Forwards revised response to NRC B30414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions individuals counseled in OA program requirements Wome oversize drawing Aperture card in PDR MILLS,L H Tennessee Valley Authority B3/09/28 O'REILLY, J P Region 2, Office of Director 4pp 20897 303 24X Fiche 50-438.83/10/19 8310250301
- --8310250313 Responds to NRC 830414 ltr re violations noted in IE Insp. Repts 50-439/83-09 & 50-439/83-08 Corrective actions failure to perform holiday test on fire protection piping documented Violation re const flush configuration denied MILLS, L.M. Tennessee Valley Authority 83/05/18 O'REILLY, J.P. Region 2, Office of Director 6pp 20897 308 24X Fiche 50-438.83/10/19.8310250301
- --8310250318 Forwards IE insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/04/ PARRISH 9 Tennessee Valley Authority 2pp 20897 314 24X Fiche 50-438,83/10/19,8310250301
- --8310250324 Notice of violation from insp on 830201-28 a Division of Project & Resident Programs 83/04// 20897 316 24X Ficha 50-438,83/10/17,8310250301 83/04/14 2pp
- --8310250333 IE Insp Repts 50-439/83-08 & 50-439/83-08 on 830201-28
 Noncompliance noted inadequate holiday test of fire
 protection const flush configuration control & valve lineup
 MILCOX.J D Region 2. Office of Director QUICK.D R Division
 Project & Rasident Programs 83/04/14 14pp 20897 318 24X
 fiche 50-436,83/10/19,8310250301
- Q Inspection reports. IE Bullatins & correspondence
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Tuxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8310110365 F01A request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82 F0LEY. JR Foley, Hoag & Eliat 83/08/09 OllLILAND. J Office of Public Affairs 1p 20712 351 24X Fiche 50-438.83/08/09,
- 8310110361 Responds to FOIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82 Lists repts identified by Region II of: prepared in 1981-82 Repts available in PDR FELTON J M Division of Rules and Records 83/08/18 FOLEY, J R Foley Hoag & Eliot 1p 20712 350 24% Fichs 50-438,63/08/18,8310110361
- B310040211 Forwards IE Insp Repts 50-438/-83-18 & 50-439/83-18 on B30B01-05 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs B3/09/0 PARRIS.H Q Tennessee Valley Authority 2pp 20615 007 24X Fichs 50-438,83/09/02.8310040211 83/09/02
- 8310040244 IE Insp Repts 30-438/83-18 & 50-439/83-18 on 830801-05 No noncompliance noted Major areas inspected QA insp of civil (anchor bolts) & mechanical/piping installation work activities & licenses identified (OCFRSO 55(s) items HRIGHT, R H, MCFARLAND, C R Region 2. Office of Director UPRIGHT, C M Division of Engineering & Operational Programs, 83/08/31 10pp 20615 009 24X Fichs 50-438,83/09/02,8310040211
- I308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list enc] Gualification Tests " Svc list enc] JORDAN, E. Division of Emergency Preparedness & Engineering Response (Poxt 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754-022 24X Fiche 50-000,83/09/26,8308300340
- 308300345 1E Info Notice 83-63, "Potential Feilures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 DOI 24X Fiche 50-000.83/09/26,8308300345

- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 99 Evaluation " Svc list
 - JORDAN, E.L. Division of Emergency Preparedness & Ingingering Response (Post 830103) B3/09/29 Consolidated Eduson Co. of New York, Inc. 115pp 20714-324 24% Fiche 50-000,63/09/49,6908(60/49)
- 8310250373 Forwards IE Insp Repts 50-438/03-25 & 40-439/03-2b on 830913-16 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs (9.3/10, PARRIS.H O Tennessee Valley Authority 2pp 20099-178 (4) 0.3/10/0.1 Fiche 50-438,83/10/03,83102503/3
- --8310250380 IE Insp Repts 50-438/83-25 & 50-439/83-25 on 830910-16 No noncompliance noted Major areas inspected licenses artism on previous enforcement matters, inspector Pollowup items, licenses identified items, electrical cables & terminations RUFF, A B Region 2, Office of Director CONLON, T | Division of Englineering & Operational Programs 83/09/29 5pp 2010/8 100 24X Fichs 50-438, 63/10/03, 8310250373
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypaus Loops Used in Westinghouse Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of Ro York, Inc. 74pp 20827 213 24X Fiche 80-000,03/10/07,83008/3003 0/07 Consolidated Edison Co. of No. 24X Fiche 50-000,01/10/07,8008000,1/0
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Nev York, Inc 77pp 20882 026 24x Fiche 50-000,63/10/07,0300300/52
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/11 Consolidated Edison (o of New York, Inc. 117pp 21043-075 24x Fiche 50-000, 83/10/11, 83083000/37.
- 8308300761 IE Info Notice 83-68, "Respirator User Waining Defactive Self-Contained Breathing Apparatus Air Cylindors " 9vc list enci JORDAN,E L Division of Emergency Proparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 127 24X Fiche 50-000,83/10/11.8308300/61
- 8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps Side No. 1 Ack receipt of BOUDIU & 0928 itrs informing NRC of taken to correct violations noted in II Insp Repts 50-438/83-08 & 50-439/83-08 Records revised to delete Item B of violation re maint of cleanliness control VERRELLI, D M Division of Project & Resident Programs E PARRIS, H & Tennessee Valley Authority 2pp 2087/301 Fichs 50-438,83/10/19,8310250301 03/10/19
- --8310250306 Forwards revised response to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions individuals counseled in 9A program requirements W/one oversize drawing Aperture card in PDR HILLS, L H Tennesses Valley Authority 83/09/28 U'RETLLY, J P Region 2, Office of Director App. 20897 303 24X Fiche 50-438,83/10/19,8310250301
- --8310250313 Responds to NRC 830414 ltr re violations noted in If Inap Repts 50-438/83-08 & 50-439/83-08 Corrective actions failure to perform holiday test on fire protection piping documented Violation re const flush configuration denied MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY, J.P. Region 2, Office of Director App 20897 308 24X Fiche 50-438,83/10/19,8310250301
- --8310250318 Forwards 1E Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/04 PARRIS, H 9 Tennessee Valley Authority 2pp 20897 314 24 Fiche 50-438,83/10/19,8310250301 03/04/14
- --8310250324 Notice of violation from insp on 830201-28 * Division of Project & Resident Programs 83/04/14 20897 316 24% Fiche 50-438,83/10/19,8310250301 ₽ов.
- ~-8310250333 IE Insp Repts 50-438/83~08 & 50-439/83-08 on 830201-20 Noncompliance noted inadequate holiday test of fire protection control to the protection control to the lineup MILCOX.J D Region 2, Office of Director QUICK.D R Division Project & Resident Programs 83/04/14 14pp 20897 318 24x Fichs 50-438,83/10/19,8310250301 Division of

S Reportable occurrences. LERs & related correspondence

- 8310030233 Third interim deficiency rept re GA program on Tubeline matl supplied by Capitol Pipe Initially reported on 830329 Step work order issued T-L fittings/flanges not installed in safety-related sys Next rept by 831108
 MILLS, L M Tennessee Valley Authority 83/09/21 D'REILLY, J P Region 2. Office of Director Spp 20590 343 24X
 Fiche 50-000,83/09/21,8310030233
- 8310030388 Second interim deficiency rept re GA program for personal svc contract Initially reported an 830404 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
 MILLS.L M Tennessee Valley Authority 83/09/21 O'REJLLY, J P Region 2, Office of Director 2pp 20592 139 24X
 Fiche 50-000,83/09/21,8310030388
- B310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Matts Bor Keys will be replaced by 840201 Also reportable per Part 21 MILLS, L.M. Tennessee Valley Authority 83/09/22 O'REILLY, J.P. Region 2, Office of Director 3pp 20601 194 24X Fiche 50-000,83/09/22,8310030506
- 8310030938 Final deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830304 Response spectrum utilized in analyzing earthquake effect results in conservative displacements MILLS, L M Tennessee Valley Authority 83/09/22 G'REILLY, J P Region 2, Office of Director 3pp 20601 207 24X Fiche 50-000,03/09/22,8310030538
- 8310030436 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714 Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220 MTLLS.L M Tennessee Valley Authority 83/09/23 O'REILLY, J. P Region 2. Office of Director 2pp 20602 095 24X Fiche 50-000, 83/09/23, 8310030436
- 9310040172 First interim Deficiency Rept 2 re QA on valve purchase orders Initially reported on 830901 Hold on valve shipment initiated on 830902 & contractor reviewing deviation Next rept uill be submitted by 831221 HILLS.L M Tennesses Valley Authority 83/09/26 O'REJLLY.J.P Region 2. Office of Director 2pp 20608 035 24% Fiche 50-436,83/09/26,8310040172
- 8310060331 Final & eighth interim deficiency repts for Watts Bar & Bellefonterrespectively re inconsistent establishment of insp program Initially reported on BiO324 Requirements, control & use of const requirements manual developed MILLS, L M Tennessee Valley Authority B3/07/30 O'REILLY, J P Region 2, Office of Director 4pp 20641 001 24X Fiche 50-000,83/09/30,8310060331
- 8310120228 First interim deficiency rept re flexible canduit requiring O-ring installed in various areas of plant w/o O-rings Initially reported on 830706 Procedures will include compliance w/manufacturer instructions Next rept by 840208 MELLS, L M Tennesses Valley Authority 63/10/04 O'REILLY, J P Region 2, Office of Director 2pp 20692 176 24X Fiche 50-438,83/10/04,8310120228
- 8310140277 Second interim deficiency rept re welds on baffle plates in care support assembly mgt by B&W Initially reported on 830302 Baffle plates on former bolt locking pin welds repaired Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/10/05 O'REILLY, J P Region 2 Office of Director 19pp 20761:195 24X Fiche 50-43B.83/10/05.8310140277
- 8310210096 Final rept re QA program deficiencies in Gilbert Assoc personal svcs contract Initially reported on 830406 Specific problems not identified by audit Items not reportable per 10GFR90 55(r) MILLS.L. M. Tennessee Valley Authority 83/10/12 O'REILLY.J.P Region 2, Office of Director 4pp. 20858 197. 24X Fiche 50 000,83/10/12,8310210096
- 8310190089 Final deficiency rept re discrepancy in interface coordination of design review process Initially reported on 810717 Finding of coordination problem not significant & should not have been reported to NRC per 10CFR50 55(e) MILLS, L M Tennessee Valley Authority 83/10/13 0'REILLY, J. P. Region 2. Office of Director 3pp 20818-132 24X Fiche 50-000,83/10/13,8310190089

- 8310190224 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents Initially reported on 811215 Listed changes to design review process will be implemented by 840101
 MILLS,L M Tennessee Valley Authority 83/10/13 O'REILLY, J P Region 2, Office of Director 3pp 20818 045 24X
 Fiche 50-000.83/10/13.8310190224
- 8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns. Initially reported on 830120 New requirements for assessing piping vibration problems during preoperational testing requirements issued HILLS, L. M. Tennessee Valley Authority 83/10/13 0/REILLY, J. P. Region 2, Office of Director 3pp 20855 345 24X Fiche 50-000, 83/10/13,8310210011
- 8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Bections in EN DEB-EP 4 02 addressing voiding of ECNs changed in Rev 12. issued on 830203 MILLS.L. M Tennessee Valley Authority 83/10/13 D'REILLY.J P Region 2, Defice of Director 2pp 20855 304 24X Fiche 50-000.83/10/13.8310210049
- 8310190220 Final deficiency rept re generic implications of failure to implement design criteria in design drawings Initially reported on 810401 Eight addit nonconformances identified Functional control logic diagrams will be revised by 840301 HILLS,L M Tennessee Valley Authority 83/10/14 0'REILLY,J.P Region 2, Office of Director 2pp 20818 067 24% Fiche 50-438,83/10/14,8310170220
- 8310250110 Second revised final deficiency rept re overpressurization of makeup & purification piping & valves Initially reported on 820528 Site personnel retrained to Div of Const test procedure for hydrostatic sys
 MILLS.L M Tennessee Valley Authority 83/10/17 D/RCILLY, J. P. Region 2. 08fice of Director 2pp. 20876 255 24%
 Fiche 50-438.83/10/17.8310250110
- 8310250149 Final deficiency rept re power for emergency air cleanup units after loss of offsite power Initially reported on 830103 Control logic corrected to allow cleanup units to be automatically loaded as part of loading sequence MILLS,L M Tennessee Vallay Authority 83/10/17, O/REILLY,J P Region 2, Office of Director 2pp R0896 341 24% Fiche 50-438.83/10/17,8310250149
- 8310270248 Final deficiency rept re cable bené radius going from vertical to horizontal trays Initially reported on 830422 Cable acceptable as-is,per Okonite Co evaluation Condition not reportable per 100FR80 55(e) MILLS,L M Tennessee Valley Authority 83/10/18 O'REILLY,J P Region 2, Office of Director 2pp 20924 049 24X Fiche 50-438,83/10/18,8310270248
- 8310310197 Final deficiency rept re inadequate expansion anchor sparing criteria Initially reported on 820607 Item not reportable under 10CFR50 55(s) Sampling programs indicated low probability of defects
 MILLS,L M Tennessee Valley Authority 83/10/19, O'REILLY, J P Region 2, Office of Director 2pp 20939 048, 24X Fiche 50-438,83/10/19,8310310157

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8310210178 Advises that scheduled fuel load date remains May 1985 for Unit 1, per NRC 810803 request Any changes will be reported in next querterly update MILLS,L M Tennessee Valley Authority 83/10/17. EISENHUT,D 0 Division of Licensing Ip 20856 124 24% Fiche 50-438,83/10/17. 8310210178
- 8310310443 Requests info to determine if operation of plant may affect cultural resources listed or eligible for listing in Natl Register of Historic Places.

 ADENSAM, E. G. Licensing Branch 4 83/10/18 GAKS, L. Alabama, State of 1p 20765 169 24X Fiche 50~438, 83/10/18, 8310310443
- F Security, medical, emergency & fire protection plans
- 8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08. Records revised to delete ltem 8 of violation re maint of cleanliness control VERRELLI,D M Division of Project & Resident Programs 83/10/19 PARRIS,H,O Tennessee Vallsy Authority 2pp 20897,301 24% Fiche 50-438,83/10/19.8310230301

- ~-8310250306 Forwards revised response to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 t 50-439/83-08 Corrective actions individuals counseled in GA program requirements Myone oversize drawing Aperture card in PDR MILLS, L M Tennessee Valley Authority 83/09/28 0'REILLY, J P Region 2, Office of Director 4pp. 20897 303 24X Fiche 50-438,83/10/19,8310280301
- --8310250313 Responds to NRC B30414 ltr re violations noted in If lnsp Repts 50-438/83-08 & 50-439/83-08 Corrective actions failure to perform haliday test on fire protection piping documented Violation re const flush configuration denied HILLS.L M Tennesse Vallay Authority 83/05/18 O'REILLY, J.P. Region 2, Office of Director. App 20877 308 24X Fiche 50-438,83/10/19,8310250301
- --831025031B Forwards IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-20 & notice of violation VERRELLI,D H Division of Project & Resident Programs 83/04/14 PARNIS,H G Tennessee Valley Authority 2pp 20897 314, 24X Fiche 50-438,83/10/19,8310250301
- ~-8310250324 Notice of violation from insp on 830201-28 * Division of Project & Resident Programs 83/04/14 2pg 20877 316 24X Fiche 50-438,83/10/19,83(0250301
- --8310250333 IE Insp Repts 50-438/83-08 & 50-437/83-08 on 830201-28 Noncompliance noted: inadequate holiday test of fire protection:const flush configuration control & valve lineup WICCOX,J D Region 2. Office of Director 83/04/14 14pp 20897 318 24\(\) Fiche 50-438,83/10/19.8310250301
- G Inspection reports. IE Bulletins & correspondence
- B310110365 F0IA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82 FDLEV.J.R Foley, Hoag & Eliot B3/08/09 GILLILAND.J Office of Public Affairs 1p 20712 351. 24X Fiche 50-438.83/08/09. B310110365
- 8310110361 Responds to FOIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82 Lists repts identified by Region II of: prepared in 1981-82 Repts available in FDR FELTON, J M Division of Rules and Records 83/08/18 FOLEY, J R Foley, Hoag & Eliot 1p. 20712 350 24% Fichs. 50-438, 83/08/18, 8310110361
- 8310040211 Forwards IE Insp Repts 50-438/-83-18 & 50-439/83-18 on 830801-05 Np nuncompliance noted VERRELLI,D M Division of Project & Resident Pregrams 83/09/02 PARRIS.H, G Tennessee Valley Authority 2pp 20615 007 24X Fiche 50-438,83/09/02,8310040211
- ~~8310040244 IE Insp Repts 50~438/83~18 & 50~439/83~18 on 830801-05 No noncompliance noted Major engas inspected OA insp of civil (enchor bolts) & mechanical/piping installation work activities & licensee identified 10CFR50.55(e) items HRIGHT-R W : MCFARLAND.C R Region 2. Office of Director UPRIGHT.C M Division of Engineering & Operational Programs 83/08/31 10pp 20615:009 24X Fiche 50~438.83/09/02.8310040211
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Syc list encl JORDAN E L Division of Emergency Preparadness & Engineering Response (Post 830103), 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list ent! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777-210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Pailures of Westinghouse Yype 8A-1 Differential Relays " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (fost 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345.
- 830B300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation " Svc list encl, JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716-384, 24X Ficher 50-000,83/09/29,8308300349

- 8310250373 Forwards IE Insp Repts 50-438/83-25 & 50-439/83-25 on 830913-16 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 63/10/03 PARRIS,H C Tennessee Valley Authority 2pp 20898 178 24x F1Che 50-438,83/10/03.8310250373
- --8310250380 IE Insp Repts 50-438/83-25 & 50-439/83-25 on 830913-16 No noncompliance noted Major areas inspected licenses action on previous enforcement matters, inspector followup stems, licenses identified stems, electrical cables & terminations RUFF, A B Region 2. Office of Director CONLON.T E Division of Engineering & Operational Programs 83/09/29 5pp 20898 180 24% Fiche 80-408,83/10/03,8310250373
- 8308300978 IE Info Natice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critica)
 Facility " 8vc list encl
 JORDAN, EL Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/10/07 Consolidated Edison Co of New
 York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases "Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of Hew York Inc 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Bvt list encl JURDAN, E. L. Diviston of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000.83/t0/11.8308300761
- 8310250301 Ack receipt of 830518 & 0928 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Records revised to delete Item 8 of violation re maint of cleanliness control VERRELLI.D M. Division of Project & Resident Programs 83/10/19 PARRIS.H @ Tennessee Valley Authority 2pp 20897 301 24X Fiche.50-438,83/10/19,8310250301
- --8310250306 Forwards revised response to NRC 830414 ltr re violations noted in IE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions individuals counsaited in GA program requirements Wione oversize drawing Aperture cand in PDR MILLE: L M Tennessee Valley Authority 83/09/28 D'REILLY: J P Region 2, Office of Director 4pp 20897 303 24X Fiche 50-428,83/10/19,8310250301
- --8310250313 Responds to NRC 830414 ltr re violations noted in tE Insp Repts 50-438/83-08 & 50-439/83-08 Corrective actions failure to perform holiday test on fire protection piping documented Violation re const flush configuration denied MILLS.L M Tennessee Valley Authority 83/05/18 D'REILLY.J P Region 2, Office of Director 6pp 20897 308 24X Fiche 50-438,83/10/19,8310250301
- --8310250318 Forwards IE Insp Repts 50-438/83-08 & 50-439/83-08 on 830201-28 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/04/14 PARTIS H G Tennessee Valley Authority 2pp 20877 314 24X Fiche: 50-438,83/10/19,8310250301
- --8310R\$0324 Notice of violation from Insp on 930R01-28 * Division of Project & Resident Programs 93/04/14 2pp 20897 316 24X Fiche 50-438.83/10/19.8310250301
- --8310250333 IE Insp Repts 50-438/83-08 & 50-439/83-08 on 630201-28
 Noncompliance noted inadequate holiday test of fire
 protection const flush configuration control & valve lineup
 WILCOX, J D Region 2, Office of Director QUICK, D R Division of
 Project & Resident Programs 63/04/14 14pp 20897 318 24X
 Fiche: 50-438, 83/10/19, 8310250301
- 8 Reportable occurrences, LERs & related correspondence
- 8310030233 Third interim deficiency rept re GA program on Tubeline math supplied by Capitol Pipe Initially reported on 830329 Stop work order issued. Tot fittings/flanges not installed in safety-related sys Next rept by 83108, MILLELL M Tennessee Vallay Authority 83/09/21 ()'REILLY, J P Region 2, Office of Director 5pp 20590 343 24X Fiche: 50-000, 83/09/21, 8310030233

- 83100303BB Second interim deficiency rept re GA program for personal svc contract Initially reported on 830406 Controlled copies of engineering procedures sent to Gilbert Assoc Next rept expected by 831014
 MILLS,L M Tennessee Valley Authority 83/09/21 D'REILLY, J P Region 2, 0ffice of Director 2pp 20592 139 24x
 Fiche 50-000.83/09/21.83100303BB
- 8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21 MILLS.L M Tennesse Valley Authority 83/09/22 D'REILLY, J P Region 2. Office of Director 3pp 20201 194 247 Fiche 50-000, 83/09/22, 8310030506
- 8310030538 Final deficiency rept re incorrect max pipe movements contained in TFIPE program Initially reported on B30504 Response spectrum utilized in analyzing earthquake effect results in conservative displacements HILLS,L H Tennessee Valley Authority B3/09/22 O'REILLY,J Region 2, Office of Director 3pp 20601 207 24X Fiche 50-000,83/09/22,8310030538 O'REILLY, J P
- 8310030436 First interim deficiency rept re calculation of support design loads in TPIPE Initially reported on 830714 Procedure developed allowing recomputation of design loads near localized phenomena by hand Next rept by 831220.

 MILLES, L. M. Tennessee Valley Authority B3/09/23 (1'ACILLY, J.P. Region 2, Office of Director 2pp 20602 095 24X Fiche 50-000,83/09/23,8310030436
- 8310040172 First interim Deficiency Rept 2 re QA on valve purchase orders Initially reported on 830701 Hold on valve shipment initiated on 830702 & contractor reviewing deviation Next rept will be submitted by 831221 MILLG.L M Tennessee Valley Authority 83/07/26 O'REILLY, J P Region 2, Office of Director 2pp 20608 055 24X Fiche 30-438,63/09/26,8310040172
- 8310040331 Final & eighth interim deficioncy repts for Watts Bar & Beliefonte, respectively re inconsistent establishment of insp program Initially reported on 810324 Requirements, control & use of const requirements manual developed MILLS.L. M. Tennessee Valley Authority 83/09/30 O'REILLY, J.P. Region 2. Office of Director App 20641 001 24X Fiche 50-000,83/09/30,8310060331
- 8310120228 First interim deficiency rept re flexible conduit requiring O-ring installed in various areas of plant w/o O-rings Initially reported on 830906 Procedures will include compliance w/manufacturer instructions Naxt rept by 840208 MILLE, L. M. Tennessee Valley Authority 83/10/04 O'REJLLY, J.P. Region 2, Office of Director 2pp 20492 176 24X Fiche 50-438,83/10/04,83101202PB
- 8310210096 Final rept re GA program deficiencies in Oilbert Assoc personal svcs contract Initially reported on 830404 Specific problems not identified by audit Items not reportable per IOCFR30 53(e) MILLS.L M Tennessee Valley Authority 83/10/12 O'REJLLY, J P Region 2. Office of Director App 20838 197 24X Fiche 50-000,83/10/12.8310210074
- 8310170087 Final deficiency rept re discrepancy in interface coordination of design review process. Initially reported or 810717 Finding of coordination problem not significant & should not have been reported to NRC per 100FR50 85(e) MILLS,L M Tennessee Valley Authority 83/10/13 O'REILL Region 2, Office of Director 3pp 20818 132 24X Fiche 50-000,83/10/13,8310190089 O'REILLY, J P
- 83101702R4 Final deficiency rept re design review failure to verify accuracy & adequacy of design documents. Initially reported on 811215 Listed changes to design review process will be implemented by 840101
 MILLS.L.M. Tennesse Valley Authority. 83/10/13 O'REILLY, J.P. Region 2. Office of Director 3pp 20618.045 24X
 Fiche 30-000,83/10/13.8310190224
- 8310210011 Final deficiency rept re resolution of unanticipated vibratory loading concerns Initially reported on 820120 New requirements for assessing piping vibration problems during preoperational testing requirements issued MILLB.L M Tennessee Valley Authority 83/10/13 0'REILLY, J P Region 2. Office of Director. 3pp. 20855-345 24X Fiche. 50-000, 83/10/13, 8310210011
- 8310210049 Revised final deficiency rept re voiding of engineering change notices (ECNs) w/o proper review Initially reported on 820816 Sections in EN DES-EP 4.02 addressing voiding of ECNs changed in Rev 12. issued on 830203 MILLS, LM Tennessee Valley Authority 83/10/13 O'REJLLY, J P Region 2, Office of Director 2pp 20855 304 24X Fiche 50-000, 83/10/13, 8310210047

- 8310190220 Final deficiency rept re generic implications of failure to implement design criteria in design drawings Initially reported on 810401 Eight add1 nonconformances identified Functional control logic diagrams will be revised by 840301 MILLS.L. M Tennessee Valley Authority 83/10/14 O'REILLY, J P Region 2. Office of Director 2pp 20818 069 24X Fiche 50-438,83/10/14,8310190220
- 8310250149 Final deficiency rept re power for emergency air cleanup units after loss of offsite power Initially reported on 830103 Control logic corrected to allow cleanup units to be automatically loaded as part of loading sequence MILLG.L M Tennossee Valley Authority 83/10/17 0/REILLY, J P Region 2. Office of Director 2pp 20896 341 24X Fiche 50-438,83/10/17,8310250149
- 8310270248 Final deficiency rept re-cable bend radius going from vertical to horizontal trays Initially reported on 830422 Cable acceptable as-is, per Okonite Co evaluation Condition not reportable per 10CFR50 53(e)
 MILLSI, L. M. Tannessee Valley Authority 83/10/18 O'REILLY, J. Region 2. Office of Director 2pp 20724 049 24X
 Fiche 50-438,83/10/18,8310270248 D'REILLY, J. P.
- 8310310157 Final deficiency rept re inadequate expansion anchor spacing criteria Initially reported on 820607 Item not reportable under 10CFR50 55(e) Sampling programs indicated low probability of defects
 MILLS,L M Tennesse Valley Authority 83/10/19 O'REILLY, J. P. Region 2. Office of Director. 2pp 20757 048 24%
 Fiche 50-438,83/10/17,8310310157
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8398300357 Board Notification 82-105A forwards evaluation of allegations re design deficiancies in Class I piping sys
 Info applicable to Diablo Canyon 1 & 2.Fermi 2 & Callavay
 EIECHHUT, D 9 Division of Licensing 83/09/29 PALLADING, N J
 Commissioners 3pp 20432 001 24X Fiche 50-000,83/09/29,
 8308300357
- 8308300771 Doard Notification 83-128A forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid valves EIBENHUT, D.G. Division of Licensing 83/10/06 PALLADINO, N.J. Commissioners 31pp 20818 OO1 24X Fiche 50-000,83/10/06,
- 8310200395 Forwards TM Novak 821112 memo to DO Eisenhut & J Stefano 821115 informal note to TM Novak re caseload panel review of facility.per R Oanulin FDIA-B3-583 request Caseload Forecast Panek rept dtd 830317 also available STEFANO. J Licensing Branch 1 83/10/07, WILSON, V Management Analysis Branch 1p 20874 272 24X Fiche. 50-440, 83/10/07, 8310200395
- --8310200397 Advises of Caseload Forecast Panel review scheduled for by of 830110.

 STEFAND. J NRC - No Detailed Affiliation Given 82/11/15

 NOVAK. T M NRC - No Detailed Affiliation Given 1p 20874-275

 24X Fiche 50-440.83/10/07.8310200395
- --8310200400 Advises that site review by Caseload Forerast Panel scheduled for wk of 830110

 BASSETT.H S Division of Data Automation & Management Information 82/11/12 BPESSARD,R L Director's Office, Office of Inspection and Enforcement 1p 20874 276 24X Fiche 50-440,83/10/07,8310200375
- ~~8310200404 Discusses need for Caseload Forecast Panel review of facility STEFANO, J J NRC - No Detailed Affiliation Given 82/ NGVAK, T M NRC - No Detailed Affiliation Given 2pp 24X Fiche 50-440,83/10/07,8310200395 82/10/20.
- ---8310200407 Forwards R Oanulin FDIA-83-583 request for all documents re Caseload Forecast Panel meetings held during 1982-83 concerning plant const WILSON,V H Management Analysis Branch 83/10/05 YUUNGBLOOD,B. J Licensing Branch i 2pp. 20874;279 24X Fiche. 50-440, 83/10/07, 8310200395
- 8308310050 Board Notification 83-140, provides info re 830812 failure of main crasssable on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENHUT, D & Division of Licensing 83/10/14 PALLADING, N J Commissioners 15pp. 67056:070. 24X Fiche 50-000, 83/10/14.

- 8310240165 Clarifies Criteria 1,2 & 10 of 830916 submittal re TMI Action Plan Item Jl B 3, "Post-Accident Sampling Sus " Chemistry technicians requalified biannually Offsite boron analysis performed only on undiluted sample EDELMAN.M R Cleveland Electric Jiluminating Co 83/10/14 YOUNGBLOOD, B J Licensing Branch 1 2pp 2088 313 24X Fiche 50-440,83/10/14,8310240165
- 8310310378 Provides clarification on quencher tie-down loads Design dynamic stress from bending moment on quencher arm greater than 5,000 psi Facility design meets acceptance criteria EDELMAN.M R Cleveland Electric Illuminating Co 83/10/21 YOUNGELOUD.8 Licensing Branch i Jp 20959 362 24% Fiche 50-440,83/10/21.8310310378
- 8310310050 Forwards response to 830805 request for add1 info re changes to diesel generator air starting sys Info will be incorporated into future FSAR amend EDELMAN, H R Cleveland Electric Illuminating Co 83/10/24 YOUNGBLOOD, B J Licensing Branch 1 40pp 20947 240 24% Fiche 80-440, 83/10/24, 8310/310050
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310040227 Forwards info to resolve SER License Condition ? per TMI Action Plan Item II B 3. "Post-Accident Sampling Sys "
 W/two oversite drawings Apprture cards are available in PDR Proprietary info withheld tref 100FR2 790)
 EDELMAN,M R Cleveland Electric Illuminating Co 83/09/16
 YOUNDBLOOD, D J Licensing Branch 1 App 20612 067. 24X
 Fiche 50-440,83/09/16.8310040227
- --8310040227 "Evaluation of Post-Accident Sampling Bys for Perry Nucleur Power Plant" • Cleveland Electric Illuminating Co 83/07/31 31pp 20612 071 24X Fiche 50-440,83/09/16,8310040227
- --8310040231 Preliminary Rev O to Procedure CHI-22. Chemistry Equipment Instruction. "Single Channel Analyzer Conberra " WESTBROOK, N Cleveland Electric Illuminating Co 83/09/16 17pp 20612·102 24X Fiche 50-440, 03/09/16, 8310040227
- -8310040234 Preliminary Rev O to Procedure CHI-12. Chemistry Equipment Instruction: "Multi-Channel Analyzer, Camberra, Beries 85° WESTBROOK, W W Cleveland Electric Illuminating Co 93/09/16 18pp 20612 119 24X Fiche 50-440,83/09/16,8310040227
- 310110499 Requests input for BSER 4 by 831021 for Nov 1983 scheduled issuance Listing of info & responsible review branch encl SEER 4 will be basis for addressing steam erosion issue YOUNOBLOOD.B J Licensing Branch I 83/09/27. NDDNAN, V Equipment Gualification Branch BOSNAK.R Mechanical Engineering Branch LIAM.B Materials Engineering Branch 4pp 20714 313 24X Fiche 50-440,83/09/27,8310110495
- 31020023B Responds to SER Dutstanding Issue 10 re containment purge, documenting design mod & sys operation limits, per 830526 meeting Containment purge sys provides for filtered purging for personnel entry & maint access EDELMAN.M R Clevelend Electric Illuminating Co 83/10/07 YOUNDELDOB, B J Licensing Branch 1. Spp 2093J 052 24X Ficher 50-440, 83/10/07, 8310200238

Adjudicatory correspondence

- 10090375 Forwards JE Konklin affidavit & JL Streeter & TE Vandel Joint affidavit re inspector certification & GA advisory committee to the street of the str
- 13100503B2 Affidavit of JE Konklin re inspector certifications & GA advisory committee meetings KONKLIN.J E Region 3. Office of Director 83/09/27. App 29634 003 24X Fiche 50-440.83/09/29,8310050375
- 310050389 Affidavit of JF Straeter & TE Vendel supporting NRC position on GA advisory committee, Prof quelifications encl BTREETER, J. F. VENDEL, T. E. Region 3. Office of Director B3/09/27 7pp 20634 007 24% Fich. 50-440
- 0050520 Answer apposing Dhio Citizens for Responsible Energy 830916 otton to resubmit Contention 2 re diesel generator eliability Motion falls to meet criteria of adequate basis specificity Certificate of Svc encl HIGER. M A Cieveland Electric Illuminating Co SWIGER, M A Shaw, ttman, Potts & Trowbridge 83/10/03 Atomic Safety and censing Board Panel, 53pp 20634:126, 24X Fiche 50-440,83/10/03,110050520,

- 8310110061 Order extending time until 831007 for Commission to act to review ALAB-736 CHILK.S J Office of the Secretary of the Commission 83/10/03 Commissioners ip 20668 238 24X Fiche 50-440,83/10/03, 8310110061
- 8310120099 Reply to applicant & NRC affidavits remotion to reopen GA record FOIA request made in Nov 1982 produced negative results Formal discovery closed 3 months prior to ASIB issue identification W/Certificate of Bvc Related correspondence HIATT.S L. Ohio Citizens for Responsible Energy 83/10/07 Atomic Safety and Licensing Board Panel lipp 2049/ 109 24X Fiche 50-140,83/10/07,8310120099
- 8310130224 Advises that time for Commission to review ALAN-736 expired Commission declined review Decision became final agency action on 831007 CHILK,8 J Office of the Secretary of the Commission 83/10/12 Office of the Executive Legal Director 1p 20724 094 24X Fiche 30-440.83710/12.8310130224
- 8310180337 Motion for reconsideration of ASLB 830809 Memorandum & Drém LBP-83-46 granting summary disposition of Issue 13 Motion based on add1 evidence Certificate of Svc encl Related correspondence HIATT.S L Ohio Citizens for Responsible Energy 83/10/14 Atomic 8afety and Licensing Board Panel 4pp 20803 002 24X Fiche 50-440,83/10/14/8310180377
- 8310190061 Response to util & NRC 831003 & O6 answers, respectively, to Ohio Cititens for Responsible Energy 830916 motion to resubmit Contention 2 NRC misunderstood thrust of motion Contention should be admitted W/Certificate of SVc HIATT, S L Dhio Cititens for Responsible Energy 83/10/14 Atomic Safety and Licensing Board Panel 11pp 20823 211 24X Fiche 50-440,83/10/14,83/10/9004
- 8310270252 Answer apposing Ohio Citizens for Responsible Energy (OCRE)
 831007 request to hold open Issue 3 record until fuel load
 Request reiterates previously denied OCRE motion Certificate
 of Svc encl
 OLASSPIEGEL, H. Cleveland Electric Illuminating Co. 83/10/24
 Atomic Safety and Licensing Board Panel. App. 20723-240. 24X
 Fiche 50-440.63/10/24,8310270252
- B310270330 Response opposing Ohio Citizens for Responsible Energy (OCRE) B31014 response to NRC & util answers to OCRE motion to resubmit Contention 2 re diesel generator OCRE competence remains unproven Certificate of Sv uncl S1JEERG.JE Cityeland Electric Illuminating Co BILBERG.JE Shew. Pittman. Potts & Trowbridge 83/10/25 Atomic Bafrty and Licensing Board Panel 7pp 20723 145 24X Fiche 50-440,83/10/25.8310270330
- G Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co
- B30B300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York: Inc. 116pp. 20777 210 24% Fiche 50-000,83/09/26,830830024/
- B30B300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B2/09/26 Consolidated Edison Co of New York: Inc 118pp 2077B 001 24X Fiche 50-000.83/09/26.8308.00345
- 8310170662 Forwards 1E Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0831 & notice of violation KNOP.R C Region 3. Office of Director 83/09/28 EDELMAN, M R Cleveland Cletric Illuminating Co 2pp 20779 286 24% Fiche 50-440, 83/09/28. 8310170662
- --8310170667 Notice of violation from insp on 830701-09.11 KNOP.R C Region 3. Office of Director 83/09/28 lp 20779 288 24X Fiche 50-440.83/09/28,8310170662

- --83101706/0 IE insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0841 Noncompliance noted failure to follow problem evaluation for IOCFR50 55(e) reportability procedures GILDNER,M L , KUNKLIN,J E Region J, Office of Director 83/09/27 4pp 20779 289 24X Fiche 50-440,83/09/28,8310170662
- 8308300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 59 Evaluation " Svc list encl
 - encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300347
- 8310240121 Forwards IE Insp Repts 50-440/H3-28 & 50-441/83-27 on 830922-23 No noncompliance noted KNOP.R C Region 3. Office of Director 83/10/04 EDELHAN, M R Cleveland Electric Illuminating Co 2pp 20881 145 24X Fiche 90-440,83/10/04,8310240121
- --8310240137 IE Insp Repts 50-440/83-28 & 50-441/83-27 on 830921-23 No noncompliance noted Major areas inspected licenses actions on previous insp findings, 10CFR50 55(e) reportable items & IC bulletin
 PELKE,P R, DAVIS,A B, KONKLIN,J E Region 3, Office of Director 83/10/03 3pp 20881 147 24X Fiche 50-440,83/10/04,8310240121
- 8310200045 forwards IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19 & notices of violation & deviation LITTLE.W S Region 3. Office of Director 83/10/05 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 20836 009 24X Fiche 50-440,83/10/05.8310200045
- --8310200049 Natice of violation from insp on 830816-19 LITTLE,W S Region 3, Office of Director 83/10/05 ip 20836 011 24X Fiche 50-440,83/10/05 8310200045
- --8310200053 Notice of deviation from insp on 830816-17 LITTLE.W S Region 3, Office of Director 83/10/05 1 20836 012 24% Fiche 50-440,83/10/05,8310200045
- --8310200057 IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19
 Noncompliance noted bus bar support between 4.160-volt
 switchgear cubicles modified w/o approval & GA records
 corrected improperly
 MERRIMEATHER N Region 3. Office of Director CONLON, T E
 Division of Engineering 63/10/05 7pp 20836 013 24X
 Fiche 50-440,83/10/05.8310200045
- B30B300378 IE Info Notice B3-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Past B30103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, B3/10/07, B30B30037B
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83~67. "Emergency Use Respirator Matl Defect Causes Production of Notious Gases " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043-075 24X Fichs 50-000,83/10/11.8308300757
- 8308300761 IE Info Notice 93-68, "Respirator User Harning Defective Belf-Contained Breathing Apparatus Air Cylinders" Svt list encl JORDAN, C. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fichs 50-000,83/10/11,8308300761
- 8310180215 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON, W.L. Region 3, Office of Director 83/10/14 EDELMAN, M.R. Cleveland Electric 111uminating Co. 7pp. 20808 309 24X Fiche 50-440,83/10/14.8310180215
- 8310270422 Forwards IE Insp Repts 50-440/83-27 & 50-441/83-28 on 830927-30 & notice of violation SPEBSARD, R.L. Division of Engineering 83/10/14 EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp. 20923 065 24X Fiche 50 440.83/10/14.8310270422
- --8310270493 Notice of violation from insp on 880927-30 SPESBARD.R L Division of Engineering 83/10/14 1p 20923 067 24% Fiche 50-440.83/10/14.8310270422

- --8310270426 IE Insp Repts 50-440/83-29 & 50-441/83-28 on 830927-30 Noncompliance noted licensee GA program did not provide for developing approving & distributing relay setting sheets MERRIMEATHER.N Region 3. Office of Director CONLON.T E Division of Engineering 83/10/11 App 20923 068 24% Fiche 50-440.83/10/14.8310270422
- S Reportable occurrences. LERs & related correspondence
- B310110425 FD1A request for info re PND-III-83-027 concerning faulty valve radiographs, PND-III-83-026 concerning use of lubricant on valve seats & info on DDE/NRC 830419-20 meetings concerning geologic repository in salt program HIATT, S L Ohio Citizens for Responsible Energy 83/05/10 FELION, J M Division of Rules and Records 1p 20706 001 24X Fiche 50 000, 83/05/10.8310110425
- 8310110430 Responds to FOIA request for four different categories of documents described in 830510 ltr Forwards matl listed in App A, responsive to Items 1.2 & 4 DDE should be contacted for matl requested in Item 3 of ltr FELTON.J M Division of Rules and Records 83/06/14 HIATT, S L Onio Citizens for Responsible Energy 3pp 20706 002 24X Fiche 50-000,83/06/14,8310110430
- --8310110443 Forwards PNO & morning rept re faulty Borg-Warner valve radiographs Problem may be generic Related info encl LITTLE. W S Region 3, Office of Director 83/04/13 POTAPDVS, U Region 4, Office of Director 15pp 20706 005 24X Fiche 50-000,83/06/14,8310110430
- --8310110461 Excerpt from notification of events at two different facilities re deficiency concerning control complex chilled water mys & info received that grease incorrectly used on MSIVs, respectively Related info encl
 * Region 3, Office of Director 83/04/08 lipp 20706 044 24X Fichs 30-000.83/06/14.8310110430
- 8310040404 Final deficiency rept re NAMCO Controls limit switches mfg to inadequately implemented QA program Initially reported on 810210 Bill of mati spec (8P793-05-4349-00) developed, reviewed & approved for procurement of NAMCO switches EDELMAN.M R Cleveland Electric Illuminating Co 83/09/27 KEPPLER.J & Region 3, Office of Director 3pp 20617 357 24X Fiche.50-440,83/09/27.8310040404
- 83i0120286 Interim deficiency rept re failure of panel circuit wiring in Transamerica Delaval standby diesel generators to meet IEEE 383 insulation flame test Vendor info under review Final rept scheduled for submittal by 831230 EDELMAN.M R Cleveland Electric Illuminating Co 83/09/27 KEPPLER.J G Region 3, Office of Directo: 1p 20693 346 24X Fiche 50-440,83/09/27.8310120286
- 8310060340 Final deficiency rept re violations of spec requirements during installation of adjacent Hilti Rwik bolts Initially reported on 830207 One-inch bolts will no longer be used Insp program will be implemented EDELMAN.M R Cleveland Electric Illuminating Co 83/09/30 KEPPLER, J O Region 3, Office of Director 2pp 20646 125 24X Fiche 50-440, 83/09/30, 83/0060340
- B310060392 Final deficiency rept re rejection of previously accepted radiographs on containment vessel shell plate welds Initially reported on 820405 Accessible rejectable welds excavated, repaired & reradiographed EDELMAN.M.R. Cleveland Electric Illuminating Co. 83/09/30 KEPPLER.J C. Region 3. Office of Director 2pp 20646:105 24X Fiche 50-440.83/09/30.8310060392
- 8310170469 Second interim Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturer recommendations on standby dizzel generators for HPCB Intitally reported on 830809 Further mads required Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co 83/10/06 KEPPLERJ G Region 3, Office of Director 2pp 20784 101 24X Fiche 50-440,83/10/06,83/10/70469
- 8310210112 Interim deficiency rept re damage during removal of shroud head/separator from reactor pressure vessel by use of strongback & polar crane Initially reported on 830916 Further evaluation required Next rept by 840131 EDELMAN.M R Cleveland Electric Illuminating Co 83/10/12 KEPPLER.J O Region 3. Office of Director 2pp 20858 232 24X Fiche 50-440,83/10/12,8310210112
- 8310270030 Interim deficiency rept re pips support shop welds supplied by Power Piping Co Initially reported on 830921 Engineer support evaluation will be completed in Dec 1783 Final rept will be submitted by 831215 EDELMAN.M R Cleveland Electric Illuminating Co 83/10/18 KEPPLER.J & Region 3. Office of Director 2pp 20924 334 24X Fiche 50-440.83/10/18.8310270030

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039/40 DSR 48) Instruction for cable changeout due in Nov BOYER, R.E. Transamerica Delaval, Inc. 83/10/20 Director's Office, Office of Inspection and Enforcement 1p 20724 IOR 24x Fiche 50-000.83/10/20,831027020A

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2-Fermt 2 & Callaway E[SENHUT, D G Division of Licensing 83/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000,83/09/29, 8308300357
- 8308300771 Board Notification 8U-128A forwards Equipment Qualification Branch conclusions repotential problems w/ASCO solenoid valves EISENHUT, D.G. Division of Literaing 83/10/06 PALLADING, N.J. Commissioners Sipp 20818 001 24X Fiche 50-000, 83/10/06, 83083007/1
- 8310200395 Forwards TM Novak B21112 memo to D9 Eisenhut & J Stefano B21115 informal note to TM Novak re caseload panel review of facility, per R Ganulin FOIA-83-583 request Caseload Forecast Panel rept dtd 839317 also available STEFAND. J Licensing Branch I 83/10/07 WILSON, V Management Analysis Branch ip 20874 272 24x Fiche 50-440,63/10/07,8310200395
- --8310200400 Advises that site review by Caseload Forecast Panel scheduled for which 830110
 BASSETT.H S Division of Data Automation & Management Information 82/11/12 SPRESARD.R L Director's Office. Office of Inspection and Enforcement 1p 20874 276 24X Fiche 50-440,83/10/0/, 231070208
- --8310200407 Forwards R Ganulin FOIA-83-583 request for all documents re Caseload Forecast Panel meetings held during 1982-83 concerning plant const WILSON, V H Management Analysis Branch 83/10/09 YOUNGRLOOD, B J Licensing Dranch 1 2pp 20874 279 24X Fiche 50-440,83/10/07,8310200395
- 8308310050 Board Notification B3-160 provides info re 830812 failure of main trankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENNUT.D 0 Division of Licensing 83/10/14 PALLADINO,N J Commissioners 15pp 67056 070 24X Fiche 50-000,83/10/14, B308310050
- 8310240165 Clarifies Criteria 1,2 & 10 of 830916 submittal re 1Mi Action Plan Item II 3, "Post-Accident Sampling Sys " Chemistry technicians requalified biannually Offsite boron analysis performed only on undiluted sample EDELMAN-H R Cleveland Electric Illuminating Co. 83/10/14 YOUN08100018 J Licensing Branch 1 2pp 20881 313 24X Fiche 50~440.83/10/14.8310240165
- 8310310378 Provides clarification on quencher tie-down loads Design dynamic stress from bending moment on quencher arm greater than 5,000 psi Facility design meets acceptance criteria EDELMAN.M R Clevyland Electric Illuminating Co 83/10/21 YOUNOBLOOD, R Licensing Branch 1 lp 20959 362, 24% Fiche 50-440,83/10/21,8310310378.
- ISIOSIOOSO Forwards response to BODBOS request for add1 info re changes to diesel generator air starting sys info will be incorporated into future FSAR amend EDELMAN.M R. Cloveland Electric IJluminating Co BG/10/24 YOUNGBLOOD.B J Licensing Branch 1 40pp 20947 240 24X Fiche 50-440.B3/10/24.B310310050
- NRC Safety Evaluation Report (SER), supple & correspondence
- 310040227 Forwards info to resolve SER License Condition 7 per TMI Artion Plan Item II B 3, "Post-Accident Sampling Sys "
 M/two oversize drawings Aperture cards are available in FDR Proprietary info withheld (ref 100FR2 /90)
 EDELMAN, M R. (leveland Electric Illuminating Co. 83/09/16 YOUNORLOUGH, Licensing Branch 1 4pp 20612 067 24X Fiche 30-440,83/09/16.8310040827
- B310040227 "Evaluation of Post-Accident Sampling Bys for Perry Nuclear Fower Plant" * Cleveland Electric Illuminating Co 83/07/31 31pp 20612.071 24X Fishe 50-440.83/09/16.8310040227

- --8310040231 Preliminary Rev 0 to Procedure CHI-22 Chemistry (quipment Instruction, "Single Channel Analyze, Camberra "
 HE87DRODK, W Cleveland Licctiz Illuminating Co 83/09/16
 17pp 20612 102 24x Fishe 50-440,8 1/09/16,831004022
- --8310040234 Preliminary Rev O to Procedure CHI-12. Chemistry Equipment Instruction. "Multi-Channel Analyzer, Capberra, Series 85" WESTOROOK, W Cleveland Liectric Illuminating (a 83/09/16 18pp 20612 119 24X Ficht 50-440, 8/09/16, 831004022
- 83(0110495 Requests input for SSER 4 by 831021 for Nov 1783 scheduld issuance Listing of info & responsible review branch encl SSER 4 will be bar is for addressing stam erosion issue YOUNGBLODD. B. J. Licensing Branch I 84/09/27 NOUNGN.V Equipmend Qualification Branch BOSNAK.R Mechanical Engineering Branch LIAM.B. Materials Engineering Branch 4µp 20714 317 24x
 Fichs 50-440.83/09/27.8310110495
- 8310200239 Responds to SER Outstanding 19500 10 re containment purgedocumenting design mod & sys operation limits.per 830546 meeting Containment purge sys provides for filtered purging for personnel entry & maint access EDELMAN. # R Cloveland Electric Illuminating Co 83/10/07 YOUNGBLOOD, B J Licensing Branch 1 hpp 20833 052 24Y Fiche 50-440,83/10/07.8310200208
- G Adjudicatory torrespondence
- 8310050375 Forwards JE Konklin uffidavit & JL Streeter & TE Vandel Jeint affidavit re inspector certification & GA advising committee GCLDBERG, S.C. Hearing Branch 4 83/09/29 BLOC'I, P.B., BRIGHI, G.C., KLINE, J.R. Atomic Safety and Licensing Board Panel ip 20634 00: 24X Fiche 50-440, 83/09/29, 8310050375
- --8310050382 Affidavit of JE Kunklin re inspector certifications & QA advisory committee meeting. KONKLIN-J E Region 3. Office of Director 83/09/27 App 20634 003 24% Fiche 50-440,83/09/29.8310050375
- --8310050387 Affidavit of JF Streeter & Tf. Vendel supporting NRC position on GA advisory committee Prof qualifications encl STREETER.J F. VENDEL, T E. Region 3. Office of birector 63/09/29 7pp 20634 009 24X Fiche 80-440,83/09/29,8310050175
- 8310050520 Answer apposing this Citizens for Responsible Energy 0'0016 motion to resubmit Contention 2 reduced generator reliability Motion fails to meet criteria of adequate basis & specificity Certificate of Sycienci SWIGER, M.A. Cleveland Electric Illuminating Co. SWIGER, M.A. Shew, Pittman, Potts & Trowbridge 83/10/03 Atomic Safety and Licensing Board Panel 53pp. 20634-106. 24X Fiche 50-440.83/10/03.8310050570
- 8310110061 Order extending time until 83100/ for Commission to act to review ALAB-73A CHILK, 9 J Office of the Secretary of the Commission 83/10/05 Commissioners to 20668 238 24X fiche 50-440,83/10/03, 8310110061
- 8310130144 Response opposing Unio Citizens for Responsible Energy 830916 motion to resubmit original proposed Contention 4 in diesel generator reliability Requirements for late-filed contentions not mot Certificate of Svc entl GCLDEFRO.S C Hearing Branch 4 93/10/06 Atomic Safety and Licensing Goard Panel 46pp 20749 092 24X Fiche 50-440.83/10/06.8310130144
- 8310120099 Reply to applicant & NRC affidavits re-motion to reopth GA record FUIA request made in Nov 1989 pinduced negative results formal discovery closed 3 months prior to ASIII issue identification W/Certificate of Svc Related correspondence HIATT, 5 L Ohio Citizens for Responsible Energy 83/10/07 Atomic Safety and Licensing Board Panel 11pp 20697 109 4X Fiche 30-440,83/10/07,8310120099
- 8310130224 Advises that time for Commission to review ALAB-736 expired Commission declined review Decision became final agency action on 831007 CHILKIS J Office of the Societary of the Commission 83/10/12 Office of the Executive Legal Director 1p 20724 094 24X Fiche 50-440,83/10/12,8310130224
- 8310180337 Motion for reconsideration of ASLB 830807 Memorandum & Bider LBP-83-46 granting summary disposition of Issue 13 Motion based on addi evidence Certificate of Svc enci Related correspondence MIATT-S L Ohio (itizens for Meaponsible Energy 83/10/14 Atomic Safety and Licensing Board Panel App 20803 002 24% Fiche 50-440,83/10/14,8310180347

- 9310190061 Response to util & NKC B31003 & 06 answers respectively to Ohio Citizens for Responsible Energy 830916 motion to resubmit Contention 2 NRC misunderstood thrust of motion Contention should be admitted W/Certificate of Svc HIATT.S L. Ohio Citizens for Responsible Energy 83/10/14 Atomic Bafety and Licensing Board Panel 11pp 20823 211 24X Fiche 50-440.83/10/14.8310190061
- 8310270252 Answer opposing Ohio Citizens for Responsible Energy (OCRE) 831007 request to hald open Issue 3 record until fuel load Request reiterates previously denied OtkE motion Certificate of Svc encl GLASSPIEGEL.H Cleveland Liectric Illuminating Co 83/10/24 Atomic Safety and Liensing Voard Panel Open 20923 240 247 Fiche 50-440,83/10/24,8310270262
- 8310270330 Response opposing this Citizens for Responsible Energy (OCRE) 831014 response to NRC & util answers to OCRE motion to resubmit Contention 2 re diseasel generator DCRE competence remains unproven Certificate of Syc entl SILBERG, J E (leveland Electric Illuminating Co SILBERG, J F Shaw, Pittman, Potts & Trowbridge 83/10/25 Atomic Safety and Licensing Board Panel 7pp 20923 145 24X Fiche 50-440,83/10/25,8310270330
- G. Inspection reports, IE Bulletins & correspondence
- B306300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Sec list encl JCRDAN, C.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/24 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300J40
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Vruti)ation Air Intakes " Syc list encl JORDANIC L. Division of Emergency Precaredness & Engineering Response (Post 830103) 83/09/26 Commodidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list end! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 E4X Fiche 50-000,83/09/26,8308300345
- 8310170662 Forwards IE Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0831 & notice of violation KNDP.R C Region 3. Office of Director 83/09/28 EDELMAN, N R Cleveland Electric Illuminating Co 2pp 20779 286 24X Fiche 50-440,83/09/28,8310170662
- --8310170667 Notice of violation from insp on 830701-0831 KNOP,R C Region 3, Office of Director 83/09/28 Ip 20779 288 24% Fiche 50-440,83/09/28,8310170662
- --9310170670 IE Insp Repts 50-440/83-27 & 50-441/83-26 on 830701-0831 Noncompliance noted failure to follow problem evaluation for 10CFR50 55(e) reportability procedures GILDNER,M L., KONKLIN, J E Region 3. Office of Director 83/09/27 4pp 20779 289 24X Fiche 30-440,83/09/28,83J0170662
- 8308300349 JE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFRSO 59 Evaluation." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20714-324 24% Fiche 50-000,83/09/29,8308300349
- 8310240121 Forwards IE Insp Repts 50-440/83-28 & 50-441/83-27 on 830722-23 No noncompliance noted KNOP.R C Region 3. Office of Directp: 83/10/04 EDELMAN, M R Cleveland Electric Illuminating Ca 2np 20881 145 24X Fiche 50-440,83/10/04,8310240121
- --8310240137 IE Insp Repts 50-440/83-28 & 50-441/83-27 on 830721-23 Nn noncompliance noted Major areas inspected licensee actions on previous insp findings. NOCFR50 50(e) reportable items & IE bulletin pelkE,P R , DAVIS,A B , KONKLIN,J E Region G, Office of Director 63/10/03 3pp 20881 147 24X Fiche 30-440,83/10/04,8310240121
- 8310200045 Forwards IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19 & notices of violation & deviation LITTLE, W B Region 3, Office of Director 83/10/05 EDELMAN, N R Cleveland Electric Illuminating Co 2pp 20836 009 24X Fiche 50-440,83/10/05,8310200045

- --8310200057 IE Insp Repts 50-440/83-26 & 50-441/83-25 on 830816-19
 Noncompliance noted bus bar support between 4,160-volt
 switchgear cubicles modified w/o approval & GA records
 corrected improperly
 MERRIMEATHER, N. Region 3, Office of Director CONLON.T E
 Division of Engineering 83/10/05 7pp 20836 013 24X
 Fiche 50-440.83/10/05,8310200045
- 8308300378 IE Info Natice 83-65. "Surveyllance of Flow in ATD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, C.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consulidated Edison Co. of New York, Inc. 76pp 20827 213 24% Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " 8vc list one) JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830)03] B3/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergancy Use Respirator Matl Defect Causes Production of Nox1ous Gases " Svc list encl JORDAN.E L Division of Emergancy Preparadness & Engineering Response (Post 830103) 83710711 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 127 24% Fiche 50-000,83/10/11,8308300761
- 8310180215 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON.W L. Region 3, Office of Director 89/10/14 EDELMAN.M f Cleveland Electric Illuminating Co. 7pp. 20808-309 24X Fiche 50-440.83/10/14.8310180215
- 8310270422 Forwards IE Insp Repts 50-440/83-29 & 50-441/83-28 on 830927-30 & notice of violation SPESSARD.R L. Division of Engineering 89/10/14 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 20923 045 24X Fiche 50-440,83/10/14,8310270422
- --8310270423 Notice of violation from insp on 830927-30 SPESBARD,R L. Division of Engineering 83/10/14 ip 20923 067 24X Fiche 50-440.83/10/14.8310270422
- --8310270426 IE Insp Repts 50-440/83-29 & 50-441/83-29 on 830927-30 Noncompliance noted licenses GA program did not provide for developing approving & distributing relay setting sheets MERRIWEATHER.N Region 3, Office of Director CONLONIT E Division of Engineering 83/60/11 &pp 20923.068 24X Fichs 50-440,83/10/14.8310270422
- S Reportable occurrences, LERs & related correspondence
- 8310110425 FOIA request for info re PNO-III-83-027 concerning faulty valve radiographs, PNO-III-83-026 concerning use of lubricant on valve seats & info on DDE/NRC 830419-20 meetings concerning geologic repository in salt program HIATT, S. L. Dhio Citizens for Responsible Energy 83/05/10 FELTON, J.H. Division of Rules and Records is 20706-001 24X Fiche 50-000, 83/05/10, 8310110425
- 8310110430 Responds to FOIA request for four different categories of documents described in B30510 ltr Forwards matl listed in App Airesponsive to Items 1:2 & 4.DOE should be contacted for matl requested in litem 3 of itr FELTON.JM Division of Rules and Records. B3/06/14 HIATJ.B.L. Ohio Citizens for Responsible Energy 3pp 20706/002 24X Fiche 50~000,83/06/14.8310110430
- ~-8310110443 Forwards PNG & morning rept to faulty Borg~Harner valve radiographs.Problem may be generic Related info encl LITTLE,W B Region 3, Office of Director. 83/04/13 POFAPOVS,U Region 4, Office of Director 15pp 20706 005 24X Fiche 50-000,83/06/14,8310110430
- --8310110461 Excerpt from notification of events at two different facilities re deficiency concerning control complex chilled water sys & info received that grease incorrectly used on MSIVs, respectively Related info encl
 * Region 3, Office of Director 83/04/08 iipp 20706 044 24X Fiche 80-000,83/06/14,8310110430

- 8310040404 Final deficiency rept re NANCO Controls limit switches mfg to inadequately implemented 0A program Initially Reported on 810210 Bill of matl age: (\$8793-05-4549-00) developed, reviewed & approved for procurement of NANCO switches EDELMAN.H R Cleyeland Electric Illuminating Co 83/09/27 KEPPLER.J G Region 3. Office of Director 3pp 20617 357 44X Fiche 30-440.83/09/27.8310040404
- 8310120286 Interim deficiency rept re failure of panel circuit witing in Transamerica Delaval standby diesel generators to meet IEEE 383 insulation flame test Vendor info under review Final rept scheduled for submittal by 831230 EDELMANIM R Cleveland Electric Illuminating Co 83/09/27 KEPPLERJ O Region 3. Office of Director ip 20693 346 24X Fiche 50-440,83/09/27.8310120286
- B3100A0340 Final deficiency rept re violations of spec requirements during installation of adjacent Hilti Kwik bolts Initially reported on 830207 One-inch balts will no longer be used Insp program will be implemented EDELMAN.H R Cleveland Electric Illuminating Co 83/09/30 KEPPLER.J O Region 3. 0ffice of Director 2pp 20646 125 243 Fichs 30-440.83/09/30.8310060340
- 8310060392 Final deficiency rept re rejection of previously accepted fadiographs on containment vessel shell plate welds initially reported on 820405 Accessible rejectable welds excavated, repaired & reradiographed EDELMAN.H R Cleveland Electric Illuminating Co 83/09/30 KEPPLERJ 0 Region 3, Office of Director 2pp 20644 105 24X Fiche 50-440.83/09/30.8310060392
- 8310170469 Second interia Deficiency Rept RDC 78(83) re exhaust line back pressures exceeding manufacturer recommendations on standby diesel generators for HPCS Initially reported on 830805 Further mods required Also reported per Part 21 EDELMAN.H R Cleveland Electric Illuminating Co 83/10/06 KEPPLER.J Q Region 3, Office of Director 2pp 20784 101 24X Fichs 30-440.83/10/06.8310170469
- 8310250483 Final deficiency rept re contact leads on OE HMA relays Initially reported on 820818 Evaluation revealed no instances of insufficient lead to terminal spacing Potential deficiency not applicable to Unit 2 HMA relays EDELMAN.M R Claveland Electric Illuminating Co 83/10/18 KEPPLERIJ 0 Region 3, Office of Director ip 20897 142 24X Fiche 50-441,83/10/18.8310250483
- B310270030 Interim deficiency rept re pipe support shap welds sumplied by Power Piping Co Initially reported on 830921 Engineer support evaluation will be completed in Dec 1983 Final rept will be summitted by 831215 EDELMAN.M g Clevelsnd Electric Illuminating Co 83/10/18 KEPPLER.J g Region J. Office of Director 2pp 20924 334 Q4X Ficha 50-440.83/10/18.8310270030
- B310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as B30927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Seria) 74039/40 DSR 48) Instruction for cable changeout due in Nov B0YER.R E Transamerica Delayal. Inc 83/10/20 Director's Office. Office of Inspection and Enforcement 1p 20924 108 24X Fiche 50-000.83/10/20.8310270206
- DOCKET 50-443 SEABROOK MUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8310070232 Notification of Significant Licensee Heeting B3-86 on 831005 at alter to discuss open electrical items.issues & commitments
 CERME.A Region i. Office of Director 83/09/28 Region i.
 Office of Director is 20664 362 24% Fiche 30-443,83/09/28,
 8310070232
- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Mestinghouse plant numer provide statement that required plant-specific calculations have been performed for Pirst cycls
 EISENMUTD G Division of Licensing 83/09/29 PALLADIND, N. J Commissioners 10pp 20632 106 24X Fiche 50-000, 83/09/29, 8308300355
- 8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants.in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISEN-NIT.D Q Division of Licensing 83/10/04 PALLADINO, N J Commissioners 2pp. 20698 033 24x Fiche 50-000, 83/10/04, 8308300763.

- B310120263 Forwards resolution & press release re reduced expenditure level & const artivity on Unit 2 Reduced expenditure level will be continued until fuel loading for Unit 1 completed, unless Unit 2 canceled
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire B3/10/05 KNIGHTON, 6 W Lirensing Branch 3 5pp 20693 073 24X Fishe 50-443,83/10/05,8310120263
- B30830077; Board Notification B3-128A forwards Equipment Qualification Branch conclusions re potential problems w/ASCO solonoid valves EISEMMATA C Division of Licensing B3/10/06 PALLADIND, N J Commissioners 31pp 20818 001 24X Fiche 50-000, 83/10/06, 83083007/1
- 8310240187 Forwards Amend 51 to application for DL transferring
 0 412597 punership share from Vermont flectric Cooperative,
 Inc to Vermont Electric Generation & Transmission
 Cooperative, Inc Certificate of Eye encl
 RITSHER.J A Ropes & Gray 83/10/17 Division of Licensiny Ip
 20912 252 24X Fiche 50-443.83/10/17.8310240187
- --83i0260201 Amend 51 to application for DL transferring O 41747% awnership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc. JOHNBON, V P. Public Service Co. of New Hampshire. 83/10/00; Division of Licensing. Opp. 20912 253 24X Fiche 50-441, 83/10/17, 8310260187
- ---8310260208 Info furnished per 10CFR90 33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements enc.)
 GALLAGHER, JW Vermont Electric Cooperative, Inc. 63/09/30
 24pp 20912 259 24X Fishe 50-443,83/10/17.8310240187
- F Security, medical, emergency & fire protection plans
- 8310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREO-0584" LESSY, R P Hearing Branch 3 83/10/12 HOYT, H, LUEDKC, L A, HARBOUR, J Atomic Bafety and Licensing Board Panel 24pp 20785 045 24X Fiche 50-443,83/10/12,8310170394
- O Adjudicatory correspondence
- 8310030355 Motion to diamiss DL application for Unit 2 Further const efforts deferred until Unit 1 complete Jul 1987 estimated const completion date for Unit 2 abandoned W/Certificate of Svc BACKUB, R A Seecoast Anti-Pollution League BACKUB, R A Huckus, Shea & Meyer 83/09/26 Atomic Safety and Licensing Board Panel 7pp 20593 063 24X Fiche 50-443,83/09/26,8310030355
- 8310030397 Comments on scheduling of offsite emergency planning contentions should be contentions should be litigated together Issues similar & seems withersee will testify on both plans Certificate of Ovc encl BISBEE.G D New Hampshire. State of 80/09/26 7pp 20592 343 24X Fiche 50-443,83/09/26,8310030397
- 8310040533 Objects to conduct at 830831 hearing re continued participation of Town of Rye, NM representative G Chichester Earlier telicon did not advise Town that Chichester dismissed from further participation
 NADEAU-JP, YOUNG, Mt., HOLWAY, FI Rye, NH 83/09/26 NOVI, FI Atomic Safety and Licensing Board Panel 2pp 20623 279 PAX Fiche 50-443,83/09/26,8310040533.
- 8310050366 Response to State of MA Atty General 830909 contention re offsite emergency planning for Towns of Seabrook, Hampton, North Hampton & Rye Present wording of contention w/o regulatory basis Certificate of Svc encl PATTERSON, W F. LEBSY, R P. Hearing Dranch 3 83/09/26 Alomic Safety and Licensing Board Panel 9pp 20630 345 24X Fiche 50-443,83/09/26,8310050366
- 8310030472 Response to Town of Hampton Falls, NH 830906 offsite emergency planning contention Contention not apposed LESSY, R F. PATTERSON W F. Hearing Dranch 3 83/09/26 Atomic Safety and Licensing Board Panel 3pp 20633 190 24X Fiche, 50-443, 83/09/26, 8310050472
- --8310050474 Response to Commonwealth of MA 830909 motion for clarification of ASLB 830830 order admitting contentions k motion for reconsideration of ABLB 830830 order on evacuation time estimates Notions not opposed LESSY, R. P. PATTERSON, W. F. Hearing Branch 3, 83/09/26. Atomic Safety and Licensing Board Panel 3pp 20833, 193 24X Fiche 50-443, 83/09/26, 8310050472

- --8310050477 Response opposing JF Doherty 830906 petition to intervene No good cause shown for petition late by 22 months Ditter factors for untimely intervention not mot PATTERSON, W F. LESSY, R P Hearing Branch 3 83/09/26 Atomic Safety and Licensing Board Panel 7pp 20633 196 24X Fiche 50-443,83/09/26,8310050472
- --B310030480 Response to Hampton Beach Area Chamber of Commerce 830708 contentions on offsite emergency planning for Town of Hampton, NH Objects to admission of Contentions 1,11,111 & IV(a,b,e,f & q) Certificate of Svc untl PATTERSON, W F , LEGSY, R P Hearing Branch 3 83/09/26 Atomic Bafety and Licensing Board Panel 13pp 20633 203 24X Fiche 30~443,63/09/26,83100304/2
- B310040510 Position on schedule of offsite emergency planning isques Hearings on New Hampshire radiological emergency response plans & local plans should be postponed until Mar 1984 Certificate of Svc encl CASSIDY, B P Federal Emergency Management Agency B3/09/27 29pp 20625 216 24X Fiche 80-443,83/97/27,8310040510
- 8310050551 Response to Town of Kensington contentions re emergency planning Town of Kensington resolution of concerns & inadequacies expected prior to litigation of Contentions I(a-d) & II Certificate of Svc encl
 PATTERSON.W F . LEBGY.R P Hearing Branch 3 83/09/27 Atomic Safety and Licensing Board Panel Bpp 20629 346 24X
 Fiche 50-443,83/09/27,8310050551
- 8310040256 Interrogatories & requests for documents re emergency planning for State of NH
 BELLOTTIFF X Massachusetts, Commonwealth of 83/09/29 Federal Emergency Management Agency 12pp 20613 005 24X
 Fiche 50-443,63/09/29,8310040256
- --8310040262 Interrogatories & requests for documents re emergency planning for State of NH BELLOTTIF X Massachusetts, Commonwealth of 83/09/29 New Hampshire, State of 12pp 20613 017 24X Fiche 50-443,83/09/29,8310040284
- --B310040272 Notice of 831017 deposition in Boston, MA of all util, NRC, State of NH or FEMA witnesses re admitted contentions on draft New Hampshire radiological emergency response plans SHOTWELL, J A Nassachusetts, Commonwealth of B3/09/29 2pp 20613 029 24X Fiche 50-443, 83/09/29, 8310040256
- --8310040277 Interrogatories & requests for documents re emergancy planning for State of NH Certificate of Svc encl
 BELLOTTI,F X Massachusetts, Commonwealth of 83/09/29 Public Service Co of New Hampshire 11pp 20613 031 24X
 Fiche 50-443,83/09/29,8310040256
- 0310050373 Response to Seacoast Anti-Pollution League 030909 supplemental petition for leave to intervene & contentions re offsite emergency planning Objects to Contentions 11.14. 15.17.18.19.20.22 & 23 Certificate of Svc ancl PATTERSON.W F. LESSY.R P. Heaving Branch 3 83/09/29 Atomic Safety and Licensing Board Panel 25pp 20632 268 24X Fiche 50-443.83/09/29.8310050373
- --B310050381 Response to New England Coalition on Nuclear Pollution 830909 contentions on State of NH offsite radiological amergency response planning Objects to listed contentions Certificate of Svc encl PATTERSON, W F , LESSY.R F Hearing Branch 3 83/09/29 Atomic 8afety and Licensing Board Panel. 21pp 20432,273 24X Fiche 50-443,83/09/29,8310050373
- --8310050388 Response to Town of Beabrook,NH 830707 contentions re offsite emergency planning Objects to Contentions 1,5,6,7, 12 & 10 Contificate of Svc encl PERLIB,R G , PATTERSON,W F , LEBSY,R F Hearing Branch 3 83/07/29 Atomic Safety and Licensing Board Panel 14pp 20632 314 24% Fiche 50-443,83/07/29,8310050373
- 8310080378 Opposes presently worded proposed contention on local emergency planning 8td of providing complete protection under all circumstances not dictated by law PATTER80N.W F Hearing Branch 3 83/10/03 8HOTWELL.J Massachusetts, Commonwealth of 2pp 20629 337 24X Fiche.50-443,83/10/03.8310050378
- 8310110152 Motion for leave to file response to NRC & applicant answers to Atty General FX Bellotti motion for reconsideration of ASLB ruling on evacuation time estimate preparation time Gentificate of Byc encl.

 8HOTHELL, J A Hassachusetts, Commonwealth of 83/10/03 Atomic Safety and Licensing Board Panel 5pp 20666 287 24X Fiche 50-443,83/10/03,8310110152

- 831012017B Requests to be advised of steps necessary to appeal ASLB dismissal of 9 Chichester from proceeding & advises that contentions will be resubmitted NADEAU.JP, YOUNG, M.L., HOLMAY, F.I. Rye, NH 83/10/03 HOYT, H.F. Atomic Safety and Licensing Board Panel 3pp 20695 292 24X Fiche 50-443,83/10/03.831012017B
- 8310110302 Amended petition for leave to intervene Syc of Process encl DDHERTY, J F Doherty, J F 83/10/04 Atomic Safety and Licensing Board Panel 7pp 20465:024 24X Fishe 50-443,83/10/04,8310110202
- 93i01i03i6 Requests leave to amend potition for leave to intervene Amended petition based on applicant & NRC urging for uncountenanced expansion of NRC rulings & misrepresentation of petitioner arguments in one case

 DOHERTY, J F Doherty, J F 83/10/04 Atomic 8afety and Licensing Board Panel 1p 20665 006 24X Fiche 50-443,83/10/04:83i01i03i6
- 83i0110049 Order extending time until 83i013 for Commission to act to review ALAB-737
 CHILK.8 J Office of the Becretary of the Commission 83/10/05
 Commissioners ip 20668 272 24X Fiche 50-443, 83/10/05, 831010049
- B310110083 Forwards proposed findings of fact & conclusions of law GAD,R K Ropes & Oray GAD,R K Public Service Co of New Hampshire B3/10/05 Office of the Secretary of the Commission ip 20668 157 24X Fiche 50-443, B3/10/05, B3101100B3
- --8310110092 Proposed findings of fact & conclusions of law.Certificate of Syc enel DIONAN.T G , OAD,R K Public Service Co of New Hampshire DIONAN.T G Ropes & Gray 83/10/05 54pp 20668 158 24X Fiche 50-443.83/10/05.8310110083
- 8310110158 First set of interrogaturies on State of NH radiological emergency response plan CURRAN,D., JORDAN,W S. New England Coalition on Nuclear Pollution CURRAN,D. Harmon & Weiss 83/10/05 Federal Emergency Management Agency 4pp 20866 241 24% Fiche 50-443,83/10/05,8310110158
- ---B310110165 First set of interrogatories on State of NH radiological emergency response plan CURRAN, D . JORDAN, W B New England Coalition on Nuclear Pollution CURRAN, D. Harmon & Weiss 83/10/05 Public Service Co of New Hampshire 3pp 20666 245 24X Fiths 50-443,83/10/05,8310110158
- ~-8310110170 Objection to improper ASLB conduct, response to util position as to scheduling of emergency planning issues & request for hearing on licensing schedule CURRAN, D. JURDAN, W.S. New England Coalition on Nuclear Pollution CURRAN, D. Harmon & Weiss 83/10/05 10pp 20666 248 24X Fiche 50-443,83/10/05,8310110188
- --8310110175 First set of interrogatories on State of NH radiological emergency response plan Certificate of Byc encl.
 CURRAN.D., JORDAN.W.S. New England Coalition on Nuclear Pollution.
 CURRAN.D. Harmon & Weiss 83/10/05 New Hampshire, State of 15pp 20666 258. 24X Fiche 50-443.83/10/05
- 8310110227 Interrogatories & requests for documents on emergency planning for State of NH Related correspondence BACKUB,R.A Seacoast Anti-Pollution League. BACKUB,R A Backus. Bhea & Heyer B3/10/05 Public Service Co of New Hampshire 7pp 20665 316 24X Fiche 50-443,83/10/05,8310110227
- 8310520133 Answer opposing Seacoast Anti-Pollution League 830926 motion to dismiss OL application for Unit 2 Hoong regulation cited NRR.not ASLB.issues DLs League argument previously rejected by ABLB Certificate of Svc encl DIGNAN.T O , OAD,R % Public Service Co of New Hampshire DIGNAN.T O goes & Gray 83/10/06 Atomic Safety and Licensing Board Panel 9pp 20695 270. 24% Fichar 50-443,83/10/06,8310120133
- B310120428 Response opposing Town of Hampton B30919 contentions on town radiological emergency response plan. No justification offered for late filing Towns should not be allowed to attack own plans Centificate of Svc encl
 DIONAN. T. G. OAD, R. K. Public Bervice Co. of New Hampshire
 DIONAN. T. G. Ropes & Gray B3/10/06. Atomic Safety and Licensing Board Panel 4pp 20698 326 24X Ficha 50-443, 83/10/06. B310120428.
- 8310130255 Discusses rev to NRC 830926 response to State of MA contentions on offsite emergancy planning for Towns of Beabrook, Hampton, North Hampton & Rye. Rev limited to local plans & provisions re Town sheltering responsibilities PATTERSON.W F Hearing Branch 3 83/10/06, SHOTMELL, J A Massachusetts, Cammonwealth of 3pp 20723 234 24X Fiche 30-443,83/10/04,8310130255

- 8310140015 Lists OA procedures approved for implementation & available for imp at station Svc list encl QAD.R K Ropes & Gray 83/10/06 CURRAN,D Harmon & Weiss Spp 20767 041 24X Fiche 50-443,83/10/06,8310140015
- 8310140021 Response to applicant 830921 motion for denial of Towns of AUDISONAL INSPONSE to applicant B3092; motion for denial of Kensingston & South Hampton contentions re emergency planning Plans Formulated by private consulting firm & not endorsed by towns Certificate of Svc encl CAVUTES, Sensington, NH VERGE, A W South Hampton, NH 83/10/06 Atomic Safety and Licensing Board Panel 9pp 20747 032 24X Fiche 50-443,83/10/06,8310140021
- B310120107 Motion for disqualification of Judge Hoyt Hostility toward intervenor & state counsel.as well as municipal representatives apparent & ever-increasing Appearance of partiality established BACKUB, R A Beacoast Anti-Pollution League BACKUB, R A Beacoast Anti-Pollution League
- --8310120111 Reply opposing applicant objection to Sedcoast Anti-Pollution League supplemental petition for leave to intervene Applicant objections w/o merit Contentions should be adaptical BACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Rai be aparties BACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Bact Bhea & Meyer 83/10/07 Aboatc Safety and Licensing Board Panel 7pp 20695 247 24X Fiche 50-443.83/10/07.8310120107
- --0310120115 Affidavit in support of 831007 motion for recusal of Judge BACKUS,R A Seacoast Anti-Pollution League B. Shea & Meyer 83/10/07 2pp 20695 254 24X Fiche 50-443.83/10/07.8310120107 BACKUS, R A Backus,
- --8310120122 Answer supporting New England Coalition on Nuclear Pollution (NECNP) reply to applicant & NRC responses to NECNP contentions on State of NH radiological emergency response plan BACKUS, R A Seacoest Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Panel Ip 20695 256 24X Fiche 50-443-83/10/07.8310120107
- --8310120126 Erreta to 830926 motion to dismiss DL application for Unit 2 City on Page 1 should read IDCFR57(a)(1) BACKUS,R A Spacoast Anti-Pollution League BACKUS,R A Backus, Share & Mayer 83/10/07 Atomic Safety and Licensing Board Panel 1p 20695 257 24X Fichy 50-443.83/10/07.8310120107
- ~-B310120135 Hotion to stay further ASLB rulings pending review & appeal of Seacoast Anti-Pollution League motion for recusal of Judge Hout BACKUB.R A Seacoast Anti-Pollution League BACKUB.R A Backus, Shaw & Heyer B3/10/07 Atomic Safety and Licensing Soard Panel 1p 20695 258 24X Fishe 50-443.83/10/07.6310120107
- ~-B310120141 Reply to NRC response to Seacoast Anti-Pollution League supplemental petition for leave to intervene concerning sacragency planning contentions Certificate of Svc encl RACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backu Shea & Mayer B3/10/07 Atomic Gafety and Licensing Board Panel 9pp 20695 239 24% Fiche 30-443, B3/10/07, B310120107
- 8310)20147 Motion for summary disposition of Commonwealth of MA Contentions I.II.III.IV A & IV 9.Seacoast Anti-Pollution League Contention 5 & New England Coalition on Nuclear Pollution Contentions 3.4.5.7.12 & 13 SHOTWELL. J A Massachusetts, Commonwealth of 83/10/07 A Safety and Licensing Board Panel 46pp 20696 042 24% Fishe 50-443.83/10/07.8310120147 Atomic
- --8310120131 Answer to NRC & util 830926 & 20, respectively, responses to Commonwealth of MA B30909 seergency planning contentions Evecuation within times extimated will subj beachgoers to State radiation doses Certificate of Svc encl BMOTHELL. J A Massachusetts, Commonwealth of 83/10/07, Atomic Bafety and Licensing Board Panel 10pp. 20676 088 24X Fiches 30-443,83/10/07,8310120147
- #310130046 Response opposing Town of Rue contentions re emergency planning for State of NH & Town of Rue Contention I vague & raises issues outside hearing scope Contention 2 already likingsted Certificate of Svc encl. PATTERSON, H. F. LESSY, P. Hearing Branch 3 B3/10/11 Atom Safety and Licensing Beard Panel 10pp 20725-065 24x Fiche. 50-443, 83/10/11, 8310130046

- B310j40171 Reply to util & NRC responses to New England Coulitian on Nuclear Pollution contention on State of NH local emergency response plans Coalition has specifically alleged unreliability of info in plans W/Certificate of Bvc CURRAN, D. JORDAN, W S. New England Coalition on Nuclear Pallution CURRAN, D. Harmon & Weiss B3/10/11 Atomic Safety and Licensing Board Panel 16pp 20762 315 247 Fishe 50-443 83/10/11.
- B310170394 Forwards draft App D to radiological amergency response plans for Towns of NewFredgs.New Castle.North Hampton & Brentwoods.NH. shtitled "Cross-Reference to NURCE-065A" LESSY.R P Hearing Branch 3 83/10/12 HUYT.H., LUCIBEC, A., Atomic Safety and Licensing Doard Panel Pape 20785 045 24% Fische 50-443-83/10/12/8310170394
- B310180150 Forwards applicant B31012 response to FX Bellotti molion for leave to file responses to NRC & util answers to Diale of MA motion for reconsideration of ASLB ruling on systemation time estimates preparation time of the Service Co of New Hampshire B3/10/12 Office of the Service Co of New Hampshire B3/10/12 Office of the Service not the Commission in 2000 154 24X Fichs 50-443,83/10/12,8310180130
- --83(0180153 Response to FX Bellotti 831003 motion for leave to file response to NRC & util answers to mation for reconsideration of ABLB ruling on evacuation time estimates preparation time Certificate of Svc encl DIGNAN.T 6 . GAD.R K Public Service Co of New Hampshire DIGNAN.T 6 Ropes & Gray 83/10/10 Atomic Bafety and Licensing Board Panel 14pp 20809 155 24X Fiche 50-443,83/10/12,8310180150.
- 8310180368 Notice of continuance of depositions of witnesses on State of NH radiological emergency response plan scheduled for wk of 831017
 SHOTMELL, J.A. Massachusetts, Commonwealth of 83/10/12 Opp 20803 175 24X Fiche 50-443,83/10/12,8310180340
- --B3101B0373 Motion for leave to file response to NRC B31006)tr which constituted supplemental answer to Commonwealth of MA contention on emergency planning Contention is not untime)y Certificate of Syc enci SHOTHELL.J A Massachusetts, Commonwealth of B3/10/12 Atomic Safety and Licensing Board Panel 5pp 20803 177 24X Fiche 50-443,83/10/12,8310180368
- 8310170424 Order extending time until 831025 for Commission to act to review ALAB-737 CHILKS J Office of the Secretary of the Commission 83/10/13 Commissioners ip 20784 037 24X Fiche 50~443,83/10/13,
- 8310180165 Forwards answer to Atty General Bellotti interrogatories & requests for documents on emergency planning for State of NH NH GADLR K Ropes & Gray GAD.R K Public Bervice Co of New Hampshire B3/10/13 Docketing & Services Branch Ip 20809 114 24k Fiche 50-443,83/10/13.8310180165
- --8310180170 Answers to interrogatories & requests for documents on emergency planning for State of NH Certificate of Svc section of New Hampshire D10NAN, T G , GAD, R K Public Service Co of New Hampshire D10NAN, T G Ropes & Gray B3/10/13 Massachusetts.

 Commonwealth of 22pp 20807 115 PAX Fiche 50-443,83/10/13,8310180165
- 8310180329 Contentions on State of NH evacuation time atudy. Certificate of Byc encl of Byc encl CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution CURRAN, D Harmon & Weiss B3/10/13 Atomic Bafety and Licensing B310180329

 B310180329
- B310200R67 Answer supporting JF Doherty B31004 request for leave to amend petition to intervene Petition for leave to intervene, as amended, should be denied Certificate of Svc encl DIGNAN, T 9, OAD,R K. Public Service Co of New Hampshire DIGNAN,T 9 Ropes & Grey B3/10/17, Atomic Bafety and Licensing Board Panel App 20830 047, 24X Fiche 50-443,83/10/17,831020026/
- 8310200277 Response to New England Coalition on Nuclear Pollution B31005 objection to improper ABLB conduct, response to applicant position as to scheduling of emergency planning issues & request for hearing Certificate of Box encl DIGNAN, T 0 , DAD, R K Public Service Co. of New Hempshire. DIGNAN, T 0 Ropes & Gray B3/10/17 Atomic Bafety and Licensing Board Panel 7pp 20829 311 24X Fiche 50-445.83/10/17.831020027/

- B310250319 Response opposing Seacoast Anti-Pollution League 830926 motion to dismiss application for Seabrook Unit 2 Subj not properly before ASLB but NRR Certificate of Svc encl LESBY,R P. PATTERSON,W F. Hearing Branch 3 83/10/17 Atomic Bafety and Licensing Board Panel App. 20898-003 24X Fiche 50-443.83/10/17.8310250319
- 8310260262 Inquires if ASLB issued order re author 830906 petition for leave to intervene & 831004 request for leave to amend petition for leave to intervene Related correspondence DOHERTY, J.F. B3/10/20 HDYT.H., HARBOUR, J. LUEBKE, E. A. Atomic Safety and Licensing Board Panel 1p 20911 328 24X Fiche 50-443.83/10/20.8310260262
- 8310250044 Order denying Seacoast Anti-Pollution League 831007 motion to stay further ASLB rulings pending review & appeal of motion for disqualification of Judge Hoyt Orounds for stay insufficient Delay would disrupt proceeding HOYT.H F Atomic Safety and Licensing Board Panel 83/10/21 Seacoast Anti-Pollution League 2pp 20874 195 24X Fiche 50-443,83/10/21,8310250044
- 0310250056 Motion to compel answers to Atty General Bellotti
 interrogatories & requests for documents to applicants on
 emergency planning for State of NH Subj matter of witness
 testimony not described Certificate of Svc ancl
 SNEIDER, C B Massachusetts, Commonwealth of 83/10/21 Atomic
 Safety and Licensing Board Fanel 12pp 20876 096 24X
 Fiche 50-443,83/10/21,8310250056
- 8310260254 Answer opposing Seacoast Anti-Follution League (SAPL) 831007 motion to stay further ASLB rulings pending review & appeal of SAPL motion for disqualification Motion frivolous, absurd & allows Judge-shopping Certificate of Svc encl DIGNAN.T G , OADLR K Public Service Co of New Hampsbire DIGNAN.T G fores & Gray 83/10/24 Atomic Safety and Licensing Board Panel 5pp 20912 124 24X Fiche 50-443,83/10/24,8310260254
- --8310260261 Answers to 831005 interrogatories & requests for documents on emergency planning Certificate of 8vc ancl JOHNSON W P. DIGNAN.T G , 6AD.R K Public Service Co of New Hampshire 83/10/24 Beacoast Anti-Pollution League 11pp 20912 129 24X Fiche 50-443,83/10/24.8310260254
- --8310260266 Answer to 831005 first set of interrogatories on State of NH radiological emergency response plan Certificats of Syc encl
 JOHNSON, 4 F. DIONAN, T. C., CAD, R. K. Public Service Co. of Nrw 'Hampshire 83/10/24 New England Coalition on Nuclear Pollution 7pp 20912 140 24X Fiche 50-445, 83/10/24, B310260254
- --83102A0272 Answer opposing Beacoast Anti-Pollution League (BAPL) 83100/motion for disqualification of Judge Hoyt SAPL spoiling for fight disrespectful & contemptuous of ASLB & guilty of Judge-batting Centificate of Syc encl
 DIGNAN, T G . GAD, R K Public Bervico Co of New Hampshire,
 DIGNAN, T G . Ropes & Gray B3/10/24 Atomic Safety and
 Licensing Board Panel 37pp 20912 147 24X
 Fichs 50-443,83/10/24,8310260254
- B31027021B Order extending time until B31101 for Commission to act to review ALAB-737 CHILK,8 J Office of the Secretory of the Commission 83/10/25 Commissioners ip 20924 040 24% Fiche 50-443,83/10/25, 8310270218
- 8310280109 Order granting Atty General Bellotti 831012 motion for leave to file response to NRC 831006 ltr & NRC 831024 metion for leave to file supplemental response to proposed contention re offsite emergency planning HDYT.H F Atomic Safety and Licensing Gourd Panel 83/10/26 Massachusetts. Commonwealth of 2pp 20729 215 24X Fiche 50-443.83/10/26.8310280107
- B310310202 Proposed findings of fact & conclusions of law on Contentions I B 2, III i, III 3 & 21 Certificate of Bvc encl CURRAN, D. JORDAN, W S. New England Coalition on Nuclear Pollution CURRAN, D. Harmon & Weiss. B3/10/27 24pp 2095B 332. R4X Fiche 50-443, B3/10/27, 8310310202

H General correspondence

8310050508 Requests assistance in obtaining financial repts & other info from Yankee Atomic Electric Co by being included on svc list CHICHESTER, G Rye, NH CHICHESTER, G Rye Nuclear Intervention Committee. 83/09/07 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 20634-016 24X Fiche 50-443,83/09/07,8310050508

I Financial information

- 8310240187 Forwards Amend 51 to application for OL transferring 0 41259% ownership share from Varmont Electric Cooperative. Inc to Vermont Electric Generation & Transmission Cooperative, Inc Certificate of Svc encl RITSHER, J A Ropes & Gray 83/10/17 Division of Licensing. 1p 20912 252 24X fiche 50-443,83/10/17,8310260187
- --8310260208 Info furnished per 10CFR50 33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements encl GALLAGHER. J W Vermont Electric Cooperative, Inc. 83/07/30 24pp 20912 259 24X Fiche 50-443,83/10/17.8310260187
- O Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand~Ins for Welder Qualification Tests " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83709726 Consolidated Edison Co of New York, Inc 117pp 20754 022 24% Fiche 50-000,83709726,8308300340
- 8308300342 IE Info Notice 83-82, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list enct JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26, Consolidated Edison Co of New York, Inc. 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Byo list encl JURDAN E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24x Fiche 50-000,83/09/26.8388300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 57 Evaluation " Syc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/27 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24% Fiche 50-000, 83/09/29, 8308300349
- 8310190133 Forwards IE Insp Rept 50-443/83-12 on 830808-12 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 83/10/05 HARRISON, R J Public Service Co of New Hampshire 2pp 20820 276 24X Fiche 50-443,83/10/05,8310190133
- --8310190136 Notice of Violation from insp on 830808-12 * Region 1. Office of Director 83/10/05 ip 20820-278 24X Fiche 50-443.83/10/05.8310170133
- --8310190142 IE insp Rept 50-443/83-12 on 830808-12. Noncompliance noted Ultrasonic exam for acceptance of safety-related components (fillet welds) performed w/o qualified ultrasonic test procedure

procedure
MCBREARTY, R A , NARROW, L , ORAY, E H Region 1, Office of Director
83/09/28 8pp 20820 279, 24% Fiche 50-443,83/10/05,8310190133

- 8310190172 Forwards IE Insp Repts 50-443/83-14 & 50-444/83-11 on B30815-19 & notice of violation MARTIN, T. T Division of Engineering & Technical Programs B3/10/05. HARRISON, R J Public Service Co of New Hampshire 2pp 20821 080 24X Fiche 50-443,83/10/05,8310190172
- --8310190175 Notice of violation from insp on 830815-19 * Region 1, Office of Director 83/10/05 1p 20821.082 24X Fiche: 50-443.83/10/05,8310190172
- --8310190180 IE Inep Repts 50-443/83-14 & 50-444/83-11 on 830815-19, Noncompliance noted failurs to properly inspect electrical terminations of small gauge conductors RICHARDS, E. ANDERBON, C. Region 1, Office of Director, 83/10/05, 6pp 20821;083, 24X Fiche 50-443,83/10/05,8310190172
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Byo list encl. JORDAN.E.L Division of Emergency Preparedness & Engineering Response (fost 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp. 20827.213 24X Fiche: 50-000, 83/10/07, 8308300378.
- 8308300752 IE Info Notice 83-64. "Fatality at Argentine Critical Facility " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp. 20882 026. 24% Fiche, 50-000, 83/10/07, 8308300752.

- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Hatl Defect Causes Production of Novious Gases" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24% Fiche 50-000,83/10/11 830B300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York: Inc. 120pp 20827 129 24X Fichs 50-000.83/10/11.8208300761
- 8310270445 Forwards IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821226 830110-14 & 16-21 & 50-443/1-83-007 & 50-444/1-83-007 on 63041-0603 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/10/19 HARRISON&R J Public Service Co of New Hampshire 2pp 20922 016 24X Fiche 50-443, 83/10/13.8310270445
- --B310270462 IE Investigation Repts 50-443/1-B3-001 & 50-444/1-B3-001 on B2122B, B30110-14 & 18-21 No noncompliance noted Major areas investigated allegations re intinidation & harrassment of GC inspector & hanger weld deficiencies SHEPHERD, R. E. CHRISTOPHER, R. MARD, W. Office of Investigation 83/08/02 3pp. 20922 018 24% Fiche 50-443,83/10/13,8310270445
- --8310270474 IE Investigation Repts 50-443/1-83-007 & 50-444/1-83-007 on 830411-0603 No noncompliance noted Majar areas investigated alleged employer discrimation by licensee contractor Perini Power Constructors. Inc SHEPHERD, R. C. CHRISTOPHER, R. HARD. M. Office of Investigation. 83/08/19 4pp 20922 021 24X Fiche 50-443.83/10/13.8310270445
- 8310210243 Ack receipt of 830907 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 50-443/83-08 MARTIN.T T Division of Engineering & Technical Programs 83/10/17 HARRISON.R J Public Service Co. of New Hampshire 1p 20852 012 24X Fiche 50-443,83/10/17.8310210243
- --8310210250 Responds to NRC 830809 itr re violations noted in IE Insp. Rept 50-443/83-08 Corrective actions engineers reindoctrinated re in-place storage requirement & need for preventative maint Rules on cleanliness established DEVINCENTIS.J Yankes Atomic Electric Co. DEVINCENTIS.J Public Service Co. of New Hampshitre 83/09/07 MARTIN.7 T Division of Engineering & Technical Programs App. 20852-013 24X Fiche 80-443,83/10/17.8310210243
- S Reportable occurrences. LERs & related correspondence
- 8310070163 Part 21 rept re potential defects in molded case of 100amp frame, multi-pole E & HE series circuit breakers Initially reported on 830902 ERHARDT.J V Gould: Inc 83/09/26 MURLEY, T E Region 1. Office of Director. 10pp 20659 095 24X Fiche 50-000,83/09/26, 8310070163
- 8310060343 Part 21 rept re Gould unitized starters supplied as spare parts Initially reported on 830723 Final rept expected 831130 BEVINCENTIS, J Public Service Co of New Hampshire 83/09/28 Region 1, Office of Director 4pp 20646-135 24X Fiche 80-448,83/09/28-8310060343
- B3101400B2 PNO-I-83-105 on B31007, seismic event occurred in northeastern US w/magnitude of 5 2 on Richter scale in NY & 4 0 in NH No damage to equipment identified OALLO,R M Region 1. Office of Director B3/10/07 ip 20766 116 24X Fiche. 50-000. 83/10/07. 8310140082
- U. Congressional/Executive Correspondence
- 8310060363 Forwards ABLB 830927 ltr to C Nord re accidental oversight in skipping C Nord at recent limited appearance session. ABLB allowed Nord to submit written statement LEMIS.D R. Atomic Safety and Licensing Board Panel 83/10/04 HTLDT.B. Massachusetts, Commonwealth of ip 20646 072 24X Fiche 50-443, 83/10/04.8310060363
- ---8310060364 Requests assistance in determining reason for ABLB not allowing constituent C Nord to testify at 83083; hearing HILDT.B Massachusetts, Commonwealth of 83/09/27 LEMIB.D R Atomic Safety and Licensing Board Panel 1p. 20646 074 24X Fichs. 30-443, 83/10/04, 8310060363

- B3102800BB Requests public notification of hearings that hearings be held in State of MA or near site & that C Nord be scheduled to present public oral comments
 COSTELLO,N J Massachusetts, Commonwealth of 83/10/04 NOY1,N .
 LUEBKE,E A . HARBOUR.J Atomic Safety and Licensing Board Fanel
 4pp 20735 081 24X Fiche 50-443,83/10/04,831028008B
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8310070232 Notification of Significant Licenses Meeting 83-86 on 83100°, at site to discuss open electrical items, issues & commitments.

 CERNE, A Region I, Office of Director 83/09/28 Region I, Uffice of Director ip 20664 362 24X Fiche 50-443,83/09/28, 8310070232
- 8308300355 Board Notification 83-66A advises that position re rod drep issue revised to require each Westinghouse plant owner provide Statement that required plant-specific calculations have been performed for first cycle EISENHUT, D & Division of Licensing 83/09/29 PALLADING,N J Commissioners 10pp 20632 106 24X Fiche 50-000,83/09/29,8308300355
- B30B300763 Board Notification B3-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants.in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclea: Power Station EISENHUT. D 9 Division of Licensing B3/10/04 PALLADINO.N J Commissioners 2pp 2047B 033 24X Fiche 50-000.83/10/04. B3083000763
- 8310120243 Forwards resolution & press release re reduced expenditure level & const activity on Unit 2 Reduced expenditure level will be continued until fuel loading for Unit 1 completed, unless Unit 2 canceled BEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/10/05 KNIGHTON.C W Licensing Branch 3 5pp 20693 073 24X Fiche 50-443,83/10/05.8310120249
- 8308300771 Board Notification 83-128A forwards Equipment Gualification Branch conclusions repotential problems w/ASCO solenoid valves EISENHUT, D. O. Division of Licensing 83/10/06 PALLADINO, N. J. Commissioners 31pp 20818 001 24X Fiche 50-000,83/10/06, 8308300771
- 8310260187 Forwards Amend 51 to application for OL transferring O 41259% ownership share from Vermont Electric Cooperative. Inc to Vermont Electric Generation & Transmission Cooperative.Inc Certificate of Svc encl RITSHER.J A Ropes & Gray 83/10/17 Division of Licensing 19 20912 252 24X Fiche 50-443.83/10/17.8310240187
- --8310260201 Amend 51 to application for OL transferring O 41757% ownership share from Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc JOHNSON, V P Public Service Co of New Hampshire 83/10/03 Division of Licensing App 20912 253 24% Fiche 50-443, 83/10/17,8310260187
- --8310260208 Info furnished per 10CFR50 33 of Commission rules & regulations as part of request for partial transfer of commership of CP Financial statements encl GALLAGHER, JW Vermont Electric Cooperative, Inc. 83/09/30 24pp 20912 259 24X Fiche 50-443.83/10/17.8310260187
- F Security, medical, emergency & fire protection plans
- 8310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields, New Castle, North Hampton & Brentwood, NH, entitled "Cross-Reference to NUREG-0A54" LESSY, R P Hearing Branch 3 83/10/12 HDYT, H Atomic Sofety and Licensing Board Panel 26pp 20785 045 24X Fiche 50-443,83/10/12,8310170394
- Q. Adjudicatory correspondence
- B310030355 Motion to dismiss OL application for Unit 2 Further const
 efforts deferred until Unit 1 complete Jul 1987 estimated
 const completion date for Unit 2 abandoned W/Certificate of
 Svc.
 BACKUB, R A Seacoast Anti-follution League BACKUB, R A Backus,
 Shea & Meyer B3709726 Atomic Safety and Licensing Board Pauri
 7pp. 20593 043 24% Fiche 50-443.6370726,8310030355

- 8310030397 Comments on scheduling of affilte emergency planning contentions All offsite planning contentions should be litigated together Issues similar & some witnesses will testify on both plans Certificate of Svc encl
 BISBEE, O D New Hampshire, State of 83/09/26 7pp 20592 349 24X Fiche 50-443, 83/09/26, 8310030397
- 8310040533 Objects to conduct at 830831 hearing re continued participation of Town of Rye.NH representative G Chickester Earlier telcon did not advise Town that Chichestor dismissed from further participation
 NADEAU, J P., YDUNG, M L., HOLWAY, F I Rye, NH 83/09/26 HOYT, N Atomic Safety and Licensing Board Panel 2pp 20623 279 24X
 Fiche 50-443,83/09/26,8310040533
- 8310030366 Response to State of MA Atty General 830909 contention re offsits emergency planning for Towns of Seabrook, Hampton. North Hampton & Rye Present wording of contention w/n regulatory basis Certificate of Svc encl
 PATTERSON.W F. LESSY.R P Hearing Branch 3 83/09/26 Atomic Safety and Licensing Board Panel 9pp 20630 345 24X
 Fiche 50-443.83/09/26.8310050366
- 8310050472 Response to Town of Hampton Falls, NH 830906 offsite emergency planning contention Contention not opposed LEGSY, R.P., PATTERSON, W.F. Hearing Branch 3 B3709/26 Atomic Safety and Licensing Board Panel 3pp 20633 170 24X Fiche 50-443,83/09/26,8310050472
- --B310050474 Response to Commonwealth of NA B30907 motion for clarification of ASLB B30B30 order admitting contentions & motion for reconsideration of ASLB B30630 order on evacuation time estimates Motions not opposed LEBSY.R P . PATTERSON.W F Hearing Branch 3 B3/09/26 Atomic Safety and Licensing Board Panel 3pp 20633 193 24X Fichs 50-443.83/09/26.8310050472
- --8310030477 Response opposing JF Doberty H30906 petition to intervene No good cause shown for petition late by 22 months Other factors for untimely intervention not met PATTERSON.W F., LESBY.R P. Hearing Branch 3 83/09/26 Atomic Bafety and Licensing Board Panel 7pp 20633 176 24X Fiche 50-443.83/09/26,8310050472
- ---B3100504B0 Response to Hampton Beach Area Chamber of Commerce 830908 contentions on offsite emergency planning for Town of Hampton, NH Objects to admission of Contentions I, II, III & IV(a, b, e, f & g) Certificate of Svc enc!
 PATTERSON, W F , LESBY, R P Hearing Branch 3 83/09/26 Atomic Safety and Licensing Board Panel 13pp. 20633 203 24X Fiche. 50-443, 83/09/26, 8310050472
- B310040510 Position on schedule of offsite emergency planning issues
 Hearings on New Hampshire radiological emergency response
 plans & local plans should be postponed until Mar 1984
 Certificate of Bvc encl
 CASSIDY.B P Federal Emergency Management Agency
 20625 214 24X Fichs 50-443.83/09/27.8310040510
- 8310050551 Response to Town of Kensington contentions re emergency planning Town of Kensington resolution of concerns & inadequacies expected prior to litigation of Contentions I(a-d) & II Centificate of Svc and PATTERSON.W F. LESSY.R P Hearing Dranch 3 83/09/27. Atomic Safety and Licensing Board Panel Spp 20627 346. 24% Fiche 50-443,83/09/27,8310050555
- 8310040256 Interrogatories & requests for documents re emergency planning for State of NH BELLOTTI.F X Massachusetts, Commonwealth of 83/09/29 Federa: Emergency Management Agency 12pp 20613 008 24X Fiche 50-443,83/09/29.8310040256
- --B310040262 Interrogatories & requests for documents re emergancy planning for State of NH BELLOTTI.F X Massachusetts, Commonwealth of. B3/09/29 New Hampshire, State of 12pp 20613 017. 24X Fiche 50-443,83/09/29, B310040256
- --8310040272 Notice of 831017 deposition in Boston, MA of all util, NRC, State of NH or FEMA withesses re admitted contentions on draft New Hampshire radiological emergency response plans BHOTWELL, J. Massachusetts, Commonwealth of 83/09/29 2pp, 20613 029 24% Fiche 50-443,83/09/29,8310040256,
- --B310040277 Interrogatories & requests for documents to emergency planning for State of NH. Certificate of Svc encl
 BELLOTTI, F X Massachusetts, Commonwealth of B3/09/29 Public Service Co. of New Hampshire. lipp 20613 031 24X
 Fiche 50-443,83/09/29,8310040256

- 8310050373 Response to Seacoast Anti-Pollution League 830909 supplemental petition for heave to intervene & contentions re offsite emergency planning Objects to Contentions 11.14, 15.17.18.19.20, 22 & 23 Certificate of Svc encl PATTERSON W F. LESSY.R P Hearing Branch 3 83/09/27 Atomic Safety and Licensing Board Panel 25pp 20632 268 24X Fiche 50-443.83/09/29.8310050373
- --8310050381 Response to New England Coalition on Nuclear Pollution 830707 contentions on State of NH offsite radiological emergency response planning Objects to listed contentions Certificate of Svc encl PATTERSON.W F , LESSY.R F Hearing Branch 3 83/09/29 Atomic Bafety and Licensing Board Panel 21pp 20632 293 24X Fiche 50-443,83/09/29,8310050373
- --8310050388 Response to Town of Scabrook,NH 830909 contentions re offsite emergency planning Objects to Contentions 1:5,6,9, 12 & 10 Certificate of Svc encl PERLIS.R G . PATTERSON, H F , LESSY, R F Hearing Branch 3 83/09/29 Atomic Safety and Licensing Board Panel 14pp 20632 314 24X Fiche 50-443,83/09/29,8310050373
- 83:0050378 Opposes presently worded proposed contention on local emergency planning 8td of providing complete protection under all circumstances not dictated by law PATTERBON.W F Hearing Branch 3 83/10/03. SHOTWELL, J Massachusetts. Commonwealth of. 2pp. 20629:337 24X Fiche 50-443.83/10/03.8310050378
- B310110152 Motion for leave to file response to NRC & applicant answers to Atty General FX Bellotti motion for reconsideration of ASLB ruling on execuation time estimate preparation time Certificate of Bvc encl
 SHOTWELL, J A Massachusetts, Commonwealth of B3/10/03 Atomic
 Safety and Licensing Board Panel Spp 20666 287 24X
 Fiche 50-443,83/10/03.8310110152
- B31012017B Requests to be advised of steps necessary to appeal ASLB dismissal of G Chichester from proceeding & advises that contentions will be resubmitted NADEAU, JF, YOUNG, M L, HOLHAY, F I Rye, NH 83/10/03 HOY1, H F Atomic Bafety and Licensing Board Panel 3pp 20695 272 24X Fiche 50-443,83/10/03,831012017B
- 8310110202 Amended petition for leave to intervene Svc of Process encl DOHERTY, J F Doherty, J F 83/10/04. Atomic Safety and Licensing Board Panel 7pp 20665 024 24% Fiche, 50-443, 83/10/04, 8310110202
- 8310110316 Requests leave to amend petition for leave to intervenc Amended petition based on applicant & NRC urging for uncountenanced expansion of NRC rulings & misrepresentation of petitioner arguments in one case DOHERTYJF Doherty, JF 83/10/04 Atomic Safety and Licensing Board Panel ip 20665-006 24X Fiche 50-443,83/10/04,8310110316
- 8310110049 Order extending time until 831013 for Commission to act to review ALAB-737 CHILK,B J Office of the Secretary of the Commission 83/10/05. Commissioners ip 20648 272 24X Fiche 50-443,83/10/05, 8310110049
- 8310110083 Forwards proposed findings of fact & conclusions of law GAD,R K Ropes & Gray GAD,R K Public Service Co of New Hampshire 83/10/05 Office of the Secretary of the Commission. ip 20668, 157 24% Fiche 50-443,83/10/05
- --8310110072 Proposed findings of fact & conclusions of law Certificat of Byc encl DIGNAN.T.G., PAD.R K. Public Service Co of New Hampshire DIGNAN.T.G. Ropes & Gray 83/10/05 54pp. 20668 158 24X Fiche 50-443,83/10/05,8310110083
- 8310110158 First set of interrogatories on State of NH radiological emergency response plan CURRAN.D., JGRDAN.W.8 New England Coalition on Nuclear Pollution CURRAN.D. Harmon & Weiss. 83/10/05. Federal Emergency Managemen Agency 4pp 20666 241 24X Fiche 50-443.83/10/05.8310110158
- ---B310110165 First set of interrogetories on State of NH radiological emergency response plan.

 CURRAN, D., JORDAN, W. S. New England Coalition on Nuclear Pollution CURRAN, D. Harmon & Helss B3/10/05. Public Service Co. of New Hampehire 3pp. 20666 245 24X Fithe, 50-443, 83/10/05, 8310110158
- ---B310110170 Objection to improper ASLE conduct, response to util positions to scheduling of emergency planning issues & request for hearing on licensing schedule CURRAN, D., JORDAN, W. B. New England Coelition on Nuclear Pollution CURRAN, D. Harmon & Weiss B3/10/05 10pp. 20666 248, 24X Fiche 50-443,83/10/05,8310110158

- --8310110175 First set of interrogatories on State of NH radiological emergency response plan Certificate of Svc encl CURRAN.D. JORDAN.H S. New England Coalition on Nuclear Pollution CURRAN.D. Harmon & Weiss 83/10/05 New Hampshire, State of 15pp 20664 238 24% Fiche 50-443.83/10/05,8310110158
- 8310110227 Interrogatories & requests for documents on emergency planning for State of NH Related correspondence BACKUS, R. A Backus, Shea & Meyer BAJ10/05 Public Service Co of New Hampshire 9pp 20665 316 24X Fiche: 50-443,83/10/05,8310110227
- 8310120133 Answer opposing Beacoast Anti-Pollution League 830926 motion to dismiss OL application for Unit 2 Hrong regulation cited NRR.not ABLB.issues OLs League argument previously rejected by ASLB Certificate of Svc encl DIGNAN.T 0 . OAD.R K Public Service Co of New Hampshire DIGNAN.T 0 . Ropes & Gray 83/10/06 Atomic Safety and Licensing Board Panel 9pp 20495 270 24X Fiche 50-443.83/10/06.8310120133
- 8310120428 Response opposing Town of Hampton 830919 contentions on town radiological emergency response plan No justification offered for late filing Towns should not be allowed to attack own plans Certificate of Svc encl
 DIGNAN.T G. GAD.R K. Public Bervice Co. of New Hampshire.
 DIGNAN.T G. Ropes & Oray 83/10/06. Atomic Safety and Licensing Board Panel App. 20498-326. 24X Fichs 50~443.83/10/06.8310120428
- 8310130255 Discusses rev to NRC 830926 response to State of MA contentions on offsite emergency planning for Towns of Seabrook, Hampton Hampton & Rye Rev limited to local plans & provisions re Town sheltering responsibilities PATTERSON, W.F. Hearing Branch 3 83/10/06 SHOTHELL, J.A. Massachusetts, Commonwealth of 3pp 20723 234 24X Fiche 50-443,83/10/06,8310130255
- 8310140015 Lists QA procedures approved for implementation & available for inep at station. Svc list encl
 QAD, R K. Ropes & Gray 83/10/06 CURRAN, D Harmon & Weiss Dpp
 20767 Q41 24X Fiche 50-443.83/10/06.8310140015
- 8310140021 Response to applicant 830921 motion for denial of Towns of Kensington & Bouth Hampton contentions re emergency planning Plans formulated by private consulting firm & not endorsed by towns Certificate of Svc ancl GAVUTIO.8 Kensington, NH VERGE.A W South Hampton, NH 83/10/06 Atomic Safety and Licensing Board Panel 9pp 20767 032 24X Fichs 50-443,83/10/06,8310140021
- 8310120107 Motion for disqualification of Judge Hout Hostility toward intervenor & state Counsel, as well as municipal representatives apparent & ever-increasing Appearance of partiality established BACKUS, R A Seacoast Amti-Pollution League BACKUS, R.A Bactus, Shea & Meyer 82/10/07 Atomic Safety and Licensing Board Fanel 68pp 20695 178 24X Fiche 50-443,69/10/07,6310120107
- --B310120111 Reply opposing applicant objection to Beacoast Anti-Follution League supplemental petition for leave to intervene Applicant objections w/o merit Contentions should be admitted
 BACKUB.R.A Seacoast Anti-Pollution League. BACKUB.R.A Backus.
 Shea & Mayer 83/10/07 Atomic Safety and Licensing Board Panel. 7pp. 20695 247 24X Fiche 50-443,83/10/07.8301220107
- --8310120115 Affidavit in support of 831007 motion for recusal of Judge Hout BACKUS,R.A Seacoast Anti-Pollution League BACKUS,R.A Backus, Shea & Meyer 83/10/07 2pp 20695, 254 24X Ficha: 50-443,83/10/07,8310120107.
- --8310120122 Answer supporting New England Coalition on Nuclear Pollution (NECNP) reply to applicant & NRC responses to NECNP contentions on State of NH radiological amergency response plan

 BACKUS, R. A. Beacoast Anti-Pollution League BACKUS, R. A. Backus, Shea & Mayer 83/10/07 Atomic Safety and Licensing Board Panel 1p 20695 256 24X Ficher 50-445,83/10/07,8310120107
- ---8310120126 Errata to 830926 motion to diamiss OL application for Unit 2 Cite on Page 1 should read 10CFR57(a)(1) BACKUS,R A Seaccast Anti-Pollution League BACKUS,R A Backus, Shea & Hayer 83/10/07 Atomic Safety and Licensing Board Panel. 1p 20695:287 24% Fiche 50-443,83/10/07.8310120107.
- --8310120135 Motion to stay further AGLB rulings pending review & appeal of Beacoast Anti-Pollution League motion for recusal of Judge Hout BACKUB, R.A. Beacoast Anti-Pollution League, BACKUB, R.A. Backus, Shea & Meyer. 83/10/07, Atomic Safety and Licensing Board Panel, 1p. 20695-258 24X Fiche 50-443,83/10/07,8310120107.

- --8310120141 Reply to NRC response to Seacoast Anti-Pollution League supplemental petition for leave to intervene concerning emergency planning contentions Certificate of Svc encl BACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Backus, Shea & Meyer 83/10/07 Atomic Safety and Licensing Board Fanel 9pp 20695 259 24X Fiche SO-443,83/10/07,8310120107
- 8310120147 Motion for summary disposition of Communuealth of MA Contentions I.II./III.IV A & IV G.Beacoast Anti-Pollution League Contentions 5 & Now England Coalition on Nuclear Pollution Contentions 3.4, 5.7, 12 & 13 SHOTHELL. J A Massachusetts, Commonwealth of 83/10/07 Atomic Safety and Licensing Board Panel 46pp 20696 042 24X Fichs. 50-443.83/10/07.8310120147
- -8310120151 Answer to NRC & util 830926 & 20. respectively, responses to Commonwealth of MA 830909 emergency planning contentions Evacuation within times estimated will subj beachgoers to fatal radiation doses Certificate of Svc encl SHOTMELL, J A Massachusetts, Commonwealth of B3/10/07 Atomic Safety and Licensing Board Panel 10pp 20696 088 24% Fiche 50-443,83/10/07,8310120147
- 8310130044 Response opposing Town of Rye contentions to emergency planning for State of NH & Town of Rye Contention 1 vague & raises issues outside hearing scope Contention 2 already litigated Certificate of Svc encl PATTERBON.W F. LESSY.R P. Hearing Branch 3 83/10/11 Atomic Sefety and Licensing Board Panel 10pp 20725 065 24X Fiche 50-443,83/10/11,8310130046
- B310140191 Reply to util & NRC responses to New England Coalition on Nuclear Pollution contention on State of NH local emergency response plans Coalition has specifically alleged unreliability of info in plans W/Certificate of Svc CURRAN, D. JURDAN, W S. New England Coalition on Nuclear Pollution CURRAN, D. Harmon & Weiss B3/10/11 Atomic Safety and Licensing Board Panel 16pp 20762 315 24X Fiche 50-443,83/10/11, B310140191
- B310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields.New Castle, North Hampton & Brentwoods.NH, entitled "Cross-Reference to NURGO-0654" LESSY.R P Hearing Branch 3 B3/10/12 HOYT.H., LUEDKE,E A. HARBOUR.J Atomic Safety and Licensing Board Panel Zópp 20785 045 24X Fiche 50-443,83/10/12,8310170394
- 8310180150 Forwards applicant B31012 response to FX Bellotti motion for leave to file responses to NRC & util answers to State of MA motion for reconsideration of ASLB ruling on evacuation time estimates preparation time GAD,R K Ropes & Gray GAD,R K Public Service Co of New Hampshire 83/10/12 Office of the Secretary of the Commission in 20807 154. 24X Fiche 50-443,83/10/12,8310100150
- --B310180153 Response to FX Bellotti B31003 motion for leave to file response to NRC & util answers to motion for reconsideration of ABLB ruling on evacuation time estimates preparation time certificate of Svc encl DIGNAN, T G, GAD, R K Public Service Co of New Hampshire DIGNAN, T G Ropes & Gray B3/10/12 Atomic Safety and Licensing Board Panel 14pp 20809 155 24X Fiche 50-443,83/10/12,8310180150
- 8310180368 Notice of continuance of depositions of witnesses on State of NH radiological emergency response plan scheduled for wk of 831017 SHOTHELL,J A Hassachusetts, Commonwealth of 83/10/12 2pp 20803 178 24X Fiche 50-443,83/10/12,8310180368
- --8310180373 Motion for leave to file response to NRC 831006 ltr which constituted supplemental answer to Commonwealth of MA contention on emergency planning Contention is not untimely Certificate of 8vc encl
 SHOTMELLU A Massachusetts, Commonwealth of 83/10/12 Atomic Safety and Licensing Board Panel Spp 20803 177 24X
 Fiche 50-443, 83/10/12. 8310180348
- 8310170424 Order extending time until 831025 for Commission to act to review ALAB-737 CHILKS J Office of the Secretary of the Commission 83/10/13 Commissioners 1p. 20784 037 24% Fiche 50-443,83/10/13,8310170424
- 8310180165 Forwards answer to Atty General Bellutti interrogatories & requests for documents on emergency planning for State of NH GAD, R K Ropes & Gray GAD, R K Public Service Co of New Hempshire, 83/10/13 Docksting & Bervices Branch 1p 20809 114 24X Fiche 50-443.83/10/13,8310180165

DOCKETED ITEMS

- --8310180170 Answers to interrogatories & requests for documents on emergency planning for State of NH Certificate of Svc encl DIGNAN.T G , GAD.R K Public Service Co of New Hampshire DIGNAN.T G Ropes & Gray 83/10/13 Massachusetts.

 Commonwralth of 22pp 20809 115 24X Fiche 50-443.83/10/13, 220180148
- 8310180327 Contentions on State of NH evacuation time study Certificate of Svc encl
 CURRAN.D., JORDAN,W S. New England Coelition on Nuclear Pollution
 CURRAN.D Harmon & Weiss 83/10/13 Atomic Safety and Licensing
 Board Panel 10pp 20801 154 24X Fiche 50-443,83/10/13,
 8310180329
- 8310200267 Answer supporting JF Doherty 831004 request for leave to amend patition to intervene Petition for leave to intervene, as amended, should be denied Certificate of Svc encl.

 DIGNAN, T G , GAD, R K Public Service Co of New Hampshire

 DIGNAN, T G Ropes & Gray 83/10/17 Atomic Safety and Licensing Board Panel 4pp 20830 047 247 Fiche 50-443, 83/10/17, 83102002067
- 6310200277 Response to New England Coalition on Nuclear Pollution
 831005 objection to improper ASLB conduct, response to
 applicant position as to scheduling of emergency planning
 issues & request for hearing Centificate of Svc encl
 DIGNAN.T G . GAD, R K Public Service Co of New Hampshire
 DIGNAN.T G Ropes & Gray. 83/10/17 Atomic Safety and Licensing
 Board Panel 7pp 20829 311 24X Fiche 50~443,83/10/17.8310200277
- 8310250319 Response opposing Seacoast Anti-Pollution League 830924 motion to dismiss application for Beabrook Unit 2 Subj not properly before ASLB but NRR Certificate of Svc encl LESSY,R P , PATTERSON,W F Hearing Branch 3 83/10/17 Atomic Safety and Licensing Board Panel App 20898 003 24X Fiche 50-443,83/10/17,8310250319
- 8310260262 Inquires if ASLB issued order re author 830906 petition for leave to intervene & 831004 request for leave to amend petition for leave to intervene Related correspondence DOHERTY. J F Doherty. J F 83/10/20 HQYT.H , HARBOUR.J , LUEBKE, E A Atomic 84fety and Licensing Board Panel Ip 20911 328 24X Fichs 50-443,83/10/20.8310260262
- 8310290044 Order denying Seacoast Anti-Pollution League 831007 motion to stay further ASLB rulings pending review & appeal of motion for disqualification of Judge Hoyt Grounds for stay insufficient Delay would disrupt proceeding. HOYT.H F Atomic Safety and Licensing Board Panel 83/10/21 Seacoast Anti-Pollution league 2pp 20894 195 24X Fiche 90-443.83/10/21.8310250044
- 8310290096 Motion to compel answers to Atty General Bellotti
 interrogatories & requests for documents to applicants on
 emergency planning for State of NH Subj matter of witness
 testimony not described Cortificate of Syc encl
 SNEIDER(C S Massachusetts, Commonwealth of 83/10/21 Atomic
 Safety and Licensing Board Panel 12pp 20876 086 24X
 Fiche: 50-443,83/10/21,8310250056
- 8310260254 Answer opposing Seacoost Anti-Pollution League (SAPL) 831007 motion to stay further ASLD rulings pending review & appeal of SAPL motion for disqualification Motion frivolous absurd & allows judge-shopping Certificate of Svc encl DIGMAN.T G . GAD,R K Public Service Co of New Hampshire DIGMAN.T G Ropes & Gray 83/10/24 Atomic Safety and Licensing Board Fanel 5pp 20912 124 24X Fiche 50-443,83/10/24,8310260254
- --8310260261 Answers to 931005 interrogatories & requests for documents on emergency planning Certificate of Svc encl
 JOHNSON-W P , DIGNAN-T 9 , GAD,R K Fublic Service Co. of New Hampshire 83/10/24 Beaccast Anti-Follution League 11pp,
 20912 129 24X Fiche 50-443.83/10/24,8310260254
- --8310260266 Answer to B31005 first set of interrogatories on State of NH radiological emergency response plan Certificate of Svc encl
 JDHNSON:WP, DIGNAN:TG, GAD,RK Public Service Co. of New
 Hampshire 83/10/24 New England Coalition on Nuclear
 Pollution 9pp 20912 140 24X Fithe 50-443,83/10/24.8310260254
- --8310260272 Answer opposing Spacoast Anti-Pollution League (BAPL) 831007 motion for disqualification of Judge Hout SAPL spoiling for fight disrespectful & contemptuous of ASLB & guilty of judge-baiting Certificate of Svc enc!

 DIGNAN.T G , GAD,R K Public Service Co of New Hampshire DIGNAN.T G Ropes & Gray 83/10/24. Atomic Safety and Licensing Board Panel 37pp 20712 147 24X Fiche 50-443.83/10/24.8310260254

- 8310270218 Order extending time until 831101 for Commission to act to review ALAB-73/ CHILK:5 J Office of the Secretary of the Commission. B3/10/25 Commissioners ip 20924.040 24X Fiche 50-443.83/10/25, 8310270218
- 8310280109 Order granting Atty General Bellotti 831012 motion for leav to file response to NRC 831006 ltr & NRC 831024 motion for leave to file supplemental response to proposed contention re offsite emergency planning HDYT.H F Atomic Safety and Licensing Board Panel. 83/10/26 Massachusetts. Commonwealth of 2pp 20929 215 24X Fiche 50-443.83/10/26.8310280109
- 8310310202 Proposed findings of fact & conclusions of law on Contentions I B 2,III 1,III 3 & 21 Certificate of Svc encl. CURRAN, D. JDRDAN, M S. New England Coalition on Nuclear Pollution CURRAN, D. Harmon & Weiss 83/10/27. 24pp 20958 332 24X Fiche 50-443.83/10/27.8310310202
- H General correspondence
- 8310050508 Requests assistance in obtaining financial repts & other info from Yankee Atomic Electric Co by being included on svc list CHICKESTER, G. Rye, NH. CHICKESTER, G. Rye Nuclear Intervention Committee 83/09/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p. 20634-016 24X Fiche: 30-443, 83/09/07, 8310050508.
- I Financial information
- 8310260187 Forwards Amend 51 to application for OL transferring O A1259% ownership share From Vermont Electric Cooperative, Inc to Vermont Electric Generation & Transmission Cooperative, Inc Certificate of Syc and RITSHER, J A Ropes & Gray 83/10/17 Division of Licenting 20912 252 24X Fiche 50-443,83/10/17,8310260187.
- --8310260208 Info furnished per 10CFR30 33 of Commission rules & regulations as part of request for partial transfer of ownership of CP Financial statements encl
 OALLAGHER, J W Vermont Electric Cooperative, Inc 83/09/30
 24pp 20912 239 24X Fiche 50-443,83/10/17,8310260187
- P Operating license stage documents & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list ancl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000, 83/09/26, 8308300340,
- O Inspection reports, IE Bulletins & correspondence
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Yoxic Pas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consulidated Edison Co. of New York, Inc 116pp, 20777 210 24X Fiche 50-000,83/09/26,8308300342
- B30B300345 IE Info Notice B3-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc. 118pp. 20778:001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related 8ys W/o 10CFR50 59 Evaluation." Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349.
- 8310190172 Forwards IE Insp Repts 50-443/83-14 & 50-444/83-11 on 830815-19 & notice of violation MARTIN.T T. Division of Engineering & Technical Programs. 83/10/05 HARRISON,R J. Public Service Co of New Hampshire 2pp 20821-080 24X Fiche 50-443.83/10/05,8310190172.
- --8310190180 IE Insp Repts 50-443/83-14 & 50-444/83-11 on 830815-19.
 Noncompliance noted feilure to properly inspect electrical terminations of small gauge conductors.
 RICHARDS, S. ANDERSON, C. Region 1, Office of Director, 83/10/05 App. 20821 083 24X Fiche.50-443,83/10/05,8310190172.

DOCKETED ITEMS

- 308300378 IE Info Notice 83-65. "Surveillance of Flow in RID Bypass Loops Used in Westinghouse Plants " Svc list end! JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 900103) 63/10/07 Consolidated Edison Co of Net York, Inc. 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- 308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Syc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of No. York, Inc. 79pp 20802 026 24X Fiche 50-000,83/10/07.8308360752
- 108300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Notious Gases" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co. of New
 York, Inc. 117pp. 21043:075 24X Fiche 50-000,83/10/11,8308300759
- 08300761 IE Info Notice 63-68, "Respirator User Harning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list and
- enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/11. Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 10270445 Forwards IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821228,830110-14 & 18-21 & 50-444/1-83-007 & 50-444/1-83-007 on 830411-0603 No noncompliance moted
- BTARGETCKI, R. Division of Project & Resident Programs B3/10/13 HARRISON, R. J. Public Service Co. of New Hampshire 2pp 20922 016 24% Ficher 50-443.83/10/13.83/0270445
- 3310270442 IE Investigation Repts 50-443/1-83-001 & 50-444/1-83-001 on 821228, 830110-14 & 18-21 No noncompliance noted, Major areas investigated, allegations re intimidation & harrassment of 9G inspector & hanger weld deficiencies, SHEPHERD, R. E., CHRISTOPHER, R., WARD, W Office of Investigation 83/08/02, 3pp 20922:018 24X Fichs 50-443,83/10/13,8310270445.
- 3310270474 IE Investigation Repts 50-449/i-83-007 & 50-444/i-83-007 on 830411-0603. No noncompliance noted Major areas investigated alleged employee discrimination by licenses contractor Perini Power Constructors. Inc SHEPHERD.R E. CHRISTOPHER.R. WARD.W. Office of Investigation 83/08/i9 4pp. 20922 021 24X Fichs 50-443.83/10/i3.8310270445
- Reportable occurrences, LERs & related correspondence
- 0070163 Part 21 rept re potential defects in molded case of 100-mp frame, multi-pole E & HE series circuit breakers nitially reported on 830902, RHARDT.J.V. Quuld, Inc. 83/09/26 HURLEY, T E. Region i, Office f Director. 10pp 20659 095 24X Fiche 50-000,83/09/26, 310070163
- 0040343 Part 21 rest re Gould unitized starters supplied as spare arts Initially reported on 830923. Final rest expected 31130
- EVINGENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public ervice Co of New Hampshire 83/09/28. Region 1, Office of irector App. 20646 135 24X Fiche 50-443,83/09/28,8310060343
- 0140082 PNO-I-83-105 on 831007, seismic event occurred in ortheastern UB w/magnitude of 5 2 on Richter scale in NY 4 0 in NH No damage to equipment identified.
 ALLO, RM. Region i, DPfice of Director 83/10/07 1p. 20766 116
- Congressional/Executive Correspondence
- DO60363 Forwards ASLB 830927 ltm to C Nord me accidental oversight n skipping C Nord at recent limited appearance session ASLB llowed Nord to submit written statement SWIS.D.R. Atomic Safety and Licensing Board Panel 83/10/04 ILDT.B Massachusetts. Commonwealth of. 1p. 20646-072. 24X Iche. 30-443,83/10/04-8310060363
- 310060364 Requests assistance in determining reason for ASLB not allowing constituent C Nord to testify at 830831 hearing.
 HILDT/B. Massachusetts, Commonwealth of. 83/09/27. LEHIB.D R Atomic Safety and Licensing Board Panel, 1p 20646:074. 24X Fiche: 50-443.83/10/04.8310060363.
- 280088 Requests public notification of hearings, that hearings be ld in State of MA or near site & that C Nord be scheduled present public oral comments.

 STELLO.N.J. Hassachusetts, Commonwealth of, B3/10/04 HOYT.H., EBKI.E.A.: HARBUR.J. Atomic Safety and Licensing Board Panel p. 20935:081. 24% Fiche 50-443,83/10/04,8310280088.

- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA JUNIT 1

 A Application/construction stage documents & correspondence
- 8310110007 Responds to FOIA request for SECY-82-279, SECY-82-330 & SECY-83-120 Forwards documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/07/15 PEDRO.J NUS Corp ip 20712 280 24X Fiche 50-445, 83/07/15, 8310110007
- --B310110022 Recommends issuance of encl proposed order directing ASLB to resume hearings as soon as possible on issue not involving informant identities
 PLAINE.H H Office of the General Counsel SECY-83-120
 83/04/01 4pp 20712 319 24X Fiche 50-445,83/07/15,8310110007
- 8310180582 FOIA request for VS Noonan 830426 memo to BJ Youngblood re add1 info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment PEDROLJ NUS Corp 83/08/17 Division of Rules and Records 1 20817 329 24X Fiche 50-445,83/08/17,8310180582
- 8310260279 Forwards nonproprietary & proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept." Proprietary version withheld (ref 10CFR2 790) RAHE,E P Westinghouse Electric Corp 83/08/26 EISENHUT,D G Division of Licensing. 2pp 20909 354 24X Fiche 50-445,83/08/26,8310260279
- --8310260281 Application for withholding proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept," per 10CFR2 770 Affidavit encl
- --8310260284 Nanproprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept" * Westinghouse Electric Corp SGPR-8301 83/06/30 140pp 20910 005 24X Fiche 50-445,83/08/26.8310260279
- --8310240286 Nunproprietary version of "Counterflow Preheat Steam Generator Tube Vibration Summery Rept "
 * Wastinghouse Electric Corp SOPR-8302 83/06/30 180pp 20910 144 24X Fichs 50-445,83/08/26.8310260277
- 83i0i80588 Responds to FOIA request for VS Noonan 830426 memo re add1 info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical squipment Forwards document FELTON.J.M Division of Rules and Records 83/09/06 PEDRO.J NUM Corp 19 20817 330 24X Fiche 50-445,83/09/06,83i0i80588
- --8305060124 Forwards request for add1 info necessary to complete review of licensee 830330 info re environ qualification of safety-related mechanical equipment located in horsh environ NOONAN, V S Equipment Qualification Branch 83/04/26 YOUNOBLOOD, B J. Licensing Branch 1 2pp 20817 331 24X Fiche 50-445, 83/09/06, 83/0180588
- 8308300355 Board Notification 83-66A advises that position re-rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle EISENHUT, D. G. Division of Licensing 83/09/29 PALLADING, N. J. Commissioners. 10pp 20632 106 24X Fiche 50-000,83/09/29, 0230830355
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canuon I & 2.Fermi 2 & Callaway EISENHUT, D G Division of Licensing 83/09/29 PALLADING, N J Commissioners. 3pp 20632 001 24X Fichs 50-000,83/09/29,8308300357
- 8310040604 Informs that instrument accuracy study for TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," will not be available on B30930 as stated in response to Generic Ltr 83-10C SCHMIDT, H. C. Texas Utilities Bervices, Inc. 83/09/30 YUUNOBLOOD, B. J. Licensing Branch i 1p. 20625 336 24X Fiche: 50-445, 83/09/30, 8310040604

- 8310040604 Informs that instrument accuracy study for TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," will not be available on 830930 as stated in response to Generic Ltr 63-10C SCHMIDT.H C Texas Utilities Services, Inc 83/09/30 YOUN08LODD,B J Licensing Branch i Jp 20625 336 24X Fiche 50-445, 83/09/30.8310040604
- B30B300763 Board Notification B3-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants.in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT,D 9 Division of Licensing B3/10/04 PALLADING,N J Commissioners 2pp 2069B 033 24X Fiche 50-000,B3/10/04.
- 830 B300771 Board Notification B3-12BA forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid valves
 EISENHUT, B B Division of Licensing B3/10/06 PALLADING, N J Commissioners 3ipp 20818 001 24X Fiche 50-000, B3/10/06, B308300771
- 8310170715 Forwards safety evaluation of FBAR Amend 3B re NUREG-0737, Item II F 2, "Detection of Inadequate Core Cooling " Amend unacceptable Justification for proposed late implementation of in-core thermocouples requested YQUNGBLOUD, B J Licensing Branch 1 83/10/07 GRAY, R J Texas Utilities Generating Co 4pp 20778 122 24X Fiche 50-445, 83/10/07,8310170715
- 8310280041 Forwards new heatup & cooldown curves for draft Tech Specs Curves not impacted by new 10CFR50, Apps Q & H which address metal temp of closure head flange Temp graphs encl SCHMIDT, H C Texas Utilities Services. Inc 83/10/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 20933 326 24% Fiche 50-445,83/10/11,8310280041
- 830B310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shoreham EISENKUT, D. G. Division of Licensing B3/10/14 PALLADING, N. J. Commissioners 15pp 67086 070 24X Fiche 50-000, B3/10/14, B308310050
- 8310210081 Informs that util response to TMI Item II.F 2 will be submitted by 831117 MARSHALL.J S Texas Utilities Generating Co 83/10/18 BURNELL.S B Licensing Branch 1 ip 20855 332 24X Fishe 50-448,83/10/18,8310210081
- F Security, medical, emergency & fire protection plans
- 8310040156 Forwards IE Insp Rept 50-445/83-29 on 830712-14 No noncompliance nated MADSEN, O. L. Region 4. Office of Director 83/09/02 GARY, R. J. Texas Utilities Generating Co. 3pp 20608 218 24X Fichs 50-445,83/09/02,8310040156
- --B310040160 IE Insp Rept 50-445/B3-29 on 839712-14 No noncompliance noted Major areas inspected approved guard training & qualification plan (App B to 10CFR73) Details withheld (ref 10CFR73 21)
 EVANS.C A. XELLY.J Region 4. Office of Director. 83/08/11 Ip 20608 221 24X Fichs 50-445,83/09/03,8310040156
- B310050424 Forwards DM Rohrer B30723 memo re B30707 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held B30726-1007 ROTHSCHILD, M U Hearing Branch 1 B3/07/27 BLGCH.P B , JURDAN.W H , MCCOLLON.K A Atomic Safety and Licensing Board Panel 3pp 20632 354 24X Fiche, 50-445, 83/07/27, 8310050424
- 8310110173 Forwards position paper "Engineering Basis for Structural Integrity of Raceway Supports Associated W/L H Rated Cable Protective Envelope Sys Upon Exposure to Fire "
 SCHMIDT: H C Taxas Utilities Services. Int 83/10/04
 YOUNOBLOOD, B J Office of Nuclear Reactor Regulation, Director ip 20466-227 24% Fiche 50-445,83/10/04,8310110173.
- --8310110177 "Engineering Basis for Structural Integrity of Raceway Supports Associated W/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire."

 * Texas Utilities Services, Inc 83/09/27 8pp. 20666 228 24X Fiche.50-445,83/10/04,8310110173.
- 8310110109 Releases public version of applicant ltr forwarding revised emergency plan implementing procedures FELTON, J M. Division of Rules and Records 83/10/05. Document Hanagement Branch 1p 20687 318 24X Fiche 50-445

- --B310110116 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-101 repreparation of emergency plan procedures & EPP-201 reassessment of emergency action levels W/o encl SCHMIDT.H C Towns Utilities Bervices, Inc 83/08/18, COLLINS, J T Region 4, Office of Director 2pp 20687 319 24X Fiche 50-445, 63/10/05, 6310110109
- B310310256 Forwards IE Mgt Meeting Repts 50-445/B3-37 & 50-446/B3-19 on B30908 No noncompliance noted MADSEN, C L Region 4. Office of Director 83/10/07 GARY, R J Texas Utilities Generating Ca 2pp 20947 171 24X Fiche 50-445,83/10/07,B310310256
- ---8310310264 IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908
 No noncompliance noted Major areas discussed & inspected emergency preparedness appraisal & emergency response facilities equipment BAIRD. J B . HUNNICUTT, D M Region 4, Office of Director 83/10/05 2pp 20947 173 24X Fiche 50-445,83/10/07,8310310256
- 8310270175 Forwards test results re fire rating of watertight doors, verifying acceptability of std industrial watertight doors utilized at facility as 3 h fire barriers SCHMIDT.H C Texas Utilities Services, Inc 83/10/24 YOUNDELOOD, B J Office of Nuclear Reactor Regulation, Director 4pp 20925 033 24X Fiche 50-445,83/10/24,8310270175
- 8310270185 Requests withdrawal of 831004 "Engineering Basis for Structural Integrity of Raceway Supports Associated w/I H Rated Cable Protective Envelope Sys Upon Exposure to Fire "Supports capable of withstanding I h fire SCHMIDT.H C Texas Utilities Services, Inc 83/10/24 YOUNOBLOOD,B J Licensing Branch I 1p 20924 184 24X Fiche 50-445,83/10/24.8310270185

G Adjudicatory correspondence

- B310050430 Forwards IE Insp Repts 50-445/B3-34 & 50-446/B3-18 on allegations concerning Atchison dismissal & reactor vessel outer wall Caseload Forecast Panel meeting & site visit scheduled for B30927-29 W/o encl ROTHSCHILD, M U Hearing Branch 1 83/09/26 BLOCH, P B, MCCOLLUM, K A, JORDAN, P H Atomic Sefecty and Licensing Board Panel ip 20633 319 24X Fichs 30-445,83/09/26,8310050430
- 8310050435 Forwards NUREO-1000, vol 2, "Generic Implications of ATMS Events at Salem Nuclear Pquer Plant" & SECY-83-248, "Generic Actions for Licensees & Staff in Response to ATMS Events at Salem "W/o encis ROTHSCHILD, M U Hearing Branch 1 83/09/27 BLOCH, PB, JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel, 1p 20628 362 24X Fiche 50-445,83/09/27,8310050435
- 8310030528 Advises that time for Commission to review Director's Decision DD-B3-11 expired Commission declined review Decision became final agency action on 830923 CHILK, B J Dffice of the Secretary of the Commission B3/09/29 ELLIB, J Citizens Association for Sound Energy 1p 20602-031 24X Fiche 50-445,83/09/29,8310030528
- 8310040230 Answer opposing util 830922 motions to cancel evidentiary hearings & for expedited consideration Hearing set for Wk of 831017 on NRC insp of fuel bldg must go forward & J Gagliardo of NRC must testify Certificate of 8vc encl ELLIS.J Citizens Association for Sound Energy 83/09/29. Atomic Safety and Licensing Board Panel 14pp 20613 074 24X Fiche 50-445,83/09/29,8310040230
- 8310050424 Forwards IM Rohrer 830923 memo re 830909 conversation w/
 Judge Bloch on schedule for NRC emergency preparedness
 implementation audit Audit should not be confused w/annual
 emergency preparedness exercise & will be held 830926-1007.
 ROTHSCHILD, M U Hearing Branch I 83/09/99 BLOCK-P, B,
 JORDAN, W H, MCCOLLOM, K A Atomic Safety and Licensing Board Panel
 3pp 20632 354 24% Fiche 50-445,83/09/29,8310050424
- 8310050525 Answer to util 830922 motions to cancel evidentiary hearings & for expedited consideration ASLB must determine signsignificance of matters raised in IE Insp Rept 83-23 Certificate of Byc encl ROTHECHILD, M U Hearing Branch 1 83/09/29. Atomic Safety and Licensing Board Panel. 7pp 20632 328. 24% Fichs. 50-445, 63/09/29, 8310050525
- 8310050433 Forwards ABLB proposed initial decision requesting that ACRS be informed of matters re deletion of boron injection tank M/o encl.

 TREBY, B A. Hearing Branch i 83/09/30 FRALEY, R F. ACRS Advisory Committee on Reactor Safeguards ip. 20629 040 24X Fiche 50-445,83/09/30,8310050433

- B310120414 Forwards revised list of some of Citizens Assoc for Sound Energy exhibits, matching exhibit numbers to transcript page where document accepted into evidence to transcript page where document accepted into Polymore Sound Energy 83/10/01 BLICH, P B., JORDAN, W H., MCCOLLOM, K A. Atomic Safety and Licensing Board Panel 39pp 20698 332 24% Fiche 50-445,83/10/01,8310120414
- 8310060316 Confirms B31003 oral motion for extension until B31011 to respond to ASLB 830920 memorandum on computerization of nonconformances Related correspondence REYNOLDB, N S Depending & Liberman REYNOLDB, N S Texas Utilities Ownerating Co 83/10/03 BLOCH, PB Atomic Safety and Licensing Board Panel 1p 20646 276 24X Fiche 50-445,83/10/03,8310060316
- 3310110266 Partial Initial Decision LBP-83-63 re change in mat1 properties for A500 steel Util ordered to file analyses demonstrating pipe supports mfg w/A500 steel have adequate safety margins Replies due 15 days after analyses filed BLOCH-PB , JORDAN-H H , McCOLLOM-K A Atomic Safety and Licensing Board Panel 83/10/06 Texas Utilities Generating Co 9pp 20666-131 24X Fiche 50-445.83/10/06.8310110266
- 3310110322 Motion for reconsideration of ASLB 830923 memorandum & order affirming declaration of intervenor default of contentions re emergency planning, GA/6C & Board issues Certificate of Svr encl REYNOLDS, N 8, HORIN, W A Texas Utilities Generating Co REYNOLDS, N 8 Dedevoise & Liberman 83/10/06 Atomic Safety and Licensing Board Panel 49pp 20666-002 24x Fiche 50-445,83/10/06,8310110322
- 310130031 Motion for reconsideration of 830723 memorandum & order re emergency planning, 8A & Board issues ASLB erred in retaining jurisdiction over emergency planning Record should be closed Certificate of Svc encl ROTHSCHILD, M U Hearing Branch 1 83/10/06 Atomic Safety and Licensing Board Panel 15pp 20726 259 24X Fiche 50-445,83/10/06, 8310130031
- 310130167 Memorandum cautioning parties not to place great weight on ASLB characterization of LBP-83-63 as partial initial decision, in determining appealability of LBP-83-63 as matter of right
- SHOEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel B3/10/11 4pp. 20724 293 24% Fiche 50-445,83/10/11.8310130167
- G10170412 Forwards telecopy facsimile of RG Tolson affidavit responding to ASLB questions re computerization of nonconformances Driginal forthcoming REYNOLDS.N S Debevoise & Liberman REYNOLDS.N S Texas Utilities Omerating Co BG/10/11 BLOCH.P B., JORDAN.W H , MCCGLLON.K A Atomic Sefety and Licensing Board Fanel 5pg 20784 103 24X Fiche 30-445,83/10/11.8310170412
- -8310170417 Supports NRC opposition to Citizens Assoc for Sound Energy 830729 motion to require presence of NRC Region IV Director, Div of Resident Reactor Project & Engineering Programs, J Oepilardo et 851017 hearings REYNOLDS, N S Texas Utilities Generating Co. 83/10/11 BLOCH, P B , JORDAN, H H , MCCDLLOM, K A Atomic Safety and Licensing Board Penel ip 20784 108 24X Fichs 50-445,83/10/11.8310170412
- 310170488 Answer to Citizens Assoc for Sound Energy 830929 motion to require testimony of JC Qagiiardo Testimony may not be required since exceptional circumstances not shown Certificate of Svc enci ROTHSCHILD, N.U. Hearing Branch i 83/10/11 Atomic Safety and Licensing Board Panel. 8pp. 20784:093 24X Fiche 50-445.83/10/11, 8310170488
- 310140018 Memorandum inviting parties to file briefs by 831104 on relationship to DL proceeding of Board Notification 82-105A re NBC evaluation of allegations of potential design deficiencies in Class I piping
 BLOCH.P B Atomic Safety and Licensing Board Panel 83/10/12 ip 20768-045 24X Fiche 30-445,83/10/12,8310140018
- 310140083 Memorandum re Citizena Assoc for Sound Energy 830926 request for info re potential conflict of interest of Judge McCollom Indirect interest in funds contributed by Brown & Root inconsequential BLOCH.P.B., "ORDAN.W H. Atomic Bafety and Licensing Board Panel. 83/10/12. 4pp 20767:046. 24X Fiche 50-445.83/10/12.8310140083.
- -8310140085 Advises that Halliburton Foundation grant monies do not constitute conflict of interest for author as member of ASLB. Contribution is small & author does not receive any funds for personal use from foundation MCCCLLOM.K A. Oklahoma State Univ. 83/10/03 BLOCH.P.B Atomic Safety and Licensing Board Panel. 2pp 20767 050 24X Fiche: 50-445,83/10/12,8310140083.

- 8310170577 Advises that Ofc of Investigations is conducting several ongoing investigations involving plant Ofc will provide oral presentation of investigations in camera ex parte when ASLB meets in Arlington, TX for 831017 hearings
 HAYES, B B Office of Investigation 83/10/13 BLOCH, P B Atomic Safety and Licensing Board Pancl 1p 20780 (8B 24X Fiche 50~445,83/10/13,83101705/7
- 8310180339 Requests stipulations/admissions to authenticity of documents attached as offer of proof to Citizens Assoc for Sound Energy motion to add new contention & motion for discovery ELLIS.J Citizens Association for Sound Energy 83/10/13 REYNOLDS,NS Lowenstein, Newman, Reis, Axelrad & Toll Spg 20805 019 24X fiche 50-445,83/10/13,8310180339
- --8310180342 Motion to add proposed Contention 26 re hot functional test, motion for discovery & offer of proof Cortificate of Svc encl
 ELLIS.J Citizens Association for Sound Energy 83/10/13
 Atomic Safety and Licensing Board Panel 497pp 20805 022 24X
 Fiche 50-445,83710/13,8310180339
- 83i0180188 Forwards stipulation re allegations of discouraging identification of nonconforming conditions, per ASLB request HORIN, W.A. Debevoise & Liberman HORIN, W.A. Texas Utilities Generating Co. B3/10/14 BLOCH, P.B., JORDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel ip 20809 029 24X Fiche 50-445,83/10/14.8310180158
- --8310180163 Stipulation on results of util employee interviews re allegations of discouragement of reporting nonconforming conditions TREBY.8 A Hearing Branch 1 PREIBIER.D J Texas. State of HORIN.W A Texas Utilities Generating Co 83/10/11 opp 20809 030 24% Fiche 50-445.83/10/14.8310180158
- 9310250260 Forwards unexecuted affidavits of WP Chen & J1 Tapia on openitems re Walsh/Dnyle concerns
 MIZUND, G S Hearing Branch I 83/10/14 BLOCH, F B . JDRDAN, W H .
 MCCDLLON, X A Atomic Safety and Licensing Board Panel 89pp
 20898 267 24X Fiche 50-445,83/10/14,8310250260
- 8310250295 Forwards calculations for support (CC-1-028-039-533R) & 517 checklist utilized in independent design verification of 100 pipe supports W/o encl HIZUND.GS Hoaring Branch i 83/10/14 ELLIS,J Citizens Association for Sound Energy ip 20895 342 24X Fiche 50-445,83/10/14-8310250295
- 8310250489 Forwards IE Insp Repts 50~445/83-27.50~445/83-28 & 50~446/83-14 re RL Messerley allegations of improper const practices W/o encls ROTHSCHILD, M U Hearing Branch 1 83/10/14, BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 1p 20902 070 24X Fiche 50~445,83/10/14.8310250489
- 8310210184 Forwards priginal signature page of RG Tolson 831011
 affidavit ve computerization of nonconformances
 HORIN, W.A. Debevoise & Liberman HORIN, W.A. Texas Utilities
 Generating Co. B3/10/19 STVCKY, S.W. Docketing & Services Branch
 1p. 20855 115 24X Fiche 50-445,83/10/19,8310210184
- --8310210196 Original signature page of RG Tolson of 831011 affidavit re computerization of nonconformances TOLSON.R.O Texas Utilities Cenerating Co 83/10/11 ip 20855 116 24X Fiche 50-445,83/10/19.8310210184
- 8310280059 Forwards 831022 & 0923 news articles re illegal firing of QC inspector & adequacy of emergency sirens, respectively ELLIS, J. Citizens Association for Sound Energy 83/10/24 BLOCH, P.B., JORDAN, W.H., MCCDLLOM, K.A., Akomic Safety and Licensing Board Panel. 7pp 20933 332 24X Fiche 50-445,83/10/24,8310280059
- 8310270228 Memorandum on adopted procedure re GA hearings to be conducted for finished safety sys. Cygna rept & applicant followup insp of protective coatings Citizens Assoc for Sound Energy will file allegations on GA deficiencies BLOCH P B JORDAN, W H , MCCDLLON, K A Atomic Bafety and Licensing Board Panel 83/10/25 Spp. 20924 071 24X Fiche. 50-445,83/10/25,8310270228
- 8310270293 Memorandum & order LBP-B3-69, instructing util to inspect sample of Westinghouse coatings & to submit further evidence re plug welds & further testimony or proposals responding to other adverse findings in ABLE 830923 memorandum & order BLOCH.P B. JORDAN W H , MCCOLLON,K A Atomic Bafety and Licensing Board Panel B3/10/25 Tests Utilities Generating Co 14pp. 20923 207. 24X Fiche 50-445,83/10/25,8310270293

- 8310280070 Memorandum informing that directed certification of ASLB 831004 partial initial decision may still be sought ASLAB will continue to treat order as totally interlocutory SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/10/27 Atomic Safety and Licensing Appeal Panel 3pp 20935 061 24X Fiche 30-445.83/10/27.8310280070
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 8310180179 Forwards revised pages to FSAR Amend 41. Chapter 17 1 re
 Westinghouse GA organization Revs reflect changes to
 GA program description
 GARY.R J Texas Utilities Generating Co 83/08/12 COLLINS, J T
 Region 4. Office of Director ip 20808 352 24X
 Fiche 50~445.83/08/12.8310180179
- --9310180183 Errata to FSAR Amend 41.Chapter 17 1 re Westinghouse GA organization * Texas Utilities Generating Co 83/07/11 5pp 20808 353 24X Fiche 50-445.83/08/12.8310180179
- B310140180 Amend 44 to FSAR W/B31010 ltr GARY/R J Texas Utilities Generating Co B3/10/10 DENTON.HR Dffice of Nuclear Reactor Regulation, Director 332pp 20745 095 24% Fiche 50-445,83/10/10,8310140180
- 8310200149 Forwards affidevit of svc of Amend 44 to FSAR SCHMIDT.H C Texas Utilities Bervices, Inc 83/10/11 DENTON,H R Defice of Nuclear Reactor Regulation, Director App 20836 322 24X Ficho 50-449,83/10/11.8310200149
- O Inspection reports, IE Bulletins & correspondence
- 8310040181 Forwards IE Insp Rept 50-445/83-32 on 830701-31 No noncompliance noted MADSEN, G. L. Region 4. Office of Director 83/08/24 GARY, R. J. Teyas Utilities Generating Co. 2pp. 20608 057 24X Fiche 50-445,83/08/24.8310040181
- --8310040186 IE Insp Rept 50-445/83-32 on 830701-31 No noncompliance noted Major areas inspected initial startup test procedure review. Tech Spec review, sys walkdown, plant tours & plant status
 KELLEY, D L. JONES, W B., HUNNICUTT, D N. Region 4, Office of Director 83/08/23 9pp 20608 059 24X Fiche 50-445,83/08/24,8310040101
- 8310040223 Forwards IE Insp Repts 50-445/83-24 & 50-446/83-15 on 830301-0731 MADGEN, G L Region 4, Dffice of Director 83/08/24 GARY, R J Texas Utilities Generating Co 2pp 20614 239 24X Fiche 50-445,83/08/24,8310040223
- --8310040240 IE Insp Repts 50-445/83-24 & 50-446/83-15 on 830301-0731.No noncompliance noted Insp confirmed need to issue violations re MVAC, equipment installation, document control & equipment in storage
 TAYLOR.R 0 , HUNNICUTT, D M Region 4, Office of Director 83/08/17 23pp 20614 241 24% Fichs 50-445,83/08/24,8310040223
- 8310030395 Forwards notice of violation & proposed imposition of civil penalty in amount of \$40,000 based on violation of employee protection provisions of Energy Reorganization Act of 1974
 COLLING.J T Region 4, Office of Director 83/08/27 GARY.R J Texas Utilities Generating Co. 3pp. 20593 078, 24X
 Fiche 50-445,83/08/29,9310030395
- --83100304ii Notice of violation & proposed imposition of civil penalty based on Dept of Labor 8306i0 determination that Brown & Root GA program failed to provide sufficient organizational freedom to GA inspectors
 CCLLING.J T Region 4, Office of Director 83/08/27 2pp 20573 081 24X Fiche 50-445,83/08/27,8310030375
- 8310040156 Forwards IE Insp Rept 50-445/83-29 on 830712-14 No moncompliance noted MADSEN.G L. Region 4. Office of Director 83/09/02 GARY.R J Texas Utilities Senerating Co. 3pp. 20608-218 24X Fiche 50-445,83/09/02,8310040156
- --B310040160 IE Insp Rept 50-445/83-29 on B30712-14 No noncompliance noted Major areas inspected approved guard training & qualification plan (App B to 10CFR73) Details withheld (ref 10CFR73 21)

 EVAND.C A, KELLY, J. Region 4, Office of Director B3/08/11 ip 20608.221. 24X Fiche B0-445,83/09/02,8310040186

- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24% Fiche 30-000.83/09/26,8308300340.
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse
 Type SA-1 Differential Relays " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co. of New
 York, Inc 118pp 20778 001 24X Fiche 50-000, 83/09/26,8308300345.
- 8310180466 Forwards IE Insp Rept 50-445/83-36 on 830801-31 No moncompliance noted MADSEN.G L Region 4. Office of Director 83/09/27 GARY,R J Texas Utilities Generating Co 2pp 20802 032 24X Fiche 50-445,83/09/27.8310180466
- --B310180472 IE Insp Rept 50-445/83-36 on 830B01-31 No noncompliance noted Major areas inspected initial startup test procedure review.penetration seal installation.sys walkdown.plant tours & plant status
 KELLEV.D L. JONES.W B. HUNNICUTT.D M. Region 4. Office of Director 83/09/27 7pp 20802 034 PAX Fiche 50-445.83/09/27.8310180466
- 9310050403 Responds to 830927 notice of violation & proposed imposition of civil penalty in amount of \$40,000 (EA-83-64) re slleged violation of iOCFR50,App B.Criterion I Answer protesting civil penalty encl
 GARY,R J Texas Utilities Generating Co 83/09/28 DEYOUNG,R C Director's Office of Inspection and Enforcement RApp 20873 057 24% Fiche 50-445,83/09/28.6310050403
- --B310030412 Response opposing imposition of civil penalty in amount of \$40,000 for alleged violation of IOCFR30, App B. Criterion I Requests proposed civil penalty be withdrawn or mitigated in full # Texas Utilities Generating Co B3/09/28 Commissioners 10pp 20630 130 24X Fiche 50-445,83/09/28.8310030403.
- 8308300347 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 57 Evaluation " Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp 20716 324 24X Fichs 50-000, 83/09/29, 83083000349
- 8310180214 Forwards IE Insp Rept 50-445/83-27 on 830510-0701 & 0909-22 No noncompliance noted MADSEN, G L Region 4, Office of Director 83/09/29, QARY, R, J Texas Utilities Generating Co 2pp 20808 189 24X Fiche 50-448,83/09/29,8310180214
- --83(0180219 IE Insp Rept 30-445/83-27 on 830510-0701 & 0909-22 No noncompliance noted Major areas inspected alleged improper const practices expressed by RL Messerly in affidavit dtd 830203 Allegation re improper documentation substantiated STEMART.R C., HUNNICUTT, D. N. Region 4, Office of Director 83/09/28 22pp 20808 191 24X Fiche, 50-445,83/09/29,8310180214
- --8310180223 "Comanche Peak: Alleged Improper Const Practices "
 GRIFFIN, H. B., HERR, R. K. Region 4, Office of Director 83/05/20
 3pp 20808 213, 24% Fiche 50-445, 83/09/29, 8310180214
- --8310180229 "Comanche Peak Steam Electric Station Allaged Improper Const Practices " GRIFFIN.H B , HERR.R.K Region 4, Office of Director. 1p 20808 216 24X Fiche 50-445,83/09/29.8310180214
- 8310180218 Forwards IE Insp Repts 50-445/83-28 & 50-446/83-14 on 830627-0916 No noncompliance noted. MADSEN, 9 L Region 4. Office of Director 83/10/03 9ARY, R J. Texas Utilities Generating Co 2pp 20808 270 24X Fiche 50-445,83/10/03.8310180218
- --8310180227 IE Insp Repts 50-445/83-28 % 50-446/83-14 on 830627-0916.No noncompliance noted Major areas Inspected followup on Const Appraisal Team Insp Repts 50-445/83-18 % 50-446/83-12 MARTIN.L E. HUNNICUTT, D M Region 4, Office of Director 83/09/23 35pp 20808 272 24X Fichs 50-445.83/10/03,8310180218

- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 800103) 82/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8310310256 Forwards IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908 No noncompliance noted.

 MADSEN. G L Region 4. Office of Director 83/10/07 GARY, R J. Texas Utilities Generating Co 2pp 20947 171 24X

 Fiche 50-445,83/10/07.8310310256
- --8310310264 IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908
 No noncompliance noted Major areas discussed & inspected
 emergency preparedness appraisal & emergency response
 facilities equipment
 BAIRD, J B , HUNNICUTT, D M Region 4, Office of Director
 83/10/05 2pp 20947 173 24X Fiche 50-445,83/10/07,8310310256
- 8308300757 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Piche 50-000, 83/10/11.8308300759
- 8308300761 lE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list enc!
 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129, 24X Fiche 50-000,83/10/11.8308300761
- 8310180478 Ack receipt of 830824 & 31 ltrs informing NRC of steps taken to correct violations noted in IF Insp Rept 30-445/83-23 JOHNSON, E M Region 4, Office of Director 83/10/13 GARY, R J Texas Utilities Generating Co 1p 20800-158 24X Fiche 50-445,83/10/13,8310180478
- --8310180484 Responds to NRC 830727 ltr re violations noted in IE Insp Rapt 50-445/83-23 Corrective actions five loose jam nuts on large bore ASME pipe supports reworked & verified snug tight Extension of due date until 830901 granted by NRC QARY.R J Texas Utilities Ognerating Co 83/08/24 MADSEN, 0 L Region 4, Defice of Director 2pp 20800 159 24X Fiche 50-445,83/10/13,8310180478
- --8310180468 Responds to NRC 830727 ltm me violations noted in IE Insp Rept 50-445/83-23 Corrective actions engineering evaluation concluded that plant safety would not have been affected Mode made to insp procedures. GARY.R.J Texas Utilities Generating Co 83/08/31. MADSEN, G L Region 4, Office of Director 3pp. 20800 161 24X Fichs, 50-445, 83/10/13, 8310180478
- 8 Reportable occurrences, LERs & related correspondence
- 8310130278 Final deficiency rept re pipe wall thickness of reactor coolant pressurizer surge line initially reported on 821101 Deficiency not reportable per 10CFR30 55(#) OARY,R J Texas Utilities Generating Co 82/11/23 MADSEN, G L Region 4, Office of Director ip. 20723, 197 24x Fiche 50-445,82/11/23,8310130278
- 831013026B Interis deficiency rept re temp in excess of FSAR parameters experienced in annulus between reactor vessel insulation & shield wail Conling increased by reducing chilled water temp & installing addl conling coil OARY.0. Texas Utilities Generating Co 83/09/26 MADBEN.C L Region 4. Office of Director. 28p. 20723 215 24x Fichs. 30-445.83/09/26.8310130268
- B310030516 Advises of meeting tentatively scheduled for B31013 w/util, Westinghouse & NRR to discuss Pacific Pump multi-vans diffuser linear indications.

 GARY.R.J. Taxas Utilities Generating Co 83/10/01 NADDEN, C L Region 4, Dffice of Director. Ip. 20601-200 24X Fiche: 50-445, 83/10/01, 8310030516
- 8310280003 Final deficiency meptine premature corrollon of valves in svc water sys, initially reported on 830919 Investigation complete. Item not reportable under 100FR50, 35(a). OARY,R J. Texas Utilities Generating Co. 83/10/17 JOHNSON,E Region 4. Office of Director. ip 20933:330. 24X Fiche. 30-445, 83/10/17, 8310280003.

- T Hearing transcripts on non-antitrust matters
- 8310140022 Forwards testimony of RO Tolson & GR Purdy re NRC insp of fuel bldg & design change verification REYNOLDS:N S Debevoise & Liberman REYNOLDS:N S Texas Utilities Generating Co 83/10/12 BLOCH.P B. JORDAN:W H. M. COLION,K A Atomic Safety and Licensing Board Panel 1p 2074B 064 24X Fiche 50-445.83/10/12.8310140022
- --8310140024 Testimony of RO Tolson & OR Purdy re NRC insp of fuel bldg & design change verification
 TOLSON,R G , PURDY,O R Texas Utilities Generating Co PURDY,O R
 Brown & Root Corp (subs of Halliburton Corp) 83/10/12 10pp
 20768 067 24X Fiche 50-445,83/10/12,8310140022
- 83101706B3 Testimony of TF Westerman, CR Oberg, JE Bess, CE Johnson, JI Tapia, AA Whittlesey & RC Taylor re findings of 830523-O610 special insp of fuel bidg Prof qualifications encl WESTERMAN, TF, OBERG, CR Region 4, Office of Director BESS, J E Division of Resident, Reactor Project & Engineering Programs 83/10/12 14pp 20779 232 24X Fiche 50-445,83/10/12.83101706B3
- --B3101706BB Testimony of RG Taylor re relationship between as-built certified design & vendor certified design Certificate of Svc encl
 TAYLDR.R & Region 4, Office of Director B3/10/12 10pp 20779 246 24X Fiche 50-445, B3/10/12 8330170683
- 8310210057 Transcript of 831017 hearing in Fort Worth, TX Pp 8,751-6,927 Supporting documentation enct + Commissioners 83/10/17 273pp 2085/ 276 24X Fiche 50-445,83/10/17,8310210057.
- 8310210059 Transcript of 831018 hearing in Fort Worth,TX Pp 8,428-9,075 Supporting documentation encl * Commissioners 83/10/18 78pp 20058 265 24x Fichs 50-445,83/10/18,8310210059
- 8310250103 Transcript of 831021 telcon in Bethesda, MD Pp 9.076-9,134 * Atomic Safety and Licensing Board Panel 83/10/21 60pp 20896 186 24% Fiche 50-445,83/10/21,8310250103
- U Congressional/Executive Correspondence
- 8310200062 Responds to 830913 ltr re investigation of QA/GC program at facility PALLADINO.N J Commissioners 83/10/07 UDALL, M K House of Rep , Interior & Insular Affairs 3pp 20872 280 24X Fiche 50-445,63/10/07.8310200062
- --B310200073 Requests copies of listed documents re QA/GC program problems at facility
 UDALL,M K House of Rep , Interior & Insular Affairs B3/09/13
 PALLADINO,N J Commissioners 2pp 20873 093 24X
 Fiche 50-445.83/10/07.8310200062
- DGCKET 50-444 CDMANCHE PEAK STEAM ELECTRIC STA .UNIT 2

 A Application/construction stage documents & correspondence
- 8310110007 Responds to FOIA request for SECY-82-279.SECY-82-330 & SECY-83-120 Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/15 PEDRO, J NU Corp ip 20712 280 24X Fiche 50-445.83/07/15.8310110007
- --8310110022 Recommends issuance of encl proposed order directing ASLB to resume hearings as soon as possible on issue not involving informant identities PLAINE.H H Office of the General Counsel SECY-83-120 B3/04/01 App 20712,319 24X Fiche.50-445,83/07/15,8310110007
- 8310180582 FOIA request for VS Noonan 830424 memo to BJ Youngblood re addl info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment FEDRO.J. NUS Corp. 83/08/17 Division of Rules and Records 1p 20817 327. 24X Fiche 80-445,83/08/17,8310180582
- 8310260279 Forwards nonproprietary & proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept" Proprietary version withheld (ref iOCFR2 790) RAHE.E.P Westinghouse Electric Corp 83/08/26 EIBENHUT.D Q. Division of Licensing 2pp. 20709:354 24X Fiche 50-445,83/08/26,8310260279

- --8310260281 Application for withholding proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept." per 100FR2 790 Affidavit encl
 WIESEMANN,R A Westinghouse Electric Corp 83/08/26
 EISENHUT, D & Division of Licensing 9pp 20909 358 24X
 Fiche 50-445,83/08/26,8310260279
- --8310260284 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept" * Westinghouse Electric Corp SOPR-8301 83/06/30 I40pp 20910 005 24X Fiche 50-445.83/08/26.8310R60279
- --8310260286 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Vibration Summary Rept " * Wostinghouse Electric Corp SGPR-8302 83/06/30 180pp 20910 144 24% Fiche 50-445.83/08/26.8310260277
- 8310180588 Responds to FOIA request for V5 Noonan 830426 memo re add1 info needed by Equipment Gualification Branch to complete review of environ qualification of mechanical equipment Forwards document FELTON. J M Division of Rules and Records 83/09/06 PEDRO, J NUSCOP IP 20817 330 24% Fiche 50-445,83/09/06,8310180588
- --8305060124 Forwards request for add1 info necessary to complete review of licensee 830300 info re environ qualification of safety-related mechanical equipment located in harsh environ NOCHAN, V 9 Equipment Qualification Branch 83/04/26 YOUNGBLOOD, B J Licensing Branch 1 2pp 20817 331 24X Fiche 30-445,83/09/06,8310180588
- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycls EISENHUT.D G Division of Licensing 83/09/29 PALLADING.N J Commissioners 10pp 20632 104 24X Fiche 50-000,83/09/29,8308300355
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diable Canyon I & 2.Fermi 2 & Callaway EISENHUT, D G Division of Liconsing 83/09/29 PALLADING, N J Commissioners 3pp 20632 001 24X Fiche 50-000,83/09/29,8308300357
- 8310040604 Informs that instrument accuracy study for TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," will not be available on 830930 as stated in response to Generic Ltr 83-10C SCHMIDT.H C Texas Utilities Services, Inc 83/09/30 YOUNGBLOOD,B J Licensing Branch 1 ip 20685 336 24X Fichs 30-443,83/09/30,8310040604
- B30B300763 Board Notification B3-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT.D 0 Division of Licensing B3/10/04 PALLADINO,N J Commissioners 2pp 2069B 033 24X Fiche 50-000,B3/10/04,B30B300763
- 3308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid valves EISENHUT.D @ Division of Licensing 83/10/06 PALLADING.N.J Commissioners 31pp 20818 001 24X Fiche 50-000.83/10/06. 8308300771
- #310170715 Forwards safety evaluation of FBAR Amend 3B re NUREG-0737, Item 11 F 2, "Detection of Inadequate Core Cooling " Amend Unacceptable Justification for proposed late implementation of in-core thermocouples requested YOUNGBLOOD, B J Licensing Branch # 83/10/07, GRAY, R J, Texas Utilities Generating Co 4pp 20798 #22 24X Fiche 50-445, 83/10/07,8310170715
- 3310280041 Forwards new heatup & cooldown curves for draft Tech Specs. Curves not impacted by new lOCFRSO. Apps Q & H which address metal temp of closure head flange Temp graphs encl.

 SCHMIDT.H C Texas Utilities Bervices. Inc 83/10/11 DENTON.H R Uffice of Nuclear Reactor Regulation. Director 4pp. 20933 326 24X Fiche 50-445,83/10/11.8310280041
- ISOBS10050 Doard Notification 83-140 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval smergasty diesel generators at Shoreham EISENHUT.D g Division of Licensing B3/10/14 PALLADING.N.J Commissioners 15pp 67056 070 24X Fiche 50-000.B3/10/14.B3008310050

- 8310210081 Informs that util response to TMJ Item II F 2 will be submitted by 831117 MARSHALL.J S Texas Utilities Generating Co 83/10/18 BURWELL.S D Licensing Branch 1 1p 20855 332 24X Fiche 50-445,83/10/18,8310210081
- F Security, medical, emergency & fire protection plans
- 8310050424 Forwards DM Rohrer B30923 memo re 830909 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held 830926-1007 ROTHSCHILD, M U Hearing Branck I 83/09/29 BLOCH, P B Atomic Safety and Licensing Board Panel 3pp. 20632 354 24X Fiche 50-445,83/09/29,8310050424
- 8310110173 Forwards position paper "Engineering Basis for Structural Integrity of Raceway Supports Associated W/I H Rated Cable Protective Envelope Sys Upon Exposure to Fire "
 SCHHIDT, H C Texas Utilities Services, Inc 83/10/04
 YOUNGELOUD, B J Office of Nuclear Reactor Regulation, Director 1, 20666 227 24X Fiche 50-445, 83/10/04, 8310110173
- --8310110177 "Engineering Dasis for Structural Integrity of Raceway Supports Associated W/1 H Rated Cable Protective Envelope Sys Upon Exposure to Fire "

 * Texas Utilities Services, Inc. 83/09/27 Bpp. 20656 228 24X Fichs 50-445,831010/34.8310110173
- 8310110109 Releases public version of applicant ltr forwarding revised emergency plan implementing procedures
 FELTON, J M Division of Rules and Records 83/10/05 Document Management Branch 1p 20687:318 24X Fiche 50-445.83/10/05, 8310110109
- --8310110116 Forwards public version of ravisad emergency plan implementing procedures.including Procedures EPP--101 re preparation of emergency plan procedures EPP-201 re assessment of emergency action levels W/o ancl SCHNIDT.H C Texas Utilities Services. Inc 83/08/18 COLLING.J T Region 4, Office of Director. 2pp 20687 319 24X Ficho: 50-445,83/10/05,8310110109
- 8310310256 Forwards IE Mgt Heeting Repts 50~445/83-37 & 50~446/83-19 on 830908 No noncompliance noted MADSEN.O L Region 4. Office of Director 83/10/07. GARY, R J. Texas Utilities Generating Co 2pp 20947 171 24X Fiche, 50-445, 83/10/07, 8310310254
- --8310310264 IE Mgt Meeting Repts 50-445/83-37 & 50-446/83-19 on 830908
 No noncompliance noted Major areas discussed & inspected mergency preparedness appraisal & emergency response facilities equipment BAIRD. J B Region 4. Office of Director. 83/10/05 2pp. 20947 173 24X Fiche 50-445,83/10/07,8310310256
- 8310270175 Forwards test results re fire rating of watertight doors, verifying acceptability of std industrial watertight doors utilized at facility as 3 h fire barriers SCHMIDT, H C Texas Utilities Services, Inc 83/10/24, YOUNDBLODD, B J Office of Nuclear Reactor Regulation, Director App 20925 033 24X Fiche 50-445,83/10/24,8310270175
- 8310270185 Requests withdrawal of 831004 "Engineering Basis for Structura) Integrity of Raceway Supports Associated w/I H Rated Cable Protective Envelope Sys Upon Expasure to Fire "Supports capable of withstanding 1 h fire SCHMIDT, H C Texas Utilities Bervices, Inc. 83/10/24 YOUNOBLOOD, B J Licensing Branch 1 lp. 20924:184. 24X Fiche 50-445, 83/10/24;8310270185
- G Adjudicatory correspondence
- 8310050430 Forwards IE Insp Repts 50-445/83-34 & 50-446/83-18 on allegations concerning Atchison dismissed & reactor vessel outer wall Caseload Forecast Panel meeting & site visit scheduled for 830927-27 W/o encl.
 ROTHSCHILD, M U. Hearing Brench 1, 83/09/26 BLOCH, P B. MCCOLLOM, K A. JORDAN, W H. Atomic Safety and Licensing Board Panel 1p. 20633 319, 24X Fichs 50-445,83/09/26,8310050430,
- 8310050435 Forwards NUREQ-1000, Vol 2, "Generic Implications of ATHS
 Events at Galem Nuclear Power Plant" & SECY-83-248,
 "Generic Actions for Licenses & Staff in Response to ATHS
 Events at Salem " W/o encis
 ROTHSCHILD, M U, Hearing Branch 1 83/09/27 BLOCH.P.B.,
 JORDAN M. H., MCCOLLON, K A Atomic Safety and Licensing Board Panel,
 ip 20628 362 24X Fiche 50-445,83/09/27,8310050435

- 8310030528 Advises that time for Commission to review Director's Decision DD-83-II expired Commission declined review Decision became final agency action on 830923 CHILK.8 J Office of the Secretary of the Commission 83/09/29 ELLIS, J Citizens Association for Sound Energy 1p 20402 031 24X Fiche 50-445,83/09/29.8310030328
- 8310040230 Answer opposing util 830782 motions to cancel evidentiary hearings & for expedited consideration Hearing set for wk of 831017 on NRC insp of fuel bldg must go forward & J eggliardo of NRC must testify Certificate of Svc encl ELLIS.J Citizens Association for Sound Energy 83/09/29 Atomic Safety and Licensing Board Panel 14pp 20613 074 24X Fiche 30-445,83/09/29.8310040230
- 8310050424 Forwards DM Ruhrer 830923 memb re 830907 conversation w/ Judge Bloch on schedule for NRC emergency preparedness implementation audit Audit should not be confused w/annual emergency preparedness exercise & will be held 830926-1007 ROTHSCHILD,M U Hearing Branch I 83/09/29 BLOCH,P B . JORDAN.W H, MCCOLLON.K A Atomic Safety and Licensing Board Panel 3pp 20632 354 24X Fichs 50-445,83/09/29,8310050424
- 8310050525 Answer to util 830922 motions to cancel evidentiary hearings & for expedited consideration ASLB must determine sign-significance of matters raised in IE Insp Rept 83-23 Certificate of Suc encl ROTHSCHILD, M U Hearing Branch 1 83/09/29 Atomic Bafety and Licensing Board Panel 7pp 20632 328 24X Fiche 50-445,83/09/29,8310050525
- 8310050433 Forwards ASL8 proposed initial decision requesting that ACRB be informed of matters re deletion of boron injection tank W/O encl
 TREBY,S A Hearing Branch 1 83/09/30 FRALEY,R F ACRS Advisory Committee on Reactor Esfeguards 1p 20629 040 24X
 Fiche, 50-445,83/09/30,8310050433
- B310120414 Forwards revised list of some of Citizens Assoc for Gound Energy exhibits, matching exhibit numbers to transcript page where document accepted into evidence ELLIB, J Citizens Association for Bound Energy B3/10/01.
 BLOCH, P.B., JDRDAN, W.H., MCCCLLOM, K.A. Atomic Safety and Licensing Board Panel 39pp 20498 332 24X Fiche 50-445,83/10/01.
 B310120414
- 8310060316 Confirms 831003 oral motion for extension until 831011 to respond to ASLB 830920 memorandum on computerization of nonconformances Related correspondence REYNOLDS.N S Debevoice & Liberman. REYNOLDS.N S. Texas Utilities Generating Co 83/10/03 BLOCH.P B Atomic Safety and Licensing Board Panel 1p 20446:274 24X Fiche 50-445.83/10/03.8310060314
- 8310110266 Partial Initial Decision LBP-63-63 re change in matl properties for A500 steel Util ordered to file analyses demonstrating pipe supports mfg w/A500 steel have adequate safety margins Replies due 15 days after analyses filed BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 83/10/06 Texas Utilities Generating Co. 9pp 20666 131 24X Fiche 50-445,83/10/06.8310110266
- 8310110322 Motion for reconsideration of ASLB 830923 memorandum & order affirming declaration of intervanor default of contentions re emergency planning, GA/GC & Board issues Certificate of Svc enci.
 REYNOLDB, N S . HORIN, W A Texas Utilities Generating Co REYNOLDB, N S Debevoise & Liberman. 83/10/06 Atomic Bafety and Licensing Board Panel 49pp 20666 002. 24X Fiche 50-445,83/10/06,8310110322
- 8310130031 Motion for reconsideration of 830923 memorandum & order respectly planning, GA & Board issues ASLB erred in retaining jurisdiction over emergency planning. Record should be closed Centificate of Svc enc!
 ROTHSCHILD, M. U. Hearing Branch 1 83/10/06 Atomic Safety and Licensing Board Panel 15pp 20726:259 24X Fiche 50-445.83/10/06, 8310130031
- 8310130167 Memorandum cautioning parties not to place great weight on ASLB characterization of LBP-83-63 as pertial initial decision in determining appealability of LBP-83-63 as matter of right

 SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel. 83/10/11
 4pp 20724 293 24% Fiche: 50-445.83/10/11,8310130167
- 8310170412 Forwards telecopy facsimile of RQ Tolson affidavit responding to ABLB questions re computerization of nonconformances Original farthcoming REYNOLDS N.S Debevoise & Libermen REYNOLDS, N.S Texas Utilities Generating Co 83/10/11 BLOCH.P.B., JORDAN.W H., MCCCLLCM, K.A. Atomic Bafety and Licensing Soard Panel Spp 20784-103. 24X Fiche: 50-445, 83/10/11, 8310170412

- --8310170417 Supports NRC opposition to Citizens Assoc for Sound Energy 830929 motion to require presence of NRC Region IV Director, Div of Resident Reactor Project & Engineering Programs, J Gagliardo at 831017 hearings REYNOLDS, N & Debevoise & Liberman REYNOLDS, N & Texas Utilities Generating Co 83/10/11 BLOCH, P D , JORDAN, W H , MCCOLLON, K A Atomic Safety and Licensing Board Fanel 1p 20784 108 24X Fiche 50-445,83/10/11,8310170412
- 8310170488 Answer to Citizens Assoc for Sound Energy 830929 motion to require testimony of JE Gagliardo Testimony may not be required since exceptional circumstances not shown Certificate of Syc encl ROTHSCHTLD.M U Nearing Branch 1 83/10/11 Atomic Safety and Licensing Board Panel 8pp 20784 093 24X Fiche 50-445.83/10/11, 8310170488
- 8310140018 Memorandum inviting parties to file briefs by 831104 on relationship to DL proceeding of Board Notification 82-105A re NRC evaluation of allegations of potential design deficiencies in Class I piping BLOCH.F B Atomic Safety and Licensing Board Panel 83/10/12 ip 20768 065 24X Fiche 50-445,83/10/12,8310140018
- 83i0140083 Memorandum re Citizens Assoc for Sound Energy 830926 request for info re potential conflict of interest of Judge McCollom Indirect interest in funds contributed by Brown & Root inconsequential BLOCK P B , JONDAN, W H Atomic Safety and Licensing Board Panel 83/10/12 4pp 20767 046 24X Fiche 50-445,83/10/12 83i0140083
- ---B310140085 Advases that Halliburton Foundation grant monies do not constitute conflict of interest for author as member of ASLB Contribution is small & author does not receive any funds for personal was from foundation MCCOLLONK A Diklahoma State Univ B3/10/03 BLOCH.P B Atomic Safety and Licensing Board Paipel 2pp 20767 050 24X Fiche 50-445,83/10/12,8310140083
- 83101705/7 Advises that Oft of Investigations is conducting several ongoing Investigations involving plant Oft will provide oral presentation of investigations in camera exparts when ASLD meets in Arlington, TX for 831017 hearings
 HAYEB, B B Office of Investigation 83/10/13 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 20780 188 24X
 Fiche 50-445,83/10/13-83101700/7
- 8310180339 Requests stipulations/admissions to authenticity of documents attached as offer of proof to Citizens Assoc for Sound Energy motion to add new contention & motion for discovery ELLISJ Citizens Association for Sound Energy 83/10/13 REVNOLDS N S Lowenstein Newman Reis, Axelrad & Toll 3pp 20805 019 24X Fichs 50-445,83/10/13,8310180339
- --B310180342 Motion to add proposed Contention 26 re hot functional test, motion for discovery & offer of proof Certificate of Svc encl
 ELLIS, J Citizens Association for Sound Energy B3/10/13
 Atomic Safety and Licensing Board Panel 497pp 20805 022 24X
 Fiche 50-445, B3/10/13, B3/1080339
- 8310180158 Forwards atipulation re allegations of discouraging identification of nonconforming conditions, per ASLB request HORIN, W.A. Depevoise & Liberman HORIN, W.A. Texas Utilities Generating Co. 93/10/14 BLOCH, P.B. JORDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel ip 20807 027 24X Fiche 50-445,83/10/14.8310180158
- --8310180163 Stipulation on results of util employee interviews re allegations of discouragement of reporting nonconforming conditions TREBY, S A Hearing Branch 1 PREISTER, D J Texas, State of HORIN, M A Texas Utilities Generating Co 83/10//11 App 20809 030 24% Fiche 50-445.83/10//14,8310180158
- B310250260 Forwards unexecuted affidavits of WP Chen & JI Tapis on open items re Walsh/Doyle concerns MIZUNDIG, 9 Hearing Branch 1 B3/10/14 BLOCH,F B , JURDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel 89pp 2089B 269 24X Fiche 50-445,B3/10/14,B310250260
- 8310250295 Forwards calculations for support (CC-1-028-039-533R) & SIT checklist utilized in independent design verification of 100 pipe supports M/o encl MIZUND, 0.5 Hearing Branch 1 83/10/14 ELLIS, J Citizens Association for Bound Energy 1p 20895 342 24X Fiche: 50-445, 83/10/14, 8310250295

- 8310250489 Forwards IE Insp Repts 50-445/83-27,50-445/83-28 & 50-446/83-14 re RL Messerley allegations of improper const practices W/o encls
 ROTHSCHILD,M U Hearing Branch i B3/10/14 BLOCH,P B ,
 JORDAN,W H , MCCGLOM,K A Atomic Sefety and Licensing Board Panel
 1p 20702 070 24% Fiche 50-445,83/10/14,8310250489
- 8310210184 Forwards original signature page of RG Tolson 931011 affidavit re computerization of nonconformances HORIN, W A Debevoise & Liberman HORIN, W A Texas Utilities Generating Co. 83/10/19 STUCKY, S W Docketing & Services Branch 1p 20855 115 24X Fiche 30-445,83/10/19,8310210184
- --8310210196 Original signature page of RG Tolson of 831011 affidavit re computerization of nonconformances TOLSON,R G Texas Utilities Generating Co 83/10/11 lp 20855 116 24% Fiche 50-444,83/10/19.83102k0184
- 8310280059 Forwards 831022 & 0923 news articles re illegal firing of GC inspector & adequacy of emergency sirens respectively ELLIS, J Citizens Association for Sound Energy 83/10/24 BLOCH, P B., JORDAN, W H., MCCOLLOM, K A Atomic Safety and Licensing Board Panel 7pp 20933 332 24X Fiche 50-445,83/10/24.8310280059
- 8310270228 Memorandum on adopted procedure re QA hearings to be conducted for finished safety sys.Cygna rept & applicant follows insp of protective coatings Citizens Assoc for Sound Energy will file allegations on QA deficiencies BLDCH, P.B., JORDAN, W.H., MCCGLLOM, X.A. Atomic Safety and Licensing Board Panel 83/10/25 3pp 20924 071 24X Fiche 50-445,83/10/25,831027828
- 6310270293 Memorandum & order LBP-83-69, instructing util to inspect sample of Westinghouse coatings & to submit further evidence re plug welds & further testimony or proposals responding to other adverse findings in ASLB 830923 memorandum & order BLOCH, P B . JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel B9/10/25 Texas Utilities Generating Co 14pp 20923 207 24X Fiche 50-445,83/10/25,8310270293
- 8310280070 Memorandum informing that directed certification of ASLB B31006 partial initial decision may still be sought ABLAB will continue to treat order as totally interlocutory SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel B3/10/2 Atomic Safety and Licensing Appeal Panel 3pp 20935 061 24X Fiche 50-445,83/10/27,8310280070
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310180179 Forwards revised pages to FBAR Amend 41. Chapter 17 i re Westinghouse GA organization Revs reflect changes to GA program description GARY, R. J. Texas Utilities Generating Co. 83/08/12 COLLINS, J.T. Region 4. Office of Director ip 20808-352 24X Fiche 50-445,83/08/12,8310180179
- --9310180183 Errata to FSAR Amend 41, Chapter 17 1 re Westinghouse GA organization * Texas Utilities Generating Co 83/07/11 5pp 20808 353 249 Fiche 50-445,83/08/12,8310180179
- B310140180 Amend 44 to FSAR W/B31010 ltr OARY,R J Texas Utilities Generating Co B3/10/10 DEN1ON.H R Office of Nuclear Reactor Regulation, Director 332pp 20765 095 24X Fiche 50-445,83/10/10,8310140180
- 8310200149 Forwards affidavit of svc of Amend 44 to FbAR SCHMIDT,H C Texas Utilitios Bervices, Inc 83/10/11 DENTON,H R Office of Nuclear Reactor Regulation, Director App 20836.322 24X Fiche 50-445,83/10/11,8310200149
- @ Inspection reports. IE Bulletins & correspondence
- B310040223 Forwards IE Insp Repts 50-445/83-24 & 50-446/83-15 on B30301-0/31 MADSEN.0 L Region 4, Office of Director B3/08/24, GARY.R J. Texas Utilities Generating Co 2pp 20614 239 24X Fiche 50-445,83/08/24.8310040223
- --8310040240 IE Insp Repts 50-445/83-24 & 50-446/83-15 on 830301-0731 No noncompliance noted Insp confirmed need to issue violations rs HVAG squipment installation, document control & equipment in storage
 TAYLOR,R 0 , HUNNICUTT, D M Region 4. Office of Director 83/08/19 23pp 20614,241. 24X Fiche 50-445,83/08/24.8310040223

- 8310030395 Forwards notice of violation & proposed imposition of civil penalty in amount of \$40,000 based on violation of amployee protection provisions of Energy Reorganization Act of 1974
 COLLING.J T Region 4, Office of Director 83/08/29 GARY, R J Texas Utilities Generating Co. 3pp. 20593 078 24X
 Fiche 50-445,83/08/29.8310030395
- --8310030411 Notice of violation & proposed imposition of civil penali based on Dept of Labor 830610 determination that Brown & Root GA program failed to provide sufficient organizational freedom to GA inspectors COLLINS
- B30B300340 IE info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JBRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/22 Consolidated Edison Co of New York, Inc 137pp 20754.022 24X Fiche 50-000,83/09/26,830B30034C
- 8308300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche-50-000,83/09/26,830830004E
- B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Svt list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co. of New Yark, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 83:0050403 Responds to 830827 notice of violation & proposed impositio of clvil penalty in amount of \$40,000 (EA-83-64) re alleged violation of 10CFR50.App B.Criterion I Answer protesting civil penalty encl
 GARY.R J Texas Utilities Generating Co 83/09/28 DEYGUNO.R C. Director's Office, Office of Inspection and Enforcement. 26pp 20873 057 24X Fichs 50-445,83/09/28.8310050403
- ~~8310050412 Response apposing imposition of civil penalty in amount a \$40,000 for alleged violation of 100FR50,App B.Criterion I Requests proposed civil penalty be withdrawn or mitigated in full

 * Texas Utilities Generating Co B3/09/28 Commissioners 10pp 20630 13D 24X Fiche 30-445,83/09/28,8310050403
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Evc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc 115pp. 20716 324 24X Fiche 80-000,83/09/29,8308300349
- 8310180218 Forwards IE Insp Repts 50-445/83-28 & 50-446/83-14 on 830627-0916 No noncompliance noted MADSEN, 0 L. Region 4, Office of Director, 83/10/03. GARY, R J Texas Utilities Generating Co. 2pp 20808 270 24X Fiche 50-445,83/10/03.8310180218
- --8310180227 IE Insp Repts 50-445/83-28 & 50-446/83-14 on 830627-0916, noncompliance noted Major areas inspected followup on Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 MARTIN-L.E. HUNNICUTT, D.M. Region 4, Office of Director 83/09/23 35pp 20808 272 24X Fiche 50-445,83/10/03,8310180218
- 8306300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Sypass Loops Used in Westinghouse Plants " Svc list encl.

 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Conspil
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc 79pp 20882 026 24% Fiche 50-000, 93/10/07. 83083000752
- 8310310256 Forwards IE Mgt Meeting Repts 50-445/83-37 & 80-446/83-19 of 830908 No monocompliance noted MADSEN.O. L Region 4, Office of Director 83/10/07. GARY,R J Texas Utilities Generating Co. 2pp 20947 171 24X Fichs 50-445,83/10/07,8310310256
- --83i03i0264 IE Mgt Meeting Rapts 50-445/83-37 & 50-446/83-19 on 83090 No noncompliance noted Major areas discussed & inspected; emargency preparedness appraisal & emergency response facilities equipment BAIRD, J B. HUNNICUIT, D. M. Region 4, Office of Director 83/10/05 2pp 20947 173 24X Fiche 50-445,83/10/07.8310310256

- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" "Svc list encl JURBAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
 - JORDAN. E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 P4X Fiche 50-000,83/10/11,8308300761

S Reportable occurrences. LERs & related correspondence

- 8310130278 Final deficiency rept re pipe wall thickness of reactor coolant pressurizer surge line Initially reported on 821101 Deficiency not reportable par 10CFR90 834e)
 OARY,R J Texas Utilities Generating Co. 82/11/23 MADSEN, O L Region 4, Office of Director Ip 20723 197 24%
 Fichs 50-445.82/11/23,8310130278
- 831013026B Interim deficiency rept re temp in excess of FSAR parameters experienced in annulus between reactor vessel insulation & shield wall Cooling increased by reducing chilled water temp & installing addi cooling coil OARY, 0 L. Texas Utilities Generating Co. 83/09/26 MADSEN, 0 L. Region 4, Office of Director 2pp 20723 215. 24X Fiche 50-445,83/09/26,8310130268
- 8310030514 Advises of meeting tentatively scheduled for 831013 u/util. Westinghouse & NRR to discuss Pacific Pump multi-vane diffuser linear indications GARY,R J Texas Utilities Generating Co 83/10/01 MADOEN,G L Region 4, Dffice of Director 1p 20401.200 24X Fiche 50-445.83/10/01.8310030516
- B310280003 Final deficiency rept re premature corrosion of valves in svc water sys Initially reported on B30919 Investigation complete Item not reportable under IOCFR90.55(e) OARY,R J Texas Utilities Generating Co B3/10/17 JOHNSON,F Region 4. Office of Director is 20933 330 24X Fiche.50-445.83/10/17.8310280003

T. Hearing transcripts on non-antitrust matters

- B310140022 Forwards testimony of RO Tolson & GR Purdy re NRC insp of fuel bldg & design change verification REYNOLDS.N 8 Debevoice & Liberman REYNOLDS.N 8 Texas Utilities Generating Co B3/10/12 BLOCH.P B , JORDAN.W H , MCCOLLDS.K A Atomic Bafety and Licensing Board Panel 1p 20768 066 24X Fiche 50-445.83/10/12.8310140022
- --8310140024 Testimony of RC Telson & OR Purdy re NRC insp of fuel bldg & design change verification
 TOLSDN.R G , PURDY.G R. Texas Utilities Generating Co PURDY.G R
 Brown & Root Corp (subs of Halliburton Corp.) 83/10/12 10pp
 20768 067 24X Fichs. 50-445, 83/10/12, 8310140022
- 8310170683 Testimony of TF Westerman, CR Oberg, JE Bess, CE Johnson, JI Tapia, KA Whittlesey & RO Taylor re findings of 830523-0610 special insp of fuel bldg Prof qualifications encl.
 WESTERMAN, TF. OBERG, CR Region 4. Office of Director BESS, J E Division of Resident, Reactor Project & Engineering Programs 83/10/12, 14pp 20779 232 24X Fiche 50-445, 83/10/12, 8310170683
- --8310170688 Testimony of RG Taylor re relationship between as-built centified design & vendor centified design Centificate of 8vc encl TAYLOR.R G Region 4. Office of Director 83/10/12 10gp 20779 246 24X Fiche 50-445,83/10/12.8310170680
- B310210057 Transcript of 831017 hearing in Fort Worth, TX, Pp 8,751-8,927 Supporting documentation encl.
 * Commissioners. B3/10/17, 273pp 20857, 274, 24X
 Fiche 30-445,83/10/17,8310210057.
- 8310210059 Transcript of 831018 hearing in Fort Worth, TX Pp B, 928-9,075. Supporting documentation encl * Commissioners. 83/10/18 78pp. 20858 265, 24X Fiche 50-445,83/10/18,8310210059
- 8310250103 Transcript of 831021 telcon in Bethesda, MU Pp 9,076-9,134 * Atomic Safety and Licensing Board Panel. 83/10/21 60pp 20896 186. 24X Fiche 50-445,83/10/21.8310250103.

U Congressional/Executive Correspondence

- 8310200062 Responds to B30913 ltr re investigation of QA/QC program at facility PALLADINO.N J Commissioners 83/10/07 UDALL.M K House of Rep , Interior & Insular Affairs 3pp 20072 280 24X Fiche 50-445.83/10/07.8310200062
- --8310200073 Requests copies of listed documents re QA/QC program problems at facility UDALL, M K House of Rep , Interior & Insular Affairs B3/09/17 PALLADINO, N J Commissioners 2pp 20873 093 74X Fiche 50-445,83/10/07,8310200062

DOCKET STN-50-447 GESSAR-238

- A Application/construction stage documents & correspondence
- 8310210342 Notification of 831017 meeting w/vendor & BNL in Bethesda, MD to discuss vendor response to NRC question re GESSAR-II PRA & recent seismic events analysis submittal SCALETTI, D C Standardization & Special Projects Branch 83/10/12 THOMAS, C D Standardization & Special Projects Branch 2pp 20863 143 24X Fiche 50-447, 83/10/12, 8310210342
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310260204 Forwards Amend 20 to GESBAR-II, responding to Confirmatory Issue 18 of SER, Suppl 1 to NUREO-09/9, revised responses to NRC 820825 ltr re communication & lighting sys & updating interface tables of Subsection 1 9 1
 SHERMODD, 8 G Ceneral Electric Co 83/10/04 EISENHUT, D 6
 Division of Licensing 3pp 20909 001 24X Fiche 50-447,83/10/04,8310260206
- ---83102602il Amend 20 to GESSAR-II * General Electric Co 83/10/04 205pp 20909 004 24X Fiche 50-447,83/10/04,8310260206

K Utility Final Safety Analysis Report (FSAR) & amends

- 8310260106 Forwards proprietary Rev 20 to GESSAR-II re environ qualification of safety-related equipment Rev should be withheld (ref 10C1R2 790) Affidavit encl SHERMOOD.0 G General Electric Co 83/10/04 EISENHUT.D G Division of Licensing opp 20912 09/ 24X Fiche 30-447.83/10/04.3310280106
- B310260206 Forwards Amend 20 to GEBSAR-11.responding to Confirmatory Issue 18 of SEM.Suppl 1 to NUREQ-0779, revised responses to NRC 920825 1tr re communication & lighting sys & updating interface tables of Subsection 1 9 1 SHERMODD.0 0. Guneral Electric Co 83/10/04 FISENHUT.D 0 Division of Licensing 3pp 20909 001 24X Fiche 50-447.83/10/04, 8310240206
- --8310260211 Amend 20 to GESSAR-II * General Electric Co 83/10/04 205pp 20909 004 24X Fiche 50-447,83/10/04,6310260204

DOCKET STN-50-454 BYRON STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle EISENHUT.D 0 Division of Licensing 83/09/29 PALLADIND,N J. OILINSKY.V. ROBERTS.T M Commissioners 10pp 20632 106 24X Ficher 50-000.83/09/29.8308300355
- 9309300357 Board Notification 62-105A Forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2.Fermi 2 & Callaway EISENHUT, D 0 Division of Licensing 83/09/29 PALLADIND, N J Commissioners 3pp 20632 001 24X Fiche 50-000, 83/09/29, 8308300007
- B310110605 Notification of B31013 meeting w/util in Bethesda,MD to discuss control room human factors review OLSHAN.L N Licensing Branch 1. 83/09/29 YOUNOBLOOD,B J Licensing Branch 1 3pp 20714 349 24X Fiche 50-454,83/09/29, 8310110605

- 8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants.in light of recent info concerning steam generator tube rupture procedure for Uprssele Nuclea: Power Station EISENHUT.D 9 Division of Licensing 83/10/04 PALLADING.N J Commissioners 2pp 20698 03.1 24X Fiche 50-000,83/10/04,8308300763
- 8310130049 Notification of date change from 831013 to 831026 for meeting w/util to discuss control room factors review
 DLSHAN,L N Licensing Branch 1 83/10/04 YOUNGBLOOD,B J
 Licensing Branch 1 3pp 20276 231 24X Fiche 50-454,83/10/04,
 B310130047
- 9310200273 Forwards schedules for equipment qualification test programmer for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target dates" to not as firm dates
 BARNES.P L Cemmonwealth Edison Co 83/10/05 KFPPLER.J C Regions 3. Office of Director 10pp 20830 034 24X Fiche 50-000.83/10/05.
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions re-potential problems w/ASCO solenoid EISENHUT, D.G. Division of Litensing 83/10/06 PALLABINO, N Commissioners Sipp 20818 (01 24X Fithe 50-000.83/10/06.83083007/I L. N. ONTRALIAG
- 8310240031 Notification of 831117 meeting w/util in Bethesda MD to discuss turbine maint program for turbine missile issue OLSHANIL N Liconsing Branch 1 83/10/14 YOUNGBLOOD, B J Licensing Branch 1 3pp 20903 242 24X Fiche 50-454.83/10/14.8310240031
- B310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables enr!

 LENTINE, F O Commonwealth Edison Co 03/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director Bpp 20951 024 24X Fiche 50-000, 83/10/24, 8310310060
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310120427 Requests review of Westinghouse rept. "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time Noise measurement acceptable pur terrisection 7 2 2 5 TRAMM.TR Commonwealth Edison Co. 81/09/28 DENTUN.HR Office of Nuclear Reactor Regulation. Director 1p. 20699-043 24X Fichs 50-000.81/09/28-8310120427
- F Security, medical, emergency & fire protection plans
- 8310210234 Forwards Amend 2 to fire protection rept Amend incorporates info re instrumentation, communications & suppression sys & add1 info & commutments responding to NHC concerns from fire protection audit protection agost TRAMM.TR Commonwealth Edison Co 83/ of Nuclear Reactor Regulation, Director Fiche 50-000,83/10/13,8310210234 83/J0/13 DEN]ON H R OF tor 8pp 20853 015 24X Office
- --8310210236 Amend 2 to fire protection rept.incorporating info re instrumentation, communications & suppression sys & add1 info & commitments responding to NRC concerns from fire protection audit with Commonwealth Edison Co 83/10/31. 200pp 20853 023 24X Fiche 50-000,83/10/13,8310210234
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/21 Decum Management Branch 1p 2093/216 24X Fiche 50-000,83/10/21,8310270526
- --B310270537 Public version of Rev 2 to Lmergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager" W/831017 ltr & receipt form NELLIS,C A Commonwealth Edison Co B3/02/18 DENTON,H R NRC --No Detailed Affillation Given 7pp 20937,217 24X Fiche 50-000,63/10/21,8310270526
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory.
 FELTON J M Division of Rules and Records 83/10/25 Document Management Branch ip 20943 124 24X Fiche 50-000.83/10/25, 8310280307

- --8310280314 Public version of revised generating stations emergency fluctuation Public version of revised generating stations emergency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 83/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 44pp 20963 127 24X Fiche 50-000.83/10/25.8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/26 Docum Management Branch 1p 20962 266 24X Fiche 50-000-83/10/26, 8310280191 Document
- --8310280209 Public version of Rev 1 to Laurgency Plan Implementing Procedure EOF-15. "Emergency Operations Facility Activation" MORRER D Commonwealth Edison Co 83/08/02 50pp 20942 247 24X Fiche 50 000.83/10/26.8310280191
- G Adjudicatory correspondence
- 8310040205 Partial proposed fundings of fact & conclusions of law on Contention IA Certificate of Svc encl
 WHICHER, J M League of Homen Voters of Rockford, IL WHICHER, J. M
 DeKaib Area Alliance for Responsible Energy WHICHER, J M
 Sinnissippi Alliance for the Environment (SAFE) B3/09/30, 44pp
 20614 280 24X Fiche 50-454,83/09/30,B310040205
- 8310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
 YOUNG: M A Hearing Branch 4 83/09/30 9MITH: I W . COLE.R.F., CALLIHAN: A D Atomic Safety and Licensing Board Panel. 1p 20630 001 24X Fiche 50-454.83/09/30.8310050452
- --B310050468 Proposed supplemental findings of fact & conclusions of la on GA/GC 1850es YOUNG,M A Hearing Branch 4 83/09/30 34pp 20630 002 24X Fichs 50-454.83/09/30,8310050452
- --8310050475 Proposed transcript corrections for 830810-12 hearings. Certificate of Syc encl YOUNG.M Hearing Branch 4 83/09/30 4pp 20630 036 24X Fiche 50-434.83/09/30.8310050432
- 8310060319 Forwards util addl proposed findings of fact & conclusions of law re 0A & 9C FURSE,M C Commonwealth Edison Co 83/09/30 SMITH,I W. COLE.R F. CALLIHAN.A D Atomic Safety and Licensing Board Panel 1p 20646 232 24X Fiche 50-454,83/09/30.8310060319
- --8310060321 Addl proposed findings of fact & conclusions of law re GA GC Certificate of Svc wncl MILLER.M 1. BECKER.B D. FURBE.M C Commonwealth Edison Co. 83/09/30 31pp 20646 233. 24X Fishe 50-454.83/09/30.8310060319
- 8310050440 Forwards IE Imsp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 Insp investigated allegations re Hatfield
- Electric Co YOUNO, M A Hearing Branch 4, 83/10/03 SMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel Bpp, 20633 340 24X Fiche 50-454,83/10/03,8310050440
- 8310050488 Memorandum taking official notice of publications of Illinois State Geological Survey SMITH, I W Atomic Safety and Licensing Board Panel 83/10/03 47pp 20632 116 24% Fichs 50-454,83/10/03,8310050488.
- 8310060314 Advises of revised initial fuel load date, from 831201 to 840215 Rev attributable to unanticipated addl work required to complete piping supports & mods to ventilation duct work MILLER, M I Isham, Lincoln & Beale HILLER, M I Commonwealth Edison Co 83/10/03 SMITH, J W, COLE, R F, CALLIHAN, A. D. Atom: Safety and Licensing Board Panel 1p 20641 008, 24X Fichs 50-454,83/10/03,8310060314
- 8310170346 Advises that util does not object to ABLB taking official notice of EPA rept. "Protective Action Evaluation Part II, Evacuation & Sheltering as Protective Actions Against Nuclear Actionts Involving Poseous Release "Part I encl COPELAND, V Q Isham Lincoln & Beale COPELAND, V Q Commonwealth Edison Co. 83/10/10 BMITH.I M.: COLE.R.F., CALLIHAN, A D Atomic Safety and Licensing Board Panel. 2pp 20786:030 24X Fiche 30-434,83/10/10,8310170346.
- ---B310170356 Affidavit of DD Ed, clarifying testimony re EFA rept,
 "Protective Action Evaluation Part 11.Evacuation &
 Sheltering as Protective Actions Against Nuclear Accidents
 Involving Gassous Releases." Involving Gassous Releases."

 ED.D D Commonwealth Edison Co ED.D D Illinois, State of, 83/10/10 119pp 20786.032. 24% Fiche, 50-454, 83/10/10, 8310170346

- 8310130014 Response to ASLB 830920 memorandum advising of intent to take official notice of amergency planning witness testimony NRC has no objection to notice Certificate of Svo enci YOUNG,M A Hearing Branch 4 83/10/11 Atomic Bafety and Licensing Board Panel 4pp 20/25 204 24X Fiche 50-454,83/10/11. 8310130014
- B310140067 Response to DC Thomas motion to strike proposed findings of fact & conclusions of law & to withdraw as Rockford League of Momen Voters counsel Rockford objects to motion to strike but not to withdrawal Related correspondence LEWIS.E League of Women Voters of Rockford, IL 63/10/13 Atomic Safety and Licensing Board Panel 2pp 20768 009 24X Fiche 50-454,83/10/13,8310140067
- --B310140070 Motion to strike Rockford League of Women Voters proposed findings of fact & conclusions of law & for leave to withdraw as Rockford counsel Rockford told counsel of disastisfaction w/findings Related correspondence THOMAS, D.C. League of Women Voters of Rockford, IL. THOMAS, D.C. Thomas, D.C. B3/10/13 ip 2076B 011 24X Fiche. 50-494. 83/10/13,8310140067
- B310180275 Forwards applicant reply to Joint Intervenors partial proposed findings of fact & conclusions of law on Contention IA FURSE, M C Isham, Lincoln & Beale FURSE, M C Commonwealth Edison Co B3/10/14 SMITH. I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel ip 20807 003 24X Fiche 50-454,83/10/14,8310180275
- ---B3101B0279 Reply to Joint Intervenors partial proposed findings of fact & conclusions of law on Contention iA Intervenors findings misleading & inaccurate & should not be adopted Certificate of Svc encl FURSE, M C . BECKER, B D Commonwealth Edison Co FURSE, M C Isham, Lincoln & Beale 83/10/14 2ipp 20807 004 24X Fiche 50-454, 83/10/14, 8310180275
- B310200097 Reply to util supplemental findings of fact & conclusions of law on OA/GC Certificate of Svc encl HHICHER, J M DeKalb Area Alliance for Responsible Energy HHICHER, J M Hhicher, J M HHICHER, J M Sinnissippi Alliance for the Environment (BAFE) 83/10/17 12pp 20836 04B 24X Fiche 50-454,83/10/17,8310200097
- 8310250486 Forwards reply to Joint Intervenors partial proposed findings of fact & conclusions of law re OA/AC YOUNO, M A Hearing Branch 4 83/10/17 SMITH, I W. COLE, R F. CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20902 090 24X Fiche 50-454,83/10/17,8310250486
- --8310250504 Response to Joint Intervenors 830930 partial proposed findings of fact & conclusions of law re GA/GC Findings should be rejected Certificate of Svc encl YOUNG.N A Hearing Branch 4 B3/10/17 Atomic Safety and Licensing Board Panel 12pp 20902 091 24% Fiche 50-454.83/10/17.8310250486
- 8310210204 Advises of author absence on 831109 D Cassel will be contact for intervenor group WHICHER, J M Businessmen for the Public Interest B3/10/18 BMITH, I W, COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 19 20852 102 24X Fiche 50-454,83/10/18,8310210204
- --B310210219 Motion for limited discovery against NRC & util re B40215 projected fuel load date Date critical to proceeding at present stage HHCHER.J M Dekaib Area Alliance for Responsible Energy WHICHER.J M Sinnissippi Alliance for the Environment (BAFE) WHICHER.J M Whicher, J.M 83/10/18 Atomic Bafety and Licensing Board Panel 8pp 20852 103 24% Fiche 50-454, 83/10/18,8310210204.
 - 10250513 Forwards corrected Page 2 of reply to Joint Intervenors partial proposed findings of fact & conclusions of law on GA/GC "OUNG M A Hearing Branch 4 83/10/18 SMITH, I W , COLE, R F , ALLIHAN, A D Atomic Safety and Licensing Board Fanel ip 0901 258 24X Fiche 50-494.83/10/18.8310250513

 - 9310250520 Corrected Page 2 of reply to Joint Intervenors proposed findings of Fact & conclusions of law on GA/GC.

 4 Office of the Executive Legal Director 83/10/18 ip 20901 259 24X Fiche: 50-454.83/10/18,8310250513
 - O250117 Forwards IE Insp Repts 50-454/83-38 & 50-455/83-28 ddressing Hughes allegations re welding of cable support ay & 830804 mgt meeting on reinsp program NNO,M A Hearing Branch 4 83/10/21 6HITH,I W , COLE,R F , LLIHAN,A D. Atomic Safety and Licensing Board Panel ip U897 240 24X Fiche 50-454,83/10/21,8310250117

- 8310310127 Withdrawal of previous response to own counsel motion to strike proposed findings of fact & conclusions of law Motion to strike never filed but mailed to syr list to intimidate intervenor into paying disputed fee Related correspondence LEWIS,E League of Women Yoters of Rockford, IL 83/10/27 Atomic Safety and Licensing Board Pane) 3pp 20749 107 24X Fiche 50-454,03/10/27.8310310127
- H General correspondence
- 8310030349 Package of four public comments opposing plant const & Incensing

 CAMPBELLS E . BEARLE, L. K. Sinnissippi Alliance for the Environment

 CAMPBELL B B . BEARLE, L. K. Sinnissippi Alliance for the Environment

 CAMPE) B3/09/29 SMITH. J W. Atomic Safety and Licensing Board

 Panel Bpp 20590 156 24X Fishe 50-454.83/09/29,8310030347
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310040554 Forwards affidavit certifying distribution of FSAR.Amend 43 310040554 Forwards afficient Edison Co 83/09/28 DEN/ON, H R Office of Nuclear Regulation, Director 2pp 20629 210 24x Fiche 50-000,83/09/28,8310040554
- O Inspection reports, IE Bulletins & correspondence
- B310170525 Forwards IE Insp Repts 50-454/83-38 & 50-455/83-28 nm B30803-04 & 08 No noncompliance noted KNOP.R C Region 3. Office of Director 83/09/01 RECD.C Commonwealth Edison Co 2pp 20784 192 24X Fiche 50-454,83/09/01. B310170525
- --B310170529 IE Insp Repts 50-454/83-38 & 50-455/83-28 on 830803-04 & 0B No noncompliance noted Major areas inspected followup on allegations re station electrical contractor, including exam of procedures & records, observations & interviews HAYEBJD W. KNOP,R C. Region 3, Office of Director B3/09/01 5pp 20784 194 24X Fiche 50-454,83/09/01,8310170525
- B310040424 Forwards IE Insp Repts B0-454/B3-41 & 50-455/B3-31 on B30701-0B31 No noncompliance noted KNOP.R C Region 3. Office of Director B3/09/23 REED.C Commonwealth Edison Co 2pp 20619 117 24% Fiche B0-454, B3/09/23.
- --B310040430 IE Insp Repts 50-454/B3-41 & 50-455/B3-31 on 830701-08.11 No noncompliance noted Major areas inspected preoperational testing operations & procedures. IE circular file responses & licensee actions on previously identified items CONNAUGHTON. K . HAYES. D W Region 3. Office of Director B3/09/23 5pp 20619 119 24X Fiche 50-454,83/09/23.8310040424
- 8306300340 IE Info Natice 83-61, "Alleged Use of Stand-Ins for Wolder Qualification Tests " Byo list and I JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- B30B300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas-Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post B30103) 83/09/26 Consulidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 830BJD034P
- B30B300345 IE Info Notice B3-63. "Potential Failures of Westinghouse Type SA-i Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, B3/09/26, B30D300347
- B310040237 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-484/83-33 Gencura w/util opinion that violations should be categorized as Severity Level V LITLE.W 5 Region 3. Office of Director 63/09/28 REED.C Commonwealth Edison Co 1p 20614 064 24X Fiche 30-494.03/09/28.8310040257
- --8310040260 Responds to NRC 830822 ltr re violations noted in If Insp Rept 30-494/83-33 Corrective actions snubber number corrected in rev to test procedure Violation should be categorized as Severity Level V FARRARD L Commonwealth Edison Co 83/09/26 KEPPLER, J G Region 3, Office of Director 3pp 20614 065 24X Fiche 50-454,83/09/28,8310040257

- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list
 - enci JORDAN, É L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716-324 24% Fithe 50-000,83/09/29,8308300349
- B310140179 Forwards IE Insg Rept 50-454/B3-39 on B30B0B-12.16-19 & 0907-09 No noncompliance noted LITTLE, W S Region 3. Office of Director B3/09/29 REED, C Commonwealth Edison Co 2pp 20765 030 24% Fiche 50-454, B3/09/29, 8310140179
- --B310140192 IE Insp Rept 50-454/83-37 on 830808-12.16-19 & 0907 07
 No noncompliance noted Major areas inspected licensee action on previously identified items re roinsp program for Powers-Arco-Pope & Hatfield Electric Co
 LOVE.R S., WILLIAMS, C.C. Region 3, Office of Director 83/09/28
 13pp 20765 032 24X Fiche 50-454,83/09/29,8310140179
- B310190264 Forwards IE Integrated Design Insp Rept 50-454/B3-32 on B30523-0610 & 20-30 Findings re errors, procedural violations & inconsistencies identified in rept DEVOUNG.R C Director's Office of Inspection and Enforcement B3/09/30 REED.C Commonwealth Edison Co App 20842 054 24X Fiche 50-454,83/09/30,8310190266
- --8310190270 IE Integrated Design Insp Rept 50-454/83-32 on 830523-0610 & 20-30 Major areas inspected mechanical sys & components, electrical power, instrumentation & control & civil & structural engineering ALLISON, D P Director's Office. Office of Inspection and Enforcement AILHONN, J. QA Branch 83/09/29 228pp 20842 060 24X Fiche 50-454.83/09/30,8310190266
- 8310050440 Forwards IE Insp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 Insp investigated allegations re Hatfield B30701-0831 1989 1975-25400 --- ... Electric Co YOUNG, H A Hearing Branch 4 B3/10/03 SMITH, I W: COLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel Bpp 20633 340 24X Fiche 50-454, 83/10/03, 8310050440
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/83-18,50-237/83-27, 50-249/83-25,50-264/83-27,50-269/83-26,50-275/83-19, 50-304/83-20,50-376/83-38,50-374/83-38,50-454/83-44, 50-455/83-33,50-456/83-14 & 50-457/83-13 NORELIUS,C E Division of Project & fresident Programs 83/10/04 REED.C Commonwealth Edison Co 2pp 20834 098 24% Fiche 50-000,83/10/04,8310200124
- --8310200148 IE Mgt Meeting Repts 50-020/83-18,50-237/83-27,50-249/83-25,50-254/83-27,50-245/83-26,50-295/83-19,50-304/83-20,50-373/83-38,50-374/83-38,50-454/83-44,50-495/83-33, 50-456/83-14 & 50-457/83-13 NORELIUS.C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000,83/10/04,8310700124
- 8310120302 Ack receipt of 830926 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-18 & 50-455/83-15
- 50-455/83-15
 NORELUB: C E Division of Project & Resident Programs
 REED. C Commonwealth Edison Co 1p 20699 009 24X
 Fiche: 50-454: 83/10/05: 8310120302
- --G310120401 Supple response to NRC 830576 ltr re violations noted in 1E Insp Repts 50-454/83-18 & 50-455/83-15 Corrective actions nonconformance repts reviewed to determine whether FSAR change required & whether change actually made FARRAR, D.L. Commonwealth Edison Co. 83/09/26 KEPPLER, J. 8 Region 3, Office of Director 2pp 20699 010 24% Fiche 50-454,83/10/05,8310120302
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Net York: Inc. 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc)ist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/10/07 Consolidated Edison Co. of Net York, Inc. 79pp 20882 026 24X Fiche 50~000.83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300757

- 8308300761 IE Info Notice 83~68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830:103) 83/10/11 Consolidated Edison Co of New York. Inc 120pp 20827 129 24% Fiche 50-000.83/10/11.8308300761
- 8310270128 Forwards IE Insp Repts 50-454/83-40 & 50-455/83-30 on B30811-0919 & notice of violation STREETER.J F Region 3. Office of Director 83/10/11 REED.C Commonwealth Edison Co 2pp 20924 124 24% Fiche 50-454,83/10/11,
- --8310270134 Natice of violation from insp on 830811-0919 STREETER, J.F. Region 3, Office of Director 83/10/1 20924 126 24X Fiche 50-454,83/10/11,8310270128
- --8310270140 IE Insp Repts 50-454/83-40 & 50-455/83-30 on 930811-0919 Noncompliance noted failure to follow out-of-syc procedures for valve lineup of chemical & vol control sys RINO.M. VANDENBURGH. C. REYES. L. A. Region 3. Office of Director 83/10/11 10pp 20924 128 24% Fiche 50-454.83/10/11.8310270128
- B310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design inserrept FISENHUT.D G Uzvision of Licensing B3/10/12 REED, C Commonwealth Edison Co App 20945 318 24X Fiche 50-000, 83/10/12, 8310310134
- 8310180275 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 4 months AXELSON.W L Region 3, Office of Director 83/10/14 REED.C. Commonwealth Edison Co. 2pp. 20806-354 24X Fiche.50-454,83/10/14,8310180275
- B30B300777 Board Notification B3-157 forwards B31003 & 1012 memos re GA integrated design insp NDVAK.T M Assistant Director for Licensing B3/10/17 Atomic Bafety and Licensing Board Pawel 2pp 20B30 236 24x Fichs 50-454,83/10/17,830B300777
- --8310200244 Responds to 830811 request for concurrence w/proposed ltr (
 util cancluding programs re integrated design insp
 sufficient to assure design per FSAR & recommended addl
 design GA efforts Requirements for GA efforts listed
 TAYLOR, J M Division of GA, Safeguards & Inspection Programs (Post
 B30103) 83710703 NOVAK, T M Division of Licensing 2pp
 20830 238 24X Fiche 50-454,83/10/17,83083Q0777
- --8310200248 Summarizes 830504 meeting w/util to determine if GA & design verification program sufficient to ensure design in accordance w/FBAR Response, including position re generic aspects of program requested EISENHUT.D 9 Division of Licensing 83/10/12 REED, C Commonwealth Edison Co 4pp 20830 240 24X Fiche 50-454,83/10/17,8308300777
- B Reportable occurrences, LERs & related correspondence
- 8310170411 Interim deficiency rept re Westinghouse A-200 motor control ctrs Initially reported on 830909 All affected overload blocks identified by personnel will be replaced w/properly calibr overload blocks SMARTZ, E D Commonwealth Edison Co 83/10/04 KEPPLER, J O Region 3, Office of Director 2pp 20784 017 E4X Fiche 50-000,83/10/06,83/10/70411
- 8310170573 Final deficiency rept re Anaconda flexible conduit splitting Initially reported on 830909 Caused by exceeding specified bending radius & exposure to high temps during installation Conduit Jackets covered by Okonite T-33 tape.

 SWARTZ,E D Commonwealth Edison Co 83/10/06, KEPPLER, J G Region 3, Office of Director 2pp 20780 337, 24X Fiche-50-000,83/10/06,83/10/2072 8310170573
- T Hearing transcripts on non-antitrust matters
- B310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
 YOUNG,M A Hearing Branch 4 B3/09/30 SHITH.I W, COLE,R F, CALLIHAN,A D Atomic Safety and Licensing Board Panel Ip, 20630 001 24X Fichs 50~454,83/09/30,8310050452
- --8310050475 Proposed transcript corrections for 830810-12 hearings Certificate of Svc encl YOUNG.M Hearing Branch 4 83/09/30 4pp 20630 036 24X Fiche 50-454,63/09/30.6310050452

DOCKET STN-50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents, & correspondence
- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle EISENHUT.D G Division of Licensing 83/09/29 PALLADINO.N J Commissioners 10pp 20632:104 24X Fiche 50-000.83/09/29. 8308300355
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2.Fermi 2 & Callaway EISENNUT.D Q Division of Licensing 83/09/29 PALLADINO,N J Commissioners 3pp 20632 001 24X Fiche 50-000.83/09/29, 8308300357.
- 8310110605 Notification of 831013 meeting w/util in Bethesda, MD to discuss control room buman factors review QL6HAN, L N Licensing Branch 1 83/09/29 YOUNGBLOOD, B J Licensing Branch 1 3pp 20714 349 24X Fiche 50-454,83/09/29, B310110405
- 8308300763 Board Notification 83-151 provides info re desirability of current ECCS actuation logic for Westinghouse plants in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EIBENHUT.D 9. Division of Licensing 83/10/04 PALLADINO,N J Commissioners 2pp 20698 033 24X Fiche 50-000,83/10/04, 8308300763
- 8310130049 Notification of date change from B31013 to B31026 for meeting w/util to discuss control room factors review OLBHAN, L. N. Licensing Branch 1 B3/10/04. YOUNGBLOOD, B J. Licensing Branch 1 Spp. 20776 231 24X Fiche 50-454,83/10/04,8310130049
- 8310200273 Forwards schedules for equipment qualification test programs for facilities, per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates
 8ARNES.F.L. Commonwealth Edison Co 83/10/05 KEPPLER.J & Region 3. Office of Director 10pp 20930-034 24X Fiche 50-000.83/10/05.8310200273
- 8308300771 Board Notification 83-128A forwards Equipment Gualification Branch conclusions re-potential problems w/ASCO solenoid valves. EISEMHUT,D Q. Division of Licensing 83/10/06 PALLADINO,N J Commissioners. 31pp 20818 001 24X Fichs 50-000.83/10/06, 8308300771
- 8310240031 Notification of 831117 meeting w/util in Bathesda.MD to discuss turbine maint program for turbine missile issue DLBMAN.L N Licensing Branch 1 83/10/14 YOUNGELOOD, B J Licensing Branch 1 3pp 20903 242 24X Fiche: 50-454,83/10/14,8310240031
- 8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing. Criteria tables encl.

 LENTINE, F. O. Commonwealth Edison Co. 83/10/24 DENTON, H.R. Office of Nuclear Reactor Angulation, Director Spp. 20951-024 24X Fichs. 50-000, 83/10/24, 8310310060
- E. NRC Safety Evaluation Report (BER), supply & correspondence
- 8310120427 Requests review of Westinghouse rept. "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time Noise measurement acceptable per SER, Bection 7 2 2 5 TRANH.TR. Commonweith Edison Co. 83/09/28 DENTON, HR Office of Nuclear Reactor Regulation, Director 1p 20499 043 24x Fiche: 50-000, 63/09/28, 8310120427

Security, medical, emergency & fire protection plans

10210234 Forwards Amend 2 to fire protection rept. Amend incorporates info re instrumentation.communications & suppression sys & add1 info & commitments responding to NRC concerns from fire protection audit.

TRANN.T.R. Commonwealth Edison Co 83/10/13 DENTON.H R Office of Nuclear Regulation. Director Spp 20853:015 24X Tiche. 50-000, 83/10/13, 8310210234.

- --8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit * Commonwealth Edison Co 83/10/31 200pp 20853 023 P4X Fiche 50-000, 83/10/13, 8310210234
- 8310270526 Releases public version of revised emergency plan implementing procedure FELTON, JM Division of Rules and Records 83/10/21 Document Management Branch Jp 2093/ 216 24X Fiche 50~000.83/10/21.
- --8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager" W/831017 ltr & receipt form NELLIS,C A Commonwealth Edison Co 83/02/18 DENION,H R NRC No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000, 83/10/21, 8310270526
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24X Fichs 50-000, 83/10/25, 83(0280307
- --8310280314 Public version of revised generating stations emergency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 83/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 64pp 20763 12/ 24X Fiche 50-000, 83/10/25, 8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/26 Document Management Branch 1p 20942 266 24X Fichs 50-000,83/10/26,8310280191
- --8310280207 Public version of Rev 1 to Emergency Plan Implementing Procedure ECV-15, "Emergency Operations Facility Activation" MORE, R D Commonwealth Edison Co 83/08/02 50pp 20762 267 24X Fiche 50-000,83/10/26,8310280191
- G Adjudicatory correspondence
- 8310040205 Partial proposed findings of fact & conclusions of law on Contention IA Certificate of 80c encl
 HHICHER.J M League of Homen Vaters of Rockford, IL WHICHER.J N
 DeKalb Area Alliance for Responsible Energy WHICHER.J N
 Sinnissippi Alliance for the Environment (SAFE) 83/09/30 44pp
 20614 280 24X Fiche 50-454,83/09/30,8310040205
- 8310030452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
 YOUNG, M A Hearing Branch 4 83/09/30 SMITH, IW, CGLE, R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel ip
 20630 001 24X Fiche 30-454,83/09/30,8310050452
- --831005046B Proposed Supplemental findings of fact & conclusions of law on GA/GC issues YBUNG, M A Hearing Branch 4 83/09/30, 34pp 20630 002 24X Fichs 50-454,83/09/30,8310050452
- 8310060319 Forwards util addl proposed findings of fact & conclusions of law re GA & GC FURSE,M C. Isham, Lincoln & Beale FURSE,M C. Commonwealth Edison Co. 83/09/30 SMITH,I W., COLE,R F., CALLIHAN,A D. Atomic Safrty and Licensing Board Panel 1p 20646 232 24X Fichs 50-454,83/09/30,8310060319
- --B310060324 Add1 proposed findings of fact & conclusions of law re QA & GC Certificate of Bvc encl.
 MILLER, H I , BECKER, B D , FURBE, M C. Commonwealth Edison Co.
 B3/09/30 31pp 20446 233 24X Fiche 50-454, 83/09/30, B310060319
- B310050440 Forwards IE Insp Repts 50-494/83-41 & 50-495/83-31 on 830701-0831 Insp investigated allegations re Hatfield Electric Co.
 YOUNG H A Hearing Branch 4 83/10/03 SMITH I W , COLE.R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 8pp 20633 340, 24X Fiche 50-494,83/10/03.8310050440
- B310050488 Memorandum taking official notice of publications of Illinois State Geotogical Survey. BMITH I W. Atomic Safety and Licensing Board Panel, 83/10/03 47pp 20632 116 24% Fiche 50-454,83/10/03.8310050488

- 8310060314 Advises of revised initial fuel load date, from 831201 to 840215 Rev attributable to unanticipated addl work required to complete piping supports & mods to ventilation duct work MILLER, M 1 Isham. Lincoln & Boale MILLER, M 1 Commonwealth, Edison Co 83/10/03 SMITH.1 W, COLE-R F, CALLIHAN, A D Atomic Safety and Licensing Board Panel 1p 20641 000 24X Fiche 50-454,83/10/03.8310060314
- 8310170346 Advises that util does not object to ASLB taking official notice of EPA rept, "Protective Action Evaluation Part II. Evacuation to Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Release "Part I encl COPELAND, V 0 Isham, Lincoln & Beale COPELAND, V 0 Commonwealth Edison Co B3/10/10 SMITH.I W., COLF.R F., CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 20786 030 24X Fiche 50-454,83/10/10.83101/0346
- --8310170354 Affidavit of DD Ed.clarifying testimony re EPA rept,
 "Protective Action Evaluation Part II.Evacuation &
 Sheltering as Protective Actions Against Nuclear Accidents
 Involving Gaseous Releases "
 ED.D D Commonwealth Edison Co ED.D D Illinois, State of
 83/10/10 119pp 20786 03P 24X Fiche 50-454,83/10/10,
 8310170346
- 8310130014 Response to ASLB 830920 memorandum advising of intent to take official notice of emergency planning uitness testimony NRC has no objection to notice Certificate of Svc encl
 YOUNG, M A. Hearing Branch 4 83/10/11 Atomic Safety and Licensing Board Panel 4pp 20725 204 24X Fiche 50-454,83/10/11,8310130014
- 8310140047 Response to DC Thomas motion to strike proposed findings of fact & canclusions of law & to withdraw as Rockford League of Homen Voters counsel Rockford objects to motion to strike but not to withdrawal Related correspondence

 LEMIS.E League of Women Voters of Rockford, IL 83/10/13
 Atomic Safety and Licensing Board Panel 2pp 20768 009 24%
 Fiche 50-454,83/10/13,8310140067
- --8310140070 Motion to strike Rockford League of Women Voters proposed findings of fact & conclusions of law & for leave to withdraw as Rockford counsel Rockford told counsel of dissatisfaction w/Findings Related correspondence THDMAS.D C League of Women Voters of Rockford. IL THDMAS.D C Thomas.D C 83/10/13 1p 20748 Oli 24X Fiche 50-454, 83/10/13, 8310140067
- 8310180275 Forwards applicant reply to Joint Intervenors partial proposed findings of fact & conclusions of law on Contention 1A FURSE, M C Isham, Lincoln & Beale FURSE, M C Commonwealth Edison Co 83/10/14 SMITH, J W COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel ip 20807 003 24% Fiche 50-454,83/10/14,8310180275
- ~-B3101B0279 Reply to Joint Intervenors partial proposed findings of fact & conclusions of law on Contention IA Intervenors findings misleading & inaccurate & should not be adopted Certificate of Swc encl FURSE.M C . BECKER, B D Commonwealth Edison Co. FURSE.M C Isham, Lincoln & Beale B3/10/14 21pp 20807 004 24X Fiche 50-494,83/10/14,83J0180275
- 8310200097 Reply to util supplemental findings of fact & conclusions of law on GA/GC Certificate of Svc encl
 HHICHER.J M DEKAIb Area Alliance for Responsible Energy
 WHICHER.J M WHICHER.J M Sinnissippi Alliance for the Environment (SAFE) 83/10/17 12pp, 20836 048 24X
 Fiche 50-454.83/10/17.8310200097
- D310250AB6 Forwards reply to Joint Intervenors partial proposed findings of fact & conclusions of law re GA/GC YOUNG, M A Hearing Branch 4 B3/10/17 BMITH, I W. COLE, R F. CALLIHAN, A D Atomic Safety and Licensing Board Panel, 1p 20902 090 24X Fichs 50-454,83/10/17,8310250486
- --8310230504 Response to Joint Intervenors 830930 partial proposed findings of fact & conclusions of law re QA/QC Findings should be rejected. Certificate of Svc encl YQUNQ, M A Hearing Branch 4 83/10/17 Atomic Safety and Licensing Board Panel 12pp 20902 091, 24X Fiche 50-454,83/10/17,8310250486
- 8310210204 Advises of author absence on 831109 D Cassel will be contact for intervenor group HHICHER, J M Businessmen for the Public Interest 83/10/18 SMITH. I W. COLE,R F. CALLIHAN,A D Atomic Safety and Licensing Board Panel 1p 20852 102 24X Fiche 50-454,83/10/18.8310210204

- --8310210219 Motion for limited discovery against NRC & util re 840215 projected fuel load date Date critical to proceeding at present stage WHICHER.J M Dekalb Area Alliance for Responsible Energy WHICHER.J M Sinnissippi Alliance for the Environment (SAFE) WHICHER.J M Whicher. J.M 83/10/18 Atomic Safety and Licensing Board Panel Bpp 20852 103 24X Fiche 50-454, 83/10/18 83/0/18 03/0210204
- 8310250513 Forwards corrected Page 2 of reply to Joint Intervenors partial proposed findings of fact & conclusions of law on GA/GC YOUNG, M A Hearing Branch 4 83/10/18 SMITH, I W . COLE, R F . CALLIHAN, A D Atomic Safety and Licensing Board Panel ip 20901 258 24X Fiche 50-454,83/10/18,8310250513
- 8310250117 Forwards IE Insp Repts 50-454/83-38 & 50-455/83-28 addressing Hughes allegations re welding of cable support tray & 830804 mgt meeting on reinsp program YOUNG.H A Hearing Branch 4 83/10/21 SMITH.I W. COLE.R F. CALLIHAN.A D Atomic Safety and Licensing Board Panel ip 20877 240 24X Fiche 50-454.83/10/21.8310250117
- 8310310127 Withdrawal of previous response to own counsel motion to strike proposed findings of fact & conclusions of law Motion to strike never filed but mailed to svc list to intimidate intervenor into paying disputed fee Rolated correspondence LEWIS.E League of Women Voters of Rockford, IL 83/10/27 Atomic Safety and Licensing Board Panel 3pp 20949 107 24X Fiche 50-454,83/10/27,8310310127
- H General correspondence
- B310030349 Package of four public comments opposing plant const & licensing CAMPBELL, S E , SEARLS, L K Sinnissippi Alliance for the Environment (SAFE) B3/09/29 SMITH, J W Atomic Safety and Licensing Board Panel Bpp 20590
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8310040554 Forwards affidavit certifying distribution of FSAR, Amend 43 per NRC 781020 ltr
 TRAMM.T.R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20623 210 24X
 Fichs 50-000, 83/09/28, 8310040554
- Q Inspection reports. IE Bulletins & correspondence
- B310170525 Forwards IE Insp Repts 50~454/B3-38 & 50~455/B3-28 on B30B03-04 & 08 No noncompliance noted KNOP,R C Region 3. Office of Director 83/09/01 REED,C Commonwealth Edison Co 2pp 20784 192 24X Fiche 50~454,83/09/01, B310170525
- --8310170529 IE Insp Repts 50-454/83-38 & 50-455/83-28 on 830803-04 & 08
 No noncompliance noted Major areas inspected followup on
 allegations re station electrical contractor, including exam
 of procedures & records, observations & interviews
 HAVES,D W. KNOP,R C. Region 3, Office of Director 83/09/01,
 5pp 20784 194 24X Fiche 50-454,83/09/01,8310170525,
- B310040424 Forwards IE Insp Repts 50-454/83-41 & 50-455/83-31 on 830701-0831 No noncompliance noted KNOP.R C Region 3. Office of Director 83/09/23 REED.C Commonwealth Edison Co 2pp 20419 117 24X Fiche 50-454,83/09/23,8310040424
- --B310040430 IE Insp Repts 50-454/B3-41 & 50-455/B3-31 on B30701-0B31 No noncompliance noted Major areas inspected preoperational testing operations & procedures. IE circular file responses & licenses actions on previously identified items CONNAUGHTON, K., HAYES, D. W. Region 3, Office of Director. B3/09/23 5pp 20619 119 24X Fiche 50-454, B3/09/23, B310040424
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Syc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edjson Co of New York, Inc 117pp 20754 022 24X Fiche 50-000.83/09/26.8308300040

- 830B300342 IE Info Notice 83~62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26.8308300342
- 8308300345 IE Info Notice 83~63, "Potential Failures of Westinghouse Type SA-i Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedmass & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50~005,83/09/26,8308300345
- 8308300347 IE Info Notice 83-64, "Lead Shielding Attacked to Safety-Related Bys W/o 10CFR50 57 Evaluation " Syc list encl
- Haftey-Helated Bys N. o 1951, 1957,
- 8310050440 Forwards IE Insp Repts 50~454/83-41 & 50~455/83~31 on 830701~0831 Insp investigated allegations re Hatfield Electric Co YOUNG, M A Hearing Branch 4 83/10/03 EMITH, I W Atomic Safety and Licensing Board Panel Bpp 20633 340 24% Fiche 50~454,83/10/03,8310050440
- 8310200124 Forwards IE Hgt Meeting Repts 50-010/83-18,50-237/83-27,50-247/83-25,50-254/83-27,50-245/83-26,50-295/83-19,50-304/83-20,50-373/83-38,50-354/83-34,50-455/83-33,50-456/83-14 & 50-457/83-13 NORELIUS,C E Division of Project & Resident Programs REED.C Commonwealth Edison Co 2pp 20824 098 24X Fiche.50-000,83/10/04.8310200124
- --8310200148 IE Mgt Meeting Repts 50-020/83-18,50-237/83-27,50-249/83-26,50-254/83-27,50-265/83-26,50-295/83-19,50-304/83-20,50-373/83-38,50-374/83-38,50-454/83-44,50-455/83-33,50-456/83-14 & 50-457/83-13
 NORELIUS,C. & Division of Project & Resident Programs 83/10/03 4pp 20834 100 24% Fiche 50-000,83/10/04,8310200124
- 8310120302 Ack receipt of 830924 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-18 & 50-455/83-15 NORELIUS,C E Division of Project & Resident Programs 83/10/05 REED,C Commonwealth Edison Co ip 20499 009 24X Fiche, 50-454,83/10/05,8310120302
- --B310120401 Suppls response to NRC B30525 ltr re viplations noted in)E Insp Repts 30-454/83-18 & 50-455/B3-15 Corrective actions nonconformance repts reviewed to determine whether FSAR change required & whether change actually made FARRARI DL Commonwealth Edison Co B3/09/25 KEPPLER. J G Region 3, Office of Director 2pp 20699 010 24% Fiche. 50-454, 83/10/05, 8310120302
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Hestinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24% Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " 8vc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83~67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Byc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 85/10/11 Consolidated Edison Co of New York, Inc 117pp. 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 6308300761 IE Info Notice 83-69, "Respirator User Marning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 93/10/11. Consolidated Edison Co. of New York, Inc. 120pp. 20827 127 24X Fithe 50-000, 83/10/11, 8308300761
- 831027012B Forwards IE Insp Repts 50-454/83-40 & 50-455/83-30 on B30811-0719 & notice of violation 3TREETER, J F. Region 3, Office of Director 83/10/11 REED, C commonwealth Edison Co 2pp 20724-124, 24X Fiche 50-454,83/10/11,331027012B
 - 3310270134 Notice of violation from insp on 830811-0919 STREETER, J. F. Region 3, Office of Director 83/10/11 2p 20924 126 24% Fiche 50~454.83/10/11,8310270128

- --8310270140 IE Insp Repts 50-454/83-40 & S0-455/83-30 on 8308ti-0919
 Noncompliance noted failure to follow out-of-svc procedures
 for valve lineup of chemical & vol critical sys
 RINS, M., VANDENBURGH, C., REYES, L. A. Region 3, Office of Director
 83/10/11 10pp 20924 128 24X Fishe 50-454,83/10/11.8310270120
- 8310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design insprept EIBENHUT.D C Division of Licensing 83/10/12 REED, C Commonwealth Edison Co App 20965 318 24X Fiche 50-000, 83/10/12, 8310310134
- 8310180295 Clarifies NRC position re-procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON.W L Region 3, Office of Director B3/10/14 RECD.C Commonwealth Edison Co 7pp 20806 354 24X Fiche 50-454,83/10/14,83/1080295
- S Reportable occurrences: LERs & related correspondence
- 8310170411 Interim deficiency rept re Westinghouse A-200 motor control ctrs Initially reported on 830907 All affected overload blocks identified by personnel will be replaced w/properly calibr overload blocks
 SWARTZ.E D Commonwealth Edison Co 83/10/06 KEPPLER, J & Region 3, Office of Director Rpp 20784 019 24X Fiche 50-000,83/10/06,83/107041
- 8310170573 Final deficiency rept re Anaconda flexible conduit splitting Initially reported on B30907 Caused by exceeding specified bending radius & exposure to high temps during installation Conduit jackets covered by Okonite T-33 tage SWARTZ. E.D. Commonwealth Edison Co. 83/10/06 KEPPLER. J. G. Regim 3, Office of Director Rpp. 20780-337 24X Fiche 50-000,83/10/06,83/10/170973
- T Hearing transcripts on non-antitrust matters
- B310050452 Forwards NRC proposed supplemental findings of fact & conclusions of law on GA/GC issues & list of proposed transcript corrections
 YOUNG M A Hearing Branch 4 83/09/30 SMITH W Atomic Bafety and Licensing Buard Panel 1p 20630 CO1 24X
 Fiche 30-454,83/09/30.6310050452
- --8310050475 Proposed transcript corrections for 830810-12 hearings Certificate of Syc encl YOUNG,M Hearing Branch 4 83/09/30 4pp 20630 036 24X Fiche 50-644,63/09/30,8310050452
- DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B310200273 Forwards schedules for equipment qualification test programs for facilities, per B10528 ltr Dates given for current qualification activities should be viewed as "target-dates" b not as firm dates

 BARNES.F L Commonwealth Edison Co B3/10/05 KEPPLER.J C Region 3, Office of Director 10pp 20830 034 24X Fiche 50-000,83/10/05,83/10/200273
- 8310310168 Requests info opcessary to initiate determination of aligibility per request to keeper of Natl Register of Historic Places re Area il Ka 179 identified in archeological survey repts by Illinois State Museum Soc YOUNOBLOOD, B. J. Licensing Branch 1 83/10/12 L'ARRAR, D. L. Commonwealth Edison Co. 8pp. 20765 308 24% Fiche 50-456, 83/10/12.
- 8310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaBalle & Quad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood.consisting of Chapters 7 2 & 8 0 BENNETT.C J Commonwealth Edison Co B3/10/21 CASE.E G Uffice of Nuclear Reactor Regulation, Director 1p 20894 259 24X Fiche 50-000,83/10/21.8310250293
- --8310250302 Rev 9 to Offsite Dose Calculation Manual for Braidwoot. consisting of Chapters 7 2 & 8 0 * Commonwealth Edison Co 83/08/31 56pp 20894 304 24X Fiche 50-000,83/10/21,8310250293

- 8310310040 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rad worth measurements using rod swap technique during reload physics testing Criteria tables encl
 LENTINE.F 0 Commonwealth Edison Co 83/10/24 DENTON.H N Office of Nuclear Reactor Regulation. Director 8pp 20751 024 24X Fiche 50-000.63/10/24.8310310060
- C Utility Environmental Report (ER), amends & correspondence
- 8310110302 Forwards majority of Amend 4 to environ rept OL stage, containing responses to NRC 830907 & 14 requests for add1 info Amended response to Question ER470 3 encl W/six oversize drawings Aperture cards are available in PDR MCDONOUGH, C L Commonwealth Edison Co 83/10/06 STEVENS, J A Licensing Branch i 4pp 20669 085 24X Fiche 50-456,83/10/06,8310110302
- --8310110304 Advance copy of Amend 4 to environ rept DL stage * Commonwealth Edison Co 83/10/31 47pp 20669 089 24X Fiche 30-456.83/10/06.8310110302
- B3101B0252 Forwards Amend 2 to environ rept OL stage, containing responses to B30907 & 14 requests for add1 info & info on site/environ interfaces & affluent & environ measurements/monitoring programs
 SWARTZ.F.D. Commonwealth Edison Co. B3/10/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 20B04 337 24X
 Fiche 50-456, B3/10/14, B3101B0252
- ---8310180351 Amend 4 to environ rept DL stage * Commonwealth Edison Co 83/10/31 40pp 20804 339 24X Fiche 50-456,83/10/14,8310180252
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8310120427 Requests review of Westinghouse rept. "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of Use of process noise sensor response time Noise measurement acceptable per SER. Section 7 2 2 5 TRAMM.T R Commonwealth Edison Co 83/09/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 20699 043 24X Fiche 50-000.63/09/28,8310120427
- 8310120219 Responds to unresolved issues contained in draft SEX, NUREO-1002 dtd 830715 Some items re NRC site audits unresolved SHARTZ,E D Commonwealth Edison Co 83/09/30 DENTON,H R Dffic of Nuclear Reactor Regulation, Director 44pp 20692 179 24X Fiche 50-456,83/09/30,8310120219
- F Security, medical, emergency & fire protection plans
- 8310210234 Forwards Amend 2 to fire protection rept Amend incorporates info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit
 TRAMM.TR Commonwealth Edison Co 83/10/13 DENTON,HR Office of Nuclear Reactor Regulation, Director 8pp 20853 015 24X
 Fiche 50-000.83/10/13.8310210234
- --8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit * Commonwealth Edison Co 83/10/31 200pp 20833 023 24X Fiche 50-000,83/10/13,8310210234
- 83i0270526 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records B3/10/21 Document Management Branch 1p 20937 216 24X Fiche 50-000,83/10/21, 83i0270526,
- --8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EOF-6. "Administration & Logistics Manager" W/831017 ltr & receipt form NELLIS,C A Commonwealth Edison Co 83/02/18 DENTON,H R NRC No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000,83/10/21,8310270526
- 8310280307 Releases public version of revised generating stations emergency plan telephone directory FELTON.J M Division of Rules and Records, 83/10/25 Document Management Branch ip 20963 126 24% Fiche: 50-000,83/10/25, 8310280307.

- --8310280314 Public version of revised generating stations emergency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 83/08/11. DENTON, H.R. Office of Nuclear Reactor Regulation. Director 64pp 20963 127 24X Fiche 50-000.83/10/25.8310280307
- 8310280191 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/10/24 Document Management Branch ip 20962 266 24X Fichs 50-000.83/10/26, 8310280191
- --8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EOF-15, "Emergency Operations Facility Activation" MORRE, R D Commonwealth Edison Co 83/08/02, 50sp 20962 267 24X Fiche 50~000,83/10/26,8310280191.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310040554 Forwards affidavit certifying distribution of F9AR, Amend 43 per NRC 781020 ltr TRAMM.T.R Commonwealth Edison Co 83/09/28 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 2pp 20623 210 24X Fiche 50-000,83/09/28.8310040554
- à Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co of New York, Inc 117pp 20754,022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list enc! JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York: Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342.
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fichs, 50-000, 83/09/26, 83083003045.
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys M/o 10CFR50 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,83083803349
- 8310040158 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/83-08 & 50-457/83-08 KNOP,R C Region 3, Office of Director. 83/09/29 REED,C Commonwealth Edison Co 1p 20608 039 24X Fichs 50-456,83/09/29,831000158
- ~-8310040162 Responds to NRC 830823 ltr re violations noted in 1E Insp. Repts 50-454/83-08 & 50-457/83-08 Corrective actions motor control ctr cleaned, injector pump covers tightened & mud between bottom of accumulator tanks & support skirt removed, FARRAR, D L Commonwealth Edison Co 83/09/22. KEPPLER, J 9. Region 3, Office of Director 4pp 20608 040 24X Fiche 50-456,83/09/29,8310040158
- 8310200124 Forwards IE Mgt Meeting Kapts 50-010/83-18, 50-237/83-27, 50-249/83-25, 50-254/83-27, 50-245/83-25, 50-254/83-27, 50-245/83-29, 50-304/83-28, 50-374/83-38, 50-457/83-13
 50-455/83-33, 50-456/83-14 & 50-457/83-13
 NURELIUS, C E Division of Project & Resident Programs, 83/10/04 REED. C Commonwealth Edison CO 2pp 20834 098 24X
 Fiche 50-000, 83/10/04, 8310200124
- --8310200148 IE Mgt Meeting Repts 50-020/83-18:50-237/83-27:50-249/83-50-254/83-27:50-255/83-28:50-295/83-19:50-304/83-20:50-373/83-38:50-374/83-88:50-454/83-44:50-455/83-33:50-456/83-14 & 50-457/83-13
 NORELIUB.C E. Division of Project & Resident Programs. 83/10/03
 App 20834 100 24X Fiche 50-000:83/10/04:8310200124.
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loaps Used in Wastinghouse Plants," Byo list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Cp. of Net York, Inc. 76pp. 20827 213 24X Fiche 50-000,83/10/07.8308300378.

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Syx list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-57. "Emergency Use Respirator Matl Defect Causes Production of Noticus Gases " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300757
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310310134 Requests that util response to generic implications of audits of design implementation address grogram for all plants Util position may be included in response to integrated design insprept integrated design insprept EISENHUT,D 9 Division of Licensing 83/10/12 REED.C Commonwealth Edison Co app 20945 318 24% Fiche 50-000,83/10/12,8310310134
- 8310170666 Ack receipt of 830907 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-435/83-07 & 50-457/83-07 Viplation re inadequate drawing control restated.

 NORELIUS, C E Division of Project & Resident Programs. 83/10/13 REED, C Commonwealth Edison Co 2pp 20779-307 24X Fiche 50-456, 83/10/13, 8310170866
- --8310170671 Responds to NRC 830808 ltr re violations noted in IE Insp Repts 50-456/83-07 & 50-437/83-07 Corrective actions: drawings exhibiting discrepancies reviewed & review results listed Log established to improve drawing traceability FARRAR.D L Commonwealth Edison Co 83/09/09 KEPPLER.J G. Region 3, Office of Director 12pp 20779:309. 24X Fichs 50-456.83/10/13.8310170666
- 8310180116 Forwards access lists for NRC personnel requiring access to vital areas on announced or unannounced basis Encls affective upon receipt Updates will be provided every 6 months

 AXELBON. W.L. Region 3. Office of Director 83/10/14, REED, C. Commonwealth Edison Co. 7pp. 20807 208 24X Fiche 50-456.83/10/14. 8310180116
- B310240069 Ack receipt of B30730 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-456/83-13.
 LITTLE W B Region 3. Office of Director. B3/10/19 REED, C Commonwealth Edison Co. Ip. 20881 340 24X Fiche: 90-456, B3/10/19. B310240069
 - 8310240077 Responds to NRC 830902 ltr re violations noted in IE Insp. Rept 50-454/83-13 Corrective actions Phillips, Gerschow Co. issued Field Change Order 1AF563 to correct reversed instrument sensing lines FARRAR.D.L. Commonwealth Edison Co. 83/09/30 KEPPLER, J.G. Region 3, Office of Director. 3pp. 20881, 341, 24X Fichs 50-456,83/10/19,8310240069
- 3 Reportable occurrences. LERs & related correspondence
- 8310170411 Interim deficiency rept re Hestinghouse A-200 motor control ctrs Initially reported on 830909 All affected overload blocks identified by personnel will be replaced u/properly calibr overload blocks

 BHARTZ, E D Commonwealth Edison Co B3/10/06, KEPPLER, J Q Region 3, Office of Director 2pp 20784 019 24% Fiche: 50-000,83/10/06,8310170411
- 8310170373 Final deficiency rept to Anaconda flexible conduit splitting. Initially reported on 830999 Caused by exceeding specified bending radius & exposure to high temps during installation. Conduit jackets covered by Okonite T-33 tape SMARTZ.E D. Commonwealth Edison Co 83/10/06 KEPPLER.J 0 Region 3, Office of Director 2pp 20780 337 24X Fiche: 50-000.83/10/06.8310170573.
- 8310270188 Interim Deficiency Rept 83-08 re fabrication of duct fittings w/o approved design documentation, Initially reported on 830701. Pullman Sheet Hetal submitted Rev A to duct brochure, Final approval by Sargent & Lundy pending SWARTZ.E D. Commonwealth Edison Co. 83/10/20 KEPPLER, J G Region 3, Office of Director. 2pp 20924-356. 24X Fiche-50-456.83/10/20.8310270188

- DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8310200273 Forwards schedules for equipment qualification test programs for facilities.per 810528 ltr Dates given for current qualification activities should be viewed as "target-dates" & not as firm dates

 BARNES.P L Commonwealth Edison Co 83/10/05 KEPPLER.J & Region J. Office of Director 10pp 20830 034 24X Fiche 50-000.83/10/05, 8310200273
- 8310310168 Requests info necessary to initiate determination of eligibility per request to keeper of Nutl Register of Historic Places re Area 11 Ka 179 identified in archeological survey repts by Illinois State Museum Soc YOUNOBLOOD.B J Licensing Branch 1 83/10/12 FARRAR.D L. Commonwealth Edison Co. 8pp. 20965 308 24X Fiche 50-456.83/10/12, 8310310168
- 8310250293 Forwards Rev 10 to Offsite Dose Calculation Manual for LaBalle & Guad Cities & Rev 9 to Offsite Dose Calculation Manual for Braidwood.consisting of Chapters 7 2 & 8 0 BENNETT.C J Commonwealth Edison Co 83/10/21 CASE.E G Office of Nuclear Reactor Regulation. Birector 1p 20894 259 24X Fiche 50-000.83/10/21.8310250293
- --8310250302 Rev 7 to Offsite Dose Calculation Manual for Braidwood, consisting of Chapters 7 2 & 8 0 * Commonwealth Edison Co 83/08/31 56pp 20894 304 24X Fiche 50-000,83/10/21.8310250293
- 8310310060 Submits info re Edison rod swap analysis method for review & approval Methods employed in support of control rod worth measurements using rod swap technique during reload physics testing Criteria tables encl
 LENTINE.F G Commonwealth Edison Co 83/10/24 DENION.H R Office of Nuclear Reactor Regulation, Director Bpp 20951 024 24x
 Fiche.50-000.83/10/24.8310310060
- C Utility Environmental Report (ER), amends & correspondence
- 8310110302 Forwards majority of Amend 4 to environ rept OL stage, containing responses to NRC 830907 & 14 requests for add1 info. Amended response to Question ER470 3 encl M/six oversize drawings Aperture caids are available in PDR MCDDNQUOH.C L Commonwealth Edison Co 83/10/06 STEVENS. J A Licensing Branch 1 4pp 20669 085 24X Fiche 50-456.83/10/06.831010302
- --8310110304 Advance copy of Amerid 4 to environ rept OL stage # Commonwealth Edison Co B3/10/31 47pp 20669 089 24x Fiche 50-456,83/10/06,8310110302
- 8310180252 Forwards Amend 2 to environ rept UL stage, containing responses to 830907 & 14 requests for addl info & info on site/environ interfaces & effluent & environ measurements/monitoring programs

 8WARTZ.E.D. Commonwealth Edison Co. 83/10/14 DENTON.H.R. Offic of Nuclear Reactor Regulation, Director 2pp. 20804-337 24X Fiche. 50-456.83/10/14.8310180252
- --8310180351 Amend 4 to environ rept DL stage * Commonwealth Edison Co 83/10/31 40pp 20804 339 24X Fiche 50-456,83/10/14,8310180252
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310120427 Requests review of Westinghouse rept. "Use of Process Noise Measurements to Determine Response Characteristics in US Plant" & approval of use of process noise sensor response time Noise measurement acceptable per SER. Bection 7 2 2 5 TRAMM, T R Commonwealth Edison Co 83/09/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 20699 043 24X Fiche. 50-000.83/09/28, 8310120427
- 8310120219 Responds to unresolved issues contained in draft SER, NUREG-1002 dtd 830715 Some items re NRC site audits unresolved SWARTZ,E D. Commonwealth Edison Co. 83/09/30 DENTON,H R. Office of Nuclear Reactor Regulation, Director 44pp 20692:179 24X Fiche 50-486,83/09/30.8310120219

- F Security, medical, emergency & fire protection plans
- 8310210234 Forwards Amend 2 to fire protection rept Amend incorporates info re instrumentation.communications & suppression sys & addl info & commitments responding to NRC concerns from fire Office

protection audit
TRAMM.T R Commonwealth Edison Co 83/10/13 DENTON,H R Of
of Nuclear Reactor Regulation, Director 8pp 20853 015 24X
Fiche 50-000,83/10/13.8310210234

--8310210236 Amend 2 to fire protection rept, incorporating info re instrumentation, communications & suppression sys & addl info & commitments responding to NRC concerns from fire protection audit * Commonwealth Edison Co 83/10/31 200pp 20853 023 24X Fiche 50-000,83/10/13,8310210234

8310270526 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/10/21 Docum Management Branch Ip 20937 216 24X Fiche 50-000.83/10/21. 8310270526

--8310270537 Public version of Rev 2 to Emergency Plan Implementing Procedure EDF-6, "Administration & Logistics Manager" W/831017 itr & receipt form NELLIS,C A Commonwealth Edison Co 83/02/18 DENTON,H R NRC - No Detailed Affiliation Given 7pp 20937 217 24X Fiche 50-000,83/10/21,83102/0526

- 83i0280307 Releases public version of revised generating stations emergency plan telephone directory FELTON, J M Division of Rules and Records 83/10/25 Document Management Branch 1p 20963 126 24% Fiche 50-000.83/10/25, 8310280307.

--8310280314 Public version of revised generating stations embrgency plan telephone directory GALLE, D.P. Commonwealth Edison Co. 83/08/11 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 64pp 20963 127 24X Fiche 50-000, 83/10/25, 8310280307.

8310280191 Releases public version of revised emergency plan

implementing procedure
FELTON, J M Division of Rules and Records 83/10/26 Docum
Management Branch 1p 20962 266 24% Fiche 50-000, 83/10/26. Document

--8310280209 Public version of Rev 1 to Emergency Plan Implementing Procedure EOF-15, "Emergency Operations Facility Activation" MORE,R D Commonwealth Edison Co 83/08/02 50pp 20982 267 24X Fiche 50-000,83/10/26,8310280191

- K Utility Final Bafety Analysis Report (FSAR) & amends
- B310040554 Forwards affidavit certifying distribution of FSAR, Amend 43 per NRC 781020 ltr TRAMM, T R Commonwealth Edison Co B0/09/28 DENTON, H R Office

per nno reluzo ltr TRAMM,TR Commonwealth Edison Co 83/09/28 DENTON,HR Office of Nuclear Reactor Regulation, Director 2pp 20623 210 24X Fiche 50-000,83/09/28,8310040554

- G Inspection reports: IE Bulletins & correspondence

8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Syc list encl JORDAN,E L Division of Emergency Preparadness & Enginearing Response (Post 830103) 83/07/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340

B308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fishe 50-000, 83/09/26, 8308300342.

- B30B300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list and JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) B3709786 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000, B3709726, B30B300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation" Svc list
 - encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/29 Consolidated Edison Co. of New
 York, Inc. 118pp 20716 324 24X Fiche 50-000, 83/09/29, 8308300349

- 8310040158 Ack receipt of 830922 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-455/93-08 & 50-457/83-08 XNOP:R C Region 3. Office of Director 83/09/29 REED.C Commonwealth Edison Co 1p 20608 039. 24X Fichs 50-456,83/09/29.
- --8310040162 Responds to NRC 830823 ltr re violations noted in IE Insp Repts 50-456/83-08 & 50-457/83-08 Corrective actions motor control ctr cleaned, in jector pump covers tightened & mud between bottom of accumulator tanks & support akirt removed FARRAR.D L Commonwealth Edison Co 83/09/22. KEPPLER, J G. Region 3, Office of Director 4pp 20608-040 24X Fische 50-456,83/09/29,8310040158
- 8310200124 Forwards IE Mgt Meeting Repts 50-010/B3-18,50-237/B3-27, 30-247/B3-25,50-254/B3-27,50-265/B3-26,50-275/B3-19, 50-304/B3-20,50-375/B3-3B,50-454/B3-44, 50-455/B3-33,50-456/B3-14 & 50-457/B3-13

 NORELIUS,C E Division of Project & Resident Programs REED,C Commonwealth Edison Co 2pp 20B34 09B 24X Fiche 50-000,B3/10/04,B310200124
- --8310200148 IE Mgt Heeting Repts 50-020/83-18,50-237/83-27,50-249/83-25, 50-254/83-27,50-265/83-26,50-295/83-17,50-304/83-20, 50-373/83-33,50-374/83-38,50-454/83-44,50-455/83-33, 50-454/83-14 & 50-457/83-13 NORELIUS,C E Division of Project & Resident Programs 83/10/03 4pp 20834 100 24X Fiche 50-000,83/10/04,8310200124
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Wastinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Net York, Inc 76pp. 20827-213 24X Fiche 50-000,83/10/07.8308300378
- B30B300752 IE Info Notice B3-65, "Fatality at Argentine Critical Facility." Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co. of New York, Inc. 79pp. 20882 026 24% Fiche 50-000, B3/10/07, B30B300752
- 830B300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Syc list encl JURDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11.830B300759.
- 8308300761 IE Info Notice 83-68, "Respirator User Warning.Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Conspidented Edison Co. of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310310134 Requests that util response to generic implications of audits of design implementation address program for all plants Util position may be included in response to integrated design insprept.

 EISENHUT.D 9 Division of Licensing 83/10/12, REED.C Commonwealth Edison Co App 20965:318 24% Fiche 50-000,83/10/12,8310310134
- 8310170666 Ack receipt of 830709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/83-07 & 50-457/83-07 Violation re inadequate drawing control restated. NORELIVS,CE Division of Project & Resident Programs 83/10/13 REED,C Commonwealth Edison Co Rpp 20779 307 24X Ficher50-456,83/10/13,8310170666 restated.
- --8310170671 Responds to NRC 830808 ltm re violations noted in IE Insp Repts 30-456/83-07 & 50-457/83-07 Corrective actions drawings exhibiting discrepancies reviewed & review results listed. Log established to improve drawing traceability. FARRAR, D.L. Commonwealth Edison Co. 83/07/09. KEPPLER, J. Q. Region 3, Office of Director 12pp 20779 309. 24X Fiche: 50-456,83/10/13,8310170666
- 8310180116 Forwards access lists for NRC personnel requiring access to vital areas on announced or unannounced basis Encis effective upon receipt Updates will be provided every 6 months AXELBON,W L. Region 3, Office of Director 83/10/14 REED.C Communuealth Edison Co 7pp 20807.208 24X Fiche 50-454,83/10/14, 8310180114

8 Reportable occurrences. LERs & related correspondence

- 8310170411 Interim deficiency rept re Westinghouse A-200 motor control ctrs Initially reported on 830909 All affected overload blocks identified by personnel will be replaced w/properly califor overload blocks
 SWARTZ, E D Commonwealth Edison Co 83/10/06 KEPPLER, J Q Region 3, Office of Director 2pp 20784 019 24% Fiche 50-000, 83/10/06. 83/10/0411
- 8310170573 Final deficiency rept re Anaconda flexible conduit splitting Initially reported on 830909 Caused by exceeding specified bending radius & exposure to high temps during installation Conduit jackets covered by Okonite T-33 tape SHARTZ.E D Commonwealth Edison Co 83/10/06 KEPPLER.J Q Region 3. Office of Director 2pp 20780 337 24X Fichs 50-000.83/10/06.8310170573
- 8310270188 Interim Deficiency Rept 83-08 re fabrication of duct fittings w/o approved design documentation Initially reported on 830701 Pullman Sheet Netal submitted Rev A to duct brochure Final approval by Sargent & Lundy pending SHARTZ, E D Commonwealth Edison Co 83/10/20 KEPPLER, J G Requor 3, Office of Director 2pp 20924 356 24X Fiche 50-456,83/10/20,8310270188

DOCKET 50-458 RIVER BEND STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B307260003 Forwards const GA program identifying changes to program since issuance of CP W/o encl BOOKER, J.E. Gulf States Utilities Co. B3/06/10 COLLINS, J.T. Region 4, Office of Director. Ip. 20626-082 24X Fiche 50-458,83/06/10,8307260003
- --8310040615 Const GA program for River Bend Station. * Qulf States Utilities Co. 83703/31 91pp 20626 083 24X Fiche 50-459.83706/10.8307260003
- B310280183 Appeals partial denial of FDIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit

 FALKENHEINER, D Louisiane Consumer's League, Inc. FALKENHEINER, D Falkenheiner, D.

 B3709701 Office of the Executive Director for Operations 2pp 20963 342 24X Fiche 50-458, B3709701, B310280183
- 8310070319 Responds to B10330 ltr re ultimate capacity analysis of Mark III containments Ultimate capacities of containment equipment hatch & personnel airlock determined to be 56 psi & 72 psi, respectively.
 BOOKER, J E Quif States Utilities Co 83/09/30 NOVAK, T M Assistant Director for Licensing 7pp, R0652 177 24X Fichs 50-458,83/09/30,8310070319
- 8310210221 Summarizes analysis of inclusion of redundant chlorine & ammonia detectors in Control bldg ventilation sys design NRC reconsideration of requirement requested Meeting in Bethesda, HD in Nov proposed BOOKER, J E Gulf States Utilities Cb. 83/10/17 SCHWENCER, A Licensing Branch 2 5pp 20852 084 24X Fiche 50-458,83/10/17,8310210221
- 8310250014 Forwards request for add1 info re mechanical engineering to proceed w/review of OL application
 SCHMENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Qulf
 States Utilities Co 3pp 20928 043 24% Fiche: 50-458, 83/10/18, 8310250014
- B310280189 Responds to appeal re partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit Forwards complete version of requested documents
 DIRCKS.W J Office of the Executive Director for Operations, 83/10/18, FALKENHEINER, D Falkenheiner, D 19, 20743 344. 24X Fiche. 50-458,83/10/18,8310280189.
- -8310280199 Calculations re facility components, Supporting documentation encl
 * Quif States Utilities Co 83/03/30. 11pp 20963:350, 24X
 Fichs: 50-458, 83/10/18, 8310280189
- 10360442 Notification of 831117 meeting w/util in Betheada, MD to fiscuss squipment qualification programs ethNAM-E J Licensing Branch 2 83/10/19. SCHWENCER. A Licensing Branch 2. 3pp 20926-354 24X Fiche: 50-458.83/10/19: 8310260442

- C Utility Environmental Report (ER), amends & correspondence
- 8310030232 Forwards Suppl 6 to environ rept CL stage Review questions attached to NRC 830/08 ltr renumbered Affidavit of Svc encl CAHLL.W J Gulf States Utilities Co 83/09/27 EISENHUT, D C Division of Licensing 7pp 20590 079 24X Fiche 50-458,83/09/27,8310030332
- --8310030238 Suppl 6 to environ rept 01 stage * Stone & Wobster, Inc 83/09/30 62pp 20590 086 24X Fishs 50-458.83/09/27.8310030232
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310240272 Requests estimated dates for submitting add1 info associated W/SER open & confirmatory issues Response requested within 7 days SCHWENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 2pp 20907 332 24X Fiche 50~458.83/10/18, 8310240272
- 8310270181 Revises schedule for providing responses to draft SER issue, & clarifications to FSAR Responses previously committed for 831015 will be provided between 831101 & 1231 BOOKER, J E Gulf States Utilities Co 83/10/25 9CHWENCER, A Licensing Branch 2 ip 20924 175 24X Fiche 50-458,83/10/25,8310270181
- f Security, medical, emergency & fire protection plans
- 8310130084 Notification of 831012-13 meetings w/util in 8t Francisville,LA to discuss onsite emergency preparedness topics WEINKAM.E J Licensing Branch 2 83/10/03 SHWENCER.A Licensing Branch 2 3pp 20777 022 24X Fiche 50-458,83/10/03,8310130084
- 8310240135 Notification of 831017-21 meetings w/util & BNUPPS in Fulton, MD to audit fire protection design EDISON, G E Licensing Branch 1 83/10/11 YOUNOBLODD, B J Licensing Branch 1 3pp 20884 358 24X Fiche 50-450,83/10/11,8310240135
- G Adjudicatory correspondence
- B31012039B Order rewording Contention 2 re probability of failure of old river control structure COTTER, B P, CDLE.R F, LINENNERGER, O Atomic Safety and Licensing Board Panel B3/10/07 2pp 20700 204 24% Fiche 50-458,83/10/07, 83(6120398)
- k Utility Final Safety Analysis Report (FSAR) & amends
- 8310030226 Certifies syc of Amend 10 to FSAR on 830913 Distribution list enc) LIBERTOWICZ,F Gulf States Utilities Co LIBERTOWICZ,F Stone & Webster, Inc 83/09/27 2pp 20590 147 24X Fiche 50-458, 83/09/27,8310030226
- M Antitrust correspondence
- 8310250171 Forwards NRC updated QL antitrust inquiry transmitted to util on 830816
 VOLGER, B H Hearing Branch 2 83/10/13 SPIEGEL, O Spiegel & McDlarmid 23pp 20893 282 24X Fichs 50-458.83/10/13,8310250171
- G Inspection reports: IE Bulletins & correspondence
- B310030402 Forwards IE Insp Rept 50-458/83-12 on B30603-0728 No noncompliance noted MADSEN.O L Region 4. Office of Director B3/08/17 CAHILL.W J Gulf States Utilities Co 2pp 20593 148 24X Fiche 50-458.83/08/17.8310030402
- --8310030420 IE Insp Rept 50-458/83-12 on 830603-0728 No noncompliance noted Major areas inspected followup of licenses identified const deficiencies. IE bulletins. Action I tem H07003098 & allegations, training & weld matl control BROWN, R L . CROSSMAN, W A Region 4. Defice of Director 83/08/15 12pp 20593 150 24X Fiche 50-458.83/08/17,8310030402
- B310130247 Forwards IE Insp Rept 50~45B/B3-14 on B3071B-22 No noncompliance noted MADSEN.G.L. Region 4. Office of Director B3/0B/19. CAHILL.W J Gulf States Utilities Co 2pp 20723 237 24X Fiche 50-459,83/0B/19.8310130247

- --8310130252 IE Insp Rept 50-458/83-14 on 830718-22 No noncompliance noted Major areas inspected const activities including site tour review of procedures re electrical & instrumentation cable pulling & termination.

 BESS. J E , JOHNSON.L E , HULL, R E Region 4. Office of Director 83/08/19 8pp 20723 239 24% Fiche 50-458,83/08/19.8310130247
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Enganeering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDAN. E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edjson Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8310180144 Forwards IE Insp Rept 50-458/83-i4 on 630729-0909 No noncompliance noted MADSEN. 9 L. Repion 4, Office of Director 83/09/27 CAHILL, W J Quif 8 Bates Utilities Co 2pp 20809 170 24X Fiche 50-458,63/09/27,8310180144
- --8310180149 IE Insp Rept 80-458/83-16 on 830729-0909 No noncompliance noted Major areas inspected followup of licenses identified const deficiencies & IE bulletins.preoperational test procedures review & safety-related component installation BROHN.R L , GARCIA.H L , CROSSMAN.W A Region 4, Office of Director 83/09/27 8pp 20809 172 24X Fiche 50-458.83/09/27, 8310180144
- 8308300349 1E Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300347
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Respense (Post 830103) B3/10/07 Consolidated Edison Co of Net York, Inc 76pp 20827 213 24% Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl #GRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 024 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Noxious Gases "Byo Jist and JORDAN, E.L. Division of Emergency Praparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000, 83/10/11, 8308300759
- 830B3007&1 IE Info Notice 83-48; "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24% Fiche 50-000.83/10/11.83083007&1
- 8310240017 Forwards request for add1 info re preservice/inservice insp programs to proceed w/review of DL application SCHWENCER.A Licensing Branch 2 B3/10/18 CAHILL.W J Gulf States Utilities Co 4pp 20924 359 24X Fiche 50-458,83/10/18, B310240017
- S Reportable occurrences. LERs & related correspondence
- 8310030549 Interim Deficiency Rept DR-127 Investigation incomplete Next rept will be provided by 831110 BOOKER.J E Quie States Utilities Co 83/09/19 COLLINS.J T Region 4. Office of Director. Ip. 20601 210 24X Fiche 50-458
- 8310040318 Interim Deficiency Rept DR-61 Investigation ongoing Interim or final status rept will be submitted by 831020, 80DKER, J.E. Oulf States Utilities Co. 83/09/23 COLLINS, J.T. Region 4, Office of Director. ip 20620

- 8310040126 Interim Deficiency Rept DR~129 Investigation ongoing Interim or final status rept will be provided by B31215 BOOKER, J E Gulf Btates Utilities Co B3/09/26 COLLINS, J T. Region 4, Office of Director ip 20608 004 24X Fiche 50-458/83/09/26/8310040126
- 8310040130 Interim Deficiency Rept DR-128 Investigation ongoing Interim or final rept will be submitted by 831108 BOUKER, J E Guir States Utilities Co 83/09/26 COLLINS, J T. Region 4, Office of Director in 20608 COS 24X Fiche 50-458,83/09/26,8310040130
- 8310040496 Interim Deficiency Rept DR-10B Investigation incomplete Nex rept will be provided by 831111 800KER, J E Gulf States Utilities Co 83/09/26 COLLINS, J T Region 4, Office of Director 19 20622 362 24X Fiche 50-458,83/09/26,8310040496
- 8310060074 Interim Deficiency Rept DR-125 Investigation not completed Interim or final status rept will be provided by B31107 BOOKER.J E Gulf States Utilities Co B3709/27 COLLING.J T Region 4. Office of Director. 1p 20647
- 8310130210 Interim Deficiency Rept DR-72 Investigation ongoing Interim or final rept will be provided by 831117 BDDKER.J E Gulf Btates Utilities Co 83/09/28 CDLLINS, J. T Region 4, Office of Director ip 20725 023 24X Fiche 50-450.63/09/28.6310130210.
- 8310130254 Interim Deficiency Rept DR-74 Investigation incomplete Next rept will be submitted by 831117 800KER, J E Gulf States Utilities Co 83/09/28 COLLING, J T Region 4, Office of Director. 1p 20723 233 24X Fiche 50-458,83/09/28,8310130254
- 8310130183 Interim Deficiency Rept DR-97 Investigation ongoing, Next rept will be provided by 831110 BOCKER, J E 901f Btates Utilities Co 83/09/29 COLLINS, J. T. Region 4, Office of Director. ip 20724 326, 24X Fichs 50-458
- 8310130322 Interim Deficiency Rept DR-130 Investigation incomplete. Interim or final rept expected by 831122 800KER.J E Quif States Utilities Co 83/09/29 CDLLINS, J, T Region 4, Office of Director 1p 20719 360 24X Fiche 50-458.83/09/29.8310130322
- 8310130215 Interim Deficiency Rept DR-107 Util investigation incomplete Next rept will be submitted by B31025 BDDKER, J E Guif States Utilities Co 83/09/30 CDLLINS, J, T, Region 4, Office of Director. Ip 20725 048 24X Fiche 50-458,83/09/30.8310130215
- 8310130258 Final Deficiency Rept DR-117 re previously unanalyzed containment negative pressure scenario Condition does not meet criteria for reportability under 10CFR50 55(e).
 BOOKER, J. E. Gulf States Utilities Co. 83/09/30 COLLINS, J. T. Region 4, Office of Director. Ip. 20723 224 24X
 Fiche 50-458,83/09/30,8310130258
- 8310180303 Interim Deficiency Rept DR-126 Investigation not completed Next rept will be submitted by 831114 BOOKER, J. E. Quif States Utilities Co. 83/10/03, COLLINS, J. T. Region 4, Office of Director 1p. 20806 325 24X Fiche 50-458.83/10/03.8310180303
- 8310180461 Interim Deficiency Rept DR-131 Investigation ongoing. Interigor final status rept will be provided by 831104
 BDOKER, J E Oulf States Utilities Co 83/10/03 CDLLINS, J T Region 4, Office of Director ip 20802 064 24X
 Fiche 80-458,83/10/03,8310180461.
- 8310180305 Final Deficiency Rept DR-80 re defective piston skirt castings installed in emergency diesel generator engines supplied by Transamerica Delaval, Initially reported 821124 Piston skirts replaced Also reported per Part 21, BOOKER, J E Quif States Utilities Co 83/10/06. COLLINS, J T Region 4, Office of Director 2pp 20803 076, 24X Fiche 50-458,83/10/06,8310180305
- 8310180269 Interim Deficiency Rept DR-132, Investigation incomplete. Next rept will be provided by 831128 BOOKER, J. E Gulf States Utilities Co 83/10/07. CDLUINS, J. T Region 4. Office of Director. 1p 20801 114 24X Fiche 50-458,83/10/07,8310180269
- 8310180460 Interim Deficiency Rept DR-124. Investigation engoing Interior final status rept will be provided by 831124
 BOOKER, J. E. Gulf States Utilities Co. 83/10/11 COLLINS, J. T. Region 4. Office of Director. Ip. 20802

- 8310210149 Interim Deficiency Rept DR-94 Investigation ongoing Interim or final status rept will be provided by 831123 BOOKER, J E Quif States Utilities Co 83/10/12 COLLINS, J T Region 4, Office of Director 1p 20856 097 24X Fiche 50-458,83/10/12,8310210149
- 8310210262 Interim Deficiency Rept BR-103 Investigation ongoing Interim or final rept will be provided by 831129 BODKER, J E Gulf Btates Utilities Co 83/10/13 CDLLINS, J T Region 4. Office of Director ip 20849.139 24X Fiche 50-458.83/10/13,8310210262.
- B310210175 Interim Deficiency Rept DR-134 Investigation incomplete. Next rept will be submitted by B31123 BODKER, J.E. Gulf States Utilities Co. B3/10/14 COLLINS, J T Region 4. Defice of Director ip 20856-150 24X Fiche 50-458, 83/10/14, 8310210175
- B310210201 Interim Deficiency Rept DR-435 Investigation incomplete Next rept will be submitted by B31130 BOUKER, J E Quilf Status Utilities Co B3/10/14 COLLINS, J T. Region 4, Office of Director ip. 20856 OBI 24X Fiche 50-458, B3/10/14, B310210201
- 8310210255 Part 21 rept re potential defects in molded case, 100 ampere frame, multi-pole E & HE series circuit breakers Enct suppls 830926 ltr.
 FENNETEAU, M M Gould, Inc 83/10/14 MURLEY, T. E Region 1, Office of Director 2pp 20851.047 24X Fiche; 50-458, 83/10/14, 8310210255
- B310280030 Interim Deficiency Rept DR~136 Investigation incomplete Interim or final status rept will be provided by B31207 BDDKER.J E. Oulf States Utilities Co. B3/10/17 COLLINS.J T. Region 4, Office of Director ip 2093
- 8310280084 Interim Deficiency Rept DR-112. Investigation engoing Interim or final status rapt will be provided by 831130. BOOKER, J E 9014 States Utilities Co 83/10/17 COLLINS, J T Region 4, Office of Director ip 20735 0
- 8310280117 Interim Deficiency Rept DR-78 Investigation Incomplete Next rept will be submitted by 840116.

 800KER, J. E. Quif States Utilities Co. 83/10/17 COLLINS, J T Region 4, Office of Director ip. 20929, 263 24X Fiche 50-458,83/10/17,8310280117
- 8310280011 Final Deficiency Rept DR-61 re length of capscrew which holds starting air valve assembly in cylinder head of standby diesel generators Condition not reportable under 100FR80 55(e) 300KER, J E. Oulf States Utilities Co. 83/10/18 CDLLINS, J T legion 4, Office of Director ip 20932, 278 24X Fiche 50-458, 83/10/18, 8310280011
 - 10280033 Interim Deficiency Rept DR-119 Investigation incomplete. Final or interim rept expected by 83:1111 800KER, J E. Gulf States Utilities Co. 83/10/18. COLLINS, J T Region. 4. Office of Director 1p. 20933 331 24X Fiche 50-458,83/10/18.8310280053
- #310270206 Part 21 rept re engine mounted electrical cables, Defective cable not installed as 830927 ltr states Parts shipped & installed on Guif States River Bend Site (Engine Serial 74039740 DSR 48) Instruction for cable changeout due in Nov BOYER, R. E. Transamerica Delaval, Inc. 83/10/20. Director's Office, Office of Inspection and Enforcement ip 20924:108 24X Fiche: 50-000, 83/10/20, 8310270206
 - KET 50-459 RIVER BEND STATION. UNIT 2
 - Application/construction stage documents & correspondence
 - 0280183 Appeals partial denial of FOIA request for four categories of info re Caseloaf Forecast Panel 830330-31 meeting & site visit ALKENHEINER, D. Louisiana Consumer's League, Inc. 83/09/01 lefice of the Executive Director for Operations 2pp. 20963,342,4X Fiche,50-459,83/09/01,8310280183
 - 0070319 Responds to 810330 ltr re-ultimate capacity analysis of ark III containments Ultimate capacities of containment quipment hatch & personnel airlock determined to be 56 psi 72 psi/respectively DOKER, J E Quif States Utilities Co. 83/09/30 NOVAK, T M. ssistant Director for Licensing. 7pp 20652:177. 24X iche: 50-458,83/09/30,8310070319.

- 831021022[Summarizes analysis of inclusion of redundant chloring & ammonia detectors in control bldg ventilation sys design NRC reconsideration of requirement requested Meeting in Bathesda. MD in Nov progosed BOOKER. J E Gulf States Utilities Co 83/10/17 SCHWENCER. A Licensing Branch 2 5pp 20852 084 24X Fiche 50-458.83/10/1/.8310210221
- 8310260014 Forwards request for add1 info re mechanical engineering to proceed w/review of DL application SCHHENGER.A Licensing Branch 2 83/10/18 CAHILL.W J Gulf States Utilities Ca 3pp 20928 043 24X Fiche 50-458.83/10/18, 8310260014
- 8310280189 Responds to appeal re partial denial of FOIA request for four categories of info re Caselpad Forecast Panel 830330-31 meeting & site visit Forwards complete version of requested documents
 DIRCKS, H J Office of the Executive Director for Operations
 83/10/18 FALKENHEINER,D Falkenheiner, D ip 20963 344 24%
 Fiche. 50-458, 83/10/18, 8310280189
- --8310280199 Calculations re facility components Supporting documentation encl. * Gulf States Utilities Co 83/03/30 llpp 20963 350 24% Fiche 50-458,83/10/18.8310280189
- 8310260442 Notification of 831117 meeting w/util in Bethesds.MD to discuss equipment qualification programs MEINKAM.E J Licensing Branch 2 83/10/19 SCHWENCER.A Licensing Branch 2 3pp 20926 354 24X Fiche 50~458.83/10/19.8310260442
- C Utility Environmental Report (ER), amends & correspondence
- B310030232 Forwards Suppl 6 to environ rept OL stage Review questions attached to NRC B30708 ltr renumbered Affidavit of Svc encl CAHILL, W J Gulf States Utilities Co 83/09/27 EISENHUT, D C Division of Licensing 7pp 20590 079 24X Fiche 50~458,83/09/27,8310030232
- --8310030238 Suppl 6 to environ rept Ol stage * Stone & Webster, Inc 83/09/20 62pp 20590:086 24X Fiche 50-458,83/09/27,8310030232
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8310240272 Requests estimated dates for submitting add1 info associated w/SER open & confirmatory issues Response requested within 7 days SCHMENCER, A Licensing Branch 2 83/10/18 CAHILL, W J Gulf States Utilities Co 2pp 20907 332 24X Fichs 50-458,83/10/18.83/10240272
- 8310270181 Revises schedule for providing responses to draft SER issues & clarifications to FBAR Responses previously committed for 831015 will be provided between 831101 & 1231 BOOKER, J E Gulf States Utilities Co 83/10/25 ECHWENCER, A Licensing Branch 2 lp 20924 175 24X Fiche 50-458,83/10/25,8310270181
- F Security, medical, emergency & fire protection plans
- 8310130084 Notification of 831012-13 meetings w/util in St Francisville,LA to discuss onsite emergency preparedness topics WEINXAM,E J Licensing Branch 2 83/10/03 8HWENCER,A Licensing Branch 2 3pp. 20777 022 24X Fichs 50-458,83/10/03,8310130084
- **Q** Adjudicatory correspondence
- B31012039B Order rewording Contention 2 re probability of Failure of old river control structure COTTER, B P , COLE, R F , LINENBERGER, G Atomic Safety and Licensing Board Panel 83/10/07 2pp 20700 204 24X Fiche 50-45B, B3/10/07, B310120398
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8310030226 Certifies syc of Amend iO to FSAR on B30913 Distribution list enci LIBERTOWICZ,F. Gulf States Utilities Co LIBERTOWICZ,F Stone & Webster, Inc 83/09/27 2pp 20590-147 24X Fiche. 50-45B, 83/09/27, 8310030226

M Antitrust correspondence

- B310250171 Forwards NRC updated OL antitrust inquiry transmitted to util on B30B16
 VOLGER.B H Hearing Branch 2 B3/10/13 SPIEGEL.G Spiegel & McDiarmid 23pp 20893 282 24X Fiche 50-458.83/10/13.B310250171
- G Inspection reports, IE Bulletans & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Hilder Qualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co
- B30B300342 IE Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Bvz list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 830B300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co of New York, Inc 118pp 20778 CO1 24X Fiche 30-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324, 24X Fiche 50-000.83/09/29.8308300349
- B308300378 IE Info Notice 83~65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- B308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 OR6 24X Fiche 50-000,83/10/07,8308300752
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York Inc 117pp 21043:075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129, 24X Fichs 50-000,83/10/11,8308300761
- 8310260017 Forwards request for addl info re preservice/inservice insp programs to proceed w/review of OL application SCHWENCER.A Licensing Branch 2 83/10/18 CAHILL.W J Oulf States Utilities Co App. 20926 359 24X Fiche 50-458.83/10/18, 8310260017
- S Reportable occurrences, LERs & related correspondence
- 8310270206 Part 21 rept re angine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf Btates River Bend Site (Engine Berial 74039/40 DBR 48) Instruction for cable changeout dwg in Nov BUYER, R E Transamerica Delaval, Inc. 83/10/20 Director's Office, Office of Inspection and Enforcement, ip 20924:108 24X Fiche 50-000,83/10/20,83/10270206
- DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8310030303 Forwards Rev 1 to BAM-1762. "Auxiliary Feedwater Bys Reliability Study for WPPSS Unit 1," in response to NUREG-0737. Item II, E 1 1 BORENSEN, G C Hashington Public Power Supply System 83/09/23 ADENSAM.E Q, Licensing Branch 4 ip 20593,191 24X Ficher 50-460,83/09/23,8310030303.

- --8310030306 Rev 1 to "Auxiliary Feedwater Bys Reliability Study of WPPSS Unit 1"

 * Babcock & Hilcox Co BAH-1762 R01 83/06/30 41pp 20593 183 24X Fiche 50-460,83/09/23,8310030303
- 8310210224 Forwards "Rept on Containment Structural Integrity Test for WPPSS Unit 1 " Containment responded satisfactorily to test pressure loads & acceptance criteria of ABME III, Div 2. SORENSEN, G C Washington Public Power Bupply System 83/09/28 ADENSAM, E Q Licensing Branch 4 1p 20847 084 24X Fiche 50-440,83/09/28,8310210224
- --8310210225 "Rept on Containment Structural Integrity Test for WPP88 Unit 1" W/seven oversize figures Aperture Cards are available in PDR W United Engineers & Constructors, Inc (subs of Raytheon Co) 83/06/03 482pp 20847 085 24X Fiche 50-460,63/09/28,8310210224
- B310310469 Bummary of B30826 meeting w/B&W Owners Group re implementation of Generic Ltr 83-28 concerning defenses against ATMB & proposed ATMS rule for B&W plants. List of attendees & visugraphs encl KADAMBI.F Operating Reactors Branch 4 83/10/20. Operating Reactors Branch 4 13pp 20965 147 24X Fichs 50-000,83/10/20, B310310489
- F Security, medical, emergency & fire protection plans
- B309300239 Forwards Amend 4 to "Fire Protection Evaluation,"
 Vols 1 & 2, in response to 820105 request & 10CFR50.App R.
 SCRENGEN, 0 C Washington Public Power Supply System 83/09/22
 ADENSAM, E Q Licensing Branch 4 ip. 20544 199, 24X
 Fichs 50-460, 83/09/22,8309300239
- --8309300244 "Fire Protection Evaluation," Vols 1 & 2 W/oversized drawings Aperture cards available in PDR # Washington Public Power Supply System 83/09/22 650pp 20344,200 24X Fiche 50-460,83/09/22.8309300239
- Q Adjudicatory correspondence
- 8310040200 Updated response to 830812 second set of interrogatories & request to produce Certificate of 8vc encl ROSOLIE.E Coalition for 8afe Power 83/09/27 Washington Public Power Supply System 5pp 20615:028 24X Fiche 50-440, 83/09/27, 8310040200
- B310040175 Memorandum & order granting util 830706 motion to strike Coalition for Bafe Power 830822 motion to compel util responses to Coalition 830713 third set of interrugatories. Coalition alternate request to suspend hearing denied GROSBAN.H Atomic Bafety and Licensing Board Panel 83/09/30. Washington Public Power Supply System 4pp 20608 076 24% Fithe 50-460,83/09/30.8310040175.
- 8310180320 Memorandum & Order LBP-83-66, admitting Coalition for Safe Power as intervenor-ruling on contentions & holding proceeding in abeyance Util ordered to file quarterly repts on const activities GROSSHMAN, H. Atomic Safety and Licensing Board Panel 63/10/14. Coalition for Safe Power 40pp 20806, 188 24X Fiche 50-460, 83/10/14,8310180320
- 8310200240 Memorandum & order denying util 830712 motion to compel Coalition for Safe Power to produce documents referenced in response to util interrogatories Requests denied as moot or for other reasons as noted GROBSMAN.H Atomic Safety and Licensing Board Panel 83/10/18 Washington Public Power Supply System 5pp. 20833 059, 24X Fiche. 50-460, 83/10/18.8310200240.
- 8310210203 Order scheduling 831027 telephone conference re 840110 hearing. OROSSMAN.H. Atomic Bafety and Licensing Board Panel 83/10/19. 2pp 20855:113 24X Fiche 50-460.83/10/19.8310210203.
- 8310310226 Memorandum & order confirming 831027 telcon w/all parties to ensure resolution of discovery matters & adherence to previously adopted schedule.

 OROBSMAN, M. Atomic Safety and Licensing Board Panel. 83/10/28

 Zpp 20947-125 24X Fiche 50-460,83/10/28,8310310226
- G. Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN: E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26. Consolidated Edison Co. of New York: Inc 117pp 20754:022 24X Fiche 50-000:83/09/26:8308300340

- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Inteles " Syr list encl
 - Intakes " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24x Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Convolidated Edison Co of New York, Inc 188pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 1E Info Notice 83-64. "Lead Shielding Attached to Safety-Related Bys W/o 10CFRSO. 59 Evaluation " Svc list encl
 - untl JURDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/29 Consolidated Edison Co of New York, Inc. 113pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8371077 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Factlity" Svc list encl. JORDAN EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882,026 24X Fiche 50-000,83/10/07,8308300752
- B30B300759 IE Info Notice B3-67. "Emergency Use Respirator Mat1 Defect Causes Production of Noxious Gases." Svc list enci JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075. 24X Fiche 50-000,83/10/11,8308300759
- B30B300761 IE Info Natice B3-68, "Respirator User Warning Defective Belf-Contained Breathing Apparatus Air Cylinders " Svc list anci.

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consulidated Edison Co of New York Inc 120pp 20827 129 24X Fiche 50-000, 83/10/11, 830B300761.

S Reportable occurrences, LERs & related correspondence

8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Berial 74039/40 DSR 48) Instruction for cable changeout due in Nov SQYER.R E Transamerica Delayal, Inc 83/10/20 Director's Defice, Office of Inspection and Enforcement 1p 20924 108 24X Fiche. 50-000, 83/10/20, 8310270206

V. Operator Examinations

- 8310030142 Requests schedule, by 831028, for requelification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs.

 8198MP, T W. Division of Resident, Reactor Project & Engineering Programs 83/09/26. GODFFREY. G Washington Public Power Supply Bystem 2pp 20590 040 24% Fiche 50-397, 83/09/26, 8310030142
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8310120181 Informs that final corrective action item re recovery verification team assessment of QA program & implementation as applied to mechanical equipment, piping, pipe supports/ restraints & HVAC complete on 830718, per 820421 ltr. HALL, DP Illinois Power Co. 83708/04 KEPPLER, J @ Region 3, Office of Director ip 20495-275 24X Ficha 30-461.83/08/04, 8310120181
- B310050085 Advises of conditional acceptance of use of ASME Code Case N-315, "Repair of Bellows Section III, Div 1," to repair 10 guard pips expansion bellows Description & justification of repair not replacement, must be submitted BCHMENGER, A Licensing Branch 2 B3/09/27 NELBON, R M Illinois Power Go 2pp 20450 189 24X Fiche 50-441, 83/09/27, 8310050085.
- 8310210009 Informs that HPCS diesel generator preoperational testing frogrem complying w/Reg Guides 1.108 & 1 9 & IEEE Btd 387-1977 will be implemented Progrem description provided. NELSON, R.M. Illimote Power Co. 85/10/14 86HHENCER: A Licensing Branch 2. 2pp. 20856.069. 24X Ficher 50-461.83/10/14,8310210009.

- B310260346 Summary of Caseload Forecast Panel B30B10-12 meetings w/utj) in Clinton.IL re const status of factlity Viewgraphs encl ABELSON,H Licensing Branch 2 83/10/17 Licensing Branch 2 164pp 20948 084 24X Fiche 30-461
- B310240254 Submits daily highlights Unit 2 canceled on B31014 Const on Unit 1 continuing & not affected by cancellation MARRISON, 0 Licensing Branch 2 B3/10/18 DENTON, H R , CASE, E 0 , CARTER, J Defice of Nuclear Reactor Regulation, Director ip 20907 277 24X Fiche 50-461,83/10/18,8310240294
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8309120437 Provides proposed responses to questions re SER (NURAG-0853)
 Confirmatory Issue 1 concerning degraded core hydrogen
 control & emergency plan dose assessment reporting sys
 NELGON: R M Illinois Pawer Co 83/09/06 SCHWENCER, A Licensing
 Branch 2 App 20335 248 24X Fiche 50-461,83/09/06,8309120437
- B310120359 Advises that util has incorporated three LRG-II position papers into DL application Position Paper 3-CSB, "Periodic Low Pressure Leakage Testing of Drywell," constituting response to Cunfirmatory Issue 66 of SER (NURED-OBB3) NELSON, R M Illinois Power Co 83/09/30 SCHWENCER, A Licensing Branch 2 3pp 20700 206 24X Fiche 50-461, B3/09/30.8310120359
- 8310140228 Forwards draft FSAR page changes on SER Confirmatory Issues 45 & 46 re TMI Action Plan Items II K 3 13. "HPCI & RCIC Initiation Levels" & II K 3 15. "Isolation of HPCI & RCIC " Engineering design completed NELSON, R M Illinois Power Co 83/10/06 SCHWENCER, A Licensing Branch 2 11pp 20761 253 24X Fiche 50-461,83/10/06,8310140228
- B310270552 Releases public version of revised emergency plan FELTON, J M Division of Rules and Records B3/10/21 Document Management Branch Ip 20944 017 24X Fiche 50-461,83/10/21, B310270592
- --8310270569 Forwards public version of draft Amend 28 to FSAR, App 13 li, consisting of Rev 2 to Emergency Plan OAP1890 008 Rev should resolve SER Outstanding Issue 18 (NUREG-0893) NELSON, R M. Illinois Power Co 83/10/14 86HHENCER, A Licensing Branch 2 ip 20944 018 24X Fiche 50-461,83/10/21,8310270552
- F Security, medical, emergency & fire protection plans
- 8309120437 frovides proposed responses to questions re SER (NUREG-0053)
 Confirmatory Issue 1 concerning degraded core hydrogen
 control & emergency plan dose assessment reporting sys
 NELSONR M, Illingis Power Co 83/09/06 SCHMENCER, A Licensing
 Branch 2 App 20335 248 24X Fiche 50-461.83/09/06.8309120437
- 8310200201 Forwards Amend 27 to FBAR, consisting of safety reliaf valve monitoring description, Chapter 14 updating & responses to NRC questions on emergency preparedness meteorological program

 HALL-D P. Illinois Power Co 83/10/11, DENTON, H R Office of Nuclear Regulation, Director ip 20828 292 24X

 Fiche 50-441,83/10/11,8310200201
- 8310270552 Releases public version of revised emergency plan FELTON J M Division of Rules and Records 83/10/21 Document Management Branch. 1p 20744 017 24X Fiche 50-461,83/10/21, 83/0270552
- --8310270567 Forwards public version of draft Amend 28 to F8AR, App 13 B, consisting of Rev 2 to Emergency Plan DAP1890 008 Rev should resolve SER Dutstanding Issue 18 (NURE9-0853) NELBON, R M Illinois Power Co 89/10/14 SCHWENCER, A Licensing Branch 2 lp 20944 018 24X Fiche 50-441,83/10/21,8310270552
- --8310270574 Public version of draft Amend 28 to FSAR, App 13 B, consisting of Rev 2 to emergency plan # Illinois Power Co 83/10/10 303pp 20944 019 24X Fiche: 30-461, 83/10/21, 8310270552
- Q Adjudicatory correspondence
- 8310120403 Notice of appearance in proceeding Certificate of Svc encl BAMELSON, A Illinois, State of 83/10/06 5pp 20699 01/ 24X Fiche 50-461,83/10/06,8310120403
- H General correspondence

- K Utility Final Safety Analysis Report (FBAR) & amends
- B310200201 Forwards Amend 27 to FSAR, consisting of safety relief valve monitoring description, Chapter 14 updating & responses to NRC questions on emergency preparedness meteorological program 2010N.H R Office of 20828 292 24Y

program

HALL,D P Illinois Power Ca 83/10/11 DENTON.H R

Nuclear Reactor Regulation, Director 1p 20828 292

Fiche 50-461.83/10/11.8310200201

- --8310200205 Amend 27 to FSAR # 11linais Pawer Co 83/10/31 Fiche 50-461.83/10/11.8310200201 365pm 20828 293 24X
- Q Inspection reports, 16 Oulletins & correspondence
- 8310060282 Forwards IE Insp Rept 50-461/83-14 on 830824-26 No noncompliance noted

 KNOP,R C Region 3, Office of Director. 83/09/14 GERSTNER,W C

 Illinois Power Co 2pp 20646 159 24X Fiche 50-461,83/09/14, 8310040282
- --8310060309 IE Insp Rept 50-461/83-14 on 830824-26 No mancompliance noted Major areas inspected licensee action on open items, results of study on noncompromance repts & design verification of electrical access support sypport yellow ARYES, DW Region 3, Office of Director 63/09/14 20pp 20646 161 24X Fiche 50-461,83/09/14,8310060282
- 8310140147 Forwards IE Insp Rept 50-461/83-15 on 830824-26 & 31-0901 & notice of violation

 BTREETER, J.F. Region 3, Office of Director 83/09/29

 GERSTNER, W.C. Illinois Power Co. 2pp. 20763 025 2

 Fiche 30-461.03/09/29.8310140147
- --8310140148 Notice of violation from insp on 830824-24 & 31-0701 STREETER,J F Region 3, Office of Director 83/09/29 2pp 20763 027 24X Fiche 50-461.83/09/29.8310140147
- -8310140150 IE Insp Rept 50~461/83-15 on 830824-26 Noncompliance noted failure to specify that 10CFR21 provisions applied to five welding math procurement documents & to assure bore bent piping compliance SCHULZ,R D. HUNTER,D R. Region 3. Office of Director 10pp 20763 029 24X Fiche 50-461.83/09/29.8310140147 83/09/29
- 8310250636 Forwards IE Insp Rept 50-461/83-13 on 830727-0915, No Noncompliance noted
 KNOP,R C Region 3, Office of Director 83/09/30 GERSTNFR.W C
 Illinois Power Ca 2pp 20700-296, 24% Fiche 50-461,83/09/30, 8310250636
- --8310250642 IE Insp Rept 50-461/83-13 on 830727-0915 No noncompliance #10230642 IE insp Rept 50-46/103-13 on B3072/-0915 No noncompliance noted Major areas inspected const activities, including matl leydown & storage areas, program control, licensee action on previous insp findings & welding activities activities (CHRISTIANSON,F. HAYNES, DW Region 3, Office of Director 83/09/29 5pp 20700 278 24X Fiche 50-461,83/09/30, Director 83/09/29 8310250636
- 8310060395 Ack receipt of 830728 ltr requesting concurrence in plans for proceeding w/Phase III insp activities delineated in HVAC recovery plan outline Phase III reinsp & plans to remove galvanox from welds acceptable KEPPLER, J C Region 3, Office of Director. 83/10/03 GERSTNER, W Illinois Pawer Co ip 20641.218 24X Fiche 50-461.83/10/03, 823004335 8310060395
- --8310060409 Requests review & concurrence to proceed w/Phase III of HVAC recovery plan Also requests concurrence to remove galvanox on all accessible first attachment, hanger structural & hanger-to-duct welds
 HALL,D P IIInois Power Co 83/07/28 KEPPLER,J 0 Region 3, Office of Director 2pp. 20641:219 24X Fiche 50-461.83/10/03, 8310040288
- 8310310289 Forwards IE Insp Rept 50-461/83-16 on 830913-16, No Noncompliance noted

 KNOP,R C Region 3. Office of Director B3/10/12 QERSTNER,W C.

 Illinois Power Co 2pp 20957:087 24% Fichs 50-461,83/10/12. 8310310289
- --8310310293 IE Insp Rept 50-461/83-16 on 830713-16 No noncompliance noted Major areas inspected assessment & progress w/record & field verification & open item action (ref confirmation of 820901 & 1006 action 1trs)

 JABLONSKII-F, J. HAYES, D. W Region 3, Office of Director 83/10/12 8pp 20957:089 24X Fiche 50-461,83/10/12.8310310289

- 8310180271 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON, WL Region 3. Office of Director 83/10/14 GERETNER, [111nois Power Co 7pp 20807 036 24% Fiche 50-461,83/10/14, 2210180274
- 8310250619 Describes significant improvements in corrective action program, eliminating need for checklist trending, in response to notices of violation & 820701 confirmation of action ltr HALL.D P Illinois Power Co 83/10/17. KEPPLER.J G. Region 3, Office of Director 2pp 20900 287 24X Fiche 50-461,83/10/17, 221026419
- S Reportable occurrences. LERs & related correspondence
- B310040204 Final Deficiency Rept 55-83-05 re failure of certain 1/4-inch 20-hex head cap screws during installation of conduit strap attachments to supports Initially reported on 830412 litem not reportable per 10CFR50 55(e) HALLD P Illinois Fower Co 83/09/26 KEPPLER, J 9. Region 3, Office of Director 4pp 20614 276 24X Fiche 50-461.83/09/26, parameters. 8310040204
- 8310040238 Final deficiency rept re wall thickness for safety-related piping Initially reported on 821007 Lines ILP21A4 & ILP2184 will be used as-installed & penetration sleeve will be modified to shield pipe from external loads HALL. D P Illinois Power Co 83/09/26 KEPPLER, J 0 Region 3, Office of Director 4pp 20413 220 24X Fiche 50-441,83/09/26, 831008288
- 83i0120077 Final Deficiency Rept 83-04 re control of design change documents Initially reported on 830215 Procedures revised re methods of posting & handling design change documents.
 HALL.D P. Illinois Power Co 83/09/30 KEPPLER, J. 9 Region 3, Office of Director 4pp 20697 157 24X Fiche 50-461,83/09/30,8310120077
- 8310120441 Potential Deficiency 55-82-07 re small bore/instrumentation piping & conduit support design calculations Initially reported on 820902 Personnel reviewing small bore/instrumentation piping support calculations retrained HALL.D P Illinois Power Co. 83709/30 KEPPLER.J & Region 3, Office of Director App 20678.313 24X Fiche 50-461,83/09/30, 0230120441 8310120441

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8310240254 Bubmits daily highlights Unit 2 canceled on B31014 Const on Unit 1 continuing & not affected by cancellation HARRISON.0 Licensing Branch 2 83/10/18 DENTON.H.R.. CABE.E 9 . CARTER.J. Office of Nuclear Reactor Regulation. Director 1p 20707 277 24X Fiche 50-461.83/10/18.8310240254
- G Inspection reports, IE Bulletins & correspondence
- 8310180271 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas and Updates will be provided every 6 months. AXELEGON, W. L. Regipn 3, Office of Director 83/10/14 GERSTNER, W. C. Illinois Power Co. 7pp. 20807.036 24X Fiche. 50-461.63/10/14, page 10807.7 8310180271

DOCKET STN-50-470 CESSAR SYSTEM SO

- A Application/construction stage documents & correspondence
- 8310070274 Discusses referenceability of GESSAR-F final design approval NRC support for standardization as abstract concept for future plants w/o resolving present issues inconsistent. SCHERER, A E Combustion Engineering, Inc. 83/09/30. EISENHUT, D. Q Division of Licensing 2pp. 20657:026 24X Fiche: 50-470,83/09/30,8310070274 Division of Licensing 8310070274
- 8310270006 Notification of 831026 meeting w/C-E in Bethesda.MD to discuss use of pipe whip restraints in C-E atd 8AR design.
 MEYER.G.C Standardization & Special Projects Branch 83/10/19.
 THOMAS.C.D. 42 Handardization & Special Projects Branch. 2pp
 20940.165. 24X Fiche 50-470.83/10/19.8310270006
- 8310280306 Discusses confirmatory issues impinging on C-E exceptions to limitations placed on GESBAR final design approval (FDA) & possible similar limitations on CEBBAR FDA MEYER, G. C. Btandardization & Special Projects Brench 83/10/21, EISENHUT, D. G. Division of Licensing, 5pp 20764-356 24% Fiche 50-470,83/10/21,8310280306

- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310050232 SAFETY EVALUATION REPORT RELATED TO THE FINAL DESIGN OF THE STANDARD NUCLEAR STEAM SUPPLY REFERENCE SYSTEM. CESSAR SYSTEM 80 Bocket No 50-470 (Combustion Engineering, Incorporated) # Office of Nuclear Reactor Regulation. Director NUREG-0852 502 83/09/30 163pg 20635 151 24X Fiche 50-470.83/09/30.8310050232
- 8310170204 Forwards SBER 2 (NUREG-0832) re CESSAR & application for final design approval W/o encl.
 THOMAS.C O Standardization & Special Projects Branch 83/09/30
 8CHERER.A E Combustion Engineering, Inc. 2pp. 20798-092 24X
 Fiche 50-470.83/09/30.8310170204

DOCKET 50-471 PILGRIM NUCLEAR POWER STATION. UNIT 2

- S Reportable occurrences, LERs & related correspondence
- 8310140082 PNO-I-83-105 on B31007, seismic event occurred in northeastern US w/magnitude of 5 2 on Richter scale in NY & 4 0 in NY No damage to equipment identified, GALLOR M Region I, Office of Director. 83/10/07 ip 20766 I16 24X Fichs 50-000,83/10/07,8310140082

DOCKET STN-50-482 HOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- 8310230054 Provides supplemental info on Item 6, "Final Acceptance Criteria," of util 830729 ltr re sys turnover quality action plan Info addresses means by which util util conduct final sys walkdown surveillance verification program KDESTER, Q. L. Kansas Qas & Electric Co B3/08/25 SEIDLE, W. C Region 4, Office of Director ip 20894 199, 24X Fichs 30-482:83/08/25.8310250054
- B310110600 Requests that encl B30B30 memo re postulated primary reactor coolant loop breaks be reviewed to determine whether change in radiation shielding constitutes agreement that double-ended guillotine pipebreak need not be postulated.

 NGVAN.T H Assistant Director for Licensing 83/09/28 KNIOHT, J P Assistant Director for Comp & Structures Engineering (Post B30201) HOUSTON,R W Assistant Director for Radiation Service MULLER, D R Assistant Director for Radiation Protection 2pp 20714 344 24X Fichs 30-000,83/09/28/8310110600.
- 83iO240039 Notification of 83iO25 meeting w/util in Rockville, MD to discuse NRC comments on detailed control room design review HOLONICH, J. J., EDIBON.9 E. Licensing Branch 1 83/10/12 YCUNOBLOOD, B J Licensing Branch 1 4pp 20703 23B. 24X Fiche 30-000,83/10/12,83iO240039
- 8310240075 Notification of 831026 meeting w/utils & Bechtel in Bethesda, MD to discuss autstanding issues associated w/qualification of electrical equipment HOLONICH, J. J. EDISON, 9 E Licensing Branch 1 83/10/13 YOUNOSLOOD, B J Licensing Branch 1. 4pp 20903 210 24X Fiche 50-000, 83/10/13, 8310240075
- 8310280133 Forwards marked-up Tech Spec Section & O, "Administrative Controls," for review & approval KOESTER,9 L. Kansas Gas & Electric Co. 83/10/21, DENTON,H R. Office of Nuclear Reactor Regulation, Director. 52pp. 20899
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- B3i0180317 Forwards Rev 1 to "Emergency Procedure Generation Package," & Rev 1 to "Hriters Guide For Emergency Operating Procedures," par Generic Ltr 82-33 (NUREG-0737, Suppl 1). Listed SER items resolved KDESTER,O.L. Kanses Gas & Electric Co. 83/10/14 DENTON,H R. Office of Nuclear Reactor Regulation, Director. 2pp. 20803 101. 24X Fiche 30-482,83/10/14,8310180317
- --8310180321 Rev 1 to Procedura ADM 01-052 "Emergency Procedure Generation Package." AMMSTRONO, B Kaness Oas & Electric Co. 83/10/11 14pp 20803.103 24X Fichs 50-482,83/10/14,8310180317
- --8310180325 Rev 1 to Procedure APM 02-022 "Writers Quide for Emergency Operating Procedures."

 ARMSTRUNG, S. Kansas Cas & Electric Co., 83/10/03 30pp 20803:117 24X Fiche:50-482,83/10/14.8310180317.

- F Security, medical, emergency & fire protection plans
- B310110376 Forwards request for add1 info for review of emergency plan Info requested within 2 wks YOUNOBLOOD, B J Licensing Branch 1 83/09/23 KOESTER, G L Kansas Oas & Electric Co 3pp 20713 225, 24X Fiche 50-482, 83/09/24, 8310110376
- B310170713 Forwards request for add1 info re instrumentation & control sys remote safe shutdown Info needed within 2 wks of receipt of 1tr
 YOUNOBLOUD, B J Licensing Branch 1 B3/10/05 KOESTER. G L Kansas Gas & Electric Co SCHNELL, D F Union Electric Co Spp
 20798 126 24X Fiche 50-000, 83/10/05, 8310170713
- 8310170722 Forwards comments on util detailed control room design review submitted in response to Generic Ltr 82-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability " Info mgt sys discussion needs more detail YOUNOBLOOD.B J Licensing Branch I 83/10/05 KOEBTER.Q L Kansas Gas & Electric Co 10pp 20798 100 24X Fiche 50-000.83/10/05, 8310170722
- 8310180317 Forwards Rev 1 to "Emergency Procedure Generation Package," & Rev 1 to "Writers Guide For Emergency Operating Procedures," per Generic Ltr 82-33 (NUREG-0737.8uppl 1) Listed SER Items resolved KOESTER.O L Kansas Oas & Electric Co B3/10/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20803:101 24X Fiche 50-482,83/10/14,8310180317
- --8310180321 Rev 1 to Procedure ADM 01-052 "Emargency Procedure Generation Package " ARMSTRING, 8 Kansas Gas & Electric Co 83/10/11 14pp 20803-103 24X Fiche 50-482,83/10/14,8310180317
- --8310180325 Rev 1 to Procedure ADM 02-022 "Writers Guide for Emergency Operating Procedures"
 ARMSTRONG, 8 Kansas Cas & Electric Co 83/10/03 30pp 20803 117 24X Fiche 50-482,83/10/14,8310180317
- 8310210414 Releases public version of licensee responses to questions re emergency plan FELTON,J M Division of Rules and Records 83/10/17 Document Management Branch 1p 20882 327 24X Fiche 50~482,83/10/17, 8310210414
- --8310210415 Forwards public version of responses to questions re emergency plan Responses will be incorporated in Rev 12 to FSAR KOESTER, C. L. Kansas Gas & Electric Co. 83/10/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 20882-378 24X Fichs 30-482,83/10/17,8310210414
- G Adjudicatory correspondence
- 8310140020 Informs that D Garner will tour plant on 831021 OL.
 proceeding issues will not be discussed Trip rept will be
 served Certificate of Svc encl
 REAMER, C W Commissioners 83/10/13 LAURENBON, J A ,
 ANDERBON, 9 C , PAXTON, H C Atomic Safety and Licensing Board Panel
 2pp. 20767:030 24X Fiche 50-482,83/10/13,8310140020
- Q Inspection reports. IE Bulletins & correspondence
- 8310250084 Describes add1 mgt initiatives implemented to change QA plans Joint final insp of sys & components released prior to start proposed MOESTER, G L Mansas Qas & Electric Co 83/07/29 SEIDLE, W G Region 4. Office of Director Spp 20894 072, 24X Fiche 50-482,83/07/29,8310250084
- 8310130172 Forwards IE Insp Rept 50~482/83-19 on 930701-31 No noncompliance noted SEIDLE,W.C Region 4. Office of Director 83/08/22 KOESTER.O L Kansas Gas & Electric Co 2pp 20724 298 24X Fichs 50~482.83/08/22.8310130172
- --8310130178 IE Insp Rept 50-482/83-19 on 830701-31. No noncompliants noted Major areas inspected; observation of startup activities & secondary hydrostatic testing, procedure review & followup on previous violations
 JOHNSDN, W D , SCHUM, W. S , WHITTLESEY, K A Region 4, Office of Director 83/08/19. Spp 20724 300 24X Fiche 50-482,83/08/22,8310130172
- 8310130241 Forwards IE Insp Rept 50-482/83-21 on 830416-0815 & notice of violation SEIDLE, W C Region 4, Office of Director. 83/09/06 KDESTER, G L Kansas Gas & Electric Co 2pp 20723 272 24X Fiche: 50-482, 83/09/06, 8310130241.

- --B310130246 Notice of violation from insp on 830616-0815 * Region 4, Office of Director 83/09/06 1p 20723 274 24) Fiche 50-482,83/09/06,8310130241
- --B310130251 IE Insp Rept 50-482/83-21 on 830616-0815 Noncompliance noted failure to fallow &/ar implement quality requirements for work operations on traveler G-SAP-MC-030 RDBERDS.H W. JDHNSON.W D Region 4. Office of Director 83/09/01 Bpp 20723 275 24X Fiche 50-482,83/09/06,83/0130241
- 8310130257 Forwards IT Insp Rept 50-482/83-22 on 830822-24 No noncompliance noted SEIDLE: W C Region 4. Office of Director 83/09/13 KDESTER.G L Kansas Gas & Electric Co 2pp 20723 225 24X Fiche 50-482,83/09/13.8310130257
- --8310130259 IE Insp Rept 50-482/83-22 on 830822-26 No noncompliance noted Major areas inspected const GA & turnover of sys for prooperational testing JAUDON, J P. JOHNSON, W D. Region 4. Office of Director 83/09/12 6pp 20723 227 24X Fiche 50-482.83/09/13.8310130257
- B30B300340 IE Info Notice B3-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3709/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022 24X Fiche 50-000.83/09/26,830B300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- B308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " 8vc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 601. 24X Fiche 50-000,83/09/26,8308300345
- B30B300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFRSO 59 Evaluation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 80-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl JORDAN, E i Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24% Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JURDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Naxious Gases," Syc list encl JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- B30B300761 IE Info Notice B3-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Byc list encl.

 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 127 24X Fichs 50-000.83/10/11.8308300761
- 8310280121 Forwards NRR SALP rept based partly on input solicited from selected reviewers & NRR SALP input for Aug 1982 Jul 1983 Staffing & training attributes contained in rept removed, based on 830913 meeting in Region IV.
 HOLONICH.J J Licensing Branch 1 83/10/12 EISENHUT.D 0
 Division of Licensing App 20945 083, 24X Fiche 50-482,83/10/12.
- S Reportable occurrences, LtRs & related correspondence
- 8310120092 Part 21 rept re snubber failure during shock arrestor test Caused by broken capstan spring Vendor effecting corrective action w/J Evans Co to inspect shock arrestors containing Evans springs HADNAOY,P A Pacific Scientific 83/09/14 Region 5, Office of Director 4pp 20696 167 24% Fiche 30-482,83/09/14,8310120092

- B3100403B6 Interim deficiency rept re Could-Rundel Type 99-3
 handswitches w/binding cams Initially reported on B30824 AE
 evaluating concern Next rept will be submitted by 840120
 Switches subj of 1E Info Notice B3-42
 KOESTER.G L. Kansas Gas & Electric Co B3/09/23 SEIDLE.W C
 Region 4. Office of Director 1p 20617 295. 24X
 Fiche 50-482,83/09/23,8310040386
- 8310130192 Fourth Interim deficiency rept re documentation & hardware discrepancies in burated refueling water sys Initially reported on 830121 Evaluation of safety significance of away strut washer ongoing Final rept will be submitted by 831209. XOE8TER.6 L Kansas Gas & Electric Co 83/09/28 SEIDLE, W C Region 4. Office of Director 2pp 20724 330 24X Fiche 50-482,63/09/28.8310130192
- 8310130223 Interim deficiency rept re Vulkens Supreme cable terminations Initially reported on 830620 AE evaluation results expected within 2 wks Next rept will be submitted by 831123 MOESTER, 0 L. Kansas Gas & Electric Co. 83/09/28 SCIDLE, W.C. Region 4. Office of Director 1p. 20724 095 24X Fiche 50-482,83/09/28,8310130223
- 8310130231 Interim deficiency rept re Culter-Hammer push button switches Initially reported on 830609 Condition still under evaluation Next rept will be submitted by 831209 KOESTER, G L Kansas Gas & Electric Co. 83/09/28 SEIDLE, W C. Region 4. Office of Director ip 20723 286 24X Fiche 50-482,83/09/28,8310130231
- 8310180387 Interim deficiency rept re miscellaneous component failures in safety-related Power Conversion Products battery charger Initially reported on 830307 Bottery charger testing near completion Next rept by 840120 KOESTER.G L Kansas Gas & Electric Co B3/10/03 SEIDLE, W C. Region 4. Office of Director ip 20803 174 24X Fiche 50-482,83/10/03,8310180387
- 8310180171 Final deficiency rept re changes to hanger notes & symbol drawings Initially reported on B30221 Matter not reportable per 10CFR50 55(c) KOESTER,G L. Kansas Gas & Electric Co. 83/10/07 SEIDLE,W C. Region 4, Office of Director ip 20808 360 24X Fichs 50-482,63/10/07,8310180171
- 8310180254 Final deficiency rept re cracked insulated couplings in QE AKR breakers. Initially reported on 830620 Item determined not to be reportable per 10CFR50 55(e) KDESTER.0 L. Kansas Qas & Electric Co. 83/10/07 BEIDLE, W.C. Region 4. Office of Director 1p. 20802 340 24X Fiche: 50-482, 83/10/07, 8310180256.
- 8310210244 Interim deficiency rept re Pacific Scientific Co snubbers Initially reported on 830913 Preliminary investigation results revealed suspect springs restricted to one subvendor Final rept will be submitted by 831130. KOESTER, 6 L Kansas Oas & Electric Co 83/10/13 OAOLIARDO, J E. Division of Resident, Reactor Project & Engineering Programs. 2pp 20851-269 24X Fiche 50-482.83/10/13.8310210244
- 8310210188 Final deficiency rept re Ouyon 1/2-inch socket couplings.
 Initially reported on 830617 Item not reportable per
 100FR80 55(e)
 KOESTER, G L Kansas Gas & Electric Ca 83/10/14, GAGLIARDO, J E.
 Division of Resident, Reactor Project & Engineering Programs 1p.
 20856 080 24X Fiche: 50-482,83/10/14,8310210188
- 8310310074 Part 21 rept re design deficiency involving combination supports for Class IE cable trays & HVAC ducts. Initially reported on B31025 Due to misclassification, supports specified w/less than full safety-related GA program MEYERS, B L Bechtel Corp B3/10/27 DEYOUNG, R Director's Office, Office of Inspection and Enforcement. 3pp 20951 040 24X Fiche 50-000,83/10/27,8310310074
- DOCKET STN-50-483 CALLAWAY PLANT, UNIT I
- A Application/construction stage documents & correspondence
- B310110600 Requests that encl B30B30 memo re postulated primary reactor coolant loop breaks be reviewed to determine whather change in radiation shielding constitutes agreement that double-ended guillotine pipebreak need not be postulated NOVAK.T M Assistant Director for Licensing. B3/09/28, KNICHT, J. P. Assistant Director for Comp & Structures Engineering (Post B30001) HOUSTON,R.W Assistant Director for Reactor Bafety, MULER, D R. Assistant Director for Reactor Bafety. MULER, D R.

- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle
 EISENHUT.D G Division of Licensing 83/09/29 PALLADINO,N J Commissioners 10pp 20632 106 24X Fiche. 50-000, 83/09/29, 8308300355
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping Sys Info applicable to Diablo Campon I & 2. Fermi 2 & Calkaway EISENHUT, D G Division of Licensing B3/09/29 PALLADINO, N J Commissioners 3pp 20632 001 24X Fiche 50-000.83/09/29, 8308300357
- B30B300763 Board Notification B3-151 provides info me desirability of current ECCS actuation logic for Wastinghouse plants.in light of recent info concerning steam generator tube rupture procedure for Borsaels Nuclear Power Station EISENHUT.D 0 Division of Licensing. B3/10/04 PALLADING,N J Commissioners 2pp 20678 033 24X Fiche 50-000,83/10/04, 8300300743
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions repotential problems w/ASCO solenoid valves EISENHUT.D 9 Division of Licensing 83/10/06, PALLADINO,N J Commissioners 31pp 20818 001 24X Fiche 50-000,83/10/06, B3083007/1
- 8310240039 Notification of 831025 meeting w/util in Nockville.HD to discuss NRC comments on detailed control room design review HOLONICH.J J . EDISON.Q E Licensing Branch & 83/10/12 YDUNGBLOOD,B J Licensing Branch & 4pp 20703 23B 24X Fiche 50-000,83/10/12,8310240039
- 8310240075 Notification of 831026 meeting w/utils & Bechtel in Betherds, ND to discuss outstanding issues associated w/qualification of electrical equipment HOLONICH, J. J. EDIBON, O. E. Licensing Branch 1 83/10/13 YOUNDBLODD, B. J. Licensing Branch 1 4pp 20903 210 24X Fichs 50-000, 83/10/13, 8310240075
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310270443 Forwards comments on Rev 5A to emergency plan Comments will be categorized as improvement items since BER states plan meets 10CFR50 47(b) stds & 10CFR50 App E requirements, per NURCO-0830
 PAPERIELLO, C. J. Region 3, Office of Director 83/10/25
 MATTHEWS, D. B. Emergency Preparedness Branch App 20923 091 24X Fichs 50-483, 83/10/25, 8310270443
- F Security, medical, emergency & fire protection plans
- 8310170713 Forwards request for addl info re instrumentation & control sys remote safe shutdown Info needed within 2 wks of receipt of 1tr
 YOUNOBLOOD, B. J. Licensing Branch I 83/10/05 KGESTER, G. L. Kansas
 Gas & Electric Co. SCHNELL, D. F. Union Electric Co. Spp.
 20798 126 24X Fiche 50-000, 83/10/05, 8310170713
- 8310170722 Forwards comments on util detailed control room design review submitted in response to Generic Ltr 82-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability " Info mgt sys discussion needs more detail YOUNGELOOD, B J Licensing Branch 1, 83/10/05, KDEGTER, C L Kansas Oas & Electric Co 10pp 20798 100 24% Fiche, 50-000, 83/10/05, 8310170722
- 8310250656 Releases public version of revised emergancy plan implementing procedures FELTON J M Division of Rules and Records 83/10/20 Document Management Branch ip 20916-260 24X Fiche 50-483,83/10/20, 8310250656
 - B310250661 Forwards public version of revised emergency plan implementing procedures, including Procedures EIP-ZZ-00101 reclassification of emergencies, EIP-ZZ-00102 re emergency implementing actions & EIP-ZZ-00201 re notifications SCHNELL, DF Union Electric Co 83/10/05 KEPPLER, J, G Region 3, Dffice of Director 3pp. 20916 261 24X Fiche 50-483, 83/10/20, 8310250536
 - 3310250664 Public version of revised amergency plan implementing procedures including Procedures EIP-ZZ-00101 re classification of emergencies EIP-ZZ-00102 re emergency implementing actions & EIP-ZZ-00201 re notifications.

 * Union Electric Co. 83/07/18, 540pp. 20916-264 24X Fichs 50-483,83/10/20,8310250656

- 8310270443 forwards comments on Rev 5A to emergency plan Comments will be categorized as improvement items since SER states plan meets 10CFR50 47(b) stds & 10CFR50 App E requirements, per NUREO-0830
 PAPERIELLO,C J Region 3, Office of Director 83/10/25
 HATTHEWS,D B Emergency Preparedness Branch App 20923 091 24x
 Fiche 50-483,83/10/25.8310270443
- Q Adjudicatory correspondence
- B310050457 Motion to withdraw portion of DM Rohrer testimony re use of source terms in policy development on prodistribution of potassium iodide to general public Certificate of Svc encl PCRLIS.R G Hearing Branch 3 B3/09/27 Atomic Safety and Licensing Board Panel 7pp 20632 16/ 24X Fiche 50-483.83/09/27, 831005045/
- 8310040225 Motion for extension to file, w/Commission, petition for review of ASLAB 830914 Decision ALAB-740 Extension should be granted until 15 days after ASLAB role, on Joint Intervenors 830923 reconsideration petition Certificate of Svc enc) CHACKES.K M Joint Intervenors-Callaway CHACKES.K N Chackes & Hoare 83/09/29 Commissioners 3pp 20614 236 24X Fiche 50-483,83/09/29.8310040725
- 8310040217 Order advising that time within which Commission may review ALAB-740 on Commission motion or time within which parties may file petitions for review of ALAB-740 will not communce until date ASLAB rules on reconsideration petition CHILK, S. J. Office of the Secretary of the Commission 83/10/03 Commissioners in 20614-235 24X Fiche 50-483,83/10/03,8310040217
- 8310050509 Nemorandum & order approving NRC motion for leave to withdraw testimony of witness DM Rohrer Agreement of parties approved re-schedule of filing proposed findings of fact & conclusions of law QLEASON, J.P. Atomic Safety and Licensing Board Panel 83/10/04 Office of the Executive Legal Director 1p 20634-018 24X Fiche 50-483.83/10/04.8310050509
- 8310120420 Findings of fact & conclusions of law Certificate of Svc encl REED.J O Reed, J 9 83/10/06 10pp 20698 282 24X Fiche 50-483,83/10/96.8310120420
- 8310140063 Response to Joint Intervenors 830823 petition for reconsideration of ASLB 830914 Decision ALAB-740 Insufficient showing made to justify reopening record Certificate of Svc encl GALEN.R E Shaw, Pittman, Potts & Trowbridge 83/10/12 Atomic Safety and Licensing Appeal Panel 201pp 20767 140 24% Fiche 50-483,83/10/12,8310140063
- 8310170419 Response opposing Joint Intervenors 830923 petition for reconsideration of ALAB-740 & to reopen record Integrated design insp program rept not presented in timely fashion Notice of appearance & Certificate of 8vc encil REPKA.D A. PERLIS.R O Hearing Branch 3 83/10/12 Atomic Safety and Licensing Appeal Panel 21pp 20779 174 24X Fiche 50-483,83/10/12,8310170419
- 8310240180 Memorandum & order directing applicant & NRC to discluse sufficient addl info & views re intervenor 830923 petition for reconsideration of ALAB-740 by 831104 & 15, respectively Disposition of patition awaits receipt of info SMGEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/10/20 Union Electric Co 4pp 20880 034 24X Fiche 50-483,83/10/20 8310240180
- B310250163 Proposed findings of fact & conclusions of law on J Reed contentions re emergency planning Final decision to 1550e license should be ordered Certificate of Svc encl PERLIS, R O Hearing Branch 3 83/10/21 28pp 20896 296 PAX Fiche 50-483,83/10/21,8310250163
- 8310310200 Reply to Reed 831006 proposed findings of fact & conclusions of law re Contention & Findings mischaracterized FDA recommendation & position of applicant & State of MO Certificate of Svc encl
 BAXTER.T A Union Electric Co BAXTER.T A Shaw, Pittman, Potts & Troubridge 83/10/27 13pp 20959 167 24X Fiche 50-483,83/10/27,8310310200
- M Antitrust correspondence
- 8310280166 Forwards most recent correspondence re Union Electric Cotransmission svc & arrangements for interconnecting svc Unconvinced that unbrella-typs transmission svc is proper approach
 BARNETT. B J Missouri Joint Municipal Electric Utility Commission 83/09/06 LAMBE.W NRC No Detailed Affiliation Given 5pp 20929 001, 24x Fiche 50-483,83/09/06.8310280166

O Inspection reports, IE Bulletins & correspondence

- 8310060447 Forwads IE Insp Rept 50-483/8.1-15 on 830701-0031 & notice of violation
 KNOP.R (Region 3. Office of Director 83/09/23 SCHNELL, D F
 Union Electric Co 2pp 20641 032 P4x Fiche 50-483.83/09/23,
 8310060447
- --8310060453 Notice of violation from into an 830701-0831 KNOP,R C Rigion 3. Office of Director 83/09/23 1; 20641 034 24% Fiche 50-483,83/09/23,8310060449
- --B310060482 IE Insp Rupt 50-4B3/83-15 on B30701-0B31 Noncompliance noted procedural controls inadequate to prevent unauthorized temporary alterations of plant components from being accomplished by startup personnel NEISLER, J H. KONKLIN, J E. Region 3, Office of Director B3/09/23 7pp 20641 035 24X Fiche 80-4B3,83/09/23,8310060449
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Gualification Tests " Svc list enc!
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24% Fiche 50-000, 83/08/26, 8308300340
- 830B300342 lt Info Nutice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Fost 830163) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,830B300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list one1 JORDAN, E | Division of Lawrgency Proparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fithe 50-000,83/09/26,8300300345
- B30B300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys Wo 1007830 57 Evaluation" Svc list onel, JORDAN, E L Division of Laergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 113pp 20716 324 24X Fiche 30-000,83/09/29,8308300349
- 8310040268 Ack receipt of 830720 ltm clarifying status of turbine driven auxiliary feedwater pump turbine control panels in response to IL Insp Rept 50-483/83-14 KNDP.R C Region 3. Office of Director 83/09/30 SCHNELL.D & Union Electric Co 1p 20613 001 24X Fiche 80-483/83/09/30, 83/09/3
- --8310040273 Responds to NRC B30728 & 0902 ltrs re IE Insp Rept 50-4B3/83-14 Turbine driven auxiliary feedwater pump turbine control panel procuped.received & installed BCHNELL.D F Union Electric Co B3/09/20 KNDP.R C Region 3. Office of Director ip 20613 00P 24X Fiche 50-483,83/09/30, 8310040248
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants" SVL list encl JORDAN, C t Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07,83083003/8
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list onel JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 930103) 83/10/07 Consolidated Edison Co of New York, Inc. 74pp 20882 026 24X Fiche 80-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Hatl Defect Causes Production of Noticus Bases " Eye list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000.83/10/11,8308300757
- 8308300741 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl.

 JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Inc. 120pp 20827 179 24X Fiche 50-000,83/10/11.8308300761
- B310180260 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas entl Updates will be provided every 6 months AXELSON, W.L. Region 3, Office of Director 83/10/14 8CRNLLL.D F Union Electric Co. 7pp. 20802-268 24X Fiche 50-483.83/10/14, 8310180240.

- 8310310285 Ack roceipt of 831010 transmittal of 1982 annual rept for facility radiological environ monitoring program Open item identified in IE Insp Rept 50-483/83-07-02 closed out PAPERIELLD.C J Region 3. Opfice of Director B3/10/26 SCHNELL.D F Union Electric Co ip 20961 283 24X Fiche 30-483.83/10/26.8310310285
- R Periodic operating reports & related correspondence
- 8310120069 Provides quarterly status rept in response to 810527 ltr Schedule unchanged Fuel load scheduled for Apr 1984 w/ commercial operation scheduled for late 1984 or early 1985 SCHNELL.D F Union Electric Co 83/10/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 20497 163 24X Fiche 50-483,83/10/03,8310120069
- 8310310285 Ack receipt of 831010 transmittal of 1982 annual rept for facility radiological environ monitoring program Open item identified in 1E Insp Rept 50-483/83-07-02 closed out PAPERIELLO.C J Region 3. Office of Director B3/10/26 SCHNELL.D F Union Electric Co ip 20761 283 24X Fiche 50-483,83/10/26,8310310285
- S Reportable accurrences. LERs & related correspondence
- 8310210098 Interim Deficiency Rept U-63 re broken or cracked capstan spring tangs on Pacific Scientific mechanical snubbers Initially reported on 830916 Caused by age hardening snubber springs prior to plating Final rept by 831111 SCHNELL.D F Union Electric Co 83/10/14 KEPPLER.J 9 Region 3, Office of Director ip 20858 260 24X Fiche 50-483,83/10/14,8310210098
- 8310310074 Part 21 rept re design deficiency involving combination supports for Class IE cable trays & HVAC ducts Initially reported on 831025 Due to misclassification supports specified w/less than full safety-related GA program MEYERS.B L. Bechtel Corp. 83/10/27 DEYDUNG, R. Director's Office, Office of Inspection and Enforcement Spp. 20951-040 24X Fiche 50-000, 83/10/27, 8310310074
- DOCKET STN-50-486 CALLAWAY PLAN), UNIT 2
- A Application/construction stage documents & correspondence
- 8308300355 Board Notification 83-66A advises that position re rod drop issue revised to require each Westinghouse plant owner provide statement that required plant-specific calculations have been performed for first cycle EISENHUT, D G Division of Licensing 83/09/29 PALLADING, N J Commissioners 10pp 20632 106 24X Fithe 50-000,83/09/29, 8308300355
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon 1 & 2, Fermi 2 & Callaway EISENHUT, D. G. Division of Licensing B3/09/29 PALLADINO, N. J. Commissioners 3pp 20632 001 24x Fiche 50-000, 83/09/29, 8308300357
- 8308300763 Board Notification 83-151 provides info my desirability of current ECCS actuation logic for Westinghouse plants, in light of recent info concerning steam generator tube rupture procedure for Borssele Nuclear Power Station EISENHUT, D. G. Division of Licensing 83/10/04 PALLADING, N. J. Commissioners Rpp 20698 033 24% Fiche 30-000,83/10/04,8308300763
- 8308300771 Board Notification 83-128A forwards Equipment Qualification Branch conclusions repotential problems w/ASCO solenoid valves
 EISENHUT, D. G. Division of Licensing 89/10/06 PALLADING, N. J. Commissioners 31pp 20818 001 24X Fiche 50-000.83/10/06, 8308300771
- G Adjudicatory correspondence
- 8310270307 Errata correcting Pages 3 & 435 of ASLB 831024 recommendations to Commission GLEASON.J P Atomic Bafety and Licensing Board Panel 83/10/25 p 20923 192 24X Fiche 50-247,83/10/25,8310270307

- @ Inspection reports, IE Bulletins & correspondence
- 8310180260 Clarifies NRC position re procedures for admitting NRC personnel to facilities List of personnel requiring access to vital areas encl Updates will be provided every 6 months

 AXELSON, W. L. Region 3, Office of Director 83/10/14 SCHNELL, D. F. Union Electric Co. 7pp. 20802 268 24X Fiche 50~483,83/10/14. 8310180260
- S Reportable occurrences. LERs & related correspondence
- 8310310074 Part 21 rept re design deficiency involving combination supports for Class IE cable trays & HVAC ducts Initially reported on B31025 Due to misclassification, supports specified w/less than full safety-related (A program MEYERB.B L Bechtel Corp 83/10/27 DEYOUNG.R Director's Office, Office of Inspection and Enforcement 3pp 20951 040 24X Fiche 30-000.B3/10/27.8310310074

DOCKET 6TN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

O Adjudicatory correspondence

- 8310110068 Motion to terminate appellate jurisdiction retained in ALAB-482 & ALAB-540 re environ effects of radon releases from U mining & milling for Puel Issue now moot Certificate of Svc encl
 CARRIA V Buke Power Co CARRIA V Debevoise & Liberman 83/10/04 Atomic Safety and Licensing Appeal Panel 25pp 20668.212 24X Fiche 50-491.83/10/04.8310110068
- 8310130197 Memorandum & Order ALAB-745, granting util request to terminate appellate jurisdiction retained in ALAB-482 relissue of environ effects associated w/radon gas release Plants canceled & CPs surrendered SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 83/10/12 Duke Power Co 3pp 20725 006 24X Fiche 50-491.83/10/12, 8310130197

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

O Adjudicatory correspondence

- 8310110068 Motion to terminate appellate jurisdiction retained in ALAB-482 & ALAB-540 re environ effects of radon releases from U mining & milling for fuel Issue now moot Certificate of Svc encl
 CARR.A.V Buke Power Co CARR.A V Debevoise & Liberman.
 83/10/04 Atomic Safety and Licensing Appeal Panel 26pp 20688 212 24X Fiche 50-471.83/10/04.8310110068
- B310130197 Memorandum & Order ALAB-745, granting util request to terminate appellate jurisdiction retained in ALAB-4B2 re issue of environ effects associated w/radon gas release Plants canceled & CPs surrendered BHOEMANER.C J Atomic Bafety and Licensing Appeal Panel B3/10/12 Dute Power Co 3pp 20725 006 24X Fiche 50-491, B3/10/12, B310130197

DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

O Adjudicatory correspondence

- 8310110048 Motion to terminate appellate jurisdiction retained in ALAB-482 & ALAB-540 re environ effects of radon releases from U mining & milling for fuel, Issue now moot Certificate of Svc enci
 GARR.A.V Duke Power Co CARR.A V, Debevoise & Liberman.
 83/10/04 Atomic Safety and Licensing Appeal Panel 25pp
 20668 212 24X Fiche 50-491.83/10/04,8310110068
- 8310130197 Memorandum & Order ALAB-745, granting util request to terminate appellate jurisdiction retained in ALAB-482 reissue of environ effects associated wiradon gas release. Plants canceled & CPs surrendered 8HOEMANER.C J. Atomic Safety and Licensing Appeal Panel 83/10/12 Dute Power Co 3pp 20725 006 24X Fiche: 50-471.83/10/12, 8310130197

- DOCKET 50-494 MONTAGUE NUCLEAR POWER STATION, UNIT 1
- Q Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-41, "Alleged Use of Stand-Ins for Welder Qualification Tests" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Int. 117pp 20754 022 24X Fiche 50-000,03/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-43, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Evo list onel JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/24,830830830340
- 8308300349 lE Info Notice 83-64, "Load Shielding Attached to Bafety-Related Sys W/o 10CFR30 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000.83/09/29,8308300349
- B308300378 IE Info Notice B3-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 74pp 20827 213 24X Fiche 50-000, 83/10/07, 8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Concolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- B308300759 IE Info Notice 83-67, "Emergency Use Respirator Math Defett Causes Production of Noxious Gases " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000,82/10/11,8308300759
- 8308300761 IE Info Notice B3-6B, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300765
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

 G Inspection reports, IE Bulletins & carrespondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Evo list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Int 117pp 20754 022 24X Fiche 50-000,83/09/26,8308J00340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" 8vc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/86 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000, 83/09/26, 8308380342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list oncl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778:001 24X Fiche 50-000,83/09/26.8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to 8afety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp. 20716 324, 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Sv. list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07, Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 80-000,83/10/07.8308300378

- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " Svc list encl JDRDAN.E D Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24% Fiche 50-000,83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/10/11 Consolidated Edison Co of New York, Inc 11/pp 21043 075 24X Fishe 50-000.83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc 1:st encl
 URDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/10/11 Consolidated Edison Co of New York: Inc 120pp 20827 129 24% Fiche 50-000.83/10/11.8308300761

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8310070184 Notification of contract execution "Review of Tornado Missile PRA-South Texas Project" awarded to NBS W1001NB.E Technical Assistance Contracts Branch FIN 8-865/83/09/29 MATISON,R J Division of Systems Integration (post 811005). SINOH,B K NRC No Detailed Affiliation Given Ip 20680 248 24% Fiche 50-498,83/09/29,8310070184
- --8310070168 Ltr Contract NRC-03-83-114 "Review of Tornado Missile PRA-South Texas Project." awarded to NBS MORTON.K V Division of Contracts Fin D-8657 83/09/21 SIMIU.E Commerce. Dept of, National Bureau of Standards 7pp 20480 249 24K Fiche 30-498.83/09/29.8310070184

O Adjudicatory correspondence

- 8310110220 Motion for order limiting scape of Citizens Concerned About Nuclear Power participation in Phase II of OL proceeding Request based on intervenor failure to meet obligations Certificate of Svc encl
 QUTTERMAN.A H Joint Applicants-South Texas Project GUTTLRMAN,A H Lowenstein, Newman, Reis, Axclvad & Foll 83/10/06 Atomic Safety and Licensing Board Panel 17pp 20666 051 24X Fiche 50-478,83/10/06.8310110220
- 8310170556 Notifies of Commissioner Palladina 831102 site visit One representative of each party may accompany Commissioner on visit Parties must make arrangements w/util Svc list encl REAMER, C W Commissioners 83/10/14 BECHHOEFER, C, LAMB, J C, HILL, E E Atomic Safety and Licensing Board Panel 2pp 20780 345 24X Fiche 50-498,83/10/14,8310170556
- 8310250545 Forwards response to State of TX interrogatories on Contention 4 & Guadrex & documents in response to Guadrex Interrogatories 7, 11, 18, 20, 30, 31, 36, 42, 45, 46, 47, 49 & 50 Documents re Interrogatories 23, 33 & 34 forthcoming PERLIS.R 0 Hearing Branch 3 83/10/18 BERWICK, B. E Texas, State of 1p 20901 062 24X Fiche 50-498, 83/10/18, 8310250545
- --83i0250551 Response to first set of interrogatories & request for production of documents on Quadrex

 * Office of the Executive Legal Director 83/10/18 Texas,
 State of 35pp 20701 063 24X Fichs 80-498,83/10/18,8310250545
- ---8310250558 Response to first set of interrogatories & request for production of documents on Contention 4 re wind speeds # Office of the Executive Legal Director # 83/10/18 Texas, State of 46pp 20901 098 24X Fithe 50-498,83/10/18,8310250545
- 8310260249 Informs of extension for reply to applicant 831006 motion for sanctions Reply date extended to 831031 SINKIN.L Citizens Concerned About Nuclear Power, Inc. SINKIN,L SINKIN,L A 83/10/19 BECHHOEFER.C , LAMB,J C , HILL,E E. Atomic Safety and Licensing Board Panel 1p 20912 123 24X Fiche 30-498,83/10/19.8310260249
- 8310260269 Motion for new contention re instability of soil beneath facility Recently submitted deficiency rept provide; sufficient avidence to warrant inquiry. Certificate of Svc encl ginkIN.L Citizens Concerned About Nuclear Power, Inc SINKIN,L Binkin, L A 83/10/20 Atomic Safety and Licensing Board Panel 17pp 20911 311 24X Fiche 50-498,83/10/20.8310260269

H General correspondence

- 8310130142 Responds to 830617 ltr re constituents concerns re environ impact of const & operation of 400 kV dc power line from Walker to Matagorda County, TX No NRC approval required Texas Public Util Commission to hold hearings on application DIRCKS,W J Office of the Executive Director for Operations 83/09/20 TOMER,J Senate 10pp 20777 082 24X Fiche 50-498,83/09/20,8310130142
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310030167 Forwards Amend 33 to F9AR Amend revises responses to NUREO-0737.II K Items & NRC questions & updates Sections 2 5 1,3 1-3,3 1-12 & 5 2 Affidavit encl oldBER6.JH Houston Lighting & Power Co 83/09/27. DENION,H Office of Nuclear Reactor Regulation, Director 5pp 20593 323 24X Fiche 50-498.83/09/27.8310030167
- --8310030148 Amend 33 to FSAR, revising responses to NUREQ-0737.11 K item & NRC questions & updating Sections 2 5 1.3 1-3.3 11-12 & 5 2 * Houston Lighting & Power Co 83/09/27 377pp 20593 328 24X Fiche 50-498,83/09/27,8310030167
- @ Inspection reports, IE Bulleting & correspondence
- B310140030 F01A request for IE Insp Rept 79-19,associated notice of proposed imposition of civil penalties, notice of violation & order to show cause HAMLIN.J B Show, Pittman, Potts & Trowbridge 83/05/31. Office of Administration &pp 20794 110 24X Fiche 50-498.83/05/31.
- 8310130176 Forwards IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-29 No noncompliance noted MADSEN,0 L Region 4. Office of Director. 83/08/22 OPREA, G W. Houston Lighting & Power Co. 2pp. 20724.315 24X Fiche 50-498
- --8310130190 IE Insp Repts 50-498/63-14 & 50-499/83-14 on 830725-29 No noncompliance noted Major areas inspected radiographs, weld-related nonconformance repts, control of whid filler matls, Ebasco audits & structural steel matl control CROBSMAN, M A . HALL, R E Region 4, Diffice of Director 83/08/17.

 8pp 20724 317 24% Fiche 50-498,83/08/22,8310130176
- 8310140031 Partial response to FOIA request for documents re IE Insp. Rept 77-17 & associated notice of proposed imposition of civil penalties, notice of viplation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/08/23 HAMLIN, J B Shaw, Pittman, Potts & Troubridge ip 20794 114 24X Fiche 50-498, 83/08/23, 8310140031
- --B00B270592 Forwards Region 5 rept of investigation re alleged falsification of GA records by Brown & Root inspector W/o enc!
 WARN W J Office of Inspection & Enforcement, Office of the Director B0/0B/01 FORTUNA.R Office of Inspector & Auditor.
 1p 20795 186 24X Fiche 50~498,83/08/23,8310140031
- --8310140032 "Bouth Texas Project History "
 # NRC No Detailed Affiliation Diven 83/05/31 4pp 20794 117 24X Fiche 50-498.83/08/23.8310140031.
- --8310140037 Notification of 800819 meeting w/util & Brown & Root in B; City, TX to clarify util response to 800430 show cause order. * NRC - No Detailed Affiliation Given B3/10/13. NRC - No Detailed Affiliation Given. 4pp 20794 129 24X Fiche 50-498.83/08/23.8310140031
- --B310140041 Requests formal public hearing, w/full disclosure, re NRC 771110 investigation of Bouth Teras Project Affiliation Unknown B0/02/07 NRC No Detailed Affiliation Given 1p. 20794 103 24X Fichs S0-498,83/08/23,8310140031.
- --8310140044 NRC proposal to fine Texas Utils for alleged noncomplianc w/NRC requirements re Brown & Root GA program & violation of piping weld tests
 * NRC No Detailed Affiliation Given 83/10/13 2pp.
 20794 134 24X Fiche 50-498/83/08/23/8310140031
- --8310140047 Enforcement history.South Texas Project, Oct 1975 Mar 19 * NRC - No Detailed Affiliation Given 83/10/13, 3pp. 20794:136 24% Fiche 50-498,83/08/23,8310140031

- --8310140080 Discusses notice of violation issued as result of 791110-820207 insps Noncompliance noted QC insp by Brown & Root not sufficiently independent Marked-up copy * NRC - No Detailed Affiliation Given B3/05/31 NRC - No Detailed Affiliation Given 35pp 20794 139 P4X Fiche 50-498 83/08/23 8310140031
- --8310140092 Forwards draft investigation rept & proposed enforcement action for comment Commission briefing on investigation & enforcement planned for who f 800414 Draft rept also sent to pertinent NRC personnel SHEWMAKER, R E Director's Office, Office of Inspection and Enforcement 80/04/01 TriORNBURG, H D Director's Office of Inspection and Enforcement 140pp 20794 175 24X Fiche 50-498,83/08/23,8310140031
- --8310140062 Requisition for payment to Continental Airlines for PBX svi of pkg to Houston.TX * NRC - No Detailed Affiliation Given 80/05/01 2pp 20795 071 24X Fiche 50-498.83/08/23.8310140031
- --8310140088 Advises that, due to seriousness of violations by Brown & Root & util at South Texas Project, Full-scale public hearing in Matagorda County, TX mandatory VAN MOY. G Affiliation Unknown BO/05/20 STELLD, V Director's Office, Office of Inspection and Enforcement ip 20795 079 24X Fiche 50-498, 82/08/23, 8310140031
- --B310140095 Bubmits draft generic ltr for use w/incoming correspondence as result of 800430 IE enforcement pkg
 STELLD.V Director's Office, Office of Inspection and Enforcement
 83/10/13 Affiliation Unknown 3pp 20795 167 24X
 Fiche 50-498.83/08/23.8310140031
- 8310040536 Forwards IE Insp Repts 50-498/83-12 & 50-497/83-12 on 830711-21 No noncompliance noted MADSEN. G L Region 4. Office of Director 83/08/29 OPREA. 6 W Houston Lighting & Power Co 2pp 20623 254 24X Fiche 50-498,83/08/29,8310040536
- --8310040546 IE Insp Repts 50-498/83-12 & 50-499/83-12 on 830711-21 No noncompliance noted Major areas inspected licensee mgt of GA activities & GA insp of performance OBERG-C R . GROSSMAN, M A Region 4. Office of Director 83/08/12 12pp 20423 256 24X Fiche 50-498,83/08/29,8310040536
- 8310030385 Forwards IE Insp Repts 90-498/83-15 & 50-499/83-15 on 830701-0814 No noncompliance noted MADBEN.9 L Region 4. Diffice of Director 83/09/07 QPREA.G W Houston Lighting & Power Co 2pp 20572 143 24X Fichs 50-498,83/09/07.8310030385
- --B310030372 IE Insp Repts 50-498/B3-15 & 50-499/B3-15 on B30701-0B14 No noncompliance noted Major areas inspected previous insp findings, storage & maint of equipment nonconformance repts, structural concrete & matl control & identification HILL-W M , CROSSMAN.W A Region 4, Dffice of Director B3/09/02 Bpp 20592 145 24X Fiche 50-498,63/09/07.8310030365
- 8310130221 Forwards 1E Insp Repts 50-498/83-17 & 50-499/83-17 on 930815-17 & notice of violation MADSEN.G L Region 4. Office of Director 83/09/07 OPREA. 0 & Houston Lighting & Power Co 2pp 20724 096 24X Fichs 50-498,83/09/07.8310130221
- --8310130227 Notice of Violation from insp on 830815-17
 # Region 4, Office of Director 83/09/07 2pp 20724 098 24X
 Ficher 50-498,83/09/07,8310130221
- --8310130230 IE Insp Repts 50-498/83-17 & 50-499/83-17 on 830815-17 Noncompliance noted failure to maintain identification & control of mats TOMLINGON, D.P., CROSSMAN, W.A., HALL, R.E., Region 4, Office of Director 83/09/02 5pp 20724 100, 24X Fiche 50-498/83/09/07, 8310130221
 - :10180412 Forwards IE Insp Rapts 50-498/83-16 & 50-499/83-16 on 830906-08 No noncompliance noted MADBEN. G.L. Region 4. Office of Director 83/09/22 OFREA. G W Houston Lighting & Power Co. 2pp 20803 165 24X Fiche. 50-498.83/09/22.8310180412
 - 33(0180414 IE Insp Repts 50-498/83-16 & 50-497/83-16 on 830906-08. No noncompliance noted Major areas inspected const activities, including licenser actions on 10CFR50 55(e) rept of breakfawn in GA program for procurement cycle BOARDMAN, J R. CROSSHAN, W A Region 4, Office of Director 83/09/21 Opp 20803 167 24% Fiche 50-498,83/09/22,8310180412

- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Weldor Qualification Tests " Svc list encl JCRDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24% Fiche 50-000.83/09/26.8308300340
- B30B300342 IC Info Notice B3-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co. of New York Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26,8308380048
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc Jist encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83709725. Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83709726,8308300345
- B30B300349 IE Info Notice B3-64, "Lead Shielding Attached to Safety-Related Bys W/o 10CFR50 59 Evaluation" Svc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fishe 50-000, B3/09/29, B300G00347
- B30B30037B IE Info Notice B3-65. "Burveillance of Flow in RTD Bupdss Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 830B300370
- B30B300752 IE Info Notice B3-66. "Fatality at Argentino Critica)
 Facility " Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/10/07 Consolidated Edison Co of New
 York, Inc 79pp 20882 026 R4X Fiche 50-000, B3/10/07. B30B300752
- B30B300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630)03) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 675 24X Fiche 50-000,83/10/11.8308300759
- B308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103)
 B3710/11 Consolidated Edison Co of New York, Inc. 120pp. 20827 129
 24X Fiche 50-000, B3/10/11, B308300761
- S Reportable occurrences, LERs & related correspondence
- 8310040410 Final deficiency rept re auxiliary feedwater sys containment isolation valves Initially reported on 830822 Sys design modified to require performance sys function of safety-grad; active valves Also reported per Part 21 OPREA.G W Houston Lighting & Power Co 83/09/21 COLLINS, J T Region 4, Office of Director 5pp 20617 035 24X Fichs 30-498,83/09/21,8310040410
- 8310040289 First interim deficiency rept re corrosion on reactor containment bidg post-tensioning sys tendons Initially reported on 830826 Evaluation underway to determine if condition impairs tendon strongth Next rept by 840227 OPREA.0 W Houston Lighting & Power Co 83/09/22 CDLLINS, J. 1 Region 4, Office of Director 3pp 20614 213 24% Fiche 50-498.93/09/22,8310040289
- 8310130187 Revised final deficiency rept re essential cooling water intake structure gantry crane Initially reported on 790516 Crane design revised for severe & extreme environ loadings to retain structural integrity OPREA.0 W Houston Lighting & Power Co 83/09/28 COLLING.J T Region 4. Office of Director 3pp 20724 327 24X Fiche 50-498.83/09/28.8310130187
- 8310130265 First interim deficiency rept re design basis flood calculations not considering erosion effects of postulated embankment breach Initially reported on 830830 Next rept expected by 840120 OPREA:0 W Houston Lighting & Power Co 83/09/28 CULLINB, J 1 Region 4. Office of Director App 20/23 217 247 Fiche 50-498.83/09/28.8310130265
- 8310130319 Supplemental final deficiency rept re Westinghouse supplied pressure & level transmitters Transmitters will be provided for applications described in 830804 ltr.per Westinghouse Group 8 & WCAP-8587 generic qualifications OPREA:0 W Houston Lighting & Power Co 83/09/28 COLLINS.J 7 Region 4, Office of Director 2pp 20719 361 24X Fiche 50-498.83/09/28.8310130319

- 6310180290 Seventh interim deficiency rept re nonconformances of welds in vendor-fabricated Category I structural steel Initially reported on B10108 Review continuing Final rept will be submitted by 83:230

 ORREALO W Houston Lighting & Power Co 83/09/30 COLLINS. J T Region 4, Office of Director 2pp 20006 289 24x

 Fiche 50-498,83/09/30,8310180290
- 8310210193 Final deficiency rept re computer program verification Initially reported on 810508 Verification program for review & acceptance of Brown & Root computer calculations implemented OPREA, 0 W Houston Lighting & Power Co. 83/10/14 COLLING, J. Region 4, Office of Director 8pp. 20856 071 24x Fiche 50-498.83/10/14.8310210193

V Operator Examinations

- 8310140110 Revises 830228 response to Generic Ltr 83-01 "Operator Licensing Exam Site Visit" Applications will be submitted in Feb 1984 for 10 persons scheduled for Sept 1984 instructor certification exam GGLDBERG, J H Houston Lighting & Pawer Co 83/09/28 EISENHUF, D (*) Division of Licensing 2pp 20766 108 24X Fiche 50-498, 83/09/28, 8310140110
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8310070184 Notification of contract execution "Review of Tornodo Missils PRA-South Texas Project" awarded to NBS HTGGINS.E Technical Assistance Contracts Branch FIN B-8657 83/09/29 MATISON, R J Division of Systems Integration (pust 811005) SINOH, B K NRC No Detailed Affiliation Given 1p 20680 248 24% Fichs 50-498,83/09/29,8310070184
- --431007018B Ltr Contract NRC-03-83-114 "Review of Tornado Missile PHA-South Texas Project." awarded to NBS MORTON.K V Division of Contracts FIN 8-8657 83/09/21 SIMBU.E Commerce. Dept of, National Dureau of Standards 7pp 20680 249 24X Fiche 50-498,83/09/29,8310070184

G Adjudicatory correspondence

- 8310110220 Motion for order limiting scope of Citizens Concerned About Nuclear Power participation in Phase II of OL proceeding Request based on intervenor Failure to meet obligations Centificate of Svc encl
 GUTTERMAN, A H Joint Applicants-South Texas Project GUTTERMAN, A H Lowenstein, Nowman, Reis. Azelrad & Toll 83/10/06 Atomic Safety and Licensing Board Famel 17pp 20666 091 24X
 Fiche 50-498,83/10/06.8310110220
- 8310170556 Notifies of Commissioner Palladino 831102 site visit Dne representative of each party may accompany Commissioner on visit Parties must make arrangements w/util 8vc list encl REAMER, C W Commissioners 83/10/14 BECHHOEFER, C , LAMB, J C , HILL, E E Atomic 9afety and Licensing Board Panel 2pp 20780 345 24% Fiche 50-498,83/10/14,8310170556
- 8310250545 Forwards response to State of TX interrogatories on Contention 4 & Guadrex & documents in response to Guadrex Interrogatories 7,11,18,20,30,31,36,42,45,46,47,49 & 50 Documents re Interrogatories 23,33 & 34 forthcoming PERLISIR G Hearing Branch 3 83/10/18 BERMICK, B F Texas, State of 1p 20901 062 24X Fiche 50~498,83/10/18,8310250545
- ~-8310250551 Response to first set of interrogatories & request for production of documents on Quadrex * Office of the Executive Legal Director 83/10/18 Texas, State of 35pp 20901 063 24X Fichs 50-498,83/10/18,8310250540
- --B310250558 Response to first set of interrogatories & request for production of documents on Contention A re wind speeds

 * Office of the Executive Legal Director B3/10/18 Toxas.

 State of 46pp 20901 098 24X Fiche 50-498,83/10/18,8310250545
- 8310260249 Informs of extension for reply to applicant 831006 motion for sanctions Reply date extended to 831031
 SINKIN,L Citizens Concerned About Nuclear Power, Inc. SINKIN,L Sinkin, L. A. 83/10/19 BECHHOEFER, C., LAMB, J. C., HILL, E. E. Atomic Safety and Licensing Board Panel 1p. 20912 123 24X
 Fiche 50-498,83/10/19.8310260249

8310250269 Motion for new contention re instability of soil beneath facility Recently submitted deficiency rept provides sufficient evidence to warrant inquiry Certificate of Svc encl
SINKIN.L Citizens Concerned About Nuclear Power, Inc BINKIN.L Sinkin. L A 83/10/20 Atomic Safety and Licensing Moard Panel 17pp 20911 311 24X Fiche 50-498.83/10/20.8310260269

H General correspondence

- B310130142 Responds to B30617 ltr re constituents concerns re environ impact of const & operation of 400 kV dc power line from Walker to Matagorda County,TX No NRC approval required Texas Public Util Commission to hold hearings on application DIRCKS.W J Office of the Executive Director for Operations B3/09/20 TOWER,J Senate 10pp 20777 052 24X Fiche 50-478.B3/09/20,B310130142
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8310030167 Forwards Amend 33 to FSAR Amend revises responses to NUREG-0737.II X items & NRC questions & updates Sections 2 5 1.3 1-3.3 11-12 & 5 2 Affidavit encl.

 GDLDBERG, J H Houston Lighting & Fower Co 83/09/27. DENTON.H Office of Nuclear Reactor Regulation. Director 5pp 20593 323 24X Fiche 50-498,83/09/27,8310030167
- --8310030168 Amend 33 to FBAR, revising responses to NUREQ-0737, IJ K its & NRC questions & updating Sections 2 5 1,3 1-3,3 11-12 & 5 2 * Houston Lighting & Pawer Co 83/09/27 377pp 20593 328 24 Fiche 50-498.83/09/27,8310030167
- Q Inspection reports, IE Bulletins & correspondence
- B310140030 FOIA request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause HAMLIN. J B Shaw. Pittman. Potts & Trowbridge 83/05/31. Office of Administration App 20794 110 24% Fiche 50-498, 83/05/31, B310140030
- 8310130176 Forwards IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-27 No noncompliance noted MADDEN.G L. Region 4. Office of Director 83/08/22 OPREA.O W Houston Lighting & Power Co 2pp 20724 315 24X Fiche 50-498.83/08/22.8310130174
- --8310130190 IE Insp Repts 50-498/83-14 & 50-499/83-14 on 830725-29 No noncompliance noted Major areas inspected radiographs, weld-related nonconformance repts, control of weld filler matls, Ebasco audits & structural steel matl control CROSSMAN, H A. HALL, R E. Region 4, Office of Director 83/08/17 8pp 20724 317 24X Fiche 80-498,83/08/22,8310130174
- 8310140031 Partial response to FOIA request for documents re IE Insp Rept 79-19 & associated notice of proposed inposition of civil penalties, notice of violation & order to show cause Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records. 83/08/23 HAMLIN, J B Shaw, Pittman, Potts & Troubridge Ip 20794.114 24X Fiche 50-498.83/08/23.8310140031
- --B00B270592 Forwards Region 5 rept of investigation re alleged falsification of GA records by Brown & Root inspector. W/o encl WARD,W J Office of Inspection & Enforcement, Office of the Director B0/0B/01 FORTUNA.R Office of Inspector & Auditor ip 20795 186 24X Fiche 50-498,83/0B/23,8310140031
- --8310140032 "South Texas Project History " # NRC - No Detailed Affiliation Given 83/05/31 App 20794 117 24X Fiche 50-498,83/08/23,8310140031.
- ~~8310140037 Notification of 800819 meeting w/util & Brown & Root in B City,TX to clarify util response to 800430 show cause order. * NRC - No Detailed Affiliation Given 83/10/13 NRC - No Detailed Affiliation Given 4pp 20794 129 24X Fiche: 50-498,83/08/23,83101400J1
- --B310140041 Requests formal public hearing, w/full disclosure.re NRC 791110 investigation of South Texas Project Affiliation Unknown B0/02/07 NRC No Detailed Affiliation Olven ip 20794 133 24X Fiche 50-498/83/08/23/8310140031.
- --8310140044 NRC proposal to fine Taxas Utils for alleged noncompliant w/NRC requirements ro Brown & Root GA program & violation of piping weld tests
 * NRC No Detailed Affiliation Given 83/10/13 2pp
 20794 134 24X Fiche 50-498,83/08/23.8310140031

- --8310140047 Enforcement history, South Texas Project, Oct 1976 Mar i/U0 * NRC - No Detailed Affiliation Given 83/10/13 Opp 20794 136 24% Fiche 50-498, 83/08/23, 8310140031
- --8310140050 Discusses notice of violation issued as result of 791110 820207 insps Moncompliance noted QC insp by Brown & Root not sufficiently independent Marked-up copy * NRC No Detailed Affiliation Given 83/05/31 NRC No Detailed Affiliation Given 35pg 20794 139 24X Fichs 30-498.83/08/23,8310140031
- ~-8310140082 Forwards draft investigation rept & proposed enforcement action for comment Commission briefing on investigation & enforcement planned for wk of 800414 Draft rept also sent to pertinent NRC personnel SHEWMAKER, RE Director's Office. Office of Inspection and Enforcement 80/04/01 THORNBURG, H D Director's Office, of Inspection and Enforcement 140pp 20794 175 24% Fichs 30-498,83/08/23,8310140031
- --8310140062 Requisition for payment to Continental Airlines for PBX hyc of pkg to Houston.TX * NRC - No Detailed Affiliation Given 80/05/01 2pp. 20795 071 24X Fiche 50-476.83/08/23.8310140031
- --8310140088 Advises that due to seriousness of violations by Brown & Root & util at South Texas Project, full-scale public hearing in Matagorda County, TX mandatory VAN HDY, 0 Affiliation Unknown B0/05/20 STELLO, V Director's Office, Office of Inspection and Enforcement Jp 20795 079 24% Fiche 30-498,83/08/23,8310140031
- --8310140095 Bubmits draft generic ltr for use w/incoming correspondence as result of 800430 IE enforcement pkg BTELLO.V. Director's Office. Office of Inspection and Enforcement 83/10/13 Affiliation Unknown Spp 20795 167 24X fiche 30-498,83/08/23,8310140031
- 8310040536 Forwards IE Insp Repts 30-498/83-12 & 30-499/83-12 on B30711-21 No noncompliance noted MADSEN 0 L Region 4. Office of Director. B3/08/29 OPREA.0 W Houston Lighting & Power Co. 2pp 20423 254 24X Fiche 50-498.83/08/29.8310040536
- --8310040544 IE Insp Repts 50-498/83-12 & 50-499/83-12 on 830711-21 No noncompliance noted Major areas inspected licensee mgt of GA activities & GA insp of performance OBERG.C R. CROBSMAN,W A Region 4. Office of Director 83/08/12 12pp. 20623 254 24X Fiche 50-498,83/08/29,8310040536
- 8310030385 Forwards IE Insp Repts 50-498/83-15 & 50-499/83-15 on 830701-0814 No noncompliance noted MAD8EN 9 L Region 4. Diffice of Director 83/09/07 DPREA, 0 W Houston Lighting & Pawer Co. 2pp 20592.143 24X Fiche 50-498,83/09/07.8310030385
- --8310030392 IE Insp Repts 50-498/83-15 & 50-499/83-15 on 830701-0814 No noncompliance noted Major areas inspected previous filter inspected previous filt
- 310130221 Forwards IE Insp Repts 50-498/83-17 & 50-499/83-17 on 830815-17 & notice of violation MADBEN. 9. L. Region 4. Office of Director 83/09/07. OPREA, 6 W Houston Lighting & Power Co 2pp. 20724 096 24X Fiche 50-498, 83/09/07, 8310130221
- ~8310130227 Notice of violation from insp on 830815-17 * Region 4, Office of Director 83/09/07 2pp 20724 098 24% Fiche-50-498,83/09/07,8310130221.
- 83i0130230 IE Inap Repts 50-498/83-17 & 50-499/83-17 on 830815-17 Noncompliance noted failure to maintain identification & control of matls TOMLINBON.D P., CROSSMAN.W A., HALL.R E Region 4, Diffice of Director. 83/09/02 5pp 20724.100. 24X Fiche 50-498.83/09/07, 83i0130221.
-)180412 Forwards IE Insp Repts 50-498/83-16 & 50-499/83-16 on 30906-08 No noncompliance noted (DBEN.9 L. Region 4. Office of Director 83/09/22 DPREA.G W louston Lighting & Power Co 2pp 20803 165 24% iche: 50-478,83/09/22,8310180412
- | 10180414 IE Insp Repts 50-498/83-16 & 50-499/83-16 on 830906-08 No noncompliance noted Major areas inspected const activities, including licensee actions on 100FR80 85(e) rept of freekdown in GA program for procurement cycle | 10ARDMAN.J R. (ROBSMAN.J A. Region 4, Office of Director 13/09/21 App. 20803 167. 24x Fiche 50-498,83/09/22,8310180412

- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Wilder Gualification Tests " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 11/pp 20754 022 24X Fiche 50-000.83/09/26.8308.00340
- 8308300342 IE Info Natice 83-62. "Failure of Redundant loxic Gas Detectors Positianed at Control Roam Ventilation Air Intakes " Byo list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 114pp 20777 210 24X Fiche 50-000,83/09/26,8308/00347
- 8308300349 IE Info Notice 83-63 "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24% Fiche 50-000,83/09/26,8308300345
- 830B300349 IE Info Notice 83-64. "Lead Shielding Attacked to Safety-Related Sys W/o 10CFR50 59 Evaluation "Svc list encl JORDAN,E L Divísion of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Lapps Used in Westinghouse Plants" Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Ne. York, Inc 75pp 20827 213 24X Fiche 50-000.83/10/07.83083003/8
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 77pp 20882 026 24X Fiche 50-000.83/10/07.8308300/52
- B30B300759 IE Info Notice B3-47. "Emergency Use Respirator Matl Defect Causes Production of Noxious Qases "Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Fiche 50-000, B3/10/11, B30B300759
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300/61
- S Reportable occurrences, LERs & related correspondence
- 8310040410 Final deficiency rept re auxiliary feedwater sys containment isolation valves Initially reported on 830822 Bys design modified to require performance sys function of safety-grade active valves Also reported por Part 21 OPREA. G W Houston Lighting & Power Co 83/09/21 COLLING, J 1 Region 4. Office of Director 5pp 20619 035 24X Fiche 50-498,83/09/21,8310040410
- B3100402B9 First interim deficiency rept re corrosion on reactor containment bldg post-tensioning sys tendons Initially reported on B30826 Evaluation underway to determine if condition impairs tendon strength Next rapt by B40229 OPREA: G W Houston Lighting & Power Co B3/09/22 COLLINS, J T Region 4. Office of Director 3pp 20614 213 24X Fiche 50-498,83/09/22,8310040289
- 8310130187 Revised final deficiency rept re essential cooling water intake structure gantry crane Initially reported on 790516 Crane design revised for severe & extreme environ loadings to retain structural integrity OPREA GW Houston Lighting & Power Co 83/09/28 COLLINS, J T Region 4, Office of Director 3pp. 20724 327 24X Fiche \$0-478,83/09/28,8310130187
- 8310130265 First interim deficiency rept re design basis flood calculations not considering erosion effects of postelated embankment breach Initially reported on 830830 Next rept expected by 840120 OPREA: G. W. Houston Lighting & Power Co. 83/09/28 COLLINB, J.T. Region 4. Defice of Director App. 20723 217 24X Fiche 50-478.83/09/28.8310130265
- B3i0130319 Supplemental final deficiency rept re Westinghouse supplied pressure & level transmitters Transmitters will be grovided for applications described in B30804 ltr.per Westinghouse Group B & WCAP-BB87 generic qualifications.

 OPREA: O W Houston Lighting & Power Co 83/09/28 COLLINS, J T Region 4, Dffice of Director 2pp 20/19 361, 24X Fiche 50-498,83/09/28,8310130319

- 8310180290 Seventh interim deficiency rept re nonconformances of welds in vendor-fabricated Category I structural steel Initially reported on 810108 Review continuing Final rept will be submitted by 831230 OPREA: G W Houston Lighting & Power Co. 83/09/30 COLLING. J Region 4. Office of Director 2pp 20606 289 24X Fiche 50-498.83/09/30.8310180290
- 8310210193 Final deficiency rept re computer program verification Initially reported on 810508 Verification program for review & acceptance of Brown & Root computer calculations implemented OPREAGO W Houston Lighting & Power Co 83/10/14 COLLING, J 7
- Implemented
 OPREA:G W Houston Lighting & Pawer Co 83/10/14 COLLINS, J T
 Region 4, Office of Director Bpp 20856 071 24X
 Fiche 50-498,83/10/14.8310210193

V Operator Examinations

83i0140110 Revises 830228 response to Generic Ltr 83-01 "Operator Licensing Exam Site Visit" Applications will be submitted in Feb 1984 for 10 persons scheduled for Sept 1984 instructor certification exam 60LDERRG. J H Houston Lighting & Power Co 83/09/28 EISENHUT, D & Division of Licensing 2pp 20746 108 24% Fiche 50-498,83/09/28,8310140110

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT. UNIT 3

A Application/construction stage documents & correspondence

- 8310140176 Forwards "Mgt Plan for Extended Const Delay of WNP-3 (Leve) II)." per GC Sorensen 830712 ltr Util executive board expected to approve budget rather than approve plan details SORENSEN.G C Washington Public Power Supply System 83/09/15 KNIGHTON.G W Licensing Branch 3 ip 20764 324 24X Fiche 50-508.83/09/15.8310140176
- --8310140182 "Mgt Plan for Extended Const Delay of WNP-3 (Level]]) "
 * Washington Public Power Supply System 83/08/04 37pp
 20764 325 24X Fiche 50-508.83/09/15,8310140174
- 8310030337 Responds to 830807 ltr re concerns to prevent further erosion impacts in vicinity of Ranney intake structures & Elizabeth Creek during const delay Dressing & seeding of Ranney Well area near Elizabeth Creek completed SURENSEN, G C Washington Public Power Supply System 83/09/28 KNIGHTON, O W Licensing Branch 3 2pp 20590 305 24X Fiche 50-508, 83/09/28, 8310030333
- 8310040344 Concludes that proposed project will have no effect on known cultural resources included in or eligible for inclusion in Natl Register of Historic Places
 WHITLAM,R Q Washington, State of 83/09/29 KNIGHTON,G W
 Licensing Branch 3 ip 20617 279 24X Fiche 50-508,83/09/24,
 8310040344
- 8310190152 Forwards Amend 2 & suppl to application for DL clarifying & explicitly stating intent that once issued. DL is to run for 40 yrs commencing w/date of issuance & provides updated info re const & status & membership of Boards of Directors BORENSEN. O C Washington Public Fower Supply System 83/10/11 KNIGHTON, C Licensing Branch 3 3pp 20820 124 24X Fiche, 50-508, 83/10/11,8310190152
- --B310190154 Amend 2 & suppleto application for OL clarifying & explicitly stating intent that license run for 40 yrs commencing w/date of issuance Updated const status & membership of Boards of Directors also provided SORENSUN, C C Washington Fubbic Power Supply System, 83/10/11 36pp 20820 127 24X Fiche 50-508,83/10/11.8310190152
- 8310310149 Forwards draft "Ecological Monitoring Preoperational/ Operational Program" & draft "Rept on Fish Bioassays Toxicity of Copper,Zinc & Chemical Forms to Coho Salmon & Steelhead Trout in Chehalis River: MA " SURENBEN,O C Washington Public Power Supply System. 83/10/21 KNIOHTON,O W Licensing Branch 3 2pp 20950 042 P4X Fiche 50-508,83/10/21,8310310149
- --B310310151 Draft "Ecological Monitoring Preoperational/Operational Program " * Washington Public Power Supply Bystem 83/10/21 5pp 20950 044 24X Fiche 50-508,83/10/21,8310310149
- --B310310154 Draft "Rept on Fish Bioessays Toxicity of Copper, Zinc & Chemical Forms to Coho Salmon & Steelhead Trout in Chemalis River, MA "
 DAVIS, W., NORTHSTROM, T.E., JEANE, Q.S., Washington Public Power Bupply System 83/09/30 290pp 20750 049 24x
 Fiche: 50-508, 83/10/21, 8310310149

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8310310063 FOIA request for documents re const & operation of C~E plants List of info required submitted BELL, N Coallation for Safe Power 83/03/31 Office of Administration 1p 20998 173 24% Fiche 50-000,83/03/31, B310310063
- F Security, medical, emergency & fire protection plans
- 8310260189 Forwards WPPS-3/5 physical security plan, Rev 2 & WPPS-3/5 safeguards contangency plan, Rev 1 Revs withheld (ref 10CFR73 21)
 SORENSEN, 0 C Washington Public Power Supply System 83/10/17 KNIOHTON, 0 Licensing Branch 3 2pp 20912 234 24X
 Fiche 50-508, 83/10/17, 8310260189

G Adjudicatory correspondence

- 8310140066 Brief supporting util 830915 notice of appeal from ASLB 830421 & 0927 memoranda & orders admitting Coalition for Safe Power as party ASLB abused discretion by granting untimely petition Certificate of Svc encl REYNOLDS,N S Washington Public Power Supply System REYNOLDS,N S Debevoise & Liberman 83/10/12 Atomic Safety and Licensing Appeal Panel 54pp 20766 241 24X Fiche 50-508,83/10/12.
- 8310140086 Notice of appeal of ASLD 830421 & 0927 memoranda & orders admitting Coalition for Safe Power as intervenor Order of 830421 should be reversed 830927 order vacated & proceeding dismissed Certificate of Bvc enel REYNOLDS.N S Washington Public Power Bupply System. REYNOLDS.N S Debevoise & Liberman 83/10/12 3pp 20767 060 24X Fiche 50-508,83/10/12,8310140086
- 8310180333 Notice of ASLAB constitution AB Rosenthal, chairman & GJ Edles & HA Wilber, members SHOEMAKER, CJ Atomic Safety and Licensing Appeal Panel 83/10/14 p 20802 347 24% Fiche 50-508.83/10/14,8310180333
- 8310280126 Comments on impact of ALAB-743 denying untimely petition to intervene Portions of analysis directly applicable to applicant 831012 appeal of ASLB grant of untimely petition to intorvene REYNOLDS:N S Debevoise & Liberman REYNOLDS:N S Washington Public Power Supply 8ystem. B3/10/26 ROSENTHAL,A S; EDLES:O J; WILBER:H A Atomic Bafety and Licensing Appeal Panel Spp 20929 24B 24X Fiche 50-508; B3/10/26:8310280126
- 8310310175 Addresses impact of ALAB-743 on proceeding in accordance W/obligation to identify & address recent developments in law affecting pending cases REVNOLDS.N S Debevoise & Liberman REVNOLDS.N S Washington Public Power Supply System 83/10/26 ROSENTHAL, A S , WILBER, H A., EDLES, G J Atomic Bafety and Licensing Appeal Panel Spp 20757 002 24X Fiche 50-508.83/10/26.8310310175

H General correspondence

- 8310180586 FOIA request for util corporate chart in PSAR CONSTAS.J Pro-Tach Support Services.Inc 83/08/17 Office of Administration ip 20825 323 24X Fiche 50-508,83/08/17, 8310180584
- 8310180590 Responds to FDIA request for util corporate chart in PBAR Forwards chart
 FELTON.J M Division of Rules and Records 83/09/06 CONSTAS.J
 Pro-Tech Support Services, Inc. ip 20825 324 24X
 Fiche 50-508,83/09/06,8310180590
- Q Inspection reports. IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fichs 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Cas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/07/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 PAX Fiche 50-000.83/07/26,8308300342

- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Int 118pp 20778 001 24X Fiche 50-000.83/09/24.8308300345
- 8310170453 Forwards IE Insg Rept 50-508/83-06 on 830516-20 No
- noncompliance noted
 BISHOP.T W Division of Resident, Reactor Project & Engineering
 Programs 83/09/28 KOHLER.A D Washington Public Power Bupply
 System Zpp 20780 181 24% Fiche 50-508, 83/09/28, 8310170653
- --8310170663 JE Insp Rept 50-508/83-06 on 830516-20 No moncompliance sior/vocal le insp kept 30-508/83-05 on 830516-20 No monco noted Major areas inspected design control, followup on design of rigid strut bracket & review of heat treatment procedures & records for ASME III work by 251 contractor HAIST. D P, DODOS R T Region 5, Office of Director B 5pp 20780 183 24X Fiche 50-508,83/09/28,8310170653 83/09/27
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 S9 Evaluation " Svc list
- enci JORDAN, E i Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 50-000,83/09/27,8308300347
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24% Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxicus Gases " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Inc 117pp, 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 8308300761 lE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list
 - encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 930103) 93/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827-129 24X Fiche 50-000.83/10/11.8308300761

V Operator Examinations

- 8310030142 Requests schedule, by 83102B; for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs BISHOP, T W Division of Resident, Reactor Project & Engineering Programs. 83/09/26 GODFFREY, G Washington Public Power Supply System 2pp 20590 040 24% Fiche 50-397,83/09/26,8310030142
- DOCKET 50-519 WPP89 NUCLEAR PROJECT: UNIT 4
- B. Reportable occurrences, LERs & related correspondence
- 8310270206 Part 21 rept re engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on 001f States River Bend Site (Engine Serial 74039/40 DBR 4B) Instruction for cable changeout due in Nov 80YER, R E Transamerica Delaval, Inc 83/10/20 Director's Office, Office of Inspection and Enforcement ip 20924 108 24X Fiche 50-000,83/10/20,8310270206
- DOCKET 50-514 PEBBLE SPRENDS NUCLEAR PLANT, UNIT 1
 - Application/construction stage documents & correspondence
- 10180417 Requests info re NRC costs for withdrawing CP application, per 830709 ltr. Extension of due date for payment of 830713 invoice requested WITHERS, B. D. Portland General Electric Co 83/10/11. MILLER, W. D. License Fee Management Branch | p 20803 310 24% iche 50-514,83/10/11,8310180417

- G Inspection reports: IE Bulletins & correspondence
- B308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Hylder Gualification Tests " Svc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000.83/09/26,8308300040 117рр
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl JURDAN,E L Division of Cherregency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26.8308300343
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o (OCFRSO 59 Evaluation " Svc list
- B30B30037B IE Info Notice B3-65, "Burveillance of Flow in RTD Bupass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidate Edison Co of New York, Inc 7App 20827 213 24X Fiche 50-000,83/10/07,830B30037B
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical 199300752 te into Notice 83-65. "Patality at Angentine Cristal Facility " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Net York, Inc. 79pp 20882 026 24X Fichs, 50-000, 83/10/07, 8308300752
- B30B300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 P4X Fiche 50-000,83710/11,830B300757
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " 8vt list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827-129 24X Fichs 50-000,83/10/11,8308500761
- DOCKET 50-515 PEDBLE SPRINGE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8310180417 Requests info re NRC costs for withdrawing CP application, per 830909 ltr Extension of due date for payment of 830913 invoice requested invoice requested WITHERS, D.D. Portiand General Electric Co. 83/10/1 License Fee Management Branch. 1p. 20803 310 24X Fichs 50-514,83/10/11,8310180417 83/10/11 MILLER.W ()
- G Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp, 20754 022 24X Fiche 50-000,83/09/26,83080000340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Byo list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 114pp 20777, 210 24X Fiche 50-000, 83/09/26, 8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list enci JORDAN,E 1. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York, Inc., 118pp 20778,001 24X Fiche 50-000,83/09/26,8308360345

- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl
 - enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co. of New York, Inc. 115pp 20716 324 24% Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Byposs Loops Used in Westinghouse Plants " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,830830037B
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility" Svc list encl JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 11/pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JCRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 8J/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fishe 50-000,83/10/11,8308300761
- DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1
- G Adjudicatory correspondence
- 8310030390 Second request for addl extension until 840115 to answer intervenor motion for summary disposition of Contention I Fortland General Electric Co expects to decide on plant termination by end of 1983 Certificate of Svc encl THOMSEN, F. T. Puget Sound Power & Light Co THOMSEN, F. T. Perkins, Coie, Stone, Olsen & Williams 83/09/28 Atomic Safety and Licensing Board Panel 7pp 20993 040 24X Fiche 50-522,83/09/28,8310030390
- 8310140089 Memorandum & order granting util 830928 request for extension until 840115 to file response to intervenor motion for symmary disposition of Contention I MULF, J F. Atomic Safety and Licensing Board Panel 83/10/12 Puget Sound Power & Light Co 2pp 20767 021 24X Fiche 50-522,83/10/12,8310140089
- O Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000.83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Qas Detectors Positioned at Control Room Ventilation Air Intakes " 8vc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24% Fiche 50-000,83/09/26,830830030345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Eafety-Related Sys W/o 10CFR50 59 Evaluation " Syc list encl JORDAN, E Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300049
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07. Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fishe 50-000,83/10/07,8308300338
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " 8vc list encl JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24% Fiche 50-000,83/10/07,8308300752

- 8308300759 lE Info Nutice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24x Fiche 50-000,83/10/11,8308300759
- 830B300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders." By: 11st enc!

 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24x Fiche 50-000,83/10/11,830B300761
- DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

 G Adjudicatory correspondence
- 8310030390 Second request for addl extension until 840115 to answer intervenor motion for summary disposition of Contention 1 Portland General Electric Co expects to decide on plant termination by end of 1983 Certificate of Svc encl THOMSEN.F T Puget Sound Power & Light Co THOMSEN.F T Perkins, Coie, Stone, Olsen & Williams 83/09/28 Atomic Safety and Licensing Board Panel 7pp 20593 040 24X Fiche 50-522,83/09/28,83100303390
- 8310140089 Memorandum & order granting util 830928 request for extension until 840115 to file response to intervenor motion for summary disposition of Contention I MOLF, J F Atomic Safety and Licensing Board Panel 83/10/12 Puget Sound Power & Light Co 2pp 20747 021 24X Fiche 50-522.83/10/12.8310140089
- G Inspection reports: IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-41, "Alleged Use of Stand-Ins for Welder Gualification Tests " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Concolidated Edison Co of New York, Inc 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24% Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-43, "Potential Failures of Westinghouse Type SA-1 Differential Relays" Svc list encl
 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 1188p 20778 001. 24X Fisher 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 8308300378 IE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche.50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York, Inc. 79pp 20882 026 24X Fiche 50-000, 83/10/07, 8308300752
- B308300759 IE Info Notice B3-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fichs 50-000(83/10/11,8308300759.
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fichs 30-000.83/10/11.8308300761

- DOCKET STN-50-52B PALO VERDE NUCLEAR STATION, UNIT 1

 A Application/construction stage documents & correspondence
- 8310240197 Partial response to L Bernabai 830805 FOIA request for agency records relevant to &/or generated in connection w/
 NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents
 FELTON, J M Division of Rules and Records 83/09/08 GARDE, 8 Government Accountability Project App 20903 251 24X
 Fiche 50-528,83/09/08,8310240197
- --B2040B04B7 Comments on B20511 ltr re allegations of improper electrical work Inquiry being made DIRCKB,W J Office of the Executive Director for Operations B2/05/26 W00DB,T G Arizona Public Service Co lp 20904 12B 24X Fiche 50-528,B3/09/08,B310240197
- --8310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form ECKHARDI.J H NRC No Detailed Affiliation Given 82/12/17 SHACKLETON.O NRC No Detailed Affiliation Given 1p. 20703 335 24X Fiche 80-528.83/07/08.8310240197
- --8310240203 Submits results from informal 830323 meeting re unreviewed affidavits from Govt Accountability Project Shactleton analyzed Gunderson affidavit & will identify any new areas to Region V
 NARBUT.P P Region 5, Office of Director 83/03/23
 STERNBERG.D M . YOUNG, T . FIORELLI.0. NRC No Detailed Affiliation Given 1p 20903 33A 24X Fiche 50-528,83/09/08,
- --8310240219 Forwards M Young & L Bernabei FOIA request for documents re allegations of R Gunderson & senior Becktel manager FOIA time record form should be completed & returned GRIMSLEY, D H NRC No Detailed Affiliation Olven 83/03/31, WILSON, V Office of Nuclear Reactor Regulation, Director SHEENEY, M Office of the General Counsel 2pp 20904 049 24X Fiche 50-528,83/09/08,8310240197
- ~~8310240220 Requests that documents be provided in attached FDIA Request B3~450 Documents required to be delivered to I Alexander by B30817 Forwards FDIA Request B3~450 & list of documents on sub; Documents need not be duplicated NARBUT.P Region 5. Office of Director B3/08/14 MARTIN.J., BTERNDERO,D. YOUNG.T NRC ~ No Detailed Affiliation Given 4pp 20904 051 24X Fiche 50-528.B3/09/08,8310240197
- --8310R40236 Notifies that author had no involvement in investigation into allegations at facility.per Narbut 830816 memo No relevant documents re FOIA Request 83-450 in author possession JOHNSON:P NRC No Detailed Affiliation Given 83/08/18 ALEXANDER.I. NRC No Detailed Affiliation Given 1p 20704 111 24X Fiche 50-528,83/09/08.8310240197
- 8310050347 Notification of 831012 meeting w/util & C-E in Bethesda. MD to discuss updated status re reactor internals, evaluation of reactor coulant pumps, thermal sleeves & thermowells LICITRA.E A Licensing Branch 3 83/09/19 KNIGHTON. Q W Licensing Branch 3 83/09/19 KNIGHTON. G W 6310030347
- 8310050010 Submits updated status on RCB pumps, thermal slaeves & C-F shroud assemblies per 830913 & 14 telcons Design of pumps will be modified Followup status meeting scheduled for 831012 LICITRALE A Licensing Branch 3 83/09/28 NOVAK.T M Assistant Director for Licensing 3pp 20650 855 24X Fiche 50-528,83/09/28,8310050010
- 8310130126 Forwards Rev 3 to "Solt Deposition & Impact Monitoring Plan"
 VAN BRUNTLE E Arizona Public Bervice Co 83/09/29 KNIGHTON, 0
 Licensing Branch 3 2pp 20726 325 24% Fiche: 50-528, 83/09/29, 8310130126
- --8310130129 Rev 3 to "Salt Deposition & Impact Monitoring Plan "
 * NUS Corp 83/07/31 18pp 20725, 327, 24X
 Fiche 50-528,83/09/29,8310130126
- 8310260156 Forwards Rev 1 to Buppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR " Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feed

- --8310260160 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressuritation & DHR" * Combustion Engineering, Inc. CEN-239 SO3 R01 83/09/30 3/3pp 20914 181 247 Fiche 50-528.83/10/13.83/0260156
- 8310210252 Forwards revised responses to NRC 830727 request for adding or entil proposed rev to FSAR Section 1 8 concerning exceptions to Reg Guide 1 88 to permit use of records storage facility w/level concrete floor & roof VAN BRUNT, E E Arizona Public Service Co 83/10/17 KNIGHIUN, 0 Licensing Branch 3 App 20851 263 £4X Fiche 50-528,83/10/17,8310210252
- 8310250146 Forwards documents re recent reactor coolant pump problems per FOIA Request 83-448 Documents contain no proprietary info VAN BRUNT,E E Arizona Public Service Co 83/10/19 BISHOP,T W Division of Resident,Reactor Project & Engineering Programs | 11pp 20876 327 24% Fiche 50-328.83/10/19,8310250146
- 8310310372 Informs that info requested in 830920 ltr re import of high energy line breaks on control sys & exceptions taken in FSAR Section 3 8 1 6 6 1 will by submitted by 83117 VAN BRUNT, E E Arizona Public Service Co 83/10/21 KNIGHTON, C Licensing Branch 3 ip 20960 001 24X Fiche 50-528, 83/10/21. 8310310372
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclea: Owneration Station Fuel Assembly Spacer Grid Impact Loads Under Faulted Conditions: "per SER (NUREO-0857) Section 4 2 1 Affidavit encl Rept withheld (ref 10CFR2 790) VAN BRUNT, E E Arizona Public Bervice Co 83/09/26 KNIGHTON, G Licensing Branch 3 7pp 20002 219 24X Fiche 50-528.83/09/26, 8310030425
- F Security, medical, emergency & fire protection plans
- 8310040375 Forwards revised response to outstanding fire protection Open Items 2,4.8,10,16,21 & 23 identified at 830803 meeting in Bethesda, MD Revised response to Items 1,3.5 & 25 will be provided by 831130

 VAN BRUNT, E E Ariiona Public Service Co 83/09/29 KNIGHTON, G Licensing Branch 3 34pp 20620 288 24X Fiche 50-528,83/09/29,8310040375
- Q Adjudicatory correspondence
- B310240177 Partial response to L Bernabe: B30805 F0IA request for agency records relevant to X/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Ounderson & W Royce Forwards App A documents FCLION, J M Division of Rules and Records B3/09/08 OARDE, B G0vernment Accountability Project 4pp 20903 251 24X Fiche. 50-528, B3/09/08 3310240197
- --8310240212 Forwards Dept of Labor 830324 Recommended Decision & Older of Administrative Law Judge in 4 Royce vs Dechtel Corp case BUTLER.9 D Bechtel Corp 83703/30 Bechtel Corp 12pp 20904 001 24X Fiche 50-528.83/09/08.8310240197
- G Inspection reports. IE Bulletins & correspondence
- 8310240196 FOIA request for agency records relevant to &/or generated inconnection w/MRC investigations, insp or repts on allegations made by R Gunderson & W Royce re facilities BERNABELL Government Accountability Project 83/08/05 Office of Administration, 2pp 20903 249 24% Fiche 50-528,83/08/05,8310240196
- 8310240197 Partial response to L Bernabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents FELTON.J M Division of Rules and Records 83/09/08 GARDE, B Overnment Accountability Project 4pp 20903 251 24X Fiche. 50~528,83/09/08.8310240197
- --8310240197 Requests assistance in disclosing worker allegations re problems at facility Various allegations by workers re const QA & QC problems existing at plant discussed MORRISON, J R Palo Verde Intervention Fund 82/12/07 GARDE, B Government Accountability Project 3pp 20903 332 24X Fiche 50-528,83/09/08,8310240197

- --8310240215 Requests review of NRC serious mishandling of investigation of worker allegations re deficiencies in electrical work & startup testing program at facilities, on behalf of R Gunderson & W Royce Related matt encl BERNABI J. Covernment Accountability Project 83/07/14 PALLADINO, N , GILINSKY, V , AHCARNE, J Commissioners 17pp 20904 013 24X Fiche 50-528,83/09/08,8310240197
- --9310240218 Submits list of documents in Region V files which apply to Young & Dornabei FOIA-83-161 request for documents re allegations of electrical problems Related matl encl ALEXANDER, I Region 5, Office of Director 83/05/06 TOMS.V NRC No Detailed Affiliation Given 5pp 20904 045 24X Fiche 50-528.83/09/08,8310240197
- --8310240221 Forwards L Bernabe: FOIA request for documents in connection w/NRC, investigations, inspirepts or repts on allegations made by R Gunderson & W Royce re facilities List of questions for response to NL Toms requested by 830816
 GRIMSLEY,D H NRC No Detailed Affiliation Given 83/08/09 DROWN,N Office of the Secretary of the Commission SMEENEY,M Office of the General Counsel 2pp 20904 055 24X Fiche 50-528, 83/09/08, 8310240197
- --8310240222 Notifies that special unannounced insp scheduled at facility on B30404-08 Team consisting of author. A Johnson. J Burdoin. G Fibrelli & L Vorderbrueggen will examine facts surrounding as many allegations as possible during insp YOUNG. T Region 5, Office of Director 83/03/31 STERNBERG, D NRC No Detailed Affiliation Given 1p 20904 059 24X Fiche 50-528, 83/09/08, 8310240197
- --B310240223 Discusses NRC insp entrance interview conducted on 830615, to describe NRC planned insp activities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related mattenct

 IDE.W E Arizona Public Service Co 82/06/15 ROEDEL, J A Arizona Public Service Co 4pp 20/04/102 24X

 Fiche 50-528, 83/09/08, 8310240197
- ~-8310240227 Discusses status of special inspire allegations, in response to 830411 memo Lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to 830601 Relevant documents issued & received encl MARTIN.J B Region 5. Office of Director 83/05/02 CUNNINGHAM.Q H Office of the Executive Legal Director 2pp 20904 104 24x Fichs 50-528,83/09/08,8310240197
- --B310240239 Forwards documents to FBIA request for NRC investigation, insps or repts on allegations made by R Gunderson & W Royce concerning facilities Excerpt of installation spec for cable splicing one l
 ALEXANDER, I Region 5. Diffice of Director 83/08/19 TOMS, N
 NRC No Detailed Affiliation Given 7pp 20704 112 24X
 Fichs 50-528, 83/09/08/8310240197
- --B310240251 Discusses immediate effectiveness review of facilities ro analysis of pending insp/investigation items identified in Ofc of Insp & LDO repts of 830325 & 27 Presumes BECY will extend raylew time to accommodate Commission consideration ASSELSTINE, J K Commissioners B3/04/01 FALLADIND Commissioners 19 20904 131 24X Fiche 50-528,83/09/08, B3/03/09/09
- B310040932 Forwards IE Insp Rept 50-528/83-38 on B30801-31 No noncompliance noted BISHOP, T.W. Division of Resident, Reactor Project & Engineering Programs 63/09/19, ANDOGNINI.0 C Arizona Public Service Co 2pp 20424 010 24X Fiche 50-528.83/09/19.8310040532
- --0310040537 IE Insp Rept 50-528/83-38 on 830801-31 No noncompliance noted Major areas inspected aquipment qualification, startup testing, TMI followup items, NSSS problems & plant mod FIGRELLI, G., JOHNSTON, G., YOUNG, T. Region 5, Office of Director 83/09/15 7pp 20624 012 24X Fiche 50-528, 83/09/19, 8310040532
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list entl JORDAN: E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24X Fiche 50-000,83/09/26,8308300340
- B309300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes" Syc list encl JORDAN.E L Davision of Emergency Preparedness & Engineering Response (Foat 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp. 20777 210 24X Fiche 50-000,83/09/26,83083000342
- 8308300345 IE Info Notice 83-63, "Potentia) Failures of Westinghouse Type 8A-1 Differential Relays " Syc list encl JORDAN.C L Division of Emergency Prependerss & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 00) BAX Fiche 50-000,83/09/26,8308300345

- 8310170468 Forwards IE insp Rept 50-528/83-26 on 830705-08 & 19-22 No noncompliance noted BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/09/28 ANDDOMINI, G O Arizona Public Service Co 2pp 20783 252 24% Ficha 50-528,83/09/28,8310170468
- --8310170470 lE Insp Rept 50-528/83-26 on 830705-08 & 19-22 No noncompliance noted Major areas inspected plant procedures, surveillance testing % independent insp effort JOHNSON.P H , YOUNO, T Region 5. Office of Director 83/09/26 4pp 20783 254 24% Fiche 50-528,83/09/28,8310170468
- 830B300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys M/o 10CFR80 59 Evaluation" Syc list enc!
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- 830B30037B IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- B30B300752 IE Info Notice B3-46. "Fatality at Argentine Critical Facility " Svc list encl JORDAN.C L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 024 24% Fiche 50-000, B3/10/07, B30B300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Oases " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York: Inc. 117pp 21043 075 24X Fiche 50-000.83/10/11.8308300759
- 830830074i IE Info Notice 83-48, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 URDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000,83/10/11.8308300761
- 8310310396 Forwards IE Insp Rept 50-528/82-35 on 821216-23 No noncompliance noted BISHOP.TW Division of Resident.Reactor Project & Engineering Programs 83/10/13 ANDOGNINI.G C Arizona Public Servica Co 2pp 20959 355 24X Fiche 50-528.83/10/13.8310310394
- --B310310378 IE Insp Rept 50-528/82-35 on 821216-23 No noncompliance noted Major areas inspected preoperational containment leak rate test, procedure review inferviews w/personnel & witnessing portions of structural integrity test D'ANGELO, A J., YOUNG, T Region 5, Office of Director 83/10/13 5pp 20759 357 24% Fiche 50-528,83/10/13,8310310396
- S Reportable occurrences, LERs & related correspondence
- 8310070286 Final Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full load current at max site soil temp Initially reported on 821126 Condition not reportable per 10CFR50 55(e)

 VAN BRUNT, E E Arizona Public Service Co 83/09/16 STERNBERG, D M Region 5, Office of Director 5pp 20657 028 24X

 Fiche 50-528,83/09/16.8310070286
- ---8310070289 "Soil Thermal Property Measurements for Palo Verde Nuclear Plant " MARTIN M A M&E Technology, Inc 83/02/09 32pp 20657 033 24X Fiche 50-528,83/09/16,8310070286
- 8310070006 Final Deficiency Rept DER 83-41 re flooding in control bldg train Room B Pipe penetrations between circulating water intake canal & pump pit will be sealed to limit leakage rate into pump pit to within pit drainage sys capacity VAN BRUNT.E E Arizona Public Service Co 83/09/21 STERNBERG, D M Region 5, Office of Director Spp 20657 084 24% Fiche 50-528,83/09/21,8310070006
- 8310070147 Final Deficiency Rept DER 83-25 re instrumentation tubing w/o required boundary class break Initially reported on 830421 Deficiency determined not reportable under 10CFR50 55(e)
 VAN BRUNT, E E Arisona Public Service Co 83/09/21 STERNBERG, D. M Region 5, Office of Director 13pp 20659 068 24X Fiche 50-528,83/09/21,8310070147

- B310070352 Interim Deficiency Rept DER B3-42 re thermowells in RCS Initially reported on B30729 Final rept extension requested due to extensive investigation & evaluation Final rept will be submitted by B31201 VAN BRUNT.E E Arizona Public Service Co B3/09/21 STERNBERG, D M Region 5. Office of Director 2pp 20651 095 24X Fiche 50-528,83/09/21,8310070352
- 8310140267 Final Deficiency Rept DER 83-15 Te Marathon Stoel A354 anchor holt breaking under installation torque after test acceptance Initially reported on 830318 Analysis concluded bolt torsional failure caused by ductile shear overload VAN BRUNTLE E Arizona Public Service Co 83/07/23 STERNBERG, D N Region 5. Office of Director 5pp 20761 270 24% Fiche 50-529,83/09/23.8310140269
- 8310140259 Final Deficiency Rept DER 83-45 re cable separations in control room panels Initially reported on 830707 Procedures revised to ref Const Spec 13-EM-306 for separation criteria requirements Also reportable per Part 21 VAN DRUNTLE E Arizona Public Service Co 83/09/26, STERNBERQ, D M Region 5. Office of Director 15pp 20762 069 24X Fiche 50-528,83/09/26,8310140259
- B3i0140012 Final Deficiency Rept DER 83-14 re failure of Westinghouse diesel generator protective relays due to leaking capacitors Initially reported on 830316 Relays will be returned to supplier Capacitors will be replaced VAN BRUNIEE & Arizona Public Service Co 83/09/27 STERNBERG, D N Region 5, Office of Director 3pp. 20767 006 24X Fiche 50-528,83/09/27,8310140012
- 8310270430 Final Deficiency Rept DER 83-43 re improper crimp terminations in 12 cabinets furnished by Harlo Corp Initially reported on 830708 Harlo cabinets for all Units Uil be inspected & reworked Also reportable per Part 21 VAN BRUNTLE E Arizona Public Service Co 83/09/27 BISHOP, T W. Division of Resident Reactor Project & Engineering Programs & pp 20923 085 24X Fiche 50-528,83/09/27,8310970430
- ISIO14023B Interim Deficiency Rept DER 83-46 re Borg Warner valve manually overtorqued during hydrostatic testing Initially reported on 830715 Time extension until B31214 requested for final rept.due to extensive investigation required VAN BRUNT.E E Arizona Public Service Co 83/09/28 STERNBERG, D M Region 5, Office of Director 2pp 20761 321 24X Fiche, 50-528, 83/09/28, 8310140238
- 8310230099 Interim Deficiency Rept DER 83-40 re low pressure safety injection & CS pump motors leaking oil & w/defective welds initially reported on 830729 Due to extensive investigation, rept will not be submitted until 831206 VAN BRUNTLE E Arizona Public Service Co 83/10/05 BISHOP.T H Region 5. Office of Director 2pp 20895.277 24X Fiche 50-528.83/10/05.8310250099
- 8310250415 Interim Deficiency Repts DER 82-57, DER 82-64 & DER 83-32 re conditions & circumstances surrounding design processes involved w/dissimilar metal socket welds

 VAN BRUNT, E Arizona Pubbic Service Co 83/10/06. BISHOP, T W. Division of Resident. Reactor Project & Engineering Programs 2pp 20897 245 24X Fiche 50-528,83/10/04,8310250415
- 331025054B Final Deficiency Rept DER 83-3B re Steiler Steel clip angles used for HVAC supports that do not meet ASTM A-34 requirements initially reported on 83062B Deficiency determined not reportable per 100FR90 856c)

 VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 90pp 20901 324 24X Fiche 50-528, 83/10/06, 8310250568
- 3310250079 Interim Deficiency Rept 83-10 re main steam relief valve tests exceeding specified 5% blowdown limit. Initially reported 830228 Due to extensive investigation & evaluation required, rept will not be submitted until 831118. VANBRUNT, E.E. Arizona Public Service Co. 83/10/07 SISHOP, T. W. Region 5, Office of Director. 2pp. 20894 139 24X Fiche: 50-528,83/10/07,8310250079.
- |310310138 Interim Deficiency Rept DER 80-54 Te washers in stoam generators 1 & 2 Initially reported on 830802 Due to extensive evaluation required, next rept will be submitted by 831213 VAN SRUNT, E.E. Arizona Public Service Co. 83/10/13 818HDP.T W Division of Resident, Reactor Project & Engineering Programs . 2pp 20959 035 24X Fiche 50-528,83/10/13,8310310138

- 8310310316 Interim Deficiency Rept DER 83-61 re law pressure safety injection pumps failing to start & to produce required head initially reported on 830914 Due to extensive investigation & evaluation, final rept will be submitted by 840126 VAN BRUNT.E E Arizona Public Service Co 83/10/13 818HOP.T N Division of Resident.Reactor Project & Engineering Programs Topp 20961 164 24X Fiche 50-528,83/10/13.8310310316
- U Congressional/Executive Correspondence
- 8310240197 Partial response to L Dernabel B30805 FOIA request fol agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & W Royce Forwards App A documents FELTON, J M Division of Rules and Records 83/09/08 GARDF, D Government Accountability Project 4pp 20903 251 24X Fiche 50-528,83/09/08.8310240197
- ---8310240217 Requests response to issues raised by J Morrison B30703 lti espressing concerns w/manner in which Regional V & Ofc of Investigation handled allegations of violations at plant J Morrison B30703 itr encl UDALL.M K House of Rep , Interior & Insular Affairs B3/0//17 PALLADINO, N Commissioners 4pp 20904 040 24X Fiche 50-528,83/09/08,8310240197
- --B310240241 Notifies of receipt of T Woods B20511 ltr to NRC re allegations about safety at facilities Requests to be advised of any action taken by NRC in subj matter RUDD. E House of Rep B2/05/19 PALLADINO, N J Commissioners 1p 20904 129 24X Fiche 50-528,83/09/08.8310240197
- --8310240246 Ack receipt of 820519 ltr to Chairman Pallading expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter w/legal assistance
 KAMMERER, C Office of Congressional Affairs 82/04/01 RUDD, E House of Rep | p 20704 130 24x Fiche 50-528,83/07/08,8310240197
- V Operator Examinations
- 8310030154 Requests schedule, by 830928, for requalification training & exams for 1984 in order to coordinate Region V audit of operator requalification programs

 BISHOP.T W Division of Resident Reactor Project & Engineering Programs

 B3/09/26 ANDOGNINI.G C Arizona Public Service Co
- DOCKET BIN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8206080487 Comments on 820511 ltr re allegations of improper electrical work Inquiry being made DIRCKS,M J Office of the Executive Director for Operations 82/05/26 MODIS: 7 & Artsona Public Service Co lp 20704 128 24X Fiche 50-528,83/09/08,8310240197
- --8310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form ECKHARDT, J. H NRC No Detailed Affiliation Given 82/12/17 SHACKLETON, O NRC No Detailed Affiliation Given 1p 20703 335 24X Fiche 50-528,83/09/08,8310240197
- --8310240203 Submits results from informal 830323 meeting re unreviewed affidavita from Govt Accountability Project Shackleton analyzed Gunderson affidavit & will identify any new areas to Region V NARBUT,P P Region 5. Office of Director 83/03/23 STERNBERO,D M , YOUNG,T , FIGRELLI,G NRC No Detailed Affiliation Given 1p 20903 336 24X Fiche 50-528,83/09/06,8310240197
- ---8310240219 Forwards M Young & L Bernabei FOIA request for documents re allegations of R Qunderson & senior Bechtel manager FOIA time record form should be completed & returned ORIMSLEY.D H NRC No Detailed Affiliation Given 83/03/31 WILSON.V Office of Nuclear Reactor Regulation, Director SWEENEY,M Office of the General Counsel 2pp 20904 047 24X Fiche 50-528.83/09/08.8310240197
- --8310240220 Request® that documents be provided in attached FO)A Request®-450 Documents required to be delivered to I Alexander by B30817, Forwards FOIA Request 83-450 & list of documents on subj Documents need not be duplicated NARBUT.P Region 5, Office of Director 83/08/16 MARTIN.J. STERNBERQ,D. YOUND.T NRC No Detailed Affiliation Given 4pp 20904 051 24% Fiche 80-528,83/09/08,8310240197

- 8310050347 Notification of 831012 meeting w/util & C-E in Bethesda, MD to discuss updated status re reactor internals, evaluation of reactor coolant pumps, thermal sleeves & thermouells LICITRA, E A Licensing Branch 3 83/09/19 KNIGHTON, G W Licensing Branch 3 3pp 20650 051 24X Fiche 50-528,83/09/19,8310050347
- 8310050010 Submits updated status on RCS pumps, thermal sleeves & C-F shroud assemblies per 830913 & 14 telcons Design of pumps will be modified followup status meeting scheduled for 831012
 LICITRA, E A Licensing Branch 3 83/09/28 NOVAK, T M Assistant Director for Licensing 3pp 20650 255 24X Fiche 50-528,83/09/28,8310050010
- 8310130126 Forwards Rev 3 to "Salt Deposition & Impact Monitoring Plan " VAN BRUNT,E E Arizona Public Service Co 83/09/29 KNICHTON,G Licensing Branch 3 2pp 20726 325 24X Fiche 50-526,83/09/27, 8310130126
- --8310130127 Rev 3 to "Salt Deposition & Impact Monitoring Plan" 4 NUS Corp. G3/07/31 18pp. 20726-327 24X Fiche 50-528.83/09/29,8310130126
- 8310260156 Forwards Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR " Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feeduater restoration VAN BRUNTLE E Arizona Public Service Co 83/10/13 KNIGHTON.C Licensing Dranch 3 3pp 20914 178 24X Fiche 50-528,83/10/13.8310260156
- --8310260160 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR "

 * Combustion Engineering, Inc CEN-239 803 ROI 83/09/30 373pp 20914 181 24% Fiche 50-528,83/10/13.8310260156
- 8310210252 Forwards revised responses to NRC 830727 request for addition or each proposed revito F5AR Bectson 1 8 concerning exceptions to Reg Quide 1 88 to permit use of records storage facility w/level concrete floor & roof VAN BRUNTLE E Arizona Public Service Co 83/10/17 KNIGHTON, Q Licensing Branch 3 App 20851 263 24X Fiche 50-528, 83/10/17, 8310210252
- 8310310372 Informs that info requested in 830920 ltr re impact of high energy line breaks on control sys & exceptions taken in FSAR Section 3 8 i 6 6 i will by submitted by 83117 VAN BRUNTLE E Arizona Public Service Co 83/10/21 KNIGHTUN. 6 Licensing Branch 3 ip 20960 001 24X Fiche 50-528,83/10/21, 8310310372
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8310030425 Forwards proprietary "Finel Assessment of Palo Verde Nuclear Generation Station Fuel Assembly Spacer Orid Impact Loads Under Faulted Conditions," per BER (NUKEG-0887) Section 4 2 1 Affidavit encl Rept withheld (ref 10CFR2 770) VAN BRUNTLE E Arizona Public Service Co 83/09/26 KNIGHTON.G Licensing Branch 3 7pp 20602 219 24% Fichs 50-526,83/09/26.8310030425
- F Security, medical, emergency & fire protection plans
- 8310040375 Forwards revised response to outstanding fire protection Open Items 2.4.8.10.16.21 & 23 identified at 830803 meeting in Bethesda, MD Revised response to Items 1.3.5 & 25 will be provided by 831130

 VAN BRUNT, F. E. Arizona Public Service Co. 83/09/29 KNIGHTON, Q. Licensing Branch 3. 34pp. 20620 288 24X Fiche 50-528,83/09/29, 8310040375
- G Adjudicatory correspondence
- B310240197 Partial response to L Bernabei B30805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & M Royce Forwards App A documents FELTON. J M Division of Rules and Records B3/09/08 GARDE. B Government Accountability Project App 20903 251 24X Fiche 50-528,83/09/08,8310240197

- ~-8310240212 Forwards Dept of Labor 830324 Recommended Decision & Ord of Administrative Law Judge in W Royce vs Bechtel Corp case BUTLER,S D Bechtel Corp 83/03/30 Bechtel Corp 12pp 20704 001 24X Fiche 50~528,83/09/08.8310240197
- B310250264 Forwards several inspirepts or investigations of allegation by former constituorkers
 DEMEY, L.S. NRC No Detailed Affiliation Given B3/10/21
 LAZO, R.M., COLE, R.F., CALLIMAN, D. Atomic Safety and Licensing Boar
 Panel 5pp 20899 088 24X Fiche 50-529,83/10/21,8310250264
- 8310270234 Order extending time until 831108 for Commission to art to review ALAB-742 CHILK.B J Office of the Secretary of the Commission 83/10/26 Commissioners 1p 20924 070 24X Fiche 50-529,83/10/26,8310270234
- O Inspection reports, IE Dulletins & correspondence
- 8310240194 FOIA request for agency records relevant to &/or generated inconnection w/NRC investigations, insp or repts on allegations made by R Gunderson & W Royce re facilities BERNABEI, L Government Accountability Project 83/08/05 Offic of Administration 2pp 20903 249 24% Fiche 50-528,83/08/05.8310240194
- 8310240197 Partial response to L Barnabei 830805 FOIA request for agency records relevant to &/or generated in connection w/ NRC investigations.inags or repts on allegations made by R Gunderson & W Royce Forwards App A documents FELTON.J M Division of Rules and Records 83/09/08 GARDE, B Government Accountability Project App 20903 251 24X Ficne 50-528,83/09/08,8310240197
- --8310240199 Requests assistance in disclosing worker allegations reproblems at facility Various allegations by workers reconst QA & QC problems existing at plant discussed MQRRISON.J R Palo Varde Intervention Fund 82/12/07 QARDE, B Quvernment Accountability Project 3pp 20903 332 24X Fiche, 50-528, 83/09/08, 8310240197
- --8310240215 Requests review of NRC serious mishandling of investiga of worker allegations re deficiencies in electrical work & startup testing program at facilities, on behalf of R Gunderson & W Royce Related math encl

 BERNABEL, Covernment Accountability Project 83/07/14

 PALLADINO, N. 9 CLINSKY, V. AHERINE, J. Commissioners 19pp

 20904 013 24X Fiche 50-528,83/09/08,8310240197
- --8310240218 Submits list of documents in Region V files which apply to Young & Burnabei FOIA-83-161 request for documents re allegations of electrical problems Related matl encl ALEXANDER, I Region 5. Office of Director 83/05/06 TOMS,V NRC No Detailed Affiliation Oiven Spp 20904 045 24X Fiche 50-528 83/09/08 8310240197
- --8310240221 Forwards L Bernabai FOIA request for documents in common/MRC investigations, inspirepts or repts on allegations made by R Quiderson & W Royce refacilities List of questions for response to N. Toms requested by 830916

 ORIMSLEY, D H NRC No Detailed Affiliation Qiven 83/08/09 BROWN, N Office of the Secretary of the Commission SWEENEY, M Office of the Queral Counsel 2pp 20904 055 24X Fiche 50-528,83/09/08,8310240197
- --B310240222 Notifies that special unannounced insp scheduled at facility on 830404-0B Team consisting of author. A Johnson, J Burdoin, G Fiorelli & L Vorderbrueggen will examine facts surrounding as many allegations as possible during insp YOUNG, T Region 5. Office of Director 83/03/31 STERNBERO, D NRC No Detailed Affiliation Given 1p 20704 059 24X Fiche 50-528,83/09/08,8310240197
- --8310240223 Discusses NRC insplentrance interview conducted on 830 describe NRC planned insplentivities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related math and IDE, W.E. Arizona Public Service Co. 82/06/15, ROEDEL, J.A. Arizona Public Service Co. 4pp. 20904 102 24X Ficha 50-528,82/09/08,8310240197
- --8310240227 Discusses status of special inspire allegations, in res to 830411 memo Lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to 830601 Relevant documents issued & received encl MARTIN, J.B. Region 5. Office of Director 83/05/02 CUNNINGHAM, 9. Office of the Executive Legal Director 2pp 20904 106 24X Fiche 50-528,83/09/08,8310240197

- --8310240237 Forwards documents re FOIA request for NRC investigation.
 insps or repts on allegations made by R Gunderson & W Royce
 concerning facilities Except of installation spec for cable
 splicing encl
 ALEXANDER, I Region 5. Office of Director B3/08/19 TOMS, N
 NRC No Detailed Affiliation Given 9pp 20904 112 24X
 Fiche 50-328, B3/09/08, B310240197
- --8310240251 Discusses immediate effectiveness review of facilities to analysis of pending insp/investigation items identified in Ofc of Insp & EDO repts of 830025 & 27 Presumes SECY will either the review time to accommodate Commission consideration ASSELSTINE, J. K. Commissioners 62/04/01 PALLADING Commissioners 1p 20904 131 24X Fiche 50-528.83/09/08.8310240197
- B30B300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Wilder Qualification Yests" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York, Inc 117pp 20794 022 24X Fiche 50-000.83/09/26,830B300340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list enct JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50~000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JORDANIE L Division of Emergency Prophedimess & Engineering Response (Post 830103) 83/09/26 Consulidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice B3-64. "Lead Shielding Attached to Safety-Related Sys M/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 EUTPSN1 Consolidated Edison Co of New York, Inc 115pp 20716 324 24X Fiche 50-000.83/09/29, 8308300349
- 8308300378 IE Info Notice 83-65. "Survei)lance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 800103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300078
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24% Fiche 50-000.83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Hatl Defect Causes Production of Noticus Oases " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24x Fiche 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Manning Defective Self-Contained Breathing Apparatus Air Cylanders " Svc list enc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consplicated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310250264 Forwards several inap rapts re investigations of allegations by former const workers
 DENEY,LS NRC No Detailed Affiliation Given 83/10/21
 LAZO,R H, COLE,R F, CALLIHAN,D Atomic Safety and Licensing Board
 Panel 5pp 20899 088 24X Fiche 50-529,83/10/21,8310250264
- S Reportable occurrences, LERs & related correspondence
- 8310070286 Final Deficiency Rept DER 82-68 re underground cables to startup transformers which may not carry full load current at max site soil temp initially reported on 82126 Condition not reportable per IOCFR50 55(e) VAN BRUNT.E E Arizona Public Service Co 83/09/16 STERNBERG, D M Region 5, 06ftce of Director 5pp 20657 028 24X Fiche 50-528,83/09/16,8310070286
- --8310070287 "Soil Thermal Property Measurements for Palo Verde Nuclear Plant " HARTIN:M A M&E Technology, Inc. 83/02/09 32pp 20657 033 24X Fiche 50-528:83/09/16:8310070286

- B310070339 Final Deficiency Rept DER 83-34 re instrument racks in containment w/surface cracks on various welds to embed plates Institutly reported on 830927 Item not reportable under 10CFR50 55(e)

 VAN BRUNT, E E Ariiona Public Service Co 83/09/19 STERNBLEC, D // Region 5, Office of Director 4pp 20651 060 24X

 Fiche 50-529,83/09/19,8310070339
- 8310070147 Final Deficiency Rept DER 83-25 re instrumentation tubing w/o required boundary class break Initially reported on 830421 Deficiency determined not reportable under 100FR50 55(e)
 VAN BRUNT, E E Arizona Public Service Co 83/09/21 STERNBERG, D & Region 5, Office of Director 13pp 20659 068 24X Fiche 50-528,83/09/21,8310070147
- 8310070352 Interim Deficiency Rept DER 8J-42 re thermowells in RCS Initially reported on 830729 Final rept extension requested due to extensive investigation & evaluation Final rept will be submitted by 831201

 VAN BRUNT, C. E. Arizona Public Service Co. 83/09/21 STERNBERG, D. H. Region 5. Office of Director 2pp. 20451 095 247

 Fiche 50-528,83/09/21,8310070J52
- B310140269 Final Deficiency Rept DER B3-15 re Marathon Steel A354 anchor bolt breaking under installation torque after test acceptance Initially reported on B30318 Analysis concluded bolt torsional failure caused by ductile shear overload VAN BRUNT, E E Arizona Public Service Co 83/09/23 STEANBEAG, D N Region 5, Office of Director 5pp 20761 270 24X Fiche 50-529,83/09/23,8310140269
- --8310140274 "Failure Analysis of ASIM A-384 Bolt "
 GGNZALES, J C . SCHMIDT, G R . HACKNEY, B D Bechtel Corp 0363 03
 FA 83/03/31 20pp 20761 275 24X Fithe 50-527, 83/09/23,
 8310140249
- B310140012 Final Deficiency Rept DFR 83-14 re failure of Westinghouse diesel generator protective relays due to leaking capacitors Initially reported on 830316 Relays will be returned to supplier Capacitors will be replaced VAN BRUNT, E.E. Arizona Public Service Co. 83/09/27 STERNBERG, D. H. Region 5. Office of Director 3pp. 20767 006 24X Fichs 50-528,83/09/27,8310140012
- 8310140238 Interim Deficiency Ropt DER 83-46 re Borg Harner valve manually overtorqued during hydrostatic testing Initially reported on 830715 Time extension until 831214 requested for final reptidue to extensive investigation required VAN BRUNT.E E Arizona Public Service Co 83/09/28 STERNBERG.D H Region 5. Office of Director 2pp 20761 321 24X Fichs 50-528.83/09/28.8310140238
- B310270413 Interim Deficiency Rept DER 83-59 re IEEE-304 separation criteria violated by wiring in post-accident control room & safety radiation monitoring cabinets Initially reported on 830830 Final rept to be submitted by B31129
 VAN BRUNTLE E Arizona Public Service Co 83/10/03 STERNBENC.D N Region 5. Office of Director 3pp 20924 028 24X
 Fiche 50-529,83/10/03.8310270413
- 8310270460 Interim Deficiency Ropt DER 83-60 re failure of wiring in main steam & fordwater actuation sys supplied by Vitro Labs
 Div to meet IECE-384 separation criteria Initially reported on 830830 Completion of evaluation & final rept by 831130
 VAN BRUNT.E E Aritona Public Service Co 83/10/03 STERNBERG.D H
 Region 5. Office of Director 3pp 20922 025 24X
 Fich* 50-529.83/10/03.8310270460
- 8310250415 Interim Deficiency Repts DER 82-57. DER 82-64 & DER 83-02 is conditions & circumstances surrounding design processes involved w/dissimilar metal socket welds

 VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHIDP, T W Division of Resident. Reactor Project & Engineering Programs Proposed 2087/245 24X Fiche 50-528.83/10/06.8310250415
- B31025056B Final Deficiency Rept DER B3-3B re Steiler Steel clip amples used for HVAC supports that do not meet ABTM A-36 requirements initially reported on B3762D Deficiency determined not reportable per 10CFR50 55(c) VAN BRUNT.E E Arisona Public Service Co B3/10/06 BISHOP.T W DIVISION of Resident Reactor Project & Engineering Programs 93pp 20901 324 24X Fiche 50-52B 83/10/06 B1025056B
- U Congressional/Executive Correspondence
- B310240217 Requests response to issues raised by J Morrison B30703 its expressing concerns w/manner in which Regional V & Ofc of Investigation handled allegations of violations at plant J Morrison B30703 itr encl
 UDALLIM K House of Rep , Interior & Insular Affairs B3/07/17 PALLADINO, N Commissioners 4pp 20904 040 24X Fiche 50-528,83/09/08,8310240197

- --8310240241 Notifies of receipt of T Woods 820511 ltr to NRC re allegations about safety at facilities Requests to be advised of any action taken by NRC in subj matter RUDD: E. House of Rep. 82/05/19 PALLADIND.N J. Commissioners 1p. 20904 129 24X Fiche 50~528,83/09/08,8310240197
- --BJ10240246 Ack receipt of B20519 ltr to Chairman Palladino expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter wilegal assistance

 KAMMERER, C. Office of Congressional Affairs 82/06/01 RUDD, E. House of Rep. 1p. 20904-130. 24X Fiche 50-528, 83/09/08, 831024019/

V Operator Examinations

- 8310030154 Requests schedule, by B30928, for requalification training & exams for 1924 in order to coordinate Region V audit of operator requalification programs
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs B3/09/24 ANDDGNINI.0 C Arizona Public Service Co 2pp 20590 030 24% Fiche 50-528, 83/09/24, 8310030154
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

 A Application/construction stage documents & correspondence
- 8204080487 Comments on 820511 ltr re allegations of improper electrical work Inquiry being made DIRCKS:W J Office of the Executive Director for Operations 827092/26 W0005,T 9 Arizona Public Service Co 1p 20704 128 24X Fiche 50~528,83/09/08,8310240197
- --B310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form ECKHARDTJ H NRC ~ No Detailed Affiliation Given B2/12/17 SHACKLETON.0 NRC ~ No Detailed Affiliation Given Ip 20903 335 24X Ficho 50-528.83/09/08.8310240197
- --8310240203 Submits results from informal 830323 meeting re unreviewed affidavits from Govt Accountability Project Shackleton analyzed Ounderson affidavit & will identify any new areas to Region V NARBUT, P. P. Region 5, Diffice of Director 83/03/23 STERNBERG D M NRC No Detailed Affiliation Given 1p 20903 336 24% Fiche 50-528,83/07/08,8310240197
- --8310240219 Forwards M Young & L Bernabei FOIA request for documents re allegations of R Gunderson & senior Bechtel manager FOIA time record form should be completed & returned GRIMBLEY.D II NRC No Detailed Affiliation Given 83/03/31 WILSON,V Office of Nuclear Reactor Regulation, Director 2pp 20904 049 24X Fiche 50-528,03/09/08,8310240197
- --8310240220 Requests that documents be provided in attached FOIA Request B3-450 Documents required to be delivered to I Alexander by B30817 Forwards FDIA Request B3-450 & list of documents on subj Documents need not be duplicated NARBUT. P Region 5, Office of Director 83/08/16 MARTIN, J NRC No Detailed Affiliation Given 4pp 20904 051 24X Fiche 50-528,83/09/08,8310240197
- --8310240236 Notifies that author had no involvement in investigation into allegations at facility, per Narbut 830816 memo No relevant documents re FOIA Request 83-450 in author possession
 JOHNSON, P. NRC No Detailed Affiliation Given 83/08/18
 ALEXANDER, I. NRC No Detailed Affiliation Given 1p. 20704 111
 24X Ficho 80-828,63/09/08,8310240197
- 8310050347 Notification of 831012 meeting w/util & C-E in Bethesda, MD to discuss updated status re reactor internals evaluation of reactor coolant pumps, thermal sleeves & thermowells LIGITRA, E A Licensing Branch 3 83/09/19 KNIGHTON, Q W Licensing Branch 3 3pp 20650 051 RAX fiche 50-528, 83/09/19, 8310050347
- 83:10050010 Submits updated status on RCS pumps, thermal sleeves & C-E shroud assemblies per 830913 & 14 belcons Design of pumps will be modified Followup status meeting scheduled for 83:1012
 LIGITRALE.A Licensing Branch 3, 83/09/28 NOVAK,T M Assistant Director for Licensing 3pp 20650 255 24% Fiche 50-528,83/09/28,8310050010
- 8310130126 Forwards Rev 3 to "Balt Deposition & Impact Monitoring Plan" VAN BRUNT,E E Arizona Public Service Co 83/09/29 KN1GHTON, Q Licensing Branch 3 2pp 20726 325 24X Fiche 50-528.83/09/29, 8310130126

- --8310130129 Rev 3 to "Salt Deposition & Impact Monitoring Plan "

 * NUB Corp 83/07/31 18pp 20726 327 24X
 Fiche 50-528.83/09/29.8310130126
- 8310260156 Forwards Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR." Changes are result of detailed treatment of automatic PORV cases & complete analysis of auxiliary feedwater restoration VAN BRUNTLE E Arizona Public Service Co 83/10/13 KNIGHTON, @ Licensting Branch 3 3pp 20714 178 24X Fiche 50-528,83/10/13.8310260156
- ~-B310260160 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR "

 * Combustion Engineering, Inc CEN-239 S03 R01 83/09/30 373pp 20914 IBI 24% Fitch 50~528,83/10/13.8310260156
- 8310210252 Forwards revised responses to NRC 830727 request for additinfore util proposed revito FbAR Section 1 8 concerning exceptions to Reg Quide 1 88 to permit use of records storage facility w/level concrete floor & roof VAN BRUNT, E E Arisona Public Bervice Co 83/10/17. KNIQHTON, Q Licensing Branch 3. App 20851 263 24X Fiche 50-528.83/10/17, 8310210252
- 8310310372 Informs that info requested in 830720 ltr re impact of high energy line breaks on control sys & exceptions taken in FSAR Section 3 8 1 6 6 1 will by submitted by 831117 VAN BRUNT, E E Arizona Public Service Co 83/10/21 KN19HTON, 8 Licensing Branch 3 1p 20760 001 24X Fiche. 50-528, 83/10/21, 8310310372
- E NRC Safety Evaluation Report (SER), supply & correspondence
- B310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclear Generation Station Fuel Assembly Spacer Grid Impact Loads Under Faulted Conditions." per SER (NUREG-0857) Section 4 2 1 Affidavit encl Rept withheld (ref 10cFR2.790) VAN BRUNT.E E Arizona Public Bervice Co B3/09/24 KNIOHTON, 9 Licensing Branch 3 7pp 20602 219. 24X Fiche 50~528, B3/09/26, B310030425
- F Security, medical, emergency & fire protection plans
- 8310040375 Forwards revised response to outstanding fire protection Open Items 2.4.8.10.16.21 & 23 identified at 830803 meeting in BethesdarMD Revised response to Items 1.3.5 & 25 will be provided by 831130

 VAN BRUNT, E E Arizona Public Service Co 83/09/29 KNIGHTON, Q Licensing Branch 3 34pp 20620 288 24X Fichs 50-528, 83/09/29, 8310040375
- G Adjudicatory correspondence
- 8310240197 Partial response to L Bernabei B30805 F0IA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Gunderson & N Royce Forwards App A documents. FELTON.J M Division of Rules and Records, 83/09/08 GARDE, B Government Accountability Project App 20903 251, 24X Fiche 50-528,83/09/08,8310240197
- --8310240212 Forwards Dept of Labor 830324 Recommended Decision & Order of Administrative Law Judge in W Rouce vs Bechtel Corp cate BUTLER, B D Bechtel Corp 83/03/30 Bechtel Corp. 12pp 20904 001 24% Fiche 50-528.83/09/08.8310240197.
- B310250264 Forwards several insp rapts re investigations of allegations by former const workers
 DEMEY, L B NRC NO Detailed Affiliation Given. B3/10/21.
 LAZO, R M , COLE, R F., CALLIHAN, D Atomic Safety and Licensing Board
 Panel 5pp 20899 088 24X Ficha 50-529,83/10/21,8310250264
- 8310270234 Order extending time until 831108 for Commission to act to review ALAB-742 CHILK: 8 J. Office of the Secretary of the Commission 83/10/26 Commissioners 1p. 20924-070 24X Fiche 50-529.83/10/26, 8310270234
- G Inspection reports, IE Bulletins & correspondence
- B310240176 FOIA request for agency records relevant to b/or generated inconnection w/NRC investigations.insp or repts on allegations made by R Punderson & H Royce re facilities.
 BERNABEI, L Government Accountability Project B3/08/05 Office of Administration 2pp 20703 247 24X Fiche 50-528.83/08/05, B310240176

- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 9A-1 Differential Relays " Svc list and JDRDAN:E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 OD1 24X Fishe 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Bafety-Related Sys W/o 10CFR30 59 Evaluation " Svc list ancl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 EUTPSNH Consolidated Edison Co of New York, Inc 113pp 20716.324 24x Fiche 50-000,83/09/29, 8308300349
- 8308300378 lE Info Notice 83-65, "Burveillance of Flow in RTD Bypass Loops Used in Hestinghouse Plants " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consoludated Edison Co of Ne York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-64, "Fatality at Argentine Critical Facility " 8vc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/10/07 Consolidated Edison Co of New York, Inc. 79pp 20882 026 24X Fiche 30-000, 83/10/07, 8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxidus Oases " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Canabildated Edison Ca of New York, Inc. 1179p 21043 075 24X Fiche 50-000, 83/10/11.8308300759
- 830830076(IE Info Notice 83-68, "Respirator User Warning Defective 8a Pr-Contained Breathing Apparatus Air Cylinders." Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 (27 24x Fiche 50-000,83/10/11,830830076)
- 8310250264 Forwards geveral insp repts re investigations of allegations by former const workers
 DEWEY,L B NRC NO Detailed Affiliation Given 83/10/21
 LAZO,R. M Atomic Safety and Licensing Board Panel 5pp 20899 088
 24% Fiche 50-529,83/10/21,8310250264
- 8 Reportable occurrences. LERs & related correspondence
- 8310070286 Final Deficiency Rept DER 82-48 re underground cables to startup transformers which may not carry full lasd current at max site soil temp. Initially reported on 821126 Condition not reportable per 100FR30. 35te.)

 VAN BRUNT, E.E. Arizons Public Service Co. 83/09/16. STERNBERG, D. M. Region 5. Office of Director. Spp. 20457. 028 24X

 Fiche: 50-528,83/09/16,8310070286
- -8310070289 "Soil Thermal Property Measurements for Palo Verde Nuclear Plant." MARTIN:H A M&E Technology, Inc. 83/02/09 32pp 20657-033 24X Fiche 50-528,83/09/16.8310070286
- 310070147 Final Deficiency Rept DER 83-25 re instrumentation tubing w/o required boundary class break. Inftfally reported on 830421, Deficiency determined not reportable under 10CFR3D 55(e)
 VAN BRUNT,E E Arizona Public Service Co. 83/07/21 STERNBERG,D H Region 5. Office of Director. 13pp 20659 068 24X Fiche, 50-528,83/09/21,8310070147
- 8310070352 Interim Deficiency Rept DER 83-42 re thermowells in RCS Initially reported on 830729 final rept extension requested due to extensive investigation & evaluation final rept will be submitted by 831201.

 VAN BRUNTLE E. Arizona Public Service Co 83/09/21 STERNBERG, D M Region 5, Office of Director. 2pp 20451.093 24X Fiche 50-528,83/09/21,8310070352
- 310140269 Final Deficiency Rept DER 83-15 or Marathon Steel A354 anchor bolt breaking under installation torque after test acceptance. Initially reported on 8303/8 Analysis concluded bolt torsional failure caused by ductile shear overload.

 "AN BRUNT, E E Afizona Public Service Co 83/09/23 STERNBERG, D M Region 5. Dffice of Director. Spp 20761:270 24X iche-50-529,83/09/23,8310140269
 - 0140274 "Failure Analysis of ASTM A-054 Bolt." ONZALES, J. C., BCHMIDT, G. R., HACKNEY, B. D. Bechtel Corp. 0383-03 A. 83/03/31, 20pp. 20761; 275, 24X Fiche, 50-529, 83/09/23, 310140249

- B310240197 Partial response to L Bernabei B30805 F0IA request for agency records relevant to &/or generated in connection w/ NRC investigations, insps or repts on allegations made by R Junderson & W Royce Forwards App A documents FELTON, J M Division of Rules and Records B3/09/08 GARDE, B Government Accountability Project 4pp 20703 251 P4X Fiche 50-528,83/09/08,8310240197
- --8310240199 Requests assistance in disclosing worker allegations reproblems at facility Various allegations by workers reconst. 0A & 8C problems existing at plant discussed MGRRISON. J R Palo Verde Intervention Fund 82/12/07 GARD#. D Government Accountability Project 3pp 20903 332 24X Fiche 50-528.83/09/08.8310240197
- --B310240215 Requests review of NRC serious mishandling of investigation of worker allegations re deficiencies in electrical work & startup testing program at facilities on behalf of R Gunderson & W Royce Related matl enci
 BERNABELL Government Accountability Project B3/07/14
 PALLADING, N Commissioners 17pp 20904 013 24X
 Fiche 50-528,83/09/08.8310240197
- --8310240218 Submits list of documents in Region V files which apply to Young & Bernabel FOIA-83-161 request for documents re allegations of glectrical problems Related mattenel ALEXANDER, I Region 5, Office of Director 82/05/06 TOMS, V NRC No Datailed Affiliation Given 5pp 20904 045 24% fiche 50-528,83/09/08,8310240197
- --B310240R21 Forwards L Bernabei FOIA request for documents in connection w/NRC investigations, insp repts or repts on allegations made by R Gunderson & W Royce re facilities List of questions for response to NL Toms requested by 830816
 GRIMSLEY, D H NRC ~ No Detailed Affiliation Given 83/08/07
 BROWN, N Office of the Secretary of the Commission 20904 055 24X Fiche 50-528, 83/09/08-8310240197
- --8310240222 Notifies that special, unannounced insp scheduled at facility on 830404-08 Team consisting of author. A Johnson. J Burdoin. G Fiorelli & L Vorderbruggen will examine facts surrounding as many allegations as possible during Insp YOUNG. T Region 5. Office of Director 83/03/31 STERNDERG. D NRC No Detailed Affiliation Given 1p 20904 059 24X Fiche 50-528.83/09/08.8310240197
- ~-8310240223 Discusses NRC insplentrance interview conducted on 830615, to describe NRC planned insplactivities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related mathematical encludes of the Arizona Public Service Co 82/06/15 ROEDEL, J A Arizona Public Service Co 402 20904 102 24X Fiche 50-528,83/09/08,8310240197
- ---B310240227 Discusses status of special inspire allegations, in response to 830411 memo Lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to 830601 Relevant documents issued & received encl MARTIN: JB Region 5. Office of Director 83/05/02 CUNNINOHAM, GH Office of the Executive Legal Director 820904 104 24X Fiche 50-528,83/09/08,8310240197
- --8310240237 Forwards documents re FOIA request for NRC investigation.
 insps or repts on allegations made by R Gunderson & W Roure
 concerning facilities Excerpt of installation spec for cable
 splicing encl
 ALEXANDER: Region 5. Office of Director 83/08/19 TOMS, N
 NRC No Detailed Affiliation Given 9pp 20904 112 24X
 Fiche 50-528,83/09/08.8310240197
- --8310240251 Discusses immediate effectiveness review of facilities re analysis of pending insp/investigation items identified in Ofc of Insp & EDO repts of 830325 & 29 Presumes SECY will extend review time to accommodate Commission consideration ASSELSTINE, J K Commissioners 83/04/01 PALLADING Commissioners 1p 20904 131 24X Fiche 50-528,83/09/08, 8310240197
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Gualification Tests " Syc list enci JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Byc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308380342

- 8310140238 Interim Deficiency Rept DER 83-46 re Borg Warner valve manually overtorqued during hydrostatic testing Initially reported on 830715 Time extension until 831214 requested for final rept. due to extension until 831214 requested for final rept. due to extension investigation required VAN BRUNT, E E Arizona Public Service Co 83/09/28 STERNBERO, D M Regian 5. Office of Director 2pp 20761 321 24X Fiche 50-528,83/09/28,8310140238
- 8310250415 Interim Deficiency Repts DER 82-87.DER 82-64 & DER 83-32 re conditions & circumstances surrounding design processes involved w/dissimilar metal socket welds VAN BRUNT.E E Arizona Public Service Co 83/10/06 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 2pp 20897 245 24X Fiche 50-528,83/10/06.8310250415
- 831025056B Final Deficiency Rept DER 83-38 re Steiler Steel clip angles used for HVAC supports that do not meet ASTM A-36 requirements Initially reported on 830628 Deficiency determined not reportable per 10CFR50 55(e)

 VAN BRUNT, E E Arizona Public Service Co 83/10/06 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 93pp 20901 324 24% Fiche 50-528,83/10/06.8310250568
- 8310270409 Interim Deficiency Rept DER 83-36 re excessive recycling of ITT hydramotor actuators Initially reported on 830629 Due to extensive investigation & evaluation, final rept expected by 83/10/12 BISHOP, T W
 - B31208

 VAN BRUNT,E E Arizona Public Service Co B3/10/12 BISHOP

 Bivision of Resident.Reactor Project & Engineering Programs

 20924 031 24X Fiche 50-530,83/10/12,8310270409

U Congressional/Executive Correspondence

- 8310240217 Requests response to issues raised by J Morrison 830703 lt1 expressing concerns w/manner in which Hegional V & Ofc of Envestigation handled allegations of violations at plant J Morrison 830703 ltr encl UDALL, M K House of Rep , Interior & Insular Affairs 83/07/17 PALLADINO, N Commissioners 4pp 20904 040 24X Fiche 50-528,83/09/08,8310240197
- --8310240241 Notifies of receipt of T Woods 820511 ltr to NRC re allegations about safety at facilities Requests to be advised of any action taken by NRC in subj matter RUDD, E House of Rep 82/05/19 PALLADINO,N J Commissioners 1p 20904 129 24X Fiche 50-528.83/09/08.8310240197
- --8310240246 Ack receipt of 820519 ltr to Chairman Palladino expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter u/legal assistance
 KAMMERER, C Office of Congressional Affairs 82/06/01 RUDD, E House of Rep 1p 20904 130 24X Fiche 30-528, 83/09/08, 8310240197

V Operator Examinations

8310030154 Requests achedule, by 830928, for regualification training & 110030154 Requests schedule, by 830428, for requalification training exams for 1984 in order to coordinate Region V audit of operator requalification programs
BIGHOP.T W Division of Resident Reactor Project & Engineering Programs 83/09/26 ANDOGNINI.G C Arizona Public Service Co
2pp 20590 030 24X Fiche 50-528,83/09/26,8310030154

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

- B310260309 Summarizes B30808 informal meeting on contract ra PRA review of CRBR (Task 4) & NRC concerns associated w/Technology for Energy Corp deliverables schedule JOHNSON, B Science Applications, Inc NRC-03-82-096 83/08/11 SPAND, A NRC No Detailed Affiliation Given 10pp 20911 343 24X Fiche 50-537,83/08/11,8310260309
- 8310050405 Notification of B31004 meeting w/util, DOE & Project Mgt Corp in Bethesda, MD to discuss applicants probabilistic risk assessment STARK, R. M. Clinch River Breeder Reactor Program Office B3/09/2 QRACE, J. N. Clinch River Breeder Reactor Program Office 4pp 20450 004, 24X Fiche 50-537, B3/09/24, B310050405. 8210079A
- 8308300357 Board Notification 82-105A forwards evaluation of allegations re design deficiencies in Class I piping sys Info applicable to Diablo Canyon i & 2.Fermi 2 & Collaway EIBENHUT,D Q Division of Licensing 83/09/29 PALLADING,N J. Commissioners. 3pp 20632 001 24X Fiche 50-000.83/09/29, 8308300357

- 8310130159 Notification of 831095 meeting w/DOE, Project Mgt Corp & util in Oak Bidge, TN to discuss applicants equipment storage in Oak Ridge. Th to discuss applicants equipment storage requirements
 STARK.R M Clinch River Breeder Reactor Program Office. 83/10/05
 GRACE.J N Clinch River Breeder Reactor Program Office 3pp
 20777 175 24X Fiche 50-537.83/10/05.8310130159
- 8308300771 Board Notification 83-128A forwards Equipment Gualification Branch conclusions regutential problems w/ASCO splenoid Valves
 EISENHUT,D G Division of Licensing 83/10/06 PALLADINO,N J.
 Commissioners 31pp 20818 001 24X Fiche 50-000,83/10/06,8308300771
- 8308310050 Board Notification 83-160 provides info re 830812 failure of main crankshaft on one of three Transamerica Delaval emergency diesel generators at Shorsham EISENHUT.D G Division of Licensing 83/10/14 PALLADINO.N J Commissioners 15pp 67056 070 24X Fiche 50-000,83/10/14, 2000
- 8310310059 Summarizes 831004 meeting w/NRC.ACRS & LNR Assoc re mgt of CRBR PRA program Viewgraphs & list of meeting attendees encl GAYIOAN.F X Energy. Dept of, Clinch River Breeder Reactor Plant. 83/10/24 GRACE.J N Clinch River Breeder Reactor Program Office 19pp 20951 005 24X Fiche 50-537.83/10/24.8310310059

G Adjudicatory correspondence

8308310050

- 8310130150 Response to ASLB 830915 order, applicant 830921 motion to close record & motion for leave to file NRC affidavit & supplemental proposed findings of fact Supports motion to close record TURK,S E Hearing Branch I. 83/10/06 Atomic Safety and Licensing Board Panel 6pp 20724:251 24% Fiche.50-537,83/10/06.
- --8310130152 Affidavit of SJ Brocoum.RL Rothman & RB McMullen providing NRC evaluation of recent discovery of faults at site Faults not capable & do not represent hazardous site condition BROCOUN.8 J. ROTHMAN.R L. MCMULLEN.R B Geosciences Branch 83/10/06 18pp 20724 257 24X Fiche 50-537.83/10/06.8310/30150
- --B310130156 Supplemental proposed findings of fact re site faults.
 Certificate of Svc encl
 TURK, S E Hearing Branch 1 83/10/06 5pp 20724.275 24X
 Fiche 30-537,83/10/06.8310130150
- 8310260272 Supplemental citations supporting thesis that following hydrodynamic core disruptive accident reactor vessel closure head is more susceptible to failure than reactor vessel head Certificate of SVx encl EDGAR, G.L. Project Management Corp. EDGAR, G.L. Edger, G.L. LUCK, W.D. Energy, Dept. of 83/10/25, 7.pp. 20912 001 24X Fiche 50-537,83/10/25,8310260292
- 8310240301 Order accepting into evidence, applicant 8309R1 & NRC 831004 written responses to ASLB 830915 request for seismic info Ruling on applicant motion to close record deferred. NRDC response to Hulman affidavit will be reviewed by ASLB MILLER.M E Atomic Safety and Licensing Board Panel. 83/10/25, 4gp 20911 035 24X Fichs 80-537.83/10/25,8310240301.

O Inspection reports, IE Bulletins & correspondence

- 8310250231 Forwards IE Insp Rept 50-537/83-10 on 630901-02 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 83/09/22.
 BREWINGTON, P Tennessee Valley Authority 2pp. 20899-047 E
 Fiche. 50-537, 83/09/22, 8310250231.
- --8310250236 IE Insp Rept 50-537/83-10 on 830901-02. No noncompliance noted Major areas inspected site preparation & structural concrete concrete
 HARRIB.J.R. Region 2, Office of Director. CONLON.T E Division
 of Engineering & Operational Programs 83/09/20. 3pp. 20899:049
 24X Fiche 50-537.83/09/22.8310250231.
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 117pp 20754 022, 24X Fiche 50-000,83/09/26,8308300340.
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Rome Ventilation Air Intakes " Svc list and JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777-210 24X Fiche-50-000,83/09/26,8308300342

- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Svc list encl JORDAN.E i. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20-778 001 24X Fiche 50-000.83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 100FR50 59 Evaluation " Syc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/29 Convolidated Edison Co of New
 York, Inc 115pg 20716 324 24X Fiche 50-000,83/09/29,83083000349
- B30B300378 IE Info Notice B3-65, "Surveillance of Flow in RYD Bypas» Logs Used in Westinghouse Plants " Svc list encl JURDAM.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E. Davisson of Emergency Preparedness & Engineering Response (Post 839103) 83/10/07 Consolidated Edison Co of Ne York, Inc 79pp 20882 026 24% Fiche 30-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Gauss Production of Nozious Gases " Svc list encl JORDAN: E Division of Emergency Preparedness & Engineering Response (Post B30)031 B2/10/11 Composidated Edison Co of New York: Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300757
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830:03) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fithe 50-000,83/10/11,8,308300761

DOCKET BIN-50-546 MARBLE HILL MUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B310040428 Forwards status of outstanding Third Quarter 1983 commitments in amends to FBAR Description of containment hydrogen monitoriing sys will be submitted during First Quarter 1984 SHIELDS, 5 W Public Service Co of Indiana. Inc 83/09/30 DENTON, H R Office of Nuclear Reactor Regulation, Director. 20617.106 24X Fiche 50-545.83/09/30.8310040428
- 10240179 "Independent Const Review of Merble Hill Units 1 & 2,"
 Vol 1: "Executive Summary "
 * Tarrey Fines Technology GA-C17258 Vol 83/09/30 25pp
 20878 115 24X Fichs 50-346:83/09/30,8310240178
- B310240179 "Independent Const Review of Marble Hill Units 1 & 2,"
 Vol 2. "Fragram Results "
 * Torrey Pines Technology GA-C17258 V02 B3/07/30 129pp
 20878 144 24X Fichs 50-546,83/07/30.8310240178
- -8310240182 "Independent Const Review of Marble Hill Units 1 b 2."

 Vol 3. "Potential Finding Repts & Corrective Action Plans "

 Torrey Pines Technology GA-C17258 VO3 83/09/30 327pp

 20878 273 24X Fiche 50-546,83/09/30.8310240178
- 8310130047 Notification of 831013 meeting w/util in Bethesds. ND to discuss Geosciences Branch request for addl info O'CONNOR, P.W. Licensing Branch 1 83/10/03 YOUNGBLOOD, B.J. Licensing Branch 1 3pp 20776 234 24X Fiche 50-546,83/10/03, 1310130047
 - B300775 Board Notification 83-135A forwards 830919 revised draft of GA Case Study Morking Paper Case C, * & cover & ransatital manos re Diablo Canyon ISEMAUT, D. & Division of Cicensing 83/10/14 PALLADINO, N. J. 308300775 3pp 20799 001 24X Fiche, 50-000, 83/10/14,
 - 310180505 Informs that working papers for three QA case studies complete, par 830923 memo. Case C re Diable Canuon, dtd 830919, is rev to 830719 draft transmitted in Roard Notification 83-135 on 830902. Papers & transmitted ltrs forwarded 7AYLORUJ QA Branch 83/09/28 EISENHUID © Division of Licensing 2pp 20799 GO4 24X Fichs 50-000, 83/10/14, 8308300775
- O310133 Ack receipt of 830902 request for extension to submit 20-day response to Generic Ltr 83-28 re Salem ATHS events equest granted Submittal by 840401 requested DUNO9L000, 8. J. Licensing Branch 1 83/10/19 SHIELDS, 8 W Public Prvice Co. of Indiana, Inc.: 2pp 20965 316 24x

- C Utility Environmental Report (ER), amends & correspondence
- 83i0110383 Forwards request for addl info to environ review requires to complete evaluation of application for OLs Requests results of review of environ rept YOUNOBLOOD, B. J. Licensing Branch i 83/09/28 BHIELDS, § # Publish Service Co. of Indiana, Inc. 7pp 20/13 297 24X Fiche 50-546,83/09/28,83i0110/883
- 8310110501 Forwards request for odd1 info required to complete evaluation of environ rept Response requested by 831101 1 10000086.030,8 J Licensing Branch I 83709729 SHITLES,8 M. Public Service Co of Indiana, Int App 20/14 360 24X Fiche 50-546,83/09/29,8310110501
- G Adjudicatory correspondence
- 9310260291 Petition of Bave the Valley for leave to intervene, listing 15 contentions re integrity of concrete in safety-related structures, electrical work ovacuation plans & common mode failures Certificate of Sec enc. CASSIDY.H G. Save the Valley Save Morble Hill 80/10/21 Office of the Secretary of the Commission App. 20911 337 244 Fiche 50-546.89/10/21.8310260291
- 83(0310177 Informs that recent filings by intervenors received by A'th wordy one copy for all three members Procedures require each party & ASI U member to be served individually ASI It requires all parties comply w/groper filing procedures MORAN, D M Atomic Safety and Licensing Board Panel 83/10/20 Ip 20959 001 247 Fiche 50-546.83/10/28.8310310179
- O Inspection reports. IE Bulletins & correspondence
- 8310040390 Expresses appreciation for conperation w/IL activities to comply w/Congressional direction to NRC to porform GA studies & pilot program Draft GA case study working paper enci TAYLOR, J.M. Division of GA. Bafeguards & Inspection Programs (Post 830(63) 83/08/02 SHIELDS, B.W. Public Bervice Co. of Indiana. Inc. 74pp. 20420-049 24X Fiche 90-546,83/08/02,83100/00390
- 8310040526 Forwards IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 & notice of violation RNGP.R C Region 3, Office of Director 83/09/13 SHIELDER 11 H Public Service Co of Indiana. Inc 2pp 20623 268 24X Fiche 50-546,83/09/13,8310040526
- --8310040531 Notice of Violation from insp pp 830701-0831 # Region 3, Office of Director 83/09/13 lp 206 Fiche 50-546,83/09/13,8310040526 20423 270
- --B310040540 IE Insp Repts 50-546/B3-15 & 30-547/B3-15 on B30/D1 OE II Noncompliance noted failure to document nonconforming condition re I beam column linear indication SCHAPKER, J F , KONKLIN, J E Region 3, Defice of Director B3/09/12 Bpp 20623 271 24X Fishb 50-546,83/09/13,83100400006
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Wolder Gualification Tests "(Svc list encl JORDAN, E L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fichs 50-000,83/09/26,8300300-140
- 8308300342 IE Info Notice 83-62, "Failure of Radundant Toxic Gas Detactors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 80-000,83/09/26,8308309344
- 830B300345 IE Info Notice 83-60, "Potential Failures of Westinghouse Type SA-1 Differential Relays " Syr list enci JARDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24% Fiche 50-000.83/09/26, 020E400345
- 8308300349 IE Info Notice 83-64. "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation." Syc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/29 Consolidated Edison Co of New
 York, Inc 115pp 20716 324 24X Fiche 50-000,83/09/29,83083000349
- 8308300378 IE Info Notice 89-85. "Surveillance of Flow in RYD Dypass Loops Used in Westinghouse Plents." See list encl JORDAN, El Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/07. Consultdated Edison Ca of New York, Inc 76pp 20827 213 24X Fiche 50-000, 83/10/07, 83/8300378

- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility 'Svc list enci JORPAN, E.L. Bivision of Emergency Preparedness & Engineering Response (Post 8:30103) 83/10/07 Consolidated Edison Co. of Nei York, Int. 77pp 20882 026 24X Fishe 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043-075-24X Ficho 50-000.83/10/11.8308300759
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Syc list ORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827-129 24X Fiche 50-000,83/10/11,8308300761
- 8310180233 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 83/10/14 SHI 0808 1/4 24X MAXELSON,W.L. Region 3, Office of Director 83/10/14 Public Service Co. of Indiana, Inc. 7pp 20808 1/4 Fiche 50-545,83/10/14,83101808/3 SHIELDS, S W
- 8310240066 Ack receipt of 831011 it: informing NRC of steps taken to correct violations noted in IL lnsp Repts 50-546/83-15 & Fublic Service Co of Indiana, Inc. ip 20878 099 24X 50 546.83/10/19,8310240066
- --8310240081 Responds to NRC 8J0913 ltr re violations noted in II Insp Repts 50-546/83-15 & 50-547/63-15 Corrective actions directive will be issued to Pullman Const Industries emphasizing resposibility for reporting nonconformances SHIELDS, S. W. Public Service Co. of Indiana, Inc. 83/10/11 KEPPLER. J. G. Region 3. Uffice of Director 2pp. 20878 100 P4X Fiche 50-546,83/10/19,8330240066
- 8310280175 Forwards ltrs to Comm Ed & Byron integrated design insplicpt identifying GA & design verification issues for Byron & Braidwood stations Response required within 90 days YOUNGBLOOD, B J Licensing Branch i 83/10/17 SHIELDS, B W Public Service Co of Indiana, Inc. Spp. 20764 144 24X Fiche 50-546,83/10/17,8310280175
- S Reportable occurrences. Liks & related correspondence
- 8310040337 Interim deficiency rept re potential for spec/design changes to remain unincorporated in as-built configuration of safety-related equipment or structures Initially reported on Bit208 Procedure changes in progress Next rept by B40217 SHIELOB.5 W Public Service (o of Indiana, Inc. B3/09/30 KEPPLER.J & Region 3, Office of Director 2pp. 20446 129 P4X Fiche 50-546.83/09/30.8310060:837
- 83i02i0023 Interim deficiency rept re indications that Pullman Const Industries, Inc failed to adequately implement GA program Initially reported on 830228 Reinsp continuing Next rept will be submitted by 840210 SHIELDS, 8 W Public Service Co of Indiana, Inc 83/10/13 KEPPLER, J G Region 3, Office of Director 2pp 20858 204 24X Fiche 50-546,83/10/13,8310210025
- 8310270378 Interim deficiency rept re Westinghouse centrifugal charging pumps at min allowable flow rate when RCS reaches value below pressurizer safety value setypoint pressure Instially reported on 800507 Also rejorted per Part 21 SHIELDB.8 W Public Service to of Indiana. Inc 83/10/20 KEPPLER.J O Region 3. Office of Director 2pp 20724 034 24X Fiche 50-546.83/10/20,8310270375
- B310270458 Interim deficiency rept re welding techniques not covered by GA grogram used in fabrication of safety-related switchgear Initially reported on 820525 GA menual rewritten & procedures revised to include controls on welding SHIELDB.5 W Public Service (o of Indiana. In: 83/10/20 KEPPLER.J Q Region 3. Office of Director 2pp 20723 105 24X Fiche 50-546.83/10/20.8310270458

- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8310040428 Forwards status of outstanding Third Quarter 1983 commitments in amends to FSAR Description of containment hydrogen monitoriing sys will be submitted during First Quarter 1984 SHIELDS: SW Public Service Co of Indiano, Inc. 83/09/30 DENTON H R Office of Nuclear Reactor Regulation, Director 20617 104 24% fiche 50-546.63/09/30.8310040428

260.

- 8310240178 "Independent Const Review of Marble Hill Units I & 2." Vol 1. "Executive Summary "

 * Torrey Pines Technology GA-C17258 Vol 83/09/30: 25pp 20878 115 24X Fiche 50-546.83/09/30.8310240178
- --8310240179 "Independent Const Review of Marble Hill Units 1 & 2," Vol 2, "Program Results" * Toriey Pines Technology GA-C17258 VO2 83/09/30 129pp 20878 144 24X Fiche 50-546,83/09/30,8310240178
- --0310240182 "Independent Const Review of Marble Hill Units 1 & 2," Vol 3, "Potential Finding Repts & Corrective Action Plans " * Torrey Pines Technology 0A-C17250 VO3 83/09/30 327pp. 20878 273 24X Fiche 50-546.83/09/30,8310240178
- 8310130047 Notification of 831013 meeting w/util in Bethesda, ND to discuss Geosciences Branch request for addl info O'CONNOR, P W Licensing Branch i 83/10/03 YOUNGBLOOD, B J Licensing Branch I 3pp 20/76 234 24X Fichs 50-546, 83/10/03, 8310130047
- 8308300775 Board Notification BC-135A forwards 830919 revised draft of "GA Case Study Working Paper Case C." & cover & transmittal memos re Diablo Canyon EISENHUT, D. O. Division of Licensing 83/10/14 PALLADINO, N. J. Commissioners app 20799 001 24X Fiche 50-000, B3/10/14, 8308300775
- --8310180505 Informs that working papers for three QA case studies complete, per 830923 memo Case C re Diablo Canyon, dtd 830919, is rev to 830719 draft transmitted in Board Notification 83-125 on 830902 Papers & transmittal ltrs forwarded TAYLOR, J M QA Branch 83/09/28 EISENHUT, D Q Division of Licensing 2pp 20799 004 24X Fiche 50-000, 83/10/14, 8308304 24X Fiche 50-000, 83/10/14, 8308300775
- 8310310153 Ack receipt of 830902 request for extension to submit 120-day response to Generic Ltr 83-28 re Salem ATWS events Request granted Submittal by 840401 requested YOUNOBLOOD, B J Licensing Branch 1 83/10/19 SHIELDS, S W Service Co of Indiana, Inc 2pp 20965 316 24X Fiche 50-546,83/10/17.8310310153 SHIELDS, S W Publi
- C Utility Environmental Report (ER), amends & correspondence
- B310110383 Forwards request for add1 info re environ review required to complete evaluation of application for OLs Requests results of review of environ rept YOUNOBLOOD, B J Licensing Branch 1 83/09/28 SHIELDB, 8 W Publi Service Co of Indiana, Inc. 9pp 20713 297 24X Fiche 50-546,83/09/28.8310110383
- 8310110501 Forwards request for addl info required to complete evaluation of environ rept Response requested by 831101 YOUNGELOOD, D J. Liconsing Branch 1 83/09/29 SHIELDB, S W Service Co of Indiana. Inc. 4pp 20714 360 24X Fiche 50-546,83/09/29,8310110501 Publi
- Adjudicatory correspondence
- B310260291 Petition of Save the Valley for leave to intervene, listing 15 contentions re integrity of concrete in safety-related structures, electrical work, evacuation plans & common mode failures Certificate of Svc encl CASBIDY, M o Save the Valley Save Marble Hill 83/10/21 Office of the Secretary of the Commission App 20911-357 24X Fiche 50-546.83/10/21,8310260291
- 8310310179 Informs that recent filings by intervenors received by ABLII w/only one copy for all three members Procedures require each party & ASLB member to be served individually ASLB requires all porties comply w/proper filing procedures MCRAN.D M Atomic Safety and Licensing Board Panel. 83/10/28 ip. 20759 001 24X Fiche 50-546,83/10/28,8310310179

- @ Inspection reports. IE Bulletins & correspondence
- 8310040390 Expresses appreciation for cooperation w/IE activities to comply w/Congressional direction to NRC to perform QA studies & pilot program Draft QA case study working paper encl
 TAYLOR, J M Division of QA, Safeguards & Inspection Programs (Pos
- enci enci TAYLOR, J M Division of GA, Safeguards & Inspection Programs (Post 830103) B3/08/02 SHIELDS, S W Public Service Co of Indiana, Inc 76pp 20620 049 24X Fiche 50-546, 83/08/02, 8310040390
- 8310040526 Forwards IE Insp Repts 50-546/83-15 & 50-547/83-15 on 83D701-0831 & notice of violation KNOP.R C Region 3. Office of Director 83/09/13 SHIELDS, 8 W Public Service Co of Indiana. Inc 2op 20623 268 24X Fiche 50-546,83/09/13,8310040524
- --8310040531 Notice of violation from insp on 830701-0831 * Region 3. Office of Director 83/09/13 ip 20623 2/0 24x Fiche 50-546.83/09/13.8310040596
- --8310040540 IE Insp Repts 30-546/83-15 & 50-547/83-15 on 830701-0831 Noncompliance noted failure to document noncomforming condition re I beem column linear indication SCHAPKER, J.F. KDAKLIN, J.E. Region 3, Office of Director 83/09/12 8pp 20623 271 24X Fiche 50-546.83/09/13,8310040526
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ens for Welder Gualification Tests " Svc list encl JORDÁN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison to of New York Inc 117pp 20754 022 24X Fishe 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant loxic Gas Detactors Positioned at Control Room Ventilation Air Intakes" Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63, "Potential Failures of Mastinghouse Type 8A-1 Differential Relays " Syt list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fiche 50-000, 83/09/26, 8308000345
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 809103) 83/10/07 Consolidated Edison Co of New York Inc 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN E L Division of Emargency Preparedness & Engineering Response (Post 630103) 83/10/07 Consulidated Edison Co of New York, Inc 75pp 20882 026 24x Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emgrgency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc Jist encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Inc 117pp 21043 075 P4X Fiche 50-000,83/10/11.830830075/7
- 8308300761 IE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svt list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fithe 50-000, 83/10/11, 8308300761
- 8310180233 Clarifies NRC position re procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Updates will be provided every 6 months AXELSON.W.L. Region 3. Office of Director 83/10/14 SHIELDS, S.W. Public Bervice Co. of Indiana. Inc. 7pp 20808 174 24X Fichs 50-546,83/10/14,8310180833
- B310240066 Ack receipt of 83101) ltr informing NRC of steps taken to correct violations noted in lE Insp Repts 50-546/83-15 & 50-547/83-15 KNOP.R C Region 3. Office of Director 83/10/19. SHIELDS, S W. Public Service Co of Indiana, Int. 1p 20878 099 24X Fiche 50-546,83/10/19,8310240066
- --8310240081 Responds to NRC 830913 ltr re violations noted in IE Insp Repts 50-346/83-15 & 50-547/83-15 Corrective actions directive will be issued to Pullman Const Industries emphasizing respossibility for reporting nonconformances SHIELDS.S W Public Service Co of Indiana. Inc 83/10/11 KEPPLER.J 9 Region 3. Diffice of Director 2pp 20878 100. 24X Fiche: 50-546,83/10/19,8310240066

- 8310280195 Forwards ltrs to Comm Ed & Bulon Integrated design inspiring identifying GA & design verification irruos for Bulon & Braidwood stations Response required within 90 days YOUNGBLOOD, B J Licensing Branch | BJ/10/19 SHILLDS, S W Public Service Co of Indiana. Inc. 2pp 20964-144 24X Fiche 50-546.8710/19.8310/80199
- S Reportable providences, LLRs vielated correspondence
- B310060337 Interim deficiency right re-potential for spec/design changes to remain unincorporated in an about configuration of safety-related equipment or structures Instally reported on B11208 Procedure changes in progress Next rept by 840217 SHIELDS: S.W. Public Service (o. of Indiana, Inc. 83/09/30 KEPPLER: J.G. Region 3, Office of Director 2pp 20646-129 P4X Fiche 50-546,63/09/30,8310060337
- 8310170530 Final rept re cracks in welds at stiffeners to box beams
 Initially reported on 830715 Welding method medified Cracked
 areas ground out & repaired using approved procedures
 SHIELDS.S W ("ublic Service (o of Indiana, Inc. 83/10/07
 KEPPLER.J & Region 3, Office of Director 2pp 20/94 234 24X
 Fiche 50-547,83/10/07.8310170530
- B310210025 Interim deficiency ript re indications that Pullman Const Industries Inc failed to adequately implement GA program Initially reported on B30228 Meinsp continuing Next rept will be submitted by 840210 SMIELDS, 8 W Public Service (e of Indiana, Inc B3/10/13 KEPPLER, J G Region 3, Office of Director 2pp 20858 204 24X Fiche 50-546,83/10/13,8310210075
- 8310270375 Interim deficiency ript ne Weitinghouse centrifugal charging pumps at min allowable flow rute when KCS reaches value below pressurizer safety valve setpoint pressure Initially reported on 800507 Also reported per Part 21 SHIELDS:8 W Public Service Co of Indiana. Inc 83/10/20 KEPPLERJ 6 Region 3, Office of Director 2pp 20724 034 24X Fiche 50-546.83/10/20.8310270799
- 8310270458 Interim deficiency rept re welding techniques not covered by GA program used in fabrication of safetu-related switchgear Initially reported on 820525 GA manual rowritten & procedures revised to include controls on welding SHIELDS.5 W Public Service Co of Indiana. Inc 83/10/20 KEPPLER.J & Region 3, Office of Director 2pp 20923 105 24X Fiche 50-546,83/10/20,8310270058
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNII 1
- 8310210177 Forwards Memorandum % Order ALAB-745, suggesting TVA file motion to terminate proceedings for canceled units SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel BURGER, J. F. Tennessee Valley Authority ip 20836-127 P4X Fiche 50-553, 83/10/19, 8310210177

DOCKET SIN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

- G Adjudicatory correspondence
- 8310210177 Forwards Memorandum & Order ALAB-745, suggesting TVA file motion to terminate proceedings for canceled units SHDEMAKER.C J. Atomic Safety and Licensing Appeal Panel 83/10/17 BURGER.J F. Teinessee Valley Authority 1p 20856 127 24X Fiche 50-553,83/10/19,8310210177

DOCKET STN-50-556 BLACK FOX STATION, UNII 1

G Inspection reports, IE Bulletins & correspondence

- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Welder Qualification Tests" Svc lint encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 PAX Fishe 50-000,83/09/26,8308300040
- 8308300342 IE Info Notice 83-68, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation All Intakes " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fishe 50-000,83/09/26,8308300342

- 8308300345 IE info Notice 83-63, "Potential Failures of Westinghouse Type SA-I Differential Relays " Svc list encl JURDAN, E. I. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308J00345
- 830830037B IE Info Notice 83-65, "Surveillance of Flow in R1D Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN, E 1 Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- B30B300752 IE Info Notice 63-66, "fatality at Argentine Critical Facility " Syc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300/57
- 8308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11,8308300761
- DOCKET STN-50-55/ BLACK FOX STATION, UNIT 2

 G Inspection reports, IE Bulletins & correspondence
- 8308300340 IE Info Notice 83-6i, "Alleged Use of Stand-Ins for Helder Gualification Tests " Svc list encl JORDAN, G. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 117pp 20754 022 24X Fiche 50-000.83/09/26,8308300340
- 6308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 116pp 20777 210 24X Fiche 50-000.83/09/26,8308300342
- 8308300345 IE Info Notice 83-43, "Potential Failures of Westinghouse Type 8A-1 Differential Relays " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26,8308300345
- B30B300349 IE Info Notice B3~64. "Lead Shielding Attached to Bafety-Related Sys W/g 10CFR50 59 Evaluation " Svc list encl JORDAN, E t Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/29 Consolidated Edison Co of New York, Inc 115pp 20716-324 24X Fiche 50-000.83/09/29.8308300349
- 8308300378 IE Info Notice 83-65, "Surveillance of Flow in RTD Bypess Loops Used in Westinghouse Plants " Svc list encl JORDAN, El Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 30-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66, "Fatality at Argentine Critical Facility " Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison in af New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67. "Emergency Use Respirator Matl Defect Causes Production of Noxious Cases "Eye list enel JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidate Edison Co. of New York, Inc. 117pp 21043 075 24X Fiche 50-000,83/10/11,8308300759
- B30B300761 IE Info Notice B3-6B, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl
 JURDAN, E L Division of Emergency Preparedness & Engineering
- encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York: Inc. 120pp 20827 129 24X Fiche 50-000:83/10/11:8308000761

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA
- 8310240225 Advises that Suppl 5 to AI-74-44, "SNM Control Program for EBR-II Blanket Fuel Decladding," acceptable subj to listed confirmation All decladding operations conducted within Cells 3 & 4 will be performed under inert atmosphere BROWN,W B Fuel Facility Safeguards Licensing Branch 83/08/25 REMLEY,M E Rockwell International Corp 2pp 20707 311
- 8310170071 Forwards app to Suppl 5 of "SNM Control Program for EPR-II Blantet Fuel Decladding," per 830825 request App clarifies orally presented info W/o encl # Rockwell International Corp 83/09/20 BROWN,W 8 Fuel Facility Safeguards Licensing Branch | Ip 20798 018
- 8310120390 Memorandum & order terminating proceeding No responses to Commission 830602 order meet intervention requirements NRC authorized to renew License SNM-21 when all regulatory requirements met LAZO.R M Atomic Safety and Licensing Board Panel. 83/10/07 8pp 20699 113
- DOCKET 70-0027 BABCOCK & WILGOX CO , LYNCHBURG, VA
- 8310240101 Revises License Condition 2 1 to Amend MPP-1 to License SNH-42 per 930429,0513.0608 & 0723 ltrs transmitting revised pages to foundamental nuclear matl control plan.

 BROWN.W B Fuel Facility Safeguards Licensing Brench B3/07/28 REGAN.N A Babcock & Wilcax Co ip 20891 355
- 8310170034 Application for amend to License SNM-42, Section IV refundamental nuclear matts control plan Encl restricted data withheld # Babcock & Wilcox Co 83/08/03 BRGMN, W B Fuel Facility Safeguards Licensing Branch 1p 20798 333
- B3i024008B Responds to B30721 ltr requesting time extension to complete requirements of iOCFR7O 50(e)(4)(i) for May-June 1983 mat1 balance period License SMM-42 revised by adding new unnumbered license condition BROWN.W B Fuel Facility Safeguards Licensing Branch. 83/08/04 REGANN A Babcock & Wilcox Co ip 20891:362
- 8310240210 Grants 10-day extension to meet NRC requirements for preparation & distribution of Form DDE/NRC 741 New unnumbered license condition added to Safeguards Amend MPP-1 to License SMM-42 to reflect extension BROWN.W B Fuel Facility Safeguards Licensing Branch 83/08/18 REGAN:N A Babcock & Wilcox Co 1p 20707 319
- 8310270556 Advises that Safeguards Amend MPP-1 to License SNM-42 revised, adding new License Condition 2 1.1, effective immediately Amend incorporates new pages to fundamental nuclear mat1 control plan proposed in 830803 & 23 ltrs.

 BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/24 REGAN, N A Babcock & Wilco: Cp ip 20743 352
- 8310170229 Advises that certain changes to physical security plan submitted on 830601 Changes do not decrease effectiveness of plan & were implemented per loc(R70 22(e)) REGANN A Babuck & Wilcox Co 83/08/25 O'REILLY, J P Region 2, Office of Director 2pp 20796 284
- 8310170315 Advises that revised pages to safeguards contingency plan submitted on 830427 Changes do not decrease effectiveness of plan & were implemented per 10CFR70 32to) REGANNA Baboock & Wilcox Co 83/08/25 O'REILLY. J P. Region 2, Office of Director 2pp 20795 278
- 8310040503 Forwards 1E Safeguards Insp Rept 70-0027/83-15 on 830726-27 No noncompliance noted.Rept withheld (ref 100FR2 770) STOHR,J P. Division of Emergency Preparadness & Materials Safety, 83/09/01 ECKERT,J P Babcock & Wilcox Co 2pp 20622:351
- B310170081 Forwards revised pages to License SNM-42 fundamental nuclear matls control plan.per B30B24 approval of amend request Encis withheld * Babcock & Wilcox Co. 83/09/02 BROWN,W B Fuel Facility Safeguards Licensing Branch Ip 21241 C67.
- 8310170727 Forwards Drawing LP-3239-EB, inadvertently omitted from attachment to 830601 ltr re changes to security plan.
 Photo of site facility details also transmitted W/o ancls REGAN,N A Babcock & Wilcox Co 83/09/08 Region 2, Office of Director ip 20797, 358

- G Inspection reports, IE Bulletins & correspondence
- 8310040370 Expresses appreciation for comperation w/IE activities to comply w/Congressional direction to NRC to perform GA studies & priot program Droft GA case study working paper enc!

 TAYLOR, J M Division of GA, Bafeguards & Inspection Programs (Post B30103) 83/08/02 SHIELDS. S W Public Service Co of Indiana, Inc. 76pp 20620 049 24X Fiche 50-546,83/08/02,8310040340
- 8310040526 Forwards IE Insp Repts 50-546/83-15 & 50-547/83-15 on 830701-0831 & notice of violation KNDP.R C Region 3. Office of Director 83/09/13 SHIELDS, S W Public Service Co of Indiana. Inc. 20p 20623 268 24X Fiche 50-546,83/09/13.8310040524
- --8310040531 Notice of Violation from inse on 830701-0831 * Region 3. Office of Director 83/09/13 lp 20623 270 24X Fiche 50-546.83/09/13.8310040526
- --8310040540 IE Insp Repts 50-545/83-15 & 50-547/83-15 on 83070[-08R]
 Noncompliance noted failure to document nonconforming
 condition re I beam column linear indication
 SCHAPKER, J F, KONKLIN, J E Repton 3, Office of Director
 83/09/12 dpp 20623 271 24X Fiche 50-546.83/09/13.8310040526
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Gualification Tests" Svc list entl JORDÁN,E L. Division of Emergency Preparedness & Engineering Response (Pust 830103) 83709726 Conselidated Edison Co. of New York Inc. 117pp 20754 022 24X Firms 50-000.83709726.83083800340
- 8308300342 IE Info Notice 83-62. "Failure of Redundant loxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Syr list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Notice 83-63. "Potential Failures of Westinghouse Type SA-1 Differential Relays " Bvc list encl. JORDAN,E L. Division of Emergency Precaredness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20778 001 24X Fiche 50-000,83/09/26,8308300345
- 8308300378 IE Info Notice 83-65. "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN,E L. Division of Emergency Preparodness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of Not York, Inc. 76pp 20827 213 24X Fiche 50-000,83/10/07.8308300378
- 8308300752 IE Info Notice 83-66, "Fatelitu at Argentine Critical Facility " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edyson Co of New York, Inc. 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Nozious Gases" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York Inc 117pp 21043 075 24X Fiche 50-000 83/10/11,830800075/7
- 8308300761 IE Info Notice 83-68, "Hespirator User Warning Defactive Belf-Contained Breathing Apparatus Air Cylinders " Svc list encl.

 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp. 20827 129 24X Fiche 50-000,83/10/11,8308300761
- 8310180233 Clarifies NRC position re-procedures for admitting NRC personnel to facility List of personnel requiring access to vital areas encl Vpdates will be provided every 6 months

 AXELSON.W L. Region 3, Office of Director 83/10/14 SHIELDS.G W Public Service Co of Indiana, Inc. 7pp. 20808 174 24X Fiche. 50-546, 83/10/14.8310180233
- 8310240066 Ack receipt of 83101) Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/83-15 & 50-547/83-15, Whoper C. Region 3, Office of Director, 83/10/17 SHIELDS, 9 W Public Service Co. of Indiana, Inc. ip. 20878 099 24% fiche 50-546.83/10/19.8310240066
- --8310240081 Responds to NRC 830913 ltr re violations noted in IE Insp Repts 50-546/83-15 & 50-547/83-15 Corrective actions directive will be issued to Pullman Const Industries emphasizing resposibility for reporting nonconformances. SHIELDS & W. Public Service Co. of Indiana. Int. 83/10/11. KEPPLER, J. G. Region 3. Office of Director. 2pp. 20878 100 24X Fithe-50-546.83/10/19.8310240066

- 8310280199 Forwards ltrs to Comm Ed & Buyon integrated design into lept identifying QA & design verification induces for Buyon & Braidwood stations Response required within 90 days YOUNGBLOOD, B J Licensing Branch 1 83/10/19 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp 20/64 144 24X Fiche 50-546.8 //10/19.8310/80195
- S Reportable occurrences, LERs & related correspondence
- 8310060337 Interim deficiency ript re potential for spec/design changes to remain unincorporated in as built configuration of affety-related equipment or structures Initially reported on Bil208 Procedure changes in progress Next rept by 840217 SHELDS, SW Public Service to of Indiana, Inc. 83/09/30 KEPPLER, J & Region 3, Office of Director 2pp. 20446 129 P4X Fiche 50-546,81/09/30,8310040333
- 0310170530 Final rept re cracks in welds at stiffeners to box beams
 Initially reported on 830715 Welding method modified Cracked
 areas ground out & repaired Using approved procedures
 SHIELD9.8 W Public Service (o of Indiano, Inc. 03/10/0/
 KEPPLER.J G Region 3. Office of Director 2pp 20704 234 24X
 Fichs 50-547.03/10/07.8310170530
- 8310210025 Interim deficiency ript re indications that Pullman Const Industries, Inc failed to adequately implement GA program Initially reported on B30228 Heimsp continuing Next rept will be submitted by 840210 SHTELDS, 8 W Public Service to of Indiana, Inc 83/10/13 KEPPLER, J G Region 3, Office of Director 2pp 20858 204 F4X Fiche 50-546,83/10/13,8310210025
- 8310270395 Interim deficiency ript re Weitinghouse centrifugal charging pumps at min allowable flow rate when ktS reaches value below pressurises safety valve setpoint pressure Initially reported on 800509 Also reported per Part 21 SHIELDS.S W Public Service Co of Indians, Inc 89/10/20 KEPPLER.J G Region 3, Office of Director 2pp 20724 034 P4X Fiche 50-546,03/10/20.8310270375
- B310270458 Interim deficiency rept re welding techniques not covered by GA program used in fabrication of safety-related switchgear Initially reported on B20525 GA manual rewritten & procedures revised to include controls on welding SHIELDS.5 W Public Service (o of Indiana, Inc. B3/10/20 KEPPLER.J G Region 3, Office of Director 2pp 20923 10) 24X Fiche 50-546,83/10/20,8310J70408
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1
- 8310210177 Forwards Memorandum & Order ALAB-745, suggesting TVA file motion to terminate proceedings for canceled units SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel B3/10/17 PURGER, J. Tennessee Valley Authority 1p 20856 127 PAX Fache 50-553,83/10/19,8310210177

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

8310210177 Forwards Memorandum & Order ALAB-745, suggrsting TVA file motion to terminate proceedings for canceled units SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/10/19 BURGER, J. F. Tenessee Valley Authority 1p 20856-127 24X Fiche 50-553,83/10/19,8310210177

DOCKET STN-50-956 BLACK FOX STATION, UNII 1 9 Inspection reports, IE Bulletins & collespondence

- 8308300340 IE Info Notice 83-61, "Allaged Use of Stand-Ins for Welder Qualification Tests" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 117pp 20754 022 P4X Ficher 50-000, 83/09/26, 8308300340
- 8308300342 IE Info Notice 83-62, "Fai)ure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/09/26 Consolidated Edison Co of New
 York, Inc. 116pp 20777 210 24x Fiche 50-000,83/04/26,8308300342

- 8308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type SA-i Differential Relays " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/07/26 Consolidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000,83/09/26,8308J00345
- 8308300378 JE Info Notice B3-45. "Surveillance of Flow in RID Bypass Loops Used in Westinghouse Plants" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000.83/10/07.8308300378
- B30B300752 IE Info Notice B3-66. "Fatality at Argentine Critical Facility " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3710/07 Consolidated Edison Co of New York Inc 79pp 20882 026 24X Fiche 50-000.83/10/07.8308300752
- B308300759 IE Info Notice B3-6/. "Emergency Use Respirator Matl Defect Causes Production of Noticus Gases " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/10/11 Consolidated Edison Co. of New York, Inc. 117pp 21043 075 24X Firhe 50-000.83/10/11.8308300/57
- 8308300761 lE Info Notice 83-68. "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders" Svc list encl
 JORDAN, L L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 (punolidated Edison Co of New York, Inc. 120pp 20827 129 24X Fiche 50-000,83/10/11.8308300761
- DOCKET STN-50-55/ BLACK FOX STATION, UNIT 2
- Q Inspection reports, IE Bulletins & correspondence
- 8308300340 1E Info Notice 83-61, "Alleged Une of Stand-Ins for Wulder Gualification Tests" Suc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co of New York, Inc. 117pp 20754 022 24% Fiche 50-000,83/09/26,8308300340
- 8308300342 IE Info Notice 83-62, "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co. of New York, Inc 116pp 20777 210 24X Fiche 50-000,83/09/26,8308300342
- 8308300345 IE Info Nutice B3-63, "Potential Failures of Westinghouse Type BA-1 Differential Relays " Byr list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consulidated Edison Co of New York, Inc 118pp 20778 001 24X Fiche 50-000.83/09/26.8308300345
- B308300347 IE Info Notice 83-64. "Lead Shielding Attached to Bafety-Related Sys W/o 10CFR50 59 Evaluation " Svc list enc! JCRDAN.E t Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/29 Consolidated Edison Co of New York, Inc 115pp 20716 324 24% Fiche 50-000.83/09/29,8308300349
- 8308300378 IE Info Notice 83-45, "Burveillance of Flow in RTD Dypass Loops Used in Westinghouse Plants" Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 76pp 20827 213 24X Fiche 50-000,83/10/07,8308300378
- 8308300752 IE Info Notice 83-66. "Fatality at Argentine Critical Facility " 8vc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000.83/10/07.8308300752
- 8308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp 21043 075 24X Ficha 50-000,83/10/11,8308300759
- 8308300761 LE Info Notice 83-68, "Respirator User Warning: Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Pust 830103) 83/10/11 Consolidated Edison Co of New York, Inc 120pp 20827 129 24X Fiche 50-000.83/10/11.8308300761

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP . CANDOA PARK, CA
- B310240225 Advises that Suppl 5 to AI-74-44, "SNM Control Program for EBR-II Blanket Fuel Decladding," acceptable subj to listed confirmation All decladding operations conducted within Cells 3 & 4 will be performed under inert atmosphere. BROWN, W B Fuel Facility Safeguards Licensing Branch. B3/08/25 REMLEY, M E Rockwell International Corp 2pp 20907 311.
- 8310170071 Forwards app to Suppl 5 of "SNM Control Program for EPR-II Blanket Fuel Decladding," per 830825 request App clarifies orally presented info W/o encl # Rockwell International Corp 83/09/20 BROWN.W B Fuel Facility Safeguards Licensing Branch by 20798 018
- 8310120390 Memorandum & order terminating proceeding No responses to Commission 8306.02 order meet intervention requirements NRC authorized to renew License SNM-21 when all regulatory requirements mot LAZO.R M Atomic Safety and Licensing Board Panel, 83/10/07 App. 206.99 113
- DOCKET 70-0027 BABCOCK & WILCOX CD . LYNCHBURG. VA
- B310240101 Revises License Condition 2 1 to Amend MPP-1 to License SNM-42 per B30429.0513.060B & 0723 ltrs transmitting revised pages to fundamental nuclear matl control plan BROWN.W B Fuol Facility Safeguards Licensing Branch B3/07/28 REGAN.N A Babcock & Wilcox Co 1p 20891 355
- 8310170034 Application for amend to License 8NM-42 Section IV re fundamental nuclear maths control plan. Encl restricted data withheld # Babcock & Wilcox Co 83/08/03 BRDWN, W B Fuel Facility Safeguards Licensing Branch ip 20798 333
- 8310240088 Responds to 830721 ltr requesting time extension to complete requirements of 10CFR70 50(e)(4)(i) for May-June 1983 mat1 balance period License SNM-42 revised by adding new unnumbered license condition BROWN.W B Fue) Facility Safeguards Licensing Branch 83/08/04 REGAN.N A Babcock & Wilcor Co ip 20891 362
- 8310240210 Grants 10-day extension to meet NRC requirements for preparation & distribution of Form DOE/NRC 741 New unnumbered license condition added to Bafeguards Amend MPP-1 to License SNM-42 to reflect extension BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/18 REGAN, N A Babcock & Wilcox Co ip 20907 319
- 8310270556 Advises that Safeguards Amend MPP-1 to License SNM-42 revised, adding new License Condition 2 l 1, effective immediately Amend incorporates new pages to fundamental nuclear mati control glan proposed in 830803 & 23 ltrs BROWN.W B Fuel Facility Safeguards Licensing Branch B3/08/24 REGAN.N A Babcock & Wilcox Co lp 20943 352
- 9310170229 Advises that certain changes to physical security plan submitted on B30601 Changes do not decrease effectiveness of plan & were implemented per 100FR70 32(e) REGAN,N,A Babucck & Wilcox Co B3/08/25 O'REILLY,J.P Region 2, Office of Director 2pp 20796 284
- 8310170315 Advises that revised pages to safeguards contingency plan submitted on 830629 Changes do not decrease effectiveness of plan & were implemented per 100FR70 32(e) REGAN,N A Babcock & Wilcox Co 83/08/25 O'REILLY, J.P. Region 2, Office of Director 2pp 20795 278
- B310040503 Forwards IE Safeguards Insp Rept 70-0027/B3-15 on B30726-29. No noncompliance noted Rept withheld (ref 10CFR2 790) BTDHR, J P Division of Emergency Preparedness & Materials Hafety B3/09/01 ECKERT, J P Babcock & Wilcox Co 2pp 20622 351.
- 8310370081 Forwards revised pages to License SNM-42 fundamental nuclear matls control plansper 830824 approval of amend request Encls withheld * Baboock & Wilcox Co 83/09/02 BROWN, W B Fuel Facility Safeguards Licensing Branch ip 21241.067
- 8310170727 Forwards Drawing LP-3239-88, inadvertently emitted from attachment to 830601 ltr re changes to security plan. Photo of site facility details also transmitted, M/o encls REGAN, N A Babcock Milcox Co 83/09/08 Region 2, Office of Director 1p 20797 358

- B310040409 Forwards IE Safeguards Insp Rept 70-0027/83-18 on B30023-24 No noncompliance noted BTORN, J P Davision of Emergency Preparedness & Materials Safety B3/09/14 ECKERT. J P Babcock & Wilcox Co 2pp 20629 348
- GOVOTOTO TO COMMITTE BARCOCK & MILLOR GO 200 20022 348
- --8310040493 IE Safeguards Insp Rept 70-0027/83-18 on 800823-26 No noncompliance noted Major areas inspected licensee action on previous findings & inventory differences & associated limit of error Details withheld (ref 10CFR2 790) JONES D U , MCALPINE E J Region 2, Office of Director 83/09/14 1p 20622 350
- 8309200181 Ack receipt of 830401 ltr transmitting 830401 rev to physical security plan Rev transferred to Fuel Facility Safeguards Licensing Branch of NMSS BTDRR, UP Division of Emergency Preparedness & Materials Safety 83/09/14 ECMERT, UP Babcock & Wilcox Co 1p 20430 336
- 831017006# Forwards revised pages of B30803 application for safeguards amond to License BNM-42, per request Rev replaces info submitted on B30702 Pages withheld (ref lOCFR2 770)

 * Babcock & Wilcox Co. B3/09/22 BROWN, W.B. Fuel Facility
 Safeguards Licensing Branch 1p 20778 028
- 8310170206 Forwards officer certificates for Licenses SNM-42, 145, 414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, per GO Zipf 780313 commitment JORDÁNAL V Babrook & Wilcox Co 83/09/23 PAGE.R O Uranium Full Licensing Branch 5pp 20798 087
- 8310040464 Ack receipt of 830908 ltr informing NRC of steps taken to correct violations noted in IE Imsp Rept 70-0027/83-09
 STORM J P Division of Emergency Preparedness & Materials Safety 83/09/26 ECKERT, J P Babcock & Wilcox Co ip 20623 127
- --0310040470 Responds to NRC 830811 ltr re violations noted in IE Insp Rept 70-0027/83-09 Corrective actions previous repts containing data from cellulose filter paper will be corrected & completed by 831030 ECKERT, J P Babcock & Wilcox Co 83/09/08 O'REILLY, J P Region 2, Office of Director 3pp 20623 128
- --8310040486 Forwards 1E Insp Rept 70-0027/83-09 on 830613-17 & notice of violation STOHR, J P Division of Emergency Preparedness & Materials Safety 83/08/11 ECKERT, J P Babcock & Hilcox Co 2pp 20623 131
- --8310040501 Notice of violation from insp on 830413-17 * Region 2, Office of Director 83/06/11 1p 20623 133
- --8310040508 IE Insp Rept 70-0027/83-09 on 830613-17 Noncompliance noted failure to determine surface collection efficiency of recovery bldg stack air sampler filter media KAMLE.J B Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs. B3/07/18 9pp 20623 134.
- B310200418 Application to amend License SNM-42, installing second phase of U fuel powder processing Rev O to Section V of license entl
 REGAN, N A Babcock & Hilcox Co 83/09/27, PAGE, R G Uranium Fuel Licensing Branch 23pp 20859 26!
- B310260433 Responds to B30822 itr Authorization to deviate from certain provisions of approved physical protection plan granted allowing employees w/o DOE clearances to work with; n particular mati access area for limited time.

 BRDNN W B Fuel Facility Safeguards Licensing Branch B3/09/30 REGAN N A Babcock & Wilcox Co. Ip 20926 336
- 6310170239 Forwards IE Safeguards Insp Rept 70-0027/83-21 on 830920-23 No noncompliance hobbed STOHRJP Division of Emergency Proparedness & Materials Safety 83/10/11 ECKERT, J.P. Dabcock & Wilcox Co. 2pp. 20787 102
- 310260154 Ack receipt of 830802 & 31 ltrs informing NRC of steps taken to correct deviation noted in IE Safeguards Insp Rept 70-0027/83-11.
 TOPR.J P Division of Emergency Preparedness & Materials Safety 3/10/12 ECKERT.J P Sabcock & Wilcox Co 1p 20912 086

- --8310260166 Clarifies 830802 response re audit performed during whof 830613 All working stds used in calibr of well counters stored in tampersafe condition Direct cognizance means accountability personnel never lose sight of stds. REGAN,N A Babcock & Wilcox Co 83/08/31 MCALPING.E Region () Office of Director 2pp 20912 087
- ~-8310260179 Responds to NRC 830713 ltr re deviation noted in If Safeguards Insp Rept 70~0027/83-11 Corrective actions Std Operating Procedures E41-70 & E46-39 will be revised ECKERIJF Babcock & Wilcox Co 83/08/02 O'RELLY, J F Region 2, Office of Director 3pp 20912 089
- DOCKET 70-0034 COMBUSTION ENGINEERING, INC . WINDSOR. CT
- B310040359 Forwards IE lnsp Rept 70~0036/B3-03 on B30816-19 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support B3/09716 LICHTENBERGER Combustion Engineering, Int 2pp 20620 224
- ~-8310040360 IE Insp Rept 70-0036/83-03 on 830816-19 No noncompliance noted Major areas inspected radiation protection raduatts mgt.organization.criticality safety, audits, facility mods & emergency planning GRANT, W B , SMITH, B W , GREGER, L R Region 3, Office of Director B3/09/15 7pp 20620 226
- B310140181 Forwards addendum to IE Insp Rept 70-0036/B3-01 re comparative results for samples collected & split during insp Results of analyses in Table 1 compared w/100f-R20 App B.Table II limits for natural U PAPERIELLO,C J Region 3, Diffice of Director 83/10/I1 LICHTENDERGER Combustion Engineering, Inc. 2pp 20761 242
- --8310140186 Addendum I to IE Insp Rept /0-0036/83-01 re confirmatory measurements program * Region 3. Office of Birector 83/04/15 1p 20741 243
- DOCKET 70-0135 BABCOCK & WILCOX CO , APOLLO, PA
- 8310270989 Responds to 830310 ltr transmitting fundamental nurlear matl control glan for low enriched U decontamination activities & seven exemptions Sections S.D through B O of Safeguards Amend MPP-1 to License SNM-145 revised BURNETT.RF Division of Safeguards 83/08/11 AUSTIN.N A Babcock & Wilcox Co 5pp 20744 262
- 8310270538 Responds to 830808 ltr transmitting fundamental nuclear math control plan for low enriched U scrap recovery License Condition 2 1 3 of Safeguards Amend MPP-1 to License SNM-145 revised Plan withheld (ref 10CFR2 790)
 BROWN.W B Fuel Facility Safeguards Licensing Branch 83/08/26 AUSTIN.W A Babcock & Wilcox Co ip 20938-034
- 8310120195 Forwards IE Safeguards Insp Rept 70-0135/83-06 on 830815-t9 No noncompliance noted MARTIN,T T Division of Engineering & Technical Programs 83/09/19 COLEMAN,W L Babcock & Wilcox Co 2pp 20692 223
- ---8310120201 IE Bafeguards Insp Rept 70-0135/83-06 on 830815-19 No noncompliance noted Major areas inspected shipper/receiver & inventory verification WOLTNER.E. (ODY, A T Region 1: Office of Director. 83/09/14 2pp 20692 225
- B310170205 Forwards officer certificates for licenses BNM-A2,145,414,778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, per G0 Zipf 780213 commitment JURDANL V Babcock & Wilcor Co B3/09/23 PAGE.R G Uranium Fucl Licensing Branch 5pp 20778 087
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN
- 8310240074 Responds to 830624 request re extension for submittal of physical inventory rept required under License Condition 5.4 of Safeguards Amend MPP-1 Request granted New license condition issued BROWN.W B. Fuel Facility Safeguards Licensing Branch. 83/07/11. HENSLEY,K D. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 1p. 20703.214
- B310240089 Responds to B30719 request for 31-day extension for completing 10CFR70 51(e)(4) requirements for B30623 high enriched U physical inventory Request granted BURNETT, R F Fuel Facility Bafeguards Licensing Branch B3/07/26 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty 011 Co) 3pp 20891 359

- 8310240214 Advises that Rev 13 to physical safeguards plan dtd 830805
- approved & incorporated
 BROUN, W B Fuel Facility Safeguards Licensing Branch 83/08/08
 HENSLEY, K Nuclear Fuel Services, Inc (subs of Getty Oil Co)
 ip 20707 318
- 8310070256 Forwards IE Safeguards Insp Rept 70-0143/83-30 on 830712-15 & notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21)
 STOHRJP Division of Emergency Preparedness & Materials Safety 83/08/12 QUINN:F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 20656 360
- --8310070259 IE Safeguards Insp Rept 70-0143/83-30 on 830712-15
 Noncompliance noted inadequate Procedure 83-30-010
 Details withheld (ref 10CFR73 21)
 TOBIN.W J Region 2, Office of Director MCGVIRE, D R Division of Emergency Preparedness & Materials Safety 83/08/12 ip 20454 342
- 8310240231 Approves 830805 request for rev to Safeguards License Condition 2 7(3) increasing allowed amount of combustible waste on 830423 physical inventory to 2 5 kg U BROWN. W B Fuel Facility Safeguards Licensing Branch 83/08/12 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 20707 305
- B310170036 Forwards Rev 7 to interim security measures implemented B20731 Attachments III & IV revised to extend completion date of uninterruptable power supply sys & to update upgrade items Incorporation requested Encl withheld HENSLEY.K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/08/26 BROWN.W B Division of Safeguards 1p 20798 332
- 8310170299 Application for amend to License BNM-124 deleting Conditions 61 & 67 Ventilation upgrade project complete & monthly status rept required by Condition 67 unnecessary Amend fee BILDEKER, R L. Nuclear Fuel Services. Inc. (subs. of Getty Qi) Cn.) 83/08/29 PAGE, R.G. Uranium Fuel Licensing Branch 3pp 20776 239
- 8310040190 Forwards 1E Insp Rept 70-0143/83-34 on 830814-19 No noncompliance noted

 STOHR, J P Division of Emergency Preparedness & Materials Safety
 B3/09/08 QUINN, F K Nuclear Fuel Services. Inc (subs of Getty
 D(1 Co) 1p 20608 272
- --8310040197 IE Insp Rept 70-0143/83-34 on 830816-19 No noncompliance noted Major areas inspected facility changes & mods.safety committees, procedure control operations, nuclear criticality safety & LER followup CORVELL.0 P Region 2. Office of Director MCALPINE.E J Division of Chergency Preparedness & Materials Safety 83/09/07 Spg 20408 273
- 8310110164 Ack receipt of 830629 ltr forwarding Rev 5 to site security training plan Changes inconsistent w/provisions of LOCFR70 32(c) encl Encl withheld (ref IOCFR73 21) STOHR, J P Division of Emergency Preparedness & Materials Safety 83/09/14 QUINN,F K Nuclear Fuel Services, Inc (subs of Octty Oil Co) 2pp 20666 236
- 8310110181 Ack receipt of 830630 ltr forwarding Rev 12 to physical safeguards plan One portion inconsistent w/100FR70 32(e) Comments provided for mod of plan W/o encl STOHR, J.P. Division of Emergency Preparedness & Materials Safety 83/09/14 QUINN.F.K. Nuclear Fuel Solvices, Inc. (subs. of Gett. Oil Co.) Ip 20665 014
- 8310040346 Ack receipt of 830809 ltr informing NRC of steps taken to correct violation noted in 1E Insp Rept 70-0143/83-23 STOHR, J P Division of Emergency Preparedness & Materials Safety 83/09/20 OUINN,F K Nuclear Fuel Services, Inc (subs of Getty Gil Co) ip 20617 271
- --8310040350 Responds to NRC 830713 ltr re violation noted in IE Imap Nesponos to MKC 830/13 itr me violation noted in IE Ins Rept 70-0143/83-23 Corrective actions incoming make-up air reduced on 830517 & differential pressure gauges installed QUINN,F K Nuclear Fuel Services, inc (subs of Getty Oil Co) 83/08/09 STOHR,J P Division of Emergency Preparedness & Materials Safety 3pp 20617 292
- 8310040303 Ack receipt of 830624 % 0727 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/83-17 STOHR, J.P. Division of Emergency Preparedness & Materials Bafety 83/09/21 GUINN.F K Nuclear Fuel Services: Inc (subs of Getty Oil Co.) Ip 20620-338

- --8310040309 Notifies that corrective actions stated in 830624 & 0729 ltrs re violation noted in IE Insp Rept 70-0143/83-17 re training of hourly personnel inaccurate Training will begin on 830912 on 830912 OUINN,F K Nuclear Fuel Services. Inc (subs of Getty Dil Co) 83/09/09 STOHR,J P Division of Emergency Preparedness & Materials Safety ip 20420 339
- --8310040312 Forwards IE Insp Rept 70-0143/83-17 on 830418-22 & notice of violation STOHR, J.P. Division of Emergency Preparedness & Materials Safety B3/05/25 MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Get Oil Co.) 2pp. 20620-349
- --8310040314 Notice of violation from insp on 830418-22 * Region 2. Office of Director 83/05/25 2pp 20620 351
- ---8310040340 IE Insp Rept 70-0143/83-17 on 830418-22 Noncompliance mated contrary to licensee procedure, personnel crossed yellow barricade lines into control areas & out again, w/o donning white shoecovers

 KAHLE, J B Region 2, Office of Director BARR, K P Division of
 Engineering & Operational Programs 83/05/19 10pp. 20620 353
- 8310050471 Ack receipt of 830727 & 0831 ltrs informing NRC of steps taken to correct violation noted in 1E Safeguards Insp Rept 70-0143/83-22 STOHR, J.P. Division of Emergency Preparedness & Materials Safety 83709721 OUINN.F.K. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 1p. 20432 346
- --8310050473 Forwards proprietary supplemental response to NRC 830630 ltr re violation noted in IE Bafeguards Insp Rept 70-0143/43-22 Encl withheld (ref 10CFR2 790) GUINN.F K Nuclear Tuel Services, Inc (subs of Getty Oil Co) 83/08/31 STOHR.P Division of Emergency Preparedness & Materials Safety 1p 20632 347
- B310170737 Application for Amend MPP-1 to Litense SNM-124 Amend withheld (ref 100FR2 790)
 HENBLEY.K D Nuclear Fuel Services. Inc (subs of Getty Oil Co)
 B3/09722 BROWN W R Division of Safeguards 1p 20796 361
- 8310170680 Confirms 830908 tolcon re liquid found in Bldg 303 furnace pit Drain line unplugged & coolant water spill cleaned up by production personnel Pitch of trough changed to divert future water overflows
 GUINN,F K. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)
 83/09/26 O'REILLY,J P. Region 2, Dffice of Director 3pp
 20798 221
- 8310270571 Orants 830922 request for 19-day extension for completing certain requirements of 10CFR70 51(e)(4) for 830826 high enriched U physical inventory New unnumbered license condition to Amend MPP-1 issued effective immediately BURNETT.R F Division of Safeguards 83/09/26 HENSLEY.K D Nuclear Fuel Bervices, Inc (subs of Oetty 011 Co) ip 20946 255
- 8310190290 Ack receipt of IE Insp Rept 70-0143/83-32 dtd 830831 No proprietary info OUINN:F K Nuclear Fuel Bervices, Inc (subs of Getty Oil Co). 83/09/27 STOHR.J.P Division of Emergency Preparedness & Materials Safety ip 20842 052
- B310250500 Ack receipt of B3090B ltr forwarding IE lnsp Rept 70-0143/B3-34 No proprietary info GUINN.F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) B3/09/27 BTOHR, JP Division of Engineering & Operational Programs IP 20902 0B5
- 8310050527 Ack receipt of 830805 & 0909 ltrs informing NRC of steps taken to correct violation noted in IC Safeguards Insp Rept 70-0143/83-25 STOHR, J P Division of Emergency Preparedness & Materials Bafety. 83/09/29 QUINN, F K Nuclear Fuel Services, Inc (subs of Getty Dil Co) ip 20632-266
- --8310050535 Forwards proprietary supplemental response to NRC 830713 ltr re-violation noted in IE Safeguards Insp Rept 70-0143/83-25 Encl withheld (ref 10CFR2 790) GUINN.F K. Nuclear Fuel Services, Inc (subs of Getty Dil Co) 83/09/09 STOHR.P Division of Emergency Preparedness & Materials Safety 1p 20632-267
- 8310170724 Forwards Rev 8 to interim security measures implemented on 82073i Implementation revised to extend completion dates of uninterruptable power supply says & controlled access areas Incorporation of pages rejuested W/A encl HENSLEY.K D Nuclear Fuel Services. Inc (subs of Getty Gil Co) 83/09/29 BROWN W B Fuel Facility Safeguards Licensing Branch ip 20798 094

- 8310060079 RADIOLOGICAL SURVEY OF THE NUCLEAR FUEL SERVICES, INC. ERWIN'
 - PLANT BURIAL SITE

 BOOTH/L F , NYERGES P L , GROFF, D W Rediation Management Corp FIN

 B-6901 NUREG/CR-3486 83/09/30 Division of Fuel Cycle &

 Material Safety 54pp 20864 OD1
- B310070139 Ack receipt of B30914 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/B3-30
 STORR.J.P. Division of Emergency Preparedness & Materials Safety B3/10/04 GUNN.F & Auclear Fuel Services, Inc. (subs. of Cetty Oil Co.). Ip 20657 082
- --8310070145 Responds to NRC 830812 ltr re violations noted in IE Insp Rept 70-0143/83-30 Corrective actions withheld GUINN.F K Nuclear Fuel Services, Inc (subs of Getty D.) Co) 83/09/14. STOHR, J P Division of Emergency Preparedness & Materials Safety ip 20/57.083
- 8310260077 Forwards proprietary IE Safeguards Insp Rept 70-0143/83-35 on 830815-26 No noncompliance mated Rept withheld (ref 10CFR2 790)
 STDUR, J P Division of Emergency Preparedness & Materials Safety 83/10/04. QUINN, F K Nuclear Fuel Services, Inc. (subs of Getty Oil Co) 2pp 20912 095
- B310180011 Advises of issuance of Amend 22 to License SNM-124, revising groundwater monitoring program, per B21015 & B30603 applications SER approving amend encl PAOEIR G Uranjum Fuel Licensing Branch B3/10/05 IDEKER, R. Nuclear Fuel Services, Inc. (subs. of Oetty Gil Co.) 2pp
- --8310180015 Sefety evaluation supporting licenses 821015 & 830/63 applications for amend to license SNM-124 to implement proposed groundwater monitoring program WYNOARDEN, S. D. & ROW-W F. Uranium Fuel Licensing Branch 83/10/05 App. 20825 070
- 8310170691 Advises of issuance of Amend 23 to License SNM-124, incorporating changes in organizational structures PAGE.R Q Uranium Fuel Licensing Branch 83/10/06 IDEXER,R Nuclear Fuel Services: Inc (subs of Getty Qil Go) Ip.
- --8310170693 Safety evaluation supporting issuance of Amend 23 to License BNM-124 SOCNO.A L., CROW,W T Uranium Fuel Licensing Branch 83/10/06 2pp. 20798 164
- 8310230336 Ack receipt of 830714 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/83-28
 O'REILLY.J P Region 2. Office of Director 83/10/06 GUINN,F K Nuclear Fuel Services. Inc (subs of Getty Oil Co) Ip
- --8310250340 Responds to NRC 830017 ltr re violation noted in IE Insp Rept 70-0143/83-88 Corrective actions procedures involved in pactaging & loading waste shipment reviewed Procedure NFB-HB-A-23 issued OUINN.F.K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 82/09/14 O'REILLY, J.P. Region 2, Office of Director 3pp 20898 055
- --8310250344 Forwards IE Insp Rept 70-0143/83-28 on 830627-30 & notice of violation
 O'REILLY, J.P. Region 2, Office of Director 83/08/17
 Nuclear Fuel Bervices, Inc. (subs. of Getty Oil Co.) B3/OB/17 GUINN,F K Dil Co) 2pp
- --8310250347 Notice of violation from insp on 830627-30 * Region 2: Office of Director 83/00/17 2pg. 20898 060
- --8310250352 IE Insp Rept 70-0143/83-28 on 830627-30 Noncompliance noted failure to provide reviewed & approved procedure for air particle site measurements & waste shipment in violation of particle site measurements.

 DOT regulations

 CUNNINGHAN, A L , TROUP, O L Region 2, Office of Director

 MONTODHERY, D M. Division of Engineering & Operational Programs

 83/08/09. Spp 20898, 062
- 1310260029 Approves Rev B to interim security measures submitted in B30929 ltr Physical security plan scheduled revs acceptable. BROWN # B Fuel Facility Safeguards Licensing Branch B3/09/30 HENSLEY, K Nuclear Fuel Services, Inc. (subs of Getty Oil Co). ip 20921 359.

- BUCKET 70-0364 BABCUCK & WILCOX CO , APOLLO, PA
- 8310270564 Advises of rev to Amend MPP-1 to License SNM-414, deleting Section 7, physical protection requirements in entirety, effective immediately (ref 830307 ltr)
 BROWN, W B Fuel Facility Safeguards Licensing Branch 83/08/31
 AUSTIN, M A Babcock & Wilcox Co 1p 20943 354
- 8310070016 Forwards Amend 20 to Litense GNM-414, revising Spec i -l to reflect reduction in quantity of SNM held at facility & changing Condition IO to authorize use of U-235 as calibr or Project & Resident Programs 83/09/27 QREENMAN, E Q Division of Project & Resident Programs 83/09/27 AUSTIN, N A Babcock & Milcox Co 2pp 20674 344
- --831007002A Safety evaluation supporting Amend 20 to License SNM-414 List of effective pages to Section ! of B&W application encl * NRC No Detailed Affiliation Given 83/09/23 4pp 20474 344
- --8310070027 Amend 20 to License SNM-414 revising Spec I-1 to reflect reduction in quantity of SNM held at facility & changing Condition 10 to authorize use of U-255 as calabr or ref GREENMAN, E G I 3pp 20674 350 Division of Project & Resident Programs 83/09/06
- --8310070028 Forwards revised Page 1 B 1 O to License SNM-414 to replay page submitted in 830630 transmittal.per 830712 telcon Encl page more accurately reflects mat1 possession limits at AUSTIN.M A Babcock & Wilcox Co 83/07/13 ROTH.J Region t. Office of Director ip 20674 353
- --8310070032 Proposed Page I B i O to License SNM-414, reflecting mat1 possession limits * Babcock & Wilcox Co B3/06/30 ip 20674 394
- --B310070035 Requests Condition 10 of License SNM-414 be changed to authorize use of Items R & B at Pu plant & Items Q,R & B at metals & hafrium complex Request should be included w/B30409 application Revised pages of Spec I to license encl AUSTIN.M A Babcock & Wilcox Co B3/06/30 Region 1, Office of Director 1p 20674 355
- --B310070038 Proposed Pages I B 1 0 & I B 1 0(a) to Spec I of Litense SNM-414, permitting use of Itens R & 5 at Pu plant & Itens Q, R & S at metals & hafnium complex * Babcock & Wilcox Co B3/06/30 2pp 20674 356
- --B310070040 Requests reduction in possession limits of metls author);ed under License SNM-414 Reduction will permit disconnection of criticality monitoring sys at Pu & Tupe II facilities Affected Page I B 1 O of Spec I-1 encl AUSTIN.H A Babcock & Wilcox Co B3/04/08 ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch ip 20474 359
- --8310070042 Proposed Page I B 1 O of Spec I-1 to License SNN-414, reducing possession limits for Pu & U-235 * Bøbcock & Wilcox Co 83/04/08 Ip 20674 359
- 8310170206 Forwards officer certificates for Licenses SNM-42, 145, 414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, par 60 Zipf 780313 commitment JORDAN, V Babtock & Wilcox Co 83/09/23 PAGE, R Ø Uranium Fulicensing Branch 5pp 20798 087 Uranium Fue)
- DOCKET 70-0371 UNG NAVAL PRODUCTS, INC , UNCASVILLE, CT
- B310270515 Responds to 83080B request for 1-wk extension to complete U & isotopic content assay & rept Amend MPP-1 to License SNM-36B issued, extending rept due date until 830812 BURNETIR F Division of Safeguards 83/08/19 KIRK.W F United Nuclear Corp 1p 20928 360 KIRK, W.F. United
- 8310170083 Forwards status rept for Aug 1983 re progress of final constitem listed in Chapter 13 of physical protection plan Rept withheld withheld GUSTAFBDN,R B United Nuclear Corp 83/09/01 Facility Safeguards Licensing Branch Ip 207 BROWN W 8 Fuel 20798 005
- 8310110599 Forwards comments on & request for add1 info re application for renewal of License SNM-368 License conditions in current license & amends should be incorporated into license renewal application Info due in 60 days
 BIDINGERO H Uranium Fuel Licensing Branch 83/10/03 KIRK, W F United Nuclear Corp 12pp 20704 318

- 8310270164 Forwards IE Safeguards Insp Rept 70-0371/83-10 on 830913-16 & notice of violation MARTIN.T 1 Division of Engineering & Technical Programs 83/10/13 AMY, 6 0 United Nuclear Corp 2pp 20925 005
- --8310270169 Notice of violation from insp on 830913-16 * Region 1. Office of Director 87/10/13 ip 20925 007
- --8310270178 IE Safeguards Insp Rept 70-0371/83-10 on 830913-16
 Noncompliance noted failure of security personnel to take
 annual requalification exam
 SMITH-G C , DUNLAP.J M Region 1. Office of Director GODY.A T
 Division of Engineering & Technical Programs 83/10/11 5pp
 20925 008

DUCKET 70-0474 UPSALA COLLEGE, FAST ORANGE, NJ

- 8310310337 Discusses IE Insp Rept 70-0474/83-01 conducted on 830922 No noncompliance noted Major areas inspected selective exams of procedures & representative records, interviews w/personnel, measurement & observations by inspector MARTIN.T T Division of Engineering & Technical Programs 83/10/24 FELDER,R Upsale College 2pp 20961 323
- DOCKET 70-0572 MONSANTO RESEARCH CORP , DAYTON, OH
- 8310120279 Forwards IE Insp Rept 70-0572/03-01 on 830815-19 % notice of violation SRENIAMENI,D J Region 3, Office of Director 83/10/07 SCHIMMEL,R L Monagnto Research Corp 2pp 20691 016
- --8310120283 Notice of violation from insp on 830815-19 SRENIAMSKI,D J Region 3, Office of Director 83/10/04 2pp 20691 018
- --8310120288 IE Insp Rept 70-0572/83-01 on 830815-19 Noncompliance noted failure to perform adequate personnel surveys & failure to provide fire extinguisher in each glove box SLAWINGKI, W. J., CANIANO, R., SRENIAMBKI, D. J. Region 3, Office of Director 83/10/04 20pp 20491 000
- ~-8310120292 Forwards rept of 830425 contamination event, in compliance w/100FR20 404(a)(5)
 HDADLEY,S D Monsanto Research Corp 83/05/06 Region 3,
 Office of Director 3pp 20691 040

DOCKET 70-0498 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

- 8310170197 Forwards "Groundwater Monitoring Bamples at Waltz Hill Site," Guarterly Rept 3 GALM.D T Westinghouse Electric Corp 83/09/23 MURLEY. (Region 1. Office of Director 2pp 20812 340
- --8310170203 "Groundwater Monitoring Samples at Waltz Mill Site." Quarterly Rept 3 * Westinghouse Electric Corp 83/08/23 24pp 20812 342
- BOCKET 70-0734 GA TECHNOLOGIES, INC . SAN DIEGO, CA
- 83i0180217 Forwards IE Safeguards Insp Rept 70-0734/83-10 on 830825-26, 0919-23 & 26-30 No noncompliance noted Rept withheld (ref 10CFR73 21)
 NORDERHAVO, L. R. Region 5, Office of Director 83/10/11
 PARKER, J. W. GA Technologies, Inc./General Atomic Co. 2pp 200808 307
- 8310180120 Forwards IE Safeguards Insp Rept 70-0734/83-12 on 830829-0901 No noncompliance noted NORDERHAUG, L.R. Region 5. Office of Director 83/10/12 PARKER, J.W. GA Technologies, Inc /General Atomic Co. 2pp 20808 171
- --8310180123 IE Bafeguards Insp Rept 70-0734/83-12 on 830829-0901 No noncompliance noted Major areas inspected measurement controls, shipper-receiver verification & inventory difference Details withheld (ref 10CFR2 770) NELEON, 6 B, NORDERNAUO, L R Region 5, Office of Director 83/10/11 1p 20808 173
- 8310310258 PNS-V-83-010 on 830912, latest bimonthly physical inventory indicated difference (ID gain) occurred in high enriched U HTOR fuel mfg area Past IDs did not exceed limit of error Current gain reduces cumulative ID by one half WIEDER.A V. NELSON. 9.8 Region 5. Office of Director 83/10/20 2pp 20947 160

- DOCKET 70 0754 GENERAL ELECTRIC CO . PLEASANTON, CA
- 8310120372 Memorandum & order granting J Turk 830915 request for 60-day extension of deadline for filing amends to contentions & petition FRYE.J H Atomic Safety and Licensing Board Panel 83/10/07 TURK.J Turk, J ip 20699 253 24X Fiche 50-070,83/10/07,8310120372
- DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JUNCTION, RI
- 83i0170030 Quarterly progress rept for Contract NRC-02-80-074 re calibr of flow & containment transport model WARNER, D. L. Don L. Warner, Inc. NRC-02-80-076 83/09/21 WYNGARDEN, S. D. Dffice of Nuclear Material Safety & Safeguards, Director 2pp 20798 342
- 8310200163 Furwards IE Insp Rept 70-0820/83-07 on 830822-26 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 83/09/30 AMY, 6. 0 United Nuclear Corp 2pp 20834 080
- --8310200169 IE Insp Rept 70-0820/83-07 on 830822-26 No noncompliance noted Major areas inspected in-ofc insp to follow confirmatory survey of licensee decommissioned facility. ROTH, J Region 1. Office of Director ELBASSER, T C Division of Project & Resident Programs 83/09/28 5pp. 20834.082
- 8310250440 Ack receipt of 830713 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/83-04.

 MARTIN, T T Division of Engineering & Technical Programs 83/10/18

 ANY, 8 0 United Nuclear Corp ip 20897 105
- --8310250445 Forwards response to NRC 830822 ltr re violations noted in IE Insp Rept 70-0820/83-04 Corrective actions entries for documents made in general ledger Matl status repts submitted GREGO.R J United Nuclear Corp 83/09/13 MARTIN.T T Division of Engineering & Technical Programs 2pp 20897 104
- DOCKET 70-0824 BABCOCK & WILCOX CO . LYNCHBURG. VA
- B31024022B Documents branch position re investigation & corrective action necessary to reconcile shipper/receiver differences involving U element weight Investigation & corrective action must consider weight, U & isotopic assay BROWN, W B Fuel Facility Bafeguards Licensing Branch B3/0B/16 DLSEN, A F Babcock & Wilcox Co ip 20907 308
- G310270562 Advises that Safeguards Amend MPP-1 to License SNM-778 amended by deleting Bections I through 8,effective B30B1!
 Amend due to reduction of possession limit of U & Pu to less than 1 effective kg
 BROWN, W B Fuel Facility Safeguards Licensing Branch B3/0B/19.
 OLSEN, A F Babcock & Wilcox Co is 20943 353
- 8310170730 Forwards 10CFR70 32(e) rev to Bidg C security plan, reflecting administrative changes Rev withheld (ref 10CFR2 790)
 OLSEN, A F Babcock & Wilcox Co 83/09/19 Division of Safeguards ip 20797 395
- B310170206 Forwards officer certificates for Licenses SNM-42,145,414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities,per 60 Zipf 780313 commitment JURDAN,L V Babcock & Wilcox Co 83/09/23 PAGE,R G Uranium Fue Licensing Branch 5pp 20798 087
- 8310040337 Forwards IE Safeguards Insp Rept 70-0824/83-05 on 830824-24 No noncompliance noted STOHR.J.P. Division of Emergency Preparedness & Materials Safety 83/09/29. ENGELDER.T.C. Babcock & Wilcox Co. 2pp. 20420-335
- --8310040342 [E Safeguards Insp Rapt 70-0824/83-05 on 830824-24 No noncompliance noted Major areas inspected facility organization a paration, measurements & statistical controls Details withheld (ref 100FR2.790)
 BATES.JW. SABADDS.JW. Region 2. Office of Director MCALPINCE, J Division of Emergency Preparedness & Materials Safety 83/09/27 ip 20420 337

- DOCKET 70-0984 BATTELLE MEMORIAL INSTITUTE, RICHLAND, WA
- 8310170669 Forwards revised pages to Manual PNL-MA-11, "Emergency Preparedness," for insertion KOYAMA, E Battelle Memorial Institute, Pacific Northwest Laboratory 83/08/29 Battelle Memorial Institute, Pacific Northwest Laboratory 2pp 20798 223
- --8310170675 Manual PNL-MA-11. "Emergency Preparadness " ASMUND, V C Sattelle Hemorial Institute, Pacific Northwest Laboratory 83/08/22 104pp 20778 224
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC , WINDSOR, CT
- B310270494 Confirms verbal consent to use of CE-Windsor license poper format in preparing design info questionnaire License Condition 2 4 added to Amend MPP-4 to License SNM-1067, granting exemption from IOCFR7S 11(d) BURNETT, R F Division of Bafeguards 93/08/31 LICHTENBERGER Combustion Engineering, Inc. 1p 20938 101
- 8310190215 Application for amend to License SNM-1067 to renew license for 5 yrs & to make administrative changes LICHTENBERGER Combustion Engineering. Inc. 83/09/16 PAGE.R G Uranium Fuel Licensing Branch Sopp 20838 108
- 8310120082 Forwards IE Insp Repts 70-1100/83-03 & 30-03754/83-01 on 830718-21 & notice of deviation STAROSTECKI, R Division of Project & Resident Programs 83/09/19 LICHTENBERGER Combustion Engineering, Inc. 2pp 20497 142
- --8310120085 Notice of deviation from insp on 830718-21 * Region 1. Office of Director 83/09/19 1p 20497 144
- ---8310120088 IE Insp Repts 70-1100/83-03 & 30-03754/83-01 on 830718-21 Noncompliance noted failure to properly handle breathing zone sampler head filter paper w/clean gloves ROTH-J Repjon 1, Office of Director. ELSASSER.T C Division of Project & Resident Programs 83/08/12. [Opp 20697.145]
- B310070211 Discusses items of interest Meeting held on B30921 w/C-F in Windsor.CT re C-E proposed license amend application to modify air sampling sys On B30915 NRC concurred in DDE remedial action plan for Canonsburg.PA site PAGE.R Q Uranium Fuel Licensing Branch B3/09/22 DAVIS.J Q Office of Nuclear Material Safety & Bafeguards, Director ip 20679 353
- 8310110441 Summary of 830715 & 21 meetings w/DDE & C-E re remedial action plan & proposed license amend application concerning mod of air sampling sys in Windsor plant respectively PAGE.R O Uranium Fuel Licensing Branch. 83/09/22 DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director ip 20714 341
- 8310190192 Forwards MA Elmaghrabi resume to be included in 830916 application for amend to License SNM-1067 LICHTENBERGER Combustion Engineering, Inc. 83/10/09 PAGE,R G Uranium Fuel Licensing Branch 3pp 20838 094
- 3310180027 Forwards page changes to 830916 application for amend to License SNM--1067 LICHTENNERGER Combustion Engineering, Inc. 83/10/05 PAGE,R O Uranium Fuel Licensing Branch Ip. 20825-049
- --8310180031 Page changes to 930914 application for amend to License 8NM-1067 * Combustion Engineering, Inc. 83/10/05 3pp. 20825-050
- 3310240082 Forwards IE Bafeguards Insp Rept 70-1100/83-04 on 830906-09 No noncompliance noted MARTIN,T T. Division of Engineering & Technical Programs 83/10/07 LICHTENBERGER Combustion Engineering, Inc. 2pp 20881 017
- --8310240085 IE Safeguards Insp Rept 70-1100/83-04 on B30704-07 No noncompliance noted Major areas inspected measurement control program & inventory difference & associated limit of error verification.
 ZIBULSKY, H., SANBORN, J., GODY, A.T., Region 1, Office of Director B3/10/07 Spp. 20881-019.
- R310310282 Ack receipt of itr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1190/83-03 & 30-03754/83-01.
 STAROSTECKI,R Division of Project & Resident Programs 83/10/20 LICHTENBEROER Combustion Engineering, Inc. 1p. 20957 084

- --8310310287 Responds to NRC 830919 ltr re violations noted in I6 Insp. Repts 70-1100/83-03 & 30-03/54/83-01 Corrective actions applicable personnel reinstructed in proper use of breathing zone air sampler devices
 LICHTENBERGER Combustion Engineering, Inc 83/10/31
 STARDSTCCKI.R Division of Project & Resident Programs 2pp 20957 085
- DOCKET 70-1113 GENERAL ELECTRIC CO . WILMINGTON, NO.
- 8310170249 Application for amend to License SNM-1097 to include storage of waste boxes prepared for shipment in site warehouse Details encl VAUGHAN.C M General Electric Ca 83/08/17 CROW.W [Unanium Fve] Licensing Branch 4pp 20796 26/
- --8310170253 Ack receipt of 830817 payment re rev to License Condition (to License SNN-1097)
 HEISB.D.J. Uranium Fuel Licensing Branch 83/09/13 VAUDHAN.C.H.
 General Electric Co. 2pp. 20796 2/1
- B310170051 Request for amend to License 5NM-1097 authorizing rescipt of SNM under special conditions on one-time basis Encl withhold (ref 10CFR2 790) VAUQHAN.C M General Electric Co 83/09/23 BROWN.W D fuel Facility Safeguards Licensing Branch Ip 20798 040
- 8310250547 Forwards 1E Insp Rept 70-1113/83-24 on 830822-26 No noncompliance noted STGHR.J P Division of Emergency Preparedness & Materials Bafrty 83/09/26 LDNG.J A General Electric Co 2pp 20901 001
- --B310250554 IE Insp Rept 70-1113/B3-24 on B30822-26 No nuncompliants noted Major areas inspected calibr & uso of instruments, external exposure control, posting, labeling & control of radiological areas HOBEY.C M Region 2, Office of Director BARR.K P Division of Engineering & Operational Programs 83/09/14 7pp 20901 00%
- 8310130225 Forwards Chapters 15 & 16 to license renewal application document dtd 830725 VAUGHAN,C M General Electric Co 83/09/30 CROW,W T Office of Nuclear Material Safety & Safeguards,Director lipp 20754 191
- --8310130228 Chapters 15 & 16 to 830725 license renewal application * General Electric Co 83/09/30 122pp 20754 203
- B310240226 Grants B30923 request to receive low enriched U under special conditions on one time basis Two unnumbered license conditions added to Amend MPP-3 to License SNM-1097, effective immediately BURNETT/R F Division of Safeguards 83/09/30 VAUGHAN, C M General Electric Co 2pp 20907 309
- B310170155 Forwards Rev 1 to Chapter 6 of 830725 application for amend to License SNM-1097 VAUDHAN.C M General Electric Co 83/10/03 CROW, W. T Office of Nuclear Material Safety & Safeguards, Director ip 20013 032
- --8310170158 Rev 1 to Chapter 6 of 830725 application for amend to License SNM-1097 * General Electric Co 83/10/03 App 20813 053
- 8310250427 Ack receipt of IE Insp Rept 70-1113/83-24 on 830822-26 No proprietary info VAUGHANIC M General Electric Co 83/10/03 STDHR, J P Division of Emergency Preparedness & Materials Safety 19 20897.181
- 8310260170 Forwards IE Safeguards lnsp Rept 70-1113/83-27 on 830913-16 No noncompliance noted 870HR. J.P. Division of Emergency Preparedness & Matorials Safety 83/10/05 LONG, J.A. General Electric Co. 2pp. 20712 103
- --8310260194 IE Søfeguards Insp Rept 70-1113/83-27 on 830913-16 No noncompliance noted Major areas inspected measurement & statistical control & followup on previous insp findings Details withheld (ref 100FR2 790)
 SABADIS, J W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety B3/10/05 ip 20912-105,
- 8310260215 Forwards IC Safeguards Insp Rept 70-1113/83-23 on 830906-00 No noncompliance noted STORR, J P Division of Emergency Preparedness & Materials Safety 83/10/05 LONG, J A Owneral Electric Co 2pp 20912 092

- --8310260221 IE Safeguards Insp Rept 70-1113/83-23 on 830906-08 No noncompliance noted Major areas inspected review of licenser approved physical security plan for SNM of low strategic significance Details withheld (ref IOCFR2 790) ENNIS.J D. McGUIRE.D R. Division of Emergency Preparedness & Materials Safety 83/10/04 ip 20912-094
- 8310260297 Ack receipt of 830907 ltr informing NRC of steps taken to correct violations noted in IL Safeguards Insp Rept 70-1113/83-21
 STOMR, J.P. Division of Engineering & Operational Programs 83/10/05 LDNG, J.A. General Liectric Co. 1p. 20909-222
- --8310260307 Responds to NRC B30B16 ltr re violations noted in IE Safeguards Insp Rept 70-1113/B3-21 Corrective actions withheld (ref IOCFR2 790) VAUGHAN.C M General Electric Co. 83/09/09 STOIR, J.P. Division of Engineering & Operational Programs Ip. 20909 223
- DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- B310260045 Forwards Rev 1 to "Final Survey Results From Decommissioning Bldg 7 Westinghouse-NFD U Dride Lab," per requirements of License Condition 20 NARDIA J Westinghouse Clectric Corp B3/09/22 MURLEY, T I Region I. Office of Director Ip 2092B 053
- --8310260054 Rev 1 to "Final Survey Results From Decommissioning Bldg 7 Westinghouse-NFD U Dxide Lab " * Westinghouse Electric Colp 83/09/30 19pp 20928 004
- 8310240248 Forwards "Final Survey Results of Decontamination of Pu Fuels Development Lab " NARDI.A J Westinghouse Electric Corp 83/10/04. MURLEY,T E Region 1, Office of Director 1p 20905-001
- --B310240250 "Final Survey Results of Decontamination of Pu Fuels Development Lab " * Westinghouse Electric Corp B3/10/31 749pp 20905 00P

DOCKET 70-1144 OHMART CORP , CINCINNATI, OH

- 8310240019 Responds to FDIA request for matl re Dhmart Corp on & offsite radiation-related incidents Forwards App A documents. App B documents partially withheld (ref FDIA Exemptions & & 7)
 FELTON.J M Division of Rules and Records 83/07/15 CARPENIER, T Cincinnati Alliance for Responsible Energy 10pp 2092/002
- --8310260119 Submits matter to be reviewed re high film badge exposure reported in Ohmart 750122 ltr
 NDRELIUS,C E Region 3. Chicago. Office of the Director.
 75/01/27 Region 3. Chicago. Office of the Director ip
 20727 078
- --8310260128 Submits matter to be reviewed during next insp re high film badge exposure per Ohmart Corp 750430 ltr * Region 3. Chicago, Office of the Director 75/02/26 Region 3. Chicago, Office of the Director 1p 20927 098
- --B310260146 Responds to 770511 ltr re calculated dose received by personnel from Oct 1976 Mor 1977, training program & source handling procedures Trainess will be subj to verbal sexum COOK, H L Ohmart Corp 77/05/26 TI
- --8310240149 Suppls 770414.0512 & 26 ltrs re noncompliance concerning handling unshielded sources & exposure of individuals to radiation info deleted COOK, H & Dhmart Corp 77/06/17 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 24pp 20927 117
- ---8310260165 Ack receipt of 721023 ltr informing AEC of steps taken to correct items of noncompliance noted in insp of Licenses 34-00639-01.34-00639-030 & SNM-1091 GRIER.B H Region 3, Chicago, Office of the Director 72/11/02, KELLY, Q A Dhwart Corp 1p 20927 181
- --8310260250 IE Insp Repts 70-1144/77-01, 30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Noncompliance noted individual received overexposure while handling licensed matl & no evaluation made of extremity exposure SCHULTZ, W H., PHILLIP, G A., LONERGAN, C, T., Region 3, Chicago, Office of the Director 77/05/04 17pp 20927 273.

- --8310260265 Discusses IE Insp Repts 70-1144/77-01;30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Ltr & insp rept will be placed in PDR unless licensee believes portions are proprietary & should be withheld KEPPLER.J G Ragion 3. Chicago, Office of the Director 77/05/1COOK.H L Ohmart Corp 2pp 20927 292
- --8310260287 Discusses insp of Licenses SNM-1091.34-00639-01 & 34-00639-039 on 770330-0401 & 11-12 & forwards notice of violation THOMPSON.D Office of Inspection & Enforcement, Office of the Director 77/05/11 CODK.P L Obmart Carp 3pp 20927 318
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP . PITTSBURGH, PA
- 8310240224 Discusses concerns re nondestructive assay of solid waste contained in large wooden boxes, reliability of LEID values 2. SNM procedures contained in MC&A safegwards program BROWN.W B Fuel Facility Safeguards Licensing Branch 83/08/24 SANDERG.C F Westinghouse Electric Corp 2pp 20907 313
- 8310040143 Forwards IE Safeguards Insp Rept 70-1151/83-16 on 830808-12 No noncompliance noted STORR, J P Division of Emergency Preparedness & Operational Support, 83/09/01 IRITTON.W H Westinghouse Electric Corp 2pp
- --8310040148 IE Safeguards Insp Rept 70-1151/83-16 on 83080B-12 No noncompliance noted Major areas inspected facility operation testistical controls associated w/SNM accountability measurements Details withheld (ref 10CFR2 770)

 JONES,D W Region 2, Office of Director MCALPINE,F J Division of Emergency Preparedness & Materials Safety 83/08/31 lp 20608 281
- 8310170330 Requests exemption from provisions of 10CFR70 53(b) for License SNM-1107, to permit 10-day extension for reporting LEID calculation results & 20-day extension for reporting overall mat1 balance for inventory period NARDLA J Westinghouse Electric Corp 83/09/06 BROWN, W B Fuel Facility Bafeguards Licensing Branch 3pp 20795 272
- 8310170219 Forwards info re const & use of new bldg to be constructed within control access area & to be used by contractor during installation of equipment for new IDR MAP project Const to begin in Early Bept REITLER.E K. Westinghouse Electric Corp. 83/09/13 CROW.W T Uranium Fuel Licensing Branch. 3pp. 20794 294
- 8310240230 Advises that proposed change in methodology for determining U element content of solid waste represents upgrade Rev to fundamental nuclear mati control plan should describe how average enrichment factor will be calculated BROWN, W B Fuel Facility Safeguards Licensing Branch 83/09/20 SANDERS, C F Westinghouse Electric Corp 1p, 20908 002
- 8310240227 Approves 830906 request for exceptions from 10CFR70 53(b) requirements to calculate U element & U-235 LEID values for each physical inventory & to submit rept within 50 calender days

 RROWN.W D Fuel Facility Safeguards Licensing Branch 83/09/21 SANDERS, C F Westinghouse Electric Corp 2pp. 20907 306.
- 8310040144 Responds to 830913 ltr re preengineered IDR const bldg NRC has no objection to const & use by contractor, however, use of bldg for licensed math will require license amend BIDINGER, G H. Uranium Fuel Licensing Branch 83/09/22 REITLER, E K. Hestinghouse Electric Corp. ip 20634.340
- 8310040622 Ack receipt of 830823 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/83-11. O'REILLY, J.P. Region 2, Office of Director 83/09/23. BRITTON, W. H. Westinghouse Electric Corp. 1p. 20626-045
- --8310040628 Responds to NRC 830725 itr re violation noted in IE Insp Rept 70-1181/83-11 Corrective actions: all drummed waste packaged & shipped in BDT spec steel dryms Insp checklists rewritten to clarify acceptance criteria BRITTON, W H Westinghouse Clectric Corp 83/08/29 O'REILLY, J P. Region 2, Office of Director 2pp. 20626,046
- --B310040632 Forwards IE Insp Rept 70-1151/B3-11 on 830606-10 & notice of violation Since civil penalty issued by State of SC, no NRC civil penalty action will be taken. O'ABILLY, JP Region 2, Office of Director 83/07/25 BRITTON, W. H. Westinghouse Electric Corp. 2pp. 20626 048
- --8310040635 Notice of violation from insp on 830604-10 * Region 2, Office of Director 83/07/25 ip 20626.050.

- --8310040637 IE Insp Rept 70-1151/83-11 on 830606-10 Noncompliance noted holes existed in six steel drums containing low specific radwaste shipped to Barnwell.80 on 830921 to 23 PEERY.W W Region 2. Office of Director DARR.K P Division of Engineering & Operational Programs 83/07/08 4pp 20626-051
- 8310050013 Summarizes 830912-16 safety insp of fuel fabrication facility in Columbia: SC Noncompliances noted handling of radwaste, bood air velocity & unidentified change in radiation protection organization COUL. D A Uranium Fuel Licensing Branch 83/09/26 Uranium Fuel Licensing Branch 83/09/26
- 8310250310 Ack receipt of 830901 ltr re IE Safeguards Insp Rept 70-1151/83-16 on 830808-12 5ANDERS,C F Westinghouse Electric Corp 83/09/27 O'REILLY,J P Region 2, Office of Director 1p 20895 291
- 8310260104 Forwards IE Safeguards Insp Rept 70-1151/83-19 on 830912-15 No noncompliance noted STOHR: J.P. Division of Emergency Preparedness & Materials Bafety. 83/10/12 BRITTON, W.H. Wostinghouse Electric Corp. 2pp 20912 106
- --8310260114 IE Safeguards Insp Rept 70-1151/83-19 on 830912-15 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 100FR2 790). RICHARDS, B L. MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/10/11 Ip 20912 108
- 8310240078 Trip rept of 831005-07 visit to Westinghouse in Columbia, SC to review inventory of scrapped cladding, combustible contaminated waste & contaminated matls from plant maint & mod 810100ER, C.H. Uranium Fuel Licensing Branch 82/10/18 CRUW, W T Uranium Fuel Licensing Branch 20703 209
- DOCKET 70-1201 BARCOCK & WILCOX CO . LYNCHBURG, VA
- B310240070 Responds to B30715 request for use of estimated weights for 12 fuel rods loaded w/low enriched U pellets Amend MPP-2 to License SNM-1168 revised to include new unnumbered license condition to use extended U & U-235 values BROWN W B Fuel Facility Safeguards Licensing Branch B3/07/22 FORD J T Babcock & Wilcux Co ip 20903 215
- 8310170076 Forwards revised fundamental nuclear matls control plan for License 8NM-1168 Rev deletes requirements for pellet mfg & incorporates changes for pellet receipt Plan withheld (ref 10CFR2 790) FORD-J T Babtock & Wilcox Co B3/08/24 BRDWN,W B Fuel Facility Bafeguards Licensing Branch 19 20798 017
- 8310170740 Forwards page-date index,table of contents & fundamental nuclear matl control plan Plan withheld tref 10CFR2.790).
 FORD,J T Babcock & Wilcox Co 83/09/21 BROWN,W.B Division of Safguards Ip 20796 362.
- 8310170206 Forwards officer certificates for Licenses GNM-42, 145,414, 778 & 1168 financially assuring payment for decommissioning costs of nuclear facilities, per GO 21pf 780313 commitment JORDAN, L V Babcock & Wilcox Co 83/07/23 PAGE, R C Uranium Fuel Licensing Branch 5pp 20778 087
- DOCKET 70-1257 EXXON NUCLEAR CO., INC., RICHLAND, WA
- 9310260046 Grants approval for rev to License SNM-1227 adding Condition 4 7 to Amend MPP-2, per 830706 request re performance of contractor lab data audits at interval not to exceed 24 months.
 - months BURNETT,R F Division of Safeguards 83/07/31 SCHNEIDER,R A Exson Nuclear Co., Inc. (subs. of Exxon Corp.). 1p. 20921-354
- B310270626 Informs that Rev 5 to physical protection plan for math of low strategic significance, submitted on B30630, acceptable.
 Rev withheld (ref 100FR2 790)
 BRONN-W B. Fuel Facility Safeguards Licensing Brench, B3/08/05
 MALODY, C W. Exion Nuclear Co., Inc. (subs. of Exxon Corp.) ip
- B31013020B Application for amend to License SNN-1227 providing for storage warehouse for fuel assemblies MALDDY.C.W Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 83/08/20. CRON.H.T Uranium Fuel Licensing Branch. App. 20751 331

- 8310240240 Grants 830815 request for 1-month extension for scheduled start of SNM inventory Unnumbered license condition added to Amend MPP-2 to License SNM-122/ to require next physical inventory on or before 831110 BROWN, W.D. Fuel Facility Safequards Licensing Branch 83/09/P2 SCHNEIDER, R.A. Exton Nuclear Co., Inc. (subs. of Lixon Corp.) in 20090 pool
- B310050110 Advises that 820428 & 830218 submittals re changes in radiological contingency plan reviewed & incorporated into plan No license amend necessary Changer do not decrease plan effectiveness CARDARELLI,R D Granium Fuel Licensing Branch 83/09/21 MALODY,M C W Exxon Nuclear (o , Inc (subs of Exxon Corp) ip 20450 233
- 8310170233 Forwards revised Page 3 to application for Amend 11 to License SNM-12P7 re enrichment levels MALDDY.C W Exxon Nuclear Co , Inc (Subs of Exxon Corp) 83/09/29 CROW.W T Uranium Fuel Licensing Branch 1p 20013 037
- --8310170236 Revised Page 3 to application for Amond 11 to License SNM-1227 Amend covers criticality safety & environ impacts MALODY.C W Exxon Nuclear (e , Inc (subs of Exxon Corp) 83/07/18 1p 20813 040
- 8310120340 Ack receipt of 830919 ltr informing NRC of steps taken to correct violations noted in II insp rept
 HENSLAWSKI,F A Region 5, Office of Director 83/10/06
 MALODY,C W Exxon Nuclear Co , Inc (subs of Exxon Corp) Jp
 20698 050
- --B310120357 Responds to NRC 830831 ltr re violations noted in It insprept Corrective actions detailed list of requirements of amends to license will be transmatted to personnel responsible for operation cavered by amend MALODY: C W Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/09/17 (HOMAS, R D Region 5, Office of Director 2pp 20698 054
- DOCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA
- 83:0140212 Forwards 16 Insp Rept 72-0001/83-03 on 830729-0722 No noncompliance noted PAPERIELLO, C. J. Region 3, Office of Director 83/09/29 VAN HODMISSEN General Electric Co. 2pp. 20742 296
- --8310140216 IE Insp Rept 72-0001/83-03 on 830729-0722 No noncompliance noted Major areas inspected spent reactor fuel shipping & general plant maint activities, raduate mgt. 10CFR21 reporting & periodic maint of packagings LOVENDALC, P. C., GREGER, R. P. PRILE, D. L. Region 3, Office of Director 83/09/27 9pp 20762 298
- DOCKET 70-1426 TRANSNUCLEAR, INC , FALLS CHURCH, VA
- B31006055B Forwards modified B30922 primary spent fuel route from Host Valley.NY to Morris.IL SHERR.T 5 Material Transfer Safeguards Licensing Branch B'3/09/2/ MANGUSI,J Transmuclear, Inc. 7pp 20661 275
- DOCKET 70-1442 HARPER HOSP , DETROIT, MI
- 8310180048 Forwards sanitized version of 831003 modified alternate spent fuel route from West Valley.NY to Dresden facility Remaining provisions of NRC 830914 1tr unchanged SHERR.T B Material Transfer Bafeguards Licensing Branch 83/10/05 MANGUSI.J Trane Co 9pp 20824 292
- DOCKET 70-1487 DOW CHEMICAL USA, MIDLAND, MI
- 8310110065 Further response to FDIA request for records re incineration of radioactive matls by Dow Chemical Co Midland, MI plant Forwards App B documents Documents also available in PDR FELION, J M Division of Rules and Records 83/06/20 GARDE, B P Government Accountability Project 2pp 20704 001
- --0310110139 Discusses insp of License SNM-1451,21-00265-04 & 21-00265-06 on 761006 & forwards description of noncompliance ALLAN.J M Region 3, Chicago, Office of the Director 76/10/20 LANGNER, R R Dow Chemical Co 2pp 20704.087

DOCKET 70-1795 GEORGE WASHINGTON UNIV , WASHINGTON, DC

- B310270635 Responds to B30927 memo re civil penalties imposed on George Mashington Univ Medical Ctr & Nuclear Metals, Inc Ltrs to licensees, notices of violation & inep repts encl DIRCKG, W J Office of the Executive Director for Operations 83/10/03 GILINSKY, V Commissioners ip 20946-041
- --8310270639 Discusses IE insp on 830601-02 & forwards notice of violetion & proposed imposition of civil penalty MURLEY.1 E Region 1. Office of Director 83/09/01 LEDNARD.F George Washington Univ Medical Center Wash DC 3pp 20946 04c
- --83102/0644 Notice of violation & proposed imposition of civil penalty in amount of \$2,500 Noncompliance noted adequate survey not performed to assure compliance w/100fR20 106(a) re radioactive releases MURLEY.1 E Region 1. Office of Director 83/09/01 5pp 20946 045
- -8310270656 Requests description of noncompliances identified at George Washington Univ Medical Ctr & Nuclear Metals, Inc which resulted in proposed fines of \$2,500 & \$9,000 respectively GILINSKY,V Commissioners 83/09/2/ AXELRAD,J Director Office. Office of Inspection and Enforcement. AXELRAD, J Director's ement, ip 20946-098

DOCKET 70-2047 UNION CARBIDE CORP , MARIETTA, OH

- 8310170282 Forwards ORNL 830914 ltm re analytical data on epoxy floor covering samples from process bldg Info establishes thorium/U ratio in contaminants on floors to develor appropriate guidelines for decontamination

 EVANS,L G Union Carbide Corp 83/10/05 PAPERIELLO,C J Region

 3. Office of Director 4pp 20784 315
- DOCKET 70-2319 OUR LADY OF LOURDES HOSP , CAMDEN, NJ
- 8310310419 Ack receipt of 830912 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 70-2319/83-01 MARTIN T Division of Engineering & Technical Programs 83/10/25 PETERS, A Our Lady of Lourdes Hosp , Camden, NJ ip 20959 239
- --8310310425 Responds to NRC 830719 ltr re violations noted in JE Insp Rept 70-2319783-01 Corrective actions all original NRC licenses, including SNM license, will be kept on file in administration ofc PETERS,A Our Lady of Lourdes Hosp, Camden, NJ 83/09/12 Region 1, Office of Director ip 70759 240

DOCKET 70-2430 MERCER MEDICAL CENTER, TRENTON, NJ

- 8310310414 Ack receipt of 830916 ltr informing NRC of steps taken to correct violations noted in If Insp Repts 70-2430/83-01, 30-02411/83-01 to 830630 MARTIN,T T Division of Engineering & Technical Programs 83/10/25 STEWART,C C Mercer Medical Center Trenton,NJ. 1p 20959 285
- --8310310418 Responds to NRC 830818 ltr re violations noted in IE Insp Repts 70-2430/83-01.30-02411/83-01 & 30-00341/83-01 on 830630 Corrective actions, disposable gloves will be utilized by all personnel when handling radioactive matl STEWART.C C Morcer Medical Center Treaton.NJ 83/09/16 MARTIN.T T Division of Engineering & Technical Programs lp 20959 284

DOCKET 70~2808 WESTMORELAND HOSP , GREENSBURG, PA

- E3i0180137 Discusses IE Insp Repts 70-2808/83-01 & 30-09731/83-01 on 830826 No noncompliance noted Major areas inspected. procedures & records & interviews w/personnel Pu powered pacematers never received under License SNM-1815 MARTIN.T) Division of Engineering & Technical Programs 83/09/8 WILCOX.H K Westmoreland Hosp Greensburg.PA 2pp 20800 165 83/09/29
- DOCKET 70-2941 TENNESSEE VALLEY AUTHORITY, CHATTANODGA, TN
- 8310170733 Suppl to application to amend 810106 physical security plan, reflecting section & div changes Amend withhold (ref 10CFR2 790)
 MILLS,L.M Tennessee Valley Authority 83/08/24 D'REILLY,J P
 Region 2. Office of Director Ip 20797 352

- DOCKET 70-2945 UNION ELECTRIC CO. ST. LOUIS, MO.
- 8310040133 Issues Amend 3 to License SNM-1901 increasing possession limit to 27 O g U-235 Safety evaluation encl PAGE,R G Uranium Fuel Licensing Branch 83/09/23 SCHNELL,D F Union Electric Co ip 20627 356
- --B310040137 Safety evaluation supporting Amend 3 to License SNM-1901 SERINI, B L , CROW, W 7 Uranium Fuel Licensing Branch B3/09/23 3pp 20627 357

DOCKET 70-2946 LOVISIANA POWER & LIGHT CO , NEW ORLEANS, LA

- DOCKET 70-2949 ARIZONA PUBLIC SERVICE CO . PHOENIX. AZ
- 8310040174 IE Insp Findings & Licensee Ack 4td 830713 of License SNM-1887 Insp findings no violations observed SKOV.D D Region 5: Office of Director 83/07/26 1p 20448 353.

DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

- DOCKET 70-2960 KANSAS GAS & ELECTRIC CO , WICHITA, KS
- 8310170644 Forwards Rev 2 to SNN license application updating technical info re crane usage fire protection & security for SNM & dosimetry for fuel handling activities Six fission chambers & 10 detector foils also added to application KOESTER. G L Kansas Gas & Electric Co 83/09/23 DAVIS.J 0. Office of Nuclear Material Safety & Safeguards, Director 2pp 20780 205
- --8310170654 Rev 2 to BNM license application updating technical info to crane usage, fire protection & security for SNM & dosimetry for fuel handling activities * Kansas Oas & Electric Co 83/09/30 12pp 20798 207
- 8310210075 Forwards Rev 2 to SNM license application, providing technical info updates re crane usage, fire protection & security for SNM KCESTER, O.L. Kansos Gas & Electric Co 83/07/23, DAVIB, J Q Office of Nuclear Material Safety & Safeguards, Director 3pp
- --8310210100 Rev 2 to application for SNM license for receipt & possession of reactor fuel & associated matl from Wolf Creek
 - kansas Gas & Electric Co 83/09/23 11pp. 20883 255
- DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO . CLEVELAND, OH
- 8310170613 Forwards response to 830325 request for add1 info re license application for storage only of unirradiated reactor fuel & associated radioactive mat1 at Perry Unit 1 EDELMAN.M R Cleveland Electric Illuminating Co 83/05/27 KILLINGER.M H Uranium Fuel Licensing Branch 5pp 20614.149.
- DOCKET 70-2973 COMMONWEALTH EDISON CO , CHICAGO, IL
- 831017071B Forwards Rev 1 to Security plan for 9NM security.per 10CFR70 32(e) Rev withheld (ref 10CFR73 21) FARRAR.D L Commonwealth Edison Co 83/09/13 BROWN.W Fuel Facility Safeguards Licensing Branch 1p 20798 115

DOCKET 70-2977 DETROIT EDISON CO . DETROIT, MI

- B310250575 Forwards IE Safeguards Insp Repts 70-2977/83-01 & 70-2977/83-02 on 830926-27 & 30 No noncompliance noted AXELSON,N E Region 3, Office of Director 83/10/21 WELLS,D A Detroit Edison Co. 2pp. 20900 303
- --83102505B2 IE Safeguards Insp Repts 70-2977/83-01 & 70-2977/83 02 on 830926-27 & 30 No noncompliance noted Major areas inspected SNM controls & accountability & new fuel security Details withheld (ref 10CFR2 790)
 MADEDA, I J , KNICELEY, JR , CREED, JR Region 3, Dffice of Director 83/10/21 lp 20900 305

DOCKET 70-2983 PENNSYLVANIA FOWER & LIGHT CO , ALLENTOWN, PA

8310240099 Determines that 830505 physical security plan for protection of SMM of low strategic significance meets requirements of 10CFR73 67 7 Plan must be fully implemented by fuel receipt date BROMM.W II Fuel Facility Safeguards Licensing Branch 83/07/14 CURTIS.N W Pennsylvansa Power & Light Co. 1p. 20891 356

DOCKET 70-2988 PHILADELPHIA ELECTRIC CO . PHILADELPHIA, PA

- 8310170225 Responds to 830915 telcon request for add) info re SNM license application for Limerick Unit 1 KEMPER, J B Philadelphia Electric Co 83/09/20 PAGE,R G Uranium Fuel Licensing Branch. 4pp 20796 288
- 8310060543 Forwards License SNM-1926 authorizing receipt, possession, storage & use of U enriched in U-235 contained in fission chambers PAGE.R O Uranium Fuel Licensing Branch 83/09/23 BAVER.E O Philadelphia Electric Co 2pp 20661 287
- --8310060548 License SNM-1726 for Philadelphia Electric Co authorizing use of U enriched in U-235 contained in sealed sources PAGE.R G Division of Fuel Cycle & Material Safety 83/07/23 2pp 20661 287
- --8310060553 Safety evaluation supporting License SNM-1926 re receipt, possession & use of fission chambers
 EERINI, B L Uranium Fuel Licensing Branch B3/09/23 31pp 20661 291

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0037 NAVY, DEPT OF

- 8310050124 Forwards GA program approval for Radioactive Matl Package 0037.Rev 2 MACDDNALD.C E Transportation Branch B3/09/23 Navy, Dept of 1p 20650 055
- -8310050133 QA program approval for Radioactive Matl Package 0077.Rev 2 MACDONALD.C E Transportation Branch 83/09/23 ip 20450-054

JOCKET 71-0059 GENERAL ELECTRIC CO

8310050014 Informs that GA program approval for Radioactive Matl Package 0039 terminated after 830923 per 830909 request MACDONALD.C E Transportation Branch 83/09/26 JOLLY, J Gineral Electric Co | p 20650 260

DOCKET 71-0137 METALS TESTING CO . INC.

8310170322 Advises that on Jul 1980 ownership changed & radiographic insp sycs discontinued Future FR changes or certificates of compliance for radioactive matl not needed.

CAYEN.C F Metals Testing Co. Inc. 83/09/13 MACDONALD.C F Transportation Branch. 2pp 20793: 276

DOCKET 71-0148 UNITED ENGINEERS & CONSTRUCTORS, INC.

8310190269 Ack receipt of Rev 1 to GA program approval for Kadioactive Matl Packge 014B submitted in support of Matls/Byproduct License 37-01546-04 GA program inactive since 800630.per encl Amend 5 to license POLTOUIN, T E United Engineers & Constitutors, Inc. (subs. of Raytheon Co.) 83/09/23 MACDONALD.C E Transportation Branch 1p. 20843 197

DOCKET 71-0466 MINNESOTA MINING & MANUFACTURING CO (3M CD)

- 8310040094 Forwards QA program approval for Radioactive Matl Package O466.Rev 3 MACDONALD.C C. Transportation Branch 83/09/23 HEDLAND,R 3M Co. Minnesota Mining & Mfg. Co. 1p. 20434-357
- --8310040079 OA program approval for Radioactive Matl Package 0466.Rev J MACDONALD.C E Transportation Branch 83/09/23 1p 20634 358

DOCKET 71-0503 PENN INSPECTION CO

- BJ10130253 Forwards response to 830824 request re organization, GA/GC program & implementing procedures
 PATTERSON.H Big State X-Ray B3/09/26 MACDONALD, C £
 Transportation Branch 6pp 20/54 351
- 8310240305 Forwards QA program approval for Radioactive Matl Package 0503.Rev 0 MACDUNALD,C C Transportation Branch 83/10/18 PATTERSON, H Pani Inspection Co Ip 20904 358
- --0310240307 GA program approval for Radioactive Matl Package 0505.Rev 0 MACDDNALD.C E Transportation Branch 83/10/18 ip 20/04/359

DOCKET 71-0504 TEXAS UTILITY GENERATING CO

- 8310180379 Notifies of intention to apply 10CFR50.App D GA program to packaging & transportation of radioactive matls as required by 10CFR71 Bi & 10CFR71 101(b) KUYKCNDALL, J C Texas Utilities Generating Co 83/09/17 Offic of Nuclear Material Safety & Safeguards, Director 1p 20825 359
- 8310240317 Forwards QA program approval for Radioactive Matl Package 0504:Rev 0 MACDOMALD, C E Transportation Branch 83/10/18 JONES R A Texas Utilities Generating Co ip 20907 163
- --9310240319 GA program approval for Radioactive Matl Package O504. Rev O MACDONALD.C E Transportation Branch 83/10/18 Ip 20907 t64

DOCKET 71-0505 SOUTHWEST RESEARCH INSTITUTE

- 8310170343 Provides matrix showing applicability of GA program manual to Reg Guide 7 10 for shipment of reactor pressure vessel surveillance capsules.per 830920 telcon NORRIS,E B. MARRITO,B. Southwest Research Institute 83/09/21 GORDON.L. Transportation Branch 3pp 20842 303
- 8310110402 Forwards QA program approval for Radioactive Matl Package 0305 Rev 0 MACDONALD,C E Transportation Brunch 83/09/29 MABRITO, B Southwest Research Institute 1p 20713 342
- --5310110410 QA program approval for Radioactive Matl Package 0505, Rev 0 MACDUNALD.C E Transportation Branch 83/09/29 ip 20713 343

DOCKET 71-0505 BABCOCK & WILCOX CO

- 8310110416 Forwards QA program opproval for Radioactive Matl Package O306, Rev O MACDDALD, C E Transportation Branch 83/09/29 FERREE, D V. Babcock & Wilcox Co ip 20713 352
- --8310110423 0A program approval for Radioactive Matl Package 0506.Rev O MACDONALD,C E Transportation Branch 83/09/29 jp 20/13 353

- DOCKET 71-4909 NODEL GE-21PF-1, GENERAL ELECTRIC CO
- 8310050019 Informs that drawings submitted w/830720 application re Model W-2:PF-1 packaging will be placed in PDR unless withholding requested within 15 days of 1tr MACDINALD, C. E. Transportation Branch 83/09/24 NARDI, A. J. Westinghouse Ejectric Corp. jp. 20630 271
- 8310170342 Requests registration as user of Models GE-21PF-1 & W-21PF-1 WEINTRAUB, A A Energy, Dept of 83/10/03 MACDDNALD, C E Transportation Branch 1p 20795 239
- DOCKET 71-5059 MODEL NES-URANYL NIT , NUCLEAR FUEL SERVICES, INC.
- 8310050114 Notification of registration as user of Model NFS-VRANYL-NIi in response to 830901 request MACDONALD.C £ Transportation Branch 83/09/26 MAICR.J B Allied General Nuclear Services ip 20650 237
- DOCKET 71-5088 MODEL 034710-1, 034710-2, ROCKWELL INTERNATIONAL CORP
- 8310050097 Notification of registration as user of Models D 34710-1 & B 34710-2 in response to 830927 request MACDDNALD, C E Transportation Branch 83/09/26 CDDK, G M Michigan, Univ of, Ang Arbor, M1 Ip 20550 054
- DOCKET 71-\$450 MODEL RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP
- 8310200451 Application to amend Certificate of Compliance 5450 for RCC shipping package.increasing fuel enrichment by limiting shipment to one fuel assembly per shipping container NARDI. A J Wastinghouse Electric Corp 89/10/04 MACDONALD, C E Transportation Branch 4pp 20844 352
- 8310240257 Ferwards Rev 17 to Certificate of Compliance 5450 for Models RCC.4RCC-1.RCC-2.RCC-3 & RCC-4 MACDDNALD.C E Transportation Branch 83/10/13 NARDI.A J Westinghouse Electric Corp 2pp 20907 268
- --8310240259 Certificate of Compliance 5450,Rev 17.for Models RCC.RCC-1, RCC-2,RCC-3 & RCC-4 MACDDNALD.C E Transportation Branch 83/10/13 App 20907 270
- DOCKET 71-5595 MODEL LAM ORNL URANIUM SHIELDED CASK, ENERGY, DEPT OF
- 8310190335 Forwards Certificate of Compliance 5595.Rev 5 for Models L & M Changes include deletion of detemposition temp for special form, corrections to print ref & changes re rev to DOT regulations TRAVIS.W H Energy, Dept of 83/09/30 MACDONALD.C E Transportation Brench 1p 20843 167
- B310170170 Forwards Rev 5 to Certificate of Compliance 5595 for Models L & M ORNI U shielded cask WEINTRAUB.A A Energy, Dept of B3/10/04. MACDONALD,C E Transportation Branch 3pp 20798:202
- --8310170175 Certificate of Compliance 5595,Rev 5,for Models L & M CANL U shielded cask TRAVIS,W H Energy: Dept of 83/09/20 2pp 20798 204
- 8310190237 Forwards Rev O to Certificate of Compliance 5575 for Model Lam MACDOMALD, C E Trensportation Branch 83/10/13 WEINTRAUB, A A Energy, Dept of ip 20838 087
- --9310170240 Certificate of Compliance 5575, Rev O. for Model L&M MACDONALD, C E Transportation Branch 83/10/13, 4pp 20838:08D,
- DOCKET 71-5797 MODEL INNER & OUTER HFIR UN, ENERGY, DEPT OF
- 8310200333 Requests registration as user of Models HFIR.UN & TREAT. REGAN.N.A Babcock & Wilcox Co 83/10/10 MACDONALD.C E Transportation Branch 3pp 20844 266

- DOCKET 71-5805 MODEL CNS 3-55, CHEM-NUCLEAR SYSTEMS, INC
- 8310190332 Application for rev to Certificate of Compliance 5805 for CNS 3-55 cask allowing 15 shipments of activated stainless steel in thermal shield sections for transport to Barnwell aute by 831231 Fee encl POPPE, L K Chem-Nuclear Systems, Inc 83/08/10 MACDONALD, C E Transportation Branch 5pp 20842 298
- DOCKET 71-5828 MODEL TREAT, ENERGY, DEPT OF
- 8310200333 Requests registration as user of Models HFIR,UN & TREAT REGAN,N A Babcock & Wilcox Co 83/10/10 MACDONALD.C E Transportation Branch 3pp 20844 266
- DOCKET 71-5908 MODEL DOT-AM TYPE B, BADCOCK & WILCOX CO
- 8310130249 Requests registration as user of Model DOT-6M BOATRIGHT.P A 01 Corp 83/09/28 MACDONALD.C E Transportation Branch 2pp 20754 357
- DOCKET 71-5939 MODEL GE-1500, GENERAL ELECTRIC CD
- 8310170744 Requests registration as user of Model QE 1500 WEINTRAUB.A A Energy, Dept of 83/09/28, MACDONALD.C E Transportation Branch 2pp 20796 355
- 8310190272 Summary of B31007 meeting w/GE in Silver Spring.MD reproposed amends to package design concerning Models GE-200.1000.1600 & 6500
 ODECARDEN.R H Transportation Branch 83/10/13 Transportation Branch 2pp 20843 165
- DOCKET 71-5957 MODEL BM1-1, BATTELLE COLUMBUS LABORATORY
- 8310070005 Forwards request for add1 info needed to complete review of request for amend to Model BMI-1 packaging. Info should be submitted in form of revised pages within 30 days of ltr date MACDONALD.C E Transportation Branch 83/09/22 BURIAN.R J Hattelle Memorial Institute. Columbus Loboratories 3pp 20674-360
- 8310050077 Notification of registration as user of Models D 34710-1 & D 34710-2 in response to 830922 request MACDONALD, C E Transportation Branch 83/09/26 COCK. C. M Michigan, Univ of, Ann Arbor, MI Ip 20650 054
- DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO
- 83:0190272 Summary of 83:007 meeting w/GE in Silver Spring.MD reproposed amends to package design concerning Models GE-200.18:00, 16:00 & 85:00 GE-200.18:00, 16:00 & HD00 GE-200.18:00, 16:00 & GE-200.18:00 GE-200.
- DOCKET 71-6009 MODEL: M-130, ENERGY, DEPT OF
- B310050016 Forwards Rev 6 to Certificate of Compliance 6003 for Model M-130
 MACDUNALD,C E Transportation Branch B3/09/26 ENGEL.W P
 Energy, Dept of lpp 20650 261
- --8310050041 Certificate of Compliance 6003.Rev 6, for Model M-130. MACDONALD, C.E. Transportation Branch 83/09/26. 6pp 20650 262
- DOCKET 71-6144 MODEL: B-2, U S ECOLOGY, INC
- 8310200422 Forwards summary of radioactive matls inventory scheduled for delivery to Monterrey, Mexico to reestablish business operations MALKER, E.L. Ead Metallurgical, Inc. 83/09/28. RAWL, R.R. Transportation, Dept. of 10pp 20859 283
- 8310130075 Summary of B30928 meeting w/EAD Metallurgical. Inc in Bilver Spring. MD re shipment of radioactive matl stored in Richer Harehouser-Laredo. TX to Monterey. Mexico for reestablishment of smoke detector business

 ODEGAARDEN.R H Fransportation Branch 83/10/06. Transportation Branch 2pp. 20777 025

- 8310200012 Amends Certificate of Compliance 6144 to authorize certain radioactive maths described in 830923 ltr as add1 contents for Model 8-2 McCDONALD.C E Transportation Branch 83/10/13 WALKER.E L Ead Metallurgical, Inc. 2pp. 20844-263
- BOCKET 71-6166 MODEL O ST. ENERGY, DEPT OF
- 8310110619 Forwards Rev 2 to Certificate of Compliance 6166 for Model 0 9T MACDONALD.C E Transportation Branch 83/10/06 JACKSON,C D Energy, Dept of 1p 20701 393
- --8310110622 Certificate of Compliance 6166.Rev 2 for Model 0 5T MACDONALD,C E Transportation Branch 83/10/06 3pp 20701 354
- DOCKET 71-6346 MODEL FSV-1, GA TECHNOLOGIES, INC
- 8310130270 Application for amend to Certificate of Compliance 5346, allowing use of 2x4-inch bar of steel fashioned into 13-inch ID ring as added shielding for contents of burial liner HOWAY, W.R. GA Technologies, Inc./General Atomic Co. B3/09/19 MACEDNALD, C. Transportation Branch 2pp 20751 284
- --8310130274 "Consolidated Design Rept for Fort St Vrain Fuel Shipping Cask" * GA Technologies Inc /General Atomic Co. GADR-55 ADD04 83/09/30 & GOpp 20781 286
- 8310170064 Forwards section of Chapter 2 from "Theory of Flow & Fracture of Solids." Vol 2 by A Nadai.in response to criticisms of safety analysis. CADR. Addendum IV. Rev 1 for waste canister for small highly irradiated hardware MOWRY.N R GA Technologies. Inc / General Atomic Co 83/09/30 MACDONALD.C Transportation Branch App 20798 029
- DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP
- 83i0170739 Forwards add1 info supporting Naval Reactors 830422 statement re reactivity effect of replacing all or part of polyurethane foam w/water Reactivity level would decrease slightly due to importance of neutron absorption ENOBL.W P Energy. Dept of 83/09/26 MACDONALD.C E Transportation Branch. 5pp 20796-35/
- 8310040332 Summary of 830922 meeting w/Sandia Natl Labs in Bilver Spring, MD re shipments of transuranic waste matls in TRUPAC packaging. ODECARDEN, R H Transportation Branch 83/09/29 Transportation Branch 2pp 20660.212
- DOCKET 71-6478 MODEL 4T, ENERGY, DEPT OF
- B310120001 Forwards Rev 2 to Certificate of Compliance 6478 for Model 4T MACDONALD, C E Fransportation Branch 83/10/06 JACKSON, C D Energy, Dept of 2pp 20749 356
- --83i0120002 Certificate of Compliance 6478, Rev 2. for Model 4| MACDONALD, C E Transportation Brench 83/10/06 3pp 20749 350
- DOCKET 71-6550 MODEL 6-08-1, ENERGY, DEPT OF
- B310170306 Application for rev to Certificate of Compliance 6550 to approve use of shielded shipping cask sys for shipment of 1 Ci Re-226 in form of RaBr(2) in spherical beryllium container

 WEINTRAUB.A.A Energy, Dept. of. B3/10/04. MACDONALD.C E Transportation Branch. 11pp 20796 134
- DOCKET 71-6574 MODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP.
- 8310200014 Requests registration as user of Hittmen Nuclear & Development Corp Model HN-200.
 ZUPKO, J. M Public Bervice Electric & Gas Co of New Jersey
 83/07/29 MACDONALD, C E Transportation Branch 2pp. 20844 261
- 9310240289 Notification of registration as user of Model HN-200 in response to 830729 request.

 MACDONALD.C E Transportation Branch 83/10/18 MIDURA.H J.

 ublic Service Electric & Gas Co. of New Jersey. Ip 20907-327

- DOCKET 71-6601 MODEL CNS 8-120, CHEM-NUCLEAR SYSTEMS, INC
- 8310170748 Application for renewal of Centificate of Compliance 8601 for Model CNS 8-120 SAR encl CORBETT./ S Chem-Nuclear Systems, Inc 79/11/19 MACDONALD.C L Transportation Branch 1p 20012 001
- --83:0170750 "SAR for Shipment of Radioactive Matl in (NS 8-120 (LL-50-100) Cask "

 * Chem-Nuclear Systems, Inc 79/10/31 152pp 20812 808
- DOCKET 71-6679 NODEL 6679, U.S. ECOLOGY, INC.
- 8310200330 Advises that response to 830914 request for add1 info re 821223,830410 & 0630 applications for renewal of Certificate of Compliance 6679 will be provided by 831104 WALLER, W.K. U.S. Ecology, Inc. (formerly Nuclear Engineering) 83/10/12 MACDONALD, C.E. Transportation Branch 2pp 26844 272
- DDCKET 71-6697 HODEL GE-8500, GENERAL ELCCTRIC CO
- B310170232 Requests registration as user of Model GC-8900 Forwarding address for all future correspondence & documentation provided DEAL-R C. Chem-Nuclear Systems, Inc. B3/09/30 MACDONALD, C & Transportation Branch 2pp 20796 282
- 831019027.2 Summary of 831007 meeting w/GE in Silver Spring.MD re proposed amends to package design concerning Models GE-200, 1800, 1600 & 8500 ODECAARDEN,R H Transportation Branch 83/10/13 Transportation Branch 2pp 20843 165
- DOCKET 71-6771 MODEL SN-1, METROPOLITAN CDISON CO
- B310190351 Requests registration as user of Models NUPAC 14/190L, NUPAC 14/190H, NUPAC 14/190M & SN-1 Forwarding address for all future correspondence provided

 DEAL R L Chem-Muclear Systems, Inc 83/09/22 MACDONALD, C E Transportation Branch 2pp 20843 171
- 8310240277 Notification of registration as user of Models BN-1 & NUPAC-14/190L,14/190H & 14/190M in response to 830922 request MACDONALD, C.E., Transportation Branch 83/10/18 DEAL, R. Chem-Nuclear Systems, Inc. 1p. 20704-330
- DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO
- 8310070017 Requests submittal of consolidated application, w/drawings-incorporating all previous submittals, for renewal of Certificate of Compliance 9009 for Model Ft. 10-1 packaging Rev 10 will not expire until final NRC determination MACDUNALD, C E Transportation Branch 83/09/22 VAUGHAN, C M General Electric Co 1p 20671 363
- DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC
- 8310170234 Discusses status of util preparations to remove spent fuel from Hestern New York Nuclear Svc Ctr Utils will rely on DGE to undertake all activities re loading fuel for shipment per B30812 meeting Ltr forwarded to DGE enc! CHARNOFF, O Shaw, fittman, Potts & Trombridge CHARNOFF, O Hisconsin Electric fower Co CHARNOFF, O Commonwealth Edison Co B3/09/21 MACDONALD, C E Transportation Branch 9pp 20/96 273
- B310190328 Requests registration as user of Model NLI-1/2 for License DPR-16 FIEDLER,P B General Public Utilities - GPU Service Corp Office of Nuclear Material Safety & Safeguards, Director 20842 295
- 8310250015 Notification of registration as user of Model NLI-1/2 in response to 830926 request MACDDNALD.CE Transportation Branch 83/10/18 SNIDER.T General Public Utilities - OPU Service Corp 1p 20916 109

DOCKET 71-9016 MODEL TN-9, NO USERS

- 8310170234 Discusses status of util preparations to remove spent fuel from Western New York Nuclear Svc Ctr Utils will rely on DDE to undertake all activities re loading fuel for shipment, per 830812 meeting Lti forwarded to DDE encl CHARNOFF, G Shaw, Pittman, Potts & Trombridge CHARNOFF, G Wisconsin Electric Power Co CHARNOFF, G Commonwealth Edison Co 83/09/21 MACDUNALD.C E Transportation Branch 9pp 20796 27.5
- DOCKET 71-9027 MODEL 741 & 741F, TECHNICAL OPERATIONS, INC
- 8310170221 Requests registration as user of Models 741,850,920 & 771 MALINOWSKI.F A Ebasco Services, Inc. (subs. of Enserch Corp.) 83/09/20 MACDONALD.C E Transportation Branch 2pp. 20796-294
- 8310240292 Notification of registration as user of Models 741.850,920 & 771 in response to 830920 request
 MACDDNALD.C E Transportation Branch 83/10/18 BULLEN.H C
 Ebasco Services, Inc (subs of Enserch Corp.) ip 20904 349
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- 8310190293 Requests registration as user of Models 660 & 650 DRIGGERS, S E LaBarge, Inc 83/09/29 Transportation Branci ip 20842 050
- 8310170215 Requests registration as user of Tech/Ops Model 650 KAWACHI,M H. Navy, Dept of, Pearl Harbor Naval Shipyard 83/10/03 MACDDNALD,C C. Transportation Branch Ip 20797 361
- DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC.
- 8310190273 Requests registration as user of Models 660 & 650 DRIGGERS: S E LaBarge, Inc. 83/09/29 Transportation Branch 1p. 20842-050
- 8310170209 Requests registration as usor of Tech/Ops Model 440 KAWACHI.M Navy, Dept of, Peerl Harbor Naval Shipyard 83/10/12 MACDONALD.C E Transportation Branch 1p 20798 085
- DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC
- 8310170334 Requests registration as user of Model 715 Rev 6 to Certificate of Compliance 9039 encl LEMIS.L Duke Power Co 83/09/27 MACDONALD.C E Transportation Branch 1p 20795 269
- 8310250022 Natification of registration as user of Model 715 in response to 830927 request MACDONALD.C E Transportation Branch 83/10/18 PARKER.W 0 Duke Power Co 1p 20908 359
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- B310190272 Summary of B31007 meeting w/GE in Bilver Spring,MD re proposed amends to package design concerning Models GE-200, 1500, 1600 & 8500 ODEGAARDEN,R H Transportation Branch B3/10/13 Transportation Branch 2pp 20843
- DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF
- B310170027 Application for rev to Certificate of Compliance 7070 to include fissile powder as authorized contents of overpeck shipping container Model N~55 ENGEL.W F Energy. Dupt of B3/07/27 MACDONALD, C E Transportation Branch 4pp 2079B 34B
- 9310060599 Forwards Rev 9 to Certificate of Compliance 9070 for Madel N-55 MACDDNALD,C E Transportation Branch 83/09/29 SIMCHUK,J D Nuclear Packaging, Inc. 3pp. 20661 193
- --8310060600 Certificate of Compliance 9070.Rev 9. for Model N-55 Approval record encl MACDDNALD,C E Transportation Branch 83/09/29, 4pp 20661 156

- 8310110090 Amends Certificate of Compliance 9070 to authorize U oxide bearing waste matis containing up to 5 g U-233 & U-235 as add1 contents of Model N-55 package Approval record encl MACDONALD.C E Transpartation Branch 83/09/29 ENGEL.W P. Energy. Dept of 2pp 20687 351
- DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8310050046 Marked-up memo advising that enc1 Hittman Nuclear & Development Corp 830818 proprietary application, associated SARs & drawings re Model 9080 package design should be placed in PDR MACDONALD,C E Transportation Branch 83/08/18 SCOTT,8 Document Management Branch 1p 20650 076
- --B310030036 Forwards responses to NRC 830620 ltr re application for renewal of Certificate of Compliance 9080, authorizing use of Model 9080 radioactive matts package W/three oversize drawings Aperture cards are available in PDR PHILLIPS, J W Hittman Nuclear & Development Corp (subs of Hittman Corp) 83/08/18 MACDONALD, C E Transportation Branch 5pp 20650 077
- --8310050065 Replacement pages for "SAR for Model 9080 Radweste Shipping Cask" * Hittman Nuclear & Development Corp (subs of Hittman Corp). 83/08/18 23pp 20650 OBI
- --8310050074 Rev 5 to Procedure HNDC-0-001-7, "Cask Handling Procedure for HN-600 Shielded Transport Cask " * Hittman Nuclear & Development Corp (subs of Hittman Corp). 83/08/15 18pp 20650 104
- 83:0190324 Requests registration as user of Comm Ed Model 7-100 for License DPR-40 Forwarding address for all future correspondence t documentation provided JONES, W.C. Undha Public Power District 83/09/16 MACDONALD.C.E Transportation Branch 2pp 20842 293
- 83:0050195 Forwards request for addl info re renewal of Certificate of Compliance 9080 for Model 9080 packaging Info should be submitted in form of revised pages within 45 days MACDONALD:C Transportation Branch 83/09/22 PHILLIPB.J.W. Hittman Corp 2pp 20650 214
- DOCKET 71-9084 MODEL HN-100, SERIES 1, HITTMAN NUCLEAR & DEV. CORP
- 8310190302 Requests registration as user of Hittman Nuclear & Development Corp Model HN-100 ZUPKO,J M Public Service Electric & Gas Co of New Jersey B3/07/29 MACDONALD,C E Transportation Branch. Ip 20840,325
- 8310310428 Advises that encl proprietary drawing & 831011 application re Model HN-100 Series 1 package design should be placed in PDR MACDONALD.C E Transportation Branch 83/10/14 800TT.S Document Management Branch 1p 20965
- --B310310430 Forwards, for ref, one oversize drawing reflecting as-built configuration of drain plug Tube outer edge joined around perimeter of cask body w/existing fillet weld Aperture card is available in PDR LEDUC, R. J. Hittman Nuclear & Development Corp. (subs of Hittman Corp.) B3/10/11 MACDONALD, C. Transportation Branch 2pp. 20945 120
- 8310240308 Notification of registration as user of Model HN-100. Beries I in response to 830727 request MACDUNALD, C E Transportation Branch 83/10/18 HIDURA, H J Public Bervice Electric & Gas Co of New Jarsey Ip. 20704 360.
- DOCKET 71-9089 MODEL HN-1008, HITTMAN NUCLEAR & DEVELOP, CORP
- 8310170278 Requests registration as user of Hittman Nuclear & Development Corp Model HN-1008 for License DPR-28 MURPHY: WP Vermont Yankee Nuclear Power Corp 83/09/28 Office of Nuclear Material Safety & Safeguards, Director. 3pp 20841:338
- 8310250029 Notification of registration as user of Model HN-1008 in response to 830928 request.

 HACDDNALD.C E Transportation Branch 89/10/18 Vermont Yankee Nuclear Power Corp. 19 20408.338

- DOCKET 71-9092 MODEL HN-300, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8310170228 Application to revise Certificate of Compliance 9092 for HNDC Hode! HN-300, extending expiration date to 891130 LEDUC,R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 82/09/30 MACDDNALB,C Transportation Branch 1p 20794 286
- DOCKET 71-9093 HODEL HN-400, HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8310170218 Application to revise Certificate of Compliance 9093 for HNDC Model HN-400, extending expiration date to BB130 LEDUC, R J Hittman Nuclear & Development Corp (subs of Hittman Corp) 83/09/30 MACDONALD, C Transportation Branch 1p 20797 359
- DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC
- 8310170211 Requests registration as user of Model CNS 21-300 MELSHJJ A International Neutronics, Inc 83/10/04 MACDONALD, C F Transportation Branch 1p 20798 083
- DOCKET 71-9100 MODEL KKP-20-4950, KERR-MCGEE NUCLEAR CORP.
- 8310050053 Forwards Rev 4 to Certificate of Compliance 9100 for Model KKP-20-4950 MACDONALD.C E Transportation Branch 83/09/26 SHELLEY,W J Kern-McGee Nuclear Corp 2pp 20650 145
- --8310050057 Certificate of Compliance 9100,Rev 4.for Model KKP-20-4950 MACDONALD.C.E Transportation Branch 83/09/26 4pp 20650 147
- DOCKET 71-9105 MODEL RAD-WABTE CR. 1, CHEM-NUCLEAR SYSTEMS, INC
- 8310170192 Forwards response to 830425 questions re Model CNS 6-101 shipping package Rev 1 to SAR for Model CNS 6-101 also encl POPPE, L K Chem-Nuctear Systems, Inc 63/09/30 MACDONALD, C E Transportation Branch 7pp 20813 011
- --8310170195 Rev I to "SAR for Chem-Nuclear Sys, Inc Model CNS 6-101 Type A Radwaste Shipping Cask " * Chem-Nuclear Systems, Inc 83/09/30 12pp 20813 017
- DOCKET 71-9107 MODEL: 771, TECHNICAL OPERATIONS, INC
- 6310170221 Requests registration as user of Models 741.850,920 & 771 MALINOWSKI,F A Ebasco Services, Inc. (subs of Enserch Corp.) 63/09/20 MACDONALD,C E Transportation Branch 2pp 20796-294
- B310240292 Notification of registration as user of Models 741,880,920 & 771 in response to 830920 request MACDDNALD,C E. Transportation Branch. B3/10/18 BULLEN.H C Ebasco Services, Inc (subs of Enserch Corp) ip 20904 349
- DOCKET 71-9108 MODEL CNS 6-75, CHEM-NUCLEAR SYSTEMS, INC
- 8310110628 Forwards Rev 4 to Certificate of Compliance 9108 for Model CNB 6-75 MACDONALD.C E Transportation Branch 83/09/30, DEAL.R Chem-Nuclear Systems, inc. 3pp. 20706 349
- --8310110431 Certificate of Compliance 9108, Rev 4, for Model CNS 6-75 MACDDNALD, C. E. Trensportation Branch 83/09/30 5pp 20706 352.
- DOCKET 71-9111 MODEL: CNS 6-80-2 & CNS 6-80-2A. CHER-NUCLEAR SYS. INC.
- 8310170605 Advises that Model CNBA-BO-2 will be used for shipment of radioactive matl generated at Duster Creek FIEDLER,P,B General Public Utilities GPU Service Corp. 83/09/16 Office of Nuclear Material Safety & Safeguards, Director 3pp 20814:1446.
- 8310260013 Notification of registration as user of Model CNS 6-80-2 in response to 830916 request, MACDONALD, C.E. Transportation Branch. 83/10/18 SNIDER, T. General Public Utilities GPU Service Corp., ip., 20928-046

- DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRICE
- 8310170295 Forwards payments for request for renewal of Certificates of Compliance 9126,9127 & 9128 which expire on 831031 Existing & future packages will be mfg & used according to previously submitted drawings & info STUCKEY.8 G Nuclear System 83/09/13 MACDONALD.C E Transportation Branch 2pp 20/96 241
- 93i01i0625 Forwards Rev 3 to Certificate of Compliance 4126 for Models 20,20A:50 & 50A MACDOMALD, C E Transportation Branch B3/10/06 RIDDLE, D H Nuclear System 2pp 20706 357
- --8310110627 Certificate of Compliance 4126, Rev 3, for Models 20, 20A. 5 50A MACDUNALD, C E Transportation Branch 83/10/06 3pp 20706 35
- DOCKET 71-9127 MODEL 100, 100A, 200, 200A, GAMMA INDUSTRIES
- B310170295 Forwards payments for request for renewal of Certificates of Compliance 9126,9127 & 9128 which expire on B31031 Existing & future packages will be mfg & used according to previously submitted drawings & info STUCKEY.S G Nuclear System B3709/13 MACDONALD.C F Transportation Branch 2pp 20796 241
- 8310110621 Forwards Rev 3 to Certificate of Compliance 9127 for Medel 100.100A; 200 & 200A MACDDNALD, C & Transportation Branch 83/10/06 RIDDLE, D H Nuclear System 2pp 20714 352
- ---8310110423 Certaficate of Compliance 9127, Rev 3, for Models 100,1004 & 200A MACDONALD, C E Transportation Branch 83/10/04 3pp 20714 35
- DOCKET 71-9128 MODEL C-8, GAMMA INDUSTRIES
- B310170295 Forwards payments for request for renewal of Certificates of Compliance 9126,9127 & 9128 which expire on B31031 Existing & future packages will be mfg & used according to previously submitted drawings & info STUCKEY,8 g Nuclear System 83/09/13 MACDONALD,C E Transportation Branch 2pp 20796 241
- B310170355 Requests registration as user of Model C-B *AHACHI.M H Navy. Dept of, Pearl Harbor Naval Shipyard B3/10/0 MACDONALD.C E Transportation Branch ip 20795 238
- 8310110611 Forwards Rev 3 to Certificate of Compliance 912B for Model C-8 MACDONALD,C E Transportation Branch 83/10/06 RIDPLE.D H Nuclear System. 2pp 20703 346
- --8310110614 Certificate of Compliance 9128, Rev 3, For Model C-8 MACDDNALD, C E Transportation Branch 83/10/06 3pp 20703 34
- DOCKET 71-9132 MODEL THS. ENERGY, DEPT OF
- 8310170291 Forwards amended Page 6-6 to T-3 SAR clarifying 830215 request for add1 info re test procedure insuring all residual sodium clarified MANSEN.L J Pacific Nuclear Systems & Services, Inc. 83/09/19 MACDUNALD.C E Transportation Branch 3pp 20796 242
- DOCKET 71-9143 MODEL: 920, TECHNICAL OPERATIONS, INC
- 8310170221 Requests registration as user of Models 741,850,920 & 771 MACINOWSKI,F A Ebasco Services, Inc. (subs of Enserch Corp.) 83/09/20 MACDONALD.C E Transportation Branch 2pp. 20796-294
- B310240292 Notification of registration as user of Models 741.850,920 & 771 in response to B30920 request MACDDNALD.C E Transportation Branch 83/10/18 BULLEN.H C Ebasco Services. Inc (subs of Enserch Corp.) ip 20904 349

- BOCKET 71-9145 MODEL NUPAC 50-1 5L, -2 5L, -3 OL & -4 OL, NO USERS
- 8310190285 Application for rev to Certificate of Compliance 9145 for NUPAC 50. upgrading const matl to ASTM A-516 Grade 70 HANSEN.L J. Nuclear Packaging, Inc. BO/09/19 MACDUNALD.C E Transportation Branch Jpp 20840 204
- --831019028B Revised NUPAC 50 SAR * Nuclear Packaging, Inc 80/09/19 125pp 20840 20/
- DOCKET 71-9147 MODEL 850, TECHNICAL OPERATIONS, INC.
- B310170221 Requests registration as user of Models 741.850.920 & 771
 MALINDWERLER A Ebasco Services. Inc. (subs. of Enserth Corp.)
 B3/09/20 MACDDNALD.C E Transportation Branch 2pp 20796 294
- 8310240272 Notification of registration as user of Models 741,850,920 & /71 in response to 830920 request MACDUNALD.C E Transportation Branch 83/10/18 BULLEN.H C Ebasco Services, Inc (subs of Enserch Corp.) 1p 20904 349
- DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP
- B310030561 Forwards revised pages to 830629 application for Model HR-100, Beries 3 packaging, per B30824 request Summary of changes encl W/five oversize drawings Aperture rards are available in PDR VOIT.R E NUB Corp B3/09/12 MACDDNALD, C E Division of Fuel Cycle & Material Safety 2pp 20603 025
- --8310030568 Rev C to Procedure WM-014. "Operating Instructions for Loading & Unloading NUS-14-170 Series i Cask " * NUS Corp 83/09/12 18pp 20603 02/
- --B310030574 Rev B to Procedure MM-012, "NUS-14-170 Series 1 Maint "
 * NUS Corp B3/09/12 13pp 20603 045
- DOCKET 71-9152 MODEL CNS 1-13C II. CHEM-NUCLEAR SYSTEMS, INC
- 8310070099 Forwards Rev 4 to Certificate of Compliance 9152 for Model CNS 1-13C II MACDGNALDs C E Transportation Branch 83/09/26 DEAL.R Chem-Nuclear Systems, Inc. 2pp. 20671 344
- --8316070062 Certificate of Compliance 9152, Rev 4, for Model CNS 1-13C J1 MACDONALD, C E Transportation Branch 83/09/26 4pp. 20671 346
- DOCKET 71-9158 MODEL CNS 3-70, RIDIHALGH, EGGERS & ASSOCIATES
- B310050021 Ack withdrawal of B20126 application requesting approval of Undel CNS 3-70 packaging Review terminated HACDUNALD.C E Transportation Branch, 83/09/23 EGGERS,P E Ridihalgh, Eggers & Associates ip 20650-272
- DOCKET 71-9159 MODEL NUPAC 14/190L, /190M & /190H, NUCLEAR PACKAGING,
- B3:0190351 Requests registration as user of Models NUPAC 14/190L, NUPAC 14/190H, NUPAC 14/190M & SN-1 Forwarding address for all future correspondence provided DEAL, R L Chem-Nuclear Systems, Inc 83/09/22 MACDONALD, C E Transportation Branch 2pp 20843 171
- 8310240297 Notification of registration as user of Models SN-1 & NUPAC-14/190L,14/190H & 14/190M in response to 830922 request MACDONALD, C E Transportation Branch 83/10/18 DEAL, R Chem-Nuclear Systems, Inc. ip 20904 350
- DUCKET 71-9160 MODEL 20-VS & 40-VS, GULF NUCLEAR, INC
- 83101303B4 Forwards application for Type B certification for 20-VB & 40-VS Tadiography camera HOPCRAFT.C P Gulf Nuclear, Inc. 83/09/16 MACDONALD.C E Transportation Branch 1p 20770 017
- --B3101303B6 Application for Type D certification for 20-VS & 40-VS radiography camera # 901f Nuclear, Inc 83/09/16 33pp 20770,018

- DOCKET 71-9163 MODEL GNG-20, GULF NUCLEAR, INC
- 8310030028 Requests registration as user of Model ONG-20 PITTS.R W Petroleum Measurement Corp 83/08/30 MACDONALD.C E Transportation Branch 1p 20602 356
- DOCKET 71-9181 MODEL PAS-2, NUCLEAR PACKAGING, INC
- 8310210331 Forwards Rev 1 to 8AR in response to 830727 comments Rev provides testable containment boundary within sample shield cavity Authorization to ship NUPAC PAS-2 packaging by air requested HANSEN.L J Nuclear Packaging. Inc. 83/09/09 HACDONALD, C.E. Transcortation Branch. 3bp. 20882 157
- --8310210333 Rev 1 to NUPAS-2 9AR, changing containment boundary sample shield * Nuclear Packaging. Inc 83/09/09 55pp 20882 160
- DOCKET 71-9182 MODEL HUSMAN IRRADIATOR, AGRICULTURE, DEPT OF
- 8310040171 Forwards request for add1 info re 830516 application for Model Husman Irradiator packaging Add1 info should be submitted in form of revised pages Response schedule requested within 30 days MACDONALD,C E Transportation Branch 83/09/22 STREUTKER,8 R Nuclear Packaging, Inc. 3pp. 20627-360
- 8310170344 Forwards Rev 1 amends to Husman Irradiator BAR TEMUB.C J Nuclear Packaging, Inc. 83/10/03 MACDONALD.C E Transportation Branch ip 20796 299
- --8310170349 Rev 1 amends to Husman Irradiator BAR * Nuclear Packaging: Inc 83/10/31 13pp 20796 300
- 8310310481 Forwards request for add1 info re 830516 application, supplemented 831003, for approval of Husman Irradiator packaging Notification of planned submittal date requested within 30 days MACDONALD, C E Transportation Branch 83/10/21 TEMUS, C J Nuclear Packaging, Ins. 2pp 20765 188
- DOCKET 71-9184 MODEL PAS-1, NUCLEAR PACKAGING, INC
- 8310200408 Application for certificate of compliance for Model PAS-i TEMUS.C J Nuclear Packaging, Inc. 83/10/06, MACDONALD.C E Transportation Branch 9pp 20874 073
- --8310200415 "BAR for NUPAC PAB-1 Packaging to 10CFR71 Type B Packaging Requirements " * Nuclear Packaging, Inc B3/10/06 137pp 20874 082
- DOCKET 71-9510 MODEL OPHS, ENERGY, DEPT OF
- B310050025 Forwards Rev O to Certificate of Compliance 9510 for Nodel General Purpose Heat Bource Container MACDUNALD, C E Transportation Branch 83/09/23 PRICHARD, R P Energy, Dept of 19 20650 273
- --8310050030 Certificate of Compliance 9510 Rev O, for Model General Purpose Heat Source Container MACDUNALD, C. E. Transportation Branch 83/09/23 5pp 20650*274
- DOCKET 71-9852 MODEL DT-14, ENERGY, DEPT OF
- B310060023 Summary of B30922 meeting w/DDE & Union Carbide in Silver Spring, MD re proposed mods to Model DT-14 shipping container LAKE, W H Office of Nuclear Material Safety & Safeguards, Director, B3/09/25 Office of Nuclear Material Safety & Safeguards, Director ip 20863 362
- 8310240279 Forwards Rev 2 to Certificate of Compliance 9852 for Model DT-14 MACDUNALD,C & Transportation Branch 83/10/18 WEINTRAUB,A A Energy, Dept of ip 20704 351
- --8310240303 Certificate of Compliance 9852, Rev 2, for Model DT-14 MACDDNALD, C.E. Transportation Branch 83/10/18, 4pp 20904-352

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8310140212 Forwards 1E Insp Rept 72-0001/83-03 on 830729-0922 No Roncompliance noted PAPERIELLO,C J Region 3, Defice of Director 83/09/29 VAN HODMISSEN General Electric Co 2pp 20762 296 --8310140216 IE Insp Rept 72-0001/83-03 on 830729-0922 No noncompliants noted Major areas inspected spent reactor fuel shipping & general plant maint activities, radwaste mgt. 10CFR21 reporting & periodic maint of packagings LOVENDALE,P c., GREGER,L R., PIRTLE,G L. Region 3, Office of Director 83/09/29 9pp 20762 298

10040117 Transcript of 830916 meeting w/Advisory Panel on Decontamination of TMI-2 in Washington, DC Pp 1-65 4 Commissioners 83/09/16 69pp 20634 252 24X Tiche 50-320,83/09/16,8310040117 .0040592 Staff requirements memo re 830921 discussion in lashington,DC re public comments on waste confidence lectuion & proposed ravs to IOCFR50 & 51 Commission ontinued meeting in closed session ICYLE,J C Defice of the Secretary of the Commission M 33/09/23 ZERDE,J C Office of Policy Evaluations ip M830921B 0050107 Staff requirements memo re 83072; affirmation/discussion & outs in Washington, DC on Washington Legal Foundation motion of disqualify Commissioner Ollinsky Order disposing of nation approved Office of the Secretary of the Commission MB30921C Office of the Secretary of the Commission 1p IDYLE, J C 13/09/22 O050442 Transcript of Commission 830927 briefing in Washington.DC re 'acility schedule Pp i-34 Viewgraphs & supporting focumentation enc! I Commissioners 83/09/27 52pp 20640 218 24X 'iche 50-275.83/09/27.8310050442 O050448 Transcript of 830727 briefing in Washington, DC re rept of lommittee on Rights of Individuals in Investigations $\uparrow p$ 1-35 Supporting documentation encl : Commissioners 83709727 67pp 20640 146 O050450 Transcript of 830928 briefing by Torrey Pines, Inc in lashing ton, DC rs independent review of util project up t Pp i -66 Supporting documentation encl : Commissioners 83/09/28 133pp 20640 001 24X iche 50-358.83/09/28.8310050450 OO60463 Staff requirements memo on 830927 briefing in Washington, DC we rept of Committee on Rights of Individuals in avastigations HYLLK, S J Office of the Secretary of the Commission 13/09/30 PLAINE, H E Office of the General Counsel Iffice of Investigation 1p 20650 361 MB30927A 0070209 Staff requirements memo re B30927 discussion of proceeding chadule Commission will hold B3102B public meeting in lashington. DC re issues related to fuel loading HILK. B J Office of the Becretary of the Commission M830927B 13/09/30 Office of the Secretary of the Commission 10476: 362 24X Fiche 50-275, B3/09/30, B310070209 OilOO75 Transcript of 830930 affirmation/discussion & vote in lashington. DC re SEGY-B3-343, "Final Rule on Temporary OL tuthority" Pp 1-4
. Commissioners 83/09/30 7pp 20682 348 OJIO427 Transcript of 830930 discussion/possible vote in Washington, IC on BECY-83-293 re amends to 10CFR30 concerning ATMS
'p i-73 Supporting documentation encl
Commissioners 83/09/30 88pp 20686 048 Ol20017 Transcript of 831004 public meeting in Washington, DC reproposed insider safeguards rule Pp 1-94 Viewgraphs encl Commussioners 83/10/04. 105pp 20750 189

D120029 Transcript of B31003 open session in Washington DC remergency planning Pp 1-28, Supporting documentation encl commissioners B3/10/03 tilpp 20750:076 24X tchs 50-003.83/10/03,B310120029

:FR

COMMISSION MEETING RECORDS

B310120031 Transcript of B31003 briefing in Washington.DC on BWR pipe crack issues Pp 1-6B Supporting documentation encl * Commissioners B3/10/03 74pp 20750 001 8310130123 Staff requirements memo re 830930 discussion & possible vote in Washington, DC on proposed rules on ATMS contained in SECY-83-293 CHILK, S J Office of the Secretary of the Commission M830930A 83/10/03 Office of the Secretary of the Commission 1p 20777 021 8310130372 Transcript of 831004 briefing in Washington,DC re results of GPU & B&W trial matl Pp 1-42 Supporting documentation encl Fiche 50-289,83/10/06,8310130372 8310130392 Transcript of 831007 briefing by Swedish representatives on PIUS reactor in Mashington.DC Pp 1-84 Supporting documentation encl * Commissioners 83/10/07 84pp 20770 193 B310130403 Btaff requirements memo re 831004 discussion of proposed insider safeguards rule, per SECY-83-311 & 83-3114 in Mashington, DC CHILK, S J Office of the Secretary of the Commission M831004 B3/10/07 DIRCKS, W J Office of the Executive Director for Operations ZERBE, J E Office of Policy Evaluations 2pp 20769 345 8310130408 Staff requirements mamo re 830916 periodic meeting in Hashington, DC w/Advisory Panel on decontamination of TMI-2 CHILK, S J Office of the Secretary of the Commission M830916C 83/10/07 DIRECTS, W J Office of the Executive Director for Operations FOUCHARD, J Office of Public Affairs FRALEY, R FACRS - Advisory Committee on Reactor Safeguards 2pp 20769 348 24X Fiche 50-320, 83/10/07, 8310130408 8310170056 Staff requirements memo re 831007 briefing by Swedish representatives on Plus reactor CHILK, SJ Office of the Secretary of the Commission B3/10/11 Office of the Secretary of the Commission Ip B31017005B Staff requirements memo re 831003 briefing on BWR pipe crack issues
CHILK,S J Office of the Becretary of the Commission M831003B
83/10/07 DIRCKS,W J Diffice of the Executive Director for
Operations ip 20798 055 B310170321 Staff requirements mamor to Commission B31003 briefing by FEMA on recent emergency planning exercises in vicinity of facilities Commission noted successful completion of exercise Enforcement action unnecessary CHILK, J. Office of the Secretary of the Commission B3/10/11 Office of the Secretary of the Commission 1p 20795 277 24X Fiche 50-247,83/10/11,8310170321 B310170695 Staff requirements memo re B31006 briefing on results of OPU vs B&W trial matl & other uncontested matters re TMI-1 restart Commission made no requests & took no action CHILK, B J Office of the Secretary of the Commission MB31006A B3/10/06 Office of the Secretary of the Commission 19 20798-158 24x Fiche 50-289,83/10/06,8310170695 B310180035 Staff requirements memo on Torrey Pines, Inc 830928 briefing in Washington, DC re independent review of project mgt CHILK, B J Office of the Becretary of the Commission M830928 B3/10/05 DIRCKS, W J Office of the Executive Director for Operations Ip. 20825 038 24% Fiche 50-358, 83/10/05, 8310180035

- 8310180041 Staff requirements memb on 830930 affirmation/discussion & vote in Washington, DC re final rule on temporary OL authority (8ECY-83-342/342A) Separate views of Commissioners Gliinsky & Asselstine encl GHILK, 3 J Office of the Secretary of the Commission M930930B 83/10/05 DIRCKS W J. Office of the Executive Director for Operations KAMTERER, C. Office of Congressional Affairs FOUCHARD, J J Office of Public Affairs, 6pp 20825 032
- 8310190267 Transcript of 831013 brisfing in Washington.DC re automatic data processing organization Pp 1-50 Viewgraphs encl # Commissioners 83/10/13 70pp 20843 187
- 8310210147 Staff requirements mamp re 831013 briefing in Washington.DC on automatic data processing organization CHILK-S J Office of the Secretary of the Commission M831013 83/10/17 Office of the Secretary of the Commission 19 20883 356
- 8310270132 Responds to FOIA request for info re possible rev to radiological emergency planning guidance & info on whether NRC emergency planning regulations appropriate in light of anticipated accident scenarios Forwards documents FELTON, J M Division of Rules and Records. 83/07/15 BRANDENBURG. B Consolidated Edison Co of New York, Inc ip 20742 235.
- --8310270145 Staff requirements memo re 821110 briefing in Washington.DC on Sandia consequences study Commission briefed on NUREO/CR-2239 (SANDB1-1349), "Technical Guidance for Siting Criteria Development "Viewgraph encl.
 CHILK.8 J Office of the Secretary of the Commission M821110B B2/11/18 DIRCKS,H J. Office of the Executive Director for Operations 3pp. 20942 237

ACRB ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

- B310060260 Transcript of ACRS Subcommittee on DHR Sys 831004 meeting in Washington.DC Pp 1-294 Viewgraphs encl 4 ACRS Advisory Committee on Reactor Bafeguards 83/10/04 425pp 20442 335
- 8310120168 Transcript of AGRS Subcommittee on Limerick Generating Station Units | & 2 831008 meeting in Pottstown.FA Pp 253-530 * AGRS - Advisory Committee on Reactor Safeguards 83/10/08 278pp 20493-349 24X Fiche 50-352.83/10/08.8310120148
- 8310120176 Transcript of ACRS Subcommittee on Limerick Generating Station Units 1 & 2 831007 meeting in Pottstown,PA Pp 1-252 Viewgraphs encl * ACRS - Advisory Committee on Reactor Safeguards 83/10/07 272pp 20474,267, 24X Fiche 50-352,83/10/07,8310120176
- 8310140113 Transcript of ACRS Subcommittee on Metal Components & DHR 831012 meeting in Washington.DC Pp 1-139. Supporting documentation anci.

 ACRS Advisory Committee on Reactor Safeguards 83/10/12 165pp. 20764 011.
- 8310140115 Transcript of ACRS Subcommittee on Extreme External Phenomena 831012 meeting in Washington.DC.Pp 1-116 Supporting documentation encl. * ACRS Advisory Committee on Reactor Safeguards 83/10/12136pp. 20764 177.
- B310140124 Transcript of ACRS Subcommittee on Class 9 Accidents 83:012 meeting in Heshington, DC, Pp 1-167. Supporting documentation enci * ACRS Advisory Committee on Reactor Safeguards 83/10/12 237pp. 20763:087
- 3310170135 Transcript of ACRS 282nd general meeting on 831013 in Washington DC, Pp 1-352, Supplementary documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/10/13 529pp. 20792 139.
- IBI0180071 Transcript of ACRB 282nd general meeting on 801014 in Washington, DC Pg 382-578 Supporting documentation encl. * ACRB Advisory Committee on Reactor Safeguards 80/10/14 308pp. 20807 222
- 310310462 Summarires ACRS 262nd meeting on 831013-15 re draft, "Severe Accident Decisions for Existing Nuclear Power Plants."
 Blending deterministic & probabilistic approaches endorsed RAV. J. ACRS Advisory Committee on Reactor Safeguards. 83/10/18 DIRCKS:W J Office of the Executive Director for Operations 1p 20945.161

8310310465 Summarizes ACRS 282nd meeting on 831013-15 on NRC integrates program for resolution of Unresolved Safety Issues A-3.A-4 & A-5 re PHR steam generators Proposals should be implemented as recommendations only RAY, J J ACRS - Advisory Committee on Reactor Safeguards 83/10/18 PALLADINO.N J Commissioners ip 20765 160

ADVCM NRC ADVISORY COMMITTEE

- 8310030524 Notification of contract execution Mod 1 to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation "Contractor Schwalb. Donnenfeld, Bray & Silbert TOWNSEND, B Administrative Contracts Branch FIN 8-8182 NRC-18-83-406 83/09/21 FITZGERALD, J A Office of the General Counsel LEVI.R NRC No Detailed Affiliation Given 1p 20602 354
- --8310030534 Mod 1.extending period of performance to 830930 & increasing funding, to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation "

 SILBERT.E J Schwalb, Donnenfeld, Bray & Silbert REBELLO, J E Administrative Contracts Branch FIN B-8182 NRC-18-83-406 83/09/21 1p 20602 355
- B310040117 Transcript of B30916 meeting w/Advisory Panel on Decontamination of TMI-2 in Washington, DC Pp 1-65 * Commissioners B3/09/16 69pp 20634 252 24X Fiche B6-320.B3/09/16.B310040117
- 831005044B Transcript of 830927 briefing in Washington, DC re rept of Committee on Rights of Individuals in Investigations
 Pp 1-35 Supporting documentation encl
 * Commissioners 83/09/27 67pp 20640 146
- B310060463 Staff requirements memo on B30927 briefing in Hashington.CC re rept of Committee on Rights of Individuals in Investigations CHILM.S J Office of the Secretary of the Commission MB30927A B3/09/30 PLAINE.H E Office of the General Counsel MAYES.B B Office of Investigation ip 20430 361
- B31013040B Staff requirements memo re B30916 periodic meeting in Hashington.DC w/Advisory Panel on decontamination of TMI-2 CHILK.B J Office of the Secretary of the Commission MB30916C B3/10/07 DIRCHB.H J Office of the Executive Director for Operations FOUCHARD.J J Office of Public Affairs FRALEY.R FACRS Advisory Committee on Reactor Bafeguards 2pp. 20769 348 24X Fiche 50-320,83/10/07,8310130408
- B310140025 Resigns as chairman of Advisory Panel for Decontamination of TMT-2 Facility should be closed Public deserves faster cleanup MINTCH.JE Advisory Council for Decontamination of TMT Unit 2 B3/10/05 PALLADINO.N J Commissioners ip 20768 077 24X Fiche 50-320. B3/10/05, B310140025
- 8310190341 Transcript of 830927 public meeting in Middletown PA re reactor bldg polar crane Pp 1~172 Supporting documentation encl # Commissioners 83/09/27 212pp 20842 306 24X Fiche 50-320,83/09/27 8310190341
- #310200347 Transcript of Advisory Panel for Decontamination of TMI-2 #30928 public meeting in Harrisburg, PA Pp 1-109 Supporting documentation encl # Advisory Council for Decontamination of TMI Unit 2 #83/09/28 #207pp 20873 095 24X Fiche: 50-320, 83/09/28, 8310200347
- 8310210337 Notification of contract execution. Mod IA to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation "Contractor Kator. Scott & Heller TOWNSEND. B Purchasing Section FIN B-8182 NRC-18-83-409 83/09/20 FITZCERALD. J A Office of the General Counsel LEVI. R NRC No Detailed Affiliation Given ip 20862 362

COMMISSION NRC COMMISSIONERS

- 8310060921 Weekly info rept for uk ending 830923 REHM.T A Office of the Executive Director for Operations 83/09/29 39pp 20662 320
- B310060591 Forwards response to 830727 questions re NRC inquiry team 830628 meeting in New Orleans, LA Inquiry team 830714 rept on GA allegations & IE 830804 status rept encl PALLADINO, N J Commissioners 83/09/08 MARKEY, E J House of Rep , Interior & Insular Affairs 7pp 20661 160 24X Fiche 50-382,83/09/08,8310060591

- --83:0060593 Forwards inquiry team rept re GA allegations Meeting to discuss followup requested DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83:087.04 CAIN.J M Louisiana Power & Light Co ip 20461 183 24% Fiche 50-382.83/09/08.8310060591
- --83i0060574 Requests info re circumstances of June 1983 interviews w/NRC investigation team
 MARKEY.E J House of Rep , Interior & Insular Affairs 83/07/27
 PALLADING, N J Commissioners (p. 2006) 192 24x
 Fiche 50-382,83/09/08.8310060591
- 8310070041 Responds to 830623 request for views on SB 1275,
 "Administrative Law Judge (ALJ) Corps Act " Act acceptable
 Bill leaves existing Commission authority to use boards
 independent of ALJ Corps
 PALLADING,N J Commissioners 83/09/12 FREY,J M President of US
 & Executive Offices 2pp 20680 058
- --8310070043 Forwards SB 1275, "Administrative Law Judge (ALJ) Corps " Comments due by 830722 BWEENEY,N R President of US & Executive Offices 83/06/23 Office of Congressional Affairs 25pp 20680 060
- 8310070363 Responds to 830628 ltr re Inside NRC article reporting J Tourtellotte remarks on backfitting Reassignment of J Tourtellotte due to strong views for reform not acceptable PALLADIND, N J Commissioners 83/09/13 MEIBS, E R Union of Concerned Scientists 1p 20664 307
- --B310070369 informs that B30516 request for reassignment of JR Tourteliotte mixtakenly not sent to Commissioners Tourteliotte alleged behavior at conference clarified JR Tourtellotte B30614 response enc! WEISS.E R Union of Concerned Bcientists B3/06/28 PALLADINO.N, OILINSKY, V. AMEARNE.J Commissioners Zp. 20/646 308
- 8310070377 Clarifies position on need for public predistribution of potassium iodide, Revised rept re cost/benefit & advisability of stockpiling/predistributing being evaluated PALLADINO, N J Commissioners 83/09/13 MARKEY, E J House of Rep. Interior & Insular Affairs 3pp 20664 335
- --B310070380 Comments on NRC negligence in not developing unified natl policy on distribution of potassium iodide. Views expressed at Bubcommittee on Oversight & Investigations 820305 hearing MARKEY. E. J. House of Rep., Interior & Insular Affairs B3/08/11 PALLADING, N. J. Commissioners 3pp 20664 338
- 8310070383 Responds to 830818 request to initiate immediate proceedings to solicit public comment on safety of continued plant operation pending full environ review Commission intends to initiate rulemaking per UCS vs NRC proceeding CHILK-5 J Office of the Secretary of the Commission 83/09/02 WEISS-E R Harmon & Weiss WEISS-E R Union of Concerned Scientists ip 20644:341
- ---B3100703B6 Requests Commission immediately commence proceedings to solicit public comment on continued plant operation ω/ο snviron qualification of equipment important to safety.

 WEISS.E R Harmon & Weiss WEISS.E R Union of Concerned Scientists B3/08/1B PALLADINO.N J. ASSELSTING.J., OILINSKY, V Commissioners 2pp 20644 342
- 8310110002 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Davelopment Appropriations Bill for FY83 requirements for relevancy of NRC research program to regulatory program W/o encl ROBERTS, T M. Commissioners 83/09/15 OTTINGER, R L House of Rep , Energy & Commerce 1p 20709 212
- --8310110006 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FYB3 requirements for relevancy of NRC research program to regulatory program H/o encl ROBERTS, T M Commissioners 83/09/15 SIMPBON, A Senate, Environment & Public Works 1p 20709 213.
- --8310110008 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FYB3 requirements for relevancy of NRC research program to regulatory program W/o encl ROBERTS, T M Commissioners 83/09/15 UDALL, M House of Rep , Interior & Insular Affairs, 1p. 20709-214

- --B310110012 Forwards "Rept on Regulatory Utilization of Research." to fulfill Energy & Water Development Appropriations Bill for FYB3 requirements for relevancy of NRC research program to regulatory program H/o enci RUBERTS.T M Commissioners 83/09/15 HATFIELD.M O Benate. Appropriations ip 20709 215
- ~-8310110014 Forwards "Rept on Regulatory Utilization of Research," to fulfill Energy & Water Development Appropriations Bill for FYB3 requirements for relevancy of NRC research program to regulatory program ROBERTB,T M Commissioners 83/09/15 BEVILL.T House of Rep Appropriations ip 20709 216
- ~-B310110015 "Rept on Regulatory Utilization of Research "
 # Office of Nuclear Regulatory Research. Director B3/08/31
 B1pp 20709 217
- 8310110073 Confirms Commissioner Asselstine 830809 telcon requesting increase of funds for FV84 for 90 full-time equivalent positions to implement responsibilities under Nuclear Haste Policy Act of 1782 PALLADIND.N J Commissioners 83/09/19 KHEDDURI,F N. Office of Management & Budget 1p 20687 336
- 8310110352 Forwards response to 830728 request for info on conduct of litigation involving NRC PALLADINO,N J Cummissioners 83/09/13 DINGELL,J D House of Rep. Energy & Commerce 9pp 20713 209
- --8310110354 Requests additinfore control & mgt of litigation of agencies within Committee on Energy & Commerce jurisdiction Response by 830817 requested DINGELL, J D House of Rep. Energy & Commerce B3/07/28 PALLADING, N J Commissioners 2pp 20713 218
- B3101105B9 Responds to B30B17 ltr urging NRC to undertake addl research on effects of work schedules & shift rotations on operational performance as part of human factors program Expanded research program beyond scope of current plans PALLADINO,N J Commissioners B3/09/22 ODRE,A House of Rep , Ecience & Tachnology 2pp 20703.353
- --B310110594 Responds to B30B17 ltr urging NRC to undertake addl researc on effects of work schedules & shift rotations on operational performance as part of human factors program Expanded research program beyond scope of current plans. PALLADING, N J Commissioners B3/09/22 SKEEN, J House of Rep Science & Technology App 20703 355
- ---B3i0110597 Urges NRC undertake additesearch on effects of work schedules & shift rotations on operational performance as part of human factors program GORE, A. SKEEN, J. House of Rep.: Bilance & Technology. B3/08/17 PALLADINO, N. J. Commissioners 2pp 20703 357
- 8310110608 Forwards fourth monthly FR notice of amends issued or proposed to be issued based on NSHC determination M/o encl. DENTGN.H R. Defice of Nuclear Reactor Regulation, Director 83/09/08 STAFFORD,R.T., SIMPSON.A. Senate, Environment & Public Morks UDALL,M K. House of Rep., Interior & Insular Affairs 2pp 20703 351
- 8310110612 Requests appointment of state liaison officer to NRC.
 Appointee will be invited to hatl/state liaison officer
 831206-07 meetings in Washington, DC
 PALLADINO, N J Commissioners 83/09/22 HUNT, J B North Carolina.
 8tate of ip 20703 359
- --B310110615 Notification of natl state limiton officer 831206-07 meetings in Mashington, DC Agenda encl KERR, O W Office of State Programs, Director 83/09/16, Office of State Programs, Director 3pp 20703 360
- B310120467 Weekly info rept for wk ending B30930 REHM,T A Office of the Executive Director for Operations. B3/10/96 65pp. 20750:300.
- 8310140025 Resigns as chairman of Advisory Panel for Decontamination of TMI-2. Facility should be closed Public deserves faster cleanup MINNICH. J E. Advisory Council for Decontamination of TMI Unit 2 83/10/05 PALLADINO, N J. Commissioners ip 20748 077 24X Piche: 50-320, 83/10/05. 8310140025
- B310140027 Urges Commission to reject util emergency preparedness plan. Btate of NY will not impose radiological emergency preparedness plan on Suffoik County County will refrain from implementing plan Public safety cannot be assured CUOND. M New York, State of ISBUANCES OL-3, B3/10/04. PALLADIND.N J Commissioners 2pp 20767 349 24X Fiche 50-322.83/10/04.8310140027

- B310140028 Forwards Ofc of Investigations rept. "TMI Nuclear Generating Unit 2 Allegations re Safety-Related Hods. GA Procedures & Use of Polar Crane " Prompt attention should be given to mpt controls over Bechtel cleanup activities W/o encl PALLADINO,N J Commissioners B3/10/07 KUHNS,W General Public Utilities OPU Service Corp 2pp 20767 347 24K Fiche 50-380.83/10/07,8310140028
- B310170361 Weekly info rept for wk ending B31007 REHM.T A Office of the Executive Director for Operations 83/10/13 42pp 20795 196
- 8310170696 Responds to 830714 ltr expressing concern re proposed release of radwatts water containing significant amounts of tritium into Susquehanna River Proposal for disposal of processed accident water not yet received DIRCKS, W. J. Office of the Executive Director for Operations 83/10/03 BARRANES, P. B. Senate. 4pp. 20798 166 24% Fichs 50-320.83/10/03,8310170686
- --8310170690 Expresses concern re proposed release of radwaste water containing significant amounts of tritium into Busquehanna River, citing potential impact on Chesapeaks Bay BARBANES, P B Benate B3/09/14 PALLADINO, N J Commissioners 1p 20798 170 24X Fiche 50-320.83/10/03.8310170686
- 8310170694 Responds to 830817 ltm re EPA proposed stds for disposal of high level radwaste Assurance requirements not necessary part of EPA stds & should not be promulgated in 40CFR191. PALLADIMO.N J. Commissioners 83/09/29 RUCKELSHAUS, WENVIronmental Protection Agency. 2pp 20798 159
- --8310170699 Responds to 830511 ltr rm NRC views on assurance requirements in EPA proposed stds for disposal of high level radwaste Most public comments favored assurance requirements as essential part of rule RUCKELSHAUS.R Environmental Protection Agency 83/09/17. PALLADINO, N J Commissioners. Rpp 20798 161
- 8310170701 Expresses dissatisfaction w/DDE actions in approving EURATOM request to retransfer 143 metric tons of US-origin heavy water from Heat Garmany to Angentina NRC was not provided complete & accurate info on Executive Branch position PALLADINO.N J. Commissioners 83/10/04 HODEL, D.P. Energy, Dept of 3pp 20798-154
- 8310170704 Requests new state ligison officer to NRC be appointed. Natl state ligison meeting will be held on 831206-07 in Washington. DC PALLADINO.N J Commissioners. 83/09/29 ROCKEFELLER, J West Virginia, State of 1p 20778 i30
- 83i0180010 Advises that hearing process has not delayed any nuclear power plant operation & that Commission does not know of unnecessary backfit requirements in response to 830720 inquiry PALLADINO.N J Commissioners 83/09/29 MITCHELL, G J Senate, Environment & Public Works ip 20825:076.
- --8310180016 Requests info re possible instances where hearing process has delayed nuclear power plant operation & info re unnecessary backfitting requirements MITCHELL, 20, 8 senste, Environment & Public Works 83/07/20. PALLADING, N J Commissioners 2pp 20825-077
- B310200062 Responds to B30913 ltr re investigation of QA/GC program at facility PALLADINON J Commissioners B3/10/07 UDALL M K House of Rep , Interior & Insular Affairs, 3pp. 20872 280 24X Fiche 30-445-83/10/07:8310200062,
- --8310200068 Forwards findings ltr dtd 820907 re CA Atchison & Tompkins-Beckwith, Inc. BASS, C. H. Labor, Dept of. 82/09/27 DRISKELL, D. Region 4, Office of Director 7pp 20873 005
- ---B310200073 Requests copies of listed documents to GA/GC program problems at facility.

 UDALL:H X. House of Rep., Interior & Insular Affairs, B3/09/13, PALLADINO,NJ. Commissioners 2pp. 20873:073, 24X Fiche 50-445, B3/10/07, B310200062.
- 8310200442 Responds to 830922 ltr re NRC handling of several working papers for case studies being conducted to support NRC rept to Congress per Section 13 of NRC Authorization Act Three working papers ehcl
 PALLADINO.N J. Commissioners. 83/10/07 FORD.W.H. Senate. 3pp. 20871 295 24X Fiche 50-000,83/10/07,8310200442.

- --8310200449 Responds to 830922 ltr re NRC handling of several working papers for case studies being conducted to support rept to Congress per Section 13 of NRC Authorization Act Summary chronology of actions encl
 PALLADINON N J Commissioners 83/10/07 MARKEY.E J House of Rep. Interior & Insular Affairs 7pp 20871 298 24X
 Fiche 50-000,83/10/07.8310200442
- --B310200455 Expresses appreciation for cooperation w/IE activities to comply w/Congressional directive to NRC to perform GA studies Draft working paper for study encl TAYLOR, J M Division of GA, Safeguards & Inspection Programs (Post 830103) 83/08/02 KELLY, R J Georgia Power Co ip 20871 307 24X Fiche \$0-000.83/16/07.8310200442
- --B310200457 Forwards "QA Case Study Working Paper, Case C " Document no longer draft ALTMAN, W D NRC - No Detailed Affiliation Given 83/09/27 NRC - No Detailed Affiliation Given 1p 20871 311 24X Fiche 50-000, 83/10/07, 8310200442
- --8310200459 "QA Case Study Working Paper Case C," revised draft working paper
 * Affiliation Unknown 83/09/19 NRC No Detailed Affiliation Given 43pp 20871 312 24X Fiche 50-000,83/10/07,8310200442
- --8310200461 Paper entitled," NRC Site Assessments & GA Reviews Special Study of Nuclear GA.GA Case Studies," presented at tenth annual Natl Energy Div Conference ALTMAN.W D GA Branch. 83/10/07 8pp 20871 354 24X Fiche 50-000,83/10/07.8310200442
- --B310200463 Forwards undated "GA Case Study Working Paper, Case A, Draft Horking Paper" ALTMAN, H D NRC - No Detailed Affiliation Given B3/09/27 NRC - No Detailed Affiliation Given 70pp 20872 016 24X Fiche 50-000, 83/10/07, 8310200442
- --B310200464 Forwards "OA Case Study Working Paper.Case D." draft working paper ALTMAN.W D NRC - No Detailed Affiliation Given B3/09/27 NRC - No Detailed Affiliation Given 73pp 20872 094 24X Fiche 50-000,83/10/07.8310200442
- --8310200466 "GA Case Study Working Paper Case C." draft working paper # NRC - No Detailed Affiliation Given 83/07/31 5ipp 20872 165 24X Fiche 50-000,83/10/07,8310200442
- --83i0200467 Expresses concern re release of draft repts concerning QA at nuclear power plants to licenseed FORD: H H Senate B3/09/22 FALLADING, N J Commissioners 2pp 20872 215 24X Fiche 50-000,83/10/07,8310200442
- --8310200469 Expresses disappointment re release of draft study on GA programs at Diablo Camyon to licensee, Full explanation requested MARKEY, E. J. House of Rep., Interior & Insular Affairt 83/09/21 PALLADING, N. J. Commissioners 2pp 20872:217 24X Fiche 50-000,83/10/07,8310200442
- B310260060 Weetly info rept for wk ending B31014 REHM.T A Office of the Executive Director for Operations B3/10/20 33pp 20721 319
- CONTRACT NRC CONTRACTS AND HODIFICATIONS
- 8310030524 Notification of contract execution, Mod 1 to "Advisory Gommittee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation."

 Gontractor Schwalb: Donnenfeld, Bray & Bilbert
 TOWNBEND, B. Administrative Contracts Branch FIN B-8182
 NRC-18-83-406 83/09/21 FITZGERALD, J.A. Office of the General
 Counsel LEVI, R. NRC No Detailed Affiliation Given 1p.
 20602.334
- --B310030334 Mod 1.extending period of performance to 830930 & increasing funding to "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licenses Employees Under Investigation "

 SILBERT.E J Schwalb, Donnenfeld, Bray & Silbert REBELLD, J E Administrative Contracts Branch FIN B-8182 NRC-18-83-406 63/09/21 1p 20602 355
- B310050319 Notification of contract execution: "Autoprint 1800 "F" Microfiche Printer," awarded to Tameron Inc FIELDS, J. A. Administrative Contracts Branch NRC-10-83-723 B3/09/21, BEBAN, W. Division of Technical Information & Document Control SKOCZLAS, J. NRC No Detailed Affiliation Given 1p 20650:288

- --B310050323 Contract "Autoprint 1800 "F" Microfiche Printer," awarded to Tameron.Inc * Tameron. Inc MATTIA,M J Division of Contracts NRC-10-83-723 B3/09/21 10pp 20650 289
- 8310050336 Notification of contract execution.Mod 7 to "Trench Design & Const Techniques" Contractor US Army Corps of Engineers UMBEL D M Technical Assistance Contracts Branch FIN B-6981 NRC-02-81-034 83/09/26 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director PENNIFILL, R NRC No Detailed Affiliation Given 1p 20650 049
- --8310050337 Mpd 7, deobligating funds for FYB2, to "Trench Design & Const Techniques"
 MARCUSON, W.F. Army, Dept of, Corps of Engineers GUSTAVE, R.P.
 Bivision of Contracts FIN 8-6981 NRC-02-81-034 83/09/26 18
 20650 050
- 8310050343 Notification of contract execution "Medical Uses of Radioisotopes Course for NRC Matl Radiation Specialist Inspectors," awarded to Univ of Texas Health Science Ctr DAVIS, K A Administrative Contracts Branch FIN 8-8711 NRC-09-83-221 83/07/26 DEYONO, R C Director's Diffice, Office of Inspection and Enforcement HASSELBERG, F W NRC No Detailed Affiliation Given 1p 20635 009
- --8310050349 Contract "Medical Uses of Radicisotopes Course for NRC Mati Radiation Specialist Inspectors," awarded to Univ of Texas Health Science Ctr * Texas. Univ of, San Antonio MATTIA, M J Division of Contracts FIN 8-8711 NRC-05-83-221 83/09/26 37pp 20635 010
- 8310050357 Notification of contract execution, Mod 3 to "Audiovisual Consultant Svcs " Contractor N Hall PERLMAN, J Administrative Contracts Branch FIN B-8181 NRC-47-83-398 83/09/27 CHILK.8, MAGEE, W Becretary of the Commission ip 20450 047
- --B310050362 Mod 3.extending period of performance to 840228 & adding add1 funds.to "Audiovisual Consultant Svcs "
 HALL.N M Hall. N SMITH.P A Technical Assistance Contracts
 Branch FIN B-B181 NRC-17-83-398 83/09/27 ip 20450.048
- 8310050365 Natification of contract execution, Mod 10 to "Study of New England Seismicity w/Emphasis on MA & NR "Contractor: MIT. JACOBS. A Technical Assistance Contracts Branch FIN A-4058 NRC-04-76-209 83/09/26 BATSON.W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Given 10 20469 355
- --B310050370 Mod 10, extending funds through B40831, to "Btudy of New England Beismicity w/Emphasis on MA & NH " KEOHAN, P J Massachusetts Institute of Technology, Cambridge, MA GUBTAVE, R P Technical Assistance Contracts Branch. FIN A-4058 NRC-04-76-209 B3/09/26 Spp 20649 356
- 8310050367 Notification of contract execution.Mod 4 to "Records Holding Area Support Svc " Contractor SDA/Maxima Corp MCLEAREN.T Administrative Contracts Branch NRC-10-82-396 B3/09/26 BESAH.W J Division of Technical Information & Document Control HARRIS, J NRC No Detailed Affiliation Given 1p. 20650.039
- --8310050369 Mod 4.allowing for adjusted billing & deobligating funds:to "Records Holding Area Support Svc "
 JONES.P.E Maxima Corp DENNISTON.S F Email Business Administration HAGAN.T F Administrative Contracts Branch.
 NRC-10-88-396 83/09/26 3pp 20450.040
- 8310030379 Notification of contract execution, Mod 2 to "Programming, Training, Testing, Conversion & Implementation of Facility Control Sys " Contracot Boeing Computer Sycs Co PERLMAN, J Administrative Contracts Branch FIN 8-8848, NRC-33-83-438 83/09/26 BASSETT, H S. WRIGHT, G Division of Data Automation & Management Information. 1p 20650 004,
- --8310050387 Mod 2, extending period of performance to 831014 & adjusting cost of money factor, to "Programming, Training, Testing, Conversion & Implementation of Facility Control 89s."
 HOPKINS, H R Geeing Co SMITH, P A Administrative Contracts
 Branch FIN 8-8848 NRC-33-83-458 83/09/26 ip 20650-005
- B3100503B3 Notification of contract execution, Mod 10 to "Review to Evaluation of Geologic & Beismic Features of Nuclear Power Sites " Contractor USGS FLEENOR, C Technical Assistance Contracts Branch FIN B-6839, NRC-03-80-113 83/09/26 VOLLMER, R H Division of Engineering, JACKSON, R. NRC No Detailed Affiliation Given 1p 20640, 361.

- ---B310080391 Mod 10, terminating effort under Tasks 3 & 10 & obligating funds, to "Review & Evaluation of Geologic & Seismic Features of Nuclear Power Sites "FILSON.J R Interior, Dept of, Geological Survey FIN 8-6839 NRC-03-80-113 83/09/26 ip 20640 362
- B310030409 Notification of contract execution "Maint & Operation of LPDRs," awarded to Wheeler Basin, AL Regional Library HOPPER, A Administrative Contracts Branch NRC-10-B3-751 B3/09/22 FELTON, J M Division of Rules and Records. BOUDER, J NRC No Detailed Affiliation Given 1p 20640 136
- --8310050420 Contract "Maint & Operation of LPDRs," awarded to Wheeler Basin AL Regional Library SEARS,C A Decatur, AL REBELLO,JE Division of Contracts NRC-10-83-751 83/09722 9pp 20640 137
- B310050456 Notification of contract execution, Mod 1 to "Panel Member & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of Draft Rept Entitled "Contractor D Rowe TOHNSEND, B L. Administrative Contracts Branch FIN 8-8948 NRC-04-B3-007 B3/09/26 BABSETT. D E Division of Accident Evaluation JANKOMSKI, M W NRC No Detailed Affiliation Given 19 20450 031
- --8310050458 Mod 1, extending period of performance to 831030, adding one addit meeting & document review & increasing funds, to "Panel Kember & Documentation Review of NUREO Prior to & During Selected Meetings of Peer Review Group for Review ."

 ROME.D 8 Rowe Associates REBELLO.J.E Division of Contracts FIN 8-8988 NRC-04-83-007 83/09/24. 1p. 20450 032.
- B310050459 Notification of contract execution, Mod 3 to "Maint of Licensing & Insp Planning Profile Bys Boftware " Contractor SUA/Bys Architects, Inc SMITH.P A Administrative Contracts Branch NRC-10-B1-395 B3/09/29 BPRINGER:M Office of Administration BURTON, J E NRC -No Datailed Affiliation Given 1p. 20450 001
- --8310050460 Mod 3.deobligating belance remaining for closeout, to "Maint of Licensing & Insp Planning Profile Sys Software" KAHN.V System Architects, Inc. * Small Business Administration SHITH, P A Administrative Contracts Branch NRC-10-81-395, 83/09/29 App. 20650 002
- B310050462 Notification of contract execution Mod 2 to "Incident Response Communication Ctr " Contractor Boise Interagency Fire Ctr MCLEAREN. T Administrative Contracts Branch NRC-10-83-342, 83/09/28 CORLEY, J. H Division of Facilities & Operations, MELVILLE, T, COMEN. 8 Telecommunications Branch 1p. 20664:125
- ---8310050464 Mod 2, obligating addl fuñds, to "Incident Response Communication Ctr." * Interior, Dept of HAGAN, T.F. Division of Contracts NRC-10-83-342 83/09/28 ip 20664 126.
- 8310050466 Notification of contract execution: "Maint & Operation of LPDRs," awarded to Phoenix.AZ Public Library FLYNN.B J Administrative Contracts Branch NRC-10-83-734. 83/09/29 FELTON, J M Division of Rules and Records. BOUDER, J NRC No Detailed Affiliation Given 1p 20650.010.
- --8310050467 Contract. "Maint & Operation of LPDRs." awarded to Phoenix.AZ Public Library * Phoenix. A2 MATTIA.H J Division of Contracts NRC-10-83-794 83/09/29 18pp 20650 012
- 8310050539 Notification of contract execution. Mod 9 to "Technical Assistance in Repository Design " Contractor Golder Assoc DELOATCH, V Technical Assistance Contracts Branch. FIN 8-6983-3. NRC-02-81-037. 83/09/28. DAVIS.
- --B310050545 Mod 9, modifying Article II re period of performance milestones & deliverables to "Technical Assistance in Repository Design."
 TALBOT, R Colder Associates GUBTAVE, R P. Technical Assistance Contracts Branch, FIN B-6983-3 NRC-02-91-037 B3/09/28 ip.
- B310050549 Notification of contract execution, Mod 16 to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 "Contractor: Science Applications. Inc. WOLLETT. S. Technical Assistance Contracts Branch FIN 8-8012 NRC-03-B2-096, B3/09/28 EISENHUT. D. Division of Licensing BAJHA, S NRC No Detailed Affiliation Given ip. 20650 218

- --8310080950 Mod 16.providing incremental funding to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2 " ogram = " Bcience Applications, Inc. GUSTAVE.R P. Technical Assistance noracts Branch FIN B-8012 NRC-03-82-096 83/09/88 2pp
 - Contracts Branch 20650 219
- 0310050559 Notification of contract execution, Mod 2 to "Development of Reg Quide & Regulatory Analyses " Contractor Analysis & Technology, Inc RECOMPOSED FOR THE CONTROL OF THE PROPERTY OF
- --8310050556 Hod 2.funding extension of contract w/revised statement of work, "Development of Reg Quide & Regulatory Analyses" | HDDDS-V L Analysis & Technology, Inc GUSTAVE.R P Technical Assistance Contracts Branch FIN B-8645 NRC-03-83-107 83/09/27 3pp 20650 222
- B310060007 Notification of contract execution Mod 1 to "Incident Response Communication Svc " Contractor Boise Interagency Fire Ctr Fire Ctr
 MCLEAREN, T Contract Policy Branch NRC-10-83-342 83/09/28
 CORLEY, J H Division of Facilities & Operations Helille, T ,
 COHEN, S NRC - No Detailed Affiliation Given 1pp 20664 121
- --B310060010 Mod i,definitizing task order procedures & increasing total amount obligated to "Incident Response Communication Svc "HLSBN.F Interior. Dept of HAGAN.T Contract Policy Branch NRC-10-83-342 83/09/28 3pp 20664 122
- B310060071 Notification of contract execution.Mod 10 to "Fission Product Transport Analysis " Contractor Battella Columbus Product Transport Humanyas Contracts Branch FIN 8-6747 MDLLETT, S. Technical Assistance Contracts Branch FIN 8-6747 NRC-04-80-177 83/09/28 BATSON, W. Office of Nuclear Regulatory Research, Director WALKER, T. NRC - No Detailed Affiliation Given ip 20463 350
- --8310060103 Mod 10, providing incremental funding for cost increase & extending period of performance to 840930, to "Fission Product Transport Analysis"

 BEHELL, H Battelle Memorial Institute, Columbus Laboratories GUSTAVE, R P Division of Contracts FIN 8-6747 NRC-04-80-177 83/09/28 2p 20663 351
- B310060109 Notification of contract execution.Mod 3 to "Courses in C-E Facility Design & Operation " Contractor C-E DELDATCH.V Technical Assistance Contracts Branch FIN 8-1301 NRC-05-82-241 B3/09/27 BLAHA.J Director's Office. Office of Inspection and Enforcement SHOWE.8 NRC No Detailed Affiliation Given ip 20661 090
- --8310060115 Mod 3, increasing funds & exercising option for addl course, to "Courses in C-E Factility Design & Operation"
 LECLAIR.D E Combustion Engineering, Inc QUBTAVE, R P Division of Contracts FIN 8-1301 MRC-05-82-241, 83/09/27 ip
- 8310060117 Notification of contract execution. Hod 1 to "Mgt & Operation of NRR Reading/Ref Room " Contractor. Intersyst, Ltd OILDEMHORN. A J Administrative Contracts Branch NRC-10-83-725 83/09/29. BESAN, W J. 8COTT. 8 Division of Technica) Information & Document Control 1p 20661.017
- -8310060138 Mod 1, extending period of performance to B31021 & increasing contract amount, to "Mgt & Operation of NRR Reading/Ref Room"

 ROOM "

 XILPATRICK, 0 Intersyst, Ltd HAGAN, T F Division of Contracts

 NRC-10-83-725 83/09/29 2pp. 20661.018
- B310060122 Notification of contract execution. Mod 11 to "Technical Assistance in Repository Design " Contractor Golder Assoc DELOATCH. V Technical Assistance Contracts Branch FIN 8-6983-3 NRC-02-81-037. B3/09/23 DAVIS. J Office of Nuclear Material Safaty & Safagyards Director HARTUNG, L NRC No Detailed Affiliation Given 1p. 20661 013
- --8310060127 Mod | i.adding funds to cover microfiche cost.to "Technical Assistance in Repository Design" TALBOT.R. Golder Associates GUBTAVE.R P Division of Contracts FIN 8-6983-3 NRC-02-81-037 83/09/23 2pp 20661 014
- 8310040140 Notification of contract execution. Mod 9 to "Sheffield JIOGOOI+O Notification of contract execution, Mod 7 to "Beeffield Trench Cap Study "Contractor, Unit of Illinois DELDATCH, V. Technical Assistance Contracts Branch FIN 8-6965-3 NRC-02-80-074 837/97/23. DAVIS, J. Diffice of Nuclear Material Safety & Safeguards, Director SHAFFNER, J. NRC - No Detailed Affiliation Given 1p. 20660-361.

- --B3100601B4 Mod 9, adding funds to Article III for contractor to attend conference in Denver.CD to "Sheffield Trench Cap Study "

 * Illinois, Univ of, Urbana, IL GUSTAVE, R P Division of Contracts FIN B-6965-3 NRC-02-80-074 B3/07/23 Ip
- 8310060154 Notification of contract execution "Maint & Operation of LPDRs," awarded to Rochester,NY Public Library HOPPER,A Administrative Contracts Branch NRC-10-83-729 83/09/17 FELTON JM Division of Rules and Records SOUDER,JNRC No Detailed Affiliation Given 1p 20660 348
- --B310060168 Contract "Maint & Operation of LPDRs," awarded to Rochester. NY Public Library BUTZ.L H Rochester.NY REBELLO,JE Division of Contracts NRC-10-83-729 83/09/17 9pp 20660 349
- 8310060178 Natification of contract execution, Mod 13 to "Structural Integrity of Hater Reactor Boundry Components" Contractor ENBA: Inc MOLLETT:S Division of Contracts FIN B-8133 NRC-04-82-013 WOLLETT: 5 Division of Contracts FIN B-8133 NRC-04-82-013 B3/09/27 FOREHAND, W Office of Nuclear Regulatory Research. VAGINS, M NRC - No Detailed Affiliation Given ip
- ---B310060191 Nod 13 providing for contractor efforts through 831116 & increasing incremental funding to "Structural Integrity of Water Reactor Boundary Components "HAAB M N ENSA Inc GUSTAVE.R P Division of Contracts FIN B-8133 NRC-04-82-013 83/09/27 5pp 20660 327
- 8310060278 Notification of contract execution "Maint & Operation of LPDRs." awarded to Shoreham-Wading River.NY Public Library HDYLE.A Purchasing Section NRC-10-83-728 83/09/13 FELTON.J M Division of Rules and Records SOUDER.J NRC No Detailed Affiliation Given 1p 20660 216
- --B310060290 Contract "Maint & Operation of LPDRs," awarded to Shorehan-Wading River, NY Public Library Shoreham, NY REBELLO, J E Division of Contracts NRC-10-B3-72B B3/09/13 9pp 20660 217
- 831006031B Notification of contract execution, Mod i to "Panel Member & Documentation Review of NUREO Prior to & During Selected Moetings of Peer Review Group for Review of Draft Rept Entitled "Contractor W Kastenberg TDWNSEND, B L Administrative Contracts Branch FIN B-8990 NRC-04-83-015 B3/09/24 BASSETT DE Division of Accident Evaluation JANKOWSKI, M W NRC No Detailed Affiliation Given 1p 20660 214
- --83:0060326 Mod 1. extending period of performance to 83:030, adding one add1 meeting & increasing funding. to "Panel Member & Documentation Review of NUREO Prior to & During Belected Meetings of Peer Review Group for Review of "
 KASTENBERD.W E Kastenberg, W E REBELLO, J E Division of Contracts FIN B-8790 NRC-04-83-015 83/07/24 lpp 20460 215
- 8310060471 Notification of contract Execution "Maint & Operation of LPDRs." awarded to Perry.OH Public Library TOWNSEND.B L Purchasing Section NRC-10-83-736 83/09/20 FELTON.J M Division of Rules and Records SOUDER.J L NRC -- No Detailed Affiliation Given 1p 20660 162
- --B310060483 Contract "Maint & Operation of LPDRs," awarded to Perry, OH Public Library LOCKE, D.L. Perry, OH REBELLO, J.E. Division of Contracts NRC-10-83-736 83/09/20 9pp 20660 163
- B310060487 Notification of contract execution "Maint & Operation of LPDRs," awarded to WH Abel Memorial Library HOPPER, A Purchasing Section NRC-10-83-753 89/09/30 FELTON, JM Division of Rules and Records SOUDER, J NRC No Detailed Affiliation Given ip 20660 188
- --8310060493 Contract "Maint & Operation of LPDRs," awarded to WH Abel 310060443 CONTRACT THE TOTAL T
- B310060495 Notification of contract execution "Maint & Operation of LPPRs:" awarded to Morris, IL Public Library HOYLE: A Purchasing Section NRC-10-83-735 83/09/19 FELTON. J Division of Rules and Records SOUDER, J NRC No Detailed Affiliation Given. 1p 20660 198 FELTON: J M
- --B310060496 Contract "Maint & Operation of LPDRs," awarded to Morris. IL Public Library. WILSON.P Morris, IL REBELLO, JE Division of Contracts NRC-10-83-735 83/09/19 9pp 20660 199



- 8310060499 Notification of contract execution "Maint & Operation of LPDRs," awarded to White Plains.NY Public Library HDYLE.A Purchasing Section NRC-10-83-730 83/09/13 FELTON, J M Division of Rules and Records SDUDER, J NRC No Detailed Affiliation Given 1p 20643 269
- --8310060501 Contract "Maint & Operation of LPDRs," awarded to White Plains,NY Public Library DOM, O B White Plains,NY REBELLO,J E Division of Contracts NRC-10-83-730 83/09/13 9pp 20663 270
- 8310060503 Notification of contract execution, Mod 6 to "Performance of Engineered Barriers in Geologic Repository " Contractor Golder Association DELOATCH, V Technical Assistance Contracts Branch FIN B-6986-3 NRC-02-81-027 83/09/23 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director PITTIGLIA, L NRC No Detailed Affiliation Given ip 20663 266
- --8310060506 Mod & adding funding for microfiche requirement, to "Performance of Engineered Barriers in Opologic Repository " TALBOT.R Golder Associates FIN B-6986-3 NRC-02-81-027 83/09/23 2pp 20663 267
- B31006D507 Notification of contract execution "Maint & Operation of LPDRs," awarded to Florida Intl Univ MURPHY.L 0 Purchasing Section NRC-10-83-726. B3/07/19, FELTDN,J M Division of Rules and Records 1p 20663 256
- --8310060512 Contract "Maint & Operation of LPDRs," awarded to Florida Intl Univ MILLER,L Florida International Univ REBELLO, J E Division of Contracts NRC-10-83-726 83/09/19 9pp 20663 257
- B310070099 Notification of contract execution. Mod 1 to "Panel Review of NUREO Prior to Peer Review Oroup Review of Draft Rept Entitled 'Radionuclide Release Under LHR Specific Accident Conditions'" Contractor Univ of VA TOWNSEND. B L Administrative Contracts Branch FIN B-8985 NRC-04-83-010 83/09/26 BASSETT. O E Division of Accident Evaluation JANKOWSKI, M. W NRC No Detailed Affiliation Given ip 20671 315
- --8310070106 Mod 1.extending period of performance to 831030 & increasing funding, to "Panel Review of NUREO Prior to Peer Review Group Review of Ponet Rept Rept (*Radionuclide Release Under LWR Specific Accident Conditions '" REYNOLDSA B. Virginia. Univ of Charlottesville, VA REBELLO, J E Division of Contracts FIN B-8985 NRC-04-83-010 83/09/24 ip 20471 316
- 8310070115 Natification of contract execution "Maint & Operation of LPBRs." awarded to Minneapolis, MN Public Library & Info Ctr. HURPHY, L Q Purchasing Section NRC-10-83-744 83/09/21 FELION, J M Division of Rules and Records SOUDER, J NRC No Detailed Affiliation Given 1p. 20671 300
- --8310070117 Contract "Maint & Operation of LPDRs," awarded to Minneapolis, NN Public Library & Info Ctr SHANNDN: Z Minneapolis, MN REBELLOJ E. Division of Contracts. NRC-10-83-744 83/09/21 9pp 20671 301
- B310070121 Notification of contract execution "Maint & Operation of LPDRs." awarded to Indian River Community College HDPPER:A Purchasing Bection NRC-10-83-750 83/09/17. FELTON.JM Division of Rules and Records BOUDER.J. NRC No Detailed Affiliation Given 1p. 20680 351
- --B310070148 Contract "Maint & Operation of LPDRs," awarded to Indian River Community College HIDMANR P Indian River Community College REBELLO. J E. Division of Contracts NRC-10-83-750. B3/09/17 9pp 20680-352
- 8310070165 Notification of contract execution. "Purchase & Installation of Alpha/Beta Counting Sys." awarded to Tennelec.Inc FALSON, V K Administrative Contracts Branch. FIN 8-8367 NRC-28-83-613 83/09/29, FERRI, R. T Division of Resource Hanagement & Administration KOTTAN, J J. NRC ~ No Detailed Affiliation Given ip 20664,312
- --8310070173 Contract, "Purchase & Installation of Alpha/Beta Counting 8ys," awarded to Tennelec. Inc COLE.P.A Tennelec: Inc MATTIA,M.J. Division of Contracts FIN 8-8367, NRC-28-83-613 83/09/29 22pp. 20664:313
- 8310070172 Notification of contract execution "Developing Automatic Contractural Documentation Capability," awarded to Bosing Conguter Svcs Co.
 CDLEMAN.R Administrative Contracts Branch. FIN B-8845.
 NRC-33-63-463 83/09/28 BABSETT, H B Office of Resource Hanagement, Director THOMPSON.R NRC No Detailed Affiliation Oiven. ip 20480 273

- --8310070175 Contract "Developing Automatic Contractural Documentation Capability," awarded to Boeing Computer Svcs Co HDPKINB.H R Boeing Computer Services, Inc (subs of Boeing Co) MATTIA.M J Division of Contracts FIN B-8865 NRC-33-83-463 B3/07/2B 10pp 20680 294
- B31007017B Notification of contract execution "Maint & Operation of LPDRs," awarded to Salem, NJ Free Library MURPHY. G Administrative Contracts Branch NRC-10-83-752 83/09/26 FELTON, J M Division of Rules and Records BDUDER, J NRC No Detailed Affiliation Given ip 20680 267
- --9310070181 Contract "Maint & Operation of LPDRs." awarded to Salem NJ Free Library FOGGE C Balem NJ REBELLO: J E Division of Contracts NRC-10-83-752 83/09/24 9pp 20480 248
- 8310070184 Notification of contract execution "Review of Tornado Missile PRA-South Taxas Project," awarded to NBB HIGOINS,E Technical Assistance Contracts Branch FIN 8-8657 NRC-03-83-114 83/09/29 MATTBON,R J Division of Bystems Integration (gost 811005) SINGH,B K NRC No Detailed Affiliation Given 1p. 20680 248 24X Fiche 50-498,83/09/29,8310070184
- --831007018B Ltr Contract NRC-03-83-114 "Review of Tornado Missile PRA-South Texas Project," awarded to NBS MORTON,K V Bivision of Contracts FIN B-8657 NRC-03-83-114 B3/09/21 SIMIU.E. Commerce, Dept of, National Bureau of Standards 7pp 20680-249. 24X Fiche 50-498.83/09/29,8310070184
- B310070195 Notification of contract execution, Mod 9 to "Computer Time-Bharing & Related Sycs," Contractor NIH
 BROMBERGO B Administrative Contracts Branch FIN B-1666.
 NRC-25-82-912 89/09/22. BASSSTT, H S Division of Data Automation
 & Management Information SHIELDS, J NRC No Detailed Affiliation
 Given 1p 20679 356
- --8310070203 Nod 9, extending period of performance for 1 yr, to "Computer Time-Sharing & Related Svcs"
 PRATT, A MHB, Dept of US Public Health Service HALMAN.E L
 Administrative Contracts Branch FIN B-1666 NRC-25-82-312
 83/09/22 1p 20679-357
- 8310070187 Notification of contract execution. Mod 3 to "Evaluation of Matl Accounting Performances at Nuclear Fuel Cycle Facilities" Contractor NUBAC, Inc. JACOBB, A Technical Assistance Contracts Branch FIN B-7379-3 NRC-02-83-027 83/09/22 DAVIS, J Diffice of Nuclear Material Safety & Safeguands, Director Miller, M NRC No Detailed Affiliation Given 1p 20679-354
- --8310070189 Mod 3, funding action to fix reimbursable costs, to "Evaluation of Mati Accounting Performances at Nuclear Fuel Cycle Facilities "
 LUMB, R.F., NUBAG, Inc. QUBTAVE, R.P. Technical Assistance Contracts Branch. FIN 8-7379-3, NRC-02-83-027 83/09/22 1
- B310070193 Notification of grant execution "Geometric Analysis of Ensemble of Bolutions in Two-Phase Flows & Complete Resolution of Problem Choking," awarded to Brown Univ. UMBEL.D Technical Assistance Contracts Branch FIN 9-1036 NGC-9-04-83-013 B3/09/87 BATBDN:W Office of Nuclear Regulatory Research, Director ZUBER, N. NRC No Detailed Affiliation Given ip 20680-232
- --8310070196 Grant. "Geometric Analysis of Ensemble of Solutions in Two-Phase Flows & Complete Resolution of Problem Choking." awayded to Brown Univ HUNDERLICH, T.K. Brown Univ MORTON, K.V. Technical Assistance Contracts Branch. FIN G-1086. NRC-0-04-83-019 83/09/27 2pp. 20680. 233
- B310070195 Notification of contract execution, Mod 1 to "Panel Hember & Documentation Review of NUREO Prior to & During Selected Hestings of Paer Review Group for Review of Draft Rept Entitled ..." Contractor: S Levy TOWNSEND, B L. Administrative Contracts Brench FIN B-8987, NRC-04-83-014. B3/09/26, BASSETT, D E. Division of Accident Evaluation JANNOHSKI, M W NRC No Detailed Affiliation Given in 20479 358
- ~-8310070198 Mod i, extending period of performance to 831030, adding on add1 measting & document review & increasing funding, to "Panel Member & Documentation Review of NUREO Prior to & During Selected Meetings of Peer Review Group for Review, "LEVY.8 8, Levy, Inc., REBELLO, J. E. Administrative Contracts Branch. FIN 8-8989 NRC-04-83-014 83/09/26 ip 20679:339.

- 8310070197 Notification of contract elecution "Hydrogeologic Evaluations," awarded to INTERA Environ Consultants MIGGINS, E. Technical Assistance Contracts Branch FIN B-7384-3 NRC-02-83-041 83/09/20 BROGN.R S Office of Nuclear Regulatory Research, Director WIDMAYER NRC No Detailed Affiliation Given 20680 213
- --B310070200 Contract "Hydrogeologic Evaluations," awarded to INTERA Environ Consultants PAHHALS B INTERA Environmental Consultants, Inc. MGRTON.K V Division of Contracts FIN B-7384-3 NRC-02-83-041 83/09/28 206B0 214
- 8310070201 Notification of grant secution "Eight World Conference on Earthquake Engineering." awarded to Earthquake Engineering Research Inst MCDERMOTT.D Technical Assistance Contracts Branch FIN 0-1058 NRC-0-04-83-010 83/09/28 BATSON,W Office of Nuclear Regulatory Research, Director COSTELLO, J NRC No Detailed Affiliation Oiven 1p 20680 210
- --8310070205 Grant "Eight Horld Conference on Earthquake Engineering."
 awarded to Earthquake Engineering Research Inst
 PENZIEN.J Earth Sciences Associates HORTON.K V Technical
 Assistance Contracts Branch FIN G-1058 NRC-0-04-83-010
 83/09/28 2pp 20680 211
- 831007020A Notification of contract execution "Technical Basis for Foreign Exchange of Codes," awarded to Intl Energy Assoc, Ltd
- JEGSUP, B Technical Assistance Contracts Branch FIN D-1132 NRC-04-83-185 83/09/22 BATSON, W Office of Nuclear Regulatory Research, Director KELBER, C NRC No Detailed Affiliation Given 1p 20679 327
- --8310070210 Contract "Technical Basis for Foreign Exchange of Codes," awarded to Intl Energy Assoc.Ltd
 ALIKONIS,N A International Energy Associates, Ltd MORTON,K V Administrative Contracts Branch FIN D-1132 NRC-04-83-185
- 8310070213 Notification of contract execution "Behavior of Sub-Critical & Slow-Stable Crack Following Post-Irradiation Thermal Anneal Cycle," awarded to Matls Engineering Assoc,
- Inc JEBSUP, B Tec NRC-04-83-187 JEBSUP, B Technical Assistance Contracts Branch Fin D-1134 NRC-04-83-187 83/09/22 BATSON W Office of Nuclear Regulatory Research, Director STROBNIDER, J NRC - No Detailed Affiliation Given. 1p 20480 192
- --8310070217 Contract "Behavior of Bub-Critical & Blow-Stable Crack Following Post-Irradiation Thermal Anneal Cycle," awarded to Matls Engineering Assoc.Inc GREENBLATT.N Materials Engineering Associates. Inc MORTON, K V Division of Contracts FIN D-1134 NRC-04-83-187. 83/09/22 17pp 20680 193
- B310070214 Notification of contract execution "Reviewing Hydrogeologic Investigation of Badded & Dome Salt Basins Project A," awarded to Hilliams & Assoc. Inc Higgins E Technical Assistance Contracts Branch FIN B-7389-3 NRC-02-B3-033 B3/09/29. BROWN.R S Program Support Branch JOHNSON.R NRC No Datailed Affiliation Given. 1p. 20680 147
- --8310070221 Contract "Reviewing Hydrogeologic Investigations of Bedded & Dome Balt Basins Project A." awarded to Williams & Assoc. Inc HILLIAMS R Hilliams & Associates MORTON, K V Division of Contracts FIN 8-7389-3 NRC-02-83-033 83/07/29 44pp.
- 8310070218 Notification of contract execution "Common Cause Failure Analysis Data Base Assessment & Development," awarded to JBF Assoc,Inc
- JESSUP, B. Technical Assistance Contracts Branch FIN D-1130 NRC-04-83-183 83/09/22 BATSON, W. Office of Nuclear Regulatory Research, Director ROBINSON, R NRC No Datailed Affiliation Given ip 20680 129
- --B310070220 Contract "Common Cause Failure Analysis Data Base Assessment & Davelopment," awarded to JBF Assoc, Inc FUSBELL, J B JBF Associates MORTON, K V Division of Contracts FIN D-1130 NRC-04-83-183 B3/09/22 17pp. 20680 130
- 3310070222 Notification of contract execution, "Maint & Operation of LPDRs," awanded to Sacramento, CA Public Library.
 HOYLE, A Administrative Contracts Branch, NRC-10-83-739 83/09/29.
 FELTON, J. M. Division of Rules and Records SOUDER, J. NRC No. Detailed Affiliation Given 1p 20676-348

- --8310070224 Contract "Maint & Operation of LPDRs," awarded to Bacramento.CA Public Library RICHARD.R Sacramento.CA REBELLO.J E Division of Contracts NRC-10-83-739 83/09/29 9pp 20676 349
- B310070226 Notification of grant execution "Committee on Earthquake Engineering," awarded to Natl Academy of Sciences UMBELD M Technical Assistance Contracts Branch FIN G-1061 NRC-0-04-B3-012 83/09/26 BATSON, W Office of Nuclear Regulatory Research, Director BURNS, J NRC No Detailed Affiliation Given Ip 20680 024 "Committee on Earthquake
- --B310070230 Grant "Committee on Earthquake Engineering," awarded to Natl Academy of Sciences SMITH.P National Academy of Bciences MORTON, K V Technical Assistance Contracts Branch FIN G-1063 NRC-G-04-83-012 B3/09/26 23pp 20680 035
- 8310070228 Notification of contract execution "Maint & Operation of LPDRs." awarded to GA Dow Memorial Library FLYNN.H J Administrative Contracts Branch NRC-10-83-743 83/09/29 FELTON.J Division of Rules and Records SDUDER.J NI-No Detailed Affiliation Given ip 20069 348
- -8310070231 Contract "Maint & Operation of LPDRs." awarded to QA Dow Memorial Library BYEAS.R Hidland County, MI MATTIA.M J Division of Contracts NRC-10-83-743 83/09/29 15pp 20669 349
- 8310070233 Notification of contract execution "Uncertaintie Analysis Part of Seismic PRA," awarded to Future Resources "Uncertainties in Gys Associate To Technical Assistance Contracts Branch FIN D-1129

 JESSUP, B Technical Assistance Contracts Branch FIN D-1129

 NRC-04-B3-1B2 B3/09/27 BATSON, W Office of Nuclear Regulatory

 Research, Director MURPHY, J NRC - No Detailed Affiliation Given 20669 330
- --8310070240 Contract "Uncertainties in Sys Analysis Part of Seismic PRA: "awarded to Future Resources Associanc BUDNITZ: R Future Resources Associates; Inc MORTON, M. V Division of Contracts FIN D-1129 NRC-04-83-182 83/09/27 20669 331
- 8310070234 Notification of contract execution "Maint & Operation of LPDRs." awarded to Richland.WA Public Library FLYNN.W J Technical Assistance Contracts Branch NRC-10-83-746 83/09/29 FELTON.J M Division of Rules and Records BOUDER.J NRC No Detailed Affiliation Oiven 1p 20664.344
- --8310070237 Contract "Maint & Operation of LPDRs." awarded to Richland.WA Public Library ROBERTS.D & Richland. WA MATTIA.H J Division of Contra NRC-10-83-746 83/09/29 15pp 20664 345 Division of Contracts
- B310070244 Natification of contract execution "Development of PWR Transient Analysis Model," awarded to B Levy,Inc JEBSUP,B Technical Assistance Contracts Dranch FIN D-113] NRC-04-B3-184 B3/09/27 BATSON.W Office of Nuclear Regulatory Research, Director ZUBER,N NRC No Detailed Affiliation Given Research, Director 1p 20669 310
- --8310070267 Contract "Development of PWR Transient Analysis Model," awarded to S Levy, Inc BCHREPLE, D B Levy, Inc MORTON, K V Division of Contracts FIR D-1131 NRC-04-83-184 83/09/27 17pp 20659 311
- B310070327 Notification of contract execution "Mod of Existing Air Pathway Model for Low Level Waste Assessment & Training Course," awarded to NDAA WIGGINS, E. JACOBS, A Technical Assistance Contracts Branch FIR B-7339-3 NRC-02-83-031 B3/09/09, BROWN, R B Program Support Branch NEUDER, B NRC No Detailed Affiliation Given ip
- --8310070331 Contract: "Mod of Existing Air Pathway Model for Low Level Waste Assessment & Training Course;" awarded to NOAA MAMLER:R J Commerce: Dept of: Natl Oceanographic & Atmospheric Administration MORTON:K V. Technical Assistance Contracts Branch FIN 8-7359-3 NRC-02-83-031 83/09/09 11pp 20464 274
- 8310070407 Notification of contract execution "Development of Draft Stds in Area of Rock Mechanics," awarded to ABTM FLEENOR, C Technical Assistance Contracts Branch FIN D-1123 NRC-04-8J-17B 8J0/9/21, BATSON, W Office of Nuclear Regulatory Research, Director SCHMITT, T NRC No Datailed Affiliation Given ip 20676-321.

- --8310070415 Contract "Development of Draft Stds in Area of Rock Mechanics," awarded to ASTM CAVANAUGH W T American Society for Testing & Materials HORTON, K V Technical Assistance Contracts Branch FIN D-1123 NRC-04-83-178 83/09/21 8pp R0676 322
- B31007042B Notification of contract execution Mod 13 to "Evaluation of Soil Behavior Under Earthquake Loading Conditions"
 Contractor Shannon & Wilson, Inc & Agabian Assoc
 UMBEL, D Technical Assistance Contracts Branch FIN B-3015
 NRC-04-76-200 63/09/2B BATSON, W Office of Nuclear Regulatory
 Research, Director HARBDUR, J NRC No Detailed Affiliation Given
 ip 20676-319
- --8310070429 Mod i3. deobligating funds to "Evaluation of Boil Behavior Under Earthquake Loading Conditions" MILLER: R P Shannon & Wilson Inc * Agbabian Associates GUSTAVE, R P Technical Assistance Contracts Branch FIN B-3015 NRC-04-76-200 83/09/28 1p 20676 320
- 8310070431 Notification of contract execution, Mod 5 to "Statistical Review of Documents & Statistical Methods in Risk Assassment" Contractor SBA Subcontractor Automated Sciences Group.

 BROMBERG, B. Administrative Contracts Branch FIN B-1321.

 NRC-07-79-312 83/09/19 HALLER, N. Office of Management and Program Analysis ABRAMSON, L. NRC No Detailed Affiliation Given ip 20676 315
- --B3:0070432 Mod 5.extending period of performance to 840926, to
 "Statistical Review of Documents & Statistical Methods in
 Risk Assessment"
 BENGIT.H Automated Sciences Group, Inc DENNISTON 8 F Small
 Business Administration SMITH.P A Administrative Contracts
 Branch FIN B-1321 NRC-07-79-312 83/09/19 3pp 20676 316
- 8310070434 Notification of contract execution, Mod 5 to "Bafety Assessment of Concrete Nuclear Structures" Contractor MIT UMBEL, D M Technical Assistance Contracts Branch FIN 8-6618 NRC-04-79-181 B3/09/29 FOREMAND, W Défice of Nuclear Regulatory Research, Director BROWZIN, B NRC No Detailed Affiliation Given 19 20676 309
- --B310070435 Mod 5, providing funds to cover cost overrun, to "Safety Assessment of Concrete Nuclear Structures" DUMMER.0 H Massachusetts Institute of Technology, Cambridge, MA QUSTAVE.R P Technical Assistance Contracts Branch FIN 8-6618 NRC-04-79-181 83/09/29 5pp 20676 310
- B310110003 Notification of contract execution, Mod 4 to "Agrospace Electric Power Workshop Conference on Commercial Nuclear Power." Contractor American Inst of Agronautics. UMSEL. D Technical Assistance Contracts Branch FIN 0-1005 NRC-0-04-81-002 B3/09/23 BATSON. W Office of Nuclear Regulatory Research, Director, EISB, A NRC No Detailed Affiliation Given ip 20686 004
- --B310110009 Mod 4, extending period of performance to B31231 at no cost, to "Aerospace Electric Power Workshop Conference on Commercial Nuclear Power "

 A American Institute of Aeronautics & Astronautics MORTON, K V Technical Assistance Contracts Branch FIN G-1005 NRC-Q-04-B1-002 B3/09/23 ip 20686 005
- B310110026 Notification of grant execution "Study of Radionuclide Release from Severe Accidents at Nuclear Power Plants." awarded to APS UMBEL, D M Technical Assistance Contracts Branch FIN 0-1051 NRC-0-04-B3-011 83/09/23 BATBON, W Office of Nuclear Regulatory Research, Director SILBERBERG, M NRC No Detailed Affiliation Oiven ip 20487 354
- --8310110029 Grant "Study of Radionuclide Release from Bevere Accidents at Nuclear Power Plants," awarded to APS BURTON, J.A. American Physical Society, MORTON, K.V. Technical Assistance Contracts Branch FIN 0-1051 NRC-0-04-83-011 83/09/23 2pp 20487:355
- B310110086 Notification of contract execution "NRC Computer Security Program for Unclassified Sensitive Sys." awarded to MBB BAZIN, J P. Administrative Contracts Branch FIN B-6879 NRC-33-83-465 83/09/28 BABSETT, H S. CONSOLIA Division of Data Automation & Management Information. 1p 20686 010
- ---83:0110089 Contract. "NRC Computer Security Program for Unclassified Sensitive Sys," awarded to NBB.
 SHREVE, D B. Commerce, Dept of National Bureau of Standards HATTIA, M Administrative Contracts Branch FIN B-8879
 NRC-33-83-465 83/09/28 ip 20686:011.

- 8310110185 Notification of contract execution "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS," awarded to Labat-Anderson. Inc BAZIN.JP Administrative Contracts Branch NRC-10-83-722 83/09/30 RESAW.W.J., SKOCZLAS,J. Division of Technical Information & Document Control 1pp 20701 322
- --8310110172 Contract "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS." awarded to Labat-Anderson. Inc LABAT.V Labat-Anderson. Inc DENNISTON.8 F Administrative Contracts Branch NRC-10-83-722 83/09/30 15pg 20701 323
- B310110262 Notification of contract execution. Mod I to "Panel Member? Documentation Review of NUREC Prior to & During Selected Heetings of Peer Review Group for Review of Draft "Contractor LR Zumwalt TOHNSEND.B L Administrative Contracts Branch FIN B-8986 NRC-04-83-009 83/09/26 BASSETT.O E Division of Accident Evaluation JANKOSKI.M W NRC -- No Detailed Affiliation Given Ip 20687 360
- --8310110271 Mod i.extending period of performance to 831030, increasing attendance at addit meeting & increasing funding, to "Panel Meeting & Documentation Review of NUREG Prior to & During Selected Meetings of Peer Review Group for Review of "ZUMMALTIL R Zumwalt L R REBELLD. J E Administrative Contracts Branch FIN 8-8986 NRC-04-83-009 83/09/26 ip 20687 361
- B310110336 Notification of contract execution "Maint & Operation of LPDRs." awarded to Greeley.CO Public Library MURPHY.L O Administrative Contracts Branch NRC-10-83-742 B3/09/13 FELTON.J M Division of Rules and Records SOUDER.J NRC No Detailed Affiliation Given 19 20686 038
- --8310110337 Contract "Maint & Operation of LPDRs," awarded to Greeley. CD Public Library FROMM, E Greely, CO REBELLO, J. E Division of Contracts NRC-10-83-742 83/09/13 9pp 20684 039
- B31011033B Notification of contract execution "Maint & Operation of LPDRs." awarded to Plymouth MA Public Library TOWNSEND, B L Administrative Contracts Branch NRC-10-83-748 83/09/29 FELTON, J M Division of Rules and Records SDUDER, J L NRC - No Detailed Affiliation Given 1p 20713 354
- --8310110340 Contract "Maint & Operation of LPDRs," awarded to Plymouth MA Public Library * Plymouth, MA REBELLO, J E Division of Contracts NRC-10-83-748 83/09/29 9pp 20713 355
- B31011034P Notification of contract execution "Maint & Operation of LPDRs," awarded to California Polytechnic State Univ FLYNN.M J Administrative Contracts Branch NRC-10-83-737 B3709/29 FELTON, J. M. Division of Ruiës and Records BOUDER, J NRC No Detailed Affiliation Given 1p 20686 018
- --83iOi10344 Contract "Maint & Operation of LPDRs," awarded to Californie Polytechnic State Univ FLORES, A B California Polytechnic State Univ, San Luis Obispo, CA MATTIAM J Division of Contracts NRC-10-83-737 83/09/29 19pp 20686-019
- B310110344 Responds to FOIA request for seven categories of documents re NRC document control sys Forwards App A documents App B documents withheld (ref FOIA Exemption 4) FELTON.J M Division of Rules and Records B3/04/13 BLAIR.L R Affiliation Unknown. App 20483 002
- --83(01)0414 Mod 5, changing performance evaluation plan in Attachment C of contract, to "Operation & Maint of NRC Document Control Sys"

 THAMM, E G Planning Research Corp SMITH, P A Division of Contracts NRC-10-82-356 82/08/06 3pp 20684 268
- --8310110417 Mod 6.changing refs to Ofc of Controller in contractual document or billing instructions to Ofc of Resource Mgt. to "Operation & Maint of NRC Document Control Bys " # Planning Research Corp SMITH, P A Division of Contracts NRC-10-82-356 82/08/23 ip 20684 271.
- B310110494 Notification of contract execution "Software Maint," awarded to Intel Bus Corp
 BAZIN, J P Administrative Contracts Branch. FIN 8-8860
 NRC-33-83-461 83/09/27 BASSETT, H S Division of Data Automation
 & Management Information JOHNSON, C NRC No Detailed Affiliation
 Given, 1p 20709.346,
- --B310110499 Contract. "Software Meint," awarded to Intel Sys Corp SINK, J M Intel Corp MATTIA.M J Division of Contracts FIN B-8860 NRC-33-83-461 B3/09/27 10pp 20709 347

- 8310110506 Notification of contract execution. Mod 1 to "Cost Analyses of Proposed Changes in NRC Requirements" Contractor Science & Engineering Assoc. Inc OILDENMORN Administrative Contracts Branch FIN 8-8838 NRC-33-83-500 83/09/26 BARRY.L J Division of Data Automation & Management Information FOWLER. O NRC No Detailed Affiliation Given ip 20709 344
- --B310110310 Mod 1, correcting error in award amount of basic contract to changing key personnel, to "Cost Analyses of Proposed Changes in NRC Requirements"

 ROSS, B R Science & Engineering Associates, Inc. HAGAN, T F. Division of Contracts FIN B-8838 NRC-33-83-500 83/09/26 ip 20709 345
- B310110508 Notification of contract execution "Cost Analyses of Proposed Changes in NRC Requirements. (Scope of Hort 8)." awarded to Belence & Englineering Assoc. Inc. HAGEY, H.A. Administrative Contracts Branch FIN 8-8888 NRC-33-83-500 93/09/20 TRINER. E. G. Division of Budget & Analysis FOMLER. O. NRC No Detailed Affiliation Given ip 20715 175
- --8310110512 Contract "Cost Analyses of Proposed Changes in NRC Requirements, (Scope of Work B)." awarded to Science & Engineering Assoc. Inc ROSS.B Science & Engineering Associates. Inc MATTIA.M J Division of Contracts FIN B-8838 NRC-33-83-500 83/09/20 11pp 20715 17&
- 8310110516 Notification of contract execution "Atomic Bafety Licensing to Regulating Peaceful Atomic Energy, 1946-1963," awarded to Univ of CA Press
 CULEMAN.R W. Administrative Contracts Branch NRC-10-83-338
 83/09/29 CHILK, 8 J. MAZUZAN, G. Office of the Secretary of the Commission 1p. 20715 187
- --B31D110524 Contract "Atomic Safety Licensing & Regulating Peaceful Atomic Energy, 1946-1943:" awarded to Univ of CA Press HILES.J R Univ of California Press MATTIA.M J Division of Contracts NRC-10-83-338 83/09/29 12pp 20715 188
- 8310110525 Notification of contract execution.Mod 9 to "Graphics/ Photographic Sycs." Contractor Robert Charles Moles & Assoc OILDENHORN, A J. Administrative Contracts Branch NRC-05-81-257 83/10/05. BLAHA.J.L. Program Support Branch THAYER.C Director's Office, Office of Inspection and Enforcement 10 20714 326
- --8310110528 Mod 9 extending pariod of performance to 831031 w/no change in unit prices of contract to "Graphics/Photographic Svcs " MCLES,R C Robert Charles Moles & Associates HAGAN,T F Division of Contracts NRC-05-81-257 83/10/05 ip 20714 327
- 8310110533 Notification of contract execution "Robotics Application for Exposure Reduction." awarded to Remote Technology Corp JEBSUP. B Technical Assistance Contracts Branch FIN D-1128 NRC-04-83-181 83/09/22 BATSON. W Office of Nuclear Regulatory Research, Director ROBENLEIN.A NRC No Detailed Affiliation Oven 1p 20704 330
- --8310110549 Contract "Robotics Application for Exposure Reduction," awarded to Remote Technology Corp HORTON, K V Division of Contracts FIN D-1128 NRC-04-83-181 83/09/22 17pp
- B3iOlio572 Notification of contract execution "Selection of Earthquaks Resistant Design Criteria for Nuclear Power Plants.
 Methodology & Technical Bases," awarded to Structural & Earthquake Engineering Consultants
 EDGEWORTH, P J Technical Assistance Contracts Branch FIN 8-8298
 NRC-04-83-022 83/09/29 BATEON, W Office of Nuclear Regulatory
 Research, Director, MURPHY, A, NRC No Detailed Affiliation Given
 ip 20709-071
- --B3101105B2 Contract "Selection of Earthquake Resistant Besign Criteria for Nuclear Power Plants, Methodology & Technical Bases."

 awarded to Btructural & Earthquake Engineering Consultants

 LUCO. J E Btructural & Earthquake Engineering Consultants

 MORTON, K. V. Division of Contracts FIN B-827B NRC-04-83-022

 83/09/29 14pp 20709 072
- 9310110613 Notification of contract execution. "Ultra-High Speed Residue Processor for Shaft Insp Sys Image Enhancement." awarded to Spectron Development Labs JEBSUF.B. Technical Assistance Contracts Branch. FIN D-1133. NRC-04-83-186 63/09/24. BATSON.W Office of Nuclear Regulatory Research, Director. STROSNIDER.J NRC - No Detailed Affiliation Given 1p 20715-142.

- ---8310110616 Contract "Ultra-High Speed Residue Processor for Shaft Insp Sys Image Enhancement," awarded to Spectron Development Labs MCBRIDE,C S Spectron Development Laboratories MORTON,K V Administrative Contracts Branch FIN D-1133 NRC-04-83-196 83/09/24 17pp 20715 143
- B310120010 Notification of contract execution, Mod 2 to "Modeling Mesoscale Dispersion & Transport Process for Release Within Coastal Zones During Land/Sea Breezes "Contractor Univ of MN UMBEL, D M Fechnical Assistance Contracts Branch FIN B-6048 NRC-04-76-368 B3/09/20 BATSON, W Office of Nuclear Regulatory Research, Director ABBEY, R NRC No Detailed Affiliation Given ip 20749 212
- --B310120019 Ltr Contract NRC-04-76-368. Mod 2, deobligating FY79 funds, to "Modeling Mesoscale Dispersion & Transport Process for Release Hithin Coastal Zones During Land/Sea Breezos "GUSTAVE.R P Technical Assistance Contracts Branch FIN 8-6040 NRC-04-76-368 83/07/14 QARLID, M Minnesota, Univ of 1p 20749 213
- B310120021 Notification of contract execution, Mod 3 to "Automobile Impact Forces on Concrete Wall Panels " Contractor Chiapetta: Welch & Assoc: Ltd UMBEL, D M Technical Assistance Contracts Branch FIN 8-6409 NRC-04-79-188 83/09/23 BATSON, W Office of Nuclear Regulatory Research, Director COSTELLO, J NRC No Detailed Affiliation Given ip 20747 181
- --8310120024 Mod 3 adding funds to cover increases in indirect cost rates, to "Automobile Impact Forces on Concrete Wall Panels" CHIAPETTA,R L Chiapetta, Walch & Associates, Ltd GUSTAVE, R P Division of Contracts FIN 8-6609 NRC-04-79-188 83/09/23 lp 20749 182
- B310120033 Notification of contract execution, Mod 4 to "Reviewing Hydrologic Investigations of BWIP, Project B" Contractor Golder Assoc FLEENOR, C Technical Assistance Contracts Branch FIN B-7373-3 NRC-02-82-045 83/09/28 DAVIS. J Office of Nuclear Material Safety & Bafeguards, Director LOOSDON, M NRC No Detailed Affiliation Given 1p 20715 349
- --B310120035 Mod 4, revising & expanding statement of work obligating funds & extending pariod of parformance to 840930, to "Reviewing Hydrologic Investigations of BWIP. Project B" TALBOT.R Colder Associates GUSTAVE.R P Division of Contracts FIN B-7373-3 NRC-02-82-045 B3/09/28 12pp 20715 350
- 831012003B Notification of contract execution, Mod 3 to "Reviewing Hydrologic Investigations of BWIP" Contractor Williams & Assoc FLEENDR, G Technical Assistance Contract's Branch FIN B-7372-3 NRC-02-82-044 83/09/29 DAVIS, J Office of Nuclear Material Bafety & Safaguards, Director LOSDON, M NRC No Detailed Affiliation Given Ip 20715-328
- --0310120040 Mod 3, changing contractors name, revising & expanding statement of work, extending period of performance to 040930 b obligating funds, to "Reviewing Hydrologic Investigations of BMIP"

 WILLIAMS.R.E. Williams & Associates GUBTAVE, R.P. Division of Contracts FIN B-7372-3 NRC-02-82-044 83/09/29 20pp 20715 329
- 8310120032 Notification of contract execution, Mod 3 to "Preventive & Remedial Maint of Multichannel Analyzers " Contractor Nuclear Data-Inc.
 01LDENNORNA J Administrative Contracts Branch NRC-05-81-260 83/09/28 PAGE, M Region 2: Office of Director 1pp 20715 314
- ---8310120055 Mod 3, adding flunds for travel & travel time for second yr performance, revising & clarifying statement of work & extending period of performance to 840930, to "Preventive & Remedial Maint of Multichannel Analyzers"

 BRACKMAN.T W Nuclear Data, Inc HAGAN, T, F Administrative Contracts Branch NRC-05-81-260 83/09/28 12pp 20715'315
- B310130162 Notification of grant execution "Stability Under Seismic Loading," awarded to Lehigh Univ UMBEL.D Technical Assistance Contracts Branch FIN G-1060 NGC-0-04-83-009 B3/09/20 BATBON, H Office of Nuclear Reactor Regulation, Director ARNOT, Q NRC No Detailed Affiliation Given ip 20777 168
- --8310130165 Grant: "Stability Under Seismic Loading," awarded to Lehigh Univ. OCLDSTEIN, J I Lehigh Univ , Bethlehem, PA MORTON, K V Technical Assistance Contracts Branch FIN 0-1060 NRC-0-04-83-009. 83/09/20 2pp 20777 169

- 831613019B Notification of contract execution "Reviewing Hydrogeologic Investigations of Bedded & Dome Salt Basins-Project D." swarded to Golder Assoc WIGGINS-E Technical Assistance Contracts Branch FIN B-7390-3 NRC-02-83-034 83/09/30 BROWN,R S Program Support Branch JOHNSON,R NRC No Detailed Affiliation Given 1p 20772 332
- ~-8310130201 Contract "Reviewing Hydrogeologic Investigations of Bedded & Done Salt Basins-Project B." awarded to Golder Assoc TALDOT.R Golder Associates MORTON.K V Division of Contracts FIN 8-7390-3 NRC*02-83-034 83/09/30 44pp 20772 333
- 8310130263 Corrected notification of contract execution, Mod 3, to "freventive & Remedial Maint of Multichannel Analyzers "Contractor Nuclear Data, Inc QILDENHORN, A J Administrative Contracts Branch MRC-05-81-260 83/09/28 PAGE,M Region 2, Office of Director ip 20754 350
- 8310130380 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of NY UMBEL. D M Technical Assistance Contracts Branch FIN B-8355 NRC-28-83-610 83/09/29 MCOSCAR. J Region 1. Office of Director COSTELLO. F NRC No Detailed Affiliation Given 1p 20770 118
- -B310130385 Mod 1, adding funds to incorporate TLD program, to "Radiation Monitoring Program Requirements"

 LEAVY, W F New York, State of GUSTAVE, R F Technical Assistance Contracts Branch FIN B-8355 NRC-28-63-610 83/09/29 ip
- B31013038B Notification of contract execution "Maint & Operation of LPDRs." awarded to Univ of New Orleans FLYNN, M J Administrative Contracts Branch NRC-10-83-727 B3/09/30 FELTON, J Division of Rules and Records SOUDER, J NR-No Detailed Affiliation Given 1p 20771 027 NRC-10-83-727 Records SOUDER,J NRC
- --8310130389 Contract "Maint & Operation of LPDRs," awarded to Univ of New Orleans GIPMS.P M New Orleans, Univ of MATYIA,M J Ac Contracts Branch NRC-10-83-727 83/09/30 15pp Administrative
- B310130404 Notification of contract execution "Region V Data Entry Bvcs:" awarded to Phoenix Intl/BBA FIELDB.J A Administrative Contracts Branch FIN B-8891 NRC-33-83-467 B3/09/30 BASSETT:H 8 Office of Resource Management
- ---B310130406 Contract "Region V Data Entry Sycs." Awarded to Phoenix Intl/88A THOMAS, 8 T THOMAS, B T Phoenix International MIMS, R Division of Contracts FIN B-8891 NRC-33-83-467 83/09/30 2pp
- --8310130407 Contract "Region V Data Entry Svcs." awarded to Phoenix 11013040/ Contract Region v 2004 - 3.7. Section 11013040/ Intl/580 HIMB,R Small Business Administration * Phoenix International HATTIA,M J Division of Contracts FIN B-8891 NRC-33-83-447 83/09/30 2pp 20749 250
- 0310130417 Nobification of contract execution "Licensing Assistance/ Geotechnical & Hydrological Evaluations/URFO," awarded to Goodson & Assoc, Inc Higoln8: E Technical Assistance Contracts Branch FIN B-8507 NRC-R64-83-673 83/09/27 SMITH,R D Uranium Recovery Field Office GARCIA,P NRC No Detailed Affiliation Given ip 20768 332
- --8310130418 Contract: "Litensing Assistance/Odetechnical & Hydrological Evaluations/URFO:" awarded to Goodson & Assoc.Inc FUJIMOTO.R I Goodson & Associates, Inc FIN 8-8507 NRC-RG-83-673 83/09/29 37pp 20768,333
- B310170040 Notification of contract execution: "In Situ Stress Measurements In Earth Crust In Eastern VB," awarded to Engineers Intl.Inc Engineers Intl, Inc BAISDEN,L Technical Assistance Contracts Branch FIN 8-8292 NRC-04-83-016 83/09/30 BATSON,W Office of Nuclear Regulatory Research, Director, SCHMIYT,T NRC - No Datailed Affiliation Given 1p 20798 041
- Party Contract "In Situ Stress Measurements In Earth Crust In Eastern US," awarded to Engineers Intl, Inc.
 SINGH, M.M. Engineers International, Inc. MORTON, K.V. Division of Contracts, FIN 8-8292 NRC-04-83-016 83/09/30 13pp.
 20798.042 --8310170067 Contract "In Situ Stress Measurements In Earth Crust In

- 8310170082 Notification of contract execution, Mod 2 to "Furnishing Engineering, Installation & Maint of Complete Operational Inservice Automatic Telephone Switching Bys/Equipment "Contractor American Telephone & Telegraph GILDENHORN, A J Administrative Contracts Branch NRC-31-83-661 83/09/30 COLLING, J Region 4, Office of Director MELVILLE, T NRC No Detailed Affiliation Given 1p 20798 007
- --8310170084 Mod 2. expanding base sys & changing sys turnover date to "Furnishing Engineering. Installation & Maint of Complete Operational Inservice Automatic Telephone Switching Bys/Equipment"

 VOLZER: H J American Telephone & Telegraph Co /American Bell. HAGEN.T F Division of Contracts NRC-31-83-661 83/09/30 6pt 20798 008
- B310170111 Notification of contract execution, Mod 9 to "Technical Assistance to Support NRC-IE Personnel in Investigations of Incidents" Contractor Parameter: Inc MOLLETT, 8 Technical Assistance Contracts Branch FIN 8-1302 NRC-05-82-249 83/09/29 BLAHA, J Director's Office, Office of Inspection and Enforcement LAUDAN, W NRC No Detailed Affiliation Given ip 20814 154
- --8310170550 Mod 9, issuing Task Order 54, to "Tachnical Assistance to Support NRC-IE Personnel in Investigations of Incidents " LOFY,R A Parameter, Inc QUSTAVE,R P Tachnical Assistance Contracts Branch FIN 8-1302 NRC-05-82-249 83/09/29 3pp
- 8310170112 Notification of contract execution.Mod 4 to "Info Mgt Sys for NRC Operation Ctr " Contractor Phoenix Assoc.Inc GILDENHURN A J Administrative Contracts Branch. FIN B-8709 NRC-05-83-218 B3/10/11 MUIR.A P Program Support Branch HIMES.J NRC No Detailed Affiliation Given ip 20813 123
- ---B31017011B Mod 4, adding requirement for CEO sys design document & increasing contract amount, to "Info Myt Bys for NRC Operation Ctr"
 FENSTERBTOCK, J Phoenix Associates, Inc HAGAN, T F Administrative Contracts Branch FIN B-8709 NRC-09-83-218 B3/10/11 3pp. 20813 124
- 8310180101 Notification of contract execution "Stochastic Analysis of Bolute Transport in Unsaturated Boil." awarded to MIT DELDATCH. V Technical Assistance Contracts Branch. FIN 8-8955 NRC-04-83-174 83/09/30 BATSON, W Office of Nuclear Regulatory Research, Director NICHOLSON, T NRC No Detailed Affiliation Given 1p 20824 043 "Stochastic Analysis of
- ~-8310180105 Contract "Stochastic Analysis of Solute Transport in Unsaturated Soil," awarded to MIT.

 DUMMER, G M Hassachusetts Institute of Technology, Cambridge, MARTON, K V Division of Contracts FIN B-8756 NRC~04-83-174
 83/07/30 80pp 20824 044
- 8310180147 Notification of contract execution, Mod & to "Evaluation of Relative Surface Properties of Alternative Nuclear Waste Encapsulants " Contractor Univ of Florida DELOATCH.V Technical Assistance Contracts Branch FIN F-6352 NRC-04-78-252 83/10/13 BATSON, W Office of Nuclear Regulatory Research, Director, KIM, K NRC No Detailed Affiliation Given ip 20827 050
- ---B310180187 Mod 6.modifying scope of work at no cost a changing title:
 "Evaluation of Relative Surface Properties of Alternative
 Nuclear Waste Encapsulants"
 BTEVENS.A R Florida, Univ of, Quinesville, FL QUBTAVE,R.P
 Technical Assistance Contracts Branch. FIN F-6352 NRC-04-78-252
 B3/10/13. 4pp. 20827.051.
- 8310180168 Notification of contract execution, Mod 2 to "Bubscriptions to Publications. Inside Energy/W/Federal Lands, Inside FERC, Inside NRC, Nuclear Fuel, Nucleonics Wk " Contractor McGraw-Will-Inside NRC, Nuclear Fuel, Nucleonics Wk " Contractor McGraw-Will-Inside NRC, Nuclear Fuel, Nucleonics Wk " Contractor McGraw-Will-Inside NRC, Nuclear Fuel, HANKINS, D. A. Administrative Contracts Branch. NRC-10-B3-321
 B3/10/13 BEBAN, N. J. Division of Technical Information & Document
 Control CONYNOHAM, M. NRC - No Detailed Affiliation Given | 1p
- --8310180175 Mod 2:cancelling subscription to "Inside FERC" & decreasi total contract amount, to "Bubscription to Publications: Inside Energy/H/Federal Lands: Inside FERC, Inside NRC: Nuclear Fuel; Nucleonis Wk "FERRANTE: J McGraw-Hill Publications Co HAGAN, T. Division of Contracts NRC-10-83-321 83/10/13. 2pp. 20827,041.

- B310180554 Notification of contract execution, Mod 7 to "Evaluating Radiation Effects, Analytical Techniques & Testing Methods for Evaluation of Radiation Damage in Reactor Vessels "Contractor Naval Research Lab SILVIS, RM Technical Assistance Contracts Branch FIN B-1151 NRC-03-76-348 83/10/12 DENTON, HR Office of Nuclear Reactor Regulation Director HOGE, K NRC ~ No Detailed Affiliation Given ip 20827 120
- --8310180557 Mod 7, deobligating funds, to "Evaluating Radiation Effects, Analytical Techniques & Testing Methods for Evaluation of Radiation Damage in Reactor Vessels"

 MCMORRIS, J.A. Navy, Dept. of, Naval Research Lab. QUBTAVE, R.P. Division of Contracts FIN 8-1151 NRC-03-76-348 83/10/12 1p. 20827 121
- B310180573 Notification of contract execution, Mod 1 to "Fundamentals of Bias Correction Problems " Contractor Battelle Hemorial Inst DELOATCH, V. Technical Assistance Contracts Branch FIN 8-8105 NRC-04-82-012 B3/10/12 FOREMAND, W. Office of Nuclear Regulatory Research, Director RIVERS, J D NRC No Detailed Affiliation Qiven 1p 20817 359
- --8310180576 Mod 1, changing Articles I & II to extend period of performance 3 months, to "Fundamentals of Bias Correction Problems"

 ACE, J K Battelle Memorial Institute GUSTAVE, R P Division of Contracts FIN B-8105 NRC-04-82-012 83/10/12 2pp 20817 360
- 8310180581 Notification of contract execution, Mod ii to "Tornado Parameters for Nuclear Power Plants " Contractor Univ of Chicago BiLVIB,R M Technical Assistance Contracts Branch FIN A-4059 NRC-04-74-239 83/07/11 BATSUN.W Office of Nuclear Regulatory Research, Director ABBEY,R NRC No Detailed Affiliation Given ip. 20817 357
- --B310180585 Ltr Contract NRC-04-74-239.Mod 11.deobligating funds.to "Tornado Parameters for Nuclear Power Plants" GUSTAVE.R P Technical Assistance Contracts Branch FIN A-4059. NRC-04-74-239 83/05/18 SIGAL.D S Chicago. Univ ef. Chicago. IL ip 20817 358
- 8310180592 Notification of contract execution, Mod 6 to "ADP Sys Support " Contractor SBA/Technassociates, Inc MCLEAREN.T. Administrative Contracts Branch FIN 8-1664 NRC-25-82-315 83/10/13 BARRY.L W Office of Resource Management, Director BURTON, J NRC - No Detailed Affiliation Given ip 20817 355
- ---8310180576 Mod & increasing amount obligated to "ADP Sys Support"

 * Small Susiness Administration * Technassociates, Inc
 HAGAN.T F Division of Contracts FIN 8-1664 NRC-25-82-315
 B3/10/13 19 20817 356
- 8310190276 Notification of contract execution "Assessment of Implications of Low Enrichment U Fuel for Research Reactors," awarded to Rensselaer Polytechnic Inst HCDERHOTT.D Technical Assistance Contracts Branch FIN D-1126 NRC-04-83-179 83/09/21 BATSON.W Diffice of Nuclear Regulatory Research, Director, KELBER, C NRC No Detailed Affiliation Given ip 20843 177.
- --831019028: Contract "Assessment Implications of Low Enrichment U Fuel for Research Reactors," awarded to Rensselaer Polytechnic Inst. LOGIUDICE, J M Rensselaer Polytechnic Inst. Troy, NY. HORTON, K V Division of Contracts FIN D-1126 NRC-04-83-179 83/69/21 9pp 20843 178
- 8310200458 Notification of contract execution "Removal of Irradiated & Unirradiated Hati From KRB-A Qundremmingen Reactor, Quntburg, Federal Republic of Germany," awarded to GO Noel OmbH.

 MCDERNOTT, D Technical Assistance Contracts Branch FIN B-8942

 NRC-04-83-017 83/07/12 FOREMAND; W Office of Nuclear Regulatory Research, Director, SERFAN, C 2 NRC No Detailed Affiliation Given ip 20872 219
- ~~B310200462 Contract "Removal of Irradiated & Unitradiated Mat1 From KRB-A Gundrammingen Reactor, Gunzburg, Federal Republic of Germany," searded to 60 Noel GmbH HURZBURG, 9, N. GO Noell GmbH HORTON, K.V. Division of Contracts FIN B-8942 NRC-04-B3-017 B3/07/12 60pp 20872, 220.
- B310210083 Notification of contract execution "Independent Assessment Destructive Testing & Analysis," swarded to Franklin Inst.
 BAISDEN.L Technical Assistance Contracts Brench FIN B-8708
 NRC-05-83-216 B3/07/30 HURA Director's Office, Office of Inspection and Enforcement LAUDAN.W NRC No Detailed Affiliation Oiven ip 20884 031.

- --B310210097 Contract "Independent Assessment Destructive Testing *Analysis: "Awarded to Franklin Inst
 ROSENBERG.E B Franklin Institute/Franklin Research Center
 MORTON,K V Division of Contracts FIN B-8708 NRC-05-83-214
 83/09/30 30pp 20884 032
- B310210086 Notification of contract execution, Mod 10 to "Graphics/ Photographic Sycs " Contractor Robert Charles Mole & Assoc GILDENHORN, A J Administrative Contracts Branch FIN 8-1297 NRC-05-81-257 B3/10/18 BLAHA, J L Program Support Branch THAYER, C NRC - No Detailed Affiliation Given 1p 20883 341
- --B310210087 Mod 10. adding incremental funding balance.to "Graphics Photographic Sycs " * Robert Charles Moles & Associates HAGAN.T F Administrative Contracts Branch FIN B-1297 NRC-05-81-257 83/10/18 1p 20883 342
- 831021007i Notification of contract execution, Mod 4 to "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations " Contractor Univ of Washington WOLLETT. B Administrative Contracts Branch FIN B-7018 NRC-04-80-214 83/10/06 BATSON: W Office of Nuclear Regulatory Research, Director SWANBERG, F NRC No Detailed Affiliation Oiven 1p 20883 339
- --8310210093 Mod 4,adding no cost extension to 840430,to "Evaluation of Ecosystem Simulation Models as Tools for Assessment of Power Plant Impacts on Fish Populations" ALEN,D R Mashington Univ MDRTON.K V Administrative Contracts Branch FIN 8-7018 NRC-04-80-214 83/10/06 1p 20883 340
- 8310210150 Notification of contract execution, Mod 1 to "Reorganizing & Purging of Bafety Reactor Files at PDR & ACRS" Contractor.Labat-Anderson, Inc/SBA MCLEAREN.T Administrative Contracts Branch NRC-10-83-722 83/10/17 BESAW, W J Division of Technical Information & Document Control SKOCZLAS, J NRC No Detailed Affiliation Given 1p 20883 357
- --8310210155 Mod i.correcting base upon which G&A rate is computed to "Reorganizing & Purging of Safety Reactor Files at PDR & ACRS "

 * Small Business Administration * Labat-Anderson, Inc HAGAN,T F Administrative Contracts Branch NRC-10-83-722 83/10/17 ip 20883 358
- 8310210164 Notification of contract execution, Mod 1 to "Development of Nuclear Reactor Data Bank " Contractor Technology Development of California JACOBB, A Administrative Contracts Branch, FIN B-7077, NRC-04-80-215 83/09/12 BATSON, W Office of Nuclear Regulatory Research, Director TRGUTHAN, C NRC- No Detailed Affiliation Given 1p 20884 083
- --8310210180 Mod 1.extending period of performance to 841030 & adding Tasks 17-23.to "Development of Nuclear Reactor Plant Data Bank"

 HDDARSKI,L J Small Business Administration GREENE,F. 8

 Technology Development of California, Inc. GUSTAVE,R

 Administrative Contracts Branch FIN 8-7077 NRC-04-80-215

 83/09/12 7pp 20884 084
- B3102101B9 Notification of contract execution, Mod 7 to "Transient Prototypical Steam Generator MB-2 Research Testing Program "Contractor EPRI/Mestinghouse, BAISBEN.L Administrative Contracts Brench, FIN B-8232 NRC-04-82-080 B3/10/14 BATSON, W Office of Nuclear Regulatory Research, Director BECKNER, W NRC No Detailed Affiliation Given ip 20884 091
- --8310210198 Mod 7, extending period of performance to 830930 & adding addl funds, to "Transient Prototypical Steam Generator MB-2 Research Testing Program" ROBENBLATT, H B Westinghouse Electric Corp RYTKONEN, 8 D Electric Power Research Institute MDRTON, K V Administrative Contracts Branch FIN 8-8252 NRC-04-82-020 83/10/14 2pp 20884 092
- 8310210205 Notification of grant execution, Mod 1 to "Evaluation of Benefits of Response-Time In Situ Testing of Neutron Sensors Used in Nuclear Power Reactor Protection Sys " Grantee, Ohio State Univ Research Foundation UMBEL.D M Administrative Contracts Branch FIN 9-1044 NRC-9-04-83-01 83/10/05, BATSON, W Office of Nuclear Regulatory Research, Director HINTZE, A NRC No Detailed Affiliation Given ip 20884 074

8-1302

- --B310210211 Mod i.extending period of performance to B31130.to "Evaluation of Benefits of Response-Time in Situ Testing of Neutron Sensors Used in Nuclear Power Reactor Protoction Sys " SLDAN,K W Ohio State Univ , Columbus, OH MORTON,K V Administrative Contracts Branch FIN G-1044 NRC-G-04-B3/10/05 1p 20884 095 NRC-G-04-83-01
- B310210337 Notification of contract execution.Mod iA to "Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation" Contractor Katon.Scott & Heller TOWNSEND.B Purchasing Section FIN B-8182 NRC-18-83-409 B3/09/20 FITZGERALD.J A Office of the General Counsel LEVINRC No Detailed Affiliation Given 1p 20882 362 LEVI R
- B310240097 Notification of contract execution.Mod 3 to "Accelerating Establishment of Stds & Adoption as Reg Guides by AEC " Contractor ANSI WHEEL, D M Tochnical Assistance Contracts Branch NRC-01-75-83/10/12 FOREHAND, W Office of Nuclear Regulatory Research, Director TING.P NRC - No Detailed Affiliation Given 1p 20891 357 NRC-01-75-094
- --8310240098 Mod 3.deobligating balance of funds to "Accelerating Establishment of Stds & Adoption as Reg Guidos by AEC " MORRISON, J K American National Standards Institute GUSTAVE, R P Division of Contracts NRC-01-75-094 83/10/12 ip 20891 358
- B310240104 Notification of contract execution, Mod 1 to "Managerial Competencies" Contractor USDA Graduate School PERLMAN, J Administrative Contracts Branch NRC-10-83-300 83/10/19 OCLDMAN, P J, ALLEN, R A Office of Administration 20891 353
- --8310240106 Mod i.clarifying ordering procedures to "Managerial Competencies" * Agriculture, Dept of, Oraduate School HAGAN. T F Administrative Contracts Branch NRC-10-83-300 83/10/19 20891 334 41 \$1\04\EB
- B310240127 Notification of contract execution.Mod 1 to "Executive Development Program " Contractor USDA Graduate School PERLMAN.J Administrative Contracts Branch NRC-10-83-299 B3/10/19 GULDMAN.P J , ALLEN.R A Office of Administration 20884 361
- --8310240130 Mod 1,modifying ordering procedures,to "Executive Bevelopment Program" * Agriculture, Dept of, Graduate School HAGAN.T F Division of Contracts NRC-10-83-299 B3/10/19 ip 20884 362
- 8310260290 Notification of contract execution.Mod 2 to "Classified Waste Paper Destruction Project" Contractor Simkins Industries.Inc HAWKINS, D A Division of Contracts NRC-10-82-403 B3/10/19 BRADY, R J Division of Security BURNSIDE.W NRC -- No Detailed Affiliation Given 1p 20918 333
- --B310260276 Mod 2, clarifying formula under which Govt shall be reimbursed for classified waste paper, to "Classified Waste Paper Destruction Project"
 RUBSELL.V Sinkins Industries, Inc SMITH, P.A. Division of Contracts NRC-10-82-403 B3/10/17 Ip 20718 334
- 8310260371 Notification of contract execution, Mod 10 to "Licensing Technical Assistance" Contractor Science Applications Inc WDLETT.S Administrative Contracts Branch NRC-02-83-035-03/10/13 DAVIS, J. Diffice of Nuclear Material Safety & Safeguards, Director LOYSEN, P. NRC No Detailed Affiliation Given top. 20918-036 20918 356
- --8310260375 Mod 10, extending period of performance on Tasks 002 to 831231 & 007 to 831130 at no add1 cost to govt.to "Licensing Technical Assistance FINDLEY,D E Brience Applications, Inc. GUSTAVE.R P Administrative Contracts Branch NRC-02-83-035 83/10/13 ipp 20718 357 83/10/13 1pp
- B310270567 Notification of contract execution "Examine Facts in Employee Grievance:Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." awarded to L Aronin MURPHY. G Administrative Contracts Branch NRC-10-84-240 B3/10/21 BIRD,P E Division of Organization and Personnel MOHRWINKLE,C NRC No Detailed Affiliation Given 1p 20946 034
- --B310270377 Contract "Examine Facts in Employee Grisvance; Hold Hearing Including Taking of Testimony & Acceptance of Evidentiary Matl & Make Final Written Rept." awarded to L Aronin ARONIN, L Aronin, L REBELLOJ E Administrative Contracts Branch NRC-10-B4-240 G3/10/21 App 20946 035

- 8310270596 Notification of contract execution, Mod 10 to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents " Contractor Parameter, Inc MCLLETT.S Technical Assistance Contracts Branch FIN B-1302 NRC-05-B2-249 83/10/19 BLAHA, J Director's Office, Office of Inspection and Enforcement LAUDEN, W NRC No Detailed Affiliation Given Ip 20946 836
- --8310270606 Mod 10 providing for administrative changes to "Technical Assistance to Support NRC IE Personnel in Investigations of Incidents" .s" beter, Inc. GUSTAVE.R.P. Division of Contracts FIN NRC-05-82-249 83/10/19 2pp 20946 257 lidents Parameter, Inc
- B310280062 Notification of contract execution, Mod 3 to "Reviewing Hydrogenbogic Investigations of Nevada Test Site Project C " Contractor Williams & Assoc, Inc FLEENOR, C Administrative Contracts Branch NRC-02-82-046 B3/10/19 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director FOHLE, J NRC No Detailed Affiliation Given 1p 20964 113
- --8310280068 Mod 3.changing contractor name from Williams-Robinette & Assoc to Williams & Assoc, Inc. to "Reviewing Hydrogeologic Investigations of Nevada Test Site -- Project C "
 WILLIAMS.R E Williams-Robinstte & Associates, Inc QUSTAVE,R
 Administrative Contracts Branch NRC-02-82-046 83/10/19 6pp
- B3102B0074 Notification of grant execution.Mod 3.to "Formation of Recommendations on Radiation Protection & Measurement re Technology Base Noeded to Assess Safety of Nuclear Power " Grantee Natl Council on Radiation Protection & Measurements UMBEL.D Administrative Contracts Branch FIN 0-1030 NRCC-04-81-029 B3710/20 BATSON.W Office of Nuclear Regulatory Research. Director FOULKE.J NRC No Detailed Affiliation Given NRCG-04-81-029 B3. Research, Director 1p 20764 108
- --B3102B0104 Mod 3, changing method of payment, to "Formation of Recommendations on Radiation Protection & Measurement re Technology Base Needed to Assess Safety of Nuclear Power "MAY.W R National Council on Radiation Protection & Measurements MORTIN.K V Administrative Contracts Branch FIN 6-1030 NRC-6-04-81-029 83/10/20 1p 20944 109
- 8310280133 Notification of contract execution Mod 1 to "Technical Assistance in Defense of Appeal of TERA Advanced Sycs Corp (TASC) Before 08A Board of Contract Appeals "Contractor TABLE Before the Bodie of Contracts Pranch NRC-10-83-368 TOWNBEND, B Administrative Contracts Branch NRC-10-83-368 83/10/25 NURRY, P & Office of Administration AVERY, R E No Detailed Affiliation Civen 1p 20763 361
- --8310280137 Mod 1.adding one add1 trip.increasing level of effort & increasing funding.to "Technical Assistance in Defénse of Appeal of TERA Advanced Svcs Corp (TASC) Before GSA Board of Contract Appeals "BOUDNINOFF, B Dataflow Systems. Inc REBELLO, J E Administrative Contracts Branch. NRC-10-83-368 83/10/25 ip 20963 362
- FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8310110001 FOIA request for listed documents to be placed in PDR Documents requested are references from NUREO-0800.Pages 3 5 1 6-7 PEDRO. J NUB Corp CD-15-83-047 83/06/17 Division of Ru CD-15-83-047 83/06/17 Division of Rules PEDRO, J NUB Corp CD-15-8: and Records 1p 20704 136
- 83i0ii0004 Responds to FDIA request for five documents Forwards documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/07/01 PEDRO.J NUS Corp 2pp 20704:137 24X Fiche 30-000.83/07/01.83i0110004
- --8310110010 "Appraisal of Fire Effects From Aircraft Crash At Zion Power Reactor Facility " PINKEL.I I Atomic Energy Commission 72/07/17 35pp 20704 139 24X Fiche 50-000,83/07/01.8310110004
- --8310110011 Testimony of DG Eisenhut re Zion/Waukegan Airport * Atomic Energy Commission B3/07/01 10pp 20704.174 24X Fiche 80-000, B3/07/01.8310110004
- ---B310110013 Forwards preliminary evaluation of aircraft hazards at Pabble Springs site, per 731010 request Site probably acceptable provided reasonable care taken to minimize effective target area DEYDUNO,R C Atomic Energy Commission, Directorate of Licensing 73/11/23 WILLIAMS,J L Portland General Electric Co Spp R0704 184

- --B310110016 Informs that preapplication safety review completed based on util 730507 submittal of proposed facility design Vital areas & mods to be made prior to operation discussed DEYGUNG, R C Atomic Energy Commission, Directorate of Licensing 73/10/12 WILLIAMS, J L Portland General Electric Co 2pp 20704 189
- --B31011001B "Aircraft Considerations Preapplication Site Review"

 JM Campbell 710519 ltr to CPC encl

 * Atomic Energy Commission, Directorate of Licensing 73/10/12

 58pp 20704 191 24X Fiche 50-000, B3/07/01, B310110004
- B310110005 FDIA request for SECY-82-279. SECY-82-330 & SECY-83-120 PEDRO-J NUS Corp CP-18-83-035 83/06/14 Division of Rules and Records ip 20712 279
- 8310110007 Responds to FDIA request for SECY-82-279, SECY-82-330 & BECY-83-120 Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/15 PEDRD. J NUSCORP 1p 20712 280 24% Fiche 50-445, 83/07/15, 8310110007
- ---8208270562 SECY-82-330
 Recommends approval of mods to NRC personnel security clearance program to sharply reduce investigative costs w/o lessening operational effectiveness DIRCKS, W J Diffice of the Executive Director for Operations 82/08/03 12pp 20712 307
- ---8010110017 SECY-82-279
 Provides info paper on current status of nuclear plant reliability data sys
 DIRCKS,W J Office of the Executive Director for Operations 82/07/01 26pp 20712 281
- --B3i0i10022 SECY-B3-120

 Recommends issuance of encl proposed order directing ASLB to resume hearings as soon as possible on issue not involving informant (dentities PLAINE, H H Office of the General Counsel 83/04/01 4pp 20712 319 24X Fiche 50-445.83/07/15,8310110007
- B310110020 FOIA request for RFP RS-ORM-B3-464

 DDHERTY,E A Raytheon Corp EAD OMD B3 3367 B3/06/30

 FELTON-J M Division of Rules and Records ip 20706 251
- B310110021 Responds to FDIA request for RFP RB-ORM-83-464, successful bidders proposal & contract Forwards RFP Successful bidders proposal & contract not yet available RFP also available in PDR.
 FELTON, J M Division of Rules and Records B3/07/15 DDHERTY, E A Raytheon Corp ip 20706 252
- --B3i0i10025 Requests proposals for R8-ADM-83-444. "Design.Programming. Testing.Training.Implementation & Documentation of Licensing Mgt Bys (LMS)," w/basic contract for ADP development, NRC-33-83-452 Related info enc! MATTIA.M J Division of Contracts NRC-33-83-452 83/05/23 Affiliation Unknown 52pp 20706 253
- 8310110030 Add1 response to FOIA request for winning technical proposels under RFP RB-ORM-83-452 resulting in multiple award task order Contracts NRC-33-83-452-01 through 07 Forwards App C document Document also available in PDR FELTON.J M Division of Rules and Records B3/06/30 PAUL.L.K Affiliation Unknown. 2pp 20704 249
- --8310110033 "Technical Proposal for Multiple Award Task Order Contract for ADP Development " Info deleted # Automation Industries, Inc. VL-C-71026 82/07/14 63pp 20704 251
- 6310110034 Further response to FOIA request for records to NUREG-0862 investigative rept & investigations concerning facilities Forwards App A documents Commissioner Bradford 811217 memo withheld (ref FDIA Exemption 3) FELTON, J M Division of Rules and Records 63/06/15 REYNOLDS, J Center for Law in the Public Interest 4pp. 20713 001 24X Fichs, 50-275, 83/06/15, 8310110034
- --8208010014 Requests issuance of final statement clearing RL Cloud Associates from allegations of wrongdoing in preparation of "Preliminary Rept. Seismic Verification Program," per NRC investigation results in NUREG-0862: Issue 3 CLOUD, R L. Robert L Cloud Associates, Inc. 82/08/24, PALLADINO, N J Commissioners, 3pp. 20713,032 24% Fiche 50-275,83/06/15,8310110034
- ---8310110037 Excerpt from meeting trenscript re RL C)oud rept * NRC - No Detailed Affiliation Given 81/12/17. Spp 20713 005.

- --8310110039 Forwards draft itrs to Subcommittee on Energy & Environ 'Subcommittee on Energy Conservation & Power transmitting NRC review of NUREG-0862 Comments requested by 820811 KAMMERER, C. Office of Congressional Affairs 82/08/09 BICKWIT.L. Office of the Oeneral Counsel CUMMINOS, J. Office or Inspector & Auditor FirzgeRALD, J. Office of Investigation 5p., 20713 008 24X Fiche 50-275,83/06/15,8310110034
- --0310110046 Responds to B11217 ltr expressing concern re delays in licensing process Immediate issue concerns acceptability of util proposed auditors, RL Cloud Assoc Investigation scheduled for completion on 821108 & 830201 KAMMERER, C Office of Congressional Affairs 82/01/10 ROUSSELOT. JH House of Rep 1p 20713 013 24x Fiche 50-275, B3/06/15, 8310110034
- --8310110048 "Chronolgy of Events" # Affiliation Unknown 83/06/15 8pp 20713 015 24X Fiche 50-275,83/06/15,8310110034
- --B310110057 Draft ltrs re adequacy of NRC investigation into development of RL Cloud Assoc rept.per NUREO-0862. "Insp Rept of Preliminary Rept. Beismic Reverification Program at Diablo Cangon Nuclear Power Plant"

 PALLADING, N Commissioners 83/06/15 UDALL,M K House of Rep Interior & Insular Affairs OTTINGER,R, DINOELL,J House of Rep Febroy & Commerce 7pp 20713 024 24X

 Fiche 50-275,83/06/15,8310110034
- --8310110095 Forwards RL Cloud B20824 request for final statement on conclusions of Cloud/util investigation to clear Cloud prof reputation Matter presented in NUREG-0862 & SECV-82-89 Commission guidance requested DIRCKS.W J Office of the Executive Director for Operations B3/09/08 PALLADINN, Commissioners ip 20713 031 24X Fiche 50-275,89/04/15,8310110034
- --8310110103 Informs of delay in review of investigation reported in NUREG-0862 Completion of rept review expected by 820802 CUMMINGS. J. Office of Inspector & Auditor 82/07/15 PALLADIND.N. Commissioners 1p 20713 035
- --8310110107 Forwards summary documenting record actions of peer review group
 REHM.T A Diffice of the Executive Director for Operations
 82/02/18 PALLADING,N , GILINGKY,V , BRADFORD,P Commissioners
 1p 20713 036 24X Fiche 50-279,83/06/15,8310110034
- --B310110111 Forwards summary of Region V peer review group assistance w/
 investigation of RL Cloud Assoc Related info encl
 CORNELLE K Office of the Executive Director for Operations
 CASE. 6 Office of Nuclear Reactor Regulation, Director
 SNIEZEK.J H Director's Office of Inspection and
 Enforcement 82/02/18 DIRCKS.W J Office of the Executive
 Director for Operations 74pp 20713 037 24X
 Fiche 50-275,83/04/15,8310110034
- 8310110040 FD1A request for SALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on SALP insp findings or conclusions based on SALP reviews
 RIDENHOUR, R. Oambit 83/05/04 GRIMSLEY, D.C. NRC No Detailed Affiliation Given 2pp 20713 306 24% Fiche 50-382, 83/05/04, 8310110040
- 8310110044 Responds to FOIA request for BALP documents, written or routed since 1979, which mention or refer to facility & describe or provide info on BALP insp findings or conclusions re BALP reviews Forwards App A documents FELTON, J M Division of Rules and Records 83/07/20 RIDENHOUR, R Qambit 2pp 20713 308, 24X Fiche 50-000.83/07/20,8310110044
- --8112170188 Advises that Cycle 2 of systematic evaluation of licensee performance will cover Jul 1980-June 1981 Regional board meetings will be conducted Jul-Dec 1981 All Cycle 2 NRR performance systuation encl EISENHUT. D 0 Division of Licensing 81/06/04 Division of Engineering 4pp 20713, 310 24X Fiche 50-382, 83/07/20, 8310110044
- --B208230434 Requests input & appropriate comments re systematic assessment of licenses performance, (EALP) for Aug 1781-Jul 1782. Response required by 820806 SALP criteria encl BLACK.5 Licensing Branch 3 82/08/03 Licensing Branch 3 13pp 20713 324. 24% Fiche.50-382.63/07/20:8310110044
- --B209010314 Forwards draft NRR input for systematic assessment of licensee performance. Draft based partly on input solicited from selected staff personnel having contact & involvement w/util licensing activities
 BLACK.S Licensing Branch 3. 82/08/11 EISENHUT.D @ Division of Licensing Spp 20713 331 24X Fiche.50-382,83/07/20,8310110044

- --B210050447 Forwards final NRR input for Cycle 3 systematic assessment of licensee performance Performance is rated Category 2 Licensee resources adequate although staffing could be Improved
 BLACK.S Operating Reactors Branch 3 82/08/23 E18ENHUT.D G
 Division of Licensing 5pp 20713 336 24X Fiche 50-382,
 83/07/20,8310110044
- ---8310110031 BALP rept for Jul 1980 June 1981 Const allegations reviewed SEYFRIT,K V Region 4, Office of Director 83/4 20713 314 24X Fiche 30-382.83/07/20.8310110044 83/07/20 10pp
- --B310110039 Forwards case chronology re allegations concerning welding issues at facilities M/o encl
 ALDERSON.C E Region 2. Office of Director 83/02/23
 JOHNSON.G E Office of the Executive Legal Director 1p
 20713 341 24X Fichs 50-413.83/07/20.8310110044
- 8310110065 Further response to FOIA request for records re incineration of radioactive matls by Dow Chemical Co Midland, MI plant Forwards App B documents Documents also available in PDR FELTON, J M Olysian of Rules and Records 83/06/20 GARDE, B P Government Accountability Project 2pp 20704 001
- --B310110070 Forwards Div of Compliance info re noncompliance of activities under License 21-00265-04 Corrective steps to be taken requested Related info encl HAGEMAN, R C Atomic Energy Commission 66/02/07 BEAMER, W H Daw Chemical Co 36pp 20704 004
- --B3i0110097 Informs that 651229 wipe test of 20 mCl Br-90 beta source in Barber-Coleman Co instrument revealed leakage of sealed radinactive source Source removed from instrument & now stored in sealed container Bource to be replaced BEAMER.W H Dow Chemical Co 66/01/19 Atomic Energy Commission ip 20704 041
- ---8310110101 Insp Findings & Licensee Ack dtd 681007-08 of Licenses 21-00265-04 & 21-00265-06 Insp findings no noncompliance noted Related info encl * Atomic Energy Commission 68/11/21 10pp 20704 042
- --B3i011010B Forwards Insp Findings & Licensee Ack re activities under Licenses 21-00265-04, STB-527 & SMB-111 & Div of Compliance Form AEC-592 concerning noncompliance activities under Licenses 21-00265-02 & 21-00265-06 GRIER. B H Atomic Energy Commission 70/06/08, SILVERSTEIN, L Dow Chemical Co. ip 20704-052
- --B310110115 Insp Findings & Licensee Ack dtd 700919-20 of Licenses STB-527, SMB-111 & 21-000265-04 Insp findings no noncompliance noted Related info ancl. BGHMLTZIW H Atomic Energy Commission 70/06/08 16pp 20704 053
- --B310110125 Responds to 700608 ltr re noncompliance noted for Licenses 21-00265-02 & 21-00265-06 Corrective actions users of byproduct matl will be given formal written approval by radiation hazards committee Related info encl HOYLE.H R Dow Chemical Co 70/06/16 SCHULTZ.W H Atomic Energy Commission 3pp 20704 069
- --B310110130 Ack receipt of 700616 ltr informing NRC of steps taken to correct noncompliance noted in 700608 ltr GRIER, B H Atomic Energy Commission, 70/06/22 HOYLE, H R Dew Chemical Co Ip 20704 074.
- --8310110134 Inap Findings & Licensee Ack dtd 740821-22 of Licenses 21-00265-02;21-00265-04 & 21-00265-06 Inap findings Part 17 documents not posted Related info encl 4 Region 3, Chicago, Office of the Director 74/08/22 12pp, 20704 075
- --B310110137 Discusses insp of License BNM-1451,21-00265-04 & 21-00265-06 on 761006 & forwards description of moncompliance ALLAN.J M Region 3, Chicago, Diffice of the Director 76/10/20 LANGNER,R R Dow Chemical Co 2pp 20704,087,
- --8310110143 Notice of noncompliance from insp of License 21-00265-06 on 761006 Noncompliance noted individuals received overexposures when allowed to enter unrestricted area Draft insp rept encl.

 * Region 3. Chicago, Office of the Director. 76/10/20. 28pp 20704 089

- --B310110147 1E Insp Rept 30-04783/81-01 on B11214-15 No noncompliance 110110147 IE Insp Rept 30-04/83/81-01 on 011214-13 No noncompila noted Major areas inspected review of lab procedures & records, industrial hygiens dept training & bldg tour Related info encl SLOWINSKI.W J. MADDEN, J. R. SRENIAWEKI, D. J. Region 3, Chicago Office of the Director IEB-79-19 B1/12/24 19pp 20704 11
- B310110350 Final response to FOIA request for mathre NRC consultation w/EPA to promulgate stds for remedial actions at inactive U processing sites C Kammerer 821222 memo to Commissioners encl FELTON.J M Division of Rules and Records 83/06/13 DUNN.K Beers & Dickson 4pp 20712 341
- --B310ii035i Forwards EPA 82i2i3 press release re environ protection stds for cleanup & long-torm control of U mill tailings XAMMERER.C Office of Congressional Affairs 82/12/22 PALLADINO.N , GILINSKY,V . AHEARNE.J P Commissioners ip
- B310110353 Responds to FOIA request for Myaming Fuel Co application for source mat1 license Forwards requested info Records do not indicate that FOIA request received from P Girouard dtd B30210 M/o encl FELTON. J M Division of Rules and Records B3/08/04 HOFFMAN.T E Western Nebraska Resources Council ip 20712 352
- 8310110336 FOIA request for Myoming Fuel Co application for source matl license Requests NRC hold hearing on application Response mever received for Girouard 830210 FOIA request HOFFMAN, T E. Western Nebraska Resources Council 83/07/06 FELTON, J M. Division of Rules and Records ip 20712 353
- 8310110357 FOIA request for seven Categories of documents to NRC document control sys BLAIR.L R Affiliation Unknown 83/05/02 Division of Rules and Records 1p 20883 001
- B310110361 Responds to FOIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1981-82 Lists repts identified by Region II ofc prepared in 1981-82 Repts awailable in FDR FELTON, J M Division of Rules and Records 83/08/18 FOLEY, J R Foley, Hosg & Eliot ip 20712 350 24X Fiche 50-438,83/08/18,8310110361
- 8310110364 Responds to FOIA request for seven categories of documents re NRC document control sys, Forwards App A documents, App B documents withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 83/06/13 BLAIR, L R Affiliation Unknown 4pp. 20683 002
- --8310110371 Trip rept of B10414-15 visit to DCAA & TERA re DCAA audit of TERA CFY-80 billings to NRC & TERA briefing on development of Boolean search sys ROWE.P Office of the Executive Director for Operations 81/04/21 Office of the Executive Director for Operations 2pp 20683 042
- --8310110375 Forwards 810526 memo documenting technical input to NRC decisions to continued lease or purchase of document control sys computer hardware BALL.C G. Air Force. Dept of 81/07/07 RDMC.P Office of the Executive Director for Operations 14pp. 20683 006
- --B31011037B Forwards document control sys (BCS) equipment & software listings & certification stating that listings represent everything required to operate & maintain BCS, per 810513 request Sys schematic will be provided LONG, J. A. TERA Corp. NRC-10-78-580 TTN-W213 8:/06/10 LEBO, C.B. Division of Contracts 14pp. 20683 044
- ---B310110384 Forwards federal computer performance evaluation & simulation ctr inputs to document control sys feasibility study BALL.C Q Air Force, Dept of B2/03/31 ROME.P Office study DALL.C G Air Force, Dept of 82/03/31 ROHE.P Defice of the Executive Director for Operations 74pp 20683 059
- -- B3101103BB "Document Control Sys Requirements & Feasibility Study." ols 1-2 Office of Administration 82/07/31. 371pp 20483:133
- --- 83:0:10371 "NRC Document Control Bys," monthly progress rept for Apr 1983, # Planning Research Corp NRC-10-82-356 83/04/30 Detailed Affiliation Given 70pp. 20684: 283
- --8310:10393 "NRC Document Control Sys," monthly progress rept for Mar 1983. * Planning Research Gorp NRC-10-82-334. 83/03/31. NRC - No Detailed Affiliation Given. 71pp 20684:383

- --8310110395 "NRC Document Control Sys." monthly progress tept for Feb
 - * Planning Research Corp NRC-10-82-356 83/02/28 NRC No Detailed Affiliation Given 46pp 20685 061
- --8310110400 "NRC Document Control Sys Semiannual Sys Review.Feb-Jul 1982 "
 - * Planning Research Corp NRC-10-82-354 82/09/30 NRC No Detailed Affiliation Given 61pp 20684 144
- ---8310110404 Summary of Document Control Sys (DCS) Working Group 821117 meeting re operational changes to DCS recommended by contractor in semiamoual sys review under Task 9 of contract Meeting agenda encl LUNDY, J. R. Office of Administration 82/12/03 Office of Administration 31pp 20484 203
- --B310110414 Mod 5, changing performance evaluation plan in Attachment C of contract, to "Operation & Maint of NRC Document Control Bys " THAMM.E G Planning Research Corp SMITH, P A Division of Contracts NRC-10-B2-356 82/08/06 3pp 20684 268
- --8310110419 Mod & changing refs to Oft of Controller in contractual document or billing instructions to Oft of Resource Mgt. to "Operation & Maint of NRC Document Control Sys" # Planning Research Corp SMITH-P A Division of Contracts NRC-10-82-356 82/08/23 ip 20484 271
- --8310110422 Consents to subcontract w/Commart (Contract NRC-10-82-356).

 per contractor 830316 & 24 ltrs Subcontract should not be
 used in calculations for obtaining add1 fee under Article
 XI
 SMITH.P A Administrative Contracts Branch NRC-10-82-356
 83/04/12 LIPPERINI:A Planning Research Corp 1p 20684 281
- --8310110367 Forwards preliminary project plan/customer agreement re NRC document control sys.per 810220 & 0317 discussions BALL-C G Air Force. Dept of 81/03/31 ROME,P Office of the Executive Director for Operations 12 20683 033
- 8310110365 FDIA request for NRC rept re violations at facility over misplaced & misfiled documents during 1991-92 FOLEY.J R Foley, Hoag & Eliot 83/08/09 CILLILAND, J Office of Public Affairs 1p 20712 351 24X Fiche 50-438,83/08/09,8310110365
- 8310110425 FOIA request for info re PNO-III-83-027 concerning faulty valve radiographs, PNO-III-83-026 concerning use of lubricant on valve seats & info on DOE/NRC 830419-20 meetings concerning geologic repository in salt program HIATT, S.L. Ohio Citizens for Responsible Energy 83/05/10 FELTON, JM Division of Rules and Records 1p 20706 001 24X Fiche 30-000, 83/05/10, 8310110425
 - l0110430 Responds to FOIA request for four different categories of incuments described in 830510 ltr Forwards math listed in App Arresponsive to Items 1.2 & 4 DDE should be contacted for math requested in Item 3 of ltr

 "ELTON.J M Division of Rules and Records 83/06/14 HIATT, S L sin Citizens for Responsible Energy 3pp 20706 002 24X che 50-000,83/06/14,8310110430
 - Oil0443 Forwards PND & morning rept re faulty Borg-Warner valve adiographs Problem may be generic Related info encl ITTLE.W S Region 3. Office of Director 83/04/13 PDTAPOVS.U agion 4. Office of Director 15pp 20706 005 24x ichs 50-000,83/06/14.8310110430
 - .10110455 Rev 1 to DMP 200-38 "MSIV 10% Closure Stram Setpoint Check" * Affiliation Unknown 79/11/30 4pp 20706 031
- B310110458 Rev O to DMP 200-39 "MSIV Naint-Electrical " Related info encl * Affiliation Unknown B3/01/31 9pp. 20706 035
- --8310110461 Excerpt from notification of events at two different facilities re deficiency concerning control complex chilled water sys & info received that grease incorrectly used on MBIVs, respectively Related info encl
 % Region 3, Office of Director, 83/04/08 lipp. 20706 044 24X Fiche 50-000,83/06/14.8310110430
- --8310110464 Rev 1 to QW-482 "Welding Procedure Spec (QW-482) " Related info encl * Commonwealth Edison Co 81/08/27 7ap 20706 055

- --8310110467 Daily rept re events at three different facilities LACBWF experienced scram due to low water level PNO-III-83-026 updates use of lubricants on valve seats # Region 3, Office of Director 83/04/14 lp 20706 062 24x Fiche 50-000,83/06/14,8310110430
- --B310110478 Responds to B30413 ltr requesting info re use of foreign matts on valve seating surfaces Lubricants & cleaning solvents used on valve component surfaces per vendor recommendations & maint practices
 FARRAR.D L Commonwealth Edison Co 13878 B3/04/22
 KEPPLER.J G Region 3, Office of Director 4pp 20706 063 24×
 Fiche 50-000.83/06/14,8310110430
- ---B3101104B4 Rev 9 to DAP 15-1 Attachment C procedure re fasdwater checkvalve * Affiliation Unknown 83/04/09 9pp 20706 067
- ~~8310110486 DTS 1600~1 R08 Rev B to DTS 1600~1 "Primary Containment Penetration Loak Rate Test Data Sheet " W/related info GRRISTEL Affiliation Unknown 83/03/09 22pp 20706 076
- ---8310110490 Draft "Integral Sys Testing Program For D&W-Designed NSS9," final rept * Babcock & Wilcox Operating Plants Owners Group 83/03/31 128pp 20706 123
- B310110432 F01A request for RFP RS-ORM-83-500. "Cost Analyses of Proposed Changes in NRC Requirements." & SECY B3-197 to be placed in PDR ORABER, L. NUS Corp. CS-18-83-059 83/06/21 Division of Rules and Records 1p. 20706
- 8310110434 Responds to FOIA request for RFP RS-ORM-83-500 & SECY-83-157 RS-ORM-83-500 placed in PDR SECY-83-157 partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/07/20 GRABER, L NUS Corp 2pp 20706 308 24% Fiche 50-322.83/07/20,8310110436
- --8310110439 SECY-83-157
 Requests approval of proposed order re low power license for facility
 PLAINE.H H Dffice of the General Counsel 83/05/02 4pp 20704 310 24% Ficha 50-322,83/07/20.8310110436
- B310110444 Responds to FOIA request for WJ Dircks 830413 memo to 8J Chilk re test facility accreditation Document placed in PDR FELTON.J M Division of Rules and Records 83/07/20 PEDRO,J NUS Corp ip 20706 305
- B31011046B FOIA request for "Topical Rept on Methodology for Uncertainty Analysis of LWR Meltdown Accident Consequences" & "Methodology for Uncertainty Analysis of LWR Meltdown Accident Consequences"

 SHOLLY'S C Union of Concerned Scientists 83/05/06 FELTON, J M Division of Rules and Records ip 20705 001
- 8310110470 Responds to PDIA request for two 1980 BMNL repts & documents per contracts between NRC & BMI under which repts were produced. Rept placed in PDR FELTON.J.M Division of Rules and Records 83/06/15 SHOLLY, S Union of Concerned Scientists 1p 20705 002
- --8310110475 "Topical Rept on Uncertainty Analysis of LWR Meltdown Accident Consequences Methodology Development " BAYBUTT.P . KURTH.R E Battelle Memorial Institute, Pacific Northwest Laboratory FIN A-4067 NRC-04-76-293 78/01/10 Office of Nuclear Regulatory Research, Director i20pp 20705-003
- --8310110480 "Methodology for Uncertainty Analysis of LWR Meltdown Accident Consequences "BAYBUTT.P., COX,D C , KURTH,R E Battelle Memorial Institute, Pacific Northwest Laboratory FIN A-4067 NRC-04-76-273 B1/05/31 Office of Nuclear Regulatory Research, Director 84pp 20705 110
- 8310110496 FDIA request for BMR Dwners Group control room survey program, reviewed in Generic Ltr 83-18 MILLIAMS.0 G Affiliation Unknown GL-83-18 03/06/20 FELTON, J M Division of Rules and Records ip 20708 001
- B310110503 Responds to FOIA request for BHR Owners Group control room survey program Requested info placed in LPDR FELTON.J.M. Division of Rules and Records B3/07/08 WILLIAMS.O G Affiliation Unknown ip 20708 002

- --8310110505 Forwards BWR Owners Group control room program plan, followup B20108 | Itr. BWR Owners Group survey suppl & presentation Slides from BWR Owners Group/NRC Jul 1980, Aug 1981, Mar & Jul 1982 meetings BITTER, D B General Electric Co MFN-131-82 82/09/14 WEISS.S H Human Factors Engineering Branch 20p 20708 003
- --8310110509 Requests NRC concurrence on whether control room design review program being conducted by BMR Dwners Group meets intent of NRC evaluation criteria for detailed control room design reviews
 ARMSTRONG, W BWR Dwners Group BWROG-8151 81/08/25 MODRE, V A Human Factors Engineering Branch 4pp 20708 005
- ---8310110511 "BWR Owners Group Control Room Improvements Committee Human Factors Engineering Control Room Survey " PANNRATI.D R , ROSS, K C , MULLEE, G R BWR Owners Group Bi/Oi/19 BRn 20708 007
- ---8310110513 "BWR Owners Group Control Room Design Review Program, Bevelopment & Methodology " a General Electric Co 81/08/01 26pp 20708 096
- ---8310110518 "BWR Owners Group Control Room Survey Workshop, Human Factors Engineering," w/suppls & viewpraphs * BWR Owners Group 83/08/01 310pp 20708 121
- E310110520 FOIA request for all records re three specified ltrs,830209 meeting & discussions between AK Wilson & Region III during past yr concerning Dow Chemical Co incineration of radwaste HILSON,A K Environmental Congress of Mid-Michigan B3705/26 MALLETT.B S Region 3: Office of Director ip 20705 194
- 8310110523 Responds to FOIA request for all records re three specified ltrs,830207 meeting & discussions between AK Wilson & Region III during past yr concerning Dow Chemical Co incineration of radwasto Forwards documents listed in app FELTON, J M Division of Rules and Records 93/06/15 WILSON, A K Environmental Congress of Mid-Michigan 2pp 20705 175
- --8010110534 Forwards two AK Wilson 820727 ltrs re recent amend to License 21-00265-06 authorizing Dow Chemical Co to incinerate radwaste Licensee may be in violation of license Commission should be responsive to ltrs in timely manner MALLETT, B S Region 3. Office of Director 82/08/19 MILLER, J R Region 3. Office of Director 1p 20705 200
- --8310110538 Advises that Dow Chemical Co may be in violation of License 21-00265-06 by incinerating both toxic & radwaste simultaneously If practice acceptable to NRC.EIS should be prepared WILSON.A X Affiliation Unknown 82/07/27 MALLETT.B S Region 3. Office of Director 1p 20705 201
- --8310110541 Requests issuance of EIS re Dow Chemical Co License 21-00265-04 authorizing incineration of radwaste Issues to be included in EIS discussed List of technical questions to be considered and! WILBOWA K Affiliation Unknown 82/07/27 MALLETT, B 8 Region 3, Office of Director 17pp 20705 202
- --8310110547 Requests written justification for issuance of broad scope License 21-00265-06 to Dow Chemical Co & License Condition 18 re incineration of radwaste WILBON,A K Affiliation Unknown 82/09/13 MALLETT, B 8 Region 3, Office of Director 1p 20705 219
- --8310110562 Forwards draft response to AK Wilson 820913 & 27 ltrs re Dow Chemical Co License 21-00265-06 to incinerate byproduct mati waste Signature requested Handwritten notes of discussions w/various parties re Dow Chemical Co encl HALLETT.B S Region 3. Office of Director 02/12/17 MILLER.J R Region 3. Office of Director 8pp 20705 222
- --8310110974 Submits handwritten comments re draft response to A Wilson ltrs concerning Dow Chemical Co Undated handwritten note re conversation w/P Berg. Govt Accountability Projectienci.
 HIND.J NRC No Detailed Affiliation Given 83/05/04
 HILLER.J., MALLETT.B NRC No Detailed Affiliation Given 4pp R0705 231
- --B3101103B3 Responds to B20603.0727 & 0913 & B30216 ltrs re issuance of License 21-00265-06 to Dow Chemical Co to incinerate byproduct waste Response to B30105 ltr will be transmitted separately M/o stated encis KEPLER.J G Region 3. Office of Director B3/06/10 WILSON.A K Environmental Congress of Mid-Michigan 6pp 20705 358

- 8310110557 Responds to FDIA request for submittals awarded NRC Contracts RS-NRR-83-107.R8-DRM-83-500 & EDG-83-426 Cnly RFP RS-NRR-83-107 resulted in award of Contract NRC-03-83-107 Nongroprietary version of proposal in PDR FELTON.J M Division of Rules and Records 83/06/13 NEWMAN,K A Debevoise & Liberman ip 20709 357
- B310110560 FOIA request for submittals awarded MRC Contracts RS-NRR-83-107, R8-DRM-83-500 & EDD-83-426 NEWHAN-K A Debevoise & Liberman 83/05/31 FELTON, J M Division of Rules and Records lp 20709 358
- 8310110544 Responds to FOIA request for SECY-82-388, "Withdrawal of Medical Misadministration Reporting Requirements" Attachments 1, 6 & 7 exempt Attachments 2, 3, 4 & 5 available in PDR FELTON-J M Division of Rules and Records 83/07/15 PRASAD. 0 P Evanston Moso Evanston, IL 2pp 20709 359
- 8310110567 FOIA request for copy of 54 page rept to NRC Commissioners, "Withdrawal of Medical Misadministration Reporting Requirements"
 PRASAD, S G Evanston Hosp Evanston, IL 83/04/25 Region 3, Office of Director. 1p 20709 361
- 8310110371 Final response to FOIA request for documents made available under FOIA Request 83~153 Final response to FOIA 83~153 & 821222 memo to Commission encl W/o encl FELTON, J. F. Division of Rules and Records 83/06/13. KAPPEL, B. Hamel, Park. McCabe & Baunders 1p 20686 361
- B3i0110581 F0IA request for three categories of documents re technical support for util group on ATMS, reactor coolant pump seal failure & survey & critique of RPB reliability studies.
 BHOLLY, S. C. Union of Concerned Scientists B3/07/28 FELTON, J. M. Division of Rules and Records ip 20714 213
- 63:01:10596 Responds to FOIA request for three categories of documents re 8:123:.5A1-0:1-82-5J, "Technical Support for Util Group on ATMS," 8:0327 mamo from TE Murley to DG Eisenhut & 82:10:1:5A1-12200363700 rept Item 1 in LPDR & Items b & c in PDR FELTON, J M Division of Rules and Records 83/08/19 5HOLLY, B Union of Concerned Scientists ip 20714 2:14
- --8310110591 "Burvey & Critique of Reactor Protection Sys.Reliability Studies." draft rept GALYEAN.H J. NELSON.W E , LINDSAY.W E Sandia Laboratories 82/10/11 55pp 20714 223
- B310120005 FDIA request for documents re costs & const of & improvements to Western New York Nuclear Bvc Ctr.West Valley, NY
 ARNOLD, Q A Shaw, Pittmen, Potts & Trowbridge B3/06/27 Office of Administration 2pp 20751:067. 24K Fiche 50-201, B3/06/27, B310120005
- 8310120006 Responds to FOIA request for documents re costs & const of & improvements to Western New York Nuclear Svc Ctr.West Valley.NY Forwards documents listed in App A Documents also available in FDR FELTON.J M Division of Rules and Records. 83/07/14 ARNOLD.0 A Shaw. Pittman, Potts & Trowbridge 3pp 20751 071. 24X Fiche 50-201.83/07/14.8310120006.
- --8310120008 Forwards schedule showing source & application of funds for Man-June 1966 to demonstrate that vendor has necessary funds to continue const of facility, per 660322 ltr RUNIGN, T. C. Nuclear Fue) Bervices, Inc. (subs. of Getty Oil Co.) 66/03/28 MCBRIDE: J. A. Atomic Emergy Commission 2pp 20751 074 24X Fiche, 50-201, 83/07/14, 8310120006
- ---8310120007 Forwards schedule showing vendor consolidated balance sheet as of 660228 & consolidated balance sheet projected for 660331 Add1 line of credit of \$1.000,000 received from Mfg & Traders Trust Co Ltr enc.)
 RUNION.T.C. Nuclear Fuel Services, Inc. (subs of Getty Gil Co) 66/03/22 HORRIDE, J A Atomic Energy Commission 20751:076 24X Fiche 50-201,83/07/14.8310120006
- ---B310120011 Forwards "Info Subsequent to CP Submission 5," from vendor, requesting extension of const completion date to 660630 Request includes financial data to cover period through 660630 BECHROEFER, 8 0 Scharfeld, Bechhuefer & Beron. 66/02/25 MCBRIDE, J. A. Atomic Energy Commission ip 20751.081. 24X Fiche 50-201,83/07/14,8310120006.
- --8310120012 Application to amend License CBF-1, extending const completion date to 660630. Certificate of Svc & consolidated balance sheet encl RVMIDN.T.C Nuclear Fuel Bervices, Inc. (subs. of Cetty Oil Co.) 66/02/24. 9pp 20751 082 24X Fiche: 50-201.83/07/14.8310120006

- --B310120013 Forwards "Info Subsequent to CP Submission 3," containing suppl info requested by NRC Info in Part 1 covers statement of general financial responsibility Info contained in second gart should be withheld (ref 10CFR2 790)
 RUNIGN-T C Nuclear Fuel Services. Inc (subs of Getty Oil Co.)
 65/08/25 MCBRIDE. JA Atomic Energy Commission ip 20751 091
 24X Fiche 50-201,83/07/14,8310120006
- --8310120014 Application to amend License CSF-1, supplementing or replacing & superseding Paragraph 7 re applicant financial responsibility RUMION.T.C. Nuclear Fuel Bervices, Inc. (subs. of Getty Dil Co.) 45/08/25 4pp 2075; 092 24x Fiche 50-201, 83/07/14, 8310120006
- --B310120015 Forwards "Info Subsequent to CP, Submission 2," dtd 650719, Centificate of Svc & marked-up "Info Subsequent to CP Submission 1"
 BECHMOEFER.B G Scharfeld, Dechhoefer & Baron 65/07/19
 MCBRIDE.J A Atomic Energy Commission 1p 20751 096 24X
 Fiche 50-201.83/07/14.8310120006
- --8310120020 Discusses current appraisal of NFS reprocessing project Elummary of most current cost review encl Advi data will be included in semilanual rept to be filed in Oct 1964.in connection willcensing procedure RUNION T C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 64/08/17 ECABORGO 9 T. Atomic Energy Commission 3pp 20731 137 24X Fiche 50-201.83/07/14.8310120006
- --B910120023 Notifies that on 640402, substantially all fixed assets & portion of quick assets of fuel fabrication facility at Port Hope were sold & transferred by NFS to Canadian Westinghouse Co.Ltd

 BECHHOEFER, B Q Scherfeld, Bechhoefer & Baron 64/05/15
 JOHNSON, L E Atomic Energy Commission 1p 20751 140 24X
 Fiche 50-201,83/07/14,8310120006
- --8310120026 Order amending provisional CP CPCSF-2 to require NFS to file rept covering 6-month period ending Mar 31 & Bept 30 of each yr w/Director of Div of Licensing RIGOS.E , NOLMAN.A , CALLIHAN.D Atomic Safety and Licensing Board Panel 63/11/29 Nuclear Fuel Services, Inc (subs of Cetty Dil Co) 4pp 20751 141 R4X Fiche 50-201.83/07/14.8310120006
- --8310120028 Response to applicant motion for amend to provisional CP CPCBF-2 Info provided by applicant in proposed "NFB Ethibit E" & in statement of Commission 630516 memorandum & order "CDNNER:T B Nuclear Fuel Services, Inc (subs of Getty Oil Co.) CONNER:T B New York, State of CONNER:T B Atomic Energy Commission 63/11/14 7pp 20751 145 24X Fiche 50-201, 83/07/14,8310120006
- --8310120030 Statement in support of NFS 631023 motion requesting Commission take actions on loan arrangements & submittal of financial repts Braft NFS motion. Certificate of Svc & term loan agreement encl RCEBKAUSEN. OM New York, State of Affiliation Unknown. 63/10/29 23pp 20751.152 24X Fiche 50-201.83/07/14.8310120006
- --8310120032 Memorandum & order amending CPCBF-2 by incorporating condition to require applicants to durnish evidence of financial qualifications adequate to constitute proper basis for required finding MCCDOL.H.B. Atomic Energy Commission 83/09/13 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) App. 20781.175 24% Fiche 50-201.83/07/14.8310120306
- --B310120034 Forwards Amend 1 to NFB 630130 CP application submitted by NY State Atomic & Space Development Authority Certificate of Byc encl .

 RUESHAUSEN, O M Debevoise & Plimaton 63/04/09 MGCOOL, M II Atomic Energy Commission ip 20751 179 24X
 Fiche 50-201, 83/07/14,8310120006
- --8310120036 Memorandum of Agreement between NY State Ofc of Atomic Davelopment & NY State Atomic R&D Authority to coordinate respective responsibilities for development of atomic energy Certificate of Syc enci.

 AXELRAD, M. Atomic Energy Commission. TOWNSEND, O., PERQUSON, W. New York, State of 63/03/21 13pp 20751 184 24X

 Fiche 30-201,83/07/14.8310120006
- --B310120039 Responds to 630213 Itr re NFB application for licenses.

 Memorandum of Agreement between NY State Ofc of Atomic
 Bavelopment & NY State Atomic R&D Authority from Governor of
 State of NY encl.

 TOWNSEND. D. New York, State of. 63/04/08 LOWENSTEIN:R Atomic
 Energy Commission 2pp 20751 197 24X Fiche, 50-201, 83/07/14,
 8310120006

- --B310120042 Forwards Amend 4 to Part A of NFS CP application refinancial qualifications & related info STUMBLER, A Scharfeld, Bechhoefer & Baron 63/03/27 CONNER, T A Atomic Energy Commission ip 20751 199 247 Fiche 30-201,83/07/14.B310120006
- --8310120044 Amend 4 to CP application to construct spent fuol reprocessing plant Amend responds to Commission 630314 ltr, requesting addl finantial data re pending application Addl financial info encl RUNION.T C Nuclear Fuel Services. Inc (subs of Getty 011 to 163/03/29 20pp 20751 200 24% Fiche 50-201.83/07/14.831012000c.
- --8310120047 Forwards Amend 1 to Part A of NFS application for license to construct & operate Spent fuel processing plant BECHNOEFER.B G Schanfeld, Bechhoefer & Baron 63/02/13 Atomic Energy Commission ip 2075; 220 24X Fiche 50-201.83/07/14.8310120006
- --8310120049 Amend 1 to Part A of application for license to construct & operate spent fuel processing plant Certificate of Svc & financial info encl
 RUNION.T C Nuclear Fuel Services. Inc (subs of Cetty 0:1 Co)
 63/02/12 32pp 20751 221 24X Fiche 50-201.83/0//14.6310120905
- --8310120207 Application to amend License CSF-1, revising Paragraph 5 f original application re applicant financial qualifications RUMION:T C Nuclear Fuel Services. Inc (subs of Getty Oil Co) * Scharfeld, Bechhoefer & Baron 65/07/15 26pp 20731 G97 24X Fiche 50-201.83/07/14.8310120006
- B310120016 Add1 response to FOIA request for document to problems w/ Tech Specs applying to RCS leakage determinations in PWRs Forwards App A documents
 FOLTON.J M Division of Rules and Records B3/07/0/ VOIGT. H H LeBosuf
- --B003240118 Requests specs for surveillance & limiting conditions to ensure valve integrity if Event 5 valve configuration exists NRC B00225 itr requesting LWR licensees to indicate if Event 5 yalvs configuration exists at facility and POLK.P J Operating Reactors Branch 3 (Pre 800428) 80/02/29 WETMORE, J Operating Reactors Branch 2 (Pre 800428) 2pp 20751 027
- --B003240123 Ltr all LWR licensees requesting that periodic valve tests or continuous surveillance be performed to determine if Event 5 valve configuration exists at facility Requests listed info re valve configuration
 EIBENHUT.D 0 Division of Operating Reactors 80/02/25
 Division of Operating Reactors 3pp 20751 034
- ---B007290663 Forwards SER suppl. Revision 1. re periodic leak testang of pressure isolation valves Replaces 800702 transmittn;
 KN19HT.JP Assistant Director for Comp & Structures Engineeyin;
 (Pre 830201) 80/07/16 TEDESCO.R L Assistant Director for Licensing ip 20751 043 24X Fiche 50-000.83/07/07.8310120016
- --8007290676 SER supplication for periodic leak testing of pressure isolation valves Additions to Tech Specs acceptable
 * Assistant Director for Comp & Structures Engineering (Pre 830201) 80/07/16 3pp 20751 044 24% Fiche 50-000, 93/07/07, 8310120016
- --B310120018 Notifies of decision to expand existing contract G/Frankly-Inst to include technical assistance on Generic Activity B-45. "LURP Primary Coolant Sys Pressure Isolation Valves " Mgt concurrence requested PDLK.P J. Operating Reactors Branch 3 (Pre 800428) B0/03/06 BUTCHER, E NRC No Detailed Affiliation Given 23pp 20751 Gos
- --8310120022 Safety evaluation requiring test of primary coolant symposture isolation valves be incorporated into plant Tach Spaces
 * NRC No Detailed Affiliation Given 81/04/20 ip 20/51 037 24X Fiche. 50-000, 83/07/07. 8310120016
- B310130390 F0IA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ABLB proceedings GARDE, E.P. Government Accountability Project B3/08/08. Office of Administration, 2pp 20769 352 24X Fiche, 50-329, 83/08/08.
- 83i0130394 Responds to FOIA request for all records on re-review of structural adequacy of diesel generator bldg subsequent to May testimony of R Landsman in ASLB proceedings Forwards App A documents Documents also in PDR FELTON, J M Division of Rules and Records 83/08/25 OARDE, B proceedings Forwards App A 354 24X Fiche 50-329,83/08/25,8310130394

- --9308150338 Advises of assignment as member of task group to reevaluate structural design & const adequacy of plant diesel generator bldg
 - blidg
 KUD.P T
 Structural & Geotechnical Engineering Branch
 TAN.C P
 Structural & Geotechnical Engineering Branch
 1p
 20769 362
 24X Fiche 50-329,83/08/25,8310130394
- --8308290029 Requests meeting on B30822 to discuss Landsman concerns that diesel generator bldg inadequate to return to svc based on inability to meet design requirements VQLLMER:R NRC No Detailed Affiliation Given B3/08/15 KNIGHT.J NRC No Detailed Affiliation Given 1p 20769 361 24% Fiche 50-329,83/08/25,8310130394
- B310130402 FDIA request for list of reporting requirements imposed on public w/copy of applicable form & ofc, telephone number & room number where filing of reporting requirements made DAY. M S. Mashington Knowledge Network B3/09/11 FELTON, J M Division of Rules and Records 1p 20/71 001
- 8310130409 Responds to FOIA request for list of reporting requirements imposed an public. w/copy of applicable form A ofc. telephone number & room number where filings of reporting requirements made FELTON, J H Division of Rules and Records 83/08/29 DAY, M S Washington Knawledge Network 1p 20771 002
- --8310130410 "NRC List of Active Repts Approved Under Federal Repts Act as of 830727 " * NRC - No Detailed Affiliation Givon 83/07/29 9pp 20771 003
- 8310130412 Responds to FOIA request for any repts of insps or investigations of facilities of Nuclear Medicine Assoc. Inc No insps or investigations of facility made vince 800101 No documents available subj to request FELTON, J M Division of Rules and Records 83/08/25 KELLY, D L Peper, Martin, Jensen, Maichel & Hetlage 1p 20769 350
- B310130413 F01A request for repts of insps or investigations of facilities of Nuclear Medicine Assoc Inc since B00101 MELLY.D L. Peper Martin, Junsen Maichel & Hetlage B3/08/05 Office of Administration ip 20769 351
- B310140030 F01A request for IE Insp Rept 79-19, associated notice of proposed imposition of civil penalties, notice of violation & order to show cause HAMLIN.JB Shaw, Pittman, Potts & Trowbridge 83/05/31 Office of Administration 6pp 20794 i10 24X Fiche 50-498,83/05/31.
- B31014003: Partial response to FOIA request for documents re IE Insp
 Rept 79-19 & associated notice of proposed imposition of
 civil penalties, notice of violation & order to show cause
 Forwards App A documents Documents also available in PDR
 FELTON.J M Division of Rules and Records B3/0B/23 HAMLIN.J B
 Bhaw. Pittman, Potts & Trombridge 1p 20794 116 24X
 Fiche 50-498.83/08/23.8310140031
- --B00B270592 Forwards Region 5 rept of investigation re alleged falsification of QA records by Brown & Root inspector W/o encl
 WARD.W J Office of Inspection & Enforcement, Office of the Director 80/08/01 FORTUNA:R Office of Inspector & Auditor 1p 20795 186 24X Fiche 50~498.83/08/23,8310140031
- --93k0140032 "South Texas Project History " * NRC - No Detailed Affiliation Given 83/05/31 App 20794 k17 24X Fiche 50-498.83/08/23.8310140031
- --8310140037 Notification of B00819 meeting w/util & Brown & Root in Bay City.TX to clarify util response to 800430 show cause order # NRC - No Detailed Affiliation 91ven 83/10/13 NRC - No Detailed Affiliation Given 4pp 20794 129 24X Fiche 50-498,83/08/23,8310140031
- --B310140044 NRC proposal to fine Texas Utils for alleged noncomplian e w/NRC requirements re Brown & Root QA program & violation of piping weld tests > NRC - No Detailed Affiliation Given B3/10/13 2pp 20794 134 24X Fiche 50-498.83/08/23.8310140031
- --8310140047 Enforcement history.South Texas Project.Oct 1976 Mar 1980 * NRC - No Detailed Affiliation Given 83/10/13 3pp 20794 136 24X Fiche 50-498.83/08/23.8310140031

- --0310140050 Discusses notice of violation issued as result of 791110-820207 insps Noncompliance noted QC insp by Brown & Root not sufficiently independent Marked-up copy # NRC - No Detailed Affiliation Given 83/05/31 NRC - No Detailed Affiliation Given 35pp 20794 139 24X Fiche 50-498,83/08/23,8310140031
- --B310140052 Forwards draft investigation rept & proposed enforcement action for comment Commission briefing on investigation & enforcement planned for wk of 800414 Draft rept also sent to pertinent NRC personnel
 SHEMNAKER: R E Director's Office. Office of Inspection and Enforcement B0/04/01 THORNBURG, H D Director's Office of Inspection and Enforcement 140pp 20794 175 24X
 Fiche 50-498,83/08/23,8310140031
- --B310140062 Requisition for payment to Continental Airlines for PBX svc of pkg to Houston, TX * NRC No Detailed Affiliation Given 80/05/01 2gp 20795 071 24X Fiche 50-498,83/08/23.8310140031
- --8310140088 Advises that, due to seriousness of violations by Brown & Root & util at South Teras Project, Pull-scale public hearing in Matagorda County, TX mandatory VAN HOY, G Affiliation Unknown 80/05/20 STELLO, V Director's Office, Office of Inspection and Enforcement 1p 20793 079 24X Fiche 50-498, 83/08/23, 8310140031
- ---8310140095 Submits draft generic ltr for use w/incoming correspondence as result of 800430 IE enforcement pkg STELLO.V Director's Office. Office of Inspection and Enforcement 83/10/13 Affiliation Unknown 3pp 20795 167 24x Fiche 50-498,83/08/23,8310140031
- B310170020 FDIA request for documents re NRC &/or NRC consultant participation in Committee on Safety of Nuclear Installation sponsored "Group of Experts on Nuclear Aerosols" & "Group of Experts on Source Terms"

 BHOLLY: S C Union of Concerned Scientists B3/05/02 FELTON, J M Division of Rules and Records 1p 20814 158
- 8310170029 Responds to FOIA request for matl re NRC participation in Committee on Safety of Nuclear Installation sponsored "Group of Experts on Nuclear Aerosols" Forwards App A documents App B documents withheld (ref FOIA Exemption 4) FELTON.J M Division of Rules and Records 83/06/29 SHDLLY.5 C Union of Concerned Scientists 5pp 20814 159
- --8310170033 informs that M Silberberg requested to be in Bologns. Italy by 780918 to attend Committee on Safety of Nuclear Installation 780919 meeting Meeting held to complete preliminary rept editing Meeting held to complete KELBER. C N Assistant Director for Advanced Reactor Safety Research 78/08/29 LAMASTRA. R Office of Administration 1p 20814 164
- --8310170037 Forwards draft stats-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna, Italy BILBERBERG, M. Esperimental Fast Reactor Sefety Research Branch 78/08/30 PRODI, V. Italy, Covt of, ip 20814-165
- --B310170044 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna. Italy 51LBERBERG.M Experimental Fast Reactor Safety Research Branch 78708/30 SHOCK/W Germany. Federal Republic of ip 20814 i
- --BBi0170047 Forwards draft state-of-the-art rept on nuclear er Final revs will be completed at 780920-22 meetings in Bologne. Italy BILBERBERG.M Experimental Fast Reactor Sefety Research I 78/08/30 HILLIARD.R K Hanford Engineering Development 20814 167
- --B310170050 Forwards draft state-of-the-art rept on nuclear aero Final revs will be completed at 780920-22 meetings in Bnlogna.Italy SILBERBERO.M Experimental Fast Reactor Safety Research Brar 78/08/30 GIESEKE.J.A Battelle Nemorial Institute. Columbu Laboratories ip 20814 168
- --8310170055 Forwards draft state-of-the-art rept on nuclear aerc Final revs will be completed at 780920-22 meetings in Bologna. Italy SILBERBERG, M. Experimental Fast Reactor Safety Research Brai 78/08/30 LANZA.S. Italy. Covt of: ip 20814 169
- --8310170057 Forwards draft state-of-the-art rept on nuclear aero Final revs will be completed at 780920-22 meetings in Bologna: (taly SILBERBERG, M. Experimental Fast Reactor Safety Research Bran 78/08/30 KITANI.S Japan, Govt of ip 20814 170

- --8310170059 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 760920-22 meetings in Bologna, Italy SILBERBERG. H. Esperimental Fast Reactor Safety Research Branch 78/08/30 HARBISON, B. A. United Kingdom ip 20814 171
- ---8310170062 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna.ttaly SILBERBERG.M Experimental Fast Reactor Safety Research Branch 78/08/30 GOOSSENS, I W Belgium, Govt of, ip 20814 172
- --B310170066 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920~22 meetings in Bologne-Italy SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 FERMANDUIAN,M France, Govt of. 1p 20814 173
- --8310170072 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna, Ifaly SILBERBERG,M Experimental Fast Reactor Safety Research Branch 78/08/30 AKA9ANE,K Japan, Govt of ip 20814 174
- --8310170090 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna.Italy SILBERBERO,M Experimental Fast Reactor Safety Research Branch 78/08/30 ABBEY,F United Kingdom Atomic Energy Authority ip 20814 175
- ---8310170094 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologna, Italy SILBERBERG, M. Experimental Fast Reactor Safety Research Branch 78/08/30 VAN DE VATE, J. Netherlands ip 20814 176.
- --83:0170:102 Forwards draft state-of-the-art rept on nuclear aerosols Final revs will be completed at 780920-22 meetings in Bologns, Italy SILBERBERG, M. Experimental Fast Reactor Bafety Research Branch 78/08/30 MANESSE, D. France, Govt of, 1p. 20814 177
- ---8310170110 Comments on serosol experts group rept Sub; of nuclear serosols has significant impact on evaluation of consequences of postulated reactor accidents
 SILBERBERON Experimental Fast Reactor Bafety Research Branch
 78/10/27 ABBEY, F United Kingdom 7pp 20814 178
- --8310170116 Discusses 790214 telton W/K Stadie re status of NRC perticipation at Committee on Safety of Nuclear Installation specialist meeting in Bournemouth, England Budget restraints may prevent NRC representation SILBERBERG-M NRC No Detailed Affiliation Given 79/02/16 MURLEY-T E Assistent Director for Advanced Reactor Safety Research (p. 20814-183
- --B310170120 Forwards review it; & revs to draft state-of-the-art matimated to group of experts. Arrangements for group dinner on 790404 requested SILBERBERO, Experimental Fest Reactor Sefety Research Branch 79/03/09 OLIVIER. J P France, Govt of, ip 20814 186
- --B310170123 Forwards nevs to draft state-of-the-ent rept on nuclear ambisols in reactor tafety. Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested BILBERBERO, M M Experimental Fast Reactor Safety Research Branch LANZE, S Italy, Govt of, 1p 208:4 187
- --B31017012B Forwards revs to draft state-of-the-art rept on nuclear agrosols in reactor safety Items to be considered histed Review of revs in preparation for 790403 meeting in Paris requested
 SILBERBERGON Experimental Fast Reactor Safety Research Branch 79/03/09 SCHOCK.W Germany, Federal Republic of 1p 20814 188
- --8310170130 Forwards revs to draft state-of-the-art rept on nuclear apropols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested
 BilBERBERG,H Experimental Fast Reactor Safety Research Branch
 77/03/09 BCHIKARSKI,W Q Germany, Federal Republic of Ip
 20814 189
- --B310170136 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested BILBERBERO, M Esperimental Past Reactor Bafety Research Branch ITANI.S Japan, Govt of 1p 20814 170 KITANI, B

- ---8310170140 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested SILBERBERG.M Experimental Fast Reactor Safety Research Branch 79/03/09 MARBISON.S A United Kingdom 1p 20814 191
- --8310170144 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris
 - requested
 SILBERBERG, M Experimental Fast Reactor Safety Research Branch
 79/03/09 HILLIARD, R K Hanford Engineering Development 1p
 20814-172
- --8310170190 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety items to be considered listed Review of revs in preparation for 790403 meeting in Paris
 - requested SILBERBERG,M Experimental Fast Reactor Safety Research Branch 79/03/09 GIESEKE.J A Battelle Memorial Institute. Columbus Laboratories ip 20814 193
- --0310170161 Forwards revs to draft state-of-the-art rept on nuclear agrossls in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested requested SILBERBERG.M Experimental Past Reactor Safety Research Branch 79/03/09 GOOSENS.I W Belgium. Govt of. ip 20814 194
- ~-83i0170164 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris
 - requested SILBERBERG, M ,M Experimental Fast Reactor Safety Research Branch PRODI.V Italy, Govt of, 1p 20814 195
- --8310170166 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested requested SILBERGERG.M Experimental Fast Reactor Safety Research Branch 79/03/09 MANESSE.M France, Govt of, ip 20814-196
- --0310170169 Forwards revs to draft state-of-the-ort rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris M Experimental Fast Reactor Safety Research Branch VAN DE VATE, J Netherlands 1p 20814 197
- --B310170171 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested requested SILBERBERG.M Experimental Fast Reactor Bafety Research Branch 79/03/09 ABBEY.F United Kingdom ip 20814 198
- --8310170176 Forwards tevs to draft state-of-the-art rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested 0.M Experimental Fast Reactor Safety Research Branch AKAGANE.K Japan. Govt of ip 20814 199 SILBERBERG, M
- --83i0170180 Forwards revs to draft state-of-the-art rept on nuclear aerosols in reactor safety Items to be considered listed Review of revs in preparation for 790403 meeting in Paris requested GILBERBERG, M. Experimental Fast Reactor Safety Research Branch 79/03/09 FERMANDJIAN, J. France, Govt of, Ip. 20814 200
- --8310170182 "Nuclear Aerosols in Reactor Safety "

 * Organization for Economic Compenation & Development (Paris)
 79/06/30 4pp 20814 201
- --B310170237 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by B30B17 if attendance at meeting in Seattle not possible SILBERBERO, H Experimental Fast Reactor Safety Research Branch 79/07/27 HARBISON, S.A. United Kingdom 7pp 20814 205
- --B310170242 Forwards final draft of revised summary statments from 790405 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendence at meeting in Seattle not possible W/o encl SILBERBERG M Experimental Fast Reactor Safety Research Branch 79/07/27 SCHOCK W Germany, Federal Republic of 1p 20814-212

- --B310170247 Forwards finel draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILBERBERG,M Experimental Fast Reactor Safety Research Branch 79/07/27 PRODI.V Italy, Govt of. ip 20814 213
- --B310170252 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aprosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILBERBERG, M. Experimental Fast Reactor Safety Research Branch 79/07/27 KITANI, A. Japan, Govt of ip 20814 214
- --B310170289 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILBERBERO.M Experimental Fast Reactor Safety Research Branch 79/07/27 VAN DE VATE.J Netherlands ip 20814 215
- --B310170265 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILBERBERO,M Experimental Fast Reactor Safety Research Branch 79/07/27 ABBEY,F United Kingdom ip 20814 216
- --B310170269 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Geattle not possible W/o encl
 SILBERBERD,M Experimental Fast Reactor Safety Research Branch 7970727 OLEBEKE, J A Battelle Memorial Institute, Columbus Laboratories ip 20814 217
- --8310170275 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILBERBERG,M Experimental Fast Reactor Safety Research Branch 79/07/27 FERMANDJIAN,J France, Govt of, 1p 20814 218
- --8310170280 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILDERBERG,M Experimental Fast Reactor Safety Research Branch 79/07/27 GLIVIER.J P France. Govt of, ip 20814 219
- ---B3101702B4 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790B17 if attendance at meeting in Beattle not possible W/o encl BILBERDERO, M Experimental Fast Reactor Safety Research Branch 79707/27 SCHIKARSKI, B Gormany, Federal Republic of 1p R0B14 220
- --B3101702BB Forwards final draft of revised summary statements from 790403 monting on "Critical Review of Aerosol Instruments," for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o enc! SILBERBERG.M Experimental Fast Reactor Safety Research Branch 79/07/27 AKAOANE.K Japan, Govt of ip 20814 221.
- --B310170294 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Smattle not possible W/o encl BILBERGERG.M Experimental Fast Reactor Safety Research Branch 79/07/27 HILLIARD.R K Hanford Engineering Development 1p 20814 222
- --#310170300 Forwards final draft of revised summary statements from 790403 meeting on "Critical Review of Aerosol Instruments." for comment Comments requested by 790817 if attendance at meeting in Seattle not possible W/o encl SILBERBERO.M Experimental Fast Reactor Safety Research Branch 79/07/27 LANZA.9 Italy, Govt of. ip 20814 223.
- --B310170303 Forwards "Bummary Rept on Critical Review of Aerosol Measurements Techniques" Rept will be highlighted at Committee on Bafety of Nuclear Installation meeting. W/o encl
 BILBERBERG, M Experimental Fast Reactor Safety Research Branch
 79/10/05 KITANI.A Japan. Oovt of ip 20814
- --8310170305 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques "Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o entl SILBERBERG, M Experimental Fast Reactor Safety Research Branch 79/10/05 HARBISONS A United Kingdom ip 20814 225

- --8310170309 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl SILDERBERG, M Experimental Fast Reactor Safety Research Branch 79/10/05 SCHIKARSKI, B Germany, Federal Republic of 19 30814 304
- --B310170314 Forwards "Summary Rept on Critical Review of Aerosol Measurements Techniques" Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
 SILBERBERG.M Experimental Fast Reactor Safety Research Branch
 79/10/05 FERMANDJIAN.J France. Covt of. ip 20814 227
- --8310170319 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl BILBERBERG,M Experimental Fast Reactor Safety Research Branch 79/10/05 PRODLY Italy, Govt of, ip 20814 228
- --B310170323 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
 SILBERBERG, M Experimental Fast Reactor Safety Research Branch, 79/10/05 01ESEKE. J.A. Battelle Memorial Institute, Columbus Laboratories ip 20814-229
- --8310170326 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl
 SILBERBERG,M Experimental Fast Reactor Safety Research Branch 79/10/03 SCHOCK,W Germany, Federal Republic of ip 20814 230
- --B310170328 Forwards "Bummary Rept on Critical Review of Aerosol Measurement Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o enc!

 BILBERBERO M Experimental Fast Reactor Safety Research Branch 79/10/05 ABEV.F United Kingdom, Ip 20814 231.
- --B310170332 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques" Rept will be highlighted at Committee on Safety of Nuclear Installation meeting W/o encl.

 81LBERBERG, M Experimental Fast Reactor Safety Research Branch 79/10/05 HILLIARD, R.K. Hanford Engineering Development ip 20814 232
- --B310170335 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques " Rept will be highlighted at Committee on Safety of Nuclear Installation meeting, W/o encl BILBERBERO, M Experimental Fast Reactor Safety Research Branch 77/10/05 VAN DE VATE.J. Netherlands 10 20814 233
- ~-8310170340 Forwards "Summary Rept on Critical Review of Aerosol Measurement Techniques " Appreciation expressed for continuing effort & support for Group of Experts on Nuclear Bafety Aerosols H/o encl SILBERBERG.M Experimental Fast Reactor Bafety Research Branch 79/10/05 OLIVIER.J P France, Govt of, ip 20814:234
- --8310170343 Forwards "Bummary Rept on Critical Review of Aerosol Heasurement Techniques " Rept will be transmitted to Committee on Bafety of Nuclear Installation for annual meeting in Nov H/o encl BILBERBERG, M Experimental Fast Reactor Bafety Research Branch 79/10/05 MOCHIZUKI, K Japan, Govt of, 1p 20814 235.
- --8310170347 Forwards "Summary Rept on Critical Review of Aerosol Measurement Tschniques " Rept will be transmitted to Committee on Safety of Nuclear Installation for annual meeting in Nov W/o encl SilbERBERO,M Experimental Fast Reactor Safety Research Branch, 79/10/05 MAY,F Q Australia, Govt of ip 20814:236.
- --8310170352 Forwards "Summary Rept on Critical Review of Aerosol
 Heasurement Techniques " Rept will be transmitted to
 Committee on Safety of Nuclear Installation for annual
 meeting in Nov M/o end
 SILBERBERG,M Experimental Fast Reactor Safety Research Branch
 79/10/05, TORGERSON,D C Canada, Govt of.. ip 20814:237

- ~-8310170358 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear agrosols in reactor safety in Catlinburg. TN Recipient carticipation requested Background info.purpose & agenda encl W/a encl SILBERBERG.M Esperimental Fast Reactor Safety Research Branch 79/11/09 LONG.J K Office of Nuclear Reactor Regulation. Director 2pp 20814 238
- --B310170362 Notifies of Committee on Bafety of Nuclear Installations
 B00415-17 specialist meeting on nuclear aerosols in reactor
 safety in Gatlinburg, TN Recipient participation requested
 Background info, purpose & agenda enti Wo entl
 SILBERBERG, M Experimental Fast Reactor Safety Research Branch
 79/11/09 SHERRY, R R NRC No Detailed Affiliation Given 2pp
 20814 240
- --B310170370 Notifies of Committee on Safety of Nuclear Installations
 B00415-17 specialist meeting on nuclear aerosols in reactor
 safety in Gatlinburg, TN Recipient participation requested
 Background info.purpose & agenda enci W/o enci
 BILBERBERO, M Experimental Fast Reactor Safety Research Branch
 79/11/09 LARKINB, J T NRC No Detailed Affiliation Given 2pp
 20814 242
- --8310170374 Notifies of Committee on Safety of Nuclear Installations
 800415-17 specialist meeting on nuclear aerosols in reactor
 safety in Gatlinburg. TN Recipient participation requested
 Background info.purpose & agenda enci W/o enci
 BILDERBERG. H Experimental Fast Reactor Safety Research Branch
 79/11/08 KRESS.S T Oak Ridge National Laboratory 2pp.
 20814 244
- --B310170379 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg, TN Recipient participation requested Background info.purpose & agenda encl W/o enci SILBERDERO, M Experimental Fast Reactor Safety Research Dranch 79/11/08 POWERS, D Sandia Laboratories 2pp 20814:246
- --9310170386 Notifies of Committee on Safety of Nuclear Installations 890415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg, TN Recipient participation requested Background info.purpose & agenda encl W/o sncl 81LBERDERG,M Experimental Fast Reactor Safety Research Branch 79/11/08 NALINAUSKAS, A Dat Ridge National Laboratory 2pp 20814 248
- --B310170371 Notifies of Committee on Safety of Auctear Installations
 BQ0413-17 specialist meeting on nuclear aerosols in reactor
 safety in Gatlimburg. TN Recipient participation requested
 Background info.purpose & agenda encl W/o encl
 BILBERDERO.M Experimental Fast Reactor Safety Research Branch
 79/11/08 WRIGHT.A Dak Ridge National Laboratory 2pp
 20014 200
- --8310170392 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg, TN Recipient participation requested Sackground inforpurpose & agenda encl W/o encl 81LBERBERG, M. Experimental Fast Reactor Safety Research Branch 79/11/08 GIESEKE, J. A. Battelle Memorial Institute, Columbus Laboratories 2pp 20814 252
- --B310170396 Notifies of Committee on Safety of Nuclear Installations B00415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg, TN Recipient participation requested Background info.purpose & agenda entl W/o enci B1LBERBERG, M. Experimental Fast Reactor Safety Research Branch 79/1/08 LEEK Battelle Memorial Institute, Columbus Laboratories 23p 20814 254
- --B310170402 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear arrosols in reactor safety in Gatlinburg, TN Recipient participation requested, Background info, purpose & agenda enci W/o encl SILBERBERG, M Experimental Fast Reactor Safety Research Branch 79/1/08 ADAMS, R Dak Ridge National Laboratory 2pp 20814 236
- --8310170406 Notifies of Committee on Bafety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg. Th Recipient participation requested. Background info, purpose t agenda encl. W/o encl. SILBERBERG.M Experimental Fast Reactor Gafety Research Branch 79/11/08 ELRICK.R Sandia Laboratories 2pp 20814 258
- ~-B310170410 Notifies of Committee on Safety of Nuclear Installations B00415-17 specialist meeting on nuclear aerosols in reactor safety in Qatlinburg, TN Recipient participation requested Background info, purpose to agenda encl W/o encl BILBERBERO, H Esperimental Fast Reactor Safety Research Branch 79/11/08, JORDAN, H Battelle Hemorial Institute, Columbus Leboratories 2pp 20814 260

- --8310170413 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Oatlinburg IN Recipient participation requested Background info.purpose & agenda encl W/o encl SILBERDERG:M Experimental Fast Reactor Safety Research Branch 79/11/08 PARKER:G W Oak Ridge National Laboratory 2pp 20814 262
- --8310170415 Notifies of Committee on Safety of Nuclear Installations
 800415-17 specialist meeting on nuclear aerosols in reactor
 safety in Gatlinburg TN Recipiont participation requested
 Background info.purpose & agenda encl W/o encl
 SILBERBERG, M Experimental Fast Reactor Safety Research Branch
 79/11/07 CASTLEMAN.A W Colorado, Univ of 2pp 20814 264
- --B310170418 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg, TN Recipient participation requested Background info, purpose t agenda enti W/o enti S1LBERGERG, M Experimental Fast Reactor Safety Research Branch 79/11/07 CDOPER, D Harvard Univ , Cambridge, MA 2pp 20814 266
- --8310170422 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Catlinburg. Th Recipient participation requested Background infe, purpose & agonda enci W/o onci SILBERBERG.M Experimental Fast Reactor Safety Research Branch 79/11/07 LOYALKA, S K Missours, Univ of, Columbia, MO 2pp 20814 268
- ~-83:0170429 Notifies of Committee on Safety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg. TN Recipient participation requested Background info.purpose & agenda uncl U/o encl SILBERDERG.M Experimental Fast Reactor Safety Research Branch 79/11/07 LIU.B Y Minnesota. Univ of 2cp 20814 270
- --8310170431 Notifies of Committee on Safety of Nuclear Installations
 800415-17 specialist meeting on nuclear aerosols in reactor
 safety in Gatlinburg.TN Recipient participation requested
 Background info.puppose t agende oncl W/o enci
 SILBERBERO.M Experimental Fast Reactor Safety Research Branch
 77/11/07 BROCK.J R Texas. Univ of, Austin, TX 2pp
 20814 272
- --B3i0170434 Notifies of Committee on Safety of Nuclear Installations
 800415-17 specialist meeting on nuclear aerosols in reactor
 safety in Qatlinburg.TN Recipient participation requests of
 Background info.purpose & agenda enci W/o enci
 BILDERBERG.M Experimental Fast Reactor Safety Research Branch
 79/ii/707 MANAPILLY.G M Inhelation Toxicology Research
 Institute 2pp 20814 274
- --8310:7043B Notifies of Committee on Bafety of Nuclear Installations 800415-17 specialist meeting on nuclear aerosols in reactor safety in Gatlinburg. TN Recipient participation requested Background info.purpose & agenda encl W/o encl SILBERBERG. M Experimental Fast Reactor Bafety Research Branch 79/11/07 SEHMEL. G A Battelle Memorial Institute. Pacific Northwest Laboratory 2pg 20814 276
- --B310170444 Lists reasons for deferral of meeting w/Group of Excepts :-Nuclear Aerosols to update 1979 state-of-the-art rept until late 1982 BluBERBERG, M Fuel Behavior Branch B2/02/22 RDYEN, J France. Govt of. 2pp 20814 278
- --8310170445 Informs of plans to attend 820422-23 meeting of Committee : Safety of Nuclear Installations Group of Experts on Nuclear Association Reactor Safety SILBERBERG, M. Fuel Dehavior Branch 82/04/07 ROYEN, J. France. Govt of, 1p. 20814 280
- --B310170450 Requests addl listed info re input to draft suppl to Committee on Safety of Nuclear Installations rept Related info encl SILBERBERO,M Fuel Behavior Branch 82/05/13 GIESEKE,J Battelle Hemorial Institute, Columbus Laboratories 3pp 20814 281
- --8310170452 Notifies that J Gieseke & T Kress will attend 820707-10 meetings of Committee on Bafety of Nuclear Installation on Nuclear Associated on Reactor Bafety experts Related info encl
 SILBERBERO,M NRC No Detailed Affiliation Given 82/08/31 RDYEN,J France, Govt of, 5pp 20814 283

- --8310170457 Discusses Group of Experts under Committee for Safety of Nuclear Installation Working Group 4 meetings & travel funding Travel funding continuing problem Meeting w/W Dircks might be necessary to permit travel by NRC LAFLEUR, J D Office of International Programs. Director 83/02/03 HOUSTON.R W Office of Nuclear Reactor Regulation. Director ip 20914 288
- --8310170461 Responds to B21214 request for NRC representation on Committee on Safety of Nuclear Installation principle Horking Oroup 4 Recommendations listed SILBERBERG.M Accident Source Term Program Office 83/02/28 LAFLEUR.J D Office of International Programs, Director 1p 20814 289
- --B310170463 Advises of NRC representation at Group of Experts on Source Term meeting Resolution of accident source term issue is major NRC objective HBUSTON,R W Assistant Director for Reactor Safety 83/03/18 LAFLEUR.J D Office of International Programs, Director ip
- 8310170049 Responds to FOIA request for records re 1974-75 research grants to Boarden Chemical Div & Reichold Chemical for research on urea formaldshyde foam insulation No records available subj to request FELTON, J M Division of Rules and Records 83/09/01 MOSHER, D Citizens Engaged in Removal of Toxic Substances, Inc. 2pp 20798 057
- 8310170032 FOIA request for records re 1974-75 research grants to Boarden Chemical Div & Reichold Chemical for research on urea formaldehyde foam insulation MCSHER, D Citizens Engaged in Removal of Toxic Substances, Inc 83/08/19 NRC - No Detailed Affiliation Given ip 20798 059
- B310:7007B Responds to JP Berg FOIA request for copies of active licenses issued by NRC to Pharmatopes, Inc or Syncor Corp Forwards App A documents FELTON, J M Division of Rules and Records B3/04/07 Rosenfeld & Falk, Inc 3pp 20797 001
- --7908060318 Mat1/Byproduct License 34-19007-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125 & Xe-133 in production of Tc-99m pertechnetate, instrument calibr & compound mixing VACCA, P C Licensing Management Branch 79/06/29 App 20797 695
- --7908270319 Matl/Dyproduct License 34-18484-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60 Ba-133, I-125, Xe-133 & byproduct matls in Groups 1-5 in various forms for instrument calibr preparation of radios forms VACCA.P C Licensing Management Branch 79/07/24 opp
- --7909140005 Mati/Byproduct License 34-1900B-01MD for Pharmatopes, Inc authorizing use of Mo-99, Cs-137, Co-60, Ba-133, I-125, Xe-133 & byproduct matis Groups 1-5 in various forms for distribution & calibr of instruments WALKER, W J Licensing Management Branch 79/08/09 App 20797 069
- --7911300172 Mat1/Byproduct License 37-18467-01MD for Pharmco Nuclear.
 Inc authorizing use of Mo-99 in Mo-99/Tc-99m generator.
 Ba-133.Cs-137 & Groups I.II.IV.V byproduct matls for
 production of Tc-99m & IR-113a chloride
 VACCA.P C Licensing Management Branch 79/10/25 App
 20797 133
- --8001040244 Mati/Byproduct License 21-19219-01MD for Pharmatopes.inc authorizing use of Mo-99.Cs-137.Co-60.Ba-133.I-125.Xe-133 & any byproduct mati in Groups I.II.IV & V for dispensing & distribution of radiopharms
 VACCA.P C Licensing Management Branch 79/11/27 6pp 20797 194
- --8004230428 Mati/Byproduct License 37-18467-01MD for Pharma Co Nuclear-Inc is amended per 800115 application Amend 2 adds any Syproduct mati listed in 10CFR31 ii(a), in any prepackaged in vitro diagnostic test kits VACCA:P C Licensing Management Branch 80/03/18 ip 20797 141
- --B00417010D Matl/Byproduct License 12-19333-01MD for Pharmatopes.Inc authorizing use of Mo-79.(S-137.Co-60.Ba-133.ke-133.k Groups I-V byproduct matl for instrument calibr & distribution of prepared radiopharms
 VACGA.P. C. Licensing Management Branch. B0/05/06 4pp 20797 217

- --B006200467 Matl/Byproduct License OB-18308-01MD for Pharmatopes, Inc. is amended per B00519 ltr Amend 1 authorizes use of U depleted in U-235 as metal encased in stainless steel for shielding not!

 VACCA.P C Licensing Hanagement Branch 80/05/25 ip 20797 180
- --B007170042 Matl/Buproduct License 21-19219-01MD for Pharmatoges.Inc is amended per 800519 ltr Amend 1 authorizes U.depleted in U-235.as shielding of Mo-99/TC-99m generators VACCA.P C Licensing Management Branch B0/06/25 1p 20797 201
- --8007170067 Mat1/Byproduct License 34-19007-01MD for Pharmatopes, Inc is amended per 800319 ltr Amend 1 adds U. depleted in U-235, as shielding of Mo-99/Tc-99m generators & adds conditions of use VACCA.P C Licensing Management Branch 80/06/26 ip 20797 101
- --8007170227 Mati/Bysroduct License 34-16405-01MD for Pharmaco Nuclear Inc. is amended per 800609 ltr Amend 13 adds U.depleted in U-235.as shielding of Mo-99/TC-99m generators LAMASTRA,M A Licensing Management Branch 80/06/27 ip 20797 215
- --8009160105 Matl/Byproduct License 24-19360-01MD for Pharmaco Nuclear, Inc.authorizing use of No-99 in any Mo-99/Tc-99m generator for production of Tc-99m pertechnetate * Licensing Management Branch 80/08/22 8pp 20797.159
- --B00924D099 Matl/Byproduct License 37-18467-0iMD for Pharmaco Nuclear, Inc.is amended per 800609-10 ltrs Amend 3 authorizes use of U depleted in U-235 as shielding in Mα-99/Tc-99m generators * Licensing Management Branch 80/08/21 1p 20797 142
- --80:0070328 Mati/Byproduct License OB-18308-01MD for Pharmatopes, Inc. is amended per 800910 ltr Amend 2 authorizes MT Hebner, MC Fu. R Irwin, M Vetica & A McKusick as users of licensed matis VACCA, P.C. Licensing Management Branch 80/09/12 ip 20797 179
- --8012010377 Mati/Byproduct License 34-19007-01MD for Pharmatopes, Inc is amended per 800903 ltr Amend 2 authorizes MT Hebner, MC Fu, J Fields, 8J Clark & RJ Schnieders as users of licensed matls

 DELMEDICO.J Licensing Management Branch 80/11/12 1p. 20797 102
- --B012310197 Matl/Byproduct License 12-19333-OIMD for Pharmatopes, Inc is amonded per B00720 ltr Amend 2 changes reading of Condition 12 re names of users of licensed matl DELMEDICO, J Licensing Management Branch B0/11/14 1p
- ---B012310245 Matl/Byproduct License 21-19219-OIMD for Pharmatopes, Inc is amended per B00731 ltr Amend 2 changes reading of Condition 12 re names of users of licensed matl BELMEDICOL J Licensing Management Branch B0/12/03 ip
- --8012310507 Mat1/Byproduct License 13-17451-01MD for Pharmatopes, Inc authorizes use of Cs-137.Co-60 & Ba-133 sealed sources for instrument calibr DELMEDICD, J Licensing Management Branch 80/11/14 7pp
- --B1010704B6 Mat1/Byproduct License 24-19360-01HD for Pharmaco Nuclear, Inc is amended per B01021 ltr.Amend 2 changes reading of Conditions 12 & 23 re possession & use of licensed matis DELMEDICO, J Licensing Management Branch, 80/12/0B ip, 20797,16B
- --Bi01070060 Matl/Byproduct License OB-1830B-01MD for Pharmatopes, Inc is amended per 801027 k 1117 ltrs Amend 3 changes reading of Items 8 A, BH, B K, 6 F, 7 F & B F & Conditions 12 & 20 re use of licensed matl. DELMEDICO, J Licensing Management Branch 80/12/05 2pp. 20797 IBI.
- ---8101090109 Matl/Byproduct License 37-18467-01MD for Pharmaco Nuclear, Inc is amended per 801028 ltr Amend 4 changes reading of Items 8 A & 9 A & Condition 23 re distribution, possession & USE. DELMEDICO.J Licensing Management Branch 80/12/03 ip.
- --8103060697 Metl/Byproduct License 35-19583-OIMD for Pharmatopes, Inc authorizes use of Mo-99, Cs-137, Co-60, Ba-133, I-125 & Xe-133 for medical purposes & instrument calibr DELMEDICO, J. Licensing Management Branch 81/02/03 App 20797 063

- ---BiO3180096 Matl/Byproduct License 13-19451-01MD for Pharmatopes, Inc. is amended per BiO120 itr Amend i authorites MT Rebner. MM Fu.CE Palmer.CR Blaum, DM Donahue or BC Blaum as usert of licensed matl
 DELMEDICO.J Licensing Management Branch 81/02/20 ip 20797 241
- --BIO4170659 Mati/Byproduct License i2-i9333-0iMD for Pharmatopes, Inc is amended per 800524 & 810216 ltrs Amend 4 changes reading of Condition 12 re use of licensed mati DELMEDICO. J. Licensing Management Branch 81/03/18 ip 20707 2018 20797 225
- --9104170666 Nati/Byproduct License 34-19007-01MD for Pharmatopes: Inc is amended per Amend 3 changing reading of Condition 12 re use of licensed mat! DELMEDICO.J Licensing Management Branch 81/03/18 ip 103
- --B104210028 Mat1/Byproduct License 12-1933-01HD for Phamatopes, Inc. is amended per 810120 ltr Amend 3 authorizes users of licensed mat1 & requires physical presence of one user at place of DELMEDICO.J M Licensing Management Branch 81/02/24 ip
- --8310170132 Amend 15 to Matl/Byproduct License 34-16654-01MD, authorizing use of Mo-99, Xe-133, I-131, Tc-99m for redistribution of generators to authorized recipients, per 821217 application DELMEDICG, J. Licensing Management Branch 83/04/28 7pp 20797 008 20797 008
- --B310170142 Amend 14 to Mati/Byproduct License 34-16654-01MB, revising Condition 12 re users & supervisors of licensed matl.per 821208 ltr.
 VACCA.P Licensing Management Branch 82/12/30 1p 20797 015
- --8310170147 Amend 13 to Mati/Byproduct License 34-16654-01MD, revising Conditions 12 to 23 recusers of licensed mati, per 750711 application to listed ltrs

 BELMEDICO, J. Licensing Management Branch 82/09/21 1p
- --B310170154 Amend 12 to Matl/Byproduct License 34-16694-01MD, revising Condition 12 re users of licensed matl.per B1122B ltr BELMEDICO.J. Licensing Management Branch 82/02/03 1p
- --B310170156 Amend if to Math/Byproduct License 34-16654-01MD, revising Condition 12, re users of licensed math, per 810612 ltr BELMEDICO, J. Licensing Management Branch 81/07/16 Ip
- --B310170160 Amend 10 to Matl/Byproduct License 34-16654-01MD, revising Conditions 12 & 22; authorizing use of licensed matl by MT Hebner-MM Fu & R Irwin & requiring annual survey meter calibriper B00908 ltr DCLMEDICG. J Licensing Management Branch B0/12/08 ip. 20797 019
- --B310170184 Amand 9 to Matl/Buproduct License 34-16654-01MB, authorizing use of Mo-99, Br-113, Cs-137, Co-60, Am-241, I-125 or I-131 & Xe-133 sealed sources for production of Tc-99m pertechnetate & other listed uses, per B00519 ltr
 LAMABTRA, M A Licensing Management Branch, B0/07/03 7pp 2039 000 20797 020
- ---8010170191 Amend 14 to Mati/Byproduct License 21-17189-01MD, authorizing use of Mo-99, Xe-133, I-131, Tc-99m smaled sources for production of Tc-99m pertechnetate & other listed uses, per 821217 application DELMEDICO, J. Licensing Management Branch 83/03/07 7ep 20797, 027
- --B310170194 Amend 16 to Mat1/Byproduct License 21-17189-01MD.revising Condition 24 re possession, use, packaging, labeling & distribution of licensed mat1 in Items 6-B per 630323 1tr DELMEDICO, J Licensing Management Branch 83/04/22 19 20797 034
- --B3:0170196 Amend 15 to Mat1/Bygroduct License 21-17:B7-01MD; revising Condition 12 Arra users of licensed mat1.per B30214 ltr DELMEDICD. J Licensing Management Branch B3/03/12 lp 20797 035
- --8310170202 Amend 10 to Matl/Byproduct License 45-17769-01MD, authorizing use of Ho-99, Xe-133.1-131 k Tc-99m seeled sources for production of Tc-99m pertechnetate & redistribution to general & specific licensees.per 82:123 application DELMEDICO, J. Licensing Management Branch. B3/03/07. 7pp 20797.036

- --8310170205 Amend 11 to Matl/Byproduct License 45-17769-01MD, revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl described in Items 6-8, per 830324 ltr
 DELMEDICG, J Licensing Management Branch 83/04/15 1p 20.797 047
- --B31017020B Amend 12 to Matl/Byproduct License 45-17769-01MD, revising Condition 24 re possession.use, packaging, labeling & distribution of licensed matl in Items 6-8, per 830427 ltr DELMEDICG, J Licensing Management Branch 83/06/07 ip
- --8310170210 Amend 4 to Mat1/Byproduct License 34-18309-01MD, author(11) use of No-99, Co-60, Ba-133, Cs-137, Xe-133, I-131 & Tc-99m sealed sources for production of Tc-99m pertechnetate per 810910 itr DELMEDICO, J Licensing Management Branch 20797 045 82/02/09 700
- --B310170213 Amend 5 to Mat1/Byproduct License 34-18309-01MD, revising Condition 12 re users of licensed mati, per B20309 ltr DELMEDICOJ Licensing Management Branch B2/03/26 ip
- Conditions 10 & 23 re place of use & possession, use of packaging, labeling & distribution of licensed matl in Items 6-B, per 781005 application ST MARY, FA Licensing Management Branch 82/06/02 20797 053 --B310170217 Amend 6 to Matl/Byproduct License 34-18309-01MD, revising
- --8310170220 Amend 7 to Mat1/Byproduct License 34-18309-01HD, revising Condition 12, re users of licensed mat1, per 820802 ltr 8ELMEDICD. J Licensing Management Branch 82/09/03 ip 20797 054
- --B310170223 Amend B to Matl/Byproduct License 34-18309-01MD, revising Condition 12 re users of licensed matl, per 821217 ltr DELMEDICO, J Licensing Management Brench 83/01/13 ip
- --83:0170226 Amend 1 to Mat1/Byproduct License 45-18378-01MD, mytheriting use of Mo-99,(s-137.Ca-60.Ba-133.I-125 & Xe-133 sealed sources for production of Tc-99m pertechnetate,per 791002 VACCA.P C Licensing Management Branch 79/12/14 6pp 20797 056
- --8310170231 Amend 2 to Matl/Byproduct License 49-18378-DIMD, adding U _ 35 encased in stainless steel as shielding of Mo-99/Tc-99m generators & amending Condition 23 re possession & use, per 800519 ltr Licensing Management Branch 80/08/07 1p 20797 062
- --8310170241 Amend 1 to Matl/Byproduct Licenso 34--1908-01MD, adding 91 agdepleted U-235, as shielding for Mo-97/Tc-99m generators & amending Condition 24 re possession & use.per 800519 ltr. VACCA.P C Licensing Management Branch 80/06/26 ip 20797 075
- --B310170245 Amend 2 to Mat1/Byproduct License 34-19008-01MD, revising Condition 12 re users of licensed mat1 & authorizing R Irwin as radiation safety officer, per 801022 application DELMEDICO J Licensing Management Branch. 80/10/30 1p 20797 076
- --8310170250 Amend 3 to Mati/Byproduct License 34-1908-0iMD, revising Condition 12, re users of licensed matl & designating HC Wilson as radiation safety officer, per 801022 application DELMEDICO.J Licensing Management Branch 80/12/03 lp 20797 077
- --9310170256 Amend 4 to Matl/Byproduct License 34-19008-01MD revising Conditions 12 & 24 re users of licensed matl & possession & use of licensed matl in Items 6-8 per 810302 Itr VACCA.P. Licensing Management Branch 81/03/31 ip 20797 078
- --8310170267 Amend 4 to Matl/Byproduct License 34-19007-01HD, revising Condition 12, re users of licensed matl.per 810415 ltr DELMEDICO.J Licensing Management Branch. 81/06/18 ip 20797 079
- --83:0170274 Amend 5 to Matl/Byproduct License 34-19007-01MD, revising Condition 12, re users of licensed matl, per 820309 ltr DELMEDICO, J Licensing Management Branch. 82/03/26 ip 20797 080

- --8310170277 Amend 6 to Matl/Byproduct License 34-19007-01MD, revising Condition 12, revisers of licensed matl.per 821217 ltr DELMEDICO. J Licensing Management Branch 83/01/14 ip 20797 081
- --B310170279 Matl/Byproduct License 37-21092-01MD for Pharmatopes. Inc. authorizing use of Mo-99/Tc-99m generator, Xe-133, I-131 & Tc-99m for use in production & distribution of Tc-99m partechnetate BELMEDICO, J Licensing Management Branch 82/09/13 7pp 20797 082
- --B310170282 Amend 4 to Matl/Byproduct License 35-19383-01MD, adding use of any sealed source matl per 10CFR35 14 for instrument callbr & changing Conditions 12 & 24 re users, possession & distribution.per B21210 ltr
 DELMEDICO, J Licensing Management Branch 93/01/t1 2pp 20797 099
- --B3101702B6 Amend 5 to Mati/Byproduct License 35-19583-OIMD, revising Condition 24 re possession, use, packaging, labeling & distribution of licensed matl & deleting Condition 25, per B30105 ltr
 DELMEDICG, J Licensing Management Branch G3/01/27 ip
- --8310170290 Amend 1 to Matl/Byproduct License 35-19583-OIMD, revising Condition 12, re users of licensed matl & adding Condition 25 re onsite audits, per 810218 ltr
 DELMEDICO, J. Licensing Management Branch 81/04/01 ip
- --B310170293 Amend 2 to Mat1/Byproduct License 33-19583-OIMD revising Condition 25 re possession, use packaging Labeling & distribution of licensed matl described in Items 6-8, per 810706 ltr
 DELHEDICO, J Licensing Management Branch 81/08/12 ip 20797 093
- --8310170297 Amend 3 to Matl/Byproduct License 35-19583-QIMD, revising Condition 12, revisers of licensed matl, per 920610 ltr DELMEDICO, J. Licensing Management Branch 82/08/27 1p
- --8310170316 Amend 3 to Matl/Byproduct License 45-18378-QiMD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl described in Items 6-8 & adding Conditions 24 & 25, per 800201 ltr BELMEDICO, J Licensing Management Branch 81/03/05 ip 20797 104
- --B310170320 Amend 4 to Mat1/Byproduct License 45-18378-01MD, revising Condition 12, re users of licensed mat1
 DELMEDICO, J Licensing Management Branch 81/08/31 ip 20797 105
- --B310170324 Amend 5 to Matl/Byproduct License 45-18378-01MD, revising Condition 12 re users of licensed matl.per 830118 ltr
 DELHEDICO, J Licensing Management Branch 83/02/09 ip.
 20797 106
- --B310170331 Amend 6 to Matl/Byproduct License 45-18378-01MD, revising Condition 23 re-passession, use, packaging, labeling & distribution of licensed matl & changing licensee name from Pharmatopes, Inc to Byncor Corp. per 830427 ltr
 DELNEDICO, J Licensing Management Branch 83/06/07 ip
- --B310170345 Amend i to Matl/Byproduct License 34-18484-01MD, revising Condition 12, re users of licensed matl & Condition 24 repossession & use of matl.per 791226 ltr
 VACCA.P., Licensing Management Branch B0/02/28 ip 20797 114
- --8310170350 Amend 2 to Matl/Byproduct License 34-18484-0iMD,adding U-235 cadmium plated metal as shielding in linear accelerator & revising Condition 24 re possession & use.per 800519 ltr VACCA.P.C Licensing Management Branch 80/06/25 ip 20797 115
- --B310170384 Amend 3 to Mat1/Byproduct License 34-18484-01MD, revising Condition 12:re users of licensed mat1.per B10907 ltr DELMEDICD. J Licensing Management Branch 81/10/14 ip 20797 116
- --8310170359 Amend 4 to Mat1/Byproduct License 34-18484-0iMD, revising Condition 12, re-users of licensed mat1, per 830128 | tr. BELMEDICO, J Licensing Management Branch 83/02/22 ip 20797 ii7

- --B310170363 Amend 1 to Matl/Byproduct License 37-21092-01MD, revising Condition 12, re-users of licensed matl.per 830303 ltr DELMEDICO, J Licensing Management Branch 83/03/22 ip 20797 118
- --8310170367 Amend 2 to Matl/Byproduct License 37-21092-01MD, revising Condition 22 re possession, use, packaging, labeling & distribution of licensed matl & changing licensee name from Pharmatopes, loc to Syncor Corp, per 830427 ltr
 DELMEDICO, J. Licensing Management Branch 83/05/07 lp
- --B310170372 Amend 14 to Matl/Byproduct License 34-16405-01MD, revising Condition 12, re users of licensed matl, per 810316 ltr DELMEDICO, J Licensing Hanagement Branch 81/05/26 1p 20797 120
- --8310170074 Amend 15 to Mati/Byproduct License 34-14405-01MD, revising Condition 12, re-users of licensed matl, per 811019 ltr DELMEDICO, J. Licensing Management Branch 81/11/13 lp 20797 121
- ---B310170381 Amend 16 to Matl/Byproduct License 34-16405-01MD, adding 150 mCi of 100fR35 14 sealed source byproduct matl for redistribution to authorized recipients & revising Condition 22 re possession & was, per 820312 1tr DELMEDICD, J Licensing Management Branch 82/04/13 1p
- --8310170385 Amend 17 to Matl/Byproduct License 34-i6405-01MD, adding Condition 23 allowing licenses to use Calicheck device for linearity test of fose calibrator.per BII210 ltr DELMEDICO.J Licensing Management Branch 82/04/19 ip
- --8310170388 Amend 18 to Matl/Byproduct License 34-16403-01MD,changing licensee name from Pharmaco Nuclear,Inc to Pharmatopes,Inc (Corrected copy) DELMEDICO, J. Licensing Management Branch. 83/03/28 1p
- --B310170399 Amend 12 to Metl/Byproduct License 34-16405-01MD, authorizing use of Mo-99, Bn-113.Cs-137, I-125, I-131 & Xe-133 for production of Tc-99m pertechnetate, In-113m chloride & instrument calibr.per 791227 ltr
 VACCA,P.C Licensing Management Branch B0/01/24 7pp
 20797 125
- --B310170403 Amend iS to Matl/Byproduct License 34-16405-01MD, chan licensee name from Pharmaco Nuclear, Inc to Pharmatopes: Inc. per B2120B ltr DELMEDICO, J. Licensing Management Branch 83/01/31. 19.
- --B310170425 Amend 1 to Matl/Byproduct License 37-18467-01MD, addi Xe-133 gas solution for distribution to authorized recipients, per 791101 ltr. VACCA, P C Licensing Management Branch 79/12/20 2pp. 20797 139
- --B310170433 Amend 5 to Matl/Byproduct License 37-18467-01MD, rev Condition 23 re possession, use, packaging, labeling & distribution of licensed matl.per B10117 ltr DELMEDICO, J Licensing Management Branch B1/07/15 ip 20797 144
- --B3i0170437 Amend & to Matl/Byproduct License 37-18467-01MD.r/
 Bubitems B I & 7 A re production of Tc-99m pertechnetate &
 Condition 23 re possession.use.labeling & distribution of
 licensed matl.per B10928 ltr
 DELMEDICO, J Licensing Management Branch. B1/10/23 1p
 20797 145
- --B310170441 Amend 7 to Mati/Byproduct License 37-IB467-01MD Condition 12.re users of licensed mat1.per 811019 ltr DELMEDICO.J Licensing Management Branch 81/11/03 1 20797 146
- --8310170447 Mat1/Byproduct License 21-21141-01MD for Pharma authorizing use of Mo-99, Xe-13G, J-131 & Tc-99m for production of Tc-99m pertechnetate & distribution of generators to authorized recipients, per 820720 applicati BELMEDICO, J Licensing Management Branch. 82/10/06. 7 90797 147
- --8310170449 Amend 1 to Meti/Suproduct License 21-21141-01MD Condition 22 re possession, userpackaging, labeling & distribution of license mati.per 821217 ltr DELMEDICO, J Licensing Management Branch 82/01/14. 1 20797 154

- --8310170453 Amend B to Mat1/Byproduct License 37-18467-01MD, adding 150 mC1 byproduct, source & SNM sealed sources for redistribution to authorized recipients & revising Condition 23 re possession & veeper ESGG15 ltr DELMEDICO, J Licensing Management Branch 82/04/13 ip 2077 155
- --8310170455 Amend 9 to Mat1/Byproduct License 37-18467-01MD, revising Condition 12, re users of licensed mat1, per 820510 ltr DELMEDICGLJ Licensing Management Branch 82/06/18 ip
- --B310170460 Amend 10 to Matl/Byproduct License 37-18467-01MD, changing name of licensee from Pharmaco Nuclear, Inc to Pharmatopes, Inc.per 821110 ltr
 DELMEDICO, J. Licensing Management Branch 82/12/09 1p
 20797 157
- --B310170462 Amend 11 to Mat1/Dyproduct License 37-18447-01MD, revising Condition 23 re-possession, use-packaging, labeling & distribution of licensed mat1, per 621129 ltr * Licensing Management Branch 62/01/14 ip 20797 158
- --8310170467 Amend 1 to Mati/Byproduct License 24-19360-01MD, revising Conditions 12 & 23, re users of licensed mati & possession & use, per 801021 ltr
 DELMEDICO, J Licensing Management Branch 80/12/09 ip 20797 167
- --8310170472 Amend 3 to Matl/Byproduct License 24-19350-01MD revising
 Item 9 re authorized use & Condition 12 re users of licensed
 matl.per 810115 & 0510 ltrs
 BELHEDICO J Licensing Management Branck 81/05/26 ip
 20797 169
- --B310170475 Amend 3 to Mati/Byproduct License 24-19360-01HD, revising Item 9 re authorized use & Conditions 12 & 23 re users & pussession & use of licensed meth.ger 8:01:5 & 04:0 itrs DELMEDICO. J. Licensing Management Branch 8:/09/01 2pp 20702-170.
- --B310170477 Amend 4 to Matl/Byproduct License 24-19360-0:MD revising Condition 12 re users of licensed matl.per 820510 ltr DELHEDICO.J Licensing Hanagement Branch 82/06/02 1p
- --B3101704B2 Amend 5 to Matl/Dyproduct License 24-17360-QIMD, revising Condition 23 re-possession, use, packaging labeling & distribution of licensed matl & changing licensee name from Pharmaco Nuclear, Inc to Syncor Corp.per 830427 ltr BELMEDICD J Licensing Management Branch. 83/04/07 ip 20797 173
- --B310170487 Mat1/Byproduct License 08-18308-0180 for Pharmatopes, Inc. authorizing use of Mo-99, Cs-137, Co-60, Br-133, I-125, I-131 & Xe-133 for production of Tc-99m pertechnetate, per 781005 application to 781127 ltr VACCA, P.C. Licensing Management Branch 78/12/12 5pp 20797 174
- --8310170474 Amend 4 to Mat1/Byproduct License 08-18308-01HD revising Conditions 12 & 20 re users of licensed mat1 & possession & user per BIO626 ltr DELMEDICO.J Licensing Management Branch 81/07/17 ip 20797 183
- --8310170497 Amend 5 to Matl/Byproduct License 08-18308-01MD revising Condition 12 re-users of licensed meth, per 810630 ltr
 DELMEDICO.J Licensing Management Branch 81/08/07 ip 90797 184.
- --8310170502 Amend & to Mati/Byproduct License 08-18308-01MD, revising Condition 12, re-users of licensed mati, per 820118 ltr.
 DELMEDICD, J Licensing Hanagement Branch. 82/02/03 ip 20797 185.
- --BB10170505 Amend 7 to Mat1/Byproduct License OB-18308-01MD.revising Conditions 12 & 20.re users of licensed mat1 & possession & user par 920204 ltr.

 DELMEDICO, J Licensing Management Branch 82/03/12 Ip 20797.184
- --8310170510 Amend 2 to Mat1/Byproduct License 13-19229-01MD, authorizing use of Co-60, Ba-133, Cs-137, I-131 for production of Yc-99m pertechnetate, per 791128 application & 800519 ltr DELMEDICO, J. Licensing Management Branch 81/11/24, 7pp. 20797:187

- ---8310170516 Amend 4 to Matl/Byproduct License 21-19219-01MD, revising Condition 12 re users of licensed matl, per 820331 ltr BELMEDICO. J Licensing Management Branch 82/06/02 lp 20797 200
- --8310170521 Amend 3 to Mati/Byproduct License 21-19219-01MD, revising Condition 12, relaters of licensed mati.per 820601 ltr DELMEDICO, J. Licensing Management Branch 82/02/05 ip 20797 203
- --8310170527 Amend 1 to Mat1/Byproduct License 06-19661-01MD, authorigar; use of Mo-99, Co-60, Ba-133, Cs-137, I-131 & Tc-99m for production of Tc-99m pertechnetate, per 810612 ltr DELMEDICO, J Licensing Management Branch 81/07/17 7pp 20797 204
- --B310170528 Amend 2 to Matl/Byproduct License 06-19661-01MD, revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl.per 810715 ltr DELMEDICO, J Licensing Management Branch 81/08/11 lp 20797 211
- --B3i0170332 Amend 3 to Matl/Byproduct License 06-19661-01MD.revising Condition 12,re users of licensed matl,per 811215 ltr DELMEDICO.J Licensing Management Branch 82/01/22 ip 20797 212
- --8310170939 Amend 5 to Matl/Byproduct License 06-19661-01MD.revising Condition 12,re users of licensed matl,per 830128 ltr DELMEDICO.J Licensing Management Branch 82/02/15 ip 82/02/7 213
- --B310170537 Amend 7 to Matl/Byproduct License 06-19661-01MD.reviting Candition 23 re possession.use.packaging.labeling & distribution of licensed matl.per 820318 ltr # Licensing Hanagement Branch 82/04/07 lp 20797 214
- --8310k70946 Amend 1 to Matl/Byproduct License 12-19333-0iHD.adding U depleted in U-235, as metal encased in stainless storl as shielding for Mo-99/fc-99m generators, per 800518 & 24 lirs UACCA.P C Licensing Management Branch 80/07/24 Spp 20797 216
- --8310170570 Amend 5 to Matl/Byproduct License 12-1933-01MP, revising Conditions 12 & 23 re users of licensed matl & possession & use, per 810414 ltr
 DELMEDICO, J Licensing Management Branch 81/07/20 ip 20797 226
- --B310170574 Amend 6 to Matl/Byproduct License 12-19333-01MD.revising Condition 12 re users of licensed matl.per 810909 ltr DELMEDICO, J Licensing Management Branch 81/10/15 ib 20797 227
- --B310170578 Amend 7 to Matl/Byproduct License 12-17333-01HD, revising Item 8 A to read 65 Ci.per undated itr received 820222 DELMEDICO.J Licensing Management Branch 82/06/03 | p 20797 228
- ---B310170580 Amend 8 to Matl/Byproduct License 12~19330-01MD.revtelrp Condition 12 re users of licensed matl.per B20602 itr DELMEDICO J Licensing Management Branch. 82/06/04 1p
- --8310170385 Amend 9 to Matl/Dyproduct License 12-19303-01MD, revealn*
 Subitem 8 F to read 2 5 C1 & adding Condition 24 re fume
 hood airflow rating.per 811204 ltr
 DELMEDICO.J Licensing Management Branch 82/06/24 ip
 90797 230
- --B3101709B7 Amend 10 to Matl/Byproduct License 12-1933G-01MD. review, Condition 12 re users of licensed matl.per 820707 ltr
 DELMEDICO, J. Licensing Management Branch 82/08/13 ip 20797 231
- --BSk0170590 Amend it to Matl/Byproduct License 12-19333-01MD.revietr; Confition 12 re users of licensed matl.per 820723 ltr BELMEDICG-J Licensing Management Branch 82/08/26 ip 20797 232
- --B310170593 Amend 12 to Hatl/Byproduct License 12-19333-01MD, revising Condition 12 re users of licensed matl, per 820602 ltr DELMEDICG. J. Licensing Management Branch. 82/10/01 lp 20797:233
- --8310170615 Amend 2 to Matl/Byproduct License 13-17451-01HD. revailing Condition 12 re users of licensed matl.per 810328 ltr DELMEDICO.J Licensing Management Branch 81/04/20 lp. 20797 242

- --8310170618 Amend 3 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl.per 810812 ltr DELMEDICO, J Licensing Management Branch 81/09/24 [p 20797 243
- --B3[0]70625 Amend 4 to Matl/Byproduct License 13-19451-0]HD, revising Condition 12 re users of licensed matl.per 810909 ltr
 DELMEDICD J Licensing Management Branch 81/10/14 lp 20/97 244
- --B310170628 Amend 5 to Matl/Byproduct License 13-19451-01MD, revising Condition 24 re possession & use of licensed matl.per B11218 itr DELMEDICO. J Licensing Management Branch B2/01/19 1p 20797 245
- ~~8310170435 Amend & to Matl/Byproduct License i3-19451-01MD, revising Condition 12 re users of licensed math, per 820518 telegram VACCA.P C Licensing Management Branch 82/05/19 ip 20797 246
- --8310170637 Amend 8 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl.per 820727 ltr DELMEDICO. J Licensing Management Branch 82/08/30 ip 20797 247
- --8310170640 Amend 8 to Matl/Byproduct License 13-19451-01MD, revising Condition 12 re users of licensed matl.per 830406 ltr DELMEDICO, J Licensing Management Branch 83/05/16 ip
- --9310170545 Amend 7 to Matl/Bygraduct License 13-19431-01MD, revising Condition 12 re users of licensed matl.per 820730 telegram DELMEDICO.J Licensing Management Branch 82/08/02 ip 20797 249
- --8310170650 Matl/Byproduct License 29-19608-01MD for Pharmatopes, Inc authorizing use of Mo-99, Co-60, Ba-133, Cs-137, I-125, Xe-133, I-131 & Tc-99m for various uses, per B01202 application DELHEDICO. J Licensing Management Branch 81/05/21 7pp 20797 250
- --8310170652 Amend 2 to Mati/Byproduct License 29-19608-01MD, changing expiration date to 860531 & revising Conditions 10 & 24 replace of use & possession, use, packaging, labeling & distribution of licensed mati, per 810225 ltr

 BELMEDICO. J Licensing Management Branch 81/05/28 ip 20707 257
- --8310170660 Amend 2 to Matl/Byproduct License 29-19608-01MD changing expiration date to 860531 & revising Conditions 10,12 & 24 re place of use users & possession & use of licensed matl, respectively, per 810225 ltr (Corrected copy)
 DELMEDICO. J Licensing Management Branch 81/07/28 ip
- --8310170665 Amend 3 to Matl/Byproduct License 29-19608-01MD, changing licensee address & revising Conditions 10 & 24 re place of use & possession, use, packaging, labeling & distribution of licensed matl, per 810804 ltr
 DELMEDICO, J Licensing Management Branch 81/09/02 1p 20797 237
- ~-8310170668 Amend 4 to Matl/Byproduct License 29-19608-01MD, revising Condition 12 re users of licensed matl.par 810825 ltr.
 BELHEDIOC, J Licensing Management Branch, 81/10/20 ip
- --8310170673 Amend 5 to Matl/Byproduct License 29-17608-01MD, revising Condition 12 re users of licensed matl.per 820713 ltr PELMEDICO, J. Licensing Management Branch 82/08/16 ip. 20797 2641
- --8310170475 Amend 6 to Matl/Byproduct License 29-17608-DIMD, revising Conditions 12 & R4 re users of licensed matl & possession, use, packaging, labeling & distribution, per 821208 ltr DELMEDICO, J Licensing Management Branch 83/03/23 lp 20797 262
- --B310170677 Amend 7 to Matl/Byproduct License 29-19608-01MD, changing licenses name from Pharmatopes, Inc to Syncor Corp & revising Condition 24 re possession, uses packaging, labeling & distribution of licensed matl.per 803027 ltr * Licensing Management Branch 83/06/07 lp. 20797, 263
- --8310170681 Amend 16 to Matl/Byproduct License 24-16617-01MD authorizing use of Mo-99, Xe-133, I-131, Tc-97m for production of Tc-97m pertechnetate & other uses, per 821221 application DELMEDICO, U Licensing Hanagement Branch 83/04/25 7pp 20797-264

- --8310170484 Amend 17 to Mat1/Byproduct License 24-14617-01MD revising Condition 23 re possession, use, packaging, labeling & distribution of licensed matl & changing licensee name to Syncor Corp. per 830427 ltr
 DELMEDICO.J Licensing Management Branch B3/06/07 ip 20797 271
- 8310170101 FOIA request for copies of active licenses issued by NRC to Pharmatopes. Inc or Syncor Corp BERG, J.P. Syncor International 83/05/10 Office of Administration 4pp 20797 004
- B310180531 F01A request for Target Technology.Ltd documents re pipe supports WEIBS,E R Union of Concerned Scientists B3/0B/11 FELTON,J M Division of Rules and Records ip 20825 005 24X Fiche 50-333.83/0B/11.8310180531
- 8310180534 Responds to FDIA request for Target Technology,Ltd documents re-pipe supports Forwards document encl Document also available in PDR FELTON, J M Division of Rules and Records 83/09/06 WEISB,E R Union of Concerned Scientists ip 20825-006 24X Fiche 50-333,83/09/06.8310180534
- --8310180338 Comments on pipe support design noncompliance u/FSAR Summary of 830627 meeting w/S&W re list of 20 unacceptable supports submitted on 830103 discussed DAINURA, J Target Technology Ltd 63/06/30 GUAGUIL, L fower Authority of the State of New York 5pp 20825 007, 24x Fiche 50-333,83/09/06,8310180534
- 8310180556 Responds to FOIA request for names & addresses of past licensees permitted to mfg glazes, paints, dues, enamels, glasses & ceramics W/o encis.
 FELTON, J M Division of Rules and Records 83/09/08 THOMAS, A W Greater Reston Arts Center, Inc. ip 20825 344
- 8310180559 FDIA request for names & addresses of past licensees permitted to mfg glazes,paints,dues,enamels,glasses & ceramics
 THOMAS.A W Greater Reston Arts Center, Inc. 83/08/20 NRC No Detailed Affiliation Given 1p 20825 345
- 83:0180366 F0IA request for name, title, phone number & address of all individuals directly in charge of maint activities on NRC computer equipment/sys using disk drives &/or dot matr; printers BIMPSON.R O Granada Data Bystoms, Inc 83/08/16 Office of Administration in 20825 341
- 8310180571 Responds to FDIA request for name, title, phone number & address of all individuals directly in charge of maint activity on NRC computer equipment/sqs using disk drives &/ or dot matrix printers List furnishing info encl FELTON, J M Division of Rules and Records 83/09/06 BIMPSON, R D Granada Data Systems, Inc. 1p 20825 342
- --8310180575 List of all NRC individuals directly in charge of maint activity on NRC computer equipment/sys using disk drives &/or dot matrix printers
 NRC No Dytailed Affiliation Given 83/09/06 ip 20825 343
- 9310180582 FDIA request for VS Noonan 830426 memo to BJ Youngblood re add1 info needed by Equipment Gualification Branch to complete review of environ qualification of mechanical equipment PEDRO.U. NUS Corp GD-IS-83-265 83/08/17 Division of Rules and Records ip 20817-329 24X Fiche 50-445.83/08/17.8310180582
- 8310180596 FOIA request for util corporate chart in PBAR CONSTABL J Pro-Tech Support Services Inc. 83/08/17 Office of Administration 1p 20825-323 24% Fiche 50-508,83/08/17. 8310180586
- B310180588 Responds to FDIA request for VS Noonan B30426 memo re add1 info needed by Equipment Qualification Branch to complete review of environ qualification of mechanical equipment Forwards document. FELTON, J M Division of Rules and Records B3/09/06 PEDRO, J. NUS Corp 19 20817, 330 24% Fiche 50-445, 83/09/06, 8310180588
- --B305060124 Forwards request for add1 info necessary to complete review of licensee B30330 info re environ qualification of tafety-releted mechanical equipment located in harsh environ MODRAN, V B Equipment Qualification Branch. 83/04/26 YOUNGBLOOD: B J Licensing Branch 1 2pp 20817 331 24X Fichs 50-445,83/09/06,8310180588

- 8310180590 Responds to FOIA request for util corporate chart in PSAR
- Forwards chart FELTON.J.M Division of Rules and Records 83/09/06 CONSTAS.J Pro-Tech Support Services.Inc 1p 20825.324 24X Fiche 50-508.83/09/06.8310180590
- B310180575 FOIA request for all documents & records re radiation surveys of Makepeace.Inc SULLIVAN.J W Affiliation Unknown. 83/08/30 NDRRY.P G Dffice of Administration ip 20825-336
- --B310180602 FOIA request for all records re radiation contamination surveys of DE Makepeace.Div of Engelhard Industries BULIVAN, J W Affiliation Unknown 83/08/30 CROCKER, H Region 1, Office of Director 2pp 20825 337 Office of Director 2pp
- 8310180597 FOIA request for list of mods to containment undertaken by util in response to NUREO-0487 MAFNER.B Suffolk Nuclear Study Group 83/04/25 Office of Administration ip 20827 124 24X Fiche 50-322,83/04/25.
- 8310180600 Responds to FOIA request for info re mods to containment undertaken by util Info contained in Rev 5 to Plant Besign Assessment Rept Util not required to rept changes but must comply w/acceptance criteria in Rev 5 FELTON, J M Division of Rules and Records 83/09/06 HAFNER, I Suffalk Nuclear Study Group ip 20827 125 24X Fiche: 50-322,83/09/06.8310180600
- 8310180403 Responds to FOIA request for all documents re Makepeace, Inc or Englehard, Inc Info available in PDR FELTON, J M Division of Rules and Records 83/09/04 SULLIVAN, J W Affiliation Unknown ip 20825 340
- 8310180409 FOIA request for complete set of BNL repts an seismic design of facilities
 CALEGYAS.C D Affiliation Unknown 83/08/16 Region 5. Office of
 Director 4pp 20824 315 24X Fiche 50-275,83/08/16,8310180609
- B310180610 Responds to FOIA request for complete set of BNL repts on seismic design of facilities Documents listed in app available in PDR
 FELTON.J M Division of Rules and Records 83/09/01 CALBOYAS.C Affiliation Unknown 2pp R0824 319 24X Fiche 50-275,83/09/01. CALBOYAS, C D Affiliation Unknown 8310180610
- --8310180613 Summary & evaluation rept of RL Cloud & Assoc rept, "Diable Canyon Unit 1 IDVP Varification Program for P9&E Corrective Action."

 * Brookhaven National Laboratory 83/09/01 4pp 20824 321 24X Fiche 50-275,83/09/01,8310180610
- --8310180615 Summary & evaluation rept of RF Reedy rept, "Development of Syc-Related Contractor List for Nonseismic Design Work Performed for Diablo Canyon Nuclear Power Plant, Unit 1 Prior to 780601. Phase II" # Brookhaven National Laboratory 83/09/01 3pp 20824 325 24X Fiche: 50-275. 83/09/01. 8310180610
- --8310180617 Summary & evaluation rept of RL Cloud & Assoc rept, "Diable Canyon Unit 1 IDVP Verification of Design Analysis Hospri Spectra."

 * Brookhaven National Laboratory 83/09/01 3pp 20824 328 24X Fiche 50-275,83/09/01,8310180610.
- --8310180619 Summary & evaluation rept of RL Cloud & Assoc rept "Diablo Campon Unit | IDVP Soils Intake Structure " * Brookhaven National Laboratory 83/09/01 3pp 20824 391 24% Fiche 30-275.83/09/01.8310180610
- --B3101B0621 Bummary & evaluation rept of RL Cloud & Assoc rept, "Diable Canyon Unit 1 IDVP Boil Gutdoor Water Storage Tenks "

 * Brookhaven National Laboratory B3/09/01 3pp 20824 334
 24X Fichs 50-278,83/09/01,8310180610.
- --8310180624 Summary & evaluation rept of RL Cloud & Assoc rept, "Diable Conyon Unit 1 IDVP HVAC Components,"

 + Brookhaven National Laboratory. 83/09/01 5pg 20824.343
 24% Fiche: 30-275,83/09/01,8310180610.
- --- 8310180626 Summary & evaluation rept of RL Cloud & Assoc rept. "IBVP Valves, * Brookhaven National Laboratory. (24X Fiche: 50-275, 83/09/01, 83/0180610 83/09/01 4pp 20824:348

- ---B310180627 Summary & evaluation rept of RL Cloud & Assoc rept, "IDVP -HVAC Duct & Bupports Rept " * Brookhaven National Laboratory B3/09/01 5pp 20824 352 24% Fiche 50-275.83/09/01,8310180610
- B310180618 FOIA request for documents submitted by util for consideration of candidats companies or methodologies to perform const implementation overview of const completion plan GARDE, B P Dovernment Accountability Project 83/08/05 Off of Administration 2pp 20839 110 24X Fiche 50-329, 83/08/05, 8310180648 Office
- 8310180625 Responds to FOIA request for records submitted by util & reviewed during consideration of candidate companies or methodologies re const implementation overview Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/09/01 GARDE, B P Government Accountability Project 3pp 20837 112 24X Fiche 50~327,83/09/01.8310180625
- --8210280450 Forwards util 821005 three-part independent review program, consisting of biennial quality audits. INPD-type const evaluation & independent design verification of auxiliary feedwater sys Meeting scheduled for 821019 to discuss plan NGVAK.T M Assistant Director for Licensing 82/10/07 VULLMER.R H Division of Engineering 1p 20839 124 24X Fiche 50-329,83/09/01.8310180425
- --8212300076 Documents conclusions reached at 821207 meeting in Bethesda, MD re 0A implementation at facility Region 3 insp of diesel generator bldg & util decision to stop certain safety-related work being performed by Occhtel
 HERNAN,R W Licensing Branch 4 82/12/21 NOVAK,Y M Assistant Director for Licensing 3pp 20839 128 24X
 Fiche 50-327,83/09/01.8310180625
- --831018062B Forwards util 820512 response to Interrogatory IV re Contention 8 on independent design audit * NRC No Detailed Affiliation Given 82/10/01 NRC No Detailed Affiliation Given 1p 20837 115 24X Fiche 50-329,83/09/01.8310180625 NRC - Na
- --0310180629 Response to Interrogatory IV re Contention 8 on independent design audit * Consumers Power Co 82/05/12 Stamiris, B 8pp 20839 116 24% Fiche 50-329,83/09/01,8310180625
- --B310180630 Forwards util revised plan for const completion Programicalludes measures to be taken as result of work slowdown & elements of GA implementation & third-party assessments elements of GA implementation & third-party assessments requested by NRC W/o enci HeRNAN.R Division of Licensing 83/01/12 ADEMSAM.E NRC - No Detailed Affiliation Given ip 20839 128 24X Fiche 30-329.83/09/01.8310180625
- ---8310190034 Rev 1 to Quality Control Instruction 10 01, "Const Implementation Overview Assessment " THOMPSON.J C Stone t Webster Engineering Corp 83/06/27 App 20839:134 24X Firms 50-329.83/09/01.8310180625
- --B310190036 Rev Q to Verification Attribute Checklist P-2 20V, "Pipe Supports "
 BARANOW, S W Stone & Webster Engineering Corp 83/07/21 10pp
 20837 140 24X Fiche 50-327.83/07/01.8310180625
- ~-8310190038 Rev 1 to third-party const implementation gverview approval KELLY:R B Stone & Webster Engineering Corp 83/08/05 5pp 20839 150 24X Fiche 50-329:83/09/01:8310180625
- --B3i0170042 Rev 1 to Quality Control Instruction ib 01. "Nonconformance Identification & Reporting "
 BARAMORE.8 Stone & Webster Engineering Corp 89/08/05 5pp
 20839 155 24% Fiche 50-329,83/09/01,8310180625
- --8310190047 Rev 1 for third-party const implementation overview re GA plan BARAMDRE, S., WALTERS, C., KELLY, R. B. Stone & Webster Engineering Corp., 83/08/05 4pp 20839 160 24X Fiche 50-329, 83/09/01, 8310180625
- 8310190035 FDIA request for AEC Rept TID-2021. "Some Aspects of Stored Energy in Irradiated Graphite, Part II. Storage of Energy in Graphite on Irradiation" AFTERGOOD, S. Committee to Bridge the Gap. 83/08/26. Office of Administration 1p. 20837-164

- 8310190041 Responds to FOIA request for AEC Rept TID-2021, "Some Aspects of Stored Energy in Irradiated Graphite.Part II. Storage of Energy on Irradiation" NRC does not possess decument Rept may be obtained from Oak Ridge TN FELTON.JM Division of Rules and Records E3/09/13 AFTERQUED.S Committee to Bridge the Oap 1p 20039 165
- 8310190046 FDIA request to place SECY-83-183, SECY-83-195, SECY-83-269 % SECY-83-342 in PDR BUCKLES, R NUS Corp CD-18-83-253 83/08/15 Division of Roles and Records 1p 20838 272
- 8310190049 Responds to FDIA request Forwards documents Documents also available in PDR FELTON.JM Division of Rules and Records 03/09/13 BUCKLES.R NUS Corp 19 20036 273
- --8307220156 SECY-83-269
 Provides rept on fire protection rule for future plants
 (SECY-82-267), summarizing licenses fire protection exemption
 requests disposition of requests & generic issues raised by
 requests
 DIRCKS.W J Office of the Executive Director for Operations
 83/07/05 52pp 20838 297
- --8310190053 SECY-83-103
 Informs of first integrated schedule amend for implementing new & existing requirements at operating plants Action represents first step towards developing industry-wide approach for establishing realistic schedules
 DIRCKG.W J Office of the Executive Director for Operations 83/05/13 23pp 20038 274
- 8310170039 FOIA request for info on effects of sabotage on PWRs & BWRs & fault tree analyses SHOLLY,8 C Union of Concerned Scientists 03/07/20 FELTON.J M Division of Rules and Records ip 20039.077
- B310190062 Responds to FOIA request for info on effects of sabotage on PHRs & PARs & fault tree analyses forwards documents NUREG/CR-3268 will be issued in 2 months Remaining requested items not found in PDR FELTON, J M Division of Rules and Records 03/09/12 SHOLLY, 8 C Union of Concerned Scientists 1p 20039, 070
- BBIG1900BB FOIA request for RA Udell & R Alvarez 820422 ltr to Commissioner Palladino & R Denton 820403 response PEDRO J NUS Corp CD-IS-63-279 83/08/22 Division of Rules and Records ip 20838 178
- 8310190093 Responds to FOIA request for RA Udell & R Alvarer 820422 ltr to Chairman Palladino & B Denton 820403 response Forwards decuments Documents also available in PDR FELTON, J M Division of Rules and Records, 83/09/07 PEDRO, J NUS Corp. ip. 20838 199
- --B205140137 Forwards English language abstract of Inst fuer Energia und Unweltforschung study, "Secondary Bide Emmissions From Pressurized LWRs for Normal Operation & Belected Accidents "Comments on study submitted DIRCKS.W J Office of the Executive Director for Operations B2/05/07 PALLADING.N Commissioners & pp 20838 203
- --8205140143 "Secondary Loop Releases of LWRs in Normal Operation & in Selected Breakdowns " KOCh T Germany, Federal Republic of 82/05/07 50pp 20878-214
- --8206140401 Responds to B20422 itr transmitting Inst Fuer Energie Und Umweltforchung rapt re steam generator tube problems. Rept reviewed & comments listed in 820507 ltr to Chairman Palladino No new issues presented BENTON. HR Office of Nuclear Reactor Regulation, Director. 82/06/03 UDELL. R A Critical Mess Energy Project. 3pp 20838 200
- --8206140403 Forwards Inst fuer Energie und Umweltforschung rept "Secondary Loup Releases of LWRs in Normal Operation & in Belected Breakdowns " Evidence presented re accident scenarios involving steam generator tubes UDELL:R A Critical Mass Energy Project, 82/04/22 PALLADING,N J Commissioners, 5pp 20838.209
- 8310190300 Appeals denial of FDIA request for documents re caseload forecast panel 830419 meeting on plant const Denial effectively denied bulk of documents requested CARDE,8 P Government Accountability Project 83/08/10 DIRKER,W J Office of the Executive Director for Operations 20, 20840 326 24x Fiche 50-329, 83/08/10, 8310190300

- B310190305 Responds to appeal re denial of FOIA request for documents on caseload forecast panel 830419 meeting on plant const All documents identified subj to request Appeal re T Novak draft itr to JM Cook most DIRCKS.W J Defice of the Executive Director for Operations B3/09/13 GARDE.B P Overnment Accountability Project 1p 20840 328 24% Fiche 50-329,83/09/13.8310190305
- B310190306 FOIA request for comments on NUREQ/CR-1278, "Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications " SHDLLY-9 C Union of Concerned Scientists 83/08/06 FELTON, J M Division of Rules and Records 1p 20840 337
- 8310190309 Responds to FOIA request for comments on NUREO/CR-1278, "Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications "Forwards document Document also available in PDR FELTON, J M Division of Rules and Records 83/09/12 SHOLLY, S Union of Concerned Scientists ip 20840 338
- --8310190313 SANDB2-7054

 "Peer Group Btudy of Draft Handbook for Human Retiability
 Analysis Wiemphasis on Nuclear Power Plant Applications,
 NUREO/CR-1278

 BRUNE,R L. HEINSTEIN,M , FITZWATER,M & Human Performance
 Technologies, inc 83/01/31 229pp 20840 339
- B310190311 FDIA request for documents re caseload forecast panel B30419 masting on plant const.

 OARDE, B P Government Accountability Project B3/07/11 Office of Administration 2pp 20840 329 24X Fiche 50~329, B3/07/11.
- B310190316 Responds to FOIA request for documents re caseload forecast panel B30419 meeting on plant const Info partially withheld JH Cook draft ltr to TM Novak (ref FOIA Exemption 5) FELTON.JM Division of Rules and Records B3/08/09. GARDE.B P Government Accountability Project 6pp 21116 001 24X Fiche 30-329.83/08/09.B310190316
- 8310190318 F01A request for copies of winning proposals issued for RFPs RB-NRR-83-092 & RB-NRR-83-093, "Severe Accident Consequence Mitigation" & "Severe Accident Core/Vessel/Containment Interactions." respectively SIEHART.D Battelle Hemorial Institute, Columbus Laboratories 83/08/24 GRIMSLEY,D Division of Rules and Records 1p 20841 208
- 8310190321 FOIA request for documents re-formulation of Board Notification 83-63 GROBECH, C. L. Citizens for Safe Energy 83/08/22 Office of the General Counsel 2pp 20841 288
- 8310190322 Responds to FOIA request for copies of winning proposals issued for RFPs re severe accident Forwards RFPs RF-NRR-83-092 RFP-RF-NRR-83-092 available in PR FELTON, J M Division of Rules and Records 83/09/13 STEWART, D Battelle Hemorial Institute, Columbus Laboratories ip. 20841 209
- --8310190326 Forwards proposal "Severe Accident Core/Vessel/Containment Interactions " Deletion of travel regulations requested Core-reimbursement type contract recommended DAVISR L Purdue Research Foundation DSP #A634 83/01/27 Division of Contracts. 2pp. 20841 210
- --B310190329 "Beyere Accident Core/Vessel/Containment Interactions "
 THEOFANOUS:T G . LYMOUDIS.P. B . HANCOCK.J C Purdue Research
 Foundation RB-NRR-B3-093, 82/01/31, 71pp 2084; 212
- B310190325 Responds to FDIA request for documents re formulation of Board Notification 83-63 Forwards document Board notification.w/encls.previously distributed to Citizens for Safe Energy PELTON.J M Division of Rules and Records 83/09/15, GROEBCH.D.L Citizens for Safe Energy 1p. 20841 290
- B310190337 FDIA request for documents re degradation of fuel assemblies while in spent fuel storage pools in UB nuclear power plants
 MAXMELL.B Rochester Post-Bulletin, Rochester, MN B3/08/10, NRC
 No Detailed Affiliation Given 19 20844 057
- 8010190340 Responds to FOIA request for documents re degradation of fuel assemblies while in spent fuel pool in US nuclear power plants Forwards App A documents App B documents available in PDR FELTON.J M Division of Rules and Records 83/09/15 MAXHELL.B Rochester Post-Bullstin, Rochester, MN 5pp 20844:058, 24X Pichs 30-282.83/09/15,8310190340.

- --B301070386 Informs of preliminary assessment of fuel assembly degradation observed in spent fuel storage pool & actions taken to assess failure mechanism & safety implication potential BU.P Chemical Engineering Branch 82/12/22 BENAROYA, V Chemical Engineering Branch 3pp 20844 074 24X Fiche 50-282,83/09/15,8310190340
- --B304200240 Forwards matl presented by util during B30223 meeting refuel assembly failure in spent fuel pool Review establishing NRC position on listed issues requested Working meeting scheduled for B30420 Encl withheld
 DIIANNI.D C Operating Reactors Branch 3 TAC 49353 B3/04/08 BU.P NRC No Detailed Affiliation Given 2pp 20844 129 24x Fiche 50-282,83/09/15,8310190340
- --B305030044 Describes plan for review of Northern States Power Co & Westinghouse submittal on fuel assembly degradation while in spent fuel storage pool.prompted by fuel assembly cracking incident at Prairie Island WU.P. Chemical Engineering Branch B3/04/20 BENARDYA.V Chemical Engineering Branch 2pp 20844 131 24x Fiche 50-282,83/09/15,8310190340
- --8305240300 Advises of informal preliminary review of potential safety issues that may exist as result of in-core fuel assembly nozzle separations Westinghouse analysis indicates no problem associated w/prevention of control rod insertions TOKAR, & Core Performance Branch TAC 49353 83/05/16 MU.P Chemical Engineering Branch 2pp 20844 154 24x Fiche 50-282,83/09/15,8310190340
- --8308180258 Forwards 830617 SER refuel assembly corrosion in spent fuel pool & draft info notice addressing corrosion problems at BMRs & PMRs Fuel assembly bulge Joint 811216 failure w/o precedent & w/o determined cause W/o entls
 BENARDYALV Chemical Engineering Branch 83/08/02 HOLAHAN,O Operating Reactors Assessment Branch 2pp 20844-156 24x
 Fiche 50-282,83/09/15,8310190340
- ---8310190344 Forwards proposed subjs of discussion for upcoming NRC-licensee-vendor meeting on spent fuel assembly failure evaluation Main concern lies in possible generic implication & licenses/vendor conclusion on failure mechanism UU.P Chemical Engineering Branch 82/01/17 Chemical Engineering Branch 82
- --8310190358 Forwards safety evaluation of fuel assembly failure event during fuel handling in spent fuel pool in Dec 1981 Evidence insufficient to deduce generic affect.

 JOHNBTON.W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/04/20 LAINAS, 0 C Assistant Director for Deparating Reactors 4pp 20844 133 24X Fiche 30-282, 83/09/15, 8310190340
- --8310170350 Bafety evaluation concluding that evidence insufficient to draw peneric conclusions from Dec 1781 fuel pool assembly failure event ** NRC No Detailed Affiliation Given 83/04/20 17pp 20844 137 24X Fiche 50-282,83/07/15.8310190340
- --8310190361 Gafety evaluation of spent fuel assembly degradation Event was isolated incident. No generic implications exist Draft IE info notice to potential contamination of RCS enc.1 * NRC No Detailed Affiliation Given 837/06/17 12pp 20844 160 24X Fiche.50-282,63/09/15,8310190340
- 83i0200026 FDIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCB leak rate tests News article dtd 830523 from Patriot News encl VOIOT.H H. LeBosuf. Lamb, Leiby & HacRae 83/05/26 Office of Administration 2pp 20844 238 24X Fiche 50-287,83/05/26. 83k0200026
- 8310200032 Responds to FOIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCB leak rate tests Forwards App A documents Portions of requested documents withheld (ref FOIA Exemption 7) FELTON.U.H Division of Rules and Records 83/09/15 VOIGT.H H LeBosuf, Lamb, Leiby & MacRae 2pp 20844 236 24X Fiche: 50-289, 83/09/15, 8310200032
- --8310200038 Ack receipt of 830317 ltr re DOJ investigation into allegations re possible criminal wrongdoing Separate NRC investigation will be initiated PALLADINON J. Commissioners 83/05/27, JENSON, D. L. Justice, Dept. of 1p 20844 240 24X Fishe 50-289,83/09/15,8310200032
- --8310200044 Requests that DDJ investigation on allegations refalsification of RCS leak rate tests be completed by 830515 Response within 2 wks requested Info partially elected. PALLADINO, N Commissioners. 63/04/11. BHITH.H F Justice, Dept of 2pp ROB44 241 24X Fiche 50-289,83/09/15,8310200032

- --B3i020004B Responds to B304ii ltr re TMI-1 restart / DUJ investigat / into allegations is mgt competence investigation being pursued diligently but will not be completed by requested date info partially deleted JENSUN, D.L. Justice, Dept of B3/05/17 PALLADIND, N.J. Commissioners App. 20844 243 24X Fiche 50-289, B3/09/15, B310200032
- 8310200353 FOLA request for comments on proposed rule 10CFR50 re ATW3 NRC evaluation of comments & draft/final versions of rule HIATIS L Objo Citizens for Responsible Energy 83/08/17 FELTON J M Division of Rules and Records 1p 20868 272
- 8310200334 Responds to FOIA request for proposed ATMS rule, NRC evaluation of comments & draft/final version of rule Forwards Documents i-8 of App A Documents 9 & 10 partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/09/23 HIAFT, S L Obio Citizens for Responsible Energy 3pp 20848 273
- --9207280124 Provides status of ATMS rulemaking in response to 820430 request DIRCKE.W J Office of the Executive Director for Operations 82/06/11 PALLADING, N J Commissioners 2pp 20871 079
- --8307270223 Summarizes ACRS 279th meeting on 830707-09 re proposed first rule on ATMS Comprehensive program encompassing all plant safety-related sys recommended Consideration should be given to listed comments before rule issued in final form RAY, J J ACRS Advisory Committee on Reactor Safeguards 83707/15 PALLADINO, N J Commissioners 4pp 20871 099
- --8308080690 Forwards response to ACRS 830715 ltr rept on proposed first rule to ATWS Rev to rule not watranted DIRCMS, W J Office of the Executive Director for Operations B370727 RAY, J J ACRS - Advisory Committee on Reactor Safeguards 5pp 20871 288
- --8310200337 Comments on proposed rule 10CFR50 & petition for rulemating PRM-50-29 me stds for reduction of risk from ATMS event Opposes rule & rulemaking due to lack of technical justification in basic premises & cost of implementation BUCHEY, O D Mashington Public Power Supply System 46FR57521 OOS 82/04/15 Docketing & Services Branch Spp 20848 284
- --8310200359 Requests brief paper be prepared describing status of ATM3 rule & plans for resolution Response due by 820321
 PALLADINO, N J Commissioners 82/04/30 DIRCKS, N J Office of the Executive Director for Operations 1p 20871 078
- --8310200364 Requests listed info needed in order to act on 9ECY-93-2-7 "Amends to 10CFR90 re ATWS Events" ASSELBTINE.J. K Commissioners 83/08/11 DIRCKS,W J Office of the Executive Director for Operations 2pp 20871 293
- 8310200374 FOIA request for access to documents re investigations of Nuclear Matis & Equipment Corp & ZM Shapiro, company president LISTER, B E Patterson, Belknap, Webb & Tyler FIALKA, J Affiliation Unknown 83/08/19 SNIDER, W J Justice, Dept of 3pp 20874 219
- B310200379 Responds to FQIA request for documents re DDJ investigations of Nuclear Matis & Equipment Corp & ZM Shapino.company prestident Forwards seven documents Documents also available in PDR FELTON.J M Division of Rules and Records B3/09/15 LISTER.S E Patterson. Belknap. Webb & Tyler ip 20874 222
- --8310200383 Responds to 780912 request for T McTiernan 780630 means re loss of U from NUMEC facility in Apollo, PA W/o sncls KELLEY, J L. Office of the General Counsel 78/09/18 HEYMANN, P B Justice, Dept of 1p 20874 223
- --8310200387 Requests assistance for newly appointed Commissioner Aberre investigation of NUMEC COBSICK.L V Office of the Executive Director for Operations 78/10/04 HEYMANN.P B Justice, Dept of ip 20874-224
- --B310200391 Responds to J Conran 780303 allegations re conduct of OGC/QIA inquiry into EDD testimony, per 780620 request Memo should be available to public MCTIERNAN.T J Office of Inspector & Auditor 78/06/30 HENDRIE, J. GILINSKY, V. KENNEDY, R.T. Commissioners 19pp 20874 226
- --8310200394 Comments on J Conran Mar 1977 itr to Congressman Udall exconduct of Old/OBC investigation
 FITSGERALD, J A Office of the General Counsel 78/06/29
 Office of the General Counsel 7pp 20874 245

- --B310200398 Concedes w/Fitigerald memo re investigation into EDO testimony CRAME.P Office of the General Counsel 78/05/29 Office of the Denoral Counsel 6pp 20874 252
- --8310200401 Documents circumstances leading to J Conrad allegations re unavailability of union representative for second interview in Gossick-Gilinsky rept HCTIERNAN, J J Office of Inspector & Auditor 78/02/23 Offic of Inspector & Auditor 3pp 20874 258
- --8310210001 Requests FB1 repts on investigation of RE Biesecker allegations re NUMEC CUMMINOS.J J Office of Inspector & Auditor 80/06/11 MARTIN.J Justice. Dept of ip 20874 225
- 8310200448 FOIA request for EG&G Rept EGG-CDD-6001, "Model for Release of Fission Products from Fuel Pellets & Debris"
 PASCHALL-A A INFO/DDC 83/08/25 Office of Administration 1p
- 8310200450 Responds to FOIA request for EG&C Rept EGG-CDD-6001, "Model for Release of Fission Products from Fuel Pellets & Debris " NRC does not have rept Rept may be obtainable from EG&G FELTEN, J M Division of Rules and Records 83/09/13 PASCHALL, A A INFO/DOC 1p 20859 340
- 8310210307 FDIA request for records re radioactive substances at Magupod Chemical Works or Stepan Chemical Co TYKULSKER,D Ball, Hayden, Kiernan & Livingston 83/09/12 NRC No Detailed Affiliation Given 2pp 20884 175
- 8310210311 Responds to FDIA request for records re Maywood Chemical Morks or Stepan Chemical Co Forwards responses to FDIA Requests 81-38,81-196,81-197,82-350,82-464 & 83-212 W/o encis FELTON,J M Division of Rules and Records 83/09/22 TYKULSKER,D Ball, Hayden, Kiernan & Livingston 1p 20884 177
- 9310210315 Responds to FOIA request for documents re decision to conduct Caseload Forecast Panel meetings & only tour facility & any documents re rationale or basis for decision Forwards documents
 FELTON, J M Division of Rules and Records 83/07/29 BUGARMAN, R ' Sugarman & Denworth 2pp 20883 170 24X Fiche 50-352, 83/07/29, B310210315
- --8303230300 Requests Cameload Forecast Panel site visit to update assessment of const completion status
 EISCHMUT.D G Division of Licensing 83/03/16 HARTFIELD.R A Management Information Branch 1p 20883 194 24X
 Fiche 50-352.83/07/29,8310210315
- B310210320 FOIA request for plant manager IM ? iling labels
 LEE.G W Trans-Continental Consultants, Inc 83/07/13 Division
 of Rules and Records 1p 20884 171
- 8310210323 Responds to FDIA request for list of plant managers in label form Forwards requested list W/o encl FELTON.J M Division of Rules and Records 83/09/22 LEE.0 W Trans-Continental Consultants, Inc. lp 20884 179
- 9310210324 FDIA request for Westinghouse 800708 notification of unreviewed safety question under 10CFR50 59 re boron dilution GRABERL D NUS Corp CD-IS-83-325 83/09/08 Division of Rules and Records ip 20884 173
- B330210325 Responds to FDIA request for Westinghouse B00708
 notification of reviewed safety question Document evailable
 in FDR
 FELTON.J M Division of Rules and Records 83/09/21 GRABER.L D
 NUS Corp 1p 20884 174
- BJ10210327 FD1A request for all documents re significantly high rate of equipment failures for QE BRR/4 rated at 2,436 MW HAFNER: 9 Suffolk Nuclear Study Group B3/07/05 Office of Administration ip 20882 222
- 8310210329 Responds to FOIA request for all documents re significantly high rate of equipment failures for GE BWR/4 rated at 2.436 MH Forwards App A documents Documents also available in FDR FELTON.J M Division of Rules and Records 83/07/28 HAFNER. B Suffolk Nuclear Study Group 2pp 20882 223 24X Fiche 50-000.83/07/28.8310210329

- --B2101B0246 Submits preliminary account of events associated w/820825 reactor trip Reactor tripped from 99% power due to overpower condition on average power range monitor Caused by clasure of one isolation valve on C main steam line RUBIN.S D Reactor Operations Analysis Branch AEGD/E240 B2/09/29 SEYFRII.W V Reactor Operations Analysis Branch 3pp 20882 249 24% Fithe 50-000,83/07/28.8310210329
- ---830:180513 Evaluates LERs for Jul 1981 Oct 1982 in support of upcoming SALP review LERs minimally adequate in harrative sections Large number considered mpt deficiency-related SEYFRIT.K V Director's Office 83/01/12 LEWIS,R Division of Project & Resident Programs 5pp 20882 225 24X Fiche 50-000,83/07/28,83:02:10329
- --8302020202 Summarizes evaluation of LERs for 1982 in support of upcoming SALP review Licensee performance adequate SEYFRIT.K V Reactor Operations Analysis Branch 83/01/26 STARUSTECKI.R Division of Project & Resident Programs. Spp 20882:254 24X Fiche 50-000,83/07/28,8310210329
- --8302180539 Discusses results of evaluation of LERs for Jul 1981 Dec 1982, for SALP rept Quality & quantity of LERs within range of average BUR facility SEYFRIT, K V Reactor Operations Analysis Branch 83/02/09 LEMIB.R C Division of Project & Resident Programs 3pp 20882 257 24X Fiche 50-000,83/07/28.8310210329.
- --8303030103 Comments of LERs submitted from Feb 1982 Jan 1983 in support of SALP review LERs generally prepared adequately w/occasional exceptions Litensee performance typical of average BHR facility in initial phase of plant startup SEYFRIT.K V Reactor Operations Analysis Branch 83/02/22 STAROSTECKI.R Division of Project & Resident Programs 2pp. 20882 263 24X Fiche 50-000.83/07/28.9310210329
- --B303240341 Summarizes evaluation of LERs for 1982 LER submittals usually acceptable Potential mpt weakness indicated by large number of procedural deficiencies lack of followup repts committed to & possible training problems.

 SEYFRITAK V Reactor Operations Analysis Branch B3/03/15 LEWIS.R C Division of Project & Resident Programs 4pp 20882 267 24X Fiche 50-000.83/07/28.8310210329
- --B303240364 Summarizes evaluation of LERs for Mar 1982 Feb 1983 LER submittals acceptable Supplemental or followup info would improve operational experience analysis SEYFRIT.K V Reactor Operations Analysis Branch 83/03/16 STARGSTECKI.R Division of Project & Resident Programs 3pp 20862 273 24X Fiche 30-000.83/07/28,8310210329
- --B30601000B Discusses evaluation of LERs submitted during appraisal period May 1982-Apr 1983 for technical accuracy.completeness & intelligibility Screening for trends & patterns produced few cases which could indicate potential mgt weakness SEVTRIT.K V Reactor Operations Analysis Branch 83/05/18 STANDSTECKI,R Division of Project & Resident Programs 3pp 20882 276 24X Fiche 50-000.63/07/28.8310210329
- 8310240012 Partial response to FDIA request for transcripts of deposition testimony prepared in discovery in DL proceeding for facilities Forwards App A documents Documents also available in PDR FELTON.J & Division of Rules and Records 83/08/10. AHLERS, D M Palmetto Alliance 3pp 20885 001 24% Fiche 50-413, 83/08/10. 8310240012
- --8310240014 Transcript of M Birch deposition in Charlotte,NC re Contention 27 BIRCH,M Duke Power Co 83/05/11 126pp 20885 008 24X Fiche 50-413,83/08/10.8310240012
- ~-8310240017 Transcript of CW Graves deposition in Charlotte.NC re Contention 8 GRAVES.C W Duke Power Co 83/05/12 44pp 20885.134. 24X Fiche 50-413.83/08/10.8310240012
- ~-8310240018 Transcript of PK Vandoorn deposition in Charlotte, NC re-Contention & VANDDORN, P K Duke Power Co 83/05/19 150pp 20885: 178 24X Ficha 50-413,83/08/10,8310240012
- --8310240021 Transcript of HR McAfe» deposition in Charlotte,NC re Contention & HCAFEE,W R Palmetto Alliance. 83/05/19 128pp 20885 328 24X Fishe 50-413,83/08/10,8310240012
- --8310240022 Transcript of NL Hoopengardner deposition in Charlotte,NC re Contention & HODPENGARDNER Palmetto Alliance 83/05/19 47pp 20886:094 24X Fishe 50-413,83/08/10,8310240012

- --8310240024 Transcript of NR Hoopingarner deposition in Charlotte, NC to Contention 6 HOOPINGARNER, N Palmetto Alliance 83/05/20 109pp 20886 142 24% Fiche 50-413,83/08/10,8310240012
- --8310240030 Transcript of GE Vaughn deposition in Charlotte NC re Contention 7 VAUSHN G E Duke Power Co 83/05/20 41pp 20884 251 24X Fiche 50-413,83/08/10/8310240012
- --8310240032 Transcript of JC Bryant deposition in Charlotte.NC re Contentions & & 7 BRYANT.J C NRC - No Detailed Affiliation Given 83/05/20 80pp 20886 292 24X Fiche 50-413.83/08/10.8310240012
- --B310240038 Transcript of PK Vandoorn deposition in Charlotte,NC re Contention 6,Vol II VANDODRN:P K Dute Power Co 83/05/20 137pp 20887 011 24X Piche 50-413,83/08/10,8310240012
- --8310240040 Transcript of BG Addis deposition in Charlotte NC re Contention & ADDIS B G Duke Pawer Co B3/06/27 129pp 20887 139 24X Fiche 50-413.83/08/10.8310240012
- --8310240043 Transcript of GH Bell deposition in Charlotte, NC re Contention & BELL.Q H Duke Power Co 83/06/27 75pp 20887 269 24X Fiche 50-413,83/08/10,8310240012
- --B310240047 Transcript of JC Rogers deposition in Charlotte.NC re Contention 6 RODERS, J C Duke Power Co B3/06/27 32pp 20887 346 24X Fiche 50-413,83/08/10,8310240012
- --8310240047 Transcript of WO Henry deposition in Charlotte NC re Contention A MENRY, WO Duke Power Co 83/06/28 133pp 20888 017 24x Fiche 50-413,83/08/10,8310240012
- --8310240053 Transcript of DC Beam deposition in Charlotte.NC re Contention & BEAM D O Duke Power Co 83/06/28 81pp 20888 152 24X Fiche 50-413,83/08/10,8310240012
- --8310240056 Transcript of AE Allum 830627 deposition in Charlotte, NC re Contention 6 ALLUM. A E Duke Power Co 83/06/29 114pp 20888 300 24X Fiche 30-413, 83/08/10, 8310240012
- --8310240057 Transcript of CR Baldwin 830627 deposition in Charlotte.Fc re Contention 6 BALDWIN,C R Duke Power Co 83/06/29 191pp 20889 052 24X Fiche 50-413,83/08/10,8310240012
- --8310240058 Transcript of JE Grogan deposition in Charlotte, NC Related info encl GROGAN, J E Duke Power Co 83/07/G1 27pp 20889 241 24x Fiche 50-413, 83/08/10, 8310240012
- --B310240039 Transcript of WH Bradley deposition in Charlotte,NC re Contention 6 BRADLEY:N H Dute Power Co 83/07/07 56pp 20889 270 24X Fiche 50-413,83/08/10,8310240012
- --8310240040 Transcript of CN Alexander deposition in Charlotte, NC re Contention 6 Related info enci ALEXANDER C N Duke Power Co 83/07/07 ilOpp 20889 327 24 v Fishe 50-413,83/08/10,8310240012
- --B310240061 Transcript of WS Les deposition in Charlotte, NC Related info anc! LEE.W S Dute Power Co 83/07/12 78pp 20890 074 24X Fiche 50-413,83/08/10,8310240012
- --B310240062 Transcript of RA Morgan deposition in Charlotte,NC re Contention & MCR9AN.R A Dute Power Co B3/07/13 120pp 20890 153 24X Fiche 50-413, 83/08/10, 8310240012
- --8310240065 Transcript of BW Deaton deposition in Charlotte,NC re Contention 6 DEATON,B W Duke Power Co. 83/07/14 49pp 20890 274 24x Fiche 50-413,83/08/10,8310240012

- --B31024006B Transcript of S Ledford deposition in Charlotte.NC re Cantentian & LEDFORD, S Duke Power Co B3/07/14 26pp 20890 325 24X Fiche 50-413, B3/08/10.8310240012
- --B310240073 Transcript of JC Shropshire deposition in Charlotte, NC To Contention & Related info encl SHROPSHIRE, J C Duke Power Co 83/07/14 87pp 20890 353 247 Fiche 50-413,83/08/10,8310240012
- --8310240075 Transcript of L 5:fford deposition in Charlotte.NC re Contention 6 SIFFORD,W L Duke Power Co 83/07/14 38pp 20891 083 24v Fiche 50-413,83/08/10.8310240012
- B310240167 F01A request for documents re M Adler &/or Scorpio Music Distributors. Inc & documents re investigation concerning Thomas Jefferson Univ Hosp & DA Zane JACOBSON.P J Jacobson.P J B3/06/06 NRC - No Detailed Affiliation Given 2pp 20891 303
- 8310240171 Partial response to FOIA request for documents re M Adder //
 or Scorpio Music Distributors, Inc & investigation concerning
 Thomas Jefferson Univ Hosp & DA Zane Forwards app documents
 Review of remaining documents incomplete
 FELTON-J M Division of Rules and Records 83/07/04 JACOBSON.P /
 Jacobson, P J 2pp 20871 305
- ---790A2501B1 Discusses IE insp of License 37-00148-06 on 781109 & 14 *
 forwards notice of violation
 MCCLINTOCK,R D. Region i, Philadelphia, Office of the Director
 78/12/18 SWEENEY,F Thomas Jefferson Hosp Philadelphia,PA
 2pp 20091 319
- --7906230189 Notice of violation from insp on 781109 & 14 Noncompliance noted coffee was drunk in labs.radiopharms were injected w/o waterproof gloves & syringe shields & Ofc of Radiation safety was not notified of spill & Ragion 1, Philadelphia, Office of the Director 78/12/18 2pc 20891 321
- ~-8310240173 Authorizes release of records to PJ Jacobson
 ADLER.N Affiliation Unknown 83/06/01 NRC No Detailed
 Affiliation Given 1p 20891 307
- ~-8310240175 Discusses statements made by DA Zane, Tadiation technologist at Thomas Jefferson Univ Hosp, Philadelphia PA, detailing radioactive matl misuse & personnel abuses ADLER.M Affiliation Unknown 78/07/20 HENDRIE, J M Commissioners 7pp 20891 308
- --8310240176 Ack receipt of 780720 ltr Several issues raised require airl analysis & further inquiry ABBTON.O G Office of Inspector & Auditor 78/08/09 ADLER.A AFFILIAtion Unknown Ip 20891 317
- --8310240181 Forwards 781004 memo re complaint conterning Thomas Jefferson Univ Hosp Basis for radiological conditions:per M Adler 780720 ltr.will be examined M/o stated encl W/draft field notes of IE Insp Rept 30-02741/78-02 ALLAN.J M Region i. Philadelphia. Office of the Director 78/10/12 HIGGINSOTHAM:L Division of Fuel Facility & Materials Safety 1p 20891 323
- ~~8310240185 Responds to 780720 ltr re general disregard for good radiological safety practices at Thomas Jefferson Univ Hosp Unannounced insp conducted on 781109 & 14 Noncompliance re failure to follow safety procedures identified GRIER.B H NRC No Detailed Affiliation Given 78/02/01 ADLER.M Affiliation Unknown 2pp 20891 332
- B310240189 Responds to FDIA request for copies of ltrs to Univ of Michigan following insps of broad license from 1980-82 Forwards App A documents W/d encil Documents also in PDR FELTON. J M Division of Rules and Records B3/07/08 SAENGER, E L Univ of Cincinnati Medical Ctr., Cincinnati, OH 2pp 20907 165
- B310240170 FOIA request for copies of itrs to Univ of Michigan following ineps of broad license from 1780-82 SAENOER.E C. Univ of Cincinnati Medical Ctr , Cincinnati, DR 83/06/24 Division of Rules and Records ip 20707 167
- 8310240191 Final response to FOIA request for documents re M Adler 1/cr Biorpio Music Distributors & investigation of Thomas Jefferson Univ Hosp & DA Zane Document released in 830706 ltr
- FELTON, J M Division of Rules and Records 83/09/06 JACOBSON, P . Jacobson, P J 1p 20903 245

- 8310240192 FDIA request for four categories of documents
 SHOLLY, S.C. Union of Concerned Scientists 83/06/0/ FELTON, J.M.
 Division of Rules and Records 1p 20884 178
- B310240193 Responds to FOIA request for four categolies of documents Forwards App A documents responsive to Itums 1.2 & 3 Records re Item 4 can be obtained from DOC FELTON, J M Division of Rivleo and Records 03/07/01 SHOLLY, 8 Union of Concerned Scientists Pp POSB4 179
- --8310240194 "Rept to Commission, Review of NRC Reactor Safeguards Program" CUMMINOS, J J Office of Inspector & Auditor 83/04/30 144pp
- --B310240195 Summary of 830910 meeting w/LASL in los Alamos, NM re TRAC/
 HIMAB review & integration
 HAN, J T. AUDETTE, R. NRC No Detailed Affiliation Given
 B3/05/24 MARING, G P. CURTIS, R T. NRC No Detailed Affiliation
 Given 4pp 20884 325
- B310240196 FOIA request for agency records relevant to &/er generated inconnection w/MRC investigations, insp or repts on altegations made by R Quiderson & W Royce re factilities BERNABEI, L Government Accountability Project 83/08/05 Office of Administration 2pp 20903 249 24X Ficho 50-528, 83/08/05, 8310240196
- B310240197 Partial response to L Bernabet B30805 fully request for agency records relevant to \$\forall \text{or generated in connection \$\text{w}/\text{or senerated in connection \$\text{w}/\text{or RU of the senerate for all of attents made by R Gunderson \$\text{W} Roger Forwards App A documents FELTON, \$\text{J} M & \text{Division of Rules and Records 83/09/08 QARDE, \$\text{R} \text{Government Accountability Project App 20903 201 24X Fichs 50-528, 83/09/08, B310240197
- --8206080487 Comments on 820511 ltr re allogations of improper electrical work Inquiry being made DIRCKS,W J. Office of the Executive Director for Operations 82/05/26 MODDs,T & Arizona Public Service Co. 1p. 20704 128 24X Fiche 50-528,83/09/08,B31004019/
- --8310240199 Requests assistance in disclosing worker allegations re problems at facility Various allegations by workers re const. GA & GC problems existing at plant discussed HORRISON, J. R. Palo Verde Intervention Fund 82/12/07 GARDE, B Government Accountability Project 3pp 2093 332 24X Fiche 50-528, 83/09/08, B31024019/
- --8310240201 Submits list of plant electrician allegations that author considers readily documented w/o further investigation Some items listed already documented in rough form ECKHARDT.J H NRC No Detailed Affiliation Given 82/12/17 SHACKLETON.O NRC No Detailed Affiliation Given 1p 20903 335 24X Fichs 50-520.83/09/08.8310240197
- ~-8310240203 Bubmits results from informal B30323 meeting re unreviewed affidavits from Oovt Accountability Project Bhackleton analysed Bunderson affidavit & will identify any new areas to Region V
 MARBUT,P P Region 5, Office of Director 83/03/23
 STERNBERG,D M. YOUNG,T. FIGRELLIQ NRC No Detailed Affiliation Given 1p 20903 336 24X Fiche 50-528,83/09/08,8310240197
- ~~8310R40207 Discusses B Idel B3042/ telcon re terminations & crimpling tools Narbut allegation logs & related matls encl NARBUT.P NRC No Detailed Affiliation Diven B3/09/08 NRC No Detailed Affiliation Given lopp 20903 339
- ~8310240207 Notifies of results of Dept of Labor compliance actions in W Royce vs Bechts1 Corp case Lists actions required to abate violation & provide appropriate relief Right to appeal findings within 5 days of itr receipt permitted BREEN. J. Labor, Dept of 62/12/20 BUTLER. 6 Bechts1 Corp 29p 20703 362
- --8310240212 Forwards Dept of Labor 830324 Recommended Decision & Order of Administrative Law Judge in W Rouce vs Bechtel Corp case BULER, S D Bechtel Corp. 83/03/30 Bechtel Corp. 12pp 20904 001 24X Fiche 50-528,93/07/08,8310240197
- --B310240215 Requests review of NRC serious mishandling of investigation of worker allegations re deficiencies in electrical work & startup tosting program at facilities, on behalf of R Gunderson & W Royce Related math encl BERNABELL Government Accountability Project B3/07/14 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 19pp 20704 013 24X Fiche 50~520,83/09/08.8310240177

- --B310240217 Requests response to issues raised by J Morrison 830703 itr expressing concerns w/manner in which Regional V & Ofc of Investigation handled allegations of violations at plant J Morrison 830703 itr enel UDALL M K House of Rep , Interior & Insular Affairs 83/07/17 PALLADINO. N Commissioners 4pp 20904 040 24X Fiche 50-528.83/09/08.8310240197
- --B310240218 Submits list of documents in Region V files which apply to Young & Bernabei FOIA-83-161 request for documents realispations of electrical problems Related matl encl ALEXANDER, I Region 5. Office of Director B3/05/06 TDMS, V NRC No Detailed Affiliation Given 5pp 20904 045 24X Fiche 50-528,83/09/08,8310240197
- --B310240219 Forwards it Young & L Bernabei FQIA request for documents re allegations of R Gunderson & sensor Bechtel manager FDIA time record form should be completed & returned ORIMSLEY, D H NRC No Detailed Affiliation Given B3/03/31 HILSON, V Office of Nuclear Reactor Regulation, Director SMSENEY, M Office of the General Counsel 2pp 20904 049 24X Fiche 50-528, B3/09/08, B310240197
- --B310240B20 Requests that documents be provided in attached FGIA Request 83-450 Documents required to be delivered to I Alexander by 830B17 Forwards FGIA Request 83-450 & list of documents on auth Documents need not be duplicated NARBUT.P Region 5. Defice of Director 83/08/16 MARTIN.J., STERNBERG, D., YOUNG, T. NRC No Detailed Affiliation Given App 20904 051 24X Fiche 50-528.83/09/08.8310240197
- --8310240221 Forwards L. Bernabei FOIA request for documents in connection w/NRC investigations, insprepts or regts on allegations made by R Gunderson & H Royce re facilities List of questions for response to NL Toms requested by 830816 GRIHBLEV.D H NRC No Detailed Affiliation Given 83/08/09. BROHN.N Office of the Secretary of the Commission. SWEENEY, M Office of the General Counsel 2pp 20904 055 24X Fiche 50-528,83/09/08,8310240197
- --B310240222 Notifies that special unannounced insp scheduled at facility on 830404-08 Team consisting of author. A Johnson, J Burdoin, G Figrelli & L Vorderbrueggen will examine facts surrounding as many allegations as possible during insp YOUNG, T Region 5, Office of Director 83/03/31 STERNBERG, D NRC No Detailed Affiliation Given in 20904 059 24% Fiche 30-528, 83/09/08, 8310240197
- --8310240223 Discusses NRC insplentrance interview conducted on 830615, to describe NRC planned insplactivities Lists NRC inspectors & areas of investigation NRC will be primarily investigating allegations during visit Related matlenci
 IDE:WE Arizona Public Service Co GAD 82 8 94 82/06/15
 RGEDEL:JA Arizona Public Service Co 4pp 20904 102 24X
 Fiche 50-528,83/09/08,8310240197
- --B3102402R7 Discusses status of special inspire allegations, in response to B304ii memo lists items not addressed Efforts will be concluded & pertinent repts issued on listed items prior to B30601 Relevant documents issued & received encl MARTIN.J B Region 5. Office of Director B3/05/02 CUNNINGHAM.O H Office of the Executive Legal Director 2pp R0904 106 24X Fiche 50-528.83/09/08.8310240197
- --B310240236 Notifies that author had no involvement in investigation into allegations at facility.per Narbut 830816 memo Norelevant documents re FOIA Request 83-450 in author possession JOHNSON.P NRC No Detailed Affiliation Given B3/08/18 ALEXANDER.1 NRC No Detailed Affiliation Given ip 20904 its 24X Fiche 50-528.83/09/08.8310240197
- --8310240239 Forwards documents re FOIA request for NRC investigation insps or repts on allegations made by R Gunderson & W Royce toncerning facilities Excerpt of installation spec for cable splicing enci.

 ALEXANDER: I Region 5. Office of Director 83/08/19 TOMS, N NRC ND Detailed Affiliation Given 7pp. 20904 112 24X Fiche 50-528,83/09/08,8310240197
- ---8310240241 Notifies of receipt of T Woods 820511 1tr to NRC re allegations about safety at facilities Requests to be advised of any action taken by NRC in subj matter RUDD, E House of Rep 82/05/19 PALLADING, N J Commissioners Ip 20904 129 24% Fiche 50-528,83/09/08,8310240197
- --B310240246 Ack receipt of B20519 ltm to Chairman Pailadino expressing concern re allegations of improper electrical work at facilities Region V initiated independent inquiry into matter w/legal assistance.

 KAMMERER: C Office of Congressional Affairs B2/06/01 RUDD.E House of Rep ip 20704 i30 24% Fiche 50-528.83/09/08.

- --B310240251 Discusses immediate effectiveness review of facilities remailysis of pending insp/investigation items identified in Ofc of Insp & EDD repts of B30325 & 27 Presumes EECV will extend review time to accommodate Commission consideration ASSELSTINE. J K Commissioners. 83/04/01 PALLADING Commissioners ip 20904 131 24X Fiche 50-528.83/07/08, 8310240197
- 8310240233 FOIA request for three listed documents to be placed in PDR PEDRO.J NUS Corp. CO-18-83-018 83/06/06 Division of Rules and Records ip 20891 224
- B310240234 Further response to FOIA request for winning technical proposals under RFP RB-ORM-B3-452 resulting in multiple award task order Contracts NRC-33-83-452-01 through 07 Forwards App D document Addl records undergoing review FELTON, J M Division of Rules and Records 83/07/08 PAUL, L K Affiliation Unknown 2pp 20907 148
- --8310240238 "Multiple Award Task Order Contract for ADP Development." technical proposal * Rehab Group, Inc. RS-DRM-83-452 82/07/14 95pp 20907.171
- 8310240235 Responds to FOIA request for three documents to be placed in PDR. Ferwards documents listed in app FELTON, J M Division of Rules and Records 83/07/11 PEDNO, J NUS Carp 2pp 20891 225
- ~-801103023B Notification of 800903 meeting w/GE in Bethasda.ND to discuss proposed BNR feedwater norrile leakage detection sys BNATDER.R P. Systematic Evaluation Program Branch 80/08/14 KNIEL.K Generic Issues Branch ip 20891 828
- ~-8011190749 Summary of B00903 meeting w/GE to discuss draft NEDE-24265-P (propriatory) re proposed feedwater nozzle surveillance instrumentation sys List of attendees encl BNAIDER, P. Generic Issues Branch 80/09/15 KNIEL, K Generic Iesues Branch 39p 20891 229
- --Bi02260210 Summary of 801217 meeting w/utils & vendors in Bethesda.MD re inclusion of linear plastic fracture mechanics in resolution of potential for low fracture toughness & lamellar tearing on component supports
 SNAIDER:R Ceneric Issues Branch 80/12/30 KNIEL:K Generic Issues Branch 499 20891 233
- 8310240237 Responds to FDIA request for RFP RS-ORM-83-500 & BECY-83-157 Forwards RFP & related info BECY undergoing review for disclosure determination, RFP also evailable in PBR FELTON, J M. Division of Rules and Records. 83/07/06 GRABER, L NUS Corp 1p 20915: 253
- --8305130302 Forwards RFP RB-DRM-83-500, "Const Analyses of Proposed Changes in NRC Requirements " MATTIA:N J Administrative Contracts Branch 83/03/16 Affiliation Unknown 6pp 20915 255
- --8305180304 REP RS-URM-83-500. "Cost Analyses of Proposed Changes in NRC Requirements" # Division of Contracts 83/03/16 52pp 20915 261
- --8305130306 "Regulatory Analysis Guidelines of NRC" * NRC - No Detailed Affiliation Given 82/12/13 160pp 20916-001

- 8310240279 FOLA request for Online Computer Sys, Inc bid proposal for Contract RB-DRM-B3-454, "Automated Library Sys " Expresses reservations & concerns re propriety of decision to award contract to Online Computer Sys, Inc DICK, R B Avatar Systems, Inc B3/05/13 COLEMAN, R NRC No Detailed Affiliation Given ip 20708 011
- 8310240281 Responds to FOIA request for successful proposal under RFP RB-ORM-83-454 Confirms 830527 telcon agreement to accept nonproprietary version of proposal. excluding cost proposal entirely Forwards document Document also available in PDR FELTON.J M Division of Rules and Retords 83/07/11 DICK,R S Avatar Systems, Inc. ip 20908 012
- --8310240286 "Automated Library Sys at NRC Using Integrated Library Sys (ILS)." proposal in response to RFP R8-0RM-83-454
 Proprietary info & cost proposal withheld
 * Online Computer Systems, Inc. 83/01/18 Division of Technical Information & Document Control 40pp 20908 013
- 8310240312 Responds to FOIA request for FOIA requests received during past 4 months from journalists, television, radio news, newspaper & magazine reporters Forwards documents listed in app 1/10 encl
 FELTON.J M Division of Rules and Records 83/10/11 KOLI.E.
 Cable News Network, Inc. 2pp 20907 159
- 8310240315 F01A request for F01A requests received during past 4 months from journalists, television, radio news, newspaper & magazine reporters.

 MOLI,E Cable News Network, Inc 83/09/29 NRC No Detailed Affiliation Given Ip 20907 161
- 8310240320 Add1 response to FOIA request for documents re Teth Spec problems applicable to RCS leakage determinations in PMRs Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/14 VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 2pp 20907 036 24X Fiche 50-348.83/07/14.8310240320
- --8010010786 Trip rept for site visit re development of portable calculator for RCS leak rates for PWRs Forwards programs for T1 59 k HP 41C calculators used during visit to compute leak rate WODDRUFF, D C Division of Reactor Operations Inspections 80/08/14 JURDANIE L Division of Reactor Operations Inspections 27pg 20907 039 24x Fiche 50-348,83/07/14,8310240320
- 8310250002 Responds to FOIA request for distribution list used for mailing NUREO-0737 (Suppl 1). "Control Room Design Reviews "Forwards list W/o and FELTON. J M Division of Rules and Records 83/07/14 DEBOR. J Biotechnology. Inc. 1p. 20908-337
- B310230007 FOIA request for distribution list used for mailing NUREG-0737 (Suppl 1), "Control Room Design Reviews " Info received will be used to support util conference on NUREG-0737 DENOR. J Biotechnology, Inc 83/07/05 Division of Rules and Records 1p 20708 338
- 8310230009 Responds to appeal re denial of FOIA request for SECY-82-388 "Withdrawal of Medical Missadminstration Reporting Requirements "Forwards Attachments 2,3.4 & 5 Attachments 1, 6, 7 & two page analysis withheld (ref FOIA Exemption 5) CHILM.B J Defice of the Secretary of the Commission 83/07/01 ERNSTHAL.H L Society of Nuclear Medicine 3pp 20916 231
- --B310250014 Discusses 82010B meeting w/J Halprin of FDA re misadministration reporting rules FDA comparable rules listed Rules have little relevance to misadministration FDA does not plan to engage in reporting CUNNINGHAM.R E Division of Fuel Cycle & Material Safety B2/01/15 Division of Fuel Cycle & Material Safety ip 20916-223
- --8310250017 Bummary of B10B11 preliminary meeting w/Joint Commission on Accreditation of Hosps Meeting attendess purpose program scops mode of operation, info on misadministrations & canclusions provided ROCHE-FARMER, L NRC No Detailed Affiliation Given 81/08/18 NRC No Detailed Affiliation Given 8294 254
- --B310230017 Summary of B10806 meeting w/S Kidder, Dept of Health & Human Svcs Neeting purpose, program scope, mode of operation & conclusions provided ROCHE-FARMER, L NRC No Detailed Affiliation Given B1/08/28, NRC No Detailed Affiliation Given 2pp 20916 255

- --8310250024 Notification of 820119 meeting w/Joint Commission on Accreditation of Hosps (JCAH) to determine feasibility of JCAH taking over day-to-day operations of misadministration reporting requirements ROCHE,L A Uranium Fuel Licensing Branch 82/01/22 Uranium Fuel Licensing Branch 1p 20716 257
- ~-8310250025 Summary of meeting on petitions for rulemaking on misadminstration rule by American College of Radiology, SNM & American Suc of Therapeutic Radiologists Meeting agenda & list of attendees provided ROCHE-FARMER, L. NRC No Detailed Affiliation Given 81/09/11 NRC No Detailed Affiliation Given 1p 20916 258
- --8310250014 Discusses 820108 meeting w/J Halprin of FDA remisadministration reporting rules FDA comparable rules listed Rules have little relevance to misadministration FDA does not plan to engage in reporting CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 82/01/15 Division of Fuel Cycle & Material Safety 1p 20086 253
- --B310250017 Summary of 810811 preliminary meeting w/Joint Commission on Actreditation of Hosps Meeting attendess, purpose, program scope, mode of operation, info on misadministrations & conclusions provided RCCHE-FARMER, L. NRC No Detailed Affiliation Given 81/08/18 NRC No Detailed Affiliation Given 2pp 20916 254
- --8310250019 Summary of B10806 meeting w/S Kidder Dept of Health & Human Svcs Meeting purpose program scope mode of operation & conclusions provided ROCHE-FARMER, L NRC - No Detailed Affiliation Given 81/08/28 NRC - No Detailed Affiliation Given 2pp 20916 255
- --8310250024 Notification of 820119 meeting w/Joint Commission on Accreditation of Hosps (JCAH) to determine feasibility of JCAH taking over day-to-day operations of misadminstration reporting requirements RCCHE.L A Uranium Fuel Licensing Branch 82/01/22 Uranium Fuel Licensing Branch 82/01/22 Uranium
- --9310250025 Summary of meeting on petitions for rulemaking on misadminstration rule by American College of Radiology, SNM & American Soc of Therapautic Radiologists Meeting agenda & list of attendees provided RICHE-FARMER, L NRC No Detailed Affiliation Given 81/09/11 NRC No Detailed Affiliation 61ven 1p 20916 298
- 8310250026 FGIA request for SECY-B3-030, "TMI-Related Requirements at Operating Reactors," to be placed in PDR
 BUCKLES.R NUB COC-IS-B3-069 83/06/24 Division of Ruiss and Records ip 20916 177
- 8310230028 Responds to FDIA request for SECY-83-030, "TMI-Related Requirements at Operating Reactors," be placed in PDR Forwards requested document Document also available in FDR FELTON, J M Division of Rules and Records 83/07/19 BUCKLES, R NUS Corp 1p 20916 178
- --0310250090 SECY-83-030
 Advises of NRR plan to take licensing action on TMI action plan requirements specified in NUREO-0737 scheduled for implementation after 810630
 DIRCKS.W.J. Office of the Executive Director for Operations 83/01/21 31pp 20916 179
- 8310250031 FOIA request for A Szukiewicz 820809 & 830114 memos to K Kniel.summarizing NRC 820728 & 1229-30 meetings w/EGt0 re Unresolved Bafety Issue A-47.to be placed in PDR BUCKLES.R NUB Corp. CD-15-83-100 83/06/30 Division of Rules and Records 1p 20708 281
- 8310250032 Responds to FOIA request that A Stukiewica 820809 & 830114 memos to K Kniel. summarizing NRC 820728 & 1229-30 meetings w/EQ&Q re Unresolved Safety Iosue A-47. be placed in PDR Forwards documents FELTON. J M Division of Rules and Records 83/07/15 BUCKLEB.R NUS Corp 1p 20908 282.
- --8208240121 Summary of 820728 meeting w/EQ&Q. ID in Bethesda.MD re Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Modeling of control sys to begin in Aug 1982 W/o handouts SZUKIEWICZ.A J Generic Issues Branch 82/08/09 KNEIL.K Generic Issues Branch 35pp 80908 288

- --8301250200 Summary of 821227 % 30 meetings w/EG&G in Idaho Falls, ID re status & progress of Browns Ferry plant review & progress on Unresolved Safety Issue A-47 concerning safety implications of control sys Agenda & attendance list encl SZUKJEHICZ, A Generic Issues Branch 83/01/14 KNIEL, K Generic Issues Granch 5pp 20908 283
- B310250673 Appeals dental of FOIA request for SECY-B2-388. "Withdrawal of Medical Misadministration Reporting Requirements" BRNSITMAL.H L Society of Nuclear Medicine B3/03/08 Dffice of the Executive Director for Operations ip 20716 234
- B31026000B Add1 response to FOIA request for 17 categories of records Forwards documents listed in Apps B.C & D Info re fraudolent practices of Ray Miller-Inc available in PDR FELTON.J M Division of Rules and Records B3/06/23 CLEWETT.J Public Citizen Litigation Group 15pp 20290 001 24X Fiche 50-000.83/06/23.8310260008
- --B207260091 Discusses licensee Mar 1982 testing & evaluations of steam extraction line elbow which ruptured on B20828, in response to 820709 request for add1 steam line break info E1SENHUT, D G Division of Licensing B2/07/14 REMM, T A Office of the Executive Director for Operations 2pp 20920 020 , 24% Fiche 50-000, B3/06/23, B310860008
- --8211020311 Summary of operating reactor events 820929 meeting.
 Viewgraphs encl
 MIRAGLIA: J Assistant Director for Safety Assessment 82/10/05
 EISENHUT: D 0 Division of Licensing 4pp 20921 099.
- --B211040474 Forwards summary of 621013 operating reactor event meeting to brief ofc director, div directors & representatives on current events
 MIRAGLIA.F J Assistant Director for Safety Assessment. B2/10/21
 RISENHUT.D G Division of Licensing 5pp 2092; 103
- --B212130174 Summary of Operating Reactor Events 821124 meeting re BWR pipe crack indications & various events MTRAGLEAFT J. Assistant Director for Safety Assessment 82/12/01 EISENHUT.D G. Division of Licensing 8pp 20921
- --B304010047 Forwards list of rankings of nuclear power plants w/respect to population within 10 & 20 miles, in response to Senator Simpson 630317 ltr VULLHER,R H Division of Engineering 63/03/23 FUNCHES,J Planning & Program Analysis Staff App 20721 136
- --8310260027 Forwards initial info re 830628 steamline break event at facility, per 830702 telcon request Review of licensee actions continuing MARTIN.R D Region 2. Office of Director 83/07/07 REHM.T A Office of the Executive Director for Operations 5pp 20920 022 24% Fiche 50-000.83/06/23.831026008
- --B310260031 Forwards "Rept on Effects of Lightning on Nuclear Power Station Bys." in response to question of frequency of lightning on nuclear power plants RYBER.C ACRS Advisory Committee on Reactor Safeguards B2/12/07 RAY.J ACRS Advisory Committee on Reactor Safeguards ip 20920 032
- --8310260034 "Rept on Effects of Lightning on Nuclear Power Station Bys "
 RYBER:C P ACRB Advisory Committee on Reactor Safeguards
 82/12/31 18pp 20920 033
- --8310260037 Forwards "Rept on Comparison of BALP Evaluations & Outage Rates of Nuclear Power Plants " RYDER: C ACRS - Advisory Committee on Reactor Safeguards 82/11/19 HOELLER: D ACRS - Advisory Committee on Reactor Safeguards ip 20920-317
- --831026004; "Rept on Comparison on SALP Evaluations & Dutage Rates of Nuclear Power Plants " RYDER.C ACRS - Advisory Committee on Reactor Safeguards S2/11/30 5pp 20920 3IB
- --8310260049 Forwards "Power Outages at Commercial Nuclear Power Reactors During 1976 - 1979 " RYDER, C. ACRB - Advisory Committee on Reactor Safeguards 83/03/279 MOELLER, D. ACRB - Advisory Committee on Reactor Safeguards ip 20920 323
- --B310240050 "Power Gutages at Commercial Nuclear Power Reactors During 1976 - 1979 " RYDER,C ACRS - Advisory Committee on Reactor Safeguards 83/03/29 23pp 20920:324

- --8310260053 Summary of 820122 operating reactor events meeting Next meeting scheduled for 820203 Meeting attendees, events discussed & significant event elements encl LAINMB, & C. Assistant Director for Operating Reactors 82/01/28 EISENHUT. D. Q. Division of Licensing 13pp 20920 347
- --8310260058 Summary of 820211 operating reactor events meeting Next meeting stheduled for 820224 Meeting attenders, events discussed & significant event elements encl LAINAG, G C. Assistant Director for Operating Reactors 82/02/23 EISENRUT. D G. Division of Licenting 11pp 20720 360
- --B310260061 Summary of B20303 operating reactor events meeting Next desting scheduled for 820310 Meeting attendees events discussed & significant event elements encl LAINAS.0 C Assistant Director for Operating Reactors B2/03/08 EISENHUT.D Q. Bivision of Licensing Bpp 20921 009
- ---B31026066 Summary of 820317 operating reactor events meeting Next meeting scheduled for 820324 Meeting attendees, events discussed & significant event elements encl LAINAG. G C Assistant Director for Operating Reactors 82/03/22 EISENHUT. D 0 Division of Licensing 4pp 20921.017
- --8310260067 Bunmary of B20331 operating reactur events meeting Next meeting scheduled for B20407 Meeting attendees, events & significant event elements encl LAINAGE OC Assistant Director for Operating Reactors B2/04/05 EIBENKUT, D G Division of Licensing 11pp 20928 021
- --B310260071 Summary of 820421 operating reactor events meeting Next meeting scheduled for 820428 Meeting attendees, events discussed & significant event elements and LANNAS, & C. Assistant Director for Operating Reactors
- --8310260075 Summary of 820505 operating reactor events meeting Next meeting scheduled for 820517 Neeting attenders, events discussed & significant event elements encl LAINABG C C Assistant Director for Operating Reactors 82/05/14 EISENHUT, D Q Division of Licensing 9pp 20921 042
- --B31026007B Summary of 820527 operating reactor events meeting Next meeting scheduled for B20607 Meeting attendess, events discussed & significant event elements encl. LAINABLO C Assistant Director for Operating Reactors 62/06/03 EISENHUT.D G Division of Licensing Bpp 20921 051
- --B310260080 Summary of 820616 operating reactor events meeting Next meeting scheduled for 820623 Meeting attendees, events discussed & significant event elements encl LAINABS Q C Assistant Director for Operating Reactors 82/06/24 RISENHUT, D Q Division of Licensing 9pp 20921 059
- --8310260082 Summary of 820707 operating reactor events meeting Next meeting scheduled for 820721 Meeting attenders, events discussed & significant event elements encl LAINAS: G C Assistant Director for Operating Reactors 82/07/14 EISENHUT, D Q Division of Licensing 7pp 20921 068
- --8310260085 Summary of 820811 operating reactor events meeting Next meeting scheduled for 820825 Meeting attandees, events discussed & significant event elements encl IPPOLITO.T.A Assistant Director for Operating Reactors 82/08/24 EISENHUT.D O Division of Licensing 12pp. 20921 082
- ~~8310260086 Summary of S2D915 operating reactor events maeting Meeting attendses, events discussed & significant event elements encl.

 MIRAQLIA.F J Assistant Director for Operating Reactors 82/09/21. EISENHUT.D Q Division of Licensing 3pp. 20921 094
- ~-8310260089 Summary of 821027 operating reactor events meeting Meeting attendees & events briefing encl
 MIRAQLIA,F. J. Assistant Director for Operating Reactors
 82/10/27. EISENHUT,D 9 Division of Licensing 6pp 20921 108
- --8310260091 Summary of 821216 operating reactor events meeting Meeting attendees & events briefing encl MIRAGILA: F. J. Assistant Director for Operating Reactors. 82/12/20 EISENHUT.D G Division of Licensing 6pp. 20921 123
- --B310260092 Summary of B30113 operating reactor events meeting Meeting attendees & events briefing enti HRAQLIA.F.J Assistant Director for Operating Reactors 63/01/13 EISENHUT.D.G. Division of Licensing 7pp 20921 129

- --8310240096 Describes facility 821203 flood & corrective actions taken Chronology of events encl, including notification of event & procedure for briefing commissioner PERKINS,K E NRC No Detailed Affiliation Given 83/06/08 DEYBUNG,R C Director's Office. Office of Inspection and Enforcement lipp 20921 136 24X Fiche 50-010,83/06/23, 4210240008
- --B\$10260103 "Review Procedure for Routine Insp. Operational Data & LEF., "

 * Office of Nuclear Material Safety & Safeguards, Director
 B\$104/23 9pp 20921 147
- B310260016 FDIA request for matt re Ohmart Corp on 5 offsite radiation-related incidents CARPENTER.T Cincinnati Alliance for Responsible Energy 83/05/18 Region 3, Office of Director ip 20927 001
- 8310260019 Responds to FOIA request for matl re Ohmart Corp on & offsite radiation-related incidents Forwards App A documents App B documents partially withheld (ref FOIA Exemptions & & 7)
 FELTON-J M Division of Rules and Records 83/07/15 CARPENTER, T Cincinnati Alliance for Responsible Energy 10pp 20927 002
- --B202230210 Informs that on 820121,100 mCi Cs-137 sealed source capsule received from 3M company showing 0 01 microcurie of removable contamination Capsule removed & returned to 3M Orginal container decontaminated CODK,H L Ohmart Corp 82/02/12 Region 3, Office of Director ip 20927-359
- --B310260021 Discusses 650614 telcon w/C Stearns re Ohmart gauge numed by DuPont License 07-00465-15 not restricted from installing Dhmart gauges License permits use of matl throughout US except in Agreement States
 ALLAN.J M Atomic Energy Commission 65/06/14 Atomic Energy Commission 1p 20927 012
- --8310260023 Forwards 650611 telegram reporting 650608 Cs-137 contamination Region III investigation concluded occurence not reportable per 100FR20 ALLANIJ M Atomic Energy Commission 65/06/14 ROEDER, J R Atomic Energy Commission ip 20927 013
- --8310260025 Telecopy itr informing of 650608 release of 100 uCi Cs-187 Cleanup complete CDOX:H L Uhmart Corp 65/06/11 ALLAN:J Atomic Energy Commission ip 20927 014
- --8310260026 Insp Findings & Licensee Ack did 620117 of License 34-00639-01 Insp findings rooms & areas not properly posted to indicate presence of radioactive mat! OPARKA, E.J. Atomic Energy Commission 62/01/17 1p 20927 015
- --8310260028 Forwards talegram confirming telcon rept of contamination incident at Ohmart Corp H/o encl RGEDER.J R. Atomic Energy Commission 65/06/17 PAGE.R G Atomic Energy Commission 19 20927 016
- --8310260030 Discusses telcon w/T Brockett re Taylor Chain Co insp rept which Region III requested enforcement action be delayed & investigation of illegal shipments from Ohmart DAVIS.J 9 Atomic Energy Commission 62/11/30 Atomic Energy Commission 1p 20927 017
- --8310260032 Comments on 680623 telcon w/L Cook to inform that 650608 Cs-137 contamination incident was not considered reportable. Requested whole body count to be supplied. FOSTER: D. L. Atomic Energy Commission 65/06/23 Atomic Energy Commission 1p 20927 Oid
- ---B310260033 Discusses inquiry into possible unauthorized possession of 1,000 mCi Sr-90 in beta gauge KIRKHAN,R W Atomic Energy Commission 63/06/26 RADCLOFF,W A Atomic Energy Commission 8pp 20927 019
- --B310260035 Discusses telcon w/R0 Cavanaugh re 630805 & 23 investigations of License 34-00637-01 RADELOFF.W A Atomic Energy Commission 63/09/06 Atomic Energy Commission ip 20727 027
- --831026003B Comments on 650702 teleon w/J Roeder re request that Ohmart Corp submit rept on recent Cs-137 contamination Incident not considered reportable Ohmart will submit rept per Candition i7 of license ALLAN, J M Atomic Energy Commission 65/07/02 Atomic Energy Commission ip 20927 028

- --8310260040 Discusses talcon w/RG Cavanaugh ro investigation of License 74-00439-01
 RADELOFF, W A Atomic Energy Commission 63/08/28
 20927 029
 - Energy Commission
- --B310260043 Confirms that NRC will not correspond w/Ohmart Corp re 650610 investigation concerning damaged 50 mCi Cs-137 sealed source as enforcement action inappropriate No noncompliance HANDLER, R Atomic Energy Commission 65/07/28 Commission 1p 20927 030
- --8310260044 Discusses telcan w/WO Millor to location of file record of 1959 meeting w/Dhmart.JR Mason.Millor & others Dhmart claims to have been told to operate w/byproduct matl-contained gauges RADELDFF, W.A. Atomic Energy Commission 63/08/26 Energy Commission 1p 20927 031 Atomic
- --B310260047 Discusses telcon w/RG Cavanaugh re investigation of Ohmast Corp RADELOFF, W.A. Atomic Energy Commission 63/08/0/ Energy Commission 1p 20927 032
- --B31026004B Ack receipt of 650719 1tr informing of Cs-137 wource rusture TUSTURE
 PAGE.R G Atomic Energy Committation 45/07/20 COUK.R L Ohmort
 Corp ip 20927 033
- --B310260051 Discusses telcon w/W Kerr re L&R definition of developing-testing distribution & demonstrating at Ohmart Corp Permission to rent byproduct matl contained gauges to customers questioned RADELOFF, W.A. Atomic Energy Commission 63/07/17 Atomic Energy Commission 1p 2092/034
- --8310260052 Forwards telegram from Region III re personnel exposure under License 34-00639-01 W/o encl MILLER,M R Atomic Energy Commission 65/11/12 PAGE,R G Atomic Energy Commission ip 20927 039
- --8310260055 Discusses telcon w/RO Cavanaugh re issuance of License 34-00639-01 concerning rental of byproduct matl contained in RADELDIF, W.A. Atamic Energy Commission 63/07/17
 February Commission 1p 20927 036
- --831026055 Comments on 660426 ltr from Ohmart Corp reporting overexposure of employee Region III will investigate matter during next insp ALLAN,J M Atomic Energy Commission 66/04/R8 Atomic Energy Commission ip 20927 037
- --8310260059 Discusses telcon w/RO Cavanaugh re status of Region I investigation concerning Ohmart Corp transfer of 1,000 mCi Sr-90 bets gauge to AVCO Corp RADELOFF.W A Atomic Energy Commission 63/07/17 Ato Energy Commission ip 20727 03B
- --B310260062 Forwards 630626 memos from Region I w/results of investigation at Ohmart Corp & requests add1 investigation W/o encl DUJINSKI,L Atomic Energy Commission 63/07/05 PRICE,E R Atomic Energy Commission ip 20927 039
- --8310250055 Ack receipt of 551027 ltr reporting overexposure of employee PRICE: ER Atomic Energy Commission 66/11/09 KING. J H Ohmart Corp ip 20927 040
- --B310260067 Requests NRC withdrawal of matl attached to 630903 ltr addressed to R Cunningham Matters clarified & acceptable plan of action finalized at 631218 meeting in Bethesda. MD COM. N L Ohmart Corp 63/12/31 PRICE, E R Atomic Energy Commission 1p 20927 041
- --8310260070 Comments on 661121 telcon w/D Griffin to rept stolen 80 uCi radium source in steel capsule on 661118 Police notified MAPPLE T Atomic Energy Commission 66/11/21 Atomic Energy Commission IP 20927 042
- --8310260072 Ack receipt of 631231 ltr re 631218 meeting concerning authorization of installation of equipment containing approduct matte only by employees of Ohmart Corp PRICE, ER Atomic Energy Commission 64/01/27 COOK, H L Ohmart Corp 2pp 20927 043

- --8310260076 Comments on 661121 telcon w/J Peterson re O5 uC1 Sr-90, 50 uC1 radium & O5 uC1 Cs-137 sources stolen from D Oriffin car Matter referred to police ALLAN, J M Atomic Energy Commission 66/11/23 Atomic Energy Commission 2pp 20927 049
- --8310260077 Discusses 640626 telcon w/H Baldwin re lost Co-60 source at Obmart Corp ALLANJ M Atomic Energy Commission 64/06/26 Atomic Energy Commission ip 20927 047
- --831026008i Informs of plans to investigate lost 20 uCi Co-60 source from License 34-00639-01 site RDY,6 W Atomic Energy Commission 64/06/26 Atomic Energy Commission ip 20927 048
- --B310260084 Discusses 640626 telcon w/WA Radeloff re lost 20 uCi Co-60 source from Ohmart Corp Dump & city incinerator will be surveyed on 640626 HILLERM R Atomic Energy Commission 64/06/29 Atomic Energy Commission ip 20927 049
- --8310260087 Comments on 670515 teleon w/HL Cook re corrective steps taken concerning 670426 insp Portion of tag on gauge w/ combination will attach to manual & packing slip FUSTER:D L. Atomic Energy Commission 67/05/17 Atomic Energ Commission 1p 20927 050
- --B310260090 Forwards 670413 ltr from United Kingdom Ministry of Transport describing 670223 release of radioactive matte on SB American Press Investigation of involvement of Ohmart DYRD, H K Transportation, Dept of 67/05/10 BECK, C K Atomic Energy Commission Spp 20927 051
- ---B310260093 Comments on 670519 telcon w/AJ Stevens to arrange joint investigation of compliance of Ohmart Co concerning break up of shipping containers during shipments to United Kingdom FOSTER,D L. Atomic Energy Commission 67/05/19 Atomic Energy Commission 1p 20927-056
- --8310260093 Responds to 670510 request for joint investigation of radioactive math packaging practices of Ohmart Corp Investigation planned for wk of 670603 BECK, C K. Atomic Energy Commission 67/05/25 BYRD, W Transportation, Dept of 1p 20927 037
- ~~8310260099 Forwards 640626 memo re lost source at Ohmart Corp Rept of 640689 investigation in preparation RADELOFF,W A Atomic Energy Commission 64/07/06 Atomic Energy Commission ip 20927 058
- --8310260100 Forwards investigation rept oftd 640710 of Ohmart Corp. License 34-00639-01 W/o encl ALLAN.J M Atomic Energy Commission 64/07/24 ROEDER.J Atomic Energy Commission Ip 20927 061
- --83i0260i02 Submits matter to be reviewed during next insp re high exposure during Fourth Quarter 1973.per 731229 ltr NORELIUS.C E Region 3. Chicago. Office of the Director 74/02/04 Region 3. Chicago. Office of the Director 1p 74/02/04 20927 089
- --8310260105 Informs of loss of 20 uCi Co-60 sealed source on 640601 Caused by inadvertently leaving source in storage box left w/trash collection Procedure for authorizing discard of CODK.H L Ohmart Corp 64/07/15 2pp 20927 062 Atomic Energy Commission
- --8310260107 Notifies of employee overexposure to radiation based on 1973 film badge rept Overexposure occurred while handling variety of Cs-137 sealed sources. Employee reassigned jobs not handling radiation sources Into deleted MING.J H Obmart Corp 73/12/29 Atomic Energy Commission, Directorate of Regulatory Operations 2pp 20927 090
- --B31026010B Discusses 640626 telcon w/HL Cook from Ohmart Corp reporting lost 20 uCl Co-60 sealed source McCarthy & Baseger from Gincinnati General Hosp will attempt to locate source in city dump & incinerator.
 ROY, 0 H Atomic Energy Commission 64/06/26 Atomic Energy Commission 2pp 20927 059.
- --B310260111 Forwards 640724 memo re investigation rept dtd 640710 of Ohmant Corp & 640715 ltr reporting lost source M/o encl RDEDER, J.R. Atomic Energy Commission 64/07/31 PAGE, R.Q. Atomic Energy Commission 1p. 20927 064

- --8310260112 Submits matter to be reviewed re rept of high film badge in Ohmart 741021 ltr Info deleted NORELIUS.C E Region 3. Chicago. Office of the Director 74/11/06 Region 3. Chicago. Office of the Director 2pp
- --8310260115 Discusses insp of Licenses 34-00637-01 t 34-00637-02 on 640612.19 & 29 Noncompliance noted byproduct matl sealed sources not leak tested at intervals of 6 months or less & lead container not properly labeled FRICE.E R Atomic Energy Commission 64/08/06 GHMART.P E Ghmart Corp 2pp 20727 065
- --B310260116 Advises of overexposure of employee to radiation per Sept 1974 film badge rept Overexposure occurred while handling variety of Cs-137 sealed sources Employee reassigned to Jobs not involving handling of radiation sources Info deleted KING. J H Dhmart Corp 74/10/21 Atomic Energy Commissions Directorate of Regulatory Operations 19 20927 094
- --B310260119 Submits matter to be reviewed re high film badge exposure reported in Ohmort 750122 ltr
 NORSELTUS: C.E. Region 3, Chicago, Office of the Director 75/01/27 Region 3, Chicago, Office of the Director 1p 20927 095
- --8310260120 Informs that 670517 memo route slip provided details re package failure of several containers of radioactive matl enroute to United Kingdom from Obmart Corp Region III will visit Ohmart w/DOT on 670605, per request PHILLIP.0 A Atomic Energy Commission 1p 20927 067
- --8310260121 Responds to 640806 itr re noncompliance noted in Licenses 34-00639-01 & 34-00639-02 Corrective actions administrative procedure changes will be initiated within 60 days CDDM,H L Dhmart Corp 64/08/20 PRICE,E R Atomic Energy Commission 1p 20927 068
- --B310260124 Advises of employee overexposure to radiation based on Dec 1974 film badge rept Overexposure occurred while handling variety of Cs-137 sealed sources Employee reassigned to jubs not involving radiation sources Info deleted KING, J H Dhmart Corp 75/01/22 Atomic Energy Commission, Directorate of Regulatory Operations 2pp 20927 096
- --8310260125 Informs that no noncompliance noted during 670605 investigation at Chmart Corp re failure of radioactive matl packaging during shipping Enforcement action inappropriate HANDLER.R Atomic Energy Commission 67/06/30 Atomic Energy Commission ip 20927-069
- --8310260126 Ack receipt of 640820 ltr informing of corrective actions re matters described in 640806 notice concerning Licenses 34-00639-01 & 34-00639-02 PRICE, E.R. Atomic Energy Commission 64/08/27 COOK, H.L. Ohmart Corp. 1p. 20927 070 10
- --8310260127 Forwards rept of investigation w/DDT re packaging of radioactive matl lost at sea Matter considered closed DUBINEKI.4. Atomic Energy Commission 67/07/06 BECK.C K Atomic Energy Commission 1p 20927 071
- --8310260128 Submits matter to be reviewed during next insp re high film badge exposure per Ohmart Corp 750430 ltr * Region 3, Chicago, Office of the Director 75/02/26 Region 3, Chicago, Office of the Director 1p 20927 098
- --8310260129 Requests response to 640827 ltr re corrective actions of matters described in 640806 notice concerning Licenses 34-00639-01 & 34-00639-02 PRICE, E.R. Atomic Energy Commission 64/11/28 COOK, H.L. Obmart Corp. 1p 20927 079
- --B310260130 Comments on joint investigation of shipping damage to Ohmart radioactive mat1 package Inadequacy of cover-plate flange bolts indicates need for more substantive packaging design critaria BECK.C K Atomic Energy Commission 67/07/08 BYRD.W K Transportation. Dept of 1p 20927 074
- --8310260131 Ack receipt of 671127 itr reporting exposure of individuals to radiation. Administrative change noted LOW.L.D. Atomic Energy Commission. 67/12/11 COOK, M.L. Ohmart Corp. ip 20727 075
- --B310260132 Advises of employee overexposure to radiation based on Mar 1975 film badge rept Overexposure occurred while handling various Cs-137 sealed sources Employee reassigned to jobs not involving radiation Info deleted KINO.J H Ohmart Corp 75/04/30 Atomic Energy Commission, Directorate of Regulatory Operations 3pp 20927 099

- --8310260133 Responds to 641125 request for followup rept on corrective actions per 640806 notice Wipe test interval sys data will be placed on addressograph plates CCON.H L. Dhmart Corp. 64712/11 PRICE.E R. Atomic Energy Commission 2pp 20927 080
- --B3(0260135 Comments on 671215 telcon w/L Cook re 671127 ltr concerning 10CFR20 103(b)(1) % (2) interpretations Ltr will be sent to Washington DC for evaluation FOSTER.D L Abomic Energy Commission 67/12/15 Atomic Energy Commission ip 20927 076
- --B310240136 Advises that on 750630 employee film badge recorded overexposure to radiation Add1 info will be forwarded when obtained KELLY,9 Dhmart Corp. 75/06/30 LANERGAN,G T Region 3, Chicago, Office of the Director. 5pp. 20927 102
- --8310260137 Ack receipt of 641211 ltr responding to NRC 640827 & 1125 PRICE: ER Atomic Energy Commission 64/12/17 COOK, H L Ohmart Corp 19 20927 082
- ---B310260138 Advises of 481220 telcon w/E Giebel re discovery of Ohmart Corp label & radiation sign on street in Cincinnati, OH on 681209 Person finding label sustained no radiation bestorsure
 ALLAN.J M Atomic Energy Commission 68/12/27 ROEDER, J R
 Atomic Energy Commission 2pp 20927 077
- --B310R60139 Comments on 750630 telcon w/GT Lonergan re employee overexposure to radiation, based on June 1975 film badge rept film badge may be invalid due to employee exposure to denti x-rays Info deleted LONERGAN. G T Region 3, Chicago, Office of the Director 75/06/30 Region 3, Chicago, Office of the Director 1p 20927 112
- --B310260140 Forwards 630609 telegram from Region III re 65060B containment incident ROEDER, JR Atomic Energy Commission 65/06/11 PAGE, R O Atomic Energy Commission 1p 20927 083
- --8310260142 Comments on 770223 telcon w/F Klein re complaint from former Ohmart employee concerning incorrect training & practices while working w/radiation sources Info deleted PHILLIP, A Region 3, Chicago. Office of the Director 77/03 Region 3, Chicago, Office of the Director 5pp 20727 107 77/03/09
- --8310260144 Ack receipt of 770526 & 0617 ltrs informing NRC of steps taken to correct mancompliance identified in 770511 ltr ROY.6 W Division of Fuel Facility & Materials Safety 77/07/28 COOK.H L Ohmart Corp 1p 20927 113
- --83i0260146 Responds to 770511 ltr re calculated dose received by personnel from Oct 1976 Mar 1977, training program & source handling procedures Trainees will be subj to verbal exam COOK, H L Ohmart Corp 77708726 THOMPSON, D Office of Inspection & Enforcement, Office of the Director 3pp 20927 20927 114
- --8310260149 Supple 770414,0312 & 26 ltrs re noncompliance cond handling unshielded sources & exposure of individuals to radisation Info deleted CODM.H L Dhmart Corp 77/06/17 THOMPSON.D Office of Inspection & Enforcement. Office of the Director 24pp 20927 117
- ---BJio240193 Comments on 490324 telcon w/Q Kelley re lost shipment of 100 mCi Ph-210 source sent to Memorex Corp from Ohmart Corp Rept will be given to US Public Health Svc in Chicago & Cincinnati if TWA can not locate shipment ALLAN.J M Atomic Energy Commission 69/04/04 ROEDER, J R Atomic Energy Commission 29p 20927 072
- --B310260155 Ack receipt of rept submitted per 10CFR20 405, received on KEPPLER, J Q Region 3, Chicago, Office of the Director 79/12/28
 DIRLING, F N Dhmart Corp 1p 20927 142 Dhmart Corp 1p
- --B310260137 Discusses 690626 insp of License 34-00639-01 re leaking 0 3 mCi Cs-137 source Removable contamination found when source leak tested on 690612
 ALLAN:J H Atomic Energy Commission 69/07/25 RDEDER, J R Atomic Energy Commission 1p 20927 084
- --B3iO26015B Informs of 690429 receipt of sealed source w/removable contamination in excess of 005 uCi Vial cap & filter paper replaced KELLY, O A Dhmart Corp 69/06/26 Atomic Energy Commission Lp 20927 085

- --B310260159 Advises that on 800220 personnel drilling through steel squree housing inadvertently ruptured 100 mCi Cs-137 radioactive source Caused by improper procedure Personnel & area decontaminated & new procedures developed DIRLING.F N Chmart Corp 80/03/28 KEPPLER.J G Region 3, Office of Director 15pp 20927 160
- --E310260161 Discusses 481120 memo re State of FL problems w/unauthorized individuals installing generally licensed gauges distributed by Ohmart Corp Ohmart not advising customers of requirement Info deleted ALLAN.JM Atomic Energy Commission 68/11/29 ROEDER.JR Atomic Energy Commission 3pp 20927 177
- --8310260162 Ack receipt of 690626 ltr informing of leak test revealing presence of removable contamination on Cs-137 source RDEDER.J R Atomic Energy Commission 69/07/09 KELLY,O A Dhmart Corp Ip 20927 086
- --B310260163 Responds to 721004 ltr relitems of noncompliance noted in 720913-14 imap Corrective actions add1 safes obtained for storage of sealed sources & leak test forms issued to supervisors responsible for leak tests
 MELLY. G. A. Ohmant Corp. 72/10/23 GRIER. B. H. Region 3, Chicago Office of the Director 2pp. 20927-087
- --8310260164 Informs of RF Warnick 800221 telcon w/individual expressing concern Te friend employed by Ohmart Corp Friend drilled into radioactive source & was contaminated Info deleted PHILLIF, GA Region 3, Office of Director 80/03/07 Region 3, Office of Director 1p 20927 180
- --B310260165 Ack receipt of 721023 ltr informing AEC of steps taken to correct items of noncompliance noted in insp of Licenses 34-00637-01,34-00637-030 & SNM-1071 GRIER.B H Region 3, Chicago, Office of the Director 72/11/02 KELLY.G A Obmart Corp 1p 20727 181
- --8310260167 Informs that 690626 reinsp revealed Dec 1968 leak test of 40 mCi Cd-109 sealed source indicated leaking source Supplier repaired source & returned source to Ohmart On 690510 No further leakage noted ALLAN.J M Atomic Energy Commission 69/07/25 ROEDER, J R Atomic Energy Commission ip 20927 196
- --9310260168 Ack receipt of 730202 ltr Transfer of devices not specifically authorized for transfer to general licensees under License 34-00639-039 may result in noncompliance w/regulations 01ANNELLI.J M Atomic Energy Commission, Directorate of Licensing 73/02/14 KELLY.O A Ohmart Corp 2pp 20927 182
- --B310260169 Notifies that Dec 1968 leak test of 40 mCi Cd-109 sealed source revealed 0 0018 uCi removable contamination Capsule repaired SELLY, G A Ohmart Corp 69/07/08 Atomic Energy Commission ip 20927 197
- --8310260170 Advises of shipment of Model CL-30 Cs-137 gauge to customer prior to NRC approval of request for amend to License 34-00639-030 KELLY, G A Ohmart Corp 73/02/02 MALARO, J Atomic Energy Commission, Directorate of Licensing 2pp 20927 184
- --8310260171 Ack receipt of 690708 ltr reporting detection of removable contamination on Cd-109 source
 RDEDER.J R Atomic Energy Commission 69/07/24 KELLY.¢ A
 Cheart Corp ip 20927 198
- --8310260172 Application to amend License 34-00639-036,ch*nging design of Model CS gauges to incorporate detector housing revs Model CX detector housing replaced w/Model EX-1(8) detector housing KELLY, G A Ohmart Corp 73/02/02 MALARO, J Atomic Energy Commission, Directorate of Licensing 2pp 20727 184
- --8310260173 Advises of 700126 receipt of 25 mCi Co-60 sealed sources w/ removable contamination in excess of QO5 uCi Container returned to Gamma Industries on 700211 KELLY, G A Dhmart Corp 70/02/25 Atomic Energy Commission ip 20927 199
- --8310260174 Ack receipt of 731229 ltr reporting exposure of individual to radiation during Fourth Quarter 1973
 DAVIB.J G Atomic Energy Commission, Directorate of Regulatory
 Operations 74/01/11 KINO.J H Ohmart Corp ip 20927 188

- --8310260175 Forwards 740521 ltr from State of CA & NRC 740604 reply Inquiry into Ohmar. Corp oractices re installation of generally licensed devices requested BLANC.GA Attack Energy Commission, Directorate of Licensing 74/06/07 THORNBURGH D Atomic Energy Commission, Directorate of Regulatory Operations ip 20927 189
- --B31026017& Informs that an 700202 leak test of Co-60 source revealed O 01 uCi removable contamination & O 025 uCi contamination on interior of shipping container ALLAN.J M Atomic Energy Commission 70/03/04 ROEDER.J R Atomic Energy Commission 1p 20727 200
- --B310260177 Responds to 740521 ltr re practices concerning installation of generally licensed devices W/respect to Ohmart Corp, distinction must be made between device being placed in svc & being installed BLANC.0 A Atomic Energy—Commission, Directorate of Licensing 74/06/07 PICKLER,D A California, State of ip 20927-190
- --B310260178 Ack receipt of 700225 1tr informing of detection of removable contamination on Co-60 source ROEDER, J. R. Atomic Energy Commission 70/03/12 KELLY, G. A. Chmart Corp. ip. 20927 201
- --8310260180 Requests info re obligations of distributor of devices under G-type license, per 10CFR32 31 to ensure that device distributed as generally licensed installed by authorized licensee Ohmart Corp policy listed PICMLER.D A California, State of 74/05/21 BLANC, 9 A Atomic Energy Commission ip 20927 191
- --8310260182 Informs of 710513 telcon w/G Kelly re loss of two i uCi Br-90 sealed sources Bources possibly fell on floor & swept away to city incinerator ALLAN.J M Atmoic Energy Commission 71/05/28 RGY.@ W Atomic Energy Commission 2pp 20927 202
- --9310260183 Responds to 711210 ltr re interpretation of installation used in 10CFR31 5 concerning installation of licensed devices by authorized person HARLESS.B & Atomic Energy Commission, 72/01/03 WARD, J California, State of 2pp 20927 192
- --8310260184 Notifies of loss of two 1 vCi sealed sources on 710512 Sources possibly sent to incinerator in trash Branch continuing KELLY,O Ohmart Corp 71/05/12 ALLAN,J Atomic Energy Commission Ip 20927 204
- --8310260185 Comments on interpretation of "install" used in 10CFR31 5(b) (2),per recent NRC ltr re License 12-11184-020 Authorized person must be physically present & supervise installation WARD J C California, State of 71/12/10 MARLESS, B L Atomic Energy Commission 2pp 20927 194
- ~~B310260188 Notifies of loss of two 1 oCi sealed sources on 710512 Sources possibly sent to incinerator in trash Search continuing KELLY.0 Ohmart Corp 71/05/13 ALLAN.J M Atomic Energy Commission ip 20927 205
- --8310260191 Forwards Mobil Chemical Co 710521 & State of FL Dept of Health 710528 ltrs re Ohmert Corp transfer of Cs-137 density gauges to unauthorised recipient HANDLER.R Atomic Energy Commission 71/06/02 ALLAN.R Atomic Energy Commission 3pp 20927 206
- --8310260193 Submits program for correcting apparent mislabeling of certain devices distributed to general licensees under Condition 11A of License 34-00639-030 Authorization to use label, Part 38-21335 in progress KELLY.9 A Ohmart Corp 74/10/31 ALLAN.J Atomic Energy Commission, Directorate of Licensing 2pp. 20927 212
- ---B310260195 Advises of 710512 loss of two 1 uCl Br-90 sources
 Radinactive mat1 mistaken for small pieces of wire
 considered trash.3H Co will separately package & label each
 source in sealed vial
 KELLY, Q A Ohmart Corp 71/05/10 Atomic Energy Commission
 2pp 20927 209
- --B310260197 Forwards Amend 5 to License 34-00639-030 Amend omits provision in Condition 17(c)(3), per 10CFR31 5(d)(4), re sycs involving radioactive matl performed by authorized person H/o encl OlANNELLI.J M Atomic Energy Commission, Directorate of Licensing 73/04/18 KELLY.G A Ohmart Corp. 1p 20927 214

- --8310260199 Ack receipt of 710610 ltr reporting loss of two 1 uCi Sr-90 sources
 LOM-L D Atomic Energy Commission 71/07/08 KELLY G A Dhmart
 Corp ip 20927 211
- --8310260204 Advises of amend to License 34-00639-039 to reflect current
- requirements re labeling of devices to he distributed to general licensess under 10CFR31 5 Related info encl
 BELL.J M Atomic Energy Commission, Directorate of Licensing
 74/10/02 KELLY, J A Ohmart Carp 5pp 20927 215
- --B310260207 Discusses insp of License 34-00639-039 on 741015 & forwards notice of violation ALLANIJM Region 3, Chicago, Office of the Director 75/01/23 COOK, H L Ohmart Corp 2pp 20927 220
- --B310260210 Notice of noncompliance from insp of License 34-00637-03G on 741015 Noncompliance noted seven devices distributed under license in 1974 not labeled to indicate AEC or Agreement State requirements met # Region 3. Chicago, Office of the Director 75/01/23 ip 20927 222
- --B310260213 Comments on 741015 insp of License 34-00639-030 re distribution & installation of generally licensed gauges Uhmart makes distinction between "place in svc" & "Installation" for generally licensed devices ALLAN.J M Region 3. Chicago. Office of the Director 75/01/15 THORNBURGH D Atomic Emergy Commission, Directorate of Regulatory Operations App 20927 223
- --8310260218 Submits instructions for review of unauthorized transfer during imp * Region 3, Chicago, Office of the Director 76/05/10 Region 3, Chicago, Office of the Director 1p 20927 227
- --B310260223 Informs of erroneous distribution of Model BGCD-96 gauge to License 12-02052-01 before application to amend license for shipment added to License 34-00639-030 Model now added to license KELLY.G A Ohmart Corp 76/04/15 BASSIN.N Radioisotopes Licensing Branch (Fre 770501) 1p 20927 228
- --8310260226 Forwards 1tr received from Ohmart Corp re installation of gauge at Joanna Western Mills Co Device installed prior to authorization for distribution to general licensees M/o encl
 SINGER, B Radiolsotopes Licensing Branch (Pre 790501) 76/04/29
 RQY, Q W Office of Inspection & Enforcement, Office of the Director ip 20927 229
- --B310260229 Forwards external ltrs dtd 760511,0608 & 1013 between State of AL & Ohmart Corp re svc & installation of specifically licensed devices by Ohmart Ltrs discuss lack of personnel monitoring equipments survey meter & operating procedures KERR.G H Assistant Director for State Agreements Programs 76/11/10 RDY.G W Office of Inspection & Enforcement, Office of the Director SINGER, B Radioisotopes Licensing Branch (Pre 790501) Spp 20927 230
- --B3i0260234 Forwards draft order to suspend source handling & loading operations under License 34-00639-01 Order based on employee overexposure while handling sealed sources of Various radioactive matis in gauges Addl investigations planned KEPPLER.J G Region 3 Chicago, Office of the Director 77/04/06 THOMPSON,D Office of Inspection & Enforcement, Office of the Director 6pp 20927 238
- --B310260238 Responds to 770407 order suspending License 34-00639-01 Procedures to reduce overexposure while handling radioactive sources listed CODK.H L Obmart Corp 77/04/14 VOLGENAU.E Office of Inspection & Enforcement, Office of the Director 14pp 20727 244
- --8310260240 Order to show cause & order suspending License 34-00639-01 based on employee overexposure while handling scaled accross of various radioactive matis VOLGENAU.E Office of Inspection & Enforcement, Office of the Director 77/04/07 Ohmart Corp 7pg 20927 258
- --8310260243 Forwards draft itr detailing results of inse disclosing three items of noncompliance including overexposure Order to show cause & order suspending license issued to Dhmart on 270407 re violation of source handling activities NORELIUS.CE Region 3. Chicago. Office of the Director 77/05/03 ELLIS.W P Office of Inspection & Enforcement. Office of the Director 8pp 20927 265

- --9310260250 IE [nsp Repts 70-1144/77-01:30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Noncompliance noted individual received overexposure while handling licensed matl & no evaluation made of stremity exposure SCHULTZ:W H , PHILLIP.G A , LONERGAN.G T Region 3. Chicago, Office of the Director 30-5635/77-01 77/05/04 17pp 20927 273
- ---8310260252 Order reinstating License 34-00639-01 due to full effective & prompt correction of violations VOLOENAU.E Office of Inspection & Enforcement, Office of the Director 77/04/18 Ohmart Corp ip 20927 290
- --0310260258 Advises that review of records & procedures to refine doses reveal percentage of personnel receiving calculated overexposure to hands same as reported in 770414 ltr Arrangements made w/local hosp to examine employees COOK.H L Obmart Corp 77/05/12 VOIGENAU.E Office of Inspection & Enforcement, Office of the Director 1p 20927 291
- --B310260265 Discusses IE Insp Repts 70-1144/77-01.30-05634/77-01 & 30-05635/77-01 on 770330-0401 & 11-12 Ltr & insp rept will be placed in PDR unless licensee believes portions are groprietary & should be withheld KEPPLER.J G Region 3. Chicago. Office of the Director 77/05/17 CGOK.H L Ohmart Corp 2pp 20927 292
- ---8310260271 Repts receipt of shipment w/container exceeding 230 MR/HR at surface due to shifing of container inside larger cardboard box Shipper & carrier natified LIVINGSTON.A J Obmart Corp 77/05/23 SCHULTZ.B Region 3, Chicago, Office of the Director 1p 20927 311
- --8310260275 Discusses 770523 telcon w/AJ Livingston reporting receipt of Cs-137 package exceeding Part 20 limits Condition due to lead container shifting in larger cardboard box during shipment SCHULT2,W H Region 3, Chicago, Office of the Director 77/05/29 Region 3, Chicago, Office of the Director 1p 20927 312
- --8310240278 Confirms 770409 telcon re time extension in providing info concerning exposure of Chmart personnel to industrial radiation sources Exam indicates no evidence of radiation injury SAENDER, E.L. Univ of Cincinnati Medical Ctr., Cincinnati. Ch. 77/06/09 ALLAN, J. Region 3, Chicago, Office of the Director io 20927 313
- --B310260280 Ack receipt of 780323 ltr reporting receipt of leaking sources & resultant contamination of soveral tools discovered on 780320 Performance of cleanup operation on tools & return of sources to supplier also ack PACLIARO. J A Region 3, Chicago. Office of the Director 78/04/10 LIVINGSTON. A J Ohmart Corp 2pp 20927-314
- --8310260282 Informs that on 780320, wipe test of Co-60 source, received from Gamma Industries on 771227, revealed presence of 02 uCi removable contamination Subsequently, wipe of tools, equipment & amployees revealed between 001-005 uCi contamination LIVINOSTON, A J Chmart Corp 78/03/23 NRC No Detailed Affiliation Given 2pp 20927 316
- --8310260287 Discusses insp of Licenses SNM-1091,34-00639-01 & 34-00639-039 on 770330-0401 & 11-12 & forwards notice of violation THOMPSON,D Office of Inspection & Enforcement, Office of the Director 77/05/11 COOK.P L Obmart Corp 3pp 20927 310
- --8310260288 Notice of violation from insp on 77030-0401 & i1-i2
 Noncompliance noted licenses used licensed matl in manner as
 to cause individuals in restricted area to receive whole
 body dose in excess of i 25 roms in calendar quanter
 * Atomic Energy Commission 77/05/11 3pp 20927 321
- --8310260295 Forwards comparison of four highest exposures during Aprins & first 2 months of third & fourth quarters Badges U3 & P5 received readings minimal in wks time since Landover repts less than 10 mr gamma.40 mr beta & 20 mr neutron LIVINGSTON.A J Ohmart Corp 7B/01/11 VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 2pp 20927 323
- --83i0260298 Responds to 79i217 ltr forwarding insp rept re shipment of radicattive matls.arriving at Ohmart Corp w/excessive surface radiation level readings W/o stated correspondence to Baltimore.MD ofc requesting investigation MCANDREW.A R Transportation, Dept of, Federal Highway Administration, HMC-II I 80/01/04 KEPPLER.J G Region 3, Office of Director Ip 20927 336

- --0310260300 Telecopy itr informing that on 800220, personnel drilling through steel source housing inadvertently ruptured radioactive source containing 100 mC; insolvable radioactive Cs-137 source Area & personnel decontaminated DIRLING, F Ohmert Corp 83/07/15 WIEDEMAN, D NRC No Detailed Affiliation Given ip 20927 346
- --B310260303 Notifies that in Nov 1979, Uhmart inadvertently shipped one Weight ART 4100 Series scale to Kaiser Cement Corp in CA Caused by misinterpretation of license which authorizes possession of one scale Future shipments to be approved DIRLING, F N Ohmart Corp B0/05/13 SCHULTZ, B Region 3, Office of Director 1p 20927 347
- --8310260317 Notifies that some time in Dec 1981.0hmart Corpinadvertently transferred gauges labeled Densart Series 300.5H-100.Cs-137 & 50 mC: to Fiberboard Corp Transfer not per NRC regulations for stated reasons Related info enc1 FRANKASZEX.J J California, State of 82/04/13 Region 3, Office of Director 4pp 20927 360
- --8316240325 Discuses 650607 telcon w/JM Allan reporting contamination incident occurring at Ohmart Corp on 650608 Incident occurred during unloading of Cs-137 sealed source from gauge Employee unine samples recommended Info deleted RDEDER, J R Atomic Energy Commission 65/06/10 Atomic Energy Commission 1p 20928 004
- --B31026G327 Lists info discussed w/D Foster during 650610 telcon.re Cs-137 contamination Info deleted ALLAN.J M Atomic Energy Commission 65/06/10 Atomic Energy Commission ip 20928-005
- --B310260329 Repts leaking Cs-137 source on 65060B, resulting in spill & contamination of facilities & personnel Facility & personnel decontaminated Info deleted ALLAN.J M. Atomic Energy Commission 65/04/09 ROEDER.J R Atomic Energy Commission 3pp 20928 006
- --83)0260332 Discusses 650609 telcon w/HL Cook re spill from Ce-i37 source, removed from Model SHRM holder, which contaminated personnel & facilities Facility & personnel decontaminated Info deleted ROY.6 W Atomic Energy Commission 65/06/09 Atomic Energy Commission 2pp 20928 009
- --B310260337 Lists questions & responses from 650609 telcon w/L Cook re Cs-137 contamination Info deleted ALLAN, J M Atomic Energy Commission 65/06/09 Atomic Energy Commission 2pp 20928 011
- --8310260338 Discusses 651108 telcon w/HL Cook me film badge mept indicating overexposure of Ohmart employee Overexposure occurred while working w/300 Sr-90 source info deleted ROY. Q W Atomic Energy Commission 65/11/08 Atomic Energy Commission 2pp 20928 013
- --B310260341 Discusses 651107 telcon w/RS Laudauer re film hadge appearing to have been exposed to low energy radiation No svidence on film of damage-contamination or routine reasons for erroneous results into deleted ROY. G W Atomic Energy Commission 65/11/09 Atomic Energy Commission 19 20928 015
- --8310260345 Repts exposure of Dhmart personnel to two 300 mC: Sr~90 sources during wk of 651025 Processor requested to reinterpret film Info deleted ALLAN J M Atomic Energy Commission 65/11/09 RDEDER.J R Atomic Energy Commission 2pp 20928 016
- --B310260347 Repts personnel film badge reading of 49 37 rem beta & 1 28 rem gamma Possible exposure obtained while experimenting w/ 300 mCi Sr-90 Info deleted COOK. H L Ohmert Corp 65/11/09 Atomic Energy Commission 2pp 20928 018
- --B310260351 Forwards telecopy itr reporting exposure of Ohmart employee M/o anci info deleted HILLER. H R Atomic Energy Commission 65/11/12 PAGE.R G Atomic Energy Commission 1p 20928 020

- --8310260354 Notifies that Dhmart Corp 651130 ltr reporting high film badge exposure not placed in FDR as incident not reportable per 10CFR20 405 Individual exposure to radioactive matl in excess of limit doubtful HANDLER.R Atomic Energy Commission 65/12/08 Atomic Energy Commission 1p 20928 021
- --8310260336 Ack receipt of 651130 ltr reporting high film badge exposure PRICE.E R Atomic Energy Commission 45/12/08 COOK.H L Ohmart Corp 1p 20928 022
- --8310260359 Advises that film bedge of employee indicated esposure of 47 57 rem beta & 1 28 rem gamma while handling two 300 mc Sr-90 sources Technician did not receive same exposure as film badge indicated Info deleted CODK, H. L. Ohmart Corp &5/11/30 Atomic Energy Commission 3pp 20728 023
- ~-8310260361 Ack receipt of 660426 ltr reporting exposure of employer to radiation PRICE, E.R. Atomic Energy Commission 66/05/04 XING, J.H. Obmart Corp. ip. 20928-026
- ~-8310260366 Advises of employee radiation exposure for First Quarter 1966 film badge rept Employee received radiation while handling various quantities of Cs-137 sealed sources Info deleted

 KING. J H Dhmart Corp 66/04/26 Atomic Energy Commission 3pg 20928 027
- --8310260372 Advises that 661027 rept of personnel overexposure will be reviewed during next insp Into deleted ALLAN.J M Atomic Energy Commission 66/10/31 Atomic Energy Commission 2pp 20928-030
- --B310260374 Notifies of employer overexposure to rediation in Third Quarter 1966 Radiation occurred while handling gauges containing Cs-137 sealed source Info deleted KING. J H Ohmert Corp 66/10/27 Atomic Energy Commission 2pp 20928 032
- --8310260378 Act receipt of 671127 ltr informing AEC of steps taken to correct noncompliance noted in 671108 ltr & Form AEC-392 M/o stated encl ORIER, B. H. Atomic Energy Commission 67/12/18 COOK, H. L. Ohmart Corp Ip 20928 034
- --8310260384 Advises that rept to Commission re apparent overesposure to employees mailed on 671127 Notice mailed to employee on 671127 CODX.H L. Ohmert Corp 67/11/27 Atomic Energy Commission to 20928 035
- --B3102603B8 Advises of failure to rept two overesposures to personnel due to misunderstanding & oversight Individuals no longer employed by licensee, Info deleted CQOR.-H L. Ghmart Corp. 67/11/27 Atomic Energy Commission 2pp. 20928-036
- --8310260394 Advises of expansion of educational programs & rev to administrative procedures to assure personnel do not receive oversposure to radiation Preliminary wipe test procedure ent!
 COOK.H L Obsert Corp. 67/11/27 BRIER.B H Atomic Energy Commission. Spp. 20928-038
- B310270011 Add1 response to FDIA request for four documents re TMI restart & SECY-83-988 & SECY-83-980 Items 1, 2, 4 % 5 encl Item 3 included within Item 2 Review of Item 6 incomplete FELTOW, J M Division of Rules and Records 83/07/15 DANIELBON, L M HMB Technical Associates ip 20940 309 24X Fiche 50-289,83/07/15,8310270011
- B310270020 Responds to FDIA request for SJ Chilk B30413 memo to MJ Dirchs re alternate plans for test facility accreditation FOWARDS document FELTON-J M Division of Rules and Records B3/07/18 LEAVEY, M E Stone & Webster, Inc. 1p R0943 123
- --B310040261 Herhed-up memo informing that Commission decided not to issue notice of proposed rulemaking on accreditation of qualification testing organizations Specific alternative actions provided CHILK.S J. Office of the Secretary of the Commission. 83/04/13 DIRCKS.H J. Office of the Esecutive Director for Operations 39 20943 125

- 8310270027 Responds to FOIA request for info re licensed medical institutions & private physicians in State of PA Forwards computer printout W/o enci FELTON.J M Division of Rules and Records 83/07/15 GOULDIN,J A Williamsport Hosp Williamsport,PA ip 20940 342
- B310270031 FOIA request for list of private physicians licensed in State of PA
 90ULDIN.J A Williamsport Hosp Williamsport,PA 83/06/20
 ABRAHAM.K Region i. Office of Director 1p 20940 343
- B310270035 FOIA request for all documents containing info re emission of radioactive iodine & other Fission products during accident at facility RODERS, H A Affiliation Unknown 83/06/07 Office of the General Counsel ip 20
- 8310270040 Responds to FDIA request for documents containing info re emission of radioactive iodine & other fission products during reactor accidents Forwards App A documents App B documents can be purchased from NRC FELTON.J M Division of Rules and Records 83/07/06 ROGERS, H A Affiliation Unknown App 20940 345 24% Fiche 50-320,83/07/06.8310270040
- --8310270041 Forwards draft "Comparison of Indine Behavior During TM1-2 Accident M/Predictions Based on WASH-1400 Mathodology " POSTMAIA K Denton City Technology 82/04/13 PASEDAO, W F Accident Evaluation Branch 41pp 20940 347 24X Fiche 50-320,83/07/06,8310270040
- --8310270044 Dreft "Comparison of Iodine Behavior During THI-2 Accident W/Predictions Based on MASH-1400 Hethodology " POSTMA:A K Benton City Technology 82/04/13 40pp 20940 350 24X Fiche 50-320:83/07/06:8310270040
- --8310270045 BMI-2104
 Draft "PRR-Large Dry Containment-Radionuclide Release Under Specific Accident Conditions"

 * Bettelle Mamorial Institute, Columbus Laboratories * Sandia Laboratories B3/02/09 Office of Nuclear Regulatory Research, Director 348pp 20941 028
- 8310270051 Responds to FDIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Document withheld (ref FDIA Exemption 4) FELTON, J. H. Division of Rules and Records 83/07/14 PEDRO, J. NUS Corp. 1p. 20942-016
- 8310270057 FOIA request for "Mestinghouse Advanced PHR Licensing Control Document," dtd Aug 1982, to be placed in PDR Rept referenced at NRC 821180 meeting w/Westinghouse FEDRO, J NUS Corp CD-15-83-021 83/06/08 Division of Rules and Records 1p 20942-017
- MIG270065 FGIA request for draft BNL rept, "Grouping of LHR According to DHR Capability," transcript of B30519 meeting re ATHS rulemaking, transcript of ACRS 830526-27 meeting. LHR hydrogen manual 4 BMI-2104. Vol 2
 HIATT, B L Ohio Citizens for Responsible Energy 83/06/13
 FELTON, J M Division of Rules and Records ip 20942 271
- 310270070 FOIA request for info re nuclear cooperation between US & Bouth Africa, training of South African personnel in UB, sale of nuclear meth to South Africa & strategic value of Bouth African U to UB, for period of 1900-65 KEYTENRING, N E New Heapshire, Univ of, 83/09/08 NRC No Detailed Affiliation Given ip 20942 194
- 6310270071 Responds to FDIA request for five separate categories of documents Forwards App A documents responsive to Items 1:2 & 3 of request Item 4 re LLM hydrogen manual should be published during Sept 1983 Item 5 not available FELTON, J M Division of Rules and Records 63/07/14 HIATT, S L Ohio Citizens for Responsible Energy 2pp 20942 272
- --B310270075 Draft *Grouping of LWRs for Evaluation of DMR Capability MAROLER, FREECD.A., PERKING, M. R. Brookhaven National Laboratory 82/12/31 NRC - No Detailed Affiliation Given 77pp 20942: 278
- B310270074 Responds to F01A request for info re nuclear cooperation between Bouth Africa & UB for period of 1960-63 Forwards documents listed in App A Documents also evailable in PDR DOE should be contacted for further info FELTON, J M Division of Rules and Records B3/10/11 METTENRING, N E. New Hampthire, Univ of, 3pp 20942 195
- --B310370080 Forwards License XR-42 for cancellation M/o encl KELLY.J P Treasury, Dept of, U S Custome Service 1-MIM-JTC 10 66/01/27 Atomic Energy Commission 1p

- --B3102700B4 Export clearance continuation sheet for period 631129-650315

 * Treasury, Dept of, U.S. Customs Service 65/03/15 ip 20942 199
- ---8310270072 Expresses appreciation for expeditious handling of Export License XR-42 ABELL E Allis-Chalmers Corp 63/11/14 CASE E G Atomic Energy Commission 1p 20742 200
- --B310270097 Advises of issuance of amend to License XR-42, increasing total price & extending expiration date to 651231 PRICELE R Atomic Energy Commission 63/11/14 LYGNS, T D Allis-Chalmers Corp 2pp 20942 201
- --B310270100 Authorizes clearance of partial shipment on 631115 against License XR-42, permitting export of nuclear reactor to Bouth Africa Amended license forthcoming PRICE: ER Atomic Energy Commission 63/11/14 COLLIGAN, W Treasury, Dept of US Customs Service 2pp 20942 203
- --8310270105 Application for amend to Export License XR-42 extending date to 651231 & increasing value LYONS.T D Allis-Chalmers Corp 63/11/12 MASON,N D Atomic Energy Commission 2pp 20942 205
- --8310270113 License for Allis-Chalmers Mfg Co to export nuclear reactor to South Africa KIRK,R L Atomic Energy Commission 61/06/14 2pp 20942 208
- --8310270116 Informs of 610620 FR publication of notice of issuance of License XR-42 to Allis-Chalmers Mfg Co.muthorizing export of nuclear reactor to South Africa FREDERICK, R J Atomic Energy Commission 61/06/21 Atomic Energy Commission 1p 20942 209
- --8310270122 Informs of issuance of license to Allis-Chalmers Mfg Co, authorizing export of 20,000 kW thermal nuclear reactor to Bouth Africa
 KIRK: A Latomic Energy Commission 61/06/15 RAMEY, J T Congress (Joint & Rotating Committees, etc.) ip 20942 211
- --B310270127 Forwards, for FR publication, notice of issuance of utilization facility export license to Allis-Chalmers Mfg Go W/o encl # Atomic Energy Commission 61/06/14 EBERHART, D C National Archives & Records Service 1p 20942 212
- --BJ102701J3 Forwards Litense XR-42 issued to Allis-Chalmers Mfg Co. authorizing export of nuclear reactor to Bouth Africa South of South Africa should be advised that litense does not imply Commission assumption of responsibility for safety LOMENSTEIN.R Atomic Energy Commission 61/06/14 HELLS.A.A. Atomic Energy Commission 19 20742 213
- --B310270137 Forwards License XR-42, authorizing export of nuclear reactor to South Africa W/a anci KIRK:R L. Atomic Energy Commission 61/06/14 NICKEL, H C Allis-Chalmers Corp ip 20942 214
- --B310270144 Informs that since no request for formal hearing filed.
 License XR-42 issued to Allis-Chalmers Mfg Co.authorizing
 export of nuclear reactor to South Africa
 LOMENSTEIN.R Atomic Energy Commission 61/06/14 PRICE.H L
 Atomic Energy Commission 1p 20942 215
- --B310270147 Notice of issuance of License XR-42 to Allis-Chalmers Mfg Co.authorizing export of nuclear reactor to South Africa KIRK.R L Atomic Energy Commission 61/06/14 ip 20942 216
- --B310270151 Recommends issuance of license to Allis-Chalmers Mfg Coauthorizing export of nuclear reactor to South Africa HELLS: A A Atomic Energy Commission 61/05/31 LOHENSTEIN, R Atomic Energy Commission 1p 20942 218
- --8310270156 Informs of 610224 FR publication of Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to Bouth Africa FREDERICK, R J Atomic Energy Commission 61/02/28 EDWARDS, C T Atomic Energy Commission 1p 20942 219

- --8310270199 Forwards for FR publication notice of Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa * Atomic Energy Commission 61/02/17 EBERHART, D C National Archives & Records Service 1p 20942 220
- ~-B310270163 Notice of issuance of Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa KIRK,R L. Atomic Energy Commission 61/02/16 2pp 20742 221
- ---B31027016B Informs of receipt of Allis-Chalmers 610106 application for license to export nuclear reactor to South Africa W/o enc. KIRK,R L Atomic Energy Commission 61/02/17 RAMEY,J T Congress (Joint & Rotating Committees, etc.) 1p 20942-223
- ~-8310270170 Forwards Allis-Chalmers Mfg Co 610106 application for license to export nuclear reactor to South Africa W/o encl PRICE.H L. Atomic Energy Commission 61/02/16 HELLS.A A Atomic Energy Commission 1p 20942 224
- ~-B310270174 Forwards FR notice of issuance of application for license to export nuclear reactor to Bouth Africa W/o encl KIRK.R L. Atomic Energy Commission 61/02/16 NICKEL.H C Allis-Chalmers Corp ip 20942 225
- --8310270177 Forwards FR notice of issuance of Allis-Chalmers Mfg Co application for license to export nuclear reactor to Bouth Africa W/o encl MASON, M D Atomic Energy Commission 61/01/26 HUGHEB, W E Atomic Energy Commission 1p 20942 226
- --B310270182 Furnishes info requested by NRC re application for license to export nuclear reactor to Bouth Africa Roberts Const Co will be prime contractor South African Atomic Energy Board will be reactor owner NICKEL.H C Allis-Chalmers Corp 61/01/13 PRICE,H L Atomic Energy Commission 1p 20942 227
- --B310270186 Forwards application for license to export nuclear reactor to South Africa
 NICKEL,H C Allis-Chalmers Corp 61/01/10 PRICE,H.L Atomic Energy Commission 1p 20942 228
- --8310270189 Application for license to export nuclear reactor to South Africa CASPER.R M Allis-Chalmers Corp 61/01/06 4pp 20942 229
- B3102700B2 Responds to FDIA request for successful proposal under RFP EDD-83-436 Requested records nonexistent NRC did not award contract since sycs not required File closed FELTON, JM Division of Rules and Records B3/07/20 NEWMAN, K A Debevoise & Liberman lp 20742 267
- B310270085 F01A request for successful proposal under RFP EDO-83-436.
 "Developing Decisionmaking Rationale for Establishing New Regulatory Requirements"
 NEFMAN.K A Debevoise & Liberman 83/07/14 FRLYON.J M Divisio of Rules and Records ip 20742 270 83/07/14 FRLTON, J M Division
- 8310270089 Responds to FOIA request for Contract NRC-33-83-454 & successful proposal submitted by On-Line Computer 8ys.inc Nonproprietary version available in PDR & filed Under FOIA Request 83-274 (R Dick) FELTON.J M Division of Rules and Records NRC-33-83-454 B3/07/13 MASSENGALE.E W ORL, Inc. 1p 20942 267
- 8310270093 FOIA request for successful proposal & Contract NRC-33-83-494 awarded to On-Line Computer Sys.inc MASSENGALE.E ORI. Inc NRC-33-83-454 \$3/06/16 Division of Rules and Records ip 20742 268
- B310270097 FOIA request for Ocean Data Sys. Inc. (Olobal Weather Dynamics, Inc.) response to RFP RS-MPA-82-319 QLICKMAN, T WBI Corp. B3/06/23 RQBINSON, L. Division of Rules and Records 1p 20942 242
- B310270104 Responds to FOIA request for Ocean Data Bys, Inc/01obal Weather Dynamics, Inc proposal submitted per R8-MPA-82~319 Nonproprietary version of technical proposal can be found under FOIA Request 83-353 located in PDR FELTON, J M Division of Rules and Records B3/07/19 GLICKMAN, T WSI Corp ip 20742 243
- --8310270107 Forwards Proposal 897346 "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrievel Sys." in response to RFF R8-HPA-82-319 Proposal remains valid for 90 days. & Olobal Weather Dynamics, Inc 82/08/27 Division of Contracts ip 20942.244

- -B310270110 Technical Proposal 897346 "Comprehensive Current (Real-Time)
 Geophysical Data Storage & Retrieval Sys." submitted in
 response to RFP RS-MPA-B2-319
 # Global Weather Dynamics. Inc. R8-MPA-82-319 82/08/05 22pp
- 9310270117 Responds to FOIA request for SECY-82-487 & SECY-82-13E to be placed in PDR SECY-82-13E not located TELTON, J M Division of Rules and Records 83/07/15 GRABER, L D NUS Corp is 20942 240
- 8310270121 FOIA request for SECY-82-489 & SECY-82-13E to be placed in PDR GRAMER: L. D. NUS Corp. CD-LIB-7153 83/05/06 and Records 1p. 20742 241 Division of Rules
- 83i0270126 FOIA request for documents to discussions within Commission or communications between E80 & FEMA concerning possible revitor addictogical emergency planning guidance, per NUREO-0654/FEMA-REP-1. ReviteVIN. J. Power Authority of the State of New York BRANDENBURG, B. Consolidated Edison Co. of New York BRANDENBURG, B. Division of Rules and Records 2pp 20942 233
- B310270132 Responds to FDIA request for info re possible rev to radiological emergency planning guidance & info on whether NRC emergency planning regulations appropriate in light of anticipated accident scenarios Forwards documents FELTON, J M Division of Rules and Records 83/07/15 BRANDENBURG. B Consolidated Edison Co of New York, Inc. ip
- --8310270138 Agrees w/actions recommended in 810204 memo Draft memo re emergency planning rule requested Recommendation by B10217 requested AHEARNE, J. NRC No Detailed Affiliation Given 81/02/09 No Detailed Affiliation Given ip 20942 236
- --B310270145 Staff requirements memo re 821110 briefing in Washington.DC on Sandia consequences study Commission briefed on NUREO/CR-2239 (BANDBI-1547). "Technical Quidance for Siting Criteria Development " Vieugraph encl CHILK.B J Office of the Secretary of the Commission H8211108 B2/11/18 DIRCMS,W J Office of the Executive Director for Operations 3pp 20942 237
- 8310270250 Responds to FOIA request for Polk & Schierling 830218 memo to Knighton & Lear re reverification progrem Memo placed in PDR FELTON, J.M | NUS Corp 10 Division of Rules end Records. 83/07/15 BUCKLES, p 20943 065 24X Fiche-50-275,83/07/15,8310270250
- 8310270255 F0IA request for Polk & Schierling 830218 memo to Knighton & Lwar re reverification program to be placed in PDR DUCKLES, R NUB Carp CD-18-83-102 83/06/30 Division of Rules and Records ip 2043 066 24X Fiche 50-275,83/06/30,8310270255
- 8310270262 Second response to FOIA request for NRC mapt on investigation of charges that Bechtel representatives onsite prior to Bechtel momination to conduct independent mpt review Documents in App A available in FDR FELTON, J. H. Division of Rules and Records 83/07/14 ANDERSON, P. Bhaw. Pittman, Posts & Trowbridge 2pp. 20943 067 24X Fiche: 50-358.83/07/14.8310270262
- 83102702B1 Further response to FOIA request for math re enactment of Bection 13(c) of Public Lew 97~41D requiring NRC to undertake pilot program to study two plants where const, GA & QC deficiencies identified. Forwards SECY-83-032A FELTON, J H Division of Rules and Records 83/07/18 HAMLIN, J B Shaw, Pittman, Potts & Trowbridge Ip 20943 071
- --8310270286 SECY-83-032A
 Requests info rept on status of implementation of QA
 initiatives identified in BECY-82-332
 DIRCKB,W J. Office of the Executive Director for Operations
 83/04/21 idep. 20943 072 DIRCKB,W J. Off: 83/04/21 16pp.
- 8310270298 Appeals denial of FGIA request for placement of IE Investigation Rept 1-83-003 in PDR KILCOYNE, J. J. Kilcoyne, J.J. 83/05/31 Office of the Secretary of the Commission. 1p 20942:356. 24X Fiche 50-289,83/05/31.
- 8310270304 Responds to appeal re denial of FOIA request for IE
 Investigation Rept 1-83-003 Forwards document Document also
 available in PDR Portions of rept withheld (ref FOIA
 Exemptions 3 & 7)
 CHILLE J. Office of the Secretary of the Commission,
 KILCOYNE, J. J. Kilcoyne, J.J. 2pp 20742,357 24X
 Fiche 50-287,83/10/03,8310270304

- --8310270324 IE Investigation Rept i-83-003 on 830125-0211 Status closed Major area investigated alleged compromise of preemployment psychological exams CHRISTOPHER R. HAYES, B.B. Office of Investigation 83/02/25 58pp 20
- 8310270340 FOIA request for placement of listed LERs in PDR
 GRABER, L D NUS Corp CD-15-83-324 83/07/08 Division of Rules
 and Records 2pp. 20938 058 24X Fiche 50-000,83/07/08,8310270340
- B310270347 Responds to FDIA request for release of 23 LERs to PDR Forwards 12 LERs to be released Documents also available in PDR One LER canceled Eight LERs not received FELTON, J M Division of Rules and Records 83/09/29 GRABER, L D NUS Corp ip 20938,060 24X Fiche 50-000,83/09/29,8310270347
- --B310270384 LER 83-002/0iT-0 on B30405, spent fuel assembly X-13 dropped back into rack from fully lifted position Caused by cable stress due to limit suitch failure Insp for cladding damage will be conducted W/B30419 itr BARRY, Z E , WILLIAMS, J W Florida Power & Light Co PNS-LI-B3 B3/04/19 0/REILLY, J P. Region 2, Office of Director App 20938 061 24X Fiche 50-000,83/09/29,8310270347
- --B310270339 LER 83-002/05L-D on B30109, power loss in RCIC governor control sys occurred Caused by failed Pacific Electric 70-watt resistor Resistor replaced w/improved design W/B3020B Itr
 YOLLERSON, J. L., HUBOLF, D. Northern States Power Co. 83/02/08 Region 3, Office of Director. 3pp. 2093B 065 24X
 Fiche 50-000,83/09/29,8310270347
- --8310270344 LER 83-003/03L-0 on B30207.RHR loop B made inoperable due to unmaintainable RHR 12 HX differential pressure Caused by piston ring wear Graphite rings replaced w/spring loaded Teflon rings W/830309 ltr CARPENTER.9 L . MUSQLF.D Northern States Power Co 83/03/07 Region G. Office of Director 3pp 20938 068 24X Fiche 50-000.83/09/29.8310270347
- --8310270380 LER 83-004/03L-0 on 830210, measured flow of 3,100 cfm for train B standby gas treatment did not meet min Tech Barc requirement of 3,150 cfm. Caused by cloged demisters.

 Demisters cleaned & procedure will be revised W/830311 ltr IVERSON, 0, MUSDLF, D. Northern States Power Co 93/03/11 Region 3, Office of Director 3pp 20938:071 24x Fiche 50-000.83/09/29,8310270347
- --8310270390 LER 83-007/03L-0 on 830411. **ssential motor control cti 133A feeder breaker tripped Caused by drifted right phase overcurrent trip device Device replaced & breaker reclosed & replaced We30511 ltr HUSOLF.D. Northern States Power Co 83/03/11 Region 3. Office of Director 3pp 20938 074 24X Fiche 50-000.83/09/29, 8310270347
- --8310270410 LER 83-008/03L-0 on 830413, leak in feedwater heater extraction steam trip outlet pipe 15A found. Caused by steam erosion Leaking pipe section replaced & erosion program will be accelerated & amended M/830516 ltr
 MAIER.P MUSCLE, D Northern States Power Co 83/05/13 Region 3, Office of Director 3pp 20938 077. 24X Fiche 50-000. 83/09/29,8310270347.
- --8310270414 LER 83-009/01T-0 on 830504, HPCI Woodward Governor EGR hydraulic actuator coil discovered grounded Caused by faulty wire lead insulation, Emergency generator reactor & HPCI lube oil replaced Sample being analyzed W/830318 ltr WOJCHOUSKI, A. V. MUSDLF, D. Northern States Power Co. 83/05/18 Region 3. Office of Director. 3pp. 20938 080 24X Fiche 50-000, 83/09/29, 8310270347
- -8310270415 LER 82-023/03L-0 on B21121.containment pressure sensing line found capped Caused by personnel error. Units will be labeled W/831230 ltr.
 HUNBTAD, A A Northern States Power Co 82/12/21. Region 3, Office of Director 2pp. 20938 085 24X Fiche: 50-000.83/09/29, 8310270347
 - G10270418 LER 82-026/03L-0 on 821115, turbine driven auxiliary feedwater pump 11 failed to deliver full flow of 200 gpm to steam generators Caused by unscrewed governor valve Valve seat reinstalled & staked in position W/821215 ltr HNNSTAD.A A., MUBOLF,D Northern States Power Co 82/12/15 Region 3 Office of Director. 2pp. 20938 087 24X Fiche 50-000,63/09/29,8310270347.
 - 110270421 LER 83-001/01T-0. on 830204, Exxon ECCS analysis error discovered, Caused by input error into codes W/830218 ltr HJMSTAD, A A , MUSOLF, D Northern States Power Co. 83/02/18 Region 3, Office of Director. 3pp 20938, 089 24X Fiche. 50-000, 83/09/29, 8310270347

- --8310270425 LER 83-007/03L-0 on 830330.steam line radiation monitors discovered inoperable Monitors repaired & surveillance procedure revised to include daily check W/830429 ltr MUSDLF. D. Northern States Power Co. 83/04/29 Region 3. Office of Director 3pp 20938 092 24X Fiche 50-000,83/09/29,8310270347
- --8310270427 LER 83-011/03L-0 on 830510, diesel generator D2 tripped Caused by drift in Dryer pressure switch Model 1822 1 Suitch recalibr HUNSTAD,A A. MUSDLF,D Northern States Power Co 83/05/24 Region 3. Office of Director 3pp 20938 095 24X Fiche 50-000,83/09/29,8310870347
- --8310270429 LER 83-008/03L-0 on 830410, right hand stop valve failed Caused by separation of valve disc from clapper arm disc Valve repaired & will be replaced at mext refueling outage Left hand stop valve also inspected W/830510 ltr HUNSTAD.A A. NUSGLF.D Northern States Power Co 83/05/10 Region 3. Defice of Director 3pp 20938 098 24X Fiche 50-000,83/09/29,8310270347
- B310270355 FDIA request for release of SECY-82-242 & SECY-83-317 to PDR PEDRO. J NUS Carp CD-18-83-247 B3/08/12 Division of Rules and Records 19 20943 295
- 8310270360 Responds to FOIA request for SECY-82-242 & SECY-83-317 Forwards SECY-82-242 SECY-83-317 withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/09/29 PEDRD, J NUS Corp 2pp 20943 296
- --8206240098 SECY-82-242
 Requests Commission approval re mod of NRC regulations involving requirements for fracture taughness of RCPB, including surveillance of neutron radiation embrittlement of reactor vessel beltline matl
 DIRCKS.W J Office of the Executive Director for Operations 82/06/14 39pp 20943 298
- 8310270366 FOIA request for SECY-83-278 & SECY-83-270, transmitting 830624 "Rept on Adequacy & Safety of Relief Valve Testing & Performance "
 WEISS E R Union of Concerned Scientists 83/08/30 FELTON, J
 Division of Rules and Records 1p 20743 128
- 8310270369 Responds to FOIA request for SECY-83-278 & SECY-83-270, transmitting 836624 "Rept on Adequacy & Safey of Relief Valve Testing & Performance "Forwards requested documents FELTON. J M Division of Rules and Records 83/10/04 WEIBS, & R Union of Concerned Scientists 19 20943 129 24X Fiche \$0-289,83/10/04.8310270369
- --B307270430 SECY-B3-278
 Forwards revised certification & noncertification status tables per B30622 request Table 1 revised to clarify inspectatus of certification items for which insperviously noted as not applicable DIRCKS W J Office of the Executive Director for Operations B3/07/11 43pp 20943 130 24X Fiche 50-289,83/10/04,8310270369
- --8307220250 SECY-83-270
 Frovides summary of primary sys relief & safety valve testing & performance since TMI-2 accident per NUREG-0737, Item II D i
 DIRCKB-W J Office of the Executive Director for Operations 83/07/05 122pp 20943 173
- 8310270465 FOIA request for current printouts of computerized steam generator status info & addl summary info on US or foreign steam generator status CONNER. L Doc-Sparch Associates 83/08/29 NRC No Detailed Affiliation Given. ip 20937 242
- 8310270468 Responds to FOIA request for current printouts & interpretive keys of computerized steam generator status info & add1 summary info on US or foreign status Forwards printout & Congressman Markey ltrs Info available in PDR FELTON, J M Division of Rules and Records 83/10/04 CONNER, L Doc-Bearch Associates ip 20937 243
- --8212150242 Forwards util responses to Generic Ltr 82-22 re economic v worker safety aspects of steam generator tube degradation problem per NRC 821027 ltr KAMMERER. C Gffice of Congressional Affairs GL-82-22 82/11/30 HARKEY.E J House of Rep , Interior & Insular Affairs 2pp 20937 327.

- --8212150246 Forwards completed questionnaire in response to Generic itr 82-22, "Congressional Request for Info re Steam Generator Tube Integrity " No major steam generator repairs anticipated in next 5 yrs MUSOLF.D Northern States Power Co GL-82-22 82/11/11 Office of Nuclear Reactor Regulation, Director 2pp 20937 336
- --8212290072 Forwards add1 responses to info requested in 821026 ltr re steam generator integrity (Generic Ltr 82-22) & list of licensees which have & have not responded KAMMERER,C Office of Congressional Affairs GL-82-22 82/12/10 MARKEY,E J House of Rep , Interior & Insular Affairs 3pp 20937 356
- --8310270470 Computer printout of steam generator status info * NRC - No Detailed Affiliation Given 83/10/04 83pp 20937 244
- 8310270496 FDIA request for list of utils accused of making mati false statements from Jan 1975 to present HAFNER, B Suffolk Nuclear Study Group 83/06/27 Office of Administration 1p 20928 353
- 8310270501 Responds to FOIA request for list of utils accused of making matl false statements from Jan 1975 to present Forwards requested list Addl info re listed utils available in PDR FELTON, J M Division of Rules and Records 83/07/28 HAFNER, B Suffolk Nuclear Study Group ip 20928 354
- --B310270505 List of utils accused of making matl false statements from Jan 1975 to present * NRC - No Detailed Affiliation Given 83/07/28 2pp 20928 355
- B310270503 Partial response to FOIA request for documents re emergency operation facilities located 10-20 miles from nuclear plant & documents approving or denying request to locate at distance greater than 20 miles App A documents in PDR FELTON, J M Division of Rules and Records B3/07/28 O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 2pp 20928-357
- 8310270808 Appeals denial of FOIA request for DDE/NRC Form 741 detailing movement of South African origin matl Reasons for confidential nature of Form 741 requested KNAPIKM McGraw-Hill Publications Co 83/06/10 Office of the Executive Director for Operations ip 20928 329
- 8310270512 FGIA request for records relating to commenting on supporting criticizing or otherwise referring to NRC recommendation that emergency operation facilities be lorated at distance between 10 & 20 miles from plant O'NEILL. J H Shaw Pittman, Potts & Trowbridge 83/06/21 Office of Administration 1p 20928 359
- 8310270514 Responds to appeal re denial of FOIA request for DDE/NRC Forms 741 detailing movement of South African origin matl Appeal denied Document withheld (ref FOIA Exemption 4) DIRCKB, W J Office of the Executive Director for Operations 83/07/26 KNAPIK.M McGraw-Hill Publications Co 2pp 20928 330
- 8310270527 FOIA request for three categories of documents re 830404 gas leak at facility AROYROS.D Chamlin, Schottland, Rosen, Cavanagh & Uliano 83/04/22 NRC - No Detailed Affiliation Given lp 20937 224 24X Fiche 50-219,83/04/22,8310270527
- B310270541 Responds to FOIA request for three categories of documents re B30606 gas leak at facility Forwards App A documents FELTON.J M Division of Rules and Records B3/07/22 ARGYROS.D L. Chambin, Schottland, Rosen, Cav
- --8310270547 Submits morning rept for Region I.listing 830606 & 07 events ALLAN.J M Region I. Office of Director 83/06/07 BLAHA.J Program Support Branch 1p 20937 228 24X Fiche 50-000. B3/07/22,8310270541
- B3i0280071 FOIA request for AEOD rept. "Loss of Shutdown Cooling & Subsequent Roron Dilution at San Onofre 2." dtd 830425 & info re fuel rod degradation problem described in IE Info Notice 82-27
 HIATTS L Ohio Citizens for Responsible Energy IEIN-82-27
 B3/04/29 FELTON, J M Division of Rules and Records 1p
 20942 195 24X Fiche 50-341,83/04/27,8310280071

- 8310280079 Responds to FOIA request for AEOD rept. "Loss of Shutdown Cooling & Subsequent Boron Dilution at Sam Onofre 2," 6td 830425 & documents re fuel rod degradation problem described in IE Info Notice 82-27 Forwards App A documents FELTON, J M Division of Rules and Records 83/07/28 HIATT, 8 L Onio Citizens for Responsible Energy 2pp 20962 136 24X Fiche 50-000,83/07/28,8310280079
- --8305030115 Forwards "Loss of Shutdown Cooling & Subsequent Boron Dilution," engineering evaluation rept CINTULAIT C Reactor Operations Analysis Branch AEOD/E310.83/04/25 SEYFRIT.K V Reactor Operations Analysis Branch 1,
- --B305030120 AE0D/E310
 "Loss of Shutdawn Cooling & Bubsequent Boron Dilution."
 engineering evaluation summary
 » Director's Office 83/04/25 i3pp 20962 240 24x
 Fiche 50-000.83/07/28.8310280079
- --B305i60184 Forwards draft IE info notice on possible safety concern to all PWRs re encl engineering avaluation rept on 8303i4 & 24 loss of shutdown cooling & subsequent boron dilution HELTEMES, C. J. Docketing & Services Branch 83/05/06 JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 19 20962 238 24X Fiche 50-000, 83/07/26, 8310280079.
- --8310280132 Forwards IE Circular 80-17, "Fuel Pin Damage Due to Mater Jet From Baffle Plats Corner," for issuance on 800723 Draft transmittal itr also encl MOSELEY, N. C. Division of Reactor Operations Inspections 80/07/21 GRIER B.H. Region 1, Philadelphia, Office of the Director O'REILLY, J.P. Region 2, Atlanta, Office of the Director KEPPLER, J.9 Region 3, Chicago, Office of the Director 2pp 20962 163
- --8310280136 Forwards safety evaluations prepared by licenses & Region V re loose fuel pellets & clad pieces in RCS GREWB.J L Division of Resident Reactor Project & Engineering Programs 82/07/22 CLARK-R Operating Reactors Branch 3 4pp 20762 220 24% Fiche 50-000.83/07/28.8310280079
- --B3102B013B Safety evaluation re loose fuel pellets & clad pieces in RCS Strong evidence exists that no more than 20 pellets remain in RCS Licensee performed comprehensive evaluation of proposed operation Related info encl * Region 5. Office of Director B2/07/21 12pp 20762 226, 24% Fiche 50-000, B3/07/28, B310280077
- --B3102B016B LER 50-266/75-18 on 751217, during Cycle 3-4 refueling, discovered section of fuel rod missing Caused by water impingement through baffle plate while failed assembly in Cycle 2 position H-: Investigation in progress W/751230 ltr BOBE, P £ , BURSTEIN.S Wisconsin Electric Power Co 75/12/30 RUSCHE, B C Office of Nuclear Reactor Regulation, Director 10pp 20962 203 24X Fiche 50-000,83/07/28,8310280079
- --831028017: LER 50-266/76-12 on 761222.wall cladding defects noted in one rod of fuel assembly 007 Caused by rod vibrating against rod retaining grid springs Peening of core baffle plate joints: completed in Nov 1976; should prevent recurrence BUBE.P E Wistonsin Electric Power Co 77/01/04 3pp 20762 263 24X Fiche 50-000.83/07/28.8310280079
- 8310280169 Appeals partial denial of FQIA request for correspondence between Chairman Palladino & DOJ re investigation of alleged falsification of RCS leak rate tests VQIOT.H H LeBopuf. Lamb. Leiby & MacRas. 83/09/19. CHILK.S. J Office of the Secretary of the Commission 2pp 20965 055 24X Fiche 50~289.83/09/19.8310280169
- 8310280172 Responds to appeal re partial denial of FOIA request for correspondence between Chairman Palladino & DDJ re investigation of alleged falsification of RCS leak rate tasts. Info partially withheld (ref FOIA Exemption 3) CHILKS J Office of the Secretary of the Commission 83/10/14 VDIOT.H H LeBosuf, Lamb, Leiby & MacRae 2pp 20965-057 24X Fiche 50-287,83/10/14.8310280172
- --8310280179 Comments on questions raised in 830517 ltr to Chairman Palladino re communication between agencies DGJ should commit to completion date for investigation Supporting documentation encl CUMMINOS.J.J. Office of Inspector & Auditor 83/05/31, JENSEN,D L. Justice, Dept of 4pp 20945 064 24% Fiche 50-289,83/10/14.8310280172
- B310280174 F0IA request for all internal nonpublic documentation reconst flaws & improper conduct by inspectors, util contractors or subcontractors MCINNIS D News & Observer B3/07/19 FELTON, J Division of Rules and Records ip 20963 287 24X Fiche 50-400, B3/07/19, 8310280174.

- 8310280176 Responds to FOIA request for internal nonpublic documentation re const flaws & improper conduct of ARC inspectors & util contractors or subcontractors Forwards documents listed in App A FELYON, J M Division of Rules and Records 83/09/23 VADEN, T News & Observer 3pp. 20963:288 24X Fiche 50~400,83/09/23.8310280176
- --8310280173 Documents 0 Zacher 790212 request for current status of remand hearing & NRC actions to recommendations in Ofic of Inspector & Auditor rept Recommendations will be adopted FOBTER.NH Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor 79/02/13 Office of Inspector & Auditor. 1p 20963 291 24X Fiche 50-400,83/09/23,8310280176
- --B310280197 Forwards draft Ofc of Inspector & Auditor 781109 rept on inquiry into alleged omission of line inspector views from CP hearing, for perusal W/o encl MURRAY, J P Deputy Executive Legal Director 78/12/18 CUMNINGS, J D Office of Inspector & Auditor 3pp 20963 292 24X Fichs 50-400, 83/09/23, 8310280176
- --8310280202 Documents telcon w/FC Cantrell re insp file in preparation for testimony Instructions not received to review fils Cantrell relied solely on personal notes & records to prepare testimony FOSTER-WH Office of Inspector & Auditor 78/11/01. Office of Inspector & Auditor 78/11/01. Office of Inspector & Auditor 1p. 20963.295 24X Fiche 50-400.83/09/23, 8310280174
- --8310280207 Advises that ASLAB Chairman, AS Rosenthal will decline interview, claiming purposelessness FOSTER, WH Office of Inspector & Auditor. 78/10/26. Office of Inspector & Auditor. 78/10/26. Office of Inspector & Auditor. 78/10/26. 83/09/23, 8310280176
- --8310280211 Advises that IE Manual Chapter 94010-8 only written policy for preparing testimony for licensing hearings.per 781025 taicon w/RC Paulus FOBTER.W H Office of Inspector & Auditor 78/10/26. Befice of Inspector & Auditor 19 20963 297 24X Fiche 50-400.83/09/23.8310280176
- --B310280214 Forwards AS Rosenthal 781024 memo to QG Abston for perusal ABBTON 0 9 Office of Inspector & Auditor 78/10/25 HENDRIE, J M Commissioners 1p. 20969 298 24X Fiche 50-400,83/09/23,8310280176
- ---B310280218 Advises that ASLAB members not willing to be interviewed due to possible future involvement in case
 ROBENTHALIAS Atomic Safety and Licensing Appeal Panel
 78/10/24 ABBTON, D @ Office of Inspector & Auditor. ip
 R0963-299, 24X Fiche 50-400,83/09/23,8310280174
- -- 8310280222 Requests interview w/ASLAB members to discuss impact of unission of line inspector views from written & oral tastimony ABBTON.0 9. Office of Inspector & Auditor 78/10/24 RDSENTHALA 8 Atomic Safety and Licensing Appeal Panel. ip 20963 300. 24X Fiche.50-400,83/09/23.8310280176.
- --8310280225 Forwards info re Dfc of Inspector & Auditor interview of ASLAB (ref yore 781019 memo to Commissioners) FRYE.J H Atomic Safety and Licensing Board Penel 78/10/20. RGSENTHAL.A , KELLEY.J L , ABSTON.0 C. NRC No Detailed Affiliation Given 1p. 20963 301 24X Fiche: 50-400, 83/09/23, 8310280176.
- --8310280236 Forwards DH Gamble 781017 memo, for Interest. ABBYON.0 9 Office of Inspector & Auditor 78/10/20 HENDRIE, J. M. Commissioners ip 20963 312 24X Fiche: 50-400,83/09/23,8310280176.
- --8310280238 Summarizes A Rosenthal 781019 telcon opposing potential interview w/ASLAB members, citing unpleasantness of ASLB interview Ofc of Inspector & Auditor must assure different line of questioning before interview is granted.

 GAMBLE, D. H. Office of Inspector & Auditor, 78/10/19, Office of Inspector & Auditor, 78/10/19, Office of Inspector & Auditor, 2pp 20969:313 24X Fiche.50~400.83/09/23, 8310280176
- --8310280242 Forwards documentation of 781017 conversation w/JM Vareia, former AEC employee me V Brownlee Conversation connected w/ current investigation, DAVIS.J.O Director's Office, Office of Inspection and Enforcement, 78/10/19 ABBTON,O O, Office of Inspector & Auditor ip, 20763.315 24X Fiche 50-400,83/09/23,8310280176

- --B310280244 Documents 781017 conversation w/J Varela, former Region II employee. Brownlee directed Varela to change info in insprept, causing dispute DAVIS, J O Director's Office of Inspection and Enforcement 78/10/19 Director's Office, Office of Inspection and Enforcement 1p 20963 316 24X Fiche 50-400,83/09/23, B310280176
- --8310280246 Documents 781017 conversation w/C Barth (DELD) re testimony forwarded to ASLB before 771004 hearing ASLB should be required to read testimony before hearing FOSTER, W A Office of Inspector & Auditor 78/10/18 Office of Inspector & Auditor 78/10/18 Office of B310280176
- --831028024B Advises of Oft of Inspector & Auditor inability to procure useful info during interview W/ASLB due to ASLB unresponsiveness ABBTON.0 9 Office of Inspector & Auditor /8/10/17 HENDRIE.J M , GILINGKY.V , KENNEDY.R T Commissioners 2pp 20763 324 24X Fiche 50-400,83/09/23.8310280176
- --8310280250 Advises that HA Wilbur perusal of Dance testimony disclosed no ref to QA problems listed in subj insprepts FOSTER. WH Office of Inspector & Auditor 78/10/10 Office of Inspector & Auditor 78/10/10 Office of B310280176
- --8310280254 Forwards case assignments for ASLB members QO Bright, JV Leeds & IN Smith,per request FITTLC J Atomic Safety and Licensing Board Panel 78/10/06 GAMBLE, D H Office of Inspector & Auditor 6pp 20943 327 24x Fiche 50-400,83/09/23,8310280174
- --B310280256 Forwards Acting General Counsel opinion indicating no ex parts problem w/DFc of Inspector & Auditor interview of ASLB members ABSTON, D 0 DFfice of Inspector & Auditor 78/10/03 YORE, J R . ROSENTHAL. A 3 Atomic Bafety and Licensing Board Panel ip 20943 333 24X Fithe 50-400,83/09/23,8310280176
- --8310280259 Informs of 781003 conversation w/I 8mith of ASLB re Ofc of Inspector & Auditor interview w/ASLB members, to fulfill Commission order Interview will probably not be granted due to ax parte rule FOSTER, W H Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 78/10/03 Office of Inspector & Auditor 78/10/03 Office of S10280176
- --8310280263 Summarizes continued attempts to gain ASLB interview through 780927 conversation w/JV Leeds Leeds will not cooperate. citing ex parts rule FOSTER, W.H. Office of Inspector & Auditor 78/09/27 Office of Inspector & Auditor 2pp 20943 334 24X Fiche 50-400, 83/09/23, 8310280176
- --B3102B0265 Informs of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries VORBE.J Y. Office of Investigation 02-B3-011 83/03/04 ALBERGON.C Y NRC NO Detailed Affiliation Given 1p 20963 33B 24X Fiche 50-400.83/09/23.83102B0176
- --8310280270 Discusses alleged improprieties re deficiency discrepancy repts & corresponding logbook entries
 BURCH.R H Office of Investigation Q2-83-011 83/03/03
 Office of Investigation 1p 20763 339 24X
 Fich: 50-400,83/09/23,8310280174
- --8310280299 Advises that no new info revealed after inquiry of alleged improprieties re deficiency discrepancy repts & corresponding logbook entries VORSE, J Y Office of Investigation 02-83-011 83/05/06 TODD, G NRC No Detailed Affiliation Given 1p 20963 340 24x Fiche 50-400,83/09/23.8310280176
- --8310280303 Advises that inquiry into alleged improprieties re deficiency discrepancy repts & corresponding logbook entries closed Util cited for violation BURCH,R H Office of Investigation Q2-83-011 83/05/04 Office of Investigation ip 20963 341 24X Fiche 50-400,83/09/23,8310280176
- G310280183 Appeals partial denial of FDIA request for four categories of info re Cakeload Forecast Panel 830330-01 meeting & site visit.

 FALKENHEINER, D. Leuisiana Consumer's League, Inc. FALKENHEINER, D. Falkenheiner, D. B3/09/01. Office of the Executive Director for Operations 2pp. 20963-342 24X Ficha 50-458,83/09/01.8310280183

- BOIG280189 Responds to appeal re partial denial of FOIA request for four categories of info re Caseload Forecast Panel 830330-31 meeting & site visit forwards tomplete version of requested documents
 DIRCKS. W J Office of the Executive Director for Operations
 BO/10/18 FALKENHEINER, D Falkenheiner, D ip 20963 344 24K
- --8310280199 Calculations re facility components Supporting documentation encl * Qulf States Utilities Co 83/03/30 lipp 20963 350 24X Fiche 50-458,83/10/18,8310280189
- BOIO280204 Appeals denial of FDIA request for Oft of Investigation repts re allegations concerning presence of Bachtel representative at facility prior to Nov 1982 BEVINE: T Government Accountability Project 83/06/16 CHILK, S J Office of the Secretary of the Commission 2pp 20984 192 24X Fiche 50-358, 83/06/16, 8310280204
- 8310260212 Responds to appeal re denial of FOIA request for Ofc of anvestigation repts concerning facility Grants appeal in part Forwards document Info partially withheld (ref FOIA Esemption 7)
 CHILK, B.J. Office of the Secretary of the Commission B3/08/24
 DEVINE. T. Government Accountability Project 2pp 20964 198 24x
 Fithe B0-358,83/08/24,8310280212
- --B3102B0220 IE Investigation Rept H-83-00) on 830120-0301 No noncompliance noted Major areas investigated allegations re-presence of Bechtel representatives at facility prior to Nov 1982 Affidavit encl Info deleted GILBERT, E. C., WARD, W. J., HAYES, B. B. Office of Investigation 83/03/11 60pp 20964 205 24X Fiche 50-358, 83/08/24, 8310280212
- --B310280224 Submits revised proposal for providing completion svcs for facility Rev to proposal, originally submitted on B2110B. responds to Commission B21122 order to show cause List of independent review team members encl
 REINSCH.H O Dechtei Corp B2/11/23 DICKHONER.W H Cincinnate Oas & Electric Co 7pp 20944 265 24% Fiche 50-358.83/09/24.8310280212
- --B310280229 Supple 821123 ltr in response to JG Keppler 821228 request. directed to util, re Bechtel mpt role Soderholm involvement discussed WAHL. H W Bechtel Corp. 82/12/29 DICKHONER, W H Cincinnati Gas & Electric Co. 6pp. 20964 296. 24X Fiche 50-358, 83/08/24, 8310280212
- --8310280231 Forwards description of steps to be taken to identify necessary organizational & procedural action.resumes Of Phase I team members, summarizes of Bechtel nuclear experience & contract forms Info deleted REINSCH.H O Bechtel Corp 82/11/00 DICKHONER,W H Cincinnat Gas & Electric Co ABpp 20964 308 24X Fiche 50-358.83/08/24,8310280212
- ~-8310280220 IE Investigation Rept H-83-001 on B30120-0301 No noncompliance noted Major areas investigated allegations re presence of Bechtel representatives at facility prior to Nov 1982 Afridavit encl Info deleted GILBERT.E C , WARD.H J , HAYES.B B Office of Investigation. B3/03/11 60pp 20964 203 24X Fiche 50-358,83/08/24,8310280212
- --8310280224 Submits revised proposal for providing completion type facility Rev to proposal, originally submitted on 821108, responds to Commission 821122 order to show cause List of independent review team members encl
 REINSCH. H O Bechtel Corp 82/11/23 DICKHONER, W H Cincinnati
 Gas & Electric Co. 7pp 20964 265 24X Fiche 50-358,83/08/24,8310280212
- --8310280229 Supple Bill23 ltr in response to JO Keppler 821228 request. directed to util re Bechtel mgt role Soderholm involvement discussed WAHL.H W Bechtel Carp 82/12/29 DICKHONER.W H Cincinneti Gas & Electric Co App 20964, 296 24% Fiche 50-358, 83/08/24, 8310280212
- ~~B3102B0231 Forwards description of steps to be taken to identify necessary organizational & procedural action, resumes of Phase I team members; summarizes of Bethtel nuclear experience & contract forms Info deleted REINBCH. H O Bethtel Corp B2/11/08 DICKHONER. H H Cincinnations & Electric Co 48pp 20964 308 24X Fiche 50~358.83/08/24.8310280212
- B310310017 FOIA request for documents re integrated leak rate tests for listed facilities to be placed in PDR CDNNER: L Affilation Unknown B3/05/02 NRC - No Detailed Affiliation Given ip 21004 270 24X Fiche 50-000, B3/05/02, B310310017

- B310310031 Responds to FOIA request for documents re integrated leak rate tests for facilities to be placed in PDR Forwards documents to be placed in PDR & list of facilities for which repts are unavailable FELTON-14 M Division of Rules and Records B3/07/06 CONNER.L Affiliation Unknown ip 21004 271 24X Fiche 50-000:B3/07/06:8310310031
- --8310310056 "Reactor Containment Bldg Integrated Leak Rate Test "

 * Nebraska Public Power District 76/11/30 250pp 21004 272
 24% Fiche 50-000.83/07/06.8310310031
- --8310310058 "Integrated Leak Rate Tost Computer Program for Primary Containment" * Power Authority of the State of New York 74/03/20 100pp 21005 179 24X Fiche 50-000.83/07/06.8310310031
- ---B310310061 YAEC-1055
 "Integrated Primary Containment Leakage Rate Test "
 TARNUZERE C Vermont Yankee Nuclear Power Corp 72/02/07
 67pp 21005 280 24% Fiche 50-000.83/07/06.8310310031
- --8310310064 "Reactor Containment Bldg Integrated Leakage Rate Test Rept " W770628 ltr ULIRICH,W T Philadelphia Electric Co 77/04/04 109pp 21005 313 24X Fiche 50-000.83/07/06.8310310031
- ~-B3i0310067 "Reactor Containment Bldg Integrated Leak Rate Test." summary technical rept ROMAN.H D Epasco Bervices, Inc (subs of Enserth Corp J 76/02/14 56pp 21006 065 24X Fiche 50~000.B3/07/06.B310310031
- ~-8310310068 Operating Procedure 13100 1, "Integrated Leak Rate Test "
 ROMAN.H D Ebasco Services, Inc (subs of Enserch Corp)
 75/11/01. 200pp 21006 159 24X Fiche 50-000.83/07/04,
 8310310031
- --8310310070 "Containment Leak Rate Tests." Type B & C test repts * Florida Power & Light Co 76/02/14 9pp 21006 325 24X Fiche 50-000,83/07/06.8310310031
- --8310310072 "Reactor Containment Bldg Integrated Leak Rate Test" W/730612 ltr + Hillstone Point Co 73/03/31 120pp 21006 334 24X Fiche 50-000,83/07/08.8310310031
- --83i03i0073 Forwards "Reactor Containment Bldg Integrated Leak Rate Test" including analysis & interpretation of Type A test results & summary analysis of Type B & C tests performed since last Type A test in Oct 1972 WHITE, L B Rochester Gas & Electric Corp 76/05/19 PURPLE,R A Office of Nuclear Reactor Regulation, Director ip 21007 098 24X Fiche 50-000,83/07/06,83103f003f
- ~-8310310076 "Reactor Containment Bldg Integrated Leak Rate Yest "
 * Rochester Gam & Electric Corp 76/02/28 120pp 21007 096
 24X Fiche. 50-000, 83/07/06, 8310310031
- --B310310077 "Reactor Containment Bidg Integrated Leak Rate Test "
 # Indiana & Michigan Power Co 75/02/26 47pp 21007 215 24x
 Fiche 50-000.83/07/06.8310310031
- ~-8310310080 "Reactor Containment Bldg Integrated Leak Rate Test (Preoperational) "
 # Indiana & Michigan Power Co * American Electric Power Co .
 Inc 78/04/10 12ipp 21007 283 24X Fiche 50-000.83/07/06,
 8310310031
- B310310063 F0IA request for documents re const & operation of C-E plants List of info required submitted BELL-N Coalition for Bafe Power B3/03/31 Office of Administration 1p 2099B 173 24X Fiche 50-000 83/03/31.
- 8310310076 FDIA request for SECY-82-7,82-121,82-141,82-141A,82-168,82-221,82-243,82-251,82-460,82-466,82-483,83-30,83-44,83-72,83-73 & 83-105 to be placed in PDR BHOLLY,9 C Union of Concrined Scientists 83/07/14 FELTON,J M Division of Rules and Records. 2pp 21000-144
- B310310097 Responds to FQTA request that 14 SECYs be placed in PDR Forwards App A documents SECY-B2-466 withheld (ref FQTA Exemption 5) FELTON.J M Division of Rules and Records 83/09/19 BHOLLY, 8 C Union of Concerned Scientists 3pp. 21000 146 24% Fiche 50-320,83/09/19,8310310097

--8203120050 SECY-82-077

203120050 SECY-B2-077
Informs Commission of NRC progress in developing criteria & strategies re use of potassium iodide (KI) to block thyroid gland in event of accidental release of radioiodine Validity of distribution of KI to general public questioned DIRCKS, W J Office of the Executive Director for Operations 82/02/19 11pp 21000 256

--8204070171 SECY-82-121
Advises of current status of studies assessing potential technical, regulatory & socioeconomic impacts of proposed alternatives for accident water disposition
Office of the Executive Director for Operations 82/0
13pp 2:000 149 24X Fishe 50-320.83/09/19.8310310097

--8205050588 SECY-82-168

205050598 SECY-62-148
Informs of revision of 10CFR20 stds for protection against radiation, & efforts to ascertain adverse technical & economic impacts on NRC & licensee of revised regulation Comparison of 10CFR20 salient issues w/alternatives encl DIRCKS.W J Office of the Executive Director for Operations 82/04/21 8pp 21000 169

---8206100323 SECY-82-221
Forwards study re NRC role in contested nuclear power reactor initial licensing proceedings Study concludes that different "neutral" NRC role should be adopted on trial basis in selected cases
BICKMIT.L. Office of the General Counsel 82/06/03 68pp 21000 177

---B206250316 GECY-B2-251
Provides Commission w/rept re property insurance for decontamination of nuclear reactors as published in NUREG-0891
DIRCKS,W J Office of the Executive Director for Operations
82/06/16 4pp 21000 248

--B206300342 SECY-B2-243
Informs Commission of status of NRC activities re development of improved safeguards info sys DRRCKS,N J DPfice of the Executive Director for Operations B2/06/10 3pp 21000 245

--8211270108 SECY-82-460 Informs Commission of historical & current rates of license issuance & exam failures for reactor operators & senior DIRCKS,W J Office of the Executive Director for Operations 82/11/17 4pp 21000 252

--B302160056 SECY-B3-044

Submits alternatives for scope of guidelines for post-accident recovery in event of nuclear-related accidents Recommends deferment of plan development until completion of severe accident & source term research DIRCKS.W J Diffice of the Executive Director for Operations B3/01/31 16pp 21000 276

|304220088 SECY-83-126 Requests approval for publication of proposed rule ensuring that certain contractors & subcontractors of IOCFR50 licensees post NRC Form 3 DIRCKS.W J Office of the Executive Director for Operations 83/04/06 4pp 21000 162

-8310310116 SECY-82-141A
Informs of historical & current rates of license issuance & sam failures for reactor & senior reactor operators
Supporting data encl Failure rates of 27% & 25% for reactor operator & senior reactor operator.respectively noted.
DIRCKGN J Office of the Executive Director for Operations
83/08/23 3pp 21000 166

-8310310131 SECY-82-483
Informs of present status of TMI-1 restart certification affort & provides update on NUREC-0737 items status
DIRCKSH J Office of the Executive Director for Operations
82/12/09 16pp 21000 260 24X Fishe 50-289.83/09/19.831031009/

-8310310136 SECY-83-072
Informs of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operator Pess/fail rate remained consistent throughout Third Quarter FY82
DIRCKS.W J Office of the Executive Director for Operations 83/02/18 4pp 21000.292

-8310310140 8ECY-83-093
Transmits INPO "Performance Objectives & Criteria for Componate Evaluations" & informs of plans to defer further action on THI Action Plan Item I B i 1 M/o encl DIRCKS,W J Office of the Executive Director for Operations, 83/03/09 3pp. 21000-296

GEN TEC IS GENERIC TECHNICAL ISSUES

8310030308 Forwards response to 830816 memo re 830125 main feedwater line break Response based on NUREG-0918, NUREG-0691 & proposed rev to Jan-Mar AO rept DIRKKS,W J Office of the Executive Director for Operations 83/09/21 ASSELSTINE,J K Commissioners 13pp 20404 039 Fiche 50-309,83/09/21,8310030308

--830A020357 Operating Reactor Event Memorandum 83-01 re B30125 loss-of-main-feedwater event which resulted in rupture of main feedwater line 2 Plant-specific PRA studies addressing Generic Issue A-Ol on water hammer recommended E19ENHUT.D 0 Division of Licensing B3/05/20 SPCIS.T Division of Bafety Technology VOLLMER.R Division of Engineering MATTSON.R Division of Systems Integration (post 811005) 17pp 20404 052 24X Fiche 50-309,83/09/21.831003030308

--8310030316 Requests responses to listed questions re main feedwater line break due to water hammer ABSELBTINE.J K Commissioners 83/08/16 DIRCKS,W J Office of the Executive Director for Operations 3pp 20604 071 24X Fiche 50-309.83/09/21.8310030308

8310030641 Forwards Alden Research Lab 830916 test results re transport of reflective metallic insulation Completed evaluation will be used for resolution of Unresolved Safety Issue A-43, "Containment Sump Performance "
KNIEL K Generic Issues Branch 83/09/23 FARRAR, D L
Commonwealth Edison Co 87ALAY, R Atomic Industrial Forum BUDZIK, D M Consumers Power Co 2pp 20626 293

--8310030645 Forwards summary of results of transportation tests on pipe insulation sample Test results on foil sheets not yet receives BROCARD,D N Alden Rosearch Laboratory 83/09/16 SERKIZ,A Coneric Issues Branch 14pp 20626 295

B310040052 Forwards 9-month response for NURE9-0612, "Control of Heavy Loads at Nuclear Power Plants" Electrical interlocks prevent main hoist of reactor bldg Crane from being used over reactor well or spent fuel pool CURTIBLA W Pennsylvania Power & Light Co PLA-1843 B3/09/29 SCHWENCERA Licensing Branch 2 63pp 2060B 143 24X Fiche 50-388.83/09/29.8310040052

B310040310 Forwards addl info requested in 830810 telcon re Franklin Research Ctr 830617 draft technical evaluation rept on util response to Phase 1 of NOREO-0612. "Control of Heavy Loads at Nuclear Power Plants "FAY, C W Wisconsin Electric Power Co 83/09/28 MILLER, J R Office of Nuclear Reacton Regulation, Director MILLER, J R Operating Reactors Branch 3 Epp 20613 096 24X Fiths 50-266,83/09/28,8310040310

8310040498 Respec of Contention I-41 re sys interaction Certificate of Several Severa

B310040530 Comments on draft Task Action Plan for Generic Issue A-29, "Nuclear Power Plant Design for Reduction of Vulnerability to Babotage " Final responsibility for selection of criteria belongs w/NRC STARK, S J Ca General Electric Co MFN-179-83 83/09/29 VE Auxiliary Systems Branch 7pp 20623 FICRAVANTE N E

8310040572 Forwards responses to 830728 request for add1 info required to resolve open items in Franklin Resparch Ctr technical evaluation rept on control of heavy loads Info on Sections 2a & 2b re turbine bldg crane to be submitted by 831024 MUSCLE, D. Northern States Power Co. 83709727 Office of Nuclear Reactor Regulation. Director 5pp. 20622 270 24X Fiche 50-263.83709727.8310040572

B310040597 Forwards response to dreft technical evaluation rept assessing conformance w/general load handling guidelines of NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Addl response will be provided by B31115 LEMPOES, T E Niagara Mohauk Power Corp 83/09/30 EISENHUT, D & Division of Licensing 9pp 20625 327 24X Fichs 50-220,83/09/30 8310040597

8310050144 Discusses 830307 & 17 ltrs re pressurized thermal shock flux reduction Commitment to fuel mgt plan for Cycle 6 & estimated schedules for fuel mgt plans to be used in subsequent cycles requested in 30 days
EISENHUT.D 0 Division of Licensing 83/09/12 HUKILL, H D
Oeneral Public Utilities - OPU Service Corp Spp 20650 209, 24X
Fiche 50-289,83/09/12,8310050144

- 8310040413 Forwards "HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept," documenting results of flux reduction program to resolve pressurized thermal shock issue CUTTER: A B Carolina Power & Light Co LAP-83-439 83/09/30 DENTON, HR Office of Nuclear Reactor Regulation, Director 2p 20441 291 24% Fiche 50-261.83/09/30.8310040413
- --B310060418 R-83-030
 "HB Robinson Fluence Reduction Analysis for Partial-Length Shield Assembly Concept"
 * Technology for Energy Corp * Carolina Power & Light Co B3/09/30 198pp 20641 293 24X Fiche 50-261.83/09/30.
- 8310070216 "Resolution of Generic Issue C-8, 'MSIV Leakage & Leak Control Sys Failure. Task 2 Base Case Benchmark Calculation,'" Itr rept MURPHY.D W, ES9IG.T H Battelle Memorial Institute. Pacific Northwest Laboratory FIN 8-2529 93/09/23 RIDGELY, J Office of Nuclear Reactor Regulation, Director 8pp 20679 345
- BS1007040B Forwards SER re control of heavy loads based on util response to S01222 generic ltr Ouidelines in NURE9-0612. Section 5 i 1 % 5 3 satisfied VARGA. B A Operating Reactors Branch 1 83/09/20 DOLAN, J Indiana & Michigan Electric Co 2pp 20675 332 24% Fiche 50-315,83/09/20,8310070408
- --8310070409 Safety evaluation re control of heavy loads Guidelines in NUREO-0612 Bertian 5 1 1 & 5 3 satisfied * NRC No Detailed Affiliation Given 83/09/20 2pp 20675 334 24X Fiche 50-315.83/09/20.8310070408
- --B307060263 TER-C5506-344/345
 "Control of Heavy Loads (C-10) Indiana & Michigan Electric
 Co.DC Cook Nuclear Plant Units i & 2." technical evaluation
 rept
 VOSBURY, F W Franklin Institute/Franklin Research Center
 NRC-03-B1-130 TAC 07981 83/09/01 SINGH, A NRC No Detailed
 Affiliation Given 33pp 20675 336 24X Fiche 50-315, 83/09/20.
 B310070408
- 8310110345 NUREG-1018
 SEISMIC GUALIFICATION OF EQUIPMENT IN OPERATING PLANTS
 Status Report Unresolved Safety Issue A-46
 CHANO, T Y Division of Safety Technology 83/09/30 87pp
 Available at NRC \$4 50 20714 074
- 8310110494 Forwards safety evaluation & Frenklin Research Ctr technical evaluation rept re NUREG-0612, "Control of Heavy Loads (Phase I) " Phase I acceptable Need for single failure-proof handling equipment will be addressed in Phase II STOLZ, J F Operating Reactors Branch 4 E3/09/21 BAUER. E O Philadelphia Electric Co 3pp 20712 076 24X Fiche 50-277,83/09/21.8310110454
- ~-8310110459 Safety evaluation re util 810618,1222,820520,1025 & 83081C responses to NUREG-0612, "Control of Heavy Loads (Phase I) "
 Phase I acceptable * NRC No Detailed Affiliation Given 83/07/09 2pp 20712 079 24% Fiche 50~277,83/09/21,8310110454
- 8310110492 Requests brief summary of key points made during 830818 teleon & results of flux reduction program due to revised results for surveillance wall capsule 263 Submittal requested within 120 days of itr receipt MILLER, J.R. Operating Reactors Branch 3 83/09/24 GARRITY, J.H. Maine Yankee Atomic Power Co. 3pp. 20714 357 24X Fiche 50-309, 83/09/24,8310110492
- 8310120252 Forwards response to Phase I of NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants." per BJ Youngblood 830811 request for add info All cranes & hoists purchased to Sargent & Lundy specs WILLIAMS. J Cincinnati Oas & Electric Co LOZ-B3-0163 83/10/04 DENTON: R Office of Nuclear Reactor Regulation, Director 4pp. 20672 103 24% Fiche 50-358,83/10/06,8310120252
- 8310120407 Forwards nongroprietary rept & Suppl 1 to "HE Robinson Unit 2, Cycle 10 SAR "Also forwards proprietary "ECCS & Plant Transient Analyses " & "Mechanical Design Rept" Repts withheld (ref 10CFR2 790)
 UTLEY.E E Carolina Power & Light Co LAP-83-446 83/10/05
 VARQA. 9 A Operating Reactors Branch 1 14pp 20697 176 24X
 Fiche 50-261.83/10/05.8310120407
- --8310120415 XN-NF-83-72
 Nonproprietary "HB Robinson Unit 2.Cycle 10 SAR "
 STONE, I Z . ADAMS.F T . LAMBERT, W L Exxon Nuclear Co , Inc
 (subs of Exxon Corp) 83/09/01 39pp 20697 188 24X
 Fiche 50-261,83/10/05.8310120407

- --B310120422 XN-NF-B3-72 801

 Nonproprietary Suppl 1 to "MB Robinson Unit 2.Cycle 10 8AR"

 STONE, I 2. ADAMS. F T. LAMBERT. W L Exxon Nuclear Co., Inc.
 (subs of Exxon Corp.) B3/09/14 83pp 20697 227 24X

 Fiche 50-261,83/10/05,8310120407
- B310180132 Motion for summary disposition of Contention I-62
 WETTERHAHN, M J Philadelphia Electric Co METTERHAHN, M J Conner &
 Hetterhahn 83/10/12 Atomit Bafety and Licensing Board Panel
 19 20807 097 24X Fishe 50-332,83/10/12,8310180132
- --8310:80:139 Memorandum in support of motion for summary disposition of Contention I-A2 re pressurized thermal shock (PT8) PT8 will not be problem due to conservative design, mat1 selection, constitesting, operation & surveillance

 METTERHANNIN J Philadelphia Electric Co METTERHANNIM J Conner & Wetterhahn 83/10/12 Atomic Safety and Licensing Board Panel 15pp 20807 098 24X Fiche 50-352,83/10/12,8310180132
- 8310180166 Forwards FBAR Section 9 1 re reactor bldg crame, revised in response to NURES-0612 Changes will be incorporated into next FSAR amend CURTIS:N W Pennsylvania Power & Light Co PLA-1867 83/10/13 SCHMENCER:A Licensing Branch 2 28pp 20809 001 24X Fiche 50-388,83/10/13,8310180166
- B310180193 Forwards response to requests for add1 info re special lifting devices used for control of heavy loads (ref NUREG-0612) MAIEN, J E Pacific Gas & Electric Co 83/10/12 CRUTCHFIELD, D Operating Reactors Branch 5. 22pp 20809 061 24% Fiche 30-244,83/10/12,8310180193
- 8310180381 Supple 830720 response to Generic Ltr 81-07, "Control of Heavy Loads," in response to NRC finding in JE Insp Rept 83-11, dtd 830420, Info documents util methodology for compliance U/NUREO-0612 & ANSI N 14 6
 UHRIGER E Florida Power & Light Co QL-81-07 83/10/07
 EISENHUTED O Division of Licensing 2pp 20803 201, 24X
 Fiche 50-250,83/10/07,8310180381
- 8310180473 Responds to 831006 request for addl info be changes to amergency & abnormal procedures following review of Preliminary Safety Concern 22-82. "Potential for Pressurized Thermal Shock "
 HEBTAFER.O R Florida Power Corp 3F-1083-11 83/10/14.
 BEYGUNG.R C Director's Office. Diffice of Inspection and Enforcement 2pp 20802 028 24% Fiche 50-302,83/10/14,8310180473
- B310200050 Forwards Franklin Research Ctr draft technical evaluation rept re control of heavy loads, based on B30131,0502,06 & O610 responses to NRC requests for add1 info Telcon will be arranged after 831028 to discuss comments STOLZ,J F Operating Reactors Branch 4 B3/10/06 CROUBE,R P. Tolede Edison Co Opp 20844 299. 24X Fiche 50-346,83/10/06,8310200050
- --8308180560 TER-C5506-348 DRFT
 "Control of Heavy Loads (C-10). Toledo Edison Co, Davis-Resse
 Nuclear Power Station Unit 1," draft technical evaluation
 rept.
 BOMBERGER, C., AHMED, N. Franklin Institute/Franklin Research
 Center NRC-03-81-130 TAC 10993 83/08/09 BINOH, A. NRC Np
 Detailed Affiliation Given 33pp 20844 302 24X
 Fiche 50-346, 83/10/06, 831080050
- B310200260 Responds to EQMO Phase I recommendations re special lifting device, per NUREQ-0612. "Control of Reavy Loads " Util B30509 commitment to restrict crame hoist speeds reduced possibility of overstress in lifting devices SCHUYLER.J D Pacific Gas & Electric Co B3/10/14 KN10HTON, Q W Licensing Branch 3 Bpp 20830 078 24X Fichs 50-275.83/10/14. B310200260
- 83i02002B4 Addresses SEP Topic V-6, "Reactor Vessel Integrity," documented in NUREO-0369. "Evaluation of Integrity of SEP Reactor Vessels " SEP Topic V-6 resolved as result of evaluation performed per pressurized thermal shock issue KRIEGER.R W Southern California Edison Co IEB-78-12 83/10/13 CRUTCHFIELD.D Operating Reactors Branch 5, 2pp 20829 320 24x Fiche: 50-206, 83/10/13, 8310200284
- 8310240235 Responds to FDIA request for three documents to be placed PDR Forwards documents listed in app FELTON, J. M. Division of Rules and Records 83/07/11 PEDRO, J. N. Corp. 2pp. 20871, 225
- --Bi02260210 Summary of 801217 meeting w/utils & vendors in Bethesda, reinclusion of linear elastic fracture mechanics in resolution of putential for low fracture toughness & lamellar tearing on component supports
 BNAIDER.R Generic Issues Branch 80/12/30 KNIEL.K Generic Issues Branch 5pp 20891 233

- --BOli050238 Notification of 800903 meeting w/GE in Bethesda.MD to discuss proposed BHR feedwater nozile leakage detection sys SNAIDER.R P Systematic Evaluation Program Branch 80/08/14 KNIEL.K Generic Issues Branch 1p 20891 228
- --8011190749 Summary of B00903 meeting w/GE to discuss draft NEDE-24265-P (proprietary) re proposed feedwater nozzle surveillance instrumentation sys List of attendees encl SNAIDER.R P. Generic Issues Branch 80/09/15 KNIEL.K Generic Issues Branch 3pp 20891 229
- 8310250031 FDIA request for A Brukiewicz 820809 & 830114 memos to K Khiel.summarizing NRC 820728 & 1229-30 meetings w/EG&G re Unresolved Safety Issue A-47, to be placed in PDR BUCKLES:R NUS Corp CD-15-83-100 83/04/30 Division of Rules and Records 1p 20908 281
- 8310250032 Responds to FOIA request that A Szukiewica 820809 & 830114 memos to K Kniel, summarizing NRC 820728 & 1229-30 meetings w/E0&0 re Unresolved Safety Issue A-47, be placed in PDR Forwards documents FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R NUB Corp 1p 20908 282
- --820B240121 Summary of 820728 meeting w/EG&O,ID in Bethesda.MD re Unresolved Safety Issue A-47. "Safety Implications of Control Sys " Modeling of control sys to begin in Aug 1982 H/o handouts SZUKIEWICZ.A J Generic Issues Branch 82/08/09 KNEIL.K Generic Issues Branch 35pp 20908 288
- --B301250200 Summary of 821227 & 30 meetings w/E0&0 in Idaho Falls, ID restatus & progress of Browns Ferry plant review & progress on Unresolved Bafety Issue A-47 concerning safety implications of control sys. Agenda & attendance list encl SZUKIEHICZ, A Generic Issues Branch B3/01/14 KNIEL, K Generic Issues Branch 5pp 20908, 283
- 8310270071 Responds to FGIA request for five separate categories of documents.Forwards App A documents responsive to Items 1.2 & 3 of request Item 4 rs LMR hydrogen manual should be published during Sept 1983 Item 5 not available FELTON, J N Division of Rules and Records 83/07/14 HIATT, S L Ohio Citizens for Responsible Energy 2pp 20942 272
- --B310270075 Draft "Grouping of LWRs for Evaluation of DHR Capability "
 KAROL,R , FREECO,A , PERKINS,K R Brookhaven National Laboratory
 B2/12/31 NRC No Detailed Affiliation Given 77pp,
- 8310270379 Responds to 830826 request for review of draft task action plan for Generic Issue A-29 "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage " Div of Sys Integration should manage technical aspects of plan EISENHUT, D O Division of Licensing 83/10/18 MATTSON, R J Division of Systems Integration (post 811005) 2pp 20743:111
 - B3070B0358 Forwards task action plan for Generic Issue A-49. "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage "Bcope of task expanded to include consideration of sabotage vulnerability in existing plants.
 MATTBON.R J Division of Systems Integration (post 811005), 83/08/26 EISENHUT, D Q Division of Licensing 2pp. 20743, 113
 - 8309080363 Task Action Plan A-29" "Nuclear Power Plant Design for Reduction of Vulnerability to Sabotage" FIGRAVANTE, N Auxiliary Systems Branch 83/08/26 7pp
- 3310280123 Responds to B30912 ltr re fuel mgt glan for Cycle & estimated schedules for fuel mgt plans used to meet pressurized thermal shock flux reduction Commits to in-out-in fuel mgt plan HUMILL. H D General Public Utilities OPU Bervice Corp 5211-83-209 83/10/24 EIBENHUTJD G. Division of Licensing 2pp 20929 264 24X Fiche 50-289,83/10/24,8310280123
- B310310446 NUREG-0577 R01
 PDTENTIAL FOR LOW FRACTURE TOUGHNESB AND LAMELLAR TEARING
 IN PUR STEAM GENERATOR AND REACTOR COGLANT PUMP SUPPORTS
 Unresolved Bafety Issue A-12
 + Division of Bafety Technology B3/10/31 70pp Available at
 NRG. 84 B0 21000,304.
- B310310465 Summarizes ACRS 282nd meeting on B31013-15 on NRC integrated program for resolution of Unresolved Safety Issues A-3, A-4 & A-5 re PWR steam generators Proposals should be implemented as recommendations only.

 RAY, J. J. ACRS Advisory Committee on Reactor Safeguards. B3/10/18 PALLADING N J Commissioners. ip. 20765:160.

- 1&E INSPECTION AND ENFORCEMENT
- 8308300340 IE Info Notice 83-61. "Alleged Use of Stand-Ins for Welder Qualification Tests " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/09/26 Consolidated Edison Co
- 8308300342 IE Info Notice 83-62. "Failure of Redundant Toxic Gas Detectors Positioned at Control Room Ventilation Air Intakes " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc. 116pp 20777 210 24X Fiche 50-000.83/09/26,830830034;
- B30B300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/09/26 Consolidated Edison Co. of New York, Inc. 118pp 20777 350 24X Fichs 50-000,83/09/26,8308300345
- 8308300349 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR30 59 Evaluation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/29 Consolidated Edison Co of New York, Inc. 115pp 20716 324 24X Fiche 50-000,83/09/29,8308300349
- B30B30037B IE Info Notice 63-65, "Surveillance of Flow in RTD Bypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co. of New York. Inc. 76pp 20827 213 24% Fiche 50-000,83/10/07,8308300378
- B30B3006B9 PNO-I-B3-087A on 830B24, patient orally administered 100 mC; TC-97m labelled DTPA for gastric emptying study instead of 100 uC; Caused by typographical error in written procedures Procedures revised NICOLOBI. J Region 1, Office of Director B3/08/26 1p 2020A 281
- 830830075R IE Info Notice 83-66. "Fatality at Argentine Critical Facility " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/07 Consolidated Edison Co of New York, Inc 79pp 20882 026 24X Fiche 50-000,83/10/07,8308300752
- 8308300759 IE info Notice 83-67. "Emergency Use Respirator Matl Defect Capaes Production of Noxious Gases " Svc list encl JDROAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117ap 21043 075 24X Fiche 50-000/83/10/11/8308300759
- B30B300761 IE Info Notice B3-68, "Respirator User Warning. Defective B#1f-Contained Breathing Apparatus Air Cylinders " Svc list enc!

 JORDAN, E L. Division of Emergency Preparedness & Engineering
 R#spense (Post B30103) B3/10/11 Consolidated Edison Co of New York Inc 120pp 20827 129, 24X Fiche 50-000.83/10/11.8308300761
- 8308310105 EN-83-055 on 830701; notice of violation & proposed imposition of civil panalty will be issued in amount of \$2,500 based on multiple examples of radiation safety program failure FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/08/27. 1p 20227 027
- B30B310330'PNO-I-83-090 on B30B26, employee film bedge for Jul 1983 showed exposure of 7 77 rem Badge exposure not believed to be actual exposure to employee Add1 info requested from badge vendor to determine source of exposure FRIEDMAN.L. QLENN, J Region 1. Office of Director 83/08/26 1p 20227 203
- 8310030440 EN-83-040 on or about 830727, notice of violation & proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee Action based on inadequate reassessment of fire protection features, per 10CFR30, App R
 CRAIG.J., AXELRAD.J. Office of International Programs, Director 83/09/26 1p. 20602 089 24X Fiche 50-344,83/09/26,8310030440
- 8310030461 PND-II-83-078 on 830925 recriticality achieved after 1-yr shutdown to modify drywell cooling sys & other areas Low power physics testing will be conducted during next 3-wk period WATBON, L., JULIAN, C. A. Region 2, Office of Director 83/09/26 20501 048 24% Fiche 30-416.83/09/26.8310030461

- 931003047A PNO-IV-B3-029 on 830726, unit shut down due to inability to comply w/Tech Spec action statement following discovery that station battery 2011 failed quarterly surveillance test on 830722 condition not recognized by mgt until 830924 JOHNSON, W D. CALLAN, L J. Region 4. Office of Director 83/09/27 ip 20401 046 24% Fiche 50-348,83/09/27.8310030476
- #310030520 EN-83-014A on 830318, notice of violation & proposed imposition of civil penalties in amount of \$4,000 issued to license. Action based on failure to adhere to license conditions while administering radiologine FLACK.E. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/09/29 ip 20401 185
- 8310040213 PNS-I-83-019 on 830923 licensee contract security organization suspended two security guards Guard admitted to firinging illegal substance on site Other guard did not rept intident Both guards terminated 830926 HADDEN.W. GODY.A Region 1. Office of Director 83/09/28 ip 20614 273 24% Fiche 50-272.83/09/28.8310040213
- #3310040214 EN-83-032A on 830505, notices of violation & proposed imposition of civil penalty in amount of #885.000 issued to util based on violation of Tech Spec requirement & failure to adequately implement aspects of GA program ALINGLER.0 . AXELRAD. J Director's Office. Office of Inspection and Enforcement 83/09/29 ip 80617 240 24X Fiche 50-272, 83/09/29. 8310040214
- B310040396 PNO-V-83-041 on 830929, approx 50 items discovered in Unrestricted storage areas Surveys continuing Press release expected WENSLAHGKI.F., KIRSCH.D Region 5. Office of Director B3/09/29 ip 20619 168 24% Fiche 50-206.83/09/29,8310040396
- B310040455 PNO-1-B3-099 on 830930, contract for bargaining unit (Util Workers Union of America.Local 497) expires If strike occurs.insp will be provided to confirm of plant transition by mgt personnel HULDEN.C. HIGGINS, J., GREENMAN.E. Region 1. Office of Director 83/09/29 1p. 20623 325 24X Fichs 50-309.83/09/29.8310040455
- 8310050536 EN-83-063 on 831007, notice of violation & proposed imposition of civil penalty in amount of \$8,000 will be issued, based on failure to follow emergency procedures & to perform survey, causing radiation exposure to individual FLACK, E., AXELRAD. J. Director's Office, Office of Inspection and Enforcement 83/10/05 ip 20830-359
- 8310060005 EN-83-061 on 831006.notice of violation & proposed imposition of \$40.000 civil penalty will be issued based on util failure to place main steam line high radiation trip sys in tripped condition when both channels inoperable KLINOLER.0 . AXELRAD.J Director's Office, Office of Inspection and Enforcement 83/10/03 ip 20649 294 24X Fichs 30-220.83/10/03 8310060005
- B310060040 PNO-1-83-098A strike of Intl Brotherhood of Electrical Workers possible after contract expires Union meeting to vate on licensee proposal set for 831005 Licensee contingencies in event of strike acceptable TRIPP, L. KEIMIG.R. Region 1, Office of Director 83/09/30 lp 20647 084 24% Fiche 50-334,83/09/30,8310060040
- B310060051 PNO-I-83-100 on B30929, potential overpressurization of low pressure piping at pump suction occurred Event attributed to malfunctioning check valve Seal leak repaired Valve apparently stuck partially open JCHNON, J. CALLO.R. Region i. Office of Director 83/09/30 lp R0647 073 24X Fiche 50-293,83/09/30.8310060051
- 83100A9092 EN-83-062 on 83100A, notices of violation & proposed imposition of \$1.000 civil penalty to be issued Action based on violation of Tech Specs re alterations made to core canfiguration CRAIO.J. AXELRAD.J. Director's Office. Office of Inspection and Enforcement EN-83-62 83/10/03 ip 20647 177 24X Fiche 50-062,83/10/03,8310060092
- B310060233 PNO-I-83-009B on B30930; licensee & Util Horkers of America negotiations failed to produce settlement Operations turned over to supervisory personnel Settlement approved by union membership on B31061
 HQLDEN.C., H1061NS.J., GREENMAN.E. Region 1. Office of Director B3/10/03 1p 20647 033 24X Fiche 30-309,83/10/03,83100460253
- B310060244 PNO-III-B3-Q91 on B31001.6~month outage commenced for refueling routine maint & replacement of two steam generators Authorization to replace generators received on B30930

 JACKINI SHAFER, W. Region 3, Office of Director B3/10/03 ip 20645 265 24X Fiche 50-266, B3/10/03, B310060264

- 8310060344 Updated PNO-1~83-099A on 830930, negotiations continuing between util to Util Workers of America to settle terms of contract expiring at midnight Plans in place for NRC inspicoverage of operations to ensure smooth mgt transition HOLDEN, C. HIGGINS, J. GREENMAN, E. Region I, Office of Director 83/09/30 ip 20646 127 24X Fiche 50-309, 83/09/30, 8310060344
- B310060428 PNB-III-83-087 on 830927, temporary restraining order requested to prevent shipment of spent reactor fuel through State of OH denied Pretrial conference set for 831006 Local govts alleged inadequate preparation by local agencies STRASMA, J. MENCZER. M. Region 3, Office of Director, 83/09/30 2pp 20541 221 24x Fiche 50-000,83/09/30,8310060428
- B310070333 FNO-V~83-042 on B30929, unusual event declared when unidentified leakage from RCS of 1 17 ppm discovered Caused by high penalty factor applied in response to 1 h observation Reactor & sus normal after 20% trip test XIRSCH D Region 5, Office of Director 83/09/29 ip 20651 002 24% Fiche 50-362,83/09/29,8310070333
- B310110191 EN-83-064 on B31006.notice of confirmatory order for mod of CPs issued Order requires const implementation overview program to provide reasonable assurance that facility can be completed in accordance w/regulatory requirements STUNGLY. HEISHMAN.R Director's Office, Office of Inspection and Enforcement B3/10/06 ip 20665 007 24% Fiche 50-329.83/10/06.
- B310120043 PNO-V-83-043 on 830929, two manual valves incorrectly closed, isolating all charging pump flow to RCS Plant being shut down due to excessive leakage from RCS On B30930. Tech Spec violation recognized & valves opened.

 ECKHARDT. J. Region 5. Office of Director B3/10/03 ip 20498 R96 24X Fiche 50-362, B3/10/03, B310120065
- B310120066 PNO-V-83-044 an B31003, employee suffered heart attack during work Personnel taken to hosp No news release planned MORRILL, P J Region 5, Office of Director B3/10/04 ip 20696 157 24X Fiche 50-275,83/10/04,8310120066
- B310120124 PNO-1-83-103 on B31004.licensee commenced 6-day outage to repair moisture separator reheater tube leaks Leaks indicated in four of six reheaters Unit will be maintained in hot shutdown Cooling fan motors replaced KENNY, T. KISTER, H. Repion 1. Office of Director B3/10/05 ip 20676 154 24X Fiche 50-247.83/10/05.83(0120124
- 83i012023G PNO-III-83-085 on 830913 decontamination of onsite & offsite facilities completed as result of 830913 source damage incident Licensee must submit decontamination plan by 831019
 HIBDEMAN, D., HIND, J. Region 1, Office of Director 83/10/06 ip 20692:178
- B310120251 PND-V-83-038A on B30917.plant shut down following discovery of steam generator A tube leak One insp lane tube (78-2) plugged on B30927 Two of 360 tubes inspected showed localized thinning of approx 25% JCHNSON, P. YOUNG, T. Region 5. Office of Director B3/10/03 lp. 20592 107 24% Fiche 50-312,83/10/03,8310120231
- 8310120256 PNO-III-83-070. on 830930, licensee notified resident inspector of allegation of improper training & certification of individuals conducting reviews of safety-related records for HJ Kaiser Co.principal site contractor SCHEIBINZ.E., FORNEY. W. Region 3. Diffice of Director 19 20691 330 24% Fiche 30-358,83/10/03.8310120256
- B310120306 PND-1-83-102A on B31004,50 Ci Co-60 radiography source retrieved w/o incident No contamination indicated in recovery area Source loaded into exposure device & will be leak tested before being placed in evc.
 NICOLOBI, J. KINNEMAN, J. Region 1, Office of Director 19, 20701 Oil
- B310120309 PNG-III-83-093 on 830930, facility shut down for scheduled refueling outage Licensee expected to conduct ultrasonic testing of large diameter stainless steel pipe in drywell, per NRC order Insp will continue for 16 wks
 TONGUE, T. MALKER. R. Region 3. Office of Director. 83/10/05 tp
 20701 009 24X Fiche 30-249.83/10/05.8310120309.
- 8310120321 PNO-V-83-039A on 830919.PDRV opened at 29 paig due to additional design and substantial design and selection and substantial design and selection and substantial design and selection without the substantial design and substantial design and

- 8310120446 PNO-11I-83-072 on 831004 marijuana found in trutk owned by carpenter employed by Bechtel Corp Individual fired by Bechtel & left site No action planned by Region III State of MI will be notified
 MI will be notified
 HARRISON.J., MARNICK.R. Region 3, Office of Director 83/10/04
 ip 20698 325 24X Fiche 50-327.83/10/04.8310120446
- 83i0i4d038 PNO-I-83-106 on 83i007.plant shutdown from 100% power due to apparent hydrogen leakage into generator stator water cooling sys Similar occurrence on 830819 resulted in 5-wk uutage Btates of NJ & DE informed LIN
- 8310140060 EN-83-055 on B31013.order to show cause & order temporarily suspending license, effective immediately, issued Action based on 830928 & 30 inspacevesling that personnel monitoring devices & survey meter not obtained.

 KLINOLER, G. AZELRAD, J. Director's Office, Office of Inspection and Enforcement 83/10/13 ip 20768 001
- 8310140068 PNO-1-83-104, on 830704, during RHR & recirculation piping weld inap, 20 of 126 welds examined evidenced intergranular stress corrosion cracking Licensee repairing 16 welds by clad overlay technique
 8L000H.A R . TRIPP.L E Region 1. Office of Director 83/10/07 ip 20766 359 24% Fiche 50-277, 83/10/07, 8310140068
- B310140082 PNG-1-83-105 on B31007, seismic event occurred in horthwastern US W/magnitude of 5.2 on Richter scale in NY & 4 0 in NH No damage to equipment identified GALLO,R M , GREENHAN, E. G. Region 1, Office of Director B3/10/07 19 20766 116 24X Fiche 30-000, 83/10/07, B310140082
- 8310140090 PNO-III-83-095 on B31005.BAW issued stop work order on Class I piping hanger installation Stop work applies to both small bore & large bore piping & is based on deficiencies identified in hangers during Bechtel inep HARRIBON.J., QARDNER.R Region 3. Office of Director 83/10/08 ip 20767 059 24% Fiche 50-329.83/10/06.8310140090
- 8310140142 PNO-II-83-080 on 831007, tank truck loaded w/sand & water containing 10 mCi Ir-192 leaked when sand tracer slurry pumped out into remote well in Richie County, WV Contaminated sand & soil being held by licensee for decay POTTER. J P., COLLINS, B M Region 2, Office of Director 83/10/11 19 20763-020
- 8310140153 PNO-V-83-046 on B31003, while in Mode 3 & attempting to determine why LP turbine stop valve would not fully shut, discovered debris inside moisture separator reheater Turbine not damaged ECKHARDT, J Region 5, Office of Director 83/10/04 1p 20762 362 24X Fithe 50-362,83/10/04,8310140153
- 8310140237 EN-83-066 on 831013,order to show cause & order temporarily suspending license issued, effective immediately Insp on 831006-07 revealed unauthorized persons using moisture gauges containing radioactive math FLACK.C. AXELRAD.J Director's Office. Office of Inspection and Enforcement 83/10/13 ip 20762-040
- 8310140255 PNO-III~83-094: on 830930, contamination found on empty spent fuel cask shipped from facility Trailer used to transport empty spent fuel casks experienced brake problems on 831005 All shipments under insp LOYENDALE.P. OREGER, L. R. Region G. Defice of Director 83/10/06 2pp 20759 238 24X Fichs 50-266:83/10/06;8310140255
- B310140284 PNO-V-83-045 on B31003; two reactor trip breakers failed 35 day surveillance test Cause of Faliure under investigation Breakers placed in open position & replaced w/ spares
 ECKHARDT, J. Region 5, Office of Director B3/10/04 ip 20757-236 24x Fiche 50-361.83/10/04.83/6140284
- 8310170310 PNO-1-83-103A on 831004.licenses began unscheduled outage to repair moisture separator reheater tube leaks NRC notified on 831011 of reactor coolent leak on steam generator 22 hot leg manuay Piant will be in cold shutdown for repairs FOLEY.T. JACOBS.R. NORRHOLM.L. Repian 1. Office of Director 83/10/12. 1p 20786 151 24X Fiche 50-247.83/10/12.8310170310
- B310180199 EN-B3-068 on B31019, notice of violation & proposed imposition of civil penalties in amount of \$2,000 to be issued to licenses Action based on 12 appearant violations reuse of byproduct matis by unauthorized individuals FLACKE: AXELRADIJ. Director's Office. Office of Inspection and Enforcement B3/10/14 ip 20809 050

į

1

- 8310180413 EN-83-067 notice of violation & proposed imposition of civil penalty in amount of \$2,000 will be issued re eight examples of failure to comply w/NRC requirements one involving unauthorized use of nuclear moisture density gauge FLACKLE, AXELRAD. J. Director's Defice. Office of Inspection and Enforcement 83/10/17 ip 20803 311
- 8310180446 PNO-III-83-096 on 831011 during routine inservice insp. small crack discovered on 6-inch piping in reactor water cleanup sys Crack not in sys affected by NRC 830823 order or IE Bulletins 82-03 & 83-02 Situation being evaluated DANIELSON. D. WALKER. R. Region 3, Office of Director IEB-82-03 B3/10/13 1p 20801 343 24% Fiche 50-265,83/10/13,8310180446
- 9310180447 PND-I-83-107 on 831011, trip from full power occurred when main feedwater pump 22 tripped Containment sump pumping frequency increased due to stopping & restarting of reactor coolant pump Flant cooldown began 831012 to repair sool TRIMBLE.D. SWETLAND.P Region 1. Office of Directo: 83/10/12 ip 20802 031 24X Fiche 50-318.83/10/12.8310180467
- 8310190236 FNO-II-83-082 on 831015 control room operator traines killed instantly when fist-sired hole blow open in wall of 24-inch carbon steel pipe attached to high pressure feedwater drain pump Cause under investigation LANDIS K DANCE, H Region 2. Office of Director 83/10/17 2pp 20818 078 24% Fiche 30-280.83/10/17,8310190236
- 8310200152 PNO-111-83-097 on 831013.13 maint & janitorial workers at site resigned due to internal investigation re marijuana & alcohol use during working hours All safety-related const suspended HILL-W , FORNEY.W Region 3. Office of Director 83/10/14 ip 20836 321 24X Fiche \$0-358.83/10/14.8310200152
- B310200160 PND-I-83-10B on B31013 film badge exposed to 3,570 mrem during month of Aug 1783 Licensee conducting investigation to determine validity of preliminary findings Event not considered to be whole body exposure DAVIS.J. KINNEMAN.J. JQYNER.J. Region 1. Office of Director B3/10/14 1p 20834 093
- 8310200176 PND-V-83-047 on 831011.licensee received natification from Radiation Detection Co of one film badge indicating potential whole bady exposure of 18 rem Film badge not representative of exposure BHERMAN.C. WENGLAMSKI.F. Region 5. Office of Director 83/10/12 ip 20835 315 24X Fishe 50-224.83/10/12.8310200176
- 8310210030 EN-83-069 on 831026 natice of violation & proposed imposition of civil penalty in amount of \$100,000 to be issued Action based on fireline relocation activities performed in "9" sulls w/o prior NRC authorization LINGLER.O. ARELRAD. Director's Office, Office of Inspection and Enforcement 83/10/20 ip 20859 384 24X Fiche 50-329,83/10/20.
- 8310210122 PNO-III-83-099 on B31015, unit shut down for steam generator tube leak exam & repair Unit will be thut down for 2-3 wks Region & resident inspector will monitor course of action BCYD-D . SHAFER:W Region 3, Defice of Director 83/10/17 ip 20858 250 24X Fiche 50-316.83/10/17.8310210122
- 8310210151 PND-III-83-098 on 831014, Region III informed of discovery of circumferential crack indications in steam generator tubes near & in support plates, identified during oddy current testing Util estimates 20 to 50% of tubes offected HOLZMER, M. BOYD, D. Region 3, Office of Director B3/10/14 ip 20855 318 24% Fiche 30-255,83/10/14,8310210151
- 83102500A5 PNO-II-83-084 licensee identified & reported to NRC that contractor welding svc employee received 99 mrem occupational overexposure during Third Quanter 1963 Licensee reviewing all circumstances associated w/event DESS, B., GIBSQN, A.F. Region 2, Office of Director 83/10/20 ip 20896 085 24X Fiche 50-259.83/10/20,8310250065
- 8310250355 PNO-V-83-049 on 831018, const craft person injured working in 12 kV circuit breaken Workman accidently contacted hot const gower supply circuit, 8moke observed coming from manhols. Plant unaffected MORRILL.P Region 5, Office of Director 83/10/19 is 20898 127 24X Fiche 50-204, 83/10/19, 8310250355
- ABIO250543 PNO-V-83-048 on BBiO13 Region V notified by NRR of temp compensation error w/Barton Model 763 pressure transmitters Same problem exists w/Model 764 steam generator narrow-range water level transmitters Setpoints ravised on BBIO14 HAIST D Region 5. Office of Director BB/10/18 1p 20901 383 24X Fichs 50-344.83/10/18.8310250543

- 8310270224 PNO-II-83-085 during vitrasonic exam of 28-inch recirculation sys discharge piping, suspect indications identified in two welds Addl analyses of data for proper tategorization continuing State of NC informed BLAKE, J. HARDIN, A Region 2, Office of Director B3/10/21 ip 20924 044 24X Fiche 50-325,83/10/21,8310270224
- 8310270384 PNO-III-83-102 on 831020, security officer received bomb threat phone call from unidentified male Shift engineer instituted emergency procedures Search of vital areas conducted w/negative results Threat determined hoax BELANGER, J. CREED, J. Region 3. Office of Director 83/10/21 1, 20423 287 24% Fiche 50-295,83/10/21,8310270384
- 8310270487 PNO-III-83-101 on 831021.licensee employee discovered suspicious looking package near equipment on third level of turbine bidg Portion of bldg evacuated & MI State Police notified Package dismantled & confirmed nonexplosive CREED, J. Region 3, Office of Director 83/10/21 p 20922 001 24% Fiche 50-341,83/10/21,8310270487
- B310310273 PNO-TII-83-106 on 831023.two men in pickup truck parked outside facility delivered bomb threat Training reactor shut down & bldg searched No bomb discovered WERS.D A. CREED.J R. Region 3. Office of Director 83/10/26 ip 20947 114 24% Fiche 50-087.83/10/26.8310310275
- B310310284 PNS-V-83-011 on B31024, San Francisco Chronicle published article re use & sale of illegal drugs by current & former facility personnel Drug-related accidents or injuries not cited Repts believed to be untrue or exagerated SCHAEFER, D. W., NORDERHAUG, L. R. Region 5, Office of Director B3/10/24 ip 20961 282 24% Fiche 50-206, 83/10/24, 8310310284
- 8310310318 PNO-III-83-105 on 831025, Troxler soil density & maisture gauge. Madel 34018, containing 10 mCi Cs-137 & 50 mCi Am-241 reportedly stolen from const site WIEDEMAN, D 0, AXELSON, W L Region 3, Office of Director 83/10/26 lp 20961 213
- B310310361 PNO-I-83-109 on 831024, licensee reported that radiographs associated w/Class I piping improperly read by vendor during obtage mod work in 1981 & 1982 Part 21 implications under evaluation BLQUGH, A R , TRIPP, L E Region 1, Office of Director 83/10/25 ip 20961 121 24X Fiche 50-277, 83/10/25, 8310310361
- B310310406 EN-B3-070 on B31103, notice of violation & proposed imposition of civil penalty will be issued in amount of \$4.000 Action based on breakdown in mgt oversight & control of radiation selety program FLACK, E., AXELRAD, J. Director's Office, Office of Inspection and Enforcement EN-B3-070 83/10/27 ip 20759 183

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- B310030131 Comments on review of draft NUREQ re LER sys.per 830929 request
 DENTON:H R Office of Nuclear Reactor Regulation, Director 83/09/26 HELTEMES.C J Director's Office 50pp 20603 148
- --8309070071 Forwards draft NUREG on revised LER sys Comments requested by 830916 HELTEMES C. J. Director's Office 83/08/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director DEYDUNG, R.C. Director's Office: Office of Inspection and Enforcement MINOSUE, R.B. Office of Nuclear Regulatory Research, Director 108pp 20403 149
- 8310060134 Requests results of review be sent to F Miraglia by 831003 re EPRI list of 254 generic safety issues classified as not applicable to design certification, in EPRI standardized LWR plant design evaluation program EISENHUT.D G Division of Licensing 83/09/21 SPEIST Division of Selection of Selection of Selection MATTSON.R J Division of Systems Integration (post 811005) in 20661 008
- 83:0060142 Forwards "Procedures for Regional Implementation of Operator Licenting Functions "
 DENTON.H R Office of Nuclear Reactor Regulation, Director 83:/09/21 COLLING.J T Region 4, Office of Director MARTIN.J B Region 5, Office of Director 2pp 20661 001

- --8310060145 "Procedures for Regional Implementation of Operator Licensing Functions " DENTON.H R Dffice of Nuclear Reactor Regulation, Director 82/11/22 3pp 20641 003
- B3i0060355 Forwards response to 830729 ltr requesting info re purchase of flanges from Ray Miller Inc LETBCH D E Letto. Inc 83/09/27 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 20646 090
- 8310060515 Expresses regret for cancellation of 830907 meeting w/Z Reytblatt re alleged flaws in ANSI/ANS-56 8-1981 & App J to 100FR50 concerning containment leak rate testing Concerns should be directed to RES KEPPLER.J G Region 3. Office of Director 83/09/14 WHICHER.J M Businessmen for the Public Interest 3pp 20662 362
- 8310070125 Responds to 830921 ltr rm Ray Miller, Inc substandard matt. All Ray Miller, Inc matt purchased used in mag of form chemicals
 HOSCHAR, & E. Allied Chemical Corp. 83/09/30 BEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement in 20659 021
- ~-B310070129 Advises that Allied Chemical Corp was end user for all Ray Miller, Inc substandard matl listed on encl computer printout HOSCHAR, E. E. Allied Chemical Corp. 83/09/30 NRC ~ No Detailed Affiliation Given. 3pp. 20659 022
- B310070285 Ack receipt of 830919 ltr re detection of deficiencies in quality resulting from fraudulent actions by suppliers GA program instituted.

 TENZER, B. E. Ebasco Services, Inc. (subs. of Enserch Corp.)
 B3709729 DEYDUND, R. C., Director's Office, Office of Inspection and Enforcement ip 20657 001
- 8310110570 Porwards documents to be placed on document control sys MONTGOMERY. J M Office of Policy Evaluations 83/10/03 Document Management Branch 28pp 20715 200
- --8310110588 Forwards response to 830209 memo re accuracy of costs & reasonableness of backfits Previous backfitting cost problems worthy of stention ZERBE, J E Office of Policy Evaluations 83/05/20 AHEARNE, J F Commissioners 21pp. 20715 207
- 83:0110604 Requests re-review of final draft rept. "Seisaic qualification of Auxiliary Feedwater Sys II " Significant number of editorial problems exist BEARD, JT Operating Resctors Assessment Branch FIN A-0427 83/09/15 LU,B Lawrence Livermore Laboratory ip 207:01-362,
- 8310130042 Proposes pilot project to provide desktop microcomputer terminal at each atty workstation Project would eliminate 50% of first draft retyping & improve research & analysis & atty time & work item scheduling mgt DLMSTEAD.W J Regulations Division 83/10/06 DUBE.N L Office the Executive Legal Director 3pp 20726-290
- B310130048 Notifies of informal assessment of Region I & II implementation of 10CFR30.54(P) & 10CFR70 32 licensing responsibilities Meetings scheduled for Region I on B30920 & Region II on B30922 EISENHUT.D 0 Division of Licensing. B3/09/16 MARTIN.T.T. Division of Engineering & Technical Programs. BTOHR.J P. Division of Engineering & Technical Safety 3pp 20774-360
- 8310130080 Delegates & assigns certain operator licensing functions Regions IV & V Functions include processing applications, preparing, administering & grading exams & issuing & denying licenses.

 DIRCKS.W J Office of the Executive Director for Operations DENTON.H R Office of Nuclear Reactor Regulation, Director 0128-83-4 83/09/21 COLLINS.J T. Region 4, Office of Director MARTIN.J B Region 5, Office of Director 4pp 20777 044.
- 8310130128 Forwards "Development of Guidelines for Upgrating Maint Procedures in Nuclear Power Plants." interim rept. HORGENETERN. M Bettelle Human Affairs Research Centers 83/06/C GDODMAN, H NRC - No Detailed Affiliation Given ip 20774.260.

- ---8310130134 "Development of Quidelines for Upgrading Maint Procedures in Nuclear Power Plants." interim rept BARNEB.V E , EARLE, T C , MORGENSTERN, M Battelle Human Affairs Research Centers 83/06/30 NRC - No Detailed Affiliation Given 94pp 20774 281
- 8310140092 Advises that time for Commission to review Director's Decision DD-83-12 expired Commission declined review Decision became final agency action on 831011 CHILKS J Office of the Secretary of the Commission DD-83-12 83/10/13 GOGOL,E Affiliation Unknown 1p 20767 OR6
- 8310170302 Ack receipt of 830915 ltr re Section 2 2 2 of Generic Ltr 83-28 Concurs w/NUTAC mission to develop practical approach that will contribute to safety & reliability of nuclear plants EISENHUT, D G Division of Licensing GL-83-28 83/09/28 GRIFFING.E P Detroit Edison Co ip 20796 238
- 8310180019 Comments on draft NRC/GRNL rept. "Precursor to Potential Severe Core Damage Accident 1980-81 Status Rept." in response to 830829 memo Foreword should be rewritten to put use of PRA methodology in perspective for general public EISENHUT.D 9 Division of Licensing 83/10/06 SPEIS.T P Division of Safety Technology 3pp 20825 065
- 8310190187 Informs that effective 831001, all correspondence re radiological effairs support program & GW Hendrix (Code 112N) should be forwarded to Naval Sea Sys Command LABDON, TA Navy, Dept of Naval Facilities Engrg Command 112/TAL 83/10/14 NRC No Detailed Affiliation Given is 20820 220
- 8310200397 Forwards draft agenda for US/Federal Republic of Germany 831019-21 technical exchange maetings in Oak Ridge, TN re core melt LARKINS.J T Containment Systems Branch 83/10/05 MINUGUE,R, ROSS.D. BASSETT.D Office of Nuclear Regulatory Research, Director 7pp 20859 211
- 8310210330 Notification of 831021 meeting w/NMSS in Bethesda, MD to discuss assumptions used in vital area identification Meeting closed to public MCPEEK, E.W. Brandardization & Special Projects Branch 83/10/13 THOMAS, C.O. Standardization & Special Projects Branch 2pp. 20884 168
- 8310310464 Suggests that PORFLD computer code be included in benchmarking study to compare & evaluate several computer codes to be used for high level waste repository analyses. HRIGHTR J High Level Waste Technical Development Branch 83/08/24. OLSON O. L Energy. Dept. of 1p 20965 178
- NUREO REPORTS AND RELATED CORRESPONDENCE
- B309120437 Provides proposed responses to questions of BER (NUREQ-0853) Confirmatory Issue 1 concerning degraded core hydrogen control & emergency plan dose assessment reporting sys NELBON,R M Illinois Power Co. U-0641 B3/09/06 BCHWENCER,A Licensing Branch 2 App 20335 248 24X Fiche 50-461,B3/09/06,B309120417
- 8310030080 Forwards safety evaluation accepting snow sampling & vent procedures subj to described mod to Item 6 35 of Procedure BC-452 License Conditions 2 C(7)1 through 20 (ref NUREO-0916) satisfied CRUTCHFIELD, D Operating Reactors Branch 5 83/09/29 MAIER, J E Rockseter Oas & Electric Corp 2pp 20590 069 24% Fiche 50-244,83/09/29,8310030080
- --8310030082 Safety evaluation supporting snow sampling & vent procedures subj to mod to Procedure 8C-452

 * Office of Nuclear Reactor Regulation, Director 83/09/29 4pp 20590 071 24X Fiche 30-244.83/09/29,8310030080
- 8310030140 Comments on potential for flooding of plant site resulting from failure of Goodnough Dike &/or Windsor Dam at Guabbin Reservior Based on Franklin Research Ctr analysis, flooding protection measures provide protection against dam failure GRUTCHFIELD, D. Operating Reactors Branch 5. LS05-B3-09-033 B3/09/26 COUNSIL, W G Connecticut Yankes Atomic Power Co 4pp 20591 071 24X Fiche 50-213,83/09/26,8310030140
- 8310030141 Advises that 820715 % 0930 requests for NRC to concur w/intent to move emergency support ctr & essociated functions from Point Beach Energy Info Ctr to Milwaukee unacceptable, per NUREQ-0737, Suppl I & Generic Ltr 82-33 83/09/14 EISENHUT, D @ Division of Licensing QL-82-33 83/09/14 BURSTEIN,S Wisconsin Electric Power Co App 20604 033 24% Fiche: 50-266, 83/09/14, 8310030141

- B310030167 Forwards Amend 33 to F9AR Amend revises responses to NUREQ-0737.II K items & NRC questions & updates Sections 2 5 1.3 1-3.3 11-12 & 5 2 Affidavit encl OOLDBERG.J H Houston Lighting & Power Co 87-HL-AE-993 83/09/2/DENTON.H Office of Nuclear Reactor Regulation. Director 5pp 20593 323 24X Fiche 50-498.83/09/27.8310030167
- ---8310030168 Amend 33 to FSAR, revising responses to NUREO--0737,11 K items & NRC questions & updating Sections 2 5 1,3 1-3,3 11-12 & 5 2 * Houston Lighting & Power Co 83/09/27 377pp 20593 328 21X Fiche 50-498,83/09/27,8310030167
- 8310030303 Forwards Rev 1 to BAW-1762, "Auxiliary Feedwater Sys Reliability Study for WPPSS Unit 1." in response to NUREG-0737.1tem II E 1 i SORENSEN.0 C Washington Public Power Supply System OL-82-14 83/09/23 ADEMSAM.E 0 Licensing Branch 4 ip 20593 191 24X Fiche 30-460.83/09/23.8310030303
- --8310030306 BAH-1762 R01

 Rev i to "Auxiliary Feedwater Sys Reliability Study of WPPSS
 Unit i "

 * Babcock & Wilcox Co GL-82-14 83/06/30 41pp 20593 183
 24X Fiche 50-440.83/09/23.8310030303
- 8310030308 Forwards response to 830816 memo re 830125 main feedwater line break Response based on NVREO-0918, NVREG-0691 & proposed rev to Jan-Mar AD rept DIRCKS, W J Office of the Executive Director for Operations 83/097/21 ASELSTINE.J K Commissioners 13pp 20604 039 24x Fiche 50-309,83/09/21,8310030308
- 8310030353 Forwards B&W Owners Group final rept, "Bounding Analytical Assessment of NUREO-0630 Models on LOCA kW/ft Limits W/Use of FLECSET" Approval requested MARSHALL, J R Arkansas Power & Light Co 10AN098310 83/09/23 8TOLZ, J F Operating Reactors Branch 4 1p 20592 200 24X Fiche 50-313.83/09/23.8310030353
- --8310630354 77-1140898-01
 "Bounding Analytical Assessment of NUREQ-0630 Models on LOCA kW/ft Limits W/Use of FLECSET"
 * Babcock & Wilcox Operating Plants Owners Group 83/09/30.
 108pp 20592 201. 24X Fiche 50-313,83/09/23,8310030353
- 8310D30354 Requests extension to Apr 1984 to comply w/final rule re TMJ Action Item I A.1 3, "Shift Manning " Justification for granting request provided HARRINGTON W D Boston Edison Co 83-244 83/09/27 DENTON H R Office of Nuclear Reactor Regulation, Director 3pp 20592 340 24X Fiche 50-293,83/09/27,8310030354
- 8310030361 Discusses agreement w/NRC affecting surveillance requirements in NUREG-0892.6ER Suppl 2 re TMI Action Item II.K 3 28 on automatic depressurization sys Bottle pressure verification changed to 31 days SORENSEN.6 C Washington Public Power Supply System 002-83-841 83/09/23 6504ENCER.A Licensing Branch 2 3pp 20592 131 24X Fichs 50-397.83/09/23,8310030361
- 8310030391 Forwards description of Class A radiation dose assessment model, per util 830415 ltr Meteorological info & dose assessment sys Class A (ACRISO) program will be primary dose assessment model in emergency Operations facility ALEXICH, M P Indiana & Michigan Electric Co AEP NRC 07738 83/09/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 20593 056 24X Fiche 50-315,83/09/27,8310030391.
- 8310030419 Forwards draft NUREO-1020, Vol 1, "GPU vs B&W Lawsuit Review & Effect on TMI-1" Portions of Category 10 withheld since info pertains to ongoing investigations.
 CHILK, B. J. Office of the Secretary of the Commission 83/09/30
 Atomic Bafety and Licensing Board Panel 111pp 20602:103 24X
 Fichs 50-289.83/09/30.8310030419
- 8310030425 Forwards proprietary "Final Assessment of Palo Verde Nuclear Generation Station Fuel Assembly Spacer Grid Impact Loads Under Faulted Conditions," per 9ER (NUREO-0857) Section 4 2 1. Affidavit encl. Rept withheld (ref 10CFR2 770) VAN BRUNTLE E Arizona Public Service Co ANPP-27883-WFG/ 83/09/26 KNIGHTON. C. Licensing Branch 3 7pp 20602 219 24X Fichs 50-528.83/09/26.8310030425
- B310030443 Informs that Section 4 31 of integrated plant safety assessment rept (NVREG-0822) dtd Jan 1983 complete.except for implementation of mods to dissel generator trips by end of Cycle 11 outage & IE post-implementation review CRUTCHFIELD.D Operating Reactors Branch 5 LB05-83-09-046 83/09/29 FIEDLER.P B. General Public Utilities GPU Service Corp 2pp 20602 063 24X Fiche 30-219.83/09/29.8310030443

- #310030483 Forwards schedule for responding to #30824 request for addline on inadequate core cooling instrumentation system RUREG-0737, Item II F 2. "Inadequate Core Cooling" RODRIGUEZ, R J Sacramento Municipal Utility District RUR #3-677 #32/09/28 STOLZ, J F Operating Reactors Branch 4 2pp 20401 077 24x Fiche 50-312,83/09/28,8310030485
- 8310030571 Board Notification 83-138A informs of change to previously stated position in NUREG-0680, Suppl 2 RCS leak rate tests contain inadequacies & deviations from regulatory & procedural requirements EISEMHUT, D g Division of Licensing 83/09/23 PALLADING, N . QILINSKY, V . ROBERTS, T Commissioners 5pp 20607 335 24X Fiche 30-289, 83/09/23, 8310030571
- 83:0030601 Forwards comments on 830331 detailed control room design review final rept per Suppl 1 to NUREG-0737 Rept acceptable Heating to discuss comments before 83:017 preimplementation audit recommended ADENSAM. E 0 Licensing Branch 4 83/07/17 CDOM. J W Consumers Power Co 10pp 20607 343 24X Fiche 50-329.83/09/19.83:0030601
- 8310030603 Forwards safety evaluation concurring w/licenses conclusions that NUREG-0737, Item II K 3 2 requirements met w/existing PORV, safety valve & reactor high trip pressure setpoints. Automatic PORV isolation sys (Item II K 3 1) not required VARGA.8 A Operating Reactors Branch 1 83/09/23 CLAYTON.F L Alahama Power Co 14pp 20604 212 24X Fiche 50-348,83/09/23,8310030603
- B3i004001& Forwards one oversite revised flow diagram to comply w/Section 10 4 9 of SER re License Condition 20, loss of primary source of condensate storage water Aperture card is available in PDR TUCKER.H B Duke Power Co B3/09/28 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 2pp 20615 034 24x fiche 50-413, B3/09/28, B310040016
- B310040033 Confirms procedure for estimating core damage since restart from recent outage in response to NRC 830902 ltr Procedure not formalized, but will be incorporated as normal plant operation procedure
 LATHAM: W. K. Sacramento Municipal Utility District RJR-83-665
 83709/26 STULZ, J. F. Operating Reactors Branch 4 1p 20608, 124
 24X Fiche 50-312, 83/09/26, 8310040033
- 8310040035 Forwards safety evaluation of licenses responses to requirements of NUREG-0737. Item II B i, "RCB Vents " Item completed LLL technical evaluation rept encl VARGA. S A Operating Reactors Branch 1 83/09/19 BAYNE. J P Power Authority of the State of New York 9pp 20634 321 24X Fiche 50-286,83/09/19.8310040035
- --B30A030372 TF-334/0806A

 "Selected Operating Reactor Issues Program II RCB Vents
 (NOMES-0737, Item II B 1)." final technical evaluation rept
 HELD, J T Energy Incorporated * Lawrence Livermore Laboratory
 FIN A-0250 TAC 44379 83/02/14 ALBERTMAL/O Division of
 Licensing 6pp 20634 330 24% Fiche 50-286,83/09/19,8310040035
- 8310040052 Forwards 9-month response for NUREQ-0612, "Control of Heavy Loads at Nuclear Power Flants" Electrical interlocks prevent main hoist of reactor bidg crane from being used over reactor well or spent fuel pool CURTIS.N W Pennsylvania Power & Light Co PLA-1843 83/09/29 SCHWENCER.A Licensing Branch 2 63pp 20608 143 24X Fiche 50-388,83/09/29,8310040052
- 8310040110 Forwards final schedule for satisfying requirements of Generic Ltr 82-33 re Suppl i to NUREQ-0737, "Requirements for Emergency Response Capability"

 SCH-MENCER, A. Licensing Branch 2 GL-82-33, 83/09/26 BAUER, E. Q. Philadelphia Electric Co. 4pp. 20634-336 24X

 Fiche 30-332,83/09/26,8310040110
- B310040111 Responds to 830531 & OB26 ltrs requesting amend to 830318 confirmatory order to NUREQ-0737. Item II.F 1.5, "Containment Water Level Monitor" Amend not required Environ qualification will be addressed in 100FRSD 49 audit STOL7. JF Operating Reactors Branch 4 83/09/02 TUCKER. H B Duke Power Co 5pp. 20627 351 24% Fiche 50-269, 83/09/02.
- B310040120 Forwards "Control of Heavy Loads at Nuclear Power Plants, VC Summer Nuclear Station. Unit i (PHASE I); " EG&O technical evaluation rept Bynopsis re NRC interpretation of NUREG-0612 guidelines for resolution of open items encl NOVAK: T M Assistant Director for Licensing 83/09/16 DIXON: D H South Carolina Electric & Qas CO 2pp 20640 274. 24X Fiche 50-395,83/09/16,8310040120

- 8310040123 EQC-HS-6371
 "Control of Heavy Loads at Nuclear Power Plants.VC Summer Nuclear Station.Unit 1 (PHASE I)." technical evaluation rept FRIEDERICHS.S EG&O, Inc. FIN A-6457 B3/08/31 NRC No Detailed Affiliation Qiven 49pp 20640 276 24X Fiche 50~395.83/09/16.8310040120
- B310040227 Forwards info to resolve SER License Condition 7 per TMI Action Plan Item II 0 3. "Post-Accident Sampling Sys."

 W/two oversize drawings Apprture cards are available in PDR Proprietary info withheld (ref iOCFR2 790)

 EDELMAN.M R Cleveland Electric Illuminating Co PY-CEI/NRR-0060 83/09/16 VGUNGSLOOD B J Licensing Branch 1 4pp 20612 067 24X Fiche 50-440.83/09/16.8310040227
- --B310040229 "Evaluation of Post-Accident Sampling Sys for Perry Nuclear Power Plant "

 * Cleveland Electric Illuminating Co B3/07/31 3ipp.
 20612 071 24% Fiche 50-440.83/09/16.8310040227
- ~-8310040231 Preliminary Rev O to Procedure CHI-22, Chemistry Equipment Instruction, "Single Channel Analyzer Canberra " HEBTBROOM-H W Cleveland Electric Illuminating Co. 83/09/16. 17pp 20612 102 24X Fiche 50-440.83/09/16.8310040227
- --8310040234 Preliminary Rev O to Procedure CHI-12, Chemistry Equipment Instruction, "Multi-Channel Analyzer Camberra-Berles 85 " WESTBROOK, W M Cleveland Electric Illuminating Co 83/09/16 18pp 20612 119 24% Fiche 50-440,83/09/16,8310040227
- 8310040259 Advises that assessment of two viable options for location of grimany emergency operations facilities, per Suppl 1 to NUREO-0737, scheduled for completion in early Nov 1983 Final decision expected by 831119 MURPHY, W P Vermont Yankee Nuclear Power Corp FVV 83-104 83/09/29 VASPALLO, D B. Operating Reactors Branch 2. 2pp 20617 266 24X Fiche 30-271,83/09/29,8310040259.
- B310040287 Forwards Rev 2 to B30414 response to Suppl 1 to NURE9-0737, including rept on review of Reg Ouide 1 97
 TUCKER, H B Duke Power Co B3709/26 DENTON, H.R Diffice of Nuclear Reactor Regulation, Director ADENBAN, E. Q. Licensing Branc 4 71pp 20614 077 24X Fiche 50~413, B3/09/26, B310040287
- B310040300 Forwards IE Insp. Rept 50-312/83-24, Portions of post-accident sampling sys (NUREO-0737: Item II B.3) inoperable, Reasonable degree of sys reliability remains undemonstrated HENSLAMSKI.F A Region 5. Diffice of Director B3/09/23 STOLZ, J | Operating Reactors Branch 4 | Ip 20612 338 24% Fiche-50-312,83/09/23,8310040300
- --8310040311 IE Insp Rept 50-312/83-24 on 830712-16 Noncompliance not licensee unable to sample containment atmosphere using post-accident sampling sys.hydrogen monifors or reactor bidg atmosphere monitor NORTH. H S . YUHASI O P Region 5. Office of Director, WENSLAWSKI.F A Region 4. Office bf Director. 83/09/23 12pp 20612 341 24X Fiche 50-312,83/09/23,8310040300
- 8310040301 Forwards B&H "Bounding Analytical Assessment of NURE9-063 Models on LDCA tW/Ft Limits W/Use of FLECBET." completing response to NUREQ-0630 Compensating models documented & justification for model use provided MESTAFER.0 R Florida Power Corp 3F-0983-20 83/09/29 8TOLL.J F Operating Reactors Branch 4 2pp 20612 227 24X Fiche 50-302.83/09/29,8310040301
- --8310040304 77-1140898-01
 "Bounding Analytical Assessment of NURE9-0630 Models on LOCA kW/Ft Limits W/Use of FLECSET."
 * Babcock & Wilcox Co 83/09/30 109pp 20612-229, 24X Fiche 50-302,83/09/29,8310040301.
- B31004031D Forwards addl info requested in B30B10 telcon re Frenkli Researc. Ctr B30617 draft technical evaluation rept on util response to Phase i of NuREG-0612, "Control of Heavy Loads at Nuclear Power Plants "
 FAY.C W Wisconsin Electric Power Co. 83/09/2B, MILLER, J. R Office of Nuclear Reactor Regulation, Director Bpp 20613 096 24x Fiche 50-266,83/09/2B,8310040310
- B310040336 Forwards Procedure AD NP.16. "Nuclear Production Direct Emergency Procedure Generation Program," per NUREG-0737. Suppl 1 (Generic Ltr 82-33). HILLIAMS.J Cincinnati Gas & Electric Co. LOZ-83-0168. B3/09/DENTON.H R Office of Nuclear Reactor Regulation, Director. 2; 20617 133 24X Fiche 50-358, B3/09/30, B310040336

- 8310040353 Forwards "Pressurizer Relief Valve Qualification," & Rev 1 to "Pressurizer Safety Valve Operability Rept," per NUREG-0737. Item II D : Design load stresses on piping & fittings within allowable limits LUNDVALL.A E Baltimore Gas & Electric Co 83/09/28 MILLER.J R Operating Reactors Branch 3 4pp 20615 036 24X Fiche 50-317.83/09/28.8310040353
- 8310040363 Forwards response to NRC 830601 SER re Westinghouse Owners Ordup amergency response guidelines per Suppl ! to NUREO-0737 SHEPPARD.J J Westinghouse Operating Plants Owners Group
 - NUREW-0/J/ SHEPPARD.J J Westinghouse Operating Plants Owners Group SHEPPARD.J J Carolina Power & Light Co OG-105 83/09/27 EISENHUT.D G Division of Licensing 42pp 20620 235
- B310040387 Submits evaluation of existing Hestinghouse STB provisions. ASME Code Section XI.Reactor Safety Study (MASH 1400). NUREQ-0677 & EG&Q rept. "Inservice Leak Testing of Primary Pressure Isolation Valves." as applicable to plant design CLAYTON.F L Alabama Power Co B3/09/27 VARGA.S A Office of Nuclear Reactor Regulation. Director 16pp 20625 200 24X Fiche 50-348.83/09/27.8310040387
- I310040402 Forwards results of preliminary lighting survey for main control room, per 830727 request & NUREO-0700 HILLS:L N Tennessee Valley Authority 83709/29 ADENBAM, E Liesneing Branch 4 2pp 20617 352 24X Fiche 50-390, 83709/29, 8310040402
- 310040415 Forwards "Implementation of NUREQ-0619 Feedwater Nozzle Cracking," & proprietary "Peach Bottom Atomic Power Station, Unit 2, Feedwater Nozzle Fracture Mechanics Analysis to Show . "Proprietary rept withheld (ref 10CFR2 790)
 QALLAGHER, J W Philadelphia Electric Co 53/09/29 EISENHUT, D O Division of Licensing 2pp 20623 303 24% Fiche 50-277,83/09/29,8310040415
- -8310040429 "Implementation of NUREG-0619 Feedwater Nozzle Cracking " Affidavit encl * Philadelphia Electric Co 83/09/30 19pp 20623.305 24X Fiche 50-277,83/09/29,8310040415
- NOO40420 Confirms that technical support ctr designed to be continuously habitable for 30 days following post-accident release described in Reg Quids 1 4.Rev 2, dtd June 1974 Shielding conforms w/NUREO-0737. Items 11 B 2 & III A 1 2 HEBTAFER.0 R Florida Fower Corp 3F-0983-19 83/09/30 BENTON, HR Defice of Nuclear Reactor Regulation, Director 120619.040 24X Fiche 50-302,83/09/30,8310040420
- 10040434 Forwards safety analysis re basis on which selected parameters for safety parameter display sys sufficient to sases safety status of each function for wide range of svents, per Generic Ltm 82-33, Suppl 1 to NUREO-0737 PALLAGHER, J W Philadelphia Electric Co GL-82-33 83/09/28 EISENHUT, D G Division of Licensing Spp 20619 108 24X Fichs: 50-277, 83/09/28.8310040434
- 0040431 Forwards safety evaluation supporting Westinghouse licensee 'esponses to NUREO-0737.Items II K 3 I. "Automatic PORV solution" & II K 3 2. "Rept on PORVS" & Franklin Research tr "Operating Resector PORV Repts (F-37).TMI Action ." RUTCHFIELD.D Operating Reactors Branch 5 LS05-83-09036. 3/09/27. MAIER.J E Rockester Osa & Electric Corp 17pp. 0624 106 24X Fiche 50-244.83/09/27.8310040451
- 0040436 Forwards safety evaluation of NUREO-0737, Item II B 3. Post-Accident Sampling Sys " Util meets six of il riteria Comments requested within 30 days H/a encl ADBEN.O L NRC No Detailed Affiliation Given B3/07/22 EE.O R. Public Service Co of Colorado ip 20624 225 24X iche: 50-267,83/09/22,8310040456
- NAME OF THE PROPERTY OF CONTRACT OF THE PROPERTY OF THE PROPER
- 040532 Forwards IE Insp Rept 50-528/B3-38 on B30801-31.No ncompliance noted SMOP.T.W Division of Resident, Reactor Project & Engineering ograms B3/09/19 ANDOGNINI, 9 C Arizona Public Service Cop 2042 010 24% Fiche 50-528, 83/09/19, 8310040332
- 10040537 IE Insp Rept 50-528/83-38 on 830801-31 No noncompliance noted Major areas inspected; equipment qualification, startup testing. THI following items.NBSB problems & plant mod TIRRELLI.9, JOHNSTON,9, YOUNG,T. Region 5, Office of Director 33/09/15, 7pp 20624 012 24x Fiche, 50-528, 83/09/19, 8310040532

- 8310040551 Forwards CE Axtell & RM Marusich testimony re Christa-Maria emergency planning Contention 7(6)
 OALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co
 B3/09/30 BLOCH.P B · PARIS.O H · SHON.F J Atomic Safety and
 Licensing Board Panel Ip 20622 130 24% Fiche 50-155,83/09/30.
 B310040551
- --831004056D Testimony of RM Marusich re Christa-Maria Contention 9(4) on emergency planning radiation monitoring Util has capability to assess degree of core damage promptly following accident MARUSICH.R M Consumers Power Co 83/09/30 16pp 20622 131 24% Fiche 50-155.83/09/30,8310040551
- --8310040564 Testimony of CE Axtell re Christa-Maria Contention 9(6) on emergency planning radiation monitoring Use of noble gas effluent monitors, in-plant iodine instruments & containment high-range radiation monitors discussed AXTELL, C E Consumers Power Co 1980ANCES OLA 83/09/30 13pp 20622 147 24X Fiche 50-155,83/09/30,831004055)
- 8310040561 Forwards "Program Plan for Implementation of Control Room Design Review of Beaver Valley Power Station." following guidelines in Suppl 1 to NUREG-0737.per Generic Ltr 82-33 GAREY. J. Duquesne Light Co. GL-62-33 B3/09/27 EISENHUT. D. G. Division of Licensing Spp. 20422 145 24X fiche 50-334.83/09/27.8310040541
- ---8310040569 "Program Plan For Implementation of Control Room Design Review of Beaver Valley Nuclear Power Station " * Duquesne Light Co. 83/09/27 98pp 20622 168 24X Fiche 50-334,83/09/27,8310040561
- B310040597 Forwards response to draft technical evaluation rept assessing conformance w/general load handling guidelines of NUREO-0412. "Control of Heavy Loads at Nuclear Power Plants," Addl response will be provided by B31115

 LEMPOES. T E Niagara Mohawk Power Corp 83/09/30 EISENHUT, D G Division of Licensing 9pp 20425 327 24X Fiche 50-220,83/09/30.8310040597
- B310040630 Rept on mod of automatic depressurization sys logic in response to ASLB request ABLB should defer further consideration pending status rept on implementation of Option 2, due by 840115 Certificate of Svc encl ELLIS.TS Long Island Lighting Co ELLIS.TS Hunton & Williams ISBUANCES GL 83/09/30 7pp 20626 035 24X Fiche 50-322, 83/09/30.8310040630
- 8310040648 Forwards safety evaluation & Franklin Research Ctr technica' evaluation rept. "ECCS Repts (F-47) Action Plan Requirements Toledo Edison Co. Davis-Desse Nuclear Power Station, Unit! "NUREG-0737: Item II K 3 17 requirements met STOLZ. J F Operating Reactors Branch 4 83/09/01 CROUSE, R P Toledo Edison Co 4pp 20627 285 24X Fiche 50-346, 83/09/01, 8310040648
- --B2i2010152 TER-C5506-273

 "ECCS Repts (F-47), TMI Action Plan Requirements,

 Pavis-Besse Nuclear Power Station, Unit 1," technical

 evaluation rept

 VOSBURY. F W Franklin Institute/Franklin Research Center

 NRC-03-81-130 82/11/24 CHOW. E NRC No Detailed Affiliation

 Given 14pp 20627 289 24X Fiche 50-346, 03/09/01, 0310040648
- 8310D40650 Advises that changes re sonic flow devices meet requirement: of NUREG-0737. Item II E 1 2. "Auxiliary Feedwater Bys
 Automatic Initiation & Flow Indication" & are acceptable based on review of licenses 830524 & 0825 ltrs
 8TOLX. J F Deparating Reactors Branch 4 83709722 HUKILL.H D General Public Utilities QPU Service Corp 5pp 20627 319 24% Fiche 50-289, 83/09/22,8310040650
- B310050004 Advises that NUREG-0737, Item II B 2 2. "Design Review of Plant Shielding Corrective Actions for Access to Vital Areas." requirements met based on review of licensee B00102, 31, 1015, 810108, 820415, 0707 & 830513 submittals STOLZ.J F Operating Resctors Branch 4 83/09/12 BAUER.E 9 Philadelphia Electric Co 5pp 20650 242 24X Fiche 50-277, 83/09/12,8310050004
- B310050101 Forwards summary of proposed integrated plant safety assessment (NUREO-0827) & SEP Topics III-3 A, III-4 B & VIII-1 A Printing error in NUREO-0485 corrected to read 01/01/84.
 LINDER, F Dairyland Power Cooperative LAC-9324 83/09/29 CRUTCHFIELD. D Operating Reactors Branch 5 21pp 20628 289 2 Fiche 50-409.83/09/29.8310050101

8310050148 Forwards safety evaluation re NUREG-0737.1tem II K 3 2 k Westinghouse Duners Group Rept WCAP-9804 based on results entl in Frankin Research Ctr technical evaluation rept Automatic PORV isolation sys not required Automatic PORV isolation sys not required VARGA.5 A Operating Reactors Branch I 83/09/13 0'TQQLE.J D Consolidated Edison Co of New York. Inc 149p 20639 100 24x Fiche 50-247.83/09/13 8310050148

B380050217 NUREO/CR-3334 VD1
MEANY SECTION STEEL TECHNOLOGY PROGRAM QUARTERLY PROGRESS
MEFORT FOR JANUARY - MARCH 1983
PUGH, C E Dak Ridge National Laboratory FIN 8-0119
PUGH, C E Dak Ridge National Laboratory FIN 8-0119
CHRM./TM-8787/V1 83/09/30 Division of Engineering Technology
191pp 20636 354

8310050224 NUREO/CR-3299
CGRE RELY MATERIALS INTERACTIONS EVALUATIONS Final Report,
April 1980 - April 1983
SWANSON,D G CASTLE,J N , ANDERSON,P D Applied Science Associates,
Inc FIN B-6823 83/09/30 Division of Systems Integration (post 811005) 297pp 20635 318

B316050232 NUREG-0852 802

SAFETY EVALUATION REPORT RELATED TO THE FINAL DESIGN OF THE STANDARD NUCLEAR STEAM SUPPLY REFERENCE SYSTEM. CESSAR SYSTEM BD Docket No. 50-470 (Combustion Engineering Incorporated)

* Diffic of Nuclear Peactor Regulation, Director 83/09/30 163pp 20635 151 24% Fiche 50-470, 83/09/30, 8310050232

8310030239 NUREQ/CR-3472 V01 SURFACE PROPERTIES AND PERFORMANCE PREDICTION OF ALTERNATIVE WASTE FORMS HENCH.L L. CLARK, D E Florida State Univ 83/09/30 Division of Health. Siting & Waste Management 99pp 20636 250

8319050244 NUREG-0750 V17 N04
NUCLEAR REGULATORY COMMISSION ISSUANCES April 1983
Pages 525-729

***Division of Technical Information & Document Control 83/04/30
210pp 21020 313

8310050253 MUREO/CR-3401
LABORATORY-SCALE SUDIUM-CARBONATE AGGREGATE CONCRETE
INTERACTIONS
MESTRICH:H R , STOCKMAN,H W , SUD-ANTTILA.A Sandia Laboratories
FIM A-1054 SANDES-1502 83/09/30 Division of Accident
Evaluation 64pp 20635 084

83:0050297 Forwards safety evaluation on installation of RCS high point vents per NUREO-0737. Item II B 1, "RCS Vents" & final technical evaluation rept Vent sys acceptable subj to post-implementation audit STOLZJ F Operating Reactors Branch 4 83/08/08 WILCUS, W S Florida Power Corp Spp 20650 057 24% Fiche 50-202.83/08/08, 83:10050297

--8310000304 Safety evaluation supporting installation of RCS high point years per NUREQ-0737. Item II B 1. "RCS Vents"

*** NRC - No Detailed Affiliation Given 93/05/26 10pp
20650 060 24% Fichs 50-302.83/08/08.8310050297

-8306080306 TF-370/0817A

"Selected Operating Reactor Issues Program II:RCS Vents
(NUREG-0737, Item II B 1)," final technical evaluation rept
HELD, J T Energy Incorporated HELD, J T Lawrence Livermore
Laboratory FIN A-0250 TAC 44365 83/03/14 ALBERTHAL, O
Division of Litensing App 20650 070 24X Fiche 30-302,
83/08/98.8310050297

110050331 NUREG/CR-3437
DATA ANALYSIS USING DIONOMIAL FAILURE RATE COMMON CAUSE MODEL
ATHORDR.C.L EG&G, Inc FIN A-6283 EGG-2271 B3/09/30 Division of Risk Analysis RBpp 20639 069

10050935 NUREO/CR-3464
THE APPLICATION OF FRACTURE PROOF DESIGN METHODS USING THE PROOF DESIGN METHODS USING THE PROOF DESIGN METHODS USING THE PROOF OF T

0050337 NUREO-0020 VO7 NO6 ICEMBED OPERATING REACTORS STATUS SUMMARY REPORT Data As Df lag 31.1983 (Gray Book) Hanagement Information Branch 83/09/30 394pp 20697.187 8310050435 Forwards NUREG-1000, Vol 2, "Generic Implications of ATMS Events at Salem Nutlear Power Plant" & SECY-83-248, "Generic Actions for Licensees & Staff in Response to ATMS Events at Salem " W/o encis ROTHSCHILD, M V Hearing Branch 1 83/09/27 BLOCH, P B . JGRDAN, W H . MCCOLLOM, M A . Atomic Safety and Licensing Board Panel 1p 20428 342 24x Fiche 50-445, 83/09/27, 8310050435

B310050492 Forwards 1E Insp Rept 50-341/B3-18 on B30822-26 No noncompliance noted LITTLE: W S Region 3. Office of Director B3/09/23 WELLB: A Detroit Edison Co 2pp 20628 352 24x Fiche 50-341, 83/09/23, B310050492

--8310050497 IE Insp Rept 50-341/83-18 on B30822-24 No noncompliance noted Major areas inspected action taken on 100FR50 55(*) items. IE bullstins, IE circulars, previous insp findings & électrical design revieu RILLIAMS. C C. AMMED. I H. NAIDULK R. Region 3, Office of Director IEB-75-04 B3/09/22 Bpp 20628 354 24X Fiche 50-341,83/09/23,8310050472

B310050512 Responds to ASLAB request for NRC final position on review of upgraded auxiliary feedwater sys & related questions. Util rescheduled completion of upgraded sys to refueling Outage 8 currently estimated in Apr 1986 LEBBY. RP Hearing Branch 3 IBSUANCES SP 83/09/27 ROSENTHALA S . BUCK. J H . KOHL. C N Atomic Safety and Licensing Appeal Panel 3pp 20634 050 24% Fiche 50-312,83/09/27,8310050512

~-B310030321 Affidavit of ED Sylvester re ASLAB questions on installation of upgraded duxiliary feedwater sys per TMI Item II E i i Upgraded design will not meet current reliability guidelines SER encl SYLVESTER.E D Auxiliary Systems Branch ISSUANCES SP 83/09/27 46pp 20634 076 24X Fichs 50~312.83/09/27.8310030512

8310050524 Forwards SER re util response to NUREG-0737. Item II B 1, "RCB Vents " Item complete CRUTCHFIELD, D Operating Reactors Branch 5 LSD5-83-10-002 63/10/03 FARRAR, D L Commonwealth Edison Co 6pp 20632 335 24X Fiche: 50-237.83/10/03,8310050524

--8310090534 TF-380/0623A

"Balected Operating Reactor Issues Program II RCS Vents
(NVR60-0737, Item II B 1)," final technical evaluation rept
for Dresden Units 2 t 3

HELD, J T Laurence Livermore Laboratory FIN A-0250 TAC 44269
63/04/06 ALBERTHAL, 0 NRC - No Detailed Affiliation Given 4ps
20632 341 24X Fiche 50-237,83/10/03.8310050524

8310050537 Memorandum & order granting util request to defer further consideration of mod to automatic depressurisation syslogic pending receipt of util status rept on progress of implementation of mods by 840116

3RENNER.L. Atomic Bafety and Licensing Board Panel 83/10/03

Long Island Lighting Co 4pp 20629 354 24X Fiche 50-322.

83/10/03.8310050537

8310060021 Forwards "Control Room Design Review Program Plan," per B30415 & 0720 commitments in response to Suppl J to NUREO-0737 RODRIGUEZ, R J Sacramento Municipal Utility District RJR-83-674 03/09/30 STOLZ, J F Operating Reactors Branch 4 lp 20649 262 24% Fiche 50-312:83/09/30.8310060021

---B310060022 "Control Room Design Review Program Plan" * Bacramento Municipal Utility District B3/09/30 14p 20649 263 24X Fiche 50-312,83/09/30,8310060021

8310060031 Forwards Amend 81 to License DPR-62 & safety evaluation Amend revises Tech Specs re instrumentation used to monitor water level in suppression chamber of primary containment sys (NUREO-0737, Item II F 1 5) MACKAY.S D Operating Reactors Branch 2 83/09/22 UTLEY.E E Carolina Power & Light Co 2pp 20664 101 24X Fiche 50-324.83/09/22,8310060031

8310060079 NUREO/CR-3496
RADIOLOGICAL SURVEY OF THE NUCLEAR FUEL SERVICES.INC ERWIN
PLANT BURIAL SITE.
BOOTHL F . NYERGES, P L . GROFF, D. H Radiation Management Corp FIN
B-6901 B3/09/30 Division of Fuel Cycle & Material Safety
54pp 20664 001.

8310060157 Provides addl comments on AD rept to Congress for Becomd Guarter CY83 re proposed update of AD 73-5. "Cracks in Pipes at BHRs " DENTON.H 8 Office of Nuclear Reactor Regulation, Director 83/09/27 HELTEMES.C J Director's Office Spp 20463 289

- --B3G9160038 Forwards draft Commission paper, ltrs to Congress & Second Quarter CV83 AO rept to Congress (NUREG-0090) Updated in Forequested HELTEMES, C.J. Director's Office 83/08/31 DENTON, H.R. Office of Nuclear Reactor Regulation, Director DAVIS, J.O. Office of Nuclear Material Safety & Safeguards, Director HINOGUE, R.B. Office of Nuclear Regulatory Research, Director 46pp 20663 297
- B310060211 Forwards SAR for safety parameter display sys in response to Generic Ltr 82-33.psr AURED-0737. Buppl 1 & util 830415 itr Implementation schedule for safety parameter display sys and CURTIS.N W Pennsylvania Power & Light Co PLA-1882 B3/09/30 SCHHENCER.A Licensing Branch 2 98pp 20646 279 24% Piche: 50-387. B3/09/30.8310060211
- 8310060226 Forwards plan & schedule for resolution of NUREG-0737, Item II & 3.5. "Automatic Trip of Reactor Coolant Pumps."
 (Generic Ltr 83-10).per NRC 830208 request Operating procedures for pumps to be revised CROUSE, R P Toledo Edison Co. 987 83/10/03 EISENHUT, D 9 Division of Licensing App 20647 015 24% Fiche 50-346.83/10/03.8310060226
- B310040357 Submits amended implementation schedule for Suppl 1 to NUREO-0737 requirements for safety parameter display sys & Reg Guide 1 47 Listing of parameters available for display encl DRUMMOND, F J Louisians Power & Light Co W3P83-2936 83/09/29 KNIGHTON, G W Licensing Branch 3 Jpp 20646 107 24X Fichs 50-382,83/09/29,8310060357
- 8310060357 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept of util response to TMI Item II K 3 17, "Rept on Outages of ECCS" VAR9A, S A Licensing Branch i 83/09/27 UDERITZ,R, A Public Service Electric & Cas Co of New Jersey 4pp 20864 127 24X Fiche 50-272,83/09/27,8310060537
- --B210010087 TER-C5506-274

 "ECCS Repts (F-47) TMI Action Plan Regirements:PSE&G, Balem
 Nuctear Generating Station Unit 1." technical evaluation
 rept
 VDSBURY, F W, OVERBECK, G J, LUDINGTON, B W Franklin
 Institute/Franklin Research Center NRC-03-80-130 82/09/28
 CHGN, E NRC No Detailed Affiliation Given 14pp 20664 13
 24X Fichs 50-272, 83/09/27, 8310060557
- B310060583 Comments on proposed design for compliance w/NUREG-0737, Item II.K 3 13. "Beparate HPCI & RCIC Initiation Levels" re automatic restart Proposal acceptable VASSALLO, D B Operating Reactors Branch 2 83/09/19 PARRIS, H O Tennessee Valley Authority 3pp 20661 204 24X Fiche 50-259.83/09/19.8310060583
- 83:0070084 Forwards cafety evaluation of util response to NUREC-0737, Itam II 0 i, "Reliability Engineering" re safety & reliaf valve testing Requirements met Itam resolved VASSALLO.D B Operating Reactors Branch 2 83/09/22 BAYNE.J P Power Authority of the State of New York 17pp 20671:317 24X Fiche 50-333,83/09/22.8310070084
- 6310070077 Forwards safety evaluation of design of RCB vents Design conforms w/requirements of NUREG-0737 Item II. B. 1, QDC 1, R. 4, 14, 30 & 31 & 10CFR50 44(c)(3)(1ii) w/exception of positive valve position indication VARQA.5 A Operating Reactors Branch I 83/09/27 UDERITZ, R. A Public Service Electric & Oas Co of New Jersey 3pp 20473; 349 24% Fiche 50-272,83/09/27,8310070097
- --B310070103 Safety evaluation of RCS vent design Design compiles w/ NUREQ-0737. Item II B 1,000 1,2.4.14,30 & 31 & 10CFR30.44 + NRC - No Detailed Affiliation Given B3/05/17 6pp 20673:352 24X Fiche 50-272,83/07/27.8310070097
- --8304080112 TF-343/0807A

 "Selected Operating Reactor Issues Program II RCS Vents
 (MUREGO-0737, Item II B 1)." Final technical evaluation rept
 for Salem 1 & 2.

 HELD, J. T Energy Incorporated. FIN A-0250, TAC 44405 83/02/23

 ALBERTHAL, O. Division of Licensing. App. 20673 358 24X
 Fiche-50-272,83/09/27,8310070097
- B310070110 NUREG/CR-3475
 CRITICAL DISCHARGE OF INITIALLY SUBCOOLED WATER THROUGH
 SLITB.
 B117B.
 B108.C N . SCHROCK.V E. Lawrence Barkeley Laboratory FIN 8-3043
 LBL-14363 B3/09/30. Division of Accident Evaluation 298pp
 Available at NRC. \$7.00. 20672 001

- 8310070116 NUREG-0420 S04

 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF THE SHOREHAM NUCLEAR POWER STATION.UNIT NO 1 DOCKET NO 50-322 (Long Island Lighting Company)

 * Division of Lighting B3/09/30 71pp Available at NRC \$4 50 20671 122 24X Fiche 50-322.83/09/30,8310070116
- 8316070154 NUREO/CR-3327
 ANALYSIS OF STRONG-MOTION DATA FROM THE NEW HAMPSHIRE
 EARTHQUAKE OF 18 JANUARY 1982
 CMAND,F K. Army. Dept. of. Army Engineer Waterways Experiment
 Station FIN 8-8251 83/09/30 Division of Health. Siting &
 Waste Management 76pp Available at NRC \$4 50 20671 193
- 8310070166 Advises that automatic PORV isolation will not be provided : PORV & block valve control sys will not be modified, based on "Probabilistic Analysis & Operational Data in Response to NUREG-0737. Item II K 3 2 for Westinghouse NSSG Plants "LIDEN, E A Public Service Electric & Gas Co of New Jersey B3/09/27 VARGA S Operating Reactors Branch 1 2pp 20659 108 24X Fiche 30-272, 83/09/27,8310070166
- 8310070250 Forwards "Petailed Control Room Design Review of Plant, St Lucie Unit 2 Nuclear Power Station (NUREG-0737, Suppl 1)," per 830415 commitment UHRIO,R E Floride Power & Light Co L-83-504 93/09/30 EISENHUT,D 0 Division of Licensing 1p 20459 128 24% Fiche 50-389,83/09/30,8310070250
- ~-8310070253 "Detailed Control Room Design Review of Plant.St Lucie Unit 2 Nuclear Power Station." summary rept UHRIG.R E Florida Power & Light Co 83/09/30 315pp 20459 129 24X Fiche 50~389,83/09/30,8310070250
- B310070291 Forwards "Position Paper on Reg Guide 1 97" & "Response to NUREO-0737. Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities "
 ZIMMERMAN.S R Carolina Power & Light Co LAP-83-408 83/09/30 VASSALLO.D B Operating Reactors Branch 2 1p 20655 177 24X Fiche 50-324.83/09/30.8310070291
- --8310070293 "Position Paper on Reg Guide 1 97 " BROWN.W E. WASENKO.M Carolina Power & Light Co 83/08/09 33pp 20655 178 24X Fiche 50-324.83/09/30.8310070291
- ---B310070295 "Response to NUREG-0737. Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities " BROWN. H E. MABENKO.M Carolina Power & Light Co 83/08/09 77pp 20655 211 24X Fiche 50-324. 83/09/30.8310070291
- 8310970317 NNREG/CR-3384
 VISA A COMPUTER CODE FOR PREDICTING THE PROBABILITY OF
 REACTOR PRESSURE VESSEL FAILURE
 RTEVENS,D L , KLECKER.R H , SIMONEN,F A Battelle Memorial
 Institute, Pacific Northwest Laboratory FIN B-2310 PNL-4774
 83/09/30 Division of Engineering Technology 92pp Available at
 NRC, \$4 50 20679 236
- 8310070320 NUREO/CR-3487
 REGIONAL-INTERSTATE SITE REVIEW PROCEDURE LOW-LEVEL
 RADIOACTIVE WASTE DISPOSAL FACILITY
 * Southern States Energy Board FIN 8-50206 83/09/30 Division
 of Health, Siting & Waste Management 123pp Available at NRC
 \$5 00 20479 113
- 8310070323 NUREG/CR-3425
 LOW-ENERGY PHOTON DOSE DEPOSITION IN TISSUE SLAB AND
 SPHERICAL PHANTOMS
 NELSON, R F. CHILTON, A B lilinois, Univ of Urbana, IL FIN
 B-8101 B3/07/30 Division of Facility Operations 60pp
 Available at NRC \$4 50 20669 245
- 8310070340 Forwards Suppl 1 to plant-specific evaluation of EPRI safety & relief valve performance testing submitted on 821215
 Suppl details adequacy of inlet & discharge piping for pressurizer safety & relief valves per TMI Item II D 1
 BAYNE, JP Power Authority of the State of New York IPN-83-82
 83/09/30 VARGA 8 A Operating Reactors Branch 1 8pp 20652 157
 24X Fiche 50-284,83/09/30,8310070340
- B310070349 Forwards payment of fees for B30503 & 0601 applications for amends to License DPR-64 Payment made under protest pending final determination of legality of fee schedule BAYNE, J.P. Power Authority of the State of New York IPN-83-83 83/09/30 MILLER, W.O. License Fee Management Branch 2pp 20651 097 24X Fiche 50-286, 83/09/30, 8310070349
- 8310070406 Forwards SER re util 791231 submittal concerning design of RCS vents Vent sys in conformance w/guidelines of NVREG-0737. Item II B 1 Item closes VAROA. B A Operating Reactors Branch 1. 83/09/23 UTLEY. E Carolina Power & Light Co 14pp 20676 330 24X Fiche 50-261.83/09/23.8310070406

- 0310070408 Forwards SER re control of heavy loads based on util response to 801222 generic ltr Guidelines in NUREG-0512. Section 5 1 1 & 5 3 satisfied VARDA: S A Operating Reactors Branch 1 83/09/20 DDLAN. J Indiana & Michigan Electric Co 2pp 20675 332 24X Fiche 50-315.83/09/20.8310070408
- --B310070409 Safety evaluation re control of heavy loads Quidelines in NUREO-0612 Section 5 1 1 & 5 3 satisfied NRC NO Detailed Affiliation Given B3/09/20 2pp 20475 334 24X Fithe 50-315.83/09/20.8310070408
- --8309060263 TER-C5506-344/345
 "Centrol of Heavy Loads (C-10) Indiana & Michigan Electric
 Co.DC Cook Nuclear Plant Units 1 & 2." technical evaluation
 rept
 VOBBURY,F W , BOMBERGER,C R Franklin Institute/Franklin Research
 Center NRC-03-81-130 TAC 07980 83/09/01 SINOH,A NRC No
 Detailed Affiliation Given 33pp 20675 336 24x
 Fiche 50-315,83/09/20.8310070408
- B310070411 NURE9/CR-2482 VO4
 REVIEW OF DDE WASTE PACKAGE PROGRAM Subtask 1 1 National Waste Package Program, October 1982 March 1983
 SDO: P Brookhaven National Laboratory BNL-NURE0-51494
 Division of Waste Hanagement 180pp Available at NRC \$6.00
- B310D70414 NURCG/CR-34/3
 ROCK MASS STALING-EXPERIMENTAL ASSESSMENT OF BOREHOLE PLUG
 PERFORMANCE Annual Report June 1982 May 1983
 DARMAN, J J K , STORMANT, J C , COLDURN, N I Afizona, Univ of,
 Tucson AZ FIN B-6627 83/09/30 Division of Health, Siting &
 Waste Management 298pp Available at NRC 47 50 20676 006
- 0310070426 NUREG/CR-3122
 POTENTIAL DAMAGING FAILURE MODES OF HIGH-AND MEDIUM-VOLTAGE
 ELECTRICAL EQUIPMENT
 HOV.H C Dak Ridge National Laboratory FIN 8-1672 ORNL/NBIC-213
 83/08/31 Director's Office 90pp Available at NRC \$4
- 8310070436 NUREO/CR-3371 VO2
 TABK ANALYBIS OF NUCLEAR POWER PLANT CONTROL ROOM CREWS
 Volume 2 Data Rosults
 BURGY, D., LEMPGES, C., MILLER, A. General Physics Corp. FIN B-7491
 GP-R-221020 BJ/09/JO Division of Facility Operations 353pp
 Available at NRC #8 00 20673 001
- B310070437 NUREQ-1020 VOI

 QPU V BAN LAMBUIT REVIEW AND ITS EFFECT ON TMI-1 General
 Public Utilities Corporation.et al V The Babcock & Wilcox
 Company.et al Three Mile Island Nuclear Station.Unit I
 Docket No 50-289

 # Office of Nuclear Reactor Regulation, Director 83/09/30 85p
 Aveilable at NRC \$5.00 20674 126 24% Fiche 50-289,83/09/30,8310070437
- Q31QQ70439 NUREO-1011
 (TIMAL ENVIRONMENTAL STATEMENT RELATED TO BTEAM GENERATOR REPAIR AT THE POINT BEACH NUCLEAR PLANT, UNIT I Docket No 30-266 (Wisconsin Electric Power Company)
 COLBURN, T @ Division of Liconsing 83/09/30 60pp Available at NRC \$4.50 20672 299 24% Fichs 50-266,83/09/30,8310070439
- B310070441 NUREQ-1020 VO2

 GPU V. B&W LAMBUIT REVIEW AND ITS EFFECT ON TMI-1 General
 Public Utilities Corporation et al V The Babcock & Wilcox
 Company, et al Three Mile Island Nuclear Station Unit 1

 Docket No 50-287

 **Office of Nuclear Reactor Regulation, Director 83/07/30 832pp

 20477 CO1 24X Fiche 50-287,83/07/30,8310070441
- 8310070442 NUREG/CR-2850 VOR
 POPULATION DOSE COMMITMENTS DUE TO RADIOACTIVE RELEASES
 FROM NUCLEAR POWER PLANT SITES IN 1780
 RAKERLD A PELOGUIN.R A Battelle Memorial Institute, Pacific
 Northwest Laboratory FIN 8-7243 PNL-4221 83/08/31 Division
 of Data Automation & Management Information 122pp Available at
 NRC \$4 50 20474 001
- B310110001 FOIA request for listed documents to be placed in PDR. Documents requested are references from NUREO-0800, Pages 3.5 I 6-7 PEDROJ NUB Corp. CD-18-83-047. B3/06/17 Division of Rules and Records 1p 20704 136
- B310110023 NUREO/CR-2000 VO2 NB LICENBEE EVENT REPORT (LER) COMPILATION For Month Of August 1983 8 Oak Ridge National Laboratory FIN A-9135 DRNL/NBIC-200 B3/09/30 Director's Office 154pp 20703 128.

- BGIO110032 NUREG/CR-3345
 AN ASSESSMENT OF POTENTIAL INCREASES IN RIBH DUE TO
 DEGRADATION OF STEAM GENERATOR AND REACTOR COOLANT PUMP
 SUPPORTS Seismic Safety Margins Research Program
 BOHNIM P. WELLS, J E. SMIEHLL C. Lawrence Livermore Laboratory
 FIN A-0439 UCID-19719 B3/08/31 Division of Bafety Technology
 103pp Available at NRC \$4.75 20703 018
- 8310110034 Further response to FOIA request for records re NUREO-086; investigative rept & investigations concerning facilities forwards App A documents Commissioner Bradford 811217 memo withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 83/06/15 REYNOLDS, J Center for Law in the Public Interest 4pp 20713 001
- ~-0310110039 Forwards draft ltrs to Subcommittee on Energy & Enviror Subcommittee on Energy Conservation & Power transmitting NRC review of NUREO-0082 Comments requested by 820811 KAMMERER. C Office of Congressional Affairs 82/08/09 BICKWIT.L Office of the General Counsel 5pp 20713-008
- --8310110057 Braft ltrs re adequacy of NRC investigation into de of RL Cloud Assoc rept.per NUREO-0862. "Insp Rept of Preliminary Rept Seismic Reverification Program at Biablo Canyon Nuclear Power Plant " PALLADING.N Commissioners 83/06/15 UDALL.M K House of a Interior & Insular Affairs 7pp 20713 024
- --B310i10095 Forwards RL Cloud B20824 request for final statement on conclusions of Cloud/util investigation to clear Cloud prof reputation Matter presented in NURRO-0862 & SECY-82-89. Commission guidance requested DIRCKS-W J Office of the Elecutive Director for Operations 83/09/08 PALLADING.N Commissioners ip 20713 031.
- ---B310110103 Informs of delay in review of investigation reported in NUMEO-0862 Completion of rept review expected by 820802 CUMHINGS.J.J. Diffice of Inspector & Auditor B2/07/15. PALLADING.N. Commissioners 1p 20713-035
- 8310110056 Requests release of full unexpurgated version of recently completed NUREO-1020. "OPU vs 8&M Lawsuit Review & Effect on TMI-1"
 DIECKAMP.H General Public Utilities GPU Bervice Corp 83/10/04 PALLADINO.N . ASSELSTINE. J K . BERNTHAL.F Commissioners. 3pp 20665 003 24x Fiche 50-289,83/10/04.8310110056
- 8310110112 Forwards Phase I response for Criteria 1.2d, 3.6.11s & 11b of NUREO-0737.1tem II B 3 re post-implementation review of util post-accident sampling sys Remaining responses will be submitted in 6 months
 BAYNE,J P Fourr Authority of the State of New York JPN-83-85
 B3/10/05 VABSALLO,D D Operating Reactors Branch 2 IBpp 20647 278 24x Fishe 50-333,83/10/05.8310110112
- 8310110169 NUREC-0730 V17 NO3 NUCLEAR REQULATORY COMMISSION ISSUANCES March 1983 Pp 331-324 s Division of Technical Information & Document Control 83/03/31 200pp 21021 167
- 8310110171 NUREO/CP-0047
 TRANSACTIONS OF THE ELEVENTH MATER REACTOR BAFETY RESEARCH
 INFORMATION MEETING To Be Held At National Dureau of
 Standards, Oaithersburg, Maryland, October 24-28, 1983.
 * Diffice of Nuclear Regulatory Research, Director 83/09/30 37pp
 Available at NRC \$8 00 20702 00;
- B310110174 NUREO/CR-2631
 A LODICAL FRANCHORK FOR IDENTIFYING EQUIPMENT IMPORTANT TO SAPETY IN NUCLEAR POWER PLANTS
 OALLUP, D.R., VANNONI, H.O. Bandia Laboratories FIN A-1353
 BANDB2-2726 B3/09/30 Division of GA. Bafeguards & Inspection Programs (Post B30103) 32pp 20709 297
- 8310110204 Forwards safety evaluation re thermal-hydraulic analysis of 820125 steam generator tube rupture incident ltem 7 resolved Reviews of Items 1,3,4,5 & 17 complete Remaining items atil) under review CRUTCHFIELD, D Operating Reactors Branch 5 L805-83-10-008 83/10/05 MAIER, J E Rochester Gas & Electric Corp 2pp 20665 308 24X Fichs 50-244.83/10/05.8310110204
- --8310110R06 Bafety evaluation supporting licenses evaluation of 830125 steam generator tube rupture incidentiper NUREQ-0716 will defect of Nuclear Reactor Regulation, Director 83/10/03, dep 20665 310 24% Fichs 50-244,83/10/05,8310110204

- 8310110217 Forwards status of NUREO-0822 issues requiring refined engineering analysis or continuation of ongoing evaluation, per 830810 request Add1 submittal dates inadvertently omitted by NRC indicated by asterisks
 FIEDLER.P B General Public Utilities OPU Service Corp 83/10/04
 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 20665 056 24X
 Fiche 50-219.83/10/04.8310110217
- B310110222 Forwards application for amend to License DPR-64, changing radiological ETS Sections 6 5.6 8.6 9 & 6 10 to reflect draft flev 3 to NURGO-0472, in response to NRC 820907 ltr BAYNE, J P Power Authority of the State of New York IPN-83-84 83/09/30 VARGA, S A Operating Reactors Branch 1 2pp 20669 138 24X Fiche 50-286,83/09/30,8310110222
- --B310110228 Application for amend to License DPR-64.changing radiological ETS Sections 6 5.6 8.6 9 & 6 10 to reflect draft Rev 3 to NUREG-0472.in response to NRC 820907 itr BAYNEJ P. Power Authority of the State of New York B3/09/30 9pp 20669.140 24X Fiche 50-286.83/09/30.8310110222
- --8310110231 Proposed Tech Spec changes revising Sections & 5.6 8, 6.9 & 6.10 to reflect draft Rev 3 to NUREG-0472 * Power Authority of the State of New York 83/09/30 96pp 20669 149 24X Fiche 50-286,83/09/30.8310110222
- 8310110276 Forwards four oversize drawings, closing out NUREG-0892, SER Outstanding Issue 29 re vacuum breaker valves Valve response meets containment design bases for response time & flow capacity Aperture cards are available in PDR SDREMSEN, 0 C Washington Public Power Supply System 002-83-872 83/09/28 SCHMENCER, A Licensing Branch 2 2pp 20665 325 24X Fichs 50-397,83/09/28,8310110276
- B3i0110332 Forwards draft Tech Specs to require use of shorting links during initial source range monitors/intermediate range monitors overlap demonstration or post-mod.ger NUNEO-0123
 SOREMBEN.9 C Washington Public Power Bupply System G02-83-880
 B3/10/03 SCHHENCER.A Licensing Branch 2 7pp 20666 068 24 Fiche.50-397.83/10/03.8310110332
- 8310110341 Respands to approval request for info collection re DDE/NRC Forms 741 & 741A for nuclear matl transaction rept & NUREO/BR-0006, Request approved through 860630 under CMB Number 3150-0003 per Paperwork Reduction Act SCURRY.N Office of Management & Budget OMB 3150-0003 83/10/03 SCOTT.S Document Management Branch 2pp 20713 197
- BIO110345 NUREQ-1018
 BEISMIC QUALIFICATION OF EQUIPMENT IN OPERATING PLANTS
 Status Report, Unresolved Safety Issue A-46
 CHANG, TY Division of Safety Technology 83/09/30 87pp
 Aveilable at NRC 44 50 20714 074
- 3101(0347 MUREQ/CR-3259
 LEAM DETECTION SYSTEMS FOR URANIUM HILL TAILINGS
 IMPOUNDMENTS WITH SYNTHETIC LINERS
 WYERS D A , TYLER, S W , MITCHELL, D H Battelle Memorial Institute,
 Pacific Northwest Laboratory FIN 8-2476 PNL-4694 89/09/30
 Division of Waste Management 53pp Available at NRC 84 00
 20714 023
- 310110411 Forwards request for add1 info re NUREG-0737 items & safety-related structures, sys & components controlled by GA program (FSAR Table 3 2-1) Responses should be submitted as changes to FSAR by 831027 SCHMENCER, A Licensing Branch 2 83/09/27 RHODE, 0 K Niagara Mohawk Power Corp 7pp 20713 344 24% Ficha 50-410, 83/09/27, 8310110411
- 10110442 Informs that commitment to add high radiation signal for purge to vent valve isolation meets requirements of MVREO-0737. Item II. E 4.2 7. "Primary Containment High Radiation to Close Vent & Purge Valves"

 BTOLZ, J F Operating Reactors Branch 4 83/09/29 HECKMAN, J T Peongia Power Co 2pp 20706 319, 24X Fiche 50-321, 83/09/29, 8310110442.
- [0110446 Forwards FES (NUREQ-1011) re repair of steam generators & notice of evailability M/o encl filler, J R Operating Reactors Brench 3 83/09/30 PERRIN, S Invironmental Protection Agency 2pp 20704 351 24X Tiche 50-266,83/09/30,8310110446
- Olio454 Forwards safety evaluation & Franklin Research Ctr technical valuation rept re NUREO-0612, "Control of Heavy Loads Phase I)." Phase I acceptable Reed for single failure-proof andling equipment will be addressed in Phase II. TOLZ, J F. Operating Reactors Branch 4 83/09/21 BAUER, E 0 hiladelphis Electric Co. 3pp. 20712 076 24X iche: 50-277, 83/09/21, 8310110454

- --8310110459 Safety evaluation re util 810618,1222.820520,1025 & 830810 responses to NUREG-0612, "Control of Heavy Loads (Phase I) "
 Phase I acceptable
 * NRC No Detailed Affiliation Given 83/09/09 2pp 20712 079 24X Fiche 50-277.83/09/21,8310110454
- --8307020392 TER-C550A-379/380

 "Control of Heavy Loads (C-10), Philadelphia Electric Co, Peach Bottom Atomic Power Station, Units 2 & 3, " technical evaluation rept SARGENT, I H , DOMBERGER, C Franklin Institute/Franklin Research Center TAC 08070 83/08/31 SINGH, A NRC No Detailed Affiliation Given 32pp 20712 081 24x Fiche 50-277, 83/09/21, 8310110454
- 8.310110497 Notice of availability of FES (NUREG-1011) re steam generator repair MILLER.J F Derating Reactors Branch 3 83/09/30 2pp 20706-317 24x Fiche 50-266,83/09/30.8310110457
- 83i01i0460 Forwards safety evaluation re util responses to NUREO-0737 Item II F 1 4, "Containment Pressure Monitor," Item II F 1 5, "Containment Hater Level Monitor" & Item II F 1 6, "Containment Hydrogon Monitor " Items resolved VAROA: S A Operating Reactors Branch i 83/09/21 0/TODLE, J D Consolidated Edison Co of New York, Inc 10pp 20707 353 24X Fiche 50-247.83/09/21.83i01i0460
- 8310110466 Forwards safety evaluation re util responses to NUREG-0737. Item JI K 3 1. "Automatic PORV Isolation," Item II K 3 2. "Rept on PORVs" & GE Qumers Group generic rept Review complete Responses acceptable MILLER.J R Operating Reactors Branch 3 83/09/23 CQUNBIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 14pp 20712 114 24x Fiche 50~336.83/09/23.8310110466
- ---8307200260 TER-C3506-409
 "Operating Reactor PORV Repts (F-37), TM1 Action Plan
 Requirements, C-E Duners Group (CEN-145), "technical
 evaluation rept
 OVERBECK, G. J., JENKINS, S. M., DELGAIZO, T. J. Franklin
 Institute/Franklin Research Center NRC-03-81-130 83/07/18
 CHOM, E. NRC No. Detailed Affiliation Given 52pp 20712 128
 24X Fiche 50-336, 83/09/23, 8310110466
- 8310110471 Forwards safety evaluation of util responses to NUREO-0737.

 Them II E I I. "Auxiliary Feedwater Sys " Item I re
 protection from internal missiles unacceptable Requests
 commitment to NRC position within 30 days
 STOLZ, J F Operating Reactors Branch 4 DMB 016 83/09/26
 RODRIGUEZ, R J Bacramento Municipal Utility District 46pp
 20711 320 R4X Fiche 50-312,83/09/26,8310110471
- B310110472 Forwards Franklin Research Ctr "Operating Reactor FDRV Repts (F-37)TMI Action Plan Requirements Generic Rept-B&W Designed Units," technical evaluation rept & NRR safety evaluation accepting B&W response to TMI Item 11 N 3 2 STOLIJF Operating Reactors Branch 4 83/09/26 GRIFFIN.J M Arkansas Power & Light Co 3pp 20712 004 24X Fiche 50-313.83/09/26,8310110472
- --B308310422 Forwards safety evaluation accepting B&W licensee contention that requirements of NUREG-0737. Item II K 3 2 met w/existing PORV, safety valve & high pressure reactor trip sotpoints ROWSOME.F H Assistant Director for Technology Review B3/08/24 LAINAS-0 C Assistant Director for Operating Reactors 14pp 20712 007 24X Fiche 50-313,83/09/26,8310110472
- --B307280463 TER-C5506-410
 "Operating Reactor PORV Repts (F-37) TMI Action Plan
 Requirements Generic Rept B&W Designed Units." technical
 evaluation rept
 DVERBECK, G. J., DELGAIZO, T. J. Franklin Institute/Franklin Research
 Center NRC-03-81-130. 83/07/20 CHOW, E. NRC No Detailed
 APFIliation Given 58pp 20712 019, 24X Fiche 50-313, 83/09/26,
 83/01/0472
- B310110476 Forwards safety evaluation supporting installation of RCS high point vents per NUREG-0737. Item II B i BTOLZ, J F Operating Reactors Branch 4 B3/09/27 RODRIGUEZ, R J Bacramento Municipal Utility District 9pp 20712 265 24X Fichs 50-312, 83/09/27, 8310110476
- --B30A0B0055 TF-3A7/0B17A

 "Belected Operating Reactor Issues Program II RCB Vents
 (NUREG-0737, Item II B 1)," final technical evaulation
 rept for Rancho Seco i.

 HELD. J Energy Incorporated FIN A-0250 TAC 44402 83/03/14

 ABERTHAL.O NRC -- NO Detailed Affiliation Given 5pp
 20712 274 24X Fichs 50-312,83/09/27,8310110476

- B310110083 Forwards safety evaluation re NUREG-0737.1tem II B 3, "Post-Accident Sampling Sys (PASS)" Core damage estimate procedure including companison of PASS data w/other plant parameters, should be provided Item complete MILLER, J. R. Operating Reactors Branch 3 B3/09/28 UMRIG.R E Florida Power & Light Co. 13pp. 20714 328 24X Picha 50-335,83/09/28,83/0110483
- E310110532 NURFG-0383 VO2 RO6
 DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIDACTIVE
 MATERIALS PACKAGES Certificates Of Compliance
 # Division of Fuel Cycle & Material Safety 83/07/30 618pp
 Available at NRC 411 00 20710 001
- 8310110543 Forwards SER re util 791231.810621 & 820402 responses to NUREG-0737. Item II B i, "RCS Vents" % "Selected Operating Reactor Issues Program II RCS Vents (NUREG-0737. Item II B i)," final technical evaluation rept MILLER, J R Operating Reactors Branch 3 83/09/20 COUNSIL,W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) Ilp; 20712 180 24X Fiche 50-336,83/09/20,8310110543
- --B3060B0045 TF-349/0812A

 "Selected Operating Reactor Issues Program II RCS Vents
 (NUREG-0737, Item II B 1)." final technical evaluation rept
 HLD, J T Energy Incorporated * Lawrence Livermore Laboratory
 FIN A-0250 TAC 44385 83/03/02 ALBERTHAL. 9 NRC No Detailed
 Affiliation Given App 20712 191 24% Fichs 50-316.83/09/20,
 8310110543
- 8310110580 NUREG/CR-3048
 CLOBEDYT OF TE DULLETIN 80-21 VALVE PARTS BUPPLIED BY
 MALCOLM FOUNDRY
 FOLEY,H J , HENNICK, A Parameter, Inc FIN 0-1013 PARAMETER
 IE-12 83/09/30 Division of Emergency Preparedness & Engineering
 Response (Post 830103) 33pp Available at NRC \$3 75 20714 281
- 0310110593 NUREG-0383 VO3 RO3
 DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIDACTIVE
 HATERIALS PACKAGES Summary Report Of NRC Approved Quality
 Assurance Programs For Radioactive Material Packages
 # Division of Fuel Cycle & Material Safety 83/07/70 42pp
 Available at NRC 45 90 20713 001
- B310110630 Forwards comments on MUREG-1020 re GPU vs B&N lawsuit review & effects on TMI-1 Errors in App B should be corrected to reflect findings concerning relevance & materiality of lawsuit documents
 MATTSON, R J Division of Systems Integration (post 8)1005)
 B3/09/22 FISENHUT, D G Division of Licensing 3pp 20714 278
 24X Fichs 50-209,83/09/22,β310110630
- G310J20051 Advises that comments re NUREQ-1020 "GPU vs G&W Lawsuit Review & Effect on YMI-1." were fased to R Capra on S30920.

 JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post B30103) G3/09/27 EISEMHUT.D G Division of Licensing 1p 20715 327 24X Fiche 50-289, G3/09/27, B31012005;
- @310120034 Concurs in draft NUREQ-1020 "OPU vs B&W Lawsuit Review & Effect on TMI-1"
 VOLLHER:R H Division of Engineering 83/09/26 RUSSELL.W T. NRC
 No Ostalled Affiliation Given ip 20749 355 24X
 Fiche 30-289,83/09/26,8310120054
- B310120097 Forwards IE/Region I comments to Buby Area 5 of NUREG-1020 "GPU vs B&W Lawsuit Review & Effect on TMI-1," constituting concurrence w/NUREG TAYLOK, J M Division of GA, Safeguards & Inspection Programs (Post 8301031 B3/09/23 EISENHUT, D G Division of Licensing IP 20749 354 24X Fiche 50-289,83/09/23,8310120057
- 8360120059 Forwards marked-up Tech Spec re ECCS in response to 830923 request for proposed change to surveillance requirements on automatic depressurization sys backup air supply, per SER, NUREO-0892 & Itam II K 3 20 SOREMSEN, G C Washington Public Power Supply System GCR-83-891 89/10/04 SCHMENCER, A Licensing Branch 2 2pp 20697-101 24X Fichg 50-397,83/10/06,8310120059
- BD10120060 Forwards NUREO-1020 "GPU vs B&M Lawsuit & Effect on TMI-1"
 Distribution of Category 10 section "Mqt Competence/
 Integrity" should be limited pending Ofc of Investigations
 completion of investigation
 DIRCKB.H J Office of the Executive Director for Operations
 B3/09/28 PALLADING.N J Commissioners 2p 20715 362 24X
 Fiche 50-289.83/09/28.8310120060

- 8310120072 Discusses actions to be taken to resolve turbine missile issue identified in SSER 4.Section 1.9.including development of turbine & valve maint programs described in NUREG-0800 for main turbine throttle & governing valves DRUMMOND.F. J. Lauisiana Power & Light Co. #3583-0328 83/10/05 MRIGHTON.O W. Liensing Branch 3. 2pp. 20897 161 24X Fiche 50-382,83/10/05,8310120072
- B310120090 Forwards IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncampliance noted STAROSTECKI:R Division of Project & Resident Programs B3/09/20 RH00E, 9 K Niagara Mohawk Power Corp 2pp 20697 128 24X Fichs 50-220
- --8310120096 IE Insp Rept 50-220/83-20 on 830721 & 25-0826 No noncompliance meted Major areas inspected licensee action on previous insp findings, operational safety verification, physical security surveillance testing & safety sys HUBSON.6 D. MCDRCARTY.R A Region 1. Defice of Director LAZARUS, W. J. Division of Project & Resident Programs 83/09/16
- 8310120191 Forwards info re NUREG-0737. Item II F 2, "Instrumentation for Detection of Inadequate Core Cooling." in response to 830906 request Addl info will be submitted by 840215 SIMPSON. E C Florida Power Core 3F-1083-09 83/10/07 STOLZ. J F Operating Reactors Branch 4 6pp 20695 320 24X Fiche 50-302.83/10/07.8310120191
- 83(0120194 Forwards addl info on NUREQ-0737. Item II K 3 17, "Rept on Dutages of ECCS", per 830829 telcon & NRC 830819 ltr Addl data factored into probabilistic safety study submitted an 820305 0'TDCLE, J D Consolidated Edison Co of New York, Inc 83/09/30 YAROA'S A Operating Reactors Branch 1 5pp 20696 098 24X Fiche 50-247.83/09/30.8310120194
- 9310120198 Forwards IE Insp Rept 50-286/B3-t6 on 930816-0915 No noncompliance noted STARDSTECKI, R Division of Project & Resident Programs B3/09/20 B#ONS.J C Power Authority of the State of New York 2pp 20695 335 24x Fiche 50-286.83/09/20.8310120198
- --B310120199 IE Insp Rept 50-286/83-16 on 830816-0915 No nancompliance noted Major areas inspected maint review of monthly operating rept TMI task action plan status licensee actions on previous insp findings plant tour & surveillance KENNY.T J. ROSSBACH.L W. NORRHOLM.L. Region 1. Office of Director 83/09/19 12pp 20695 337 24X Fiche 50-286.83/09/20.8310120198
- 8310120219 Responds to unresolved (seves contained in draft SER, NUREO-1002 dtd 830715 Some items re NRC site audits unresolved SHARTZ,E D Commonwealth Edison Co 7329N B3/09/30 DENTON,H R Defice of Nuclear Reactor Regulation, Director 44pp 20492 179 24X Fiche 50-456.83/09/30,8310120219
- B310120252 Forwards response to Phase I of NUREQ-0612. "Control of Heavy Loads at Nuclear Power Plants." per BJ Youngblood B30811 request for addl info All cranes & hoists purchased to Sargent & Lundy spec. WILLIAMS. J Cincinnati Gas & Electric Co LOZ-83-0163 83/10/06 DENTON HR Office of Nuclear Reactor Regulation. Director 4pp 20692 103 P4X Fiche 50-358.83/10/06.8310120252
- 8310120305 Discusses proposed implementation of emergency preparedness training plan First phase.per NMRS-0-0534.will be completed prior to fuel load Detailed schedules will be completed & made available for review upon concurrence SORENSEN.9 Washington Public Power Supply System GD2-B3-B86 B3/10/04 SCHMENCER.4 Licensing Branch 2 2pp 20499 277 24X Fishe 50-397.83/10/04.8310120335
- B310120349 Advises that due to uncertainty in instrumentation availability & menpower resources, instrumentation necessary to meet Reg Guide i 97 requirements will be implemented by third refuring outage per Suppl 1 to NOMEG-0737 DALG. L F Mississippi Power & Light Co QL-82-33 83/10/10 DENTON HR Qefice of Nuclear Reactor Regulation, Director 2pp. 20700 231 24X Fiche 50-416.83/10/10.8310120349
- 8310120359 Advises that util has incorporated three LRG-11 position papers into OL application Position Paper 3-CSD. "Periodic Low Pressure Leakage Testing of Drywell." constituting response to Confirmatory Issue 66 of SER (NURGO-0853) NELSON,R H 1111nois Power Co U-0071 83/09/30 SCHWENCER, A Licensing Branch 2 3pp 20700 206 24X Fiche 50-461,83/09/30,8310120359

- 8310120373 Requests 2-yr extension to implementation date in amended rule 10CFR50 44(m) requiring min number of licensed operators & senior operators on shift at all times TMI Item 1 A 13 implemented using shift technical advisor MANGAN,C V Niagara Mohawk Power Corp 83/10/06 DENTON,H R Office of Nuclear Reactor Regulation. Director 1p 20679 197 24x Fiche 50-220. 8310/10/06,8310120375
- B31013001B Forwards SORT qualification summary of equipment list update & response to ESER 3 (NUREQ-0798) open items
 TAUBER: H. Detroit Edison Co. EF2-65.621 B3/10/04
 YOUNOBLOOD: J. Licensing Branch I 68pp 20725 123 24X
 Fiche 50-341.83/10/04,8310130018
- 8310130077 Forwards request for OMB review & supporting statement re Std Form 63 & supporting statements for DOE/NRC Forms 742 & 742C NORRY,P 9 Office of Administration 83/10/03 SCURRY,N Office of Management & Budget 1p 20777 011
- B310130106 Forwards safety evaluation supporting util response to TMI Item II D I, "Safety & Relief Valve Testing " Issue resolved VASSALLO, D B. Operating Reactors Branch 2 B3/09/30, PILANT, J M Nebraska Public Power District 17pp 20777 027 24X Ficha 50-298.83/09/30.8310130106
- B310130122 Forwards for review & comment, final draft of Chapter 10 to NUREO~1020, "Mgt Competence/Integrity " Requests determination as to which portions of chapter cannot be publicly released H/o enci DENTON, H R Office of Nuclear Reactor Regulation, Director B3/09/20 HAYES, B B Office of Investigation 1p 20777 074
- B310130130 NUREQ-1022 LICENSEE EVENT REPORT BYSTEM Description Of System And Quidelines For Reporting HEBDON,F J Director's Office 83/09/30 88pp 20772 189
- B310130133 NUREQ-0070 VOA NO1 REPORT TO CONORESS ON ABNORMAL OCCURRENCES January-March 1983 * Director's Office 83/09/30 49pp 20772 280
- B310130149 NUREQ-0485 VOD NOB BYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As Of August 31, 1983 (Buff Book) * Office of Resource Management, Director \$3/09/30 74pp 20773 109
- G310130151 NUREQ-0363 VOI ROA DIRECTORY OF CERTIFICATES OF COMPLIANCE FOR RADIOACTIVE MATERIALS PACKAGES Summary Report Of NRC Approved Packages • Division of Fuel Cycle & Material Safety G3/09/30 432p 20773 186
- 3310130217 Forwards Amends 75 & 36 to Licenses DPR-38 & DPR-74, respectively Amends change Tech Spec to require redundant containment hydrogen analyzers to satisfy requirements of NURED-0737. THI Action Item II F I 6 VARQA, S A Operating Reactors Branch I B3/09/30 DDLAN, J Indians & Michigan Electric Co. DBLAN, J American Electric Fower Bervice Corp Spp 20777 180 24X Fiche, 50-315, 63/09/30, 8310130217
- ~-8310130222 Amends 75 & 56 to Licenses DPR-58 & DPR-74, respectively.
 changing Tech Spac to require redundant containment hydrogen
 analyzers to satisfy requirements of NUREG-0737, TMI Action
 Item II F 1 6
 VARQA, 8 A Operating Reactors Branch 1 DPR-74 A 056 B3/09/30
 9pp 20777 183 24X Fiche 50-315, 83/09/30, 8310130217
- 8310130276 Forwards evaluation of util 830831 plant design submittal in response to integrated plant SAR (NUREO-0827) Section 4 24 1.App K, "Electrical Instrumentation & Control Reviews for LACBUR" Issue resolved CRUTCHFIELD. D Operating Reactors Branch 5 LSO5-83-10-016 82/10/07 LINDER.F Dairyland Power Cooperative 7pp 20723 198 24X Fiche 50-409.83/10/07.8310130276
- 8310130326 Forwards list of long-term actions that should be addressed in SER input Only noncertification items to be addressed in review.

 EISENHUT, D. 0. Division of Licensing 83/08/12 MATTBON: R J Division of Systems Integration (post 811005). THOMPSON: H L Division of Human Factors Safety JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 5pp 20754 332 24X Fiche, 50-289, 83/08/12, 8310130326

- B3101303B2 Forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37). Thi Action Plan Requirements, Generic Rept B&M Designed Units." technical evaluation rept & NRR safety evaluation accepting B&M response to TMI Item II K 3 2 BTGLZ.J F Operating Reactors Branch 4 B3/09/23 CRQUSE.R P Toledo Edison Co 3pp 20770 120 24X Fiche 50-346.B3/09/23, B310130382
- 8310130373 Summary of 830908 meeting w/utils soliciting feedback on proposed NRC human factors review of safety parameter display sys Encl marked-up NURE0-0835 revised to resolve 830908 comments
 BELTRACCHI.L Human Factors Engineering Branch 83/09/16
 MODRE,V A Human Factors Engineering Branch 72pp 20769 27;
- B310130421 Forwards safety evaluation & technical evaluation rept re NUREG-0737.7MI Items II K 3 1. "Automatic PDRV Isolation" & II K 3 2. "Rept on PORVs " Requirements met BTDL7.JF Operating Reactors Branch 4 B3/09/30 WILQUS.W S Florida Power Corp 3pp 20769 167 24X Fiche 50-302.83/09/30, B310130421
- B310140196 Forwards Rev O to "Plant-Unique Analysis Rept of Torus Suppression Chamber," Merk I containment program technical rept.per acceptance criteria in App A to NUREG-0661
 BAYNE, J P Power Authority of the State of New York JPN-83-88
 B3/10/11 VASSALLD.D B Denating Reactors Branch 2 ip
 20762 084 24X Fiche 50-333.83/10/11.8310140196
- --B310140202 TR-53Ri-1 R00
 Rev O to "Plant-Unique Analysis Rept of Torus Suppression Chamber." Mark I containment program technical rept for James A Fitzpatrick Nuclear Power Plant Teledyne Engineering Services 83/08/11 144pp 20742 086 24X Fiche 50-333,83/10/11,8310140196
- 8310140221 Responds to 830823 request for position re NUREG-0737, Item II E 4,2(7), "Containment Isolation on High Radiation" Completion of evaluation anticipated by 831201 MANGAN, C V Niagara Mohawk Power Corp 89/10/12 VASSALLO, D B Operating Reactors Branch 2 ip 20761 182 24X Fiche 50-220,83/10/12,8310140221
- B310140R23 Advises that in initial evaluation of SEP Topic VI-4, "Containment Isolation Sys (Electrical)" penetrations erroneously evaluated against GDC 55 instead of GDC 57 Addl mods to plant configuration unnecessary KRIEGER:R W Southern California Edison Co 83/09/30 CRUTCHFIELD, D Operating Reactors Branch \$ 2pp 20761 179 24X Fiche 50-206.83/09/30.8310140R23
- 8310140254 Forwards fourth semiannual "Rept on Environ Gualification Program for Duane Arnold Energy Ctr" covering safety-related electrical equipment MCGAUGHY.R H Iowa Electric Light & Power Ca NO-83-3368 83/09/30 DENTON.H Office of Nuclear Reactor Regulation, Director 2pp 20759 300 24X Fiche 50-331,83/09/30,8316140254
- --8310140258 "Rept on Environ Qualification Program for Duane Arnold Energy Ctr," fourth semiannual rept * Bechtel Corp LEB-79-018 83/09/22 420pp 20759 302 24x Fiche 50-331,83/09/30,8310140254
- 8310140278 Forwards draft response to 830915 Request for Add1 Info RAI 271 2 re qualification of automatic depressurization sys accumulators per TMI Item II K 3 28 Response will be incorporated in Nov 1983 FSAR rev BRADLEY.E J Philadelphia Electric Co GOVT I-1(NRC) 83/10/05 SCHMENCER:A Licensing Branch 2 9pp 20761 186 24X Fiche 50-352.83/10/05.8310140278
- 83:0170001 Forwards 830708 memo requesting support for NRC rept on OPU vs B&W lawsuit review Arrangements should be made to accommodate requested schedule
 STERLE, M L Division of Technical Information & Document Control
 83/09/09 MCVEAGH. H D Division of Technical Information & Document
 Control JOHANBEN, J Cress Branch ip 20814 048 244
 Fiche 50-289, 83/09/09, 8310170001
- --8310:70002 Requests assistance in arranging resources for production & publication of NRC evaluation of OPU vs B&W lawsuit review & impact on restart of TMI-1 (NUREO-1020) Flow chart w/projected milestones encl RUSSELL, W T OPU/B&W Lawsuit Review Team 83/09/08 BESAW, W J Division of Technical Information & Document Control 3pp 20814 049 24% Fiche 50-289,83/09/09,8310170001
- B310170009 Porwards Suppl 4 to NUREG-0420, "SER re Operation of Bhoreham Nuclear Power Station,Unit i " BCHWENCER:A Licensing Branch 2 83/09/30 POLLOCK,M S. Long Island Lighting Co 3pp 20814.067 24X Fiche 50-322,83/09/30,

- 8310170014 Forwards revised listing of subj area contents for GPU vs P&W lawsuit review, per 830727 ½ 0805 % 12 ltrs RUBSELL, W Y CPU/9½W Lawsuit Review Team 63/06/18 MORISSEAU, D . PICKETT, D . HAASS. W NRC - No Detailed Affiliation Given 14pp 20813 285 24% Fiche 50-289, 83/08/18, 8310170014
- 8310170018 Forwards draft NUREG-1020, "GPU vs B&W Lawsuit Review & Effect on [MI-1" Draft does not include Chapter 10 re mgt competence/integrity Comments or concurrence requested W/n encl RUSSELL.W Y GPU/BYW Lawsuit Review Team 83/09/19 EISENHUT, D Q Division of Licensing MATTSON, R J Division of Systems Integration (post 811005) THO!!PSON, H L Division of Human Factors Safety 2pp 20798 358 24% Fiche 50-289, 83/09/19, 8310170018
- 8310170025 Forwards final draft Chapter 10 to NUREG-1020 entitled
 "Mgt Competence/Integrity" Changes, comments or concurrence
 requested by 830922 W/o encl
 EISENHUT.D g Division of Licensing 83/09/20 MATTSON, R J
 Division of Systems Integration (post 811005) THOMPSON, H L
 Division of Human Factors Safety TAYLOR, J M Division of GA.
 Safeguards & Inspection Programs (Post 830103) 2pp 20798 353
 24x Fiche 50-289,83/09/20,8310170025
- 8310170032 Requests assistance in arranging resources for production & publication of NRC evaluation of OPU vs B&W lawsuit review & impact on TMI-1 restant (NUREG-1020)
 RUSSELL.W T @PU/B&W Lawsuit Review Team 83/07/08 BESAW.W J Division of Technical Information & Document Control 3pp 20798 334 24% Fiche 50-289.83/07/08.8310170032
- B310170039 Forwards SER & technical evaluation rept re licensee responses to NUREG-0737. Items II K 3 1, "Automatic PDRV Isolation" & II K 3 2, "Rept on PDRVs" VAROA.5 A Operating Reactors Branch 1 83/10/05 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 20812 162 24X Fiche 50-272.83/10/05,8310170039
- B310170063 Advises of disapproval of exception to habitability requirements for emergency operation facility (EGF), per 820303 ltr Plans for establishing EGF per Suppl 1 to NUREG-0737 (Generic Ltr 82-33) requested by B31128 EISENHUT.D G Division of Liconsing GL-82-33 83/09/29 WITHERS.B D Portland General Electric Co 5pp 20798 035 24X Fiche 50-344.83/09/29,8310170063
- 8310170088 forwards Franklin Research Ctr "Operating Reactor PORV Repts (F-37) TMI Action Plan Requirements.C-E Cumers Group (CEN-145)." technical evaluation rept & safety evaluation supporting responses to TMI Items II K 3 1 & II K 3 2 MILLER.J R Operating Reactors Branch 3 83/10/06 UHRIG.R E Florida Power & Light Co 3pp 20813 135 24% Fiche 50-335.83/10/06.8310170088
- ---B310170092 Safety evaluation supporting C-E licenses responses to NUREC-0737. Item II K 3 2, "Rept on PORVs " * NRC No Detailed Affiliation Given 83/10/06 62pp 20813 138 24% Fiche 50-335.83/10/06.8310170088
- B310170159 Forwards clarification of evaluation of pipe whip, jet impingement & breaks within pipe tunnel (SEP Topic III 5 B), per B30720 request transmitting integrated plant safety assessment program (NURE9-0827)
 LINDER: F Dairyland Power Cooperative LAC-9351 83/10/06
 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 20788 347 24X
 Fiche 50-409.83/10/06.8310170159
- ## B310170204 Forwards SSER 2 (NUREG-0852) re CESSAR & application for final design approval W/o encl THOMAS. C Standardization & Special Projects Branch 83/09/30 SCHERER, A E Combustion Engineering. Inc. 2pp. 20798 092 24X Fiche 50-470,83/09/30.8310170204
- 8310170235 Forwards response to telcon request for addit clarification of response to Question 640 Oi a & b re emergency operating procedures generation package SER (NUREQ-0892) Confirmatory Issue 15 re emergency procedures review closed SOMENSEN, C Washington Public Power Supply Gystem 902-83-908 89/10/11 SCHWENCER, A Licensing Branch 2 89pp 20787 013 24; Fiche 50-397, 83/10/11,8310170235
- B31017029B Forwards loose parts detection sys conformance evaluation, including action requested in NUREO-0892, SER Section 4 4 6 BORENSEN.O C Washington Public Power Supply Bystem GDZ-83-860 83/09/29 BCHMENCER.A Licensing Branch 2 8pp 20786 184 24X Fiche 50-397, 83/09/29, 8310170298
- B310170373 Forwards BCR re reactor coolant pump trip & restart criteria after 820125 tube failure incident Adequate steps taken addressing items: based on info provided in 821122 ltr & 830422 response to Generic Ltr 83-104 ltems 8 & 9 resolved CRUTCHFIELD. D Operating Reactors Branch 5 GL-83-100 83/10/14 MAIER, J E Rochester Gas & Electric Corp 2pp 20785 005 24% Fiche 50-244,83/10/14,8310170373

- --B310170378 SER supporting resolution of SER Items B & 9 re reactor coolant pump trip & restart criteria after B20125 tube failure incident # Office of Nuclear Reactor Regulation, Director # 93/10/14 5pp 20785 007 24% Fiche 50-244, B3/10/14, B310170373
- B310170394 Forwards draft App D to radiological emergency response plans for Towns of Newfields New Castle.North Hampton & Brentwood, NH. entitled "Cross-Reference to NUREG-0654" LESSY, R P Hearing Dranch 3 ISSUANCES DL B3/10/12 H0YT, H Atomic Safety and Licensing Board Panel 26pp 20785 045 24X Fiche 50-443-83/10/12.B310170394
- 8310170495 Request that NUREC-0123. "Std BMR Tech Specs," he revised to provide adequate time frame for completion of MPPSS-2 power ascension testing program Susquehanna test duration data encl SOREMSEN. G C Washington Public Power Supply System GO2-83-900 BJ/10/10 SCHMENCER A Licensing Branch 2 3pp 20784 015 24X Fiche 50-000.83/10/10.8310170495
- 8310170545 Provides add1 info re NUREG-0737.ltem II K 3 22.justifying use of HPCI logic for RCIC suction switchover RCIC sys not safety-related & is not intended as backup for HPCI sys RYBAX.B Communwealth Edison Co 7434N 83/10/07 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 20784 320 24X Fiche 50-254.83/10/07.8310170545
- 8310170656 Requests rev to confirmatory order contained in 830314 ltr for NUREG-0737 Items II F 1 & II F 1 2 to specify new B40101 completion date Replacement of Geiger-Mueller in detectors will be completed by B40101 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Villities B10800. B3/09/27 MILLER.J G Operating Reactors Branch 3 2pp 20782 070 24X Fiche 50-245,83/09/27,8310170456
- 8310170674 Forwards IE Insp Rept 50-312/83-16 on 830606-10.13 & 21-22 No noncompliance noted MENSIAWSKI, F A Region 5. Office of Director 83/09/16 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 20779 295 24% Fiche 50-312.83/09/16.8310170674.
- ~-8310170678 IE Insp Rept 50-312/83-16 on 830606-10,13 & 21~22 No nancompliance noted Major areas inspected environ protection, followup on ROs, info nutices, ansite events, noncompliance items & NUREG-0737, Items II B 3 & II F 1 NORTH.H S. WENBLANSKIIF A. Region 5. Office of Director 83/09/16 10pp 20779 297 24X Fiche 50-312,83/09/16.8310170674
- 831017070B Advises that requirements of NUREQ-0737. Item II K 3 2 re rept on PORVs met w/existing PORV safety valve & reactor high pressure trip setpoints Automatic PORV isolation sys (Item II K 3 1) not needed MILLER, J R Operating Reacture Branch 3 83/10/04 OARRITY, J H Maine Yankee Atomic Power Co 3pp 20813 200 24X Fiche 50-307, 83/10/04, 8310170708
- B310170715 Forwards safety evaluation of FSAR Amend 38 re NUREG-0737. Item II F 2. "Detection of Inadequate Core Cooling." Amend unacceptable Justification for proposed late implementation of in-core thermocouples requested YOUNOBLOOD. B J Licensing Branch 1 83/10/07 ORAY. R J Texas Utilities Generating Co 4pp 20798 122 24X Fiche 50-445. 83/10/07.8319170715
- B310170722 Forwards comments on util detailed control room design review submitted in response to Generic Ltr 82-33, "Suppl 1 to NUREG-0737 Requirements for Emergency Response Capability "Info mgt sys discussion needs more detail YOUNOBLOOD, B J Licensing Branch i GL-82-33 83/10/05 KDESTER, B L Kansas Gas & Electric Co 10pp 2079B 100 24X Fiche 50-000, B3/10/05, B310170722
- 8310170723 Forwards FES re steam generator repair (NUREO-1011) W/o encl MILLER, J R Operating Reactors Branch 3 83/09/30 FAY, C W Wisconsin Electric Power Co 2pp 20798 096 24X Fiche 50~266,83/09/30,8310170723
- 83i0180020 Forwards comments on 820812 detailed control room design review program plan Plan unacceptable per NUREO-0737. Suppl 1 Comments & response will be basis for telcon within 15 days of itr date MILLER, J. R. Deprating Reactors Branch 3 83/10/04 GARRITY, J. H. Maine Yankee Atomic Power Co. 10pp. 20825-055 24X Fiche 50-307,83/10/04,83i0180020
- 8310180071 NUREQ-0994
 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE UNIVERSITY OF OKLAHOMA RESEARCH REACTOR Docket No. 50-112.
 * Division of Licensing 83/09/30. 57pp 20826 174 24X Fichs 50-112. 83/09/30. 8310180071

- B310180076 NUREG/CR-2574
 BWR REFILL-REFLOOD FROGRAM TASK 4 7 MODEL DEVELOPMENT
 TRAC-BWR CCMPONENT MODELS
 CHEUNG, Y K PARAMESMARAN, V SHAUG, J C General Electric Co FIN
 B-5077 EPRI NP-2376 B3/09/30 Division of Accident Evaluation
 120pp Available at NRC \$5 00 20826 235
- 8310180079 NUREG/CR-3050
 CLOSEDUT OF IE BULLETIN 81-02 AND SUPPLEMENT Failure Of
 Outs-Type Valves To Close Against Differential Pressure
 FOLEY,W J. HENNICK,A Parameter, Inc. FIN 8-1013 PARAMETER
 IE-12 83/09/30 Division of Emergency Preparedness & Engineering
 Response (Post 830103) 51pp Available at NRC \$4 50 20826 11:
- B310180085 NUREG/CR-2573
 BWR REFILL-RELOAD PROGRAM TASK 4 7 MODEL DEVELOPMENT
 BASIC MODELS FOR THE BWR VERSION OF TRAC
 ANDERSEN, J G , CHU, K H , SHAUG, J C General Electric Co FIN
 B-5877 EPRI NP-2375 83/09/30 Division of Accident Evaluatio
 113pp 20826 001
- B3101B0072 Ack receipt of B30915 request for info concerning open issues re mgt integrity identified in B30519 to 0715 memos to Commission NRC evaluation of open issues proceeding w/ exception of GPU vs BtM lawsuit record DIRCKS, W J Office of the Executive Director for Operations. B3/10/07 DIECKAMP,H General Public Utilities GPU Service Corp ip 20824 125 24X Fiche 50-287, B3/10/07, B3101B0092
- --B3101B0099 Requests NRC provide identification & evaluation of specific concerns remaining or developed as result of evaluation of open issues Also requests all related recent insp repts & basis for concern in other areas
 DIECKAMP.H General Public Utilities GPU Service Corp
 B3/09/15 DIRCKS.H J Defice of the Executive Director for Operations 4pp 20824 128 24X Fiche 50-289,83/10/07,8310180092
- 8310180098 Forwards "Summary Rept & Program Plan for Control Room Besign Review," per 830707 itr re NUREO-0737.Item I D 1 activities MANGAN.C V Niagara Mohawk Power Corp 83/09/30 VASSALLO.D B Operating Reactors Branch 2 ip 20807.184 24X Fiche 50-220.83/09/30.8310180098
- --B310180102 "Summary Rept & Program Plan for Control Room Design Review" * Niagara Mohawk Power Corp 83/09/30 23pp 20807 185 24X Fiche 50-220,83/09/30,8310180098
- B31018011B NUREO/CR-3223
 BMR REFILL REFLOOD PROGRAM FINAL REPORT
 MYERS,L L General Electric Co # Electric Power Research
 Institute FIN B-8877 EPRI NP-3093 83/09/30 Division of
 Accident Evaluation 142pg Available at NRC \$5
- B310180131 Advises that continued operation until completion of mods or NUREO-0737. Item II E 4 2 concerning gang opening of two sys. Justified Licensee committed to modifying logic at first refueling outage SCHMENCER. A Licensing Branch 2 B3/09/29 CURTIS, N W Pannsylvania Power & Light Co 3pp 20827 077 24X Fiche 50-387.83/09/29.8310180131
- 8310180166 Forwards FSAR Section 9 1 re reactor bldg crane, revised in response to NUREO-0612 Changes will be incorporated into next FSAR amend CURTIS, N W Pennsylvania Power & Light Co PLA-1867 83/10/13 8CHWENGER.A Licensing Branch 2 RBpp 20809 001 24X Fiche-50-388,83/10/13,8310180166
- B310180169 NUREG-1016

 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE 10MA STATE UNIVERSITY Docket No. 50-116

 * Division of Licensing 83/09/30 B3pp Available at NRC 475. 20825 089 24% Fiche 50-116,83/09/30,8310180169.
- 8310180193 Forwards response to requests for add1 info re special lifting devices used for control of heavy loads (ref NUREG-0612) MAIER.J E Pacific Gas & Electric Co 83/10/12 CRUTCHFIELD.D Operating Reactors Branch 5 22pp 20809 061. 24X Fiche: 50-244.83/10/12.8310180193
- 8310180196 Informs that based on review of 830414 submittal, licensee forward command post (emergency operations facility) complies w/requirements of Table 1 to Suppl 1 of NUREQ-0737 MADSEN, 0 L Region 4, Office of Director 83/08/16 LEE, 0 R Public Service Co. of Colorado. ip 20808-341. 24X Fichs: 50-267, 83/08/16, 8310180196

- 8310180317 Forwards Rev 1 to "Emergency Procedure Generation Package. & Rev 1 to "Mriters Guide For Emergency Operating Procedures," per Generic Ltr 82-33 (NUREG-0737, Suppl 1) Listed SER items resolved MOESTER, G L Kansas Gas & Electric Co KMLNRC 83-132 83/10/14 BENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20803 101 24X Fiche 50-482,83/10/14,8310180317
- B310180344 Revises schedule for submittal of svc water sys analysis identified in Integrated Plant Safety Assessment.NURIC-0826 & associated SEP Topic IY-3 Delays due to upgrades per NURE0-0737. Item III D 3 4 Analysis expected by B31230 COUNSIL.W G Connecticut Yankee Atomic Power Co B10915 83/10/0 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 20802 358 24-Fiche 50-213,83/10/07.8310180344
- 8310180347 Comments on NUREC-1020 re GPU vs B&W lawsuit review NRC dinot make reasonable technical judgments, leaving issues that should have been resolved re mgt integrity as issues patentially involving integrity
 DIECKAMP.H General Public Utilities GPU Service Corp 83/10/14
 PALLADIND.N J , ASSELSTINE, J K , BERNTHAL, F Commissioners 35pp
 20804 301 24x Fiche 50-289, B3/10/14, B310180347
- B3101B0379 Approves request for withholding listed propiletary info reinadequate core cooling per TM1 Item 11 F 2 from public disclosure (ref 10CFR2 790)
 CRUYCHFIELD. D Operating Reactors Branch 5 LSO5-83~10-029
 83/10/11 WIESEMANN,R A Westinghouse Clectric Corp 2pp
 20824-355
- 83101803B1 Supple 830720 response to Generic Ltr-81-07. "Control of Heavy Loads." in response to NRC finding in IE Insp Rept 83-11.dtd 830620 Info documents util methodology for compliance w/NUREG-0612 & ANSI N 14 6 UHRIG.R E Florida Power & Light Co L-83-515 83/10/07 EISENHUT.D 9 Division of Licensing 2pp 20803 201 24X Fiche 50-250.83/10/07.8310180381
- 8310180385 Forwards list of new licensing actions, completed actions & action summary Buring Last Guarter FY83, considerable time spant on Rev 1 to update FSAR & preparation of confirmatory order for NUREG-0737 items in Suppl 1 MAGNER, P C Region 4, Office of Director 83/10/06 MADSEN, O L Region 4, Office of Director by 20803 207 24X Fiche 50-267,83/10/06,8310180385
- B3101B042) Informs of proposed minor changes to commitments made in response to implementation instructions of NUMEO-0578, re short-term lessons learned Duty technical advisor quarters will be incorporated in boundary control ctr
 FAY, C W Wisconsin Electric Power Ca B3/10/10 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 20803 306
 24X Fiche 50-266, 83/10/10, 8310180421
- 83101804R2 Requests relief from schedular requirements of 830325 confirmatory orders to install redundant in-containment radiation monitors, per NUREO-0737. Item II F 1 3 requirement Mod will be completed before startup in Cycle 7 KAMMER, D S Tennessee Valley Authority 83/10/12 DENTON, H R Office of Nuclear Resettor Regulation, Director 2pp 20803 308 24X Fiche 50-259.83/10/12.8310180422
- 8310180424 Responds to D Vassallo 830823 ltr re automatic closing of containment purgs & vent valves on high radiation signal (NUREG-0733, item II F 4 2(7)) Facility will be modified as result of evaluation of DWR Owners Group position HCQAUCHY, R W I Towa Electric Light & Power Co NO-83-3453 83/10/13 BENTON. H R Office of Nuclear Reactor Regulation. Director ip 20803 305 24X Fiche 50-331,83/10/13,8310180424
- B310180435 Forwards Rev O to "Detailed Control Room Design Review Program Plan, per NUREO-0737, Suppl 1 (Generic Ltr 82-33)
 HARRINOTON-W D Beston Edison Co 83-259 83/10/14 VASSALLO.D 3
 Operating Reactors Branch 4 1p 20803 358 24X
 Fiche 50-273, 83/10/14, 8310180435
- --B31018043B Rev O to Procedure 2 2 11/090983, "Detailed Control Room Design Review Program Plan " * Boston Edison Co GL-82-33 63/10/31 100pp 20803 359 24% Fiche 30-293, B3/10/14, 8310180435
- 8310180503 Clarifies util 820617 ltr describing emergency operations facility ventilation, per NUREG-0696 Charcoal will not be provided in ventilation sys SORENSEN, 0 C Washington Public Power Supply System 002-83-910 83/10/12 SCHWENCER. A Licensing Branch 2 1p. 20801 188 24X Fiche 50-397.83/10/12,8310180503

- 8310180579 Forwards safety evaluation supporting completion of generic issues re containment venting & purging (Multi-plant Action B-24) & NUREG-0737. Item II E 4 2 VARGA: 8 A Operating Reactors Branch 1 83/09/29 O'TDDLE, J D Consolidated Edison Co of New York: Inc 14pp 20824 301 24x Fiche 50-247.83/09/29,8310180579
- E310180397 F01A request for list of mods to containment undertaken by util in response to NUREG-0487 MAFNER, B Suffolk Nuclear Study Group 63/04/25 Office of Administration 1p 20827 124 24X Fiche 50-322,83/04/25, 8310180597
- 8310190042 Responds to FOIA request for into on effects of sabstage on PMRs & PMRs & fault tree analyses forwards documents NUREGYCR-3268 will be issued in 2 months Remaining requested items not found in PBR FELTON.J M Division of Rules and Records 83/07/12 SHOLLY.S C Union of Concerned Scientists 1p 20837 078
- 8310190131 Forwards comments on detailed control room design review program plan If implemented properly review will probably produce results that fulfill requirements of Suppl 1 to NUREG-0737 Response not required CRUTCHFIELD. D Operating Reactors Branch 5 CL-92-33 B3/10/17 LINDER: F Dairyland Power Cooperative 10pp 20B20 287 24X Fithe 50-409,83/10/17,8310190131
- B310190243 NUREC/CR-2669
 FRONT-END ANALYSIS FOR NUCLEAR POWER PLANT MAINTENANCE
 PERBONNEL RELIABILITY MODEL
 SIEGEL, A I , BARTIER, W D , WOLF, J J Dak Ridge National Laboratory
 FIN B-0461 ORNL/TH-8300 83/09/30 Division of Facility
 Operations 153pp 20843 263
- B310190283 NUREO/CR-2726 LIGHT WATER REACTOR HYDROGEN MANUAL CAMP: A L.; CUMMINGS.J.C.; SHERMAN.H P. Sandia Laboratories FIN A-1246 SAND82-1137 B3/09/30 Division of Accident Evaluation 337pp 20839 166
- 8310190306 FOIA request for comments on NUREC/CR-1278, "Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications" SHOLLY,S C Union of Concerned Scientists 83/08/06 FELTON, J M Division of Rules and Records 1p 20840 337
- 8310190309 Responds to FOIA request for comments on NUREG/CR-1278, "Handbook for Human Reliability Analysis W/Emphasis on Nuclear Power Plant Applications "Forwards document Document also available in PDR FELTON, J M Division of Rules and Records 83/09/12 SHOLLY, 9 Union of Concerned Scientists 1p 20840 338
- --8310190313 SAND82-7056
 "Peer Group Study of Draft Handbook for Human Reliability
 Analysis W/Emphasis on Nuclear Power Plant Applications,
 NUREO/CR-1278 "
 BRUNE,R L , WEINSTEIN,M , FITZWATER,M E Human Performance
 Technologies,Inc 83/01/31 229pp 20840 339
- 8310190342 NUREG-0849
 STANDARD REVIEW PLAN FOR REVIEW AND EVALUATION OF EMERGENCY PLANS FOR RESEARCH AND TEST REACTORS
 * Director's Office, Office of Inspection and Enforcement 83/10/31 30pp 20241 307
- 8310200007 Forwards IE Insp Repts 50-334/83-19 & 50-334/83-23 on 830816-0912 & 0922-23, respectively Enforcement conference scheduled for 831011, per 830926 telcon BTARUSTECKI, R Division of Project & Resident Programs 83/10/03 CAREY, J J Duquesne Light Co 3pp 20837 012 24% Fiche 50-334,83/10/03.8310200007
- --8310200010 IE Insp Rept 50-334/83-19 on 830816-0912 Noncompliance noted failure to perform surveillance test within required time period & RHR sys inoperable TROBKOSKI, W M. TRIPP.L E Region 1. Office of Director IE8-79-06C 83/09/29 17pp 20837 015 24X Fiche 50-334,83/10/03,8310200007

- B310200016 Forwards draft SER re NUREG-0737, Item 11 B 3, "Post-Accident Bampling Sys" Response addressing concerns re three outstanding Items requested Telcon to discuss early resolution should be arranged within 30 days of itr receipt STOLZ, J F Operating Reactors Branch 4 B3/10/06 BAUER, E 0 Philadelphia Electric Co 12pp 20B44 249 24X Fiche 50-277, B3/10/06, B310200016
- B310200041 Forwards SER re NUREG-0737. Item II B 1, "RCS Vents," based on encl LLL technical evaluation rept & info provided in B00130.810227.0323 & 0413 ltms concerning vent installation Vent sys design acceptable STOLZ. J F Operating Reactors Branch 4 B3/10/05 CROUSE, R P Toledo Edison Co 7pp 20844 335 24X Fiche 50-346.83/10/05.8310200041
- --B306130456 TF-366/0Bi7A

 "Selected Operating Reactor Issues Program II.RCS Vents,
 (NUREQ-0737, Item II B 1)," final technical evaluation rept
 HELD, J T Energy Incorporated * Lawrence Livermore Laboratory
 FIN A-0250 TAC 44364 B3/03/14 ALBERTHAL/O NRC No Detailed
 Affiliation Given App 20844 342 24X Fiche 50-346.83/10/05,
 B310200041
- B310200050 Forwards Franklin Research Ctr draft technical evaluation rept re control of heavy loads, based on B30131,0302,06 & O610 responses to NRC requests for addl info Telcon will be arranged after B3102B to discuss comments STOLZ, J F Operating Reactors Branch 4 B3/10/06 CROUSE, R P. Toledo Edison Co 3pp 20844 299 24% Fiche 50-346,83/10/06, B310200050
- --B308180560 TER-C3506-348 DRFT

 "Control of Heavy Loads (C-10). Toledo Edison Co. Davis-Besse
 Nuclear Power Station Unit 1." draft technical evaluation
 rept
 B0MBERGER.C., AHMED.N. Franklin Institute/Franklin Research
 Center NRC-03-B1-130 TAC 10993 83/08/09 51NgH.A NRC No
 Detailed Affiliation Given 33pp 20844 302 24X
 Fiche 50-346,83/10/06.8310200050
- B310200064 Forwards SER re NURGO-0737, Item II K 3 17, "Rept on Outages of ECCS" Review complete, however, improvement needed in area of LPIS availability Response requested within 90 days of Itr receipt
 BTDLZ.J F Operating Reactors Branch 4 B3/10/06 WILGUS, W S Florida Power Corp 5pp 20844 277 24X Fiche 50-302, B3/10/06, B310200044
- --B306160602 TER-C5506-272

 "ECCB Repts (F-47) TMI Action Plan Requirements, Floride
 Power Corp. Crystal River Unit 3," technical evaluation
 rept
 VOBBURY, F W , OVERBECK, G J , LUDINGTON, B W Franklin
 Institute/Franklin Research Center NRC-03-Bi-130 B3/06/13
 CHOW, E NRC No Detailed Affiliation Given 18pp 20844 282
 24X Fiche 50-302, 83/10/06, 8310200064
- 8310200157 Bubmits portions of draft IE info notice & 830915 itr re NUREO-0969 "Rept of NRC Evaluation Team on Quality of Const at Zimmer Nuclear Power Station," for review & commit Response requested by 831104 KEPPLER.J 0 Region 3. Office of Director 83/10/17 WILLIAMS, J Cincinnati Gas & Electric Co 19pp 20834 107 24X Fichs 80-358,83/10/17.8310200197
- 831020015B Requests extension until 831215 to submit rept on plant-specific evaluation of relief & safety valves & associated piping sys.per NUREQ-0737. Item 11. D 1 2 ALEXICH.M P Indiana & Michigan Electric Co AEP NRC 05850 83/10/14 DENYON.H R Office of Nuclear Reactor Regulation, Director 2pp 20836 313 24X Fiche 50-315.83/10/14.8310200138.
- B3102D0177 Forwards response to NRC B30627 request for add1 info to satisfy requirements of NUREG-0737. Item II D 1. "Relief & Safety Valve Testing "
 MEDFORD.M O Southern California Edison Co 83/10/14
 KNIGHTON, G W Litensing Branch 3 17pp 20835 248 24X
 Fiche 50-361. B3/10/14. B310200177
- 8310200260 Responds to EOMO Phase i recommendations re special liftin device.per NUREO-0612. "Control of Heavy Loads " Util 830509 commitment to restrict crane hoist speeds reduced possibility of overstress in lifting devices SCHUYLER, J O Pacific Gas & Electric Co 83/10/14, KNIOHTON, O W Licensing Branch 3 Spp 20830 078 24X Fiche 30~275.83/10/14, B310200PA0
- 83i0200284 Addresses SEP Topic V-6. "Reactor Vessel Integrity," documented in NUREG-0569, "Evaluation of Integrity of SEP Reactor Vessels" BEP Topic V-6 resolved as result of evaluation performed per pressurized thermal shock issue. KRIEGER.R W Southern California Edison Co IEB-78-12 83/10/13 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 20829 320 24 Fiche 50-204.83/10/13.8310200284

8310200378 NUREG/CR-3031
CLOSEGUT OF IE BULLETIN 80-05 VACUUM CONDITION RESULTING
IN DAMAGE TO LOW PRESSURE TANKS WHICH MAY CONTAIN PRIMARY
SYSTEM WATER
FOLEY W J. HENNICK, A Parameter, Inc. FIN 8-1013 PARAMETER
IR-12 83/10/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 52pp Available at NRC 44 25 20863 234

83102003B2 NURE0-0540 V05 N07
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE
July 1-31.1983
* Division of Technical Information & Document Control 93/09/30
535pp 20863 286

8310200388 NUREO/CR-1278
HANDBOOK OF HUMAN RELIABILITY ANALYBIS WITH EMPHABIS ON NUCLEAR POWER PLANT APPLICATIONS
SWAIN: A D. GUTTMANN, H E Sandia Laboratories FIN A-1188
SANDBO-0200 B3/10/31. Division of Facility Operations 699pp 20861 139

8310200389 NUREO/CR-3280
TRAC-PF1 DEVELOPMENTAL ASSESSMENT
BOYACK, B E Los Alamos Scientific Laboratory FIN A-7016
LA-9704-M8 83/09/30 Division of Accident Evaluation 506pp

B310210152 NUREG-0835 DRFT
HUMAN FACTORS REVIEW QUIDELINES FOR THE SAFETY PARAMETER
DISPLAY BYSTEM FINAL REPORT
* Human Factors Engineering Branch 83/09/19 53pp 20883 197

8310210179 Comments on incorrect statements noted in 830929 trip rept Correct milestons date for Unit i hot functional testing is Nov 1983 & May 1984 for fuel loading TUCKER. H II Dute Power Co. 83/10/13 GILINBKY, V. Commissioners 2pp 20856 125 24K Fiths 50-413.83/10/13,8310210179

8310210270 Application for amend to Licenses DPR-57 & NPF-5 transferring radiological effluent Tech Spec from App B to App A GUCWA.L T Georgia Power Co NED-83-509 83/10/17 8TOLZ, J F Operating Reactors Branch 4 App 20846 290 24% Fiche: 50-321,83/10/17,8310210270

--B310210277 Proposed Tech Spec transferring radiological effluent Tech Spec from App 8 to App A * Georgia Power Cu B3/10/17 128pp. 20846 276 24X Fiche 50-321,83/10/17,8310210270

8310210302 Forwards Ray 3 to implementation schedule in 830415 response to Generic Ltr 82-33, Suppl 1 to NUREO-0737; "Requirements for Emergency Response Capability "
MEAVER, J D Nebraska Public Power District 0L-82-33 83/10/18 SIEGEL, B Operating Reactors Branch 2 3pp. 2085) 061 24X Fiche 50-298,83/10/18,8310210302

B310210310 Forwards response to B30104 request for add1 info re NUREO-0737, Item II. D 1 "Relief & Bafety Valve Test Requirements " "Tes" quencher utilized at discharge pipe exit SINCLAIR, J B Vermont Yankee Nuclear Power Corp Fyy B3-110 83/10/17 VASSALLO, D B Operating Reactors Branch 2, 15pp 20851 137 24X Fiche 50-271,83/10/17,8310210310

B310240134 Provides status of mods required for Generic Ltr 82-28 re inadequate core cooling instrumentation & NUREG-0737. Item II.F. 2 Issues include environ qualification of two ICCI subsystems & installation of core sait thermocouple LUNDVALL. A E Baltimore Gas & Electric Co GL-83-28 83/10/14 MILLER. J R Operating Reactors Branch 3 3pp 20881 166 24X Fiche. 50-317.83/10/14,8310240134

8310240143 Forwards "Control Room Design Review Program Plan, Hope Creek Generating Station." in response to Generic Ltr 82-33, Item 5 Summary rept will be submitted by 840815 MITTL. R L Public Service Electric & Ges Co of New Jersey GL-82-33 83/10/17 SCHMENCER, A Licensing Branch 2 2pp 20880-039 24X Fiche: 50-354.83/10/17,8310240143

--8310240145 "Control Room Design Review Program Plan:Hope Creek **Perrating Station" ** Esset Corp. 83/10/14 52pp. 20880:041 24X **Fiche 50-354,83/10/17.8310240143

8310240162 Notifies of resolution of NUMEO-D737, TWI Action Plan Item II.X.2.17. "Potential for Voiding in RCB During Transients "Results of analysis presented in GEN-199 applicable to facilities wistated exception.
LUNDVALL.A E Baltimore Cas & Electric Co 83/10/19. MILLER, J R. Operating Reactors Branch 3 1p. 20881-312. 24X
Fichs: 50-317, 83/10/19, 8310240162

B310240243 Forwards SER & technical evaluation rept re NUREG-0737, Items I A 2 1, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage " Requirements met VASSALLO. D B Operating Reactors Branch 2 B3/10/12 PARRIS, H G Tennessee Valley Authority 4pp 20891 123 24X Fichs 50-259,83/10/12,8310240243

--B20B310352 SAI-184-027-50
"Improvements In Training & Requalification Programs As Required By TMI Action Items I A 2 1 & II B 4 for Browns Ferry Nuclear Plants.Units 1,2 & 3." technical evaluation rept
Science Applications, Inc NRC-03-82-096 B2/0B/25 NRC - No Detailed Affiliation Given 15pp 66280 216 24X Fiche 50-000.B3/10/12.B310240243

8310230002 Responds to FOIA request for distribution list used for mailing NUREG-0737 (Supp) i), "Control Room Design Reviews "Forwards list W/o encl FELTON, J M Division of Rules and Records 83/07/14 DEBDR, J Biotechnology, Inc. 19 20708 337

B310250007 FOIA request for distribution list used for mailing NUREG-0737 (Suppl 1). "Control Room Design Reviews " Info received will be used to support util conference on NUREG-0737 DEBORJ J Biotechnology, Inc B3/07/05 Division of Rules and Records 1p 20908 338

B310250028 Responds to FOIA request for SECY-B3-030. "TMI-Related Requirements at Operating Reactors." be placed in PDR Forwards requested document Document also available in PDR PDR FELTON, J M Division of Rules and Records 83/07/15 BUCKLES, R NUB Corp ip 20916 178

--8310250030 SECY-83-030
Advises of NRR plan to take licensing action on TM1 action plan requirements specified in NURC9-0737 scheduled for implementation after 810630
DIRCKS, M J Office of the Executive Director for Operations 83/01/21 31pp 20916 179

8310250248 Forwards IE Insp Repts 50-269/83-28,50-270/83-28 & 50-287/83-28 on 830811-0910 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/09/2 TUCKER, H B Days Power Co 1p 20899 074 24X Fiche 50-269,83/09/27,8310250248

--8310250256 IE Insp Repts 50-269/83-28.50-270/83-28 & 50-287/83-28 on 830811-0910. No noncompliance noted Major areas inspected operations maint surveillance training & NUREO-0737 Items BRYANT, J Region 2, Office of Director 50-287/83-28 83/09/27 10pp 80899 075. 24X Fiche 50-269.83/09/27.0310250248

B3i0250274 Updates present status & describes tasks performed over previous 6 months per requirements of Generic Ltr 82-33 & Supel I to NUREO-0737 re control room design review Figure 2-2 encl
MARBHALL.JR Arkansas Power & Light Co GL-82-33 83/10/20
EISEN-NUT.D O Division of Licensing 4pp 20702 340 24X
Fiche 50-313.83/10/20.8310250274

8310250281 Advises of delay in providing add1 info re NUREG-0737. Item II B 3 concerning post-accident sampling sys.per 830714 request. Sue to outage beginning ahead of schedule Info expected by 831025
MARSHALL.JR Arkanses Power & Light Co OCAN108310 B3/10/17 STOLZ.JF Operating Reactors Branch 4 MILLER.JR Operating Reactors Branch 3 ip 20898 342 24X Fiche 50-368, 83/10/17, 8310250281

8310250320 Forwards IE Insp Repts 50-280/83-23 & 50-281/83-23 on 830816-17 No nancompliance noted DANCE: H C Division of Project & Resident Programs 83/07/23 STEMART; H L Virginia Electric & Power Co 2pp 20700 084, 24x Fiche: 50-280,83/07/23,8310250320

--8310250328 IE Insp Repts 50-280/83-23 t 50-281/83-23 on 830811-17 No noncompliance noted Major areas inspected review of TMI Action Item II B 2.plant mods for vital area access.posting, labelling & control of radiological areas HOSEY.C M Region 2. Defice of Director 50-281/83-23 83/09/21 4pp. 20700 086 24X Fiche 50-280.83/09/23.8310250320

8310250391 Forwards FEMA 830928 Itr providing status of final findings of offsite preparedness State & local plans & preparedness adequate to protect public PAPERIELLO.C J Region 3, Office of Director 83/10/21 DOLAN.J F American Electric Power Service Corp DOLAN.J E Indiana & Michigan Electric Co 1p 20897 280 24X Fiche 50-315,83/10/21,83/10/21,

- --8310250401 Comments on status of offsite emergency preparedness State & local plans & preparedness adequate to protect health & safety of public Approval conditional on verification of public alerting & notification sys
- 8310250414 Forwards IE Insp Repts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No noncompliance noted BANCE.H C Division of Project & Resident Programs 83/10/05 STEWART.W L Virginia Electric & Power Co 2pp 20897 227 24x Fiche 50-338/83/10/05/8310250414
- --B310250428 IE Insp Ropts 50-338/83-22 & 50-339/83-22 on 830815-19 & 0919-20 No noncompliance noted Major areas inspected liquid & gaseous effluent releases, effluent control instrumentation, reactor colant water quality & NUREG-0737 WAAY, J R Region 2, Office of Director 50-339/83-22 83/09/30 9pp 20897 229 24X Fiche 50-338/83/10/05,8310250414
- 8310250433 Forwards safety evaluation of C-E Owners Group Rept CEN-199 compliance w/NUREG-0737. Item II K 2 17. "Voiding in RCS During Transients" Requirements met Item closed CRUTCHFIELD. D Operating Reactors Branch 5 83/10/19 VANDEWALLE. D J Consumers Power Co 9pp 20897 037 24X Fiche 50-255.83/10/19.8310250433
- 8310250463 Informs that facility will be in compliance w/NUREO-0737, Item II F 2 re inadequate core cooling instrumentation, per 830728 ltr.in response to 830627 safety evaluation, pending campletion of upgraded procedures GRUTCHFIELD, D Derating Reactors Branch 5 LSO5-83-10-048 83/10/24 KAY.J A Yankee Atomic Electric Co 5pp 20897 149 24X Fiche 50-029,83/10/24,6310250463
- B3i0250474 Ack receipt of 830923 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-23 & 50-325/83-23 O'REILLY, J P Region 2, Office of Director 83/10/11 UTLEY, E Carolina Power & Light Co ip 20900 061 24X Fiche 50-324,83/10/11,8310250474
- --8310250501 IE Insp Repts 50-324/83-23 & 50-325/83-23 on 830626-30 Noncompliance noted large quantity shipment in CNS-3-55 shipping cask not leak tested prior to delivery of package to carrier for transport ALBRIGHT.R H , BARR.K P Region 2. Office of Director 50-325/83-23 83/08/05 7pp 20900 068 24X Fiche 50-324,83/10/11.8310250474
- B310230514 Ack receipt of \$30810 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-26 & 50-370/83-33 Evaluation of radiation hazard associated w/ transfer of neutron source adequate Violation withdrawn O'REILLY.J P Region 2, Office of Director 83/10/07 TUCKER.H B Duke Power Co 2pp 20901 279 24X Fiche 50-369,83/10/07.8310250514
- --B310250540 IE lnsp Repts 50-369/83-26 & 50-370/83-33 on 830606-10 Noncompliance noted failure to perform adequate neutron radiation survey to evaluate extent of radiation hazards present prior to permitting worker entry COLLINSIT R, BARR, K P Region 2. Office of Director. 50-370/83-33 B3/06/28 bp 20901 287 24X Fiche 50-369,83/10/07,8310250514
- B310250677 Forwards SER re 830427 submittal on NUREQ-0737, Item
 Item II K 2 i7 re voiding in RCS during anticspated
 transients in C-E plants Voids generated in RCS accounted
 for in present analysis modes Review complete
 MILLER, J R Operating Reactors Branch 3 B3/10/11 GARRITY, J H
 Haine Yankee Atomic Power Co 10pp 20908 339 24x
 Fiche 50-309,83/10/11.8310250677
- 8310250681 Forwards SER (NUREO-0944) & FR notice re full-term OL application Provisional OL/full-term OL conversion issue will be resolved by ASLB M/o SER CRUTCHFIELD, D. Operating Reactors Branch 5 LSD5-83-10-038 B3/10/14 MAIER, J E Rochester Gas & Electric Corp 2pp 2090R 351 24% Fiche 50-244,83/10/14.8310250681
- --B310230682 Notice of availability of SER for full-term OL (NUREG-0944)
 CRUTCHFIELD, D Operating Reactors Branch 5 B3/10/14 ip
 20908 353 24X Fichs 50-244.83/10/14.8310250681
- 8310260206 Forwards Amend 20 to 0E88AR-II.responding to Confirmatory
 Issue 18 of SER, Suppl 1 to NUREO-0979, revised responses to
 NRC 820825 ltr re communication & lighting sys & updating
 interface tables of Subsection 1 9 1
 SHERPHODD, G O General Electric Co MFN 185-83 83/10/04
 EIBENHUT, D 9 Division of Licensing 3pp 20909 001 24X
 Fiche, 50-447, 83/10/04, 8310260206

- --B310960211 Amend 20 to QEBSAR-II • General Electric CD. 2247007 B3/10/04 205pp 20909 004 24% Fiche 50-447, B3/10/04, B310260206
- 8310260212 Forwards response to 831004 request re NUREG-0737.ltem II E 4 2. "Containment Purge & Vent Valves," design evaluation W/13 oversize drawings Aperture cards are available in PDR DALTROFF.S L Philadelphia Electric Co 83/10/19 8TOLZ, J F Operating Reactors Branch 4 72pp 20909 277 24X Fiche 50-277.83/10/19.8310260212
- B310260316 Summary of 830707 meeting w/util in Bethesda, MD re overpressurazation of standby gas treatment sys ductwork & filters Issue resolved Disposition discussed in SER. NUREO-0991 issued in Aug 1783 MARTIN, R E Licensing Branch 2 83/10/19. Licensing Branch 2 19pp 20921 220 24X Fiche 50-332.83/10/19.8310260316
- 8310260346 Summary of Caseload Foretast Panel 830810-12 meetings w/util in Clinton. IL re const status of facility Viewgraphs encl. ABELSON.H Licensing Branch 2 83/10/17 Licensing Branch 2, 164pp 20718 084 24X Fiche 50-461.83/10/17,8310260346
- 8310260353 Forwards SER (NUREQ-0821) "Integrated Plant SAR" for full committee review on util full term DL application W/o encl MIRAQLIA:F J Division of Licensing LSU5-83-10-059 83/10/14. RAY. J ACRB Advisory Committee on Reactor Safeguards ip 20918 332 24x Fiche 50-244.83/10/14.8310260353
- 8310260381 NUREQ/CR-3445
 COST-BENEFIT ANALYBIG OF UNFIRED PUO2 PELLETS AS AN
 ALTERNATIVE PLUTONIUM SHIPPING FORM
 HISHIMAJJ, BRACKENBUSH,L, LIBBY,R A Battalle Memorial Institute.
 Pactific Northwest Laboratory FIN 8-2424 PNL-4806 83/10/31.
 Division of Risk Analysis 47pp Available at NRC 84 00
 20918 248
- 8310260397 NUREQ/CR-3499

 BEVERE RAIL AND TRUCK ACCIDENTS TOWARD A DEFINITION OF BOUNDING ENVIRONMENTS FOR TRANSPORTATION PACKAGES EQUERS, P Riginalgh, Eggers & Associates FIN 8-6621 83/10/31 Division of Risk Analysis 358pp Available at NRC \$8 00. 20919 001
- 8310240423 NUREC/CR-3199
 GUIDANCE FOR DISPOSAL OF URANIUM MILL TAILINGS LONG-TERM
 STABILIZATION OF EARTHEN COVER MATERIALS
 VOORHEES, L D , SALE, H J , WEBB, J W Car Ridge National Laboratory
 FIN B-0279 ORNL/TM-8685 83/10/31 Division of Bafeguards
 110pp Available at NRC 44 75 20926 016
- 8310260427 NUREQ/CR-2146 V03
 DYNAMIC ANALYBIS TO ESTABLISH NORMAL SHOCK AND VIBRATION OF
 RADIOACTIVE MATERIAL SHIPPING PACKAGES Final Summary Report
 FIELDS.S R Hanford Engineering Development Laboratory. FIN 8-2263.
 HEDL-THE 83-18 83/10/31 Division of Risk Analysis 295pg
 Available at NRC \$7.50 20925-081
- B310270130 Requests review & concurrence w/proposed post-accident shielding alternate solution mod (NUREO-0737.Item It B 2); per 830521 & 0615 responses to Generic Ltr B2-05 HUKILL.H D General Public Utilities GPU Service Corp 5211-83-280 83/10/21 8701.Z.J F Operating Reactors Branch 4.6pp 20925 022 24X Fiche 50-289.83/10/21.8310270130
- B310270132 Responds to FDIA request for info re possible rev to radiological emergency planning guidance & info on whether NRC emergency planning regulations appropriate in light of anticipated accident scenarios Forwards documents FELTON.J M Division of Rules and Records 83/07/15.

 BRANDERBURG, B Consolidated Edison Co of New York, Inc. 1p
- --8310270145 Staff requirements memo re 821110 briefing in Washington, I on Sandia consequences study Commission briefed on NUMEQ/CR-2239 (BANDSI-1549). "Technical Guidants for Biting Criteria Development "Viewgraph end CHILK,S J Office of the Secretary of the Commission, MS211108 82/11/18 DIRCKS,W J Office of the Erecutive Director for Operations. 3pp 20942 237
- 8310270143 Forwards SER re restart following steam generator tube rupture event on 820123, per NURES-0916 Senarator tube fiber optic insplaceable, based on info in util 821122 itr. CRUTCHFIELD: D Operating Reactors Branch 5 LEO5-83-10-054, 83/10/25 MAIER, J E Rochester Oas & Electric Corp 2pp 20924 138 24X Fiche 50-244, 83/10/25, 8310270143
- --8310270149 Safety evaluation supporting steam generator tube fiber optic insp
 + Office of Nuclear Reactor Regulation, Director 83/10/25 Ppc
 20924 140 24% Fiche 50-244, 83/10/25, 8310270143

- B10270300 Suppls B30325 response to B30111 request for addl info re NUREO-0737. Item II B 3, "Post-Accident Sampling " Interim core damage assessment procedure in use until Mestinghouse Owners Group methodology completed by end of 1983 STEWART. W L Virginia Electric & Power Co 038A 83/10/20 DENTON. N R Office of Nuclear Reactor Regulation. Director 2pp 20923.193 24X Fiche 50-000.83/10/20,8310270300
- 310270369 Responds to FOIA request for SECY-83-278 & SECY-83-270, transmitting 830624 "Rept on Adequacy & Safey of Relief Valve Testing & Performance" Forwards requested documents FELTON, J M Division of Rules and Records 83/10/04 HEISS, E R Union of Concerned Scientists Ip 20743 129 24X Fiche 50-289,83/10/04,8310270369
- -8307220250 BECY-83-270
 Provides summary of primary sys relief & safety valve testing & performance since TMI-2 accident per NUREG-0737. Item II D i DIRCKS, W J Office of the Executive Director for Operations 83/07/05. i22pp 20943 i73
- 310270443 Forwards comments on Rev 5A to emergency plan Comments will be categorized as improvement items since SER states plan meets 10cFR50 47(b) stds & 10cFR50 App E requirements, per NUREG-0830 PAPERIELLO, C J Region 3. Office of Director B3/10/25 MATTHEWS.D B Emergency Preparadness Branch App 20923 091 24x Fiche-50-483, 83/10/25, 8310270443
- 310270552 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 83/10/21 Document Menagement Branch lp 20944 017 24X Fiche 50-461,83/10/21, 8310270552
- -B310270549 Forwards public version of fraft Amend 28 to FSAR.App 13 G consisting of Rev 2 to Emergency Plan OAP1890 COS Rev should resolve SER Dutstanding Issue 18 (MNREC-0853)
 NELBON.R M Illinois Power Co U-0475 B3/10/14 BCHHENCER.A Licensing Branch 2 Ip 20744 018 24X Fiche 50-461,83/10/21, B3/107052
- 310270555 Forwards safety evaluation supporting design of reactor coolant vent sys per requirement of 10CFR50 44(c)(3)(ii) & NUREQ-0737. Item II B I MILLER. J R Operating Reactors Branch 3 83/09/22 FAY, C W Misconsin Electric Power Co. 7pp 20944 003 24X Fiche 50-246.83/09/22.8310270555
- 310270502 Informs that requirements of NUREQ-0737, Item 11 K 3 17, "Rept on Dutages of ECCS," met Review of item complete VARQA, B A. Operating Reactors Branch i 83/10/19 D'TOQLE, J Consolidated Edison Co of New York, Inc 2pp 20946 259 24X Fiche: 50-247,83/10/19,8310270602
- 310280009 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept re NUMEG-0737. Items II K 3 i, "Automatic PORV is localation" & II K 3 2, "Rept on FORVs " Response acceptable CRUTCHFIELD, D. Operating Reactors Branch 5 LSG5-83-10-050 83/18/20 VANDEWALLE, D. J. Consumers Power Co. 3pp. 20934 109 24X Fiche 50-255, 83/10/20, 8310280009
- 310280044 Forwards "Detailed Control Room Design Review Program Plan for JA Fitipatrick Nuclear Power Plant," in response to 821217 Generic Ltrs 82-33 & 83-18, Suppl 1 to NOREO-0737 & THI Action Item I D 1
 BAYNE, J P Power Authority of the State of New York GL-82-33 83/10/24 VASSALLO, D 8. Operating Resctors Branch 2 2pp 20934:348 24x Fiche 50-333,83/10/24.8310280044
- -8310280054 "Detailed Control Room Design Review Program Plan for JA Fitspatrick Nuclear Power Plant " Power Authority of the State of New York OL-82-33 83/10/19 86pp. 20934 350 24x Fiche 50-333.83/10/24.8310280044.
- 310280082 Provides schedule for submittel of core damage assessment procedures eleventh criterion of NUREG-0737. Item II B 3, "Post-Accident Sampling Bys " Procedure will be submitted prior to startup Pollowing Fall 1984 refueling outage WILLIAMS, J W Florida Power & Light Co L-83-525 83/10/25 WILLIAMS, J R Operating Reactors Branch 3 1p 20934 103 24X Fiche 30-335,83/10/25,8310280082
- H0280087 Forwards safety evaluation re review of util submittal addressing NAREG-0737. Hem II.K 2 17. "Voiding in RCS During Anticipated Transients " Steam void will not result in unacceptable consequences HILLERLY R Operating Reactors Branch 3 83/10/17 JONES, W C Omaha Public Power District 9pp. 20761 349 24X Fiche 50-285,83/10/17,8310280087

- 8310280096 Responds to SER Open Item 6 re NUREG-0737. Item II F 2,
 "Instrumentation for Detection of Inadequate Core Cooling,"
 providing updated FSAR pages concerning core exit
 thermocouples & reactor vessel level measurement
 TUCKER. H B Duke Power Co 83/10/19 DENTON. H R Dffice of
 Nuclear Reactor Regulation, Director ADENSAM. 6 G Licensing Branch
 4 13pp 20935 191 24X Fiche 50-413,83/10/19.8310280094
- 8310280099 Forwards B&W Owners Group rept "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/Ft Limits W/Use of FLECSET" RODRIGUEZ.R J Sacramento Municipal Utility District RJR 83-705 83/10/21 STQLZ.J F Operating Reactors Branch 4 ip 20935 212 24X Fiche 50-312.63/10/21.8310280099
- B310280103 Forwards update of progress of control room habitability mods.per 830922 ltr re TMI Item III D 3 4 HVAC equipment operating at approx 2/3 design capacity Updated work list & schedules encl
 TUCKER.H B Duke Power Co B3/10/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 20935 324 24X
 Fiche 50-269.83/10/24.8310280105
- 8310280127 Responds to NRC 830926 ltr re schedule for meeting emergency response capability requirements Const schedule will permit fuel loading by 840801 Full scale emergency preparedness exercise rescheduled to 840725

 BDYER, V 5 Philadelphia Electric Co 83/10/25 SCHWENCER, A Licensing Branch 2 3pp 20929 273 24X Fiche 50-352,83/10/25, 8310280127
- 8310280128 Forwards safety evaluation re util 830727 response to NUREO-0827 re integrated safety assessment rept. Sections 4 26 & 4 26 3 Commitments & justification for not modifying certain Foxboro & Honeywell recorders acceptable CRUTCHFIELD D Decrating Reactors Branch 5 LSOS-83-10-041 83/10/27 LINDER:F Dairyland Power Cooperative 2pp 20727 038 24X Fiche 50-407,83/10/27.8310280128
- --B310280134 Sepety evaluation re util 830929 response to NUREO-0827 integrated plant safety assessment rept.Bactions 4 26 & 4 26 3 Commitments & Justification acceptable # Operating Reactors Branch 5 B3/10/27 2pp 20929 040 24X Fiche 50-409,83/10/27,8310280128
- 8310280141 Advises that commitments in util 830930 ltr re SEP Topic VI-4, "Containment Isolation Bys (Electrical)," NUREQ-0378 & NUREQ-0737.1tem JI E 4 2 acceptable No mods to steam generator sample & blowdown lines required PAULSON, W Operating Reactors Branch 5 LS05-83-10-064 83/10/27 DIETCH, R Southern California Edison Co 4pp 20929 042 24X Fiche 50-206.83/10/27.8310280141
- 8310280161 Discusses 831006 response to request for add1 info re integrated plant safety assessment rept (NUREG-0827). Section 4 12: "Pipe Break Dutside Containment" Criteria for jet impingement provided Section complete Evaluation encl CRUTCHFIELD. D. Operating Reactors Branch 5 LS05-83-10-062 83/10/27 LINDER.F Dairyland Power Cooperative 2pp 20927 221 24X Fiche 50-409,83/10/27.8310280161
- --8310280163 Safety evaluation supporting integrated plant safety assessment rept (NUREG-0827), Section 4 12, "Pipe Break Outside Containment"

 * NRC No Detailed Affiliation Given 83/10/27 ip 20929 223 24X Fiche 50-409,83/10/27,8310280161
- 8310280173 Forwards latest response to NUREO-0737. Item II D 3, "Direct Indication of Relief & Bafety Valve Position," reflecting as-installed location of acoustic monitoring sys accelerometer
 MILLS.L M Tennessee Valley Authority 83/10/24 ADENBAM, E Licensing Branch 4 2pp 20927 006 24X Fiche 50-390,83/10/24,8310280173
- 8310310054 Advises that pipe stresses & support loads due to dead weight of water in pipe.concurrent thermal effects & effects of postulated earthquake within design allowables reviewed, per NUREG-0737. Item II D i RYBAN, B Commonwealth Edison Co 7484N 83/10/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 20951 146 24% Fiche 50-254, 83/10/20, 8310310054
- 83:03:0066 Responds to 8308:5 request for add1 info re NUREQ-0737. Item II B G. "Post-Accident Sampling Sys." providing supplemental info concerning two of four open criteria & schedule for responding to remaining requests

 BAYNE.J P Power Authority of the State of New York IPN-83-87

 B37:0726 VARQLS A Openating Reactors Branch 1 8pp 20951 037

 24x Fiche 50-286, 83/10/26, 8310310066

8310310097 Responds to FOIA request that i& SECYs be placed in PDR Forwards App A documents SECY-82-466 withheld (ref FOIA Exemption 5)

Exemption 5)
FELTON, J M Division of Rules and Records B3/09/19 SHOLLY, S C
Union of Concerned Scientists 3pp 21000 146

--8310310140 SECY-83-093
Transmits INPO "Performance Objectives & Criteria for Corporate Evaluations" & informs of plans to defer further action on TMI Action Plan Itam I B 1 i W/o encl DIRCKS.W J Office of the Executive Director for Operations 83/03/09 3pp 21000 296

Batcallo Nurecycr-3215 VO2 ER

DRGANIZATIONAL ANALYSIS AND SAFETY FOR UTILITIES WITH

NUCLEAR POWER PLANTS

* Battelle Memorial Institute, Pacific Northwest Laboratory

PNL-4655 83/10/19 Division of Facility Operations 2pp

20965 329

B310310111 NUREG-0580 V12 NO7
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of
September 30,1983 (Blue Book)
* Management Information Branch 83/10/31 63pp 20779:146

B310310114 NUREO/CR-2830

\$10310114 NUREO/CR-2830
PERMISSIBLE RADIONUCLIDE LOADING FOR ORGANIC ION EXCHANGE
REBINS FROM NUCLEAR POWER PLANTS
HACKENZIE,D R , LIN.M , BARLETTA,R E Brookbaven National
Laboratory FIN A-3159 BNL-MUREG-51565 83/10/31 E
Haste Management 105pp 20797 210

Division of

#2310310118 NUREG-0748 VO3 NO8

OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As of August 31:1983 (Drange Book)

Management Information Branch 83/10/31, 452pp 21002 107

@310310121 NUREG-0750 V17 IO1

INDEXES TO NUCLEAR REGULATORY COMMISSION ISSUANCES

January - March 1983

* NRC - No Detailed Affiliation Given 83/03/31 65pp 20985 190

B310310123 Forwards safety evaluation based on util submittals re NUREG-0737, II B 2, "Design Review of Plant Shielding Access to Vital Areas " Requirements met MILLER, J R Operating Reactors Branch 3 B3/10/12 MUSDLF, D M Northern States Power Co 3pp 20765 324 24X Fiche 30-282,83/10/12,8310310123

E310310125 Forwards safety evaluation based on review of B20108 submittal adopting C-E Guners Group analysis on TMI Action Item II K 2 17, "Potential for Voiding in RCS During Transients " Analysis acceptable Item complete MILLER, J R Operating Reactors Branch 3 83/10/05 UMRIG.R E Florida Power & Light Co 9pp 20965 332 24X Fiche 50-335,83/10/05,8310310125

8310310127 Forwards safety evaluation based on review of util responses to NUREO-0737 items Requirements of NUREO-0737. Item II K 3 2 met MILLER, J R Deprating Reactors Branch 3 83/09/30 JONES, W C Omaha Public Power District 14pp 21000-079 24X Fiche 50-285, 83/09/30, 8310310129

310310137 Forwards safety evaluation re review of util submittal addressing NUREG-0737 Item II X 3 17, "Rept on Outages of ECCS " Requirements met VASSALLO, D B Operating Reactors Branch 2 83/10/14 UTLEY, E E Carolina Power & Light Co 4pp 20965 250 24X
Fichs 50-324,83/10/14,8310310137

"ECCS Repts (F-47) TMI Action Plan Requirements, Brunswick Steam Electric Plant, Units 1 & 2," technical evaluation

rept
VDSBURY,F W , DVERBECK, G J Franklin Institute/Franklin Research
Center NRC-03-81-130 83/06/13 CHOW,E NRC - No Detailed
Affiliation Given 22pp 20965 254 24X Fichs 50-324.83/10/14r
8310310137

8310310180 Forwards safety evaluation based on review of util responses to NUREG-0737. Items II K 3 1, "Automatic PORV Isolation" & II K 3 2, "Rept on PORVs " Requirements met.
MILLER, J R Operating Reactors Branch 3 83/10/12 LUNDVALL, A E Baltimore Gas & Electric Co 14pp 21000, 037 24X Fiche 50-317,83/10/12,8310310180

831031018B NUREG-0566 VO3 NO1-3 BTANDARDB DEVELOPMENT STATUS BUMMARY REPORT, Data As Of September 30,1983 (Green Book) * Program & Administrative Services Branch 83/10/31 90pg 21003 091

8310310191 NUREG/CR-2000 VO2 N9 LICENSEE EVENT REPORT (LER) COMPILATION-For Month Of September 1983

September 1983 * Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200 83/10/31 Director's Office. 162pp 21003 187

8310310208 NUREQ/CR-3352 FUMIGATION POTENTIAL AT INLAND AND COASTAL POWER PLANT

SITEB LINDSEY, C. G., RAMSDELL, J. V. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2514 PNL-4760. B3/10/31 Division of Systems Integration (post B11005) 32pp Available at NRC 63 75 21000 001

8310310209 NUREQ/CR-2571

310310209 NOREG/CR-2571
BWR REFILL-REFLOOD PROGRAM TASK 4 8 - TRAC-BWR MODEL
QUALIFICATION FOR BWR SAFETY ANALYSIS FINAL REPORT
ALAMOIR: M Coneral Electric Co FIN B-5877 EPRI NP-2377
83/10/31 Division of Accident Evaluation 263pp Avai
NRC \$6 50 21004 001 Available at

8310310248 NUREGYCR-2893 CORRELATION OF MEUTRON DATA TAKEN AT COMMERCIAL NUCLEAR SITES

SILES RATHBUNL A , ENDRES, 6 W Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2423 PNL-4395 B3/10/31. Division of Facility Operations 32pp Available at NRC \$3.75 20999.315

8310310306 Responds to 830906 request to resvaluate position on NUREO-0737. Item II E 4 2(7) Monitor capable of promptly & reliably providing isolation signal would not be sufficiently sensitive to detect release rates HARRINGTON, W D Boston Edison Co 83/10/25, VASSALLO, D B. Operating Reactors Branch 2 2pp 20961 227, 24X Fichs 50-293,63/10/25,8310310306

8310310307 Submits results of engineering evaluation of two primods to automatic depressurization sys logic per NUREG-0737. Item II K 3 18 Problem better addressed by using symptom-based emergency operating procedure MURPHY.W P Vermont Yankee Nuclear Power Corp FVY 83-111 83/10/24 VASSALLO, IB Operating Reactors Branch 2 2pp 20961 224 24X Fiche 50-271.83/10/26.8310310307

B310310410 Forwards B&H Owners Group Analysis Committee/Core Performance Committee Rept "Bounding Analytical Assessment of NUREG-0430 Models on LOCA tW/ft Limits W/Use of FLECSET." HUKILL, H D General Public Utilities - 0PU Service Corp 5211-B3-G05 B3/10/21 NUVAK,T Assistant Director for Licensing 1p 20941 001. 24X Fiche 50-289, B3/10/21, B310310410

--8310310413 77-1140898-01
"Bounding Analytical Assessment of NUREC-0630 Models on LOCA WH/ft Limits W/Use of FLECSET "
Babcock & Wilco Operating Plants Owners Group 83/09/30 104pp 20961 002 24X Fiche 50-289.83/10/21.8310310410.

8310310493 Forwards Amend 36 to License DFR-34 & safety evaluation Amend revises administrative Tech Specs to incorporate various editorial & format corrections per NUREO-0737. Item 13 LEE,OR 24X I A 1 3 WAGNER,P C Region 4, Office of Director 83/10/13 Public Bervice Co of Colorado 2pp 20759 194 24 Fiche: 50-267,83/10/13,8310310493.

--8310310435 Amend 36 to License DPR-34, revising administrative Tech Specs to incorporate various editorial & format corrections, per NURED-0737, Item I A i 3 JCHNBON.E H Region 4, Dffice of Director 83/10/i3, 34pp 20959: 196 24X Fiche: 50-267, 83/10/i3, 8310310433

8310310439 Responds to 830907 request for mod to NRC 830701 order confirming util commitments to implement certain post-TMI-related items set forth in NUREO-0737 to extend completion date for Item II B 3 to 831201. Request acceptable STOLZ.JF Operating Reactors Branch 4 B3/10/14 BECKHAM.J Georgia Power Co 2pp. 24% Fiche 50-321,83/10/14,8310310439 BECKHAM, J T

--8310310440 Order granting extension until B31201 to complete Item II B 3, "Post-Accident Sampling." Commitments on applicable NUREQ-0737 requirements from Generic Ltr B2-05 EIBENHUT, D. Q. Division of Licensing, QL-82-05 83/10/14. Qeorgia Power Co. Spp. 20965.164. 24X Fiche 50-321,83/10/14,8310310439

B310310444 NUREQ/CR-3081
REVIEW OF CRYSTAL RIVER NUCLEAR GENERATING STATION UNIT 3
EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS
YDUNGBLODD, R. PAPAZOGLOU, I A Brookhaven National Leboratory FIN
A-3393 BNL-NUREO-51626 B3/10/31. Division of Safety
Technology 43pp Available at NRC \$3.75 21001.016 24X
Fiche 50-302.83/10/31.8310310444

MRG

- B310310446 NUREC-0577 R01
 POTENTIAL FOR LOW FRACTURE TOUCHNESS AND LAMELLAR TEARING
 IN PWR STEAM DENERATOR AND REACTOR COOLANT PUMP SUPPORTS
 Unresolved Bafety Issue A-12
 P Division of Bafety Technology B3/10/31. 70pp Available at
 NRC \$4.30 21000 304.
- B310310447 NUREO/CR-3131 COMPLEX RADIATION DEGRADATION BEHAVIOR OF PVC MATERIALS UNDER ACCELERATED AGING CONDITIONS CLOUGH,R L , GILLEN,K T. Sandia Laboratories FIN A-1051 SANDB2-1414 B3/10/31. Division of Engineering 20pp 20945 122
- B310310449 NUREG/CR-3450
 A SUMMARY OF REPOSITORY DESIGN MODELS
 CURTIS.R.H., WART.R.J., BKIBA.E.L. Acres American, Inc. FIN B-6985
 B3/10/31 Division of Haste Management 217pp Available at
 NRC. \$6.50 21001 063
- 8310310452 NUREQ-1021 OPERATOR LICENSING EXAMINER STANDARDS * Division of Human Factors Bafety. 83/10/31 180pp Available at NRC. \$6.00 21001 284
- 8308300340 IE Info Notice 83-61, "Alleged Use of Stand-Ins for Helder Qualification Tests" Syc list enc1 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Efison Co. of New York, Inc. 117pp 20754:022 24X Fiche:50-000,83/09/24,8308300340

CORRESPONDENCE WITH OTHER ORGANIZATIONS

- B30B300342 IE Info Natice 83-62, "Failure of Redundant Toxic Gas
 Detectors Positioned at Control Room Ventilation Air
 Intakes " Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/09/26 Consolidated Edison Co of New
 York, Inc. 116pp 20777 210 24X Fiche 50-000,83/09/26,B30B300342
- 3308300345 IE Info Notice 83-63, "Potential Failures of Westinghouse Type 8A-1 Differential Relays" Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103). 83/09/26 Cansolidated Edison Co of New York, Inc. 118pp 20778 001 24X Fichs 50-000.83/09/24, 8308300345
- 3308300347 IE Info Notice 83-64, "Lead Shielding Attached to Safety-Related Sys W/o 10CFR50 59 Evaluation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/09/29. Consolidated Edison Co of New York, Inc. 115pp 20716, 324 24X Fiche 50-000, 83/09/29, 8308300349
- 300300378 IE Info Notice 83-68, "Surveillance of Flow in RTD Sypass Loops Used in Westinghouse Plants " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103). 83/10/07 Consolidated Edison Co of New York, Inc 76pp, 20827.213 24X Fiche 50-000,83/10/07,8308300378
- |308300752 IE Info Notice 83-66, "Fatality at Argentine Critical |Facility " Svc list encl. | JORDAN-E L Division of Emergency Preparedness & Engineering | Response (Post 830103) | 83/10/07 | Consolidated Edison Co of New | York, Inc 79pp. 20882 026 | 24X Fiche. 50-000, 83/10/07, 8308300752
- 308300759 IE Info Notice 83-67, "Emergency Use Respirator Matl Defect Causes Production of Noxious Gases " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co of New York, Inc. 117pp. 21043-075 24X Fiche: 50-000, 83/10/11, 8308300759
- 308300761 IE Info Notice 83-68, "Respirator User Warning Defective Self-Contained Breathing Apparatus Air Cylinders " Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/10/11 Consolidated Edison Co. of New York, Inc. 120pp 20827 129 24X Fithe: 50-000, 83/10/11, 8308300761
- 310040510 Position on schedule of offsite emergency planning issues Hearings on New Hempshire rediological emergency response plans & local plans should be postponed until Mar 1984 Certificate of Box encl CASBIDY, 8 P. Federal Emergency Management Agency ISSUANCES OL. 83/09/27 27pp 20625, 216 24X Fichs 50~443, 83/09/27, 8310040510

- B310050378 Forwards NRC memo requesting FEMA Regional Assistance Committee (RAC) review of applicant transition plan by 831201 Hearings on admitted contentions may commence as scheduled on 831205.1n absence of completion of RAC review BORDENICK.B M Hearing Branch 3 ISSUANCES DL-3 B3/09/28 LAURENSON.J A , LIVINGSTON.M S , KLINE.J R Atomic Safety and Licensing Board Panel 3pp 20632 348 24X Fiche 30-322,83/09/28-8310050378
- 8310030439 Forwards EL Jordan 830915 1tr requesting Regional Assistance Committee review of util transition plan of offsite emergency preparedness Findings & determinations expected by 831201 REPKA.D A Hearing Brench 3 ISSUANCES 0L-3 83/09/28 ROSENTHAL.A S , EDLES.G J , WILBER.H A Atomic Safety and Licensing Appeal Panel 3pp 20630 360 24% Fiche 50-322.83/09/28.8310050639
- B310050348 Forwards post-exercise/post-drill assessments.per J8 Bragg B3060B commitment Previously noted deficiencies corrected MCLCROHLIN.D Federal Emergency Management Agency 83/09/29 BIRCKS, W J Office of the Executive Director for Operations 2pp 20627 267 24X Fiche 50-003,83/09/29,8310050548
- --8310050552 Post-exercise assessment of 830824-25 exercise.Rockland County.for Indian Point Nuclear Power Station * Federal Emergency Management Agency 83/09/26 56pp 20629 269 24X Fiche 50-003.83/09/29.8310050548
- --B310080334 Post-drill assessment of B30923 drill of Westchester County bus evacuation procedures for Indian Point Nuclear Power Station & Federal Emergency Management Agency B3/09/15 9pp 20629 328 24% Fiche 50-003.83/09/29.8310050348
- B310060053 Informs that based on FEMA 830811 memo & rept, deficiencies identified in 821211 emergency exercise adequately addressed or corrected during 830601 mini-exercise No enforcement actions re deficiencies will be taken MURLEY. TE Region i, Office of Director 83/09/27 RANDAZZO, J B Mains Yankee Atomic Power Co 2pp 20647 056 24% Fiche 50-309,83/09/27,8310060053
- B310110339 Responds to approval request for info collection re 10CFR90 concerning domestic licensing of production & utilization facilities Request approved through 950430 under OMB Number 3150-0011 per Paperwork Reduction Act
 BCURRY, N Office of Management & Budget OMB 3150-0011 83/10/03 8CDTT, S Document Management Branch 2pp 20713 197
- 8310110341 Responds to approval request for info collection re DDE/NRC Forms 741 & 741A for nuclear matl transaction rept & NUREO/BR-0006 Request approved through 860630 under OMB Number 3150-0003 per Paperwork Reduction Act SCURRY,N Office of Management & Budget OMB 3150-0003 83/10/03 8COTT, 9 Document Management Branch 2pp 20713 199
- 8310110343 Responds to approval request for info collection re medical license occupational ALARA program Request approved through B60531 under DHB Number 3150-0045 per Paperwork Reduction Act SCURRY.N Office of Management & Budget OMB 3150-0045 83/10/03 SCOTT.S Document Management Branch 2pp 20713 201
- 8310110346 Responds to approval request for info collection re application for medical matls license Request approved through 860930 under CMB Number 3150-0041 per Paperwork Reduction Act 8CURRY, N Office of Management & Budget CMB 3150-0041 83/10/03 8COTT.B Document Management Branch '2pp 20713 203
- B31011034B Responds to approval request for info collection re IAEA Form N-71, design info questionnaire Request approved through B6063D under OMB Number 3150-0056 per Paperwork Reduction Act
 BCURRY, N Office of Management & Budget OMB 3150-0056 83/10/03 8COTT, 8 Document Management Branch 2pp 20713 205
- 8310110349 Responds to approval request for info collection re DDE/NRC Form 740M.concise note Request approved through 860630 under OMB Number 3150-0057 per Paperwork Reduction Act SCURRY.N Diffice of Management & Budget OMB 3150-0057. 83/10/03 BCDYT.S Document Management Branch 2pp 80713 207
- 8310130077 Forwards request for DMB review & supporting statement re Btd Form 83 & supporting statements for DOE/NRC Forms 742 & 742C NORRY.P G Office of Administration 83/10/03 SCURRY,N Office of Management & Budget 1p 20777 011

- B310130305 Forwards FEMA 830929 ltr transmitting FEMA Region II post-exercise assessment of 830824 exercise of State of NY radiological emergency response interim plan for implementing compensating measures for Rockland County HASSELL, D F Hearing Branch 1 ISSUANCES SP 83/10/04 GLEASON, G P Atomic Safety and Licensing Board Panel 1p 20719 204 24X Fichs 50-247.83/10/04.8310130305
- 8310170346 Advises that util does not object to ASLB taking official notice of EPA rept. "Protective Action Evaluation Part II, Evacuation & Sheltering as Protective Actions Against Nuclear Accidents Involving Gaseous Release "Part I encl COPELAND. V G Isham, Lincoln & Beale COPELAND. V G Commonwealth Edison Co 83/10/10 SMITH. I W. COLE.R F , CALLIHAN. A D Atomic Safety and Licensing Board Panel 2pp 20786 030 24% Fiche 50-454.63/10/10.8310170346
- 8310170300 Response apposing Suffolk County 830917 motion to compet discovery re emergency planning Math not relevant but is subj to privilege Requisite showing for privilege made Unexecuted affidavit & Cortificate of Svc ancl GLASS.S M Federal Emergency Management Agency ISSUANCES QL.-3 83/10/12 Atomic Safety and Licensing Board Panel. Spp 20784 001 24X Fiche 50-322,83/10/12,8310170500
- 83i0200211 Forwards INPD evaluations on util mgt 8vc list encl BLAKE.E.L. Shaw. Pittman, Potts & Trombridge ISBUANCES SP 83/10/18 EDLES, G.J. Atomic Safety and Licensing Appeal Panel 47pp 20832 351 24X Fiche 50-000, 83/10/18,8310200211
- B310210007 Forwards request for QMB review & supporting statement re Std Form-83 & supporting statement covering NRC Form 57 reporting & recordkeeping requirements NORRY,P © Office of Administration 83/10/18 SCURRY,N Office of Management & Budget 1p 20883 344
- B310250147 Forwards std order for DDE work: "Technical Assistance Support for Region V Physical Security Insps." issued to LLL ADAMB.C Energy, Dept of FIN B-8561 83/09/16 MARTIN.J B Region 5, Office of Director 1p 20897 269
- --8310250152 8td order for DDE work: "Technical Assistance Support for Region V Physical Security Insps." issued to LLL MARTIN, J B Region 5, Office of Director MACCUSKY, J Lawrence Livermore Laboratory FIN B-8361 95-83-002 83/09/16 ip 2087 270
- 8310250391 Forwards FEMA 830928 ltr providing status of final findings of offsite preparedness State & local plans & preparedness adequate to protect public PAPERIELLO.C J Region 3. Office of Director 83/10/21 DDLAN.J E American Electric Power Service Corp 1p 20897 280 24X Fiche 50-313.83/10/21.8310250391
- --8310250401 Comments on status of offsite emergency preparedness State & local plans & preparedness adequate to protect health & safety of public Approval conditional on verification of public alerting & notification sys per NUREO-0654 MCLAUGHLIN.D Federal Emergency Management Agency 83/07/28 DIRCKS.W J Office of the Executive Director for Operations 1p 20877 281 24X Fiche 50-315,83/10/21.8310250391
- B3i0280491 Forwards final FEMA rule on review & approval of state & local radiological emergency plans & preparedness Rule effective 831028
 BORDENICK.B M Hearing Branch 3 ISSUANCES OL-3 83/10/18
 LAURENBON, J A, KLINE, J R., SHON, F, J Atomic Bafety and Licensing Board Panel. 15pp 20897 127 24X Fiche 50-322,83/10/18, 8310280491

PR PROPOSED RULE

- B3:00302B3 Package of three comments on proposed rule 10CFR50 reemergency planning & preparedness for production & utilization facilities & frequency & perticipation of exercises

 GALLAGHER, J. W Philadelphia Electric Co WHITTIER, G D Maine Yankee Atomic Power Co. SHIELDS, S W. Public Service Co of Indianalinc 48FR33307 83/09/23, CHILK, S, J Office of the Secretary of the Commission 6pp 20592 315
- 8310030300 Comments on draft Commission policy statement re engineering expertise on shift Supports policy statement.
 8TEMART, W L Virginia Electric & Power Co. 48FR3781 005
 83/09/21 Docksting & Bervices Brench ip. 2059;

- B310030311 Package of four comments on draft Commission policy statement re-engineering expertise on shift. HISENBURG.M R. Houston Lighting & Power Co. HOUGHTON, T.C. XHC. Inc. FARRAR, D.L. Communuealth Edison Co. 49FR33701 83/09/23 CHILK.S.J. Office of the Secretary of the Commission 15pp. 20591 014
- 8310030333 Comments on draft Commission policy statement re engineering expertise on shift. Opposes rule
 HARRIS. J. Affiliation Unknown 48FR33781 021 83/09/20
 Docketing & Services Branch 2pp 20590 205.
- 8310030341 Package of four comments on draft Commission policy statement re engineering expertise on shift ONNER.M W Affiliation Unknown BROCHE.D J Portland General Electric Co JONES.D W Memphis State Univ. Memphis. TN 48FR33781 83/09/26 CHILK.S J Office of the Secretary of the Commission 8pp 20390 307
- 8310030364 Package of three comments supporting proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities, frequency & participation of exercises
 KDESTER, G. L. Kansas Gas & Electric Co DALE, L. F. Mississippi Power & Light Co BRDEHL, D. J. Portland General Electric Co 48FR33307
 B3/09/26 B3/09/26 BServices Branch 5pp. 20593 004
- B310030366 Package of two comments opposing proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities frequency & participation of exercises LEH18, M I Lewis, M HIATT, S L Affiliation Unknown 83/09/26 Office of the Secretary of the Commission 2pp
- B310030376 Package of seven comments supporting draft Commission policy statement on angineering expertise on shift THORRES J R General Public Utilities GPU Service Commission MENYON, B D Pennsylvania Power & Light Co SCHUYLER, J D Pacific Gas & Electric Co 48FR33781 83/09726 CHILK, B J Office of the Secretary of the Commission 14pp 20592 352
- 831004000B Comments on interim policy or investigations & adjudicatory proceedings statement of policy Recommends insp & investigation ofce be given greater discretion or board notifications

 MNDTTS: J D Debevoise & Liberman 48FR36358 002 83/09/27
 CHILK: B J Office of the Secretary of the Commission 6pp 20608 106
- B310040030 Comments on proposed rule 10CFR50 re immediate reporting requirements for operating nuclear reactors
 BAKER K R Affiliation Unknown 46FR61894 021. 83/09/22
 CHILK,8 J Office of the Secretary of the Commission. ip
 20408 123
- B310040291 Package of three comments re draft Commission policy statement on angineering expertise on shift to combine senior reactor operator & shift technical advisor functions BAYNE, J P Power Authority of the Btate of New York MARSHALL, J R Arkensas Power & Light Co WILLIAMS, J W Atomic Industrial Forum 4BFR33781 B3709/2B. CHILK, S J Office of the Secretary of the Commission. Bpp 20614 199
- 8310040297 Package of two comments on proposed rule 10CFR50 re Frequency & participation of emergency planning & preparedness exercises CAPONE, D. W. Union Electric Co. ZIMMERMAN, S. Carolina Power & Light Co. 48FR33307 83/09/28 CHILK, S. J. Office of the Secretary of the Commission 4pp 20614 195
- 8310040307 Package of two comments supporting proposed rule 10CFR30 re emergency planning & graparedness for production & utilization facilities, frequency & participation of exercises ANDOONINI.G C Arizona Public Service Co HELFRICH, R. E Yankee Atomic Electric Co 48FR33307, 83/09/29 Docketing & Services Branch 4pp 20613-092
- 8310040334 Package of five comments on draft Commission policy statement on engineering expertise on shift.

 COUNSIL, W G , WERNER, R. P. Connecticut Yankee Atomic Power Co., GDUNSIL, W G , Northeast Nuclear Energy Co (subs of Northeast Utilities) 48FR33781. 83/09/29 CHILK, B. J. Office of the Secretary of the Commission. 13pp 20617:120
- B310050422 Comments on draft Commission policy statement re engineering expertise on shift Supports statement.
 MUSQLF, D. Northern States Power Co. 4BFR33761 031 83/09/23
 Docketing & Services Branch. ip. 20630,343

- B310050425 Comments on draft Commission policy statement re enganeering expertise on shift Opposes rule PARKYN.J D Affiliation Unknown 4BFR33781 030 83/09/23 Docketing & Services Branch ip 20630 344
- B310050431 Comments on proposed rule 10CFR50 re emergency planning & preparedness for production & utilization facilities & frequency of exercises
 COUNSIL.W G Connecticut Yankes Atomic Power Co CDUNSIL.W G

COUNSIL,W G Connecticut Yanker Atomic Power Co COUNSIL,W Northeast Oction Counsil, W Cou

- B310070146 Requests FR publication of final rule 10CFR55 re transfer of licensing authority to Region IV & V administrators Public announcement encl THDMP5DN.H L Division of Human Factors Bafety B3/09/28 FELTON,J M Division of Rules and Records 3pp 20480:331
- --8310070153 "Completion of Regionalization of Operator Licensing Function by Assignment of Function to Regions IV & V," 10CFR55 final rule Responsibility for issuing operator & senior reactor operator licenses assigned to Regions IV & V DIRCKS,W J Office of the Executive Director for Operations 83/09/21 10pp 20680 334
- 8310120255 Comments on NRC draft policy statement re engineering expertise on shift Supports establishment of alternative approach to use of shift technical advisor-housever, min goals & stds required for training courses should be limited BRADBURY, R B Stone & Webster Engineering Corp. 48FR33781 032 83/09/30 Docketing & Services Branch ip 20491 051
- B310120270 Comments on proposed rule iOCFR50 re emergency planning & preparedness for production & utilization facilities, frequency & participation of exercises COUNSIL, W 0 Connecticut Yanker Atomic Power Co COUNBIL, W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL, W 0 Northeast Utilities 3 46FR33307 074 83/09/30 Docketing & Services Branch 16pp 20693.077
- B310120275 Comments on NRC policy statement re engineering expertise on shift Recommends Commission allow individual licensees flexibility in meeting policy statement requirements FAY.C N Wisconsin Electric Power Co 48FR33781 034 83/10/07 CHILK,8 J Office of the Secretary of the Commission 2pp 20693 006,
- B310120299 Comments on proposed rule 10CFRDO re local & state govt participation in emergency preparedness exercises Opposes rule HDLT,J Public Interest Research Group, New York 48FR33307 073 83/10/01 NRC - No Detailed Affiliation Given App 20A91-310
- 8310120337 Comments on draft NRC policy statement re nuclear reactor operator degree requirements Opposes requirement that operators must obtain college credits as part of license training or retraining LABAROE, D.E. Professional Reactor Operator Society 48FR33781 033 83/10/01 CHILK.B J. Office of the Secretary of the Commission 13pp 20700 214
- B310130003 Forwards response to B30916 request for review of draft rulemating package proposing amends to IOCFR50 re emergency preparedness W/o encl.
 OLMSTEAD,W J. Regulations Division 83/10/06. BERNERO,R M Accident Source Term Program Office 1p 20725 235
- B3i0180416 Comments on draft Commission policy statement on engineering expertise on shift Requests Language of draft policy statement be amended to recognize Bachelor of Prof Studies in Nuclear Industrial Operations
 DALE.L F Mississippi Power & Light Co 48FR33781 034, 83/10/06
 Docketing & Services Branch 2pp, 20803 219.
- 8310180522 Expresses disagreement w/technical justification for

- --B310180605 Advises that encl amend to 10CFR95 re assignment of licensing responsibilities for operators & senior operators to regions will be published in FR Amend issued as final rule; effective upon publication W/o stated encls DENTON, H R Office of Nuclear Reactor Regulation, Director 48FR33243 B3709730 UDALL, M K House of Rep . Interior & Insular Affairs 1p 20817 353
- --8310180607 Advises that encl amend to iOCFR55 re assignment of licensing responsibilities for operators & senior operators to regions will be published in FR Amend issued as final rule, effective upon publication W/o stated encls DENTON.H R Office of Nuclear Reactor Regulation, Director 48FR33243 83/09/30 SIMPSON, A Senate, Environment & Public Works ip 20817 354
- 8310250331 Comments on proposed rules 10CFR40,70 % 73 re implementation of convention on physical protection of nuclear matl Opposes

HARMON,D W Braunkohle Transport & Storage, Inc. 48FR32182 001 83/10/10 Docketing & Services Branch 2pp. 20897 335

- 8310250346 Comments on proposed rules 10CFR40.70 & 73 re implementation of convention on physical protection of nuclear matl Recommends Sections 73 73(a)(1) & 73 74(a)(3) be deleted NILEGNAR Exxon Nuclear Co. Inc (subs of Exxon Corp) 48FR32182 002 83/10/12 Docketing & Services Branch 2pp 20898 075
- 8310250393 Comments on proposed rules 10CFR40.70 & 73 re implementation of convention on physical protection of nuclear matl Rules should be revised to require physical protection equivalent to Annex I & II MOWRY. W R GA Technologies. Inc /General Atomic Co 48FR32182 003 83/10/13 Docketing & Services Branch 2pp 20898 151
- 8310230448 Requests comment period be extended 2 months for proposed rule 10CFR73 re-physical protection requirements for nonpower reactor licensees possessing formula quantities of SSNM RICHARDS, W J American Nuclear Society 48FR34036 001 83/10/12 CHILK, S J Office of the Secretary of the Commission, 1p 20897 108

PRM PETITION FOR RULEMAKING

- B310030527 Comments on petition for rulemaking PRM-50-36 from Nuclear Util Backfitting & Reform Group More attention would be devoted to investigating event & completing corrective action if resident inspector becomes point-of-contact ZIMMERMAN,S R Carolina Power & Light Co 48FR28282 017 B3/09/23 CHILK,S J Docketing & Services Branch 4pp 20601 203
- PROJ PROJECTS PREDOCKET LICENSING
- 8310050197 Forwards proprietary "Westinghouse Pretendering Module 8 Integrated Control & Protection Sys " Rept withheld (ref 10CFR2 770) RAHE, E P Westinghouse Electric Corp NS-EPR-2818 83/09/23 EISENHUT, D O Division of Licensing 2pp. 20628 348
- ---8310050212 Requests proprietary classification per 10CFR2 790 for encirept, "Westinghouse Pretender Module 8 Integrated Control & Protection Bys"
 WIESEMANN, A Westinghouse Electric Corp AM-83-71 83/09/23
 EISENHUT, D & Division of Licensing 1p 20628 350
- 8310060267 Forwards proprietary "Westinghouse Advanced PWR
 Pretendering Module 9 Component Cooling Sys,"
 supplementing 821101 submittel Rept withheld (ref
 10CFR2 790)
 RAHE, E P Westinghouse Electric Corp NS-EPR-2829 83/09/30
 EISENHUT, D G Office of Nuclear Reactor Regulation, Director 2pp
 20446 151
- --8310060270 Requests "Hestinghouse Advanced PWR Pretendering Module 9 -Component Cooling Sys." be withheld per 10GFR2.790,
 WIESEMANN.R A Westinghouse Electric Corp AM-83-79 83/09/30
 EISENHUT,D G Office of Nuclear Reactor Regulation, Director 1p
 20646 153
- B3i0070136 Forwards Director's Decision 83-14. denying 830909 10CFR2 206 petition me transport of spent nuclear fuel from West Valley DAVIB. J 0 Office of Nuclear Material Safety & Bafeguards, Director DD-83-14 83/09/30 CELEREZZE, A. J. Ohio, State of 2pp 20680-308 24X Fiche 50-000, 83/09/30, 8310070156.

228

- ~-8310070161 Forwards Director's Decision 83-14.denuing 830824 10CFR2 206 signovolal forwards birector's vecision 83-14.0emying 830824 i patition re transport of spent nuclear fuel from West Valley DAVIS.J 9 Office of Nuclear Material Safety & Safeguards.Director DD-83-14 83/09/30 RESNIKOFF.M Si Club lp 20480 309 24% Fiche 50-000.83/09/30.8310070156
 - Sierra
- --8310070167 Notice of issuance of Director's Decision 83-14, denying State of CH & Sierra Club 830909 & 0824, respectively, IOCFR2 206 petitions re transport of Spent muclear fuel from West Valley DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director DD-83-14 83/07/30 2pp Fiche 90-000, 83/09/30, 8310070156 20680 310 24X
- --B310070171 Director's Decision B3-14, denying State of OH & Sierra Club B30909 & OB24, respectively, IOCFR2 206 petitions retransport of spent nuclear fuel From West Valley Request for hearing & for preparation of ETS denied DAVIS.J G Office of Nuclear Material Safety & Basely Davis December 100-82-14 B3100720 180 200480 217 2049 DAVIS.J G Office of Nuclear Material bar Bafeguards, Director DD-83-14 83/09/30 Fiche 50-000, 83/09/30, 8310070156 18pp 20480 312 24X
- B310070174 Notification of B31004 meeting w/Westinghouse in Bethesda.MD to discuss WCAP-10263 (NP) "Review Plan for Uprating Licensed Power of Advanced PWR Power Plant" MDRAN.D H Standardization & Special Projects Branch B3/09/26 THOMAS.C O Standardization & Special Projects Branch 1p 20680 291
- B310110004 Responds to FOIA request for five documents Forwards documents Documents also available in PDR FELTON, J M Division of Rules and Records B3/07/01 PEDRO, J NUS Carp 2pp 20704 137 24% Fiche 50-000, 83/07/01, 8310110004
- --B310110013 Forwards preliminary evaluation of aircraft hazards at Pebble Springs site, per 731010 request Site probably acceptable provided reasonable care taken to minimize effective target area DEYOUNG.R C Atomic Energy Commission, Directorate of Licensing 73/11/23 WILLIAMS.J L Portland General Electric Co 5pp 20704 184
- --8310110016 Informs that preapplication safety review completed based on util 730507 submittal of proposed facility design Vital areas & mods to be made prior to operation discussed DEYOUNG.R C Atomic Energy Commission, Directorate of Licensing 73/10/12 WILLIAMS.J L Portland General Electric Co 2pp 20704 189
- --B31011001B "Aircraft Considerations Preapplication Site Review"

 JN Campbell 710519 ltr to CPC encl

 A Atomic Energy Commission, Directorate of Licensing 73/10/12

 58pp 20704 191 24X Fiche 50-000.83/07/01.8310110004
- 8310130334 Forwards Rev 2 to "Topical SAR for Castor Ic Cask ISFBI (Dry Storage) "
 ROLLINS.J D Gesellschaft fuer Ruklear Service, mbH 22847
 83/09/09 Division of Fuel Cycle & Material Safety 2pp
- --8310130336 Rev 2 to "Topical SAR for Castor It Cask IBFSI (Dry Storage)" # Gesellschaft fuer Nuklear Service. mbH 22847 83/07/31 46/pp 20771 045
- 6310270051 Responds to FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR. Document withheld (ref FOIA Exemption 4) FELTON. J M Division of Rules and Records 83/07/14 PEDRO, J NUS Corp 1p 20942 016
- B310270057 FOIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Rept referenced at NRC 821130 meeting w/Westinghouse PERRO, J NVS Corp CD-18-83-021 83/06/08 Division of Rules and Records Ip 20942 017
- 8310280106 Forwards proprietary version of Westinghouse Advanced FHR RESAR SP/90 Module i, "Primary Side Bafeguards Sys Module "Rept withheld (ref 100FR2 790) RAHE, EP Westinghouse Electric Corp NS-EPR-2842 83/10/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 76pp 20078 188
- --B3102B0110 Application for withholding Westinghouse Advanced PWR REBAR SP/90. "Primary Bide Safeguards Sys Module," from public disclosure WIESEMANN.R A Westinghouse Electric Carp AH-83-93 83/10/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 99

- 8310280147 Forwards 830930 Director's Decision 83-14, denying State of OH & Sierra Club 10CFR2 206 patitions re transportation of spent fuel from Hest Valley facility.per 830930 request CUNNINGHAM.R E Division of Fuel Cycle & Material Safety DD-83-1-83/10/18 MILLER:F Environmental Policy Institute 2pp 20961 329 24X Fiche 50-000.83/10/18,8310280147 DD-83-14
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- B310030244 Final deficiency rept re offset lead-in guides on Wachter spent fuel cells Initially reported on 830318 Engineering Change Notice 4043 issued revising Wachter Assoc, Inc drauings Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 558 83/09/21. 0'REILLY.J P Region 2, Office of Director 2pp 20591 069 241 Fiche 50-390,83/09/21,8310030244
- B310030297 First interim deficiency rept re broken pin carrier plates on ERCW motors afg by Siemens-Allis Initially reported on B30B24 Vendor in process of determining max loading applied to bushings Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 558 83/09/21 0'REILLY.J P Region 2, Office of Director 2pp 20591 060 24X Fiche 50-390.83/09/21.8310030237
- 8310030373 Final & interim deficiency rept for Units 1 & 2.respectively re incorrect operation of Div I & II diesel generator load shedding & sequencing sys panels w/automatic test feature on line Initially reported 830921 Also reportable per Part 21 MCGAUGHY. J P Mississippi Power & Light Co 10CFR 050 555 83/09721 0'REILLY.J P Region 2. Office of Director 4pp 20593 083 24X Fiche 50-416.83/097/21.8310030373
- 8310030374 Second interim deficiency rept re failure of Agastat GP series relays to change state when called to operate Caused by svc aging in mild environ in combination w/mechanical configurations & tolerances of internal parts MCGAUGHY, JP Nississippi Power & Light Co 10CFR 050 55E 83/09/22 0'REILLY, JP Region 2, Office of Director 5pp 20592 190 24X Fiche 30-416.83/09/22.8310030374
- B310030462 Final deficiency rept re heat loss from Power Sys diesels Initially reported on 820729 Heat loss tests performed on B21120 & B30223 confirmed temps near safety-related equipment exceeded limits Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 55£ 83/09/23 0'REILLY.J P Region 2. Office of Director 3pp 20601 049 24) Fiche 50-370.83/09/23.8310030462
- 8310030506 Revised final deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Condition only applies to Watts Bar Keys will be replaced by 840201 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/09/22 0'REILLY.J P Region 2. Office of Director 3pp 20601 194 24% Fiche 50-000.83/09/22.8310030506
- 8310040232 Part Ri rept re plant mod implementing fire protection, including blocking vent paths from reactor bldg rooms containing high energy lines Initially reported on 830928 Six rooms require reanalysis CONN.W 9 Burns & Roe Co BROD-RO-83-013 83/07/29 Direct Office, Office of Inspection and Enforcement 2pp 20613 201 Fiche 30-397.83/09/27.8310040232
- B310040331 Part 21 rept re control circuits for safety-related valves CAC-FCV-1A & 18 powered from non-Class IS power supply Caused by failure to recognize valves have two safety-related functions; isolation & oxygen/hydrogen recombination CONN-W O Burns & Roe Co BRGO-RO-83-041 83/09/29 Director's Office, Dffice of Inspection and Enforcement 2pp 20617 118 24% Fiche 50-397,63/09/29,8310040331 29 Director's 20617 118 24X
- 8310040410 Finel deficiency rept re auxiliary feedwater sys containment isolation valves Initially reported on 830822 Sys design modified to require performance sys function of safety-grade active valves also reported per Part 21 OPREA.9 W Houston Lighting & Power Co 100FR 050 58E. 83/09/21 CQULING, J T Region 4, Office of Director 5pp 20619:035 24X Fiche 50-498.83/09/21,8310040410
- 8310050015 Final deficiency regt re valve position indication problems w/EMD gate valves Initially reported on 830203 Westinghouse equipment engineers porvided w/instructions re valve function Also reportable under Part 21 MILLSIL M Tennessee Valley Authority 10CFR 050 55E 83/09/29. 0'REILLY, J P. Region 2. Office of Director 2pp 20548-354 24% Fiche 50-390,83/09/29,8310060016

- 8310060027 Final deficiency rept re containment spray miniflow valve design error Initially reported on 820305 Mestinghouse internal design assurance & verification procedures revised Also reportable under Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/09/29 O'REILLY.J P Region 2. Office of Director 2pp 20647 091 24X Fiche 50-390,83/09/29,8310060027
- 83100&003& Third interim Deficiency Rept 77 re shop welding defects in seismic Class I cable tray, conduit & HVAC hangers Initially reported on 820802 Final rept expected by 840301 Also reportable per 10CFR2: PARSONS, R M Carolina Power & Light Co 10CFR 050 35E 83/09/27 D'REILLY, J P Region 2, Office of Director App 20647 087 24X Fiche 50-400,83/09/29,83100&003&
- 8310060221 Potential Part 21 rept re defective ITT-Grinnell hydraulic snubbers Initially reported in 830928 telcon Deficient snubber valve blocks will be remachined a snubbers rebuilt JOHNSON, B D Consumers Power Co 83/09/30 KEPPLER, J Q Region 3. Office of Director 4pp 20647 021 24X Fiche 50-255,83/09/30. 8310060221
- 8310040334 Interim deficiency rept. Item 143 re weld deficiencies in sections of ducts CC-1 & CC-2 & transformers 1D1.1D2.1E1 & IE2 from Gould & Brown-Bovers Util awaiting vendor response Also reportable per Part 21 PARSONS.R M Carolina Power & Light Co 10CFR 050 55E 83/09/27 G'RETLLY.J P Region 2. Office of Director 1p 20446 092 24% Fiche 50-400.83/09/27.8310040336
- B310040342 Final deficiency rept re steam generator lower support bolts Initially reported on B20510 Reheat treatments provide adequate strength at operating temp. sufficient fracture toughness & crack resistance Also reportable per Part 21 MILLS.L.M. Tennessee Valley Authorsky 100FR 050-55E B3/09/30 0/REILLY.J.P. Region 2. Office of Director 3pp 20644-077 24X Fiche 50-390.83/09/30.8310060342
- B310060343 Part 21 rept re Gould unitized starters supplied as spare parts Initially reported on 830923 Final rept espected 83130 DEVINCENTIB. J Yankee Atomic Electric Co DEVINCENTIB. J Public Service Co of New Hampshire SBN-368 B3/09/28 Region i, Office of Director 4pp 20646 135 24X Fiche 50-443,83/09/28,8310060343
- 8310060476 Fifth interim deficiency rept re setpoint program for overpressure mitigation sys Initially reported on 820521
 Util conducted PDRV response time tests Next rept expacted by 840103 Also reportable under Part 21
 MILLB.L M Tennessee Vailey Authority 10FR 050 556 83/09/30
 O'REILLY, J P Region 2. Office of Director 2pp 20641 017 24X
 Fiche 30-390.83/09/30.8310060476
- B310070163 Part 21 rept re potential defects in molded case of 100amp frame.multi-pole E & HE series circuit breakers Initially reported on 830902 ERHARDT.J V Gould, Inc QA15/REN/DQ 83/09/26 MURLEY.T E Region 1, Office of Director 10pp. 20639 095 24X Fichs: 50-000.83/09/26.8310070163.
- 8310070301 Potential Part 21 rept re underrange characteristic of Model N-EiiGH transmitter Underrange zero offset may occur when transmitter initially pressurized from atmospheric to suppressed zero input End users notified BERBERIAN:M J Foxboro Corp 83/09/30 Director's Office of Inspection and Enforcement lipp 20651 064 24% Fiche 50-000.83/09/30.8310070301
- B310120092 Part 21 rept re snubber failure during shock arrestor test Caused by broken capstan spring. Vendor effecting corrective action w/J Evans Co to inspect shock arrestors containing Evans springs, HADNAGY,P A Pacific Scientific B3/09/14 Region 3, Office of Director 4pp 20696-167 24X Fichs, 50-482,83/09/14,8310120092
- B310120207 Final deficiency rept re ambiguous outputs from Barton pressure transmitters in RCS Initially reported on B30409 Add1 RCS transmitters installed outside containment Also reportable per Part 21 MILLS.L M Tenness
- G310120367 Second interim deficiency rept. Items 95 & 72 & Part 21 rept re shop welding deficiencies in seismic I pipe hangers supplied by Bergen-Paterson Initially reported on 820813 & 1105 All active hangers corrected.

 1105 All active hangers corrected.
 PARSONB, R M Carolina Power & Light Co 100FR 050 55E. 83/10/03 O'REILLY, J P Region 3, Office of Director 5pp. 20699 295 24X Fiche 50-400,83/10/03.8310120367.

- B310140075 Final deficiency rept for Unit 1 & interim deficiency rept for Unit 2 re patential rupture of high pressure fuel injection lines on Div 1 & II diesel generators during engine operation Also reportable under Part 21 for Unit 1 MCGAUGHY. J P filssissippi Power & Light Co 10CFR 050 55E B3/10/05 0 (REILLY. J P Region 2. Office of Director 5pp 20768 018 24X Fiche 50-416.83/10/05.8310140075
- 8310140259 Final Deficiency Rept DER 83-45 re cable separations in control room panels Initially reported on 830707 Procedures revised to ref Const Spec 13-EM-306 for separation criteria requirements Also reportable per Part 21 VAN RRUNT.E E Artiona Public Service Co 10CFR 050 55E 83/09/26 STERNBERG.D M Region 5. Office of Director 15pp 20762 069 24X Fiche 50-528.83/09/26.8310140259
- B310140277 Second interim deficiency rept re welds on baffle plates in core support assembly mgt by B&M Initially reported on B30302 Baffle plates on former bolt locking pin welds repaired Also repartable per Part 21 MILLSL M Tennessee Valley Authority 10CFR 050 55E B3/10/05 D'REILLY,J P Region 2, Office of Director 19pp 20761 195 24X Fiche 50-436.83/10/05.8310140277
- B310170153 Interim deficiency rept re Rockwell Intl microswitch in post-LOCA hydrogen recombiners Initially reported on 830811 Final rept will be submitted by B50909 Also reported per Part 21 MANNO.8 F Niagara Mohawk Power Corp 10CFR 050 55E 83/09/01 STAROBIECKI.R Division of Project & Resident Programs 2pp 20787 114 24X Fiche 50-410.83/09/01.8310170153
- 83:0170400 Final Deficiency Rept PRD-83/15 re defective Sprague Type 40D capacitor on Brown Boveri Electric low voltage circuit breakers equipped w/solid state trip devices Initially reported on 63:1002 Also reportable per Part 21 MCGAUGHY, J P Mississippi Power & Light Co AECM-83/0666 83/10/10 0 OREILLY, J P Region 2. Office of Director 5pp 20785 080 24X Fiche 50-416,83/10/10,83:0170400
- 8310170469 Second interim Deficiency Ropt RDC 78(83) re exhaust line back pressures exceeding manufacturer recommendations on standby diesel generators for HPCS Initially reported on 830805 Further mods required Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co 10CFR 050 85E 83/10/06 KEPPLER.J 9 Region 3, Office of Director 2pp 20784 101 24X Fiche 50-440.83/10/06.8310170469
- B3101B0305 Final Deficiency Rept DR-BO re defective piston skirt castings installed in emergency diesel generator engines supplied by Transamerica Delaval Initially reported on B21124 Piston skirts replaced Also reported per Part 21 BOOKER. J E Gulf States Utilities Co 10CFR 030 55E B3/10/06 COLLINS. J T Region 4, Office of Director 2pp 20B03.096 24X Fiche 50-458.03/10/06.8310180305
- B310200165 Part 21 rept re static temp calibr check on transmitters
 Initially reported on B31013 Caused by irregular setpoint
 for pressurizer pressure safety injection function New 1.827
 psig setpoint recommended
 RAHE, E P Westinghouse Electric Corp NB-EPR-2837 B3/10/13
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 2pp 20834 078 24X Fiche 50-000.83/10/13,8310200165
- 8310210068 Final deficiency rapt for Unit 1 & third interim deficiency rapt for Unit 2 re loose mat) in steam generator Initially reported on 830325. Caused by lack of work controls Also reportable per Part 21 Next rept due by 840706
 MILLS.L.M. Tennessee Valley Authority 100FR 050 550 83/10/13
 D'REILLY.J P. Region 2. Office of Director 4pp 20857 270 24%
 Fiche 50-390.63/10/13.8310210068
- B310210115 Interim deficiency rept re calibr technique for temp compensation on Barton transmitters Westinghouse Part 21 rept described undefined errors at abnormal & accident temps Next rept in 14 days
 BMITH.W O. Indiana & Michigan Electric Co B3/10/14 KEPPLER, J G Region 3, Office of Director ip 20858 254, 24X
 Fiche: 50-315,83/10/14/8310210115
- B310210255 Part 21 rept re potential defects in molded case, 100 ampere frame, multi-pole E & HE series circuit breakers Encl suppls B30926 ltr FENNETEAU,M M Gould, Inc GA15-MMF-DG B3/10/14 MURLEY.T E Region J. Office of Director 2pp 20851 047 24X Fiche 50-458, 83/10/14, 8310210255
- B310230505 Part 21 rept re safety-related control circuits for CAC-FCV-1A & 18, being powered from non-Class IE power supply Initially reported on 830928 PED 218-E-C105 issued to provide Class IE power supplies to two valves CONN.W G Burns & Rose Co BROO-RD-83-014 83/09/29 Director's Office, Office of Inspection and Enforcement 2pp 20902 078 24) Fiche 50-397.83/09/29.8310250505

- 8310260186 Part 21 rept re potentially defective Presray mirlock seal in drywell personnel mirlock supplied by WJ Moolley Initially reported by vendor on 830919 New seal being designed by Presray Corp will be installed when available DALE.L F Mississippi Power & Light Co AECM-83/0674 83/10/24 DENTON.HR Office of Nuclear Reactor Regulation, Director 3pp 20915 250 24% Fichs 50-416.83/10/24.8310260186
- 8310270206 Fart 21 rept to engine mounted electrical cables Defective cable not installed as 830927 ltr states Parts shipped & installed on Gulf States River Bend Site (Engine Serial 74039740 DBR 48) Instruction for cable changeout due in Nov BOYER.R E Transamerica Delaval. Inc 83/10/20 Director's Office. Office of Inspection and Enforcement 19 20924 108 24% Fiche 50-000.83/10/20.8310270206
- B310270395 Interim deficiency rept re Westinghouse centrifugal charging pumps at min allowable flow rate when RCS reaches value below pressurier safety value setypoint pressure Initially reported on B00509 Also reported per Part 21 SHIELDS.S W Public Service Co of Indiana. Inc IOCFR 050 55E 83/10/20 KEPPLER.J G Region 3. Office of Director 2pp 20924 034 24X Fiche 50-546.83/10/20,8310270395
- B310270430 Final Deficiency Rept DER B3-43 re improper crimp terminations in 12 cabinets furnished by Harlo Corp Initially reported on B30708 Harlo cabinets for all units will be inspected & reworked Also reportable per Part 21 VAN BRUNT.E E Arizona Public Service Co 10CFR 050 55E B3/09/27 B1BHDP.T W Division of Resident.Reactor Project & Engineering Programs 6pp 20923 085 24X Fiche 50-528.83/09/27.8310270430
- 8310270433 Final Deficiency Rept PRD-B3/12 for Unit 1 & interim rept for Unit 2 re failure of Agastat GP series relays to switch initially reported on 830902 Deficiency reportable per Part 21 for Unit 1 Investigation ongoing for Unit 2 MCGAUGHY, J P Mississippi Power & Light Co PRD-83/12 83/10/17 D'REILLY, J P Region 2. Office of Director 5pp 20923 044 243 Fiche 50-416,63/10/17,8310270433
- 8310280065 Second interim deficiency rept re QE reactor mode switch. Initially reported on 830407 Mode switch redesigned Sample will be independently tested Also reported per Part 21 Final rept will be submitted by Dec 1983 CURTIS.N W Pennsylvania Power & Light Co 10CFR 050 33E 83/09/30 MURLEY.T E Region 1. Office of Director 6pp 20727 020 24X Fiche 50-388,83/09/30,8310280065
- 8310280093 Potential const deficiency rept re Basler Electric Coresistors installed in emergency diesel generators Initially reported on 830901 & reported by vendor under Part 21 on 830819 Final rept expected by 831130 MARTIN.TJ Public Service Electric & Gas Co of New Jersey 10CFR 050 55E 83/09/30 MRRLEY.TE Region 1. Office of Director 2pp 20935 322 24X Fiche 50-354,83/09/30,8310280093
- 8310280094 RG on 831004.i38-kV station auxiliary power supply lost when pilot wire receiver relay tripped Cause under investigation Bupply reestablished to all 6 9-kV buses Also reported per Part 21

 JACKSON.C W Consolidated Edison Co of New York, Inc. 100FR 030 35E 83/10/05 MURLEY.T E Region 1, Office of Director 1p 20935 065 24X Fiche 30-247.83/10/05.8310280094.
- 8310280130 Final deficiency rept re water hammer in essential svc water sys Initially reported on 830505 Vacuum breakers will be installed during first refueling outage Also reported par Part 21
 CURTIS.N W Pennsylvania Power & Light Go 10CFR 050 55E 83/09/22 MURLEY.T E Region 1. Office of Director 7pp 20727 254 24X Fichs 50-387.83/09/22.8310280130
- 8310280137 Interim deficiency rept re isolation of nitrogen makeup sys Also reportable per Part 21 Initially reported on 830912 Permanent design mod will be implemented Final rept will be submitted in Dec 1983 CURTIS.N W Pennsylvania Power & Light Co 10CFR 050 55E 83/10/10 MURLEY,T E Region 1. Office of Director 5pp. 20929 009 24X Fiche 50-386,83/10/10,8310280139
- B310310074 Part 21 rept re design deficiency involving combination supports for Class IE cable trays & HVAC ducts. Initially reported on B31025 Due to misclassification, supports specified w/less than full safety-related GA program MEYERS. B L Bechtel Corp BLEM-B3/249 83/10/27. DEYOUNG.R Director's Office. Office of Inspection and Enforcement 3pp. 20751 043 24% Fiche 50-000, B3/10/27, B310310074
- 8310310135 Supplemental Part 21 rept re shock arrestors w/cracked capstan spring tangs Attached customer list reflects companies which received affected arrestors List of serial numbers also encl HADNAGY.P A Pacific Scientific PT21 83-029-000 83/10/20 HAIST.D Region 5. Office of Director 94pp 20949.005.

- B310310273 Part 21 rept re defective byproduct matl, 1r-192, in Model 200-520-009 Initially reported on B31013 Caused by correded wire strands in cross-sectional areas Defective unit removed & rept requesting preventive action from supplier issued

 * Navy, Dept of B3/10/17 Region 5, Office of Director App
- B310310348 Final deficiency rept re Target Rock pressurizer PORVS failure to open Initially reported on 830922 Analyses could not identify cause for compressed rings Valves modified by vendor Also reportable per Part 21 MYLLS.L M Tennessee Valley Authority 100FR 050 55E 83/10/21 0'AELLY.J P Region 2. Office of Director 3pp 20937-074 24% Fiche 50-390.83/10/21.8310310348

GA999 GUALITY ASSURANCE INSPECTIONS

- 8308300705 Forwards QA Program Insp Rept 99700831/83-01 on 830516-18 & notices of violation & nonconformance POTAPDV9.U Region 4. Office of Director 83/08/05. PLEUNIS.B ICO Puerto Rico, Inc. 2pp 20204 308.
- --8308300712 Notice of violation from insp on 830516-18 * Region 4. Office of Director 83/08/05. 1p 20206.310
- --8308300714 Notice of nonconformante from insp on 830514-18 * Region 4, Office of Director 83/08/05 Syp 20204 311
- --8308300722 QA Program Insp Rept 9790831/83-01 on 830516-18 Noncompliance noted QA program failed to identify or describe organization functions & failed to provide measures to assure requirements included in procurement. NCNEILL: W. BARNES, 1. Region 4. Office of Director. 83/08/05 18pp 20206-316
- 8310030342 Forwards QA Program Insp Rept 99900021/83-01 on 830725-27 & notice of nonconformance POTAPOVS.U Region 4. Office of Director 83/09/16 BONES.J E Pullman Swindeli Associates, Inc. 2pp 20590 316
- --831003034B Notice of nunconformance from insp on 830725-29 * Region 4, Office of Director 83/09/16 2pp 20590:318
- --8310030332 GA Program Insp Rept 99700021/83-01 on 830725-29
 Noncompliance noted failure to perform required annual mgt
 audit of effective implementation of corporate functions at
 const sites
 NDRHAM.DE, BARNES, I Region 4. Office of Director 83/09/12
 15pp 20370 320
- 8310030377 Forwards GA Program Insp Rept 99900330/83-01 on 830801-04 & notices of violation & nonconformance POTAPDVS, U Region 4, Office of Director. 83/09/13 SAUTER, D H Westinghouse Electric Corp 3pp 20592 176
- --8310030381 Notice of violation from insp on 830801-04 * Division of Vendor & Technical Programs 83/09/13 ip. 20592 179
- --8310030383 Notice of nonconformance from insp on 830801-04 * Division of Vendor & Technical Programs. 83/07/13 2pp 20892 180
- --B310030387 QA Program Insp Rept 99700330/83-01 on 830801-04.
 Noncompliance noted outdated 10GFR21 posted & insp records
 re quality control checks on critical parts of undervoltage
 trip devices incomplete
 POTAPQUS, I Region 4, Office of Director MCNEILL, N. M Divis
 of Vendor & Technical Programs B3/09/12 Spp 20592 182

- 310030450 Notice of violation from insp on 830726-29 * Region 4. Office of Director 83/09/16 1p 20602 045
- 310030454 Notice of monconformance from insp on 830726-29
 * Region 4, Office of Director 83/09/16 ip 20602 046
- 310030457 QA Program Insp Rept 97900712/83-01 on 830726-29
 Noncompliance noted Section 206 of 1974 Energy
 Reorganization Act not posted & corrective actions for QA
 manual rev & welder monitoring & weld insp not accomplished
 ELLERSHAWL E . BARNES I Region 4, Office of Director 5:
 11pp 20602 047
- 0030464 Ack receipt of 830721 & 0912 ltrs informing NRC of steps aken to currect nonconformance noted in OA Program Insp ept 99900104/83-01 DTAPOVS.U Region 4. Office of Director 83/09/27 MILLER, T D estinghouse Electric Corp ip 20601 052
- 310030469 Responds to NRC 830822 ltr re nonconformance noted in GA Program Insp Rept 99900104/83-01 Corrective actions product & process audit reviews will be conducted Code Interpretation 3-82-17 encl MILLER.T D Westinghouse Electric Corp PA-83-074 83/09/12 POTAPOVS.U Region 4. Office of Director 2pp 20601 053

- 0040242 Forwards QA Program Insp Rept 99900271/B3-01 on 830801-05 notice of nonconformance DIAPOVS.U Region 4. Office of Director 83/09/12 KOCH.W H
- 310040246 Notice of nonconformance from insp on 830801-05 * Region 4, Office of Director 83/09/12 2pp 20613 206
- 910040249 GA Program Insp Rept 99900271/83-01 on 830801-05 Noncompliance noted:sensor stretched diagram.completed in June 1983.had wrong procedure number Internal audit log not maintained OLLER.R E , BARNES, I Region 4. Office of Director 83/09/07 12pp 20413 208
- 040343 Ack receipt of 830822 ltr informing NRC of steps taken to rrect nonconformance noted in GA Program Insp Rept 900507/83-02 TAPDV8.V Region 4. Office of Director 83/09/30 PATTERSON.R W argent & Lundy. Inc 19 20617 280
- 10040347 Responds to NRC 830722 ltr re nonconformance noted in GA Program Insp Rept 97700507/83-02 Corrective actions client audits not documented in GA coordination section meeting notes from Mar 1782 will be surveyed TAYLOR: H S Sargent & Lundy, Inc. 83/08/22 POTAPOVS, U Region 4, Office of Director 10pp 20617 281
- 040382 Ack receipt of 830802 ltr informing NRC of steps taken to rrect nonconformance noted in GA Program Insp Rept 900919/83-01 TAPOVS, U Region 4, Office of Director 83/09/30 DAVIS,A Q st-West Technology Corp ip 20620 280
- 10040383 Responds to NRC 830624 ltr re nonconformance noted in GA Program Insp Rept 99906919/83-01 Corrective actions all procurement documents for quality-related activities will be reviewed by GA manager Internal audits implemented DAVIS,TM East-Mest Technology Corp 83/08/02 POTAPOVS,U Region 4, Office of Director Spp 20620 281
- 040422 Ack receipt of 830707 & 0902 ltrs informing NRC of steps ten to correct nonconformance noted in GA Program Insp to 99900015/83-01 APDVS.U Region 4, Dêfice of Director 83/09/30 TUTTERDW.R
- 0040426 Responds to NRC 830801 ltr re nonconformance noted in GA rogram Insp Rept 97900015/83-01 Corrective actions copies of 10CFR21 posted & customer notified to verify that agnetic particle test rept received wishipment UTTEROM, R E Bowline Corp 83/09/02 POTAPOVS, U Region 4, ffice of Director 17pp 20619 138
- 0040433 Ack receipt of B30707 response to QA Program Insp Rept 9900015/B3-01,Add1 info re records retention methods & qcumentation furnished to Beldwin Assoc & B&W re heat metl reachent requested DTAPOVS.U. Region 4, Office of Director 83/08/01 UTTEROW,R.E Bowline Corp 2pp 20619,155

- ~8310040437 Responds to 830617 notice of violation contained in GA Program Insp Rept 97900015/83-01 Corrective actions GA personnel reinstructed to track exam procedure numbers TUTTEROW.RE Bowline Corp 83/07/07 POTAPOVS, U Region 4, Office of Director 10pp 20619 157
- B310040432 Forwards QA Program Insp/Investigation Rept 99900345/B2-04 * notice of nonconformance for IE Investigation Repts 99900345/B2-02 * 99900345/B2-03 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement Ex-62-132 B2/12/22 LYGNS, B P Hayward Tylor Pump Co 3pp 20624 237
- --B310040441 Notice of nonconformance from insp on 820104-0826 * Director's Office. Office of Inspection and Enforcement 82/12/22 9pp 20624 240
- ---8310040493 QA Program Insp/Investigation Rept 99900345/82-04 on 820503-0826 Noncompliance noted training records & indoctrination schedules did not meet engineering stds & correctiveactions not implemented by appropriate mgt
 MATAKES.RE A . DROMERICK.A W . PERANICH.M W . Region 4. Office of Director 82/11/12 274pp 20624 249
- 8310040485 Ack receipt of 830706 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900501/83-02 POTAPDVS,U Region 4, Office of Director 83/09/30 WAHL.H W Bechtel Corp 1p 20625 167
- --8310040488 Responds to NRC 830808 ltr re nonconformance noted in GA Program Insp Rept 99900501/83-02 Corrective actions project engineering procedures issued to incorporate mgt engineering directive revs will not be delayed in future WAHL.H W Bechtel Corp 83/09/06 POTAPOVS.U Region 4, Office of Director 2pp 20625 168
- 8310040576 Forwards QA Program Insp Rept 97900537/83-01 on 830815-18 & notices of nonconformance & violation POTAPOVS:U Region 4. Office of Director 83/09/16 GKJEI:R C John A Blume & Associates. Engineers (subs URS Corp) 2pp 20622 330
- ---8310040579 Notice of violation from insp on 830815-18 * Region 4, Office of Director 83/09/16 ip 2: 50985 335
- --B310040596 Notice of nonconformance from insp on 870\$15-18 * Region 4. Office of Director 83/09/16 ip 20628, 333
- --B310040594 GA Program Insp Rept 99900537/B3-01 on B30815-18
 Noncompliance noted contrary to 100FR21/licensee did not
 adopt appropriate procedures to provide for evaluating
 deviations or informing licensee or purchaser of deviation
 BRICKLEY,R H, HALE,C J Region 4. Office of Director
 10pp 20622 334
- 83i0130288 Confirms 9A program insp at Southwest Research Inst on 83i011-14.per 830719 telcon POTAPOVS.U Region 4. Office of Director 83/10/04 DESSEY.R L Southwest Research Institute 1p 20717 149
- 8310180142 Confirms OA program insp at Lynchburg,VA site on 831031-1104.per 830928 telcon POTAPOVS,U Region 4. Office of Director 83/10/07 DENHAM,F K Limitorque Corp 1p 20807 076
- 8310180154 Confirms QA program insp at Dak Ridge, TN plant on G31011~14, per B30919 telcon POTAPOVS.U Region 4. Office of Director 83/10/06 LORENZ, H Gilbert/Commonwealth Cos ip 20809 153
- 8310180201 Confirms QA program into at Aurora, IL plant on 831017-21, per B30920 telcon
 POTAPOVS.U Region 4, Office of Director B3/09/30 WILBON, A K
 Henry Pratt Co ip 20808 338
- 8310180216 Ack receipt of 830317,0805 & 31 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 79700276/82-01 Effective date for implementation of Item A is 83081 POTAPOVS, U Region 4, Office of Director 83/10/07 NEWMAN, 8 Ameraca Corp 2pp 20806 176
- --B310180313 Responds to NRC 830714 ltr requesting addl info re nancanformance noted in GA Program Insp Rept 99700296/82~01 Corrective actions NRC will be advised only of intended action & hold all items open until action complete MARTIN.H G Amerace Corp GA 83118 83/08/31 POTAPOVE.U Region 4, Office of Director 3pp 20806 178

- ~~B3101B0323 Ack receipt of NRC 830714 ltr requesting addl info re nonconformance noted in GA Program Insp Rept 97900296/82-01 Due to vacations, response cannot be provided until early Gept MARTIN, M 9 Americe Corp. OA 83111 83/08/05 POTAPOVS.U
 - MARTIN,M 9 Amerace Corp QA 83111 83/08/05 POTAPOVS, Region 4, Office of Director 1p 20806 181
- ---8310180332 Ack receipt of 830317 itr in response to NRC 830222 ltr re nonconformance noted in GA Program Insp Rept 97970276/82-01 Add1 info needed for Item A re description of steps taken to ensure commitments honored PDTAPOVS.U Region 4. Office of Director 83/07/14 NEWMAN.E Amerace Corp 2pp 20806 182
- --B3101B0340 Responds to NRC B30222 ltr re nonconformance noted in QA Program Insp Rept 99900294/82-01 Corrective actions Audit Procedure Q2 19 1 revised to call for check of ERN & advance ERN for signature MARTIN.M Q Amerace Corp QA B3046 B3/03/17 POTAPDVS.U Region 4, Office of Director 4pp 20806 184
- B3i0180291 Ack receipt of B30921 ltr informing NRC of steps talen to correct nonconformance noted in GA Program Insp Rept 99900532/83-01 PDTAPDVS.U Region 4. Office of Director B3/10/06 MDORE.G E Control Data Corp 1p 20806 361
- --B310180299 Responds to NRC 830824 ltr re noncenformance moted in GA Program Insp Rept 99900532/83-01 Corrective actions hotline log for previously reported PIPESD error will be modified to cross-reforence Software Problem Rept SPR PIPCO08 MODRE, G E Control Data Corp B3/09/21 POTAPOVS, U Region 4, Office of Director 3pp 20806 362
- B310180297 Confirms QA program insp at Pensacola,FL plant on B31017-21, per B30923 telcon PDTAPOVS.U Region 4, Office of Director 83/10/06 MILLER,T D Westinghouse Electric Corp ip 20806 350
- B310180312 Ack receipt of B30418 & 0812 itrs informing NRC of steps taken to correct nonconformances noted in GA Program Insp. Rept 9990904/82-02 POTAPOUS, U Region 4. Office of Director 83/09/30 MIGNOGNA, T Limitorque Corp 1p 20806 266
- --8310180314 Responds to NRC 830613 ltr re nonconformances moted in GA Program Insp Rept 99900904/82-02 Corrective actions revs made to GA manual, Section VII, Pages 2.3 & 5 Review of cited purchase orders revealed vendors in accordance w/10CFR50 MCGUILLAN, P G Limitorque Corp 83/08/12 POTAPOVS, U Region 4, Office of Director 2pp 20804 267
- --8310180318 Ack receipt of 830418 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 979009704/82-02 Addi info required re GA manual & procedures POTAPOVS, U Region 4, Office of Director 83/06/13 MIGNOGNA, F Limitorque Corp App 20806 269
- --8310180326 Responds to NRC 830225 ltr re nonconformances noted in QA Program Insp Rept 99900904/82-02 Corrective actions provisions of Part 21 inapplicable since developmental program does not impact previously supplied actuator MCGUTLLAN, P. 6 Limitorque Corp. 83/04/18 POTAPOVS, U. Region 4, Office of Director. 2pp. 20806-273
- 83i0180344 Forwards QA Program Insp Rept 99900702/83-01 on 830725-29 % notices of violation & nonconformance PDTAPOV8,U Region 4. Office of Director 83/09/30 JONES.W F Morrison-Knudsen Co . Inc 3pp 20803 020
- --8310180350 Notice of violation from insp on 830725-29 # Region 4. Office of Director 83/09/30 2pp 20803 023
- ---8310180353 Notice of nanconformance from insp on 830725-29 # Region 4, Office of Director 83/09/30 2pp 20803 025
- --8310180358 OA Program Insp Rept 99900702/83-01 on 830725-29
 Noncompliance noted rept re heat rediated concerns did not
 include date on which info obtained & number & location of
 dissel generators w/failed heat radiators not identified.
 FOSTER, W E , BARNES, I Region 4, Office of Director B3/09/24
 15pp 20803 027
- B310180360 Forwards GA Program Insp Rept 99900334/B3-01 on 830711-15 & notices of nonconformance & violation POTAPOVS, U Region 4. Office of Director B3/10/03, MATHEMS, C Transamerica Delaval, Inc. 2pp 20804 269
- --8310180365 Notice of violation from insp on 830711-15 * Region 4, Office of Director 83/10/03 1p 20804 271

- --8310180371 Notice of manconformance from insp on 830711-15 * Region 4. Office of Director 83/10/03 4pp 20804 272
- --8310180378 OA Program Insp Rept 99900334/83-01 on 830711-15 Noncompliance noted responsible officer did not notify NRC re jacket water pump shaft failures on emergency diesel generators SUTTON.J H, BARNES.I Region 4, Office of Director. 83/09/27 25pp 20804 276
- 8310180375 Ack receipt of 830708 Itr informing NRC of steps taken to correct honconformance noted in GA Program Insp Rept 93900369/83-01 POTAPDVS.U Region 4. Office of Director 83/09/30 EHRHARD.E R Automatic Switch Co ip 20803 217
- --B310180400 Responds to NRC 830818 ltr re nontonformance noted in GA Program Insp Rept 99900369/83-01 Corrective actions Procedure MP-1-051 modified by including statement that nuclear work handled under 10CFR50 inapplicable OLSEN.L. Automatic Switch Co 83/09/08 POTAPOVS.V Region 4, Office of Director Ip 20803 R18
- 8310180396 Ack receipt of 830719 % 0906 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 9990070/83-01
 POTAPDVS.U Region 4. Office of Director. 83/10/06. MILLER, J W Associated Piping & Engineering Corp (subs of Johnson Controls, Inc.) 1p 20801 122
- ---8310180401 Responds to NRC 830811 ltr re nonconformance noted in GA Program Insp Rept 9990070/83-01 Corrective actions Ebasco approved procedure for performance of actual buttering of PWHT revised Revised procedure encl URDAN.R L Associated Piping & Engineering Corp (subs of Jahnson Controls, Inc.) JORDAN.R L Johnson Controls, Inc. 83/09/06 POTAPOVS, U Region 4. Office of Director 9pp 20801 123
- --8310180404 Rev 3 to Welding Procedure Spec WP8 852-5634, "GTAW, SMAW, SAW Welding of Stainless Steel to GMAW Buttered Carbon Steel W/Heat Treat "

 « Associated Piping & Engineering Corp (subs. of Johnson Controls, Inc.) * Johnson Controls, Inc. 82/10/07 10pp 20801 132
- --8310180406 Advendum to Rev O to Welding Procedure Spec MP8 852-5634, "GTAW, SMAW, SAW Welding of Stainless Steel to GMAW Buttered Carbon Steel W/Heat Treat"

 Associated Piping & Engineering Corp (subs of Johnson Controls, Int 82/09/27 3pp 2080) 142
- --0310180407 Addendum to Rev 3 to Procedure SPPF-1002, "Heat Treatment (Carbon & Low Alloy Steel Matls P-No Groups 1,3,4 & 5 ABME Bection III " * Associated Piping & Engineering Corp (subs of Johnson Controls, Inc.) * Johnson Controls, Inc. 82/09/30 3pp. 20801 145
- --B3j0180411 Rev 3 to Procedure SPPF-1002, "Heat Treatment of Carbon & Low Ailoy Steel Matis P-No Groups 1.3.4 & 5.ASME Bection III " * Associated Piping & Engineering Corp (subs. of Johnson Controls, Inc.) 82/03/11 Spp 20801 148
- --83i0180415 Ack receipt of 830719 ltr informing NRC of steps taken to correct nonconformance noted in the Program Insp Rept 99900070/83-01 Submittal of documented evidence that dissimilar metal used procedure approved requested POTAPOVS, U. Region 4, Office of Director. 83/08/ii. HILLER, J. W. Associated Piping & Engineering Corp. (subs. of Johnson Controls, Inc.), tp. 80801-153
- 8310180429 Ack receipt of 830513 itr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 9990323/83-01
 POTAPOVS.U Region 4. Office of Director 83/09/30 ADAMS.J Conax Corp 1p 20803 294
- --B310180431 Responds to NRC 830413 ltr re nonconformances noted in GA Program Insp Rept 97900323/83-01 Corrective actions.
 Procedure IPS-1071 established for evaluation of reported deviations & nonconformance under Part 21.
 DURDURE,R L. Conox Corp. B3/05/13 POTAPOVS,U. Region 4. Office of Director 2pp 20803 295
- B310180433 Confirms OA program insp at Huntsville:AL plant on B31017-20.per B31011 telcon POTAPDVS.U Region 4, Office of Director. B3/10/13 PATEL:M C. Patel Engineers Ip 20803 279

- 83.10180441 Forwards QA Program Insp Rept 97900525/83-02 on 830802-05 % notices of nonconformance & violation POTAPOVS.U Region 4. Office of Director 83/09/20 LORENZ.H Gilbert/Commonwealth Cos 3pp 20802 126
- --8310180442 Notice of violation from insp on 830802-05 * Region 4, Office of Director 83/09/20 ip 20802 129
- ---8310180445 Notice of nonconformance from insp on 830802-05 e Region 4, Office of Director 83/09/20 1p 20802:130
- --B310180450 GA Program Insp Rept 99900525/83-02 on 830802-05 Noncompliance noted failure to rept substantial safety hazards per Part 21 HARRELL,P H. HALE.C J. Region 4. Office of Director 83/08/31 17pp 20802 131
- B310180451 Forwards QA Program Insp Rept 99900902/83-02 on 830628-070; No noncompliance nated POTAPOVB.U Region 4, Office of Director 83/09/19 HOLBROOK,W H Wyler Sales Corp 2pp 20802 090
- --B310180495 QA Program Insp Rept 99900902/B3-02 on 830628-0701 No noncompliance noted Major areas inspected evaluation of QA controls for Myle engineering development & review & approval of qualification plans & assessment repts JOHNSON, A.R., PHILLIPS, H.S. Region 4. Office of Director 83/09/14 13pp 20802-092
- 8310180476 Confirms GA program insp at Boston MA plant on 831017-20, per 830920 telcon POTAPGYS, U Region 4, Office of Director 83/10/13 BALDWIN, F B Btone & Webster Engineering Corp 1p 20801 342
- B310180515 Forwards GA Program Insp Rept 97900345/83-01 on 830825 No noncompliance noted POTAPOVS.U Region 4. Office of Director B3/09/22 PARRIN.R L Hayward Tyler Pump Co 2pp 20801 164
- --B310180519 GA Program Insp Rept 99900345/83-01 om B30825 No noncompliance noted Major areas inspected liquid penetrant exam of spare ASTM B164 Class A pump shafts returned from Comanche Peak Steam Electric Station BARNES, I Region 4. Office of Director 83/07/15 5pp 20801 166
- B310180526 Ack receipt of B30523,0719 & 0819 ltrs informing NRC of steps taken to correct violation & nonconformance noted in QA Program Insp Rept 99900311/83-01
 POTAPOVS.U Region 4. Office of Director B3/09/30 GREENE.R F General Electric Co ip 20799 t01
- --B310180527 Responds to NRC B30714 ltr re deviation & nonconformance noted in GA Program Insp Rept 99900311/83-01 Corrective actions posting requirements for 10CFR21 & Section 206 revised to indicate location of documents OREEN.R F General Electric Co 83/08/19 POTAPOVS.U Region 4. Office of Director 3pp 20799 102
- --B3101B052B Confirms 830719 telcon re extension to B30829 to respond to B30714 request for addl info re QA Program Insp Rept 9990031.

 KANTMANN.R A General Electric Co B3/07/19. PGTAPDVB.U Region 4, Office of Director Ip 20799 105
- --8310180530 Ack receipt of 830323 ltr informing NRC of steps taken to correct violation & nonconformance noted in 9A Program Insp Rept 99900311/83-01
 POTAPOVB, U Region 4, Office of Director. 83/07/14, KANTMANN,R A General Electric Co 2pp 20799 106
- --B310180532 Responds to NRC 830425 ltr re violation & noncomformance noted in GA Program Insp Rept 99900311/83-01 Corrective actions all customers notified of mod to meet requirements of AMSI 8td C37.20-1974 GREENE.R F General Electric Co 83/05/23. POTAPOVS.U Region 4. Office of Director 6pp. 20797 108.
- B310250005 Forwards GA Program Insp Rept 99900060/83-02 on 830822-26 & notice of nonconformance Description of corrective actions requested within 30 days of 1tm date POTARVB-U Region 4. Office of Director. B3/10/06 PATTARINI.D M Target Rock Corp. 2pp. 20895 259
- --B310250006 Notice of nonconformance from insp on 830822-26.
 * Region 4, Office of Director. B3/10/06 2pp. 20895:261

- --B31025000B GA Program Insp Rept 99900060/83-02 on 830822-26
 Noncompliance noted measures not established for selection & assessment of contractor (G-TEK Corp) performing vendor audit sycs.per 10CFR50.App 9
 KELLEY.W D. BARNES, I Region 4. Office of Director 83/10/04
 9pp 20895 263
- 8310250010 Ack receipt of 830916 ltr informing NRC of steps taken to correct deviation & nonconformance noted in GA Program Insp. Rept 99900338/83-01
 PDTAPDVS.U Region 4. Office of Director 83/10/20 BOLD.E R Siemans-Allis, Inc. 1p. 20894 179
- --8310250011 Responds to NRC 830819 ltr re deviation & nonconformance noted in GA Program Insp Rept 97900338/83-01 Corrective actions engineering change order form revised to include area for indication of review for Part 21 reportability BOLD. ER Siemans-Allis, Inc 83/09/16 POTAPOVS, U Region 4. Office of Director 3pp 20894 180
- 8310250104 Confirms QA program insp at Santa Ana,CA plant on 831114-18, par 831012 telcon POTAPOVS,V Region 4. Office of Director 83/10/20 HESS,L R Pacific Air Products Co 1p 20896 247
- 8310250123 Forwards QA Program Insp Rept 99900277/83-01 on 830606-10 * natices of nunconformance & violation POTAPOVS.U Region 4. Office of Director 83/09/21 REED, E S Rockbestos Co 3pp 20899 276
- --8310250127 Notice of Vialation from insp on 830606-10 * Region 4. Office of Director 83/09/21 ip 20899 279
- --8310250130 Notice of manconformance from insp on 830606-10 * Region 4. Office of Director 83/09/21 4pp 20899 280
- --8310250136 GA Program Insp Rept 99900277/83-01 on 830606-10 Violation noted safety-related testing syes procured from Isomedic, Inc w/o specifying in procurement documents that provisions of 10CFR21 applied SMITH.A L. PHILLIPS.H 9 Region 4. Office of Director 83/09/05 30pp 20897 284
- 8310250140 Ack receipt of 830919 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900787/83-01 POTAPOUS U Region 4. Office of Director 83/10/13 SANFORD, R 9 ALFAB, Inc. ip 20896 348
- --8310290148 Responds to NRC 830825 ltr re nonconformance noted in GA Program Insp Rept 99900787/83-01 Corrective actions defective matl rept issued & dispositioned to scrap conduit seismic supports Rept approved by GA manager GRANTHAM. B ALFAD, Inc. 83/09/19 Region 4, Diffice of Director 7pp 20896 349
- 8310230199 Forwards OA Program Insp Rept 99900918/83-01 on 830613-16 % notice of nonconformance POTAPOVS,U Region 4, Office of Director 83/10/07 FARWELL.C R Farwell & Hendrix, Inc. 2pp 20893 328
- --8310250201 Notice of nonconformance from insp on 830413-14 * Region 4. Office of Director 83/10/07 ip 20893 330
- --8310250206 GA Program Insp Rept 99900918/83-01 on 830613-16

 Noncompliance noted purchase orders did not contain suitable instructions that App B to 10CFR50 & 21 requirements imposed on suppliers providing safety-related equipment ADEE, J R . PHILLIPS, H B Region 4. Office of Director 83/09/26 13pp 20893;331
- B310230265 Forwards QA Program Insp Rept 99700500/B3-01 on 830808-12 to notice of nonconformance POTAPOVS.U Region 4. Office of Director 83/10/06 REINSCH.H D Bachtel Corp. 3pp 20899 152
- --8310250267 Notice of nanconformance from insp on 830808-12 * Region 4, Office of Director 83/10/06 3pp 20899 155
- --B310250270 QA Program Insp Rept 99900500/83-01 on B30808-12.
 Noncompliance noted Procurement Supplier Quality Forms
 PSQ-223s missing Instructions re implementation of problem
 investigation request sys not provided
 BREAUX, D O , HALE, C J Region 4, Office of Director 83/09/26
 Rôpp 20899, 158
- B310230272 Confirms GA program insp at Anaheim, CA plant on B31031-1104per B31012 telcon. POTAPOVB.U Region 4. Office of Director B3/10/20, HADNAGY.P A Pacific Scientific ip 20899 184

- 8310250357 Ack receipt of 830926 ltr informing NRC of steps taken to correct honconformance noted in QA Program Insp Rept 99900271/83-01 POTAPDVS.U Region 4, Office of Director 83/19/20 KDCH,W H Nosemount, Inc. 1p 20898 095
- --8310250359 Rev H-1 to Procedure 66(1) "Change Order " Supporting documentation encl Rosemount, Inc 83/09/30 21pp 20898 096
- B310250362 Ack receipt of B30616 & 0902 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 9900906/B3-01 PO\$AP0V5 U Region 4. Office of Director B3/09/23 MULNAR, J American Environments Co , Inc. 1p 20898 091
- --B310250368 Responds to NRC 830901 telcon re nonconformance noted in GA Program Insp Rept 97900906/83-01 Original 830606 transmittal of vendor purchase order & receiving design & test control procedures forwarded W/o encl VALERO, B American Environments Co . Inc 83/09/02 HUBBARD, G Region 4, Office of Director 1p 20898 092
- 8310250377 Forwards GA Program Insp Rept 99900902/83-03 on 830709-12 No noncompliance noted
 No noncompliance noted
 POTAPGVS.U Region 4, Office of Director B3/10/06 HOLDROOK.W W
 Wgle Laboratories 2pp 20898 163
- --8310250385 0A Program Insp Rept 99900902/83-03 on 830809-12 No noncompliance noted Major areas inspected evaluation of GA controls for engineering development review & approval of seismic & dynamic qualification test plans & repts JOHNSON, A. R., PHILLIPS, H.S., Region 4, Office of Director 83/09/28 10pp 20898 165
- B310250395 Ack receipt of B30923 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 9990908/83-01
 - PDTAPOVS.U Region 4. Office of Director 83/10/07 WELT.M A Process Technology. Inc. 1p 20897 282
- --B310250399 Responds to NRC 830Bil ltr re nonconformance noted in QA Program Insp Rept 99700908/83-01 Corrective actions QA manual revised to specify requirements of IQCFR50.App B BUCKLEY,R Process Technology, Inc B3/09/23 POTAPOVS.U Region 4. Office of Director 1p 20897 283
- 8310250405 Ack receipt of 830926 itr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 77900521/83~02
 - DTAPOVS, U Region 4: Office of Director 83/10/12 HINKLEMAN, L . Bechtel Corp 1p 20897 216 POTAPOVS, U
- --B31025040B Responds to NRC B30826 ltr re Nonconformance B noted in GA Program Insp Rept 99900521/83-02 Corrective actions OA review underway Extension to B31226 to submit response to Nonconformance A requested HINKLEHANL G Bechtel Corp 83/09/26 PDTAPOVS, U Region 4. Office of Director 2pp 20897 217
- OCIO250413 Ack receipt of 030415 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 97900914/83-01 POTAPOVS.U Region 4. Office of Director 83/10/12 ISON.W National Technical Systems ip 20077 238
- ---B310250420 Responds to NRC B30322 ltr re nonconformance moted in GA Program Insp Rept 99900914/83-01 Corrective actions purchase orders signed,manual revised & interim GA audit performed on BOOMELOH W.P. National Technical Systems B Region 4. Office of Director 1p. 20877 239 B3/04/15 POTAPOVS. U
- B310250432 Forwards GA Program Insp Rept 99900926/B3-01 on B30719-20 * notices of violation & nonconformance POTAPOVS, U. Region 4, Office of Director \$3/10/06 RANDALL. H W Nuclear Qualification Services 3pp 20897 184
- --- 8310250435 Notice of violation from insp on 830719-20 * Region 4, Office of Director 83/10/06 ip 2 20897 167
- --B310250441 Notice of nonconformance from insp on B30719-20 w Region 4. Office of Director B3/10/06 2pp 20897
- --B310250447 QA Program Insp Rebt 99700726/83-01 on B30719-20
 Noncompliance noted required procedures for Projects 1086,
 1134 % 1027 not developed or adopted & failure to post
 documents re mat1 regulation & Energy Reorganisation Act
 HUBBARD, G T , PHILLIPS, H S Region 4, Office of Director
 B3/09/23 11pp 20897 170

- 8310250497 Confirms GA program insp at Dakland.CA Facility on 831017-Piper B30720 telcon
 PDTAPOVS.U Region 4. Office of Director 83/10/14 BOYER.R E
 Transamerica Delaval. Inc. ip 20897 068
- 8310250503 Ack receipt of 830525 & 0808 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900722/83-01 POTAPOVS.U Region 4, Office of Director 83/10/12 JOHNSDN.I D Robert Shaw Controls Co 1p 20902 080
- --8310250510 Responds to NRC 830701 ltr re nonconformance noted in GA Program Insp Rept 99900722/83-01 Corrective actions spring & stem assemblies removed from stock, reworked to drawing configuration, inspected & replaced in stock QIESLER. J V Robert Shaw Controls Co 83/08/08 POTAPOVS, U Region 4, Office of Director 1p 20902 081
- --8310250515 Ack receipt of 830525 ltr informing NRC of steps taken to correct honconformance noted in GA Program Insp Rept 99900722/83-01 Addl info re spring & stem assemblies due in POTAPOVS.U Region 4. Office of Director 83/07/01 JOHNSON.I D Robert Shaw Controls Co 1p 20902 082
- --9310250525 Responds to NRC ltr re nonconformance moted in QA Program Insp Rept 99900722/83-01 Corrective actions dept responsible for bulletin board instructed of importance of 10CFR21 posting requirement GIESLER.J V Robert Shaw Controls Co 83/05/25 POTAPGVS,U Division of Vendor & Technical Programs 2pp 20902 083
- 8310250511 Forwards GA Program Insp Rept 99900209/83-03 on 830822-26 & notice of nonconformance POTAPOVS,U Region 4, Office of Director 83/10/06 NOREEN,H Bergen-Paterson Pipe Support Corp 2pp 20901 033
- --B310250918 Notice of nonconformance from insp on 830822-26 * Region 4, Office of Director 83/10/04 3pp 20901
- --B310250924 OA Program Insp Rept 9990209/83~03 on 630822-24 Noncompliance noted mfg Operation A checkpoint on NDE/ Fabrication record for Lot 96735 clamps not signed off & dtd & Lot 97109 clamps crossed out & not signed off OLLER R E . DARNES, I Region 4. Office of Director 83/10/03 14pp 20901 038
- 8310250532 Confirms GA program insp at Norco.CA facility on 831031-1104.per 831017 telcon POTAPOVS.U Region 4. Office of Director 83/10/19 SADLIER.R C Wyle Laboratories 1p 20702 058
- B310250537 Forwards QA Progrem Insp Rept 99900920/83-01 on B30412-15 Nc noncompliance noted PDTAPOVS.U Region 4. Office of Director B3/04/13 ARNOLD.H Westinghouse Electric Corp 2pp 20901 260
- --8310250541 QA Program Insp Rept 99900920/83-Q1 on 830412-15 No noncompliance nated Hajor areas inspected QA program product assurance manual & four supplemental procedures & compliance w/10CFR21 requirements
 JOHNSON,A R , PHILLIPS H S Region 4. Office of Director 83/06/07 17pp 20901 262
- 8310230592 Ack receipt of 830627 & 0906 ltrs informing NRC of steps taken to correct honconformance noted in GA Program Insp Rept 97900438/83-01 POTAPDYS, V Region 4. Office of Director 83/10/12 RICHARDS, D P Louis P Can
- --8310250604 Suppls 830627 response to NRC 830803 Itr re nonconforma noted in GA Program Insp Rept 99900818/83-01 Corrective actions nuclear suppl integrated into purchase order procedures as of 821201 RICHARDS,D Louis P Canuso, Inc 83/09/04 PDTAPOVS,U Region 4, Office of Director App 20900 130
- --B310250610 Ack receipt of B30627 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 97900818/83-01
 POTAPOVS.U Repion 4: Office of Director B3/08/03
 RICHARDS.D H Louis P Canuso: Inc 2pp 20900 134
- --8310250616 Responds to NRC 830602 ltr re nonconformance noted in GA Program Insp Rept 99900818/83-01 Corrective actions 10CFR21, Section 206 of Energy Reorganization Act of 1974 & Procedure O C 11 poited RICHARDS.D Louis P Canuso. Inc 83/06/27 POTAPOVS.U Region 4, Office of Director 3pp 20900 136

REGGD REGULATORY GUIDES

B310030414 Identifies specific Reg Ouide 1 97 accident monitoring equipment sys for which extension requested per B30520 & OB24 Itrs Schedules for upgrading equipment provided w/bases for extension request CLAYTON.FL Alabama Power Co B3/09/27 VARGA.S A Office of Nuclear Reactor Regulation. Director 22pp 20593 087 24X Fiche 30-348,83/09/27,8310030414

VARGA,S A Office of 20593 087 24%

3310040287 Forwards Rev 2 to 830414 response to Suppl 1 to NUREG-0737 including rept on review of Reg Guide 1 97
TUCKER:H B Duke Power Co 83/09/26 DENTON:H R Office of Nuclear Reactor Regulation, Director 91pp 20614 077 24X
Fiche 50-413.83/09/26.8310040287

I310070291 Forwards "Position Paper on Reg Guide 1 97" & "Response to NUREO-0737.5uppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities "
IIMMERMAN.S R Carolina Power & Light Co LAP-83-408 83/09/30
VASSALLO.D B Operating Reactors Branch 2 1p 20655 177 24X
Fiche 50-324.83/09/30.8310070291

-8310070293 "Position Papar on Reg Guide | 97 " BRDWN:H E Carolina Power & Light Co 83/08/09 20655 178 24X Fiche 50-324.83/09/30,8310070291 3300

-8310070295 "Response to NUREO-0737, Suppl 1 & Reg Guide 1 97 Application to Emergency Response Facilities "
BROWN.W E Carolina Power & Light Co 83/08/09
20655 211 24X Fiche 50-324.83/09/30.8310070291

310070420 Reg Quide i 85.Rev 21, "Hatls Code Case Acceptability, ASME Section III Div 1 "

#_ Office of Nuclear Regulatory Research, Director 83/09/30 lips

20674 332

| 10120175 Forwards revised Section 3 13 to FSAR Rev references util previously submitted position on Reg Guide 1 97 Rev will be incorporated in next FSAR amend CURTIS.N W Pennsylvania Power & Light Co PLA-1822 83/09/30 SCHMENCER.A Licensing Branch 2 2pp 20695 290 24X Fiche 50-388,83/09/30.8310120175

10120349 Advises that due to uncertainty in instrumentation availability & manpower resources instrumentation necessary to meet Reg Guide 1 97 requirements will be implemented by third refueling outage per Suppl 1 to NUREC-0737

JALEL F Hississippi Power & Light Co AECH-83/0652 83/10/10 26NTON-HR 0.04fice of Nuclear Reactor Regulation, Director 2pp 20700 231 24% Fiche 50-416.83/10/10.8310120349

O180468 Requests comments, refs & info to clarify Rev 2 to Reg Guide 3 & Rev 1 to Reg Guide 1 143 (Tasks SD 806-8 & 55 724-4) RUONO, L. Canada. Atomic Energy Control Board 93/10/03 locketing & Services Branch 1p 20802 030

0190343 Provides matrix showing applicability of GA program manual o Reg Guide 7 10 for shipment of reactor pressure vessel urveillance capsules.per 830920 telcon ORRIS.E B . HABRITO.B Southwest Research Institute 22875 3 ORRIS, E B , MAERITI

0240244 Agenda for CRGR Heating 4B on 831020 in Bethesda, MD to iscuss proposed exemption from CRGR review on proposed ulamaking re-codes & stds.proposed Rev 2 to Reg Guide 1 105 proposed plant operating staff degree requirements ELLO.V Committee to Review Generic Requirements 83/10/14 %TTBON.R J Director of Nuclear Reactor Regulation, Director MRDAN, EL Director's Office of Fice of Inspection and Enforcement UNNINGHAM, R E Office of Nuclear Material Safety & sfeguards, Director 2pp 20907 284

P250557 Comments on revs to proposed Reg Guide 1 82.Rev i.per 8309^0 quest Reg guide should be revised to prevent further quirements on designs which preclude air ingestion into or ocking of sunction lines used in DHR IRK.JF General Electric Co HFN-192-83 83/10/17 SPEIS.T P vision of Safety Technology 2pp 20900-314

240348 Forwards application to amend License SUA-551 reflecting front conditions or practices or to correlate w/monitoring squency per Reg Quides 8 30 & 8 31 AFF.8 J Gatty/Petrotomics Co 00633 83/09/27 GARCIA, Panium Recovery Field Office ip 20928 083

10260352 Application for amend to License SVA-351, reflecting current anditions or practices or to correlate w/monitoring trequency per Reg Guides 8 30 & 8 31 . Getty/Petrotomics Co 00633 83/09/22 11pp 20928 084

RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8310050145 "Accident Aerosol Characterization," Aug 1783 monthly OHCZARSKI,PC Battelje Memorial Institute, Pacific Northwest
Laboratory FIN B-2287 83/09/20 BERNSTEIN,S Division of Risk
Analysis 9pp 20450 228

8310050329 "Definition of Scenarios % Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC Licensed Fuel Cycle Facilities," monthly progress rept for Aug 1783 SIMAN-TOU.M Union Carbide Corp FIN 8-0495 83/09/16 BERNSTEIN: S Transportation & Materials Risk Dranch Spp. 2015 20450 225

8310070216 "Resolution of Generic Issue C-B, 'MSIV Leakage & Leak Control Sys Failure Task 2 Base Case Benchmark Calculation,'" Itr rept HURPHY.D W. ESSIG, T H Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2227 B3/09/23 RIDGELY.J Offic Nuclear Reactor Regulation, Director Spp 20679 345 Office or

8310200344 "Investigation of Ventilation Component Response to Large Pressure Pulses," monthly progress rept for Aug 1983 OREGORY, W.S. Los Alamos Scientific Laboratory FIN A-7028 83/10/03 SOLBERG.D Transportation & Materials Risk Branch 6pp 20874 063

8310280131 Guarterly rept for Jul-Sept 1783 for Contract
NRC-04-Bt-175-02 re integrated geological/geophysical study
of northern extensions of New Madrid fault zone
BRAILE, L. H. HINZE, H. J. Purdue Univ., West Lafayette, IN
KELLER, G. R. Texas, Univ. of, E.) Paso TX. NRC-04-B1-175-02
83/10/01 Office of Nuclear Regulatory Research, Director 1300 20945 089

REVIEW GRP - NRC RESEARCH REVIEW GROUPS

8310070363 Responds to 830628 ltr re Inside NRC article reporting J Tourtellatte remarks on backfitting Reassignment of J Tourtellatte due to strong views for reform not acceptable PALLADINO, N. J. Commissioners 83/09 tists ip 20664-307 83/09/13 WEISS E R Union of Concerned Scientists

--B310070369 Informs that B30516 request for reassignment of JR Tourtellotte mistakenly not sent to Commissioners Tourtellotte alleged behavior at conference clarified JR Tourtellotte B30614 response encl WEISS.E R Union of Concerned Scientists B3/06/28 PALLADINO.N . OILINSKY, V . AHEARNE.J Commissioners 26

8310240244 Agenda for CRGR Meeting 48 on 831020 in Bethesda, MD to discuss proposed exemption from CRGR review on proposed rulemating re codes & stds.proposed Rev 2 to Reg Guide 1 105 & proposed plant operating staff degree requirements

STELLD.V Committee to Review Generic Requirements 83/10/14

MATTSON.R J Diffice of Nuclear Reactor Regulation Director JORDAN.E L Director's Office of Financial Safety & Safeguards, Director 2pp 20907 284

B310270434 Designates JH Shiezek as CRGR chairman & member alternative in author absence STELLO.V Regional Operations & Generic Requirements B3/10/24 MATTSON.R Office of Nuclear Reactor Regulation. Director JURDAN.E Director's Office of finspection and Enforcement CUNNINGHAM.R Office of Nuclear Material Safety & Safeguards. Director 2pp 20923 049

POSITION PAPERS BEFORE THE COMMISSION SECY

B30B190179 SECY-B3-311
Requests approval of encl rulemaking actions re revised requirements for safeguarding power reactors DIRCKS/W J Office of the Erecutive Director for Operations B3/07/29 212pp 20716 123

B3090B0114 SECY-B3-343
Requests Commission approval of publication of final rule implementing legislation authorizing issuance of temporary OLS
DIRCKS:W J Office of the Ejecutive Director for Operations
B3/08/17 | 110pp | P0716 | 001

8310110007 Responds to FOIA request for SECY-82-279, gECY-82-330 & BECY-83-120 Forwards documents Documents also available in rum FELTON.J M Bivision of Rules and Records 83/07/15 PEDRO,J NVS Corp ip 20712-280 --8310110017 SECY-82-279
Provides info paper on current status of nuclear plant reliability data sys
DIRCMS.W J Office of the Executive Director for Operations 82/07/01 26pp 20712 281 --8208270562 SECY-82-330 EUDE/VOIOR DECYMENTIOD

RECOMMENDS approval of mods to NRC personnel security
clearance program to sharply reduce investigative costs w/o
lessening operational effectiveness
DIRCHS,W J Office of the Executive Director for Operations
BR/08/03 12pp R0712 307 --8310110022 SECY-83-120 Recommends issuance of encl proposed order directing ASLD to resume hearings as soon as possible on issue not involving informant identities
PLAINE.H H Office of the General Counsel 83/04/01 4pp 8310110436 Responds to FOIA request for RFP RS-ORM-83-500 & SECY-83-157 RS-ORM-83-500 placed in PDR SECY-83-157 partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/07/20 GR NUS Carp 2pp 20706 308 24% Fiche 50-322.63/07/20.836 GRABER I. 24X Fiche 50-322,03/07/20,8310110436 --8310110439 SECY-83-157 Requests approval of proposed order re low power license for facility PLAINC.H H Office of the General Coursel 83/05/02 4pp 24X Fiche 50-322,83/07/20,8310110436 20704 310 8310120025 SECY-83-311A 310120025 SECY-83-311A
Recommends Commission approve amends to proposed insider
safeguards rulys as set forth in Encls A.P & C of
BECY-83-311 for publication in FR
DIRCKB.W J Office of the Executive Director for Operations
83/09/15 131pp 20749 214 8310190049 Responds to FOIA request Forwards documents Documents also available in PDR FELTUN.J M Division of Rules and Records 83/09/13 DUCKLES,R NUB Corp 1p 20838 273 --8310190053 SECY-83-183 BIO170053 SECY-85-183
Informs of first integrated schedule amend for implementing new & existing requirements at operating plants Action represents first step towards developing industry-wide approach for establishing realistic schedules
DIRCKS.W J Office of the Executive Director for Operations
83/05/13 23pp 20838 274 --830722015A SECV-83-269 ADVAROLED SECY-83-269
Provides rept on fire protection rule for future plants
(SECY-82-267), summarizing licenses fire protection exemption
requests, disposition of requests & generic issues raised by
requests
DIRCKS, W. J. Office of the Executive Director for Operations ມ J Office of the Executive Director for Operations 95 ສຊາງ 20838 297 8310240263 Final response to FOIA request for three categories of records re interim storage of spent nuclear fuel at commercial power plants Forwards documents listed in app Documents also available in PDR FELTON, J M Division of Rules and Records 83/07/11 DELL, N Coalition for 8afe Power 2pp 20891 142 --R30405052A RFCV-83-112 SURVIOURS RECYMBER 12 Requests approval to publish, for public comment, proposed new 10CFR53 establishing procedures to criteria enabling NRC to determine whether adequate spent fuel storage capacity cannot reasonably be provided at individual reactor site DIRCKB, W.J. Office of the Executive Director for Operations 83/03/23 50pp 20891 175 8310250028 Responds to FOIA request for SECY-B3-030, "TMI-Related Requirements at Operating Reactors," be placed in PDR Forwards requested document Document also available in rom FELTON, J.M. Division of Rules and Records 83/07/15 BUCKLEG, R NOB Corp 1g 20916 178.

--B310250030 SECY-B3-030
Advises of NRR plan to take licensing action on TM1 action plan requirements specified in NUREO-0737 scheduled for implementation after B10630 DIRKES:4 J Office of the Executive Director for Operations B3/01/21 31pp 20916 179 8310270281 Further response to FOIA request for math re enactment of Section 13(c) of Public Law 97-415 requiring NRC to undertake pilot program to study two plants where const: GA & GC deficiencies identified Forwards EECY-83-032A FELTON, J M Division of Rules and Records 83/07/18 HAMLIN: J B Shaw, Pittman, Potts & Trowbridge 1p 20943:071 ---8310270286 SECY-83-032A SIDE/UZBO SECT-65-032A Requests info rept on status of implementation of QA initiatives identified in SECY-82-352 DIRCKB,H J Office of the Executive Director for Operations 83/04/21 16pp 20943 072 8310270360 Responds to FOIA request for SECY-82-242 & SECY-83-317
Forwards SECY-82-242 SECY-83-317 withheld (ref FOIA
Exemption 5)
FELTON, J M Division of Rules and Records 83/09/29 FEDRO, J, NUS
Corp 2pp 20743 296 --8206240098 SECY-B2-242
Requests Commission approval re mod of NRC regulations involving requirements for fracture toughness of RCPD, including surveillance of neutron radiation embrittlement of reactor vessel beltiins matl
DIRCKS,W J Defice of the Executive Director for Operations 82/06/14 39pp 20943 298 8310270369 Responds to FOIA request for BECY-83-278 & BECY-83-270, transmitting 830624 "Rept on Adequacy & Bafey of Relief Valve Testing & Performance " Forwards requested documents FELTON, J M Division of Rules and Records, 83/10/04 HEI88, E Union of Concerned Brientists 1p 20943-129 HEISSLE R --8307270430 SECY-83-278 307270430 SECV-83-278
Forwards revised certification & noncertification status tables per 830622 request Table 1 revised to clarify inspectatus of certification items for which insperviously noted as not applicable
DIRCKS.W J Diffice of the Erecutive Director for Operations.
83/07/11 43pp 20943 130 24X Fiche 50-289.83/10/04.8310270369 --8307220250 SECY-83-270 207220250 SECY-83-270
Provides summary of primary sys relief & safety valve testing & performance since TNI-2 accident per NUREQ-0737.
Item II D : DIRCKS, M J Office of the Executive Director for Operations 83/07/05. 122pg 20943 173 8310310097 Responds to FOIA request that 16 SECYs be placed in FDR Forwards App A documents SECY-82-466 withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/09/19, BHOLLY, S. C. Union of Concerned Scientists 3pp. 21000 146 -8203120050 SECY-82-077
Informs Commission of NAC progress in developing criteria & strategies re use of potassium iodide (KI) to block thyroid gland in event of accidents) release of radioiodine Validity of distribution of KI to general public questioned DIRCKS U J Office of the Executive Director for Operations 62/02/19 lipp 21000 256 --8204070171 BECY-82-121 204070171 EECY-82-121
Advises of current status of studies assessing potential technical regulatory & sociaeconomic impacts of proposed alternatives for accident water disposition

* Office of the Executive Director for Operations 82/13pp. 21000 149 24X Fiche 50-320,83/09/19,8310310097 --8304220088 BECY-83-126 SUMERVOURD DELY-MINIZO
Requests approval for publication of proposed rule ensuring that certain contractors & subcontractors of 10CFR50 licensees post NRC Form 3 DIRCKS, M. Office of the Executive Director for Operations 83/04/06 4pp 21000 162 JIO310116 SECY-B2-141A
Informs of historical & current rates of license issuance & exam failures for reactor & senior reactor operators
Bupporting data encl failure rates of 27% & 25% for reactor operator & senior reactor operator. Pespectively noted
DIRCKS.W J Office of the Executive Director for Operations.
B3/08/23 3pp 21000 166 --6310310116 SECY-82-141A

---8205050588 SECY-82-148
Informs of revision of iOCFR20, stds for protection against radiation, & efforts to ascertain adverse technical & economic impacts on NRC & licensee of revised regulation Comparison of iOCFR20 salism tissues wellternatives encl DIRCKS, W J Office of the Elecutive Director for Operations 82/04/21 8pp 21000 169

--8204100323 SECY-82-221 Forwards study re NRC role in contested nuclear power reactor initial licensing proceedings Study concludes that different "neutral" NRC role should be adopted on trial basis in selected cases SICKWIT.L. Diffice of the General Counsel 82/06/03 68pp 21000 177

-9206300342 SECY-82-243 Informs Commission of status of NRC activities re development of improved safeguards info sys DIRCKEN J Office of the Executive Director for Operations B2/06/10 3pp 21000 245

-8206250316 SECY-82-251
Provides Commission w/rept re property insurance for decontamination of nuclear reactors as published in NUREG-0891 NUREC-0891 DIRCKS.W J Office of the Executive Director for Operations 82/06/16 App 21000 248

--B211290108 BECY-82-460 Informs Commission of historical & current rates of license issuance & axam failures for reactor operators & senior Prescript operators

DIRCKS, W.J. Office of the Executive Director for Operations
89/11/17 4pp 21000 252

---8310310131 SECY-82-483
Informs of present status of TMI-1 restart certification effort & provides update on KAREO-0737 items status DIRCKS.W J. Office of the Executive Director for Operations 82/12/09 16pp 21000 260 24X Fiche 50-289,83/09/19,831031009/

-8310310136 SECY-83-072 Informs of historical & current rates of license issuance & exam failures for reactor operators & senior reactor operator Pass/fail rate remained consistent throughout Third Quarter FV82
DIRCKS.W J Office of the Executive Director for Operations 83/02/18 4pp 21000 292.

--8310310140 SECY-83-093 SIGNOIST SECTOR OF STATE OF ST

STATE PROD STATE PROGRAMS

8310070271 Forwards responses to 830726 ltr requesting add1 info to amplify 830225 technical observation re state radiation control program & personnel staffing SOLON, L. R. New York, State of 83/09/14 ALLAN, J.M. Region 1, Office of Director 3pp. 20456-357

8310070320 NUREO/CR-3487 3300/0320 NORG/CR-3487
REGIONAL-INTERSTATE SITE REVIEW PROCEDURE LOW-LEVEL
RADIOACTIVE HABTE DISPOSAL FACILITY

Southern States Energy Board FIN 8-50206 83/09/30, Diof Health, Siting & Waste Management 123pp Available at NRC
\$5 00. 20679-113

8310110612 Requests appointment of state liaison officer to NRC Appointee will be invited to natl/state liaison officer 831206-07 methings in Mashington. DC PALLADINO, N J Commissioners 83/09/22 HUNT, J B North Cerolina. 8tate of 1p 20703 359

--B310110615 Notification of natl state limits on officer B31206-07 meetings in Washington, DC Agenda encl. KERR, G W. Office of Btate Programs, Director B3/09/16 of State Programs, Director 3pp 20703 360

8310130380 Notification of contract execution.Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of NY UMBEL, D M Technical Assistance Contracts Branch FIN B-8355 NRC-28-83-610 83/09/29 MCUSCAR.J Region 1. Office of Director COSTELLO,F NRC - No Detailed Affiliation Given ip 20770 118

--B310130385 Med 1.adding funds to incorporate TLD program to "Radiation Monstoring Program Requirements"

LEAVY.W F New York, State of GUSTAVE.R P Technical Assistan P Contracts Branch FIN 8-8355 NRC-28-83-610 83/09/29 1p 20770 119

8310170704 Requests new state liaison officer to NRC be appointed Nat. state liaison meeting will be held on 831206-07 in Washington DC PALLADIMO.N J Commissioners 83/09/29 ROCKEFFLLER, J West Virginia, State of 1p 20798 150

B310200179 Forwards NRC evaluation of NY State Dept of Environ Conservation radiation control program for period 820305-830510 MURLEY.T E Region 1. Office of Director 83/09/04 MERGES.P Nov. York, State of 1p 20835 079

--8310200181 Rept of NRC evaluation of NY State Dopt of Environ Conservation radiation control program for period 820305 --830510 MURLEY, T.E. Region 1. Office of Director 83/06/28 50pp

8310250116 Ack receipt of 830914 response to comments & recommendations following review of radiation control program Training & technical assistance plan details for NY Dept of Environ Conservation radiation control program encl MURLEY, T E Region 1, Office of Director 83/10/19 WILLIAMS, H Q New York, State of 5pp 20894 065

--8310250119 Discusses NRC B30628 evaluation of radiation control program Problems associated w/program being evaluated under agreement state program options Accepts 830628 offer to provide dept w/technical assistance
WILLIAMS,H G New York, State of B3/09/14 MURLEY,T F Region 1, Office of Director 2pp 20894 070

8310260318 Responds to questions in 830930 ltr re NRC regulatory program for U milling Applicable manual chapters and NUSBBAUMER, D.A. Assistant Director for State Agreements Programs 83/10/11 SPAIN.M Virginia, Commonwealth of, 31pp 20918 30

8310280103 Forwards 830913 ltr from State of NV responding to MRC #30822 ltr on RADMAN code
NUSSBAUMER.D A Assistant Director for State Agreements Programs
83/09/21 HIGGINSOTHAM.L Low Level Wasta Licensing Branch 2p
20941 358

---B310280107 Responds to NRC B30822 ltr re RADMAN computer code No objections raised to use of code by persons licensed to dispose of radwaste at Beatty site VADEN.J Nevada, State of B3/09/13 NUBBBAUMER.D A Assist Director for State Agreements Programs 1p 20761 359

8310310271 Forwards technical comments & recommendations on NH Dapt of Welfare radiological health program, per 830827-0702 review & evaluation Prioritization of steps under consideration tp improve program recommended MURLEY,TE Region 1, Office of Director New Hampshire, State of Spp 20947 127 83/10/24 WALLAGE, W.T.

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8310030203 Forwards "Rept of Engineering Assessment, Present Pond Line: Sys Tailings Impoundment, Sweetwater U Project, Near Rawlins, WY for Minerals Exploration Co" & "Tailings Impoundment Leek Analysis" KLEIN.T J Union 76 Minerals Exploration Co 00585 83/0 BMITH.R D Uranium Recovery Field Office 2pp 20603 078 83/09/07

--8310030210 "Rept of Engineering Assessment, Present Pond Liner Sys Tailings Impoundment, Sweetwater U Project Near Rawlins, WY for Minerals Exploration Co " BODDY, J.R. Union 76 Minerals Exploration Co 00586 83/07/29 19pp 20603,080

B310030303 Forwards Rev 1 to BAW-1762, "Auxiliary Feedwater Bys Reliability Study for WPPSS Unit 1." in response to NUREQ-0737. Item II E 1 1 SDRENSEN.O C Hashington Public Power Supply System QL-82-83/09/23 ADENSAM.E Q Licensing Branch 4 1p 20593:181 Fichs 50-460.83/09/23.8310030303

 $|x| = \frac{1}{4} |x| = \left(\frac{1}{2} |x| + \frac{1}{4}\right)$

0030306 BAW-1762 RO1 ev 1 to "Auriliary Feedwater Sys Reliability Study of UPPSS

"H. 1 " Babcock & Wilcox Co GL-82-14 B3/06/30 41pp 20593 163 4X Fiche 50-460, B3/09/23, B310030303

30353 Forwards B&W Owners Group final rept, "Bounding Analytical essment of NUREG-0630 Models on LOCA kW/ft Limits W/Use FLECSET" Approval requested SHALL.JR Arkansas Power & Light Co 1CAN098310 83/09/23 LZ.JF Operating Reactors Branch 4 1p 20592 200 24% he 50-313.83/09/23 8310030353

0030354 77-1140999-01 DOUGLISS //-I-140894-01 Bounding Analytical Assessment of NUREO-0630 Models on DCA kW/Ft Limits W/Use of FLECGET " Babcock & Wilcox Operating Plants Owners Group 83/0' OBpp 20592 201 24X Fiche 50-313.83/09/23,8310030353

83/09/30

30620 Advises that encl B&W rept. "Response to GPU Nuclear stions Concerning HPI Actuation at TMI-2 About 5 41 AM 790328," completed assessment of EDS Nuclear analysis t provided to util on 830909 & to NRC on 830915 NBS.W J DFfice of the Executive Director for Operations 39/26 PALLADIND. N Commissioners 3pp 20626 351 24X to 50-289.83/09/26,8310030620

30.550 Forwards info requested at 830.824 presentation reformance of teams using crack-tip diffraction method More will be available at intergranular stress corresion king 830.707-09 workshop G J Electric Power Research Institute 83.09/07 ADINO,N J Commissioners 4pp 20607 356

10026 Affidavit supporting withholding of Mark I Containment Iram document. "Response Factors Appropriate for Use W/CO unic Response Combination Design Rules " WDQD, 60 General Electric Co 83/0//29 3pp 20608 119 214 to 50-219.83/07/29,8310040026

0301 Forwards B&W "Bounding Analytical Assessment of NUREQ-0430 is on LOCA kW/Ft Limits W/Use of FLECSET," completing onse to NUREQ-0630 Compensating models documented trification for model use provided AFER, G R Florida Power Corp 3F-0963-20 63/09/29 Z.J F Operating Reactors Branch 4 2pp 20612 227 24X a 50-302,83/09/29,8310040301

040304 77~1140898-01 Ording // 1140040-01 on LOCA /Ft Limits W/Use of FLECSET " Babcock & Wilcox Co. 83/09/30 109pp 20612 229 24% che 50-302,83/09/29.8310040301

0353 Forwards "Pressurizer Relief Valve Qualification," & Rev 1 Pressurizer Safety Valve Operability Rept." per 0-0737. Item II D 1 Design load stresses on piping & inps within allowable limits VALL, A E Daltimore Gas & Electric Co 83/09/28 MILLER, J R ating Reactors Branch 3 4pp 20615 036 24X e 50-317.83/09/28.8310040353

D40355 "Pressurizer Relief Valve Discharge Piping Qualification pt on Task 05088 ITH.J V , VENTURA.J C Bechtel Corp B3/09/2: 515 040 24X Fiche 50-317.83/09/28.8310040353 83/09/23

040357 CEN-248(B) R01 7 I to "Pressurizer Safety Valve Operability Rept Combustion Engineering. Inc. 83/09/30 100pp the 50-317.83/09/28.8310040353 20615 194 24x

3363 Forwards response to MRC B30601 SER re Westinghouse Owners a emergency response guidelines per Buppl I to 3-0737

)-0737 'ARD,J J Hestinghouse Operating Plants Owners Group 'ARD,J J Carolina Power & Light Co 00-105 83/07 HUT.D G Division of Licensing 42pp 20620 235

)415 Forwards "Implementation of NUREO-0619 Feedwater Nossle .ing." & proprietary "Peach Bottom Atomic Power Station. 2. Feedwater Nossle Fracture Michanics Analysis to Show Proprietary rept withheld (ref 10CFR 279)

10HER. J. W. Philadelphia Electric Co. 83/09/29 EISENHUT. D. G. .ion of Licensing 2pp 20623 303 24X Fiche 50-277.83/09/29

183 Forwards proprietary rev to NEDE-24011-P-A-A, "OE Std cation for Reactor Fuel," documenting expanded approach ability Affidavit encl Rev withheld (ref 100FR2 770)
LEV. J S General Electric Co MFN-183-83 83/09/30
S.C D Standardization & Special Projects Branch App

- 8310090)97 Forwards proprietary "Westinghouse Pretendering Module 8 Integrated Control & Protection Sys " Rept withheld (ref 100FR2 790) THE TOURSE 7903 RANG, E.P. Westinghouse Electric Corp. NS-EPR-2018 EISENHUT, D.G. Division of Licensing. 2pp. 20428 3 83/09/23
- --Li310050212 Requests proprietary classification per 10CFR2 790 for encl rept, "Westinghouse Pretender Module 8 Integrated Control & Protection Sys " WESSEMANN, R A Westinghouse Electric Corp AW-83-71 83/09/23 EISENHUT
- 8310050346 Forwards "RODEX2 Temp Prediction Conservatism," in response to NRC request for add1 info Info withheld (ref 10CFR2 790) CDPELAND,R A Exxon Nuclear Co. Inc (subs of Exxon Corp.) RAC 066 83 83/10/03 THOMAS.C O Standardization & Special Projects Branch 1p 20632 343
- B310090400 Forwards requested info for use in determining fee to be assessed for review of XN-NF-7B-44(NP). "Generic Analysis of Control Rod Ejection Transient for PMR"
 THOMAS, C O Standardiration & Special Projects Branch 83/09/21
 BERKOW. H N Management Analysis Branch 2pp 20640 359
- 8310050463 Forwards application to amend License DPR~20, modifying basis for limiting safety sys settings for reactor protection sys VANDEWALLE.D.J. Consumers Power Co. 83/09/29 CRUTCHFIELD.D. Operating Reactors Branch 5 ip 20630 055 24X Fiche 50-255.83/09/29.8310050463
- ~~B310050470 XN-NF-83-57 "Rod Withdrawal Transient Reanalysis for Palisades Reactor" FRYER,B C . CHANDLER.J C . KAYSER.W V Exxon Nuclear Co . Inc (subs of Exxon Corp) 83/08/26 57pp 20630 064 24X Fiche 50-255.83/09/29.8310050463
- 8310060267 Forwards proprietary "Westinghouse Advanced PHR
 Pretendering Module 9 Component Cooling Sys."
 supplementing 821101 submittal Rept withheld (ref
 10CFR2 790)
 RAMELE P Westinghouse Electric Corp NB-EPR-2829 83/09/30
 EISCHHUT, D 0 Office of Nuclear Reactor Regulation, Director 2pp
- --8310060270 Requests "Westinghouse Advanced PMR Pretendering Module 9 -Companent Cooling Sys." be withheld per 10CFR2 790 HIESEMANN.R A Westinghouse Electric Corp AM-83-79 83/09/30 EISEMHUT.D G Office of Nuclear Reactor Regulation. Director ip
- B310070104 Forwards evaluation accepting XN-NF-78-44 (NP) "Generic Analysis of Control Rod Ejection Transient for PWR," for referencing in license applications Requests nonpropriatary version within 3 months of receipt of itr THOMAS.C.O. Standardization & Special Projects Branch B3/09/21 CHANDLER.J.C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 1
- --8310070112 Evaluation accepting XN-NF-78-44 (NP) "Generic Analysis of Control Rod Ejection Transisht for PWR," for referencing in license applications * NRC -- No Detailed Affiliation Given 83/09/21 App 20681 002
- B310070174 Notification of B31004 meeting w/Hestinghouse in Bethesda. MD to discuss WCAP-10263 (NP) "Review Plan for Uprating Licensed Power of Advanced PWA Power Plant"
 MORAN-D H Standardization & Special Projects Branch 83/09/26
 THOMAS.C O Standardization & Special Projects Branch Ip
- 8310070260 Forwards proprietary XN-NF-691 (P). "Stability Evaluation of BWR Cores " Rept withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co. Inc (subs of Exxon Corp) 83/09/30 THOMAS.C O Standardization & Special Projects Branch 1p 20654 329
- B310070264 Forwards proprietary "Dresden 2/3 Nuclear Generating Plant Suppression Pool Temp Responses" "EI Hatch Nuclear Power Station Units 1 & 2 Suppression Pool Temp Response" & Mark I 830825 meeting viewgraphs Repts withheld (ref 10CFR2 770) PFEFFERIEN.H C General Electric Co MFN-180-B3 83/09/30 VASSALLO.D B Operating Reactors Branch 2 61pp 20811 292 244 Fichs 50-000.83/09/30.8310070264
- 8310070281 Forwards proprietary "Compliance of GE BWR Fuel Designs to Stability Licensing Criteria Response to Stability Action Item From NRC re Single Loop Operation " W/affidavit Rept withheld PFEFFERLEN.H C General Electric Co MFN-181-83 83/09/30 THOMAB.C O Standardization & Special Projects Branch 5pp 20657 065

- 8310070310 Forwards proprietary "Compliance of GE BHR Fuel Designs to Stability Licensing Criteria-Stability ," supporting amend to GE Ltr NEDE-24011 Affidavit encl Rept withheld PFEFFERLENH C General Electric Co MFN-182-83 83/09/30 TMOMAS, C D Standardization & Special Projects Branch 3pp 20432 219
- 8310070344 Act receipt of 830807 ltr transmitting rept of retrofit plan for Beznau Nuclear Plant Rept should be treated as commercial privileged info & encl W/o encl KRIEOER,R W Southern California Edison Co 83/07/28 CRU
- B310070359 Discusses progress of life testing at Myle Labs for builing water version of actuator referenced in Rept GtW-FSD 2938, expected in Oct 1983 Test exceeded full vibration loading expected in 40-yr plant life before mechanical failure MEISZ.D A. Gulf & Mestern Industries, Inc. FDS 83-233 83/09/28 THOMAS.C D. Standardization & Special Projects Branch 2pp 20651 093
- B310110142 Forwards proprietary Westinghouse responses to NRC Request 1 for add1 info on WCAP-10271. "Evaluation of Surveillance Frequencies " & proprietary Suppl 1 to "Evaluation of Burveillance " Encls withheld (ref 10CFR2 790) Westinghouse Operating Plants Owners Group SHEPPARD. J J Carolina Power & Light Co 00-106 83/10/04 THOMAS.C I Standardization & Special Projects Branch 2pp 20048 074
- --B3101101A9 Authorizes use of Affidavit CAM-B3-67 re withholding of proprietary responses to NRC Request 1 for add1 info on 83072B WCAP-10271 & Suppl 1 to "Evaluation of Surveillance Frequencies & Out of Svc Times for Reactor Protection "WIESEMANN.R.A Westinghouse Electric Corp CAM-83-67 83/09/13 THOMAS.C O Btandardization & Special Projects Branch 1p 20649 078 CAW-83-67 83/09/13
- B310110503 Responds to FOIA request for BWR Owners Group control room survey program Requested info placed in LPDR FELTON, J M Division of Rules and Records B3/07/08 WILLIAMS, 0 G Affiliation Unknown ip 2070B 002
- --8310110511 "BWR Owners Group Control Room Improvements Committee Human Factors Engineering Control Room Survey " PANKRATZ.D R , ROSS.K C . MULLEE.G R BWR Owners Group 81/01/19 88pp 20708 007
- --8310110513 "BWR Owners Group Control Room Design Review Program. Development & Methodology " * General Electric Co 81/08/01 26pp 20708 096
- -8310110318 "BWR Owners Group Control Room Burvey Workshop, Human Factors Engineering," w/suppls & viewgraphs + BWR Owners Group 83/08/01 310pp 20708 121

- 3310120312 Forwards technical rept "Mark I Containment Program Plant-Unique Analysis Rept of Torus Attached Piping for Vermont Yankse Nuclear Power Plant " SINCLAIR, J B Vermont Yankse Nuclear Power Corp FVY 83-108 83/10/06 VASSALLO, D B Operating Reactors Branch 2 1p 20497 255 24X Fiche 50-271,83/10/06,8310120312
- --83i0120315 TR-5319-2
 "Mark I Containment Program Plant-Unique Analysis Rept of Torus Attached Piping for Vermont Yankee Nuclear Power Plant " * Teledyne Engineering Services 83/10/03 95pp 20697 256 24X Fiche 50-271,83/10/06,8310120312
- 8310120324 Advises that Ray Miller, Inc Purchase Orders 63023 & 51810 were for items used at Mt Storm Fossil Power Station & util was end user Items were not sold to any other company or individual BROWN C A Virginia Electric & Power Co 83/10/03 DE Director's Office, Office of Inspection and Enforcement 20700 314 83/10/03 DEYOUNG, R C
- B310120407 Forwards nonproprietary rept & Suppl 1 to "HB Robinson Unit 2.Cycle 10 SAR " Also forwards proprietary "ECCS & Plant Transient Analyses " & "Mechanical Design Rept " Repts withheld (ref 10CFR2 790)

 UTLEY, E E Carolina Power & Light Co LAP-83-446 83/10/05 VARQA, S O Dyerating Reactors Branch 1 14pp 20497 176 24X Fiche, 50-241,83/10/05,8310120407.
- --8310120415 XN-NF-83-72 SIGNED TO A THE ROBINSON Unit 2.Cycle 10 SAR "
 Nonproprietary "HB Robinson Unit 2.Cycle 10 SAR "
 STONE.I.Z ADAMS.F T , LAMBERTAW L Exzon Nuclear Co , I
 (subs of Exxon Corp) 83/09/01 39pp 20497 188 24X
 Fiche 50-261.83/10/05.8310120407 Inc

- --83i0120422 XN-NF-83-72 501 Nonproprietary Suppl 1 to "HB Robinson Unit 2.Cycle 10 SAR" STONE.I 2 . ADAMS.F T . LAMBERT.W L Exton Nuclear Co . Inc (subs of Exton Corp) 83/09/14 28pp 20697 227 24X Fiche 50-261.83/10/05.8310120407
- B310130097 Forwards nonproprietary & proprietary responses to B30802 telcon request for add1 info re proposed Tech Spec change concerning in-core detectors Affidavit ent1 Proprietary rept withheld (ref 10CFR2 790) GRIFFIN.J M Arkansas Power & Light Co 2CAN098311 B3/09/30 MILLER.J R Operating Reactors Branch 3 10pp 20/25 277 24X Fiche 50-368.83/09/30,8310130097
- --8310130109 CEN-255(A)-NP
 Nonproprietary "Responses to NRC Questions re Arkansas
 Nuclear Unit 2 Cycle 3 Tech Spec Change " Proprietary info
 deleted (ref 10CFR2 790)

 * Combustion Engineering, Inc 83/08/31 5pp 20725 287
 Fiche 50-368,83/09/30,8310130097
- B310140143 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept Vol 1 Mark BZ Fuel Assembly Design Rept." in support of Cycle 9 reload planned for late 1984 Rept withheld (ref 100FR2 790)
 TUCKER, H B Duke Power Co B3/10/07 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reacto s Branch 4 2pp 20766 067 24X Fiche 50-000, 83/10/07, 8310140143
- --B310140145 Forwards proprietary "Rancho Seco Cycle 7 Reload Rept -Vol 1 Mark DZ Fuel Assembly Design Rept," Apr 1983 Affidavit supporting determination of proprietary nature of rept encl TAYLOR, J H Babtock & Wiltox Co B: Nuclear Reactor Regulation, Director Fiche 50-000,83/10/07,8310140143 83/09/13 MINER, S Office of or 8pp 20766-069 24X
- 8310140152 Notifies of B&W Owners Group ATWS Committee 830826 meeting in Bathesda, MD re conceptual designs for diverse scram sys & proposed reactor trip breaker liability monitoring program to address Generic Ltr 83-20 ENDS, J T Babcock & Wilcox Operating Plants Owners Group ENOS. J . Arkansas Power & Light Co OLC-103-03 83/10/05 EISENHUT. D G Division of Licensing 1p 20765 046
- 8310140163 Forwards Rev 2 to "QA for American Inst of Steel Const Nuclear Guality Certification Program," per Region IV 830902 ltr of approval Revised pages sent to holders of controlled SEHEK, C. American Institute of Steel Construction, Inc. NRC - No Detailed Affiliation Given. 2pp. 20745 008 83/10/11
- --8310140165 Advises that proposed Rev 2 to "QA for American Inst of Steel Const Nuclear Quality Certification Program," meets 10CFR30,App B criteria & 1s acceptable PDTAPDVS,U Region 4, Office of Director 83/09/02 PESHEK.C American Institute of Steel Construction. Inc. 2pp 20765 010 83/09/02 PESHEK.C
- --B310140174 FCTPN-7B

 Rev 2 to "QA for American Inst of Steel Const Nuclear
 Quality Certification Program"
 PEBHEK,C American Institute of Steel Construction, Inc
 B3/09/16 15pp 20765 012
- B310140227 Porwards nonproprietary response to B30923 request for additinfo on WCAP-8720.Addendum 2, "Revised PAD Code Thermal Safety Model" (proprietary) & WCAP-8785 (nonproprietary) RAHE,E P Westinghouse Electric Corp NS-EPR-2822 B3/09/30 THOMAS.C D Standardization & Special Projects Dranch 3pp
- B310140239 Forwards honproprietary & proprietary approved versions of Vol 4 of "Exxon Nuclear Co (ENC) Methodology for BMRs Application of ENC Methodology to BMR Reloads " Proprietary version withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp) JCC 091 B3 B309730 THOMAS, C, D Standardization & Special Projects Branch 1p 20759 240
- --8310140244 XN-NF-80-19(NP)(A)V4 STOCKYPETT, ANT-NET-19(NP)(A)V4

 Nonproprietary approved version of Vol 4 of "Exxon Nuclear Co (ENC) Methodology for BHRs Application of ENC Methodology to BHR Reloads "
 CHANDLER, C, OHSLEY, OF, STOUT, R B Exxon Nuclear Co | Inc (subs of Exxon Corp) B3/09/14 58pp 20759 241
- 8310170091 Forwards repts on 821209 main generator failure & proprietary & nonproprietary repts on seven main transformer failures occurring between 801129 & 821209 Proprietary rept withheld (ref 100FR2 790)
 STEWART.W.L. Virginia Electric & Power Co. 482 83/10/05 DENTON.H R. Office of Nuclear Reactor Regulation, Director MILLER, J. R. Operating Reactors Branch 3 2pp 20797 Fiche 50-338,83/10/05,8310170091

- --B310170107 Nonproprietary version of "Transformer Rept on Events at North Anna Power Station" "COSSAART.J., PETRIE.E., SKODGLUND.J. Westinghouse Electric Corp. B3706/16 276pp 20789 226 24X Fiche 50-338.83/10/05, B310170091
- 8310170190 Forwards Rev F to GA program manual Historical document containing all changes to GA manual since first edition issued in Aug 1973 encl COUNSIL.W G Northeast Utilities Service Co COUNSIL.W G Northeast Utilities B10911 83/09/30 MURLEY.T E Region 1. Office of Director 2pp 20787 116 24X Fiche 50-423.83/09/30.8310170190
- --8310170198 Rev F to GA program manual KELLY.R B . ALLEN.W F . SMIYH L S Stone & Webster Engineering Corp 81/04/06 589pp 20787 118 24X Fiche 50-423.83/09/30. 8310170190
- B310170540 Forwards Rev 1 to Vol 3 to "GESTR-LOCA & SAFER Models for Evaluation of LOCA" Encl withheld (ref LOCFR2 790) GUTRN, J F General Electric Co MFN-187-83 83/10/06 THOMAS, C 9 Standardization & Special Projects Branch 5pp 20782 183
- B310180370 Approves request for withholding CEN-181-P generic responses re inadequate core cooling per TMI I tem II F 2 from public disclosure (ref 10CFR2 790)
 CRUTCHFIELD,D Decrating Reactors Branch 5 LS05-83-10-033
 B3/10/II SCHERER,A E Combustion Engineering, Inc. 4pp
 20827 010
- 83i0180379 Approves request for withholding listed proprietary info re inadequate core cooling per TMI Item II F 2 from public disclosure (ref 10CFR2 790) CRUTCHFIELD.D Operating Reactors Branch 5 LSO5-83-10-029 83/10/11 WIESEMANN.R A Westinghouse Electric Corp 2pp 20826 355
- B310180533 Approves B11125 & 1201 requests for withholding CEN-185, Suppl 2-P "Heated Junction Thermocouple Phase II Test Rept" re TMI Item II F 2 from public disclosure (ref 10CFR2 790) CRUTCHFIELD, D Operating Reactors Branch 5 B3/10/11 SCHERER, A E Combustion Engineering, Inc. 4pp 20825 001
- B310180560 Discusses SER re GE proposal to delete control rod drop accident from std GE-BWR reload package for banked withdrawal sequence plants W/o encl THOMAS,C O Standardization & Special Projects Branch 83/10/13 RUBENSTEIN,L S Assistant Director for Core & Plant Systems ip 20824 358
- B310190007 Forwards proprietary "Koch Process Sys VR-Sys 350 Low Level Radwaste Vol Reduction Sys " Rept withheld ABRAMS, R Koch Industries, Inc. 83/10/05 Standardization & Special Projects Branch 1p 20823 127
- 8310190043 Forwards "VEPCO NOMAD Code & Model" Ropt is one of series discussing nuclear reload licensing & core foliow support capabilities STEMARTW L Virginia Electric & Power Co 545 83/10/14 DENTON:H R Office of Nuclear Reactor Regulation, Director 2pp 20822 335 24% Fiche 50-000.83/10/14.8310190043
- --8310190057 VEP-NFE-1 "VEPCO NOMAD Code & Model" BOWMAN, S M Virginia Electric & Power Co 83/09/30 118pp 20822 337 24X Picks 50-000,83/10/14,8310190043
- 8310190097 Forwards Rev 14 to operational GA program Rev addresses organizational & programmatic changes to GA program SHEPARD.A M Yanžee Atomic Electric Co FVY 83-107 83/10/12 MURLEY.T E Region 1. Office of Director 1p 20822 117 24X Fiche 50-000.83/10/12,8310190097
- --B310190105 YOGAP-I-A R14

 Rev 14 to operational GA program
 PETERSON.W K., SHEPARD, A.M., MURPHY, W.P. Yankee Atomic Electric
 Co. 83/10/12 134pp 20822 118 24X Fiche 50-000, 83/10/12,
 B310190097
- 8310200170 Forwards summary of test results & basis for conclusions for Model DB-50 circuit breaker undervoltage trip attachment.per IE Bulletin 83-01 RAHE,E P Hestinghouse Electric Corp IEB-83-01 83/10/05 DENTON.H Office of Nuclear Reactor Regulation, Director 17pp 20834 054

- 8310200193 Forwards proprietary "Westinghouse Response to NRC Guestion at B30901 Meeting on Pretendering Module 6 ~ Reactor Bys" & application for withholding proprietary info per 10CFR2 790 RAHE, E P Westinghouse Electric Corp NS-EPR-2830 83709730 EISENHUT, D G Office of Nuclear Reactor Regulation, Director 2pp 20031 259
- --8310200199 Application for withholding proprietary info in "Mestinghouse Response to NRC Questions at 830901 Meeting on Pretendering Module 6 Reactor Sys," per 10CFR2 790 WIESEMANN, R A Westinghouse Electric Corp AN-83-82. 83/09/30 EISEMHUT.D G Office of Nuclear Reactor Regulation, Director 16 2083 261
- 8310210020 Forwards proprietary version of "Rancho Seco Cycle 7 Reload Rept. Vol 1. Mark BZ Fuel Assembly Design Rept " Vol 2 will be submitted in Fall 1984 Rept withheld MATTIMOE. J Sacramento Municipal Utility District 83/10/18 EISENHUT, D @ Division of Licensing 1p 20858 201 24X Fiche 50-312.83/10/18.8310210020
- 8310210139 Forwards proprietary XN-NF-82-25(P)(A). "Generic Mechanical Design Rept Exxon 17x17 Fuel Assembly" & Rev 1 to XN-NF-82-21(P)(A). "Application of Exxon Nuclear Co PWR Thermal Margin " Repts withheld (ref 10CFR2 790) CHANDLER, J C Exxon Nuclear Co, Inc (subs of Exxon Corp) JCC 095 B3 63/10/07 THOMAS, C O Standardization & Special Projects Branch 2pp 20851 095
- 8310250013 Discusses topical rept evaluation of NEDE-24326-P. "OE Environ Qualification Program " Disclaimer contained in rept makes transition into topical rept program impossible Recommends rept remain on Perry docket MIRAGLIA,F J Assistant Director for Safety Assessment 83/10/17 NOVAK,T M Assistant Director for Licensing 2pp 20916 210
- "-8310250018 Forwards topical rept evaluation of NEDE-24326-P, "GE Environ Gualification Program " Gualification methodology presented No plant-specific qualification parameters developed Rept acceptable

 KNIGHT.JP Assistant Director for Comp & Structures Engineering (Post 830201) 83/07/14 MIRAGLIA, F.J. Assistant Director for Gafety Assistant Director for
- ---8310250021 Topical rept evaluation of NEDE-24326-P. "GE Environ Qualification Program " Rept acceptable * Commissioners B3/07/14 17pp 20916 214
- 8310250273 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller. Inc Ray Miller, inc products placed in inventory for in-house maint needs Items isolated & will be discarded

 AUSTIN, M A Babcock & Wilcox Co IEB-83-07 83/09/23 MURLEY, T E Region 1. Office of Director 2pp 20879 021
- 8310250577 Assists in resolving TMI Action Item II K 3 30 re small break LOCA methods Response listed in three segments Part I completed by C-E.Part 2 to be performed by C-E & Part 3 represents new work not considered part of CEN-203-P MELLS.R W C-E Operating Plants Gunners Group HELLS.R.W Northeas Utilities RWM-B3-54 83/10/12 THOMAS.C O Standardization & Special Projects Branch 2pp 20900 348
- 8310260156 Forwards Rev I to Suppl 3 of "Probabilistic Risk Assessment of Effects of PDRVs on Depressurization & DHR " Changes are result of detailed treatment of automatic PDRV cases & complete analysis of auxiliary feedwater restoration VAN BRUNT.E E Arisona Public Service Co ANPP-28004-WFG/83/10/13 KNIGHTON.O Licensing Branch 3 Dpp 20714 178 24X Fichs 50-528-83/10/13.8310260156
- --8310260160 CEN-237 803 R01 Rev 1 to Suppl 3 of "Probabilistic Risk Assessment of Effects of PORVs on Depressurization & DHR " * Combustion Engineering, Inc. 83/07/30 373pp 20914-181 24 Fiche 50-528,83/10/13,8310260156
- 8310260237 Forwards "Trojan Nuclear Plant Cycle 6 Startup & Power Escalation Physics Testing Rept"
 HITHERS.B D Portland General Electric Co 83/10/14 HARTIN, J B Region 5. Office of Director ip 20912 024 24X
 Fiche: 50-344
- 8310260279 Forwards monproprietary & proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tubs Vibration Summary Rept " Proprietary version withheld (ref iOCFR2.790) RAHG.E P Westinghouse Electric Corp NS-EPR-2814 83/08/26 EISENHUT.D 0 Division of Licensing 2pp 20909 354 24X Fiche 50-445.83/08/26.8310260279

- --8310260281 Application for withholding proprietary versions of "Counterflow Preheat Steam Generator Tube Expansion Rept" & "Counterflow Preheat Steam Generator Tube Vibration Summary Rept," per 10CFR2 790 Affidavit enci WIESEMANNIR A Westinghouse Electric Corp AM-83-53 83/08 EISENHUT.D © Division of Licensing 9pp 20909 358 24x Fiche 30-445,83/08/26.8310260279 AW-83-53 83/08/26 20909 358 24X
- --8310260284 SGPR-8301
 - 310260284 SGPR-8301 Nonproprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept" * Hestinghouse Electric Corp 83/06/30 140pp 20910 005 24/ Fichs 50-445.83/08/26.8310260279
- --8310260286 SGPR-8302
 - \$10260286 \$GPR-8302 Konproprietary version of "Counterflow Preheat Steam Generator Tube Vibration Summary Rept " " Wastinghouse Electric Corp 83/06/30 180pp 20910 144 24. Fiche 30-445,83/08/26.8310260279
- 8310270006 Notification of B31026 meeting w/C-E in Bethesda MD to discuss use of pipe whip restraints in C-E std SAR design MEYER. 9 C Standardization & Special Projects Branch 83/10/19 THOMAS. C Standardization & Special Projects Branch 2pp 20940 165 24X Fiche 50-470.83/10/19.8310270006
- B310270038 Forwards CASE-TR2, "GA Program for Nuclear Section of Coordinating Agency for Supplier Evaluation," in response to NRC 830826 request
 BAJADA.E C . SHANSIGER.T G Coordinating Agency for Supplier Evaluation (CASE Assoc) # Cleveland Electric Illuminating Co 83/10/05 NRC No Detailed Affiliation Given ip 20937 162
- --B310270050 Evaluation of proposed Rev 2 to "GA Program for Nuclear Bection of Coordinating Agency for Supplier Evaluation " Rev Bection or coordinating agency for Supplier Evaluation (CASE Assoc) 2pp
- --8310270055 CASE-TR2 RO2
 Rev 2 to "GA Program for Nuclear Section of Coordinating Agency for Supplier Evaluation " Coordinating Agency for Supplier Evaluation (CASE Assoc) (09/30 40pp 20937 166
- 8310270051 Responds to FDIA request for "Westinghouse Advanced PWR Licensing Control Document," dtd Aug 1982, to be placed in PDR Document withheld (ref FDIA Exemption 4) FELTON.J M Division of Rules and Records 83/07/14 PEDRO.J Corp 1p 20942-016 83/07/14 PEDROJJ NUS
- 8310270057 FOIA request for "Westinghouse Advanced PMR Licensing Control Document." dtd Aug 1982 to be placed in PDR Rept referenced at NRC 821130 meeting w/Westinghouse PEDRO. J NUS Corp CD-15-85-021 83/06/08 Division of Rules and Records ip 20942 017
- 8310270594 Forwards "Recommendations for Improvement of Equipment Qualification Methodology & Criteria," Contract
 NRC-04-81-185.Task 3 summary rept
 CAMPBELL, W E Mechanical/Structural Engineering Branch
 NRC-04-81-185 83/10/21 MORRIS B Electrical Engineering Branch
 NQCONAN, V Equipment Qualification Branch BOSNAK, R J Materials
 Engineering Branch ip 20928 255
- --8310270598 EWRI-6582-003 "Recommendations for Improvement of Equipment Qualification Mathodology & Criteria," Contract NRC-04-B1-185. Task 3 summary rept
 KANA,D D , POMERENINO,D J Southwest Research Institute
 NRC-04-B1-185 83/10/01 Office of Nuclear Regulatory Research,
 Director ABpp 20928 257
- B310280007 Forwards draft answers to NRC Request 2 for add1 info on MCAP-10079(P) Response should be withheld (ref 100FR2 790) WEISEMANN, R A Westinghouse Electric Corp AW-83-85 83/10/10 THOMAS C O Standardization & Special Projects Branch 1p. 20929 036
- --8310280017 Requests draft ensuers to NRC Request 2 for add1 info on MCAP-10079(P) be treated as proprietary (ref 100FR2 790)
 RAHE, E P Hestinghouse Electric Corp NS-EPR-2838 83/10/10
 THOMAS, C O Stendardization & Special Projects Branch 1p
- 8310280099 Forwards B&W Owners Oroup rept "Bounding Analytical Assessment of NUREO-0630 Models on LOCA kW/Ft Limits W/Use of FLEGRET" of FLEGBET "
 RODRIGUEZ, R.J. Bacramento Municipal Utility District RJR 83-705
 83/10/21 STOLZ, J.F. Operating Reactors Branch 4 ip 20935 212
 24X Fiche 50-312,83/10/21,8310200097

- 8310280106 Forwards proprietary version of Westinghouse Advanced PWR RESAR 8P/90 Module 1, "Primary Side Bafeguards Sys Module 'Rept withhold (ref 10CFR2 790) RAHE.E P Westinghouse Electric Corp NS-EPR-2842 83/10/24 DENTON:H R Office of Nuclear Reactor Regulation. Director 76pp
- --B310280110 Application for withholding Westinghouse Advanced PWR RESAR SP/90, "Primary Side Safeguards Sys Module." from public disclosure WIESEMANN, R A Westinghouse Electric Corp. AW-83-93 83/10/. DENTON-H R Office of Nuclear Reactor Regulation, Director
- B310310410 Forwards B&W Gwners Group Analysis Committee/Core
 Performance Committee Rept "Bounding Analytical Assessment
 of NUREG-0630 Models on LOCA kW/ft Limits W/Use of FLEGSET"
 HUKILL.H D General Public Utilities GPU Service Corp
 5211-83-303 83/10/21 NOVAK,T Assistant Director for Licensing
 ip 20961 001 24X Fiche 50-287, B3/10/21, B310310410
- --8310310413 77-1140898-01 "Bounding Analytical Assessment of NUREO-0630 Models on LOCA kW/ft Limits W/Use of FLEGSET"

 * Babcock & Wilcor Operating Flants Owners Group 83/0 104pp 20961 002 24% Fichs 50-289,83/10/21.8310310410
- B310310476 Approves request for withholding Rev 3 to B&W Topical Rept OOB, "Assessment of TMI-1 Plant Safety for Return to Svc After Steam Generator Repair" (ref 10CFR2 790) STULZ.JF Gperating Reactors Branch 4 B3/10/11 HUKILL.H D General Public Utilities GPU Service Corp 5pp 20765 183 24x Fiche 50-289,83/10/11.8310310476
- B310310489 Summary of 830826 meeting w/B&W Dwners Group re implementation of Generic Ltr B3-28 concerning defenses against ATWS & proposed ATWS rule for B&W plants List of Attendees 8 viewgraphs encl KADAMBI-P Operating Reactors Branch 4 GL-83-28 Operating Reactors Branch 4 13pp 20968 147 24 Fiche 50-000.83/10/20.8310310489 28 83/10/20 24X
- 8310310505 Notification of 831026 meeting w/Westinghouse in Bethesda.MD to discuss proprietary portions of review of Westinghouse safety parameter display sys DICK.0 F Operating Reactors Branch 5 83/10/20 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 20965 181
- WASH REGULATORY PUBLICATIONS - PRE-NUREG SERIES
- B310040387 Submits evaluation of existing Hestinghouse STS provisions ASME Code Section XI.Reactor Safety Study (MABH 1400).
 NUREG-0677 & EG&G rept on "Inservice Leak Testing of Primary Pressure Isolation Valves" as applicable to plant design CLAYTON.F L Alabama Power Cn 83/09/27 VAROA,S A Office of Nuclear Reactor Regulation, Director 16pp 20625 200 24X Fiche 50-348,83/09/27.8310040387
- 8310120016 Add1 response to FOIA request for document re problems w/ Tech Specs applying to RCS leakage determinations in PWRs Forwards App A documents FELTON, J M Division of Rules and Records 83/07/07 VOIGT, H H LeBosuf, Lamb, Leiby & MacRae 2pp 2075; 001 24X Fiche 50-000,83/07/07,8310120016
- --8003240118 Requests specs for surveillance & limiting conditions to ensure valve integrity if Event 5 valve configuration exists NRC 800225 ltr requesting LWR licensees to indicate if Event 5 valve configuration exists at facility entl PDLK,P J Operating Reactors Branch 3 (Pre 800428) 80/02/29 WETMORE J Operating Reactors Branch 2 (Pre 800428) 2pp
- ---8003240123 Ltr all LWR licensees requesting that periodic valve test-or continuous surveillance be performed to determine if Event 5 valve configuration exists at facility Requests listed info re valve configuration EIBENHUT.D 0 Division of Operating Reactors 80/02/25 Division of Operating Reactors 3pp 20751 034
- --B310120018 Notifies of decision to expand existing contract w/Franklinst to include technical assistance on Generic Activity B-45, "LMR Primary Coolant Sys Pressure Isolation Valves" Mgt concurrence requested POLKAP J Operating Reactions Branch 3 (Pre 800428) 80/03/06 BUTCHER,E NRC No Detailed Affiliation Given 23pp 20751 00;
- ---Bardipoopo sapar, a ciaseram especialista et alla e B1/04/20 1p, 20751 05"

- 8310270040 Rescands to FOIA request for documents containing info re ilgs/0040 Responds to FOIA request for documents contain emission of radioactive lodine & other fission products during reactor accidents Forwards App A documents App B documents can be purchased from NRC FELTON. J M Division of Rules and Records 83/07/06 Affiliation Unknown App 20940 345 24x Fiche 50-32 ROCERS H A 24x Fiche 50-320,83/07/04,
- --8310270041 Forwards draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASH-1400 Methodology " POSTMA.A K. Benton City Technology 82/04/13 PASEDAG, W.F. Accident Evaluation Branch 41pp 20940 349 24X Fiche 50-320,83/07/06,8310270040
- --8310270044 Draft "Comparison of Iodine Behavior During TMI-2 Accident W/Predictions Based on WASH-1400 Methodology " POBYMA:A K Benton City Technology 82/04/13 40pp 20940 350 24% Fiche 50-320.83/07/06.8310270040
- --8310270045 BMI-2104 Draft "PWR-Large Dry Containment-Radionuclide Release Under Specific Accident Conditions" * Battelle Memorial Institute. Columbus Laboratories * Sandia Laboratories 83/02/09 Office of Nuclear Regulatory Research 348pp 20741 028

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8310030605 Forwards revised "Summary Protocol UMTRAP Vicinity JIO030605 Forwards revised "Summary Protocol UMTRAP Vicinit, Properties Identification — Characterization — Inclusion," resulting from concerns & comments discussed during 830909 meeting & in response to 830916 ltr for review BAUBLITZ.JE Energy. Dept of 83/09/19 HIGGINBOTHOM, Level Waste Licensing Branch 1p 20603 001 HIGGINGOTHOM. I Low
- --8310030410 "Summary Protocol UnTRAP Vicinity Properties Identification Characterization Inclusion " One oversize diagram encl Aperture card is available in PDR * Energy, Dept of 83/09/30 25pp 20603 002
- B31005040B "Funding Assurances for Closure,Post-closure & Long-Term Care of Low Level Waste Disposal Facility," technical position * NRC No Detailed Affiliation Given 82/06/30 18pp 20649 33
- 8310050413 "Near Burface Disposal Facility Design & Operation," technical position PANGBURN.G C Low Level Waste Licensing Branch Division of Waste Management 82/11/30 18pp 20649 318 PENNIFILL,R A
- 8310060516 Responds to 830824 ltr requesting certain NRC computer codes Codes & associated documentation will be provided as expeditiously as practical Codes still under development & may not be used in licensing effort
 BUNIING, J.C. Licensing Process & Integration Branch. 83/09/16
 HDVIS, J.B. Hovis, Cockrill, Weaver & Bjur 3pp 20662 359
- 8310110624 Forwards "Status of NRC Concerns Pertaining to Bite Characterization Rept." consisting of dispositions/response tables prepared by BMIP covering NRC comments on draft site characterization rept 0LSON.0 L Energy. Dept of 000560 83/09/21 MRIGHT,R J Level Waste Technical Development Branch ip 20707 001
- ~-8310110626 SD-BWI-DIC-OOI ROO Rev O to "Status of NRC Concerns Pertaining to Site Characterization Rept " RUTIA C Energy, Dept of 000560 83/09/01 318pp 20707 002
- 831013000B Forwards preliminary DES to remedial actions at former Unior Carbide Corp sites in Rifle, Garfield County, CO Comments requested by 831028 MORLEY, J A Energy, Dept of. 83/10/03 MARTIN, D Low Level Waste Licensing Branch 1p 20775 001 831068 Energy, Dept of. 83/10/03 MARTIN,D Low Level Waste anch 1p 20775 001
- --83i0i300i1 DES re remedial actions at former Union Carbide Corp sites in Rifle.Garfield County.CD # NUB Corp 83/09/30 500pp 20775 002
- B310130066 Summary of 830810 mreting w/DDE, NRC & EPA re transfer of Burita site of ranchers to govt for UMTRAP & SUPERFUND HAZLE, A J Colorado, State of B3/08/11 Colorado, State of 4pp 20776 214

- 8310130067 Forwards draft "Plan for Implementing EPA 5tds for U Mill Tailings Remedial Action Sites" Repid prereview by 830930 requested Draft plan will be revised during wk of 831003 in preparation for 831103 to 04 meetings BAUBLITZ, J E Energy, Dept of 83/09/27 HIGGINBOTHOM L Division of Waste Management 2pp 20776 198
- --B310130071 Draft "Plan for Implementing EPA Stds for U Mill Tailing Remedial Action Sites" MORLEY.J A Energy, Dept of B3/09/30 54pp 20776 160
- 8310170139 "Designation of Preferred Candidate Repository Horizon for
- 8310170338 "Summary of Basis for Identification of Cohassett Flow as Proferred Candidate Repository Horizon" Meeting agenda & mgt meeting log enci # Energy. Dept of B3/09/30 32pp 20795 240

Energy, Dept of 03/10/14 3pp 20813 041

- B310190265 Forwards proposed method for qualifying process control program for stability of solidified waste at Ginna Station Assurance that program meets requirements of 10CFR61 requested BUGGAN, G J Science Applications, Inc. 83/09/23 JOHNBON, T C N No Detailed Affiliation Given. Spp. 20842 288
- 8310210130 Notification of B31127-1201 meetings w/DDE. State of WA. Rockwell & affected Indian Tribes in Richland. WA to discuss resolution of NRC concerns re underground testing portions of site characterization rept

 * NRC No Detailed Affiliation Given 83/10/12 NRC No Detailed Affiliation Given 2pp 20983 175
- 8310210335 Summary of 830829-0901 BWIP Performance Assessment Workshol NRC - No Detailed
- 8310240242 Requests assistance for input into implementation of TOUGH computer program on BML sys Code will be used in assessment of high level waste repositories Tape preprocessor programs & sample input sets encl W/o tape

 BELL.M J High Level Waste Licensing Management Branch 83/09/23
 BASSETT.H S Division of Data Automation & Management Information 19pp 20907 286
- 8310240292 Forwards "Nonisothermal Flow Modeling of Hanford Site," as discussed at Aug 1983 workshop on performance assessment of BMFP at Richland.MA W/o encl MEDER.M F High Level Waste Licensing Management Branch 83/09/27 LEHMAN.L L AFfiliation Unknown 1p 20907 279
- 8310240253 Designates add1 Edgemont.SD vicinity properties identified in encl radiological assessment repts for remedial action under Public Law 97-415 W/o encl COFFMAN.F E Energy, Dept of 83/10/05 ROMATOWSKI.R G Energy, Dept of 1p 20907 278
- 8310240255 Responds to 830919 ltr repossible discussions among State of UT, EPA, NRC & DUE concerning interpretations of EPA stds. design criteria & costing methodology Meeting w/EPA & NRC scheduled for early Nov in Albuquerque MCRLEY, J.A. Energy, Dept. of 83/10/06 MABON, J.O. Utah, State of 1p 20907 R76
- 8310240260 Submits proposed agenda for regulatory issues asssion at Annual Civilian Radwaste Mgt Info Meeting scheduled for 831212-15 in Washington.DC MILLER.H J High Level Waste Technical Development Branch 83/09/09 SHAHEEN.J Energy, Dept of 2pp 20907.266.
- 8310240262 Forwards review package from WA State re DOE designed high integrity container for disposal of EPICOR-II resins at Hanford disposal facility W/o encl HIGGINBOTHAM. Low Level Haste Licensing Branch 83/07/15 QAMMILL.W Meteorology & Effluent Treatment Branch SNYDER.B.J TMI Program Office MACDONALD.C Transportation Branch. 1p 20907 354
- 8310240265 Trip rept of 830926-29 site visit to Vitro UNTRAP re surfac & subsurface hydrology concerning potentially proposed remedial actions including stabilization in place Meeting agenda encl WEBER, M F Division of Waste Management 83/10/04. KNAPP, M R Division of Waste Management 10pp 20907 346

- 10240266 Forwards radiological assessment repts for properties in Edgement.9D for consideration re remedial action under UMTRCA W/o encis MARTIN.D Low Level Waste Licensing Branch 83/09/30 BAUBLITZ.J Energy, Dept of ip 20907 345
- 10240267 Recommends concurrence on cooperative agreement between DDF & Navajo Tribe for remedial action on Indian lands No unresolved concerns remaining MARTIN, D.E. Uranium Recovery Licensing Branch 83/10/05 HIOQINBOTHAM: L. Uranium Recovery Licensing Branch 1p 20907 343

- B310240271 Forwards, for concurrence, Cooperative Agreement
 DE-FC04-83AL16238 between DDE & Navajo Tribe Agreement
 supports UMTRAP in Navajo lands, per Public Law 95-604
 CONE, T C Energy, Dept of 83/09/16 HIGGINBOTHAM, L Low Level
 Waste Licensing Branch ip 21035 044
- 10240270 Forwards comments on test program developed to demonstrate compliance w/waste form stability requirements of 10CFR61. submitted on 830909 Test program acceptable if comments incorporated & test results meet technical position incorporated & test results meet technical position HIGOINBOTHAM.L Low Level Maste Licensing Branch 83/09/30 LANGE,R G US Gypsum Co 4pp 20907 334
- 10240276 "Branch Position on Explorations for Design & Evaluation of J Mill Tailings Retention Sys " * Uranium Recovery Licensing Branch 79/01/31 2pp 20907 328
- LO250095 Forwards, for consideration & review, proposed agreement setween DDE & util to provide for disposal of residual radioactive matis JORLEY, J.A. Energy, Dept of 83/10/03 DONOVAN, T.K. Tennessee /alley Authority 12pp 20916 165
- 10250102 Forwards,for review & comment,draft "Plan for Implementing EPA Stds for UMTRA Sites," Meetings scheduled on B31103 & 04 in Albuquerque to discuss implementation plan & design smalysis process IDRLEY.J.A Energy, Dept of B3/10/07 H1GGINBOTHAM,L High evel Waste Licensing Management Branch ip 20916 110
- 3310250107 Draft Procedure UMTRA-DOE/AL 143, "Plan for Implementing EPA Stds for UMTRA Sites " HORLEY,J A Energy, Dept of 83/10/31 54pp 20916,111
- .0280480 Bubmits proposed schedule for submittal of rept on olyethylene high integrity containers Rept scheduled for ubmittal by 831224. EARBON.8 D Chem-Mulkar Bystems, Inc TR-B3-P0420 B3/10/04 UGGINBOTHAM,L Low Level Waste Licensing Branch, ip 20908-3:
- 0260074 Forwards "Assessment of Radionuclide Apparent Bolubilities y Conservative Estimation of Steady-State Concentration." IRC draft technical position Summary of comments will be ompleted by 83:130 UBTUS: PS High Level Haste Technical Development Branch 3/09/30 MILLER.H J High Level Waste Technical Development tranch ip 20921 267
- 310260083 "Assessment of Radionuclide Apparent Solubilities by Conservative Estimation of Steady-State Concentration," NRC draft technical position * High Level Waste Technical Development Branch 83/09/30 50pp 20921 268
- OZ&OOBB Forwards request for approval to use high integrity antainers to bury EPICOR II prefilters from TMI-2 IIPSHER,W M US Ecology, Inc (formerly Nuclear Engineering) 3/07/01 XIRNER,N M Washington, State of, Dept of Sociel & Health ervices 27pp 20921 239
- 0250094 Forwards add1 supportive info providing data on how high neagrity container (HIC) will meet present criteria use in dw level radwaste disposal, for inclusion in HIC use pplication
 IPBHER,W M UB Ecology, Inc (formerly Nuclear Engineering)
 3/09/16, KIRNER,N, Washington, State of, Dept of Bocial & Health gryces 10pp 20921 162
- 0260318 Responds to questions in 830930 ltr re NRC regulatory regram for U milling Applicable manual chapters encl. USSBAUMER,D.A. Assistant Director for State Agreements Programs 3/10/11 SPAIN.H Virginia, Commonwealth of, 31pp 20918-30 20918-301.
- 0280076 Forwards,for review,DES section on geohydrology at Vitro ite Comments requested by 831027 ATTHEMS.N L Energy, Dept of. 83/10/17 MARTIN.D E. Low Level aste Licensing Branch. 100pp 20964 028

- 8310280080 Forwards correspondence w/EPA for past 3 yrs, including EPA 830817 response re duality of regulation for nuclear waste sites at Hanford, WA & Beatty, NV EASON, C F US Ecology, Inc. (formerly Nuclear Engineering) DOA-63-539 83/09/30 LOHAUS, P Division of Waste Management 9pp 20945 068
- B3102B0103 Forwards B30913 ltr from State of NV,responding to NRC B30B22 ltr on RADMAN code NUSSBAUMER,D A Assistant Director for State Agreements Programs B3/09/21 H1001NBDTHAM,L Low Level Waste Licensing Branch 2pp 20961 358
- ---8310380107 Responds to NRC 830822 Itr re RADMAN computer code No objections raised to use of code by persons licensed to dispose of radwaste at Beatty site VADEN.J Nevada, State of 83/09/13 NUSSBAUMER,D A Assist Director for State Agreements Programs 1p 20961 359 numER,D A Assistant 20961 359
- 8310280111 Forwards Rev 1 to TMI-2 Operating Procedure 2104-4 96, "Dewatering of EPICOR Liners at EPICOR II," per 830919 discussion
 GRANT.P J TMT Program Office 83/09/19 JOHNSON.T NRC - No
 Detailed Affiliation Gaven 19 20964 001
- --B310280116 Rev 1 to TM1-2 Operating Procedure 2104-4 76. "Dewatering of EPICOR Liners at EPICOR II" * General Public Utilities GPU Service Corp 81/04/24 24pp 20964 GO2
- 8310280162 Order directing designated groups to identify, within 2 wks representatives & interest for oral presentation to Commission re DDE general guidelines for recommendation of situs for nuclear waste repositories CHILN.9 J Defice of the Secretary of the Commission 83/10/26 2pp 20729 224
- 8310280283 Forwards Rev D to "Deep Borehole Strategic Correlation Charts & Structure Cross Sections." per M Guzowski request DLSON,O L Energy. Dept of 00572 83/10/13 WRIGHT.R J High Level Waste Technical Development Branch 1p 20962 001
- --B310280295 SD-BWI-DP-035 R B Rev B to "Deep Borehole Strategic Correlation Charts & Structure Cross Sections" CRDSE,R W Energy, Dept of 83/09/07 142pp 20962 002
- 8310310182 Notifies of 831103-04 meetings in Albuquerque, NM to discuss & receive comments on draft. "Plan for Implementing EPA Stds for UNTRA Sites " Draft agenda encl MORLEY, J A Energy, Dept of 83/10/18 HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 20965 276
- 8310310204 Informs of establishment of public ref ctr in Olympia,WA Requests assistance in obtaining public documents written or sponsored by NRC to aid in development of ctr STEVENB.D Washington, State of 83/10/05 BUNTING,J O Licensing Process & Integration Branch 1p 20965 303
- B31031045; Forwards requested info re Salt Lake City Vitro Mill Site as requested in B31006 telcon PRICE.J B Jacobs Engineering Oroup. Inc B3/10/17 WEBER.M NRC No Detailed Affiliation Given Bpp 20945 170

EXPORT AND IMPORT LICENSES XPORTL1C

- 8309230037 License for Exxon Nuclear Co.Inc to export 3,163 kg U-235. contained in 76,762 kg U.to Taiwan ZIMMERMAN.J.V Assistant Director for Export/Import & International Safeguards 83/07/13 2pp 20488 270
- 83100301985 Forwards IE Matl Control & Accounting Safeguards Insp Rept 110-03134/83-01 on 830914 of activities under Export License XBNM-2027 No noncompliance noted NCROERHAUG.L R Region 5. Office of Director 83/09/28 NAKAI, T Marubeni America Corp (subs of Marubeni Corp) 2pp 20390 153
- --B310030213 IE Matl Control & Accounting Safeguards Insp Rept 110-03133/83-01 on B30914 No noncompliance noted Major areas inspected shipping drum identification & tamper seal numbers to shipment packing lists Details withheld (ref 10CFR2 790) NELEGN. G B , WIEDER. A V , BROCK. B L Region 5. Office of Director B3/09/28 1ρ. 20590 155
- 8310060056 Bubmits Ofc of Intl Programs findings re BMI 830830 application for license to import 23 g enriched U from Canada Inport acceptable MODRE,R.N. Assistant Director for Export/Import & International Bafeguards 83/09/28 Assistant Director for Export/Import & International Safeguards ip 20663 361

- 8310060059 Application to amend license to export U-235 to Yugoslavia, increasing quantity & extending expiration date to 901231 HERSCH, M M Westinghouse Electric Corp MMH-413 83/09/19 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ip 20663-360
- 8310040040 Forwards application to renew export license, extending expiration date to accommodate requirement to ship sources containing Cf-252 to West Germany in Nov 1983

 JANZOW.E F Monsanto Research Corp 63/09/19 HEMBY.E Assistant Director for Export/Import 1. International Safeguards 1p 20663 357
- --8310060065 Application to renew general export license JANZOW.E F Monsanto Research Corp 825 5000 83/09/16 2pp 20663 358
- 8310060081 Forwards application to export 7,770 kg U.containing 283 605 kg U-235.to Switterland HANNETT.B A Transnuclear, Inc RBU-428 83/09/20 MOORE.R N Uffice of International Programs, Director ip 20663 354
- -8310060084 Application for license to export 7.770 kg U.containing 283 605 kg U-235 to Switzerland HANNETT.B A Transnuclear Inc RBU-428 83/09/20 2pp 20663 355
- 8310060090 Application to amend import license, extending expiration date to Dec 1988
 FOSTER.C M Ediow International Co 83/09/08 MOORE.N Assistant Director for Export/Import & International Safeguards ip 20663 353
- B310060094 Executive Branch position of Nikko Wolverine.Inc application to export 434 lb reactor grade Zircaloy-4 tubing to United Kingdom License should be granted DEVINE.J B State. Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 83/09/16 SHEA.J R Office of International Programs. Director 2pp 20663-348
- B310060078 Amend i to license for Edlaw Intl Co extending expiration date to B81231 ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards B3/09/21 ip 20663 347
- B310060104 License for BMI to import 23 g U.enriched to 93 15%,from Canada Zimmerman,J V Assistant Director for Eiport/Import & International Safeguards B3/09/2B 2pp 20663 345
- B310060107 License for Biodez. Inc to import 4 mg I-125 from Israel ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards B3/09/22 ip 20663 344
- 8310060108 License for Amersham Corp to export 2 Ci Cm-244.contained in sealed sources,to Canada ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/09/27 ip 20663 343
- B310040114 Amend 3 to Westinghouse export license, extending expiration date from 841231 to 891231
 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards 0146 83/09/22 ip 20661 089
- B3;00601;6 License for I-J Enterprises Inc to export 2,000 element cu;s & 90 head cups for cobalt adjuster element reactivity control units & adjuster unit, to Canada ZIMMERMAN.JV Assistant Director for Export/Import & International Safeguards AECL 1783 83/09/28 ip 2066; 088
- 2310060120 Application for license to export one WX33356 BF3 detector 'four uncompensated conization chambers to West Germany HEFTHER,W H Hestinghouse Flactric Corp. ZE 10552 83/09/14 ip 20661 016
- B310060123 Amend 3 to Westinghouse export license extending expiration date to B91231

 ZIMMERNAN J V Assistant Director for Export/Import & International Safeguards HP-42090-ARB B3/09/22 1p 20661 012
- B310060126 License for Carpenter Technology Corp to export 240 Zircalc,
 BWR fuel channels to Italy
 ZIMMERMAN.J V Assistant Director for Export/Import & International
 Safeguards SPD 5737 83/09/28 Ip 20661 Oil
- 3310060130 Application for license to esport 119 kg U heræfluoridecontained in 3.434 kg U to Japan FOSTEH.C M Edlow International Co KLK-17 83/09/22 ip 20661 010

- B310060131 License for Carpenter Technology Corp to export 23**0 Zircal**oy BWR fuel channels to Italy ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards SPD 5732 B3/09/28 1p 20661 009
- 8310060135 Application for license to export 115,424 16 tentalite ore. containing 590 16 U.to West Germany COYLE.F T KB1 Corp B3/09/28 1p 20661 007
- B310060141 License for Edlow Intl Co to export 40 mg Cf-252.as cermet wire to United Kingdom
 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards AMER-84 B3/09/22 ip 20661-006
- 8310060143 Amend 2 to Sigma Chemical Co export license, extending expiration date to 851001
 IIMMERMAN.J V Assistant Director for Export/Import & International Safeguards D-22 83/09/23 ip 20660-360
- 8310060147 License for Saunders-Roe Developments.Inc to export 360.000 C1 tritium.incorporated in SAFETY-10 TM exit signs,to Canada ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/09/22 ip 20460 359
- 8310060152 License for IRT Corp to export if 7 mCi Cf-252.contained in smalled neutron source to Israel ZIHMERMAN.J V Assistant Director for Export/Import & International Safeguards TUBE PS-800 83/09/27 ip 20660 358
- 8310060156 License for Mitsui & Co.Inc to export 96 kg U-235.contained in 3.632 kg U to Japan IIMMERHAN.J V Assistant Director for Export/Import & International Safeguards MBK TR-14 83/09/28 2pp 20660 346
- B310060162 Application for license to export six immersion heaters to Kolea

 * K-C Industries, Inc. 50-393 B3/09/(4 ip. 20660 345
- 8310060177 Application to amend export license, extending expiration date by 5 yrs & increasing value of export HOWRY. H R GA Technologies. Inc /General Atomic Co IEL-5034 83/09/14 ZIMMERMAN. J Assistant Director for Export/Import & International Safeguards 1p 20660 332
- B3i0060iB0 Ltr of assurance re export of 96 kg U-235.contained in 3.632 kg U-to Japan SHIRAKAHA.T Japan Covt of B3/09/07 RAYMOND.JF Energy, Dept of ip 20660-325
- B310060183 License for Exxon Nuclear Co.Inc to export 2,000 kg U-235. contained in 52,000 kg U-to West Germany ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards B3/09/21 2pp 20660 312
- 8310060187 Requests cancellation of 820505 application to export 50,000 pieces seamless rinconium tubing to Argentina SHINOHARA.K. C. Itoh & Co (America). Inc. 83/09/12 HEMBY.& O NRC No Detailed Affiliation Given ip 20660 311
- 8310060234 Informs that License XSNM-2043 may be issued No matl changed circumstances since issuance of License XSNM-2046 MQORE.R N Assistant Director for Esport/Import & International Safeguards 83/09/21 Assistant Director for Esport/Import & International Safeguards 1p 20660 309
- 8310060240 Forwards C Itoh & Co 830912 Itr requesting license application for export of irremium tubing to Argentina be withdrawn Records should be so marked W/o encl IIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/09/22 STOIBER, C State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 20660-310
- 8310060405 Forwards application for export license for minor nuclear export Ltr of assurance required M/o encil IIMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/09/28 RAYMOND.J Energy, Dept of 1p 20660 209
- B3J0060412 Application for license to export 82 microgram Pu-239, 8r-90 k Y-90, contained in calibr std set & 32 microgram Pu-239, contained in alpha calibr std set to South Korea ESPINOSA. © J Eberline Instrument Corp SO NO 894286 B3/09/07 lp 20660 208
- BD10060415 Ltr of assurance te export of 7,770 kg U to Bwitzerland MARCHAL.J European Communities. Commission of 83/09/23 RAYMOND.J Energy, Dept of 1p 20660-085

- 8310060420 Ltr of assurance re export of 583 kg U-235 to West Germany MARCHAL, J European Communities, Commission of 83/09/12 RAYMDND, J Energy, Dept of 1p 20660 084
- 8310060424 Ltr of assurance re export of 2,000 kg U-235 to West Germany MARCHAL.J European Communities, Commission of 83/09/12 RAYMOND.J Energy, Dept of 1p 20650 362
- B310120453 Amend | to Mitsul % Co (USA). Inc. export license changing licensee name from Mitsulline Travel Svc American. Inc. to Mitsul Air Intl.Inc. ZIMMERMAN. J V. Assistant Director for Export/Import & International Safguerds 83/10/05 ip 20751 283
- B310120455 Application to amend licenses to export to reflect name change in licensee section REVESIA J Mitsul & Co (USA), Inc (subs of Mitsul & Co , E.td) 83/09/21 HEMBY:E Assistant Director for Export/Import & International Safeguards in 20751 282
- 9310120459 Amend 2 to Mitsui Air Intl. Inc export licenses adding "on behalf of Mitsui & Co.(USA). Inc." in licenses section ZIMMERMAN. J V Assistant Director for Export/Import & International Safeguards 83/10/05 ip 2075
- 331012046: Amend I to Mitsui & Co (USA). Inc export license, changing name of licensee from Mitsuiline Svc America. Inc to Mitsui Air Intl. Inc ZiMMERAN. J V Assistant Director for Esport/Import & Internationa. Safaguards 83/10/05 ipp 20751 260
- IB101B002B Amend i to Westinghouse export license revising Condition 7 to reflect recent changes to 10CFR7i ZiPHERNAN.J V Assistant Director for Export/Import & International Bafeguards MMH 88/10/06 2pp 20777 001
- 310130030 Amend I to Hitsu: Air Intl.Inc export license.changing name of licensee from Mitsuiline Travel Svc America.Inc to Hitsui Air Intl.Inc
- Air Intl.Inc Zimmerman.J V Assistant Director for Export/Import & Internationa Safeguards B3/10/05 ip 20776 323
- 310130032 Amend 1 to Mitsu: Air Intl. Inc export license, changing name of licensee from Mitsuiline Travel Svc America, Inc to Mitsui
- 310130034 Amend | to Hitsu: Air Intl. Inc export license. changing name of licenses from Mitsuiline Travel Svc America. Inc to Mitsui Air Intl. Inc 11MMERNAN. J V Assistant Director for Erport/Import & Internationa. Safeguards 83/10/05 1p 20776 254
- 310:3003B Amend 1 to Mitsus Air Intl. Inc export license, changing name of licenses from Misusline Travel Svc America, Inc to Mitsus Air Intl, inc ZimmerMAN, J V Assistant Director for Export/Import & International Bafeguards 83/10/05 ip 20776 253
- HOI30050 License for Eberline Instrument Corp to export J14 micrograms Pu-239, contained in callbr std sets, to South Rocea
- Korea IlhmeRhAn, J. V. Assistant Director for Export/Import & International Safaguards SO NO 894286 83/10/06 2pp 20774 358
- 10130075 License for Circle Seal Controls to export check valve.Par' Number P148-34 & quality documentation to Canada ZIMMERMAN, J V Assistant Director for Export/Import & Internationa. Safeguerds P 30282 83/09/30 2pp 20774 336
- 10130086 Amend 1 to Transnuclear Inc export license extending expiration date to 861231
 ZIMMERHAN.J V Assistant Director for Export/Import & International Bafeguerds TNP-414 83/10/05 2pp 20777 048
- 10130092 License for Westinghouse to export 29 ex-core ion chambers Type 24016, to Canada TIMMERHAN, J. V. Assid
- TimeEnAN.J V Assistant Director for Export/Import & Internetional Bafeguards AMR 83/09/30 2pp 20777 050
- |Ol30147 License for Westinghouse to export one BF 3 detector, Model 4X 33356 & four uncompensated innitation chambers, Model 4X33358, to Mest Germany ** IPMERMAN, V Assistant Director for Esport/Import & Internationalise

- B310130349 Application for license to export fuel assembly components end plugs. Zircaloy fuel rod springs, statisless steel fuel tubing. Zircaloy noziles-top & bottom, stainless steel thimble assembly instrumentation tubes & grids to United Kingdom HERSCH.M M Westinghouse Electric Corp. MMH-416 83/09/29 1p
- 8310130355 Requests Executive Branch position re Westinghouse application for license to export superceding 830511 & 25 SAFEGUARDS B3/10/05 STOIBER.C R State, Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 1p 20754 325
- 8310130364 Amend 4 to GE export license consolidating original licens-issued 781117 & all subsequent amends through Amend 3 issued 821013 Belluid ZIMMERNAN.J V Assistant Director for Export/Import & Internationa Safeguards BOW-099-02 B3/09/30 Ip 20770 355
- B310130367 Amend 3 to Monsanto Research Corp export license, extending expiration date to 851101 % adding condition that Govt approval be obtained before any reexport of matl can be made to listed countries ZIMMERMAN, J V Assi Safeguards B25 500 ssistant Director for Export/Import & Internationa. 5000 83/10/03 2pp 20770 356 V Assis
- 8310130369 Application for license to export 25 kg U dioxide pellets to Norway WILSON, O D General Electric Co BDW-101-83 83/09/22 19
- 83:0130371 Advises that second aspect of 83:022 amend request to authorize export of Australian-origin matl will not be required at present WILSON B D General Electric Co BDW-97-83 83/09/16 WRIGHT B NRC No Detailed Affiliation Given 1p 20770 359
- 8310130391 Application for license to export equivalent of 5 kg deuterium oxide liquid over 2-yr period to Portugal * Sigma Chemical Co D-110 83/09/26 ip 20770 353
- 8310130396 Application to amend licenses to export, extending expiration HANNETT, B A Transnuclear, Inc 83/09/28 MOORE, R N Office of International Programs, Director 19 20770 360
- 8310130399 Application to amend licenses to export changing licensee section to Mitsui Air Intl.Inc. REYES.A J. Mitsuiline Travel Service of America. Inc. 83/09/21 HEMBYS. Office of International Programs. Director Ip. 20770-361
- B310130401 License for K-C Industries, Inc to export six immersion heaters, Model P/N 24030672761, to South Korea ZIMHERHAN, J V Assistant Director for Export/Import & Internationa Bafeguards 5 D-393 B3/10/07 ip 20770 362
- B310130405 Amend | to Mitsui Air Intl. Inc esport license, changing name of licensee from Mitsuiline Travel Svc America. Inc to Mitsui Air Intl Inc ZIMMRAN, J V Assistant Director for Export/Import & International Safeguards 83/10/05 ip 20769-347
- 8310130419 Amend 1 to Mitsul & Co USA, Inc export license changing name of licensee from Mitsuiline Travel Svc America, Inc to Mitsul Air Intl. Inc
 - Air Intl.Inc ZiMMERHAN.J V Assistant Director for Export/Import & Internationa. Safeguards 83/10/05 ip 20734-339 Safequards
- 8310130422 Application to amend licenses to export changing licensee section to Mitsui Air Intl.Inc.
 REVES A J. Mitsuiline Travel Service of America: Inc. 83/09/21
 HEMBY.E. Assistant Birector for Export/Import & International
 Safeguards 1p. 20769-239
- B310170023 Amend B to Transnuclear inc import license, extending expiration date to 861231
 2 IMMERMAN J V Assistant Director for Export/Import & Internationa Safeguards 83/10/07 2pp 20798 355
- 8310170038 Amend 2 to Transnuclear Inc export license extending expiration date to 861201 ZIMMERNAN J V Assistant Director for Export/Import & Internationa Safeguards NUK 248 UES/EU/ 83/10/07 2pp 20798 330
- B310170041 Amend 1 to Transnuclear inc import license, estending expiration date to BB0101
 ZIMMERMAN.J V Assistant Director for Esport/Import & International Safeguards B3/10/07 2pp 20798 362

- 8310170679 Amend 2 to GA Technologies. Inc expart license, extending expiration date to 881101, increasing dollar value & changing licensee name from GA Co to GA Technologies. Inc ZIMMERMAN, J V Assistant Director for Expert/Import & International Safeguards IEL-2000 83/10/07 1p 20798 220
- 8310180001 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 ZIMMERMAN.JV Assistant Director for Export/Import & International Safeguards 83/10/04 RAYMOND,J Energy, Dept of 1p
- 8310180095 Application for license to export 467 kg U.contained in 13,518 kg U hexafluoride, to Japan FOSTER,C M Ediow International Co KLK-18 83/10/05 ip 20824 124
- 8310180112 Application to amend license to export revising max fuel enrichments WILSON, B D General Electric Co BDW-108-83 83/10/06 WRIGHT, B L Défice of International Programs, Director 1p 20824 042
- 8310180113 Application for license to export 792 kg U.contained in 22,955 kg U hexafluoride, to Japan FOSTER.C M Edlow International Co KLK-19 83/10/05 1p
- B310180143 Forwards application to export 160 millicuries Cf-252 to France HANNETT.B A Transnuclear, Inc TNP-430 B3/10/07 MOGRE,N Office of International Programs, Director 3pp 20827 055
- --8310180148 Application for license to export 160 millicuries Cf-252 to France HANNETT, B A Transnuclear, Inc TNP-430 83/10/07 1p 20827 088
- 8310180151 Forwards application to export U hexafluoride to Japan SHIMA: S Mitsui & Co (USA), Inc (suba of Mitsui & Co , Ltd) HSA-5483-02 83/10/05 Assistant Director for Export/Import & International Safeguards 2pp 20827 047
- --8310180155 Application for license to export U hexafluoride, contained in 11.708 kg U.to Japan SHIMA, B Mitsui & Co (USA), Inc (subs of Mitsui & Co , Ltd) HSA-5483-02 83/10/05 1p 20827 049
- 8310180157 License for KBi-Div of Cabet Corp to export natural U, contained in 115.424 lbs tantalite ore, to West Germany ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/10/11 2pp 20827 044
- 8310180164 License for Nikko Wolverine.Inc to export reactor grade Zircalou-4 tubing to United Kingdom ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 1509 89/10/12 ip 20827 043
- B310180302 Application for license to import 13,000 kg i 75% U-235 from France HANNETT, B A Transnuclear, Inc TNP 429 B3/10/03 MODRE, R N DfPice of International Programs, Director 2pp 20826 358
- 8310180304 Ltr of assurance re export of 307 kg U-235, contained in 11,345 kg U to Japan SHIRAKAWA,T Japan, Govt of 83/10/06 RAYMOND,JF Energy, Dapt of 1p 20826 360
- 8310180307 Ltr of assurance re export of 937 kg U-235,contained in 32,445 kg U-to Japan SHIRAKAWA,T Japan, Govt of 83/10/06 RAYMOND,JF Energy, Dept of ip 20826 361
- B3101B0310 Application to amend licenses to export to accompdate std deviation allowance in fuel design WILBON: D General Electric Co BDW-108-B3 B3/10/06 WRIGHT: B L NRC - No Detailed Affiliation Given ip 20826 362
- 831018054i Application for license to import 4 mg U-235, in form of U oxide, from United Kingdom OREEN, A R Centronic. Inc 83/10/04 MODRE, N Office of International Programs, Director Ip 20827 123
- 8310180395 Amend 1 to license for B&W to import 25 2 kg U.containing up to 23 7 kg U-235.from Canada ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/10/14 ip 20827 122

- 8310180561 Application for Amend 1 to import license, increasing quantity to 23 700 kg U-235
 REGAN, N A Babcock & Wilcox Co 83/10/10 1p 20824 357
- G310180562 Telcopy application to amend license to export correcting ultimate consignee address FOSTER.C Ediaw International Co G3/10/05 WRIGHT.B Assistant Director for Export/Import & International Bafeguards 1p 20827 118
- --8310180565 Telropy application to amend license to export changing ultimate consignee address
 * Edlow International Co 83/10/03 MODRE,R N Office of International Programs, Director 1p 20827 119
- 8310180564 License for Saunders-Roe Developments, Inc to export 360.000 Ci tritium to all destinations except Kampuchea. North Korea. Cuba & Vietnam ZIMHERMAN. J V Assistant Director for Export/Import & International Safeguards 83/10/12 2pp 20827 116
- 8310180577 Forwards application to export natural enriched U bexafluonide, in form of cylinder heels, to Canada HILSON, B D General Electric Co BDM-105-83 83/10/05 HEMBY, E O Office of International Programs. Director ip 20827 108
- --8310180380 Application for license to export natural enriched U hexafluoride, in form of cylinder heels to Camada WILSDN.B D General Electric Co BDM-104-83 83/10/05 lp 20827 109
- B310200331 Ltr of assurance re export of 21 4 g U-235, contained in 24 g U, to Canada B015VENUELL Canada, Atomic Energy Control Board B9/09/28 RAYMOND, J F Energy, Dept of 3pp 20844 269
- 8310240300 License for Westinghouse to export specially designed or prepared fuel assembly components to United Kingdom ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards MMH-414 83/10/19 2pp 20704 356
- 8310240301 Forwards application to export three demonstration fuel elements. w/low enriched U, to 8weden FOSTER, C M Edlow International Co 83/10/13 MDORE, R. N Assistant Director for Export/Import & International Safeguards ip 20707 031
- --B310240302 Application for license to export three demonstration fuel plements, w/low enriched U, to Sweden FOBTER, C M Edlow International Co STUDS-04W B3/10/13 ip. 20707 032
- B310240306 Informs that License XBNM-2057 may be issued No math changed circumstances since issuance of License XBNM-2055 MODRE,R N Assistant Director for Export/Import & International Safeguards B3/10/17 Assistant Director for Export/Import & International Bafeguards 1p 20907 033
- --8310240309 License for GE to export 309 kg U-235, contained in 11.345 kg U to Japan ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDU-073-83 83/10/17 2pp 20907 034
- B310240311 Application to amend import license, extending expiration date to 870101
 HILSON, B D General Electric Co BDM-112-83 83/10/11
 HRIGHT, B L Assistant Director for Export/Import & International Safeguards 1p 20904
- 8310240313 Application for license to export initial fuel loadings for NSBS to Egypt MACPHERSION, B. J. Combustion Engineering, Inc. 83/10/07 Assistant Director for Export/Import & International Safeguards App 20407 323
- 8310240314 License for 9E to export 937 kg U-235.contained in 32,445 kg U-to Japan. ZIMMERNAN-J V. Assistant Director for Export/Import & International Safeguards BOM-074-83 83/10/17 2pp 20907-321
- 8310240316 Forwards application for export license for minor nuclear export Ltr of assurance required, M/o encl
 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafaguards 83/10/18 RAYMOND.J. Energy, Dept of 1p.
 20907 320

- 310240322 Informs that License XSNM-2058 may be issued. No mat! changed circumstances since issuance of License XSNM-2055 MODRE,R N Assistant Director for Export/Import & International Safeguards 83/10/17 Assistant Director for Export/Import & International Safeguards 1p 20907 162
- 310250016 Application for license to export one compen≤ated ionization chamber:Model WL23084:to Japan HEETHER:W H Westinghouse Electric Corp ZE 60282 83/10/11 3pp 20908 360
- 310250020 Forwards application for export license for minor nuclear export Ltr of assurance required W/o enc!
 ZIMMERNAN.J V Assistant Director for Export/Import & International Baseguards 83/10/17 RAYMOND.J Energy, Dept of 1p 2091& 108.
- 310250135 Application for license to export reload fuel for 950 to 1300 MW electrical NSSS to Egypt MACPHERSON.B J Combustion Engineering. Inc. 83/10/07 Assistant Director for Export/Import & International Safeguards 4pp 20908 333
- 010250142 Litense for Sigma Chemical Co to export 5 0 kg deuterium oxide to Portugal ZIMMERNAN.J V Assistant Director for Export/Import & International Befeguards D-110 83/10/18 2pp 20908.331.
- 10250130 License for Transnuclear.Inc to export 160 0 mCi Cf-252.as oxide.to France ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards TNP-430 83/10/17 ip 20908 330.
- 10230138 Application for license to export one 950 to 1,300 MW NSSS to Egypt MACPHERSON, BJ. Combustion Engineering. Inc. 83/10/07 Assistant Director for Export/Import & International Safeguards 3pp 20908-327
- 10230164 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 83/10/19 RAYMOND.J Energy, Dept of 1pp
 20908 326
- 10250172 Forwards application for export license for minor nuclear export.Ltr of assurance required W/o encl
 IIMMERMAN.J V. Assistant Director for Export/Import & International Safeguards 83/10/17 RAYHOND.J Energy, Dept of, 1p
 20708.325

- 10230178 Requests Executive Branch position re Transnuclear, Inc application for license to export highly enriched U to Buitzerland. LIMMERMAN, J V. Assistant Director for Export/Import & International Dafeguards 83/10/18 8TOIBER.C. State, Dept. of Bureau of Oceans & Intl. Environ & Scientific Affairs. 1p 20908,323
- 0250658 Application for license to export Pu-239 alpha calibr std. fodel DNS-10.to Canada LTTLE.J Ebstline Instrument Corp SOND895347. 83/10/11 ip 10908 280
- 0240004 Forwards application for export license for minor nuclear export Ltr of assurance required W/o ancl IMMERMAN, J. V. Assistant Director for Export/Import & International afeguards B3/10/18 RAYMOND, J Energy, Dept of ipp. 0921-193
- 0260009 Application to amend export license.extending expiration ate to 870101 ILBON.B D. General Electric Co BDM-111-83 83/10/11 WRIGHT ffice of International Programs, Director 1pp 20928-047
- 0260015 Application for license to export natural enrichment U.as U ioxide power, to Canada General Electric Go BDN-110-83 83/10/10. 1p. 20928.082
- 0260018 Application for license to export three BF3 proportional ounters.Model WL—24010.to Begium EETHER.W.H. Hestinghouse Electric Corp. ZE—20644. 83/10/14. ip 0921-362
- 0260020 License for Battelle Columbus Labs to export 23 g U, ontained in 21.4 g U-235, to Canada. INMERNANJ V. Assistant Director for Export/Import & International afeguards 83-1, 83/10/19, 2pp 20921-360

- 8310240022 Application for license to export fission counter, Model RS-P4-1408-110 & newtron compensated ionization chamber, Model RS-C1-2514-115, to Mexico
 * Reuter-Stokes, Inc B-9786 83/09/19 2pp 20926 357
- B310260036 Forwards application to export spare valve assembles & parts for support of installed units on fuel handling equipment to Angentina
 DAVIS.E H Marotta Scientific Controls.Inc 03/10/05 Assistant Director for Export/Import & International Safeguards 1pp 20921 357
- --8310260042 Application for license to export spare valve assemblies 'parts for support of installed units on fuel handling equipment to Argentina DAVIS.E H Maretta Scientific Controls.Inc 80 60151 83/10/04 ip 20921 358
- 8310260039 Amend 1 to GE import license, extending expiration date 10 870101 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/10/18 2pp 20921 355
- 8310240057 Amend 1 to Eberline Instrument Corp export license, revising Condition 9 to take into account recent changes to IOCFR71 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards SO NO 894259 83/10/19 2pp 20721 352
- 8310260064 Application for license to export 0 008 g Np-237 standardized solution to Canada * Amersham Corp 83/10/17 1p 20921 318
- 8310260068 Forwards application for license to expert spare parts for ball spline assembles that load & unload fuel elements into reactor to Canada BCHAUB. J B General Motors Corp 83/10/06 HEMBY. E Assistant Director for Expert/Import & International Safeguards ip 20918 361
- --8310260073 Application for license to export spare parts for bell spline assemblies that load & unload fuel elements into reactor to Canada SCHAUB. J B General Motors Corp WD 84100 83/10/03 ip
- 8310260079 Requests Executive Branch position re C-E applications for license to export 10 nuclear fuel reloads nuclear fuel for initial core & 950 to 1.3000 electrical MW NSBS to Egypt ZIMMERMAN.U V. Assistant Director for Export/Import & International Safeguards 83/10/20 STOIBER.C R State. Dept of ip
- 8310240323 Application for license to import natural U ore concentrates, containing approx 1,500,000 lb U-308 MDYER,R E Pathfinder Mines Corp 83/10/18 MOORE,N Assistant Director for Export/Import & International Safeguards 1p 20918 345
- B31026032B Amend 2 to Eberline Instrument Corp export license, revising Condition 9 on Page 2 to take into account recent changes to 10CFR71.effective B30906 Timber Corp Export/Import & International Safeguards 80 NO 894286 B3/10/19 2pp 20918 346
- B310270074 Responds to FQIA request for info re nuclear cooperation between South Africa & US for period of 1960-65 Forwards documents listed in App A Documents also available in PDR DDE should be contacted for further info FELTON.J M Division of Rules and Records B3/10/11 KETTENRING.N E New Hampshire, Univ of, 3pp 20942 195
- --B3i0270080 Forwards License XR-42 for cancellation W/o encl KELLY, J P Treasury, Dept of, U S Customs Service i-WiM-JTC 1G 66/01/27 Atomic Energy Commission ip 20742 198
- --8310270072 Expresses appreciation for expeditious handling of Export License XR-42 ABEL, L E Allia-Chalmers Corp 63/11/14 CASE, E G Atomic Energy Commission ip 20742 200
- --B310270097 Advises of issuance of amend to License XR-42, increasing total price & extending expiration date to 651231 PRICE,E R Atomic Energy Commission 63/11/14 LYONB, T D Allis-Chalmers Corp 2pp 20942 201
- --B310270100 Authorizes clearance of partial shipment on 631115 against License XR-42.permitting export of nuclear reactor to South Africa.Amended license forthcoming PRICE.E R Atomic Energy Commission 63/11/14 COLLIGAN,W Treasury, Dept of, U.S. Customs Service 2pp 20742.203

- --B310270105 Application for amend to Export License XR-42, extending date to 651231 & increasing value LYONS:T D Allis-Chalmers Corp 63/11/12 MASON,N D Atomic Energy Commission, 2pp 20742 205
- --8310270107 Forwards License XR-42 issued to Allis-Chalmers, covering matt destined for South Africa, for placement in file No shipments made yet MESSING, A W Affiliation Unknown 61/12/18 Treasury, Dept of U S Customs Service Ip 20942 207
- --8310270113 License for Allis-Chalmers Mfg Co to export nuclear reactor to South Africa KIRK,R L. Atomic Energy Commission 61/06/14 2pp 20942 209
- --B310270116 Informs of 610620 FR publication of notice of issuance of License XR-42 to Allis-Chalmers Mfg Co, authorizing export of nuclear reactor to South Africa FREDERICK, R J Atomic Energy Commission 61/06/21 Atomic Energy Commission ip 20942 209
- --B310270122 Informs of issuance of license to Allis-Chalmers Mfg Co. authorizing export of 20,000 kW thermal nuclear reactor to South Africa KIRK, R L Atomic Energy Commission 61/06/15 RAMEY, J T Congress (Joint & Rotating Committees, etc.) 1p 20942 211
- --8310270133 Forwards License XR-42 issued to Allis-Chalmers Mfg Co. authorizing export of nuclear reactor to South Africa Govt of South Africa should be advised that license does not imply Commission assumption of responsibility for safety LOWENSTEIN, R Atomic Energy Commission 61/06/14 WELLS.A A Atomic Energy Commission 1p 20942 213

- ---8310270139 Forwards Lirense XR-42, authorizing export of nuclear reactor to South Africa W/o encl KIRK, R. L. Atomic Energy Commission 61/06/14 NICKEL, H C Allis-Chalmers Corp. ip 20942 214
- --B310270144 Informs that since no request for formal hearing filed.
 License XR-42 issued to Allis-Chalmers Mfg Co.authorizing
 export of nuclear reactor to South Africa
 LOMENSTEIN.R Atomic Energy Commission 61/06/14 PRICE.H L
 Atomic Energy Commission 1p 20942 215
- --B310270147 Notice of issuance of License XR-42 to Allis-Chalmers Mfg Co.authorizing export of nuclear reactor to South Africa KIRK,R L. Atomic Energy Commission 61/06/14 ip 20942 216
- B310270540 Amend 1 to Eberline Instrument Corp export license, revising Condition 9 on Page 2 to take into account recent changes to 100FR71, effective 830904 ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards 80 ND 894286 83/10/19 2pp 20938 035
- 8310270543 Amend 2 to GE export license, extending expiration date to 870101
 ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards BDW 79202 83/10/19 2pp 20938 037
- 8310280026 Forwards application to export 4 879 kg U-235, contained in 10 747 kg U hexafluoride to Switzerland HANNETT, B A Transnuclear, Inc. NUK-431 d3/10/13 MOURE, N Office of International Programs, Director ip 20964 136
- --B310280033 Application for license to export 4 879 kg U.contained in 10 747 kg U hexafluoride to Switzerland End use statement encl HANNETT, B A Transnuclear, Inc NUK-431 B3/10/13 7pp

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAMODT, N O	8310260294	50-287 0	ALDEN, W M	8310200263*	50-277 R	ANDERSEN: M W	8310210090	50-331 S
ANEL, L E	B310270092*	FOIA	ALDEN, W M	8310200264*	50-277 R	ANDERSEN, M W	8310270290	50-331 8
abelson, H	8310260346	50-461 A	ALDERSON, C E	8310110059*	50-413 Q	ANDERSON, C	8310060012*	50-410 G
ABRAMB, R	8310170009	TOPREP	ALEXANDER C N	8310240060*	50-413 T	ANDERSON, C	8310190180*	50-443 G
ADSTON, CO 9	B310240176#	FOIA	ALEXANDER, I	8310240218*	50~528 0	ANDERSON, C J	8310200270*	50-289 Q
ABSTON, O Q	8310280214*	50-400 A	ALEXANDER, I	8310240239*	50-528 0	ANDERSON, P D	B310050224	NUREG
ABSTON, O 9	83102802224	50~400 A	ALEXICH, H P	8310030386	50~315 P	ANDERSON P H	8310140119*	50-275 R
ABSTON, O G	8310280236*	50-400 A	ALEXICH, M P	9310030391	50-315 F	ANDERSON P H	8310280164	50-400 G
ABSTON, O Q	8310280248*	50~400 A	ALEXICH. M P	8310030579*	50~315 F	ANDERSON, P H	8310280164	50~400 Q
ABSTON.O 9	8310280256*	50-400 A	ALEXICH, M P	8310050563	50-315 P	ANDOGNINI, G C	8310040307	₽R
ACE: J. K	Ø310180576*	CONTRACT	ALEXICH. M P	8310040004	50-315 P	ANDROSIK, R	8310250587	50-317 9
ADAMS, C	8310250147	ORQ .	ALEXICH, M P	8310140040	50-315 P	ANDROSIK, R	8310280081	50-317 9
ADAMS, C	8310250414	50-275 G	ALEXICH, M P	8310200158	50-315 P	ANDRUS N J	8310140295	40-4492
ADAMS, C	Ø310250591	50-312 P	ALEXICH, M P	8310270196*	50-315 F	ANTHONY R L	8310190040	50-352 G
ADAMS, F T	0310120415*	50-261 P	ALIKONIS,N A	8310070210*	CONTRACT	ANTHONY, R L	8310190044*	50-352 G
ADAMS, F T	8310120422*	50-241 P	ALLAN, J M	8310110139*	70-1487	APOSTOLAKIS, O	#P810200184	50-275 T
ADCOCK, B. R	#E1401201EB	50-170 F	ALLAN: J M	8310240181*	FOIA	APOSTOLAKIS.G	8310200184*	50-275 T
ADDIB, B Q	Ø310240040*	50~413 T	ALLAN, J M	8310260021*	FOIA	U LIGNARA	8310140045	50-373 S
ADDISON, E T	0310210295	50-352 H	ALLAN, J. M.	9310260023*	FOIA	ARANDIJ J	8310140069	50-373 8
ADENSAM, E. G	1040500158	50-329 F	ALLAN, J H	8310260038*	FOIA	ARCHITZEL, R	@310310530*	50-317 G
ADENBAM, E Q	4040000168	50-329 F	ALLAN, J M	8310260056#	FOIA	ARCHITZEL, R E	8310200107#	50-317 0
ADENSAM, E Q	Ø310120043	50-327 P	ALLAN, J M	8310240076*	FOIA	ARGYROS, D	8310270527	50~219 9
ADENSAM, E G	B310120046*	50~327 P	ALLAN, J M	8310260077*	FOIA	L LEAT RA	8310030262	50-251 S
ADENSAM, E Q	B310120050*	50-327 P	ALLAN, J M	8310260100*	FOIA	ARIAS.J	8310270277	50-251 6
ADENSAM, E Q	g310120056*	50-327 P	ALLAN, J M	8310260138*	FOIA	ARMBRUGT.A J	8310170390	27-39
ADENBAM, E Q	B310130029	50-326 P	ALLAN, J M	8310260153*	FOIA	ARMSTRONG. 5	8310160321*	50-4B2 E
ADENSAM, E 0	8310130039*	50-328 P	ALLAN, J M	8310260157*	FOIA	ARMSTRONG, S	8310180325*	50-482 E
ADENSAM, E O	8310170133	50-327 P	ALLAN, J M	8310260161*	FOIA	ARMSTRONG.W	B310110509*	FOIA
ADENBAM, E Q	8310170254*	50-327 P	ALLAN, J M	8310260167#	FOIA	ARNOLD, G A	8310120005	50~201 I
ADENSAM, E G	831017028 <i>9</i>	50-395 P	ALLAN, J. M	8310260176*	FOIA	ARNOLD, R C	8310130088	50-320 P
ADENSAMIE Q	B310170710	50-369 P	ALLAN, J M	8310240182*	FOIA	ARNOLD, R C	8310130114	50-289 P
ADENSAM, E G	831017071 <i>9</i> *	50~369 P	ALLAN, J M	8310260207#	FOIA	ARNOLD, R. C	8310180537	50-320 P
ADENSAM, E G.	8310170725	50-370 A	ALLAN, J H	8310260213*	FOIA	ARNDLD,R C	8310180548*	50-320 P
ADENSAM, E Q	0310180604	50-484 A	ALLAN, J. M	#75E04201EB	FOIA	ARNOLD,R C	8310180548*	50~320 P
ADENBAM, E Q	#4040B101EB	50-424 A	ALLAN, J M	8310260327*	FOIA	ARNOLD, R C	8310180548*	50-320 P
ADENBAM, E, O	8310210106	50-424 M	ALLAN, J M	8310260337*	FOIA	ARONIN, L	B310270577*	CONTRACT
ADENBAM, E Q	8310210109*	50~424 M 50~328 P	ALLAN, J M	8310260345*	FOIA FOIA	ASMUND, V C	8310170675#	70-984
ADENBAM, E. O	8310210341 8310280037	50-328 P 50-369 P	ALLAN, J. M ALLAN, J. M	8310260372* 8310270547*	50-277 B	ASSELSTINE, J K	#910030319#	50-309 B
ADENSAM, E. C ADENSAM, E. C	6310260037	50~438 A	ALLEN, D. R	8310210073*	CONTRACT	ASSELSTINE J K	8310200364* 8310240251*	FOIA 50-528 G
						ASSELSTINE J K,	8310240231#	30-358 0
ADISOMA, O. S	8310070414	NUREO	ALLEN, M. T	8310190238	50~324 8	ATKINGON: R V	8310250047	50-352 H
ADLER, M	8310240173#	FOIA	ALLEN, W.F	8310170198*	50-423 A	ATWOOD, C. L.	8310050331	NUREG
ADLER, M	8310240175*	FOIA	ALLIBON, D P	8310190270*	50-454 9	AUDETTE, R	8310240195*	FDIA
AFTERODOD, 8	8310190035	FOIA	ALLUM, A E	8310240056*	50-413 T	AULICK, D D	#E910060193*	50-400 G
AGEE, J R	8310250206*	GA999	ALGUIST.A E	8310240149	50-275 U	AULICK, D D	#E910060193*	50-400 Q
AQDSTI, F. E	8310210052	50-341 A	ALSWORTH, M	8310040565*	50-382 A	AULICK, D D	#E0204001EB	50-400 Q
ACOBTI.F.E.	0310210201	50-341 A	ALTMAN W D	8310180517*	50-275 P	AULICK, D D	8310040203*	50~400 Q
AHEARNE, J	8310270138*	FOIA	ALTMAN W D	8310200457*	COMMISSION	AULICK D D	8310090353	50-400 Q
AHNED, I H	8310050497*	50-341 Q	ALTMAN H D	8310200461*	COMMISSION	AULICK D D	8310040353	50-400 G
AHMED, N	8308180560*	50-346 P	ALTMAN, W D	8310200463*	COMMISSION	AULICK, D.D.	8310170543	50-400 G
ALAMQIR, M	8310310209	NUREO	ALTMAN, W. D.	8310200464*	COMMISSION	AULICK, D D	8310170543	50-400 9
ALBRIGHT R H	8310040168*	50-261 G	AMOB. C. N.	6310070110	NUREG	AULICK, D D	#80407101CB	50-400 Q
ALBRIGHT R H	8310250477*	50-324 Q	ANANDAPPA, A	0310210127	50~237 B	AULICK, D D	8310170608*	50-400
ALBRIGHT R H	8310250501*	50-324 0	ANDERBEN, J C	8310180085 8310190068	NUREQ 50-331 R	AULUCK, R	8310130212	50-397 A
ALDEN: W M	B310200261*	50-277 R	ANDERSEN, M	6310140098	90-991 K	AULUGK, R	8310130426	50-397 @

AUTHOR	ACCESSION NUMBER	SUBJE CATEG		AUTHOR	ACCESSION NUMBER	SUBJE CATEG	ORY	AUTHOR	ACCESSION NUMBER	SUBJE	
AUSTIN, C AUSTIN, M A AUSTIN, M A AUSTIN, M A AUSTIN, M A AXELRAD, J	8310120108 8310070028 8310070035 8310070040 8310250273	* 70-364 * 70-364 * 70-364 * TOPREP	R	BAJADA.E C BAXER.D A BAKER.K R BALDWIN.C R BALDWIN.M S	8310270038 8310070442 8310040030 8310240057 8310170098	TOPREP NUREG PR # 50~413	r s	BAUBLITZ, J E BAUBLITZ, J E BAUER, T L BAUER, T L BAUEREIS, E I	8310030605 8310130067 8310110396 8310110429 8310120262	WASTE # 50~192	MOT F
AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J	8308310105 8310030440 8310030520 8310040214 8310050536	50-344 I&E 50-272 I&E	s	BALL.C G BALL.C G BALL.IC G BALLINGER.P L BANAGAS.L J	8310110369 8310110375 8310110384 8310190024 8310040207	* F01A	R S	BAUNACK,W BAXTER,TA BAXTER,TA BAXTER,TA BAXTER,TA	8310140166 8310310146 8310310146 8310310200 8310310200	* 50-289 50-400 50-400 50-483 50-483	0000
AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J	8310060005 8310060072 831014006 8310140237 8310180177	50–62 &E &E &E	8	Banerji, 9 k Banerji, 8 k Baramore, 8 Baramore, 8 Baran, R	8310170308 8310200409 83101900429 83101900479 8310190031			BAYBUTT.P BAYBUTT.P BAYNE.J.P BAYNE,J.P BAYNE,J.P	8310110475 8310110480 8310040291 8310070248 8310070340		Ų P
AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J AXELRAD, J A	6310180413 6310210030 8310310404 8310050078 8310130144	1&E 50-329 40-299 50-250 50-410	а а а	Baranoh, S W Baranoh, S W Baranoh, S W Baranoh, S W Baranoh, S W	8310170540* 8310170564* 8310170567* 8310170571* 8310170575*	50-327 50-327 50-329	G G G	PAYNAB T. JAYNAB T. JAYNAB T. JAYNAB T. JAYNAB	8310070349 8310110112 8310110222 8310110228 8310130113	50-286 50-286 50-286 50-286 50-333	6 6 6 6
AXELRAD, J. A AXELRAD, J. A AXELRAD, M AXELRAD, M AXELSON, W L	8310190226 8310270493 8310120036* 8310180354 8310180116	50-275 50-456	Q I T Q	Barandw, s w Barandw, s w Barandw, s w Barandw, s w Barandw, s w	8310170598# 8310170602# 8310170606# 8310170610# 8310170036#	50-329 50-329 50-329	0 0 0 0	BAYNA T. JAYNAB T. JAYNAB T. JAYNAB P. JAYNAB	8310140196 8310170480 8310170554 8310170655* 8310210126	50-333 50-333 50-286 50-333 50-333	р 0 р
AXELSON, W L	8310180187 8310180195 8310180197 8310180202 8310180203	50-373 50-282 50-358 50-346 50-255	0 0 0	Baranow, S w Barletta, R e Barnes, I Barnes, I Barnes, I	8310270176* 8310310114 8308300722* 8310030352* 8310030459*	50-327 NUREG GA777 GA777 GA777	Q.	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8310240114 8310240185 8310280044 8310310043 8310310066	50-286 50-286 50-333 50-333 50-386	PFPP
AXELSON, W L	8310180205 8310180206 8310180215 8310180233 8310180238	50-305 50-331 50-440 50-546 50-254	0 0 0	Barnes, I Barnes, I Barnes, I Barnes, I Barnes, I	8310040249* 8310180358* 8310180378* 8310180519* 8310250008*	GA999 GA999 GA999 GA999 GA999		BAYNE, J P BAZIN, J P BAZIN, J P BEACH, Q	8310310364 8310110086 8310110185 8310110494 8310250169	50~333 CONTRACT CONTRACT CONTRACT 40~6422	q r
AXELSON, H L	8310180260 8310180262 8310180265 8310180268	50-483 50-266 50-155 50-329 50-10	G G G	BARNES, I BARNES, P L BARNES, P L BARNES, P L BARNES, V E	8310250526* 8310120061 8310120290 8310200273 8310130134*	GA779 50-265 50-373 50-237 MIGC	Q Q P	BEACHUM, S B BEAMER, U H DEARD, J T BEARDEN, D A	B310120221* B310240033* B310110097* B310110404 B310030311	50-155 50-413 FOIA MISC PR	Ť
AXELBON, W. L. AXELBON, W. L. AXELBON, W. L. AXELBON, W. L. AXELBON, W. L.	8310180271 8310180274 8310180283 8310180288 8310180289	50-461 50-407 50-295 50-263 50-341	0 0 0 0	BARNETT,B J BARR,K BARR,K P BARR,K P BARR,K P	8310280166 8310140170* 8310040168* 8310040340* 8310040497*	50-483 50-320 50-261 70-143 50-321	M G G	BEATIY.E J BEAVER.B BEAHOCFER.B BECHHOCFER.B O BECHHOCFER.B O	8310250217 8310110421* 831027014* 8310120011* 8310120015*	50~244 50~369 50~369 50~201 50~201	9 F I I
AXELSON, W L	8310180374 8310250575 8310310318 8310310342	70-2977 14E 50-341	a a	BARR.K P BARR.K P BARR.K P BARR.K P BARR.K P	8310040508* 8310040637* 8310250328* 8310250387* 8310250428*	70-27 70-1151 50-280 50-348 50-338	0 0 0	BECHHOEFER, B Q BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	8310120023* 8310120047* 8310030514 8310110210 8310280100	50-201 50-201 50-329 50-329 50-329	1 0 0
AXTELLIC E BACHMANN, R C BACHMANN, R C BACKUS, R A BACKUS, R A	83100403/3# 8310170473 8310250160 8310030355	50-155 50-266 50-155 50-443	T T Q Q	BARRIK P BARRIK P BARRIK P BARRIK P BARRIK P	8310250477* 8310250501* 8310250540* 8310250554* 8310250421*	50-324 50-324 50-369 70-1113 50-335	G G	BECHHDEFER, C BECIA, I J BECK, C K BECK, C K BECK, J W	8310310211 8308310512# 831026095# 8310260130# 8310275#	50-327 50-267 FOIA FOIA	о О
BACKUB,R A BACKUB,R A BACKUB,R A BACKUB,R A BACKUB,R,A	8310110227 8310110227 8310120107 8310120107	50-443 50-443 50-443		BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H BARRETT, L H	8310050144 8310050326 8310060144 8310060181 8310110531	50-320 50-320 50-320	R R R P	BECKER, B D BECKER, B D BECKER, B D BECKER, B D BELANGER, J	8310060321* 8310060321* 8310180279* 8310180279* 8310270384	50-454 50-454 50-454 50-454	. 0000в
BACKUB, R. A. BACKUB, R. A BACKUB, R. A BACKUB, R. A BACKUB, R. A	B310120111# B310120115# B310120115# B310120122#	50-443 (50-443 (50-443 () })	BARRETT, L H BARRETT, L H BARRY, Z E BARTH, C	8310180007 8310180122 8310190245 8310270354* 8310170626		3	BELL, O H BELL, J BELL, J M BELL, M J BELL, N	B310240043# B310140166# B310260204# B310240242 B310210063	50-413 50-289 FOIA WASTE MOT	r e
BACKUS, R A BACKUS, R A BACKUS, R A BACKUS, R A	8310120126# 8310120126# 8310120135# 8310120135#	50-443 0 50-443 0 50-443 0) 	BARTHIC A BARTHIC A. BARTHIC A BARTHIC A	8310030508 8310050565 8310170632# 8310250125 8310250167	50-400 6 50-400 6 50-400 6 50-400 6) }	BELLOTTI,F X BELLOTTI,F X BELLOTTI,F X BELTRACCHI,L BEMIB,P	8310040254 8310040252* 8310040277* 8310130393 8310250339*	50-443 (50-443 (50-443 (NUREQ	P 0 0
BACKUB,R A BAER,R E BAER,R E, BAETBEN,L A BAILEY,F C.	8310120141* 8310040391* 8310180161* 8310120206	50-443 Q 50-443 Q 50-382 Q 50-298 Q 50-305 F		Barth,c a Bartter,w.d Baskin,k p Baskin,k p Baskin,k p	8310250469 8310170243 8305240501 8310110128 8310110133*	50-400 G NUREG 50-204 P 50-361 P		BEMIS, P BEMIS, P R BEMIS, P R BEMIS, P, R BENAROYA, V,	8310250627* 8310250627* 8310040332* 8310040613* 8310250632* 8308180258*	50-261 (50-324 (50-400 (50-400 (() () () ()
BAIR, O, O, BAIR, O, O BAIRD, J, B BAIRD, J, B. BAIRD, J, B,	8310140246 8310250444 8310030457* 8310160246*	50-344 8 50-344 B 50-267 Q 50-265 Q		BASKIN, K P BASS, C H. BASSETT, H S BASSO, L F BASSO, L F,	8310200400* 8310200154	50-361 8 COMMISSION 50-440 A 50-318 8		BENNETT.C J BENDIT.H BENZ,E F BERBERIAN,M J BERG,J P	8310250293 8310070432* 8310040369* 8310070301 8310170101	50-254 P CONTRACT 50-155 T 50-10 8	г
BAIRD, J B BAISDEN, L. BAISDEN, L. BAISDEN, L.	8310170040 8310170040 8310210083	50-799 G CONTRACT CONTRACT CONTRACT		BASSO, L F BASSO, L F BATES, J H. BATTERSON, B BATTERSON, B	8310250599 8310040342* 8310190012	50-318 8 50-318 8 70-824 50-29 R 50-307 R		BERGER, J D BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	8310170011 8310110071 8310170383 8310170383 8310170383	FOIA 40-86 50-329 50-329 60-329 50-329 0) }

AUTHOR	ACCESSION NUMBER	GUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	8310170393 8310170427 8310170427 8310170524 8310170524	50-327 G 50-327 G 50-327 G 50-327 G 50-329 G	BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L	8310110280 8310110280 8310120395 8310120395 8310170398	50-382 0 50-382 0 50-289 0 50-289 0 50-382 0	BOOKER, J E. BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8310270181 8310280011 8310280030 8310280053 8310280084	50-458 50-458 50-458 50-458 50-458
BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L BERNABEI, L	8310170050 8310240174 8310240215* 8310270345 8310270345	50-329 G 50-528 G 50-528 G 50-329 G 50-329 G	BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L BLAKE,E L	8310170398 8310180355 8310180355 8310200211 8310200211	50-382 0 50~287 0 50-287 0 50-287 0 50-287 0	BODKER, J E BODTH, L F BORDENICK, B M BORDENICK, B M BORDENICK, B M	8310280117 8310060079 8310050359 8310050378 8310050395	50-458 70-143 50-322 50-322 50-322
BERNADEI.L BERNHOFT.S L DERNHOFT.S L BERNSTEIN.B	8310280145 8310280145 8310210304 8310210317 8310190213	50-329 6 50-329 6 50-305 5 50-305 6 50-333 6	BLAKE,EL BLAKE,E.L BLAKE,EL BLAKE,EL BLAKE,EL	8310210249 8310210249 8310310195 8310310195 8310310198	50-287	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDINE, T C	8310050427 8310130245 8310250122 8310250491 8310040244	50-322 50-322 50-322 50-322 50-155
BERNTHAL, F BERRY, L E BERRYMAN, R M BERTUCCA, J BERG, J E	8310180145 8310210223 831019057* 8310070414 8310130252*	50-247 G 50-251 S 50-280 P NUREO 50-458 G	BLAKE, E L Blake, E L Blake, E. L Blake, J Blake, J	8310310198 8310310382 8310310382 8310270224 8310040283*	50~289	BORDINE, T C BORDINE, T C BORDINE, T C BORDINE, T C IORDINE, T C	8310120110 8310130296 8310170465 8310170486 8310170552	50-155 50-155 50-155 50-155 50-155
BESS.JE BETOURNE,G P BETTENHAUSEN.L BIBD.H E BIBD.H E	8310170483 8310130218* 8310040044* 8310040454* 8310250528*	50-445 T 50-155 T 50-388 Q 50-335 Q 50-335 Q	BLAKE, J J Blake, J J Blake, J J Blake, J J Blake, J J	8310040316* 8310040427* 8310250259* 8310250300* 8310250404*	50-250 Q 50-390 Q 50-259 Q 50-327 Q 50-413 Q	BORDINE, T, C BOTIMER, L BOTIMER, L, A BOTIMER, L, A BOUCHEY, G, D	8310270245 8310240067 8310240023 8310240033 8310200357*	50-155 50-329 50-329 50-329 FOIA
BICEHOUSE, H J BICKWIT, L BIDINGER, G H BIDINGER, G H BIDINGER, G H	8310120217* 8206100323* 8310040144 8310110599 8310240078	50-277	BLAKE, J J BLANC, G A BLANKEMEYER, J BLEBBING, J	8310250464* 8310260175* 8310260177* 8310120322 8310140080*	50-280 Q FDIA FDIA 50-346 B 50-302 P	BOUKNIGHT,R J BOUKNIGHT,R J BOUKNIGHT,R J BOUKNIGHT,R J BOURNIA,A	8310040465 8310070278 8310310392 8310310394 8310130194	50-375 50-375 50-375 50-375 50-374
BIGOS.J M BIRKENHEIER.J BIRKENHEIER.J BISBEE.G D	8310180347* 8310240014* 8310190054 8310190054 8310030397	50~275 T 50~413 T 50~322 G 50~322 G 50~443 G	BLOCH, P.B BLOCH, P.B BLOCH, P.B BLOCH, P.B BLOCH, P.B	8310040184 8310110266 8310130194 8310140018 8310140083	50-155 Q 50-445 Q 50-155 Q 50-445 Q	Bowmaker, n J Bohman, 9. m Boyack, b e Boyd, d Boyd, d	8310310055 8310170057# 8310200389 8310210122 8310210151	50-317 50-280 NURE9 50-316 50-255
819HOP,T W BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W	8310030107 8310030142 8310030145 8310030149 8310030154	50-206 V 50-397 V 50-344 V 50-312 V 50-528 V	BLOCH, P B BLOCK, S BLOSBOM, J N BLOUGH, A R	8310270228 8310270273 8310050478* 8310030197 8310140068	50-445 0 50-445 0 50-155 T 40-8452 50-277 8	BOYD, D C. BOYD, D C BOYD, D C BOYER, L	8310040255* 8310060374* 8310240096* 8310240100* 8310060567*	50-255 50-155 50-295 50-315 50-324
BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8310030285 8310040532 8310120172 8310120248 8310170428	50-275 V 50-528 G 50-397 G 50-397 G 50-397 G	BLOUGH, A.R. BLOUGH, A.R. BLUBAUGH, R.E. BLUMBERG, N.BOARDMAN, J.R.	8310210278* 8310310361 8310170106 8310140166* 8310040877*	50-277	BOYER, L E BOYER, R, E BOYER, V, 9 BOYER, V 8 BOYER, V 8	8310040544* 8310270206 8310110300* 8310110307* 8310120388*	50-324 50-312 50-352 50-352 50-352
BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8310170468 8310170473 8310170481 8310170612 8310170653	50-528 G 50-275 G 50-397 G 50-397 G 50-508 G	BOARDMAN,J R BOATRIGHT,P A BOBE,P E BOBE,P C BODDY,J R	8310180414* 8310130247 8310280168* 8310280171* 8310030210*	50-498 Q 71-5908 50-266 S 50-266 S 40-858,	BOYER, V S BOYER, V. S. BRACKENBUSH, L BRACKMAN, T. W BRADBURY, R B	8310140101* 8310280127 8310260381 8310120055* 8310120255	50-352 50-352 NUREO CONTRACT PR
BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8310180331 8310180347* 8310180477 8310200175 8310200180	50-397 0 50-344 0 50-361 8 50-275 H 50-275 0	BODINE, J C BOOART, A BOHN, M P BOISVENUE, L BOLD, E R	8310270094* 8310140266* 8310110032 8310200331 8310250011*	50-244 F 50-302 R NUREQ XPDRTLIC GA999	BRADFORD, L BRADFORD, W H BRADLEY, E J BRADLEY, E J BRADLEY, E J	8310270372 8310040384* 8307130054 8310050437 8310070243	50~287 50~348 50~352 50~352 50~352
BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W	8310200194 8310200208 8310210043 8310210055 8310250348*	50-397 Q 50-206 G 50-397 Q 50-397 Q 50-275 P	BOLDN, A E BOLDN, A E BOMBERGER, C BOMBERGER, C BOMBERGER, C. R	8310110099 8310110113* 8308180560* 8309020392* 8309060263*	50-123 V 50-123 V 50-346 P 50-277 P 50-315 P	BRADLEY, E J BRADLEY, E J BRADLEY, E J. BRADLEY, E J BRADLEY, J	8310140097 8310140101* 8310140278 8310250035 8310110024*	50-352 50-352 50-352 50-352 50-155
BISHOP.T W BISHOP.T W BISHOP.T W BISHOP.T W BISHOP.T W	8310280036 8310280060 8310310246 8310310274 8310310276	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0	BDOHER, H R BDOKER, J E BDOKER, J E BDOKER, J, E,	8310170751 8307260003 8310030549 8310040126 8310040130	50-289 P 50-458 A 50-458 8 50-458 B	BRADLEY, W H. BRADLEY, W H. BRADY, J. A. BRADY, J. A BRAILE, L W	8310210186 8310240057* 8310200443* 8310270376* 8310280131	50-413 50-413 50-320 50-289 RES
BIGHOP.T W BISHOP.T W BISHOP.T W BIGSETT.P H BITTER.D B	8310310339 8310310394 8310310401 83101190251* 8310110505*	50-275 0 50-528 0 50-312 0 50-334 0 FOIA	BOOKER' 7 E BOOKER' 7 E BOOKER' 7 E BOOKER' 7 E	8310040318 8310040474 8310060074 8310070317 8310130183	50-458 B 50-458 S 50-458 A 50-458 A	BRAMLETT, L, S, BRANAGAN, E F BRANDENSURG, B BRANNIN, J, P, BREAUX, D Q	8310170045 8310170626 8310270124 8310250060 8310250270+	50-368 50-400 6 FOIA 50-389 6 QA999
BLACK, S BLACK, S BLACK, S BLAIR, L R BLAKE, E L	8208230434* 8209010314* 8210050447* 8310110359 8310030351	50~382 G 50~382 G 50~382 G FDIA 50~289 G	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8310130210 8310130215 8310130254 8310130258 8310130322	50-458 8 50-458 8 50-458 8 50-458 8 50-458 8	Breen: J. Brenner: L. Brenner: L Brenner: L Brenner: L	8310240209* 8310040183 8310040187 8310050537 8310060192	FOIA 50-352 50-352 50-322 50-322
BLAKE, E. L.	8310030351 8310030403 8310030403 8310040372 8310040372	50-287 0 50-287 0 50-287 0 50-287 0 50-287 0	BOOKER' 7 E BOOKER' 7 E BOOKER' 7 E BOOKER' 7 E	8310180269 8310180303 8310180305 8310180460 8310180461	50-458 8 50-458 8 50-458 8 50-458 8 50-458 8	BRENNER, L BRENNER, L BREY, H L. BREY, H L. BREY, H L	8310110052 8310240188 8310040169 8310130286 8310210253	50-352 50-352 50-247 50-247 50-267
BLAKE,E L. BLAKE,E L. BLAKE,E L BLAKE,E L BLAKE,E L	8310110205 8310110205 8310110224 8310110224 8310110272	50-289 Q 50-289 Q 50-289 Q 50-289 Q 50-289 Q	BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8310210149 8310210175 8310210201 8310210221 8310210262	50-458 S 50-458 S 50-458 S 50-458 A 50-458 S	BRICKLEY,R H BRIDEN,D W BRIDGES,T L BRIGGS,L E BRIGHT,O D	8310040596* 8310110087* 8310250570* 8310190203* 8310040192	GA999 50-346 50-409 50-352 50-142

4

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BRIGHT, G O BRIGHT, G O BRIGTON, H H BROCARD, D N BROCK, B L	8310110218 8310260263 8310040628* 8310030645* 8310030213*	50-400 6 50-142 6 70-1151 GEN TEC 16 XPORTLIC	BURNETT, R F BURNETT, R F BURNETT, R F	8310240226 8310240046 8310270494 8310270515 8310270571	70-1113 70-1257 70-1100 70-371 70-143	CARLISLE.C S CARLISLE.C S CARLISLE.C S CARLISLE.C S CARLSON.J D CARPENTER.G L	8310250425 8310250453 8310270444 8310270449 8310270364#	50-397 8 50-397 9 50-397 A 50-275 0 50-243 6
BROCOUM, S J BROCHL, D J BROCHL, D J BROCHL, D J BROMBERC, B	8310130152* 8310030341 8310030364 8310060258 8310070185	50-537 G FR PR 50-344 F CONTRACT	BURNS, L S	8310270589 8310180152* 8310130004 8710210044 8310280148*	70~135 50~332	CARPENTER, J H CARPENTER, T CARR, A V CARR, A V CARR, A V	8310110218 8310260016 8310110068 8310110068 8310110294	50-400 0 FOIA 50~491 G 50-491 0 50-413 0
BROMBERG, B BRONS, J C BRODKS, E H BROOKS, H L	8310070431 8310170603 8310170202 8310040274+ 8310050401*	CONTRACT 50-286 R 50-286 R 50-269 G 50-413 T	BUSH, M W	8310310370 8310110029* 8310190058 8310240212* 8310250517*	50-266 F CONTRACT 50-352 Q 50-528 Q 50-327 Q	Carrow, H Carrow, H Carrow, H Carrow, H Carrow, R	8310030441 8310030478* 8310260202 8310260209* 8310200082*	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-254 F
BROWN.C A BROWN.C H BROWN.G D BROWN.Q D BROWN.Q D	8310120324 8310170483* 8308150385* 8310190017 8310310375	TOPREP 50-263 Q 50-387 B 40-3453 40-8084		8310250424* 8310040146* 8310070231* 8310030274 8310030470	50-327 Q CONTRACT CONTRACT 50-416 S 50-416 S	CARTER, S E CARVER, A M CARVER, A M CASAUDON, M CASAUDON, M	8310180152* 8310050504* 8310040565* 8310130247* 8310130271*	50-352 0 50-155 T 50-382 A 50-400 E 50-400 E
BUOMN'S P BUOMN'S P BUOMN'S P BUOMN'S P BUOMN'S P BUOMN'S P	8310270370 8310030420# 8310180149# 8310270003 8310240070	50-358 H 50-458 Q 50-458 Q 50-213 F 70-1201	BYRD, R BYRD, R BYRD, R BYRD, R BYRD, R	8310040364 8310040417 8310060001 8310060002 8310060401	50~416 S 50~416 S 50~416 S 50~416 S 50~416 S	CASE, E 0 CASE, E 0 CASPER, R M CASSIDY, B P CASSIDY, H G	8310110111* 8310180572* 8310270189* 8310040510 8310260291	50-275 P 50-298 P FOIA 50-443 Q 50-546 G
BROWN, W B. BROWN, W B. BROWN, W B BROWN, W B	8310240074 8310240088 8310240099 8310240101 8310240210	70-143 70-27 70-2983 70-27 70-27	BYRD, R BYRD, R BYRD, R BYRD, R BYRD, R	8310070170 8310070192 8310070305 8310140122 8310170474	50-416 8 50-416 5 50-416 6 50-416 8 50-416 8	CABSIDY, T J CASTLE, J N CATCHPOLE, G J CATHEY, D CATHEY, D E	8310240051# 8310050224 8310180172 8310030438 8309040048	50-266 0 NUREG 40-8745 50-416 S 50-416 B
880AM' A B 880AM' A B 880AM' A B 880AM' A B	8310240214 8310240224 8310240225 8310240228 8310240227	70-143 70-1151 70-25 70-824 70-1151	BYRD, R BYRD, R BYRD, R BYRD, R	8310170512 8310170107 8310170111 8310210017 8310210182	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	CATHEY, D E CATHEY, D E CATHEY, D E, CATHEY, D E CATHEY, D E	8310030317 8310060025 8310060112 8310070239 8310120419	50-416 B 50-416 B 50-416 B 50-416 B 50-416 B
BROWN, W B BROWN, W B BROWN, W, B BROWN, W, B	8310240230 8310240231 8310240240 8310260029 8310260433	70-1151 70-143 70-1257 70-143 70-27	BYRD, R BYRD, H BYRD, H K BYRDN, P. M CAHILL, W J.	8310270235 8310270397 8310260090* 8310170643* 8310030232	50~416 6 50-416 9 FDIA 50~341 0 50~458 C	CATHEY, D E CATHEY, D E CATHEY, D E CATHEY, D E CATHEY, D E	8310140051 8310140041 8310170458 8310170078 8310170234	50-416 8 50-416 8 50-416 8 50-416 9 50-416 6
860MM' M B 860MM' M B 840MM' M B 840MM' M B	8310270536 8310270556 8310270562 8310270564 8310270626	70-135 70-27 70-824 70-364 70-1257	CAIN, J M GAIN, J. M Callan, L J Callan, L J Callan, L J	8310040559 8310260002 8310030476 8310130226* 8310130335*	50~387 A 50~382 A 50~348 S 50~313 G 50~313 G	CATHEY.D E CATHEY.D E CATTON.1 CAUSEY.J C CAVANAUGH.W T	8310140257 8310270336 8310050224 8310270327 8310070415*	50-416 8 50-416 8 NUREG 50-366 P CONTRACT
BROWN, WE BROWN, WE BROWNE, C I BROWNE, C V,	8310070293* 8310070295* 8310040601 8310070091* 8310040507*	50-324 F 50-324 F 40-8380 50-275 R 50-269 Q	CALLIHAN, D CALSOYAS, C CAMP, A L CAMPBELL, S CAMPBELL, W E	8310120026* 8310180607 8310190283 8310030347 8310270594	50-201 I 50-275 P NUREG 50-454 H TOPREP	CAYEN, C F CERNE, A CESARE, J G CHACKES, K M CHACKES, K M	8310170322 8310070232 8310170006 8310040225 8310040225	71-197 50-443 A 50-416 R 50-483 G 50-483 G
BROWNLEE, V BROWNBON, F BRUNE, R L. BRUNNER, J E BRUNNER, J E.	8310250256# 8310040079 8310190313# 8310250041 8310250073	50-269 G 70-143 FOIA 50-329 G 50-329 G	CANPE, K M CANTANO, R CANNY, J. CANTRELL, F B CANTRELL, F S	8310050441 8310120289* 8310240150 8310040384* 8310250190*	50-155 T 70-572 50-266 P 50-348 Q 50-259 Q	CHAFFE, A E CHAMBERS, G T CHAMBERB, G T CHAN, E I CHAN, E I	8310200214* 8310060380 8310270073 8310050216 8310050423	50-206 0 50-240 9 50-260 9 50-377 0 50-352 0
BRYANT, J BRYANT, J C. BUCKLES, J A BUCKLES, R	8310240507* 8310250256* 8310240032* 8310240119 8310190046	50-269 @ 50-269 @ 50-413 T 50-315 J FOIA	CANTWELL, PF CAPHTON, D CAPHTON, D. L. CAPLAN, JS CAPONE, DH	8310170609 8310200072# 8310190251* 8310190283 8310040297	50-304 8 50-271 9 50-334 9 NUREO PR	CHAN,E I CHAN,Y F CHANDLER,J C CHANDLER,J C CHANDLER,J C	8310250286 8310120218* 8310050470* 8310070260 8310140239	50-293 0 50-155 T 50-255 P TOPREP
IUCKLEY, B C	8310250026 8310250031 8310270255 8310170070 8310170124	FDIA FOIA 50-275 P 50-400 F 50-400 E	CAPRA,R A CAPRA,R A CARBEINER,R E CARDARELLI,R D CAREY,J J	8310170022 8310170747 8310170519 8310050110 8310040400	50-289 P 50-289 P 50-302 S 70-1257 50-334 G	CHANDLER, J C CHANDLER, J C CHANDLER, L J CHANDLER, L J CHANDLER, L J	8310140244* 8310210139 8310050454 8310130017 8310130019*	TOPREP TOPREP 50-275 0 50-275 0 50-275 0
UCKLEY, B. C UCKLEY, R UDMITZ, R UFE, J L UFE, J L	8310180185 8310250379* 8310070240* 8310070306 8310140123	50-400 F GA979 CONTRACT 50-302 S 50-302 S	CAREY, J. J CAREY, J. J CAREY, J. J CAREY, J. J CAREY, J. J	8310040561 8310120257 8310140208 8310180322* 8310180432	50-334 F 50-334 P 50-334 F 50-334 Q 50-334 F	CHANDLER, L J CHANDLER, L J CHANEY, H D CHANEY, H D CHANG, F K	8310250283 8310250467 8310060026* 8310060464* 8310070154	50-275 G 50-275 G 50-313 G 50-382 G NUREQ
UFE, J. L JFE, J. L JFE, J. L JNTING, J D JRCH, R. H	8310140187 8310140233 8310210021 8310060516	50-302 8 50-302 9 50-302 8 HASTE HOT 50-400 A	CAREY, J J CAREY, J J CARLEY, J CARLEY, A CARLEY, A	8310170017 8310210238 8310270154 8310270510* 8310270593*	50~334 R 50~334 P 50~334 P 50~155 F 50~155 F	CHANG, T Y CHAPLIN, S, CHAPLIN, B D CHAPLIN, S, D CHARNLEY, J S	8310110345 8310170060 8310200155 8310250434 8310050185	NUREQ 50-320 S 50-320 S 50-320 S TOPREP
		50-400 A 50-352 T 50-397 Q 50-271 R 50-329 Q	Carlible.c s Carlible.c s Carlible.c s Carlible.c s Carlible.c s	8307300331 8310120176* 8310120250* 8310170507* 8310180341*	50-397 8 50-397 0 50-397 0 50-397 0 50-397 0	CHARNOFF, G CHARNOFF, G CHARNOFF, G CHASNOFF, B A CHASNOFF, B A	8310170234 8310170234 8310170234 8310230049 8310230051	71-9010 71-9010 71-9010 27-39 27-39
		50-329 q VURE0 50-289 q 50-416 n	CARLIBLE.C. S CARLIBLE.C. S CARLIBLE.C. S CARLIBLE.C. S CARLIBLE.C. S	8310200200* 8310250088 8310250092 8310250144 8310250290	50-397 Q 50-397 A 50-397 S 50-397 S 50-397 S	CHAUDHARY, S K CHEN, P. CHEN, S CHEUNG, Y K CHIAPETTA, R L	83101702034 8310050500* 8301210240* 8310180076 8310120024*	50-352 Q 50-155 T 50-244 P NUREQ CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CHICHESTER. G CHICHESTER. G CHILK. S J CHILK. S J CHILK. S J	8310050508 8310050508 8310030419 8310030528 8310040217	50-443 H 50-443 H 50-289 G 50-445 G 50-483 G	CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CILLIS, M CILLIS, T C	8310190212 8310200102 8310200102 8310210256* 8305030115*	50-362 0 50-266 0 50-266 0 50-288 0 50-361 9	COLOMBO, R W CON, V N CON, V N CONDRA, R D CONE, T C	8310270452 8308030382* 8309200504* 8310170011 8310240271*	50-312 8 50-315 9 50-267 9 40-86 WASTE MOT
CHILK,S J CHILK,S J CHILK,B J CHILK,B J	8310040261* 8310040267 8310040274 8310040280 8310040302	FDIA 50-155 G 50-341 G 50-289 G 50-275 G	CIPOLLA.A J CLARDY, L S CLARK.D E CLARK.L CLARK, P R	8310170623 8310060145* 8310050239 8310130216 8310260143	40-3372 50-331 G NUREG 50-20 F 50-287 P	CONLON, T E	8310040042* 8310200057* 8310250236* 8310250380* 8310250452*	50-321 0 50-440 0 50-537 0 50-438 0 50-416 0
CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8310040197 8310040443 8310070209 8310070383 8310110049	50-266	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8310110521 8310270523 8310130232* 8310030147 8310030414	50-259 P 50-259 Q 50-341 A 50-348 F 50-348 P	CONN' N C CONTON' I E CONTON' I E CONTON' I E	8310250478* 8310250569* 8310270426* 8310040232 8310040331	50~348 Q 50~327 Q 50~440 Q 50~397 F 50~397 8
CHILK'S A CHILK'S A CHILK'S A CHILK'S A	8310110050 8310110061 8310110114 8310110151* 8310110223	50-289 G 50-440 G 50-275 U 50-275 U 50-289 G	CLAYTON.FL CLAYTON.FL CLAYTON.FL CLAYTON.FL CLAYTON.FL	8310040377* 8310040387 8310040436 8310060096 8310060138	50-348 Q 50-348 P 50-348 F 50-348 P 50-348 P	CONN. W 9 CONNAUGHTON, K CONNER, E CONNER, E L CONNER, E L	8310250505 8310040430* 8310140166* 8310050455 8310190203*	50-397 8 50-454 Q 50-287 Q 50-352 A 50-352 Q
CHILK'S T CHILK'S T CHILK'S T	8310110238 8310120405 8310120412 8310130123 8310130224	50-287 0 50-341 Q 50-275 G 10CFR 50-440 G	CLAYTON, F.L. CLAYTON, F.L. CLAYTON, F.L. CLAYTON, F.L. CLAYTON, F.L.	8310070270 8310070276 8310120350 8310140174 8310140224	50-344 8 50-348 8 50-348 8 50-348 P 50-348 8	CONNER. L CONNER. L CONNER. T B CONNER. T B. CONNER. T B	831027 04 65 8310310017 8310050515 8310050515 8310110216+	FDIA 50-3 P 50-352 Q 50-352 Q 50-358 Q
CHILK'R Y CHILK'R Y CHILK'R Y CHILK'R Y	8310130403 8310130408 8310140092 8310140242 8310140247	10CFR 50-320 P MIBC 50-155 Q 50-155 Q	CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8310170407 8310170416 8310180124 8310180134 8310180308	50-348 P 50-348 P 50-348 R 50-344 R 50-344 Q	CONNER, T B CONNER, T B CONNER, T B CONNER, T B CONNER, T, B	8310110287 8310110284 8310110286 8310110288 8310120028*	50~358 Q 50~358 Q 50~358 Q 50~358 Q 50~201 I
CHILK'S A CHILK'S A CHILK'S A CHILK'S A	8310140250 8310140294 8310170056 8310170058 8310170321	50-266 G 50-289 P 10CFR 10CFR 50-247 F	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F, L CLAYTON, F L	8310190071 8310210022 8310210259 8310250422 8310250479*	50-364 R 50-348 F 50-348 P 50-348 P 50-348 Q	CONNER, T B CONNER, T B CONNER, T, B CONNER, T B CONNER, T B	8310120028* 8310120028* 8310210153 8310210153 8310270381	50-201 I 50-201 I 50-358 Q 50-358 Q 50-354 Q
CHICK'S A CHICK'S A CHICK'S A CHICK'S A	9310170424 9310170695 9310180035 9310180041 9310180338	50~443 G 50~289 P 50~358 A 10CFR 50~309 G	CLAYTON, F L CLAYTON, F L CLELAND, L. L CLEMENSON, F CLEMENSON, F	8310270061 8310270374 8310250631* 8310050415* 8310050514*	50-364 8 50-348 P 50-312 P 50-413 T 50-455 T	CONSTABLE, G L CONSTAB, J CONTE, R COOK, D COOK, H L	8310310408* 8310180586 8310140166* 8310170271 8202230210*	50-382 Q 50-508 H 50-287 Q 50-254 S FUIA
CHIFK'S Y CHIFK'S Y CHIFK'S Y CHIFK'S Y	8310190091 8310190261 8310210147 8310240248# 8310250009	50~266	CLEMENTS.W L CLINE.W E CLINE.W E CLOSIUS.G J CLOSIUS.G J	8310040395 8310250304* 8310250576* 8310250315 8310250321	50-289 9 50-390 9 50-324 9 50-213 8 50-213 8	COOK, H L COOK, H L COOK, H L COOK, H L COOK, H L	8310260025* 8310260067* 8310260105* 8310260121* 8310260133*	FOIA FOIA FOIA FOIA
CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8310240241 8310270145* 8310270218 8310270234 8310270259	50-264	CLOUD, R L CLOUD, R L CLOUD, R L CLOUGH, R L COFFMAN, F E	8208010014* 83101803&1* 83101803&9* 8310310447 8310240253	50-275 P 50-275 T 50-275 T NUREO WASTE MOT	600K, H L 600K, H L 600K, H L 600K, H L	8310260146* 8310260147* 8310260238* 8310260258* 8310260321*	70-1144 70-1144 FOIA FOIA FOIA
CHILK'S A CHICK'S A CHICK'S A CHICK'S A	8310270297 8310270304 8310270317 8310270367 8310280066	50-10	COHEN. I COLBURN, N I COLBURN, T G COLBURN, T G COLBURN, T G	8310210266# 8310070414 8310070439 8310130052 8310130199	50-309 G MUREO 50-266 P 50-266 P 50-266 P	COOK, H C COOK, H C COOK, H C COOK, H L	8310260357* 8310260357* 8310260384* 8310260388* 8310260374*	FOIA FOIA FOIA FOIA FOIA
CHICKER J CHILK, B J CHILK, B J CHILK, B J	8310280162 8310280172 8310280212 8310070323 8310130001	WASTE MOT 50-289 P 50-358 Q NUREC 50-155 T	COLBURN, T O COLLE, P A COLE, R F COLEMAN, R	8310170079 8310240116 8310070173* 8310120398 8310070172	50-266 P 50-266 P CONTRACT 50-458 G CONTRACT	COOK, J. COOK, J. W. COOK, J. W. COOK, J. W.	8310120435 8310200203* 8307070257 8310070142 8310120320	50-333 R 50-397 G 50-329 B 50-329 A 50-329 A
CHOULES,N C CHOULES,N C CHOW,E CHRISBOTIMOS,N CHRISTA-MARIA	8310140215# 8310270440* 8310230482* 8310250613* 8310040545	50-373 Q 50-305 Q 50-255 P 50-254 Q 50-155 T	COTEA' O F COTEA' O F COTEA' O F COTEWAN'S A COTEWAN'S O	8310180270 8310110516 8310040283* 8310250257* 8310250464*	50-275 H CDNTRACT 50-259 G 50-259 G 50-280 G	CDDK'A M. CDDK'A M. CDDK'A M. CDDK'A M.	8310170421 8310250101 8310270245 8310270352* 8310310078	50-327 8 50-327 8 50-327 9 50-327 R
CHRISTA-MARIA CHRISTA-MARIA CHRISTA-MARIA CHRISTEL CHRISTEL, B	8310040620 8310040621* 8310040624* 8310110486* 8310270477	50-155 T 50-155 T 50-155 T FOIA 50-249 B	COLLINS, D J COLLINS, D, M COLLINS, J T COLLINS, J T	8310040019* 8310120217* 8310140142 8310030358 8310030375	50-244 G 50-277 G 1&E 50-298 G 50-445 G	CDOK, K. W. CDOK, K. W. CDOK, R. J. CDOKE, F. E.	8310120226 8310250496 8310170534* 8310170591* 8310180152*	50-382 A 50-382 E 50-329 G 50-329 G 50-352 G
CHRISTIANSON, F CHRISTMAN, J N CHRISTMAN, J N CHRISTOPHER, R CHRISTOPHER, R	8310250642* 8310170365 8310170365 8310270324* 8310270462*	50-461	COLLINS, J. T COLLINS, J T COLLINS, J T COLLINS, J T	8310030411* 8310040407 8310070144* 8310310422 8310140080*	50-445 Q 50-267 P 50-382 A 50-267 Q 50-302 P	CODNEA'N 7 CODNEA'N 7 CODNEA'N 7 CODNEA'N 7 COOC'D'Y	8310200137 8310200137 8310200257 8310250279 8310250382	70-1151 50-276 8 50-277 R 50-278 8 50-277 6
CHRIBTOPHER, R. CHRIBTOPHER, W CHU, K H CHURCHILL, B W CHURCHILL, B W	8310270474# 8310030405 8310180085 8310040833 8310040833	50-443 G 50-260 B NUREG 50-382 G 50-382 G	COLLINS, S.T. COLLINS, T R COLOMBO, R COLOMBO, R. COLOMBO, R.	8310270013 8310250540# 8310040419 8310170216 8310120145	50-29 0 50-369 0 50-312 R 50-312 R 50-312 S	COOPER, J. H COOPER, W E COOPER, W E COOPER, W E COOPER, W E	8310310281* 8310170214 8310170444 8310180361* 8310180375*	50~275 Q 50~275 R 50~275 R 50~275 T 50~275 T
CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W	8310110274 8310110274 8310170569 8310170569 8310190212	50~266	COLOMBO, R W. COLOMBO, R W. COLOMBO, R. W. COLOMBO, R. W COLOMBO, R W	8310120150 8310120167 8310120186 8310250598 8310270451	50-312 8 50-312 8 50-312 8 50-312 8	COOPER, WE COOPER, WE, COPELAND, RA COPELAND, VO COPELAND, VG	8310260260 8310270241 8310050346 8310120365 8310120365	50-275 R 50-275 R TOPREP 50-155 9 50-155 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COPELAND, V G COPELAND, V G COPELAND, V G CORBETT, J S	8310170346 8310170346 8310310206 8310310206 8310170748	50-454	Croseman. W a Croseman. W a Croseman. W a Croseman. W a Croseman. W a	8310030372* 8310030420* 8310040157* 8310040546* 8310040577*	50-498 G 50-459 G 50-382 G 50-498 G 50-285 G	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310280128 181080161 831031032 83103103 83103103	50-409 P 50-409 P 50-237 P 50-29 P 50-29 P
CORMIER, W H CORNELL, E K CORYELL, Ø P COSSAART, J COSTANTINO, C J	8310030394 8310110111# 8310040197* 8310170107* 8310210358*	50-142 G 50-275 P 70-143 50-338 S 50-275 T	Croeeman. W a Croeeman. W a Croeeman. W a Croeeman. W a Croeeman. W a	8310040391* 8310040444* 8310130190* 8310130230* 8310130232*	50-362	CULLEN, D P CULLEN, D P CUMMINGS, J J CUMMINGS, J J	8310210001* 8310110103* 8310110103*	50-302 8 50-302 8 NUREO FOIA FOIA
COSTELLO.N J COTTER.B P COTTER.B P COTTER.B P COTTER.B P	8310280088 8310040194 8310120398 8310260268 8310260305	50~443 U 27~39 50~458 Q 27~39 50~293 Q	CROSSMAN.W A CROSSMAN.W A CROSSMAN.W A CROUSE, R P CROUSE, R P	8310180149* 8310180414* 8310310408* 8310060226 8310060345	50-458	CONNINGHAW'Y F CONNINGY'N E CONNINGY'N A CONNINGR'N N	8310240194* 8310280179* 8310130224* 8310130335* 8310040517*	F01A 50-289 P 50-313 Q 50-313 Q 50-250 Q
COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O	B310030335 B310030335 B310030428 B310030428 B310040141	50-423 A 50-423 A 50-245 P 50-245 P 50-423 K	CROUSE, R P.	8310120103 8310170492 8310170599 8310180513 8310250226	50-346 P 50-346 P 50-346 P 50-346 R 50-346 P	CUNNINGHAM, A L CUNNINGHAM, A L CUNNINGHAM, G H CUNNINGHAM, G H CUNNINGHAM, R E	8310250352* 8310250438* 8310130164 8310280144 8310250014*	70-143 50-280 Q 50-250 Q 50-322 U FOIA
CONVAIT'M C CONVAIT'M C CONVAIT'M C CONVAIT'M C	8310040151 8310040334 8310040334 8310040334 8310040521	50-423 K PR PR PR 50-423 C	CROUSE, R P CROW, W T CROW, W T CROW, W T.	8310250235* 8310040137* 8310070037* 8310170493* 8310180015*	50-346 P 70-2945 40-8027 70-143 70-143	CUNNINGHAM, R E CUOMO, M CURRAN, D CURRAN, D CURRAN, D CURRAN, D	8310280147 8310140027 8310110158 8310110158 8310110145*	50-10 P 50-322 F 50-443 0 50-443 0 50-443 0
COUNBIL. W. G COUNBIL. W. G COUNBIL. W. G COUNBIL. W. G	8310040521 8310050431 8310050431 8310050431 8310060035	50-423 C PR PR PR FR 50-245 F	CROWLEY, D. R CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310250464* 8310030080 8310030140 8310030263 8310030268*	50-280 B 50-244 P 50-213 P 50-219 P 50-219 P	CURRAN: D CURRAN: D CURRAN: D CURRAN: D CURRAN: D	8310110145# 8310110170# 8310110170# 8310110175# 8310110175#	50~443 G 50~443 G 50~443 G 50~443 G 50~443 G
COUNSIL.W. 0 COUNSIL.W 0 COUNSIL.W. 0 COUNSIL.W 0	8310060035 8310060205 8310060262* 8310060262*	50-245 F 50-245 F 50-245 F 50-245 F 50-245 F	CRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D GRUTCHFIELD, D	8310030443 8310030492 8310040451 8310050054 8310050091	50-219 P 50-155 P 50-244 P 50-29 P 50-204 H	CURRAN, D CURRAN, D CURRAN, D CURRAN, D CURRAN, D	8310140191 8310140191 8310180329 8310180329 8310310202	50-443 0 50-443 0 50-443 0 50-443 0 50-443 0
COUNBIL, W G. COUNBIL, W G COUNBIL, W G. COUNBIL, W G. COUNBIL, W G.	8310120270 8310120270 8310120270 8310120375 8310170190	PR PR PR 50-213 P 50-423 A	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D. CRUTCHFIELD, D	8310050524 8310070365 8310070368* 8310110140 8310110141	50-237 P 50-244 P 50-244 P 50-237 Q 50-29 P	CURRAN, D CURTIS, C M CURTIS, M CURTIS, N W CURTIS, N W	8310310202 8310190014 8310170698 8310040052 8310040421	50-443 0 50-321 R 40-2061 50-388 A 50-388 A
CONNSIT'M O CONNSIT'M O CONNSIT'M O CONNSIT'M O	8310170190 8310170504 8310170504 8310170563 8310170563	50-423 A 50-245 P 50-245 P 50-423 A 50-423 A	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D GRUTCHFIELD, D	8310110148 8310110193 8310110204 8310120104 8310120203	50-237 P 50-213 F 50-244 S 50-409 P 50-29 P	CURTIS.N W CURTIS.N W CURTIS.N W CURTIS.N W CURTIS.N W CURTIS.N W	8310040640 8310060211 8310070160 8310070336 8310120067	50-386 A 50-387 F 50-380 A 50-380 E 50-300 A
COUNSIL, W Q COUNSIL, W Q COUNSIL, W Q COUNSIL, W Q.	8310170656 8310170656 8310180344 8310180409 8310180409	50-245 P 50-245 P 50-213 P 50-213 P 50-213 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	6310120272 6310120274 6310120303 6310120308 6310120328	50-409 P 50-155 P 50-237 P 50-213 P 50-244 P	CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W CURTIS, N W	8310120080 8310120105 8310120144 8310120175 8310130207	50-388 A 50-388 A 50-388 A 50-388 A 50-387 P
COUNSIL, W G. COUNSIL, W G. COUNSIL, W G. COUNSIL, W G. COUNSIL, W G	8310180409 8310180469 8310180469 8310200187 8310200187	50~213 P 50~245 P 50~245 P 50~336 P 50~336 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310120334 8310120354 8310120373 8310120411 8310120424	50-219 P 50-29 P 50-206 P 50-213 P 50-237 P	CURTIS, N H CURTIS, N H CURTIS, N H CURTIS, N H CURTIS, N H	8310130213* 8310140056 8310140077 8310140114 8310140155	50-387 P 50-388 0 50-388 A 50-387 P 50-387 P
COUNSIL.W C COUNSIL.W C COUNSIL.W C COUNSIL.W C	8310200229 8310200229 8310270021* 8310280313* 8310110032	50-336 P 50-336 P 50-213 F 50-213 F NUREO	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310130137 8310130203 8310130276 8310170243 8310170360	50-255 P 50-409 F 50-409 P 50-255 F 50-29 P	CURTIS, N W	8310170145 8310180146 8310180426 8310180437 8310180434	50-388 A 50-388 A 50-387 P 50-388 A 50-388 A
OX.D C OX.F OX.F OYLE.F T RAIG.J	8310110480* 8310110240* 8310260436* 8310060135 8310030440	F01A 50-280 F 50-280 F XPURTLIC 50-344 S	CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D. CRUTCHFIELD, D.	8310170373 8310180370 8310180379 8310180452 8310180459*	50-244 S TOPREP TOPREP 50-155 P 50-155 P	CURTIS, N W	8310180480 8310180507 8310210292 8310250106 8310250476	50-387 P 50-387 P 50-388 A 50-387 P 50-387 Q
raio, J. Rane, C. J Rane, P. Rane, P. A Rane, P. A	8310060072 8104070444* 8310200398* 8310030384 8310040578*	50-62 8 50-206 P FDIA 50-275 Q 50-275 P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310180533 8310180614 8310190131 8310200003 8310200005*	TDPREP 50-155 F 50-409 F 50-409 P 50-409 P	CURTIS, N W	8310270214 8310280045 8310280130 8310280139 8310280135	50-388 S 50-388 S 50-388 S 50-388 A
RANE, P. A RANE, P. A RANE, P. A RAWLEY, D. E REED, J	9310190219 9310240174 8310270263 8310110100* 8310270384	50-275 G 50-275 G 50-275 G 50-327 F 50-295 B	CRUTCHFIELD. B CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8310210159 8310250188 8310250195* 8310250307 8310250433	50-133 F 50-237 P 50-237 P 50-155 0 50-255 P	CURTIB, R H CUTTER, A B CUTTER, A B D'ANICO, L D'ANGELO, A	8310310447 8310060413 8310110145 8310260217 8310200214*	NUREQ 50~261 P 50~261 F 50~382 H 50~206 Q
(EMB, J (EED, J R (EED, J R	8310270497 8310250582* 8310310275 8310310347* 8310310347*	50-341 8 70-2977 50-87 8 50-341 4 50-206 9	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310250443 8310250566 8310250630 8310250681 8310250682*	50-29 P 50-409 P 50-206 P 50-244 P 50-244 P	D'ANGELD, A D'ANGELD, A D'ANGELD, A DAEMAN, J J K DAINDRA, J	8310310304* 8310310398* 8310310405* 8310070414 8310180538*	50-312 0 50-528 0 50-312 0 NUREO 50-333 P
EWS, J. L. OCKER, H. W. OCKER, H. W. OSE, M. A. OSS, R. H	8310280136* 8310210266* 8310270194* 8310040493* 8310280295*	50-344 8 50-309 0 50-29 0 CONTRACT WASTE MGT	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8310270143 8310270238 8310270331 8310280009 8310280112	50-244 0 50-29 P 50-219 P 50-255 P 50-213 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8309060048 8309090416 8310030296 8310030317 8310030325	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S

AUTHOR	ACCESBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
DALE, L. F DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8310030364 8310030430 8310030438 8310030472 8310030490	PR 50-416 S 50-416 S 50-416 S 50-416 S	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8310250320 8310250354 8310250383 8310250388 8310250398	50-280 G 50-269 G 50-413 G 50-280 G 50-413 G	DEFWEDICO'N DEFWEDICO'N DEFWEDICO'N DEFWEDICO'N	8310170213* 8310170220* 8310170223* 8310170245* 8310170250*	FOIA FOIA FOIA FOIA FOIA
DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8310040344 8310040417 8310060001 8310060002 8310060025	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	DANCE.H C DANCE.H C DANCE.H C DANCE.H C DANCE.H C	8310250400 8310250414 8310250429 8310250459 8310250516	50-335 0 50-338 0 50-280 0 50-280 0 50-335 0	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8310170267* 8310170274* 8310170277* 8310170279* 8310170282*	FOIA FOIA FOIA FOIA FOIA
DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8310040112 8310060401 8310070169 8310070170 8310070172	50~416 S 50~416 S 50~416 S 50~416 S 50~416 S	DANCE, H C DANCE, H C DANCE, H C DANESE, F L DANIELSON, D	8310250615 8310270012 8310270365 8310170087 8310180446	50-335	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8310170286* 8310170270* 8310170293* 8310170297* 8310170316*	FOIA FOI/ FOIA FOIA
DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8310070239 8310070305 8310120281 8310120349 8310120419	50-416 S 50-416 B 50-416 P 50-416 F 50-416 S	DANIELBON, D H DANIELBON, D H DANIELBON, D H DANIELBON, D H DAU, G J	8310040179* 8310200164* 8310200280* 8310270450* 8310030650	50-346 G 50-373 G 50-358 G 50-255 G TOPREP	DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J.	8310170320* 8310170324* 8310170331* 8310170354* 8310170359*	FDIA FOIA FOIA FOIA FOIA
DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	6310120436 6310120444 6310140051 6310140061 6310140122	50-416 P 50-416 P 50-416 B 50-416 B 50-416 B	DAUGHERTY, F DAVALLE,R G DAVENPORT,K E DAVIS,A B DAVIS,A D	8310210275* 8310210173* 8310040253* 8310200148* 8310210003	50-327 R 50-397 A 50-269 G 50-10 G 50-358 A	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8310170363* 8310170367* 8310170372* 8310170376* 8310170381*	FDIA FDIA FDIA FDIA FDIA
DALE, L. F DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8310140160 8310140169 8310170408 8310170438 8310170474	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	DAVIB, A B DAVIB, E H DAVIB, J DAVIB, J DAVIB, J Q	8310240137* 8310240034 8310240042* 8310200140 8310070020	50-440 Q XPORTLIC XPORTLIC I&E 50-10 P	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J. DELMEDICO, J	8310170385* 8310170388* 8310170403* 8310170433* 8310170437*	FDIA FOIA FOIA FOIA FOIA
DALE.L F DALE.L F, DALE.L F DALE.L F DALE.L F	8310170512 8310180304 8310180330 8310180352 8310180414	50-416 8 50-416 P 50-416 E 50-416 P PR	Q L,BIVAD O L,BIVAD Q L,BIVAD O L,BIVAD O L,BIVAD	8310070025# 8310070154 8310070161# 8310070167# 8310070171#	50-10 P 50-10 G 50-10 G 50-10 G 50-10 G	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8310170441* 8310170447* 8310170449* 8310170453* 8310170453*	FOIA FOIA FOIA FOIA
DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8310180430 8310190006 8310190037 8310190098 8310190109	50-416 F 50-416 R 50-416 P 50-416 B 50-416 B	DAVIS, J G DAVIS, J G DAVIS, J G DAVIS, K A	8310260030 # 8310260174 # 8310280242 # 8310280244 # 8310050343	FOIA FOIA 50-400 A 50-400 A CONTRACT	DELMEDICO.J DELMEDICO.J DELMEDICO.J DELMEDICO.J DELMEDICO.J	8310170460* 8310170467* 8310170472* 8310170475* 8310170477*	FOIA FOIA FOIA FOIA FOIA
DALE,L F DALE,L F DALE,L F DALE,L F DALE,L F	8310190111 8310190232 8310190234 8310190257 8310210019	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	DAVIS,L A DAVIS,R L DAVIS,T.M DAVIS,W DAY,M S	8310280170* 8310190324* 8310040383* 8310310154* 8310130402	40-279 F0IA GA999 50-508 A F0IA	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8310170482* 8310170494* 8310170497* 8310170502* 8310170505*	FOIA FOIA FOIA FOIA FOIA
DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8310210182 8310210314 8310290242 8310260186 8310260220	50-416 8 50-416 0 50-416 0 50-416 S 50-416 P	DAY.R 8 DEAGAIID,A W DEAL.R L DEAL.R L DEATON,B W	8310250128* 8310110540 8310170232 8310170351 8310240065*	50~20b P 50~346 P 71~6697 71~6771 50~413 T	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J.	8310170510* 8310170516* 8310170521* 8310170527* 8310170528*	FDIA FDIA FOIA FOIA FDIA
DALE, L F DALE, L F DALE, L F, DALE, L, F DALE, L F	8310260276 8310270037 8310270160 8310270167 8310270229	50-416 F 50-416 S 50-416 S 50-416 S 50-416 S	DEBBAGE.A G. DEBBAGE.A G. DEBBAGE.A G DEBBAGE.A G DEBBAGE.A G	8310040043* 8310040203* 8310250449* 8310250492* 8310250007	50~261 G 50-324 G 50~250 G 50~327 G FOIA	DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J.	8310170532* 8310170535* 8310170570* 8310170574* 8310170578*	FOIA FOIA FOIA FOIA FOIA
DALE, L. F DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8310270235 8310270336 8310270397 8310310044 8310310126	50-416 8 50-416 8 50-416 B 50-416 P 50-416 G	DEBB.B DEBB.B T DECKER.T R DEFAYETTE.R. DELANEY.C E	8310250065 8310250387* 8310250363* 8310200268* 8310250038	50~259 S 50~348 G 50~249 G 50~123 G 50~272 G	DELMEDICO, J. DELMEDICO, J. DELMEDICO, J DELMEDICO, J DELMEDICO, J	8310170580* 8310170585* 8310170587* 8310170590* 8310170593*	FOIA FOIA FOIA FOIA FOIA
DALTROFF.S L DALTROFF.S L DALTROFF.S L DALTROFF.S L DANCE.H	8310140203 8310200196* 8310260212 8310280257* 8310190234	50-277 Q 50-277 Q 50-277 P 50-277 F 50-280 S	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8307200260* 8307250463* 8012010577* 8012310197* 8012310245*	50-936 P 50-313 P FDIA FDIA FDIA	DELMEDICO, J DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J	8310170615* 8310170618* 8310170625* 8310170628* 8310170637*	FOIA FOIA FOIA FOIA FOIA
DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8310030274 8310040012 8310040146 8310040178* 8310040215	50-280	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	8012310507* 8101070486* 8101070060* 8101070107* 8103060677*	FOIA FOIA	DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J.	8310170640* 8310170645* 8310170650* 8310170652* 8310170660*	FOIA FOIA FOIA FOIA FOIA
DANCE; H C DANCE; H C DANCE; H C DANCE; H C DANCE; H C	0310040247 0310040252 0310040290 0310040305 0310040329	50-269 G 50-280 F 50-269 G 50-250 G 50-413 G	DEFWEDICO' ? DEFWEDICO' ? DEFWEDICO' ? DEFWEDICO' ?	B103180096* B104170659* B104170666* B310170132* B310170147*	FOIA FOIA FOIA	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J, DELMEDICO, J,	8310170645* 8310170648* 8310170673* 8310170676* 8310170681*	FOIA FOIA FOIA FOIA FOIA
DANCE, H C DANCE, H C DANCE, H C, DANCE, H C, DANCE, H C,	8310040351 8310040404 8310040425 8310040447 8310040484	50-321 F 50-413 G 50-269 V 50-335 G 50-269 G	DELMEDICO, J. DELMEDICO, J. DELMEDICO, J. DELMEDICO, J.	8310170194* 8310170196* 8310170160* 8310170191* 8310170194*	FOIA FOIA FOIA	DELMEDIGO, J DELMEDIGO, J M DELOATCH, V, DELOATCH, V DELOATCH, V	8310170684* 8104210028* 8310050539 8310060109 8310060122	FOIA FOIA CONTRACT CONTRACT CONTRACT
DANCE: H. C.	8310040475* 8310040504 8310250225 8310250231 8310250248	50-269 0 50-250 0 50-413 0 50-537 0 50-269 0	DELMEDICO, J DELMEDICO, J DELMEDICO, J DELMEDICO, J	83101701968 83101702028 83101702058 83101702088 83101702108	FOIA FOIA FOIA	DELDATCH, V DELDATCH, V DELDATCH, V, DELDATCH, V, DELDATCH, V	8310060140 8310060503 8310180101 8310180147 8310180573	27-39 CONTRACT CONTRACT CONTRACT CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	NUMBER ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT
Denison, e Denison, e Denison, e Denison, e, Denison, e	8310040509 8310070086 8310070091* 8310070094 8310070100*	50-275 R 50-275 R 50-275 R 50-275 R 50-275 R	DIEDERICH. G J DIEDERICH. G J DIEDERICH. G J DIEDERICH. G J	8310060186 8310060198 8310060271 8310120109 8310140045	50-373 S 50-373 S 50-373 S 50-373 S 50-373 S	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8304050526* 8304220088* 8307220156* 8307220250* 8307270430*	FDIA FOIA FOIA FOIA 50-289 P
DENISON, E DENISON, E DENISON, E DENISON, E DENISON, E	8310070151 8310070208 8310070212* 8310070215 8310070227*	50-275 R 50-275 R 50-275 R 50-275 R 50-275 R	DIEDERICH. 0 J DIEDERICH. 0 J DIEDERICH. 0 J DIEDERICH. 0 J	8310140057 8310140069 8310140073 8310140263 8310180273	50-373 6 50-373 5 50-373 5 50-373 5 50-373 6	DIRCKS'M Y DIRCKS'M Y DIRCKS'M Y DIRCKS'M Y	8308080690* 8308190179 8309080114 8310030308 8310030620	F01A SECY SECY 50~309 S 50~289 P
DENISON, E DENISON, E, DENISON, E, DENISON, E, DENISON, E,	8310070251 8310070257* 8310120078 8310140117 8310140117*	50-275 R 50-275 R 50-275 P 50-275 R 50-275 R	DIEDERICH. © J DIEDERICH. © J DIEDERICH. © J DIEDERICH. © J	8310210222 8310270247 8310270274 8310270276 8310270470	50-373 S 50-373 S 50-373 S 50-373 S 50-373 S	DINCKS, W J DINCKS, W J DINCKS, W J DINCKS, W J	8310070080 8310070153* 8310110017* 8310110075* 8310120025	50-346 P PR FOIA 50-275 P SECY
DENISON, E DENKOWSKI, W J DENNISTON, S. F DENNISTON, S. F. DENNISTON, S. F.	8310280157 8310130261* 8310050369* 8310070432* 8310110192*	50-275 P 50-400 E CONTRACT CONTRACT CONTRACT	DIETZ, C R DIETZ, C R. DIETZ, C R DIETZ, C R DIETZ, C R	8309200175 8310030202 8310030209 8310030422 8310040304*	50-324	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8310120060 8310130080 8310130142 8310170686 8310180092	50~289 P MISC 50~498 H 50~320 U 50~289 P
DENNY, I L. DENNY, I. L DENTON, H. DENTON, H. R DENTON, H. R	8310120314 8310310362* 8305060071* 8206140401* 8310030131	40-2061 40-2061 50-255 P FOIA MISC	DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R. DIETZ, C. R	8310040362 8310040412 8310040478 8310040582 8310040593	50-324 8 50-325 8 50-261 0 50-325 S 50-324 8	DIRCKS'M' N DIRCKS'M N DIRCKS'M N DIRCKS'M N	6310170053* 6310170305 6310210065 6310250030* 6310270286*	FOIA 50~329 A 50-358 R FOIA FOIA
DENTON: H. R DENTON: H. R DENTON: H. R DENTON: H. R DENTON: H. R.	8310050071 8310060142 8310060145* 8310060157 8310060576*	50-250 9 MISC MISC NUREO 50-269 F	DIETZ, C. R, DIETZ, C. R DIETZ, C. R DIETZ, C. R DIETZ, C. R	8310040075 8310040218 8310040237 8310040383 8310120300	50-324	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8310270514 8310270635 8310280187 8310310116* 8310310131*	FOIA 40-672 50-458 A FOIA 50-209 P
DENTON, H.R. DENTON, H.R. DENTON, H.R. DENTON, H.R. DENTON, H.R. DENTON, H.R.	831 0040580 831 01 10408 831 0130080 831 01301 22 831 0130189	50-333 0 COMMISSION MISC NUREO 50-387 8	DIETZ.C.R DIETZ.C R DIETZ.C R DIETZ.C R DIETZ.C.R	8310120426 8310130124 8310140011 8310140053 8310170414	50-324 8 50-324 R 50-325 8 50-325 8 50-325 8	DIRCKS.W J DIRCKS.W J DIRLING.F DIRLING.F N DIRLING.F N	8310310136* 8310310140* 8310260300* 8310260157* 8310260303*	FOIA FOIA FOIA FOIA
DENTON, H R DENTON, H R. DENTON, H R. DENTON, H, R. DENTON, H, R. DENTON, H R	8310180401 8310180405* 8310180407* 8310210303 8310310213	PR PR PR 50-409 P 50-320 P	DIETZ, CR. DIETZ, CR DIETZ, CR DIETZ, CR. DIETZ, CR. DIETZ, CR.	6310170596 8310170604 8310190141 8310190227 8310190238	50~324	DISCHLER, S A DIXON, O W DIXON, O W DIXON, O W	8310070414 8310030343 8310030475 8310030582* 8310040445	NURE9 50-395 8 50-395 8 50-395 F 50-395 8
DENTON, H.R. DERKS, P.B. DEVINCENTIB, J. DEVINCENTIB, J. DEVINCENTIB, J.	831 0310214* 831 0190250 831 0030341 831 0030341 831 0060343	50-320 P 50-133 R PR PR 50-443 S	DIETZ, C.R. DIETZ, C.R. DIETZ, C.R. DIETZ, C.R. DIETZ, C.R. DIGNAN, T. G.	8310250237 8310250396 8310250460* 8310250521 8310110092*	50-324 S 50-324 S 50-324 G 50-325 S 50-443 G	0 WOYIG W 0 WOXIG M 0 WOXIG M 0 WOXIG	8310070002 8310070126 8310070278 8310070338 8310170443	50-395 8 50-395 8 50-395 8 50-395 8 50-395 8
DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8310060343 8310120263 8310120263 8310210250* 8310210250*	50-443 8 50-443 A 50-443 A 50-443 G 50-443 Q	Dignan, T C Dignan, T C Dignan, T, G. Dignan, T, G. Dignan, T G.	8310110072* 8310120133 8310120133 8310120428 8310120428	50-443	01X0N,0 W 01X0N,0 W 01X0N,0 W 01X0N,0 W	8310170568 8310170028 8310200252 8310210128 8310260107	50~395 B 50~395 R 50~395 G 50~395 S 50~395 E
DEVINE, J B DEVINE, T. DEVINE, T. DEVINE, T. DEVINE, T.	8310060094 8310060245 8310060245 8310060259# 8310060266#	XPORTLIC 50-358 0 50-358 0 50-358 0 50-358 0	Dignan, T. G. Dignan, T. G. Dignan, T. G Dignan, T. G Dignan, T. G	8310180153* 6310180153* 8310180170* 8310180170* 8310200267	50~443	0 , NOXIG W G , NOXIG W G , NOXIG W G , NOXIG	8310240117 8310240232 8310240255 8310280005 8310310234	50-395 B 50-395 P 50-395 P 50-395 D 50-395 S
DEVINE,T. DEVINE,T. DEWANDEL,E P. DEWANDEL,E P. DEWEY,L B.	8310060266* 8310280204 8310110239* 8310110268* 8310250264	50-358 0 50-358 0 50-280 F 50-280 F 50-529 0	DIGNAN, T G, DIGNAN, T G DIGNAN, T G DIGNAN, T. G, DIGNAN, T G,	8310200267 8310200277 8310200277 8310260254 8310260254	50~443	DIXON, O W DIXON, O W DODDS, R T, DODDS, R T DODDS, R T	8310310392 8310310394 8310170432* 8310170621* 8310170663*	50-395 S 50-395 S 50-397 Q 50-397 Q 50-508 Q
DEMITTIR B DEYOUNG, R. C DEYOUNG, R. C. DEYOUNG, R. C. DEYOUNG, R. C.	8310310379* 8310040432 8310060593* 8310110013* 8310110016*	50-155 P 0A999 50-362 U FOIA PDIA	Dignan, T. G Dignan, T. G Dignan, T. G Dignan, T. G Dignan, T. G	8310260261* 8310260261* 8310260266* 8310260266* 8310260272*	50-443	DODDS:R T. DODDS:R T DODDS:R T DOERFLEIN,L T DOHERTY:E A	8310180367* 8310210045* 8310210060* 8310170168* 8310110020	50-344 Q 50-397 Q 50-397 Q 50-333 Q FOIA
DEYOUNG, R. C. DEYOUNG, R. C. DEYDUNG, R. C DEYDUNG, R. C. DEYOUNG, R. C.	8310110381 8310110387* 8310190246 8310200375 8310200380*	50-272 0 50-272 0 50-454 0 50-329 A 50-329 A	DIGNAN, T G DIIANNI, D. C DIIANNI, D. C DIIANNI, D. C DIIANNI, D. C	83102602724 8205270433* 8304200240* 8307030513 8310130072	50-443	DOHERTY, J F DOHERTY, J F DOHERTY, J F DOHERTY, J F DONGELOH, W P,	8310040481 8310110202 8310110314 8310260262 8310250420*	50-293 Q 50-443 Q 50-443 Q 50-443 Q GA999
DEYOUNG, R. C. DEYOUNG, R. C. DEYOUNG, R. C. DEYOUNG, R. C. DIAZ, N. J	8310200386* 8310200392* 8310240245 8310240249* 8310110366*	50-329 A 50-329 A 50-413 A 50-413 A 50-83 F	DIIANNI, D. C. Dille, R. C. Dingell, J. D. Dircke, H. J. Dircke, W. J	8310170329 8310250045 8310110354* 8203120050* 8205050588*	50-282 P 50-275 U COMMISSION FOIA FOIA	DONNELL, J L DONNELL, J L DODLITTLE, E L DODLITTLE, E L DOOLITTLE, E L	8310280078* 8310280078* 8310050453 8310180077 8310240044	50-329 0 50-327 0 50-423 A 50-423 0 50-423 A
DICK, 9, F. DICK, 9, F. DICK, 9, F. DICK, R. B. DICKERBON, M. W	8310120344 8310190029 8310310505 8310240279 8310030350*	50-244 F 50-244 B TOPREP FOIA 50-267 G	DIRCKS, W J. DIRCKS, W J. DIRCKS, W J.	8205140137* 8206080487* 8206240098* 8206250316* 8206300342*	FOIA 50-528 A FOIA FOIA FOIA	DOROSHOW, J DORBEY, J A DORBEY, J A DOUDNIKOFF, B. DOUGHERTY, J B	8310260274 8310040498 8310040498 8310280137* 8310200105	50-289 Q 50-352 Q 50-352 Q CONTRACT 50-322 Q
Dickerson, R. A Dickinson, A. C Dieckamp, H. Dieckamp, H. Dieckamp, H.	8310200141 8310200141 8310110054 8310180099* 8310180347	50-267 8 50-219 8 50-289 9 50-289 P 50-289 P	DIRCKB, W. J. Dircks, W. J Dircks, W. J Dircks, W. J Dircks, W. J	9207280124# 9209270562# 9211270168# 9212130165# 9302160056#	FOIA FOIA FOIA 50~267 P FOIA	DOUGHERTY, J. B DOUGLASS, B. J DOUGLASS, S. J DOWNING, G.	8310200105 8310070087 8310070092* 8310060501* 8310060593*	50-322 0 40-8794 40-8794 CONTRACT 50-344 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB-JECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
DRAB.J 8 DRAPER.D M DRIGGERS.S E DROMERICK.A W DRUGA.R J	8310130261* 8310120445* 8310190293 8310040453* 8310250595	50-400 E 50-316 S 71-7032 GA979 50-334 B	EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8310030375* 8310030377* 8310030380* 8310040518 8310040523	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G ELLERSHAW, L. E	8310270377 8310280142* 8310310134 8310310440* 8310030459*	GEN TEC 18 50-334 F 50-454 G 50-321 P GA999
DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J	8310030259 8310030363 8310030368 8310030468 8310030482	50-382 8 50-382 8 50-382 8 50-382 9 50-382 8	EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8310120370 8310140072 8310250037 8310250040 8310250066	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	ELLIGT, B J ELLIGTT, C W ELLIS, D W ELLIS, J	8310050392* 8310140071 8310250277 8310250418 8310040230	50-413 T 50-352 Q 50-27 B 50-29 B 50-445 Q
DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J	8310030507 8310030540 8310040372 8310040512 8310040565*	50-382 8 50-382 8 50-382 8 50-382 A	EDDLEMAN, W EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R	8310270351 8310040227 8310040404 8310060340 8310060372	50-400 @ 50-440 £ 50-440 B 50-440 B 50-440 B	ELLIS, J. ELLIS, J ELLIS, J ELLIS, J	8310120414 8310180163* 8310180339 8310180342* 8310280057	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q
DRUMMOND, F J	8310040357 8310070235 8310120072 8310130264* 8310310091	50-382 F 50-382 A 50-382 E 50-382 G 50-382 A	EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R.	8310120286 8310170467 8310170613 8310200238 8310210112	50-440 8 50-440 8 70-2768 50-440 E 50-440 8	ELLIB, T B ELLIB, T B, ELLIB, T B ELLIB, T, B ELMS, A	8310040430 8310040430 8310170409 8310170409 8310170007	50-322 0 50-322 0 50-322 0 50-322 0 50-213 R
DRUMMOND,F J DRUMMOND,F J DU BOUCHET DU BOUCHET,A V DUBINSKI,L	8310310315 8310310367 8310280006* 8310040573* 8310260062*	50~382	EDELMAN, M R EDELMAN, M. R EDELMAN, M R EDELMAN, M R EDELMAN, M. R	8310240145 8310250483 8310270030 8310310050 8310310378	50-440 A 50-441 S 50-440 B 50-440 A 50-440 A	ELROD: 8 A. ELROD: 8 A. ELBASSER: T ELBASSER: T C. ELBASSER: T C	8310040454* 8310250528* 8310190188* 8310120088* 8310180207*	50~335 q 50~335 q 50~423 q 70~1100 50~213 q
DOCK'O K DOCK'O K DOBCA'N E DOBCIE'D F DOBINEKI'F	8310240127* 8310180232* 8310240100* 8310140130 8310140240	FOIA 50-278 G 50-315 G 50-370 J 50-302 J	EDGAR, G L. EDGAR, G L EDGEWORTH, P J EDIBON, O, E. EDIBON, O E	8310260292 8310260292 8310110572 8310240039 8310240075	50-537 G 50-537 G CONTRACT 50-482 A 50-482 A	ELBASSER: T C ELBASSER: T C ELBASSER: T C ELBASSER: T C EMCH: R. L	8310180447# 8310200169# 8310240115# 8310270295# 8310050005	50-213 Q 70-820 50-225 Q 50-134 Q 50-155 P
DUDLEY, R F DUGGAN, G. J DUGGIN, G E DUGSTAD, D DUMMER, G H	8310040003 8310170245 8310030218 8310170055 8310070435*	50-29 P Waste Mgt 50-327 S 50-282 R Contract	EDISON, O E EGGENBERGER, A EGGENBERGER, A EGGERS, P EHABZ, J L	8310240135 8310120225* 8310120225* 8310260377 8310040237*	50-458 F 50-155 T 50-155 T MUREQ 50-382 Q	EMCH: R L ENDRES: G. W. ENGEL: D W. ENGEL: W P. ENGEL: W. P	8310050314* 8310310268 8310070317 8310170027 8310170739	50~155 T NUREO NUREO 71-9070 71~6400
DUMMER. G H DUNAWAY, F R DUNAWAY, F R DUNDAB, W J DUNLAP, J M	8310180105# 8310240074# 8310270313# 8310110187 8310120156#	CONTRACT 50-295	EIBENHUT, D. G EIBENHUT, D. G EIBENHUT, D. G EIBENHUT, D. G	8310040239# 8003240123# 8112170188# 8207260091# 8303230300#	50-352 A	ENNIB, J. D ENNIB, J D ENDB, J T ERDMAN. C A.	8310170149# 8310260221# 8310140152 8310140152 8310250683#	50-416 0 70-1113 TOPREP TOPREP 50-59 F
DUNLAP, J. M DUNLAP, J M DUNLOP, J M DUNNING, T G DUPONT, B G	8310250603* 8310270178* 8310120143* 8310210392* 8310050502*	50-193 Q 70-371 50-29 Q 50-275 T 50-373 Q	EIBENHUT, D G EIBENHUT, D G. EIBENHUT, D G EIBENHUT, D G	8304020357* 8308300355 8308300357 8308300358 8308300743	50-309 B 50-275 P 50-247 P 50-275 P 50-247 P	ERHARDT, J. V ERHARDT, R. J ERHARDT, R. J ERNSTTHAL, H. L. ESPINCSA, Q. J.	8310070163 8310210027 8310260331 8310250675 8310060412	50-245 8 50-329 A 50-329 A FDIA XPDRTLIC
DUPREE, D C BURAND, R J BURBIN, B L BURBIN, B L BURBIN, B L	83101700A6 8310260340* 8310120376 8310120361* 8310120386*	50-327 R 50-329 A 50-275 Q 50-275 Q 50-275 Q	EIBENHUT, D G EIBENHUT, D G EIBENHUT, D G EIBENHUT, D G	8308300744 8308300771 8308300775 8308300781 8308310029	50-275 T 50-244 P 50-275 P 50-275 R 50-275 P	ESPOSITO, B. ESPOSITO, B. ESPOSITO, B. ESSIO, T. H EVANS, C. A.	8310130267* 8310130271* 8310130277* 8310070216 8310040160*	50-400 E 50-400 E 50-400 E REB 50-445 G
DURBIN, B. L DURDEL, R. DURGURE, R. L DURR, J. P. DURR, J. P.	8310310141 8310040595* 8310180431* 8310060048* 8310190142*	50-275	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8308310050 8310030141 8310030407* 8310030571 8310030600*	50-322 8 50-266 F 50-382 A 50-289 P 50-346 P	EVANS, C. A EVANS, L. Q EVANS, P. A EVERETT, R. J. EVERETT, R. J	8310040644* 8310170262 8310030409* 8310030502 8310310380*	50-267 0 70-2067 50-413 9 40-6659 40-8084
DUB.R. DUVALL.D D DYNNER.A R DYNNER.A R DZEDZY,J L.	8310180273 8310120224 8310040618 8310040618 8310280083	50-373 S 50-341 S 50-322 0 50-322 C 50-352 H	EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D, G, EISENHUT, D, G,	8310030602 8310040061 8310040639 8310040642* 8310050077	50-312 F 50-287 G 50-362 P 50-362 P 50-346 F	EWERT, O. F EWERT, O. F EWERT, O. F. EYSTER, R. E FABRIKANT, J. 1.	8310240131 8310270066 8310310369 8310280016 8310060212*	50-329 A 50-329 A 50-329 A 50-142 T 50-400 0
DZIADOBZ,D, EAGLE.J EARLE.D K. EARLE.T.C. EARLEY.A,F.	8310190057* 8310060249 8310200109 8310130134* 8310060300	50-280 P 50-265 8 50-341 H MISC 50-322 Q	EIBENHUT, D. Q EIBENHUT, D. Q. EIBENHUT, D. Q EIBENHUT, D. Q EIBENHUT, D. Q	8310050144 8310060064* 8310060134 8310060213 8310070048*	50-289 P 50-416 P HIBC 50-213 P 50-293 P	FABRIKANT, J. I FALCONER, D. FALCONER, D. FALKENHEINER, D. FALKENHEINER, D.	8310040212* 8310040307* 8310250254* 8310280183 8310280183	50~400 0 50~269 0 50~269 0 50~458 A
EARLEY, A F EARLEY, A F. EARLEY, A F EARLEY, A F. EARLEY, A, F.	8310060300 8310120117 8310120117 8310310128 8310310128	50-322	EIBENHUT, D Q EIBENHUT, D, Q EIBENHUT, D Q EIBENHUT, D Q. EIBENHUT, D. Q.	8310070140 8310070393* 8310110246 8310120041* 8310120329	50-382 A 50-298 F 50-289 P 50-387 P 50-29 P	FALSON: V. K. FANNING: Q FARRAR: D. L. FARRAR: D. L. FARRAR: D. L.	8310070165 8310170557 8310030311 8310040162* 8310040260*	CONTRACT 50-304 8 PR 50-456 Q 50-454 Q
EABON, C. F ECKERT, H. J ECKERT, H. J. ECKERT, J. P. ECKERT, J. P.	8310280080 8310040381* 8310040381* 8310040470* 8310260179*	27-48 50-155 T 50-155 T 70-27 70-27	EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q.	8310130068 8310130326 8310130342 8310140271 8310140302	MIBC 50-289 P 50-289 P 50-289 P 50-289 Q	FARRAR, D. L.	8310040444 8310110478* 8310120401* 8310140049* 8310140104*	50-373 F 50-237 B 50-454 G 50-10 G 50-10 G
ECKHARDT, J ECKHARDT, J ECKHARDT, J. ECKHARDT, J. H ED, D D	8310120065 8310140153 8310140284 8310240201# 8310170356#	50-362 8 50-362 8 50-361 8 50-528 A 50-454 9	EIBENHUT, D. Q.	8310170025 8310170063 8310170266 8310170276# 8310170302	50-289 P 50-344 F 50-397 F 50-395 P MISC	FARRAR, D. L. FARRELL, E. V.	83101704714 8310170716 8310240077+ 8310250341+ 8310250410	50-456 0 70-2973 50-456 0 50-373 0 50-317 8
ed, D. D. Eddings, M. G Eddleman, H. Eddleman, H Eddleman, H	8310170356# 8310190066 8310030367 8310030367# 8310030372#	50-454	EIBENHUT, D. 0 EIBENHUT, D. 0 EIBENHUT, D. 0 EIBENHUT, D. 0 EIBENHUT, D. 0	8310170542* 8310180017 8310200246* 8310210344* 8310240267	50-275 G HISC 50-454 G 50-328 P 50-317 S	FARRELL,RE, FABAND,A. FAW,R,E. FAY,C W FAY,C W	8310310407* 8310140170* 8310130070 8310030616* 8310030447	50-409 0 50-320 0 50-198 R 50-266 F 50-266 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FAY.C.W FAY.C.W FAY.C W FAY.C W FAY.C W	8310040310 8310040623 8310070303 8310120089 8310120275	50-266 P 50-266 M 50-266 V 50-266 Ø PR	FELTON, J M	8310110444 8310110470 8310110503 8310110523 8310110557	FOIA FOIA FOIA FOIA FOIA	FELTON, J M	8310250656 8310250660 8310250668 8310250673 8310260008	50-483 F 50-285 F 50-331 F 50-59 F 50-10 S
FAY.C.H. FAY.C H FAY.C W FAY.C W FAY.C H.	9310170380 \$310180119 9310180421 \$310180490 9310200202	50-301	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310110564 8310110571 8310110586 8310120006 8310120016	F01A F01A F01A 50~201 I 50~339 P	Felton, J M Felton, J M Felton, J M Felton, J M Felton, J M	8310260019 8310260428 8310260431 8310270005 8310270009	70-1144 50-280 F 50-263 F 50-331 F 50-10 F
FEMRINGER, D. J FEIERABEND, C D FEIL, R A FEIL, R A FEIL, R A	8310210335 8310240102* 8310170621* 8310210045* 8310210060*	WASTE MOT 50-282 G 50-397 G 50-397 G 50-397 G	FELTON. J M	8310130102 8310130307 8310130310 8310130312 8310130374	50-344 F 50-285 F 50-409 F 50-317 F 50-329 A	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310270011 8310270018 8310270020 8310270024 8310270024	50-287 P 50-213 F FDIA 50-254 F 50-367 F
FELTON, J M. FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310030229 8310030564 8310030573 8310030609 8310040121	50-373 F 50-315 F 50-395 F 50-266 F 50-10 F	FELTON, J M	8310130407 8310130412 8310140031 8310170003 8310170004	FOIA FOIA 50-49B	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310270027 8310270039 8310270040 8310270049 8310270051	FOIA 50-309 F 50-320 P 50-389 F FOIA
FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310050327 8310050340 8310060243 8310060256 8310060265	50-289 F 50-317 F 50-313 F 50-213 F 50-269 F	FELTON, J M FELTON, J K FELTON, J M FELTON, J M FELTON, J M	8310170029 8310170049 8310170078 8310170707 8310170735	FOIA FOIA FOIA 50-373 F 50-148 F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310270071 8310270074 8310270076 8310270082 8310270089	FOIA FOIA 50-244 F FOIA FOIA
FELTON, J M FELTON, J M FELTON, J M FELTON, J M, FELTON, J M,	8310040474 8310040481 8310040470 8310040517 8310040529	50-315 F 50-387 F 50-335 F 50-280 F 50-289 F	FELTON, J M	8310170741 8310180029 8310180534 8310180555 8310180571	50-321 F 50-341 F 50-333 P FDIA FDIA	FELTON, J. M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310270104 8310270117 8310270119 8310270132 8310270250	FOIA FOIA 50~289 F FOIA 50~275 P
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8310060533 8310060541 8310060549 8310060555 8310060566	50-387 F 50-254 F 50-289 F 50-324 F 50-280 F	FELTON, J M FELTON, J, M FELTON, J M FELTON, J M FELTON, J, M	8310180586 8310180590 8310180400 8310180403 8310180610	50-445 A 50-508 H 50-322 A FOIA 50-275 P	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310270262 8310270281 8310270347 8310270360 8310270369	50-358 0 FOIA 50-29 8 FOIA 50-287 P
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M.	8310060590 8310060597 8310070128 8310070134 8310070403	50-346 F 50-313 F 50-370 F 50-267 F 50-260 F	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8310180625 8310190041 8310190049 8310190062 8310190093	SO-329 A FOIA FOIA FOIA FOIA	FELTON: J M FELTON: J M FELTON: J M FELTON: J M	8310270393 8310270468 8310270481 8310270491 8310270301	50-289 F FOIA 50-317 F 50-155 F FOIA
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J, M	8310110004 8310110007 8310110019 8310110021 8310110027	50-295 F 50-445 A 50-155 F FOIA 50-305 F	FELTON, J M FELTON, J M FELTON, J M	8310190291 8310190294 8310190309 8310190316 8310190322	50-313 F 50-313 F FD1A 50-329 A FOIA	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310270503 8310270518 8310270524 8310270532 8310270534	FOIA 50-344 F 50-10 F 50-29 F 50-277 S
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M.	8310110030 8310110034 8310110035 8310110042 8310110044	FOIA 50-275 P 50-331 F 50-382 Q	FELTON, J M FELTON, J, M, FELTON, J M FELTON, J M FELTON, J M	8310190325 8310190340 8310200032 8310200079 8310200356	FOIA 50-282 8 50-287 P 50-254 F FOIA	FELTON, J M FELTON, J, M FELTON, J, M FELTON, J, M,	8310270352 8310270566 8310270582 8310270590 8310280079	50-461 F 50-275 F 50-275 F 50-155 F 50-361 S
FELTON J H, FELTON J H, FELTON J H FELTON J H FELTON J, M	8310110064 8310110065 8310110067 8310110072 8310110082	50-309 F 40-17 50-269 F 50-369 F 50-346 F	FELTON, J M FELTON, J. M FELTON, J M FELTON, J. M FELTON, J. M	8310200379 8310200410 8310200416 8310200426 8310200437	FOIA 50-155 F 50-373 F 50-287 F 50-320 F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8310280176 8310280191 8310280206 8310280252 8310280253	50-400 A 50-10 F 50-373 F 50-277 F 50-3 F
FELTON, J. M.	8310110091 8310110109 8310110109 83101101109	50-387 F 50-327 F 50-320 F 50-446 F 50-373 F	Felton, J. M Felton, J. M Felton, J. M Felton, J. M Felton, J. M	8310200450 8310210311 8310210315 8310210323 8310210325	FOIA FOIA 50-352 A FOIA FOIA	FELTON, J M FELTON, J M FELTON, J, M FELTON, J, M	8310280307 8310280311 8310310031 8310310097 8310120374#	50-10 F 50-213 F 50-3 P 50-320 P 50-27 P
FELTON J. M FELTON J. M FELTON J. M FELTON J. M FELTON J. M	8310110124 8310110135 8310110174 8310110186 8310110195	50-346 F 50-269 F 50-263 F 50-280 F 50-259 F	Felton, J M. Felton, J M. Felton, J. M. Felton, J. M. Felton, J. M.	8310210329 8310210359 8310210362 8310210366 8310210374	50-321 8 50-346 F 50-259 F 50-265 F 50-275 F	FENNETEAU,M M FENSTERSTOCK,J FEROESON,J H FERGUSON,W FERKIN,Z G	8310210255 8310170118* 8310270021* 8310120036* 8310060305	50-458 8 CONTRACT 50-213 F 50-201 I 50-352 Q
FELTON, J. M. FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8310110234 8310110237 8310110244 8310110255 8310110263	50-267 F 50-280 F 50-317 F 50-155 F 50-280 F	FELTON, J. M. FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8310210384 8310210389 8310210412 8310210414 8310240012	50-289 F 50-305 F 50-170 F 50-482 F 50-413 T	PERKIN, Z Q FERKIN, Z Q FERKIN, Z Q FERLIC, K FERNANDEZ, W	8310140019 8310140091 8310180140 831018038&* 8310060089	50-412 Q 50-412 Q 50-412 Q 50-5 Q 50-333 B
FELTON: J K FELTON: J, M. FELTON: J, M FELTON: J M FELTON: J M	8310110325 8310110329 8310110350 8310110353 8310110361	50-254 F 50-285 F FDIA FDIA 50-438 Q	FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8310240171 8310240189 8310240191 8310240193 8310240197	FOIA FOIA FOIA FOIA 50-528 G	FERRANTE, J FEY, F L FEY, F L. FIALKA, J FIEDLER, P B	8310180175* 8310110180* 8310240435* 8310200374 8310110217	CONTRACT 50-263 F 50-263 F FDIA 50-219 P
FELTON: J M FELTON: J, M FELTON: J, M FELTON: J M	8310110362 8310110364 8310110380 8310110385 8310110413	50-83 F FOIA 50-192 F 50-219 F 50-369 F	FELTON, J. M.	8310240234 8310240235 8310240237 8310240263 8310240281	FOIA FOIA FOIA FOIA FOIA	FIEDLER, P B FIEDLER, P B FIEDLER, P, B FIEDLER, P B, FIEDLER, P B	8310110399# 8310170335 8310170405 8310170031 8310170328	50-219 F 50-219 P 71-9111 50-219 R 71-9010
FELTON, J. M.	8310110424 8310110430 8310110433 8310110434 8310110437	50-192 F 50-237 S 50-315 F 50-322 A 50-313 F	FELTON, J. H. FELTON, J. H FELTON, J. H FELTON, J. H FELTON, J. H	831 0240312 831 0240320 831 0250002 831 0250028 831 0250032	FOIA 50-348 P FOIA FOIA FDIA	FIEDLER, P. B FIEDLER, P. B FIELDER, J FIELDS, D. FIELDS, J. A	8310200161 8310270138* 8310030301 8310140268* 8310050319	50-219 8 50-219 0 50-321 J 50-302 R CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJEC
FIELDS, J A FIELDS, S R FIELDS, B L FILSON, J R	8310130404 8310200221 8310260427 8310250305 8310050391*	CONTRACT 50-387 B NUREG 50-244 S CONTRACT	FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8310200279 8310250238 8310250244 8310250325 8310250390	50-211 8 50-272 8 50-311 8 50-272 8 50-272 8	GALLAGHER, J W GALLAGHER, J W GALLE, D P GALLO, J GALLO, J	8310200172* 8310260208* 8310280314* 8310040365	50-277 50-443 50-10 50-155 50-155
FINDLEY,D C FINKEL,A FIORAVANTE,N FIORELLI,Q FITTI,C J	8310260375* 8310060012* 8309080363* 8310040537* 8310280254*	CONTRACT 50-410 G GEN TEC IS 50-528 G 50-400 A	FRAHM.R FRAHM.R FRAHM.R FRAHM.R FRAME.P W	8310250407 8310250470 8310250567 8310280024 8310170011	50-311 S 50-311 S 50-311 S 50-272 S 40-86	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8310040376 8310040376 8310040505 8310040505 8310040548	50-155 50-155 50-155 50-155 50-155
FITZGERALD, J A FITZGIBBONS, R FITZGIBBONS, R FITZGIBBONS, R FITZGIBBONS, R	8310200394* 8310310145 8310310145 8310310391 8310310391	FDIA 50~155 G 50-155 G 50-155 G 50~155 G	FRANKABZEK, J J FREDERICK, R J FREDERICK, R J FREEMAN, G J FREEMAN, M	8310260317* 8310270116* 8310270156* 8310210173* 8310260411	FDIA FDIA FDIA 50-397 A 40-8768	GALLO, J GALLO, J GALLO, J GALLO, J	8310040548 8310040551 8310040551 8310040553 8310040553	50-155 50-155 50-155 50-155 50-155
FITZPATRICK,B FITZWATER,M E FLACH,W T FLACK,E FLACK,E	8310270313# 8310170313# 8310280122* 8308310105 8310030520	50-264 G FDIA 50-311 G I&E I&E	FREEMAN, M D FRENCH, L D FRENCH, L D FRESCO, A FRIEDERICHS, S	8310260377 8310250232 8310280018 8310270075* 8310040123*	40-8768 30-29 8 50-29 8 FOIA 50-395 P	GALLO, J GALLO, J GALLO, J GALLO, J	8310040574 8310040574 8310050483 8310050483 8310050486*	50-155 50-155 50-155 50-155 50-155
FLACK, E FLACK, E FLACK, E FLACK, E FLACK, E	8310050536 8310140237 8310180177 8310180413 8310310406	1 &E 1 &E 1 &E 1 &E 40 – 299	FRIEDMAN, L FROMM, E FRYE, D L FRYE, J H FRYE, J H	8308310330 8310110337* 8310040324* 8310040172 8310110054	1&E CONTRACT 50-267 B 50-142 G 50-142 G	GALLO, J. GALLO, J GALLO, J GALLO, J GALLO, J	9310050484* 8310110045 8310110045 8310110043 8310110043	50-155 50-155 50-155 50-155 50-155
FLEENOR, C FLEENOR, C FLEENOR, C FLEENOR, C FLEENOR, C	8310050383 8310070407 8310120033 8310120038 8310280062	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	FRYE, J H FRYE, J H FRYE, J H FRYE, J H	8310110214 8310260205 8310260205 8310260225 8310260225*	50-358	GALLO, J GALLO, J GALLO, J GALLO, J	8310120211 8310120211 8310130174 8310130174 8310130214	50-155 50-155 50-155 50-155 50-155
FLIPPO,T A FLORES, A B FLYNN, M J FLYNN, M J FLYNN, M J	8310310408* 8310110344* 8310050466 8310070228 8310070234	50-382 G CONTRACT CONTRACT CONTRACT CONTRACT	FRYE.J H FRYER.B C FRYLING.R FUENKAJORN.K FUHRMAN.G R	8310310240 8310050470* 8310030484 8310070414 8310040542	50-142 G 50-255 P 50-354 G NUREG 50-317 S	QALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8310130214 8310140074 8310140074 8310170420 8310170420	50-155 50-155 50-155 50-155 50-155
FLYNN,M J FLYNN,M J FQGARTY,D J FQGGREC	8310110342 8310130388 8310120278 8310170008 8310070181*	CONTRACT CONTRACT 50-206 Q 50-206 H CONTRACT	FUHS.A FUJIMOTO,R I FULLER,C H FURSE.M C FURSE,M C	8310270400 8310130418* 8310170260 8310060319 8310060319	50~254 S CONTRACT 50~267 R 50~454 G 50~454 Q	QALLO, J. QALLO, J. QALLO, J. QALLO, J.	8310180222 8310180222 8310180230 8310180230 8310180335	50~155 50~155 50~155 50~155 50~155
FOLEY, U J FOLEY, W J FOLEY, W J FOLEY, W J	8310110365 8310170310 8310110580 8310180079 8310200378	50-43B Q 50-247 S NUREG NUREG NUREG	FURSE.M.C. FURSE.M.C FURSE.M.C FURSE.M.C FURSE.M.C	8310040321* 8310180275 8310180275 8310180277* 8310180279*	50-454	GALLO, J. GALLO, J GALLO, J. GALLO, J. GALLO, J.	8310180335 8310180346 8310180346 8310200225 8310200225	50~155 50~155 50~155 50~309 50~309
LOND'N T LOND'N T LOND'E N LOND'E N LOND'E N	8310190188* 8310250517* 8310250624* 8310170076 8310170740	50-423 Q 50-327 Q 50-327 Q 70-1201 70-1201	FUSSELL, J B GAD.R K GAD.R K GAD.R K GAD.R K	8310070220* 8310110083 8310110083 8310110072* 8310110072*	CONTRACT 50-443 Q 50-443 Q 50-443 Q 50-443 Q	GALLO, J. GALLO, J. GALLO, J. GALLO, J. GALLO, J	8310240128 8310240128 8310240132* 8310240132* 8310310139	50-155 50-155 50-155 50-155 50-155
FORD, W H FORMICA, C D FORNEY, W FORNEY, W FORNEY, W FORNEY, W L	8310200467* 8310130261* 8310120256 8310200152 8310050530*	COMMISSION 50-400 E 50-358 B 50-358 B 50-358 Q	GAD.R K GAD.R K GAD.R K GAD.R K GAD.R X	8310120133 8310120133 8310120428 8310120428 8310140015	50-443 0 50-443 0 50-443 0 50-443 0 50-443 0	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, J	8310310139 8310310204 6310310391 8310310391	50-155 50-155 50-155 50-155 50-155
FORNEY, W L FORTUNA, R FORTUNA, R FORTUNA, R FOBTER, C	8310050546# 8310270462# 8310270474# 8310040453# 8310180562	50-358 Q 50-443 G 50-443 G GA779 XPORTLIC	GAD, RK GAD, RK GAD, RK GAD, RK GAD, RK	8310180150 8310180150 8310180153* 8310180153* 8310180165	50-443	GALLO,R GALLO,R GALLO,R M. GALLO,R M GALLO,R M	8310040393* 8310060051 8310140082 8310140245* 8310190135*	50-410 50-293 50-29 50-271 50-410
FOBTER, C M FOBTER, C M, FOBTER, C M FOBTER, C M FOBTER, C M	8310040090 8310040130 8310180093 8310180113 8310240301	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	GADIR K. GADIR K. GADIR K GADIR K GADIR K	8310180165 8310180170* 8310180170* 8310200267 8310200267	50-443 0 50-443 0 50-443 0 50-443 0 50-443 0	OALLO,R M GALLUP,D.R GALM,D T. GALYEAN,W J. GAMBLE,D H	8310260437 8310110174 8310170197 8310110591* 8310280238*	50-293 NURE9 70-498 FDIA 50-400
FOSTER.C M FOSTER.D L FOSTER.D L FOSTER.D L FOSTER.D L FOSTER.D L	8310240302* 8310260032* 8310260087* 8310260073* 8310260135*	XPORTLIC FGIA FGIA FGIA FGIA	QAD, R. K QAD, R. K QAD, R. K QAD, R. K QAD, R. K.	8310200277 8310200277 8310260254 8310260254 8310260261#	50-443	OARCIA, E. M GARGIA, H. L. GARGIA, P. J GARGIA, P. J GARDE, B. P.	8310310249* 8310180149* 8310200446 8310200456 8310130390	50-73 50-458 40-8584 40-6622 50-329
FOSTER.D O FOSTER.D O FOSTER.D.O FOSTER.D O FOSTER.D O	8310120274 8310170546 8310190125 8310190124* 8310270315	50-424 B 50-424 B 50-424 A 50-424 A 50-424 B	OAD.R K GAD.R K GAD.R K GAD.R K GAD.R K	8310260261* 8310260266* 8310260266* 8310260272* 8310260272*	50-443	GARDE, B P. GARDE, B P. GARDE, B P. GARDE, B P.	8310180454 8310180465* 8310180618 8310190300 8310190311	50-329 50-329 50-329 50-329 50-329
FOSTER, W E FOSTER, W H FOSTER, W H FOSTER, W H FOSTER, W H	8310180358* 8310280173* 8310280202* 8310280207* 8310280211*	GA797 50-400 G 50-400 A 50-400 A 50-400 A	QAQLIARDO, J E. Qahm, J. H Qajic, Z Qalen, R E Qalen, R E	8310180500 8310130236 8310120174 8310140063 8310140063	50-285	GARDNER; R. GARDNER; R B GARDNER; R N GARDNER; R N GARNER; L W	B310140090 B310170591# B310170464# B310170534# B310040332#	50-329 50-329 50-329 50-329 50-324
FOSTER, W H FOSTER, W H FOSTER, M. H FOSTER, W. H FRAHM, R.	8310280246* 8310280250* 8310280259* 8310280263* 8310190178	50-400 A 50-400 A 50-400 A 50-400 A 50-311 S	OALLAGHER, E. J. OALLAGHER, J. W. OALLAGHER, J. W. OALLAGHER, J. W. OALLAGHER, J. W.	8310200454 8310030283 8310040187 8310040415 8310040434	50-320 @ PR 50-277 P 50-277 P 50-277 F	GARRITY, J H GARRITY, J H GARY, G Ł GARY, R J, GARY, R. J	8310210274* 8310270200 8310130268 8310030516 8310050403	50-309 50-309 50-445 50-445 50-445

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
GARY.R J	8310130278	50-445 S	GDDDARD,R J	8310130051	50-155 0	GREEN, R F	8310180527*	GA999
GARY.R J	8310140180	50-445 K	GODDARD,R J	8310130149	50-309 0	GREENBLATT, M	8310070217*	CONTRACT
GARY.R J	8310180179	50-445 K	GODY,A	8310040213	50-272 8	GREENE, F S	8310210180*	CONTRACT
GARY.R J	8310180484*	50-445 G	GODY,A T.	8310120143*	50-29 0	GREENE, R F	8310180532*	GA999
GARY.R J	8310180488*	50-445 G	GODY,A T	8310120156*	50-223 0	GREENE, T	8310170746*	50-321 F
GARY,R J GAUNY,R D GAVIGAN,F X GAVUTIE,S GEARS,G	831 0280003 831 0280261* 831 0310059 831 0310021 831 0210336	50-445 S 50-3 F 50-537 A 50-443 G 50-277 G	GODY, A T. GODY, A T. GODY, A T GODY, A T GODY, A T.	8310120201* 8310240085* 8310250529* 8310250603* 8310270178*	70~135 70~1100 50~272	OREENMAN, E GREENMAN, E GREENMAN, E GREENMAN, E GREENMAN, E G	8310040455 8310040253 8310040344 8310310230* 8310070014	50-309 8 50-309 8 50-309 8 50-317 0 70-364
GEDRGE, D. E. GEORGIEV, G. B. GERDEMAN, F. W. GERDEMAN, F. W. GERDEMAN, F. W.	8310140256 8310040453* 8310070402 8310180104 8310180129	50-304 원 GA979 40-7869 40-8698 40-8698	opldberg.j H opldberg.j H opldberg.s opldberg.s C opldberg.s C	8310030167 8310140110 8310200092* 8310050375 8310130144	50~498 K 50~498 V 50~271 G 50~440 G	OREENMAN,E G GREENMAN,E G OREER,W B OREGER,L R GREGER,L R	8310070027* 8310140082 8310070414 8310040360* 8310050364*	70-364 50-29 9 NUREQ 70-36 50-87 0
GERDEMAN, F W	8310180133	40~8674	GOLDSTEIN, J 1	8310130165*	CONTRACT	OREGER, L. R.	8310120204*	50-116 Q
GERNER, L	8310040545#	50~254 F	GOTTALES, J C	8310140274*	50-527 8	OREGER, L. R	8310140216*	70-1308
GERNER, L	8310270028#	50~254 F	GOODMAN, L S	8310170364	50-407 B	GREGER, L. R.	8310140285	50-266 B
GERRETS, T F	8310040134	50~382 S	GOODMAN, L S	8310190027	50-409 R	GREGER, L. R	8310210074*	50-10 Q
GERRETS, T F	8310190151	50~382 S	GOODWIN, D C	8310060407	50-276 8	OREGER, L. R	8310270313*	50-266 G
GERRETS, T. F GERRETS, T. F GERRETS, T. F GERRETS, T. F GERRETS, T. F	8310210258 8310210290 8310280012 8310280069	50-382 S 50-382 6 50-382 S 50-382 S 50-382 S	GORE, A GOSBICK, L V GOTCH, G. GOVLD, T. L. GOVLD, T. L	8310110597* 8310200387* 8310130157* 8310190075 8310190173	CDMMISSION FDIA 50-320 S 50-320 S	GREGG,R J GREGORY,W S GRESHAM,S C GRIER,D,H GRIER,B H	8310250445* 8310200344 8310270272 8310110108* 8310110130*	70-820 RES 50-261 P 40-17 FUIA
GERRETS, T F	8310310292	50-382 S	GOULD, T. L	8310190205	50-320 S	ORIER, B H ORIER, B H ORIER, B H ORIFFIN, H B ORIFFIN, H B	8310240185*	FDIA
GERRETS, T F	8310310300	50-382 S	GOULD, T L	8310200095	50-320 S		8310260165*	70-1144
GERUSKY, T M	8310030453	50-287 G	GOULD, T L	8310250317	50-320 S		8310260378*	FOIA
GIANNELLI, J M	8310240148*	FUIA	GOULD, T L	8310250478	50-320 S		8310180223*	50-445 G
GIANNELLI, J M	8310240197*	FOIA	GOULD, T L	8310250429	50-320 S		8310180229*	50-445 G
GIBBS, P M	B310250498*	50-248 Q	GOULDIN.J A	8310270031	FOIA	ORIFFIN, J M	8310030337	50-368 P
GIBBG, J J	B310250569*	50-227 Q	GRABER.L.	8310110432	FOIA	ORIFFIN, J M	8310120079	50-313 P
GIBBG, J J	B3102401B3	50-400 G	GRABER.L.D	8310210324	FOIA	ORIFFIN, J M	8310130097	50-368 P
GIBBG, J J	B3102401B3	50-400 G	GRADER.L.D	8310270121	FOIA	ORIFFITH, B C	8310040295	50-413 Q
GIBBONS, T D	B310130389*	CONTRACT	GRABER.L.D	8310270340	50-29 8	ORIMSLEY, D H,	8310240219*	50-528 A
GIBSON, A F	8310250065	50-259 S	ORACE, R H	8310170033	50-307 R	ORIMBLEY, DH	8310240221*	50-528 G
GIBSON, J	8310170207	50-336 R	GRAESBER, K L	8310120108	50-295 R	GROEBCH, GL	8310170321	FOIA
GIBSON, J,	8310200167	50-336 R	GRAESBER, K L	8310120174	50-295 S	GROFF, DW	8310060079	70-143
GIESLER, C W	8310040617	50-305 P	GRAESBER, K. L	8310140256	50-304 S	GROGAN, JE	8310240058*	50-413 T
GIESLER, C W	8310060334*	50-305 Q	GRAESBER, K L	8310170557	50-304 B	GROSBMAN, H	8310040175	50-460 G
GIESLER,C W GIESLER,C W, GIESLER,C W GIESLER,C W GIESLER,C W	8310110028* 8310120244* 8310120337 8310170341 8310180322	50-305 F 50-305 F 50-305 P 50-305 R PR	GRAESSER, K. L GRAESSER, K. L GRAESSER, K. L GRAESSER, K. L GRAESSER, K. L	8310170561 8310170579 8310170588 8310170609 8310210218	50-275 8 50-304 8 50-275 8 50-304 8 50-304 8	ordssman, H. Orossman, H Orossman, H. Orossman, H Orotsmhuis, M	8310180320 8310200240 8310210203 831031022A 8310180583	50-440 9 50-440 9 50-440 9 50-460 9
GIESLER,C W	8310210304	50-305 8	Graesser, k l	831 0270287	50-295 8	QUCMA, L T	8310070287	50-321 P
GIESLER,C,W	8310210317	50-305 9	Graffam, d.	831 01 40268*	50-302 R	QUCMA, L T	8310110124	50-321 P
GIESLER,C W	8310210394*	50-305 F	Graffam, J J	831 01 70120	50-387 8	QUCMA, L, T,	8310210270	50-321 P
GIESLER,J V	8310250510*	QA999	Gramm, R. A.	831 01 70135*	50-410 0	QUCMA, L T	8310310265	50-366 P
GIESLER,J V	8310250525*	QA999	Grant, J	831 0040373*	50-410 0	QUCMA, L T	8310310308	50-321 P
GILBERT.E.C GILBERTS.D E GILBERTS.D E GILDENHORN GILDENHORN.A J	8310280220* 8310250288* 8310250361* 8310110506 8310060117	50-35B	GRANT, J. ORANT, J. M. GRANT, N. W. GRANT, P. J. GRANT, T. J.	8310170135* 8310170203* 8310170023 8310280111 8310110412*	50-410 @ 50-352 @ 50-250 R WASTE MGT 50-400 @	QUILD, R QUILD, R QUILD, R QUILD, R, QUINN, F K	8308300480 8308300480 8308300486* 8308300486* 8310040307*	50-413 0 50-413 0 50-413 0 50-413 0 70-143
GILDENHORN, A J	8310110525	CONTRACT	GRANT, W.B.	8310040340*	70-34	OUINN, F K	8310040350#	70-143
GILDENHORN, A J	8310120052	CONTRACT	GRANT, W.B.	8310050544*	50-87 G	QUINN, F K,	8310050473#	70-143
GILDENHORN, A J	8310130243	CONTRACT	GRANT, W.B.	8310120204*	50-116 G	QUINN, F K	8310050835#	70-143
GILDENHORN, A J	8310170082	CONTRACT	GRANT, W.B.	8310140216*	70-1308	QUINN, F K	8310070145#	70-143
GILDENHORN, A J	8310170112	CONTRACT	GRANTHAM, B	8310250148*	GA999	QUINN, F, K	8310170680	70-143
GILDENHORM;A J GILDNER,M L. GILINSKY;V GILINSKY;V	831021008& 8310170470* 8310130277* 8310030408 8310070085*	CONTRACT 50-440 Q 50-400 E 50-289 Q 50-346 P	ORAVES, C W. GRAVES, R H. GRAVES, R. H. GRAVES, R. H GRAY, E H	8310240017* 8310190007 8310250315 8310250321 8310190142*	50-413 T 50-213 R 50-213 8 50-213 8 50-443 9	QUINN,F K. QUINN,F,K QUINN,F,K QUNDAKER,W.F QUNDAKER,W.F	8310170270 8310250340* 8310250500 8310040245* 8310040245*	70-143 70-143 70-143 50-382 9
GILINBKY, V	B310170054	50-275 G	Green, a r	8310180541	XPDRTL1C	GUSTAFSON, R B	8310170083	70-371
GILINBKY, V	B310270656*	40-572	Green, h J.	8310030218	50-327 8	GUBTAVE, R	8310210180*	CONTRACT
GILLEN, D M	B310240075*	40-8681	Green, h J	8310030240	50-328 9	GUSTAVE, R.	8310280068*	CONTRACT
GILLEN, K T,	B310310447	NJREG	Green, h J	8310030405	50-260 8	GUSTAVE, R. P	8310050337*	CONTRACT
GILLETT, H T	B310170064	50-316 R	Green, h J	8310030432	50-259 8	GUSTAVE, R. P.	8310050370*	CONTRACT
OILLETT, H T	8310190070	50-315 R	oreen, H. J	8310040083	50-327 8	QUSTAVE, R, P	8310050545*	CONTRACT
GLASS, B H	8310170500	50-322 0	Oreen, H. J.	8310040377	50-276 8	QUSTAVE, R. P	8310050550*	CONTRACT
GLASS, B, M	8310270239	50-322 0	Oreen, H. J.	8310040380	50-260 9	QUSTAVE, R, P.	8310050554*	CONTRACT
GLASSPIEGEL, H	8310270252	50-440 0	Oreen, H. J.	8310040407	50-276 8	QUSTAVE, R P	8310060103*	CONTRACT
GLEASON, J P,	8310270250	50-483 0	Oreen, H. J.	8310140087	50-328 9	QUSTAVE, R P,	8310060115*	CONTRACT
GLEASON, J.P.,	8310190085	50-247 0	OREEN, H. J.	8310140129	50-259 8	QUBTAVE, R. P	8310060127#	CONTRACT
GLEASON, J.P.,	8310260224	50-247 0	OREEN, H. J.	8310140200	50-260 8	QUBTAVE, R. P.	8310060184#	27-39
GLEASON, J.P.	8310270307	50-247 0	OREEN, H. J.	8310170276	50-327 8	QUBTAVE, R. P	8310060191#	CONTRACT
GLENN, J.	8308310330	I&E	OREEN, H. J.	8310170592	50-327 8	QUBTAVE, R. P.	8310070189#	CONTRACT
GLICKMAN, T.	8310270099	FOIA	OREEN, H. J.	8310170597	50-327 8	QUBTAVE, R. P.	8310070429#	CONTRACT
OLGERSEN, Y	8310140267*	50-337 0	Green, H. J.	8310170658	50-328 8	OUSTAVE, R. P	8310070435#	CONTRACT
OLDERSEN, B	8310040178*	50-331 0	Green, H. J.	8310190124	50-327 8	OUSTAVE, R. P.	8310120019#	CONTRACT
OLDVER, M. S	8310110079*	50-349 F	Green, H. J.	8310210226	50-259 8	QUSTAVE, R. P.	8310120024#	CONTRACT
ODDERD, R. J	8310050410	50-334 0	Green, H. J.	8310250077	50-327 8	QUSTAVE, R. P.	8310120035#	CONTRACT
ODDERD, R. J.	8310050443	50-322 0	Green, H. J	8310270073	50-260 8	QUSTAVE, R. P.	8310120040#	CONTRACT

AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
QUSTAVE, R P QUSTAVE, R P QUSTAVE, R P QUSTAVE, R P QUSTAVE, R P	8310130385* 8310170550* 8310180157* 8310180557* 8310180576*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HAMID, A A HAMIL, TON, P HAMLIN, J B HAN, J T HANAFORD, T	8308310512* 8310180111 8310140030 8310240195* 8310030102	50-267 @ 50-293 R 50-498 @ FDIA 50-361 R	HABSELL, D F HABSELL, D F HAUGHEY, M F HAVIAN, E HAVIAN, E	8310130233 8310130305 8310070194 8310250043 8310250043	50-329 0 50-247 0 50-410 A 50-275 0 50-275 0
GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUTKNECHT,P J	8310180585* 8310240098* 8310260375* 8310270406* 8310110347	CONTRACT CONTRACT CONTRACT CONTRACT NUREG	HANCOCK, J C HANDLER, R HANDLER, R HANDLER, R HANDLER, R	8310190329* 8310260043* 8310260125* 8310260191* 8310260354*	FOIA FOIA FOIA FOIA	HAVIAN.E HAVIAN.E HAVIAN.E R HAVIAN.E R HAWKINS,D A	8310280097 8310280097 8310040539 8310040539 8310180168	50-275 0 50-275 0 50-275 0 50-275 0 CONTRACT
GUTTERMAN, A H GUTTERMAN, A H GUTTMANN, H E GWYNN, T P HAAS, M N	8310110220 8310110220 8310200388 8310050546* 8310060191*	50-498 Q 50-498 Q NJREQ 50-358 G CONTRACT	HANNETT, B A	B310060081 B310060084* B310130376 B310180143 B310180148*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	HAWKINS,DA HAWKINS,EF HAYES,BB HAYES,BB HAYES,BB	8310240270 8310200373* 8310140035* 8310170577 8310200235	CONTRACT 40-7869 50-289 9 50-445 9 50-358 9
HAAS, P. M HAASS, W P HAASS, W P HABIGER, A HACKNEY, B D	8310170243 8310210381* 8310250182* 8310250357* 8310140274*	NUREO 50-275 T 50-275 T GA999 50-529 S	HANNETT, BA HANNETT, BA HANNETT, BA HANSEN, EM HANSEN, LJ	8310180302 8310280024 8310280033* 8310120374* 8310170291	XPORTLIC XPORTLIC XPORTLIC 50-29 P 71-9132	Hayes, B. B Hayes, B. B Hayes, B. B Hayes, B. B Hayes, D. W	8310270324* 8310270462* 8310270474* 8310280220* 8310040430*	50-287 G 50-443 G 50-443 G 50-358 G 50-454 G
HACKNEY, C A HACKNEY, C A HADNAGY, P A HADNAGY, P A HAFNER, B	8310030457* 8310310286* 8310120072 8310310135 8310180597	50-267 G 50-298 G 50-482 S PT21 50-322 A	HANSEN, L. J HANSEN, L. J HARDESTY, D HARDOROVE, T. W HARDIN, A	8310190285 8310210331 8310310130* 8310240003 8310270224	71-9145 71-9181 50-416 G 40-2259 50-325 S	HAYES, D. W HAYES, D. W, HAYNES, D. W HAYNES, J. O	8310060309* 8310170529* 8310310293* 8310250642* 8310250145	50~461 Q 50~454 Q 50~461 Q 50~461 Q 50~361 S
HAFNER, B HAFNER, B HAGAN, T HAGAN, T HAGAN, T F	8310210327 8310270474 8310060010* 8310180175* 8310050347*	FOIA FOIA CONTRACT CONTRACT CONTRACT	Harding, M Harding, M Harding, M Harding, M, R Harding, M R	8310190124 8310030218 8310030240 8310040083 8310250077	50-327 8 50-327 8 50-328 8 50-327 6 50-327 9	о Г. ВЭИЛУН О Г. ВЭИЛУН О Г. ВЭИЛУН О Г. ВЭИЛУН	8310250455 8310250465 8310250475 8310270416 8310270428	50-206 8 50-362 8 50-362 8 50-362 8
HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T F HAGAN, T F	8310050464* 8310060138* 8310110510* 8310110528* 8310120055*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Harless, B L Harmon, D W Harran, G Harran, G Harrell, E W	8310260183* 8310250331 8310190015 8310200129 8310070328	FOIA PR 50-245 R 50-245 R 50-338 S	O L JEBNYAH B L JEBNYAH D L JEBNYAH D L JEBNYAH O L JEBNYAH	8310270432 8310270434 8310270437 8310270448 8310270463	50-362 8 50-361 8 50-362 8 50-362 8 50-361 8
HAQAN, T F HAQAN, T F HAQAN, T F HAQAN, T F HAQAN, T F	8310170118* 8310180596* 8310210087* 8310210155* 8310240106*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HARRELL, E W HARRELL, E W HARRELL, E. W HARRELL, P H HARRINGTON, W D	8310140161 8310210047 8310210058 8310180450* 8307170140	50-338 S 50-339 S 50-338 S GA777 50-293 R	HAYNES, J O HAYNES, J O HAYNES, J O HAZLE, A J, HEAD, O F,	8310270495 8310270498 8310310326 8310130066 8310070279	50-362 9 50-361 8 50-361 9 HABTE HOT 50-321 P
HAGAN, T F HAGEMAN, R C HAGEN, T, F HAGEY, H A HAGUE, R L	8310240130* 8310110070* 8310170084* 8310110508 8310240003*	CONTRACT FOIA CONTRACT CONTRACT 50-301 G	HARRINGTON, W D	8310030354 8310120307 8310120330 8310180111 8310180435	50-293 P 50-293 P 50-293 P 50-293 R 50-293 F	HEAD, Q F HEALY, R. J HEBDON, F J HEETHER, W. H. HEETHER, W. H	8310120265 8310190283 8310130130 8310060120 8310250016	50-321 P NUMEO NUMEO XPORTLIC XPORTLIC
HAQUE,R.L HAIRSTON,W O HAIRSTON,W O HAIRSTON,W Q HAIRSTON,W G	8310270313* 8310030437 8310070138 8310070290 8310070299*	50-266 Q 50-364 B 50-34B B 50-364 B 50-368 B	HARRINGTON: W D	8310180479 8310180491 8310190174 8310250137 8310250282	50-293 P 50-293 P 50-293 S 50-293 S 50-293 S	HEETHER, W H HEHL, C W HEIDEL, C, M HEIDER, L H HEISHMAN, R	8310240018 8310250560* 8310170574* 8310170012 8310110191	XPORYLIC 50-321 G 50-341 K 50-27 R 50-329 G
HAIRSTON, W G HAIRSTON, W G HAIRSTON, W. G HAIRSTON, W G HAIRSTON, W G	8310070302* 8310120354* 8310120363* 8310120371* 8310140227*	50-348 8 50-348 8 50-348 8 50-348 8 50-348 8	HARRINGTON, H. D. HARRINGTON, W. D. HARRINGTON, W. D. HARRINGTON, W. D. HARRINGTON, W. D.	8310250544 8310270230* 8310310144 8310310290 8310310305	50-293 K 50-293 G 50-293 P 50-293 P 50-293 P	HELD, J T. HELD, J T. HELD, J T. HELD, J T.	8306030372* 8306080055* 8306080065* 8306080106* 8306080106*	50-284 P 50-312 P 50-336 P 50-302 P 50-302 P
Haireton, W G	8310140235* 8310180124 8310180134 8310190071 8310270108*	50-348 B 50-348 R 50-364 R 50-364 R 50-364 S	HARRIS, BL HARRIS, DR HARRIS, D. R HARRIS, H G HARRIS, J.	8310250570* 8310200051 8310200055* 8308310512* 8310030333	50-409 P 50-225 P 50-225 P 50-267 Q PR	HELD, J T. HELD, J T HELD, J T HELD, J T HELFRICH, R E HELFRICH, R E	8306080112* 8306130456* 8310050534* 8310040307 8310040334	50-272 P 50-346 P 50-237 P PR PR
HAIRSYON,W G HAIST,D HAIST,D P HALE,C,J HALE,C J	8310270115# 8310250543 8310170663# 8310040596# 8310180450#	50-364 8 50-344 8 50-508 G GA777 GA777	Harris, J R Harris, M. 9 Harris, M. 8 Harrison, F Harrison, G	8310250236* 8310170490 8310250481 8310130124 8310130020	50-507	Heller, J. K Heller, R. A Heltemes, C. J. Heltemes, C. J. Heltemes, C. J.	8310040255* 8310040322* 8305160184* 8309070071* 8309160058*	50-255 Q 50-267 S 50-351 S MISC NUREO
HALE,C J. HALL,B L. HALL,B L HALL,B L HALL,D P	8310250270* 8310030305* 8310070294* 8310270023* 8310040204	QA999 50-280 Q 50-324 Q 50-321 Q 50-461 S	Harri Bon, o Harri Bon, J Harri Bon, J. Harri Bon, J. J Harri Bon, J. J	8310240254 8310120446 8310140090 8310050393 8310140270	50-461 A 50-329 8 50-329 B 50-329 A 50-329 A	Heltemeb, C J Heltemeb, C J Heltemeb, C J Heltemeb, C, J Heltemeb, C J	B310060171 B310060175* B310060179* B3100601B5* B310060190*	50-251 8 50-251 8 50-251 8 50-251 8 50-251 8
HALL, D.P. HALL, D.P. HALL, D.P. HALL, D.P. HALL, D.P.	8310040238 8310040407* 8310110105 8310120077 8310120181	50-461 S 50-461 G 50-461 H 50-461 S 50-461 A	Harribon: J J Harribon: J J. J L Inde Irrah Harribon: J J Harribon: J J	8310170436 8310170464* 8310170534* 8310170572* 8310170591*	50-329 A 50-329 Q 50-329 Q 50-329 Q 50-329 Q	HELTEMEB, C J HENCH, L. L HENDR ICKSON, R. HENDR ICKSON, R HENNICK, A.	8310040194* 8310050239 8310030093 8310030123 8310110580	50-251 8 NURE9 50-116 P 50-116 F NURE9
HALL, D P. HALL, D P. HALL, D P. HALL, N M. HALL, R E.	8310120441 8310200201 8310250617 8310050362* 8310130170*	50-461 B 50-461 K 50-461 G CONTRACT 50-498 G	Harrison, J. J. Harrison, J. J Harrison, J. J Harrison, J. J. Harrison, G. A	8310210319# 8310250499 8310270165 8310310417# 8310040573#	50-329 G 50-329 A 50-329 G 50-329 G 50-382 A	HENNICK, A. HENNICK, A. HENRY, H. O HENRY, W. O HENRY, W. O	8310100079 8310200378 8310210192* 8310240049* 8310240055*	NUREO NUREO 50-413 T 50-413 T
HALL, R. E. HALL, R. E. HALLMAN, V. D. HALMAN, E. L. HAMEL, D. B.	8310130211* 8310130230* 8310180224* 8310070203* 8310120421	50-298 Q 50-478 Q 50-155 G CONTRACT 50-331 B	HARBTEAD, Q A HARTMANN, P. L HARTMANN, P. L HABBE, R A HABBELL, D F	8310280006* 8310240076* 8310270313* 8310140215* 8310130010	50-382 A 50-295 G 50-266 G 50-373 G 50-329 G	HENBLEY, K D HENBLEY, K D HENBLEY, K D. HERBEK, R F HERMANGKY, J	8310170036 8310170724 8310170737 8310240197 8310210146	70-143 70-143 70-143 50-247 0 40-299

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION	BUDJECT	
HERNAN, R HERNAN, R HERNAN, R, HERNAN, R, H HERNANDEZ, Q H	8310130070 83101806304 8310210116 82123000764 83103103414	50-302 P 50-329 A 50-275 Q	HOLYGAK, R H HOLYGAK, R H HOLYGAK, R H HOLIMER, M HONOLICH, J	8310110123 8310170711 8310200424 8310210151 8310170070	* 50-373 F * 50-373 F * 50-373 F 50-255 8	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	NUMBER 	CATEOOR 50-289 50-289 50-289 50-289 50-289	Y S F R P O
HERR.R K HERR.R K HERRINGTON.H N HERRMANN.T HERSCH.M M	8310180223# 8310180229# 8310030457# 8310030459 8310040059	50-445 q 50-247 q 50-333 8 XPGRTLIC	HODD, D HOOD, D 8 HOOD, D 5 HOOKER, C A HOOPENGARDNER	8310030542 8310070109 8310210134 8310030400 8310240022	50-329 A 50~329 A 40-8807	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8310250253 8310250261 8310250294 8310250430 8310250589	50-287 50-287 50-287 50-287 50-287	5 2 5 5 5 5
HERSHEY, S P HERSHEY, S P HESS, J F HESS, J F	8310130349 8310260273 8310260273 8310140076* 8310140076*	XPORTLIC 50-352 Q 50-352 Q 50-155 T 50-155 T	HOOPINGARNER, N HOPCRAFT, C P HOPKINS, H R HOPKINS, H R HOPKINS, J B	8310240024 8310130384 8310050387 8310070175 8310270135	71-9160 CONTRACT	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8310250606 8310270130 8310280108 8310280115* 8310280123	50-289 50-289 50-289	8 P P P
HEBSNER,R HETRICKIN P. HEYCOCK,P W HIATT.B L HIATT.B L	8310270537* 8310120171 8310130157* 8310030366 8310110425	50-10 F 50-320 H 50-389 Q PR 50-237 8	HOPPA, J L HOPPER, A HOPPER, A HOPPER, A HOPPER, A	8310040080 8310050409 8310040154 8310060487 8310070121	50~317 P CONTRACT CONTRACT CONTRACT CONTRACT	HUKILL, H D HULL, R E HUNNICUTT, D HUNNICUTT, D HUNNICUTT, D	8310310410 8310130252* 8310030457* 8310040644* 8310040015*	50-289 50-458 50-267 50-267	POGGG
HIATT, S L HIATT, S L HIATT, S L HIATT, S L	8310120099 8310180337 8310190061 8310200353 8310270065	50-440 G 50-440 G 50-440 G FOIA FDIA	HORIN, WAHORIN, WAHORIN, WAHORIN, WAHORIN, WAHORIN, WA	8310110322 8310110322 8310180158 8310180158 8310180163*	50-445 G 50-445 G 50-445 G 50-445 G	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	9310030350* 9310040186* 9310040240* 9310040589* 9310130211*	50-247 50-445 50-445 50-267	000
HIATT, 8 L HICKEY, W P. HICKEY, W P HIETALA, J J HIGGINBOTHAM, L	9310280071 8310040519# 9310040519# 9310140057 9310240262	50-361 B 50-155 T 50-155 T 50-373 B WASTE MOT	HORIN, H A HORIN, W A HORTON, G HOSCHAR, E E MOSCHAR, E E	8310210184 8310210184 8310040100 8310070125 8310070129*	50-445 G 50-445 G 40-277 MISC MISC	HUNNICUTT, D M	8310180219* 8310180227* 8310180232* 8310180472*	50-445 50-445 50-278 50-445	G G G G
HIGGINS, J HIGGINS, J HIGGINS, J HIGGINS, J	8310240270 8310040455 8310060253 8310060344 8310190159*	HASTE HOT 50~309 8 50~309 8 50~309 8 50~309 0	HOSEY, C M HOSEY, C M HOUGHTON, T. C HOUSTON, R HOUSTON, R W	8310250328* 8310250554* 8310030311 8310040178 8304090344*	50-280 Q	HUNNICUTT, D M HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A	8310310264* 8310310286* 8310120340 8310170641	50-298 (50-282 (50-306 (50-306 (0 9 8
HIQQINS.J HILDT.B HILL.H HILL.H M	8310310230* 8310200107* 8310060364* 8310200152 8310030392*	50-317 Q 50-317 Q 50-443 U 50-358 S 50-498 Q	HOUSTON, R. W HOUSTON, R. W HOUSTON, R. W HOUSTON, R. W HOUSTON, R. W	8310140073 8310140263 8310170463* 8310270274 8310270276	50-373 8 50-373 8 FOIA 50-373 S 50-373 S	HUNSTAD, A A	8310270415* 8310270418* 8310270421* 8310270427* 8310270429* 8310250452*	50~282 \$ 50~282 \$ 50~282 \$ 50~306 \$	8 8 9
P C'GNIH P C'GNIH P C'GNIH P'GNIH	8310110574* 8310120230 8310120274 8310140261 8310140264*	F01A 1&E 50-305	HOWE, P. W HOWE, P. W HOWE, P. W HOWE, P. W HOWE, P. W	8310040380 8310040385 8310060054 8310200166 8310200206	50-324 P 50-324 P 50-324 P 50-324 Q 50-324 P	HUNTER, D R HUNTER, D R HUNTER, D R HUNTER, D R HUNTER, D R	8310140150* 8310140215* 8310170440* 8310310407* 83101110074*	50-416 6 50-373 6 50-305 6 50-409 6	0: 0: 3:
HIND, J A HIND, J A. HIND, J A. HIND, J A HIND, J A	8310250197# 8310250284# 8310250548# 8310250550# 8310310325	50-255 Q 50-282 Q 50-155 Q 50-263 Q	HOWE, P W HOWE, P W HOWE, P W HOWE, P W KOWE, P W	8310210264 8310250036 8310250120 8310250480* 8310260141	50-324 P 50-324 P 50-324 F 50-324 G 50-324 P	IBEN, C IDE, W E IDEKER, R L INGRAM, F INMAN, S C	8310170471 8310240223* 8310170279 8310110062 8310230424*	50-254 S 50-254 S 50-528 Q 70-143 50-269 N	3
MIND, JA HINKLEHAN, LG HINZE, WJ HIPSHER, W, M. HIPSHER, WM	8310310333* 8310250408* 8310280131 8310120043 8310240088	50-305 Q Q4999 RES 27-39 Waste Mot	HOWLETY, L H HOY, H C. HOYLE, A HOYLE, A HOYLE, A	8310280178* 8310070426 8310060278 8310060495 8310060499	40-299 MUREO CONTRACT CONTRACT CONTRACT	IPPOLITO, T A IRWIN, D P IRWIN, D P IVERSON, O JABBOUR, K N	8310240085* 8310310124 8310310124 8310270380*	50-313 Q FOIA 50-322 G 50-322 G) ;
HIPSHER, W. M. HIPSHER, W. M. HOADLEY, S. D. HOCHENDONER, L. HODGOON, A. P.	8310260094 8310280281 8310120272* 8310120171 8310050432*	HASTE MOT 27-48 70-572 50-320 H 50-352 0	HOYLE, A HOYLE, H R HOYLE, J. C HOYT, H F.	8310070222 8310110125# 8310040592 8310050107 8310250044	CONTRACT FOIA 10CFR 10CFR 50-443 G	JABBOUR,K N JABBOUR,K N JABBOUR,K N JABLONSKI,F J JABLONSKI,F J	8310070150 8310110407 8310110434 8310190244 8310040309*	50-413 F 50-413 A 50-413 E 50-461 Q	! !
HODODON, A. P HOFFMAN, B HOFFMAN, O. L. HOFFMAN, T. E	8310170511 8310180038 8310180136 8310280178# 8310110356	50-352 0 40-8027 40-8639 40-299 FOIA	HOYT, H. F. HUBBARD, © T. HUBBARD, R B HUBBARD, R B HUBBARD, R B	8310280109 8310250447* 8310250178 8310200178 8310270377*	50-443 G GA999 50-275 T 50-275 T 50-275 G	Jackiw, i Jackiw, i n Jackiw, i n Jackeon, c w	8310310273* 8310060264 8310240003* 8310240102* 8310280074	50-461 0 50-266 8 50-301 0 50-282 0 50-247 9	
HOQAN, J, P, HOLCOMBE, J C HOLDEN, C HOLDEN, C	8310180319 8310110133* 8310040455 8310060253 8310060344	50-89 P 50-361 P 50-309 8 50-309 8 50-309 8	HUDSON, 8 D HUETER, L J HUETER, L, J HUFFMAN, 9 N HUFFMAN, 6 N	8310120076* 8310140216* 8310210074* 8310040413* 8310040480*	50-220 q 70-1308 50-10 q 50-413 q 50-302 q	JACOBB, A JACOBB, A JACOBB, A JACOBB, A	8310050553 8310070187 8310070329	50-413 Q CONTRACT CONTRACT CONTRACT CONTRACT	
NOLDEN, C.F. NOLDEN, C.F NOLDER, E.T. NOLLEY, J. HOLLEY, J.	8310140159* 8310060377 8310180369*	50-271	HUFFMAN, ON HUFFMAN, ON HUGHES, PO HUGHES, PO HUKIEL, HID	8310250392* 8310250409* 8310140187 8310140233 8310030103	50-413	JACOBS, A JACOBS, R JACOBS, R JACOBS, R H JACOBSON, P J	8310140038 8310170310 8310140279* 8310240167	CONTRACT 50-311 \$ 50-247 8 50-272 G FDIA	
HOLONICH, J J HOLONICH, J J HOLONICH, J J HOLONICH, J J	8310170124 8310180185 8310240039	50-313 Q 50-400 E 50-400 F 50-482 A 50-482 A	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H, D	8310040390 8310070074 8310070307 8310120340 8310140108	50-289 P 50-289 P 50-289 V 50-289 R 50-289 R	JAFFE, D JAFFE, D H JAMISON, J D JANZOH, E F	8310070176 8310030457# 8310140236# 8310060060	50-317 P 50-317 P 50-267 Q 50-271 Q XPORTLIC	
HOLDNICH, J. J. HOLT, J. HOLTZ, J. L. HOLWAY, F. I. HOLWAY, F. I.	8310120299 8310190019 8310040533	50-482 @ PR 50-334 R 50-443 @ 50-443 Q	HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D,	8310140251 8310170007* 8310180372* 8310190161 8310190164	50-289 P 50-289 F 50-289 Q 50-289 S	JANZOW, E F JAPE, F JAPE, F JAPE, F JAPE, F	8310040147# 8310040150# 8310040167# 8310040253#	XPORTLIC 50-390 0 50-413 0 50-416 0 50-269 0	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
JAPE,F JAPE,F JAPE,F JAPE,F JAUDON,J P	8310040563* 8310050419* 8310250216* 8310250230* 8310130259*	50-390 Q 50-413 T 50-416 Q 50-413 Q 50-482 Q	JONES, G T JONES, G T JONES, G T JONES, G T	8310030376 8310140127 8310190186 8310250360 8310050369*	50-296 8 50-260 8 50-259 R 50-260 B CONTRACT	KAMMER, D S KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8310250494# 8212150242# 8212290072# 8310110039# 8310110046#	50-327 C FDIA FDIA 50-275 F 50-275 F
JAUDON, J P JEANE, G S JENKINS, G R JENKINS, G R JENKINS, G R	8310130295* 8310310154* 8310040413* 8310040480* 8310250304*	50-285 G 50-50B A 50-413 G 50-302 G 50-390 G	JONES'M C JONES'M G JONES'M B JONES'A	8310170016 8310040186* 8310180472* 8310050255* 8310050310*	50-280 R 50-445 Q 50-445 Q 50-285 P 50-285 P	KAMMERER, C KAMMERER, C KANA, D D KANE, R. S KANE, R. S	8310110351# 8310240246# 8310270598# 8310180380# 8310180383#	FDIA 50-528 (TOPREP 50-199 (50-199 (
JENKINS, G R JENKINS, G R JENKINS, G R JENKINS, G R	8310250363* 8310250392* 8310250394* 8310250409* 8310250578*	50-269 Q 50-413 Q 50-280 Q 50-335 Q 50-324 Q	TDNES'M C TDNES'M C TONES'M C TONES'M C	8310110330* 8310120074 8310130308* 8310180162 8310180506*	50-285 F 50-285 G 50-285 F 50-285 R 50-285 G	Kanga, B K Kanga, B K Kanga, B K Kanga, B K Kanga, B K	8310030500 8310050055 8310110104* 8310130005 8310130064	50-320 F 50-320 F 50-320 F 50-320 F 50-320 F
JENSIW H JENSIW H JENSIW H JENSIW H JENSIW H	8310120221* 8307200240* 8310120098 8310120190 8310180034*	50-155 T 50-336 P 50-341 A 50-341 A 50-341 F	7008ER'N C 70NER'N C 70NER'N C 70NER'N C	0310170324 0310210000 0310210370* 0310250467* 0310030412	71-9000 50-285	Kanga, B K Kanga, B K Kanga, B K Kanga, B K Kanga, B K	8310130082 8310130138 8310170637 8310180200 8310190060	50-320 F 50-320 F 50-320 F 50-320 F 50-320 S
JENSON, D L JEBSUP, B JESSUP, B JESSUP, B JESSUP, B	8310200048# 8310070204 8310070213 8310070218 8310070233	50-289 P CONTRACT CONTRACT CONTRACT CONTRACT	JORDAN, E. L.	8308300340 8308300342 8308300345 8308300347 8308300378	90-3 0 90-3 0 50-3 0 50-3 0 50-3 0	KANGA, B K Kanga, B K Kanga, B K Kanga, B K Kanga, B K	8310190075 8310190173 8310190205 8310200095 8310200155	50-320 S 50-320 S 50-320 S 50-320 S 50-320 S
JEBBUP, B JEBBUP, B JEBBUP, B JOACHIM, M JOHANSEN, E	8310070244 8310110533 8310110613 8310180135 8310140257	CONTRACT CONTRACT CONTRACT 50-142 H 50-344 J	JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, L V	8308300752 8308300759 8308300761 8310120051 8310170206	50~3 Q 50~3 Q 50~3 Q 50~287 P 70~27	KANGA, B K KANGA, B K KANGA, B K KANGA, B K KANGA, B K	8310230317 8310250434 8310250478 8310250427 8310280102	50-320 \$ 50-320 \$ 50-320 \$ 50-320 \$ 50-320 \$
JOHNBON, A D JOHNBON, A R JOHNBON, A R JOHNBON, B	8310180367* 8310180455* 8310250385* 8310250541* 8310260309	50~344 Q QA999 QA999 QA999 50~537 A	JORDAN, R L JORDAN, R L JORDAN, W H JORDAN, W H JORDAN, W H	8310180401* 8310180401* 8310110246 8310140083 8310270228	QA779 QA779 50-445 6 50-445 0 50-445 Q	Kanga, B K Kantmann, R A Kaplan, S Karman, M Karol, R	8310310164* 8310180528* 8310170579 8310050447 8310270075*	50-320 (GA999 50-304 S 50-241 (FOIA
O B VOSNHOP O B VOSNHOP O	8310060221 8310120064 8310120247 8310120331 8310250250	50-255 8 50-255 8 50-255 8 50-255 8 50-255 8	Jordan, W H Jordan, W S Jordan, W S Jordan, W S Jordan, W S	8310270293 8310110158 8310110158 8310110145* 8310110145*	50-445	H C.RRAN W C.RRAN W C.RRAN W C.RRAN W C.RRAN	8310040249 8310120101 8310270257 8310270244* 8310310390	50-329 0 50-329 0 50-329 0 50-329 0 50-329 0
70HN8ON' E H 70HN8ON' C E 70HN8ON' G D 70HN8ON' B D	8310250462 8310270162 8310170683 8310070229 8310180478	50-255 S 50-255 S 50-445 T 50-352 V 50-445 Q	Jordan, W S Jordan, W S Jordan, W S Jordan, W S Jordan, W S	8310110170* 8310110170* 8310110175* 8310110175* 8310140191	50-443	KASTENBERG,WE KAUFFMAN,JT KAUFMAN,PH KAUFMAN,PH KAUFMAN,PH	8310040326* 8310110197 8310040209 8310040212* 8310040219*	CONTRACT 50-387 F 50-275 6 50-275 6 50-275 6
104N80N; E H 104N80N; E H 104N80N; E H 104N80N; E H	8310310277 8310310294 8310310298 8310310435* 8310050386	50-278 G 50-267 G 50-267 G 50-267 P 50-413 T	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	8310140191 8310180329 8310180329 8310310202 8310310202	50-443 0 50-443 0 50-443 0 50-443 0 50-443 0	MANACHIM H MANACHIM H KAYJJ A KAYJJ A	8310170209 8310170215 8310170355 8310040108 8310040330	71-9033 71-9032 71-9128 50-29 F 50-29 F
лонивои: л к лонивои: л г лонивои: л лонивои: е с лонивои: е с	8310050404 8310050562 8310040051 8310270524* 8310250631*	50-413	JORGENSEN, B L JOYNER, J JULIAN, C JULIAN, C A JULIAN, C A	B310040255* B310200160 B310040454* B310030461 B310250424*	50-255	KAYSER, W. V KEATING, D E KEIMIG, R KEISER, H	8310050470* 8310200280* 8310270450* 8310040040 8310040338*	50-255 F 50-358 G 50-255 G 50-334 F 50-387 F
ЈОНИВОМ, К. Т ЈОНИВОМ, Е. Е ЈОНИВОМ, Р ЈОНИВОМ, Р ЈОНИВОМ, Р	8310070317 8310130252* 8310120251 8310120321 8310240234*	NUREC 50~458	JUNGE, M A JUNGE, M A JUNGE, M, A JUNGE, F, B	8310200147 8310250411 8310250587 8310250599 8310260074	50-317 8 50-319 8 50-317 8 50-318 8 WASTE MOT	KEISER'H M KEISER'H M KEISER'H M KEISER'H M	8310170120 8310170145 8310170230 8310200271 8310250204	50-387 E 50-387 E 50-387 E 50-387 E 50-387 E
JOHNSON, P. H JOHNSON, R. G JOHNSON, T. L. JOHNSON, T. L. JOHNSON, V. P.	8310170470* 8310250237 8310180384 8310200452 8310260201*	50-526 Q 50-263 J 40-8698 40-8674 50-443 A	KADAMBI:P KAHLE:JB. KAHLE:JB KAHLE:JB KAHN:V	8310310487 8310040340* 8310040477* 8310040508* 8310050440*	50-269 P 70-143 50-321 G 70-27 CONTRACT	KEISER.H W KEISER.H W KEISER.H.W KEISER.H W KEISER.H W	8310250219 8310250228 8310250242 8310250245 8310250246	50-387 8 50-387 8 50-387 8 50-387 8 50-387 8
ланивои: м в ланивои: м в ланивои: м в ланиваи: н	8310040026* 8310030476 8310040577* 8310130171* 8310130178*	50-313	KAIBER, H KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8310060486* 8310060847 8310120158 8310170271 8310170353	50-387 F 50-265 S 50-254 S 50-254 B 50-254 R	KEISER,H W KEISER,H W KEISER,H W KEISER,H W	9310250345 9310250364 9310250402 9310250555 9310250574	50-387 50-387 50-387 50-387 50-387
та и човиног п и човиног п и човиног п и човиног п и човиног	8310130226* 8310130251* 8310130259* 8310130295* 8310130335*	50-313	Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakis, n	8310170491 8310170461 8310180107 8310180243 8310210016	50-254 8 50-265 8 50-254 R 50-254 R 50-265 S	Keiber, H. W. Keiber, H. W. Keiber, C. N. Kelber, G. R.	8310250422 8310280125 8310310305 8310170033* 8310280131	50-387 50-387 50-387 FDIA RES
10HN90N, W P 10HN90N, W P 10HN90N, W P 10HN90N, W V	8310180246* 8310260261* 8310260266* 8310040537* 8310190358*	50-285 Q 50-443 Q 50-443 Q 50-528 Q 50-282 S	KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KAMMER, D. S	8310210054 8310270400 8310270404 8310270419 8310110100*	50-265 S 50-254 E 50-254 S 50-265 S 50-327 F	KELLER: R KELLEY: D. L. KELLEY: D. L. KELLEY: J. L. KELLEY: J. L	8310180386# 8310040186# 8310180472# 8310040177 8310110209	50-5 50-445 50-445 50-413 50-400
JONES: D W JONES: D W JONES: D W JONES: D W	8310310014 8310060252* 8310030341 8310040148* 8310040493*	50-317 F 50-358 G PR 70-1151 70-27	KAMMER, D 8 KAMMER, D 8 KAMMER, D 8 KAMMER, D 8 KAMMER, D 8	8310180315 8310180422 8310180443 8310210023 8310250367	50-390 F 50-259 P 50-327 P 50-390 A 50-390 G	KELLEY, J L KELLEY, J L KELLEY, J L. KELLEY, J. L KELLEY, L	8310110218 8310140045 8310200383* 8310270317 8310170202	50-400 50-400 FDIA 50-400 50-286

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGDRY
KELLEY, 8 KELLEY, D KELLY, D KELLY, O	8310280146* 8310250008* 8310130413 8310280136* 8310280184*	50-322 U GA999 FGIA FDIA FDIA	H C'ONIX H C'ONIX H C'ONIX M C'NIX	8310130232* 8310260107* 8310260116* 8310260124* 8310260132*	50-341 A FOIA FOIA FOIA FOIA	KNOP:R C KNOP:R C KNOP:R C KNOP:R C KNOP:R C	8310060453* 8310170525 8310170529* 8310170629 8310170636*	50~483 0 50~454 0 50~454 0 50~341 0 50~341 0
KELLY.0 Kelly.0 A. Kelly.0 A. Kelly.0 A	8310250188* 8310250158* 8310250163* 8310250167* 8310250170*	FOIA FOIA FOIA FOIA FOIA	H L.ORIN L.ORMBUNIN L.ORMBUNIN L.ORMBUNIN D.ORMBUNIN	8310260366* 8310260374* 8310120306 8310200160 8310170143	FOIA FDIA I&E I&E 40-86	KNOP:R C KNOP:R C KNOP:R C KNOP:R C KNOP:R C	8310170662 8310170667* 8310240066 8310240121 8310250636	50-440 Q 50-440 Q 50-546 Q 50-440 Q 50-461 Q
KELLY'G V Kelly'G V' Kelly'G V' Kelly'G V	8310260172* 8310260173* 8310260173* 8310260175* 8310260223*	FOIA FOIA FOIA FOIA FOIA	KINNEY, W H KINNEY, W H KIRK, C KIRK, C	8310240115* 8310270275* 8310240133 8310170124 8310030240	50-225	KNOP,R C KNOX,J E KNOX,J L KNOOSON,M D KOCH,T	8310310289 8310040008 8310210382* 8310060406* 8205140143*	50-461 0 R9 70-275 T 50-213 P FOIA
KELTA'E B KELTA'F KETTA'N B KETTA'N	8310040160* 8310040644* 8310270080* 8310170603 8310170198*	50~445 Q 50~267 Q FOIA 50~286 R 50~423 A	KIRK, R L KIRK, R L KIRK, R L KIRK, R L KIRK, R L.	8310270113* 8310270122* 8310270139* 8310270147* 8310270163*	FOIA FOIA FOIA FOIA FOIA	KOESTER, O. L. KOESTER, O. L. KOESTER, O. L. KOESTER, O. L. KOESTER, O. L.	8310030364 8310040386 8310130192 8310130223 8310130231	PR 50-48# S 50-482 S 50-482 S 50-482 B
KEFTA'N A KEFTA'N A KEFTA'L KEFTA'U B KEFTA'U B	8310170039* 8310170047* 8310170561 8310070158 8310120136	50-329 A 50-329 A 50-295 S 50-275 S 50-275 S	Kirk.r L Kirk,r L Kirkman,r W Kirsch.d Kirsch.d	8310270168* 8310270174* 8310260033* 8310040376 8310070333	FOIA FOIA FOIA 50-206 S 50-362 6	KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L	8310170644 3310180171 8310180256 8310180317 8310180389	70-2940 50-482 8 50-482 8 50-482 E 50-482 5
KELTA'N 7 KELTA'N 7 KELTA'N 7 KELTA'N 7	8310120280 8310190051 8310250539 8310250439 8310270374	50-275 S 50-275 R 50-275 S 50-275 S 50-275 S	Kirsch, D F Kirsch, D F Kirsch, D F Kirsch, D F Kirsch, D F	6310170479* 6310200214* 6310200224* 6310310251* 6310310341*	50-275 Q 50-204 Q 50-204 Q 50-275 Q 50-275 Q	KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L KOESTER, G L	8310210075 8310210188 8310210244 8310210415* 8310250054	70-2940 50-482 8 50-482 5 50-482 F 50-482 A
KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8310040124 8310040296 8310040431 8310110132 8310120148	50-352 A 50-352 A 50-352 A 50-352 E 50-352 A	Kish, J. N Kisher, H Kister, H Kister, H B Kister, H B	8310270440* 8310310407* 8310120124 8310110179 8310170168*	50-305 Q 50-407 Q 50-247 B 50-272 S 50-333 Q	KOESTER, O L KOESTER, O L KOLB, L E KOLB, L E KOLB, L E	8310250084 8310250133 8310030343 8310070126 8310070338	50-482 0 50-482 A 50-395 8 50-395 8
KEMPER, J B KEMPER, J, S KEMPER, J, S KEMPER, J B KEMPER, J B.	8310120392 8310140093 8310140197 8310170225 8310180423	50-352 E 50-352 A 50-352 A 70-2988 50-352 C	KLECKER, R W KLEIN, T J. KLEIN, T J KLEINSORGE, W P. KLEINSORGE, W P.	8310070317 8310030203 8310030221 8310040316* 8310250404*	NUREQ 40-8584 40-8584 50-250 g 50-413 g	KONKLIN' J E KONKLIN' J E KOLB' W M KOFB' F E	8310310234 8310270283 8310240315 8310040540* 8310050382*	50-393 8 50-263 8 FOIA 50-546 0 50-440 0
KEMPER, J 8 KEMPER, J 9 KEMPTHORNE, P J KENNEDY, D M. KENNY, T.	B310250419 8310280013 8310210241* 8310120254 8310120124	50-277 0 50-352 8 50-275 T 50-255 R 50-247 8	KLIMM,R D KLIMM,R D KLINE,J R KLINGLER,G KLINGLER,G	8310050491# 8310050491# 8310040194 8310040214 8310060005	50-155 0 50-155 0 27-39 50-272 0 50-220 0	KONKLIN.JE KONKLIN.JE KONKLIN.JE KONKLIN.JE KOON,AR	8310060462* 8310170643* 8310170670* 8310240137* 8310210128	50-483
KENNY, T. J. KENT, Q. J KENYON, B. D KENYON, B. D.	8310120179# 831019037 831003039& 831018035&# 831019080	50-286 G 50-344 R PR 50-387 G 50-387 R	Whicefea' o Whee' h' e Whubir' h Wringfea' o Wringfea' o	6310140040 6310210030 8310270508 6310170243 8310140216#	16E 30-329 g FOIA NUREG 70-1308	KIISLA, B M KOUBARI, B KOVACK, T J KOVACK, T J KOYAMA, E	8310070037* 8310070414 8310060545* 8310200082* 8310170669	40-8027 NUREG 50-254 F 50-254 F 70-984
KENYON, B. D KENYON, B. D KENYON, B. D KEDHAN, P. J	8310250246 8310250252* 8310270449 8310270453* 8310030370*	50-387 P 50-387 P 50-387 P 50-387 P CONTRACT	KWICHT' 7' B KWICHT' 7' B KWICETEA' 7' B' KWICETEA' 7' B	831 0250 582* 831 031 0347* 831 0030 641 800 7290 663* 831 0050 059*	70-2977 50-341	KRAUS,H J KRAUSE,D F KRAUSE,D F KRAUSE,D F KRAUSE,D F	8310120304 8310140027 8310140137* 8310270172 8310270213*	50-35B A 50-315 8 50-316 8 50-316 8 50-315 \$
KEPPLER, J. G KEPPLER, J. G KEPPLER, J. G, KEPPLER, J. G,	8310050341 8310060375 8310060477 8310060515 8310110583#	50-327 A 50-461 Q 50-358 A MIBC FOIA	KNICHT, J P KMICHT, J P KMICHT, J, P KMICHT, J, P KMICHT, J, P.	8310210355* 8310210357* 8310210358* 8310210385* 8310250018*	50-275 T 50-275 T 50-275 T 50-275 T TOPREP	KRECHTING, JE KRECHTING, JE KREH, JL KRICH, RM KRIEGER, RW	8310180361* 8310180375* 8310250304* 8310170351 8310070283	50-275 T 50-275 T 50-390 Q 50-255 B 50-206 F
KEPPLER, J. Q. KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q	8310130234 8310140054 8310180267 8310200157 8310210067	50-358 A 50-358 A 50-358 R 50-358 G 50-358 A	Knioht, J P Knioht, M R. Knioht, M R Kniohten, G W Kniohten, G W	8310250332* 8310250294 8310250430 8310040643* 8310060508	50-275 T 50-287 S 50-287 S 50-362 P 50-362 P	KRIEGER.R W KRIEGER.R W KRIEGER.R W KRIEGER.R W KRIEGER.R W	8310070344 8310120170 8310130127 8310130314 8310140223	TOPREP 50-206 P 50-206 P 50-204 P 50-206 P
KEPPLER, J. D KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O	8310210105 8310240107 8310250191 8310250275 8310250522	50-358 G 50-329 A 50-255 G 50-282 G 50-155 G	Knighton, g w Knighton, g w Knighton, g w Knighton, g w Knighton, g, w.	8310060510 8310060514 8310060524 8310060530 8310060537*	50-412 A 50-412 A 50-412 A 50-412 A 50-387 P	KRIEGER,R W KRIEGERIR W KRUG.H E KUBICKI.D J KUBICKI.D J	8310200284 8310250174 8310250216* 8310210378* 8310250182*	50~206 P 50~206 P 50~416 G 50~275 T 50~275 T
KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G. KEPPLER, J. G.	8310250538 8310250576 8310260155* 8310260234* 8310260265*	50-263 G 50-358 G FOIA FOIA 70-1144	Knighton, C H Knighton, C H Knighton, G W Knighton, O. H Knighton, G W	8310170537 8310180177* 8310180620 8310200036 8310200042*	50-275 Q 50-361 F 50-275 F 50-412 M 50-412 M	Kuczynski, L a Kuczynski, L a Kuczynski, L a Kuczynski, L a	8310170080 8310170145 8310200271 8310250242 8310250245	50-387 fl 50-387 fl 50-387 fl 50-387 fl 50-387 fl
KEPPLER, J C. KERR, G H KERR, G H KERB, D. A KERB, L.	8310310356 8310110615* 8310260229* 8310310275 8310140267*	40-2041 Commission Foia 50-87 8 50-237 g	Knighton, G. W Knighton, G. W Knighton, G. W Knighton, G. W, Knop, R. C.	8310200070 8310200171 8310210154 8310270254 8310040158	50-382 A 50-382 A 50-275 P 50-382 A 50-454 Q	KUCZYNSKI,L A KUCZYNSKI,L A KUCZYNSKI,L A KUCZYNSKI,L A KUECHLE,C	8310250244 8310250384 8310250555 8310250422 8310210218	50-387 8 50-387 8 50-387 8 50-387 8 50-304 8
WESEL, D. T. METTENRING, N E. KIBLER, D. R. KILCOYNE, J J.	8310310359 8310270070 8310120400 8310270298 8310060138*	50-220 8 F01A 50-331 8 50-289 G CONTRACT	KNOP; R. C KNOP; R. C KNOP; R. C. KNOP; R. C. KNOP; R. C	8310040268 8310040424 8310040526 8310060282 8310060449	50-483 G 50-454 G 50-546 G 50-461 G 50-483 G	KUNGL, L G KUNGL, L G KUNGL, L G KUNDALKAR, R KUO, P	8310110178 8310180471 8310310310 8310250128* 8310210358*	50-298 P 50-298 G 50-298 G 50-296 P 50-275 T

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGOR
KUO.P	8310210371*	50-275 T	LEDUC, R J	B310310430*	71-9086	LEWIB, R C	8310040502	50-416
KUO.P T	8308150338*	50-329 A	LEE, G W	B310210320	FDIA	LEWIB, R C	8310040595	50-400
KUPIEC.C F	8310190283	NUREG	LEE, J	B3100404B3	50-920 H	LEWIB, R C	8310040608*	50-400
KURTH.R E	8310110475*	FOIA	LEE, O R	B310130173	50-267 P	LEWIB, R C	8310110157	50-324
KURTH.R E	8310110480*	FOIA	LEE, O R	B310130200*	50-267 P	LEWIS, R C	8310250131	50-259
KUYKENDALL,J C	8310180397	71~504	LEE.O R	8310130240	50-267 P	LEWIS,R C	8310250166	50-259
KYLE,W C	8310280177*	40-299	LEE.O R	8310130272	50-267 P	LEWIS,R C	8310250174*	50-259
LA VIE,S F	8310180434*	50-334 F	LEE.O R	8310130275*	50-267 P	LEWIS,R C	8310250208	50-400
LABARGE,D E	8310120339	PR	LEE.O R	8310130281	50-267 P	LEWIS,R C	8310250247*	50-259
LABAT,V	8310110192*	CONTRACT	LEE.O R	8310130300	50-267 P	LEWIS,R C	8310250268*	50-416
LABDON, T A LACEY, W S LACEY, W S LACEY, W S LAFLEUR, J D	9310190187 9310250946 8310250595 8310280010 8310170457*	MISC 50-334 S 50-334 S 50-334 S FOIA	LEE, OR LEE, OR LEE, WS LEECH, PH LEMPGES, C	8310130303* 8310130324* 8310240061* 8310240103 8310070436	50-267 P 50-267 P 50-413 T 50-336 P NUREG	LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8310250403 8310250424 8310250442* 8310250454* 8310250457*	50-327 50-250 50-250 50-327 50-324
LAINAS.G C	8310240053*	FOIA	LEMPOES, T.E.	8310040597	50-220 P	LEWIS,R C.	8310250466*	50-324
LAINAS.G C	8310240058*	FOIA	LEMPOES, T.E.	8310040361	50-220 F	LEWIS,R C	8310250475	50-327
LAINAS.G C	8310240041*	FOIA	LEMPOES, T.E	8310140111	50-220 R	LEWIS,R C	8310250519	50-321
LAINAS.G C	8310240044*	FOIA	LEMPOES, T.E	8310190169	50-220 S	LEWIS,R C.	8310250530*	50-369
LAINAS.G C	8310240049*	FOIA	LEMPOES, T.E	8310270212*	50-220 Q	LEWIS,R C.	8310250580	50-369
LAINAS, G C	8310260071*	FOIA	LEMPGES, T E	8310270217#	50-220 G	LEWIS,R C.	8310250418*	50-261
LAINAS, G C	8310260075*	FOIA	LEMPGES, T E	8310310359	50-220 S	LEWIS,R C	8310250446*	50-269
LAINAS, G C	8310260078*	FOIA	LENAHAN, J J	8310040042#	50-321 G	LEWIS,S C.	8310250047	50-352
LAINAS, G C	8310260080*	FOIA	LENTINE, F G	8310110117	50-295 P	LIBDY,R A.	8310250381	NUREC
LAINAS, G C	8310260082*	FOIA	LENTINE, F G	8310140175#	50-295 Q	LIBERTOWICZ,F	8310030226	50-458
LAKE, W H	8310060023	71-9852	LENTINE,F G	8310180110	50~295 G	LIBERTOWICZ, F	8310030224	50-459
LAMASTRA, M	8310120217#	50-277 G	LENTINE,F Q	8310200151	50~295 P	LICHTENBERGER	6310180027	70-1100
LAMASTRA, M A	8007170227#	FOIA	LENTINE,F Q	8310310047	50~295 P	LICHTENBERGER	8310190192	70-1100
LAMASTRA, M A	8310170184#	FOIA	LENTINE,F Q	8310310060	50~295 P	LICHTENBERGER	8310190215	70-1100
LAMBERT, W L	8310120415#	50-261 P	LESSY,R F	8310050381*	50~443 G	LICHTENBERGER	8310310287*	70-1100
LAMBERT, W L LANDGRAF, L C LANDIS, K LANDIS, K LANDSMAN, R B	8310120422* 8310170587 8310170236 8310250528* 8310170534*	50-261 P 50-341 K 50-280 S 50-335 Q 50-329 Q	LESSY,R F LESSY.R P LESSY.R P LESSY.R P	8310050388* 8310050346 8310050373 8310050436 8310050472	50-443 G 50-443 G 50-443 G 50-312 G 50-443 G	LICITRA, E. A LICITRA, E. A LICKUB, R M LIDEN, E. A LIDEN, E. A.	8310050010 8310050347 8310140013* 8310040325 8310040327	50-528 50-528 50-305 50-311 50-311
LANDSMAN, R B LANDSMAN, R B LANEY, R V LANEY, R. V LANG, T	8310170591* 8310210319* 8310250093* 8310250097* 8310120239	50-329 Q 50-329 Q 50-397 A 50-397 A 50-346 B	LESSY,R P LESSY,R P LESSY,R P LESSY,R P	8310050474* 8310050477* 8310050480* 8310050512 8310050551	50-443	LIDEN,E A LIDEN,E A LIDEN,E A LIDEN,E A, LIDEN,E A	8310070003 8310070166 8310180251 8310180378* 8310200318	50-272 50-272 50-272 50-272 50-311
LANG, T	6310120391	50-346 S	LEBSY.R P	8310050557	27-39	LIDEN,E A	8310210285	50-272
LANKSBURY, R D	8310050502*	50-373 G	LESBY.R P	8310130046	50-443 G	LIDEN,E A	8310250257	50-272
LANNING, W D	8310060199*	50-251 S	LESBY.R P	8310170394	50-443 G	LIDEN,E A,	8310280119	50-311
LANPHER, L C	8310190209	50-322 G	LESBY.R P	8310250319	50-443 G	LIDEN,E A	8310310225	50-311
LANPHER, L C	8310190209	50-322 G	LETBCH.D E	8310060355	MISC	LIDBTONE,C.	8310240045	40-8584
LANPHER, L C LANPHER, L C LANPHER, L C LANPHER, L C LANPHER, L C	8310200217 8310200217 8310200262 8310200262 8310240160	50-322	LETBCHE,K LETBCHE,K LETBCHE,K J LETBCHE,K J LETBCHE,K J	8310040177 8310040177 8310030456 8310030456 8310050416	50-322	LIEBERMAN, J LIN. M LINDER, F LINDER, F LINDER, F	8310180364 8310310114 8310050101 8310130311* 8310170159	50-321 NUREG 50-409 50-409 50-409
LANPHER, L C LAPP, R E LARKINS, J T LASATER, G T LASATER, G T	8310240140 8310110530 8310200377 8310050501* 8310050501*	50-322	LETSCHE, K J LETSCHE, K J LEVIN, H A LEVIN, H A LEVIN, H A	8310050416 8310270239 8310170624 8310210272 8310210275*	50-322	LINDER, F LINDER, F LINDER, F LINDER, F LINDHOLM, U B	8310170364 8310190027 8310210002 8310310163* 8310380149*	50~409 50~409 50~409 50~409 50~259
LATHAM, W	8310120358*	50-312 G	LEVIN.J J	8310270126	FOIA	LINDHOLM, U 6	8310280150*	50-259
LATHAM, W K	8310040033	50-312 F	LEVINE.J M	8310060250*	50-313 F	LINDHOLM, U 9	9310280151*	50-259
LATHAM, W K	8310250598	50-312 S	LEVINE.J M	8310110440*	50-313 F	LINDSAY, M. E	8310110591*	FOIA
LAUER, R J	8310240172	50-327 G	LEVINE.J M.	8310130180	50-348 S	LINDSEY, C. G	8310310208	NURE9
LAUER, R J	8310240172	50-327 G	LEVINE.J M	8310170275*	50-313 F	LINDSEY, D J	8310170082	50-333
LAURENBON, J A LAURENBON, J A LAURENBON, J A LAURENBON, J A	8310040196 8310040202 8310040286 8310170401 6310310190	50-322	LEVY. D LEWIS, D LEWIS, E LEWIS, E LEWIS, E	8310260302 8310070198* 8310060363 8310140067 8310310127	50-142 H CONTRACT 50-443 U 50-454 Q 50-454 G	LINEHAN, J J LINEHAN, J J LINEHAN, J J. LINEHAN, J J LINENBERGER, G	8310200373* 8310200452 8310240095* 8310270524* 8310120398	40-7869 40-8674 40-8681 40-8698 50-458
LAURENBON, J A	8310310248	50-322	LEWIS, L	8310170334	71-9039	LINTAKAS: A	8310210222	50-373
LAVERTY, J H	8310110208		LEWIS, M I	8310030366	PR	LINVILLE: J	8310140038	50-311
LAVERTY, J H	8310180243		LEWIS, M I	8310040334	PR	LINVILLE: J. C.	8310140279*	50-272
LAVERTY, J H	8310180243		LEWIS, M I	8310040491	50-352 0	LIPARULO: N J	8310140046*	50-315
LAWBON, L T	8310210312		LEWIS, M I.	8310270268	50-352 0	LISTER: S. E	8310200374	FOIA
LAZARUB, W J	8310120096*	50-220 G	LEWIS, M I	8310270354*	50-352	LITTLE, B H,	8310170643*	50-341
LAZARUB, W J	8310210220*	50-244 G	LEWIS, R, C	8310270362*		LITTLE, J	8310250658	XPORTLIC
LAZO, L	8310050352	50-412 A	LEWIS, R, C	8310040046		LITTLE, W B,	8310040176	50-346
LAZO, R M	8310120390	70-25	LEWIS, R, C	8310040220		LITTLE, W B,	8310040257	50-454
LE, A K	8309200506*	50-267 G	LEWIS, R, C	8310040269		LITTLE, W B	8310050492	50-341
LEAVERTON, W	8310210054	50-245 8	LEWIS, R. C.	8310040313	50-413 G	LITTLE, W S	8310110443*	50-315
LEAVY, W F,	8310130385*	CONTRACT	LEWIS, R. C.	8310040323*	50-413 G	LITTLE, W S	8310140179	50-454
LECLAIR, D C	8310060115*	CONTRACT	LEWIS, R. C.	8310040354	50-321 G	LITTLE, W S	8310200045	50-440
LEDDICK, R S	8310030060	50-382 K	LEWIS, R. C.	8310040374	50-416 F	LITTLE, W S	8310200049*	50-440
LEDDICK, R S	8310030063*	50-388 K	LEWIS, R. C	8310040405	50-250 G	LITTLE, W S	8310200053*	50-440
LEDDICK,R 8	8310070001	50-382 H	Lewis, R.C.	8310040458	50-335	LITTLE, H S	8310200159	50-373
LEDDICK,R,S	8310070247	50-382 A	Lewis, R.C.	8310040466		LITTLE, H S	8310200274	50-358
LEDFORD, 8	8310240068*	50-413 T	Lewis, R.C.	8310040468*		LITTLE, H S	8310240069	50-456
LEDUC,R J	8310170218	71-9093	Lewis, R.C.	8310040475*		LITTLE, H S	8310270446	50-255
LEDUC,R J	8310170228	71-9092	Lewis, R.C.	8310040476		LIVERMORE, H H.	8310250642*	50-461

Ę

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LIVINOSTON, A J LIVINOSTON, A J LIVINOSTON, A J LOCKE, D L LOCKER, R F.	8310240271* 8310240282* 8310240275* 8310040483* 8310110073	FOIA FOIA CONTRACT 50-275 G	MACDONALD, C E	8310070062* 8310110090 8310110402 8310110410* 8310110416	71-9070 71-505	MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L MADSEN, G L	8310180214 8310180218 8310180225 8310180412 8310180466	50-445 q 50-445 q 50-278 q 50-278 q 50-445 q
LOFY: R A LOGIUDICE, J M LOHR, J LOMBARDO, J, J LOMBARDO, J J	8310170550# 8310170281# 8310250369 8310210209 8310240124	CONTRACT CONTRACT 50-318 S 50-219 P 50-219 P	MACDONALD, C E	8310110423* 83101106!1 83101106!4* 83101106!9 8310110621	71~9128	MADSEN, G L MADSEN, G L MADSEN, G L MAGER, T R MAGER, T R	8310310256 8310310388* 8310310402 8310060310 8310060310	50-445 @ 50-267 P 50-382 @ 50-413 T 50-413 T
LONERGAM. G T LONERGAM, G. T LONG, J A LOTITO, E M LOUDERBACK, T E	8310240137* 8310240250* 8310110378* 8310170148 8310240052	FOIA 70-1144 FOIA 50-317 R 40-8714	MACDONALD, C E	8310110422* 8310110423* 8310110425 8310110427* 8310110428	71-9127 71-9126	MAHLER,R J MAHON.C R MAIER.J E MAIER.J E MAIER.J E	8310070331* 8310200147 8310180192 8310180193 8310250217	CONTRACT 50-317 8 50-244 P 50-244 P 50-244 S
LOVE, R. S LOVENDALE, P LOVENDALE, P C LOVENDALE, P C LOW, L. D	8310140172* 8310140255 8310140214* 8310270313* 8310240131*	50-454 G 50-266 B 70-1308 50-266 G FOIA	MACDONALD, C E	8310110631* 8310120001 8310120002* 8310170237 8310170240*	71 - 91 08 71 ~ 64 78 71 - 64 78 71 - 64 78 71 - 55 95 71 - 55 95	MAIER, J E MAIER, J E MAIER, P MALINOWSKI, F A MALLETT, B S	8310250305 8310270086* 8310270410* 8310170221 8310110534*	50-244 8 50-244 F 50-263 9 71-9027 FDIA
LOWENSTEIN, R LOWENSTEIN, R LOWENSTEIN, R LUBBOCK, D Q	8310260199* 8310270133* 8310270144* 8310040251 8310040525	FDIA FDIA FDIA 50~275 G 50~275 G	MACDONALD, C E	831 0200012 831 0240257 831 0240259* 831 0240289 831 0240292	71 -61 44 71 -54 50 71 -54 50 71 -6574 71 -9027	MALLETT, B S MALODY, C W MALODY, C W MALODY, C W MALODY, C W	8310110562* 8310120357* 8310130208 8310170233 8310170236*	FDIA 70-1257 70-1257 70-1257 70-1257
LUBBOCK, D. Q LUBBOCK, D. Q LUCK, W. D. LUCKS, A. S. LUCKS, A. S	8310050394 8310160328 8310240292 8310170538* 8310170544*	50-275 G 50-275 G 50-537 G 50-329 G 50-329 G	MACDONALD, C E	8310240297 8310240299 8310240303* 8310240305 8310240307*	71 – 6771 71 – 9852 71 – 9852 71 – 903 71 – 503	MANGAN, C V MANGAN, C V MANGAN, C V MANGAN, C V MANGAN, C V	8310040631 8310060149 8310120077 8310120205 8310120373	50-220 P 50-220 F 50-220 P 50-220 P 50-220 P
LUCKS, A. S LUCKS, A S LUCKS, A S	8310170549* 8310170555* 8310170559* 8310170616* 8310170622*	50-327 Q 50-327 Q 50-327 Q 50-327 Q 50-327 Q	MACDONALD, C E	8310240308 8310240317 8310240317* 8310250015 8310250022	71-9086 71-504 71-304 71-9010 71-9039	Mangan, C V Mangan, C V Mangan, C V Mangan, C V Mangan, C V	8310120406 8310120416* 8310140221 8310170586 8310180078	50-220 P 50-220 P 50-220 P 50-220 P 50-220 P
LUCKS, A. 8 LUCKS, A. 8. LUCO, J E LUDINGTON, B W LUDINGTON, B W	8310170627# 8310170634# 8310110582# 8210010087# 8306160602#	50-329 G 50-329 G CONTRACT 50-272 P 50-302 P	MAGDONALD.C E MAGDONALD.C E MAGDONALD.C E MAGDONALD.C E MAGDONALD.C E	6310250029 6310260013 6310310428 6310310461 6310210174	71-9089 71-9111 71-9086 71-9182 50-298 5	Mangan, C V Mangan, C V Mangan, C V Mann, B Manno, B F	6310210171 6310310228 6310310226 6310130143 6310170153	50-220 P 50-410 K 50-410 A NUREG 50-410 B
LUEBKE, E A LUEBKE, E A LUMB, R F LUNDVALL, A. E	8310040172 8310040174 8310260263 8310070189* 8310040353	50-142 G 27-39 50-142 G CONTRACT 50-317 P	Mackay, B Mackay, B D Mackay, B D Mackay, B D Mackay, B D	8310240080 8310050451 8310060031 8310060043* 8310240138	50-324 F 50-324 F 50-324 P 50-324 P 50-324 P	MANNO, 8 F MAPP, E T MARCHAL, J MARCHAL, J MARCHAL, J	8310280052 8310260070* 8310060415 8310060420 8310060424	50-410 9 FOIA XPORTLIC XPORTLIC XPORTLIC
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8310200241 8310210210* 8310240072 8310240134 8310240162	50-317 P 50-317 Q 50-317 P 50-317 P 50-317 F	MACKAY, B D. MACKENZIE, D R MACPHERSON, B J MACPHERSON, B J MACPHERSON, B J	8310280129 8310310114 8310240313 8310250135 8310250158	50-324 F NUREG XPORTLIC XPORTLIC XPORTLIC	MARCHI, M.L. MARCHI, M.L. MARCHI, M.L. MARCHI, M.L. MARCHI, M.L.	8310120209* 8310120214* 8310120216* 8310120220* 8310120223*	50-305 F 50-305 F 50-305 F 50-305 F
LUNDYALL, A. E LUNDY, J R LYCZKOWSKI, J V LYCZKOWSKI, J V LYKOUDIS, P S	8310310303 8310110404* 8310040519* 8310040519* 8310190329*	50-317 P FOIA 50-155 T 50-155 T FOIA	Macrusky, J Macrusky, J Macswain, D Macswain, D Madden, J. R	8310250423* 8310250600* 8310120341* 8310120345* 8310110147*	50-275 G 50-312 P 50-305 P 50-305 P FOIA	MARCHI,M L MARCHI,M L MARCHI,M L MARCHI,M L MARCOUX,W C	8310120227* 8310120232* 8310120235* 8310120238* 8310050298	50-305 F 50-305 F 50-305 F 50-305 F 50-285 P
LYNCH: M D, LYONB: P J L LYONB: P J L LYONB: T D MA: J.	8310240105 8310260416 8310280165 8310270105* 8310170484*	50-341 A 40-299 40-299 FOIA 50-382 Q	MADDEN, W MADEDA, T. J MADEDA, T. J MADEDA, T. J MADEDA, T. J	8310040213 8310140216* 8310250582* 8310270313* 8310310347*	50-272 8 70-1308 70-2977 50-246 G 50-341 0	MARCOUX, W C MARCUSON, W F MARIANI, L P MARKEY, E J MARKEY, E J	8310050298 8310050337* 8310030394 8310040594* 8310070380*	50-285 P CONTRACT PR 50-382 U COMMISSION
MABRITO, B MACCUSKY, J. MACDONALD, C. MACDONALD, C. E MACDONALD, C. E	8310190343 8310250152* 8310050195 8310040094 8310040099*	71-505 ORG 71-9080 71-466 71-466	MADSEN.C.L. MADSEN.G.L. MADSEN.G.L. MADSEN.G.L. MADSEN,G.L.	8310030344 8310030385 8310030402 8310030446 8310040153	50-247	MARKEY, E J MARKY, D MARKY, D MARKY, D, E MARSHALL, J R	8310200469* 8310270042* 8310270042* 8310270534* 8310030332	50-275 U 50-309 F 50-309 F 50-29 F 50-313 P
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8310040171 8310050014 8310050014 8310050019 8310050021	71-9182 71-59 71-6003 71-4909 71-9158	Madben, Q L Madben, Q L Madben, Q L. Madben, Q L. Madben, Q L.	8310040156 8310040181 8310040223 8310040456 8310040536	50-445 Q 50-445 Q 50-445 Q 50-267 P 50-498 Q	MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8310030353 8310030416 8310040149 8310040154 8310040206	50~313 P 50~313 F 50~348 S 50~313 S 50~348 S
MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E. MACDONALD, C. E MACDONALD, C. E	8310050025 8310050030* 8310050041* 8310050046 8310050053	71-9510 71-9510 71-6003 71-9080 71-9100	MADSEN, G. L. MADSEN, G. L. MADSEN, G. L. MADSEN, G. L. MADSEN, G. L.	8310040558 8310040580 8310060013 8310060377 8310060459	50-267 0 50-267 0 50-267 0 50-382 0 50-382 0	MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8310040291 8310040338 8310060402 8310060601* 8310120447	PR 50-348 S 50-313 P 50-313 F 50-313 P
MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C, E, MACDONALD, C, E,	8310050057* 8310050097 8310050114 8310050124 8310050133*	71-9100 71-5088 71-5059 71-37 71-37	MADBEN, G. L. MADSEN, G. L. MADSEN, G. L. MADSEN, G. L. MADSEN, G. L.	8310130174 8310130206 8310130211* 8310130221 8310130247	50-498 G 50-298 Q 50-298 G 50-498 G 50-458 G	MARSHALL, J. R MARSHALL, J. R MARSHALL, J. R MARSHALL, J. R MARSHALL, J. R	8310130283 8310140074 8310140225 8310180189 8310180457	50-348 8 50-348 F 50-313 P 50-348 8 50-368 9
MACDONALD, C E MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	9310040599 8310040400* 8310070005 8310070017 8310070059	71-9070 71-9070 71-957 71-909 71-9152	MADBEN, Q L MADBEN, Q L MADBEN, Q L, MADBEN, Q, L MADBEN, Q, L	8310130262 8310180144 8310180156 8310180176 8310180212	50-382 0 50-458 0 50-278 0 50-267 F 50-267 P	Marehall, J. R Marehall, J. R Marehall, J. R Marehall, J. R Marehall, J. R	8310180487 8310180529 8310190045 8310190117 8310240035	50-348 S 50-348 S 50-348 R 50-313 R 50-313 J

AUTHOR	ACCESSION RABEN	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJEC CATEGO
MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R MARSHALL, J R	8310250141 8310250153 8310250274 8310250281 8310250417	50-313	MATTIA, M J MATTIA, M J MATTIA, M J MATTIA, M J MATTIA, M J	8310050323* 8310050349* 8310050447* 8310070173* 8310070175*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MCDUFFIE, M A	8310210245 8310230571 8310250638 8310260134 8310260147	50-261 50-261 50-400 50-400 50-400
MARSHALL, JR	8310250533	50-368 P	MATTIA,M J	8310070231*	CONTRACT	MCDUFFIE,M A MCDUFFIE,M A MCDUFFIE,M A MCDUFFIE,M A MCFARLAND,C R	8310240152	50-400
MARSHALL, JR	8310250559	50-313 F	MATTIA,M J	8310070237*	CONTRACT		8310240259	50-400
MARSHALL, JR	8310310268	50-368 B	MATTIA,M J	8310110025*	FOIA		8310280014	50-400
MARSHALL, JS	8310210081	50-445 A	MATTIA,M J	8310110344*	CONTRACT		8310310027	50-241
MARSTON, RR	8310250394*	50-280 Q	MATTIA,M J	8310110499*	CONTRACT		8310040244*	50-438
MARTIN, D	8310240266	WASTE MOT	MATTIA.M J	8310110512*	CONTRACT CONTRACT CONTRACT CONTRACT 50-312 8	MCFARLAND, C R	8310040345*	50-413
MARTIN, D E	8310240267	WASTE MOT	MATTIA.M J	8310110524*		MCFARLAND, G R	8310250406*	50-370
MARTIN, G	8310110407*	50-400 Q	MATTIA.M J	8310130389*		MCGARRY, J M.	8310030406	50-413
MARTIN, J B	8310030457*	50-267 Q	MATTIA.M J	8310130407*		MCGARRY, J M	8310030406	50-413
MARTIN, J B	8310180362	50-244 Q	MATTIMOE,J J	8310120150		MCGAUQHY, J P	8310030373	50-416
MARTIN, J B	8310200220	50-204 Q	MATTIMOE, J J	8310120184	50-312 6	MCGAUGHY, J P	8310030374	50-416
	8310240227*	50-528 Q	MATTIMOE, J J	8310120394	50-312 P	MCGAUGHY, J P.	8310060227	50-416
	8310250152*	ORO	MATTIMOE, J J	8310140249	50-312 Q	MCGAUGHY, J P.	8310130117	50-416
	8310250423*	50-275 Q	MATTIMOE, J J	8310210020	50-312 P	MCGAUGHY, J P.	8310140007	50-417
	8310250400*	50-312 P	MATTIMOE, J J	8310250210	50-312 P	MCGAUGHY, J, P	8310140075	50-416
MARTIN,L E	8310180227*	50-445 Q	MATTSON,R J	8302070323*	50-255 P	McGAUGHY.J.P	8310170400	50-416
MARTIN,M A	8310070289*	50-528 B	MATTSON,R. J	8307080358*	GEN TEC IB	McGAUGHY.JP	8310250387	50-416
MARTIN,M G	8310180313*	GA777	MATTSON,R J	8310110574*	50-247 P	McGAUGHY.JP	8310270433	50-416
MARTIN,M G	8310180323*	GA779	MATTSON,R J	8310110630	50-287 P	McGAUGHY.R W	8310140254	50-331
MARTIN,M G	8310180340*	GA749	MATTSON,R. J	8310130155	50-289 P	McGAUGHY.R.W	8310170405	50-331
MARTIN,R D	8310260027*	50-270 8	W MINITURAM W MINITURAM W MINITURAM W MINITURAM W LORUSAM	8310190200	50-33B Q	MCGAUGHY,R W	8310180198	50-331
MARTIN,R E	8310030360	50-352 A		8310190200	50-33B Q	MCGAUGHY,R W	8310180424	50-331
MARTIN,R E	8310070190	50-352 E		8310260299	50-33B Q	MCGAUGHY,R W	8310200182	50-331
MARTIN,R E	8310260316	50-352 E		8310260299	50-33B Q	MCGAUGHY,R,W.	8310270459	50-331
MARTIN,R G	8310040339	50-309 P		8310060238*	50-400 Q	MCGILTONN,C H	8310210173*	50-397
MARTIN:R K MARTIN:T J MARTIN:T J MARTIN:T J MARTIN:T T	8310280177* 8310280075 8310280073 8310280101 8310030158	40-299 50-354	MAURD, J J. MAURD, J J MAXWELL, B MAXWELL, D. MAXWELL, G. F	8310060238* 8310110407* 8310190337 8310210313 8310040413*	50-400 0 50-400 0 FOIA 50-237 B 50-400 G	MCGUIRE, D. R MCGUIRE, D. R MCGUIRE, D. R MCGUIRE, D. R, MCGUIRE, D. R	8310030305* 8310070259* 8310070294* 8310170149* 8310170238*	50-280 70-143 50-324 50-416 50-259
MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T MARTIN,T T	8310030345 8310040449 8310060004 8310060017 8310060041	50-412	MAXNELL, G. F MAY, E. L MAY, E. L MAY, W. R MAYWEATHER, L	8310250632* 8310250523 8310280015 8310280104* 8310170072	50-400 G 50-29 S 50-29 S CONTRACT 50-361 R	MCQUIRE.D.R MCQUIRE.D R MCQUIRE.D R MCQUIRE.D R MCQUIRE.D R	8310170246* 8310170522* 8310210034* 8310210070* 8310260221*	70-27 50-261 50-259 50-324 70-1113
MARTIN.T T	8310060044	50-244 G	MCAFEE,W R	8310240021*	50-413 T	MCGUIRE:DR	9310270023*	50-321
MARTIN.T T	8310060341	50-334 G	MCALLISTER.B A	8310190231	50-309 8	MCGURREN:H.J	9310050371	50-275
MARTIN.T.T	8310120137	50-29 G	MCALPINE.E J.	8310040148*	70-1151	MCGURREN:HJ	9310130163	50-275
MARTIN.T T	8310120133	50-223 G	MCALPINE.E J.	8310040197*	70-143	MCGURREN:HJ	9310210350	50-275
MARTIN.T T	8310120175	70-135	MCALPINE.E J.	8310040342*	70-824	MCGURREN:HJ	9310250176	50-275
MARTIN,T.T	8310120212	50-277 G	MCALPINE,E J.	8310040493*	70-27	MCGURREN, H J	8310250326	50-275
MARTIN,T T	8310140175	50-286 G	MCALPINE,E J.	8310260114*	70-1151	MCINNIS, D.	8310280174	50-400
MARTIN,T T	8310140234	50-271 G	MCALPINE,E J.	8310260194*	70-1113	MCINTOSH, J T.	8310110076*	50-269
MARTIN,T T	8310180137	70-2808	MCANDREH,A R.	8310260296*	FOIA	MCINTOSH, J, T	8310110141*	50-269
MARTIN,T T	8310180347	50-387 G	MCBREARTY,R,A	8310120096*	50-220 G	MCINTOSH, M D	8310060268*	50-369
MARTIN,T T	8310180366	50-289 Q	MCBREARTY,R A	8310190142*	50-443 G	MCKINNEY,C J	8310070002	50-395
MARTIN,T T	8310190133	50-443 Q	MCBRIDE,C.S	8310110614*	CONTRACT	MCKINNEY,C J	8310170443	50-395
MARTIN,T T	8310190172	50-443 Q	MCBRIDE,L M	8310040322*	50-267 B	MCKINNEY,C,J	8310170568	50-395
MARTIN,T T	8310190246	50-334 Q	MCBRIDE,L M	8310040324*	50-267 B	MCLAUGHLIN,D	8310250401*	50-315
MARTIN,T T	8310200088	50-271 Q	MCBRIDE,L M	8310040328*	50-267 B	MCLAUGHLIN,L	8310190104	50-389
MARTIN,T.T	8310200218	50-289 G	MCBRIDE, M	8310060349*	50-334 G	MCLEAREN, T	8310050367	CONTRAC
MARTIN,T.T	8310210243	50-443 G	MCBRIDE, M	8310140236*	50-271 G	MCLEAREN, T	8310050462	CONTRAC
MARTIN,T T	8310210265	50-309 G	MCGLESKEY, K E	8310270239	50-322 G	MCLEAREN, T.	8310060007	CONTRAC
MARTIN,T T	8310210280	50-289 G	MCCLINTOCK, R. O	7906250181*	FOIA	MCLEAREN, T.	8310180592	CONTRAC
MARTIN,T.T.	8310210286	50-309 G	MCCOLLOM, K A	8310110266	50-445 G	MCLEAREN, T	8310210150	CONTRAC
MARTIN, T T. MARTIN, T T MARTIN, T T, MARTIN, T, T MARTIN, T, T	8310240082 8310250440 8310250512 8310250597 8310270164	70-1100 70-820 50-272	MCCOLLOM, K. A MCCOLLOM, K. A MCCOLLOM, K. A MCCONNELL, T MCCONNELL, T. L.	8310140085* 8310270228 8310270293 8310070131* 8310110079*	50-445 Q 50-445 Q 50-445 Q 50-370 F 50-369 F	MCLOUGHLIN, D. MCMORRIB, J A MCMULLEN, R B MCNAMARA, A E. MCNEILL, C A	8310050548 8310180557* 8310130152* 8310190032 8310060089	50-3 CONTRAC 50-537 50-244 50-333
MARTIN,T T. MARTIN,T,T MARTIN,T T MARTIN,T T MARTIN,T T	8310270184 8310270207 8310270225 8310310337 8310310414	50-29 Q 50-220 Q 50-293 Q 70-474 70-2430	MCCONNELL, T L MCCONNELL, T L MCCOOL, W. B MCDANIEL, A MCDERMOTT, D	8310110421* 8310270144* 8310120032* 8310040282 8310070201	50-369 F 50-369 F 50-201 I 50-261 9 CONTRACT	MCNEILL, C.A MGNEILL, C.A MGNEILL, C.A MGNEILL, C.A MGNEILL, C.A	8310120435 8310170533 8310170082 8310170150 8310170213	50-333 50-333 50-333 50-333
MARTIN, T T	8310310419	70-2317	MCDERMOTT, D	8310190274	CONTRACT	MCNEILL,C,A.	8310200134	50-333
MARTIN, H G	8310120143*	50-29 G	MCDERMOTT, D	8310200458	CONTRACT	MCNEILL,CA.	8310250294	50-333
MARUBICH, R M	8310040560*	50-155 T	MCDUNALD, D Q	8310180298	50-250 H	MCNEILL,CA.	8310250412	50-333
MARUBICH, R M	8310110293*	50-155 T	MCDUNALD, D G,	8310270129	50-250 P	MCNEILL,CA.	8310250585	50-333
MABON, C C	8310190066	50-327 R	MCDUNGUOH, C, L	8310110302	50-456 C	MCNEILL,CA	8310250614	50-333
MABON, H. D	8310270177*	FOIA	MCDUFFIE, M A. MCDUFFIE, M A. MCDUFFIE, M A. MCDUFFIE, M A. MCDUFFIE, M, A.	8310070120	50~400 A	MCNETLL,CA.	8310310203	50~333
MABBENGALE, E	8310270093	FOIA		8310110119	50~400 E	MCNETLL,R	8310070257*	50~275
MABTERSON, V	8310040271	50-373 8		8310120180	50~400 E	MCNETLL,W,	8310030722*	GA799
MATAKES, RE A	8310040453*	GA999		8310130240	50~400 E	MCNETLL,W,M	8310030387*	GA799
MATHIAU, C	8310110184*	50-263 F		8310140126	50~400 E	MCPEEK,EW	8310210330	HISC
MATTHEWS.D B	8310170028	50-289 F	MCDUFFIE, M A	8310180311	50-400 E	MCPHERSON, B R.	8310140129	50-259
MATTHEWS.M L	8310280076	WABTE MOT	MCDUFFIE, M A	8310180474	50-400 E	MCGUILLAN, P G.	8310180314*	GA999
MATTHEWS.T.P	8310180162	50-285 R	MCDUFFIE, M, A	8310210024	50-400 E	MCGUILLAN, P G.	8310180326*	GA999
MATTIA,M	8310110089*	CONTRACT	MCDUFFIE, M, A	8310210046	50-261 P	MCTIERNAN, J. J	8310200401*	FOIA
MATTIA,M.J.	8305130302*	FOIA	MCDUFFIE, M A	8310210136	50-400 F	MCTIERNAN, T. J	8310200371*	FOIA

AUTHOR	ACCESSION NUMBER	908JECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUDJECT Category
MEDFORD, M O MEDFORD, M O MEDFORD, M O MEDFORD, M O	8310030110 8310040007 8310120397 8310130012 8310200177	50-206 F 50-361 P 50-361 P 50-206 F 50-361 P	MILLER, L K MILLER, L K MILLER, L K MILLER, L K MILLER, M	831030346 8310180114 8310200174 8310210041 8310110635	50-272 R 50-311 R 50-272 R 50-311 R 50-329 A	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8310140277 8310170264 8310170733 8310180388 8310190089	50-428 8 50-390 8 70-2941 50-390 A 50-390 B
MEDFORD.M O MEDFORD.M O MEDFORD.M O MEDLOCK.R L MENCZER.W	8310210260 8310250124 8310270101 8310030241 8310060428	50-362 P 50-206 P 50-206 P 40-8452 50-10 E	MILLER, M A	8310110377 8310120464 8310130045 8310170263 8310200247	50-329 A 50-329 F 50-329 A 50-329 E 50-354 G	MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.Ł M	8310190127 8310190220 8310190224 8310210011 8310210015	50-370 B 50-438 B 50-370 B 50-370 B 50-370 B
MENDENHALL, E MENDONCA, M M MENDONCA, M M MERRITT, B MERRITT, S	8310210016 8310170479* 8310310251* 8310210165 8310270424	50-265 S 50-275 G 50-275 G 50-249 S 50-249 S	MILLER,M E MILLER,M I MILLER,M I MILLER,M I MILLER,M I	8310260301 8310060314 8310060314 8310060321* 8310060321*	50-537	MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8310210042 8310210049 8310210048 8310210078* 8310210096	50-390 8 50-390 9 50-390 8 50-259 9 50-390 8
MERRIWEATHER, N MERRIWEATHER, N MESLER, R B MESSING, A W MEYER, Q C	8310200057* 8310270426* 8310210237 8310270109* 8310270006	50-440	MILLER,M R MILLER,M R MILLER,M R MILLER,R P MILLER,T D	8310260052* 8310260084* 8310260351* 8310070429* 8310030467*	FOIA FOIA FOIA CONTRACT GA799	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8310210178 8310210301 8310210383* 8310250012 8310250034	50~438 A 50~390 E 50~259 F 50~390 S 50~390 A
MEYERJO C MEYERJT A MEYERJT A MEYERJW A MEYERBJB L	8310280306 8310060310 8310060310 8310190347 8310310074	50-470 A 50-413 T 50-413 T 50-184 F 50-482 B	MILLER,W H MILLER,W O MILLER,W O MILLER,W O	8310250498* 8310030625 8310040548 6310130424 8310180025	50-348 Q 50-339 P 50-301 P 50-206 F 50-302 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8310250082 8310250110 8310250138* 8310250149 8310250162	50-257 P 50-438 8 50-257 0 50-438 8 50-390 8
MICHAELS, T S MILES, D E MILES, J R MILHOAN, J L MILLER, A	8310140270 8310070414 8310110524* 8310190270* 8310070436	50-269 P NUREO CONTRACT 50-454 G NUREO	MILLER,W O MILLER,W O MILLER,W O MILLER,W O MILLER,W O	8310180280 8310210075 8310210080 8310210101 8310210157	50-348 P 50-250 P 50-313 P 50-278 P 50-317 P	WILLS'F W WILLS'F W WILLS'F W WILLS'F W	8310250165 8310250170* 8310250173 8310250227 8310250233	50-390 6 50-259 0 50-390 6 50-259 0 50-390 8
MILLER, C A MILLER, D B MILLER, D B MILLER, D B MILLER, D B.	8310210358* 6310140273* 8310170257 8310170437* 8310170714	50-275 T 50-329 A 50-329 A 50-329 A 50-329 A	MILLER, W O HILLER, W S MILLIGAN, H H MILLS, L M HILLS, L M	8310210351 8310280083 8310310494* 8310030214 8310030233	50-334 P 50-352 H 50-322 S 50-370 S 50-370 S	MILLS.L M MILLS.L M MILLS.L M MILLS.L M MILLS.L M	8310250240* 8310250306* 8310250313* 8310250371 8310250378	50~259 Q 50~438 Q 50~438 Q 50~390 S 50~390 S
MILLER,D B. MILLER,D E MILLER,H J MILLER,J F MILLER,J F	8310250058 8310140216* 8310240260 8310120369 8310120374*	50-329 A 70-1308 WABTE MOT 50-29 P 50-29 P	MILLE, L M MILLE, L M MILLE, L M MILLE, L M MILLE, L M	8310030244 8310030252 8310030257 8310030338 8310030365	50-390 S 50-390 B 50-390 B 50-390 B 50-390 S	MILLB, L M MILLB, L M MILLS, L M MILLS, L M	831025043&* 8310250484* 8310250602* 8310250364 8310270180	50-327 Q 50-327 Q 50-327 Q 40-1341 50-370 \$
MILLER, J R MILLER, J R MILLER, J R MILLER, J R MILLER, J R	8310040520 8310070179* 8310070183* 8310110444 8310110457	50-313 F 50-317 F 50-335 P 50-266 P	MILLB:L M MILLB:L M MILLB:L M MILLB:L M MILLB:L M	8310030370 8310030388 8310030397 8310030404 8310030424	50-370 S 50-370 S 50-370 S 50-370 S 50-370 B	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8310270183 8310270248 8310280021 8310280022 8310280148	50-390 SI 50-438 SI 50-327 P 50-327 P 50-259 P
MILLER, JR MILLER, JR MILLER, JR MILLER, JR MILLER, JR	8310110466 8310110483 8310110492 8310110497 8310110498	50-334 P 50-335 P 50-309 P 50-387 P 50-282 P	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8310030434 8310030442 8310030473 8310030504 8310030519	50-370 B 50-370 B 50-370 B 50-370 B 50-370 B	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8310280173 8310280321 8310310142 8310310148 8310310157	50-390 A 40-1341 50-259 P 50-390 B 50-438 B
MILLER, J. R MILLER, J. R MILLER, J. R MILLER, J. R MILLER, J. R	8310110304 8310110543 8310130033 8310130036* 8310130044*	50-266 P 50-336 P 50-266 P 50-266 P 50-266 P	MILLS, L M MILLS, L M MILLS, L M. MILLS, L M.	8310030538 8310040138 8310040172 8310040180 8310040193	50-390 B 50-390 B 50-43B S 50-390 S 50-390 B	MILLB.L M MILLB.L M MILLB.L M MILLB.L M MILLS.M	8310310320 8310310348 8310310387 8310310429 8310130143	50-390 8 50-390 8 50-259 F 50-327 P NUREG
MILLER, JR MILLER, JR MILLER, JR MILLER, JR MILLER, JR	8310130056# 8310130076# 8310130202# 8310130423 8310170088	50-266 P 50-282 P 50-266 P 50-389 P 50-385 P	MILLB, L M MILLB, L M MILLB, L M MILLB, L M	8310040271* 8310040402 8310040452 8310040544 8310040549	50-259 Q 50-370 F 50-259 F 50-390 S 50-390 B	MIMB, R MIMB, R MINECK, D L MINECK, D L MINECK, D L	8310130406* 8310130407* 8310120380 8310120400 8310120421	CONTRACT CONTRACT 50-331 8 50-331 8
MILLER, J R MILLER, J R MILLER, J R MILLER, J R MILLER, J R	9310170708 9310170723 8310180020 9310180405 9310180410*	50-309 P 50-266 P 50-309 F 50-285 G 50-285 G	MILLS.L M MILLS.L M MILLS.L.M. MILLS.L.M.	8310040008 8310040009 8310040014 8310040027 8310040087	50-390 S 50-390 S 50-390 S 50-390 S 50-390 S	MINECK, D L MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8310170490 8310170581 8310190068 8310210090 8310250481	50-331 R 50-331 R 50-331 R 50-331 S 50-331 S
MILLER, J R MILLER, J R, MILLER, J R MILLER, J R, MILLER, J. R	8310180608 8310240108* 8310240113* 8310240122* 8310240216	50-344 P 50-336 P 50-336 P 50-266 P 50-309 P	MILLS, L M MILLS, L M MILLS, L M. MILLS, L M.	8310060095 8310060331 8310060342 8310060436 8310060476	50-370 B 50-370 B 50-370 B 50-370 B 50-370 B	Mineck, D L Miner, 8 Minnich, J E Minnich, J E Minnich, J E	8310270290 8310050517* 8310280072 8310120171 8310140025	50-331 8 50-312 0 50-312 P 50-320 H 50-320 P
Miller, J. 8, Miller, J R Miller, J R. Miller, J, R. Miller, J R	0310250677 0310260358 0310260429 0310270555 0310280087	50-307 P 50-307 P 50-309 P 50-266 P 50-285 P	MILLS.L M MILLS.L.M MILLS.L.M MILLS.L.M	83100404BB 8310110199* 8310120100 8310120149 8310120210	50-390 B 50-259 F 50-390 B 50-390 B 50-390 B	MIRAGLIA,F. MIRAGLIA,F J MIRAGLIA,F J MIRAGLIA,F J MIRAGLIA,F J	8310140292 8211020311* 8211040474* 8212130174* 8310180351	50-287 P FOIA FOIA FOIA 50-155 Q
Miller, J. A. Miller, J A Miller, J. R. Miller, J. R Miller, J R	8310380078 8310310123 8310310125 8310310129 8310310173	50~266 P 50~282 F 50~335 P 50~285 P 50~262 G	MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	9310120228 9310120234 9310120237 9310120332 9310120336	50-438 8 50-370 8 50-370 8 50-370 8 50-370 8	MIRAGLIA:F, J. MIRAGLIA:F J MIRAGLIA:F, J. MIRAGLIA:F J MIRAGLIA:F J	8310250013 8310260086* 8310260087* 8310260071* 8310260072*	TOPREP FOIA FOIA FOIA FOIA
Hiller, J. R. Miller, J. R Hiller, J. R Miller, J. R Miller, L.	8310310177* 8310310180 8310310458 8310310479 8310040512*	50-282 Q 50-317 P 50-335 8 50-317 P CONTRACT	MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8310120389 8310120396 8310140017 8310140048 8310140224	50-390 8 50-390 8 50-390 8 50-390 8 50-390 A	Miraolia, f J Mibak, a Mibak, a L Mibhima, J Mibbio, D	8310260353 8310270404 8310180263 8310260381 8310120239	50-244 P 50-254 B 50-254 R NUREC 50-346 B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MIESIG, D	8310120391	50-344 8	MORTON, K V MORTON, K V MORTON, K V MOSELEY, N C MOSHER, D	8310210178*	CONTRACT	MUSOLF, D	8310120102	50-292 8
MITCHELL, D H	8310110347	NUREQ		8310210211*	CONTRACT	MUSOLF, D	8310120340	50-306 8
MITCHELL, G J	8310180016*	COMMISSION		8310280104*	CONTRACT	MUSOLF, D	8310120432	50-263 H
MITTL, R L	8310200239	50-354 E		8310280132*	FOIA	MUSOLF, D	8310170641	50-306 8
MITTL, R L	8310240143	50-354 F		8310170052	FOIA	MUSOLF, D	8310170021	50-263 R
MITTL.R L MIZUND.O S MIZUND.O S MOEGGENBERG.D MOELLER.P A	8310250215 8310250240 8310250275 8310180187 8310210195	50-354 A 50-445 G 50-445 G 50-368 S 50-272 F	MOBLAK, T MODRY, W R MODRY, W R MODRY, W R MODRY, W R	8310140170* 8310060177 8310130270 8310170064 8310250393	50-320 G XPORTL IC 71-6346 71-6346 PR	HUSOLF, D HUSOLF, D HUSOLF, D HUSOLF, D HUSOLF, D	8310170055 8310210257 8310270283 8310270357* 8310270364*	50-263 R 50-263 B 50-263 B 50-263 S
MOLES,R C MOLNAR,J R MONTGOMERY,D M MONTGOMERY,D M MONTGOMERY,D M	8310110528*	CONTRACT	MOYER,R E	8310260323	XPDRTLIC	MUSOLF, D	8310270380*	50-266 8
	8310190031	50-219 R	MRDCZKA,E J	8310180336	50-245 8	MUSOLF, D	8310270390*	50-263 8
	8310040517*	50-250 Q	MRDCZKA,E J	8310180336	50-245 9	MUSOLF, D	8310270410*	50-263 8
	8310250352*	70-143	MRDCZKA,E J	8310190015	50-245 R	MUSOLF, D	8310270414*	50-263 8
	8310250438*	50-280 Q	MRDCZKA,E J	8310190015	50-245 R	MUSOLF, D	8310270418*	50-282 8
WOONEY, J A MOONEY, J A MOONEY, J A MOONEY, J A MOONTONERY, J L MOONTONERY, J L	8310030457* 8310180246* 8310110570 8310040122 8310050276	50-267 G 50-285 G MIBC 50-329 A 50-329 A	MROCZKA,E J MROCZKA,E J MROCZKA,E J MROCZKA,E J MROCZKA,E J	8310190207 8310190207 8310200129 8310200167 8310250263	50-336 R 50-336 R 50-245 R 50-336 R 50-245 S	MUSDLF, D MUSDLF, D MUSDLF, D MUSDLF, D MYERB, D A	8310270421* 8310270425* 8310270427* 8310270429* 8310110347	50-282 8 50-282 8 50-306 8 MUREC
MODNEY, J A	8310050322	50-327 A	MROCZKA,E J	8310250263	50-245 S	MYERS, D O	B310040332*	50-324 Q
MODRE, D E	8310170238*	50-259 G	MUFFETT,J W	8310200164*	50-373 G	MYERS, D O	B310250560*	50-321 Q
MODRE, D E	8310210034*	50-259 G	MULHOLLAND,P J	8310260423	NUREG	MYERS, L L	B310180118	NUREO
MODRE, G E	8310180277*	GA779	MULLEE,G R	8310110511*	FDIA	MYRABO, A L	B310190021	50-263 R
MODRE, R D	8310270537*	50-10 F	MUMA,E,	8310050494*	50-155 G	NADEAU, J P	B310040533	50-443 Q
MOORE, R. D. MOORE, R. D. MOORE, R. N. MOORE, R. N. MOORE, R. N.	8310280209* 8310280314* 8310060056 8310060234 8310240306	90-10 F 50-10 F XPORTLIC XPORTLIC XPORTLIC	MUMA, E MUMA, E MURLEY, T E, MURLEY, T E	8310050494* 8310140078* 8310140078* 8310060053 8310140003	50-155 G 50-155 T 50-155 T 50-309 F 50-311 G	NADEAU, J P. NAIDU, K R NAPUDA, G NAPUDA, G NARBUT, P	8310120178 8310050497* 9310140170* 8310200092* 8310240207*	50-443 Q 50-341 Q 50-320 Q 50-271 Q FDIA
MODRE: R N	8310240322	XPORTLIC	MURLEY, T E MURLEY, T E MURLEY, T E MURLEY, T. E MURLEY, T. E	8310200177	State Prop	NARBUT,P	8310240220*	50-528 A
MODRE: S N,	8310240124	50-261 P		8310200181*	State Prop	NARBUT,P P.	8310240203*	50-528 A
MORAN: D H	8310070174	PROJ		8310250116	State Prop	NARBACCI,G.A	8310120128*	50-289 R
MORAN: D M	8310310179	50-546 0		8310270052	50-334 G	NARDI,A J	8310170330	70-1151
MORAN: R A	8310240062#	50-413 T		8310270180	50-219 P	NARDI,A J.	8310200451	71-5450
MORGAN, R E	8310030426	50-261 8	MURLEY, T E MURLEY, T E MURLEY, T, E MURLEY, T E, MURLEY, T E	8310270581	50-220 G	NARDI, A J.	B310240248	70-1143
MORGAN, R E.	8310040282	50-261 0		8310270585*	50-220 G	NARDI, A J.	B310260045	70-1143
MORGAN, R E	8310040516	50-261 8		8310270639*	40-672	NARDDCI, P. B	B310040403	50-370 B
MORGAN, R E	8310070136	50-261 8		8310270644*	40-672	NARDDCI, P. B	B310060063*	50-369 B
MORGAN, R E	8310070308	50-261 8		8310270647*	40-672	NARDDCI, P. B	B310060068*	50-369 B
MORGAN, R E MORGAN, R E MORGAN, R E MORGENSTERN, M MORGENSTERN, M	8310070322 8310170541 8310250576* 8310130128 8310130134*	50-261 8 50-261 8 50-261 9 MISC MISC	MURLEY, T. E. MURLEY, T E MURPHY, C. E. MURPHY, C E MURPHY, D H	8310270552* 8310310271 8310120446* 8310210120 8310070216	40-672 State Prog 50-316 S 50-316 S RES	NARDDCI, P. B NARDDCI, P. B NARDDCI, P. B NARDDCI, P. B NARDDCI, P. B	8310060255 8310060384 8310120413 8310170248 8310170384	50-370 B 50-369 B 50-369 B 50-369 B 50-369 B
MORLEY, J A	8310130008 8310130071* 8310240255 8310250075 8310250102	WASTE MOT WASTE MOT WASTE MOT WASTE MOT	MURPHY.L O MURPHY.L O MURPHY.L O MURPHY.L O	8310060507 8310070115 8310070178 8310110336 8310270567	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	NARDOCI, P B NARDOCI, P B NARDOCI, P. B NARDOCI, P. B NARDOCI, P B	8310170430 8310210005 8310210077 8310210308 8310210309	50-367 8 50-369 8 50-370 8 50-369 8 50-369 8
MORLEY, J A MORLEY, J A MORRILL, P. MORRILL, F, J MORRILL, F J	8310250107* 8310310182 8310250355 8310120046 8310210378*	WASTE MOT Waste mot 50-206	MURPHY: W P MURPHY: W. P. MURPHY: W. P MURPHY: W. P MURPHY: W. P.	8310040259 8310180096 8310190105* 8310190298 8310310266	50-271 F 50-271 R 50-29 P 71-9089 50-271 P	NARDOCI,P B NARDOCI,P.B NARDOCI,P.B NARDOCI,P B NARDOCI,P B	8310250071 8310250076* 8310250080* 8310270046 8310270173	50-369 8 50-369 8 50-369 8 50-370 8 50-369 8
MORRISON, J K MORRISON, J, R, MORRONGIELLO, A MORTON, K L, MORTON, K V.	B310240098*	CONTRACT	MURPHY, W P	8310310307	50-271 F	NARDOCI, P. B	8310270209	50-370 B
	B310240199*	50-528 G	MURRAY, B	8310060015*	50-267 G	NARDOCI, P. B	8310270310	50-370 B
	B310250613*	50-254 G	MURRAY, B	8310060026*	50-313 G	NARROW, L	8310190142*	50-443 Q
	B310190117	50-313 R	MURRAY, B.	8310060371*	50-362 G	NEIGHBORB, J. D.	8310110078	50-280 P
	B310070188*	50-498 A	MURRAY, B	8310060464*	50-362 G	NEIGHBORB, J. D.	8310120003	50-280 P
MORTON, K. V.	8310070196*	CONTRACT	MURRAY, B	8310180161*	50-278 Q	NEISLER, JH	8310060462*	50-493 G
MORTON, K. V.	8310070200*	CONTRACT	MURRAY, J F	8310140055*	50-358 A	NELLIS, CA	8310270537*	50-10 F
MORTON, K. V.	8310070205*	CONTRACT	MURRAY, J F.	8310280197*	50-400 A	NELSON, GB	8310030213*	XPORTLIC
MORTON, K. V.	8310070210*	CONTRACT	MURRAY, T D.	8310060365	50-346 B	NELSON, GB	8310180123*	70-734
MORTON, K. V.	8310070217*	CONTRACT	MURRAY, T D	8310060595*	50-346 F	NELSON, G, B,	8310310258	70-734
MORTON, K. V	8310070220*	CONTRACT	MURRAY, T D MURRAY, T. D MURRAY, T D MURRAY, T. D MURRAY, T. D MURRAY, T. D	8310110087*	50-346 F	NELBON; M A	8310170007*	50-289 F
MORTON, K. V	8310070221*	CONTRACT		8310110131*	50-346 F	NELBON; M A.	8310200430*	50-289 F
MORTON, K. V	8310070230*	CONTRACT		8310120222	50-346 B	NELBON; R. F	8310070323	NUREO
MORTON, K. V.	8310070240*	CONTRACT		8310120239	50-346 B	NELBON; R. M	8309120437	50-441 E
MORTON, K. V	8310070267*	CONTRACT		8310120322	50-346 B	NELBON; R M	8310120359	50-441 E
MORTON, K. V.	8310070331* 8310070415* 8310110009* 8310110029* 8310110549*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURRAY, T D. MURRAY, T. D MURRAY, T. D MURRAY, T. D. MURRAY, T. D. MURRAY, T. D.	8310120391 8310170349 8310170375 8310170498 8310190020	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8	NELSON, R M, NELSON, R M NELSON, R M NELSON, W, E NERSES, V	8310140228 8310210007 8310270569% 8310110591% 8310060534	50-461 E 50-461 A 50-461 P FOIA 50-369 P
MORTON, K. V.	8310110582*	CONTRACT	MURRAY, T. D.	8310190166	50-346 R	NEUMANN, M. R.	8310200342	40-8697
MORTON, K. V.	8310110616*	CONTRACT	MURRAY, T. D.	8310210363*	50-346 F	NEVILLE, J. T.	8310250047	50-352 H
MORTON, K. V.	8310130165*	CONTRACT	MUBELER, W. J.	8310310224*	50-322 G	NEHMAN, K. A.	8310110540	FOIA
MORTON, K. V.	8310130201*	CONTRACT	MUBOLF, D.	8212150246*	F01A	NEHMAN, K. A.	8310270085	FOIA
MORTON, K. V.	8310170067*	CONTRACT	MUBOLF, D	8310040572	50-263 P	NEYLAN, A. J.	8310040522	50-358 A
MORTON, K. V.	8310180105#	CONTRACT	MUBOLF, D.	8310050422	PR	Nicholas, H. H	8310040046*	50-388 Q
MORTON, K. V.	8310170281#	CONTRACT	MUBOLF, D.	8310060216	50-243 P	Nicholas, H. H	8310190203*	50-352 Q
MORTON, K. V.	8310200462#	CONTRACT	MUBOLF, D	8310070238	50-243 V	Nickel, H. C.	8310270182*	FOIA
MORTON, K. V.	8310210073#	CONTRACT	MUBOLF, D.	8310070272	50-263 S	Nickel, H. C.	8310270186*	FOIA
MORTON, K. V.	8310210077#	CONTRACT	MUBOLF, D	8310070311	50-263 P	Nicolaras, H	8310070157	50-263 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION RAEHUM	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NICOLARAS, H NICOLOSI, J NICOLOSI, J NIGHTINGALE, E NILSON, R	8310240149 8308300689 8310120306 8310050546* 8310250346	50-263 P 1&E 1&E 50-358 Q PR	NORRIS, E B NORRIS, E B NORRIS, E B NORRY, P G NORRY, P G	9310280149* 9310280150* 9310280151* 9310130077 9310210007	50-259 P 50-259 P 50-259 P DRG DRG	O.100TE' O D O.WEITTA' O b O.WEITTA' O b O.WEITTA' O b	8310250508 8310250514 8310250565 8310250635 8310040228	50-338 0 50-369 0 50-324 0 50-269 0 50-247 F
NIX.H C NIX.H C NIX.H C NIX.H C	8310030247 8310030304 8310030318 8310030319 8310030336	50~321 S 50~321 S 50~366 S 50~366 S 50~366 S	NORTH, H 8 NORTH, H 8 NORTHSTROM, T E NORTON, B NORTON, B	9310040311# 9310170678# 9310310154# 9310110120 9310110120	50-312	O TOOLE, J D O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D	8310120194 8310120242 8310120297 8310120366 8310130111	50-247 P 50-247 P 50-247 P 50-247 P 50-3 P
NIX.H C NIX.H C NIX.H C NIX.H C	8310030357 8310030382 8310030410 8310030415 8310030433	50-366 8 50-366 9 50-321 8 50-366 8 50-366 8	NORTON, B NORTON, B NORTON, B NORTON, B NORTON, D NORNOOD, D W	8310110278 8310110278 8310110301* 8310110301* 8310030432	50-275 0 50-275 0 50-275 0 50-275 0 50-259 5	O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D OBERG, C R	8310130115# 8310190163 8310260304 8310280261* 8310040157*	50-3 P 50-247 S 50-3 F 50-3 F 50-382 G
NIX.H C NIX.H C NIX.H C NIX.H C	8310030442 8310030481 8310030486 8310030510 8310040366*	50-366 8 50-321 8 50-366 8 50-366 8 50-321 0	NOVACHEK, F NOVACHEK, F J NOVACHEK, F J NOVACHEK, F J NOVAK, T M	8310040322* 8310040207 8310040324* 8310040328* 8210280450*	50-267 8 50-267 8 50-267 8 50-267 8 50-329 A	OBERGIC R OBERGIC R ODEGAARDENIR H ODEGAARDENIR H ODEGAARDENIR H	8310040546* 8310170683 8310060332 8310130095 8310190272	50-498 0 50-445 1 71-6400 71-6144 71-5939
NIX,H.C. NIX,H C. NIX,H C. NIX,H C. NIX,H C	8310040407 8310040524 8310040011 8310120408 8310140014	50-366 8 50-321 8 50-366 8 50-366 8 50-321 8	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8308300352 8308300747 8308300777 8308300779 8308310032	50-38P A 50-329 A 50-454 G 50-413 E 50-329 A	DOLE,K M DLLER,R E OLLER,R E OLMSTEAD,W J OLMSTEAD,W J	8310180138 8310040249* 8310290526* 8207150081* 8310130003	40-8768 GA779 GA799 50-29 P
MIX.H C. MIX.H C. MIX.H C. MIX.H C.	8310140144 8310140241 8310170163 8310170397 8310170307	50-321 8 50-321 P 50-366 P 50-321 8 50-366 8	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8308310045 8310030604 8310030604 8310040120 8310050076	50-413 8 50-327 P 50-327 P 50-375 P 50-369 P	OLMSTEAD, W J OLSEN, A F OLSEN, L OLBHAN, L N OLSHAN, L N	8310130042 8310170730 8310180400* 8310110605 8310130049	M18C 70-824 GA999 50-454 A 50-454 A
MIX.H C MIX.H C MIX.H C MIX.H C	8310170531 8310170582 8310170584 8310170743* 8310170746*	50-366 8 50-321 8 50-366 8 50-321 F 50-321 F	NBVAK, T M NBVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8310110374	50-424 A 50~482 A 50-370 A 50-327 A 50-327 P	OLSHAN, L N OLSON, O L OLSON, O L ONNER, M W OPARKA, E J	8310240031 8310110624 8310280283 8310030341 8310260026*	50~454 A WASTE HOT WASTE HOT PR FOIA
NIX.H C. NIX.H. C. NIX.H. C. NIX.H C. NIX.H C	8310190014 8310250041 8310250212 8310250285 8310250291	50~321 R 50~366 B 50~366 B 50~366 B 50~366 S	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T. M NUSSBAUMER, D A	8310170721 8310170177 8310210131 8310310172 8310260318	50-327 A 50-327 P 50-349 P 50-400 A Wabte Mgt	OPREA, G W OPREA, G W OPREA, G W OPREA, G W OPREA, G W	8310040289 8310040410 8310130187 8310130265 8310130319	50-498 8 50-498 8 50-498 8 50-498 8
NIX.H C NIX.H.C, NIX.H C NIX.H C NIX.H C	8310250311 8310250312 8310250343 8310250504 8310310234	50-366 8 50-366 9 50-366 8 50-366 8 50-366 8	NUSSBAUMER, DA NYERGES, PL O'CONNOR, JT O'CONNOR, JT O'CONNOR, PH	8310280103 8310040079 8310170308 8310200409 8310130047	WASTE MOT 70-143 40-8801 40-8801 50-546 A	OPREA, G W OPREA, G W ORDERS, W T ORLOSKY, P M OSBORN, M	8310180270 8310210173 8310040332* 8310140222 8310240159	50-498 8 50-498 9 50-324 9 50-57 R 50-289 H
NIX.H C NIX.H C NIX.H C NIX.H C NODNAN,V.B	9310310259 8310310280 8310310297 8310310343 8305040124*	50~366 8 50~366 8 50~321 8 50~366 8 50~445 A	O.WEITP' A H O.WEITP' A H O.WEITP' A O.WEITP' A	8307130169 8310110207 8310170375 8310040538 8310040538	50-155 G 50-155 G 50-344 B 50-400 G 50-400 G	OSTER, J OVERBECK, G OVERBECK, G OVERBECK, G OVERBECK, G	8310240071 8210010087* 8306160513* 8306160602* 8307200260*	50-10 J 50-272 P 50-324 P 50-302 P 50-336 P
NOONAN, V S NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R NORDERHAUG, L. R	8309300064* 8310030198 8310030213* 8310040221 8310040397	50-382 A XPORTLIC XFORTLIC 50-275 G 50-397 G	O.WEITT'N H O.WEITT'N H O.WEITT'N H O.WEITT'N H	8310060188 8310060188 8310110150 8310110150 8310110155*	50-400	OVERBECK, 0 J OWCZARSKI, P C OWSLEY, 0 F PADUANO, H N PAGE, R 0	8307230463* 8310050145 8310140244* 8310130157* 8310040133	50-313 P RED TOPREP 50-387 G 70-2745
NORDERHAUO, L. R NORDERHAUO, L. R NORDERHAUO, L. R. NORDERHAUO, L. R. NORELIUS, C.	8310180120 8310180123* 8310180217 8310310284 8310140036	70-734 70-734 70-734 50-206 S 50-10 Q	O'NEILL, J H O'NEILL, J H O'NEILL, J H	8310170620# 8310170620# 8310170620# 8310170630# 8310170630#	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0	PAGE, R. G PAGE, R. G PAGE, R. G PAGE, R. G PAGE, R. G	8310050177 8310040343 8310060548* 8310070034 8310070211	40-8794 70-2988 70-2988 40-8027 40-6500
NORELIUS, C E NORELIUS, C E NORELIUS, C E NORELIUS, C. E, NORELIUS, C. E	8310140352 8310120302 8310120326 8310140099 8310170666	50-373	O'NEILL,J H O'NEILL,J H O'REILLY,J P O'REILLY,J P	8310270512 8310280051 8310280051 8310040174 8310040263	FOIA 50-400 Q 50-400 Q 50-321 Q 50-416 Q	PAGE,R O PAGE,R,G PAGE,R,G PAGE,R G PAGE,R G	8310110441 8310170691 8310180011 8310210099 8310260048*	40-6500 70-143 70-143 40-6500 FDIA
		50-10 Q 50-10 Q 50-123 Q 50-123 Q 50-301 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8310040354 8310040416 8310040448 8310040446# 8310040487	50-261 P 50-395 8 50-327 Q 50-327 Q 50-259 Q	PAGE.R O PAGLIARO, J A PAHWA.S B PALLADINO, N PALLADINO, N	8310270576 8310260280* 8310070200* 8310110057* 8310030413	40-4940 FOIA CONTRACT 50-275 P 50-289 0
		50-301 Q 50-275 Q 50-275 Q FOIA FOIA	O'REILLY, J. P O'REILLY, J P O'REILLY, J P O'REILLY, J. P O'REILLY, J. P	8310040511 8310040528 8310040588 8310040622 8310040632*	50-369 F 50-416 Q 50-424 Q 70-1151 70-1151	PALLADINO, N J	8310030622* 8310060591 8310070041 8310070363 8310070377	50-287 P 50-382 U COMMISSION COMMISSION
		70-1144 FOIA 50-155 F 50-155 F GA777	O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J P O'REILLY, J P	8310070241 8310070273 8310210032 8310210071 8310250336	50-324 G 50-324 G 50-257 G 50-257 G 70-143	PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J	8310110073 8310110352 8310110589 8310110574* 8310110612	COMMISSION COMMISSION COMMISSION COMMISSION
		50-286 Q 50-311 8 50-247 B 50-272 Q 71-505	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P.	8310250344* 8310250350 8310250451 8310250474 8310250488*	70-143 50-302 Q 50-324 Q 50-324 Q 50-324 Q	PALLADING, N J PALLADING, N J PALLADING, N J PALLADING, N J PALLADING, N J	8310110617 8310140028 8310170674 8310170701 8310170704	50-54 U 50-320 0 COMMISSION COMMISSION COMMISSION

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJE CATEO
PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J PALLADINO,N J	8310180010 8310200038* 8310200044* 8310200062 8310200357*	COMMISSION 50-287 P 50-287 P 50-445 U FOIA	PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J	8310120300 8310120424 8310140011 8310140053 8310170414	50-325 S 50-325 S 50-325 S 50-325 S 50-325 S	PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J PETTY, J C PFAFF, S J	8310200009 8310200446 8310240094 8310170536 8310260348	40-299 40-858 40-845 50-269 40-665
PALLADIND, N J	8310200442	50-424 U	PASTVA, M J	8310170594	50-324 S	PFAFF, B J	8310270545	40-665
PALLADIND, N J	8310200447*	COMMISSION	PASTVA, M J	8310170604	50-324 S	PFEFFERLEN, H C	8310070264	50-237
PALMER, R A	8310120188	50-316 S	PASTVA, M J	8310190141	50-325 S	PFEFFERLEN, H C	8310070281	TOPREP
PALMER, R A	8310140084	50-315 S	PASTVA, M J	8310190227	50-325 S	PFEFFERLEN, H C	8310070310	TOPREP
PALMER, R A	8310140140*	50-316 S	PASTVA, M J	8310250237	50-324 S	PHILIPPACOPQULO	8310210358*	50-275
PALMER, R A	8310140141* 8310170611* 8310210191* 8310210197* 8310210199*	50-316 S 50-316 S 50-315 S 50-315 S 50-315 S	PABTVA, H J PABTVA, H J PATON, W D PATTERSON, H PATTERSON, J P	8310250376 8310250521 8310050418 8310130253 8310040178*	50-324 S 50-325 S 50-329 G 71-503 50-331 G	PHILLIP.G A PHILLIP.G A PHILLIP.G A PHILLIP.G A PHILLIP.G A	8310260120+ 8310260142+ 8310260164+ 8310260250+ 8310180455+	FOIA FOIA FOIA 70-114 QA999
PALMER, R A PALMER, R A PANCIERA, V PANCIERA, V W PANOBURN, G C	8310210202* 8310270224 8310040222* 8310250560* 8310050413	50-315 8 50-315 8 50-424 9 50-321 9 WASTE MGT	PATTERSON, W F PATTERSON, W F PATTERSON, W F PATTERSON, W F	8310050364 8310050373 8310050381* 8310050388* 8310050378	50-443 G 50-443 Q 50-443 G 50-443 G 50-443 Q	PHILLIPB.H B PHILLIPB.H B PHILLIPB.H B PHILLIPB.H B PHILLIPB.H B	8310250136* 8310250206* 8310250385* 8310250447* 8310250541*	0A777 0A777 0A777 0A777 0A777
PANGBURN.G C PANGBURN.G C PANGBURN.G C PANKRATZ.D R PAOLINO.R	8310200349 8310200412 8310240094 8310110511* 8310200270*	40-8102 40-8102 40-8452 FDIA 50-289 G	PATTERSON, W F	8310050472 8310050474* 8310050477* 8310050480* 8310050551	50-443 G 50-443 G 50-443 G 50-443 G	PHILLIPS, J W PHILLIPS, M PHILLIPS, M P PHILLIPS, M P PHILLIPS, M P	8310050056* 8310140267* 8310040178* 8310050485* 8310140013*	71~908 50~237 50~331 50~155 50~305
PAPAZOGLOU, I A PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8310310444 8310040195 8310040359 8310050559 8310120202	50-302 P 50-331 G 70-36 50-87 G 50-116 G	PATTERSON, W F PATTERSON, W F PATTERSON, W F PATTISON, R S PAUL, R A	8310130046 8310130255 8310250319 8310060502 8310210074#	50-443	PHILLIPB,M P PHILLIPB,M P PICHUMANI.R PICKLER,D A PIEHL,R H	8310140271* 8310180257* 8310170484* 8310260180* 8310210040	50-254 50-373 50-382 FUIA 50-315
PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J	8310120241	50-305 F	PAVL,R.A	8310270313*	50-266 0	PIEHL,R H.	8310210212*	50-316
	8310120269	50-263 F	PAVLK.Q L	8310250190*	50-259 0	PIEHL,R H	8310270271*	50-315
	8310140002	50-305 Q	PAVLSON,W	8310280141	50-206 P	PIEMONTESE,A P.	8310170230	50-387
	8310140013*	50-305 Q	PAVLSON,W A	8310060195	50-206 P	PIEMONTESE,A P	8310250219	50-387
	8310140181	70-36	PAVLSON,W A	8310250254	50-206 P	PIEMONTESE,A P	8310250228	50-387
PAPERIELLO, C J	8310140212	70-1308	PAYNE, K	8310250047	50-352 H	PIEMONTESE, A P	9310250345	50-387
	8310140262	50-237 G	PEARBON, 8 D	8310250480	MASTE MOT	PIEMONTESE, A P.	8310250402	50-387
	8310140267*	50-237 G	PEARBON, W R	8310250113	50-133 P	PIEMONTESE, A P.	8310250574	50-318
	8310140271*	50-234 G	PECK, B I	8310040079	70-143	PIERINGER, P	8310250047	50-318
	8310180230	50-234 G	PEDRO, J	8310110001	FOIA	PIERINGER, P.	8310250221	50-318
PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J PAPERIELLO,C J	8310210053	50-10 Q	PEDRO, J	8310110005	FOIA	PIERINGER, P	8310250443	50-318
	8310210061*	50-10 G	PEDRO, J	8310180582	50-445 A	PIERINGER, P. A	8310250287	50-318
	8310250391	50-315 F	PEDRO, J	8310190088	FOIA	PILANT, J M	8310040574	50-298
	8310270190	50-315 F	PEDRO, J	8310240233	FOIA	PILANT, J M	8310140190	50-298
	8310270294	50-246 G	PEDRO, J	8310270057	FOIA	PILANT, J. M	8310200350	50-298
PAPERIELLO, C J	8310270303*	50-266 Q	PEDRO.J	8310270355	FOIA	PINKEL, I I	8310110010*	50-295
	8310270435	50-254 Q	PECRY.W W	8310040637*	70-1151	PIRTLE, O, L	8310140216*	70-1308
	8310270443	50-483 F	PELIZZA.M S	8310210123	40-8786	PIRTLE, O L	8310270313*	50-266
	8310310158	50-407 Q	PELKE.P R	8310240137*	50-440 Q	PITTS, R. W	8310030028	71-9161
	8310310285	50-483 Q	PELLETIER.J P	8310250308	50-271 S	PLAINE, H H	8310110022*	50-445
PARAMESWARAN,V	8310180076	NUREO	PELLETIER, J P	8310250334	50-271 S	PLAINE,H H,	8310110437*	50-322
PARAMORE.D	8310070436	NUREO	PELLETIER, J P	8310250379	50-271 S	PLAINE,H.H	8310260230	50-358
PARIS.O H	8310040184	50-155 0	PELLETIER, J P	8310250531	50-271 S	PLIML,G	8310210377*	50-295
PARIS.O H	8310250048	50-320 0	PELLETIER, J P	8310250626	50-271 S	PLISCO,L	8310200270*	50-289
PARIS.O H	8310260224	50-247 0	PELOGUIN, R A	8310070442	NUREG	PLOSKI,T.	8310140267*	50-237
PARIS,P C	6310050335	NUREG	PENNIFILL, R A	8310050413	HABTE MGT	PLOSKI, T.	8310180257*	50-373
PARKER.M E	6310170643*	50-341 G	PENZIEN, J	8310070205*	CONTRACT	PLOSKI, T. J	8310140271*	50-254
PARKE.B	6310030254	50-387 8	PERANICH, M W	8310040453*	GA979	PLUMLEE, O. L	8310030350*	50-267
PARKE.B	6310260145*	50-324 P	PERKINS, K E	8310260096*	50-10 S	PLUMLEE, O. L	8310040587*	50-267
PARKE.B	6310260146*	50-324 P	PERKINS, K R	8310270075*	FOLA	POHLMAN, D. L	8310110133*	50-361
PARKS, D M	8310250037	50-389 8	PERLIB.R G	8310050388*	50-443 G	POINDEXTER, T, C	8310180046	50-320
PARKS, B, M	8310250337	50-389 8	PERLIB.R.Q.	8310050402	50-412 G	POLIQUIN, T E,	8310170267	71-148
PARKYN, J D	8310050425	PR	PERLIS.R Q.	8310050457	50-483 G	POLK, H E,	8310210358*	50-275
PARSONS, R M	8310030526	50-400 8	PERLIS.R Q.	8310050533	50-483 G	POLK, H, E,	8310210371*	50-275
PARSONS, R M	8310040224*	50-400 9	PERLIB.R Q	8310170419	50-483 G	POLK, P, J	8003240118*	FOIA
PARSONS, R M	8310040282	50-261 0	Perlis.R.G	8310250143	50-483 0	FOLK: P. J.	8310120018*	FOIA
PARSONS, R M	8310040600*	50-400 q	Perlis.R.G	8310250297	50-412 0	POLK: P. J.	8310130041	50-296
PARSONS, R M	8310040603*	50-400 q	Perlis.R.G	8310250545	50-498 0	POMERENING: D. J.	8310270578*	TOPREP
PARSONS, R M	8310040606*	50-400 q	Perlman.J	8310050357	CONTRACT	POPPE: L. K.	8310170172	71-9103
PARSONS, R M	8310060036	50-400 B	Perlman.J	8310050379	CONTRACT	POPPE: L. K.	8310170332	71-5905
PARSONS, R. M.	8310040334	50-400 8	PERLMAN, J	8310240104	CONTRACT	PORTER, R	9310200154	50-318
	8310120244	50-400 8	PERLMAN, J	8310240127	CONTRACT	PORTER, R	8310250249	50-317
	8310120347	50-400 8	PERSINKO, D	8310050475*	50-155 T	PORTER, R	8310250410	50-317
	8310170171	50-400 8	PERSINKO, D	8310130001	50-155 T	PORTZ, R	8310110036*	50-331
	8310250211*	50-400 Q	PERMEK, C	8310140163	TOPREP	PORTZ, R.	8310110055*	50-331
PABCHALL, A A	8310200448	FOIA	PEBHEK, C	8310140174*	TOPREP	PORTZ, R	8310250669*	50-331
PASTOR: R J	8310180420	50-352 D	PETERS, A	8310310425*	70-2319	POSEY, W. W.	8310250109	50-358
PASTVA: M J	8310030202	50-324 8	PETERS, M A	8310270267	50-373 8	POSTMA: A. K.	8310270041*	50-320
PASTVA: M J	8310030209	50-324 8	PETERSON, D. A	8310120254	50-255 R	POSTMA: A. K.	8310270044*	50-320
PASTVA: M J	8310030422	50-324 8	PETERSON, W K.	8310190105*	50-29 P	POTAPOVG: I	8310930387*	GA999
PASTVA, M J	8310040362	50-324 8	PETRAK, T Q.	8310170388	50-295 8	POTAPOVB, U	9309300705	GA999
PASTVA, M J	8310040412	50-325 8	PETRARCA D. J	8310210240*	50-334 P	POTAPOVB, U,	9310030342	GA999
PASTVA, M J	8310040582	50-325 8	PETRIE, E	8310170107*	50-338 8	POTAPOVB, U,	9310030379	GA999
PASTVA, M J	8310060237	50-324 8	PETRIE, L	8310060494*	50-335 F	POTAPOVB, U	9310030444	GA999
PASTVA, M J	8310060383	50-324 8	PETTENGILL, H	8310200456	40-6622	POTAPOVB, U,	9310030445	GA999

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U.	831 0030 464 831 0040 242 831 0040 343 831 0040 382 831 0040 422	GA979 GA979 GA979 GA999 GA999	PUCCI,J A PUCCI,J A PUCCI,J A PUCCI,J A PUCCI,J A	8310240050 8310240063 8310240084 8310240136 8310270066	50-327 A 50-327 A 50-327 A 50-327 A 50-327 A	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8310050420* 8310050458* 8310040148* 8310040290* 8310040324*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	831 0040433* 831 0040485 831 0040576 831 0130288 831 0140165*	GA999 GA999 GA999 GA999 TDPREP	PUOH, C E PUNT, N A PURDY, G. R PURDY, G. R PURPLE, R. A	8310050217 8310130219 8310140024* 8310140024* 8310240261*	NUREG 50-289 H 50-445 T 50-445 T 50-250 P	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8310060483* 8310060493* 8310060496* 8310060501* 8310060512*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
POTAPOVS, U POTAPOVS, U, POTAPOVS, U POTAPOVS, U,	831 0180142 831 0180154 831 0180201 831 0180214 831 0180291	GA797 GA797 GA797 GA797 GA797	PURVIS, F. QUAMME, D L QUAMME, D L QUAMME, D L QUICK, D R	8310200203* 8310250507* 8310270171* 8310310366 8310250271*	50-397	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8310070106* 8310070117* 8310070148* 8310070181* 8310070198*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U. POTAPOVB, U	8310180297 8310180312 8310180318* 8310180332* 8310180344	GA999 GA999 GA999 GA999 GA999	QUICK,D.R. QUICK,D.R. QUIRK,J.F. QUIRK,J.F. RADELOFF,W.A	8310250333* 8310250517* 8310170540 8310250557 8310260035*	50~438 G 50-327 G TOPREP REOOD FOIA	REBELLO, J E REBELLO, J E REBELLO, J E REBELLO, J E	8310070224* 8310110271* 8310110337* 8310110340* 8310270577*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
POTAPOVS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U POTAPOVS, U	831 0180340 831 0180395 831 0180394 831 0180415* 831 0180429	GA997 GA999 GA999 GA999 GA999	RADELOFF, W A RADELOFF, W A RADELOFF, W. A RADELOFF, W. A RADELOFF, W A	8310260040* 8310260044* 8310260047* 8310260051* 6310260055*	FOIA FOIA FOIA FOIA FOIA	REBELLO, J E REBELOWSKI, T REBELOWSKI, T A REBELOWSKI, T A REED, J Q	8310280137* 8310190188* 8310180209* 8310180447* 8310120420	CONTRACT 50-483 0 50-213 0 50-213 0 50-483 0
POTAPOVE, U POTAPOVE, U POTAPOVE, U. POTAPOVE, U. POTAPOVE, U	8310180433 8310180441 8310180451 8310180474 8310180515	GA599 GA999 GA999 GA999 GA999	RADELOFF,W.A RADELOFF,W.A RAHE,E P RAHE,E P RAHE,E P	8310260059# 8310260079# 8310050197 8310060267 8310140227	FOIA FOIA PROJ PROJ TOPREP	REEDY,R F REEVES,E A REGAN,N A REGAN,N A REGAN,N A	8310180361* 8310280085 8310170229 8310170315 8310170727	50-275 T 50-348 P 70-27 70-27 70-27
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U	8310180526 8310180530* 8310250005 8310250010 8310250104	ወላንግኝ ወላያግኝ ወላያግኝ ወላያግኝ ወላያግኝ	RAHE, E P RAHE, E P RAHE, E P RAHE, E P RAHE, E P	8310200165 8310200170 8310200193 8310260279 8310280017*	50-247 8 TOPREP TOPREP 50-445 A TOPREP	REGAN,N A REGAN,N A REGAN,N A REGAN,N A REGISTER,B F	8310180561 8310200333 8310200418 8310260166* 8310270417	XP OR TL. IC 71 - 5797 70 - 27 70 - 27 40 - 8599
POTAPOVS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U, POTAPOVS, U	8310250123 8310250140 8310250199 8310250245 8310250272	ወልማየዋ መልዋዎዋ ወልዋዎዋ ወልምዎዋ መልዋዎዎ	RAHE, E P RAMSDELL, J V RANDEN, L D. RANGANATH, B RASKIN, D B.	8310280106 8310310208 8310030557 8310180152* 8310120418	PROJ NUREO 40-8786 50-352 Q 50-275 Q	REHM, T A REHM, T A REHM, T A REHM, T A REHM, T A	8310060521 8310110107* 8310120467 8310170361 8310260060	COMMISSION 50-275 P COMMISSION COMMISSION COMMISSION
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8310250357 8310250362 8310250377 8310250395 8310250405	04777 04777 04777 04777 04777	RATHBUN, L. A RAWBON, R. J. RAWBON, R. J. RAWBON, R. J. RAWBON, R. J.	8310310268 8310110632 8310130048 8310130175 8310250338	NUREO 50-289 0 50-289 0 50-289 P 50-289 0	REID.M J REINSCH.H O REINSCH.H O REITER.L REITER.R	8310040282 8310280224* 8310280231* 8310130002* 8310060263*	50-261 0 50-358 A 50-358 A 50-155 T 50-358 Q
POTAPOVS, U. POTAPOVS, U. POTAPOVS, U POTAPOVS, U. POTAPOVS, U	8310250413 8310250432 8310250497 8310250503 8310250511	QA799 QA799 QA999 QA999 QA999	RAY, H. B RAY, H. B. RAY, H. B. RAY, H. B RAY, H. B	8310030102 8310070304 8310120070 8310120073 8310120075	50-361 R 50-361 S 50-361 S 50-361 S 50-362 S	REITLER,E K REPKA,D A REPKA,D A REPKA,D A REPKA,D A	8310170219 8310050439 8310130035 8310170419 8310250375	70-1151 50-322
POTAPOVS, U. POTAPOVS, U POTAPOVS, U. POTAPOVS, U. POTAPOVS, U	8310250515* 8310250532 8310250537 8310250572 8310250610*	QA779 QA779 QA779 QA779 QA779	RAY, H. B. Ray, H. B. Ray, H. B. Ray, H. B. Ray, H. B.	8310120116 8310120130 8310120146 8310120152 8310120164	50-361 8 50-361 8 50-361 8 50-361 8 50-361 8	REPKA.D A REBBLER,W C REVELEY.W T REVELEY.W T REYES.A J	8310270237 8310120125 8310140016 8310140016 8310120455	50-322 0 50-287 R 50-322 0 50-322 0 XPORTLIC
POTAPOVS.U. POTTER.J.P. POULK.R.M. POULK.R.M. POULK.R.M.	8310270050* 8310140142 8309200173 8310060075 8310060383	TOPREP 18:E 50~324 S 50~324 S 50~324 B	RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B. RAY, H. B.	8310120172 8310120183 8310120184 8310120258 8310120278	50-362 8 50-362 6 50-206 6 50-206 0	REYEB,A J REYEB,L A REYEB,L A REYROLDS,A B	8310130399 8310130422 8310050502* 8310270140* 8310070106*	XPORTLIC XPORTLIC 50-373 G 50-454 G CONTRACT
POULKIR, M. PRABHAKARAIM K. PRABHAKARAIM K PRABADIB G. PRATTIA	8310250521 8310040381* 8310040381* 8310110567 8310070203*	50-325 8 50-155 T 50-155 T FDIA CONTRACT	RAY,H B. RAY,H B. RAY,H B RAY,H,B RAY,H,B	8310120338 8310120342 8310120347* 8310120351* 8310140023	50-362 8 50-361 8 50-361 8 50-361 8 50-362 8	REANOLDS' 7 BEANOLDS' 7 BEANOLDS' 7 BEANOLDS' 7	8310040212* 8310040212* 8310050421 8310050421 8310110058	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
PREISTER, D. J. PREUSS, H PREVATTE, R. L PREVATTE, R. L PRICE, E. R.	8310180163* 8310120138 8310040613* 8310250632* 8310260065*	50-445 G 50-254 B 50-400 G 50-400 G FOIA	RAY, H B RAY, H. B RAY, H. B RAY, H B RAY, H B	8310140125 8310140167 8310140218 8310180486* 8310190010	50-362 8 50-362 8 50-362 8 50-361 8 50-266 R	REYNOLDS: J REYNOLDS: J REYNOLDS: J REYNOLDS: J	8310110038 8310110127 8310110127 8310110317 8310110317	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
PRICE, E. A. PRICE, E. R. PRICE, E. R. PRICE, E. R. PRICE, E. R.	8310260072* 8310260115* 8310260126* 8310260129* 8310260137*	FOIA FOIA FOIA FOIA FOIA	RAY: H. B RAY: H. B RAY: H. B RAY: J. J. RAY: J. J.	8310190092 8310270439 8310270498 8307290223* 8310310462	50-361 R 50-362 S 50-361 S FOIA ACRS	REANOLDB' Y BEANOLDB' Y BEANOLDB' Y BEANOLDB' Y BEANOLDB' Y	8310130243 8310130243 8310180160 8310180160 8310180248	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0
Price, E. R. Price, E. R Price, E. R. Price, E. R. Price, H. L	8310260356* 8310260361* 8310270097* 8310270100* 8310270170*	FOIA FOIA FOIA FOIA FOIA	RAY, J. J RAYHOND, W. J RAYNOR, J. W. RAYNOR, J. W. RAYNOR, J. W.	8310310465 8310140245* 831020004 8310200047 8310250221	ACRS 50-271 Q 50-318 S 50-318 S 50-318 B	REYNOLDS: J REYNOLDS: J REYNOLDS: J REYNOLDS: J	8310180248 8310210242* 8310210242* 8310240158 8310240158	50-275 Q 50-275 T 50-275 T 50-275 Q 50-275 Q
PRICE, J. B. PROCTOR, S. D PROCTOR, S. D PUCCI, J. A. PUCCI, J. A.	8310310451 8310040467 8310250053 8310240029 8310240033	MASTE MQT 50-329 0 50-329 0 50-329 A 50-329 A	REAMER, C. W. REAMER, C. W. REAVIS, J. A. REAVIS, J. A. REBELLO, J. E	8310140020 8310170556 8310180100 8310180167 8310030534#	50~482	REYNOLDS, J REYNOLDS, J. R. REYNOLDS, J. R. REYNOLDS, J. R.	8310240277 8310240277 8310210228 8310210228 8310240234	50-275 0 50-275 0 50-275 1 50-275 1 50-275 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB-JECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
BEANOTOS' 1 B BEANOTOS' 1 B BEANOTOS' 1 B BEANOTOS' 1 B	8310260236 8310270358 8310270358 8310310141 8310310141	50-275 G 50-275 G 50-275 G 50-275 G 50-275 G	ROGERS, P ROGERS, P ROGERS, P ROGERS, P ROGERS, P	8310040147 8310040154 8310040206 8310040338 8310130283	50-348 S 50-313 S 50-348 S 50-348 S 50-348 S	RUSSELL, L B RUSSELL, L, B RUSSELL, L, S RUSSELL, V, RUSSELL, W, T	8310250587 8310250599 8310260081 8310260294* 8310120058	50-317 8 50-318 8 50-317 8 50-317 8 CONTRACT 50-289 P
REANOFOR'N B REANOFOR'N B REANOFOR'N B REANOFOR'N B	8310040314 8310040314 8310110322 8310110322 8310140022	50-445	ROGERS, P, ROGERS, P ROGERS, P ROGERS, P ROGERS, W H	8310180457 8310180489 8310180529 8310310368 8310170746*	50-348 S 50-348 S 50-348 S 50-348 S 50-321 F	RUSSELL, W T RUSSELL, W T RUSSELL, W T RUSSELL, W T RUSSELL, W T	9310130108 B310130186* B310140276 B310170002* B310170012	50-289 P 50-289 P 50-289 P 50-289 P 50-289 0
HEANOTDS'N S KEANOTDS'N S KEANOTDS'N S KEANOTDS'N S	8310140022 8310140066 8310140066 8310140086 8310140086	50-445 T 50-509 G 50-508 G 50-508 Q 50-508 G	ROLLINS, J D ROMAN, T W ROMAN, W, D ROMAN, W D ROMANO, F R	8310130334 8310140111 8310310067* 8310310068* 8310030437	PRDJ 50-220 R 50-250 P 50-250 P 50-352 Q	RUSSELL, W. T RUSSELL, W. T RUSSELL, W. T RUSSELL, W. T RUSSELL, W. T	8310170014 8310170018 8310170032 8310170043 8310170717	50-289 P 50-289 P 50-289 P 50-289 P
REYNOLDS'N 8 REANOLDS'N 8 REANOLDS'N 8 REANOLDS'N 8	B310170412 B310170412 B310170417* B310170417* B3102B0126	50-445	ROMANO, F R ROMANO, F R ROMANO, F R ROMANO, F R ROMNEY, N D	8310180419 8310310336 8310310353# 8310310371* 8310070007*	50-352 0 50-352 0 50-352 0 50-352 0 50-327 A	RUTBERG, J RUTLEDGE, C RUTLEDGE, C RUTLEDGE, C. RUTZ, A C	8310250289 8310040605 8310210102 8310210107* 8310110626*	50-352 Q 40-8502 40-8502 40-8502 WASTE MOT
HEANOLDA'A BEANOLDA'A BEANOLDA'N A BEANOLDA'N B	8310280124 8310310175 8310310175 8310140170* 8310190203*	50-508 0 50-508 0 50-508 0 50-320 0 50-352 0	ROOD, H ROSENSERG, E B ROSENSLATT, H B. ROSENTHAL, A S	8310180173 8310310454* 8310210097* 8310210198* 8310280218*	50-361 P 50-322 B CONTRACT CONTRACT 50-400 A	Rybak. B Rybak. B. Rybak. B. Rybak. B	8310040320 8310040471 8310120189 8310120409 8310170337	50-237 P 50-237 P 50-237 P 50-265 G 50-237 G
RHEE, 8	8310040373	50-237 8	ROBOLIE, E	8310040200	50~4&0 Q	Rybak, b	8310170545	50-254 P
RICE, D A	8310250327	50-29 8	ROBS, B	8310110512*	CONTRACT	Rybak, b	8310170553	50-237 8
RICE, D A	8310250421	50-29 8	ROBS, B R	8310110510*	CONTRACT	Rybak, b	8310260001	50-10 P
RICHARD, D D	8310170617*	50-316 8	ROBS, K C	8310110511*	FOIA	Rybak, b	8310310054	50-254 P
RICHARD, R	8310070224*	CONTRACT	ROBS, W J	8310250300*	50-327 Q	Ryder, c	8310260031*	FOIA
Richards, Bl Richards, D Richards, D Richards, S Richards, W	8310260114* 8310250604* 8310250616* 8310170180* 8310250448	70-1151 QA979 QA999 50-443 Q PR	ROBSBACH, L W ROTELLA, T. S ROTELLA, T S ROTH, J ROTH, J J	8310120199* 8310030376 8310030446 8310120086* 8310200169*	50-286 0 50-389 8 50-389 8 70-1100 70-820	RYDER, C RYDER, C. RYDER, C RYDER, C RYDER, C	8310260037* 8310260041* 8310260049* 8310260050* 8310260034*	FOIA FOIA FOIA FOIA
RICHTER, L	8310040345	50-346 8	ROTHMAN, R L ROTHSCHILD, M U ROTHSCHILD, H U ROTHSCHILD, M U ROTHSCHILD, M U	8310130152*	50-537 Q	RYTKONEN.B D	8310210178*	CONTRACT
RICHTER, B W	8310280122*	50-311 0		8310050424	50-445 Q	BABADOB.J W	8310040342*	70-824
RIDENHOUR, R	8310110040	50-382 0		8310050430	50-445 Q	BABADOB.J W	8310260174*	70-1113
RIDGWAY, D. A	8310110272	50-287 0		8310050435	50-445 Q	BAENGER.E L	8310240170	FOIA
RIDGWAY, K R	8310200268*	50-123 0		8310050525	50-445 Q	BAENGER.E L	8310260278*	FOIA
RIOGS.E.	8310120026*	50-201 I	ROTHSCHILD, M U	8310130031	50-445 Q	Bale, m J	8310260423	NUREQ
RILEY.J L	8310110270	50-413 T	ROTHSCHILD, M U	8310170488	50-445 Q	Baltzman, J	8310180622	70-2946
RING.M	8310270140*	50-454 G	ROTHSCHILD, M U	8310230489	50-445 Q	Bamanieqo, f J	8310210241*	50-275 T
RITSHER.J A	8310260187	50-443 A	ROWE, D B	8310050458*	CONTRACT	Bamelson, a	8310120403	50-461 G
ROBERDS.H W	8310130251*	50-482 G	ROWE, P	8310110371*	FOIA	Banborn, J	8310240085*	70-1100
ROBERTE, D E	8310070237*	CONTRACT	ROWBOME, F H	6308310422*	50-313 P	BANDERS,C F	8310250310	70-1151
ROBERTS, T M	8310110002	COMMISSION	ROY, O W	8310240081*	FOIA	BANDERB,W,F	8310040222*	50-424 Q
ROBERTS, T M	8310110006*	COMMISSION	ROY, O W	8310240108*	FOIA	BANDHOP,J R	8310170283	NUREQ
ROBERTS, T M	8310110008*	COMMISSION	ROY, O W	6310240144*	FOIA	BARBANES,P,8	8310170670*	50-320 U
ROBERTS, T M	8310110012*	COMMISSION	RDY, O W	8310240332*	FOIA	BARGENT,I H	8307020372*	50-277 P
ROBERTS, T M	8310110014*	COMMISSION	RDY.Q W	6310260336*	FOIA	BARBOUR, B	8310190167#	50-346 R
ROCHE, L A	8310250024*	FOIA	RDY.Q W	6310260341*	FDIA	BARBOUR, B	8310190170#	50-346 R
ROCHE-FARMER, L	8310250017*	FOIA	RUBIN.S D	6210180246*	50-344 S	SATHER, A	8310170572#	50-329 G
ROCHE-FARMER, L	8310250019*	FOIA	RUCKELSHAUS.W	6310170699*	COMMISSION	BATHER, A	8310310417#	50-329 G
ROCHE-FARMER, L	8310250025*	FOIA	RUDD.E	6310240241*	50-528 U	BAUNDERS, J H	8310190283	NUREO
RODDIS,L H	8310250093*	50-397 A	RUDY, C R	8310180403	40-6500	SAUNDERS.R.	8310060523#	50-280 F
RODDIS,L H	8310250097*	50-397 A	RUEBHAUSEN, G M	8310120034*	50-201 I	SAUNDERS.R	8310110240#	50-280 F
RODRIGUEZ,R. J	8310030485	50-312 P	RUEBKAUSEN, D M	8310120030*	50-201 I	SAUNDERS.R.	8310170016	50-280 R
RODRIGUEZ,R J	8310040317	50-312 P	RUFF, A. B	8310250380*	50-438 Q	SAUNDERS.R	8310260436#	50-280 F
RODRIGUEZ,R J	8310040419	50-312 R	RUITER, G H	8310170341	50-305 R	SCALETTI.D C	8310210342	50-447 A
RODRIGUEZ, R J	8310040547	50-312 F	RULAND, W H,	8310040384*	50-348 0	SCARAND, R. A	8310310239	50-27 G
RODRIGUEZ, R J	8310060021	50-312 F	RUNION, T. C.	8310120008*	50-201 I	SCARAND, R. A	8310310352	50-137 G
RODRIGUEZ, R J	8310070275	50-312 S	RUNION, T C	8310120007*	50-201 I	SCHAEFER, D. W	8310310284	50-206 S
RODRIGUEZ, R J	8310120087	50-312 P	RUNION, T C	8310120012*	50-201 I	SCHAPKER, J. F	8310040540#	50-546 G
RODRIGUEZ, R J	8310120145	50-312 B	RUNION, T C	8310120013*	50-201 I	SCHAUB, J. B.	8310260068	XPDRTLIC
RODRIQUEZ, R J	8310120140	50-312 R	RUNION,T C. RUNION,T C RUNION,T C RUNION,T C RUNION,T C	8310120014*	50-201 I	Schaus, J. B	8310260073#	XPORTLIC
RODRIQUEZ, R J	8310120147	50-312 8		8310120020*	50-201 I	Schaufelberger	8310040348	50-298 Q
RODRIQUEZ, R J	8310170214	50-312 R		8310120044*	50-201 I	Scheib, G N	8310140200	50-260 8
RODRIQUEZ, R, J,	8310180074	50-312 Q		8310120047*	50-201 I	Scheibinz, E	8310120256	50-258 8
RODRIQUEZ, R J,	8310210038	50-312 P		8310120207*	50-201 I	Bcherer, A E	8310070274	50-470 A
T R.ZEUGIRGOR C R.ZEUGIRGOR C R. SEUGIRGOR R CEUGIRGOR R CEUGIRGOR	8310270451 8310270452 8310280099 8310260028* 8310260111*	50-312 8 50-312 P FOIA FOIA	RUBHMORE, J. W RUBHMORE, J. W RUBBELL, L. B RUBBELL, L. B RUBBELL, L. B.	8310140043 8310140134 8310050344* 8310110258* 8310200004	50-220 J 50-220 J 50-317 F 50-317 F 50-318 B	SCHERRER, J. B. SCHIERLING, H SCHIERLING, H. E SCHIERLING, H. E SCHIERLING, H. E	8308300317* 8310170185 8310210355* 8310210357* 8310210365*	50-213 P 50-275 P 50-275 T 50-275 T 50-275 T
ROEDER, J. R	8310260140*	FOIA	RUSSELL, L. B.	8310200047	50-318 8	Schierling, He.	8310250182#	50-275 T
ROEDER, J. R	8310260162*	FOIA	RUSSELL, L. B	8310200147	50-317 8	Schierling, He	8310250332#	50-275 T
ROEDER, J. R	8310260171*	FOIA	RUSSELL, L. B	8310200154	50-318 8	Schmidt, & R.	8310140274#	50-529 S
ROEDER, J. R	8310260176*	FOIA	RUSSELL, L. B	8310250221	50-318 8	Schmidt, H. C.	8310040604	50-445 A
ROEDER, J. R.	8310260325*	FOIA	RUSSELL, L. B	8310250249	50-317 8	Schmidt, H. C	8310040604	50-445 A
ROEBSET, J M	8310200190*	50-275 T	RUSBELL, L. B.	8310250287	50-318 8	SCHMIDT, H, C	8310110116#	50-445 F
RODERS, H. A.	8310270035	50-320 P	RUSBELL, L. B.	8310250369	50-318 8	SCHMIDT, H, C,	8310110173	50-445 F
RODERS, H. R.	8310060083	50-327 8	RUSBELL, L. B.	8310250410	50-317 8	SCHMIDT, H, C,	8310200149	50-445 K
RODERS, H. R.	8310280077	50-327 8	RUSBELL, L. B.	8310250411	50-318 8	SCHMIDT, H, C,	8310270175	50-445 F
RODERS, J. C.	8310240047*	50-413 T	RUSBELL, L. B.	8310250443	50-318 8	SCHMIDT, H, C,	8310270185	50-445 F

AUTHOR	ACCESSION NUMBER	SUBJE	DRY	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTUGO	ACCESSION	SUBJEC	
SCHMIDT, H C SCHMITENDORF, O SCHNELL, D F. SCHNELL, D F SCHNELL, D F	8310280041 8310190002 8310040273* 8310040334 8310120069	50-445 50-338 50-483 FR 50-483	A R Q	BCHWENCER, A BCHWENCER, A SCHWENCER, A BCHWENCER, A BCHWENCER, A	8310110411 8310110462 8310120007 8310120027 8310120037	50-410 50-387 50-374 50-397 50-387	A P A F	AUTHOR SHAFER, W SHAFER, W SHAFER, W D SHAFER, W D	NUMBER B310040264 B310210122 B310040250 B310040158 B310040340	50-266 50-316 50-255 50-331 50-155	
SCHNELL.D F SCHREPPLE.L D BCHROCK.V E SCHROEDER.D A	8310210098 8310250661* 8310070267* 8310070110 8310120273	50-483 50-483 CENTRA NUREG 50-237	CT R	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8310130343 8310130411 8310170009 8310170045 8310170046	50-416 50-354 50-322 50-410 50-387	P A E A P	SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	8310060372* 8310120293 8310140173 8310170476 8310240042	50~155 50~315 50~275 50~263 50~266	0 0 0 0
SCHROEDER, C W	8310120433 8310130132 8310170426 8310180247 8310180281	50-373 50-374 50-374 50-373 50-373	P A K P	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8310170048 8310170131 8310170167 8310170664 8310170716	50-387 50-397 50-416 50-373 50-410	P A P F A	SHAFER, W D SHAFER, W D SHAFER, W D SHANBAKY, M SHANBAKY, M	8310240086 8310240073 8310250605 8310060349* 8310140234*	50-282 50-315 50-254 50-334 50-271	0 0 0
SCHROEDER, C W SCHROEDER, C W SCHROEDER, C W SCHROEDER, L SCHULTZ, W H	8310180397 8310180425 8310190258 8310210054 8310070436	50-373 50-373 50-373 50-374 NUREQ	Р Р В	Schwencer, A Schwencer, A Schwencer, A Schwencer, A Schwencer, A	8310170745 8310180131 8310190222 8310200031 8310210125	50-410 50-387 50-416 50-397 50-354	А Р Н А	SHANBAKY, M M SHANBAKY, M N SHANNON, J B SHANNON, Z SHAUB, E	8310040019* 8310120217* 8310240357 8310070117* 8310200092*	50-244 50-277 40-8064 CONTRACT 50-271	g G G
SCHULTZ, W H. SCHULTZ, W H. SCHULTZ, W H SCHULZ, R. D SCHUM, W S	8310110115* 8310240250* 8310240275* 8310140150* 8310130178*	40-17 70-1144 FOTA 50-461 50-482	Q Q	Schwencer, A Schwencer, A Schwencer, A Schwencer, A Schwencer, A	8310240247 8310240272 8310240275 8310250684 8310260014	50-416 50-458 50-373 50-373 50-458	S E P A	SHAUB.E T SHAUG.J C SHEA.J J SHEARIN.R L	8310190251* 8310180076 8310180085 8310270193 8310110409*	50-334 NUREG NUREG 50-245 50-460	a a
SCHUSTER, M D SCHUYLER, J O. SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O	8310030151# 8310040224# 8310030396 8310040141 8310040570	50-27 50-275 PR 50-275 50-275	F P	SCHWENCER, A SCHWENK, G A SCINTO, J SCOTT, D J SCOTT, D J	8310240017 8310170432* 8310120333* 8310040134* 8310040373	50-458 50-400 50-29 50-10 50-237	0 P F S	SHEFTEA'M N SHEFTEA'M N SHEELB'H E SHEELB'H E	8310250093* 8310250097* 8310120310 8310180392 8310250662	50-397 50-397 40-2061 40-2061 40-2061	A
SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O	8310040585* B310040571* 8310040578* 8310070236 8310120362	50-275 50-275 50-275 50-275 50-275	F & P # 80 1	SCOTT.D J SCOTT.D J SCOTT.D.J SCOTT.D.J	0310120273 9310210127 0310210165 0310210297 8310210313	50-237 50-237 50-249 50-237 50-237	R G S S S	SHEPARD, A M SHEPARD, A M SHEPHERD, R E SHEPHERD, R E SHEPPARD, J J	8310190097 8310190105* 8310270442* 8310270474* 8310040363	50-29 50-29 50-443 50-443 TOPREP	P G G
SCHUYLER, J. O SCHUYLER, J. O SCHUYLER, J. O SCHUYLER, J. O	8310120402 8310120404 8310140121 8310170285 8310170471	50-275 50-275 50-275 50-275 50-323 50-275	F E P A	E D.TTODS SCOTT.D J SCOTT.L H SCOTT.L H SCOTT.R J	8310270017* 8310270424 6310270477 8310130136 8310190020	50-10 50-247 50-249 50-302 50-346	F 8 9 8 8	SHEPPARD, J J SHEPPARD, J J SHERMAN, C SHERMAN, C	8310040363 8310110142 8310110142 8310200176 8310040379*	TOPREP TOPREP TOPREP 50-224 50-18	g Q
SCHUYLER, J. O SCHUYLER, J. O SCHUYLER, J. O SCHUYLER, J. O SCHUYLER, J. O	8310170514 8310170517 8310170545 8310170457	50-275 50-275 50-275 50-275		SCOHN, K SCOHN, K SCOHN, K M SCURRY, N SCURRY, N	8310040226* 8310180367* 8310170432* 8310110337 8310110341	50~275 50~344 50~397 ORG ORG	G G	SHERMAN, C I SHERMAN, C I SHERMAN, M P SHERR, T S SHERR, T S	8310310241* 8310310357* 8310170283 8310060558 8310060562	50-27 50-139 NUREO 70-1426 50-266	a a F
BCHUYLER, J. D.	8310180463 8310190643 8310190197 8310190197	50~275 50~275 50~275 50~275 50~275	P E E P	SCURRY, N SCURRY, N SCURRY, N SCURRY, N SEARLS, L K	8310110343 8310110344 8310110348 8310110347 8310030349	DRG DRG DRG ORG 50-434	н	SHERR, T S SHERR, T S SHERR, T S SHERWOOD, O G SHERWOOD, O G	8310180048 8310180052 8310210158 8310040026 8310260106		F F P K
SCHUYLER, J. D SCHUYLER, J. D SCHUYLER, J. D	8310200144 8310200183* 8310200240 8310210227	50-275 50-275 50-275 50-275	E F Q P P	SEARB.C A SEARS.C F SEARS.C F SEARS.J R SEIDLE.W C	8310050420* 8310030428 8310030428 8310230384* 8310040567	CONTRACT 50-245 50-245 50-322 50-285	P P T Q	SHERWOOD, G O SHEWMAXER, R E SHIEH, L C SHIELDS, S W SHIELDS, S W	8310260206 8310140052# 8310110032 8310030283 8310040428	NUREG PR	K a A
SCHUYLER, J. D. SCHUYLER, J. D SCHUYLER, J. D SCHUYLER, J. D SCHUYLER, J. D	8310210247 8310210284 8310250115 8310270572*	50-275 50-275 50-275 50-275 50-275	R R R F	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W. C	8310040020 8310130148 8310130172 8310130220 8310130241	50-313 50-285 50-482 50-313 50-482	0 0 0 0	SHIELDS, S W SHIELDS, S W SHIELDS, S W	8310040337 8310170530 8310210025 8310240081* 8310270375	50-547 50-546 50-546	8 8 9 9
BCHUYLER, J. O. BCHUYLER, J. O. BCHUYLER, J. O. BCHUYLER, J. O.	8310270580* 8310270586* 8310270588* 8310280048*	50-275 50-275 50-275 50-275 50-275	F F G F	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8310130257 8310130292 8310130306 8310130330 8310180242	50-313	0 G F Q Q	SHIELDS S W SHIFFER, J D SHIFFER, J D SHIFFER, J D SHIFFER, J D	8310270458 8310070158 8310120134 8310120280 8310250108	50-275 50-275 50-275	9 9 9
BCHUYLER, J. D. BCHMETZ, A. J. BCHMETBINZ, E. SCHWETBINZ, E. R. BCHWENCER, A.	8310280047* 8310140039 8310120287 8310030530*	50-275 50-155 50-155 50-358 50-358	о н а	SELLS.DE SELLS.DE SELLS.DE SERBU,RJ SERINI,BL	8310070182 8310130397 8310270531 8310050419* 8310040137*	50-335 50-335	P P B T	SHIFFER, J D SHIFFER, J D SHIFFER, J D SHIMA, S SHIMA, B	8310250539 8310250439 8310270376 8310180151 8310180155*	50-275	8 8
echmencer, a BCHMENCER, a BCHMENCER, a BCHMENCER, a BCHMENCER, a	8310030085* 8310030104* 8310030590 8310040105	50-416 50-416 50-322 50-374	P P A A	SERINI, B. L SEWELL, H M SEYFRIT, K V SEYFRIT, K V	8310060553* 8310060103* 8301180513* 8302020202* 8302180539*	50-333	S S S	SHINDHARA, K SHIRAKAWA, T SHIRAKAWA, T SHIRAKAWA, T SHIRK, R E	8310050187 8310060180 8310180304 8310180307 8310140080*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-302	P
BCHMENCER, A. BCHMENCER, A. BCHMENCER, A. BCHMENCER, A. BCHMENCER, A.	8310050067 8310050073 8310050085 8310050087	50-416 50-416 50-461 50-410 50-387	P P A A	SEYFRIT, K V SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V. SEYFRIT, K V	8303030103* 8303240341* 8303240364* 8304010008* 8304170104*	50-324 50-277 50-271	8 8 8 9	SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8310030496 8310110043 8310110047 8310110212 8310110225	50-358 50-289 50-352	0 0 0 0
BCHMENCER, A. BCHMENCER, A BCHMENCER, A BCHMENCER, A.	8310050131 8310040033 8310040037* 8310040057	50-416 50-416 50-416	r A P P	BEYFRIT,K V. SEYFRIT,K V SEYFRIT,K V SHACKLETON,G C SHAFER,P W	8306170442* 8306230142* 8310110051* 8310200232* 8310130311*	50-204 50-382 50-204	0 0 0 0 F	SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8310110320 8310120385 8310130167 8310130197 8310180333	50-275 (50-445 (50-491 (9000

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8310210177 8310240180 8310260256 8310260270 8310280070	50-553	SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M	8310170347* 8310170352* 8310170358* 8310170362* 8310170370*	FOIA FOIA FOIA FOIA FOIA	SHITH, J L SHITH, J V SMITH, L B SMITH, M A SMITH, M E	831019003 8310040355* 8310170198* 8310030559 8310110291	50-322 A 50-317 P 50-423 A 40-8786 50-352 0
SHOEMAKER,C J SHOEMAKER,C J SHOLLY,S C SHOLLY,S C	8310280118 8310310181 8310310431 8310110448 8310110581	50-322 0 50-275 0 50-329 0 FOIA FOIA	SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M	8310170374* 8310170379* 8310170386* 8310170391* 8310170392*	FOIA FOIA FOIA FOIA FOIA	SHITH, P SHITH, P A SHITH, P A SHITH, P A SHITH, P A	8310070230* 8310050362* 8310050387* 8310050459 8310050460*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SHOFFA'S C SHOFFA'S C SHOFFA'S C	8310170020 8310170057 8310170306 8310240172 8310310074	FOIA FOIA FOIA FOIA FOIA	SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M	8310170396* 8310170402* 8310170406* 8310170410* 8310170413*	FOIA FOIA FOIA FOIA FOIA	SMITH, P. A SMITH, P. A SMITH, P. A SMITH, P. A SMITH, P. A	8310070432* 8310110414* 8310110417* 8310110422* 8310260276*	CONTRACT FDIA FDIA FDIA CONTRACT
SHON, F J SHON, F J SHOP, F J EHOPENN, N M SHOTWELL, J A	8310040184 8310250048 8310260224 8310310380* 8310040272*	50-155	BILBERDERO, M BILBERBERO, M BILBERBERG, M BILBERBERO, M BILBERBERO, M	8310170415* 8310170416* 8310170422* 8310170427* 8310170431*	FOIA FOIA FOIA FOIA FOIA	SMITH, P J SMITH, R D SMITH, R D SMITH, R. D SMITH, R. D	8310280323 8310200371 8310200419 8310200438 8310200470	40-2259 40-7869 40-8452 40-8584 40-8674
SHOTWELL, J A SHOTWELL, J A SHOTWELL, J A SHOTWELL, J A	8310110152 8310120147 8310120151* 8310180368 8310180373*	50-443	SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M	8310170434* 8310170438* 8310170444* 8310170445* 8310170450*	FOIA FOIA FOIA FOIA FOIA	SMITH, R D SMITH, R. D SMITH, R D SMITH, R. D SMITH, R D	8310200471 8310240090 8310240092 8310270141 8310270519	40-6622 40-8681 40-8102 40-8781 40-8678
SHREVE, D B SHROPSHIRE, J C SIEBER, J D SIEGEL, A I SIFFORD, W L	8310110089* 8310240073* 8310240146 8310190243 8310240076*	CONTRACT 50-413 T 50-334 F NUREG 50-419 T	SILBERBERO, M SILBERG, J E SILBERG, J E SILBERT, E J	8310170452* 8310170461* 8310270330 8310270330	FDIA FDIA 50-440 Q 50-440 Q CONTRACT	SMITH, R. H. SMITH, W G SMITH, W G SMITH, W G, SMITH, W G,	8310270174* 8310060369 8310120188 8310120193 8310120197	50-29 0 50-315 8 50-316 8 50-316 8 50-315 8
SILBERBERO, M SILBERBERO, M SILBERBERO, M SILBERBERO, M SILBERBERO, M	8310170037* 8310170044* 8310170047# 8310170050* 8310170055*	FOIA FOIA FOIA FOIA	SILVERMAN.F S SILVIS.R M SILVIS.R M M.VOT-NAMIS A LONNIS	8310250038 8310180554 8310180581 8310050329 8310170572*	50-272 G CONTRACT CONTRACT RES 50-329 G	SHITH, W. C. SHITH, W. C. SHITH, W. C. SHITH, W. C. SHITH, W. C.	8310120234 8310120260 8310120343 8310120379 8310120443	50~316 8 50~315 8 50~315 8 50~316 8 50~316 8
Silberberg, M Silberberg, M Silberberg, M Silberberg, M Silberberg, M	8310170057* 8310170059* 8310170062* 8310170066* 8310170072*	FOIA FOIA FOIA FOIA	BIMON, J A BIMPSON, E C BIMPSON, E C BIMPSON, E C	8310310417# 8310070317 8310110620# 8310120171 8310120387	50-327 G NUREQ 50-54 U 50-302 P 50-302 P	SMITH, W O, SMITH, W O SMITH, W O SMITH, W O, SMITH, W O,	8310140029 8310140084 8310140137 8310170337 8310170387	50-315 8 50-315 8 50-316 8 50-315 8 50-315 8
Silberbero, m Silberbero, m Silberbero, m Silberbero, m Silberbero, m	8310170070* 8310170074* 8310170102* 8310170110* 8310170116*	FOIA FOIA FOIA FOIA FOIA	BIMPBON, E C BIMPBON, E C BIMPBON, E C BIMPBON, R O BINCLAIR, J B	8310140123 8310140233 8310180436 8310180566 8310050166	50-302 S 50-302 S 50-302 P FOIA 50-29 P	SHITH, W C. SHITH, W C SHITH, W C SHITH, W C SHITH, W C	8310170507 8310190064 8310190070 8310210036 8310210040	50-316 8 50-316 R 50-315 R 50-315 P 50-315 B
SILBERBERG, M SILBERBERG, M SILBERBERG, M BILBERBERG, M SILBERBERG, M	8310170120* 8310170123* 8310170128* 8310170130* 8310170136*	FOIA FOIA FOIA FOIA POIA	Binclair, J B Binclair, J B Binderman, R W Binderman, R W Binderman, R W,	8310120312 8310210310 8310040367* 8310040357* 8310040568*	50-271 P 50-271 P 50-155 T 50-155 T 50-155 T	SHITH, W O SHITH, W. O SHITH, W. O SHITH, W O. SHITH, W O	8310210115 8310210120 8310210137 8310210187 8310210206	50-315 E 50-314 E 50-315 E 50-316 E
SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M	8310170140* 8310170144* 8310170150* 8310170161* 8310170164*	FOIA FOIA FOIA FOIA FOIA	BINDERMAN, R W BINGER, B BINGH, A BINGH, M M BINISI, J M	B310050489* B310260226* B310050415* B310170067* B310240026	50-155 G FOIA 50-413 T CONTRACT 50-29 J	SMITH, W. Q SMITH, W. Q SMITH, W. Q SMYTH, C. W SNAIDER, R	8310270172 8310270204 8310270226 8310210037 8102260210*	50-316 S 50-315 S 50-315 S 50-289 R FOIA
Bilberberg, M Silberberg, M Silberberg, M Silberberg, M Silberberg, M	8310170166* 8310170169* 8310170171* 8310170176* 8310170180*	FOIA FOIA FOIA FOIA FOIA	BINKIN, L SINK, J M SINISI, J M SINISI, J M	8310240148 8310270461 8310110479* 8310260249 8310260249	50-29 J 50-245 J CONTRACT 50-478 Q 50-498 G	SNAIDER, R. P. SNAIDER, R. P. SNEIDER, C. S SNELL, W. SNELL, W. O	8011050238* 8011190749* 8310250056 8310140267* 8310140013*	FOIA FOIA 50-443 9 50-237 9 50-305 9
SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M SILBERBERG, M	8910170237* 8310170242* 8310170247* 8310170252* 8310170259*	FOIA FOIA FOIA FOIA	SKINNER:P H SINKIN.L SKEEN,J. SKIBA.E.L SINKIN.L SINKIN.L SKINNER:P H	8310260269 8310260269 8310110597* 8310310449 8310250560*	50-478 0 50-478 0 COMMISSION NUREO 50-321 G	SNIEZEK, J H SNYDER, B J SOLDAT, K L SOLINI, J A	8310110111* 8310190032 8310240256 8310260381 8310250412	50-275 P 50-244 R 50-320 P NUREO 50-333 8
Silberberg, m Silberberg, m Silberberg, m Silberberg, m Silberberg, m	8310170265* 8310170269* 8310170275* 8310170280* 8310170284*	FOIA FOIA FOIA FOIA FOIA	SEDWINSKI, W J SEDAN, K W. SEDAN, K W. SEDWINSKI, W J.	8310170107* 8310060174 8310120288* 8310210211* 8310110147*	50-338 6 70-2949 70-372 Contract Foia	SOLLEY, 8 W SOLON, L R SOMERVILLE, K O SOO, P SOONO, A L	8310210226 8310070271 8310260414 8310070411 8310050181*	50-257 6 State Prog 40-8783 NUREO 40-8794
Silberberg, M Silberberg, M Silberberg, M Silberberg, M, Silberberg, M	8310170288# 8310170274# 8310170300# 8310170303# 8310170305#	FOIA FOIA FOIA FOIA FOIA	SMITH, A L SMITH, B W. SMITH, O C. SMITH, O C. SMITH, H. L	8310250136* 8310040360* 8310250529* 8310270178* 8310140138*	0A999 70-36 50-272 G 70-371 50-316 S	BODNO, A L BORENBEN, O BORENBEN, O C BORENBEN, O C BORENBEN, O C	8310170693* 8310120335 8309300239 8310030303 8310030339	70-143 50-397 F 50-460 F 50-460 A 50-508 A
Silberberg, M Silberberg, M Silberberg, M Silberberg, M Silberberg, M	8310170309* 8310170314* 8310170319* 8310170323* 8310170326*	FOIA FOIA FOIA FOIA	mith, I.W. Bmith, I.W Smith, I.W Smith, J.C Smith, J.C	8310040188 8310050488 8310140026 8308300607 8310030224	50-287 Q 50-454 Q 50-287 Q 40-6622 40-6622	SORENSEN, O C SORENBEN, O C SORENBEN, G. C SORENBEN, G. C SORENBEN, G. C	8310030357 8310030361 8310030396 8310040440 8310070277	50-397 A 50-397 E PR 50-397 A 50-397 P
Silberberg, M Silberberg, M Silberberg, M Silberberg, M Silberberg, M	8310170328* 8310170338* 8310170336* 8310170340* 8310170343*	FOIA FOIA FOIA FOIA	E. HTIMB J. C., HTIMB J. C., HTIMB J. C., HTIMB J. C., HTIMB	8310030374 8310110080* 8310110141* 8310120264 8310140231	PR 50-269 F 50-269 F 50-322 E 50-322 E	SORENBEN, Q. C SORENBEN, Q. C SORENBEN, Q. C SORENBEN, Q. C SORENBEN, Q. C	8310070342 8310110276 8310110332 8310120059 8310120155	50~397 # 50~397 # 50~397 # 50~397 #

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESS ION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BORENBEN, O C BORENBEN, O C BORENBEN, Q. C BORENBEN, G C BORENBEN, G C	8310120261 8310120267 8310140176 8310170212 8310170235	50-397 A 50-397 A 50-508 A 50-397 E 50-397 E	STAROBTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	6310200163 6310210165 6310210207 6310210214 6310210269	70-820 50~307	210HK'7 b 210HK'7 b 210HK'7 b 210HK'7 b	8310050527 8310070139 8310070256 8310110164 8310110181	70-143 70-143 70-143 70-143 70-143
Sorensen, 9 C Gorensen, 9, C Sorensen, 9, C Sorensen, 9 C Sorensen, 9 C	8310170298 8310170313 8310170446 8310170495 8310180387	50-397 E 50-397 A 50-397 F 50-397 A 50-397 E	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8310240110 8310270155 8310270291 8310270323 8310270445	50-225 0 50-219 0 50-134 0 50-412 0 50-443 0	4 F'SHOIS 4 F'SHOIS 4 F'SHOIS 4 F'SHOIS	8310170239 8310250547 8310240097 8310240104 8310240154	70-27 70-1113 70-143 70-1151 70-27
SORENSEN, Q C SORENSEN, Q C. SORENSEN, Q, C. SORENSEN, Q C SORENSEN, Q C	8310180449 8310180503 8310190152 8310210168 8310210224	50-397 A 50-397 F 50-508 A 50-397 A 50-460 A	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8310310161 8310310222 8310310227 8310310282 8310310338	50-320	STORR, J P STORR, J P STOLZ, J F STOLZ, J F	8310240190 8310240215 8310240297 8310030418 8310030598	70-1113 70-1113 70-1113 50-289 P 50-346 P
BORENSEN, Q C. SORENSEN, Q C. SORENSEN, Q C SORENSEN, Q C SORENSEN, Q, C	8310210305 8310240150 8310260113 8310260189 8310310149	50-397 A 50-397 A 50-397 A 50-508 F 50-508 A	STEELE, M L STEFAND, J STEFAND, J STEFAND, J STELLO, V	8310170001 8310200395 8310200397# 8310200404# 8304200046#	50-289 P 50-440 A 50-440 A 50-440 A 50-255 P	STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F	8310030611 8310040111 8310040647 8310040648 8310040650	50-312 P 50-249 P 50-269 P 50-346 P 50-289 P
SOREMSON, C. SORRELL.E.C SOUTH, D.L SPECTER, S.M SPEER, M.J.	8310170154*	50-50B A	STELLO, V	8310140095*	50-498 G	STOLZ.J F	8310050004	50-277 F
	8310170743*	50-321 F	STELLO, V	8310240244	REVIEW GRP	STOLZ.J F	8310050049	50-313 P
	8310070414	NUREG	STELLO, V.	8310270436	REVIEW GRP	STOLZ.J F	8310050051	50-277 Q
	8310270094*	50-244 F	STEPHENS, T R.	8310120343	50-315 S	STOLZ.J F	8310050060	50-302 P
	8310170010	50-206 R	STEPHENS, T R	8310120449*	50-316 S	STOLZ.J F	8310050119	50-312 F
SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L.	8310040330 8310120253 8310120305 8310270422 8310270423*	50-305 G 50-254 P 50-341 G 50-440 G	STEPHENS, V. M STEPHENS, V. M STEPHENSON, C. J STEPHENSON, C. J	8310070100* 8310070212* 8310070257* 8310170161 8310250589	50-275 R 50-275 R 50-275 R 50-287 S 50-287 S	STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F STOLZ, J F	8310050297 8310040520 8310110442 8310110454 8310110471	50-302 P 50-313 F 50-321 P 50-277 P 50-312 P
BPESBARD, R. L.	8310310397	50-409 G	STEPTOE, P. P	8310190048	50-327 9	STOLZ, J F	8310110472	50-313 P
BPESBARD, R. L.	8310310400*	50-409 G	STEPTOE, P. P	8310190048	50-327 0	STOLZ, J F	8310110476	50-312 P
BRENIAWSKI, D. J.	8310110147*	FDIA	STEPTOE, P. P	8310200254	50-327 0	STOLZ, J F	8310110544#	50-346 P
BRENIAWSKI, D. J.	8310120279	70-572	STEPTOE, P. P	8310200254	50-327 9	STOLZ, J F	8310110545	50-269 P
BRENIAWSKI, D. J.	8310120283*	70-572	STEVENS, A R	8310180157*	CONTRACT	STOLZ, J F	8310110561#	50-269 P
SRENIAWSKI.D J	8310120288#	70-572	STEVENS, D	8310310204	Waste Mgt	STOLI, J.F	8310130382	50-344 P
ST LAURENT, N	8310280018	50-29 8	STEVENS, D L	8310070317	Nureg	STOLI, J.F	8310130421	50-302 P
ST LAURENT, N, N	8310250232	50-29 8	STEVENS, J L	8310200108	50-309 B	STOLI, J.F	8310170100*	50-313 P
ST LAURENT, N, N	8310250277	50-29 8	STEWART, C C	8310310418*	70-2430	STOLI, J.F	8310170307*	50-289 P
ST LAURENT, N, N	8310250327	50-29 8	STEWART, D	8310170318	Foia	STOLI, J.F	8310180567	50-346 P
ST LAURENT, N. N.	8310250418	50-29 8	STEWART, J. M	8310140207#	50-369 P	STOLZ.J F	8310180611	50-313 P
ST LAURENT, N N	8310250421	50-29 8	STEWART, J. P	8310200214#	50-206 Q	STOLZ.J.F.	8310200016	50-277 P
ST LAURENT, N N.	8310250523	50-29 8	STEWART, R. C.	8310180219#	50-445 Q	STOLZ.J F	8310200041	50-346 P
ST LAURENT, N. N.	8310280015	50-29 8	STEWART, W. L.	8310030300	PR	STOLZ.J F	8310200050	50-346 P
BT MARY, F A	8310170217*	FDIA	STEWART, W. L.	8310040450	50-280 Q	STOLZ.J F	8310200054	50-313 P
STALBBERO, D	8310310130*	50-416 0	STEWART, W.L.	8310040550	50-338	STOLI, J F	8310200064	50-302 P
STANGE, B. J	8310050334*	50-289 F	STEWART, W.L.	8310040587		STOLI, J F	8310210117*	50-302 P
STANGE, S. J	8310060532*	50-289 F	STEWART, W.L.	8310040523*		STOLI, J F	8310210143	50-302 P
STANGE, S. J	8310060551*	50-289 F	STEWART, W.L.	8310040577*		STOLI, J F	8310260337*	50-287 P
STANGE, S. J	8310200443*	50-320 F	STEWART, W.L.	8310070416*		STOLI, J F	8310280143	50-287 P
STANCE, B. J	8310210390+	50-289 F	STEWART: W. L	8310110137	50-280 P	STOLY, J F	8310310439	50-321 P
STANCE, B. J.	8310270125+	50-289 F	STEWART: W L	8310120114	50-338 P	STOLY, J F	8310310476	50-287 P
STANCE, S. J	8310270376+	50-289 F	STEWART: W L	8310120140	50-338 P	STONE, I Z	8310120415*	50-261 P
STARK, R. M	8310050405	50-337 A	STEWART: W L	8310130103	50-338 P	STONE, I Z	8310120422*	50-261 P
STARK, R. M.	8310130159	50-537 A	STEWART: W L	8310130145	50-338 P	STONE, J	8310110191	50-329 Q
STARK, B. J	8310040530	GEN TEC IB	STEWART, W. L	8310140094	50-280 P	STORMANT, J C	8310070414	NUREG
STARKEY, R. B	8310040285*	50-261 0	BTEWART, W. L	8310170091	50-338 B	STOUT, D. M	8310240373	40-8829
STARKEY, R. B	8310040473	50-261 0	BTEWART, W. L	8310180277	50-338 F	STOUT, R B	8310140244*	TOPREF
STARKEY, R. B.	8310250608*	50-261 0	BTEWART, W. L	8310180301	50-280 F	STRASMA, J	8310040428	50-10 8
STAROSTECKI, P	8310140240	50-271 0	BTEWART, W. L	8310180307	50-338 P	STREETER, J F	8310050387*	50-440 9
BTARÚSTECKI.R.	8310040389	50-410	STEWART, W.L.	8310190440	50-338 P	STREETER: J F	8310050473	50-373 0
STARÚSTECKI.R.	8310070321		STEWART, W.L.	8310190002	50-338 R	STREETER: J F	8310050476*	50-373 0
STARÚSTECKI.R.	8310120082		STEWART, W.L.	8310190016	50-280 R	STREETER: J F	8310140147	50-461 0
STARÚSTECKI.R.	8310120090		STEWART, W.L.	8310190043	50-280 P	STREETER: J. F	8310140146*	50-461 0
STARÚSTECKI.R.	8310120198		STEWART, W.L.	8310190112	50-338 P	STREETER: J. F	8310140213	50-373 0
STAROSTECKI, R	8310140132	50-320 Q	STEWART, W L	8310200101	50-280 P	STREETER, J F	8310250356	50-373 Q
BTAROSTECKI, R	8310140162	50-287 Q	STEWART, W L	8310200289	50-338 P	STREETER, J F	8310270128	50-454 Q
STAROSTECKI, R	8310140171	50-334 P	STEWART, W L	8310250066	50-339 S	STREETER, J. F	8310270134*	50-454 Q
STAROSTECKI, R	8310140272	50-309 P	STEWART, W L.	8310250456	50-280 Q	STREETER, J F	8310270438	50-305 Q
STAROSTECKI, R	8310140276	50-272 Q	STEWART, W L.	8310260432*	50-280 F	STREETER, J F	8310110032	NJREQ
BTAROSTECKI.R	8310170163	50-309 @	STEWART, W. L.	8310270300	50-280 P	STRETARS, D.A. STROBNIDER, J. STRUMWASSER, M. STRUMWASSER, M. STRUMWASSER, M.	8310250607	50-312 A
STAROSTECKI.R.	8310180304	50-213 @	STOCKMAN, H. W.	8310050253	NUREG		8310070317	NUREO
STAROSTECKI.R.	8310180315	50-334 @	STODDART, P. Q.	8310250409#	50-335 G		8310040288	50-275 9
STAROSTECKI.R.	8310180377	50-179 @	STOHR, J. P.	8309200181	70-27		8310110053	50-275 0
STAROSTECKI.R.	8310180382	50-5 @	STOHR, J. P.	8310040143	70-1151		8310200195*	50-275 T
Byarostecki, R. Starostecki, R. Starostecki, R Starostecki, R Starostecki, R.	8310180371 8310180437 8310190128 8310190137 8310190157	50-272 0 50-213 0 50-410 0 50-307 0 50-333 0	STOHR, J P. STOHR, J. P STOHR, J. P. STOHR, J. P STOHR, J. P	8310040190 8310040303 8310040312* 8310040337 8310040346	70-143 70-143 70-143 70-824 70-143	STRUMHASSER, M STRUMHASSER, M STRUMHASSER, M STUART, K STUART, K STUCKEY, S Q	8310260277 8310270338 8310270348* 8310250625* 8310170295	50-275 0 50-275 0 50-275 0 50-312 P 71-9126
Starostecki, r.	8310190176	50~352 G	STOHR, J. P.	8310040464	70-27	STUMBLER, A	8310120042*	50-201 1
Starostecki, r.	8310190182	50~423 G	STOHR, J. P.	8310040486+	70-27	SUBRAMONIAN, N	8308030016*	50-295 0
Starostecki, r.	8310200007	50~334 G	STOHR, J. P.	8310040489	70-27	SULIYAN, J, W	8310180602*	FOIA
Starostecki, r.	8310200099	50~317 G	STOHR, J. P.	8310040503	70-27	BULLIYAN, J W	8310180395	FOIA
Starostecki, r.	8310200162	50~277 G	STOHR, J. P.	8310050471	70-143	SUMMERS, R J	8310140279*	50-272 0

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJ CATE
SUC-ANTTILA, A SUTTON, J W SYENBSON, B A SWAIN, A D EWANSIGER, T Q	8310050253 8310180378# 8310170070 8310200388 8310270038	NUREG GA979 50-315 R NUREG TOPREP	THOMAS, M THOMASON, P V THOMASON, P V THOMASON, P V THOMASON, P V THOMPSON, D	8310040543* 8310060374 8310190024 8310210174 8310260287*	50-390 Q 50-298 S 50-298 R 50-298 S 70-1144	TOOLE, R. J TOOLE, R. J TOOLE, R. J TOOLE, R. J TOOLE, R. J	8310170007* 8310200008 8310200011 8310200430* 8310250552	50-28 50-28 50-28 50-28 50-28
SWANSON, D G SWANSON, E R SWARTZ, E D SWARTZ, E D SWARTZ, E D	8310050224 8310240100* 8310120219 8310170411 8310170573	NUREQ 50-315 G 50-456 E 50-454 S 50-454 S	THOMPSON.H L THOMPSON.H L THOMPSON.J C THOMPSON.R H THOMPSON.T	8310070146 8310110556 8310190034* 8310120301 8310140236*	PR 50-287 P 50-329 A 50-302 S 50-271 G	TOWNSEND, B TOWNSEND, B TOWNSEND, B TOWNSEND, B TOWNSEND, B TOWNSEND, B TOWNSEND, B TOWNSEND, B	8310130041 8310030524 8310210337 8310280133 8310050454	50-28 CONTR CONTR CONTR CONTR
SWARTZ.E D SWARTZ.E D SWEENEY.N R SWETLAND.P SWETLAND.P	8310180252 8310270188 8310070043* 8310180467 8310190159*	50-456 C 50-456 S COMMISSION 50-318 S 50-309 Q	THOMSEN, F T THOMSEN, F T THONOS, L THORNES, C THORNBERRY, R C	8310030390 8310030390 8310140170* 8310210317 8310190051	50-522	TOHNSEND. B L.	6310060318 6310060471 6310070099 6310070195 6310110262	CONTR CONTR CONTR CONTR CONTR
SWIGER, M A SWIGER, M A SYDNOR, R SYLVESTER, E D BZCZECH, R A	8310050520 8310050520 8310250249 8310050521* 8310190164	50-440 G 50-440 G 50-317 B 50-312 G 50-289 B	THORNTON, P THORNTON, P THORNTON, P THORNTON, P THORNTON, P THORPE, J R	8310240132* 8310240132* 8310310139 8310310139 8310030376	50-155 G 50-155 G 50-155 G 50-155 G PR	TOWNSEND, B.L. TOWNSEND, O TOWNSEND, O TRAMM, T.R. TRAMM, T.R.	8310110338 8310120036* 8310120039* 8310040554 8310120427	CONTR 50-20 50-20 50-45 50-45
BZCZECH,R A BZCZECH,R A BZUKIEWICZ,A BZUKIEWICZ,A	8310200061 8310250253 8310250606 8301250200* 8208240121*	50-287 8 50-289 8 50-289 8 FOIA FOIA	THULL, T S THULL, T S TIET, G TIETZ, G TILLMAN, A	8310180336 8310250263 8310110327* 8310270028* 8310170246*	50-245 S 50-245 S 50-234 F 50-254 F 70-27	TRAMM,T R TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVIE,W H TRAVIE,W H	8310210234 8310030401 8310030401 8310170175* 8310190335	50-45 50-31 50-31 71-55 71-55
TADA, H TALBOT, R TALBOT, R TALBOT, R TALBOT, R	8310050335 8310050545* 8310040127* 8310040504* 8310120035*	NUREG CONTRACT CONTRACT CONTRACT CONTRACT	TIPP8, 8 B TIPP8, 5 B TIPP8, 5 B TIPP8, 5. B TIPP8, 5 B	8310030247 8310030304 8310030318 8310030319 8310030336	50-321 B 50-321 S 50-346 B 50-366 S 50-366 S	TREBY, S.A. TREBY, S.A. TRENT, N. TREPPA, D.C. TRIMBLE, D.	8310050433 8310180163* 8310250047 8310310184* 8310180467	50-44 50-44 50-35 50-27 50-31
TALBOT:R TAM:P B TAMBLING:T N TAPIA:J I TARNUZZER:E C	8310130201* 8310130188 8310200248* 8310170683 8310310061*	CONTRACT 50-334 P 50-123 Q 50-445 T 50-27! P	TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B TIPPS.S B	8310030359 8310030382 8310030410 8310030415 8310030433	50-366 8 50-366 8 50-321 8 50-366 8 50-366 8	TRIMBLE: D TRIMBLE: D TRIMBLE: D C TRIOLO: 8. TRIOLO: 6.	8310190159* 8310310230* 8310200107* 8308030382* 8309160203*	50-30 50-31 50-31 50-31 50-28
TAUBER.H TAUBER.H TAUBER.H TAYLOR.G J TAYLOR.H S	8310130018 8310130229 8310180470 8310190028 8310040349*	50-341 E 50-341 A 50-341 A 50-395 R GA999	TIPPS,S B TIPPS,S B TIPPS,B B TIPPS,B B TIPPB,B B.	8310030442 8310030481 8310030486 8310030510 8310040409	50~366 S 50~321 B 50~366 S 50~366 S 50~366 S	TRIPP,L TRIPP,L E TRIPP,L E TRIPP,L E TRIPP,L E	8310060040 8310130375 8310140068 8310180121 8310200010*	50-33 50-23 50-27 50-41 50-33
TAYLOR.J H TAYLOR.J M TAYLOR.J M TAYLOR.J M	8310310130* 8310140145* 8310040390 8310120057 8310180505*	50-416 @ 50-269 P 50-546 @ 50-289 P 50-275 P	TIPPS.8 B TIPPS.6 B TIPPS.5 B TIPPS.8 B TIPPS.8 B	8310040524 8310040011 8310120408 8310140014 8310140144	50-321 8 50-366 8 50-366 8 50-321 8 50-321 8	TRIPP, L E TRIPP, L E TRIPP, L E, TROSKOSKI, W M TROSKOSKI, W M	8310200021* 8310210278* 8310310361 8310200010* 8310200021*	50-33 50-27 50-27 50-33 50-33
TAYLOR, J M TAYLOR, J M TAYLOR, J M TAYLOR, P. A TAYLOR, P. A	8310180511* 8310200244* 8310200455* 8310040150* 8310250230*	50-275 P 50-454 Q 50-424 U 50-413 Q 50-413 Q	TIPPS.8 B TIPPS.8 B TIPPS.8 B TIPPS.8.B TIPPS.8 B	8310170377 8310170509 8310170531 8310170582 8310170584	50-321 8 50-366 8 50-366 9 50-321 8 50-366 8	TROUP, Q.L. TROWBRIDGE, Q.F TROWBRIDGE, Q.F TROWBRIDGE, Q.F TROWBRIDGE, Q.F	8310250352# 8310110272 8310110272 8310210148 8310210148	70-14: 50-28: 50-28: 50-28: 50-28:
TAYLOR.R.G TAYLOR.R.G TAYLOR.R.G. TEMUS.C.J. TEMUS.C.J.	8310040240* 8310170483 8310170488* 8310170344 8310200408	50-445 G 50-445 T 50-445 T 71-9182 71-9184	TIPPS.8 B TIPPS.8 B TIPPS.8 B TIPPS.8 B TIPPS.8 B	8310250212 8310250285 8310250291 8310250311 8310250312	50-366 B 50-366 B 50-366 B 50-366 B 50-366 B	TROWERIDOE, 0 F TROWERIDOE, G, F TROWERIDOE, G F TROWERIDOE, G F TROWERIDOE, G, F	8310210200 8310210200 8310240166 8310240166 8310240184	50-32 50-32 50-28 50-28 50-28
TENZER.B E TERAD.D THADANI,M C THAMM.E,G. THEOFANOUS,T Q	8310070285 8310050558* 8310270535 8310110414* 8310190327*	M18C 50-247 P 50-331 P F01A F01A	TIPPS.S B. TIPPS.S B TIPPS.S D TIPPS.S D TIPPS.S D TIPPS.S B	8310250343 8310250506 8310310236 8310310257 8310310280	50-366 8 50-366 8 50-366 8 50-366 8 50-366 8	Tromeridoe, Q. F Truono, L. Teai, B S. Teai, B S. Tucker, H. B.	8310240184 8310180468 8310140042* 8310140046* 8310030376	50-28' RE00D 50-31' 50-31' PR
THOM. T THOMAS, A W THOMAS, B L THOMAS, B T. THOMAS, C O	8310190184 8310180559 8310140133 8310130404* 8310050028	50-259 R FOIA 50-254 G CONTRACT 50-83 F	TIPPS, B, B TIPPS, S, B TOBIN, W TOBIN, W, J,	8310310297 8310310363 8310170522* 8310070259* 8310210070*	50-321 S 50-366 B 50-261 Q 70-143 50-324 Q	TUCKER, H B TUCKER, H B, TUCKER, H, B, TUCKER, H, B TUCKER, H, B	8310030423 8310040016 8310040287 8310040319* 8310040368	50-28 50-41 50-41 50-41 50-36
THOMAS, C. O.	8310050044 8310050047* 8310050400 8310070104 8310110426	50-199 P 50-199 P TOPREP TOPREP 50-406 Q	TODD: A J TODD: P. TOKAR: H. TOLF: H. L. TOLF: H. L.	8310240242* 8310270419 8305240300* 8310130267* 8310130271*	50-344 P 50-265 B 50-282 B 50-400 E 50-400 E	TUCKER, H. B.	8310040403 8310040474 8310040472* 8310040575 8310040579	50-374 50-36 50-26 50-26 50-41
THOMAS, C D THOMAS, C D THOMAS, C D THOMAS, C D. THOMAS, C D.	8310170204 8310170728 8310170731 8310170734 8310180560	50-470 E 50-148 P 50-116 P 50-123 P TUPREP	TOLF, M, L TOLL, J S. TOLL, J, S. TOLLERSON, J L TOLSON, R 9.	8310130277* 8310Q40258 8310140118 8310270359* 8310140024*	50-400 E 50-166 F 50-166 V 50-263 B 50-445 T	TUCKER, H. B.	8310040038 8310040052 8310040058 8310040255 8310040248*	50-41 50-41 50-36 50-36 50-36
THOMAS, C D THOMAS, C D. THOMAS, C D THOMAS, C D THOMAS, C D	8310210088 8310210124 8310210132* 8310210138 8310210162	50-27 F 50-2 P 50-2 P 50-166 V 50-83 F	TOLBON, R. Q. TOME, A. E TOME, A. E. TOMLINSON, D. P TONER: K. A.	8310210176# 8310040611# 8310040611# 8310130230# 8310060024	50-445 Q 50-155 T 50-155 T 50-478 Q 50-155 P	TUCKER, H. B. TUCKER, H. B. TUCKER, H. B TUCKER, H. B. TUCKER, H. B	8310060384 8310060426 8310070131# 8310070143* 8310110076*	50-36 50-26 50-37 50-26 50-26
THOMAS, C D THOMAS, C D, THOMAS, C, D, THOMAS, D C THOMAS, D C	8310240147 8310270232 8310270243* 8310140070* 8310140070*	50-166 F 50-57 P 50-57 P 50-454 Q 50-454 Q	TONER, K. A. TONER, K. A. TONGUE, T TONGUE, T. O. TOOLE, R. J	8310060047 8310070177 8310120309 8310170151* 8310070263	50-255 P 50-255 P 50-247 B 40-86 50-289 G	TUCKER, H. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B.	8310110077# 8310110141# 8310110418# 8310120413 8310140143	50-36 50-26 50-36 50-36 50-26

AUTHOR	ACCESSION NUMBER	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJEC		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO	
TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8310140159 8310140205 8310140253 8310170248 8310170384	50-249 50-349 50-249 50-349 50-369	P 9 9	UPRIGHT,C M UPRIGHT,C M UPRIGHT,C M UPRIGHT,C M UPRIGHT,C M	B310040043* 8310040203* 8310040244* B310040335* 8310040345*	50-261 50-324 50-438 50-413 50-413	0 0 0 0	VANDODRN, PK VANDOGRN, PK VANNONI, MG VARANE, LS VARELA, AA	8310240018* 8310240038* 8310110174 8310200203* 8310060048*	50-413 50-413 NUREG 50-397 50-244	T T G
TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8310170430 8310170536 8310180100 8310180167 8310180444	50~369 50~269 50~269 50~269 50~269	8 8 8 8 F	UPRIGHT,C M UPRIGHT,C M UPRIGHT,C M URBANIX,T USI,V	8310250406* 8310250449* 8310250492* 8310250381* 8310110254*	50-390 50-250 50-327 50-322 50-317	0 0 7 F	VARGA, 5 A VARGA, 5 A VARGA, 5 A VARGA, 5 A VARGA, 5 A	8310030603 8310030613 8310030659 8310030663 8310040035	50-348 50-348 50-250 50-286 50-286	ያ የ የ
TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8310170145 8310170175 8310170262 8310210005 8310210028	50~413 50~413 50~413 50~369 50~369	E & S	USI.V URI.V UTLEY.E E UTLEY.E E	8310130313* 8310170005* 8310030141 8310070244* 8310120266	50-317 50-317 50-241 50-324 50-400	F G F	VARGA, 5 A VARGA, 5 A VARGA, 5 A VARGA, 5 A VARGA, 5 A	8310040051 8310040060* 8310040068 8310050017 8310050102	50-305 50-305 50-305 50-348 50-315	0 9 P P
TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8310210077 8310210111 8310210179 8310210308 8310210309	50-370 50-413 50-413 50-369 50-369	S S A S S	UTLEY,E E UTLEY,E E UTLEY,E E VAGCA,P VAGCA,P	8310120407 8310160427 8310200143 8310170142* 8310170256*	30-261 30-324 50-324 FOIA FOIA	P G	VARGA,S A VARGA,S A VARGA,S A VARGA,S A VARGA,S A	8310050148 8310060535 8310060546 8310060547 8310060557	50-247 50-364 50-315 50-261 50-272	P P P P
TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8310240151 8310250071 8310250074 8310250524* 8310250665*	50-249 50-349 50-349 50-349 50-249	P 9 8 0	VACCA,P VACCA,P C VACCA,P C VACCA,P C VACCA,P C	8310170345* 7908060318* 7908270319* 7911300172* 8001040244*	FOIA FOIA FOIA FOIA		VARGA, S A VARGA, B A VARGA, S A VARGA, S A VARGA, S A	8310070049 8310070054* 8310070097 8310070406 8310070408	50-344 50-344 50-272 50-241 50-315	9 9 8 8
TUCKER, H B	8310270048 8310270079 8310270136* 8310270173 8310270209	50-370 50-249 50-369 50-369 50-370	9 G F 9 5	VACCA, P. C VACCA, P. C VACCA, P. C VACCA, P. C VACCA, P. C	8004230428* 8006170100* 8006200467* 8007170062* 8007170967*	FOIA FOIA FOIA FOIA FOIA		VARGA.S A VARGA.S A VARGA.S A VARGA.S A VARGA.S A	8310110081* 8310110334* 8310110454 8310110460 8310110465	50-280 50-315 50-295 50-247 50-286	Р О Р
TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8310270310 8310270412 8310270482 8310280029 8310280094	50-370 50-269 50-413 50-269 50-413	च म 8 8 8	VACCA, P C VACCA, P C VACCA, P C VACCA, P C VACCA, P C	8010070328* 8310170224* 8310170241* 8310170350* 8310170399*	FOIA FOIA FOIA FOIA FOIA		VARGA, SA VARGA, SA VARGA, SA VARGA, SA VARGA, SA	8310130025 8310130191* 8310130217 8310130222* 8310130415	50-315 50-334 50-315 50-315 50-295	Q P P P
TUCKER, H B TUCKER, H B TUCKER, H B TUCKL B E TURK, B E	8310280105 8310280124 8310310416 8310130150 8310130156*	50-269 50-269 50-369 50-537 50-537	6 6 6	VACCA,P C VACCA,P C VACCA,P C VACCA,P C VADEN,J	8310170425* 8310170487* 8310170546* 8310170635* 8310280107*	FOIA FOIA FOIA FOIA WASTE MO	г	VARGA,S A VARGA,S A VARGA,S A VARGA,S A VARGA,B A	8310130416* 8310170037 8310170042 8310170200 8310180579	50-295 50-272 50-295 50-286 50-247	P P P
TURK, B E. TUSZKA, M E TUTTEROW, R, E TUTTEROW, R E TYKULSKER, D	8310170478 8310070133 8310040426* 8310040437* 8310210307	50-382 50-312 GA999 GA999 FOIA	P	VALERO, B VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8310250348* 8310030425 8310040375 8310070004 8310070147	GA999 50-528 50-528 50-528 50-528	E F S	VARGA,S A VARGA,S A VARGA,S A VARGA,S A VARGA,S A	8310180589* 8310240258 8310270153* 8310270602 8310280072*	50-305 50-250 50-250 50-247 50-348	6 6 6 6 6
TYLER, 9, W UDALL, H K. UDALL, H, X UDELL, R A UDERITZ, R A.	8310110347 8310200073# 8310240217# 8206140403# 8310050159	NUREO 50-445 50-528 FOIA 50-272	U U P	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8310070284 8310070339 8310070352 8310130124 8310140012	50-528 50-528 50-528 50-528 50-528	S S A 8	VARGA, S A VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8310280140 8310060573 8310060574 8310040581 8310060583	50-334 50-243 50-220 50-220 50-259	# F P P
UEBBING, R UHL, H O UHRIG, R E UHRIG, R E UHRIG, R E	8310120222 8310240168 8310040145 8310040334 8310070250	50-346 50-322 50-250 PR 50-389	8 0 F	VAN BRUNT, E, E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E, E	831 01 40238 831 01 40259 831 01 40269 831 02 10252 831 02 50099	50-529 50-528	5 6 8 A 6	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8310060586 8310070045 8310070061 8310070063 8310070068	50-263 50-253 50-259 50-259 50-259	P P P P
UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E	8310070253+ 831011013B 8310110296 8310130007 8310130125	50-387 50-250 50-250 50-335 50-250	Р Р Р	VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E.E VAN BRUNT,E E VAN BRUNT,E E	8310250146 8310250415 8310250568 8310260156 8310260176	50-528 50-528 50-528	A 8 8 9	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D G	8310070084 8310070114 8310070123* 8310070371 8310070395	50-333 50-220 50-220 50-298 50-259	P 0 0 F P
UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	8310130153 8310140217 8310170222 8310170240 8310180381	50-387 50-387 50-335 50-250 50-250	0 5 F Q	VAN BRUNT,E E	8310270413 8310270430 8310270460 8310310138 8310310316	50-528 50-529 50-528	5 5 5 5 5	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D D	8310070377 8310110536* 8310130106 8310170117 8310180567	50-259 50-259 50-296 50-331 50-298	무 우 우 무
UHRIG, R. E UHRIG, R. E, ULLRICH, B UMBEL, D UMBEL, D	9310250431+ 9310250437+ 9310310054+ 9310070193 8310070428	50-250 50-250 50-278 CONTRACT CONTRACT	g g	VAN BRUNT, E E VAN COTT, H VAN HOY, G. VAN VLIET, J VAN VLIET, J.	8510310372 8310070436 8310140088* 8310170304 8310260334	NUREO 50-498 50-289	A G P P	VASBALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8310240137 8310240144* 8310240152* 8310240154 8310240243	50-259 50-324 50-263 50-259 50-259	444
UMBEL, D UMBEL, D UMBEL, D UMBEL, D, M	8310110003 8310130162 8310280074 8310050336 8310070226	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		VANBRUNT, E E VANDENBURGH, C VANDEHALLE, D VANDEHALLE, D J VANDEHALLE, D J	8310250079 8310270140* 8310250118 8310050463 8310050465*	50~454 50~155 50~255	8 9 F P	VASSALLO, D B VAUGHAN, C M VAUGHAN, C M VAUGHAN, C M	B310310117 B310310137 B310130225 B310170061 B310170155	50-331 50-324 70-1113 70-1113 70-1113	þ
UMBEL, D M.	8310070434 8310110026 8310120010 8310120021 8310130360	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J	8310040080 8310120229* 8310120318 8310120327* 8310130179*	50-255 50-155	r 3 3	VAUGHAN, C M VAUGHAN, C M VAUGHAN, C M VAUGHN, G E, VENDEL, T E	8310170249 8310250427 8310260307* 8310240030* 8310050389*	70-1113 70-1113 70-1113 50-413 50-440	T O
UMBEL, D. M. UMBEL, D. M. UNKLE, T. J. 'MBAL, A. I. 'BAL, A. I.	8310210205 8310240097 8310250443 8310040373# 8310280006#	50-382	8 A A	VANDEWALLE, D. J. VANDEWALLE, D. J. VANDEWALLE, D. J. VANDEWALLE, D. J. VANDEWALLE, D. J.	8310180464 8310200256 8310250203* 8310270219 8310310376	50-255 50-255 50-155 50-	3 3	VENTURA, J C VERGE, A N VERRELLI, D VERRELLI, D VERRELLI, D	8310040385* 8310140021 8310170141 8310170189 8310170520	50-317 50-443 50-416 50-257 50-261	P 0 0 0 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJE CATE(
VERRELLI.D VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8310210064 8310040037 8310040140 8310040163 8310040166	50-324 Q 50-261 Q 50-370 Q 50-416 Q 50-261 Q	WALKER,R WALKER,R D WALKER,R D WALKER,R D WALKER,W J	8310180446 8310060165* 8310170483* 8310250613* 7909140005*	50-265 8 50-331 0 50-263 0 50-254 0 FOIA	WELCH.F WELCHER,D K WELLS.A A WELLS.D A WELLS.D A	8310050507* 8310120260 8310270151* 8310120311* 8310210066	50-151 50-311 FOIA 50-341
VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8310040182 8310040211 8310040265 8310040275* 8310040298	50-324	WALL,C F WALLER,W K WALSH,J D WALSH,J D WALSKE,C	8310050344* 8310200330 8310120384* 8310120384* 8310110579*	50-317 F 71-6679 50-352 G 50-352 G MISC	WELLB.D A WELLB.D A WELLB.J E WELLB.R A WELLB.R W	8310250114 8310270447 8310110032 8310200265 8310250577	50-341 50-341 NUREG 50-32' TOPREF
VERRELLI, D M	8310040321* 8310040347 8310040374 8310040378* 8310040423	50-324 Q 50-261 F 50-348 Q 50-348 Q 50-370 Q	WALTERS,C WAMBACH,T V WANG,P C WARD,J O WARD,R T	8310190047* 8310250096 8310210358* 8310260185* 8310170098*	50-327 A 50-255 P 50-275 T F01A 50-338 8	WELLB.R W WELBH.J A WENGLAWSKI.F WENGLAWSKI.F	8310250577 8310170211 8310040391 8310040396 8310200176	TOPREF 71-90° 50-19 50-204 50-224
VERRELLI, D M	8310040494 8310040555 8310040581 8310250214 8310250234	50-416 V 50-390 Q 50-348 F 50-416 Q 50-259 Q	Ward, W Ward, W Ward, W J Ward, W J Wardwell, R E	8310270462* 8310270474* 8008270592* 8310280220* 8310280170*	50-443 Q 50-443 Q 50-498 Q 50-358 Q 40-299	HENSLAWSKI, FA HENSLAWSKI, FA HENSLAWSKI, FA HENSLAWSKI, FA	8310040300 8310040308* 8310040311* 8310040379* 8310120245	50-315 50-315 50-315 50-18 50-344
VERRELLI, D M	8310250299 8310250301 8310250303 8310250319* 8310250322	50-327	WARDWELL, R E WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	9310280175* 8310040207 8310040315 8310040325 8310170260	40-279 50-267 8 50-267 8 50-267 P 50-267 R	WENSLAWSKI, F A WENSLAWSKI, F A WENSLAWSKI, F A WENSLAWSKI, F A	8310120348 8310120355 8310170674 8310170678* 8310210254	70-121 50-311 50-311 50-311 50-221
VERRELLI, D M	8310250373 8310250374 8310250397 8310250439 8310250472	50-438	WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W WARNER, D L WARNICK, R	8310040210 8310040276 8310110236* 8310170030 8310120446	50~267	WENBLAWSKI, FA, WENBLAWSKI, FA, WENBLAWSKI, FA WENBLAWSKI, FA	8310210254* 8310310233 8310310241* 8310310249* 8310310357*	50-226 50-73 50-27 50-73 50-135
VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8310250485* 8310250502* 8310250543 8310250588 8310250593	50-348	WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F	8310050518 8310050522* 8310050538 8310050540* 8310120177	50-358 Q 50-358 Q 50-358 Q 50-358 Q 50-327 A	HERMIEL.J S HERMIEL.J S HERMIEL.J S HERMIEL.J S HERMIEL.J S	8310210355* 8310210357* 8310210371* 8310210387* 8310250332*	50-27: 50-27: 50-27: 50-27: 50-27:
VERRELLI.D M VERRELLI.D M VERRELLI.D M VISSING.G S VISSING.G S	8310250401* 8310250411* 8310250428 8310110418 8310130140	50-261	WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F,	8310120325 8310140135 8310170451 8310170459 8310170513	50-327 0 50-358 0 50-358 0 50-329 0 50-329 0	Werner, R P Werner, R P Werner, R P Westafer Westafer, G R	8310040334 8310040334 8310040334 8310070306 8310040301	PR PR PR 50-30; 50-30;
VIBBING, G S VOGLER, B H VOGLER, B H VOGLER, B H	8310170076 8310050429 8310130037 8310250342 8310250364*	50-313 P 50-352 Q 50-352 Q 50-352 Q 50-352 Q	WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F	8310170558 8310170562* 8310170583 8310210316 8310240285*	50-327 Q 50-327 Q 50-327 Q 50-327 Q 50-327 A	Hestaper, C R. Hestaper, G R Hestaper, G R. Hestaper, G R Hestaper, G R.	8310040420 8310040463 8310040472* 8310070307 8310120301	50-30; 50-30; 50-30; 50-30;
V091, D V019T, H, H V019T, H H V019T, H H V017, R E	8310130143 8310110182 8310200026 8310280169 8310030561	NUREG 50-287 G 50-287 P 50-287 P 71-9151	Warnick, R F Warnick, R F Wart, R J Wasenko, M Wasenko, M	8310270341 8310310411 8310310449 8310070293* 8310070295*	50-329 0 50-329 0 MUREQ 50-324 F 50-324 F	Westafer, C R Hestafer, O R. Westafer, O R Westafer, G R. Westafer, G R	8310140079 8310140243 8310170319 8310180473 8310210021	50-30; 50-30; 50-30; 50-30;
VOLGENAU, E VOLGENAU, E VOLGEN, B H VOLLMER, R	8310260240* 8310260252* 8310250171 8310180125 8308270027*	FOIA FOIA 50-458 M 40-8348 50-329 A	WATERS, J R WATSON, L WATSON, L J WEAVER, J D WEBB, D F	8310240096* 8310030461 8310230540* 8310210302 8310170146	50-275 G 50-414 B 50-321 G 50-278 F 50-358 G	Webtafer, o r Webtafer, o r Webtarook, w w Webtarook, w w Webterman, t f	8310250374* 8310250458 8310040231* 8310040234* 8310170683	50-30; 50-30; 50-44(50-44(50-44)
VDLLMER,R VDLLMER,R H VOLLMER,R H VOLLMER,R H VDLZER,H J	8310130269* 8304010047* 8310050206* 8310120054 8310170084*	50-329 A FOIA 50-244 P 50-289 P CONTRACT	WEBB, J H. WEBB, W E. WEBER, M F. WEBER, M F WEBSTER, B H	8310240423 8310110203* 8310240252 8310240265 8310040282	NUREO 50-239 F WASTE MOT WASTE MOT 50-261 O	WESTERMAN, T F. WESTPHAL, B B WESTRICH, H R WETHY, C M WETHY, C M	8310180161* 8310120109 8310050253 8310060492* 8310270053*	50-29(50-37; NUREQ 50-33; 50-38
VOORHEEB, L D VORSE, J Y VORSE, J Y VOSBURY, F. W. VOBBURY, F W	8310240423 8310280245* 8310280299* 8210010087* 8212010152*	NUREG 50~400 A 50-400 A 50-272 P 50-344 P	WEEKS, E.D WEINKAM.E.J WEINKAM.E.J WEINSTEIN.M. WEINTRAUB.A.A	8310170260 8310130084 8310260442 8310170313* 8310170170	50-133 R 50-458 F 50-458 A FOIA 71-5595	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8310040627 8310040627 8310050557 8310110275 8310110275	50-35; 50-35; 27-39 50-35; 50-35;
VOSBURY, F W VOSBURY, F W VOSBURY, F W VUMBACO, F, J WAGNER, A G	8306160513* 8306160602* 8309060263* 8310050516 8310250271*	50-324 P 50-302 P 50-315 P 40-672 50-416 G	WEINTRAUB, A. A WEINTRAUB, A. A WEINTRAUB, A. A, WEISE, B WEISE, B	8310170306 8310170342 8310170744 8310250339* 8310250627*	71-6550 71-4909 71-5939 50-261 G 50-261 G	HETTERHAHNIM J HETTERHAHNIM J HETTERHAHNIM J HETTERHAHNIM.J HETTERHAHNIM.J	8310110277# 8310110277# 8310110284# 8310110284# 8310110287#	50~35; 50~35; 50~35; 50~35; 50~35;
WAGNER, D WAGNER, D WAGNER, M E. WAGNER, M E WAGNER, P C	8310070217 8310070223 8310130048 8310250338 8310180385	50-354 A 50-354 A 50-269 Q 50-269 G 50-267 P	Weisemann, R A Weiss, D Weiss, D J Weiss, E, R Weiss, E, R	8310280007 8310070090* 8310170253* 8310050528 8310070369*	TOPREP 40-8794 70-1113 50-289 0 COMMISSION	HETTERHAHNIM J HETTERHAHNIM.J HETTERHAHNIM J. HETTERHAHNIM J HETTERHAHNIM J	8310110287# 8310110292# 8310110297# 8310110297# 8310110305	50-351 50-351 50-351 50-351 50-351
WAGNER, P.C. WAGNER, P.C. WAHL, H.W. WAHL, H.W. WALD, J.J.	8310310384 8310310433 8310040488* 8310280229* 8310040341*	50-267 P 50-267 P 0A979 50-358 A 50-358 F	WE189, E R WE189, E R WE189, E. R WE189, E. R. WE189, E. R.	9310070386* 8310070386* 8310180531 8310200231 8310250046	COMMISSION COMMISSION 50-333 P 50-289 Q 50-289 G	METTERHAHN; M. J METTERHAHN; M. J WETTERHAHN; M. J WETTERHAHN; M. J WETTERHAHN; M. J	8310110305 8310110312* 8310110312* 8310120364 8310120364	50-35; 50-35; 50-35; 50-35; 50-35;
WALDORF, J WALKEN, M WALKER, E WALKER, E WALKER, R	8310260145* 8310260148* 8310060381* 8310200422 8310120307	50-324 P 50-324 P 50-278 S 71-6144 50-249 S	Weiss, e. r Weiss, e. r Weiss, e. r Weisz, d. a Welch, f	8310260306 8310260308* 8310270366 8310070359 8310030507*	50-287 0 50-287 0 FOIA TOPREP 50-155 0	HETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M, J WETTERHAHN, M, J WETTERHAHN, M J	8310120348* 8310120348* 8310120377* 8310120377* 8310180132	50-35; 50-35; 50-35; 50-35; 50-35;

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION REDMUN	SUBJECT CATEGORY
WETTERHAHN, M J	8310180132	50-352	HILLITE, M	8310270289	50-295 B	WILSON, B D	8310260007	XPORTLIC
WETTERHAHN, M J	8310180137*		HILLARD, J	8310170498	50-346 B	WILSON, D L	8310270015*	50-331 F
WETTERHAHN, M J	8310180137*		HILLIAMS, C C	8310050497*	50-341 Q	WILSON, F	8310060010*	CONTRACT
WETTERHAHN, M J	8310180146*		WILLIAMS, C C	8310140192*	50-454 Q	WILSON, J	8310060584*	50-280 F
WETTERHAHN, M J	8310180146*		HILLIAMS, D	8310120062	50-352 A	WILSON, J L	8310060208	50-280 S
WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8310180234 8310180234 8310180237* 8310180237* 8310310231	50-352	WILLIAMS, D L WILLIAMS, F C WILLIAMS, F C WILLIAMS, F C WILLIAMS, F C	8310240102* 8310030465 8310030465 8310110310 8310110310	50-282 G 50-329 G 50-329 G 50-329 G 50-329 G	WILBON, J L WILBON, J L WILBON, P WILBON, R F	8310070164 8310210306 8310250607 8310060476* 8310110200	50-280 8 50-280 6 50-280 8 CONTRACT 50-287 P
WETTERHAHN, M J	8310310231	50-352	WILLIAMS.FC	8310280073	50-327 0	WILSON, V H	8310200407*	50-440 A
WEYANT, P A	8310170078*		WILLIAMS.FC	8310280073	50-327 0	WILSON, W E	8310030143	50-27 F
WHALEN, R J	8310210297		WILLIAMS.HG	8310280117*	State Prog	WINSOWSKI, W S	8310120240*	50-305 F
WHICHER, J. M	8310040205		WILLIAMS.J	8310040336	50-358 F	WINTERHOFF, D R	8310270490	50-373 S
WHICHER, J. M	8310040205		WILLIAMS.J	8310040459	50-358 K	WISE, R	8310030457*	50-267 G
WHICHER, J M	8310040205	50-454 0	Williams, J	8310120252	50-358 A	WIGENBURG,M R	8310030311	PR
WHICHER, J M	8310040205	50-454 0	Williams, J	8310120363	50-358 B	WITHERB,B D	8310060099	50~344 F
WHICHER, J. M	8310110278	50-367 0	Williams, J	8310120442	50-358 B	WITHERB,B,D	8310060261*	50~344 F
WHICHER, J. M	8310110278	50-367 0	Williams, J	8310130242	50-358 K	WITHERB,B D	8310060491	50~344 F
WHICHER, J M	8310200097	50-454 0	Williams, J	8310170348	50-358 B	WITHERB,B D	8310110189	50~344 P
MHICHER, J M MHICHER, J M MHICHER, J M MHICHER, J M MHICHER, J M MHICHER, J M	8310200077 8310200077 8310210204 8310210219* 8310210219*	50-454 G 50-454 O 50-454 G 50-454 G 50-454 O	Williams, J Williams, J Williams, J Williams, J Williams, J	9310170404 9310170448 9310170454* 9310170485 9310170515	50-358 8 50-358 8 50-358 0 50-358 8 50-358 A	WITHERS, B D	8310110196* 8310120247* 8310180417 8310200189 8310200192*	50-344 P 50-344 Q 50-514 A 50-344 P 50-344 P
WHICHER, J M WHIPPLE, G H WHITE, G D. WHITE, G R WHITE, J R.	8310210219* 8310060222* 8310260381 8310180343 8310110549*	50-454 0 50-400 0 NUREO 50-412 0 CONTRACT	MILL IAMS, J WILL IAMS, J WILL IAMS, J WILL IAMS, J	8310170649 8310180296 8310200098 8310200209 8310200212*	50-358	WITHERS, B D WITHERS, B D WITHERS, B D WITTENBURG, K C WIZNER, D G	8310260237 8310270521* 8310310299 8310060186 8310210215*	50-344 P 50-344 F 50-344 P 50-373 8 50-316 6
HHITE, J.R. HHITE, L.D. WHITE, R WHITENER, H.L. WHITLAM, R. Q	8310120217* 8310310073* 8310250631* 8310040147* 8310040344	50-277 G 50-244 P 50-312 P 50-370 G 50-508 A	HILLIAMS, J WILLIAMS, J WILLIAMS, J WILLIAMS, J.	8310200215* 8310200222* 8310200227* 8310200230* 8310200234*	50-358 A 50-358 A 50-358 A 50-358 A 50-358 A	WIZNER,D G WODARSKI,L J WOHL,M L WOJCHOUSKI,A V WOLF,J F	8310270223* 8310210180* 8310050481* 8310270414* 8310140089	50-315 8 CONTRACT 50-155 T 50-243 8 50~522 0
MHITNEY, O WHITNEY, O WHITNEY, O WHITNEY, O WHITNEY, O	6310250282 6309190140 8310190174 8310200226 8310250137	50-293 8 50-293 R 50-293 8 50-293 9 50-293 8	MILLIAMS, J MILLIAMS, J MILLIAMS, J MILLIAMS, J	8310210110+ 8310210113+ 8310240161 8310250366 8310250487	50-358	NDLF.JF NOLFE.R NOLFE.SJ NOLFE.SJ	8310250048 8310170243 8310170367 8310130207 8310240163	50-320 0 NUREO 50-344 8 50-289 0 50-338 0
WHITNEY, 0 0 WHITTIER, 0 D WHITTIER, 0 D WHITTIER, 0 D WHITTIER, 0 D	8310280045 8310030283 8310040616 8310070159 8310070202	50-293 5 PR 50-309 V 50-309 P 50-309 P	JRMALLIUM WILLIAMS, J WILLIAMS, J H WILLIAMS, J W WILLIAMS, J W	8310250584* 8310260076 8310210276* 8310250039 8310030254	50-358	HOLFE, B J WOLFE, B J WOLLETT, B WOLLETT, B WOLLETT, B	8310250042 8310270326 8310050547 8310060071 8310060178	50-289 0 50-338 0 CONTRACT CONTRACT
WHITTIER, G. D	8310120165	50-309 B	M F'SHVITIM	8310030262	50-251 8	₩OLLETT,8	8310170111	CONTRACT
WHITTIER, G. D	8310170148*	50-309 Q	A F'SHVITIM	8310030378	50~387 8	WOLLETT,8	8310210091	CONTRACT
WHITTIER, G. D	8310170231	50-309 B	A F'SHVITIM	8310030448	50-387 8	WOLLETT,8	8310260371	CONTRACT
WHITTIER, G. D	8310200108	50-309 B	A F'SHVITIM	8310040271	PR	WOLLETT,8	8310270596	CONTRACT
WHITTIER, G. D	8310210174*	50-309 Q	A F'SHVITIM	8310180208	50-335 P	WOŁMAN,A	8310120026*	50-201 1
WHITTIER, G. D.	8310210208*	50-307 G	WILLIAMS,J W	8310180254	50-335 P	WOLTNER, E	8310120201*	70-135
WHITTIER, G. D	8310250063	50-309 P	WILLIAMS,J W	8310180324	50-250 P	WOOD, E.C.	8310250280	50-309 B
WHITTIER, G. D	8310250384	50-309 S	WILLIAMS,J W	8310180389	50-250 S	WOODHEAD, C.P	8310310479	50-317 P
WHITTIER, G. D	8310270208*	50-309 F	WILLIAMS,J W	8310190023	50-250 R	WOODRUFF, D.C	8010010784*	50-34B P
WHITTLEBEY, K. A	8310130178*	50-482 G	WILLIAMS,J W	8310190104	50-369 S	WOODS, V.L	8310050554*	CONTRACT
WHITTLESEY, K, A	8310170683	50-445 T	WILLIAMS, J W	6310210223	50-251 8	WOOLEVER,E J	8310030360*	50-412 K
HICKS: F	8310110121	50-225 P	WILLIAMS, J W	6310240140	50-335 P	WOOLEVER,E J	8310310062	50-412 K
WICKS: F.	8310200055*	50-225 P	WILLIAMS, J W	6310250060	50-387 8	WOOLEVER,E J	8310310087	50-412 A
WIDMAN, R P.	8310070148*	CONTRACT	WILLIAMS, J W	6310250337	50-387 8	WOOLEVER,E J	8310310307	50-412 F
WIESE: J	8310140170*	50-320 G	WILLIAMS, J, W	8310270120	50-335 P	WRAY,J R	8310230428*	50-338 G
Hiedeman.d. Hiedeman.d.o Hieder.a V. Hieder.a V. Hiesemann.r a	8310120230 8310310318 831030213* 8310310258 8310050212*	I&E I&E XPORTLIC 70-734 PROJ	WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8310270211 8310270249 8310270277 8310270354* 8310280082	50-387 P 50-250 0 50-251 8 50-251 8 50-335 P	WRAY, J R WRAY, R WRIGHT, C L WRIGHT, C L WRIGHT, C L	8310250621* 8310180367* 8310070136 8310070322 8310170541	50-335 0 50-275 T 50-261 9 50-261 8 50-261 8
Hieremann, R. A	8310060270*	PRDJ	WILLIAMB, J W	8310280183	30-335 P	WRIGHT, C. WRIGHT, N. A WRIGHT, N. A WRIGHT, N. A WRIGHT, R. A WRIGHT, R. J.	8310060374*	50-155 Q
Hieremann, R. A	8310110149*	TOPREP	WILLIAMB, J W	8310310018	50-335 P		8310130010	50-329 Q
Hieremann, R. A	8310200199*	TOPREP	WILLIAMB, D G	8310110496	FOIA		8310130233	50-329 Q
Hieremann, R. A.	8310260267*	50-400 E	WILLIAMB, R E	8310070221*	CONTRACT		8310250100	50-352 Q
Hieremann, R. A.	8310260281*	50-445 A	WILLIAMB, R E	8310120040*	CONTRACT		8310310464	MISC
Hiesemaan, r a	8310280017*	50-400 E	WILLIAMB,R E	8310280048*	CONTRACT	HRIGHT, R W	8310040244*	50~438 0
Hiesemaan, r, a	8310280110*	PROJ	WILLIAMB,B J	8310200083	50-358 8	HRIGHT, R. W.	8310040335*	50~413 0
Higgins, e.	8310070184	50-498 A	WILLIAMB,T,	8310140134*	50-358 G	HRIGHT, R W	8310040345*	50~413 0
Higgins, e.	8310070197	CONTRACT	WILLBEY,W B	8310120313	50-277 R	HRIGHT, S, V	8310310207	27~48
Higgins, e.	8310070214	CONTRACT	WILSON,A,K	8310110520	FOIA	HU, P	8301070386*	50~282 \$
Higging, E Higging, E Higginton, D, Higginton, D	8310070329 8310130198 8310130417 8310040028 8310070225	CONTRACT CONTRACT CONTRACT 50-315 P 50-316 P	HILBON, A K HILBON, A. K. HILBON, A K HILBON, B D HILBON, B. D.	8310110538* 8310110541* 8310110547* 8310130369 8310130371	FOIA FOIA FOIA XPORTLIC XPORTLIC	HU, P. HU, P HUNDERLICH, T K HURZBURG, G N HYNGARDEN, B D.	8305050044* 8310170344* 8310070176* 8310200462* 8310180015*	50-282 B 50-282 B CONTRACT CONTRACT 70-143
HIGDINTON, D.L.	8310110333	50-315 P	WILBON, B D	8310180112	XPORTLIC	YANDELL,L A	8310130171*	50-285 Q
HILCOVE, M. N.	8310130028	50-320 0	WILBON, B D.	8310180310	XPORTLIC	YANEV,P. I	8310120233*	50-155 T
HILCOX, J. D.	8310250333*	50-438 0	WILBON, B D.	8310180577	XPORTLIC	YANEV,P. I	8310120233*	50-155 T
HILD, P. A.	8310170464*	50-327 0	WILBON, B D.	8310180580*	XPORTLIC	YIN, I T	8310040179*	50-346 Q
HILOUS, H. S.	8310140187	50-302 8	WILBON, B D	8310240311	XPORTLIC	YORK,W.	8310040427*	50-370 Q

AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGOR
YOST, R A	8310170548	50-358	R						
YOUNG, F	8310140166*	50~289	G	ZIMMERMAN, J V	8309230037	XPORTLIC	ZIMMERMAN, J V	8310180564	XPORTLI
YOUNG, M	8310050475*	50-454	0	ZIMMERMAN, J V	8310060078	XPORTL1C	ZIMHERMAN, J V	8310240300	XPORTL 14
YOUNG M A	8310050440	50~454	G .	ZIMMERMAN, J V	B310060104	XPORTLIC	ZIMMERMAN, J V	8310240309*	XPORTL I
YOUNG. M A	8310050452	50~454	G	ZIMMERMAN.J V	8310040107	XPORTLIC	ZIMMERMAN, J V	8310240314	XPORTL 1
TUDNGTH B	0010000100			ZIMMERMAN, J V	8010040108	XPORTLIC	ZIMHERMAN, J V	8310240314	XPORTL I
YOUNG M A	8310050468*	50-454	9	ZIMMERMAN, J V	9310060114	XPORTLIC			
AUMO'N V	B310130014	50-454	G			XPORTLIC	ZIMMERHAN, J V	8310250020	XPORTLI
YOUNG, H A	8310250117	50-454	G	ZIMMERMAN, J V	8310040114		ZIMMERMAN, J V	8310250142	XPORTL I
YOUNG, M A	8310250486	50~454	0	ZIMMERMAN, J V	8310040123	XPORTLIC	ZIMMERHAN, J V	8310250150	XPORTLI
YOUNG, M A	8310250504*	50-454	G	ZIMMERMAN, J V	8310060126	XPORTLIC	ZIMMERMAN, J V	8310250164	XPORTLI
•			_	ZIMMERMAN, J V	8310060131	XPORTLIC	ZIMMERMAN, J V	8310250172	XPORTLI
YOUNG, M A	B310250513	50~454	G						
YOUNG H L	8310040533	50-443	G	ZIMMERMAN, J V	B310060141	XPORTLIC	ZIMMERHAN, J V	831025017B	XPORTL1
YOUNG, M L	8310120178	50~443	Q	ZIMMERMAN, J V	8310060143	XFORTLIC	ZIMMERMAN, J V	8310260004	XPORTL I
YOUNG P T	#2720E101EB	50-400	E	ZIMMERMAN, J V	8310050147	XPORTLIC	ZIMMERHAN, J V	8310240020	XPDRTLI
YOUNG, T	8310040537#	50-528	G	ZIMMERMAN, J V	9310040152	XPORTLIC	ZIMMERMAN, J V	8310240039	XPORTL I
# DOMEST I	00100 1000			ZIMMERMAN, J V	8310040154	XPORTLIC	ZIMMERMAN, J V	B310260057	XPORTL I
YOUNG, T	8310120251	50-312	8						
YOUNG, T	8310120321	50~312	5	ZIMMERMAN, J V	8310060183	XPORTLIC	ZIMHERMAN, J V	B310260079	XPORTL I
YOUNG, T	8310170470*	50-528	G.	ZIMMERMAN, J V	8310040240	XPDRTLIC	ZIMMERMAN, J V	8310260328	XPORTL I
YOUNG, T	8310240222*	50-528	Q	ZIMMERMAN, J V	8310060405	XPORTLIC	ZIMMERMAN, J V	8310270540	XPORTL I
YOUNG, T	8310310304*	50~312	G .	ZIMMERMAN, J V	9310120453	*XPORTLIC	ZIMMERMAN, J V	B310270543	XPORTL I
TUCHEN				ZIMMERMAN, J V	B310120459	XPORTL1C	ZIMMERMAN, R P	8310210220*	50-244
YOUNG, T	B310310398*	50-528	G						-
YDUNG, T	8310310405*	50-312	G	zimmerman.J V	8310120461	XPORTLIC	ZIMMERMAN, B	8310040297	₽R
YOUNGBLOOD, B J	6310110376	50-482	F	ZIMMERMAN, J V	8310130023	XPORTLIC	ZIMMERMAN, S R	8310030527	PRM
YOUNGBLOOD, B J	8310110383	50-546	C	ZIMMERMAN.J V	8310130030	XPORTLIC	ZIMMERMAN, S R	8310060561#	50-324
AGONGBEDOD' B 1	8310110475	50~440	Ē	ZIMMERMAN, J V	8310130032	XPORTLIC	ZIMMERMAN, S R	8310070291	50-324
AUDIAG SECTION D. C.	0010110110			ZIMMERMAN. J V	B310130034	XPORTL IC	ZIMHERMAN, S R	8310190162	50-261
YOUNGBLOOD, B J	8310110501	50-546	C						
ADONGBEOOD'B A	8310110402	50~423	E	ZIMMERMAN.J V	8310130038	XPORTL IC	ZIMMERMAN, S R	831020005B	50-324
YOUNGBLOOD, B J	B310170049	50-423	Α	ZIMMERMAN.J V	8310130050	XPORTLIC	ZIMMERMAN, B R	8310250450	50-400
YOUNGBLOOD B J	8310170193	50-423	Α	ZIMMERMAN, J V	8310130075	XPORTL IC	ZUMWALT, L R	8310110271*	CONTRAC
AUNOBFUDD' B 1	8310170713	50~482	F	ZIMMERMAN, J V	8310130086	XPDRTL1C	ZUPKD, J M	8310180114	50-311
AUDMANCHODIN A	4010170710			ZIMMERMAN, J V	8310130092	XPDRTL IC	ZONKO' J. W	8310190178	50~311
ADMNOBFOUD'B 1	B310170715	50~445	Α						
ADMNOBLOOD'B A	8310170722	50-482	F	ZIMMERMAN, J V	8310130147	XPDRTL IC	ZUPKO, J M	8310170302	71-9086
YOUNGBLOOD, B J	6310170724	50-423	Α	ZIMMERMAN,J Y	8310130355	XPDRTL IC	ZUPKO, J M	8310200014	71-6574
YOUNGBLOOD, B J	8310280175	50-546	G	ZIMMERMAN.J V	8310130364	XPORTL IC	ZUPKO. J M	8310200174	50-272
YOUNGBLOOD, B J	8310310153	50~544	Α	ZIMMERMAN.J V	8310130367	XPORTL IC	ZUPKO. J M	8310200279	50-311
INDIABLOODI D				ZIMMERMAN.J V	8310130401	XPORTL IC	ZUPKO.J M	8310210041	50-311
AONMOBITOOD'B ?	8310310168	50-456	Ą			WD0071 16			
YOUNGBLOOD, B. J	E310310170	50-423	A	ZIMMERMAN, J V	E310130405	XPORTL IC	ZUPKD.J M	8310250238	50-272
YOUNGBLOOD, R	8310310444	50~302	P	ZIMMERMAN, J V	8310130419	XPORTLIC	ZUPKO.J M	8310250244	50~311
YOUNGLING, E J	8310310454*	50-322	6	ZIMMERMAN, J V	8310170023	XPORTL IC	ZUPKD. J M	8310250325	50-272
YUHAS, G P	#11E04001E8	50-312	a	ZIMMERHAN, J V	8310170038	XPDRTL.IC	ZUPKD. J M	B310250390	50-272
Intuen a				ZIMMERMANI J V	8310170041	XPORTL IC	ZUPKO.J M	8310250407	50-311
YUNDT, C. P.	8310140246	50-344	S		0010170/70	VIODEL TO			
YUNDT, C P	8310190039	50-344	R	ZIMMERHAN, J V	B310170679	XPORTL IC	ZUPKO,J M	B310250470	50-31 i
YUNDT, C.P.	8310250444	50-344	8	ZIMMERMAN, J V	10000101	XPORTL IC	ZUPKD.J M	8310250547	50-311
ZERBE, J E	831011058B*	MISC		ZIMMERMAN,J V	8310180159	XPORTL IC	ZUPKD.J M	B3102B0024	50-272
ZIBULSKY, H	B3102400B5*	70-1100		ZIMMERMAN.J V	8310180164	XPORTL1C	ZURAKONSKI, P R	8310030213*	XPORTLI
£450CUNITI				ZIMMERMAN, J V	8310180555	XPORTL IC	E	2	

AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQUA	ŧΥ	AFFILIATION	ACCESSION NUMBER	EVBJ CATE
	831025014B*	QA999			310170423*	50-34
ALFAB, Inc	831025014B*	9A777 50-287	G		310180124	50-34
Agmodts Acres American, Inc	8310310449	NUREG	u	8	310180134	50~36
Acton Environ Testing Corp	8310130267*	50-400	E		310180308	50-34
ACTON ENGINEE TESTING SOLF	6310130267*	50-400	É	8	310190071	50-36
	0310130271*	50-400	E		310210022	50-34 50-34
	0310130271*	50-400	E		310210259	50-34
	0310130277*	50~400	Ε		310210259 310210261*	50-34
Aero Nav Laboratories. Inc	8310130280*	50-400	E		310210261*	50~34
Agbabian Associates	0310070429*	CONTRACT	*			
Agriculture, Dept of, Graduate School	#40104S01EB	CONTRACT			310250422	50-34 50-34
•	#310240130*	CONTRACT	í		310250479¥ 310270061	50-36
Air Force: Dept of	B310110349*	FOIA			1310270001 131027010B*	50-36
	8310110375*	FOIA			310270108*	50-36
	8310110384*	FOIA				
Air and Water Pollution Patrol	8310030437	50-352	G		1310270374 3310270378*	50-34 50-34
	8310180419	50-352	0		8310270378* 8310030645*	GEN T
	6310310334	50-352	Q	Witten Masker of Constants A	3310030043*	MIBC
	8310310336 8310310353*	50~352 50~352	G		310070127*	HISC
	8310310353*	50-352	G	a	310170623	40-33
	8310310353*		G		310170633*	40-93
	8310310371*	50-352 50-352	G	Allis-Chalmers Corp	310270092*	FOIA
Alabama Power Co	8310030147	50-352	F	All is Charmon's Corp	3310270105#	FOIA
Wignama Londs Co	8310030414	50-348	P	а	3310270182*	FOIA
	8310030414	50-348	Р		9310270186*	FOIA
	8310030439	50-364	8		310270189#	FOIA
	#77E04001EB	50-348	a		3310180313*	GA999
	8310040387	50-348	P	E	3310180323#	9A777 9A777
	8310040387	50-348	P		9310180340+	
	8310040436	50-348	F	WWELTFUL CIRCLIF LAME OF 1	9310310080# 9310250348#	50-31 98999
	9310090099	50-346	P		9310250348*	CONTR
	8310070139	50~348	8	Must reals Summarene D. Marchine	331011000	* Con the
	8310070290	50-364	5	Astronautics American Institute of Steel Construction, &	2310140163	TOPRE
	8310070296	50-348	5	Inc.		
	8310070294	50-348	8	t	B310140174#	TOPRE
	8310070299*	50-348	8		B310240098*	CONTR:
	8310070302*	50-348	8	Wastrall Incress. Scallenge Tuestage	B310240078* B310140295	CUNTR:
	8310120350	50-348	5		8310140277#	40-44
	8310120350	50-348	8		B310030376	PR
		~~ 040	-		9310030376	PR
	B310120356*	50-346	8	WALICAU LINETERS CONTRACT		
	8310120363* 8310120371*	50-346	8 8	ı	9310250449	PR
	6310120371* 6310140194	50-348 50-348	p	American Physical Society	B310110029#	CONTR
	8310140174 8310140174	50-348 50-348	b.	American Society for Testing & Meterials	8310070415*	CONTR
				American Telephone & Telegraph Co	9310170084*	CONTR
	8310140199*	50-348	P	/American Bell	8310260064	XPORTI
	8310140177*	50-34B	P	Amersham Corp	BUILUEUV	A1 0
	8310140226	50-348	8	. L	6310110133#	50-36
	8310140229*	50-348	5		8310050556#	CONTR
	8310140235*	50-348	8	Anthony, R.L	0310170040	50-35;
	8310170407	50-348	P	•	8310170040	50-35
	8310170407	50-348	p-		8310170044#	50-35:
	8310170416	50-348	P			50~35:
	8310170416	50-346	₽		8310170044* 8310050224	NUREO
	8310170423#	50-348	P	Applied Science Associates, Inc	8310000447	MAKER

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	łY
Arizona Public Service Co	8310030425 8310030425 8310040307 8310040375 8310040375	50-528 50-528 PR 50-528 50-529	F		8310250141 8310250153 8310250274 8310250281 8310250417	50-313 50-313 50-313 50-368 50-313	6 6 8 8
	8310040375 8310070006 8310070147 8310070147 8310070147	50-528 50-528 50-528 50-528 50-528	5 5 5	Army, Dept of Army, Dept of, Army Engineer Waterways Experiment Station	8310250533 8310290559 8310310348 8310270417 8310070154	50-368 50-313 50-368 40-8599 NUREG	P F S
	8310070284 8310070339 8310070352 8310070352 8310070352	50-528 50-529 50-528 50-528 50-528	5	Army. Dept of, Corps of Engineers Aronin, L Associated Piping & Engineering Corp	8310050337* 8310270577* 8310180401*	CONTRACT CONTRACT GA999	
	8310130124 8310130124	50-526 50-528	A A	(subs of Johnson Controls, Inc)	8310180404# 8310180404#	9A999 9A999	
	8310140012 8310140012 8310140238	50-528 50-528 50-528	A 9 8	Atlas Minerals Atomic Industrial Forum	8310180407# 8310180411# 8310190106 8310040291	9A999 9A999 40-3453 PR	
	8310140259 8310140249 8310210252 8310240223#	50-528 50-529 50-528 50-528 50-528	6 9 A Q	Automated Sciences Group, Inc Automatic Switch Co Automation Industries, Inc Avatar Systems, Inc	8310110579# 8310070432# 8310180400# 8310110033# 8310240279	MISC CONTRACT GA999 FOIA FOIA	•
	8310250079 8310250146 8310250415 8310250415	50-528 50-528 50-528 50-528 50-528	9 8 4 9 8	BWR Owners Group Dabcock & Hilcox Go	8310110509* 8310110511* 8310110518* 8310030306* 8310040304*	FOIA FOIA FOIA 50-460 50-302	۸ P
	8310250548 8310250548 8310250548 8310260156	50-528 50-528 50-528 50-528	5 9 5 5 A		8310040470* 8310070028* 8310070032* 8310070035* 8310070038*	70-27 70-364 70-364 70-364 70-364	
	8310260156 8310270407 8310270413 8310270430 8310270460	50-528 50-530 50-529 50-528 50-529	A 8 8 8 8		8310070040* 8310070042* 8310140145* 8310170034 8310170065	70-364 70-364 50-269 70-27 70-27	P
Arizona, Univ of, Tucson, AZ Arkansas Power & Light Co	8310310138 8310310314 8310310372 8310070414 8310030332	50-528 50-528 50-528 NUREG 50-313	5 8 A P		8310170076 8310170081 8310170206 8310170229 8310170315	70-1201 70-27 70-27 70-27 70-27	
	8310030337 8310030340* 8310030833 8310030416 8310030416	50-368 50-368 50-313 50-313 50-313	후 후 후 두		8310170727 8310170730 8310170740 8310180561 8310200333	70-27 70-824 70-1201 XPORTLIC 71-5797	:
	8310030482 8310040149 8310040154 8310040206 8310040291	50~382 50~368 50~313 50~368 PR	9 9 9 5		8310200333 8310200418 8310250273 8310250424* 8310260146*	70-27 TOPREP 50-313 70-27	Q
	8310040338 8310040250* 8310040250* 8310040402	50-368 50-313 50-313 50-313	8 F F	Babcock & Wilcox Operating Plants Owners Oroug	8310110490*		P
	8310060601* 8310060601* 8310110440* 8310120079 8310120079	50-313 50-313 50-313 50-313 50-313	F F P P	Backus: Shea & Meyer	8310140152 8310310413* 8310030355 8310110227	TOPREP 50-289 50-443 50-443	P G O
	8310120081* 8310120081* 8310120083* 8310120083*	50-313 50-313 50-313 50-313	ь ь		8310120107 8310120107 8310120111* 8310120111* 8310120115*	50-443 50-443 50-443 50-443 50-443	0000
	8310120447 8310130097 8310130180 8310130283	50-313 50-368 50-368 50-368	P P S		8310120115* 8310120122* 8310120122* 8310120126* 8310120126*	50-443 50-443 50-443 50-443 50-443	00000
	8310140076 8310140152 8310140225 8310180189	50-368 TOPREP 50-313	F P 9		8310120135* 8310120135* 8310120141*	50-443 50-443 50-443 50-443	9 0000
	8310180457 8310180489 8310180529 8310190045	50-368 50-368 50-368 50-368	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Ball, Hayden, Kierpan & Livingston Baltimore Gas & Electric Co	B310120141# B310210307 B310040080 B310040080	FDIA 50-317 50-317	P P
	8310190117 8310190292* 8310190292* 8310190295*	50-313 50-313 50-313 50-313	R F F		8310040353 8310040542 8310040542	50-317 50-317 50-317	P 8
	8310240035	50-313	5		8310050344* 8310110254*	50-317 50-317	F

AUTHOR AFFILIATION	ACCESSION NUIDER	SUBJECT	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310110254* 8310110258* 8310110258* 8310120242 8310130313*	50-317 50-317 50-317 50-317 50-317	F F 8 F	Biotechnology, Inc Boeing Go Boeing Computer Services, Inc (subs of	8310070436 8310250007 8310050387*	NUREO FOIA CONTRACT CONTRACT
	8310170005* 8310170005* 8310190148 8310190148 8310200004	50-917 50-317 50-317 50-317 50-318	F F R R	Boeing Co) Boston Edisan Co	8309190140 8310030354 8310120307 8310120330	50-293 R 50-293 P 50-293 P 50-293 P
	8310200047 8310200147 8310200154 8310200241 8310210210#	50-318 50-317 50-318 50-317 50-317	8 5 9 P G		B310180111 B310180435 B310180438* B310180479 B310180483* B310180491	50-293 R 50-293 F 50-293 P 50-293 P
	8310210210* 8310240072 8310240072 8310240134 8310240134	50-317 50-317 50-317 50-317 50-317	Q P P P		8310190174 83101901226 8310250137 8310250282 8310250544	50-293 P 50-293 S 50-293 B 50-293 B 50-293 K
	8310240142 8310250221 8310250247 8310250287 8310250369	50-317 50-318 50-317 50-318 50-318	P S S S		8310250549* 8310270230* 8310260045 8310310144 8310310290	50-293 K 50-293 Q 50-293 B 50-293 P 50-293 P
	8310250410 8310250411 8310250443 8310250587 8310250597	50-317 50-318 50-318 50-317 50-318	S S S S	Bowline Corp Braunkohle Transport & Storage, Inc Brookhaven National Laboratory	8310310306 8310040426# 8310040437* 8310250331 8310070411	50-293 P GA999 GA999 PR NUREO
	8310270485* 8310280081 8310310014 8310310014 8310310055	50-317 50-317 50-317 50-317 50-317	F \$ F F	,	8310180613* 8310180615* 8310180617* 8310180617* 8310180621*	50-275 P 50-275 P 50-275 P 50-275 P 50-275 P
Battelle Human Affairs Research Centers Battelle Memorial Institute	8310310055 8310310303 8310130128 8310130134* 8310180576*	50-317 50-317 MISC MISC CONTRAC	F P		8310180423* 8310180424* 8310180626* 8310180627* 8310270075*	50-275 P 50-275 P 50-275 P 50-275 P FOIA
Battelle Memorial Institute, Columbus Laboratories	8310040103*	CONTRACT	Т	Parker & Root Corp. Javies of Hallithurton	8310310114 8310310444	NUREO 50-302 P
Battelle Memorial Institute, Pacific Northwest Laboratory	8310270045* 8310030457*	F01A 50-267	Q	Brown & Root Corp (subs of Hmlliburton Corp) Brown Hoveri Corp (subs of Brown Hovers & Co , Ltd)		50-445 T 50-341 B
	8310050145 8310070216	REB		Brown Univ Burns & Roe Co	B310070196* B310040232	CONTRACT 50-397 F
	8310070317 8310070442 8310110347 8310110479*	NUREG NUREG NUREG FOIA		Businesamen for the Public Interest C-E Operating Plants Owners Group	8310040331 8310250505 8310110278 8310210204 8310250577	50-397 B 50-397 B 50-367 Q 50-454 Q TDPREP
	8310110480* 8310170669 8310170675* 8310260381 8310310106	F01A 70-984 70-984 NUREQ NUREQ		C Itoh & Co (America), Inc. CEPA Cable News Network, Inc. California Polytechnic State Univ , Ban	8310060187 8310260273 8310240315 8310110344*	XPORTLIC 50-352 0 FOIA CONTRACT
Bear Creek Uranium Co	8310310208 8310310268 8310030199 8310030241	NUREG NUREG 40-8452 40-8452		Luis Obispo. CA California, State of	8310040209 8310040209	50-275 Q
Bechtel Corp	8310030250* 8310040127* 8310040129*	40-8452 50-352 50-352	A A		8310040212+ 8310040212+ 8310040217+ 8310040217+	50-275 G 50-275 G 50-275 G 50-275 G
	8310040131* 8310040355* 8310040488*	50-352 50-317 GA979 50-352	A P		8310040288 8310110053 8310120376 8310120376 8310120381*	50-275 @ 50-275 @ 50-275 @ 50-275 @ 50-275 @
	8310130131* 8310130323* 8310140256* 8310140274*	50-206 50-206 50-331 50-527	р Р R S		8310120381* 8310120386* 8310120386* 8310200178	50-275 Q 50-275 Q 50-275 Q 50-275 T
	8310170244* 8310210142* 8310210227* 8310240212* 8310250128*	50-250 50-327 50-275 50-528 50-204	F A P O P		8310200178 8310200184* 8310200184* 8310200170*	50-275 T 50-275 T 50-275 T 50-275 T
	B310250408* B310280224* B310280227* B310280231*	GA979 50-358 50-358 50-358	A A A		8310200190+ 8310200195+ 8310200195+ 8310240169	50-275 T 50-275 T 50-275 T 50-275 U
Benton City Technology	B310310074 B310270041* B310270044*	50-482 50-320 50-320	9 P		8310240169 8310250045 8310260180*	50-275 U 50-275 U FOIA
Big State X-Ray	8310130253	71-503			8310260185*	FOIA

	ACCESSION	TDBLBUB		AUTHOR AFF IL 1AT ION	accession Number	SUBJECT CATEGORY
AFFILIATION AFFILIATION	NUMBER B310240277 B310240317+ B310270338 B310270338	50-275 F01A 50-275 50-275) } }		8310070246* 8310070291 8310070291 8310070293* 8310070293*	50-324 0 50-324 F 50-324 F 50-324 F 50-324 F
'alifornia, Univ of, Los Ampeles, CA	8310270348* 8310270348* 8310270377* 8310310141 8310030374	50-275 50-275 50-275 50-142	; ; ; ; ;		8310070295* 8310070295* 8310070308 8310070322 8310110119	50-324 F 50-324 F 50-261 B 50-261 B 50-400 E
'anada, Atomic Energy Control Board 'arolina Environmental Study Group 'arolina Power & Light Co	8310200184* 8310180458 8310200331 8310110270 8307200175 8310030151	REGGD XPORTLIC 50-413 50-324	T S P		8310110119 8310110142 8310110149 8310110150 8310110159	TOPREP 50-261 F 50-400 G 50-400 G
	8310030202 8310030209 8310030422 8310030426 8310030441		ន ន ន o		8310110155* 8310110407* 8310110407* 8310110409*	50~400
	8310030441 8310030478* 8310030478* 8310030526 8310030527	50-400 50-400 50-400 50-400 PRM	0 0 9		8310110412# 8310110412# 8310120180 8310120180	50-400 G 50-400 G 50-400 E 50-400 E
	8310040224* 8310040262 8310040265* 8310040297 8310040304*	50-400 50-261 50-261 PR 50-324	o e e		8310120266 8310120266 8310120266 8310120300 8310120300	50-400 F 50-400 F 50-400 F 50-325 S 50-400 S
	8310040362 8310040363 8310040360 8310040365 8310040365	50-324 TDPREP 50-324 50-324 50-324	ន ទ ទ ទ		8310120367 8310120407 8310120426 8310130124 8310130124	50-324 R 50-324 R
	831004036B* 831004036B* 8310040412 8310040473 831004047B	50-324 50-324 50-325 50-261 50-261	6 6 6		8310130240 8310130273 8310130274 8310140013	# 50-400 E # 50-400 E 50-325 B
	8310040516 8310040538 8310040538 8310040541 8310040541		8 9 0		8310140126 831017054 831017054 831017054	50-325 8 50-261 8 50-400 0
	8310040582 8310040593 8310040600 8310040600 8310040603	50-400	ន ទ ប ប ប		,831017059 831017060 831017060 831017060	A 50-324 8 8* 50-400 6 8* 50-400 6
	8310040603 8310040606 8310060036 8310060036 8310060054	50-400 50-400 50-400	0 9 8 8		831017068 831017065 831017065 831018017	10* 50-400 0 10* 50-400 0 14 50-261 P
	9310060054 9310060066 9310060075 9310060186	* 50-324 * 50-324 50-324	2 2 2 2		93101803 93101804 93101804 93101804	27 50-324 F 27 50-324 F 74 50-400 E
	831009050; 831009050; 831009014; 831009018;	3# 50-400 3# 50-400 3# 50-400 3# 50-400	0		83101901 83101901 83101902 83102000 83102000	71 50-400 8 27 50-325 8 38 50-324 8
	831004021 831004021 831004022 831004022 831004023	9 50-325 2+ 50-400 2+ 50-400 7 50-324	8 0 0 8		83102001 83102001 83102001 83102001	43 50-324 0 165 50-324 0 168* 50-324 0 206 50-324 P
	831004023 831004032 831004032 831004033	8# 50-400 3 50-400 3 50-400 6 50-400) 0 0 0 0 8		8310210 8310210 8310210	024 50-400 £ 024 50-400 £ 046 50-261 P 048* 50-261 P
	831006033 83100604 83100604 83100604 83100605	3 50-32 3 50-26 8# 50-26 1* 50-32	4 8 1 P 1 P 4 F		8310510 8310510 8310510 8310510	134 50-400 F 1245 50-261 P 1246* 50-261 P 1244 50-324 P 1244 50-324 P
	83100405 83100405 83100701 83100701 83100701	57* 50-32 20 50-40 20 50-40	4 F 0 A 0 A		8310216 8310216 8310246	0268# 50-324 P 0268# 50-324 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGR	
	8310240183 8310250034 8310250034 8310250120 8310250211*	50-400 50-324 50-324 50-324 50-400	е Р Р	Chemical Waste Management, Inc Chiepetta, Welch & Associates, Ltd Christa-Maria	8310250680 8310120319+ 8310120024+ 8310040545 8310040620	WASTE MO 50-277 CONTRACT 50-155 50-155	R
	8310250237 8310250396 8310250450 8310250450	50-324 50-324 50-400 50-400	5 R R	Cincinnati Alliance for Responsible Energy	8310040621# 8310040624# 8310260016	50-155 50-155 FOIA	Ť
	8310250460* 8310250480*	50-324 50-324	a a	Cincinnati Gas & Electric Co	8310040336 8310040341*	50-358 50-358	F F
	8310250521 8310250571 8310250571 8310250594*	50-325 50-261 50-261 50-261	8 0 0 0		8310040457 8310110267 8310110286 8310120252 8310120304	50~358 50~358 50~358 50~358 50~358	K G Q A A
	8310250408* 8310250638 8310250438 8310260134 8310260134	50-261 50-400 50-400 50-400 50-400	G E E E		8310120383 8310120442 8310130237* 8310130242 8310140136*	50-358 50-358 50-358 50-358 50-358	8 8
	8310260141 8310260141 8310260145* 8310260145*	50-324 50-324 50-324 50-324 50-400	P P P E		8310170348 8310170404 8310170448 8310170454* 8310170485	50-358 50-358 50-358 50-358 50-358	888888
	B310240147 B310240148* B310240148* B310240152 B310240152	50-400 50-324 50-324 50-400 50-400	E P P E E .		8310170515 8310170518* 8310170649 8310180276 8310200083	50-358 50-358 50-358 50-358 50-358	A A 9 9 9
	8310260259 8310260259 8310280014 8310280014 8310280051	50-400 50-400 50-400 50-400 50-400	E E G		B310200078 B310200207 B310200212* B310200213* B310200222*	50-358 50-358 50-358 50-358 50-358	8 A A A
	8310280051 8310280164 8310280164 8310310027 8310310032*	50-400 50-400 50-400 50-261 50-261	6 0 0 P P		8310200227* 8310200230* 8310200234* 8310210110* 8310210113*	50-358 50-358 50-358 50-358 50-358	A A G
Center for Law in the Public Interest	8310310146 8310040212* 8310040537 8310050421 8310110058	50-400 50-275 50-275 50-275 50-275	0 0 0 0		8310210153 8310240161 8310250366 8310250487 8310250586*	50-358 50-358 50-358 50-358 50-358	9 9 9 9
	8310110058 8310110127 8310110127 8310110317 8310130243	50-275 50-275 50-275 50-275 50-275	6 9 9	Cincinnati, OH Citizens Association for Sound Energy	6310240098 6310250109 8310040230 6310120414 6310180163*	50-358 50-358 50-445 50-445 50-445	0 H 0 0 0
	8310180160 8310180160 8310180248 8310180248 8310210228	50-275 50-275 50-275 50-275 50-275	0 0 0 T		8310180337 8310180337 8310180342* 8310180342* 8310280057	50-445 50-445 50-445 50-445 50-445	0000
	B31021022B B310210242* B310210242*	50-275 50-275 50-275	T T T	Citizens Concerned About Nuclear Power, Inc	8310260249	50-498	c
	631024015B 6310250043	50-275 50-275	0 0	Citizens Engaged in Removal of Toxic	8310260269 8310170052	50-498 FOIA	0
	8310240236 8310260236 8310260277	50-275 50-275 50-275	ф 0 0	Bubstances, Inc. Citizens for Bafe Energy Claveland Electric Illuminating Co,	8310190321 8310040227	FO1A 50-440	E
	8310270358 8310270358 8310280097 8310280097	50-275 50-275 50-275 50-275	0		8310040227 8310040229* 8310040231* 8310040231* 8310040234*	50-440 50-440 50-440 50-440 50-440	E E E E
Contraria Inc	8310310141 8310310141	50-275 50-275	0		8310040234*	50-440	E
Centronic, Inc Chackes & Hoare Chamlin, Schottland, Rosen, Cavanagh &	8310180541 8310040225 8310270527	XPORTLIC 50-483 50-217	, e 8		8310040404 8310040404 8310050520 8310060340	50-440 50-440 50-440 50-440	9895
Charlevoix, MI	8310050494* 8310050501* 8310050507*	50-155 50-155 50-155	9		8310060340 8310060392 8310060392	50-440 50-440 50-440	8 8
Chem-Nuclear Systems, Inc.	831014007&* 8310140078* 8310170192 8310170195* 8310170232	50-155 50-155 71-9105 71-9105 71-6697	T T		8310120286 8310120286 8310170469 8310170613 8310200238	50-440 50-440 50-440 70-2968 50-440	8 8 8
	8310170748 8310170750#	71-6601 71-6601			8310240112 8310240165	50-440 50-440	8
	8310170730# 8310170332 8310170351	71-5801 71-5805 71-6771			8310250483 8310270030	50-441 50-440	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Made and a control of the control of	8310270030 8310270038 8310270232 8310270252 8310270252	50-440 TOPREP 50-440 50-440 50-440	8 6 6		8310120427 8310120427 8310120427 8310120427 8310120433	50-454 50-454 50-454 50-454 50-373	E E P
Cleveland-Cliffs Iron Co Coalition for Safe Power	8310310050 8310310050 8310310378 8310240052 8310040200	50-440 50-440 50-440 40-8714 50-460	A A G		8310120433 8310130132 8310140045 8310140049* 8310140057	50-373 50-374 50-373 50-10 50-373	P G G
Colorado. State of Combustion Engineering. Inc	8310310063 8310130066 8310040357* 8310040115* 8310070274	50-317 WASTE M 50-317 CONTRAC 50-470	P		8310140069 8310140073 8310140104* 8310140133 8310140175*	50-373 50-373 50-10 50-254 50-295	s 0 0
	8310130109* 8310180027 8310180031* 8310190192 8310190215	50-368 70-1100 70-1100 70-1100 70-1100	Þ		8310140256 8310140263 8310170234 8310170271 8310170337	50-304 50-373 71-9010 50-254 50-237	8 8 9
	8310200245* 8310240313 8310250135 8310250158 8310260160*	50-317 XPORTL I XPORTL I XPORTL I 50-528	3		8310170337 8310170337 8310170346 8310170346 8310170353	50-237 50-237 50-454 50-454 50-254	0 0 0 8
Commerce: Dept of, National Bureau of Standards Commerce: Dept of, Nati Oceanographic	8310310287* 8310110089*	70-1100 CONTRAC			8310170353 8310170356* 8310170356* 8310170411	50-254 50-454 50-454 50-454 50-454	R G ទ ទ
Atmospheric Administration	8310120369 8310120374*	50-29 50-29	P P		8310170411 8310170411 8310170411	50-454 50-454	5 5
Committee to Bridge the Cap Commonwealth Edison Co	8310190035 831003034* 8310030311	FOIA 50-373 PR	F		8310170411 8310170426 8310170491	50-454 50-374 50-254	8 8
	8310040136# 8310040162# 8310040260# 8310040320	50-10 50-456 50-454 50-237	F G G P F		8310170545 8310170553 8310170557 8310170561 8310170573	50-254 50-237 50-304 50-295 50-454	P 8 8 8
	8310040444 8310040444 8310040471	50-373 50-373 50-237	F P		9310170573 9310170573 9310170573	50~454 50-454 50-454	ន ឆ ន
	8310040554 8310040554 8310040554 8310040554 8310040554	50-454 50-454 50-454 50-454 50-454	K K K K		9310170573 9310170579 9310170589	50-454 50-304 50-275	8 8
	831006018A 8310060198 8310060249 8310060271	50-373 50-373 50-265 50-373	8 8 9 5		8310170607 8310170661 8310170671* 8310170711*	50-304 50-265 50-454 50-373	8 6 7
	8310060314 8310060317 8310060319 8310060321*	50-454 50-454 50-454 50-454	G G G		8310170718 8310180109 8310180110 8310180110 8310180249	70-2973 50-254 50-295 50-295 50-373	R Q Q K
	B310060321* B310060373 B310060545* B310060545*	50-454 50-237 50-254 50-254	0 8 F F		8310180252 8310180243 8310180243 8310180273	50-456 50-254 50-254 50-373	C R R S
	8310110117 8310110117 8310110123*	50-295 50-295 50-373	P P F		8310180275 8310180275 8310180279* 8310180279*	50-454 50-454 50-454 50-454	0 0 0
	8310110302 8310110302 8310110304* 8310110304*	50-456 50-456 50-456 50-456	c c c		8310180281 8310180281 8310180351*	50-373 50-373 50-454	₽ P C
	8310110327* 8310110327* 8310110464* 8310110478*	50-254 50-254 FOIA 50-237	F B		8310180351* 8310180397 8310180397 8310180397	50-456 50-373 50-373 50-373	P P
	8310120061 8310120108 8310120108 8310120109	50-245 50-275 50-275 50-273	Q R R		8310190258 8310200082* 8310200082* 8310200151	50~295	4444
	8310120159 8310120174 8310120189	50-254 50-295 50-237	5 8 8		8310200273 8310200273 8310200273	50-237 50-237 50-237	P P
	8310120219 8310120219 8310120273	50-456 50-456 50-237	E R		8310200273 8310200273 8310200424*	50-237 50-237 50-373	P F
	8310120273 8310120270 8310120401* 8310120407 8310120427	50-237 50-373 50-454 50-245 50-454	8 0 0 0 E		8310210014 8310210054 8310210054 8310210127 8310210145	50-245 50-245 50-374 50-237 50-249	8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESION NUMBER	BUBJEC	
	8310210218 8310210222 8310210234 8310210234 8310210236*	50-304 50-373 50-454 50-454 50-454	8 4 4 F		8310120368* 8310120377* 8310120377* 8310180132 8310180132	50-352 50-352 50-352 50-352 50-352	9 9
	8310210236* 8310210236* 8310210297 8310210313 8310210377*	50~454 50~454 50~237 50~237 50~275	ድ 8 8		8310180137# 8310180139# 8310180146# 8310180146# 8310180234	50-352 50-352 50-352 50-352 50-352	00000
	8310240067 8310240071 8310240077* 8310250293 8310250293	50-329 50-10 50-456 50-254 50-254	Q Q P P		8310180234 8310180237* 8310180237* 8310180243 8310180243	50 -352 50 -352 50 -352 50 -352 50 -352	0000
	8310250298* 8310250298* 8310250298* 8310250298* 8310250302*	50-254 50-254 50-254 50-254 50-254	P P P P	Consolidated Edison Co of New York, Inc	8310210153 8310270381 8310310231 8310040228 8310120194	50-358 50-354 50-352 50-247 50-247	000 F
	8310250302* 8310250361* 8310260001 8310270017* 8310270017*	50-254 50-373 50-10 50-10 50-10	Р С Р Г		8310120242 8310120243* 8310120297 8310120366 8310130111	50-247 50-247 50-247 50-247 50-3	P P P
	8310270017* 8310270028* 8310270028* 8310270032*	50-10 50-254 50-254 50-254 50-254	ቮ F F F		8310130111 8310130115* 8310130115* 8310130117*	50-3 50-3 50-3 50-3 50-3	# P P P
	8310270188 8310270267 8310270274 8310270276 8310270287	50-454 50-373 50-373 50-373 50-295	8 8 8 8		8310170163 8310260304 8310270126 8310280074 8310280261#	50-247 50-3 F01A 50-247 50-3	8 F 8 F
	8310270400 8310270404 8310270419 8310270424 8310270477	50-254 50-254 50-265 50-249 50-249	8 8 8 8	Consumers Power Co	8310280267* 8309090259 8310030465 8310040122 8310040264	50-3 50-329 50-329 50-329 50-155	F S A P
	8310270470 8310270537* 8310280209* 8310280215* 8310280314*	50-373 50-10 50-10 50-373 50-10	년 년 년		8310040266# 8310040365 8310040367# 8310040369# 8310040373#	50-155 50-155 50-155 50-155 50-155	P T T T
community Legal Services, Inc	8310310049 8310310054 8310310054 8310310060 8310260273	50-275 50-254 50-254 50-275 50-352	P P P P G		8310040376 8310040381* 8310040505 8310040519* 8310040548	50-155 50-155 50-155 50-155 50-155	T T T T
ionex Corp ionnecticut Yankee Atomic Power Co	8310180431* 8310040334 8310050431 8310060262* 8310120270	9A999 PR PR 50-213 PR	F		8310040551 8310040553 8310040557* 8310040560* 8310040544*	50-155 50-155 50-155 50-155 50-155	T T T T
	8310120375 8310180344 8310180407 8310190007 8310250315	50-213 50-213 50-213 50-213 50-213	P P R B		8310040548 8310040574 8310040611* 8310050276 8310050276	50-155 50-155 50-155 50-329 50-329	T T A A
jonner & Wetterh≥hn	8310250321 8310270021* 8310280313* 8310040627 8310050515	50-213 50-213 50-213 50-352 50-352	8 F F O O		8310050322 8310050322 8310050463 8310050465* 8310050469*	50-327 50-327 50-255 50-255 50-255	A P P
	8310110208 8310110216* 8310110267 8310110275 8310110275	50-358 50-358 50-358 50-352 50-352	0 0 0 0		8310050483 8310050486* 8310050489* 8310050491* 8310050494*	50-155 50-155 50-155 50-155 50-155	00000
	8310110277* 8310110277* 8310110284* 8310110284* 8310110286	50-352 50-352 50-352 50-352 50-358	0 0 0 0		8310050501* 8310050507* 8310060024 8310060030* 8310060047	50-155 50-155 50-155 50-155 50-255	9 9 9 9
	8310110287* 8310110287* 8310110297* 8310110297* 8310110305	50-352 50-352 50-352 50-352 50-352	0 0 0		8310040080 8310040221 8310070142 8310070142 8310070177	50-155 50-255 50-329 50-329 50-255	P 8 A A P
	8310110312* 8310110312* 8310120364 8310120364 8310120368*	50-352 50-352 50-352 50-352 50-352	0 0 0	•	8310110024* 8310110045 8310110043 8310110257* 8310110293*	50-155 50-155 50-155 50-155 50-155	F 0 F T

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE!		AUTHOR AFFILIATION	ACCESSION	SUBJECT CATEGOR	
	8310110310 8310120064 8310120110 8310120211 8310120215	50-329 50-255 50-155 50-155 50-155	6 9 9 1 1		8310250250 8310250462 8310250507# 8310250507# 8310260118	50-255 50-255 50-329 50-329 50-155	9 8 A F
	8310120218* 8310120221* 8310120225* 8310120227*	50-155 50-155 50-155 50-155 50-155	ፐ r ፓ ፓ		8310240202 8310240207* 8310240207* 8310240207*	50-400 50-400 50-400 50-400 50-329	@ @ @ A
	8310120249 8310120254 8310120318 8310120320 8310120327*	50-255 50-255 50-255 50-329 50-155	5 ? G A		8310240331 8310270044 8310270044 8310270142 8310270171*	50-329 50-329 50-329 50-255 50-329	A A 8 0
	8310120331 8310120365 8310130174 8310130179* 8310130214	50-255 50-155 50-155 50-155 50-155	5 0 T 7 †		8310270174* 8310270219 8310270221* 8310270245 8310270245	50-327 50-155 50-155 50-155 50-327	0 P 8 8
	8310130218* 8310130296 8310140074 8310140076* 8310140078*	50-155 50-155 50-155 50-155 50-155	1 P 1 T		8310270352* 8310270510* 8310270510* 8310270510* 8310270573*	50-329 50-155 50-155 50-155 50-155	G F F F
	8310140273* 8310140273* 8310170257 8310170257 8310170351	50-329 50-329 50-329 50-329 50-255	A A A A S		8310270593* 8310270593* 8310270593* 8310270597* 8310270597*	50-155 50-155 50-155 50-155 50-155	1 1 1 1 1
	8310170420 8310170421 8310170439* 8310170465 8310170486	50-155 50-329 50-329 50-155 50-155	6 8 8 8		8310280073 8310280073 8310280078* 8310310078 8310310078	50-327 50-327 50-327 50-327 50-327	9 9 R R
	8310170552 8310170714 8310170714 8310180222 8310180224*	50-155 50-329 50-329 50-155 50-155	8 A A G		8310310137 8310310145 8310310206 8310310366 8310310366	50-155 50-155 50-155 50-327 50-327	0 9 0 A
	8310180230 8310180335 8310180348 8310180464 8310180629*	50-155 50-155 50-155 50-255 50-329	0 0 F 0		8310310369 8310310367 8310310376 8310310379* 8310310383*	50~329 50-329 50-155 50-155 50-155	А Р Р
	8310170048 8310170048 8310200225 8310200254 8310200254	50-329 50-329 50-309 50-329 50-329	0 0 0 0	Control Data Corp Coordinating Agency for Supplier Evaluation (CASE Assoc)	8310310391 8310180299* 8310270038 8310270055*	50155 GA999 TOPREP TOPREP	G
	8310200254 8310200265 8310200245 8310200417* 8310200423*	50-255 50-329 50-329 50-155 50-155	Q A A F	Critical Mass Energy Project Cumberland County, PA D'Appolonia Consulting Engineers, Inc Daityland Power Cooperative	8206140403* 8310130219 8310120225* 8310130299* 8310050101 8310130311*	FOIA 50-289 50-155 50-155 50-407 50-409	H P P F
	8310210027 8310210027 8310240023 8310240023	50-329 50-329 50-329 50-329 50-329	A A A A		8310170159 8310170364 8310190027 8310210002 8310310163*	50~407 50~407 50~407 50~407 50~407	8 8 8
	8310240029 8310240033 8310240033 8310240050 8310240050	50-327 50-327 50-329 50-329 50-329	A A A A	Dataflow Systems, Inc Dauphin County, PA DeKalb Area Alliance for Responsible Energy	8310280137* 8310120171 8310040205	CONTRACT 50-320 50-454	H
	8310240063 8310240084 8310240128 8310240131 8310240132#	50-329 50-329 50-155 50-329 50-155	A Q A Q	Debevoise & Liberman	8310200077 8310210217* 8310030406 8310040008 8310060316 8310110068	50-454 50-454 50-413 PR 50-445 50-491	0 0 0
	8310240136 8310240172 8310240172 8310250041 8310250053	50-329 50-329 50-329 50-329 50-329	A 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		8310110322 8310110360 8310140022 8310140066 8310140086 8310170412	50-445 FOIA 50-445 50-508 50-508 50-445	G T G O
	8310250053 8310250058 8310250058 8310250073	50-329 50-329 50-329 50-329	ā A A Q		9310170412 9310170417* 9310170417* 9310190158	50-445 50-445 50-445 50-445	0000
	8310250101 8310250101 8310250101 8310250203* 8310250203*	50-329 50-329 50-329 50-255 50-255	6 8 8 9		8310210184 8310270085 8310280126 8310310175	50-445 FOIA 50-508 50-508	9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEQU	
Debevoise & Plimpton Decatur, Al Defense, Dept of, Defense Nuclear Agency Del Research Corp Delaware, State of	8310120034* 8310030420* 8310210413* 8310050335 8310250038	50-201 CONTRAC 50-170 NUREG 50-272	I F 0		8310110141+ 8310110274 8310110274 8310110418+ 8310110421+	50-269 50-413 50-413 50-369 50-369	F 0 F F
Detroit Edison Co	8310120078 8310120190 8310120311* 8310120018 8310130229	50-341 50-341 50-341 50-341 50-341	A G E		8310120413 8310140143 8310140159 8310140205 8310140205	50-369 50-269 50-269 50-369 50-369	B P P P
	8310170574* 8310170600* 8310180034* 8310180037* 8310180042*	50-341 50-341 50-341 50-341 50-341	Х 5 F F		8310140207* 8310140207* 8310140253 8310140253 8310140253	50-369 50-369 50-269 50-269 50-269	P P P
	8310180470 9310200107 8310210052 8310210066 8310210281	50-341 50-341 50-341 50-341 50-341	A H A B		8310170248 8310170334 8310170384 8310170430 8310170536	50-369 71-9039 50-369 50-269	9 8 8
Doc-8earch Associates Doherty, J F	8310250114 8310270447 8310270469 8310040481 8310110202	50-341 50-341 FOIA 50-293 50-443	ន ទ e		8310180100 8310180100 8310180167 8310180444 8310180444	50-369 50-369 50-269 50-269 50-269	R R F F
Don L. Warner, Inc	8310110202 8310110314 8310110316 8310240242 8310270030	50-443 50-443 50-443 50-443 70-820	G G G		8310180444 8310180444 8310180444 8310190165 8310190165	50-269 50-269 50-269 50-413 50-413	# F F E
Dorsey, J A Dougherty, J B Dou Chemical Co Drexel Univ , Philadelphia, PA	8310040498 8310200105 8310110097* 8310110125* 8308310512*	50-352 50-322 FOIA FOIA 50-267	a a		8310170173 8310170173 8310170262 8310170262 8310210005	50-413 50-413 50-413 50-413 50-369	8 E E
Duke Power Co	8310030396 8310030406 8310030409* 8310030409*	PR 50-413 50-413 50-413	G G G		8310210028 8310210077 8310210111 8310210111 8310210177	50-369 50-370 50-413 50-413 50-413	6 6 6 8
	8310030423 8310040016 8310040287 8310040319* 8310040368	50-287 50-419 50-419 50-419 50-969	9 E F G		8310210179 8310210186 8310210186 8310210192* 8310210192*	50-413 50-413 50-413 50-413	A T T T
	8310040403 8310040474 8310040474 8310040482* 8310040482*	50-370 50-369 50-369 50-369 50-369	9 P P		8310210308 8310210307 8310210312 8310240014* 8310240017*	50-369 50-369 50-369 50-413 50-413	13 J T T
	8310040492# 8310040492# 8310040492# 8310040575 8310040575	50-267 50-269 50-269 50-269 50-269	tr a a a		8310240016* 8310240030* 8310240030* 8310240038* 8310240038*	50-413 50-413 50-413 50-413 50-413	† † † † †
	8310040575 8310040599 8310040038 8310040038 8310040052	50-269 50-413 50-413 50-413 50-413	0 0 8 8 8		8310240040* 8310240040* 8310240043* 8310240043* 8310240047*	50-413 50-413 50-413 50-413	T T T T
	8310060052 8310060058 8310060058 8310060063* 8310060068*	50-413 50-369 50-369 50-369 50-369	8 8 8 8		8310240047* 8310240047* 8310240047* 8310240053* 8310240053*	50-413 50-413 50-413 50-413	T T T T
	6310040255 8310040248* 8310040275 8310040310 8310040310	50-370 50-349 50-413 50-413 50-413	8 F O T		8310240055# 8310240055# 8310240056# 8310240056# 8310240057#	50-413 50-413 50-413 50-413 50-413	T T T
	8310060384 8310060426 8310070131# 8310070143# 8310070152#	50-369 50-269 50-370 50-269 50-269	다 다 당		8310240057# 8310240058# 8310240058# 8310240059# 8310240057#	50-413 50-413 50-413 50-413 50-413	Υ Υ Τ Τ Τ
	8310070152* 8310110048 8310110074* 8310110074* 9310110074*	50-269 50-491 50-269 50-269 50-269	F G F F F		8310240060* 8310240060* 8310240061* 8310240062* 8310240065*	50-413 50-413 50-413 50-413	ቸ ተ ተ ተ
	8310110077* 8310110079* 8310110080* 8310110080*	50-249 50-249 50-249 50-349	F F F F		B310240065* B310240068* B310240068* B310240073* B310240073*	50-413 50-413 50-413 50-413 50-413	T T T T

AUTHÜR AFF ILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310240076* 8310240076* 8310240151 8310250071 8310250074	50-413 50-413 50-269 50-369 50-369	Ť P S	Eberline Instrument Corp Eddleman, W	8310310067* 8310310068* 8310060412 8310250658 8310030367	50~250 P 50~250 P XPORTLIC XPORTLIC 50~400 G
	8310250074 8310250076* 8310250080* 8310250524* 8310250665*	50-369 50-369 50-369 50-369 50-269	5 5 0 0		8310030367 8310030369* 8310030369* 8310030372* 8310030372*	50-400 G 50-400 G 50-400 G 50-400 G
	B31027004B B310270079 B310270136* B310270146* B310270173	50-370 50-249 50-369 50-369 50-369	8 0 F 5		8310030375* 8310030375* 8310030377* 8310030377* 8310030380*	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G
	8310270209 8310270310 8310270412 8310270482 8310270482	50-370 50-370 50-269 50-413 50-413	ធ ធ ធ ធ ធ		8310030380* 8310040518 8310040523 8310120370 8310140072	50-400 G 50-400 G 50-400 G 50-400 G
	8310280029 8310280029 8310280029 8310280096 8310280105	50-269 50-269 50-269 50-413 50-269	F E E P		8310250037 8310250037 8310250040 8310250040 8310250086	50-400 G 50-400 G 50-400 G 50-400 G
	8310280105 8310280105 8310280124 8310310416 8310310416	50-269 50-269 50-269 50-369 50-369	Р Р Г Г	Edgar, G L Edlow International Co	8310250086 8310270351 8310260272 8310060070 8310060130	50-400 G 50-400 G 50-537 G XPORTLIC XPORTLIC
Duquesne Light Co	8310030350* 8310040400 8310040411* 8310040551 8310040569*	50-412 50-334 50-334 50-334 50-334	Q Q Q F F		8310180095 8310180113 8310180542 8310180545* 8310240301	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8310120257 8310140208 8310180322* 8310180432 8310180434*	50-334 50-334 50-334 50-334 50-334	P F Q F F	Electric Power Research Institute Energy Incorporated	8310240302* 8310030650 8310180118 8310210198* 8306030372*	XPORTLIC TOPREP NUREG CONTRACT 50-286 P
	8010170019 8310210208 8310210240* 8310240146 8310250546	50-334 50-334 50-334 50-334 50-334	Р Р Б		8306080055* 8306080065* 8306080106* 8306080112* 8306130456*	50-312 P 50-336 P 50-302 P 50-272 P 50-346 P
	8310250595 8310270154 8310280010 8310310062 8310310089	50-334 50-334 50-334 50-412 50-412	8 8 8 K A	Energy, Dept of	8310030605 8310030610* 8310110624 8310110626* 8310130008	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT
EDB Nuclear, Inc	8310310307 8310180481* 8310180485* 8310180493* 8310180497*	50-412 50-387 50-387 50-387 50-387	F P P		8310130067 8310130071* 8310170027 8310170139 8310170170	WASTE MOT WASTE MOT 71-9070 WASTE MOT 71-5595
	8310180498* 8310180501* 8310180504* 8310180507* 8310180510*	50-387 50-387 50-387 50-387 50-387	무 우 무 무		8310170175* 8310170306 8310170398 8310170342 8310170739	71-5595 71-6550 WASTE MOT 71-4909 71-6400
	8310180514# 8310180518# 8310180520# 8310180523# 8310180525#	50-397 50-387 50-387 50-387 50-397	ե ե ե Ն		8310170744 8310180138 8310190335 8310240233 8310240255	71-5939 40-8768 71-5895 Waste Mot Waste Mot
E 949 , Inc	8310040123* 8310030331 8310030335 8310250570* 8310310346*	50-395 NUREQ NUREQ 50-409 50-275	P G		8310240271* 8310250075 8310250102 8310250107* 8310250147	WASTE MOT WASTE MOT WASTE MOT WASTE MOT ORO
ENBA, Inc. EGE, Inc. Ead Metallurgical, Inc. Earth Beiences Associates	8310310354* 8310060191* 8310120233* 8310200422 8310070205*	50-275 CONTRACT 50-155 71-6144 CONTRACT	Т		8310250416 8310250416 8310250423* 8310250423* 8310250591	50-275 G 50-275 G 50-275 G 50-275 G 50-312 P
East-West Technology Corp Ebasco Services, Inc (subs of Enserch Corp)	8310040383* 8310040237*	0A999 50-382	o		8310250591 8310250591	50-312 P 50-312 P
Í t	8310040245* 8310060238* 8310070285	50-382 50-400 MISC	0		8310280292 8310280076 8310280283	50-537 G Waste Mgt Waste Mgt
	8310130291* 8310170221 8310170230* 8310170325*	50-400 71-9027 50-335 50-335	E F	Energy, Dept of, Clinch River Breeder Reactor Plant Engineers International, Inc	8310280295* 8310310182 8310310059 8310170047*	WASTE MOT WASTE MOT 50-597 A CONTRACT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Environmental Congress of Mid-Michigan Environmental Protection Agency Essex Corp	8310110520 8310060406# 8310170697# 8310240126 8310240145#	FOIA 50-313 COMMISS 50-261 50-354	P	Florida Power Corp	8310280082 8310280153 8310310015 8310310070+ 8310040301	50-335 P 50-335 P 50-335 P 50-250 P 50-302 P
European Communities, Commission of	8310060415 8310060420 8310060424	XPORTLIC	:		8310040420 8310040463	50-302 F
Evanston Hosp Evanston, IL Exxon Corp	8310110567 8310260357	XPORTL10 FOIA 40-8064	•		8310040472* 8310070306 8310070307	50-302 G 50-302 S 50-302 S
Exxon Nuclear Co . Inc (subs of Exxon Corp)	B310050346 B310050470*	TOPREP 50~255	_		8310120191 8310120301	50-302 P 50-302 B
	8310030470# 8310070260 8310120357# 8310120415#	TOPREP 70-1257 50-261	P P		8310120387 8310130136 8310140079	50-302 P 50-302 P
	8310120422* 8310130208 8310140237 8310140244* 8310170233	50-261 70-1257 TOPREP TOPREP 70-1257	P		8310140080* 8310140123 8310140187 8310140233 8310140243	50-302 P 50-302 8 50-302 B 50-302 B 50-302 R
Falkenheiner, D Federal Emergency Management Agency	8310170236* 8310210139 8310280346 8310280183 8310040510	70-1257 TOPREP PR 50-458 50-443	A G		8310140266* 8310140268* 8310170519 8310180436 8310180473	50-302 R 50-302 R 50-302 B 50-302 P 50-302 P
	8310050548 8310050552* 8310050554* 8310170500 8310250401*	50-3 50-3 50-3 50-322 50-315	ቦ F G F	Florida State Univ Florida, Univ of, Gainesville, FL	8310210021 8310250374* 8310250458 8310050239 8310110366*	50-302 8 50-302 0 50-302 0 NUREQ 50-83 F
Fisher Controls Co Florida International Univ Florida Power & Light Co	8310270237 8310260237* 8310060512* 8310030254	50-322 50-277 CONTRACT 50-389	0 Р 5	Foley, Moag & Eliot Foxboro Corp Franklin Institute/Franklin Research Center	8310180157* 8310110365 8310070301 8104070444*	CONTRACT 50-438 Q 50-10 B 50-206 P
	8310030262	50-251	B	Ganvar	8210010087*	50-272 P
	8310030398 8310030448 8310040145 8310040334 8310060492*	50-389 50-389 50-250 PR 50-335	8 5 F		8212010152* 8301210240* 8304140513* 8304140402* 8307200240*	50-344 P 50-244 P 50-324 P 50-302 P 50-334 P
	8310060494* 8310070250 8310070253* 8310110138 8310110296	50-335 50-389 50-389 50-250 50-250	F F G G P		8307250463* 8308030016* 8308030382* 8308180560* 8308300317*	50-313 P 50-295 Q 50-315 Q 50-346 P 50-213 P
	8310130009 8310130125 8310130153 8310130154* 8310130157*	50-335 50-250 50-389 50-389 50-389	P Q Q Q		8308310512* 8307020372* 8307060263* 8307160203* 8307200506*	50-267 Q 50-277 P 50-315 P 50-266 Q 50-267 Q
	8310140217 8310170222 8310170224* 8310170240 8310170240	50-389 50-335 50-335 50-250 50-250	8 F F F	Future Resources Associates. Inc QA Technologies: Inc /General Atomic Co	8310210097# 8310070240* 8310060177 8310130270 8310130274*	CONTRACT CONTRACT XPORTLIC 71-6346 71-6346
	8310180208 8310180208 8310180211* 8310180211* 8310180254	50-335 50-335 50-335 50-335 50-335	թ թ թ	QQ Noell OmbH Qambit	8310170064 8310180319 8310250393 8310200462* 8310110040	71-6346 50-89 P PR CONTRACT 50-382 Q
	8310180324 8310180327# 8310180327# 8310180327# 8310180359	50-250 50-250 50-250 50-250 50-250	የ የ የ	General Electric Co.	8310040026 8310040330 8310030185 8310070264 8310070281	50-219 P QEN TEC IB TOPREP 50-237 P TOPREP
	8310180389 8310180381 8310180381 8310190023 8310190104	50-250 50-250 50-250 50-250 50-389	9 q q R 8		8310070310 8310110503* 8310110513* 8310130225 8310130228*	TOPREP FOIA FOIA 70-1113 70-1113
	8310210223 8310240140 8310250039 8310250060 8310250337	50-251 50-335 50-389 50-389 50-389	8 9 8		8310130369 8310130371 8310170061 8310170155 8310170158*	XFORTLIC XFORTLIC 70-1113 70-1113 70-1113
	8310250431* 8310250437* 8310270053* 8310270047* 8310270120	50-250 50-250 50-387 50-387 50-335	q q F F		8310170249 8310170540 8310180074 8310180085 8310180112	70-1113 TOPREP NURE9 NURE9 XPORTLIC
	9310270211 9310270249 8310270277 8310270354*	50-389 50-250 50-251 50-251	ቦ ዌ ዌ		8310180119 8310180310 8310180527* 8310180528*	NUREG XPORTLIC GA979 GA979

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATE	GORY		THOR IATION	ACCESSION NUMBER	SUBJECT CATEODS	
	83101805320 8310180557 83101805809 8310240311 8310250427	XPDRTL	LIC LIC			B310250430 B310250434 B310250476 B310250552 B310250587	50-289 50-320 50-320 50-289 50-289	8 9 9
	8310250357 8310260009 8310260015 8310260106 8310260206	REGOD XPORTL XPORTL 50-447 50-447	LTC 7 K			8310250606 8310250629 8310260143 8310270125* 8310270130	50-287 50-320 50-287 50-287 50-287	ន ទ F F
General Motors Corp	8310260211* 8310260307* 8310310209 8310260068 8310260073*		.1C			8310270158* 8310270396* 8310280102 8310280108 8310280115*	50-219 50-289 50-320 50-269 50-289	0 F P P
Ceneral Physics Corp General Public Utilities — GPU Bervice Corp	9310070434 9310170283 9310030103	NUREQ NUREQ 50-287	р	Organia Rayer Co		8310280116* 8310280123 8310310164* 8310310410 8310030247	WASTE MG 50-287 50-320 50-287 50-321	9T 0 0 P 8
	8310030376 8310030500 8310030055 8310030041# 8310050334# 8310060370	PR 50-320 50-320 50-320 50-289 50-289	P P	Georgia Pawer Co		8310030304 8310030318 8310030319 8310030334 8310030339	50-321 50-366 50-366 50-366 50-366	ងងងងង
	8310040531* 8310070076 8310070082* 8310070263 8310070309	50-287 50-287 50-287 50-287 50-289 50-287	F P P 8			8310030382 8310030410 8310030415 8310030433 8310030442	50-366 50-321 50-366 50-366 50-366	8888
	8310110054 8310110106# 8310110200 8310110217 8310120125	50-289 50-320 50-289 50-219 50-289	0 F Р			6310030481 8310030486 8310030510 8310040366# 8310040409	50-321 50-366 50-366 50-321 50-366	8 9 9
	8310120125 8310120350 8310130005 8310130064 8310130082	50-289 50-289 50-320 50-320 50-320	ft ft p p			8310040524 8310040011 8310070279 8310070280* 8310070287	50-321 50-364 50-321 50-321 50-321	93 P P P
	8310130088 8310130093* 8310130099* 8310130114 8310130138	50-320 50-320 50-320 50-287 50-320	ե ե ե ե			8310070287 8310110124 8310120265 8310120265 8310120276	50-321 50-321 50-321 50-321 50-424	P P P 8
	8310130141# 8310140108 8310140251 8310170007# 8310170335	50-320 50-287 50-287 50-289 50-219	Р R Р F			8310120408 8310140014 8310140144 8310140241 8310170183	50-366 50-321 50-321 50-321 50-366	8 8 8 8
	8310170605 8310170639 8310170647+ 8310180099* 8310180200	71-9111 50-320 50-320 50-289 50-320	р Р Р			8310170397 8310170509 8310170531 8310170566 8310170582	50-321 50-366 50-366 50-484 50-321	9999
	8310180347 8310180347 8310180372* 8310180537 8310180548*	50-289 50-289 50-289 50-320 50-320	P G P P			8310170584 8310170743* 8310170746* 8310190014 8310190125	50-344 50-321 50-321 50-321 50-424	S F R A
	8310190031 8310190060 8310190075 8310190161 8310190164	50-219 50-320 50-320 50-289 50-289	R S S S S			8310190125 8310190126* 8310190126* 8310210270 8310210270	50-424 50-424 50-424 50-321 50-321	A A P P
	8310190173 8310190205 8310190328 8310200008 8310200011	50-320 50-320 71-9010 50-289 50-289	# S			8310210277* 8310210277* 8310210279* 8310210279* 8310250041	50-321 50-321 50-321 50-321 50-366	5 6 6
	8310200061 8310200075 8310200155 8310200161 8310200430*	50-287 50-320 50-320 50-217 50-287	5 5 5 5 5			8310250212 8310250285 8310250291 8310250311 8310250312	50-366 50-364 50-366 50-366 50-366	8 8 8 8
	8310200443# 8310210037 8310210085 8310210283* 8310210390*	50-289 50-289 50-289 50-289	F R P G F			8310250343 8310250506 8310270315 8310270327 8310270334*	50-366 50-366 50-424 50-366 50-366	5 6 P
•	8310250253 8310250261 8310250274 8310250317	50-289 50-289 50-289 50-320	6 P 8			8310310234 8310310257 8310310265 8310310280 8310310297	50-366 50-366 50-366 50-366 50-321	88 88

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOORY
Germany, Federal Republic of Gesellschaft fuer Nuklear Service, mbH	8310310308 8310310363 8205140143* 8310130334 8310130336*	50-321 50-366 FDIA PROJ PROJ	P 9		8310070319 8310130183 8310130210 8310130215 8310130254	50-458 A 50-458 B 50-458 S 50-458 B
Getty/Petrotomics Co Gilbert/Commonwealth Cos Global Weather Dynamics, Inc	8310260348 8310260352* 8310270543 8310140080* 8310270107*	40-6659 40-6659 40-6659 50-302 FOIA	p		8310130258 8310130322 8310180267 8310180303 8310180305	50-458 8 50-458 8 50-458 8 50-458 8 50-458 8
Qalder Associates	B310270110* B310050545* B310060127* B310060506* B310120035*	FOIA CONTRAC CONTRAC CONTRAC	r r		8310180460 8310180461 8310210147 8310210175 8310210201	50-458 8 50-458 9 50-458 9 50-458 9
Goodson & Associates, Inc Gould, Inc	8310130201* 8310280322* 8310130418* 8310070163 8310210255	CONTRACT 40-1341 CONTRACT 50-245 50-438			8310210221 8310210221 8310210242 8310270181 8310280011	50-458 A 50-458 A 50-458 B 50-458 E 50-458 S
Goulds Pumps, Inc Government Accountability Project	8310130248# 8310130254# 8310060245 8310060259# 8310060266#	50-400 50-400 50-358 50-358 50-358	E E G G		8310280030 8310280053 8310280084 8310280117 8310280199*	50-458 B 50-458 B 50-458 B 50-458 B
	8310060269 8310060269 8310060291* 8310060291* 8310110071	50-329 50-329 50-329 50-329 50-329	G G G	HHB, Dept of, UB Public Health Service HMM Associates, Inc Hall, N Hanford Engineering Development Laboratory	8310070203* 8310030491* 8310030362* 8310260427	CONTRACT 50-155 G CONTRACT NUREG
	8310120101	50-327	0	Harmon & Weiss	8310070384*	COMMISSION
	8310120101 8310130370 8310170383 8310170383	50-329 50-329 50-329 50-329	G A G G		8310110158 8310110158 8310110145* 8310110145* 8310110170*	50-443 0 50-443 0 50-443 0 50-443 0
	8310170393 8310170393 8310170427 8310170427 8310170524	50-329 50-329 50-329 50-329 50-329	9 9 9 9		8310110170* 8310110175* 8310110175* 8310140191 8310180329	50-443 G 50-443 G 50-443 G 50-443 G
	8310170524 8310180436 8310180456 8310180465# 8310180618	50-329 50-329 50-329 50-329 50-329	G G G A	Harstead Engineering Associates, Inc	8310250046 8310310202 8310040573* 8310280004*	50-289 0 50-443 0 50-382 A 50-382 A
	8310190050 8310190050 8310190300 8310190311 8310240196	50-327 50-327 50-327 50-327 50-528	G G A A G	Hittman Muclear & Development Corp (subs of Hittman Corp)	8310050056# 8310050045# 8310050074# 8310170218	71-9080 71-9080 71-9090 71-9093
	8310240215* 8310270257 8310270257 8310270266* 8310270266*	50-528 50-329 50-329 50-329 50-329	e o o o	House of Rep House of Rep , Energy & Commerce House of Rep , Interior & Insular Affair:	8310170228 8310310430* 8310240241* 8310110354* 8310060594*	71-9092 71-9086 50-528 U COMMISSION 50-382 U
	0310270345	50-329	g		B310070380* B310200073*	COMMISSION 50-445 U
	8310280145 8310280145 8310280204 8310310390	50-327 50-329 50-338 50-329	9	House of Rep , Science & Technology Houston Lighting & Power Co.	8310200467* 8310240217* 8310110597* 8310030147	50-275 U 50-528 U COMMISSION 50-478 K
Oranada Data Systems, Inc Greater Reston Arts Center, Inc. Greely,CD Orundy Electric Cooperative, Inc	8310310370 8310180366 8310180559 8310110337* 8310040461*	50-329 FDIA FDIA CONTRACT 50-358	r K		8310030148* 8310030148* 8310030148* 8310030311	50-498 K 50-498 K 50-498 K PR 50-498 8
Guild, R Guilf & Wastern Industries, Inc	8308300480 8308300480 8308300484* 8308300486* 8310070359	50-413 50-413 50-413 50-413 TOPREP	0 0 0		8310040287 8310040410 8310130187 8310130187 8310130245	50-498 S 50-498 S 50-498 S 50-498 S
Guif Nuclear, Inc	8310130384	71-9140			8310130245 8310130319	50-498 S 50-498 S
Quif States Utilities Co	8310130386* 8310030226 8310030226	71-9140 50-458 50-458 50-458	A K K		8310130319 8310140110 8310140110 8310180290	50-498 8 50-498 V 50-498 V 50-498 9
	8310030232 8310030232 8310030547 8310040126 8310040130	50-458 50-458 50-458 50-458 50-458	C C B B	Human Performance Technologies,inc Hunton & Williams	8310210193 8310190313* 8310040630 8310060300 8310120119	50-478 8 FOIA 50-322 0 50-322 0 50-322 0
	8310040318 8310040496	50~458 50~458	8 8		8310140016	50-322 0
	8310040615# 8310060074 8310070319	50~458 50~458 50~458	A 8 A		8310170365 8310170409 8310190200	50-322 0 50-322 0 50-338 9

AUTHOR AFFILIATION	ACCESSION NUMBER	CATI	JECT ECORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	PRO
Xydro-Engineering	8310260279 8310310124 8310310128 8310180136 8310280178#	50-33 50-32 50-33 40-88	38 22 22 337	6	J	8310210215* 8310270172 8310270176* 8310270176* 8310270204	50-316 50-315	9 9 F
INFO/DOC INTERA Environmental Consultants, Inc Ichthyological Associates, Inc Illinois Power Co	8310200449 8310070200# 8310120128# 8309120437 8310040204		39 . 1	R E S	Indiana & Michigan Power Co	8310270213* 8310270223* 8310270226 8310270271* 8310310077*	50-315 50-315 50-315	5 5
	8310040238 8310060409* 8310110105 8310120077 9310120181	50-46 50-46 50-46 50-46	1 1	9 H B A	Intel Corp Interior, Dept of Interior, Dept of, Geological Survey	8310310680* 8310110497* 8310050464* 8310060010* 8310050391*	50~316 CONTRA CONTRA CONTRA CONTRA	CT CT CT
	8310120359 8310120441 8310140228	50-46 50-46 50-46	1 8	E 8	International Energy Associates, Ltd International Institute of Bafety & Health	8310070210* 8310110530	CONTRA 50-250	
	B310200201 8310200205*	50-46 50-46	1 1	Ř K	Nearth International Neutronics, Inc Intersyst, Ltd Iowa Electric Light & Power Co	8310170211 8310060138* 8310110036*	71~909 CONTRA 50~331	
Illinois, State of	8310210009 8310250619 8310270369* 8310270374* 8310120403	50-46 50-46 50-46 50-46 50-46	1 C 1 F 1 F	0 = =		8310110038* 8310110055* 8310110060* 8310120380 8310120400	50-331 50-331 50-331 50-331 50-331	. E E E
Illinois, Univ of, Urbana, IL	8310170356* 8310170678 8310250049 8310250051 8310060184*	30-454 40-206 27-39 27-39 27-39		•		8310120421 8310140254 8310170405 8310170490	50~331 155~03 16~03 16~03	S R R
Indian River Community College Indiana & Michigan Electric Co	8310070323 8310070148* 8310030386 8310030371 8310030879*	NUREQ CONTRA 50-315 50-315	} P	-		8310170581 8310180178 8310180424 8310170048 8310200182	50-331 50-331 50-331 50-331	R P R P
	8310030579* 8310050563 8310050547* 8310060006 8310060329*	50-315 50-315 50-315 50-315 50-315	P P	•	,	8310200186* 8310250481 8310250481 8310250467* 8310250470* 8310270015*	50~331 50~331 50~331 50~331 50~331 50~331	H H 88 89 4
1	8310050369 8310050479* 8310110434* 8310120188 8310120193	50-315 50-315 50-315 50-314 50-314	F F S		Towa State Univ , Ames, IA	8310270019* 8310270290 8310270459 8310030093 8310030100*	50-331 50-331 50-331 50-114 50-114	F 8 0 P P
	8310120197 8310120234 8310120260 8310120343 8310120379	50-315 50-315 50-315 50-316	8 8 8		Isham, Lincolπ & Beale	8310030123 8310030465 8310030465 8310040365 8310040376	50-114 50-329 50-329 50-155 50-155	F 0 0 T
	8310120443 8310120445* 8310120448* 8310120447* 8310140027	50-316 50-316 50-316 50-316 50-315	8 8 8 8			8310040467 8310040467 8310040505 8310040548 8310040551	50-329 50-329 50-155 50-155 50-155	G G T T
	B310140040 B310140040 B310140084 B310140137 B310140138#	50-315 50-315 50-315 50-316 50-316	888			8310040553 8310040594 8310050483 8310050486* 8310060314	50-155 50-155 50-155 50-155 50-454	T T G G
	8310140139# 8310140140# 8310140141# 8310170357 8310170387	50-316 50-316 50-315 50-315	8 8 8			8310040317 8310040317 8310040321* 8310110045 8310110043	50-454 50-454 50-454 50-155	g g T
	8310170387 8310170607 8310170611* 8310170619* 8310190064	50-315 50-316 50-316 50-316 50-316	9 8 8 R			8310110310 8310120211 8310120365 8310130174	50-155 50-155 50-155 50-155	G T G T
	8310190070 8310200158 8310200158 8310210036 8310210040	50-315 50-315 50-315 50-315 50-315	9 9			8310130214 8310140074 8310170346 8310170420 8310180222	50-155 50-155 50-454 50-155 50-155	T Q Q
	8310210137 8310210187 8310210191*	50-315 50-316 50-315 50-315 50-315	8 8 8			8310180230 8310180275 8310180275 8310180279* 83101802395	50-155 50-454 50-454 50-454	0 0000
	8310210202* 8310210206	50-315 50-315 50-315 50-316	8 8 8 8 8			8310180348 8310190048 8310200225 8310200254	50-155 50-155 50-327 50-307 50-327	0000

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	HΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOD	
	8310240128 6310240132* 6310240172 8310260073 6310310139	50-155 50-155 50-327 50-329 50-155	0 0 0 6	Kansas State Univ Kansas, Univ of, Lawrence, KG Kastenberg, H E	8310130090 8310170738* 8310210237 8310210239* 8310040326*	50-188 50-148 50-148 50-148 CONTRACT	R F F
JBF Associates Jacobs Engineering Group, Inc	8310310145 8310310206 8310310391 8310070220* 8310310451	30-155 50-155 30-155 CONTRAC		Kensington, NK Kentucky. Commonwealth of, Kerr-McGwe Chemical Corp (subs of Kerr-McGwe Corp)	8310140021 8310270370 8310120314	50~443 50~358 40~2061	H
Jacobson, P.J. Jamesbury Corp Japan, Govt of	8310240167 8310130282* 8310060180 8310180304 8310180307	HASTE M FOIA SO-400 XPORTLI XPORTLI XPORTLI	E C	Kerr-McGee Corp	8310180392 8310250662 8310310362* 8310120310 8310180038 8310260377	40-2061 40-2061 40-2061 40-2061 40-8027 40-8768	
Jersey Central Power & Light Co Johnson Controls, Inc	8310110399* 8310180548* 8310180401* 8310180404* 8310180404*	50-219 50-320 GA999 GA999 GA999	F	Kilcoyne, J J Kirkpatrick, Lockhart, Hill, Christopher & Phillips	8310260411 8310270298 8310030456	40-8769 50-289 50-322	0
Joint Applicants-Bouth Texas Project Joint Intervenors-Callaway Joint Intervenors-Diablo Canyon	8310180407* 8310110220 8310040225 8310040212*	QA999 50-498 50-483 50-275	0 0		8310040199 8310040618 8310050416 8310190056 8310190209	50-322 50-322 50-322 50-322 50-322	900 00
	8310040212* 8310040539 8310040539 8310050421 8310110058	50-275 50-275 50-275 50-275 50-275	0 0 0	Koch Industries, Inc LaBargo, Inc	8310200217 8310200242 8310240160 8310170007 8310170293	50-322 50-322 50-322 TOPREP 71-9032	000
	8310110127 8310110127 8310110317 8310110317	50-275 50-275 50-275 50-275 50-275	G G G G	Labor. Dopt of	8310110192* 8310210155* 8310200048* 8310240209* 8310070110	CONTRACT CONTRACT COMMISSI FOIA NUREQ	•
	8310130243 8310180140 8310180140 8310180248 8310180248	50-275 50-275 50-275 50-275 50-275	0 0 0	Laurence Livermore Laboratory	8306030372* 8306080065* 8306080106*	50-286 50-336 50-302 50-346	P P P
	8310210228 8310210228 8310210241* 8310210241*	50-275 50-275 50-275 50-275	T T T		8310050534* 8310040212* 8310070133 8310110032	50-237 50-400 50-312 NUREG	P Q P
	8310210242* 8310210242* 8310240158 8310240158	50-275 50-275 50-275 50-275	T T G		8310250152* 8310250600* 8310250625* 8310250625* 8310250631*	080 50-312 50-312 50-312 50-312	ր 9 9
	8310250043 8310250043 8310260236 8310260236 8310260237	50-275 50-275 50-275 50-275 50-275	000	LeBoeuf. Lamb, Leiby & MacRae	8310250431* 8310050245 8310050298 8310110182 8310170589	50-312 50-265 50-265 50-267 50-341	P P P C K
	8310270358 8310270358 8310270361# 8310270361#	50-275 50-275 50-275 50-275	000	League of Women Voters of Hockford, IL	8310200024 8310280169 8310040205 8310140067 8310140067	50-289 50-289 50-454 50-454 50-454	P P Q Q Q
Justice. Dept of	8310280097 8310280097 8310310141 8310310141	50-275 50-275 50-275 50-275	0 0 0	Lehigh Univ . Bethlehum, PA	8310140070* 8310140070* 8310310127 8310130165*	50-454 50-454 50-434 CONTRACT	000
K-C industries, Inc KBI Corp. KMC, Inc. Kansas Qas & Electric Co	8310060162 8310060135 8310030311 8310030364	XPORTLIC XPORTLIC PR PR 50-482		Lewis, M	8310030355 8310030355 8310040491 8310270258 8310270258	MISC PR 50-352 50-352 50-352	900
	8310130192 8310130223 8310130231 8310170644	50-482 50-482 50-482 70-2960	8 8 8		8310270356+ 8310270356+ 8310270362+ 8310270362+ 8310270368+	50-352 50-352 50-352 50-352 50-352	9 0000
	8310180171 8310180256 8310180317 8310180321#	70-2740 50-482 50-482 50-482 50-482	8 8 8	Limerick Ecology Action Limitorque Corp	8310270368* 8310040498 8310140071 8310130261* 8310130273*	50-352 50-352 50-352 50-400 50-400	0 00 E
	8310180325* 8310180387 8310210100* 8310210108	50-482 50-482 70-2960 70-2960 50-482	8	Long Island Lighting Co	9310180314* 9310180324* 9310040630 9310060300 9310120119	94799 94799 94799 94799	0
	8310210244 8310210415* 8310250034 8310250084 8310250133	50-482 50-482 50-482 50-482 50-482	S F G A		9310120121# 9310120264 9310140016 9310140231	50-322 50-322 50-322 50-322 50-322	OO EGE

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEO DR	
	8310170365 8310190003 8310190209 8310200262 8310240168	50-323 50-323 50-323 50-323	2 A 2 G 2 G		8310710208* 8310210274* 8310250063 8310250280 8310250584	50-309 50-309 50-309 50-309 50-309	0 0 9
	8310270237 8310310124 8310310128 8310310133* 8310310224*		2 G 2 G	Maine. State of	8310270042* 8310270200 8310270208* 8310270216* 8310040337	50-309 50-309 50-309 50-309 50-309	F F F P
Los Alemos Scientific Laboratory Louis P Canuso, Inc.	8310310454+ 8310200344 8310200387 8310250604+ 8310250616+	RES NUR EQ	9 8	Manhattan College, Riverdale, NY Mark Technologies Corp	8310180380* 8310180383* 8310260335* 8310260335* 8310260340*	50-199 50-199 50-329 50-329 50-329	Q Q A A A
Louisiana Consumer's teague, înc Louisiana Power & Light Co	8310280183 8310030060 8310030063* 8310030067* 8310030259	50-458 50-382 50-382 50-382	K K K	Marotta Scientífic Controls,Inc	8310260340* 8310260344* 8310260344* 8310260036 8310260042*	50-529 50-329 50-329 XPORTLIC XPORTLIC	
	8310030368 8310030368 8310030468 8310030507 8310030540	50-382 50-382 50-382 50-382 50-382	8	Marsh & McLennan, Inc.	8310030301 8310140130 8310140260 8310240026 8310240117	50-321 50-390 50-302 50-29 50-315	どしている
	8310040134 8310040233 8310040239* 8310040245* 8310040372	50-382 50-382 50-382 50-382 50-382	83 G G A	Maryland, Univ of, College Park, MD Massachusetts Institute of Technology, Cambridge, MA	8310240148 8310270461 8310040258 8310140118 8310050370*		JJFV
	8310040512 8310040559 8310040565+ 8310040233 8310040357	50-382 50-382 50-382 50-382 50-382	S A K F	Hassachusetts. Commonwealth of	8310070435* 8310130216 8310180105* 8310040256 8310040256	CONTRACT 50-443	F
	8310070001 8310070235 8310070247 8310110280 8310120072	50-362 50-362 50-362 50-362 50-362	H A Q E		8310040262* 8310040262* 8310040272* 8310040272* 8310040277*	50-443 50-443 50-443	00000
	8310130266* 8310170398 8310170409 8310170569	50-382 50-382 50-322 50-382	9 9 9		8310040277* 8310060364* 8310110152 8310120147 8310120147	50-443 50-443 50-443	9099
	8310170151 8310170212 8310210258 8310210270	50-382 50-382 50-382 50-382	8 8 8 8		8310120151* 8310120151* 8310180368 8310180368 8310180373*	50-443 50-443 50-443	999
	8310250496 8310280002 8310280012 8310280069 8310310091	50-382 50-382 50-382 50-382 50-382	E A S B	Meterials Engineering Associates, Inc Maxima Corp	8310180373* 8310250056 8310280088 8310070217* 8310050369*	50-443	Q Q U
	8310310195 8310310292 8310310300 8310310315 8310310367	50-382 50-382 50-382 50-382 50-382	9 8 9 9	McGraw-Hill Publications Co Memphis State Univ , Memphis, TN Mentor, KY Marcer Medical Center Trenton,NJ	8310180175* 8310270508 8310030341 8310190146 8310310418*	CONTRACT FOIA PR	G
Lowenstein, Neuman, Reis, Axelrad & Tolk	8310110220 8310120418 8310180354 8310180354 8310180361#	50-498 50-275 50-275 50-275 50-275	Q Q T T T	Metals Testing Co , Inc Metropolitan Edison Co	8310170322 8310030351 8310030403 8310040392 8310110205	71-137 50-289 50-289 50-289	0000
Taskaslasu T	8310180361# 8310180369# 8310180369# 8310180375# 8310180375#	50-275 50-275 50-275 50-275 50-275	T T T T		8310110224 8310110272 8310120375 8310180355 8310180548*	50-289 50-289 50-289 50-289	0000P
Technology Inc Technical Associates .aren Enginers: Inc. ne Yankee Atomic Power Co.	8310070289# 6310200178 6310280322# 8310030283 8310040616	50-528 50-275 40-1341 PR 50-309	Ħ T		8310200211 8310210148 8310210200 8310210249 8310240166	50-287 50-287 50-320 50-289	
	8310070159 8310070202 8310110066* 8310110069* 8310120165	50-309 50-309 50-309 50-309 50-309	P F F F B	Mismi Valley Power Project	6310240184 6310310198 6310310382 6310060245 6310060266*	50-289 (50-289 (50-289 (50-358 (0000
	8310170168* 8310190033 8310190231 8310200108 8310210194*	50-309 50-309 50-309 50-309 50-309	G R B S G	Michigan, Univ of, Ann Arbor, MI Middle Island, NY Midland County, MI	8310140039 8310260217 8310070231*	50-155 (G H

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFIL IATION	ACCESSION NUMBER	8UBJECT CATEGORY	Y
Minneapolis, MN	8310070117*	CONTRACT	 r		8310310044	50-416	P
Mississippi Power & Light Co	8309040068	50-416	8		8310310159	50-416	ø
	8307070416 8310030296	50-416 50-416	8	Missouri Joint Municipal Electric Utility	8310310130* 8310280146	50-416 50-483	Q M
	8310030317	50-416	8	Commission			
	8310030325	50-414	s	Missouri, Oniv or, Columbia, Mo	B310170308	40-8801	
	831003036 4 8310030373	PR 50-414	8		8310190347 8310200409	50-184 40-8801	F
	8310030373	50-414	8		6310110099	50-123	V
	8310030374	50-416	8		8310110110#	50-123	Ÿ
	8310030430	50-416	8		#310110113+	50-123	•
	8310030438 8310030472	50-416 50-416	8 8	Mitsvi & Co (USA), Inc. (subs of Mitsui & Co., Ltd)	8310120455	XPORTLIC	
	B310030490	50-416	5		8310180151	XPORTLIC	
	8310040364	50~416	6		8310180155* 8310130399	XPORTLIC	
	8310040417	50-416	s	Mitsuiline Travel Bervice of America: Inc	6310130344	XPORTLIC	
	8310040001 8310040002	50-416 50-416	S		B310130422	XPORTLIC	
	8310040025	50-416	s	Malycorp, Inc.	8310070087	40-8794	
	8310060115	50-416	8		8310070092* 8310060060	40-8794 XPORTLIC	
	8310060227	50~416	P		######################################	XPORTL IC	
	B310060401 B31007016 9	50-416 50-416	s		8310120292*	70-572	
	8310070170	50-416	g		8310180403	40-6500	
	8310070192	50-416	8		8310060493*	CONTRACT	
	8310070239	50-416	8	Morris, IL NUS Corp	8310060496# 8310030561	71-9151	
	8310070305 8310120281	50-416	8	·	B310030568*	71-9151	
	B310120347	50-416 50-416	P F		8310030574*	71-9151	
	8310120349	50-416	F		B310040381*	50-155	Т
	8310120419	50-416	8		8310110001 8310110005	FOIA FOIA	
	8310120436	30-416	P		8310110432	FOIA	
	8310120438* 8310120444	50-416 50-416	P		B310130011*	WASTE NO	т
	8310120444	50-416	P		8310130129#	50~528	Ą
	8310130117	50-416	p		8310180582 8310190046	50-445 FOIA	A
	8310130121*	50-416	P		8310190088	FOIA	
	8310140007 8310140051	50-417 50-416	9		8310210324	FOIA	
	8310140061	50-416	8		8310240233	FOIA	
	8310140075	50-416	8		8310250024 8310250031	FOIA FOIA	
	8310140075	50-416	5		B310270057	FOIA	
	8310140122 8310140140	50-416 50-416	8		8310270121	FOIA	
	8310140169	30-416	š		B310270255	50-275	p
	8310170400	50-414	ន		8310270340 8310270355	50-29 FOIA	9
	B310170408	50-416	8	NUBAC, Inc	8310070189*	CONTRACY	
	8310170458	50~416 50~416	9	SHATECEL Fredmanne, Inc	8310130232*	50-341	A
	8310170474 8310170512	50-416	В	NUTECH Engineers, Inc	B310140103*	50-352	2
	021010000	80.447	_	National Academy of Briences	8310070230*	CONTRACT	
	8310180304 8310180330	50-416 50-416	P E	National Council on Radiation Protection & Measurements	8310280104*	CONTRACT	
	8310180330	50-416	E	National Technical Bystems	8310250420*	GA999	
	8310180352 8310180352	50-416 50-416	P	Navy, Dept of	8310310273	PT21	
				Navy, Dept of, Naval Facilities Engrg	8310190187	MISC	
	8310180416 8310180430	PR 50-416	F	Command Navy: Dept of, Naval Research Lab	8310180557*	CONTRACT	
	8310180430	50-416	F	Navy, Dept of, Pearl Harbor Naval	8310170209	71-9033	
	8310170006 8310170037	50-416 50-416	R P	Shipyard	B310170215	71-9032	
			•				
	8310190098 8310190109	50-416 50-416	B	Nebraska Public Power District	B310170355 B31004034B	71-9128 50-298	a
	8310170111	50-416	8	Maniana Landate . One. Princistà	B310040574	50-298	Þ
	8310170232 8310170234	50-416 50-416	8		8310060376 8310060381*	50-278 50-278	8
	0010170234	20-418	-				
	9310190257	50-416	8		8310110178 8310110183*	50-298 50-298	P
	8310210019 8310210182	50-414 50-414	S		B310140190	50-296	P
	8310210314	50-416	g		8310180471 8310190024	50-298 50-298	G R
	8310250262	50-416	G.				
	8310250389	50-416	Q.		B310200350 B310210174	50-298 50-298	F
	8310260186 8310260186	50-416 50-416	8		8310210302	50-278	F
	8310260220	50-416	P		8310310056* 8310310310	50-278 50-278	P
	8310260220	50-416	Р				
	8310260276 8310270037	50-414 50-414	P B	Nevada, State of New England Coalition on Nuclear	8310280107# 8310110158	HASTE MG 50-443	T Q
	8310270160	50-416	8	Pollution	6310110156	50-443	Q
	8310270167 8310270229	50-416 50-416	\$ B		831011015B 8310110165*	50-443 50-443	0
					8310110165*	50-443	0
	8310270235 8310270336	50-416 50-416	8 9		8310110170*	50-443	0
	8310270397	50-416	8		B310110170*	50-443	0
	8310270433 8310310044	50-416 50-416	9 P		8310110175* 8310110175*	50-443 50-443	0
			•				

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC)RY
New Hampshire. State of New Hampshire. Univ of,	8310140191 8310180329 8310310202 8310030397 8310270070	50-443 50-443 50-443 50-443 FOIA	G G		8310170190 8310170504 8310170563 8310170656 8310180336	50-423 50-245 50-423 50-245 50-245	A P A P 8
New Orleans, Univ of New York, State Univ of, Buffalo, NY New York, State of	8310130389* 8310140222 8310070271 8310120028* 8310120030*	50-57 State F 50-201	R		8310180409 8310180469 8310190015 8310190207 8310200187	50-213 50-245 50-245 50-336 50-336	무 위 위 위
	8310120036* 8310120039* 8310130385* 8310140027 8310240187		I I E F	Northeast Utilities Service Co	8310200229 8310250263 8310250577 8310040527* 8310170190	50-336 50-245 TOPREP 50-423 50-423	P S C A
News & Observer Niagara Mohauk Power Corp	8310250117* 8310280174 8310040597 8310040631 8310040149	State F 50~400 50~220 50~220 50~220	Prog A P P F	Northern States Power Co	8212150246* 8310040572 8310050422 8310060216 8310070238	FD1A 50-263 PR 50-263 50-263	P P V
	8310060361 8310120097 8310120205 8310120208* 8310120373	50-220 50-220 50-220 50-220	ե ե ե ե		8310070272 8310070311 8310070314* 8310070316* 8310110180*	50-263 50-263 50-263 50-263 50-263	8 P P F
	B310120406 8310120416* 8310140043 8310140111 8310140154	50-220 50-220 50-220 50-220 50-220	ቅ ያ R J		8310110184* 8310120102 8310120340 8310120432 8310170641	50~243 50~282 50~304 50~263 50~304	F 8 5 1 8
	8310140221 8310170153 8310170584 8310180098 8310180102*	50-220 50-410 50-220 50-220 50-220	F S P P		8310190021 8310190055 8310210257 8310250239 8310250288*	50~243 50~282 50~243 50~243 50~282	8 8 9 0
	8310190169 8310210171 8310270212* 8310270217* 8310280052	50-220 50-220 50-220 50-220 50-410	9 0 0	•	8310250288* 8310250561* 8310250561* 8310250561* 8310260435*	50-262 50-263 50-263 50-263 50-243	0 0 0 0 F
	8310310228 8310310228 8310310238* 8310310243* 8310310359	50-410 50-410 50-410 50-410 50-220	A K C K S		8310260438* 8310270283 8310270359* 8310270364* 8310270380*	50-263 50-263 50-263 50-263 50-266	F 5 5 5 5
Northeast Nuclear Energy Co (subs. of Northeast Utilities)	8310030335 8310030428 8310040161 8310040164* 8310040334	50-423 50-245 50-423 50-423 PR	A P K X		8310270390* 8310270410* 8310270414* 8310270415* 8310270418*	50-243 50-263 50-263 50-282 50-282	99999
	8310040521 8310050431 8310060035 8310060205 8310120259	50-423 PR 50-245 50-245 50-245	C F F	Norton. Burke, Berry & French	8310270421* 8310270425* 8310270427* 8310270427* 8310110120	50-282 50-282 50-304 50-275	9 8 8 8 G
	8310120259 8310120270 8310170504 8310170504 8310170508*	50-245 PR 50-245 50-245 50-245	F P P	Nuclear Assurance Corp	8310110298 8310110298 8310110301# 8310110301# 8310170087	50-275 50-275 50-275 50-275 50-266	0 0 F
	8310170508# 8310170563 8310170656 8310170656 8310170656	50-245 50-423 50-245 50-245 50-245	P A P	Nuclear Data, Inc Nuclear Fuel Bervices, Inc (subs of Getty Gil Co)	8310040309* 8310040309* 8310050473*	CONTRACT 70-143 70-143 70-143	ŕ
	8310180409 8310180469 8310190015 8310190207 8310200129	50-213 50-245 50-245 50-336 50-245	F P R R		8310050535* 8310070145* 8310120008* 8310120009* 8310120012* 8310120013*	70-143 70-143 50-201 50-201 50-201 50-201	I I I
	8310200167 8310200187 8310200229 8310200233* 8310230263	50-336 50-336 50-334 50-335 50-245	R P P 9		8310120014* 8310120020* 8310120028* 8310120044* 8310120047*	50-201 50-201 50-201 50-201 50-201	1 1 1
ortheast Utilities	8310030335 8310030428 8310040161 8310040334 8310040521	50-423 50-245 50-423 PR 50-423	A P K C		8310120207* 8310170036 8310170299 8310170680 8310170724	50-201 70-143 70-143 70-143 70-143	1
	8310050431 8310060035 8310060205 8310120270	PR 50-245 50-245 PR	F F		8310170737 8310170270 8310250340* 8310250500	70-143 70-143 70-143 70-143	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	<u> </u>
Nuclear Metals, Inc Nuclear Packaging, Inc	8310050516 8310170344 8310170349* 8310170285 8310170288*	40-672 71-9182 71-9182 71-9145 71-9145		8310030315* 8310110330* 8310120074 8310130308* 8310130307*	50-265 50-265 50-265	P G F F
NycLear System	8310200408 8310200415* 8310210331 8310210333* 8310170275	71-9184 71-9184 71-9181 71-9181 71-9126		8310180162 8310180506* 8310190324 8310210008 8310210370*	50-285 71-9080 50-285	R OI G F
g·Netll, J gj Corp pet. Toc	8309130169 8310110207 8310130249 8310270093	50-155 0 50-155 0 71-5908 FOIA	Online Computer Systems, Inc Organization for Economic Cooperation & Development (Paris) Our Lady of Lourdes Hosp , Camden, NJ	8310250567* 8310240286* 8310170182* 8310310425*	50-265 FDIA FOIA 70-2319	F
Dak Ridge National Laboratory	8310050217 8310070426 8310110023 8310170011 8310170243 8310240423	NUREG NUREG NUREG 40-84 NUREG NUREG	Pacific Gas & Electric Co	8310030384 8310030384 8310030376 8310040141 8310040251	50-275 50-275 PR 50-275 50-275	0 F 0
Office of Management & Budget	B310310191 B310110339 B310110341 B310110343 B310110344	NUREG ORG ORG ORG ORG		8310040251 8310040525 8310040525 8310040570 8310040578# 8310040585*	50-275 50-275 50-275 50-275 50-275 50-275	0 0000
ngle Petroleum, Inc Chia Citizens for Responsible Energy	8310110348 8310110349 8310180172 8310110425 8310120099	DRG ORG 40-8745 50-237 8 50-440 0		8310040571* 8310040578* 8310050374 8310050376	50-275 50-275 50-275 50-275 50-275	B 0 0 0 0
	8310180337 8310180337 8310170061 8310170061 8310200353	50-440		8310070236 8310110073 8310110073 8310110120 8310110120	50-275 50-275 50-275 50-275 50-275	F 0 0 0 0
Ohio State Univ , Columbus, QH Ohio. State of	8310270065 8310280071 8310210211* 8310040519* 8310170548	FOIA 50-361 S CONTRACT 50-155 T 50-358 R		8310110298 8310110298 8310110301* 8310110301* 8310120136	50-275 50-275 50-275 50-275 50-275	00008
Dhmart Corp	B202230210* B310260025* B310260067* B310260105* B310260107*	FOIA FOIA FOIA FOIA		8310120280 8310120362 8310120402 8310120404 8310170285	50-275 50-275 50-275 50-275 50-275	8 5 5 5 6
	8310260116* 8310260121* 8310260124* 8310260133*	FOIA FOIA FOIA FOIA		8310170471 8310170489 8310170489 8310170514 8310170517	50-323 50-275 50-275 50-275 50-275	A P P E E
	8310260136* 8310260146* 8310260147* 8310260158* 8310260157*	FOIA 70-1144 70-1144 FOIA FOIA		6310170545 8310170457 8310180193 8310180328 8310180328	50-275 50-275 50-244 50-275 50-275	F E P Q
	9310240143* 8310240149* 8310240170* 8310240172* 8310240173*	FOIA FOIA FOIA		6310180458 8310180463 8310190051 8310190063 8310190137	50-275 50-275 50-275 50-275 50-275	PERE
	8310260184* 8310260188* 8310260193* 8310260195* 9310260223*	FOIA FOIA		8310190197 8310190197 8310190219 8310190219 8310190260	50-275 50-275 50-275 50-275 50-133	P P Q O R
	8310240242* 8310240585* 8310240528* 8310240538*	FOIA FOIA FOIA		8310200131 8310200144 8310200183* 8310200260 8310210227	50-275 50-275 50-275 50-275 50-275	E F G P
	8310240300* 8310240303* 8310240321* 8310240347* 8310240359*	FOIA FOIA FOIA		8310210227 8310210233 8310210235# 8310210247 8310210284	50-275 50-275 50-275 50-275 50-275	P R R P R
	8310240364* 8310240374* 8310240384* 8310240388* 8310240398*	FOIA FOIA FOIA		8310210284 8310210288* 8310210288* 8310240174 8310240174	50-275 50-275 50-275 50-275 50-275	R R Q
Oklahoma State Univ. Dmaha Public Power District	8310140085 8310050255 8310050271 8310050278 8310050310	# 50-285 P # 50-285 P 50-285 P		8310250108 8310250115 8310250537 8310250637	50-275 50-275 50-275 50-275	8 8 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJ CATE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG	
	9310270263 9310270376 9310270572* 9310270575* 9310270575*	50-27	5 9 5 F		6310250217 6310250228 6310250242 6310250245 6310250246	50-387 50-387 50-387 50-387 50-387	9 8 8
	8310270580* 8310270580* 8310270586* 8310270586* 8310270588*	50-27 50-27	5 F 5 F		8310250252* 8310250258* 8310250246 8310250345 8310250386	50-387 50-387 50-387 50-387 50-387	P P S S
Pacific Nuclear Systems & Services, Inc	8310280048* 8310280057 8310280061 8310280067* 8310170291	50-275 50-275 50-275 50-275 71-915	3 T 5 F 6 Q		8310250402 8310250476 8310250555 8310250574 8310250622	50-387 50-387 50-387 50-387 50-387	9 9 9
Pacific Scientific Palmetto Alliance	8310120072 8310310135 8308300480 8308300480 8308300496*	50-489 PT21 50-413 50-413	: Q		8310270214 8310270214 8310270449 8310270453* 8310270457*	50-387 50-387 50-387 50-387 50-387	Н Н Р Р
	8309300486* 8310240021* 8310240021* 8310240022* 8310240022*	50-413 50-413 50-413 50-413	T T		8310280045 8310280045 8310280125 8310280130 8310280139	50~388 50~388 50~387 50~387 50~388	9 5 5 5
Palo Verde Intervention Fund Parameter, Inc	8310240024* 8310240177* 8310110580 8310170550* 8310180079	50-413 50-528 NUREO CONTRA NUREO	a	Pennsylvania, Commonwealth of,	8310280137 8310280135 8310310305 8310310305 8310030453	50-388 50-388 50-387 50-387 50-289	8 8 8
Pathfinder Mines Corp	8310200378 8310270606* 8308300607 8308300610* 8310030205	NURED CONTRA 40-662 40-662 40-225	2 2		8310040305 8310120042 8310140017 8310140071 8310180140	50-352 50-352 50-412 50-412 50-412	0 0 0
	8310030224 8310240003 8310240006# 8310240323 8310260323	40-662: 40-225: 40-225: XPORTL 40-225:	7 7 I C	Peper, Martín, Jensen, Maichel & Hetlage Perkins, Coie, Stone, Olsen & Williams Perry, CM Petroleum Measurement Corp	8310180420 8310130413 8310030390 8310040483* 8310030028	50-352 FDIA 50-522 CONTRAC 71-9163	
Patterson: Belinap, Webb & Tyler Pennsylvania Power & Light Co	8310200374 8310030396 8310040052 8310040421 8310040640	FOIA PR 50-388 50-388 50-388	A A A	Philadeiphia Electric Co	8309130054 8310030283 8310040124 8310040124 8310040189	50-352 PR 50-352 50-352 50-277	G A A P
	8310060211 8310060211 83100604863 8310060486* 8310060338*	50-387 50-387 50-387 50-387 50-387	ት ት ት		8310040187 8310040191* 8310040296 8310040415 8310040415	50-277 50-277 50-352 50-277 50-277	P A P P
	8310070160 8310070336 8310110094* 8310110197 8310120067	50-388 50-388 50-387 50-388	A E F R		8310040429* 8310040431 8310040431 8310040434 8310040627	50-277 50-352 50-352 50-277 50-352	P A A F O
	8310120080 8310120105 8310120144 8310120175 8310130207	50-388 50-388 50-388 50-388 50-387	A A A P		8310040627 8310050437 8310050437 8310050515 8310050515	50-352 50-352 50-352 50-352 50-352	G K G G
	8310130213# 8310140056 8310140077 8310140114 8310140155	50-367 50-366 50-368 50-367 50-367	P G A P		8310070243 8310070243 8310110132 8310110132 8310110275	50-352 50-352 50-352 50-352 50-352	A E E Q
	8310140156* 8310170145 8310170148* 8310180166 8310180356*	50-387 50-388 50-388 50-388 50-387	P A A G		8310110275 8310110277* 8310110277* 8310110284* 8310110284*	50-352 50-352 50-352 50-352 50-352	0000
	8310180426 8310180426 8310180437 8310180454 8310180480	50-387 50-387 50-388 50-388 50-387	P P A A P		8310110287# 8310110287# 8310110271 8310110271 8310110272#	50-352 50-352 50-352 50-352 50-352	00000
	8310180507 8310190080 8310190120 8310190145 8310190230	50-387 50-387 50-387 50-387 50-387	P 8 8		8310110292* 8310110297* 8310110297* 8310110300* 8310110300*	50-352 50-352 50-352 50-352 50-352	0 0 0 0
	9310200271 9310210292 9310250106	50-387 50-387 50-388 50-387 50-387	8 8 A P 8		8310110305 8310110305 8310110307* 8310110312* 8310110312*	50-352 50-352 50-352 50-352 50-352	0000

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	
	8310120148 8310120148 8310120313 8310120364 8310120364	50-352 50-352 50-277 50-352 50-352	A R G		8310110194* 8310110201* 8310120247* 8310130104* 8310140244	50-344 50-344 50-344 50-344 50-344	р О Б
	8310120348* 8310120348* 8310120377* 8310120377* 8310120384*	50-352 50-352 50-352 50-352 50-352	© G G G		8310140257 8310180417 8310190037 8310200188 8310200192*	50-344 50-514 50-344 50-344 50-344	J R P P
	8310120384* 8310120388* 8310120388* 8310120392 8310120392	50-352 50-352 50-352 50-352 50-352	E G G		8310200198+ 8310250444 8310260237 8310260242+ 8310260246+	50-344 50-344 50-344 50-344 50-344	ն 6 8
	8310140093 8310140093 8310140097 8310140097 8310140101*	50-352 50-352 50-352 50-352 50-352	A A A	Power Authority of the State of New York	B310270521* B310310299 B310310301* B310040291 B310060089	50-344 50-344 50-344 PR 50-333	F P P
	8310140101* 8310140197 8310140197 8310140203 8310140278	50-352 50-352 50-352 50-277 50-352	A A Q A		8310070248 8310070340 8310070349 8310110112 8310110222	50-286 50-286 50-286 50-333 50-286	У Р Р Р
	8310140278 8310170225 8310180132 8310180132 8310180137*	50-352 70-2988 50-352 50-352 50-352	A G G G		9310110228* 9310110231* 9310120435 9310130113 9310140176	50-286 50-286 50-333 50-333	P P R Q P
	8310180137* 8310180146* 8310180146* 8310180152* 8310180234	50~352 50~352 50~352 50~352 50~352	0 0 0 0		8310170480 8310170533 8310170554 8310170603 8310170655#	50-333 50-333 50-286 50-286 50-333	0 F B F
	8310180234 8310180237* 8310180237* 8310180243 8310180243	50-352 50-352 50-352 50-352 50-352	G G G		8310170659* 8310190082 8310190150 8310190202 8310190213	50-333 50-333 50-333 50-286 50-333	F 8 8
	8310180423 8310200137 8310200172* 8310200196* 8310200257	50-352 50-278 50-277 50-277 50-277	C B G R		8310200134 8310210126 8310210129* 8310240114 8310240155	50-333 50-333 50-333 50-286 50-286	8 F P F
	8310200257 8310200261* 8310200261* 8310200263* 8310200264*	50-277 50-277 50-277 50-277 50-277	R R R R		8310250296 8310250412 8310250565 8310250614 8310270126	50-333 50-333 50-333 50-333 F01A	8 8
	8310250035 8310250279 8310250382 8310250419 8310260212	50-352 50-278 50-277 50-277 50-277	X S S Q P		8310280044 8310280054* 8310310043 8310310046* 8310310058*	50-333 50-333 50-333 50-333 50-333	F
	8310280013 8310280013 8310280127 8310280257* 8310280271*	50-352 50-352 50-352 50-277 50-277	8 6 F F	President of UB & Executive Offices	8310310066 8310310203 8310310364 8310070043# 8310280146#	50-284 50-333 50-333 COMMIBS 50-322	P S G IDN U
Philadelphia, PA Phosnis Associates, Inc Phoenix International	8310310064* 8310310231 8310170058 8310170118* 8310130406*	50-278 50-352 50-352 CONTRACT CONTRACT		Pro-Tech Support Services.Inc Process Technology, Inc Professional Reactor Operator Society Project Hanagement Corp. Public Interest Research Group, New York	8310180584 8310250399* 8310250339 8310260292 8310120299	50-508 GA799 PR 50-537 PR	н
Phoenix, AZ Planning Research Corp	8310130407# 8310050467# 8310110391# 8310110393# 8310110395#	CONTRACT CONTRACT FOIA FOIA FOIA		Public Service Co of Calorado	8310040169 8310040207 8310040210 8310040276 8310040315	50-247 50-247 50-247 50-247 50-247	0 8 0 8
Pjateau Resources, Ltd	8310110400* 8310110414* 8310110419* 8310070402 8310180104	FOIA FOIA FOIA 40-7869 40-8698			8310040322* 8310040324* 8310040325 8310040328* 8310110236*	50-267 50-267 50-267 50-267 50-267	9 4 8 4
Plymouth, MA Portland General Electric Co	8310180129 8310180133 8310110340* 8310030341 8310030364	40-8698 40-8674 CONTRACT PR PR			8310130193 8310130200* 8310130204* 8310130236 8310130260	50-267 50-267 50-267 50-267 50-267	р О Р
	8310040079 8310040258 8310040241* 8310040471 8310110187	50-344 50-344 50-344 50-344 50-344	F F F P		8310130272 8310130275* 8310130279* 8310130281 8310130284*	50-267 50-267 50-267 50-267 50-267	P P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8310130286 8310130300 8310130303* 8310130304* 8310130324*	50-267 50-267 50-267 50-267	7 P 7 P 7 P		B310210195 B310210195 B310210285 B310210285 B310240143	50-272 50-272 50-272 50-272 50-272	F F P F
Public Barvice Co of Indiana, Inc	8310130328* 8310170260 8310210253 8310030283 8310040428	50-267 50-267 50-267 PR 50-346	P P		8310250215 8310250238 8310250244 8310250257 8310250325	50-354 50-272 50-311 50-272 50-272	A B S V
	8310040428 8310040337 8310040337 8310170530 8310210025	50-546 50-546 50-546 50-547 50-546	. s		8310250390 8310250407 8310250470 8310250567 8310280024	50-272 50-311 50-311 50-311 50-272	8 8 8
	8310240081 ± 8310270393 8310270458 8310270458	50-546 50-546 50-546 50-546 50-546	5 5		8310280075 8310280093 8310280101 8310280119 8310280122*	50-354 50-354 50-354 50-311 50-311	ន ទ e e
Public Service Co of New Hampshire	8310030341 8310040343 8310110083 8310110083 8310110092#	PR 50-443 50-443 50-443 50-443	G G	Purdue Research Foundation	8310310225 8310310229* 8310030390 8310190326* 8310190329*	50-311 50-311 50-522 FOIA FOIA	G G
	8310120263 8310120133 8310120133 8310120363	50-443 50-443 50-443 50-443 50-443	G G A A	Radiation Management Corp Raytheon Corp	8310280131 8310060079 8310120316* 8310110020 8310120420	RES 70~143 50-277 FOIA 50~463	R G
	8310120428 8310120428 8310180150 8310180150 8310180153#	50-443 50-443 50-443 50-443 50-443	0000	Remote Technology Corp Rensselzer Polytechnic Inst , Troy, NY	8310240238* 8310110549* 8310110121 8310110122* 8310170281*	FOIA CONTRACT 50-225 90-225 CONTRACT	P
	8310180153* 8310180145 8310180145 8310180170* 8310180170*	50-443 50-443 50-443 50-443 50-443	0 0 0	Reuter-Stakes, Inc Richland, WA	8310200051 8310200055* 8310260022 8310070237* 8310260397	50-225 50-225 XPORTLIC CONTRACT NUREG	
	8310200247 8310200247 8310200277 8310200277 8310210250+	50-443 50-443 50-443 50-443 50-443	6 6 6	Robert Charles Moles & Associates Robert L. Cloud Associates, Inc	8310040502 8310110528* 8310210087* 8208010014* 8310040509	40-8084 CONTRACT CONTRACT 50-275 50-275	
	8310260201* 8310260254 8310260254 8310260261* 8310260261*	50-443 50-443 50-443 50-443 50-443	A 0 0 0		8310040515# 8310070086 8310070071# 8310070094 8310070100#	50-275 50-275 50-275 50-275 50-275	R R R R
Public Bervice Electric & Qas Co of New Jersey	8310260266# 8310260272# 8310260272# 8310260272# 8309190260	50-443 50-443 50-443 50-443 50-272	0 0 0 F		8310070151 8310070155# 8310070208 8310070212# 8310070215	50-275 50-275 50-275 50-275 50-275	R R R R
	8307170260 8310030346 8310030346 8310030484 8310030157	50-272 50-272 50-272 50-354 50-272	F R Q		8310070227* 8310070251 8310070257* 8310120078 8310140117	50-275 50-275 50-275 50-275 50-275	R R P R
	8310050159 8310050164* 8310050164* 8310050174* 8310060325	50-272 50-272 50-272 50-272 50-311	թ թ թ	Robert Shaw Controls Co	8310140119* 8310280157 8310250510* 8310250525* 8310140121	50-275 50-275 GA999 GA999 50-275	R P
	8310060327 8310060328* 831007003 8310070166 8310180114	50-311 50-311 50-272 50-272 50-311	P P P R		8310180192 8310190032 8310250217 8310250305 8310270084*	50-244 50-244 50-244 50-244 50-244	P R S S
	8310180251 8310180251 8310180253* 8310180253* 8310180398*	50-272 50-272 50-272 50-272 50-272	к к к ф	Rochester Post-Bulletin, Rochester, MN	8310270074* 8310310073* 8310310076* 8310190337 8310040148*	50-244 50-244 50-244 FOIA CONTRACT	4 4 4
	8310200174	50-311 71-9086 71-6574 50-272 50-354	S R E	Rocky Mountain Energy Co Ropes & Gray	8310170071 8310200342 8310110083 8310110083 8310110072*	70-25 40-8697 50-443 50-443 50-443	0
		50-311 50-311 50-311 50-311	\$ P R	•	8310110092* 8310120133 8310120133 8310120428 8310120428	50-443 50-443 50-443 50-443 50-443	6 6 6

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT CATEGORY
	8310140015 8310140015 8310180150 8310180150 8310180153*	50-443 G 50-443 G 50-443 G 50-443 G 50-443 G	Seacoast Anti-Pollution League	6310240307 6310240375* 6310280078* 6310030355 6310110227	50-537 / CONTRACY 50-329 C 50-443 C 50-443 C
	8310180153* 8310180165 8310180165 8310180170* 8310180170*	50-443 G 50-443 G 50-443 G 50-443 G 50-443 G		8310120107 8310120107 8310120111* 8310120111*	50-443 Q 50-443 Q 50-443 Q 50-443 Q 50-443 Q
	8310200267 8310200267 8310200277 8310200277 8310260187	50-443 G 50-443 G 50-443 G 50-443 G 50-443 A		8310120115* 8310120122* 8310120122* 8310120126* 8310120126*	50-443 Q 50-443 G 50-443 Q 50-443 Q 50-443 Q
	8310260187 8310260254 8310260254 8310260261* 8310260266*	50-443 A 50-443 G 50-443 G 50-443 G	Genat a	8310120135* 8310120135* 8310120141* 8310120141* 8310170670*	50-443 Q 50-443 Q 50-443 Q 50-443 Q 50-320 U
Rosemount, Inc. Rowe Associates Rye Nuclear Intervention Committee	8310260272* 6310260272* 8310250359* 8310050438* 8310050508	50-443 G 50-443 G GA799 CONTRACT 50-443 H	Senata, Environment & Public Horks Shennon & Hilson,inc Shaw, Pittman, Potts & Trowbridge	8310200467# 8310110620# 8310180016# 8310070429# 8310030351	COMMIBBION 50-54 U COMMIBBION COMMACT 50-209 O
Rye, NR S Levy, Jnc	8310040533 8310050508 8310120178 8310070198* 8310070247*	90-443 Q 50-443 H 50-443 Q CDNTRACT CONTRACT		8310030401 8310030403 8310040253 8310040372 8310040538	50-312 Q 50-209 Q 50-302 Q 50-209 Q 50-400 Q
Sacremento Municipal Utility District	8310030401 8310030485 8310040033 8310040317 8310040419	50-312 Q 50-312 P 50-312 P 50-312 P 50-312 R		8310050520 8310060188 8310060188 8310060193* 8310060193*	50-440 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
	8310040547 8310040021 8310040022* 8310070275 8310120087	50-312 F 50-312 F 50-312 F 50-312 B 50-312 P		0310060203* 0310060203* 0310060323 0310060323 0310110150	50-400 0 50-400 0 50-400 0 50-400 0
	6310120145 6310120150 6310120160 6310120161* 6310120167	50-312 8 50-312 8 50-312 R 50-312 R 50-312 8		8310110150 8310110155* 8310110155* 8310110205 8310110224	50-400 0 50-400 0 50-400 0 50-400 0 50-209 0
	8310120186 8310120358* 8310120394 8310140249 8310170216	50-312 8 50-312 0 50-312 0 50-312 R		8310110272 0310110274 0310110280 8310120005 8310120395	50-287 0 50-264 0 50-382 0 50-201 1 50-289 0
	8310180094 8310210020 8310210038 8310250210 8310250598	50-312 G 50-312 P 50-312 P 50-312 P 50-312 B		6310140030 6310140043 6310170834 6310170839 6310170843	50-498 Q 50-493 Q 71-7010 50-382 Q 50-400 Q
Sacremento, CA	8310250607 8310270451 8310270452 8310280099 8310070224*	50-312 R 50-312 S 50-312 S 50-312 P GONTRACT		8310170343 8310170369 8310170408* 8310170408* 8310170420*	50-400 Q 50-302 Q 50-400 Q 50-400 Q
Salem:NJ San Clemente, CA San Diego Gas & Electric Co Sandía Laboratories	8310070181* 8310180270 8310110133* 8310050253 8310110174	CONTRACT 50-275 H 50-361 P NUREO NUREO		0310170620* 0310170630* 0310170630* 0310180355 0310180355	50-400 Q 50-400 Q 50-400 Q 50-289 Q 50-382 Q
	8310110591# 8310190283 8310200388 8310270045* 8310310447	FOIA NUREO NUREO FOIA NUREO		8310200102 8310200211 8310210148 8310210200 8310210249	50-266 0 50-267 0 50-269 0 50-269 0
Sargent & Lundy, Inc Save the Valley - Save Marble Hill Scharfeld, Bechhoafer & Baron	8310040347* 8310240291 8310120011* 8310120015* 8310120023*	GA797 50-546 G 50-201 I 50-201 I 50-201 I		8310240166 0310240103 0310240104 0310270330 0310270512	50-287 Q 50-400 Q 50-287 Q 50-440 Q
Schwalt, Donnenfeld, Sray & Silbert Science & Engineering Associates, Inc.	8310120042* 8310120047* 8310120207* 8310030534* 8310110510*	50-201 I 50-201 I 50-201 I CONTRACT CONTRACT		8310280051 8310280051 8310280164 8310280164 8310280164	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
Science Applications, Inc	8310110512* 8208310352* 8207200354* 8310050550* 8310170265	CUNTRACT 50-259 P 50-220 G CUNTRACT WASTE MOT	Shorekam Opponents Coalition	8310310175 8310310176 8310310382 8310310382 8310300105	50-382 0 50-287 0 50-287 0 50-287 0 50-322 0

AUTHOR AFFILIATION	ACCESSION NUMBER		ECT CORY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO SUBJEC	
Shoreham, NY Siemana-Allia, Inc Sigma Chemical Co Simking Industries, Inc Sinkin, L A	8310060270+ 8310250011+ 8310130371 8310260276+ 8310260247	GA999 XPORT	LIC ACT	*	8310130012 8310130127 8310130316 8310140023 8310140125	50-206 50-206 50-206 50-362 50-362	FPSS
Sinnissippi Ailiance for the Environment (BAFE)	8310240249 8310030349 8310040209 8310200097 8310210219*	50-45 50-45 50-45 50-45 50-45	4 н 4 с 4 с		8310140167 8310140218 8310140223 8310180486* 8310190008	50-362 50-362 50-206 50-361 50-206	8 8 8 8 8 4 8 8
Small Business Administration	8310050367# 8310050460* 8310070432* 8310130407* 8310180596*	CONTRA CONTRA CONTRA CONTRA	ACT ACT ACT ACT		6310190008 8310190008 8310190010 8310190092 8310200177	50-20& 50-20& 50-20& 50-361 50-361	H R R P
Society of Nuclear Medicine South Carolina Electric & Gas Co	8310210155* 6310210180* 8310250675 8310030343 8310030475	CONTRA CONTRA FOIA 50-395 50-395	CT CT		8310200177 8310200284 8310210260 8310250124 8310250145	50-341 50-204 50-342 50-204 50-341	P P P B
	8310030582* 8310030587* 8310040465 8310070002 8310070126	50-395 50-395 50-395 50-395 50-395	. F S		8310250196 8310250455 8310250465 8310250495 8310270101	50-206 50-204 50-362 50-362 50-206	P 8 9 9
	8310070278 8310070338 8310170443 8310170568 8310170028	50-395 50-395 50-395 50-395 50-395			8310270416 8310270428 8310270432 8310270434 8310270439	50-362 50-362 50-362 50-361 50-362	5 5 5 5
	8310200252 8310210128 8310260109 8310260117 8310260232	50-395 50-395 50-395 50-395 50-395	0 8 8 P		8310270448 8310270454 8310270454 8310270463 8310270475	50-342 50-341 50-341 50-341 50-342	8 9 9 9
	8310260255 8310280005 8310310234 8310310392 8310310394	50-395 50-395 50-395 50-395 50-395	P 10 15 15 15	Southern States Energy Board Southwest Fabricating & Welding Co (subs of 1U International Corp)	8310270498 8310310326 8310310326 8310070320 8310130285*	50~341 50~341 50~341 NUREQ 50~400	5 8 8
Southern California Edison Co	9310140021 9305240501 8310030102 9310030110 9310030110	50-443 50-206 50-361 50-206 50-206	Q P R F		8310130285* 8310130287* 8310130287* 8310130287* 8310130287*	50-400 50-400 50-400 50-400 50-400	E E E E
	8310030110 8310040009 8310040009 8310070283 8310070304	50-206 50-361 50-361 50-206 50-361	F P P S	Sputhwest Research Institute	8310130290* 8310130290* 8310190343 8310210013* 8310270598*	50-400 50-400 71-505 50-285 TOPREP	E E
	8310070344 8310110128 8310110128 8310110133* 8310110133*	TOPREP 50-361 50-361 50-361 50-361	р Р Р		8310280122* 8310280147* 8310280150* 8310280151* 8310110416*	50-311 50-259 50-259 50-259 CONTRACT	Q P P
6 6 6	9310110136+ 9310110136+ 9310120070 9310120073	50-361 50-361 50-361 50-361 50-362	23 25 26 26 27 27 27 27 27 27 27 27 27 27 27 27 27	Stamiris, D	6310170383 6310170363 6310170393 6310170393 8310170427	50-329 50-329 50-329 50-329 50-329	0 0 0
6 6	9310120116 9310120130 9310120146 9310120152 9310120164	50-361 50-361 50-361 50-361 50-361	9 9 9 9		8310170427 8310170524 8310170524 8310270345 8310280145	50-329 50-329 50-329 50-329 50-329	00000
# # # # # # # # # # # # # # # # # # #	310120170 310120172 310120183 310120184	50-206 50-362 50-362	P 9	Environ & Scientific Affairs	8310060094 8310120255	XPORTL 1C	
e 8:	31012025B 310120278	50-206 50-206	S G P		8310170198* 8310190034* 8310190036*	50-423 50-329 50-329	A A
8 8 9:	310120278	50-204 50-204 50-204	Р О О		8310170038* 8310170038* 8310170042* 8310170042* 8310170047*	50-329 50-329 50-329 50-329 50-329	A A A A
81 81 81	310120338 310120342 310120347# 310120351#	50-362 50-361 50-361 50-361	8 8 8		B310170047* B310200203* B310310065* B310310312* B310030226	50-329 50-397 50-412 50-412 50-458	AGREK
93 93	310120397 310130012	50-361 50-361 50-206 50-206	P F F	•	B31003023B* B310170466* B31017053B*	50-458 50-329 50-329	c G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8310170544* 8310170549* 8310170555* 8310170559* 8310170560*	50-329 50-329 50-329 50-329 50-329	G G G O		8310030374 8310030388 8310030388 8310030388 8310030388	50-294 50-390 50-390 50-390 50-390	8 8 8
	8310170564* 8310170567* 8310170571* 8310470575* 8310470598*	50-327 50-327 50-327 50-327 50-327	G G G G		8310020368 8310030397 8310030397 8310030404 8310030404	50-390 50-390 50-390 50-390 50-390	9 8 8 9 8
	8310170602* 8310170606* 8310170610* 8310170616* 8810170622*	50-329 50-329 50-329 50-329 50-329	G G G G		8310030405 8310030424 8310030424 8310030432 8310030434	50-260 50-390 50-390 50-259 50-390	8 8 8 8
Structural & Earthquake Engineering Consultants	8310170627* 8310170624* 8310270176* 8310110582*	50-329 50-329 50-329 CONTRACT 50-155	Q Q Q		8310060484 8310080434 8310080442 8310080442 8310080473	50-370 50-370 50-370 50-370 50-370	8 8 8
Structural Mechanics Associates Suffolk County, NY	8310130302* 8310080456 8310040177 8310040618	50~155; 50~322; 50~322;	P G G G		8310030473) 8310030504 8310030504 8310030504 8310030504	50-370 50-370 50-370 50-370 50-370	5 5 6 6
	8310050415 8310170054 8310200217 8310240160 8310270237	50-322 50-322 50-322 50-322 50-322	6 6 6		8310030504; 8310030515; 8310030538; 8310030538;	50-390 50-390 50-390 50-390 50-390	8 8 8 8
Suffolk Nuclear Study Group Syncor International System Architects. Inc	8310210327 8310210327 8310270496 8310170101 8310050460*	FOIA FOIA FOIA CONTRACT			83100305385 83100308387 8310030838 83100401387 8310040138	50-390 50-390 50-390 50-390 50-390	8 8 8
TERA Corp	831040235# 8310110378# 8310170424 8310210272 8310210272	50-247 FOIA 50-329 50-329 50-329	A R R		8310040172 8310040180 8310040190 8310040193 8310040193	50-438 50-390 50-390 50-390 50-390	8 8 8
Tameron, Inc Target Technology Ltd Tayloe Associates	B310210275* B310210275* B310050323* B310180538* B310280016 B310180576*	50-327 50-329 CONTRACT 50-333 50-142 CONTRACT	P T		8310040271* 8310040402 8310040402 8310040452 8310040452	50-259 50-390 50-390 50-259 50-259	0 F F F
Technology Development of California, Inc	8310250093* 8310250097* 8310210180*	50-397 50-397 CONTRACT	A		8310040452 8310040452 8310040452 8310040544 8310040544	50-259 50-259 50-259 50-390 50-390	F F 8
Fachnology for Energy Corp Yeanetron Research, Inc Yetedyne Engineering Services	8310040418* 8310130143 8310310449 8310120315* 8310140208*	50-261 NUREG NUREG 50-271 50-333	P P		8310040547 8310060008 8310060008 8310060007 8310060007	50-390 50-390 50-390 50-390 50-390	8 8 8
	8310170214 8310170227* 8310170646 8310170651* 8310260260	50-275 50-275 50-275 50-275 50-275	R R R R		8310060016 8310060016 8310060027 8310060027 8310060083	50-390 50-390 50-390 50-390 50-327	\$ \$ \$ \$
Teledyne, inc Tannelsc, inc Tannessee Valley Authority	8310240244 8310270241 8310030451* 8310070173* 8310030214	50-275 50-275 QA999 CONTRACT 50-390	9		8310060087 8310060087 8310060095 8310060095 8310060331	50-390 50-390 50-390 50-390 50-390	8 8 8 8
	8310030214 8310030218 8310030233 8310030233 8310030233	50-390 50-327 50-390 50-390 50-390	9 9 9 9		8310040331 8310040331 8310040342 8310060342	50-390 50-390 50-390 50-390 50-390	8 8 8
	8310030233 8310030233 8310030240 8310030244 8310030244	50-370 50-370 50-328 50-370 50-370	# 5 # 5 # 5 # 5		8310060377 8310060380 8310060407 8310060436 8310060436	50-296 50-260 50-296 50-390 50-390	8 8 8
	8310030252 8310030252 8310030257 8310030257 8310030338	50-390 50-390 50-390 50-390 50-390			8310060476 8310060488 831010604 8310110100* 8310110177*	50-390 50-390 50-390 50-327 50-259	9 9 F
	831003038 8310030345 8310030345 8310030370 8310030370	50-390 50-390 50-390 50-390 50-390	5 5 8 8 8		8310110203+ 8310120100 8310120100 8310120167 8310120167	50-259 50-390 50-390 50-390 50-390	F 8 8 8 8

AUTHOR AFFILIATION	ACCESSIO NUMBER	CAT	JECT ECORY	AUTHOR AFFILIATION	ACCESBION NUMBER	SUBJECT CATEGOR	RY
	831015053 831015053 831015051 831015051	0 50~3 0 50~3 8 50~4 6 50~3	90 9 90 9 38 9		8310210386* 8310250012 8310250012 8310250034 8310250034	50-259 50-390 50-390 50-390 50-390	FSSA
	8310150339 8310150339 8310150339 831015053	2 50-3' 8 50-3' 5 50-3'	70 S 70 S 70 S		8310250077 8310250082 8310250110 8310250138* 8310250149	50-327 50-259 50-438 50-259 50-438	9 9 9 9
	8310120389 8310120389 8310120398 8310120398 8310140017	7 50-35 5 50-35 5 50-35	70 S 70 S		8310250149 8310250142 8310250162 8310250165 8310250165	50~43B 50~390 50~390 50~390 50~390	5 5 5
	8310140017 8310140048 8310140087 8310140127 8310140127	50-39 50-32 50-24	70 S 28 S 10 S		8310250170* 8310250173 8310250173 8310250227 8310250233	50~259 50~390 50~390 50~259 50~390	Q 8 9 8
	8310140200 8310140224 8310140224 8310140277 8310170264	50-26 50-39 50-39 50-43 50-39	A O		8310250240* 8310250240* 8310250240* 8310250306* 8310250313*	50-259 50-259 50-259 50-438 50-438	0 0 0 0
	8310170254 8310170276 8310170592 8310170597 8310170558	50-39 50-32 50-32 50-32 50-32	7 S 7 S		8310250360 8310250367 8310250371 8310250371 8310250378	50-260 50-390 50-390 50-390 50-390	8 8 8
	8310170733 8310180315 8310180315 8310180388 8310180388	70-29/ 50-390 50-390 50-390 50-390	3 F 3 F 3 A		8310250436* 8310250436* 8310250484* 8310250484* 8310250494*	50-327 50-327 50-327 50-327 50-327	0 0 0
	8310180422 8310180443 8310170046 8310170087 8310170087	50-259 50-327 50-327 50-390 50-390	7 P 7 R 9 S		6310250402* 6310250402* 6310240364 8310270073 6310270150	50-327 50-327 40-1341 50-240 50-390	3 8 0 0
	8310190089 8310190089 8310190089 8310190124 8310190127	50-370 50-370 50-370 50-327 50-370	S S		8310270150 8310270183 8310270183 8310270248 8310280021	50-370 50-370 50-370 50-438 50-327	8 8 8 9
	8310190127 8310190186 8310190220 8310190224 8310190224	50-390 50-259 50-439 50-390 50-390	R 8 8		8310280021 8310280022 8310280022 8310280027* 8310280027*	50-327 50-327 50-327 50-327 50-327	ያ የ የ የ
	8310190224 8310190224 8310190224 8310210011 8310210011	50-390 50-390 50-390 50-390 50-390	8 8 8		8310280040* 8310280040* 8310280148 8310280148 8310280173	50-327 50-327 50-259 50-259 50-390	P P P A
	8310210011 8310210011 8310210011 8310210015 8310210015	50-390 50-390 50-390 50-390 50-390	8 8 8 9		8310280321 8310310142 8310310148 8310310157 8310310320	40-1341 50-257 50-370 50-438 50-370	P 83 83 83 83
	8310210023 8310210023 8310210042 8310210042 8310210049	50-390 50-390 50-390 50-390 50-390	A 8 8 8		8310310320 8310310348 8310310387 8310310387 8310310387	50-370 50-370 50-257 50-259 50-259	88 F F F
	8310210049 8310210049 8310210049 8310210049 8310210048	50-390 50-390 50-390 50-390 50-390	8 9 9	Texas A&M Univ , College Station, TX	8310310429 8310310429 8310310438* 8310310438* 8310250483*	50-327 50-327 50-327 50-327 50-57	P P P F
	6310210068 6310210078* 6310210076* 8310210078* 6310210096	50-390 50-259 50-259 50-259 50-390	8 0 8	Taxas Utilities Generating Co	8310030516 8310050403 8310050403 8310050412* 8310050412*	50-445 50-445 50-445 50-445 50-445	8 0 0
	8310210096 8310210094 8310210178 8310210178 8310210226	50-390 50-390 50-438 50-438 50-259	8 A A S		8310040316 8310110322 8310130268 8310130278 8310140022	50-445 50-445 50-445 50-445 50-445	0 8 8 7
	8310210383* 8310210383* 8310210383* 8310210383*	50-390 50-390 50-259 50-259 50-259	E F F		8310140022 8310140024* 8310140024* 8310140180 8310170412	50-445 50-445 50-445 50-445 50-445	7 7 K 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8310170412 8310170417* 8310170417* 8310180158 8310180158	50-445 0 50-445 G 50-445 G 50-445 0 50-445 0	Transportation, Dept of Transportation, Dept of, Federal Highw Administration	8310260090* 9310260150 eq B310260298* 8310270292	FDIA 50-266 P FDIA 50-261 P
	8310180163* 8310180177 8310180183* 8310180397 8310180484*	50-445 G 50-445 K 50-445 K 71-504 50-445 G	Transury, Dept of U S Customs Bervic US Ecology, Inc (formerly Nuclear Engineering)	8310270080* 8310270084* 8310050557 8310120063	FOIA FOIA 87-37 27-39
	8310180488* 8310210081 8310210184 8310210196* 8310210196*	50-445 Q 50-445 A 50-445 Q 50-445 Q		8310170390 8310200330 8310260088 8310260094 8310280080	27-39 71-6679 WASTE HOT WASTE HOT 27-48
Texas Utilities Services, Inc	8310280003 8310040604 8310040604 8310040604 8310040604	50-445 S 50-445 A 50-445 A 50-445 A	Union 75 Minerals Exploration Co	8310280281 8310310207 8310030203 8310030221	27-48 27-48 40-8584 40-8504 40-8504
	8310110116* 8310110173 8310110177* 8310200149	50-445 F 50-445 F 50-445 F 50-445 K	Union Carbide Corp,	8310040100 8310050329 8310240414 8310240414	40-279 REB 70-2067 40-279 40-299
	8310270175 8310270175 8310270185 8310270185 8310280041	50-445 F 50-445 F 50-445 F 50-445 A	Union Electric Co	8310280167# 8310280177# 8310040273# 8310040297 8310040334	40-277 40-277 50-483 0 PR PR
Texas. State of Texas, Univ of, Austin, TX	8310280041 8310180163* 8310110386* 8310110390* 8310110392*	50-445 A 50-445 0 50-172 F 50-172 F 50-172 F		831028069 8310210098 8310280661* 8310280664*	50-483 R 50-483 0 50-483 B 50-483 F 50-483 F
Telas. Univ. of El Paso, TX Telas. Univ of San Antonio Thomas, D.C Three Hile Island Alert	8310110427* 8310280131 8310050349* 8310140070* 8310260274	50-172 F RES CONTRACT 50-454 0 50-289 0	Union dil Co of California Union of Concerned Scientists	8310070384# 8310070367# 8310070367# 8310070364#	50-483 0 40-8348 50-289 0 COMMISSION COMMISSION
Taleda Edison Co	8310270372 8310060224 8310060345 8310060365 8310060575*	50-289 0 50-346 P 50-346 F 50-346 8 50-346 F		6310110469 6310110561 6310170020 6310160531 6310170037	FOIA FOIA FOIA 80-300 P FOIA
	8310110085* 8310110087* 8310110131* 8310120103 8310120222	50-346 F 50-346 F 50-346 P 50-346 P		0310170304 0310200231 0310240172 0310240304 0310240300=	FOIA 50-269 0 FOIA 50-269 0 50-269 0
	8310120237 8310120322 8310120371 8310170367 8310170375	50-346 B 50-346 B 50-346 B 50-346 B	United Engineers & Constructors, Inc	0310370366 0310310076 0310370367 0310210325*	FDIA FDIA 71-148 50-460 A
	8310170492 8310170498 8310170503* 8310170599 8310180513	50-346 P 50-346 B 50-346 P 50-346 P 50-346 R	Univ of California Press Univ of Cincinnati Hedical Ctr ,	8310170003 8310250445* 8310110824* 8310240190	70-071 70-020 CONTRACT FOIA
	8310190020 8310190166 8310190167* 8310190170* 8310210363*	50-346 R 50-346 R 50-346 R 50-346 R 50-346 F	Uranium Resources, Inc	8310260276# 8310260414 8310260418# 8310210183	FOIA 40-8783 40-8783 40-8786
Tarrey Pines Technology	8310250226 8310250235* 8310250241* 831004052 8310240178	50-346 F 50-346 F 50-346 F 50-358 A 50-546 A	Vermont Liectric Cooperative, inc Vermont Yankes Nuclear Power Corp,	8310240208* 8310040259 8310030146 8310120312 8310180096	50-443 A 50-271 F 50-29 P 50-271 P 50-271 R
	8310240178 8310240179* 8310240179* 8310240182*	50-546 A 50-546 A 50-546 A 50-546 A		8310 40298 83102 6310 8310250308 8310250334 8310250379	71-9089 50-271 P 50-271 8 50-271 6 50-271 6
Trans-Continental Consultants, Inc Transamerica Delaval, Inc Transnuclear, Inc.	8310240182* 8310210320 8310270204 8310040081 8310040084*	FOIA 50-312 E XPORTLIC XPORTLIC		8310250531 8310250626 8310310041# 8310310266 8310310307	80-271 9 80-271 8 80-271 P 80-271 P 80-271 F
	8310130376 8310180143 8310180148# 8310180302 8310280026	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Virginia Electric & Power Co	8310030300 8310040208 8310040450 8310040550 8310040587	PA 50-280 B 50-280 0 50-338 G 50-338 P
	8310580033*	XPORTL IC		8310040387	60-338 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE:		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	•
	8310040590* 8310040590* 8310060523* 8310060577* 8310060577*	50-338 50-338 50-280 50-280 50-280	р Р F F		8310030396 8310040440 8310070277 8310070342 8310070346*	50-397 50-397	A K A
	8310040584* 8310070144 8310070328 8310070418* 8310110137	50-280 50-280 50-338 50-280 50-280	F 8 F P		8310110274 8310110332 8310120059 8310120155 8310120174*	50~397 8 50~397 8 50~397 8	E A E Q
	8310110170# 8310110237# 8310110237# 8310110240# 8310110240#	50-280 50-280 50-280 50-280 50-280	F F F		8310120250* 8310120261 8310120267 8310120335 8310140066	50-397 50-397 50-397	G A A F G
	8310110269* 8310120114 8310120114 8310120140 8310120140	50-280 50-338 50-338 50-338 50-338	F P P		831014008& 8310140176 8310140182* 8310170212 8310170235	50-50B / 50-50B / 50-397 E	Q A A E E
	8310120324 8310130103 8310130103 8310130107* 8310130107*	TOPREP 50-338 50-336 50-338 50-338	T T T T		8310170298 8310170313 8310170444 8310170495 8310170499*	50-397 <i>f</i> 50-397 f	A
	8310130145 8310130145 8310130148* 8310130148* 8310140094	50-338 50-338 50-338 50-338 50-280	6 6 6		8310170507* 8310180341* 8310180387 8310180449 8310180453*	50-397 C 50-397 C 50-397 E 50-397 A 50-397 A	Q E A
	8310140094 8310140161 8310170091 8310170091 8310170098*	50-280 50-338 50-338 50-338 50-338	P 8 8 8 8		8310180503 8310190152 8310190154* 8310200200* 8310200357*	50-397 F 50-508 # 50-508 # 50-397 G FOIA	A A
	8310180277 8310180301 8310180309 8310180309 8310180440	50-338 50-238 50-338 50-338 50-338	6 6 6		8310210168 8310210173* 8310210224 8310210305 8310240150	50-397 # 50-397 # 50-460 # 50-397 #	A A A
	8310190002 8310190016 8310190043 8310190043 8310190043	50-338 50-280 50-280 50-280 50-280	R R P P		8310250088 8310250092 8310250144 8310250290 8310250425	50-397 A 50-397 E 50-397 E 50-397 E 50-397 E	6 8 8
	8310190043 8310190057* 8310190057* 8310190112 8310190112	50-280 50-280 50-280 50-338 50-338	6 6 6		B310250453 B310260113 B310260122* B310260187 B310270444	50-397 8 50-397 A 50-397 A 50-50B F 50-397 A	A A F
	8310190130# 8310190130# 8310190200 8310190200 8310200101	50-338 50-338 50-338 50-280	9 9 9		8310280126 8310310149 8310310151* 8310310154* 8310310175	50-508 G 50-508 A 50-508 A 50-508 G	A A A
	8310200101 8310200289 8310210047 8310210058 8310210304	50-280 50-339 50-336 50-280	6 8 8	Washington State Univ , Pullman, WA Washington Univ Washington, State of Water, Waste & Land, Inc	8310030143 8310210093* 8310040344 8310310204 8310030215*	50-27 F CONTRACT 50-50B A Waste Mgt 40-8584	
	8310250066 8310250456 8310250456 8310250609 8310260299	50-339 50-280 50-280 50-280 50-338	8 6 5 6	Western Nebraska Resources Council Westinghouse Electric Corp.	8310280170* 8310280175* 8310110356 8310030469* 8310040628*	40-279 40-279 FOIA GA799 70-1151	
	8310260277 8310260432* 8310260432* 8310260436* 8310270300	50-338 50-280 50-280 50-280 50-280	9 F F P		8310050197 8310050212* 8310060059 8310060120 8310060267	PROJ PROJ XPORTLIC XPORTLIC PROJ	
Virginia Polytechnic Institute & Etate Univ , Blacksburg, VA Virginia, Univ. of, Charlottesville, VA	8310270300 8310270300 8310210299 8310070104*	50-280 50-280 50-124 CONTRACT	P P F		8310060270* 8310060310 8310110149* 8310130349 8310140042*	PROJ 50-413 T TOPREP XPORTLIC 50-315 P	
W R. Grace & Co. HBI Corp. Washington Knowledge Network Washington Public Power Supply System	8310170151* 8310270099 8310130402 8309300239 8309300246*	40-86 FOIA FOIA 50-460 50-460	F		B310140046* B310140227 B310170107* B310170197 8310170203*	50-315 P TOPREP 50-338 S 70-498 70-498	•
	8310030334 8310030303 8310030337 8310030361	50-397 50-460 50-508 50-397 50-397	8 A A E		8310170219 8310170330 8310200165 8310200170 8310200193	70-1151 70-1151 50-247 8 TOPREP TOPREP	i

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHUR AFFILIATION	ACCESSION NUMBER	SUBJECT	Υ
	8310200199* 8310200451 8310210198* 8310240248 8310240250*	TOPREP 71~5450 CONTRACT 70~1143 70~1143		Wasconsin Public Service Corp	8310240051* 8310280168* 8310280171* 8310310270 8310040617	50-266 50-266 50-266 50-266 50-305	0 8 9 F
	8310250016 8310250310 8310260018 8310260045 8310260054*	XPORTLIC 70~1151 XPORTLIC 70~1143 70~1143	E		8310060334* 8310110028* 8310110031* 9310120206 8310120207* 8310120214*	50-305 50-305 50-305 50-305 50-305	G F F F F
	0310260279 8310260279 8310260281# 8310260281#	50-445 50-445 50-445 50-445	A A A		B310120216* B310120220* B310120223*	50-305 50-305 50-305	F F
	8310260283* 8310260284* 8310260286* 8310260286*	50-400 50-445 50-445 50-445 50-445	E A A A		8310120227+ 8310120232+ 8310120235+ 8310120238+ 8310120240+	50-305 50-305 50-305 50-305 50-305	F F F F
	8310280007 8310280017* 8310280019* 8310280106 8310280110*	TOPREP TOPREP 50-400 PROJ PROJ	E		8310120244* 8310120337 8310120341* 8310120345* 8310170341	50-305 50-305 50-305 50-305 50-305	F P P R
Westinghouse Operating Plants Owners Group Whicher, J M	8310040363 8310110142 8310040205	TOPREP TOPREP 50-454	G		8310180522 8310210304 8310210317 8310210394* 8310210396*	PR 50-305 50-305 50-305 50-305	8 8 8
White Plains, NY Whiting Corp	8310210278 8310200097 8310210219* 8310040501* 8310120215*	50-367 50-454 50-454 CQNTRACT 50-155	T	Wood-Leaver & Associates, Inc Myoming Fuel Co Myoming Mineral Corp	8310040611* 8310260373 8310040605 8310210102 8310210107*	50-155 40-8829 40-8502 40-8502 40-8502	T
Williams & Associates Williams-Robinette & Associates, Inc	8310130297* 8310130301* 8310070221* 8310120040* 8310280068*	50-155 50-155 CONTRACT CONTRACT		Hypming, State of Yankee Atomic Electric Co	8310030359 8310210146 8310240045 8310250169 8310030341	40-8786 40-277 40-8584 40-6622 PR	
Hilliamsport Hosp Hilliamsport.PA Hisconsin Electric Power Co	8310270031 8310030447 8310030447 8310030624# 8310040310	FO1A 50-266 50-266 50-266 50-266	0 F F P		8310040108 8310040307 8310040330 8310040333* 8310040334	50-29 PR 50-29 50-29 PR	P P
	8310040310 8310040623 8310070303 8310070303 8310110187	50-266 50-266 50-266 50-266 50-266	, P		8310040343 8310120263 8310190012 8310190097 8310190097	50-443 50-443 50-29 50-29 50-29	S A P P
	8310110274 8310110274 8310120089 8310120089 8310120275	50-266 50-266 50-266 50-266 P8	G G G		8310190097 8310190105* 8310190105* 8310190105* 8310210250*	50-29 50-29 50-29 50-29 50-443	P P P Q
	8310130004 8310130004 8310170234 8310170380 8310180117	50-266 50-266 71-9010 50-301 50-266	9 8 8		8310250232 8310250277 8310250327 8310250418 8310250421	50-29 50-29 50-29 50-29 50-29	6 9 9 5
	8310180117 8310180421 8310180421 8310180490	30-266 30-266 30-266	R P P		8310250523 8310270042* 8310270534* 8310280015 8310280018	50-29 50-309 50-29 50-29 50-29	8 F 8 6
	8310180490 8310180492* 8310180492* 8310180493* 8310180497* 8310180502*	50-266 50-266 50-266 50-266 50-266 50-266	P P P P P P	Zumwalt. L. R	B310110271•	CONTRAC	T
	8310180502+ 8310200102 8310200202 8310210044 8310210044	20-569 20-599 20-301 20-599 20-599	P G P F				

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	CATEGO		REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEOGRY	OTHER REPORT REMUN
Q2-016Q-1102 R01	8310180481*	50~387	P	NUREG-0577 RO1	8310310446	NUREO	
Q2-016Q-1102 R1 APPR	8310180493* 8310180497*	50-387 50-387	P P	NUREQ-0580 V12 NO9	8310310111	NUREO	
02-0160-1102 R1 APPD	8310180478*	50-387	P	NUREO-0730 V17 NO3	B310110169	NUREG	
02-0160-1102 Rt APPE	0310100501*	50-387	P	NUREG-0748 VO3 NO8 NUREG-0750 V17 IO1	8310310118 8310310121	NUREO NUREO	
02-0160-1102 R1 APPF	B3101B0504*	50-387	P				
Q2-0160-1131 RO APPB	B310180514#	50-387	P	NURES-0750 V17 NO4	8310050244	NUREG	
02-0160-1131 RO APPC	831018051B*	50-387	P	NUREQ-0835 DRFT NUREQ-0849	8310210132 8310190342	NUREO NUREO	
Q2-01&Q-1131 RO APPD	8310180550*	50-387	P	NUREQ-0852 802	B310050232	30-470 E	
02-0160-1131 RO APPE	8310180553*	50-397	P	NUREQ-0994	8310180071	50-112 E	
02-0160-1131 RO APPF	8310180525*	50-387	P	NURE9-1011	8310070439	50-266 P	
02-0160-1131 R00	8310180509*	50~387	P	NUREG-1016	8310180169	50-116 E	
0383~03 FA	8310140274*	50-529 50-397	6 BLN 283-13	NURED-101B	B310110345	NURED	
1124-F1 VO1 1124-F3 VO3	8310250073* 8310250097*	50-397	A A	NUREQ-1020 VO1	8310070437	50-289 e	
1120 . 5 705	B310200077#		n	NUREG-1020 VO2	8310070441	50~289 e	
14331-2 ROI 14331-3 ROI	8310130267* 8310130271*	50-400 50-400	E E	NUREG-1021	8310310452	NUREO	
14801-1 R01	8310130277*	50-400	Ē	NURE9-1022	8310130130,	NUREO	
15737-2-907-102 RO3	8310170647*	50-320	P	NUREG/CP-0047 NUREG/CR-1278	8310110171 8310200388	NUREO NUREO	SANDBO-0200
5-6167-5	8310130280*	50-400	E	NUREG/CR-2000 VOZ NB	B310110023	NUREG	ORNL/NSIC-200
77-1140898-01	8310030356*	50-313	P	NUREG/CR-2000 VOZ NO	8310310191	NUREO	DRNL/NBIC-200
63-024	8310310130*	50-416	G	NUREQ/CR-2146 VO3	8310240427	NUREO	HEDL-THE 83-18
8304-1	6310040573*	50-382	Ą	NUREG/CR-2482 VO4	8310070411	NUREO	BNL-NUREG-51494
8304-2 83140-8514-8	8310280006#	50-302	A	NURE9/CR-2571	8310310209	NUREO	EPRI NP-2377
8310050145	9310050145	RES		NUREO/CR-2573	8310180085	NUREO	EPRI NP-2375
8310050329 8310060515	8310050329 8310060515	RES MISC		NUREQ/CR-2574	8310180076	NUREC	EPRI NP-2376
8310070216	8310070216	RES		NUREQ/CR-2631	B310110174	NUREC	BANDB2-2726
8310200344	8310200344	RES		NUREO/CR-2649	8310170243	NUREO	ORNL/TM-8300
8310260131	8310280131	RES		NUREQ/CR-2726 NUREQ/CR-2830	8310190283 8310310114	NUREO NUREO	SAND821137 BNLNUREG51565
AEOD/E310	*0210E070E	50-341	8	NUREG/CR-2850 VOZ	8310070442	NUREO	PNL,~4221
B0037	8310130241*	50-400	E	NUREO/CR-2893	831031026B	NUREO	PNL-4395
80045	8310130273#	50-400	臣	NUREQ/CR-3048	6310110580	NUREO	PARAMETER 1E-12
BAW-1762 RO1	*40E0E001EB	50-460	A GL-82-14	NUREO/CR-3050	8310180079	NUREC	PARAMETER IE-12
BM[-2104	8310270045*	FOIA		NUREG/CR-3051	8310200378	NUREO	PARAMETER IE-12
CASE-TR2 RO2 CEN-239 SO3 RO1	B310270055#	TOPREP		NUREG/CR-3081	6310310444	50-302 P	BNL-NUREQ-51 626
CEN-248(8) RO1	8310260160# 8310040357#	50-528 50-317	A P	NUREQ/CR-3122	B310070426	NUREC	DRNL/NSIC-213
CEN-255(A)-NP	8310130109*	50-36B	P	NUREG/CR-3151	8310310447	NUREO	SANDB2-1414
DTS 1600-1 ROS	8310110486*	FOIA	•	NUREG/CR-3199 Nureg/CR-3215 VO2 ER	8310260423 8310310106	NUREO NUREO	ORNL/TM-8685 PNL-4655
EG0-HB-6371	8310040123*	50-395	P	NUREG/CR-3223	8310180118	NUREQ	EPRI NP-3093
FCTPN-78	8310140174*	TOPREP		NUREO/CR-3259	8310110347	NUREG	PNL-4694
9A-C17258 VO1	B31024017B	50-546	A	NOREG-3290	8310200389	NUREO	LA-9704-MS
GA-C17258 VO2	8310240179*	50-544	Ą	NUREO/CR-3299	8310050224	NUREO	
QA-C17258 VO3	8310240182*	50-546	A	NUREG/CR-3327	8310070154	NUREO	
GADR-55 ADDO4	8310130274*	71-6346	22911	NURE9/CR-3334 VO1	8310050217	NUREO	ORNL/TM-8787/V1
NUREG-0020 V07 NO4 NUREG-0090 V06 NO1	8310050339 8310130133	NUREO NUREO		NUREO/CR-3345	8310110032	NUREO	UCID-19719
NURE9-0383 V01 R06	8310130133 8310130151	NUREG		NUREO/CR-3352	8310310208	NUREO	PNL-4760
NUREG-0383 VO2 ROA	8310110532	NUREG		NUREG/CR-3371 VO2 NUREG/CR-3384	831007043 <u>4</u> 8310070317	NUREO NUREO	0P-R-221020 PNL-4774
NUREQ-0383 V03 R03	8310110593	NUREO		NURE9/CR-3401	8310050253	NUREC	8AND83-1502
NUREG-0420 804	8310070116	50-322	E	NUREO/CR-3425	8310070323	NUREO	#12400만기 7 <u>작</u> 라였
NUREG-0485 VOS NOB	8310130149	NUREO		NUREG/CR-3437	B310050331	NUREO	E99-2271
NUREG-0540 VO5 NO7	8310200382	NUREG		NUREO/CR-3445	83102403B1	NUREO	PNL-4806
NUREG-0566 VO3 NO1-3	8310310188	NUREQ		NUREO/CR-3450	9310310449	NUREO	

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEODRY	OTHER REPORT NUMBER	REPORT NUMBER		SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-3451 NUREG/CR-3464 NUREG/CR-3472 VOI NUREG/CR-3473	8310130143 8310050335 8310050239 8310070414	NUREG NUREG NUREG NUREG		SECY-83-157 SECY-83-163 SECY-83-249 SECY-83-270	83101104394 83101700534 83072201544 83072202504	# FOIA # FOIA	A
NUREG/CR-3475	8310070110	NUREC	L9C-16363	SECY-83-279	8307270430		P
NUREO/CR-3484 NUREO/CR-3487 NUREO/CR-3499 P 103-4-839-034 R01 P 105-4-839-035 R01	8310040079 8310070320 8310260397 8310070100* 8310070212*	70-143 NUREQ NUREQ 50-275 R 50-275 R		SECY-83-311 SECY-83-311A SECY-83-343 SFR-CC-01 1 R01 SGPR-8301	8308190179 8310120025 8309080114 83102501284 83102402844		p A
P 105-4-839-061 R01 P 105-4-839-065 R01 P105-4-839-058 R01 P105-4-839-060 R01 P105-4-839-063 R01	8310070091* 8310140119* 8310040515* 8310070227* 8310070155*	50-275 R 50-275 R 50-275 R 50-275 R 50-275 R		8GPR-8302 SWRI-4582-003 TER-C5257-179 TER-C5504-174/175 TER-C5504-241 R01	83102602864 83102703784 81040704444 83061605134 83080303824	* TOPREP * 50~204 * 50~324	A P P Q TAC 42859
P105-4-B37-068 R01 P0E-1023-(B3) P0E-1040 R-83-030 RDD 84:5303-04:02	8310070257* 8310310301* 8310260246* 8310060418* 8310250424*	50-275 R 50-344 P 50-344 P 50-261 P 50-313 Q		TER-C5506-242 TER-C5506-243 ROI TER-C5506-261 TER-C5506-272 TER-C5506-273	8309200504 8308030014 8309160203 8306160602 8212010152	* 50-295 * 50-286 * 50-302	Q TAC 42725 Q IEB-80-11 Q IEB-80-11 P
SAI-186-028-11 SAI-186-027-50 SAND82-7056 SD-SWI-DIC-001 ROO SD-SWI-DP-035 R B	8209200354* 8208310352* 8310190313* 8310110626* 8310280295*	50-220 Q 50-259, P FOIA WASTE HOT WASTE HOT	000360	TER-C5504-294 TER-C5504-344/345 TER-C5504-348 DRFT TER-C5504-379/380 TER-C5504-409	82100100874 83070602434 83081805604 83070203724 83072002604	50-315 50-346 50-277	P TAC 07980 P TAC 10993 P TAC 08070
8ECY-82-077 SECY-82-121 SECY-82-141A SECY-82-168 SECY-82-221	8203120050* 8204070171* 8310310114* 8205050588* 8206100323*	FOIA 50-320 P FOIA FOIA		TER-C5504-410 TER-C5504-412 TER-C5504-73 TF-334/0804A TF-343/0809A	8307250463 83083003174 83012102404 83060303724 83060801124	50-213 50-244 50-284	P P TAC 41315 P TAC 8097 P TAC 44379 P TAC 44405
8ECY-82-243 8ECY-82-243 8ECY-82-251 8ECY-82-279 8ECY-82-330	8206240098# 8206300342# 8206250316# 8310110017# 8208270562#	FOIA FOIA FOIA FOIA		TF-349/0812A TF-366/0817A TF-367/0817A TF-370/0817A TF-380/0823A	8304080045* 8304130456* 8304080055* 8304080104* 8310050534*	50-346 50-312 50-302	P TAC 44385 P TAC 44364 P TAC 44402 P TAC 44363 P TAC 44369
8ECY-82-460 SECY-82-483 SECY-83-030 SECY-83-032A SECY-83-044	8211270108* 8310310131* 8310250030* 8310270264* 8302160056*	FOIA 50-289 P FOIA FOIA FOIA		TR-5319-2 TR-5321-1 ROO VEP-NFE-1 XN-NF-80-19(NP)(A)V4 XN-NF-83-57	8310120315* 8310140202* 8310140257* 8310140244* 8310050470*	50-333 50-280 TOPREP	ե ե ե
SECY-83-072 SECY-83-073 SECY-83-112 SECY-83-120 SECY-83-124	8310310136* 8310310140* 8304050526* 8310110022* 8304220088*	FDIA FDIA FDIA 50-445 A FDIA		XN-NF-83-72 XN-NF-83-72 S01 YAEC-1055 YOGAP-I-A R14	8310120415* 8310120422* 8310310041* 8310190105*	50-261 50-271	무 무 무

	N NUMBER				ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR		NCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEOD	ŘΥ
7908250181 7908250189 7908080318 7908270319 7909140005	8310240171 8310240171 8310170078 8310170078 8310170078	83/07/06 83/07/06 83/06/07 83/06/07 83/06/07	FOIA FOIA FOIA FOIA	62 82 82 82	206240078 206250316 206250342 206300342 207150081 207260071	8310270360 8310310097 8310310097 8310310097 8310120329	83/09/29 83/09/19 83/09/19 83/10/03 83/06/23	FOIA FOIA FOIA 50-29 50-269	P
7911300172 8001040244 8003240118 8003240123 8004230428	8310170078 8310170078 8310120016 8310120016 8310170078	83/06/07 83/06/07 83/07/07 83/07/07 83/06/07	FDIA FDIA FOIA FOIA FOIA	82 82 82	207280124 208010014 208230434 208240121 208270562	8310200354 8310110034 8310110044 8310250032 8310110007	83/09/23 93/06/15 83/07/20 93/07/15 83/07/15	FOIA 50-275 50-382 FOIA FOIA	ę Q
8006170100 8006200467 8007170062 8007170067 8007170227	8310170078 8310170078 8310170078 8310170078 8310170078	83/06/07 83/06/07 83/06/07 83/06/07 83/06/07	FOIA FOIA FOIA FOIA FOIA	82 82 82	208310352 209010314 209200354 210010087 210050447	8310240243 8310110044 8310070114 8310060557 8310110044	83/10/12 83/07/20 83/07/19 83/07/27 83/07/20	50-259 50-362 50-220 50-272 50-362	P 0 0 P 0
8007290463 8007290676 8008270592 8009160105 8009240099	8310120014 8310120014 8310140031 8310170078 8310170078	83/07/07 83/07/07 83/08/23 83/06/07 83/06/07	50-337 50-339** 50-498 FOIA FOIA	92 62 82 82	210180246 210280450 211020311 211040474 211290108	8310210329 8310180625 8310260008 8310260008 8310310097	83/07/28 83/09/01 83/06/23 83/06/23 83/09/19	50-366 50-327 FOIA FOIA FOIA	S Á
8010010784 8010070328 8011050238 8011190749 8012010577	9310240320 9310170078 9310240235 9310240235 9310170078	83/07/14 83/06/07 83/07/11 83/07/11 83/06/07	50-348 FOIA FOIA FOIA FOIA	82 82	12010152 12130165 12130174 12130242 12150242	8310040448 8310040407 8310260008 8310270448 8310270448	83/09/01 83/09/22 83/06/23 83/10/04 83/10/04	50-346 50-267 FOIA FOIA FOIA	P P
8012310197 8012310245 8012310507 8101070484 8101090040	8310170078 8310170078 8310170078 8310170078 8310170078	93/06/07 93/06/07 93/06/07 93/06/07 93/06/07	FOIA FOIA FOIA FOIA	83 83	12290072 12300076 101070386 101180513 101210240	6310270468 6310180425 6310170340 6310210327 6310070365	83/10/04 83/09/01 83/09/15 83/07/28 83/09/39	FOIA 50-329 50-282 50-321 50-244	A 8 9
8101070109 8102240210 8103040697 8103180096 8104070444	8310170078 8310240235 8310170078 8310170078 8308240501	83/06/07 83/07/11 83/06/07 83/06/07 83/05/20	FDIA FOIA FOIA FOIA 50-206	83 83 93	01250200 02020202 02040523 02140054 02180539	8310250032 8310210329 8307050513 8310310097 8310210329	83/07/15 83/07/28 83/06/08 83/09/19 83/07/28	FOIA 50-333 50-255 FOIA 50-257	6 P
8104170659 8104170666 8104210028 8112170188 8202230210	8310170078 8310170078 8310170078 8310110044 8310260019	83/06/07 83/06/07 83/06/07 83/07/20 83/07/15	FOIA FOIA FOIA 50-382 FOIA	#31 931 931	03030103 03230300 03230482 03240341 03240364	B310210329 B310210315 B307050513 B310210329 B310210329	93/07/29 93/07/29 83/04/08 B3/07/28 93/07/28	50-367 50-352 50-255 50-324 50-277	8 A P S
8203120050 8204070171 8205050588 8205140137 8205140143	8310310097 8310310097 8310310097 8310190093 8310190093	83/09/19 83/09/19 83/09/19 83/09/07 83/09/07	FOIA 50-320 FOIA FOIA FOIA	83(83(04010047 04050526 04200046 04200240 04220088	8310240008 8310240243 8307050513 8310190340 8310310097	83/06/23 83/07/11 83/06/08 83/07/15 83/09/19	FOIA 50-255 50-282 FOIA	P 8
8205270433 8206080487 8206100323 8206140401 8206140403	8307050513 8310240197 8310310097 8310190093 8310190093	83/04/08 83/09/08 83/09/19 83/09/07 83/09/07	50-255 50-528 FOIA FOIA FOIA	836 830 830	05030115 05030120 05050044 05060071 05060124	8310280079 8310280079 8310190340 8307050513 8310180568	83/07/28 83/07/28 83/07/15 83/04/08 83/07/04	50-361 50-361 50-292 50-255 50-445	9 9 9 8 P

ACCESS16	ON NUMBER				ACCES81	ON NUMBER			
F101 00100	PRINCIPAL	DATE	SUBJEC			PRINCIPAL	DATE	SUBJEC CATEGO	
ENCLOSURE	DOCUMENT	ISSUED	CATEGO	HY	ENCLOSURE	DOCUMENT	ISSUED	~~~~~~~	
8305130302 8305130304	8310240237 8310240237		FOIA FOIA		8310030375 8310030377	8310030367	83/09/27 83/09/27	50-460 50-460	9
830513030A 8305160184	8310240237 8310280079	83/07/06	F01A 50-361	s	93100303168 93100303188		83/09/27 83/09/13	50-400 0A999	0
8305240300	8310190340		20-585	s	B310030383		83/09/13	0A999	
830601000B	6310210329	83/07/28	50-271	9	83100303B7	8310030379	83/09/13	0A999	
8304020357 8304030372	8310030308 8310040035		50~309 50~286	g	8310030372 8310030407	8310030385	83/09/07 83/09/29	50~478 50-382	Q A
8304080055	8310110476	83/09/27	50-312	P	8310030409	8310030406	83/09/27	50-413	O
8306080065	8310110543		50-336	P	B310030411	8310030395	83/08/29	50-445	G
8304080104 8304080112	8310050297 8310070097	83/08/08 83/09/27	50-302 50-272	P	8310030420 8310030421		83/09/17 83/09/15	50~45B 50-287	g P
8306090346	8310070080	83/09/28	50-346	P	8310030450	8310030445	83/09/16	BA999	•
8306130456 8306160513	8310200041 8310310137	83/10/05 83/10/14	50-346 50-324	P	#310030451 #310030454		83/09/27 83/09/16	94777 94777	
8306160602	8310200064	B3/10/06	50~302	p	g310030457	8310030446	B3/08/08	50-267	Q
8306170106 8306170442	8310200220	83/10/14 83/10/14	50-206 50~206	g g	8310030459	8310030445	83/09/16	QA999	
8306230142	8310200220	83/10/14	50-206	G	g310030469 g310030478	8310030444 8310030441	83/09/27 83/09/23	0/1979 50-400	Q
B307200260	8310110466	83/09/23	50-336	P	#310030497	8310030492	83/09/30	50-155	þ
8307220156 8307220250	8310190049 8310270369	B3/09/13 B3/10/04	FOIA FOIA		8310030534	8310030524	83/09/21	CONTRACT 71-9151	т
8307250463	8310110472	83/07/26	50-313	P	#31003056B #310030574	8310030561 8310030561	83/09/12 83/09/12	71-9151	
8307270 430 8307290 22 3	8310270369 8310200356	83/10/04 83/09/23	50-289 FOIA	P	8310030579 8310030582	8310030564 8310030573	83/09/28 83/09/28	50~315 50~395	F
B308030014	8310110456	83/09/12	50-295	a	B310030597	8310030573	83/09/28	50-395	F
8309030 382 8308080870	8310130025 8310200356	83/09/20 83/09/23	50-315 FDIA	Q	8310030400	8310030598	83/09/07	50-346	P
8308150336	8310130394	83/08/25	50~329	A	8310030607 8310030610	831 <i>0</i> 030604 8310030605	83/09/23 83/09/19	50~327 Waste Ho	р ЭТ
8308150385	8310130189	83/10/04	50~387	8	8310030615	8310030413	83/09/20	50-348	P
8308180258 8308180560	B310190340 B310200050	83/09/15 83/10/06	50~282 50~34&	8 P	\$140600168 \$240600168	8310030409 8310030420	B3/09/28	50~264 50~269	F
8308290029 8308300317	8310130394 8310030140	83/08/25 83/09/26	50-329 50-213	A	8310030624	8310030409	83/09/26 83/09/28	50-266	F
8308300486	8308300480	83/08/26	50-413	6	8310030645 8310040042	8310030641 8310040012	83/09/23 83/09/08	GEN TEC 50-321	18 Q
8308300&10	B308300607	83/07/08	40~6622		B310040043	8310040037	83/09/02	50-261	Q
8308300712 8308300716	8308300705 8308300705	83/08/05 83/08/05	GA999 GA999		8310040055	8310040051	83/09/16	50~305	q
8308300722 8308310422	B308300705 B310110472	83/08/05 83/09/24	98999 50~313	P	8310040040 8310040072	8310040051 8310040068	83/09/16 83/09/20	50-305 50-305	G G
8309310512	8310310294	83/10/18	50-247		8310040099	8310040074	B3/09/23	71-466	
8309020392	B310110454	83/09/21	50-277	Q P	8310040123 8310040127	8310040120 8310040124	83/09/16 83/09/30	50-375 50-352	P
8307060263 8307070071	8310070408 8310030131	83/09/20 83/09/26	50-315 Misc	P	6310040129	8310040124	83/09/30	50-352	Α
8309080358	8310270379	83/10/18	QEN TEC	IB	8310940131 8310940136	8310040124 8310040121	B3/09/30 B3/09/22	50-352 50-10	F
83091600363 8309160036	B310270379	83/10/18	OEN TEC	18	B310040137	8310040133	83/09/23	70-2945	
6307140203	8310060157 8310110465	83/09/27 83/09/23	NURED 50~286	q	8310040147 8310040148	8310040140 8310040143	83/09/09 83/09/01	50-390 70-1151	æ
8307200504 8307300044	8310310294 8310200070	83/10/18 83/10/04	50-267 50-382	G. A	8310040150	8310040146	83/09/08	50~413	a
B30930024A	8309300239	83/09/22	50-460	F	8310040157	8310040153	83/80/E8	50-382	a
B3100300A3	8310030060	83/09/29	50-362	K	8310040160 8310040162	8310040156 8310040158	83/09/02 83/09/29	50~445 50~456	G G
8310030067 8310030082	B310030060 B310030080	83/09/28 83/09/29	50-382 50-244	K P	8310040164	B3100401&1	83/09/30	50~423	ĸ
8310030085	8310030081	83/09/15	50-416	P	8310040167 8310040168	8310040163 8310040166	83/09/08 83/09/07	50~416 50~261	G G
8310030068 0010000108	8310030081 8310030093	83/09/15 83/09/28	50-416 50-116	P P	8310040178	8310040174	B3/09/15	50-321	a
8310030104	19000001	83/09/15	50-416	P	8310040177 8310040186	8310040176 8310040181	83/09/21 83/08/24	50~344 50~445	a
8310030151 8310030168	8310030143 8310030167	83/09/27 83/09/27	50 <i>-27</i> 50-498	F	6310040191	8310040189	83/09/29	50-277	P
B310030210	B310030203	B3/09/07	40-8584		B310040197	8310040170	83/09/09	70~143	
8310030213 8310030215	8310030178 8310030203	83/09/29	XPORTLIC		8310040178 8310040203	8310040195 8310040182	83/09/16 83/08/30	50-331 50-324	0
8310030236	8310030229	83/09/07 83/09/28	40-8584 50-373	F	8310040212	8310040209	B3/09/29	50-275	Q
8310030238	8310030232	83/09/27	50-458	C	8310040219 8310040222	8310040207 8310040215	83/09/29 83/09/01	50~275 50~424	G G
8310030250 8310030258	8310030241 8310030263	83/09/08 83/09/28	40-8452 50-219	P	8310040224	8310040220	83/09/13	50~400	Q
8310030272 8310030305	8310030243 8310030294	83/09/28	50-219	P	8310040224 8310040229	8310040221 8310040227	83/09/20	50-275 50-440	G.
8310030309	B310030294 B310030303	83/09/28 83/09/23	50-290 50-460	G A	8310040231	B310040227	83/09/16 83/09/16	50-440	E
410000316	8310030308	83/09/21	50~309	8	8310040234	8310040227	83/09/16	50-440	E
8310030340 8310030347	8310030337 8310030344	83/09/27 83/07/21	50~368 50-267	P	8310040235 8310040239	831004022 8 8310040233	83/07/13 83/09/30	50-247 50-382	ė E
8310030348	8310030342	83/09/15	QA999	a	8310040240	8310040223	83/08/24	50~445	œ
8310030350	8310030344	83/07/21	50-267	a	8310040244 8310040245	8310040211 8310040233	83/09/30 83/09/30	50~438 50~382	G.
8310030352 831003035 <i>6</i>	8310030342 8310030353	83/09/16 ES/99/23	9A999 50-313	P	8310040246	8310040242	83/09/12	QA999	
8310030360	8310030345 8310030367	83/09/12 83/09/27	50-412	a	8310040249 8310040253	8310040242 8310040247	83/09/12 83/09/09	0A999 50-269	
B31003037g	B310030367	83/09/27	50~400 50~400	0	9310040255	8310040250	83/09/13	50-255	G G
					8310040260	9310040257	83/09/28	50-454	Q

ACCE8810	N NUMBER				ACCESS I	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJEC CATEGO		ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEOOR	
8310040261	8310270020	83/07/18	FOIA		8310040500	83100404B4	83/09/28	50-249	 0
8310040262 8310040266	9310040256 8310040264	83/09/29 83/09/28	50~443 50-155	Q P	8310040501 8310040507	8310040464 8310040484	83/09/26 83/09/28	70-27 50-269	a
8310040271 8310040272	8310040265 8310040256	83/09/14 83/09/29	50~259 50~443	G G	8310040508 8310040515	8310040464 8310040509	83/09/26 83/10/01	70~27 50~275	R
8310040273	8310040268	83/09/30	50~483	Q.	B310040517	8310040504		"	
8310040275 8310040277	8310040265 8310040256	83/07/14 83/07/29	50~259 50~443	ā	B310040519	8310040505	83/09/09 83/09/30	50-250 50-155	G T
8310040278	8310040265	83/09/14	50~259	ū	8310040527 8310040531	8310040521 8310040526	83/09/27 83/09/13	50-423 50-546	C Q
8310040283	8310040265	83/09/14	50~259	a	8310040537	8310040532	03/09/19	50-528	a
8310040265 8310040274	8310040269 8310040290	83/09/13 83/08/30	50-261 50-269	Q.	8310040540 8310040541	8310040526 8310040538	83/09/13 83/09/30	50~54 <i>6</i> 50~400	0
8310040304 8310040306	8310040301 8310040298	83/07/29 83/09/22	50-302 50~324	e G	8310040546 8310040557	8310040536 8310040553	03/08/29 03/09/29	50-478 50-155	g T
8310040308	8310040300	83/09/23	50-312	G	6310040540	8310040551	83/09/30	50-155	T
8310040309 8310040311	8310040303 8310040300	63/07/21 63/07/23	70-143 50-312	Q	8310040543 8310040543	8310040555 8310040551	83/09/12 83/09/30	50-390 50-155	Q T
8310040312 8310040314	8310040303 8310040303	83/09/21 83/09/21	70-143 70-143		B310040565 B310040566	8310040559 8310040558	83/07/27 83/07/05	50-382 50-247	Á
8310040316	8310040305	83/09/30	50-250	Q	8310040568	8310040548	83/09/30	50-155	ī
8310040319 8310040321	8310040313 8310040298	63/09/22 63/09/22	50~413 50~324	Q Q	8310040569 8310040571	B310040561 B310040567	83/09/27 83/09/19	50-334 50-285	F Q
8310040322 8310040323	8310040315 8310040313	83/09/16 83/09/22	50-267 50-413	8	8310040573	8310040559	B3/09/29	50~382	Α
B310040324	8310040315	83/09/16	50-267	B	8310040577 8310040578	8310040567 8310040570	83/08/19 83/09/29	50-285 50-275	e
8310040326 8310040327	8310040298 8310040313	83/09/22 83/09/22	50-324 50-413	G G	B310040579	8310040576	83/09/16	0A999	_
8310040328	8310040315	83/09/16 83/09/22	50-267 50-324	8	8310040583 8310040585	8310040580 8310040570	93/08/24 93/09/29	50-267 50-275	P
8310040332 8310040333	8310040298 8310040330	83/07/22	50~29	G P	8310040386 8310040389	8310040574 8310040580	83/09/16 83/08/24	0499 9 50-267	a
8310040335	E1E040313	83/09/22	50-413	g	8310040590	8310040587	83/09/29	50-338	P
8310040340 8310040341	8310040303 8310040336	83/09/21 83/09/30	70-143 50-358	F	8310040591 8310040596	8310040570 8310040576	83/09/29 83/09/16	50-275 GA999	P
8310040342 8310040345	B310040337 B310040329	83/09/29 83/09/02	70-824 50-413	œ	8310040598 8310040600	8310040570 8310040575	83/09/29 83/09/13	50-275 50-400	P G
8310040349	B310040343	83/09/30	QA999		8310040603	8310040595	83/09/13	50-400	a
8310040350 8310040355	8310040346 8310040353	83/09/20 83/09/28	70-143 50-317	Р	8310040505 8310040508	8310040595 8310040595	83/09/13 83/09/13	50-400 50-400	ā
8310040357 8310040360	8310040353 8310040359	83/09/28 83/09/16	50-317 70-36	P	8310040510 8310040511	8310040595 8310040594	83/09/13 83/09/30	50~400 50~155	G T
8310040366	8310040356	83/07/17	50-321	Q	8310040613	8310040575	83/07/13	50-400	ď
8310040367 8310040369	8310040365 8310040365	B3/09/30 B3/09/30	50-155 50-155	T	9310040615	B307260003	93/06/10	30~45B	A
8310040373 8310040377	8310040365 8310040374	83/09/30 83/09/19	50-155 50-348	i G	8310040621 8310040624	8310040620 8310040620	83/09/25 83/09/25	50-155 50-155	Ť
8310040378	8310040374	83/09/19	50-348	G	8310040628	8310040622	93/09/23	70-1151	
8310040379 8310040381	8310040374 8310040376	83/09/19	50~34B 50~155	G	8310740832 8310040835	8310040622 8310040622	83/09/23 83/09/23	70-1151 70-1151	
8310040383	8310040382	83/09/30 83/09/30	GA999	Τ .	8310040637 8310040642	8310040422 8310040439	83/09/23 83/09/16	70-1151 50-362	P
8310040384	8310040374	83/09/19	50-348	a	8310040643	8310040439	83/09/16	50-362	P
8310040388 8310040393	8310040385 8310040389	83/09/29 83/09/28	50-324 50-410	P G	8310040644 8310050022	8310040558 8310050017	83/09/06 83/09/21	50~247 50~348	Q P
8310040399 8310040411	8310040391 8310040400	83/07/15 83/07/22	50-18 50-334	Q Q	8310050030 8310050041	8310050025 8310050016	83/09/23 83/09/26	71-9510 71-6003	
8310040413	B310040406	83/09/13	50-413	œ	8310050047	8310050044	83/09/23	50-199	P
8310040426 8310040427	8310040422 8310040423	83/09/30 83/09/12	0A999 50-390	Q	8310050054 8310050057	8310050046 8310050053	83/08/18 83/09/26	71-9080 71-9100	
8310040427 8310040430	8310040415 8310040424	83/09/29 83/09/23	50-277 50-454	P G	8310050059 8310050061	8308300767 8310050055	93/10/11 93/09/30	50-329 50-320	A
8310040433	8310040422	83/09/30	QA999	_	B310050045	8310050046	83/08/18	71-9080	r
8310040437 8310040441	8310040422 8310040432	83/09/30 82/12/22	GA999 GA999		9310050074	8310050046 8310050077	93/08/19 93/09/23	71-9080 50-346	je.
8310040446 8310040453	8310040442 8310040432	82/12/22	50-327 GA999	Q	#3100500#2 #3100501#3	8310050124	83/09/23	71-37	
8310040454	8310040447	83/09/14	50-335	Q	8310050164 9310050174	8310050159 8310050159	83/08/26 83/08/26	50-272 50-272	P
8310040461 8310040468	8310040459 8310040356	83/09/30 83/09/19	50-358 50-321	K	9310050181	8310050177	83/09/21	40-8794	_
B310040470	8310040464 8310040466	83/09/26	70-27	9	9310050202 9310050212	8308300771 8310050197	83/10/06 83/09/23	50-244 PROJ	P
8310040472 8310040475	8310040466	83/09/23 83/09/23	50-302 50-302	a a	B310050255 8310050271	8310050245 8310050245	83/10/03 83/10/03	50-295 50-295	P
8310040477	8310040466	83/09/23	50-302	Q	8310050304	8310050297	83/08/09	50-302	P
8310040479 8310040480	8310040356 8310040466	83/09/19 83/09/23	50-321 50-302	G G	9310050310 9310050315	8310050278 8310050278	83/10/03 83/10/03	50-285 50-285	P
8310040482 8310040486	8310040474 8310040464	83/09/22 83/09/26	50-369 70-27	P	8310050323 8310050334	8310050317 8310050327	83/09/21 83/09/26	CONTRACT 50-289	F
8310040488	8310040485	83/07/30	GA777		B310050337	8310050336	83/09/26	CONTRACT	
8310040492 8310040493	8310040484 8310040489	83/07/28 83/07/14	50-269 70-27	a	B310050344 B310050349	8310050340 8310050343	83/09/26 83/09/26	50-317 CONTRACT	F
8310040495 8310040499	8310040484 8310040356	83/09/28 83/09/19	50-269 50-321	Q Q	9310050362 9310050362	8310050357 8310050367	83/09/27 83/09/26	CONTRACT	
					5214045051				

ACCESS11	IN NUMBER			ACCESSIO	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
9310050370 9310050381 9310050382 9310050387 9310050388	8310050345 8310050373 8310050375 8310050377 8310050373	83/09/26 83/09/29 83/09/29 83/09/26 83/09/29	CONTRACT 50-443 50-440 CONTRACT 50-443	8310060103 8310060103 8310060129 8310060138 8310060145	8310060091 8310060109 8310060122 8310060117 8310060142	83/09/28 83/09/27 83/09/23 83/09/29 83/09/21	CONTRACT CONTRACT CONTRACT CONTRACT MISC
8310050389 8310050391 8310050392 8310050401 8310050412	8310050375 8310050383 8310050384 8310050386 8310050403	83/09/29 83/09/24 83/09/30 83/09/30 83/09/28	50-440 CONTRACT 50-413 50-413 50-445	8310040145 8310040148 8310040175 8310040177 8310040177	8310060158 8310060154 8310060171 8310060171 8310060140	83/09/21 83/09/17 83/09/26 83/09/26 83/09/23	50-331 G CONTRACT 50-251 S 50-251 S 27-39
8310050415 8310050419 8310050420 8310050432 8310050458	8310050386 8310050386 8310050407 8310050429 8310050456	83/07/30 83/07/30 83/07/22 83/07/30 83/07/26	50-413 50-413 CONTRACT 50-352 CONTRACT	8310040185 8310040170 8310040191 8310040193 8310040194	8310060171 8310060171 8310060178 8310060171	83/09/26 83/09/26 83/09/27 83/10/03 83/09/26	50-251 S 50-251 G CONTRACT 50-400 G 50-251 S
8310050460 8310050464 8310050465 8310050467 8310050468	8310050459 8310050462 8310050463 8310050466 8310050452	83/09/29 83/09/29 83/09/29 83/09/29 83/09/30	CONTRACT CONTRACT 50-255 (CONTRACT 50-454 (B310060199 B310060203 B310060212 B310060222 B310060238	8310040171 8310040188 8310040188 8310040188 8310040188	83/09/24 83/10/03 83/10/03 83/10/03	50-251 S 50-400 G 50-400 G 50-400 G 50-400 G
8310050469 8310050470 8310050473 8310050474 8310050475	8310050463 8310050463 8310050471 8310050472 8310050452	83/09/29 83/09/29 83/09/21 83/09/28 83/09/30	50-255 F 50-255 F 70-143 50-443 G 50-454 G	8310040250 8310040252 8310040257 8310040241 8310040242	8310060243 8310060245 8310060245 8310060258 • 8310060256	83/09/30 83/10/03 83/10/03 83/07/18 83/09/30	50-313 F 50-358 G 50-358 G 50-344 F 50-213 F
8310050477 8310050478 8310050480 8310050481 8310050485	8310050472 8310050461 8310050472 8310050461 8310050461	83/09/26 83/09/26 83/09/26 83/09/30	50-443 (50-155 1 50-443 (50-155 1	8310060263 8310060266 9310060268 8310060270 8310060270	8310060245 8310060245 8310060265 8310060267 8310060278	83/10/03 83/10/03 83/09/30 83/09/30 83/09/13	50-358 G 50-358 G 50-369 F PROJ CONTRACT
8310050486 8310050489 8310050491 8310050494 8310050495	8310050483 8310050483 8310050483 8310050483 8310050461	83/10/02 83/10/02 83/10/02 83/10/02 83/09/30	50-155 G 50-155 G 50-155 G 50-155 G	8310060271 8310060307 8310060328 8310060328 8310060328	8310060269 8310060282 8310060319 8310060318 8310060327	83/10/03 83/09/14 83/09/30 83/09/24 83/09/28	50-327 G 50-461 G 50-454 G CONTRACT 50-311 P
8310050497 8310050498 8310050500 8310050501 8310050502	8310050492 8310050493 8310050461 8310050483 8310050493	83/09/23 83/09/22 83/09/30 83/10/02 83/09/22	50-341 6 50-373 6 50-155 T 50-155 6 50-373 6	8310040327 8310040334 8310040349 8310040344 831004034	8310040004 8310040330 8310040341 8310040343 8310040340	83/10/03 83/09/30 83/09/22 83/10/04 83/09/21	50-315 P 50-305 Q 50-334 Q 50-443 U 50-155 Q
8310030504 8310030507 8310050514 8310050517 8310050521	8310050461 8310050483 8310050461 8310050512 8310050512	83/09/30 83/10/02 83/09/30 83/09/27 83/09/27	50-155 T 50-155 G 50-155 T 50-312 G 50-312 G	83 10060374 83 10060381 83 10060391 83 10060404 83 10060409	8310040360 8310060376 8310060379 8310060402 8310060375	83/09/21 83/09/27 83/08/19 83/06/10 83/10/03	50-155 G 50-298 S 50-382 G 50-313 P 50-461 G
8310050522 8310050530 8310050534 8310050535 8310050540	8310050518 8310050518 8310050524 8310050527 8310050538	83/09/23 83/09/23 83/09/29 83/09/29 83/09/22	50-358 0 50-356 0 50-237 P 70-143 50-356 0	B310060418 8310060453 B310060462 B310060464 B310060479	8310060413 8310060449 8310060449 8310060459 8310060474	83/09/30 83/09/23 83/09/23 83/09/30	50-261 P 50-483 G 50-483 G 50-382 G 50-315 F
8310050545 8310050546 8310050550 8310050552 8310050554	6310050539 6310050538 6310050549 6310050548 6310030548	83/09/28 83/09/22 83/09/28 83/09/29	CONTRACT 50-358 G CONTRACT 50-3 F 50-3 F	8310060483 8310060486 8310060492 8310060493 8310060494	8310060471 8310060481 8310060490 8310060487 8310060490	83/07/20 83/07/22 83/07/30 83/07/30	CONTRACT 50-387 F 50-335 F CONTRACT 50-335 F
8310050556 8310050558 8310050564 8310050567 8310060010	8310050553 8309300357 8310050559 8310050563 8310060007	83/09/27 83/09/29 83/09/21 83/07/29 83/09/28	CONTRACT 50-247 P 50-87 G 50-315 P CONTRACT	8310040494 8310040501 8310040502 8310040512 8310040523	8310060495 8310060499 8310060503 8310060507 8310060519	93/09/19 93/09/19 93/09/19 93/09/19	CONTRACT CONTRACT CONTRACT CONTRACT 50-280 F
8310060012 8310060014 8310060015 8310060019 8310060022	8310060004 8310060013 8310060017 8310060021	83/09/30 83/09/22 83/08/22 83/08/22	50-410 9 50-267 9 50-267 9 50-244 9 50-312 F	8310040532 8310040537 8310040538 8310040540 8310040545	8310040529 8310040534 8310040533 8310040535 8310040541	02/90/30 83/99/16 83/99/30 83/99/16	50~287 F 50~387 P 50~387 F 50~364 P 50~254 F
8310060026 8310060030 8310060037 8310060043 8310060046	8310060020 8310060024 8310060033 8310060031 8310060041	83/08/01 83/09/20 83/09/23 83/09/22 83/09/22	50-313 0 50-155 P 50-416 P 50-324 P 50-388 0	6310060548 6310060551 8310060552 8310060553 6310060551	8310060543 8310060549 8310060547 8310060543 8310060555	83/09/23 83/09/30 83/09/27 83/09/23 83/09/30	70-2988 50-287 F 50-261 P 70-2988 50-324 F
8310060048 8310060047 8310060050 8310060063 8310060064	8310060044 8310060031 8310060033 8310060058 8310060057	83/09/22 83/09/22 83/09/23 83/09/28 83/09/23	50-244 d 50-324 p 50-416 p 50-367 s 50-416 p	8310060564 8310060567 8310060576 8310060576 8310060578	8310060555 8310060555 8310060573 8310060566 8310060574	83/09/30 83/09/30 83/09/21 83/10/05 83/09/21	50-324 F 50-324 F 50-263 F 50-280 F 50-220 P
831 0040065 831 0040066 831 0040068 831 0040071 831 0040084	8310040040 8310040054 8310040059 8310040057 8310040081	83/09/19 83/10/03 83/09/28 83/09/23 83/09/20	XPORTLIC 50-324 P 50-367 B 50-416 P XPORTLIC	8310040584 8310040593 8310040594 8310040595 8310040400	8310060566 8310060591 8310060591 8310060590 8310060599	83/10/05 83/09/08 83/09/08 83/10/05 83/09/29	50-280 F 50-382 U 50-382 U 50-346 F 71-9070

ACCESSION I	NUMBER				ACCESS10	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	SVBJEC T CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEOORY
8310070007 8310070024 8310070025	8310040597 8310210134 8310070014 8310070020 8310070014	83/10/05 83/10/12 83/09/23 83/09/22 83/09/23	50-313 50-329 70-364 50-10 70-364	FA	8310070314 8310070331 8310070346 8310070348 8310070349	8310070311 8310070329 8310070342 8310070365 8310070363	83/09/29 83/09/09 83/09/27 83/09/29 83/09/13	50-263 P CONTRACT 50-397 A 50-244 P COMMISSION
8310070032 8310070035 8310070037	8310070016 8310070016 8310070016 8310070034 8310070016	83/09/23 83/09/23 83/09/23 83/09/28	70~344 70~364 70~364 40~8027 70~364		8310070372 8310070380 8310070384 8310070393 8310070409	8310070365 8310070377 8310070383 8310070391 8310070408	03/07/29 03/07/13 03/07/02 03/07/21 03/09/20	50-244 P COMMISSION COMMISSION 50-278 F 50-315 P
6310070042 6310070043 6310070048	B310070016 B310070016 B310070041 B310070045 B310070049	83/09/23 83/09/23 83/09/12 83/09/22	70~364 70-364 CDMMIS8I 50~293 50~364	0N P G	8310070415 8310070418 8310070429 8310070432 8310070433	8310070407 8310070403 8310070428 8310070431 8310070434	83/09/21 83/09/30 83/09/19 83/09/19	CDNTRACT 50-280 F CDNTRACT CDNTRACT CDNTRACT
8310070062 8310070082 8310070083	8310070049 8310070059 8310070076 8310070080 8310070087	83/09/22 83/09/26 83/09/30 83/09/28 83/08/02	50-364 71~9152 50-289 50-346 40~8794	В Б	8310110006 6310110008 6310110010 8310110010	8310110002 8310110002 8310110003 8310110004	83/09/15 83/09/15 83/09/23 83/07/01 83/07/01	COMMISSION COMMISSION CONTRACT 50-295 F 50-295 T
8310070092 8310070100 8310070103	8310070086 8310070087 8310070094 8310070097 8310070099	83/10/02 83/08/02 83/10/04 83/09/27 83/09/26	50-275 40-8794 50-275 50-272 CONTRACT	R R P	8310110012 8310110013 8310110014 8310110016 8310110016	8310110002 8310110004 8310110002 8310110002 8310110004	83/07/15 83/07/01 83/07/15 83/07/15 83/07/01	COMMISSION FOIA COMMISSION COMMISSION FOIA
8310070117 8 8310070117 8 8310070123 8	8310070104 8310070115 8310070114 8310070114 8310070125	83/09/21 83/09/21 83/09/19 83/09/19 83/09/30	TOPREP CONTRACT 50-220 50-220 MISC	() ()	8310110017 8310110018 8310110022 8310110023 6310110025	8310110007 8310110004 8310110007 8310110019 8310110021	83/07/15 83/07/01 83/07/15 83/10/05 83/07/15	FDIA FOIA 50-445 A 50-155 F FOIA
8310070143 (8310070144 (8310070145 (8310070128 8310070134 8310070140 8310070137 8310070121	83/09/24 83/10/04 83/09/22 83/10/04 83/09/17	50-370 50-249 50-382 70-143 CONTRACT	F F A	8200110188 9200110188 100010188 6200110188 6200110188	8310110027 8310110024 8310110027 8310110030 8310110035	83/10/05 83/09/23 83/10/05 83/06/30 83/10/05	50-305 F CONTRACT 50-305 F FOIA 50-331 F
8310070153 (8310070155 (8310070161 (8310070134 8310070146 8310070151 8310070156 8310070156	83/10/04 83/09/28 83/10/02 83/09/30 83/09/30	50~247 PR 50~275 50~10 50~10	F R O	8310110037 8310110038 8310110039 8310110048	8310110034 8310110035 8310110034 8310110034 8310110034	83/06/15 83/10/05 83/06/15 83/06/15 83/04/15	FOIA 50-331 F 50-275 P 50-275 P 50-275 P
8310070173 8310070175 8310070179	8310070156 8310070165 8310070172 8310070176 8310070176	83/09/30 83/09/29 83/09/28 83/09/22 83/09/22	50-10 CONTRACY CONTRACT 50-317 50-317		8310110051 8310110055 8310110057 8310110057 8310110060	8310110044 8310110042 8310110034 8310110044 8310110042	93/07/20 93/10/05 93/06/15 93/07/20 93/10/05	50-382 G 50-331 F 50-275 P 50-413 G 50-331 F
8310070163 8310070186 8310070188	8310070178 8310070182 8310070182 8310070184 8310070187	83/09/22 83/09/22 83/09/22 83/09/29 83/09/22	CONTRACT 50-335 50-335 50-498 CONTRACT	P P A	83101 10066 B3101 10069 83101 10070 83101 10074 83101 10076	8310110064 8310110064 8310110065 8310110062 8310110067	83/10/05 83/10/05 83/04/20 83/10/05 83/10/05	50-309 F 50-309 F FOIA 50-209 H 50-269 F
B310070198 (B310070200 (B310070203 (8310070193 8310070195 8310070197 8310070185 8310070201	83/09/27 83/09/26 83/09/28 83/09/22 83/09/28	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		831011077 8310110080 8310110080 8310110081 8310110084	8310110072 8310110072 8310110067 8310110078 8310110078	83/10/07 83/10/07 83/10/05 83/07/22 83/07/22	50-369 F 50-369 F 50-269 F 50-280 P 50-280 P
8310070212 (8310070217 (8310070220 (831007020A 831007020B 8310070213 8310070218 8310070214	83/09/22 83/10/01 83/09/22 83/09/22 83/09/29	CONTRACT 50-275 CONTRACT CONTRACT CONTRACT	R	8310110083 8310110087 8310110087 8310110092 8310110094	8310110082 8310110082 8310110086 8310110083 8310110091	83/10/05 83/10/05 83/09/28 83/10/05 83/10/05	50-346 F 50-346 F CONTRACT 50-443 Q 50-387 F
8310070227 (8310070230 (8310070231 (8310070222 8310070215 8310070224 8310070228 8310070234	83/09/29 83/10/04 83/09/26 83/09/29 83/09/29	CONTRACT 50-275 CONTRACT CONTRACT CONTRACT	R	8310110075 8310110077 831011010 8310110101 8310110103	8310110034 8310110065 8310110076 8310110065 8310110034	83/06/15 83/06/20 83/10/05 83/06/20 83/06/15	50-275 P FBIA 50-327 F FBIA FBIA
8310070246 8310070253 8310070257	8310070233 8310070241 8310070250 8310070251 8310070256	83/09/27 83/10/05 83/09/30 83/10/05 83/08/12	CONTRACT 50-324 50-387 50-275 70-143	G F R	8310110104 8310110107 8310110108 8310110110 8310110111	8310110102 8310110034 8310110065 8310110079 8310110034	93/10/05 83/06/15 83/06/20 83/10/05 83/06/15	50-320 F 50-275 P 40-17 50-123 V 50-275 P
8310070280 (8310070282 (8310070289 (8310070244 8310070277 8310070273 8310070286 8310070291	83/09/27 83/09/29 83/09/01 83/09/16 83/09/30	CONTRACT 50-321 50-324 50-528 50-324	P G 8 F	0310110113 0310110115 0310110116 0310110123 0310110123	8310110099 8310110065 8310110109 8310110121 8310110118	83/10/05 83/06/20 83/10/05 83/10/05	50-123 V 40-17 50-445 F 50-225 P 50-373 F
8310070295 8310070299 8310070302	8310070273 8310070291 8310070296 8310070296 8310070311	83/09/01 83/09/30 83/09/30 83/09/30 83/09/29	50-324 50-324 50-348 50-348 50-263	0 8 8 8	8310110125 8310110130 8310110131 8310110133 8310110134	8310110045 8310110045 8310110124 8310110128 8310110045	83/06/20 83/06/20 83/10/05 83/10/03 83/06/20	FOIA FOIA 50~346 F 50~361 P FOIA

	ON NUMBER				ACCESB10				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 19SUED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y
8310110136 8310110139 8310110141 8310110143 8310110147	8310110128 8310110065 8310110135	83/10/03 83/04/20 83/10/05 83/04/20 83/04/20	50-341 70-1487 50-269 FOIA FOIA	F	8310110423 8310110429 8310110434 8310110439 8310110440	8310110416 8310110424 8310110423 8310110436 8310110437	83/09/29 83/10/05 83/10/05 83/07/20 83/10/05	71-506 50-192 50-315 50-322 50-313	F F A F
6310110149 6310110151 6310110155 6310110165 8310110166	8310110142 8310110114 8310110150 8310110158 8310110161	83/10/04 83/10/05 83/10/05 83/10/05	TOPREP 50-275 50-400 50-443 50-29	U G P	8310110443 8310110455 8310110459 8310110459 8310110461	8310110430 8310110430 8310110430 8310110454 8310110430	83/06/14 83/06/14 83/06/14 83/09/21 83/06/14	50-316 FOIA FOIA 50-277 50-237	8 P
8310110170 8310110175 8310110177 8310110180 8310110183	8310110158 8310110158 8310110173 8310110174 8310110178	83/10/05 83/10/05 83/10/04 83/10/05 83/09/26	50-443 50-443 50-445 50-263 50-298	G G F F	B310110464 B310110467 B310110475 B310110478 B310110480	8310110430 8310110430 8310110470 8310110430 8310110470	83/06/14 83/06/14 83/06/15 83/06/14 83/06/15	FOIA 50-237 FOIA 50-237 FOIA	5
8310110184 8310110170 8310110192 8310110196 8310110199	9310110176 9310110196 9310110195 9310110197 9310110195	83/10/05 83/10/05 83/09/30 83/10/04 83/10/05	50-263 50-280 CONTRACT 50-344 50-259	F F F	8310110484 8310110484 8310110499 8310110499 8310110505	8310110430 8310110430 8310110430 8310110494 8310110503	83/06/14 83/06/14 83/06/14 83/09/27 83/07/08	POIA FOIA FOIA CONTRACT FOIA	
1020110108 620110108 4020110108 4120110108 4120110108	8310110189 8310110193 8310110204 8310110208 8310110222	83/10/04 83/10/05 83/10/05 83/10/06 83/09/30	50-344 50-259 50-244 50-358 50-264	P F B O P	8310110507 8310110509 8310110510 8310110511 8310110512	8310110498 8310110503 8310110504 8310110503 8310110508	83/07/27 83/07/08 83/09/26 83/07/08 83/09/20	50-202 FDIA CONTRACT FDIA CONTRACT	P
8310110231 8310110234 8310110239 8310110240 8310110254	8310110222 8310110234 8310110237 8310110237 8310110244	83/09/30 83/10/05 83/10/05 83/10/05	50-284 50-267 50-280 50-280 50-317	4444	8310110513 8310110518 8310110528 8310110528 8310110534	8310110503 8310110503 8310110516 8310110525 8310110523	83/07/08 83/07/08 83/09/29 83/10/05 83/06/15	FOIA FOIA CONTRACT CONTRACT FOIA	
8310110258 8310110257 8310110268 8310110271 8310110277	8310110244 8310110255 8310110263 8310110262 8310110275	83/10/05 83/10/05 83/09/26 83/10/06	50-317 50-155 50-260 CONTRACT 50-352	F F	8310110534 8310110538 8310110541 8310110544 8310110547	8310110521 8310110523 8310110523 8310110540 8310110523	83/09/28 83/06/15 83/06/15 83/09/30 83/06/15	50-259 FOIA FOIA 50-346 FOIA	P
8310110284 8310110287 8310110292 8310110293 8310110297	8310110275 8310110275 8310110275 8310110045 9310110291	83/10/04 83/10/04 83/10/04 83/10/04	50-352 50-352 50-352 50-155 50-352	0 0 T 0	8310110548 8310110547 8310110551 8310110562	8310110540 8310110533 8310110521 8310110545 8310110523	83/09/30 83/09/22 83/09/28 83/09/29 83/06/15	50-346 CONTRACT 50-259 50-269 FOIA	P P
8310110300 8310110301 8310110304 8310110307 8310110312	8310110291 8310110298 8310110302 8310110305 8310110291	83/10/05 83/10/04 83/10/04 83/10/05	50-352 50-275 50-456 50-352 50-352	00000	6310110569 8310110374 8310110375 6310110376 6310110579	8310110545 8308300763 8310110545 8310110523 8310110570	83/07/29 83/10/04 83/07/29 83/06/15 83/10/03	50-249 50-247 50-269 FOIA MISC	P P
8310110327 8310110330 8310110334 8310110335 8310110337	8310110325 8310110329 8310110333 8310110333 8310110336	83/10/05 83/10/05 83/09/20 83/09/20 83/09/13	50-254 50-265 50-315 50-315 CONTRACT	F P P	9310110582 8310110583 8310110588 8310110591 8310110594	8310110572 8310110523 8310110570 8310110584 8310110587	83/09/29 83/06/15 83/10/03 83/08/19 83/09/22	CONTRACT FOIA MISC FOIA COMMISSI	ÐМ
8310110340 8310110344 8310110351 8310110354 8310110366	8310110338 8310110342 8310110350 8310110352 8310110362	83/09/29 83/09/29 83/04/13 83/09/13 83/10/05	CONTRACT CONTRACT FOIA COMMISSIC 30-83	N F	8310110397 9310110414 8310110415 8310110416 8310110420	8310110587 8310110611 8310110612 8310110613	83/07/22 83/10/06 83/07/22 83/07/24 83/07/22	COMMISSIO 71-9128 COMMISSIO CONTRACT 50-54	ĐΝ
8310110369 8310110371 8310110375 8310110378 8310110384	8310110364 8310110364 8310110364 8310110364 8310110364	83/06/14 83/06/13 83/06/13 83/06/13	FOIA FOIA FOIA FOIA FOIA		9310110422 9310110423 9310110424 9310110427 9310110431	8310110619 8310110621 8310110624 8310110625 8310110628	83/10/06 83/10/06 83/09/21 83/10/06 83/09/30	71-6166 71-9127 WASTE MO' 71-9126 71-9108	7
6310110384 6310110387 8310110386 6310110390 8310110391	8310110380 8310110381 8310110364 8310110380 8310110364	83/10/05 83/09/29 83/06/13 83/10/05 83/06/13	50-272 FOIA	F a F	8310120002 8310120008 8310120007 8310120011 8310120012	8310120001 8310120004 8310120004 8310120006 8310120006	83/10/06 83/07/14 83/07/14 83/07/14 83/07/14	71-4478 50-201 50-201 50-201 50-201	1 1 !
8310110392 8310110393 8310110395 8310110399 8310110400	8310110380 8310110364 8310110364 8310110385 8310110364	83/10/05 83/06/13 83/06/13 83/09/30 83/06/13	FOIA FOIA	f	8310120013 8310120014 8310120015 8310120019	8310120004 8310120004 8310120004 8310120014 8310120010	83/07/14 83/07/14 83/07/14 83/07/07 83/09/20	50-201 50-201 50-201 FDIA CONTRACT	1 1 1
8310110404 8310110407 8310110409 8310110410 8310110412	8310110364 8310110150 8310110150 8310110402 8310110150	83/06/13 83/10/05 83/10/05 83/09/29 83/10/05	50-400 71-505	0	8310120020 8310120022 8310120023 8310120024 8310120024	8310120004 8310120014 8310120006 8310120021 8310120006	83/07/14 83/07/07 83/07/14 83/09/23 83/07/14	50-201 50-346 50-201 CONTRACT 50-201	I I
8310110414 8310110418 8310110417 8310110421 8310110422	8310110364 8310110413 8310110364 8310110413 8310110364	83/06/13 83/10/05 83/06/13 83/10/05 83/06/13	FOIA	F	8310120028 8310120030 8310120032 8310120034 8310120035	8310120006 8310120006 8310120006 8310120006 8310120033	83/07/14 83/07/14 83/07/14 83/07/14 83/09/28	50-201 50-201 50-201 50-201 CONTRACT	1 1 1

ACCESSIO	NUMBER				ACCEGBIA	IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1880ED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IRSUED	SV8JEC CATEGO	
8310120036 8310120039 8310120040 8310120041 8310120042	8310120006 8310120006 8310120038 8310120037 8310120006	83/07/14 83/07/14 83/09/29 83/09/28 83/07/14	50-201 50-201 CONTRAC 50-367 50-201	I I T P	B310120374 B310120377 B310120381 B310120384 B310120386	8310120369 8310120364 8310120376 8310120364 8310120376	83/10/03 83/10/07 83/10/07 83/10/07 83/10/07	50-29 50-352 50-275 50-352 50-275	P 0 0 0
8310120044 8310120045 8310120046 8310120047 8310120048	8310120006 8310120037 8310120043 8310120006 8310120043	83/07/14 83/09/28 83/09/30 83/07/14 83/09/30	50-201 50-387 50-327 50-201 50-327	I P I P	8310120388 8310120401 8310120410 8310120416 8310120422	8310120364 8310120302 8310120407 8310120406 8310120407	83/10/07 83/10/05 83/10/05 83/09/26 83/10/05	50-352 50-454 50-261 50-220 50-261	9 9 9
8310120049 8310120050 8310120055 8310120056 8310120081	8310120006 8310120043 8310120052 8310120043 8310120079	83/07/14 83/09/30 83/09/28 83/09/30 83/09/30	50-201 50-327 CONTRAC 50-327 50-313	P	8310120438 8310120445 8310120446 8310120449 8310120002	8310120436 8310120443 8310120443 8310120443 8310130001	83/10/07 83/09/28 83/09/28 83/09/28 83/10/07	50-416 50-316 50-316 50-316 50-155	P 8 8 7
8310120083 8310120085 8310120096 8310120111	8310120079 8310120082 8310120082 8310120090 8310120107	83/09/30 83/09/19 83/09/19 83/09/20 83/10/07	50-313 70-1100 70-1100 50-220 50-443	P Q Q	1100210128 8100110019 8301010026 8310130036 920010100	8310130008 8310130017 8310130025 8310130033 8310130029	83/10/03 83/10/05 83/09/20 83/09/30 83/09/29	WASTE #4 50-275 50-315 50-266 50-328	9T 0 0 P P
8310120128 8310120121 8310120126 8310120126	8310120107 8310120119 8310120107 8310120107 8310120125	83/10/07 83/10/07 83/10/07 83/10/07 83/10/07	50-443 50-322 50-443 50-443 50-287	0 0 0 R	B310130040 8310130043 8310130044 8310130054 8310130062	8310130033 8310130027 8310130033 8310130052 8310130052	83/09/30 83/09/29 83/09/30 83/09/30 83/09/30	50-266 50-328 50-266 50-266 50-266	P P P
9310120135 9310120137 9310120141 9310120143 9310120151	8310120107 8310120137 8310120107 8310120137 8310120147	83/10/07 83/09/10 83/10/07 83/09/10 83/10/07	50-443 50-27 50-443 50-29 50-443	9 0 0	8310130071 8310130076 8310130079 8310130093 8310130099	8310130047 8310130072 8310130098 8310130088	83/07/27 83/10/03 83/10/03 83/07/30 83/09/30	WASTE MO 50~282 50~282 50~320 50~320	P P P P
6310120154 6310120161 6310120194 6310120199 6310120201	8310120153 8310120140 8310120192 8310120198 8310120195	83/09/21 83/09/16 83/09/28 83/09/20 83/09/19	50-223 50-312 50-397 50-286 70-135	Q R Q Q	8310130104 8310130107 8310130109 8310130118 8310130117	B310130102 B310130103 B310130111 B310130111	83/10/06 93/10/07 83/07/30 83/07/29 93/07/29	50-344 50-338 50-368 50-3 50-3	F P P
8310120204 8310120207 8310120208 8310120209 8310120213	8310150515 8310150507 8310150502 8310150007 8310150505	B3/09/23 83/07/14 83/10/05 B3/09/29 83/09/22	50-116 50-201 50-220 50-305 50-277	0 1 P G	8310130121 8310130127 8310130131 8310130134 8310130141	8310130117 8310130126 8310130127 8310130128 8310130136	83/10/11 83/07/29 83/10/11 83/06/30 83/07/23	50-414 50-528 50-204 MISC 50-320	P A P
6310120214 6310120215 6310120216 6310120217 6310120218	8310120204 8310120211 8310120204 8310120211	83/09/29 83/10/08 83/09/29 83/09/22 83/10/08	50-305 50-155 50-305 50-277 50-155	F F G T	8310130148 8310130152 8310130154 8310130154 8310130157	8310130145 8310130150 8310130153 8310130150 8310130153	83/10/04 83/10/06 83/10/06 83/10/06 83/10/06	50-338 50-537 50-389 50-537 50-389	9 0 0
8310120220 8310120221 8310120223 8310120225 8310120227	8310120204 8310120211 8310120211 8310120204	83/09/29 83/10/08 83/09/29 83/10/08 83/09/29	50-305 50-155 50-305 50-155 50-305	F F T F	8310130145 8310130171 8310130178 8310130179 8310130184	8310130162 8310130168 8310130172 8310130174 8310130175	83/09/20 83/08/10 83/08/22 83/10/11 83/07/26	CONTRACT 50-285 50-482 50-155 50-289	а Т Р
8310120229 8310120232 8310120233 8310120235 8310120238	8310120201 8310120204 8310120211 8310120204 8310120206	83/10/08 83/09/29 83/10/08 83/09/29 83/09/29	50-155 50-305 50-155 50-305 50-305	T T F F	8310130190 8310130191 8310130200 8310130200	8310130174 8310130188 8310130188 8310130193 8310130198	83/09/22 83/09/30 83/09/30 83/09/28 83/09/30	50-498 50-334 50-334 50-267 CONTRACT	9 P P
8310120240 8310120243 8310120244 8310120247 8310120250	9310120206 9310120242 9310120241 9310120245 9310120248	83/09/29 83/05/20 83/10/06 83/10/07 83/09/28	50-305 50-247 50-305 50-344 50-397	F F Q	8310130202 8310130204 8310130203 8310130211 8310130213	8310130199 8310130193 8310130199 8310130204 8310130207	83/10/06 83/09/28 83/10/06 83/09/13 83/10/07	50-266 50-267 50-266 50-298 50-387	P P Q P
8310120248 8310120283 8310120288 8310120292 8310120311	8310120246 8310120279 8310120279 8310120279 8310120305	83/10/04 83/10/07 83/10/07 83/10/07 83/10/07	50-400 70-572 70-572 70-572 50-341	F Q	8310130218 8310130222 8310130225 8310130227 8310130228	8310130214 8310130217 8310130220 8310130221 8310130225	83/10/08 83/09/30 83/08/10 83/09/07 83/09/30	50-155 50-315 50-313 50-498 70-1113	T P G
6310120315 6310120314 6310120317 6310120327 6310120333	8310120329 8310120313 8310120313 8310120326	83/10/04 83/09/22 83/09/22 83/10/05 83/10/05	50-271 50-277 50-277 50-155 50-29	P R Q P	8310130230 8310130232 8310130237 8310130244 8310130248	9310130221 9310130229 9310130234 9310130241 9310130240	83/09/07 83/10/04 83/10/07 83/09/06 83/09/19	50-498 50-341 50-358 50-492 50-400	Q A A G E
8310120341 8310120345 8310120347 8310120351 8310120356	8310120337 8310120337 8310120342 8310120342 8310120350	83/10/05 83/10/05 83/09/28 83/09/28 83/10/04	50-305 50-305 50-361 50-361 50-348	P 8 8	8310130251 8310130252 8310130257 8310130257 8310130261	8310130241 8310130247 8310130240 8310130257 8310130240	93/09/04 93/09/19 83/09/19 83/09/13 83/09/19	50-482 50-458 50-400 50-482 50-400	9 9 6 6
8310120357 8310120358 8310120363 8310120368 8310120371	8310120348 8310120355 8310120350 8310120364 8310120350	83/10/06 83/10/06 83/10/04 83/10/07 83/10/04	70-1257 50-312 50-348 50-352 50-348	G G G	8310130266 8310130267 8310130267 8310130271 8310130273	8310130262 8310130240 8308300767 8310130240 8310130240	83/10/06 83/09/19 83/10/11 83/09/19 83/09/19	50-382 50-400 50-329 50-400 50-400	0 E A E

ACCESS1	DN NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	JRY
8310130274 8310130275 8310130277 8310130279 8310130280	8310130270 8310130272 8310130240 8310130272 8310130240	83/07/28 83/07/19 83/07/28	71-6346 50-267 50-400 50-267 50-400	р Е Р Е	8310140174 8310140172 8310140182 8310140185 8310140192	8310140163 8310140173 8310140176 8310140181	83/10/11 83/10/06 83/09/15 83/10/11 83/09/29	TOPREP 50-295 50-508 70-36 50-454	G A
8310130282 8310130284 8310130285 8310130287	8310130240 8310130281 8310130240 8310130240 8310130240	83/09/28 83/09/19 83/09/19	50~400 50~267 50~400 50~400 50~400	8 8 8 8	8310140195 8310140205 8310140207 8310140215 8310140215	8310140196 8310140205 8310140213	83/10/06 83/10/11 83/10/07 83/09/29 83/09/29	50-348 50-333 50-369 50-373 70-1388	P P P Q
8310130290 8310130291 8310130293 8310130294 8310130295	8310130240 8310130240 8310130240 8310130240 8310130292	83/09/1 9 83/09/19	50-400 50-400 50-400 50-400 50-285	6 E E	8310140285 8310140235 8310140236 8310140245	8310140224 8310140234 8310140239	83/10/06 83/10/06 83/09/26 83/09/30 83/09/27	50-348 50-348 50-271 TOPREP 50-271	8 9 0
8310130297 8310130298 8310130299 8310130301 8310130302	8310130294 8310130294 8310130294 8310130294	83/10/07 83/10/07 83/10/07 83/10/07 83/10/07	50-155 50-155 50-155 50-155 50-155	P P P	8310140258 6310140244 8310140246 8310140247 8310140248	8310140261 8310140243 8310140262	83/09/30 83/09/29 83/10/11 83/09/30 83/10/11	50-331 50-354 50-302 50-237 50-302	R Q R Q R
8310130303 8310130304 8310130306 8310130309 8310130311	8310130300 8310130300 8310130307 8310130310	83/09/28 83/09/28 83/10/06 83/10/06 83/10/06	50~247 50~267 50~285 50~285 50~409	P F F	8310140271 8310140273 8310140274 8310140279 8310140297		83/09/29 83/10/06 83/09/23 83/09/26 83/08/22	50-254 50-329 50-529 50-272 40-4492	Q A B Q
8310130313 8310130323 8310130324 8310130328 8310130333	8310130330 0450510158 0450510158 0450510158	83/10/06 83/10/11 83/09/28 83/09/28 83/09/16	50-317 50-206 50-267 50-267 50-313	F F F G	8310170002 8310170003 8310170007 8310170033 8310170037	8310170001 8310170003 8310170004 8310170029 8310170029	83/09/0 7 83/10/06 83/10/06 83/06/29 83/06/29	50-289 50-317 50-289 FOIA FOIA	P F
8310130335 8310130335 8310130385 8310130386 8310130389	8310130330 8310130334 8310130380 8310130384 8310130388	83/09/16 83/09/09 83/09/29 83/09/16 83/09/30	50-313 PROJ CONTRACT 71-9160 CONTRACT		8310170044 8310170047 8310170050 8310170055 8310170057	8310170029 8310170029 8310170029 8310170029 8310170029	83/06/29 83/06/29 83/06/29 83/06/29 83/06/29	FOIA FOIA FOIA FOIA	
8310130406 8310130407 8310130410 8310130416 8310130418	8310130404 8310130404 8310130407 8310130415 8310130417	83/09/30 83/09/30 83/08/29 83/09/23 83/09/29	CONTRACT CONTRACT POLA 50-295 CONTRACT	P	6310170059 6310170045 6310170045 8310170067 6310170072	8310170029 8310170029 8310170029 8310170060 8310170029	83/06/29 83/06/29 83/06/29 83/09/30 83/06/29	FOIA FOIA FOIA CONTRACT	г
8310140004 8310140013 8310140024 8310140032 8310140035	8310140003 8310140002 8310140022 8310140031 8310140026	83/09/26 83/09/28 83/08/23 83/10/13	50-311 50-305 50-445 50-498 50-289	0 0 T 0	8310170084 8310170090 8310170090 8310170094 8310170098	8310170082 8310170029 8310170088 8310170029 8310170091	83/09/30 83/06/29 83/10/06 83/06/29 83/10/05	CONTRACT FOLA 50-335 FOLA 50~338	т Р В
8310140037 8310140041 8310140042 8310140044 8310140046	8310140031 8310140040 8310140040 8310140031 8310140040	83/08/23 83/08/23 83/10/10 83/08/23 83/10/10	50-498 50-498 50-315 50-498 50-315	0 P 0 P	8310170100 8310170102 8310170107 8310170107 8310170110	8310170094 8310170029 8310170094 8310170091 8310170029	83/10/07 83/06/29 83/10/07 83/10/05 63/06/29	50-313 F01A 50-313 50-338 F01A	P P 8
8310140047 8310140049 8310140050 8310140052 6310140055	8310140031 8310140036 8310140031 8310140031 8310140054	83/08/23 83/10/11 83/08/23 83/10/07	50-498 50-10 50-498 50-498 50-358	0 0 0 0 A	8310170116 8310170118 8310170129 8310170123 8310170125	8310170029 8310170112 8310170029 8310170029 8310170119	83/06/29 83/10/11 83/06/29 83/06/29	FOIA CONTRACT FOIA FOIA 50-331	r P
8310140052 8310140070 8310140074 8310140078 8310140080	8310140031 8310140047 8310140074 8310140074	83/08/23 83/10/13 83/10/10 83/10/10 83/10/11	50-498 50-454 50-155 50-155 50-302	@ G T T P	8310170128 8310170130 8310170130 8310170136 8310170140	8310170029 8310170029 8310170078 8310170029 8310170029	83/06/29 83/06/29 83/06/07 83/06/29 83/06/29	FOIA FOIA FOIA FOIA	
8310140085 8310140088 8310140095 8310140101 8310140103	8310140083 8310140031 8310140031 8310140097 8310140097	63/10/12 63/08/23 63/08/23 63/10/07 63/10/07	50-445 50-478 50-478 50-352 50-352	G G A	8310170142 8310170144 8310170147 8310170148 8310170149	8310170078 8310170029 8310170078 8310170145 8310170141	83/04/07 83/04/29 83/04/07 83/10/12 83/10/11	FOIA FOIA FOIA 50-388 50-416	A Q
9310140104 9310140119 9310140134 9310140136 9310140136	8310140079 8310140117 8310140132 8310140135 8310140137	83/10/05 83/10/05 83/10/05	50-10 50-275 50-320 50-358 50-316	Q R Q Q S	8310170150 8310170151 8310170154 8310170154 8310170157	8310170029 8310170143 8310170078 8310170078 8310170143	83/06/29 83/09/23 83/06/07 83/06/07 83/09/23	FOIA 40-86 FOIA FOIA 40-86	
8310140139 8310140140 8310140141 8310140143 8310140148	8310140137 8310140137 8310140137 8310140143 8310140147	83/10/05 83/10/05 83/10/05 83/10/07 83/09/29	50-314 50-314 50-314 50-269 50-461	8 8 9 0	8310170158 8310170160 8310170164 8310170164 8310170165	8310170155 8310170078 8310170027 8310170029 8310170143	83/10/03 83/06/07 83/06/29 83/06/29 83/09/23	70-1113 FOIA FOIA FOIA 40-86	
8310140150 8310140156 8310140165 8310140166 8310140170	8310140147 8310140155 8310140163 8310140162 8310140132	83/09/29 83/10/11 83/10/11 83/09/27 83/09/27	50-461 50-387 TOPREP 50-289 50-320	0 P 0	8310170166 8310170168 8310170169 8310170171 8310170175	8310170029 8310170163 8310170029 8310170029 8310170170	83/06/29 83/10/07 83/06/29 83/06/29 83/10/04	FOIA 50-309 FOIA FOIA 71-5595	G.

ACCESSIO	N NUMBER				ACCESSIO	IN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1880ED	BUBJEC	
8310170174 9310170180 8310170182 8310170184 8310170191	6310170029 6310170029 6310170029 6310170078 6310170078	83/06/29 83/06/29 83/06/29 83/06/07	FOIA FOIA FOIA FOIA		8310170350 8310170352 8310170354 8310170356 8310170358	6310170078 6310170029 8310170078 6310170344 6310170029	83/06/97 83/06/29 83/06/07 83/10/10 83/06/29	FOIA FOIA FOIA 50-454 FOIA	9
8310170194 8310170195 8310170196 8310170198 8310170202	8310170078 8310170192 8310170078 8310170190 8310170078	83/06/07 83/09/30 83/06/07 83/09/30 83/06/07	FOIA 71-9105 FOIA 50-423 FOIA	A	8310170359 8310170362 9310170363 8310170367 8310170370	8310170078 8310170029 8310170078 8310170078 8310170029	83/06/07 83/06/29 83/06/07 83/06/07 83/06/29	FOIA FOIA FOIA FOIA	
6310170203 6310170205 6310170208 6310170210 6310170213	8310170197 8310170078 8310170078 8310170078 8310170078	83/09/23 83/06/07 83/06/07 83/06/07 83/06/07	70-698 FOIA FOIA FOIA FOIA		8310170372 8310170374 8310170376 8310170378 8310170379	8310170078 8310170029 8310170078 8310170373 8310170029	83/06/07 83/06/29 83/06/07 83/10/14 83/06/29	FOIA FOIA FOIA 50-244 FOIA	ŧ
8310170217 8310170220 8310170223 8310170224 8310170224	8310170078 8310170078 8310170078 8310170078 8310170078	83/06/07 83/06/07 83/06/07 83/10/07 83/06/07	FOIA FOIA FOIA 50~335 FOIA	F	8310170381 8310170385 8310170388 8310170398 8310170391	8310170078 8310170078 8310170029 8310170078 8310170029	83/06/07 83/06/07 83/06/29 83/06/07 83/06/29	FOIA FOIA FOIA FOIA	
6310170227 6310170230 6310170231 8310170234 6310170237	8310170214 8310170222 8310170078 8310170233 8310170029	83/10/10 83/10/07 83/06/07 83/09/29 83/06/29	50-275 50-335 FOIA 70-1257 FOIA	R F	9310170392 8310170396 8310170399 8310170402 8310170403	8310170029 8310170029 8310170078 8310170029 8310170078	83/06/29 83/06/29 83/06/07 83/06/29 83/06/07	FOIA FOIA FOIA FOIA	
8310170238 8310170241 8310170242 8310170244 8310170245	8310170189 8310170078 8310170029 8310170028 8310170078	83/10/12 83/06/07 83/06/29 83/10/07 83/06/07	50-259 FDIA FDIA 50-250 FDIA	Q F	8310170406 8310170410 8310170413 8310170413 8310170417	8310170029 8310170029 8310170029 8310170029 8310170412	83/06/29 83/06/29 83/06/29 83/06/29 83/10/11	FOIA FOIA FOIA FOIA 50-445	Q.
8310170246 8310170247 8310170250 8310170252 8310170253	8310170239 8310170029 8310170078 8310170029 8310170249	83/10/11 83/06/29 83/06/07 83/06/29 83/08/17	70-27 FOIA FOIA FOIA 70-1113		8310170418 8310170422 8310170423 8310170423 8310170429	8310170029 8310170029 8310170416 8310170078 8310170029	83/06/29 83/06/29 83/10/10 83/06/07 83/06/29	FOIA FOIA 50~348 FOIA FOIA	P
8310170254 8310170254 8310170259 8310170265 8310170267	8310170133 8310170078 8310170029 8310170029 8310170078	83/10/11 83/06/07 83/06/29 83/06/29 83/06/07	50-327 FOIA FOIA FOIA FOIA	P	8310170431 8310170432 8310170433 8310170434 8310170434	8310170029 8310170428 8310170078 8310170029 8310170078	83/06/29 83/09/21 83/06/07 83/06/29 83/06/07	FOIA 50-397 FOIA FOIA FOIA	a
8310170269 8310170274 8310170275 8310170277 8310170279	8310170029 8310170076 8310170029 8310170078 8310170078	83/06/27 83/06/07 83/06/27 83/06/07	FDIA FOIA FOIA FOIA FOIA		6310170438 6310170439 8310170441 8310170444 6310170445	8310170029 8310170434 8310170078 8310170029 8310170029	83/06/29 83/10/11 83/06/07 83/06/29 83/06/29	FOIA 50-329 FOIA FOIA FOIA	٨
8310170280 8310170282 8310170284 8310170286 8310170288	8310170029 8310170078 8310170029 8310170078 8310170029	83/06/29 83/06/07 83/06/29 83/06/07 83/06/29	FOIA FOIA FOIA FOIA		8310170447 8310170449 8310170450 8310170452 8310170453	8310170078 8310170076 8310170029 8310170029 8310170078	83/04/07 83/04/07 83/04/29 83/04/29 83/04/07	FOIA FOIA FOIA FOIA	
8310170290 8310170293 8310170294 8310170296 8310170297	8310170078 8310170078 8310170027 8310170287 8310170078	83/06/07 83/06/07 83/06/29 83/10/12 83/06/07	FOIA FOIA FOIA 50-395 FOIA	P	8310170454 8310170455 8310170457 8310170460 8310170461	8310170451 8310170078 8310170029 8310170078 8310170029	83/10/11 83/06/07 83/06/29 83/06/07 83/06/29	50-358 FOIA FOIA FOIA FOIA	a
8310170300 8310170301 8310170303 8310170305 8310170307	8310170029 8310170289 8310170029 8310170029 8310170304	83/06/29 83/10/12 83/06/29 83/06/29	FDIA 50-395 FDIA FOIA 50-289	P	8310170462 8310170463 8310170464 8310170466 8310170467	8310170078 8310170029 8310170459 8310170459 8310170078	83/06/07 83/06/29 83/05/30 83/05/30 83/06/07	FOIA FOIA 50-329 50-329 FOIA	Q Q
8310170307 8310170311 8310170314 8310170316 8310170318	8310170029 8310170304 8310170029 8310170078 8308300764	83/06/29 83/10/05 83/06/29 83/06/07 83/10/07	FOIA 50-289 FOIA FOIA 50-275	p T	8310170470 8310170472 8310170475 8310170477 8310170479	8310170468 8310170076 8310170076 8310170076 8310170473	83/09/28 83/06/07 83/06/07 83/06/07 83/09/22	30-528 FOIA FOIA FOIA 50-275	a
8310170319 8310170320 8310170323 8310170324 8310170325	8310170029 8310170078 8310170029 8310170078 8310170222	83/06/29 83/06/07 83/06/29 83/06/07 83/10/07	FOIA FOIA FOIA FOIA 50-335	F	8310170482 8310170483 8310170484 8310170487 8310170494	6310170078 6310170476 6310170478 6310170078 6310170078	83/06/07 83/09/29 83/10/07 83/06/07 83/06/07	FDIA 30~263 50~362 FOIA FOIA	9
8310170324 8310170328 8310170331 8310170332 8310170336	8310170029 8310170029 8310170078 8310170029 8310170029	83/06/27 83/06/27 83/06/07 83/06/27 83/06/27	FOIA FOIA FOIA FOIA		8310170497 8310170499 8310170502 8310170503 8310170505	8310170078 8310170495 8310170076 8310170492 8310170078	83/06/07 83/10/10 83/06/07 83/10/11 83/06/07	FOIA 50-397 FOIA 50-346 FOIA	A P
8310170340 8310170343 8310170345 8310170347 8310170349	8310170029 8310170029 8310170029 8310170029 8310170344	83/06/29 83/06/29 83/06/07 83/06/29 83/10/03	FOIA FOIA FOIA FOIA 71-9182		B310170507 B31017050B B310170510 B310170516 B310170518	8310170481 8310170504 8310170078 8310170078 8310170515	83/10/07 83/10/04 83/06/07 83/06/07 83/10/03	50-397 50-245 FOIA FOIA 50-358	Q P

ACCESSI	ON NUMBER				ACCEBSI	ON NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DAYE IBBUED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8310170521 8310170522 8310170527 8310170528 8310170529	8310170078 8310170580 8310170078 8310170078 8310170525	93/10/13 93/06/07 93/06/07	FOIA 50-261 FOIA FOIA 50-454	9	8310170681 8310170684 8310170689 8310170690 8310170690	8310170078 8310170078 8310170683 8310170686 8310170491	83/06/07 83/06/07 83/10/12 83/10/03 83/10/06	FOIA FOIA 50-445 50-320 70-143	Ţ
8310170532 8310170534 8310170535 8310170537 8310170538	831017007B 8310170513 831017007B 831017007B 831017007B	83/10/03 83/06/07 83/06/07	FOIA 50-329 FOIA FOIA 50-329	a Q	8310170697 8310170711 8310170719 8310170736 8310170738	8310170694 8310170707 8310170710 8310170710 8310170735	83/09/29 83/10/13 83/10/06 83/10/06 83/10/06	COMMISS 50~373 50~369 50~369 50~148	ION F P P F
8310170542 8310170544 8310170546 8310170549 8310170550	8310170539 8310170513 8310170078 8310170513 8310170111	B3/06/07	50-275 50-329 FOIA 50-329 CONTRACT	0 0 0	8310170743 8310170746 8310170730 8310180015 8310180016	8310170741 8310170741 8310170748 8310180011 8310180010	83/10/04 83/10/04 79/11/19 83/10/05 83/09/29	50-321 50-321 71-6601 70-143 COMMISS	F F
8310170555 8310170559 8310170560 8310170562 8310170564	8310170513 8310170513 8310170513 8310170558 8310170553	93/10/03 93/10/03 93/10/03 93/10/03	50-329 50-329 50-329 50-329 50-329	0 0 0 0	8310180031 8310180034 8310180037 8310180042 8310180097	8310180027 8310180029 8310180029 8310180029 8310180092	83/10/05 83/10/13 83/10/13 83/10/13 70/01/88	70-1100 50-341 50-341 50-341 50-289	4 4 4 4
8310170547 8310170570 8310170571 8310170572 8310170574	8310170513 831017007 <i>6</i> 8310170513 8310170558 831017007 <i>8</i>	83/10/03 83/04/07 83/10/03 83/09/29 83/04/07	50-329 FDIA 50-329 50-329 FOIA	Q Q Q	8310180102 6310180105 8310180129 8310180139 8310180146	8310180098 8310180101 8310180120 8310180132 8310180132	83/09/30 83/09/30 83/10/12 83/10/12	50-220 CONTRACT 70-734 50-352 50-352	r P G G
8310170575 8310170578 8310170580 8310170585 8310170587	8310170513 8310170078 8310170078 8310170078 8310170078	83/10/03 83/06/07 83/06/07 83/06/07	50-329 FOIA FOIA FOIA FOIA	Q	8310180148 8310180147 8310180152 8310180153 8310180155	9310180143 9310180144 9310180132 9310180150 9310180151	83/10/07 83/09/27 83/10/12 83/10/12 83/10/05	XPORTL 10 50-458 50-352 50-443 XPORTL 10	0
8310170590 8310170591 8310170593 8310170594 8310170598	8310170078 8310170583 8310170078 8310170589 8310170583	83/04/07 83/10/03 83/04/07 83/10/14 83/10/03	FDIA 50-329 FOIA 50-341 50-329	Q K G	8310180157 8310180161 8310180163 8310180170 8310180175	8310180147 8310180156 8310180158 8310180165 8310180168	83/10/13 83/07/08 83/10/14 83/10/13 83/10/13	CONTRACT 50-298 50-445 50-443 CONTRAC	9
8310170600 8310170602 8310170606 8310170608 8310170610	8310170587 8310170583 8310170583 8310170543 8310170583	83/10/14 83/10/03 83/10/03 83/10/12 83/10/03	50-341 50-329 50-329 50-400 50-329	K @ @	8310180177 8310180183 8310180209 8310180219 8310180219	8310180173 8310180179 8310180204 8310180208 8310180214	83/10/04 83/08/12 83/09/27 83/10/12 83/09/29	50-361 50-445 50-213 50-335 50-445	P 6 P 0
8310170611 8310170615 8310170616 8310170618 8310170619	8310170607 8310170078 8310170583 8310170078 8310170607	83/10/10 83/06/07 83/10/03 83/06/07 83/10/10	50-316 FOIA 50-329 FOIA 50-316	6 9	8310180223 8310180224 8310180227 8310180228 8310180227	8310180214 8310180222 8310180218 8310180225 8310180214	83/09/29 83/10/15 83/10/03 83/09/22 83/09/29	50-445 50-155 50-445 50-298 50-445	0 0 0 0
8310170620 8310170621 8310170622 8310170625 8310170627	8310170543 8310170612 8310170583 8310170078 8310170583	83/10/12 83/09/29 83/10/03 83/06/07 83/10/03	50-400 50-397 50-329 FOIA 50-329	9	8310180232 8310180237 8310180244 8310180257	8310180225 8310180234 8310180242 8310180251 8310180250	83/09/22 83/10/14 83/09/20 83/10/12 83/10/04	50-298 50-352 50-285 50-272 50-373	а 9 9 К 0
8310170628 8310170630 8310170632 8310170633 8310170634	8310170078 8310170543 8310170626 8310170623 8310170583	83/06/07 83/10/12 83/10/12 83/09/30 83/10/03	FOIA 50-400 50-400 40-3392 50-329	9	8310180279 8310180279 8310180313 8310180313 8310180318	8310180275 8310180271 8310180216 8310180312 8310180312	83/10/14 83/10/06 83/10/07 83/09/30 83/09/30	50-454 Ga777 Ga777 Ga777 Ga777	¢
8310170635 8310170636 8310170637 8310170640 8310170643	8310170078 8310170629 8310170078 8310170078 8310170629	83/06/07 83/09/28 83/06/07 83/06/07 83/09/28	FOIA 50-341 FOIA FOIA 50-341	a o	920010168 220010169 320010169 310180321	8310180317 8310180314 8310180214 8310180317 8310180312	83/10/14 83/10/11 83/10/07 83/10/14 83/09/30	50-482 50-334 GA999 50-482 GA999	E Q E
8310170645 8310170647 8310170650 8310170651 8310170652	8310170078 8310170637 8310170078 8310170078 8310170078	83/06/07 83/10/11 83/06/07 83/10/10 83/06/07	FOIA 50-320 FOIA 50-275 FOIA	P R	8310180327 8310180332 8310180340 8310180341 8310180342	8310180324 8310180216 8310180216 8310180331 8310180339	83/10/13 83/10/07 83/10/07 83/10/03 83/10/13	50-250 GA999 GA999 50-397 50-445	P G
8310170454 8310170455 8310170459 8310170440 8310170443	8310170644 8310170533 8310170533 8310170078 8310170653	83/09/23 83/01/04 83/01/04 83/02/07 83/09/28	70-2960 50-333 50-333 FDIA 50-508	F G	0210180350 6210180351 8210180354 6210180358 6310180358	8310180346 8310180252 8310180346 8310180347 8310180346	83/09/30 83/10/14 83/09/30 83/10/07 83/09/30	GA777 50-456 GA777 50-387 GA777	c Q
8310170645 8310170667 8310170668 8310170670 8310170671	8310170078 8310170662 8310170078 8310170662 8310170666	83/06/07 83/09/28 83/06/07 83/09/28 83/10/13	FDIA 50-440 FDIA 50-440 50-456	a a a	8310180341 8310180345 8310180347 8310180349 8310180371	8310180354 8310180360 8310180362 8310180354 8310180360	83/10/14 83/10/03 83/10/14 83/10/14 83/10/03	50-275 QA799 50-344 50-275 QA999	T G T
8310170473 8310170475 8310170476 8310170477 8310170478	8310170078 8310170669 8310170078 8310170078 8310170674	83/06/07 83/08/29 83/06/07 83/06/07 83/09/16	FOIA 70-984 FOIA FOIA 50-312	o	8310180372 8310180373 8310180375 8310180376 8310180380	8310180366 8310180368 8310180354 8310180360 8310180377	83/10/05 83/10/12 83/10/14 83/10/03 83/10/07	50-287 50-443 50-275 0A779 50-177	G T G

ACCESSION NUMBER		ACCESSION NUMBER	
PRINCIPAL DAT		PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUE	D CATEGORY
8310180383 8310180377 83/10 8310180384 8310180382 83/10 8310180399 8310180391 83/10 8310180400 8310180395 83/00 8310180401 8310180394 83/10	703 50-5 705 50-272 730 9A999	8310180624 8310180610 83/09/ 61 8310180626 8310180610 83/09/ 6310180627 8310180610 83/09/ 8310180628 8310180625 83/09/ 8310180628 8310180625 83/09/	01 50-275 P 01 50-275 P 01 50-329 0
8310180404 8310180394 83/10 8310180406 8310180394 83/10 8310180407 8310180394 83/11 8310180408 8310180405 83/05 8310180410 8310180405 83/05	706 GA999 706 GA999 730 50-285	8310180430 8310180625 83/09/ 8310190034 8310180625 83/09/ 8310190036 8310180625 83/09/ 8310190039 8310180625 83/09/ 8310190042 8310180625 83/09/	01 50-329 A 01 50-329 A 01 50-329 A
8310180411 8310180394 83/10 8310180414 8310180412 83/05 8310180415 8310180396 83/10 8310180431 8310180429 83/05 8310180434 8310180432 83/10	/22 50-498 /04 QA999 /30 QA999	8310190044 8310190040 83/10/ 8310190047 8310180625 83/09/ 8310190053 8310190047 83/09/ 8310190057 8310190043 83/10/ 8310190105 8310190077 83/10/	/01 50-329 A /13 FDIA /14 50-280 P
8310180438 8310180435 83/10 8310180442 8310180441 83/09 8310180445 8310180441 83/09 8310180447 8310180439 83/09 8310180450 8310180441 83/05	/20 GA999 /20 GA999 /28 50-213	8310190126 8310190125 83/10/ 8310190130 8310190112 83/10/ 8310190135 8310190128 83/10/ 8310190136 8310190133 83/10/ 8310190142 8310190133 83/10/	713 50-338 P 704 50-410 Q 705 50-443 Q
8310180453 8310180444 83/10 8310180455 8310180451 83/09 8310180457 8310180452 83/10 8310180445 8310180454 83/10 8310180472 8310180464 83/09	/19 GA999 /04 50-155 /13 50-329	8310170143 8310170137 83/10/ 8310170154 8310170152 83/10/ 8310170157 8310170152 83/10/ 8310170167 8310170166 83/09/ 8310170168 8310170157 83/10/	11 50-508 A 104 50-307 Q 108 50-346 R
8310180481 8310180480 83/10 8310180483 8310180479 83/10 8310180484 8310180478 83/10 8310180485 8310180480 83/10 8310180486 8310180477 83/10	/13 50-293 /13 50-445 /14 50-387	8310190170 8310190146 83/09/ 8310190175 8310190172 83/10/ 8310190180 8310190172 83/10/ 8310190185 8310190176 83/10/ 8310190185 8310190182 83/10/	05 50-443 G 05 50-443 G 05 50-352 G
83101804BB 8310180478 83/10 8310180492 8310180490 83/10 8310180493 8310180480 83/10 8310180495 8310180490 83/10 8310180497 8310180480 83/10	/07 50-266 /14 50-387 /07 50-266	8310190203 B310190174 B3/10/ B310190208 B310190199 B3/09/ B310190240 B310190237 B3/10/ B310190251 B310190244 B3/10/ B310190270 B310190244 B3/09/	/30 50-327 P /13 71-5595 /05 50-334 9
B310180498	/07 50-246 /14 50-387 /07 50-266	8310170281 8310170274 83707 831017028B 8310170285 80707 9310170272 8310170291 837107 9 8310170273 8310170294 837107 9 8310170313 8310170307 837077	/19 71-9145 /14 50-313 F /14 50-313 F
8310180505 8308300775 83/10 8310180504 8310180500 83/10 8310180509 8310180507 83/10 8310180510 8310180507 83/10 8310180511 8308300775 83/10	/13 50-285 /14 50-387 /14 50-387	P 8310190325 8310190322 83/09, 0 8310190327 8310190322 83/09, P 8310190344 8310190340 83/09, P 8310190359 8310190340 83/09, P 8310190360 8310190340 83/09,	/13 FOIA /15 50-282 8 /15 50-282 8
8310180514 8310180507 83/10 8310180517 8308300775 83/10 8310180518 8310180507 83/10 8310180519 8310180515 83/0 8310180520 8310180507 83/10	/14 50-275 /14 50-367 /22 GA999	P 8310170361 8310170340 83/07/ P 8310200005 8310200003 83/10. P 8310200006 8310200003 83/10. 8310200010 8310200007 83/10. P 8310200021 8310200007 83/10.	/14 50-409 P /14 50-409 P /03 50-334 Q
8310180521 8308300775 83/10 8310180523 8310180507 83/10 8310180525 8310180507 83/10 8310180527 8310180524 83/00 8310180528 8310180524 83/00	/14 50-387 /14 50-387 /30 9A999	P 8310200038 8310200032 83/09, P 8310200042 8310200036 83/10, P 8310200044 8310200032 83/09, 8310200048 8310200032 83/09, 8310200049 8310200032 83/10,	/06 50-412 M /15 50-289 P /15 50-289 P
B310180530 B310180524 B3/0 ¹ B310180532 B310180524 B3/0 ¹ B310180538 B310180534 B3/0 ¹ B310180548 B310180537 B3/0 ¹ B310180557 B310180554 B3/1 ¹	/30	8310200053 8310200045 83/10. 8310200055 8310200051 83/10. P 8310200057 8310200045 83/10. P 8310200048 8310200042 83/10. 8310200073 8310200042 83/10.	/13 50-225 P /05 50-440 9 /07 COMMISSION
8310180365 8310180362 83/10 8310180370 8310180367 83/0 8310180372 8310180367 83/10 8310180375 8310180371 83/0 8310180376 8310180373 83/10	/22 50-346 /03 50-298 /06 FOIA	B310200082 B310200077 B3/10. P B310200090 B310200088 B3/07. P B310200092 B310200088 B3/07. B310200103 B310200097 B3/10. B310200107 B310200097 B3/10.	/30 50-271 9 /30 50-271 9 /03 50-317 0
8310180580 8310180577 83/1 8310180585 8310180581 83/0 8310180585 8310180583 83/1 8310180596 8310180592 83/1 8310180598 8310180583 83/1	/11 CONTRACT /06 50-305 /13 CONTRACT	B310200148 8310200124 83/10 8310200164 8310200157 83/10 8310200168 8310200166 83/10 8310200167 8310200163 83/07 8310200172 8310200162 83/10	/05 50-373 A /12 50-324 /30 70-820
8310180602 8310180595 8370 8310180605 8310180601 8370 8310180606 8310180604 8371 8310180607 8310180601 8370 8310180613 8310180610 8370	/30 PR /11 50-424 /30 PR	8310200181 8310200177 83/07 8310200183 8310200180 83/10 A 8310200184 8310200178 83/10 8310200184 8310200182 83/10 8 8310200170 8310200178 83/10	/14 50-275 Q /16 50-275 T /17 50-331 F
8310180615 8310180610 83/0 8310180617 8310180610 83/0 8310180619 8310180610 83/0 8310180621 8310180610 83/0 8310180623 8310180610 83/0	/01 50-275 /01 50-275 /01 50-275	P 8310200192 8310200198 83/10 P 8310200195 8310200178 83/10 P 8310200196 8310200142 83/10 P 8310200198 8310200188 83/10 P 8310200199 8310200193 83/09	/16 50-275 T /13 50-277 G /14 50-344 F

	ON NUMBER				ACCESSIO	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEG		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT CATEGOR	
B310200200 B310200203 B310200203 B310200212 B310200214	8310200194 8310200201	83/10/04 83/10/04 83/10/11 83/10/06	50-397 50-397 50-461 50-358 50-206	0 K A	8310210119 8310210129 8310210132 8310210143 8310210145	8310210114 8310210124 8310210124 8310210134 8310210150	83/09/20 83/10/07 83/10/17 83/10/12 83/10/17	50-302 50-333 50-2 50-329 CONTRACT	P P P A
8310200215 8310200222 8310200224 8310200227 8310200228	8310200209 8310200209 8310200220 8310200209 8310200220	83/10/05 83/10/14 83/10/06	50-358 50-256 50-206 50-358 50-206	A G A G	8310210163 8310210173 8310210180 8310210191 8310210192	8310210158 8310210168 8310210164 8310210187 8310210186	83/10/07 83/10/14 83/09/12 83/10/12 83/10/17	50-184 50-397 CONTRACT 50-315 50-413	F A S T
8310200230 8310200232 8310200233 8310200234 8310200237	8310200218 8310200209 8310200209 8310200209	83/10/14 83/10/12 83/10/06	50-358 50-206 50-336 50-358 50-289	A Q P A G	8310210194 8310210196 8310210197 8310210198 8310210198	8310210185 8310210184 8310210167 8310210187 8310210187	83/10/17 83/10/19 83/10/12 83/10/14 83/10/12	50-309 50-445 50-915 CONTRACT 50-315	0 0 5
8310200244 8310200245 8310200248 8310200250 8310200255	8308300777 8310200241 8308300777 8310200242 8310200242		50-454 50-317 50-454 50-123 50-123	0 0 0	8310210202 8310210208 8310210210 8310210211 8310210212	8310210187 8310210185 8310210207 8310210205 8310210206	83/10/12 83/10/17 83/10/05 83/10/05 83/10/12	50-315 50-309 50-317 CONTRACT 50-316	8 0
8310200261 8310200263 8310200264 8310200268 8310200270	8310200257 8310200257 8310200257 8310200242 8310200218	83/10/13 83/10/13 83/10/13 83/10/07 83/09/14	50-277 50-277 50-277 50-123 50-289	R R G	8310210215 8310210217 8310210219 8310210220 8310210225	8310210204 8310210214 8310210204 8310210214 8310210224	83/10/12 83/10/05 83/10/18 83/10/05 83/09/28	50~316 50~244 50~454 50~244 50~460	8 Q Q A
8310200280 8310200323 8310200357 8310200359 8310200364	8310200276 8310200318 8310200356 8310200356 8310200356	83/10/07 83/10/13 83/09/23 83/09/23 83/09/23	50-358 50-311 FOIA FOIA FOIA	QI P	8310210229 8310210235 8310210239 8310210239 8310210240	8310210227 8310210233 8310210234 8310210237 8310210238	83/10/13 83/10/14 83/10/13 83/10/11 83/10/11	50-275 50-275 50-454 50-149 50-334	4 4 4 4
8310200373 8310200380 8310200383 8310200384 8310200387	8310200371 8310200375 8310200379 8310200375 8310200379	83/09/30 83/10/06 83/09/15 83/10/06 83/09/15	40-7869 50-329 FOIA 50-329 FOIA	A	8310210241 8310210242 8310210246 8310210250 8310210256	8310210228 8310210228 8310210245 8310210243 8310210254	83/10/15 83/10/15 83/10/14 83/10/17 83/10/07	50-275 50-275 50-241 50-443 50-228	T P G
8310200391 8310200392 8310200394 8310200397 8310200398	8310200379 8310200375 8310200379 8310200395 8310200379	83/10/06 83/10/06 83/09/15 83/10/07 83/09/15	FOIA 50-329 FOIA 50-440 FOIA	A	8310210261 8310210266 8310210268 8310210274 8310210275	8310210259 8310210265 8310210264 8310210269 8310210272	83/10/13 83/10/07 83/10/17 83/10/03 83/10/17	50-348 50-309 50-324 50-277 50-329	P G P G R
8310200400 8310200401 8310200404 8310200407 8310200415	8310200395 8310200379 8310200395 8310200395 8310200408	83/10/07 83/09/15 83/10/07 83/10/07 83/10/06	50-440 FOIA 50-440 50-440 71-9164	A A	8310210277 8310210278 8310210279 8310210283 8310210288	8310210270 8310210269 8310210270 8310210280 8310210284	83/10/17 83/10/03 83/10/17 83/10/14 83/10/14	50-321 50-277 50-321 50-287 50-275	P Q P Q R
8310200417 8310200423 8310200424 8310200430 8310200443	8310200410 8310200410 8310200416 8310200426 8310200437	83/10/17 83/10/17 83/10/17 83/10/17 83/10/17	50-155 50-155 50-373 50-289 50-320	F F F F	8310210294 8310210319 8310210333 8310210347	8310210286 8310210314 8310210331 8310210341 8310210341	83/10/17 83/10/05 83/09/09 83/09/30 83/09/30	50-307 80-329 71-9181 50-328 50-328	Q Q P P
8310200449 8310200455 8310200457 8310200459 8310200461	8310200442 8310200442 8310200442 8310200442 8310200442	83/10/07 83/10/07 83/10/07 83/10/07 83/10/07	COMMISSI 50-424 COMMISSI COMMISSI COMMISSI	U NO1 NO3	8310210355 8310210357 8310210338 8310210388 8310210370	8310210350 8310210350 8310210350 8310210359 8310210366	83/10/14 83/10/14 83/10/14 83/10/18 83/10/17	50-275 50-275 50-275 50-346 50-285	T T F F
8310200462 8310200463 8310200464 8310200466 8310200467	8310200458 8310200442 8310200442 8310200442 8310200442	83/07/12 83/10/07 83/10/07 83/10/07 83/10/07	CONTRACT COMMISSI COMMISSI COMMISSI	ON ON	8310210371 8310210377 8310210378 8310210381 8310210382	8310210350 8310210374 8310210350 8310210350 8310210350	83/10/14 83/10/17 83/10/14 83/10/14 83/10/14	50-275 50-295 50-275 50-275 50-275	ፕ ፑ ፐ ፐ
8310200469 8310210001 8310210013 8310210034 8310210045	8310200442 8310200379 8310210008 8310210032 8310210043	83/10/07 83/09/15 83/09/26 83/09/01 83/10/13	50-275 FOIA 50-285 50-259 50-397	U Q Q	8310210383 8310210385 8310210386 8310210387 8310210390	8310210362 8310210350 8310210362 8310210350 8310210384	83/10/17 83/10/14 83/10/17 83/10/14 83/10/17		ド 下 ド ド
8310210048 8310210060 8310210061 8310210069 8310210070	8310210046 8310210055 8310210053 8310210065 8310210064	83/10/14 83/10/04 83/10/07 83/10/13 83/10/17	50-261 50-397 50-10 50-358 50-324	P G R G	8310210391 8310210392 8310210394 8310210398 8310210398	8310210350 8310210350 8310210389 8310210389 8310210350	83/10/14 83/10/14 83/10/17 83/10/17	50-275 50-275 50-305 50-305 50-275	T T F F T
8310210074 8310210078 8310210087 8310210093 8310210097	8310210053 8310210071 8310210096 8310210091 8310210093	83/10/07 83/10/17 83/10/18 83/10/06 83/09/30	50-10 50-259 CONTRACT CONTRACT CONTRACT	g g	8310210413 8310210415 831024002 831024003 8310240014	8310210412 8310210414 8310240001 8310240001 8310240012	83/10/17 83/10/17 83/10/05 83/10/05 83/08/10	50-170 50-482 50-301 50-301 50-413	F G G T
8310210100 8310210107 8310210109 8310210110 8310210113	8310210095 8310210104 8310210105 8310210105	83/09/23 83/09/28 83/10/13 83/10/17 83/10/17	70-2760 40-8502 50-424 50-358 50-358	M G G	8310240017 6310240018 8310240021 8310240022 8310240024	8310240012 8310240012 8310240012 8310240012 8310240012	83/08/10 83/08/10 83/08/10 83/08/10 83/08/10	50-413 50-413	ፕ ፕ ፕ ፕ ፕ

Section Sect	ACCESSION						CESSION				
	ENCLOSURE					ENCLDE	BURE				,
Baltonesian	B310240030							H310240267			
	831024003B	8310240012	83/08/10	50-413	T						
	8310240040 8310240043										
September Sept											
		8310240042	83/10/18	50-266	0						
## 10140009 ## 10140012 02/04/10 02-0419 T											
Bil	8310240058	8310240012	83/08/10	50-413	Т	B31025	5001B				
## 101040068 ## 101040012 ## 2789110 ## 101040068 ## 101040012 ## 10104012 ## 101040											
Sil											
	B310240065	8310240012	83/08/10	50-413	т	831025	50030	8310520058	83/07/15	FOIA	
\$10200077											
Sil											
Sal Carbon Sal	8310240081	8310240066	83/10/19	50~546		631025	50107	6310250102	83/10/07	HASTE HOT	٢
Silo240078 Sil					Q						g
\$10040009		8310240090									P
Silogation	8310240076	8310240097	83/10/12	CONTRACT	•	B31025	50136	0310250123	83/09/21	GA999	
Billogation											Œ
B310240119 B310240130 B3710707 50~325 F B31022014 B31023016 B3710707 50~235 F B310220173 B31023016 B3710707 50~235 T B310220118 B310230174 B3710707 50~235 T B310220118 B3710707 50~235 T B310220118 B3710708 50~235 T B310220118 B371020118 B3710708 50~235 T B371020118 B371020											
Salidation Sal	8310240109	8310240103	83/10/07	50-336	P	831025	50174	8310250166	83/10/04	50-259	Q
Signor S											
Saligazio Sali											
Silogato	8310240130	8310240127	83/10/19	CONTRACT	•	831025	50193	8310250191		50-255	a
Silo240144 Silo240139 Silo240149 Sil											
B310240173 B310240174 B3710706 B3710717 B370706 B3710717 B3710706 B3710717 B37107106 B3710711 B37107106 B37107106 B3710711 B37107106 B37107107 B37107107 B37107106 B37107107											Р
B310240173 B310240171 B3/07/06 F0TA B310250211 B310250210 B3110250213 B310250210 B310240171 B3/07/06 F0TA B310240181 B3/07/01 B3/07/01 F0TA B310240181 B310230234 B3/10/07 S0-287 B310240187 B3/07/01 F0TA B310240181 B31023034 B3/10/07 S0-287 B310240187 B3/07/01 B3/07/01 F0TA B310240181 B31023034 B3/10/07 S0-287 B310240181 B3/07/01 B3/07/01 B0TA B3/07	8310240145	8310240143	83/10/17	50-354	F	B31025	50203	8310250191	83/10/20	50-255	a
85.10240171 89.10240179 89.10240179					Р						a
B310240178 B310240178 B310240178 B3707705 FULA B310250218 B310250228											
B310240182 B310240178 B3/07/00 FOLA B310250240 B310250240 B3/10/07 SO-257 G B310240194 B310240171 B3/07/00 FOLA B310250241 B310250224 B3/10/07 SO-257 G B310240195 B310240197 B3/07/00 FOLA B310250247 B310250234 B3/10/07 SO-257 G B310240197 B310240197 B3/07/00 FOLA B310250234 B3/10/07 SO-257 G B310240197 B310240197 B3/07/00 SO-258 G B310240197 B3/07/00 SO-258 G B310240197 B3/07/00 SO-258 G B310240197 B3/07/00 SO-258 G B310240207 B310240197 B3/07/08 SO-258 G B310240217 B310240197 B3/07/08 SO-258 G B310240221 B310240197 B3/07/08 SO-258 G B310240222 B310240197 B3/07/08 SO-258 G B310240223 B310240197 B3/07/08 SO-258 G B310240234 B310240234 B310240234 B310240234 B310240234 B310240	B310240179	8310240178	83/09/30	50-546	A	831025	50235	0310250226	B3/10/11	50-346	P
Salidado 194					A						
## ## ## ## ## ## ## ## ## ## ## ## ##											
B310240210 B310240197 B3/09/08 50-528 A B310250286 B310250248 B3/09/27 50-269 C	8310240195	8310240193	B3/07/01	FOIA	_	931025	50251	8310250234	93/10/07	50-259	Q
S310240207 S310240197 S3709708 F01A S310250299 S310250242 S310250242 S310240197 S3709708 F01A S310240212 S310240197 S3709708 S0-528 Q S310250242 S310250242 S310250242 S310250242 S310240197 S3709708 S0-528 Q S310250249 S310250242 S310250244 S310250344											
8310240207 8310240197 83/09/08 50-528 0 8310250248 8310250262 83/08/24 50-414 0 8310240215 8310240197 83/09/08 50-528 0 8310250249 8310250262 83/08/24 50-414 0 8310250249 8310250240 8310250249 83102					A						
B310240217 B310240197 B3709708 B0-528 Q B310250270 B310250262 B3708708 B0-418 Q B310240197 B3709708 B0-528 Q B310250271 B310250273 B310250273 B3708708 B0-628 Q B310250273 B3708708 B0-628 Q B310250274 B3708708 B0-628 Q B3708708 B0-628 B0-628 Q B0-628 B0-	8310240209	8310240197	83/09/08	FOIA	_	931025	50267	8310250265	93/10/06	0A999	
B310240219 B310240197 B3709708 B309708 B309708 B309708 B310250278 B											
B310240219 B310240197 B3709708 B3709											_
## ## ## ## ## ## ## ## ## ## ## ## ##	8310240219	8310240197	83/09/08	50-528	A	831025	50278	8310250275	83/10/20	50-282	Œ
8310240223 8310240197 83709708 50-528 4 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250299 8310250293											
8310240227 8310240197 8310240197 8310240197 8310240197 8310240197 8310240234 8310230302 8310230303 8310230											
8310240238 8310240234 8310240234 83102708 FOIA 8310250304 8310250303	8310240227	8310240197	83/09/08	50-528	a	831025	50300	8310250299	83/09/28	50-327	a
8310240241 8310240197 83709708 50-828 U 8310250313 8310250301 8310250301 83710719 50-438 0 8310240247 8310240249 8310240249 8310250318 8310250301 83710719 50-438 0 8310240249 8310240249 8310240248 8310250328 8310250301 83710719 50-438 0 8310240250 8310240248 8310240249 8310250320 8310250320 8310250320 83009723 50-280 0 8310240251 8310240279 8310240279 8310240279 8310250322 8310250322 8310250322 8310250324 831025					A						-
8310240846 8310240197 83/09708 50-928 U 8310240281 8310250301 8310250301 8310240301 8310250324 8310250324 8310250324 8310250324 8310250325											
8310240250 8310240248 83/10/04 70-1143 8310250328 8310250320 8310250320 83/07/23 50-260 0 8310240251 8310240177 83/07/08 50-528 4 8310250322 8310250322 83/07/03 83/07/07 50-261 0 8310240259 8310240257 8310240257 8310240257 8310250322 83/07/07 50-275 T 8310240244 8310240258 83/07/14 50-250 F 8310250332 8310250322 83/07/07 50-248 0 8310240254 8310240258 83/10/14 50-250 F 8310250332 8310250322 83/08/31 50-241 0	8310240246	B310240197	83/09/08	50-528	Ü	831025	50318	8310250301	83/10/19	50-438	q
8310240259 8310240259 83710713 71-5450 8310250332 8310250332 8310250326 83710719 50-275 T 8310240261 8310240258 83710714 50-250 P 8310250333 8310250321 83710719 50-2438 Q 8310240244 8310240258 83710714 50-250 P 8310250339 8310250322 83708731 50-243 Q					٨						
8310240261 8310240258 83/10/14 50-250 P 8310250333 8310250301 83/10/19 50-438 Q 8310240264 8310240258 83/10/14 50-250 P 8310250339 8310250322 83/08/31 50-261 Q					Q						
	8310240261	8310240258	83/10/14	50~250		831025	50333	8310250301	83/10/19	50-438	G
					٣						4

ACCE891	ON NUMBER				ACCESS	ON NUMBER			
ENCLOSURE	PR INCIPAL DOCUMENT	DATE IBSUED	GUBJE		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8310250344 8310250347 8310250348 8310250351 8310250352	6310250336 6310250336 6306310027 6306310027 8310250336	83/10/04 83/10/04 83/10/18 83/10/18		P P	631025054 6310250550 6310250550 8310250556	8310250544 8310250538 8310250545 8310250547	83/10/11 83/10/20 83/10/18 83/07/26 83/10/18	50-293 50-263 50-498 70-1113 50-498	K G G
8310250359 8310250361 8310250363 8310250364 8310250368	8310250357 8310250354 8310250354 8310250342 8310250362	83/10/20 83/10/05	0A999 50-373 50-269 50-352 0A999	0 0	8310250560 8310250561 8310250576 8310250576	8310250538 8310250543 8310250564	83/09/19 83/10/20 83/10/06 83/10/18 83/09/21	50-321 50-263 50-327 50-409 50-324	0 0 P 0
8310250374 8310250380 8310250381 8310250384 8310250385	8310250350 8310250373 8310250375 8310250375 8310250377	83/10/13 83/10/03 83/10/13 83/10/13	50-302 50-438 50-322 50-322 GA999	Q Q T T	8310250582 8310250584 8310250596 8310250600 8310250601	8310250576 8310250588	83/10/21 83/10/21 83/10/17 83/09/16 83/10/17	70-2977 50-358 50-261 50-312 50-261	9 9 9
8310250387 8310250392 8310250394 8310250399 8310250401	8310250374 8310250383 8310250388 8310250395 8310250391	83/09/19 83/09/30 83/09/20 83/10/07 83/10/21	50-348 50-413 50-280 GA999 50-315	g g g F	8310250602 8310230603 8310230604 8310250608 8310250610	8310250593 8310250597 8310250592 8310250588 6310250592	83/10/19 83/10/04 83/10/12 83/10/17 83/10/12	50-327 50-193 GA999 50-261 GA999	0 0
8310250404 8310250404 8310250408 9310250407 8310250420	8310250378 8310250397 8310250405 8310250400 8310250413	83/09/26 83/10/04 83/10/12 83/10/05 83/10/12	50-413 50-370 QAY99 50-335 QA999	a a	8310250611 8310250616 8310250616 8310250617 8310250618	8310250593 8310250405 8310250592 8310250593 8310250588	83/10/19 83/10/18 83/10/12 83/10/19 83/10/17	50-327 50-254 GA999 50-327 50~261	G G
8310250423 8310250424 8310250428 8310250431 8310250435	8310250416 8310250417 8310250414 8310250426 8310250432	83/09/16 83/09/15 83/10/05 83/10/11 83/10/06	50-275 50-313 50-338 50-250 GAP99	9 9 9	8310250620 8310250621 8310250624 8310250625 8310250627	8310250588 8310250615 8310250593 8310250591 8310250588	83/10/17 83/09/27 83/10/19 83/09/16 83/10/17	50-261 50-335 50-327 50-312 50-261	0 0 P 0
8310250436 8310250437 8310250438 8310250441 8310250442	631 0250403 831 0250426 831 0250429 831 0250432 831 0250426	83/10/05 83/10/11 83/10/04 83/10/06 83/10/11	50-327 50-250 50-260 6A999 50-250	0 0 0	8310250631 8310250642 8310250642 8310250646 8310250652	8310250591 8310250428 8310250436 8310250435 8310250435	83/09/14 83/10/05 83/09/30 83/10/17 83/10/17	50-312 50-400 50-461 50-269 50-269	P Q Q Q
8310250445 8310250446 8310250447 8310250449 8310250452	8310250440 8310250426 8310250432 8310250426 8310250437	83/10/18 83/10/11 83/10/06 83/10/11 83/09/21	70-820 50-250 GA779 50-250 50-416	a a	8310250441 8310250644 8310250667 8310250667 8310250669	8310250456 8310250435 8310250435 8310250460 8310250488	63/10/20 63/10/20 63/10/17 63/10/20 83/10/27	50-483 50-483 50-267 50-285 50-331	4 4 6 4
8310250454 8310250457 8310250460 8310250464 8310250466	8310250403 8310250451 8310250451 8310250459 8310250403	83/10/05 83/10/17 83/10/17 83/09/22 83/10/05	50-327 50-324 50-324 50-280 50-327	0 0 0 0	B310250670 8310250682 6310250683 831026006 B310260021	8310250668 8310250681 8310250673 8310260003	83/10/27 83/10/14 83/10/21 83/09/26 83/07/15	50-331 50-244 50-59 40-2259 FOIA	F F
8310250468 8310250473 8310250477 8310250479 8310250480	8310250451 8310250451 8310250451 8310250472 8310250474	83/10/17 83/10/17 83/10/17 83/10/06 83/10/11	50-324 50-324 50-324 50-348 50-324	0 0 0 0	8310240023 8310240025 8310240026 8310240027 8310240028	8310240019 8310240019 8310240008 8310240008 8310240019	89/07/15 83/07/15 83/07/15 83/06/23 83/07/15	FOIA FOIA FOIA 50-270 FOIA	8
8310250484 8310250485 8310250488 8310250490 8310250492	8310250475 8310250472 8310250474 8310250472 8310250403	83/10/03 83/10/06 83/10/11 83/10/06 83/10/05	50-327 50-348 50-324 50-348 50-327	0 0 0 0	8310260030 8310260031 8310260032 8310260033 8310260034	8310260019 8310260008 8310260019 8310260019 8310260008	83/07/13 83/06/23 83/07/15 83/07/15 83/06/23	FOIA FOIA FOIA FOIA	
8310250493 8310250494 8310250498 8310250501 8310250502	9310250474 9310250475 9310250472 9310250474 9310250475	83/10/11 83/10/03 83/10/06 83/10/11 83/10/03	50-324 50-327 50-348 50-324 50-327	9 9 9	8310260035 8310260037 8310260040 8310260040 8310260041	8310260019 8310260019 8310260019 8310260019	83/07/15 83/06/23 83/07/15 83/07/15 83/06/23	FOIA FOIA FOIA FOIA	
8310250504 8310250507 8310250509 8310250510 8310250515	8310250486 8310250497 8310250475 8310250503 8310250503	83/10/17 83/10/19 83/10/03 83/10/12 83/10/12	50-454 50-327 50-327 GA999 GA999	Q A	8310260042 8310260043 8310260044 8310260047 8310260048	8310260036 8310260017 8310260017 8310260017 8310260019	83/10/05 83/07/15 83/07/15 83/07/15 83/07/15	XPORTLIC FOIA FOIA FOIA FOIA	
8310250517 8310250518 8310250520 8310250524 6310250525	8310250475 8310250511 8310250513 8310250514 8310250503	83/10/03 83/10/06 83/10/18 83/10/07 83/10/12	50-327 GA799 50-454 50-369 GA799	0 0	8310240049 8310240050 8310240051 8310240052 8310240053	8310240008 8310240008 8310240017 8310240019 8310240008	83/06/23 83/06/23 83/07/15 83/07/15 83/06/23	FOIA FOIA FOIA FOIA	
8310250526 8310250528 8310250529 8310250530 8310250534	8310250511 8310250516 8310250512 8310250514 8310250514	83/10/06 83/10/06 83/10/04 83/10/07 83/10/07	GA999 50-335 50-272 50-369 50-369	G G Q	8310240054 8310240055 8310240058 8310240058 8310240059	8310260045 8310260017 8310260017 8310260008 8310260017	63/09/22 63/07/15 63/07/15 63/06/23 63/07/15	70-1143 FOIA FOIA FOIA FOIA	
8310250535 8310250540 8310250541 8310250542 8310250548	8310250522 8310250514 8310250537 8310250538 8310250522	83/10/20 83/10/07 83/06/13 83/10/20 83/10/20	50-155 50-369 6A999 50-263 50-155	0 0 0	8310240041 8310240042 8310260045 8310260046 8310240047	8310260008 8310260019 8310260019 8310260008 8310260019	83/04/23 83/07/15 83/07/15 83/06/23 83/07/15	FOIA FOIA FOIA FOIA	

ACCESSION	I NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGORY	PRINCIPAL DATE ENCLOBURE DOCUMENT IBGUED	BUBJECT CATEGORY
8310260069 8310260070 8310260071 8310260072 8310260073	8310260008 8310260019 8310260008 8310260019 8310260068	83/06/23 83/07/15 83/06/23 83/07/15 83/10/06	FOIA FOIA FOIA FOIA XPORTLIC	8310260173 8310260019 83/07/1 8310260174 8310260019 83/07/1 6310260175 8310260019 83/07/1 8310260176 8310260019 83/07/1 8310260177 8310260019 83/07/1	5 FOIA 5 FOIA 5 FOIA
8310260075 8310260076 8310260077 8310260076 8310260080	8310260008 8310260019 8310260008 8310260008	83/06/23 83/07/15 83/07/15 83/06/23 83/06/23	FOIA FOIA FOIA FOIA	8310240178 8310240019 83/07/1 8310240179 8310240154 83/10/1 8310240180 8310240019 83/07/1 8310240182 8310240019 83/07/1 8310240183 8310240019 83/07/1	2 70-27 5 FOIA 5 FOIA
8310260081 8310260082 8310260083 8310260084 8310260085	8310260019 8310260008 8310260074 8310260019 8310260008	83/07/15 83/06/23 83/07/30 83/07/15 83/06/23	FOIA FOIA WASTE MOT FOIA FOIA	8310260184 8310260019 83/07/1 8310260185 8310260019 83/07/1 8310260188 8310260019 83/07/1 8310260191 8310260019 83/07/1 8310260173 8310260019 83/07/1	5 FOIA 5 FOIA 5 FOIA
8310260086 8310260087 8310260089 8310260090 8310260091	8310260008 8310260019 8310260008 8310260019 8310260008	83/06/23 83/07/15 83/06/23 83/07/15 83/06/23	FOIA FOIA FOIA FOIA	8310260194 8310260190 83/10/0 8310260195 8310260019 83/07/1 8310260197 8310260019 83/07/1 8310260199 8310260019 83/07/1 8310260201 8310260187 83/10/1	5 FOIA 5 FOIA 5 FOIA
8310240092 8310240095 8310240094 8310240094	8310260008 8310260019 8310260008 8310260008	83/06/23 83/07/15 83/07/15 83/06/23 83/07/15	FOIA FOIA FOIA 50-10 FOIA	8310260204 8310260017 83/07/1 8310260207 831026019 83/07/1 8310260208 8310260187 83/10/1 8310260209 8310260202 83/10/2 8310260210 8310260209 83/07/i	5 FDIA 7 50-443 A L 50-400 O
8310240100 8310240102 8310240103 8310240105 8310240107	8310260019 8310260019 8310260019	83/07/15 83/07/15 83/06/23 83/07/15 83/07/15	FOIA FOIA FOIA FOIA FOIA	8310260211 8310260206 83/10/0 8310260213 8310260019 83/07/1 8310260218 8310260019 83/07/1 8310260221 8310260215 83/10/0 8310260223 8310260019 83/07/1	5 FOIA 5 FOIA 5 70-1113
0310260108 8310260111 8310260112 8310260114 8310260115	8310260019 8310260019 8310260019 8310260104 8310260019	83/07/15 83/07/15 83/07/15 83/10/12 83/07/15	FOIA FOIA FOIA 70-1151 FOIA	8310240224 8310240017 83/07/1 8310240227 8310240017 83/07/1 8310240234 8310240017 83/07/1 8310240238 8310240017 83/07/1 8310240239 8310240212 83/10/1	5 FOIA 5 FOIA 5 FOIA
8310260116 8310260119 8310260121 8310260121	8310260019 8310260019 8310260019 8310260019 8310260113	83/07/15 83/07/15 83/07/15 83/07/15 83/10/17	FOIA 70-1144 FOIA FOIA 50-397	8310260240 8310260019 83/07/1 8310260242 8310260237 83/10/1 8310260243 8310260019 83/07/1 8310260246 8310260237 83/10/1 8310260250 8310260019 83/07/1	4 50-344 P 5 FOIA 4 50-344 P
8310260124 8310260125 8310260126 8310260127 8310260128	8310260019 8310260019 8310260019 8310260019	83/07/15 83/07/15 83/07/15 83/07/15	FOIA FOIA FOIA FOIA 70-1144	8310240252 8310240019 83/07/1 8310240258 8310240019 83/07/1 8310240261 8310240254 83/10/2 8310240264 8310240260 83/10/1 8310240265 8310240019 83/07/1	5 FOIA 4 50-443 0 4 50-275 R
8310260129 8310260130 8310260131 8310260132	8310260019 8310260019 8310260019 8310260019	83/07/15 83/07/15 83/07/15 83/07/15 83/07/15	FOIA FOIA FOIA FOIA	8310260264 8310260254 83/10/2 8310260267 8310260259 83/10/1 8310260271 8310260019 83/07/1 8310260272 8310260019 83/10/2 8310260275 8310260019 83/07/1	4 96-400 E 5 FOIA 4 50-443 Q
8310260135 8310260136 8310260137 8310260138 8310260139	8310260019 8310260019 8310260019 8310260019 8310260019	83/07/15 83/07/15 83/07/15 83/07/15 83/07/15	FOIA FOIA FOIA FOIA	6310260278 8310260019 83/07/1 6310260280 831026019 83/07/1 8310260281 8310260279 83/08/2 8310260282 8310260019 83/07/1 8310260283 8310260259 83/10/1	5 FOIA 6 50-445 A 5 FOIA
8310240140 8310240142 8310240144 8310240145 8310240146	8310260019 8310260019 8310260019 8310260141 8310260019	83/07/15 83/07/15 83/07/15 83/10/20 83/07/15	FOIA FOIA FOIA 50-324 70-1144	8310260284 8310260279 83/08/2 8310260285 8308310032 83/10/2 8310260286 8310260279 83/08/2 8310260287 8310260019 83/07/1 8310260288 8310260019 83/07/1	4 50-327 A 6 50-445 A 5 70-1144
8310260148 8310260149 8310260153 8310260155 8310260157	8310260141 8310260019 8310260019 8310260019	83/10/20 83/07/15 83/07/15 83/07/15 83/07/15	50-324 70-1144 FOIA FOIA FOIA	8310260293 8310260019 83/07/1 8310260296 8310260290 83/10/1 8310260298 8310260019 83/07/1 8310260300 8310260019 83/07/1 8310260303 8310260019 83/07/1	9 CONTRACT 5 FOIA 5 FOIA
8310260158 8310260159 8310260160 8310260161 8310260162	8310260019 8310260019 8310260156 8310260019	83/07/15 83/07/15 83/10/13 83/07/15 83/07/15	FOIA FOIA 50-328 FOIA FOIA	8310260307 8310260297 83/10/0 8310260308 8310260306 83/10/2 8310260317 8310260019 83/07/1 8310260321 8310260019 83/07/1 8310260325 8310260019 83/07/1	4 50-269 0 5 FDIA 5 FDIA
8310260163 8310260164 8310260165 8310260166 8310260167	8310260019 8310260019 8310260019 8310260154 8310260019	83/07/15 83/07/15 83/07/15 83/10/12 83/07/15	FOIA FOIA 70-1144 70-27 FOIA	8310260327 8310260019 83/07/1 8310260329 8310260019 83/07/1 8310260332 8310260019 83/07/1 8310260335 8310260311 83/10/1 8310260337 8310260019 83/07/1	5 FOIA 5 FOIA 7 50-327 A
8310260168 8310260169 8310260170 8310260171 8310260172	8310260019 8310260019 8310260019 8310260019	83/07/15 83/07/15 83/07/15 83/07/15	FOIA FOIA FOIA FOIA	#310260338 #310260019 #37/07/1 #310260339 #310260334 #37/07/1 #310260340 #310260331 #37/07/1 #310260341 #310260019 #37/07/1 #310260342 #310260334 #37/07/1	4 50-297 P 9 50-327 A 5 FOIA

ACCESS1	ON NUMBER				ACCEG	SION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC*	RY	ENCLOSUR		DATE ISSUED	SUBJEC CATEGO	
8310240344 8310240345 8310240347 8310240351 8310240352	8310240331 8310240019 8310240019 8310240019 8310240348	83/10/17 83/07/15 83/07/15 83/07/15 83/09/27	50-329 FOIA FOIA FOIA 40-6659	A	83102701 83102701 83102701 83102701 83102701	76 8310270165 77 8310270074 78 8310270164	11/01/E8 12/01/E8 11/01/E8 11/01/E8	FOIA 50-329 FOIA 70-371 FOIA	a
8310260354 8310260356 8310260357 8310260361 8310260366	8310260019 8310260019 8310260019 8310260019	83/07/15 83/07/15 83/07/15 83/07/15 83/07/15	FOIA FOIA FOIA FOIA FOIA		83102701 83102701 83102701 83102701 83102702	89 8310270074 94 8310270184 96 8310270190	83/10/11 83/10/11 83/10/07 83/10/24 83/08/08	FOIA FOIA 50-29 50-315 50-909	Q F F
8310260372 8310260374 8310260375 8310260378 8310260384	8310260019 8310260019 8310260371 8310260019 8310260019	89/07/15 83/07/15 89/10/13 83/07/15	FOIA FOIA CONTRACT FOIA FOIA	г	83102702 83102702 83102702 83102702 83102702	13 8310270204 16 8310270200 17 8310270207	83/10/18 83/10/18 83/08/08 83/10/18 83/10/24	50-220 50-315 50-309 50-220 50-155	0 5 6 8
8310260388 8310260394 8310260418 8310260432 8310260433	8310240019 8310240019 8310240414 8310240428 8310240431	83/07/15 83/07/15 83/07/29 83/10/21 83/10/21	FOIA FDIA 40-8783 50-280 50-263	F F	83102702 83102702 83102702 83102702 83102702	30 8310270225 43 8310270232 56 8310270257	83/10/18 83/10/20 83/10/13 83/10/21 83/10/18	50-315 50-293 50-57 50-329 50-315	8 9 9 9
6310240434 6310240438 8310270015 6310270017 8310270017	8310260428 8310260431 8310270005 8310270009 8310270005	83/10/21 83/10/21 83/10/27 83/10/21 83/10/27	50-260 50-263 50-331 50-10 50-331	7 7 7 7	83102702: 83102702: 83102703: 83102703: 83102703:	75 8310270291 9310270294 13 8310270294	83/10/11 83/10/11 83/10/14 83/10/14 83/10/03	FOIA 50-134 50-244 50-246 50-287	0 0 0
8310270021 8310270023 8310270028 8310270032 8310270041	8310270018 8310270012 8310270024 8310270024 8310270040	83/10/21 83/10/20 83/10/21 83/10/21 83/07/06	50-213 50-321 50-254 50-254 50-320	F F F P	83102703: 83102703: 83102703: 83102703: 83102703:	88 8310270338 82 8310270341 84 8310270347	83/10/20 83/10/17 83/10/21 83/09/29 83/10/24	50-366 50-275 50-327 50-251 50-352	P G S G
8310270042 8310270044 8310270045 8310270050 8310270053	8310270039 8310270040 8310270040 8310270038 8310270049	83/10/20 83/07/06 83/07/06 83/10/05 83/10/27	50-307 50-320 FOIA TOPREP 50-387	F P	83102703; 83102703; 83102703; 83102703; 83102703;	61 8310270358 62 8310270268 64 8310270347	83/07/27 83/10/25 83/10/24 83/07/27 83/10/24	50-263 50-275 50-352 50-263 50-352	80086
9310270055 9310270058 9310270067 9310270075 9310270080	8310270038 8310270052 8310270047 8310270071 8310270074	83/10/05 83/10/11 83/10/27 83/07/14 83/10/11	TOPREP 50-334 50-389 FOIA FOIA	g F	83102703; 83102703; 83102703; 83102703; 83102703;	78 8310270374 80 8310270347 90 8310270347	83/10/17 83/10/21 83/09/29 83/09/29 83/10/21	50-275 50-348 50-266 50-263 50-289	0 9 9 8
8310270084 8310270084 8310270092 8310270094 8310270097	8310270074 8310270076 8310270074 8310270076 8310270074	83/10/11 83/10/20 83/10/11 83/10/20 83/10/11	FOIA 50-244 FOIA 50-244 FOIA	F F	83102704 83102704: 83102704: 83102704 83102704	4 8310270347 5 8310270347 8 8310270347	83/09/29 83/09/29 83/09/29 83/09/29 83/09/29	50-243 50-243 50-282 50-282 50-282	8 8 8
8310270100 8310270105 8310270107 8310270108 8310270109	8310270074 8310270074 8310270104 8310270061 8310270074	83/10/11 83/10/11 83/07/19 83/10/18 83/10/11	FOIA FOIA FOIA 50-344 FOIA	8	B3102704; 83102704; 83102704; 83102704; 83102704;	8310270347 8310270422 7 8310270347	83/10/14 83/09/29 83/10/14 83/09/29 83/09/29	50-440 50-282 50-440 50-282 50-304	0 9 9 8
8310270110 8310270113 8310270115 8310270115 8310270122	8310270104 8310270074 8310270061 8310270074 8310270074	83/10/11 83/10/18 83/10/18 83/10/11	FOIA FOIA 50-364 FOIA FOIA	8	631027044 631027045 631027045 631027042 631027042	0 8310270446 3 8310270449 7 8310270449	83/10/13 83/10/14 83/10/24 83/10/24 83/10/13	50-305 50-255 50-367 50-367 50-443	0 9 P Q
8310270125 8310270127 8310270133 8310270134 8310270136	8310270119 8310270074 8310270074 8310270128 8310270026	83/10/21 83/10/11 83/10/11 83/10/11 83/10/20	50-289 FOIA FOIA 50-454 50-369	F Q F	B31027047 B31027047 B31027046 B31027050 B31027050	4 8310270445 5 8310270461 5 8310270501	83/10/04 83/10/13 83/10/21 83/07/28 83/10/21	FOIA 50-443 50-317 FOIA 50-155	a F
8310270138 8310270139 8310270140 8310270144 8310270145	8310270132 8310270074 8310270128 8310270074 8310270132	83/07/15 83/10/11 83/10/11 83/10/11 83/07/15	FOIA FOIA 50-454 FOIA FOIA	a	831027055 831027055 831027055 831027053 831027054	4 8310270519 4 8310270532 7 8310270526	83/10/21 83/09/27 83/10/21 83/10/21 83/07/22	50-344 40-8698 50-29 50-10 50-277	F F S
8310270146 8310270147 8310270149 8310270151 8310270153	8310270024 8310270074 8310270143 8310270074 8310270129	83/10/20 83/10/11 83/10/25 83/10/11 83/10/14	50-369 FOIA 50-244 FOIA 50-250	F 0 P	831027056 831027057 831027057 831027057 831027057	2 8310270566 4 8310270552 5 8310270566	83/10/21 83/10/25 83/10/21 83/10/25 83/10/21	50~461 50~275 50~461 50~275 CDNTRACT	٦ ٦ ٦
8310270156 8310270157 8310270158 8310270159 8310270161	8310270074 8310270141 8310270155 8310270074 8310270127	83/10/11 83/09/30 83/10/21 83/10/11 83/10/14	FOIA	a P	831027058 831027058 831027058 831027058 831027059	5 8310270581 6 8310270582 8 8310270582	83/10/25 83/10/06 83/10/25 83/10/25 63/10/25	50-275 50-220 50-275 50-275 50-155	F F F F
8310270163 8310270168 8310270169 8310270170 8310270171	8310270074 8310270074 8310270164 8310270074 8310270165	83/10/11 83/10/13 83/10/11 83/10/11	FDIA FDIA 70-371 FDIA 50-329	Q	831027059 831027059 831027063 831027063 831027064	8 8310270594 6 8310270594 9 8310270635	83/10/25 83/10/21 83/10/19 83/10/03 83/10/03	50-155 TOPREP CONTRACT 40-672 40-672	F

ACCEBSION	1 NUMBER			ACCESS IO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEQORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	Y
8310270647 8310270652 8310270656 8310280006 8310280017	8310270635 8310270635 8310270635 8310280002 8310280007	E0\01\E8 E0\01\E8 02\01\E8 01\01\E8	40-672 40-672 40-672 50-382 A TOPREP	8310280322 8310310032 8310310046 8310310056 8310310058	8310280321 8310310027 8310310043 8310310031 8310310031	83/09/06 83/10/25 83/10/26 83/07/06 83/07/06	40-1341 50-261 50-333 50-298	PPP
8310280017 8310280020 8310280027 8310280033 8310280040	8310280014 8310280016 8310280022 8310280024 8310280021	83/10/21 83/10/21 83/10/24 83/10/13 83/10/24	50-400 E 50-142 T 50-327 P XPORTLIC 50-327 P	8310310061 8310310064 8310310065 8310310067 8310310068	8310310031 8310310031 8310310031 8310310031	83/07/06 83/07/06 83/10/26 83/07/06 83/07/06	50-278 50-412 50-250	PPKPP
8310280048 8310280054 8310280047 8310280048 8310280078	8310280034 8310280044 8310280040 8310280042 8310280073	83/10/21 83/10/24 83/10/21 83/10/19 83/10/25	50-275 Q 50-333 F 50-275 Q CONTRACT 50~329 Q	8310310070 8310310072 8310310073 8310310076 8310310077	6310310031 8310310031 8310310031 8310310031	83/07/04 83/07/04 83/07/04 83/07/04 83/07/06	50-245 50-244 50-244	P P P P
8310280092 8310280104 8310280107 8310280110 8310280114	8310280085 8310280074 8310280103 8310280104 8310280085	83/10/14 83/10/20 83/09/21 83/10/24 83/10/14	50-348 P CONTRACT WASTE MGT PROJ 50-348 P	8310310080 8310310114 8310310130 8310310131 8310310133	6310310031 6310310097 6310310124 6310310097 6310310128	83/07/06 83/09/19 83/10/26 83/10/20	FOIA 50-416 50-289	P Q P Q
8310280115 8310280114 8310280122 8310280132 8310280134	831028010B 8310280111 8310280119 8310280079 8310280128	63/10/21 63/09/19 63/10/20 63/07/28 63/10/27	50-289 P WASTE MOT 50-311 Q FOIA 50-409 P	8310310134 8310310140 8310310151 8310310154 8310310163	8310310097 8310310097 8310310149 8310310149 8310310158	83/09/19 83/10/21 83/10/21 83/10/25	50-508	A A G
8310280134 8310280137 8310280138 8310280142 8310280144	8310280079 8310280133 8310280079 8310280140 8310280144	83/07/28 83/10/25 83/07/28 83/10/12 83/10/25	50-344 8 CONTRACT 50-344 8 50-334 F 50-322 U	8310310164 8310310176 8310310177 8310310184 8310310214	8310310141 8310310173 8310310173 8310310181 8310310213	83/10/25 83/10/12 83/10/12 83/10/27 83/10/19	50-292 50-292 50-275	9 9 9 9
8310280149 8310280150 8310280151 8310280163 8310280167	8310280148 8310280148 8310280148 8310280161 8310280165	83/10/19 83/10/19 83/10/19 83/10/27 83/09/21	50-257 P 50-257 P 50-257 P 50-407 P 40-279	8310310224 8310310227 8310310230 8310310238 8310310241	8310310225 8310310225 8310310227 8310310229 8310310239	83/10/25 83/09/21 83/10/13 83/10/24 83/10/14	50-311 50-317 50-410	0 0 0 0
8310280168 8310280170 8310280171 8310280175 8310280177	8310280079 8310280165 8310280079 8310280165 8310280165	83/07/28 83/07/28 83/07/28 83/09/21 83/09/21	50~266 S 40~299 50~266 S 40~299 40~299	8310310243 8310310249 8310310251 8310310264 8310310281	8310310228 8310310233 8310310246 8310310256 8310310274	83/10/24 83/10/17 83/10/14 83/10/07 83/10/26	50-73 50-275 50-445	K
8310280178 8310280179 8310280193 8310280197 8310280199	8310280165 8310280172 8310280176 8310280176 8310280189	83/09/21 83/10/14 83/09/23 83/09/23 83/10/18	40-297 50-289 P 50-400 Q 50-400 A 50-458 A	8310310286 8310310287 8310310293 8310310301 8310310302	8310310279 8310310282 8310310289 8310310299 8310310294	83/10/14 83/10/20 83/10/12 83/10/17 83/10/18	70-1100 50-461 50-344	0 0 0
8310280202 8310280207 8310280209 8310280211 8310280214	8310280176 8310280176 8310280191 8310280176 8310280176	83/09/23 83/09/23 83/10/26 83/09/23	50-400 A 50-400 A 50-10 F 50-400 A 50-400 A	8310310304 8310310312 8310310333 8310310341 8310310343	8310310296 8310310309 8310310325 8310310332 8310310338	83/10/13 75/10/27 81/01/18 11/01/28 11/01/28	50-412 50-305 50-275	0 F Q Q
8310280215 8310280218 8310280220 8310280222 8310280224	8310280206 8310280176 8310280212 8310280176 8310280212	83/10/25 83/09/23 83/08/24 83/09/23 83/08/24	50-373 F 50-400 A 50-358 Q 50-400 A 50-358 A	8310310346 8310310347 8310310353 8310310354 8310310357	8310310332 8310310342 8310310336 8310310332 8310310352	83/10/13 83/10/26 83/10/13 83/10/13	50-341 50~352	G G G G
8310280225 8310280227 8310280231 8310280236 8310280238	8310280176 8310280212 8310280212 8310280176 8310280176	83/09/23 83/08/24 83/08/24 83/09/23 83/09/23	50-400 A 50-358 A 50-358 A 50-400 A	8310310362 8310310371 8310310389 8310310383	8310310356 8310310336 8310310376 8310310375 8310310376	83/10/26 83/10/21 83/10/25 83/07/19 83/10/25	50-155 40-8084	o F
8310280242 8310280244 8310280246 8310280248 8310280250	8310280176 8310280176 8310280176 8310280176 8310280176	83/09/23 83/09/23 83/09/23 83/09/23	50-400 A 50-400 A 50-400 A 50-400 A 50-400 A	8310310388 8310310393 8310310398 8310310400 8310310408	8310310384 8310310384 8310310396 8310310397 8310310401	83/08/10 83/08/10 83/10/13 83/10/17 83/10/12	50~267 50~528	P G G
8310280254 8310280254 8310280257 8310280259 8310280241	8310280174 8310280174 8310280252 8310280176 8310280253	83/09/23 83/09/23 83/10/25 83/09/23 83/10/25	50-400 A 50-400 A 50-277 F 50-400 A 50-3 F	8310310407 8310310408 8310310413 8310310417 8310310418	8310310397 8310310402 8310310410 8310310411 8310310414	B3/10/17 B3/10/05 B3/10/21 B3/10/17 B3/10/25	50-409 50-382 50-289 50-329 70-2430	9 9 9
8310280263 8310280265 8310280267 8310280270 8310280271	8310280174 8310280174 8310280253 8310280174 8310280252	83/09/23 83/09/23 83/10/25 83/09/23 83/10/25	50-400 A 50-400 A 50-3 F 50-400 A 50-277 F	8310310423 8310310430 8310310435 8310310438 8310310440	8310310419 8310310428 8310310433 8310310429 8310310439	89/10/25 83/10/14 83/10/13 83/10/24 83/10/14	70-2319 71-9084 50-267 50-327 50-321	P P P
8310280295 8310280299 8310280303 8310280313 8310280314	8310280283 8310280176 8310280176 8310280311 8310280307	83/10/13 83/09/23 83/09/23 83/10/25 83/10/25	WASTE MGT 50-400 A 50-400 A 50-213 F 50-10 F	8310310454	8308310050	83/10/14	50~32 <u>5</u>	8

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- Supplements to SER.
- 3. Correspondence relating to SER.
- 4 Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3 Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6 Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2 Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2
- 4 Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6 All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP)
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly semiannual or annual operating reports (other than financial).
- 2 Periodic environmental monitoring, effluent testing, or similar reports
- 3 Periodic personnel exposure reports
- 4 Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5 Correspondence of other documents relating to the above listed items

S REPORTABLE OCCURRENCES, PNOS, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- 1. All 24-hour, 10-day, 30-day interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3 Personnel exposure reports
- 4. Construction deficiency reports submitted under 10 CFR 50 55e.
- 5 Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs)
- 6. Environmental Technical Specifications violation reports and Environmental Event reports
- 7 Part 21 Reports of defects and noncompliance
- 8 Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB
- 3 Commission meeting transcript
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress of before bodies/committees appointed by the Executive or Legislative Branches
- 2 Preparatory and backup documents for item 1
- 3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators.
- 2 NRC examination results
- 3 Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3 Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- License applications, licenses, amendments and proposed amendments to possess power reactor spent
 fuel and other radioactive materials associated with spent storage in an independent spent fuel
 storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate
 site.)
- 2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available
- 4. ACRS consultant reports, comments and related correspondence.
- ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

- Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of assuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include.

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA,

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- Draft reports of action plans to accomplish generic tasks in the regulatory program
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3 Meeting notifications and minutes
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

1&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs)

- 1. I&E Circulars, which describe an event at a hoensed facility and are informational in nature
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions
 - b. They present the results of Commission licensing and policy decisions
 - c. They present the results of technical research conducted for the Commission
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation
- 3. Internal NRC memoranda summarizing meetings of discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and energency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

"Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include.

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE. For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding.
 - cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance
 - technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting
- State Legislative Reports. 3.
- Agreement State Licensing Statistics Reports. 4.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- Topical reports, dealing with such technical matters as specifications, testing and safety ١. submitted by architect, engineers and other vendors.
- Revisions, modifications and amendments to topical reports. 2.
- Correspondence between NRC and vendors pertaining to the review of submittals. 3.
- Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, 4. programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories. 1.
- Briefings by DOE on research being conducted on spent fuel storage and nuclear waste 2. management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE. For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

5 SUPPLEMENTA	RY NOTES	APPER PER MINISTER CONTRACTOR CON	14 (Leave blank)			
Monthly		Octobe	er 1-31, 1983			
3. TYPE OF REPO	RT	PLRIOD COVE	RED (Inclusive dates)			
			11 FIN NO			
Same as 9,	above.		10 PROJECT/TASK/WORK UNIT NO			
2 SPONSORING	DRGANIZATION NAME AND MAILING A	DDRESS (Include Zip Code)				
	, DC 20555		8 (Leave blank)			
	ar Regulatory Commission		6 (Leave blank)			
	f Technical Information a Administration	na vocument Control	December 198			
	RGANIZATION NAME AND MAILING A	DATE REPORT ISSUED				
			MONTH	YEAR		
7. AUTHOR(S)			5. DATE REPORT CO			
	October 1-31, 1983		O RESTRICT D AGGESSION NO			
TILLE LIST	of Documents Made Public	3 RECIPIENT'S ACCI	ESSION NO			
	FITLE (Add Volume No , if appropriate)	2 (Leave blank)				
	BIBLIOGRAPHIC DATA S	Vol. 5, No.	Vol. 5, No. 10			
NRC FORM 335	U.S. NUCLEAR REGULATORY CO		NUREG-0540	Assigned by Doc		

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

17. KEY WORDS AND DOCUMENT ANALYSIS

17b IDENTIFIERS/OPEN-ENDED TERMS

17a DESCRIPTORS

Unlimited

19 SECURITY CLASS (This report)
21 NO OF PAGES
Unclassified
20 SECURITY CLASS (This page)
21 NO OF PAGES
Unclassified
22 PRICE
5